Available from

NRC/GPO Sales Program
Superintendent of Documents
Government Printing Office
Washington, D.C. 20402

A year's subscription consists of 12 issues of this publication

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Title List of Documents Made Publicly Available

December 1-31, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555





CONTENTS

| Preface | ٧ |
|---|-------|
| Arrangement of Items by Docket Number | ix |
| Alphabetic Arrangement of Docket 50 Items by Facility Name | XVII |
| Docketed Items | 1 |
| Low Level Radwaste Disposal Sites - Docket 27 | 1 |
| Domestic Licensing of Source Material - Docket 40 | 6 |
| Domestic Licensing of Production and Utilization Facilities - Docket 50 | 12 |
| Domestic Licensing of Special Nuclear Material - Docket 70 | 297 |
| Packaging of Radioactive Material for Transport and Transportation of | |
| Radioactive Material Under Certain Conditions – Docket 71 | 306 |
| Nondocketed Items | 313 |
| 10CFR — Commission Meeting Records | 313 |
| ACRS - Advisory Committee on Reactor Safeguards | 314 |
| COMMISSION – NRC Commissioners | 315- |
| CONTRACT - NRC Contracts and Modifications | 318 |
| DISCLOSURE - Financial Disclosure Information | 321 |
| FOIA - Freedom of Information Act Requests and Releases | 321 |
| GEN TECH IS — Generic Technical Issues | |
| I&E - Inspection and Enforcement | 342 |
| MISC – Public Document Room Miscellaneous | 343 |
| NUREG — NUREG Reports and Related Correspondence | 344 |
| ORG - Correspondence with Other Organizations | 348 |
| PR – Proposed Rule | |
| PROJ - Projects - Predocket Licensing | 366 |
| PT21 - Noncompliance Reports and Related Correspondence | 366 |
| QA999 — Quality Assurance Inspections | 366 |
| REGGD - Regulatory Guides | 370 |
| RES – Research and Technical Assistance Reports | 372 |
| REVIEW GRP – NRC Research Review Groups | . 373 |
| SECY - Position Papers Before the Commission | . 374 |
| STATE PROG — State Programs | . 375 |
| TOPREP - Vendor Reports and Related Correspondence | . 377 |
| WASTE MGT - Nuclear Waste Management | . 379 |
| XPORTLIC - Export and Import Licenses | . 380 |
| Personal Author Index | . 387 |
| Corporate Source Index | . 421 |
| Report Number Index | . 449 |
| Cross Reference of Enclosures to Principal Documents | . 451 |
| Appendix A — Definitions of Docket 50 Categories | 469 |
| Appendix B — Definitions of Nondocketed Categories | 477 |
| Whiteliary D - Dellitring at Hondrowered Carefords | |



PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

(3)


Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

P. Operating license stage documents & correspondence

7904170015 Forwards info on TMI: JM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations.



- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
- 9. This three-digit portion of this entry is the number of the frame on which this document starts.
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room. 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E - Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG — Correspondence with other organizations

PR - Proposed Rule

PRM — Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT9 — Public Records

PT21 - Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD — Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM — Rulemakings

SECY - Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence

WASTE MGT — Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:


1 NUREG - NUREG Reports and Related Correspondence



7901060007 NUREG/CR-0161

"Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory.



- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document
- 10. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
- 11. This three-digit portion of this entry is the number of the frame on which this document starts.

12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

| Do | cket | Name | Page | Docket | Name | Page |
|----|---------|---|------|---------|---|------|
| | 27-010 | Beatty, NV | 1 | 40-8231 | General Electric Co. | 9 |
| | 27-039 | Sheffield, IL, Nuclear Engineering Co. | 3 | 40-8304 | Wyoming Mineral Corp. | 9 |
| | 27-047 | Barnwell, SC, Chem-Nuclear Systems, Inc. | 5 | 40-8348 | In Situ Uranium Leaching Project | 9 |
| | 27-048 | Richland, WA, Nuclear Engineering Co. | 6 | 40-8434 | Home State Mining Co. | 9 |
| | 40-0299 | Union Carbide Corp. | 6 | 40-8502 | Irigaray Mine, Wyoming Mining Corp. | 10 |
| | 40-0672 | Nuclear Metals, Inc. | 6 | 40-8584 | Union 76 Minerals Exploration Co. | 10 |
| | 40-1162 | Western Nuclear, Inc. | 6 | 40-8585 | Wyoming Mineral Corp. | 10 |
| | 40-1341 | Edgemont Uranium Mine, TVA and | 6 | 40-8602 | United Nuclear Corp. | 10 |
| | | Mines Development, Inc. | | 40-8642 | Thiokol Corp. | 10 |
| | 40-2061 | West Chicago Facility, Kerr-McGee Corp. | 7 | 40-8681 | Energy Fuels Nuclear, Inc. | 10 |
| | 40-2259 | Pathfinder Mines Corp. | 7 | 40-8693 | Ogie Petroleum, Inc. | 10 |
| | 40-3392 | Ailied Chemical Corp. | 7 | 40-8697 | Rocky Mountain Energy Co. | 10 |
| | 40-3453 | Atlas Minerals | 7 | 40-8709 | Western Zirconium, Inc. | 10 |
| | 40-4492 | Federal American Partners (Mining) | 7 | 40-8714 | Cleveland Cliffs Iron Co. | 11 |
| | 40-6622 | Pathfinder Mines Corp. | 7 | 40-8727 | Kerr-McGee Nuclear Corp. | 11 |
| | 40-6659 | Petrotomics Co., Getty Oil Co. | 7 | 40-8728 | Teton Exploration Drilling Co., Inc. | 11 |
| | 40-6940 | Kawecki Berylco Industries, Inc. | 8 | 40-8743 | Conoco | 11 |
| | 40-7102 | Shieldalloy Corp. | 8 | 40-8745 | Ogle Petroleum | 11 |
| | 40-7402 | Allegheny Ludlum Industries, Chemtron Corp. | 8 | 40-8771 | Nuclear Assurance Corp. | 12 |
| | 40-7580 | Fansteel Metals | 8 | 40-8783 | Uranerz USA, Inc. | 12 |
| | 40-7924 | Schott Optical Glass, Inc. | 8 | 50-2 | Univ. of Michigan Research Reactor | 12 |
| | 40-8000 | Transnuclear, Inc. | 8 | 50-3 | Indian Point Station, Unit 1 | 12 |
| | · | | | | | 13 |
| | 40-8064 | Exxon Minerals Co. USA, Exxon Corp. | 8 | 50-10 | Dresden Nuclear Power Station, Unit 1 | |
| | 40-8084 | Lisbon Mine, Rio Algom Corp. | 8 | 50-13 | Babcock & Wilcox Co. Critical Facility | 15 |
| | 40-8102 | Exxon Minerals Co. USA, Exxon Corp. | 9 | 50-20 | Massachusetts Institute of Technology Research Reactor | 15 |
| | 40-8106 | Medical Center of Vermont, Burlington, VT | 9 | 50-27 | Washington State Univ. Research Reactor | 16 |
| | | | | | | |

| Docket | | Name | Page | Docket | Name | Page |
|--------|------------------|--|------|--------|---|------|
| ! | 50-29 | Yankee-Rowe Nuclear Power Station | 16 | 50-224 | Univ. of California Research Reactor | 34 |
| | 50-47 | Army Materials Research Reactor | 18 | 50-226 | Tarapur Atomic Project, India | 34 |
| | 50-54 | Union Carbide Research Reactor | 18 | 50-227 | TRIGA Thermionic Prototype Reactor | 34 |
| | 50-70 | General Electric Test Reactor | 19 | 50-228 | Aerotest Radiography & Research Reactor | 34 |
| | 50-73 | General Electric Nuclear Test Reactor | 19 | 50-237 | Dresden Nuclear Power Station, Unit 2 | 34 |
| | 50-83 | Univ. of Florida Training Reactor | 19 | 50-243 | Oregon State Univ. Research Reactor | 38 |
| | 50-89 | General Atomic Co. | 19 | 50-244 | Robert Emmet Ginna Nuclear Plant, | 38 |
| | 50-97 | Cornell Univ. Zero Power Reactor | 19 | 2321. | Unit 1 | |
| | 50-99 | Babcock & Wilcox Co. Test Reactor | 19 | 50-245 | Millstone Nuclear Power Station, Unit 1 | 39 |
| | 50-112 | Univ. of Oklahoma Research Reactor | 19 | 50-247 | Indian Point Station, Unit 2 | 41 |
| | 50-124 | Virginia Polytechnic Institute Training | 19 | 50-249 | Dresden Nuclear Power Station, Unit 3 | 44 |
| | | Reactor | 19 | 50-250 | Turkey Point Plant, Unit 3 | 47 |
| | 50-133 | Humboldt Bay Power Plant, Unit 3 | | 50-251 | Turkey Point Plant, Unit 4 | 49 |
| | 50-142 | UCLA Training Reactor | 20 | 50-254 | Quad-Cities Station, Unit 1 | 50 |
| | 50-143 | Philippines Research Reactor | 21 | 50-255 | Palisades Nuclear Plant | 52 |
| | 50-148 | Univ. of Kansas Research Reactor | 21 | 50-259 | Browns Ferry Nuclear Power Station, | 54 |
| | 50-150 | Ohio State Univ. Research Reactor | 21 | | Unit 1 | 57 |
| | 50-151 | Univ. of Illinois Research Reactor | 21 | 50-260 | Browns Ferry Nuclear Power Station, Unit 2 | 3/ |
| | 50-155 | Big Rock Point Nuclear Plant | 21 | 50-261 | H.B. Robinson Plant, Unit 2 | 59 |
| | 50-157 | Cornell Univ. Research Reactor | 24 | 50-263 | Monticello Nuclear Generating Plant | 62 |
| | 50-163 | General Atomic Co. | 24 | 50-265 | Quad-Cities Station, Unit 2 | 63 |
| | 50-166 | Univ. of Maryland Research Reactor | 24 | 50-266 | Point Beach Nuclear Plant, Unit 1 | 65 |
| | 50-170 | National Naval Medical Center | 24 | 50-267 | Fort St. Vrain Nuclear Generating | 66 |
| | 50-171 | Peach Bottom Atomic Power Station, Unit 1 | 25 | | Station | |
| | 50-182 | Purdue Univ. Research Reactor | 25 | 50-269 | Oconee Nuclear Station, Unit 1 | 68 |
| | 50-184 | National Bureau of Standards Reactor | 25 | 50-270 | Oconce Nuclear Station, Unit 2 | 70 |
| | | Univ. of Missouri Research Reactor | 25 | 50-271 | Vermont Yankee Nuclear Power Station | 72 |
| | 50-186 50-187 | Space Radiation Research Reactor | 25 | 50-272 | Salem Nuclear Generating Station, Unit 1 | 73 |
| | 50-201 | West Valley Reprocessing Plant | 25 | | | 0.0 |
| | | San Onofre Nuclear Station, Unit 1 | 26 | 50-275 | Diablo Canyon Nuclear Power Plant, Unit 1 | 76 |
| | 50-206 | · | | 50-277 | Peach Bottom Atomic Power Station, | 79 |
| | 50-213 | Haddam Neck Plant | 28 | | Unit 2 | |
| | 50-219 | Oyster Creek Nuclear Power Plant | 30 | 50-278 | Peach Bottom Atomic Power Station, | 82 |
| | 50-220 | Nine Mile Point Nuclear Station, Unit 1 | 32 | | Unit 3 | |

| Docket | Name | Page | Docket | Name | Page |
|--------|---|------|------------------|---|------------|
| 50-280 | Surry Power Station, Unit 1 | 84 | 50-324 | Brunswick Steam Electric Plant, Unit 2 | 143 |
| 50-281 | Surry Power Station, Unit 2 | 86 | 50-325 | Brunswick Steam Electric Plant, Unit 1 | 145 |
| 50-282 | Prairie Island Nuclear Station, Unit 1 | 88 | 50-326 | Univ. of California at Irvine Research Reactor | 148 |
| 50-285 | Fort Calhoun Station, Unit 1 | 90 | 50 227 | | 140 |
| 50-286 | Indian Point Station, Unit 3 | 91 | 50-327 | Sequoyah Nuclear Plant, Unit 1 | 148 |
| 50-287 | Oconee Nuclear Station, Unit 3 | 94 | 50-328 | Sequoyah Nuclear Plant, Unit 2 | 151 |
| 50-289 | Three Mile Island Nuclear Station, Unit 1 | 95 | 50-329 50-330 | Midland Plant, Unit 1 Midland Plant, Unit 2 | 153 155 |
| 50-293 | Pilgrim Nuclear Power Station, Unit 1 | 102 | 50-331 | Duane Arnold Energy Center | 157 |
| 50-295 | Zion Nuclear Power Station, Unit 1 | 104 | 50-333 | James A. Fitzpatrick Nuclear Power | 159 |
| 50-296 | Browns Ferry Nuclear Power Station, Unit 3 | 106 | 50-334 | Beaver Valley Power Station, Unit 1 | 161 |
| 50-298 | Cooper Nuclear Station | 108 | 50-335 | St. Lucie Plant, Unit 1 | 164 |
| 50-301 | Point Beach Nuclear Plant, Unit 2 | 110 | 50-336 | Millstone Nuclear Power Station, | 165 |
| 50-302 | Crystal River Nuclear Plant, Unit 3 | 111 | 50 550 | Unit 2 | 100 |
| 50-303 | Crystal River Nuclear Plant, Unit 4 | 113 | 50-338 | North Anna Power Station, Unit 1 | 167 |
| 50-304 | Zion Nuclear Power Station, Unit 2 | 113 | 50-339 | North Anna Power Station, Unit 2 | 171 |
| 50-305 | Kewaunee Nuclear Power Plant | 115 | 50-341 | Enrico Fermi Atomic Power Plant, Unit 2 | 173 |
| 50-306 | Prairie Island Nuclear Station, Unit 2 | 117 | 50-344 | Trojan Nuclear Plant | 174 |
| 50-309 | Maine Yankee Atomic Power Plant | 118 | 50-346 | Davis-Besse Nuclear Power Station, | 176 |
| 50-311 | Salem Nuclear Generating Station, | 119 | | Unit 1 | 210 |
| | Unit 2 | | 50-348 | Joseph M. Farley Nuclear Plant, Unit 1 | 178 |
| 50-312 | Rancho Seco Nuclear Generating Station | 121 | 50-352 | Limerick Generating Station, Unit 1 | 181 |
| 50-313 | Arkansas Nuclear One, Unit 1 | 123 | 50-353 | Limerick Generating Station, Unit 2 | 182 |
| 50-315 | Donald C. Cook Nuclear Power Plant, Unit 1 | 125 | 50-354 | Hope Creek Nuclear Station, Unit 1 | 183 |
| 50-316 | Donald C. Cook Nuclear Power Plant, | 126 | 50-355 | Hope Creek Nuclear Station, Unit 2 | 183 |
| | Unit 2 | | 50-356 | Univ. of Illinois LOPRA Research Reactor | 184 |
| 50-317 | Calvert Cliffs Nuclear Power Plant, Unit 1 | 127 | | | |
| 50-318 | Calvert Cliffs Nuclear Power Plant, | 129 | 50-358 | William H. Zimmer Nuclear Station, Unit 1 | 184 |
| 50-320 | Unit 2 Three Mile Island Nuclear Station, | 131 | 50-360 | Battelle Memorial Institute Critical Facility | 186 |
| 50.001 | Unit 2 | 136 | 50-361 | San Onofre Nuclear Station, Unit 2 | 186 |
| 50-321 | Edwin I. Hatch Nuclear Plant, Unit 1 | | 50-362 | San Onofre Nuclear Station, Unit 3 | 188 |
| 50-322 | Shoreham Nuclear Power Station | 138 | 50-363 | Forked River Nuclear Station, Unit 1 | 190 |
| 50-323 | Diablo Canyon Nuclear Power Plant, Unit 2 | 140 | 50-364 | Joseph M. Farley Nuclear Plant, Unit 2 | 191 |

| Doc | :ket | Name | Page | Docket | Name | Page |
|-----|--------|--|------|------------|---|------|
| | 50-366 | Edwin I. Hatch Nuclear Plant, Unit 2 | 193 | 50-416 | Grand Gulf Nuclear Station, Unit 1 | 237 |
| | 50-367 | Bailly Generating Station | 195 | 50-417 | Grand Gulf Nuclear Station, Unit 2 | 239 |
| | 50-368 | Arkansas Nuclear One, Unit 2 | 197 | 50-423 | Millstone Nuclear Power Station, Unit 3 | 241 |
| | 50-369 | William B. McGuire Nuclear Station, | 200 | 50-424 | Alvin W. Vogtle Nuclear Plant, Unit 1 | 241 |
| | | Unit 1 | 203 | 50-425 | Alvin W. Vogtle Nuclear Plant, Unit 2 | 242 |
| | 50-370 | William B. McGuire Nuclear Station, Unit 2 | 203 | 50-436 | Argentina Research Reactor | 243 |
| | 50-373 | LaSalle County Station, Unit 1 | 205 | STN-50-437 | Floating Nuclear Plant | 243 |
| | 50-374 | LaSalle County Station, Unit 2 | 206 | 50-438 | Bellefonte Nuclear Plant, Unit 1 | 243 |
| | 50-376 | North Coast Nuclear Plant, | 208 | 50-439 | Bellefonte Nuclear Plant, Unit 2 | 245 |
| | | Puerto Rico | 208 | 50-440 | Perry Nuclear Power Plant, Unit 1 | 247 |
| | 50-382 | Waterford Generating Station, Unit 3 | 209 | 50-441 | Perry Nuclear Power Plant, Unit 2 | 248 |
| | 50-387 | Susquehanna Steam Electric Station, Unit 1 | 203 | 50-443 | Seabrook Nuclear Station, Unit 1 | 249 |
| | 50-388 | Susquehanna Steam Electric Station, | 212 | 50-444 | Seabrook Nuclear Station, Unit 2 | 250 |
| | | Unit 2 | 215 | 50-445 | Comanche Peak Steam Electric Station, Unit 1 | 251 |
| | 50-389 | St. Lucie Plant, Unit 2 | 217 | 50-446 | Comanche Peak Steam Electric Station, | 254 |
| | 50-390 | Watts Bar Nuclear Plant, Unit 1 | 219 | 30 440 | Unit 2 | |
| | 50-391 | Watts Bar Nuclear Plant, Unit 2 Virgil C. Summer Nuclear Station, Unit 1 | 220 | STN-50-447 | GESSAR-238 | 256 |
| | 50-395 | | 220 | 50-448 | Douglas Point Nuclear Station, Unit 1 | 256 |
| | 50-397 | WPPSS Nuclear Project, Unit 2 | 224 | 50-449 | Douglas Point Nuclear Station, Unit 2 | 256 |
| | 50-400 | Shearon Harris Nuclear Power Plant, Unit 1 | 226 | 50-450 | Summit Nuclear Power Station, Unit 1 | 256 |
| | 50 401 | Shearon Harris Nuclear Power Plant, | 226 | 50-451 | Summit Nuclear Power Station, Unit 2 | 256 |
| | 50-401 | Unit 2 | 220 | 50-452 | Greenwood Energy Center, Unit 2 | 257 |
| | 50-402 | Shearon Harris Nuclear Power Plant, | 227 | 50-453 | Greenwood Energy Center, Unit 3 | 257 |
| | | Unit 3 | 222 | 50-454 | Byron Station, Unit 1 | 257 |
| • | 50-403 | Shearon Harris Nuclear Power Plant, Unit 4 | 228 | 50-455 | Byron Station, Unit 2 | 258 |
| | 50-404 | North Anna Power Station, Unit 3 | 229 | 50-456 | Braidwood Station, Unit 1 | 258 |
| | 50-405 | North Anna Power Station, Unit 4 | 230 | 50-457 | Braidwood Station, Unit 2 | 259 |
| | 50-409 | La Crosse Boiling Water Reactor | 230 | 50-458 | River Bend Station, Unit 1 | 260 |
| | 50-410 | | 233 | 50-459 | River Bend Station, Unit 2 | 261 |
| | | Unit 2 | | 50-460 | WPPSS Nuclear Project, Unit 1 | 261 |
| | 50-412 | Beaver Valley Power Station, Unit 2 | 234 | 50-461 | Clinton Power Station, Unit 1 | 262 |
| | 50-413 | Catawba Nuclear Station, Unit 1 | 234 | 50-462 | Clinton Power Station, Unit 2 | 263 |
| | 50-414 | Catawba Nuclear Station, Unit 2 | 235 | 50-463 | Fulton Generating Station, Unit 1 | 263 |
| | | | | | | |

| Docket | Name | Page | Docket | Name | Page |
|------------|---|------|------------|--|------|
| 50-464 | Fulton Generating Station, Unit 2 | 264 | STN-50-520 | Hartsville Nuclear Plant, Unit 3 | 283 |
| 50-466 | Allens Creek Nuclear Station, Unit 1 | 264 | STN-50-521 | Hartsville Nuclear Plant, Unit 4 | 284 |
| 50-467 | Allens Creek Nuclear Station, Unit 2 | 266 | STN-50-522 | Skagit Nuclear Power Project, Unit 1 | 285 |
| STN-50-470 | CESSAR System 80 | 266 | STN-50-523 | Skagit Nuclear Power Project, Unit 2 | 285 |
| 50-471 | Pilgrim Nuclear Power Station, Unit 2 | 266 | 50-524 | Barton, Unit 1 | 286 |
| STN-50-482 | Wolf Creek Generating Station | 267 | 50-525 | Barton, Unit 2 | 286 |
| STN-50-483 | Calloway Plant, Unit 1 | 268 | 50-526 | Barton, Unit 3 | 286 |
| STN-50-484 | Tyrone Energy Park, Unit 1 | 269 | 50-527 | Barton, Unit 4 | 286 |
| STN-50-485 | Sterling Power Project Nuclear, Unit 1 | 269 | STN-50-528 | Palo Verde Nuclear Station, Unit 1 | 286 |
| STN-50-486 | Calloway Plant, Unit 2 | 269 | STN-50-529 | Palo Verde Nuclear Station, Unit 2 | 287 |
| STN-50-488 | Perkins Nuclear Station, Unit 1 | 270 | STN-50-530 | Palo Verde Nuclear Station, Unit 3 | 289 |
| STN-50-489 | Perkins Nuclear Station, Unit 2 | 270 | 50-537 | Clinch River Breeder Reactor | 290 |
| STN-50-490 | Perkins Nuclear Station, Unit 3 | 271 | STN-50-546 | Marble Hill Nuclear Station, Unit 1 | 290 |
| STN-50-491 | Cherokee Nuclear Station, Unit 1 | 271 | STN-50-547 | Marble Hill Nuclear Station, Unit 2 | 291 |
| STN-50-492 | Cherokee Nuclear Station, Unit 2 | 272 | 50-548 | Fort Calhoun Station, Unit 2 | 292 |
| STN-50-493 | Cherokee Nuclear Station, Unit 3 | 272 | STN-50-553 | Phipps Bend Nuclear Plant, Unit 1 | 292 |
| STN-50-498 | South Texas Project, Unit 1 | 273 | STN-50-554 | Phipps Bend Nuclear Plant, Unit 2 | 293 |
| STN-50-499 | South Texas Project, Unit 2 | 275 | STN-50-556 | Black Fox Station, Unit 1 | 294 |
| 50-500 | Davis-Besse Nuclear Power Station, | 277 | STN-50-557 | Black Fox Station, Unit 2 | 295 |
| 20300 | Unit 2 | 211 | STN-50-566 | Yellow Creek Nuclear Plant, Unit 1 | 295 |
| 50-501 | Davis-Besse Nuclear Power Station, Unit 3 | 277 | STN-50-567 | Yellow Creek Nuclear Plant, Unit 2 | 296 |
| STN-50-508 | WPPSS Nuclear Project, Unit 3 | 277 | STN-50-574 | Bagnac Nuclear Power Project, Philippines | 297 |
| STN-50-509 | WPPSS Nuclear Project, Unit 5 | 278 | 50-579 | TRIGA Mark II, Pool-Type Reactor | 297 |
| 50-510 | Blue Hills Station, Unit 1 | 278 | 50-582 | Sundesert, Unit 1 | 297 |
| 50-511 | Blue Hills Station, Unit 2 | 279 | 50-583 | Sundesert, Unit 2 | 297 |
| 50-513 | WPPSS Nuclear Project, Unit 4 | 279 | STN-50-596 | New Haven, Unit 1 | 297 |
| 50-514 | Pebble Springs Nuclear Plant, Unit 1 | 279 | STN-50-597 | New Haven, Unit 2 | 297 |
| 50-515 | Pebble Springs Nuclear Plant, Unit 2 | 279 | 50-599 | Carroll Facility I | 297 |
| STN-50-516 | Jamesport Nuclear Station, Unit 1 | 280 | 50-600 | Carrolt Facility II | 297 |
| STN-50-517 | Jamesport Nuclear Station, Unit 2 | 280 | 70-0008 | Battelle Columbus Laboratories | 297 |
| STN-50-518 | Hartsville Nuclear Plant, Unit 1 | 280 | 70-0025 | Rockwell International Corp. | 297 |
| STN-50-519 | Hartsville Nuclear Plant, Unit 2 | 281 | 70-0027 | Babcock & Wilcox Co. | 298 |
| 1, 1, 0 | production of the state of the | | | | |

| Docket | Name | Page | Docket | Name | Page |
|---------|---|------|--------------------|--|------|
| 70-0033 | Texas Instruments, Inc. | 298 | 70-1739 | Tri-State Motor Transit Co. | 304 |
| 70-0036 | Combustion Engineering, Inc. | 298 | 70-1966 | Tennessee Valley Authority | 304 |
| 70-0082 | Nuclear Metals, Inc. | 298 | 70-2156 | St. John's Hospital, Lowell, MA | 304 |
| 70-0135 | Babcock & Wilcox Co. | 298 | 70-2286 | Medical Center of Vermont, Burlington, VT | 304 |
| 70-0143 | Nuclear Fuel Services, Inc. | 298 | 70-2322 | Edlow International Co. | 304 |
| 70-0157 | Univ. of Texas | 299 | | | 304 |
| 70-0258 | Univ. of Illinois at Urbana-Champaign | 300 | 70-2392 | Edlow International Co. | 304 |
| 70-0364 | Parks Township Site, Babcock & Wilcox Co. | 300 | 70-2478 70-2479 | Transnuclear, Inc. Transnuclear, Inc. | 305 |
| 70-0371 | United Nuclear Corp. | 300 | 70-2520 | West Virginia Univ. Medical Center, | 305 |
| 70-0398 | Dept. of Commerce | 300 | | Morgantown, WV | |
| 70-0687 | Union Carbide Corp. | 300 | 70-2609 | Commonwealth Edison Co. | 305 |
| 70-0698 | Waltz Mill Site, Westinghouse | 301 | 70-2623 | McGuire Spent Fuel Pool, Duke Power Co. | 305 |
| | Electric Corp. | 201 | 70-2663 | St. Mary's Hospital, Quincy, IL | 305 |
| 70-0734 | General Atomic Co. | 301 | 70-2881 | Bethesda Luthern Hospital, | 305 |
| 70-0754 | Vallecitos Nuclear Center, General Electric Co. | 301 | | St. Paul, MN | |
| 70-0820 | United Nuclear Corp. | 301 | 70-2882 | Southern California Edison Co. | 305 |
| 70-0882 | Columbia Univ. | 302 | 70-2885 | Commonwealth Edison | 305 |
| 70-0925 | Cimarron Facility, Kerr-McGee Corp. | 302 | 70-2892 | Auxilio Mutuo Hospital, Puerto Rico | 306 |
| 70-1062 | Todd Shipyards Corp. | 302 | 70-2909 | Westinghouse Electric Corp. Power Systems | 306 |
| 70-1100 | Combustion Engineering, Inc. | 302 | 70-2936 | Mississippi Power & Light Co. | 306 |
| 70-1113 | General Electric Co. | 302 | 70-2937 | Pennsylvania Power & Light Co. | 306 |
| 70-1143 | Westinghouse Electric Corp. | 302 | 71-0024 | Hittman Nuclear & Development Corp. | 306 |
| 70-1151 | Westinghouse Electric Corp. | 303 | 71-0035 | Rockwell International Corp. | 306 |
| 70-1193 | Cimarron Facility, Kerr-McGee Corp. | 303 | 71-0102 | Source Products & Equipment Co., Inc. | 306 |
| 70-1201 | UF-6 Conversion Facility, Babcock & Wilcox Co. | 303 | 71-0345 | Carolina Power & Light Co. | 306 |
| | | | 71-0350 | Picker Corp. | 307 |
| 70-1252 | Edlow International Co. | 303 | 71-0354 | Advanced Nuclear Systems | 307 |
| 70-1257 | Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc. | 303 | 71-0395 | Dept. of the Navy, Naval Facilities Engineering Command | 307 |
| | verations, General Electric Co. | 303 | 71-0399 | State of North Carolina | 307 |
| | ""'nn | 304 | 71-0400 | Dept. of the Navy | 307 |
| | d, VA | 304 | 71-0401 | Reliance Testing Laboratories, Inc. | 307 |
| | | 304 | 71-5088 | Model: D34710-1, U.S. Nuclear, Inc. | 307 |

| Docket | Name | Page | Docket | Name | Page |
|---------|--|------|---|---|------|
| 71-5362 | Model: GE-700, Dept. of Agriculture | 307 | 71-9010 | Model: NLI-1/2, NL Industries, Inc. | 309 |
| 71-5364 | Model: NPI-67-0442, Neutron Products, Inc. | 307 | 71-9011 | Model: E-MEH-00-00004, Dept. of Transportation | 309 |
| 71-5450 | Model: RCC-1, -2, -3, Westinghouse Electric Corp. | 307 | 71-9015 | Model: TN-8, Transnuclear, Inc. | 309 |
| 71-5768 | Model: BB-250-2, Combustion Engineering Co., Inc. | 307 | 71-9036 | Model: C-1, Source Production Equipment Co. | 309 |
| 71-5796 | Model: 181361, Picker Corporation | 307 | 71-9070 | Model: N-55, Dept. of Energy | 309 |
| 71-5908 | Model: DOT-GM Type B, Babcock & Wilcox Co. | 308 | 71-9073 | Model: OH-142, Nuclear Packaging, Inc. | 309 |
| 71-5957 | Model: BMI-1, Dept. of Energy | 308 | 71-9079 | Model: HN-100 Series 2, Hittman Nuclear & Development Corp. | 310 |
| 71-6058 | Model: B3-1, Nuclear Engineering Co. | 308 | 71-9080 | Model: HN-600, Hittman Nuclear & | 310 |
| 71-6144 | Model: 6144, Nuclear Engineering Co. | 308 | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | Development Corp. | 310 |
| 71-6375 | Model: PB-1, Chem-Nuclear Systems, Inc. | 308 | 71-9086 | Model: HN-100 Series 1, Hittman | 310 |
| 71-6400 | Model: Super Tiger, Westinghouse Electric Corp. | 308 | | Nuclear & Development Corp. | |
| 71-6458 | Model: BU-5, General Electric Co. | 308 | 71-9089 | Model: HN-100 S, Hittman Nuclear & Development Corp. | 310 |
| 71-6574 | Model: HN-200, Hittman Nuclear & Development Corp. | 308 | 71-9111 | Model: CN6-80A, Chem-Nuclear, Inc. | 310 |
| 71-6581 | Model: 51032-1 & 1A, Exxon Nuclear | 308 | 71-9120 | Model: TN-12, Transnuclear Corp. | 310 |
| | Co., Inc. | 000 | 71-9136 | Model: GE-9136, General Electric Co. | 311 |
| 71-6601 | Model: LL-50-100, Chem-Nuclear Systems, Inc. | 308 | 71-9139 | Model: GE-589, General Electric Co. | 311 |
| 71-6679 | Model: 1/2 Super Tiger, Nuclear Engineering Co. | 308 | 71-9141 | Model: 900 Type B, Technical Operations, Inc. | 311 |
| 71-6698 | Model: NFS-4, Nuclear Fuel Services, Inc. | 308 | 71-9144 | Model: SGC-1, Chem-Nuclear System, Inc. | 311 |
| 71-6717 | Model: 6717 B | 308 | 71-9145 | Model: NUPAC-50 Nuclear Packaging, Inc. | 311 |
| 71-6722 | Model: BS-33-180, Tennessee Valley Authority | 308 | 71-9147 | Model: 850 Type B Packaging, Tech Ops, Inc. | 311 |
| 71-6744 | Model: Poly Tiger, Nuclear Engineering Co. | 309 | 71-9853 | Model: ORNL-BNL-NBS, Unirradiated Fuel Container, Dept. of Energy | 311 |

| \$1 | | | |
|-----|---|--|--|
| | | | |
| | | | |
| | | | |
| | ¥ | | |
| | | | |
| | ÷ | | |
| | | | |
| | | | |
| | | | |

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

| Name | Docket | Page | Name | Docket | Page |
|---|------------|------|---|------------|------|
| Aerotest Radiography & Research Reactor | 50-228 | 34 | Braidwood Station, Unit 2 | 50-457 | 259 |
| Allens Creek Nuclear Station, Unit 1 | 50-466 | 264 | Browns Ferry Nuclear Power Station, | 50-259 | 54 |
| Allens Creek Nuclear Station, Unit 2 | 50-467 | 266 | Unit 1 | | • |
| Argentina Research Reactor | 50-436 | 243 | Browns Ferry Nuclear Power Station, Unit 2 | 50-260 | 57 |
| Arkansas Nuclear One, Unit 1 | 50-313 | 123 | Browns Ferry Nuclear Power Station, | 50-296 | 106 |
| Arkansas Nuclear One, Unit 2 | 50-313 | | Unit 3 | 30-230 | 100 |
| | | 197 | Brunswick Steam Electric Plant, Unit 1 | 50-325 | 145 |
| Army Materials Research Reactor | 50-47 | 18 | Brunswick Steam Electric Plant, Unit 2 | 50-324 | 143 |
| Duane Arnold Energy Center | 50-331 | 157 | Byron Station, Unit 1 | 50-454 | 257 |
| Babcock & Wilcox Co, Critical Facility | 50-13 | 15 | Byron Station, Unit 2 | 50-455 | 258 |
| Babcock & Wilcox Co. Test Reactor | 50-99 | 19 | Calloway Plant, Unit 1 | STN-50-483 | 268 |
| Bagnac Nuclear Power Project, Philippines | STN-50-574 | 297 | Calloway Plant, Unit 2 | STN-50-486 | 269 |
| Bailly Generating Station | 50-367 | 195 | Calvert Cliffs Nuclear Power Plant, | 50-317 | 127 |
| Barton, Unit 1 | 50-524 | 286 | Unit 1 | | |
| Barton, Unit 2 | 50-525 | 286 | Calvert Cliffs Nuclear Power Plant, Unit 2 | 50-318 | 129 |
| Barton, Unit 3 | 50-526 | 286 | Carroll Facility I | 50-599 | 297 |
| Barton, Unit 4 | 50-527 | 286 | • | | 297 |
| Battelle Memorial Institute Critical Facility | 50-360 | 186 | Carroll Facility II | 50-600 | |
| Beaver Valley Power Station, Unit 1 | 50-334 | 161 | Catawba Nuclear Station, Unit 1 | 50-413 | 234 |
| Beaver Valley Power Station, Unit 2 | 50-412 | 234 | Catawba Nuclear Station, Unit 2 | 50-414 | 235 |
| Bellefonte Nuclear Plant, Unit 1 | 50-438 | 243 | CESSAR System 80 | STN-50-470 | 266 |
| Bellefonte Nuclear Plant, Unit 2 | 50-439 | 245 | Cherokee Nuclear Station, Unit 1 | STN-50-491 | 271 |
| Big Rock Point Nuclear Power Plant | 50-155 | 21 | Cherokee Nuclear Station, Unit 2 | STN-50-492 | 272 |
| Black Fox Station, Unit 1 | STN-50-556 | 294 | Cherokee Nuclear Station, Unit 3 | STN-50-493 | 272 |
| Black Fox Station, Unit 2 | STN-50-557 | 295 | Clinch River Breeder Reactor | 50-537 | 290 |
| Blue Hills Station, Unit 1 | 50-510 | 278 | Clinton Power Station, Unit 1 | 50-461 | 262 |
| Blue Hills Station, Unit 2 | 50-511 | 279 | Clinton Power Station, Unit 2 | 50-462 | 263 |
| | a | | Comanche Peak Steam Electric Station, | 50-445 | 251 |
| Braidwood Station, Unit 1 | 50-456 | 258 | Unit 1 | | |

| Name | Docket | Page | Name | Docket | Page |
|---|------------|------|---|------------|------|
| Comanche Peak Steam Electric Station, Unit 2 | 50-446 | 254 | Fulton Generating Station, Unit 1 | 50-463 | 263 |
| | 50.215 | 105 | Fulton Generating Station, Unit 2 | 50-464 | 264 |
| Donald C. Cook Nuclear Power Plant, Unit 1 | 50-315 | 125 | General Atomic Co. | 50-89 | 19 |
| Donald C. Cook Nuclear Power Plant, Unit 2 | 50-316 | 126 | General Atomic Co. | 50-163 | 24 |
| Cooper Nuclear Station | 50-298 | 108 | General Electric Nuclear Test Reactor | 50-73 | 19 |
| Cornell Univ. Research Reactor | 50-157 | 24 | General Electric Test Reactor | 50-70 | 19 |
| Cornell Univ. Zero Power Reactor | 50-97 | 19 | GESSAR-238 | STN-50-447 | 256 |
| Crystal River Nuclear Plant, Unit 3 | 50-302 | 111 | Robert Emmet Ginna Nuclear Plant, Unit 1 | 50-244 | 38 |
| Crystal River Nuclear Plant, Unit 4 | 50-303 | 113 | Grand Gulf Nuclear Station, Unit 1 | 50-416 | 237 |
| Davis-Besse Nuclear Power Station, | 50-346 | 176 | Grand Gulf Nuclear Station, Unit 2 | 50-417 | 239 |
| Unit 1 | | | Greenwood Energy Center, Unit 2 | 50-452 | 257 |
| Davis-Besse Nuclear Power Station, Unit 2 | 50-500 | 277 | Greenwood Energy Center, Unit 3 | 50-453 | 257 |
| Davis-Besse Nuclear Power Station, | 50-501 | 277 | Haddam Neck Plant | 50-213 | 28 |
| Unit 3 | 50 275 | 76 | Shearon Harris Nuclear Power Plant, Unit 1 | 50-400 | 226 |
| Diablo Canyon Nuclear Power Plant, Unit 1 | 50-275 | 70 | | 50-401 | 226 |
| Diablo Canyon Nuclear Power Plant, Unit 2 | 50-323 | 140 | Shearon Harris Nuclear Power Plant, Unit 2 | | |
| Douglas Point Nuclear Station, Unit 1 | 50-448 | 256 | Shearon Harris Nuclear Power Plant, Unit 3 | 50-402 | 227 |
| Douglas Point Nuclear Station, Unit 2 | 50-449 | 256 | Shearon Harris Nuclear Power Plant, | 50-403 | 228 |
| Dresden Nuclear Power Station, Unit 1 | 50-10 | 13 | Unit 4 | OTT 50 510 | 000 |
| Dresden Nuclear Power Station, Unit 2 | 50-237 | 34 | Hartsville Nuclear Plant, Unit 1 | STN-50-518 | 280 |
| Dresden Nuclear Power Station, Unit 3 | 50-249 | 44 | Hartsville Nuclear Plant, Unit 2 | STN-50-519 | 281 |
| Joseph M. Farley Nuclear Plant, Unit 1 | 50-348 | 178 | Hartsville Nuclear Plant, Unit 3 | STN-50-520 | 283 |
| Joseph M. Farley Nuclear Plant, Unit 2 | 50-364 | 191 | Hartsville Nuclear Plant, Unit 4 | STN-50-521 | 284 |
| Enrico Fermi Atomic Power Plant, | 50-341 | 173 | Edwin I. Hatch Nuclear Plant, Unit 1 | 50-321 | 136 |
| Unit 2 | 30-341 | 173 | Edwin I. Hatch Nuclear Plant, Unit 2 | 50-366 | 193 |
| James A. Fitzpatrick Nuclear Power Plant | 50-333 | 159 | Hope Creek Nuclear Station, Unit 1 | 50-354 | 183 |
| Floating Nuclear Plant | STN-50-437 | 243 | Hope Creek Nuclear Station, Unit 2 | 50-355 | 183 |
| Forked River Nuclear Station, Unit 1 | 50-363 | 190 | Humboldt Bay Power Plant, Unit 3 | 50-133 | 19 |
| Fort Calhoun Station, Unit 1 | 50-285 | 90 | Indian Point Station, Unit 1 | 50-3 | 12 |
| | | | Indian Point Station, Unit 2 | 50-247 | 41 |
| Fort Calhoun Station, Unit 2 | 50-548 | 292 | Indian Point Station, Unit 3 | 50-286 | 91 |
| Fort St. Vrain Nuclear Generating Station | 50-267 | 66 | Jamesport Nuclear Station, Unit 1 | STN-50-516 | 280 |

| Name | Docket | Page | Name | Docket | Page |
|---|------------|------|--|------------------|-----------|
| Jamesport Nuclear Station, Unit 2 | STN-50-517 | 280 | North Coast Nuclear Plant, Puerto Rico | 50-376 | 208 |
| Kewaunee Nuclear Power Plant | 50-305 | 115 | Oconee Nuclear Station, Unit 1 | 50-269 | 68 |
| La Crosse Boiling Water Reactor | 50-409 | 230 | Oconee Nuclear Station, Unit 2 | 50-270 | 70 |
| LaSalle County Station, Unit 1 | 50-373 | 205 | Oconee Nuclear Station, Unit 3 | 50-287 | 94 |
| LaSalle County Station, Unit 2 | 50-374 | 206 | Ohio State Univ. Research Reactor | 50-150 | 21 |
| Limerick Generating Station, Unit 1 | 50-352 | 181 | Oregon State Univ. Research Reactor | 50-243 | 38 |
| Limerick Generating Station, Unit 2 | 50-353 | 182 | Oyster Creek Nuclear Power Plant | 50-219 | 30 |
| Maine Yankee Atomic Power Plant | 50-309 | 118 | Palisades Nuclear Plant | 50-255 | 52 |
| Marble Hill Nuclear Station, Unit 1 | STN-50-546 | 290 | Palo Verde Nuclear Station, Unit 1 | STN-50-528 | 286 |
| Marble Hill Nuclear Station, Unit 2 | STN-50-547 | 291 | Palo Verde Nuclear Station, Unit 2 | STN-50-529 | 287 |
| Massachusetts Institute of Technology Research Reactor | 50-20 | 15 | Palo Verde Nuclear Station, Unit 3 | STN-50-530 | 289 |
| William B. McGuire Nuclear Station, Unit 1 | 50-369 | 200 | Peach Bottom Atomic Power Station, Unit 1 | 50-171 | 25 |
| William B. McGuire Nuclear Station, Unit 2 | 50-370 | 203 | Peach Bottom Atomic Power Station, Unit 2 | 50-277 | 79 |
| Midland Plant, Unit 1 | 50-329 | 153 | Peach Bottom Atomic Power Station, Unit 3 | 50-278 | 82 |
| Midland Plant, Unit 2 | 50-330 | 155 | Pebble Springs Nuclear Plant, Unit 1 | 50-514 | 279 |
| Milistone Nuclear Power Station, Unit 1 | 50-245 | 39 | Pebble Springs Nuclear Plant, Unit 2 | 50-515 | 279 |
| Millstone Nuclear Power Station, | 50-336 | 168 | Perkins Nuclear Station, Unit 1 | STN-50-488 | 270 |
| Unit 2 | 30-330 | 165 | Perkins Nuclear Station, Unit 2 | STN-50-489 | 270 |
| Millstone Nuclear Power Station, Unit 3 | 50-423 | 241 | Perkins Nuclear Station, Unit 3 | STN-50-490 | 271 |
| Monticello Nuclear Generating Plant | 50-263 | 62 | Perry Nuclear Power Plant, Unit 1 | 50-440 | 247 |
| National Bureau of Standards Reactor | 50-184 | 25 | Perry Nuclear Power Plant, Unit 2 | 50-441 | 248 |
| National Naval Medical Center | 50-170 | 24 | Philippines Research Reactor | 50-143 | 21 |
| New Haven, Unit 1 | STN-50-596 | 297 | Phipps Bend Nuclear Plant, Unit 1 | STN-50-553 | 292 |
| New Haven, Unit 2 | STN-50-597 | 297 | Phipps Bend Nuclear Plant, Unit 2 | STN-50-554 | 293 |
| Nine Mile Point Nuclear Station, Unit 1 | 50-220 | 32 | Pilgrim Nuclear Power Station, Unit 1 Pilgrim Nuclear Power Station, Unit 2 | 50-293 50-471 | 102 |
| Nine Mile Point Nuclear Station, Unit 2 | 50-410 | 233 | Point Beach Nuclear Plant, Unit 1 | 50-266 | 266 65 |
| North Anna Power Station, Unit 1 | 50-338 | 167 | Point Beach Nuclear Plant, Unit 2 | 50-301 | 110 |
| North Anna Power Station, Unit 2 | 50-339 | 171 | Prairie Island Nuclear Station, Unit 1 | 50-282 | 88 |
| North Anna Power Station, Unit 3 | 50-404 | 229 | Prairie Island Nuclear Station, Unit 2 | 50-306 | 117 |
| North Anna Power Station, Unit 4 | 50-405 | 230 | Purdue Univ. Research Reactor | 50-182 | 25 |
| | 20 100 | 200 | Quad-Cities Station, Unit 1 | 50-254 | 50 |

| Name | Docket | Page | Name | Docket | Page |
|---|------------|------|--|------------|------|
| Quad-Cities Station, Unit 2 | 50-265 | 63 | Susquehanna Steam Electric Station, Unit 1 | 50-387 | 209 |
| Rancho Seco Nuclear Generating Station | 50-312 | 121 | Susquehanna Steam Electric Station, Unit 2 | 50-388 | 212 |
| River Bend Station, Unit 1 | 50-458 | 260 | Tarapur Atomic Project, India | 50-226 | 34 |
| River Bend Station, Unit 2 | 50-459 | 261 | Three Mile Island Nuclear Station, Unit 1 | 50-289 | 95 |
| H.B. Robinson Plant, Unit 2 | 50-261 | 59 | Three Mile Island Nuclear Station, Unit 2 | 50-320 | 131 |
| Salem Nuclear Generating Station, Unit 1 | 50-272 | 73 | TRIGA Mark II, Pool-Type Reactor | 50-579 | 297 |
| Salem Nuclear Generating Station, Unit 2 | 50-311 | 119 | TRIGA Thermionic Prototype Reactor | 50-227 | 34 |
| | | | Trojan Nuclear Plant | 50-344 | 174 |
| San Onofre Nuclear Station, Unit 1 | 50-206 | 26 | Turkey Point Plant, Unit 3 | 50-250 | 47 |
| San Onofre Nuclear Station, Unit 2 | 50-361 | 186 | Turkey Point Plant, Unit 4 | 50-251 | 49 |
| San Onofre Nuclear Station, Unit 3 | 50-362 | 188 | Tyrone Energy Park, Unit 1 | STN-50-484 | 269 |
| Seabrook Nuclear Station, Unit 1 | 50-443 | 249 | UCLA Training Reactor | 50-142 | 20 |
| Seabrook Nuclear Station, Unit 2 | 50-444 | 250 | Union Carbide Research Reactor | 50-54 | 18 |
| Sequoyah Nuclear Plant, Unit 1 | 50-327 | 148 | Univ. of California at Irvine Research | 50-326 | 148 |
| Sequoyah Nuclear Plant, Unit 2 | 50-328 | 151 | Reactor | | |
| Shoreham Nuclear Power Station | 50-322 | 138 | Univ. of California Research Reactor | 50-224 | 34 |
| Skagit Nuclear Power Project, Unit 1 | STN-50-522 | 285 | Univ. of Florida Training Reactor | 50-83 | 19 |
| Skagit Nuclear Power Project, Unit 2 | STN-50-523 | 285 | Univ. of Illinois LOPRA Research Reactor | 50-356 | 184 |
| South Texas Project, Unit 1 | STN-50-498 | 273 | Univ. of Illinois Research Reactor | 50-151 | 21 |
| South Texas Project, Unit 2 | STN-50-499 | 275 | Univ. of Kansas Research Reactor | 50-148 | 21 |
| Space Radiation Research Reactor | 50-187 | 25 | Univ. of Maryland Research Reactor | 50-166 | 24 |
| Sterling Power Project, Nuclear, | STN-50-485 | 269 | Univ. of Michigan Research Reactor | 50-2 | 12 |
| Unit 1 | 40.000 | 164 | Univ. of Missouri Research Reactor | 50-186 | 25 |
| St. Lucie Plant, Unit 1 | 50-335 | 164 | Univ. of Oklahoma Research Reactor | 50-112 | 19 |
| St. Lucie Plant, Unit 2 | 50-389 | 215 | Vermont Yankee Nuclear Power Station | 50-271 | 72 |
| Virgil C. Summer Nuclear Station, Unit 1 | 50-395 | 220 | Virginia Polytechnic Institute Training Reactor | 50-124 | 19 |
| Summit Nuclear Power Station, Unit 1 | 50-450 | 256 | Alvin W. Vogtle Nuclear Plant, Unit 1 | 50-424 | 241 |
| Summit Nuclear Power Station, Unit 2 | 50-451 | 256 | Alvin W. Vogtle Nuclear Plant, Unit 2 | 50-425 | 242 |
| Sundesert, Unit 1 | 50-582 | 297 | | 50-27 | 16 |
| Sundesert, Unit 2 | 50-583 | 297 | Washington State Univ, Research Reactor | , | |
| Surry Power Station, Unit 1 | 50-280 | 84 | Waterford Generating Station, Unit 3 | 50-382 | 208 |
| Surry Power Station, Unit 2 | 50-281 | 86 | Watts Bar Nuclear Plant, Unit 1 | 50-390 | 217 |

| Name | Docket | Page | Name | Docket | Page |
|---------------------------------|------------|------|---|------------|------|
| Watts Bar Nuclear Plant, Unit 2 | 50-391 | 219 | WPPSS Nuclear Project, Unit 5 | STN-50-509 | 278 |
| West Valley Reprocessing Plant | 50-201 | 25 | Yankee-Rowe Nuclear Power Station | 50-29 | 16 |
| Wolf Creek Generating Station | STN-50-482 | 267 | Yellow Creek Nuclear Plant, Unit 1 | STN-50-566 | 295 |
| WPPSS Nuclear Project, Unit 1 | 50-460 | 261 | Yellow Creek Nuclear Plant, Unit 2 | STN-50-567 | 296 |
| WPPSS Nuclear Project, Unit 2 | 50-397 | 224 | William H. Zimmer Nuclear Station, Unit 1 | 50-358 | 184 |
| WPPSS Nuclear Project, Unit 3 | STN-50-508 | 277 | Zion Nuclear Power Station, Unit 1 | 50-295 | 104 |
| WPPSS Nuclear Project, Unit 4 | 50-513 | 279 | Zion Nuclear Power Station, Unit 2 | 50-304 | 113 |

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-010 BEATTY, NV

- BD12030001 Responds to FGIA request for documents re sites used for dumping radwaste in Pacific Ocean. Forwards documents listed in Apps A.B.C & D. Info partially withheld: home addresses & talephone numbers (ref FGIA Exemption 6). FELTON.J.M. Division of Rules and Records. 80/10/15. 34pp. 07150:028.
- --8012030035 Requests Commission interpretation re proposed disposal method involving direct radwaste disposal into Pacific Ocean utilizing sea water dilution. CORBETT.J.B. US Ecology, Inc. (Formerly Nuclear Engineering) . 60/03/03. 2pp.
- --8012030039 Forwards Log Trip 50 for Harbor Industries.FR notices re proposed license amends & issuance of amends encl. CURBETT, J. S. US Ecology, Inc. (Formerly Nuclear Engineering) . 61/07/10. Spp.
- B012030040 Mat1/Byproduct License 04-03766-01 for Nuclear Engineering Co.Inc is amended per 601123.1223 & 610106 applications. Amend 12 revises Conditions 3 & 10 to authorize receipts disposel & packaging of source & ENM by listed personnel. LOHENSTEIN.R. Atomic Energy Commission. 61/06/01. App.
- -8012030042 Notifies of radwaste sea disposal on 600317 in Pacific Ocean. Disposal will consist of 400 drums containing 103.8837 Ci byproduct math Future disposals will be done at weekly intervals until 5.000 packages have been disposed of. CORBETTIJS. UB Ecology, Inc. (Formerly Nuclear Engineering) 60/02/26. 2pp.
- -B012030043 Reply memorandum re Nuclear Engineering Co. Inc & State of CA responses to AEC. AEC has no objection to incorporating two mods into proposed order. Certificate of Svc encl. LOMENSTEIN.R.: KESTENSAUM.L. Atomic Energy Commission. 61/02/10. 7pp.
- -9012030049 Responds to 600303 ltr re direct disposal of low level liquid waste into Pacific Ocean. Disposal of low level waste directly into ocean requires specific Commission approval. MASUN, J. R. Atomic Energy Commission. 60/05/03. ip.
- --8012030052 Requests exemption from labeling requirements for containers in which licensed matts are stored or transported. All containers will be strong & tight & exterior surfaces free of contamination.

 GCRDETT.J.B. UB Ecology, Inc. (Formerly Nuclear Engineering)

 59/04/20. 7pp.
- -8012030054 Notifies of plans to make sea disposal of packaged radwaste on 610628. Written notice of 20 days will be tendered in future & addl info will be provided as required in Condition 10 of license as amended.FR notice encl. CORBETT.J. S. UB Ecology: Inc. (Formerly Nuclear Engineering) 61/06/20. 2pp.
- ---B012030056 Notice of proposed amend of Matl/Byproduct License O4-03766-01, authorizing receipt, possession & storage of radwaste in Beatty, NV. LOKENSTEIN.R. Atomic Energy Commission. 62/01/25. 5pp.

- --BOIZO30058 Provides detail re 600321 sea disposal of packaged radwaste. Towing fins will be installed on barge for batter control of towing vessel. Next disposals will be made at weekly intervals beginning 600411.

 CORBETT.J.S. US Ecology, Inc. (Formerly Nuclear Engineering), 60/03/28, 1p.
- --8012030074 Petition to intervene re Nuclear Engineering Co, Inc 80093k application for renewal of Mati/Byproduct License 04-03766-01. Commission should amend license to prohibit leading of waste at present site.

 MOBK. 8., HARRIS. A. W. California: State of. 60/12/31. 4pp.
- --8012030091 Objections to Nuclear Engineering Co.Inc proposed amends & add1 findings of fact & conclusions of law, Certificate of Svc encl.
 MOSK, S., MARRIS, A. M. California, State of. 61/02/08, App.
- --8012030097 Forwards objections to proposed amends & addl findings of fact & conclusions of law.W/o encl.
 HARRIS.A.W California, State of. 61/02/09. ip.
- --8012030104 Forwards Nuclear Engineering Co.Inc answer'to Btate of CA objections to AEC proposed findings. CAREY.K.B. Leyman.E.S. 61/02/06. 1p.
- --8012030108 Application for amend of Matl/Byproduct License 04-03766-01, authorizing performance of experimental wasts processing w/listed limitations.

 CORBETT.J.B. US Ecology, Inc. (Formerly Nuclear Engineering)

 59/03/31. 2pp.
- --8012030118 Forwards intervenor State of CA proposed findings of fact to objections to AEC proposed findings of fact.
 HARRIS,A.W. California, State of. 61/01/26. ip.
- --8012030121 Submits add1 info in response to AEC 610425 ltr re renewal application for License 04-03764-01. Hin reinforcement of concrete blocks will consist of 4-inch by 4-inch by 10-gauge wire mesh.

 CORBETT, J. S. US Ecology, Inc. (Formerly Nuclear Engineering)

 . 61/04/28. 2pp.
- --8012030127 Proposed findings of fact & objections to AEC proposed findings of fact. If licenses continues present disposal practices, Gity of Antioch. CA may suffer damage to water supply. Certificate of Byc encl.
 MOBK.S., HARRIS, A. W. California, State of. 61/01/27. 17pp.
- --8012030129 Informs Dept of Industrial Relations, that Nuclear Engineering Co. Inc will dispose of packaged low level waste by buriel in Pacific Ocean beginning 591203. PRICE, H. L. Atomic Energy Committeion. 39711/25. 1p.
- ---B012030133 Confirms request for info during 610420 discussions, Requests specific info re min criteria of reinforcing concrete blacks, including type, size & specing of reinforcing metal & types of containers to be used for packaging metals. HABON, J. R. Atomic Energy Commission. 61/04/25. 2pp.

--901203D134 Proposed amends & add1 findings of fact & conclusions of law. Eristing Ficenee & pending renewal application do not specify loading site. Licentee intends to use Fulton Bhipyard. Fulton Shipyard log encl.
CAREY.K.S. US Ecology, Inc. (Formerly Nuclear Engineering)
CAREY.K.S. Laymen.E.S.

2

- --8012030137 Informs Dept of Fish & Oame that Nuclear Engineering Co. Inc will dispose of packaged low level waste by burial in Pacific Ocean beginning 591203. PRICE: M.L. Atomic Energy Commission. 59/11/25. 1p.
- ~-B012030144 Informs Dept of Public Health that Nuclear Engineering Co. Inc. will dispose of packaged low level waste by burial in Pacific Ocean beginning 591203. PRICE, H. L. Atomic Energy Commission. 59/11/25. 1p.
- --8012030152 Informs Dept of Industrial Relations that Nuclear Engineering Co.Inc will dispose of packaged low level waste by burial in Pacific Ocean beginning 591203. PRICE.H.L. Atomic Energy Commission. 59/11/25. 1p.
- --8012030153 Proposed findings of fact & conclusions of law re Nuclear Engineering Co.Inc application for license renewal AEC has no objection to continuing operation under existing license. W/supporting documentation.

 LOWENBTEIN.R., KESTENBAUM.L. Atomic Energy Commission. 60/12/30. 3400.
- --B012030159 Bubmits additinfo in response to AEC 610302 request re application for renewal of license. All Pu wastes, regardless of quantity, will be packaged in ICC Spec IR container. W/related documents.

 CORBETT. J. S. US Ecology, Inc. (Formerly Nuclear Engineering)

 61/03/31. 9pp.
- --B012030161 Informs Coordinator of Atomic Energy Development & Radiation Protection that Nuclear Engineering Co. Inc will dispose of packaged low level waste by burial in Pacific Ocean beginning 591203.
 PRICE, H. L. Atomic Energy Commission. 59/11/25. 1p.
- ---8012030165 Forwards Log Trips 48 & 49 for Harbor Industries 1 & corrected Log Trip 37.
 CORBETT.J.B. UB Ecology, Inc. (Formerly Nuclear Engineering)
 . 61/03/09. 4pp.
- --8012030172 Responds to 611213 ltr re sea disposal of packaged radwaste on 611207. Notification of radwaste disposal was inappropriate. Notification of sea disposal operations should be made in accordance w/Condition 10 of license. MASON, J. R. Atomic Energy Commission. 61/12/26. 1p.
- --B012030183 Application for amend of Matl/Byproduct License 04-03766-01, authorizing sea disposal of packaged radwaste in Facific Ocean within 5-mile radius of designated latitude & longitude.

 CORBETT, J. B. UB Ecology, Inc. (Formerly Nuclear Engineering)

 59/11/19. 2pp.
- --8012030186 Requests abeyance of AEC 611206 request for award of License 03-03766-01 to provide for sea disposal of cylinders containing Sr-90 contaminated earth. CORSETT.U.B. US Ecology, Inc. (Formerly Nuclear Engineering) . 61/12/14. 1p.
- --B0120301B9 Application for amend of Matl/Byproduct License 04-03766-01; to allow for 1 yr for packaging & solidification of radwaste for sea disposal Excerpt from 591183 ltr & FR notice encl. CORBETT, J.S. US Ecology, Inc. (Formerly Nuclear Engineering) 59/11/13. 4pp.
- --8012030192 Notice of issuance of matl/bygroduct license to Nuclear Engineering Co.Inc to provide radueste disposal syc. PRICE.H.L. Atomic Energy Commission, 58/10/28, 2pp.
- --B012030197 Matl/Buproduct License 04-03766-01 for Nuclear Engineering Co. Inc.authorizing receipt.possession.packaging & disposal of B00 Ci byproduct matl. 2:000 lb source & 4 g BNM. MABON, U.R. Atomic Energy Commitsion. 58/10/22. 6pp.
- ---B012030202 Notifies of 611207 sea disposal of packaged radwaste.

 Master log & sea disposal rept entl.

 CORBETT.J.S. US Ecology, Inc. (Formerly Nuclear Engineering)

 61/12/13, 3pp.

- --8012030210 Requests add1 info to suppl 601123 ltr & 600803 application for license renewal. Includes description of specific radiation safety procedures to be followed in handling waste containing Pu & U-233 up to 1 gram.

 MASON, J. R. Atomic Energy Commission. 61/03/02. 3pp.
- --8012030213 Forwards Hatl/Byproduct License 04-03766-01, authorizing disposal of byproduct, source & SNM in Atlantic & Pacific Oceans, M/o encl.
 MASUN, J.R. Atomic Energy Commission. 58/10/22. 1p.
- --8012030215 Bubmits add1 info in response to AEC 601110 ltr & in conjunction w/600803 application for amend of License O4-03766-01. Agrees w/AEC suggestion that possesion limit for byproduct math be limited to 1.000 Ci at each facility. CORBETT.J.S. US Ecology. Inc. (Formerly Nuclear Engineering) 60/11/23. 4pp.
- --8012030223 Katl/Byproduct License 04-02334-02 for Nuclear Engineering Co.Inc is amended per 580708 application. Amend 2 changes address & adds Condition 20 re byproduct matl transport. MASON.J.R. Atomic Energy Commission. 58/07/15. ip.
- --8012030231 Requests that 580703 applications be amended to include 2 g SNM. All Po will be prepariaged by customer & unopened by licensee.

 LANJJ.E. US Ecology, Inc. (Formerly Nuclear Engineering) 58/07/08. ip.
- --8012030234 Responds to 611106 request for amend of License 04-03766-01 to provide for sea disposal of cylinders containing Sr-70 contaminated earth. Requests assurance that cylinders will not leak during handling loading & disposal operations.

 MASON, J. R. Atomic Energy Commission. 61/12/06. ipp.
- --8012030245 Responds to AEC 601024 request re radwaste packaging methods being utilized.Lists radwaste packaging procedures. CORBETI.J. S. US Ecology, Inc. (Formerly Nuclear Engineering) 60/10/29. 2pp.
- --8012030257 Order & notice of hearing re application for renewal of License 04-03756-01. Public hearing will be held on 601116 in Ban Francisco.cA re pageible relocation of loading site. PRICE,H.L. Atomic Energy Commission. 60/10/19. 4pp.
- --801203023B Informs Dept of Public Health that mati/byproduct license has not been issued to Nuclear Engineering Co. Any license issued will omit specific location requirements & will specify win depth of water.

 PRICE, H. L. Atomic Energy Commission. 58/10/01. ip.
- --8012030281 Forwards State of NY, Bureau of Explosives Permit 1038 w/Stetches A.B.C & D for containers authorized for transport & 600919 1tr to Bureau of Explosives requesting issuance of permit Sketches not encl.
 CQRETT, J.S. US Ecology, Inc. (Formerly Nuclear Engineering) 60/09/30. 4pp.
- --B0120302B9 Natice of application by Nuclear Engineering Co. Inc. to provide radwaste disposal svc. Application specifies max possession limit of 800 g U-235.
 PRICE.M.L. Atomic Energy Commission. 58/07/14. 1p.
- --B012030291 Requests AEC approval to package tritium gas in concrete within 55-gallon steel drum for sea disposal. Tritium activity per container varies from max of 5 Ci down to 3.0 mGi.
 CGRBETT, J. S. US Ecology, Inc. (Formerly Nuclear Engineering) 60/12/23. 1p.
- --B012030303 Notice of proposed issuance of matl/byproduct license to Nuclear Engineering Co to provide radwaste disposal svc. Proposed license encl. PRICE, E.R. Atomic Energy Commission, 58/08/29. 7pp.
- --8012030310 Advises that date of 611206 for see disposal of radwaste is satisfactory.
 CORBETT, J. S. UB Ecology, Inc. (Formerly Nuclear Engineering)
 61/11/30. 1p.
- --8012030311 Supports Nuclear Engineering Co 580703 application for matl/ byproduct license to receive.possess.package & dispose of byproduct.source & SNI wastes in Atlantic & Pacific Oceans, PRICE.E.R. Atomic Energy Commission 58/08/29. 3pp.
- ---B012030313 Requests amend to License 04-03766-01 to prohibit redwaste loading at Fultons Shipward & designate sits downstream from Antioch Shipward inlet to assure safety of water supply in event of accident.

 PRICE, H. L. Atomic Energy Commission. 60/09/06. 2pp.

- -8012030319 Intermediate decision re renewal of License 04-03766-01.
 Recommends license renewal subj to terms & conditions listed & approved by Commission.
 JENSCH.S.W. Atomic Energy Commission 61/03/07. 24pp.
- --B012030322 Confirms 611127 telcon re 611206 proposed radwaste sea disposal. CORBETT, J. S. US Ecology, Inc. (Formerly Nuclear Engineering) . 61/11/30. 1p.
- --8012030332 Notice of receipt of Nuclear Engineering Co application for amend of Matl/Byproduct License 04-03766-01, authorizing receipt, processing, storage & burial of radioactive matl at site in Amargosa Desert.

 LOWENSTEIN.R. Atomic Energy Commission 61/11/13. 2pp.
- --8012030348 Application for amend to License 04-0376-01 to provide for sea disposal of 33 16-gauge steel cylinders containing 188 gallons each Sr-90 contaminated earth AEC draft memorandum encl.

 CORBETT, J. S. US Ecology, Inc. (Formerly Nuclear Engineering), 61/11/06. 9pp.
- -8012030363 Mat1/Byproduct License 04-02314-04 for Nuclear Engineering Co.Inc.authorizing collection.packaging.storage & disposal of 100 Ci byproduct & source matl & 2 g SNM in any form of uaste matl.

 * Atomic Energy Commission. 57/03/29. 2pp.
- --B012030366 Discusses Nuclear Engineering Co.Inc radwaste disposal business in CA.Lists major points at issue.Provides objections to continuation of disposal activities w/o mod. TD Hufft 600804 ltr to A Grandon encl. ORENDON.A. California. State of. 60/08/17. 8pp.
- --8012030370 Forwards notice of proposed issuance of byproduct, source & SNM matl license to Nuclear Engineering Co.Inc. W/o encl. PRICE, E.R. Atomic Energy Commission. 58/09/08. 1p.
- --8012030372 Forwards application for matl/byproduct license. CORRECT, J. B. UB Ecology, Inc. (Formerly Nuclear Engineering) . 61/10/06. 1p.
- --8012030375 Requests expeditious AEC action re 600526 request for authorization of DB Rogers.KC Webber & WH Cromwell to pick up.receive & sea dispose radwaste. 8vcs of these qualified employaes are needed urgently.
 CORBETT.J.S. UB Ecology, Inc. (Formerly Nuclear Engineering). 60/09/29.
- --8012030376 Application for renewal of Matl/Byproduct License 04-03766-01; authorizing possession &/or use of 2,000 Ci byproduct matl, 15,000 lb source matl & 450 g BNN for disposal. Info partially withheld (ref FOIA Exemption 6). CORRETT.J.S. US Ecology, Inc. (Formerly Nuclear Engineering). 60/08/03. 29pp.
- --8012030378 Forwards notice of proposed issuance of byproduct, source & SNM matl license to Nuclear Engineering Co. Inc. W/o encl. PRICE, E. R. Atomic Energy Commission, 58/09/08, 1p,
- --8012030383 Forwards notice of proposed issuance of byproduct, source & SNM matl license. W/o encl. PRICE, E. R. Atomic Energy Commission. 59/09/29. 1p.
- --8012030420 Application for matl/byproduct license authorizing use of unlimited amounts of any byproduct matl between Atomic Numbers 1-91 & transurante elements w/Atomic Numbers 93 & 95-99. Info partially withheld (ref FDIA Exemption 6). CORBETT.J.E. US Ecology, Inc. (Formerly Nuclear Engineering). 61/10/06. 41pp.
- --B012030437 Lists Lawrence Radiation Lab drums which do not contain 1 mCi mixed fission products Provides info re request for amend to dispose of GE waste liners at sea Draft Matl/Buproduct license 04-03766-01 encl.
 HEWITT.M.L. Parr-Richmond Terminal Co. 61/10/02, 19pp.
- --B012030449 Requests that Licenses 04-03766-01 & 04-03766-03 be amended to add MD Johnson as authorized user of byproduct matl. License 04-03766-01 should be amended to provide for ocean disposal of 450 g waste.

 CORBETT, J. B. UB Ecology, Inc. (Formerly Nuclear Engineering)

 . 39/09/04. 2pp.
- --8012030478 Forwards Amend 10 to License 04-03766-01; revising Condition 3 to add names of persons who supervise licensed program 4 designating specific disposal sites in Condition 8, 4/0 encl.

 MABON, J. R. Atomic Energy Commission. 60/06/02, 1p.

- --8012030486 Advises of issuance of Amend 10 to License 04-03764-01 held by Nuclear Engineering Co.Inc.Amend 10 revises Condition 3 to add names of persons who supervise licensed program & designates specific disposal sites in Condition 8. PRICE.H.L. Atomic Energy Commission. 60/06/02. 1p.
- --8012030488 Forwards Fulton Shippard log for See Disposals 13-18 made from barge Harbor Industries 1. CORDETT, J. 8. US Ecology, Inc. (Formarly Nuclear Engineering) . 60/08/02. Spp.
- --8012030475 Advises of issuance of Amend 10 to License 04-03764-01. revising Condition 3 to add names of parsons who supervise licensed program & designating specific disposal sites in Condition 8. Fulton Shipyard log encl. PRICE.H.L. Atomic Energy Commission, 60/06/06. 14pp.
- ---8012030303 Hat1/Buproduct License 04-02766-01 is amended per 591119, 1213,600201 & 0427 applications. Amend 10 revises Condition 3 to add names of persons who supervise licensed program & designates specific disposal a sites in Condition 8.

 MASON, J. R. Atomic Energy Commission 60/06/02, 2pp.
- --8012030508 Responds to 610816 request for add1 info re extended storage of waste in fiberboard & wooden containers. Company 4-yr safety record & safety precautions, justify current license conditions.

 CORBETT. J. 8. UB Ecology, Inc. (Formerly Nuclear Engineering), 61/08/24. 1p.
- --8012030510 Application for amend of Matl/Byproduct License 04-03766-01; adding names of authorized individuals for pickup %/or receipt % sea disposal of byproduct-source & BNM. GCRBETT.J.B. US Ecology, Inc. (Formerly Nuclear Engineering) . 60/05/26. 2pp.
- --8012030318 Matl/Buproduct License 04-03766-01 for Nuclear Engineering Cq. Inc is amended in entirety per 600803 application.

 Amend 14 authorizes receipt, processing, packaging, storage & disposal of buproduct, source & RMM waste at sea.

 LOHENSTEIN,R. Atomic Energy Commission. 62/02/23. 17pp.
- --8012030561 Application for renewal of Mati/Byproduct License 04-02314-01 authorizing JE Law to use %/or supervise use of 400 Gi byproduct & source mati & 2 g SNM. LAH.J.E. US Ecology, Inc. (Formarly Nuclear Engineering) . 58/02/17. 7pp.
- --8012030401 Responds to 580923 ltr forwarding Borough of McKees Rocks, PA. Resolution 900 re storage of radwasts by Nuclear Engineering Co. H/o notice of proposed issuence of license & mano describing safety factors of disposal.
 PRICE, H. L. Atomic Energy Commission. 58/10/15, 2pp.
- ---8012030833 Informs AEC that recent license for Nuclear Engineering Co provides that licensee shall dispose of waste in prescribed area in Pacific Ocean, thus nullifying voluntary agreement between CA agencies & firms.
- DOCKET 27-039 SHEFFIELD, IL., NUCLEAR ENGINEERING CO.
- 8012030037 Forwards responses to KS Carey & Conrad Kayne & Vandeberg. W/o encis.
 CUNNINGHAM R.E. Atomic Energy Commission, 64/10/23. 1p.
- 8012030001 Responds to FOIA request for documents re sites used for dumping radwaste in Pacific Orean. Forwards documents listed in Apps A.B.C & D. Info partially withheld; home addresses & talephone numbers (ref FOIA Exemption 6). FELTON.J.M. Division of Rules and Records. 80/10/13, 34pp. 07150:028.
- --8012030002 Submits responses to AEC 641118 questions re geology & hydrology re 640818 application for Amend 2 to license. HELGEBON, O. L. California Nuclear, Inc., 65/02/03, 4pp.
- --8012030003 Discusses 641012 request for amend of License 13-10042-01.
 Safety analysis should be revised to eliminate any
 assumptions as to manner in which matl will be contained in
 package. Review will continue upon receipt of comments.
 CUNNINGHAM.R.E. Atomic Energy Commission. 64/12/09. 1p.
- --B017030005 Lists questions for response re geology & hydrology info in 640818 application for burial of redwastes. Review will continue upon receipt of info.

 CUNNINGHAM.R.E. Atomic Energy Commission. 64/11/18. 2pp.

- --8012030007 Forwards Conrad. Kayne & Vandeberg 641020 ltr & NRC response. W/o encls. CUMNINONAM.R.E. Atomic Energy Commission. 64/10/28. 1p.
- --B012030009 Forwards to Dept of Health, notice of issuance of Amend 1 to License 13-10042-01, M/o encl. JOHNSON, L. Atomic Energy Commission, 64/10/26, 1p.
- --B012030011 Forwards to Health Dept.notice of issuance of Amend 1 to License 13-10042-01. W/o encl. JOHNBON, L. Atomic Energy Commission. 64/10/26. ip.
- --8012030014 Forwards to Dept of Commerce & Economic Development, notice of Amend 1 to License 13-10042-01.4/o encl.

 JOHNSON, L. Atomic Energy Commission. 64/10/26. 1p.
- --8012030016 Forwards Amend 1 to License 13-10042-01 & notice of issuance of license. W/o encis.

 JOHNSON: L. Atomic Energy Commission. 64/10/26. 1p.
- --B012030019 Forwards notice of issuance of Amend 1 to License 13-10042-01.W/o encl. JOHNBON.L. Atomic Energy Commission. 64/10/26. 1p.
- --8012030024 Forwards notice of issuance of Amend 1 to License 13-10042-01. W/o encl. JOHNSDN.L. Atomic Energy Commission. 64/10/26. 1p.
- --8012030028 Notice of issuance of Amend 1 to License 13-10042-01. JOHNBON, L. Atomic Energy Commission. 64/10/26. ip.
- --8012030048 Forwards Conrad, Kayne & Vandeberg telegram re application for license amend.
 CUNNINGHAM.R.E. Atomic Energy Commission. 64/10/22. 1p.
- --B012030077 Confirms 641009 telegrams & telcon re amend to License i3-10042-01 to increase amount of GNM contained in any package of radvaste. Any single package containing SNM will not contain more than 100 g U-235 or 60 g U-233 or Pu-239. HELCEBON, O. L. California Nuclear, Inc. 64/10/12, 2pp.
- --B012030083 Discusses CA Nuclear. Inc application for license to operate storage & disposal facility. License should not be issued fue to infringement on existing Patent 3.012.393. CAREY, K. S. Layman, E. S. 64/10/06. 19.
- --B012030090 Notice of issuance of proposed amend to License 13-10042-01, authorizing receipt processing, repackaging & storage of radwasts at Benton County, MA & increase in max amount of radwasts. Excerpt of FR notice & draft license amend encl. JOHNSON, L. Atomic Energy Commission. 64/10/05. 13pp.
- --8012030098 Forwards notice of proposed issuance of amend to License i3-10042-01 & Div of Maths Licensing memo summarizing considerations evaluated prior to issuance of notice of proposed licensing action. W/o encl.

 JOHNBON, L. Atomic Energy Commission. 64/10/05. 1p.
- --B012030113 Forwards State of WA.Dept of Commerce & Economic Development ltr re Hanford Burfal site.W/o encl. CURNINGHAM.R.E. Atomic Energy Commission. 64/09/24. 1p.
- --8012030120 Provides changes to amends & responses to AEC 640831 questions re License 13-10042-01. H/supporting documentation. HCLAIN.S. California Nuclear, Inc. 64/09/18. 18pp.
- --B012030130 Notifies that Dept of Commerce & Economic Development accepts responsibility of State of MA for maintymonitoring & safety of site & wastes stored at site during tenure of Btate leass. Perpetual maint fund underway.

 ROBE, R. E. Hashington, State of. 64/09/17. 2pp.
- --B012030136 Discusses CA Nuclear, Inc application to receive, process, store & bury radwaste in Benton County. Representatives will attend AEC 660915 meeting in Richland, NA re application, CUMMINOHAM, R. E. Atomic Energy Commission. 64/09/02. 1p.
- --8012030162 Forwards CA Nuclear, Inc application requesting authorization to bury radwattes at proposed site near Hanford, MA. AEC will meet w/state officials on 640915 to discuss application. W/o encl.
 NUSBBAUMER, D. A. Atomic Energy Commission. 64/09/02. ip.

- --8012030167 Invites Dept of Health to participate in AEC 640915 meeting W/CA Nuclear, Int to discuss application to receive, process, stors & bury radwaste near Hanford, WA. W/o application. GUNNINGHAM, R. E. Atomic Energy Commission. 64/09/02. 1p.
- --8012030176 Confirms 640915 meeting w/Dept of Commerce & Economic Development in Richland, WA re CA Nuclear, Inc. Forwards ltrs to Governor Rosellini, Dept of Health & Benton County Commissioners & license emend application, W/o encl. CUNNINGHAM, R. E. Atomic Energy Commission. 64/09/02, ip.
- ---8012030181 Notice of receipt of application for amend of License 13-10042-01, proposing receipt, processing, storage & burial of radwaste in Benton County, NA. NUSSBAUMER, D. Atomic Energy Commission. 64/08/31. ip.
- --8012030194 Clarifies items in 640818 application for two amends to License 13-10042-01 re collectioon & transportation of low level radwasts. Excerpt from application for matl/byproduct license encl.
 MCLAIN.S. California Nuclear. Inc. 64/08/28. 4pp.
- --8012030224 Notice of issuancs & availability of Amend 2 to License 13-10042-01. MCBRIDE: J. A. Atomic Energy Commission. 65/09/10. 1p.
- --BD12030237 Forwards to Dept of Health Amend 2 to License 13-10042-01 & notice of issuance of amend W/o encis.

 MCBRIDE, J. A. Atomic Energy Commission. 65/09/10. ip.
- --B012030251 Forwards Amend 2 to License 13-10042-01 & notice of issuance of amend. M/o encis.
 MCBRIDE, J. A. Atomic Energy Commission. 65/09/10. 1p.
- --B012030265 Forwards to Health Dept, Amend 2 to License 13-10042-01 & notice of issuance of amend W/o encis.

 MCBRIDE, J. A. Atomic Energy Commission. 65/09/10. ip.
- --B012030274 Forwards Amend 2 to License 13-10042-01 & notice of issuance of amend. W/o encis.
 MCBRIDE, J. A. Atomic Energy Commission. 65/09/10. 1p.
- --B012030286 Forwards Amend 2 to License 13-10042-01 & notice of issuance of amend. W/o encis.
 MCBRIDE, J. A. Atomic Energy Commission. 65/09/10. 1p.
- --8012030301 Forwards Amend 2 to License 13-10042-01 & notice of issuance of amend. M/o encls.
 MCDRIDE, J. A. Atomic Energy Commission. 65/09/10. 1p.
- ---B01203036i Forwards to Dept of Health, notice of proposed amend to License 13-10042-0i, authorizing burial of radwasts in Benton County, WA, memo re issuance of amend & proposed amend, W/o encls.
 HOBITOS, J. A. Atomic Energy Commission, 65/08/04, 1p.
- --B0120303B1 Forwards to Dept of Commerce & Economic Development, notice of proposed amend to License 13-10042-01, authorizing burial of radwaste in Benton County, WAL memo re issuance of of amend & proposed amend. W/o encls.

 MCBRIDE, J. A. Atomic Energy Commission. 45/08/04. 1p.
- --8012030394 Forwards to Health Dept.notice of proposed amend to License 13-10042-01, authorizing burial of radwaste in Benton County. Whimeon re issuance of amend & proposed amend. W/o encls. MCBRIDE, J. A. Atomic Energy Commission. 65/08/04. ip.
- --B012030414 Forwards notice of proposed amend to License 13-10042-01, authorizing burial of radwaste in Benton County, WA, memo re issuance of amend & proposed amend. W/o encls.

 MCBRIDE, J. A. Atomic Energy Commission. 65/08/04. ip.
- --B01203042B Forwards notice of proposed amend to License 13-10042-01, authorizing burial of radwaste in Benton, County, WA, memo re issuance of amend & proposed amend, M/o encls.

 KCBRIDE, J. A. Atomic Energy Commission. 65/08/04. 1p.
- --B012030439 Forwards notice of proposed amend to License 13-10042-01, authorizing buriel of radwaste in Benton County WA, memo re issuance of amend & proposed amend. W/o amend. MCBRIDE, J.A. Atomic Energy Commission. 65/08/04. 1p.
- --B01203045A Notice of proposed issuance of Amend 2 to License 13-10042-01. Proposed license amend, draft memo & excerpt from JE Bowyer 650720 ltr encl.

 4 Atomic Energy Commission. 65/08/04. 10pp.

- --8012030689 Responds to NRC 670201 request for info re 660816 application for mati/byproduct license re site for burial of low level radwasts. Info partially withheld (ref FOIA Exemption 6). Related info enci.

 HCLAIN.8. California Nuclear. Inc. 67/02/10. 15pp.
- 8012040159 Notification of contract execution, Mod 5 to "EIS on Sheffield Low Level Waste Disposal Site." Contractor: NUS Corp. HAIRSTON, C., SMITH, P. A. Technical Assistance Contracts Branch. FIN B-6382-9, 80/11/07. ip. 07158:074.
- 8012030903 Mod 5, deleting & adding tasks to "EIS on Sheffield Low Level Haste Disposal Site Mar 1979."

 NUS Corp. DOUGHERTY, D. J. Technical Assistance Contracts Branch, 80/11/12. 4pp. 07149:061,
- B012020079 Ack receipt of 801103.0509 & 0318 ltrs informing NRC of steps taken to correct violations noted in Waste Packaging Insp Rept 15000039779-08E. DAVIB-A.S. Region 3, Chicago, Fuel Facility & Materials Safety Branch. B0/11/14. 1p. 07147:248.
- --8012020110 Responds to NRC 800222 ltr re violations noted in Waste Packaging Insp Rept 15000039/79-08E. Corrective actions; shipping casks in use & all casks leaving station labeled "Radioactive LSA."

 ABEL.J.S. Commonwealth Edison Co. 80/11/03. 2pp. 07147:269.
- B012180393 Trip rept of 801014-15 visit to low level waste disposal facility re general observation of surface conditions & level of compliance to NRC request for improvements. One oversized drawing encl.

 8HAFFNER, J. A., SIEFKEN, D. L. Low Level Waste Licensing Branch, 80/11/28. App. 07272:328.
- 8012120542 Answer to NRC & State of IL motions for order compelling response to certain interrogatories & requests for documents. Urges denial of motions & refocusing on designated issues. W/Certificate of Svc. Related correspondence. CONNER.T.B. RADER.R.M. US Ecology, Inc. (Formerly Nuclear Engineering). CONNER.T.B. Conner. Hoore & Corber. 80/12/01. 27pp. 07237:071.
- B012220300 Request for order compelling state of IL to answer Interrogatories 1,6,7,9 % 10 fully & completely. Responses dtd B01031 unclear & unresponsive. Certificate of Bvc encl. CANNON,T.M. American Nuclear Society. CANNON,J.M. Hid-America Legal Foundation. 80/12/02. 6pp. 07307:301.
- 8012230006 Request for order compelling NRC to answer ANB, Chicago Bection, Interrogatories 4,7,9,10 & 15. Certificate of Svc encl.
 CANNON, J. M. Mid-America Legal Foundation. 80/12/02. Spp. 07311:155.
- B012300046 Response in opposition to Nuclear Engineering Co.Inc (NECO) B01115 motion to compel NRC to answer NECO requests for admissions & interragatories & to compel production of documents. Certificate of Byc enci.
 MCGURREN.H.J. Hearing Branch 1. 80/12/05. 14pp. 07856:133.
- B012300254 Response to ANS B01202 motion for order compelling NRC to answer interrogatories. Answers Interrogatories 4,7,10 & 15. ANS motion untimely, Supportive documentation, affidavits & Certificate of Svc encl.

 MCGURREN.H.J. Hearing Branch 1. B0/12/22, 20pp. 07358;131.
- DOCKET 27-047 BARNWELL, SC., CHEM-NUCLEAR SYSTEMS
- B01219059B Forwards Waste Packaging Insp Rept 15000039/80-03 on 800227-29. No noncompliance noted. STOHR.J.P. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 80/03/20. 2pp. 07288;235.
- --8012190606 Waste Fackaging Insp Rept 13000039/80-03 on 800227-29. No noncompliance noted Major areas inspected: shipping paper. DOT placards: radiation levels: removeable contamination; DOT marking & labeling packages.
 PERY, N. W., FOTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/03/17, 6pp. 07268:237.
- B012190170 Forwards Waste Packaging Insp Rept 15000039/80-05 on 800319. No noncompliance noted.
 STOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch, B0/04/14. 2pp. 07282:054.

- --B012190177 Waste Packaging Insp Rept 15000039/B0-05 on 800319.No noncompliance noted. Major areas inspected: shipping paper, DOT placards, radiation levels, removable contamination & DOT marking & labeling of packages.
 WOODRUFFIR.L., POTTER.J.P. Region 2, Atlanta, Fuel Facility & Materials, Safety Branch. 80/04/14, 10pp. 07282:056.
- 80121905BP Forwards Waste Packaging Insp Rept 15000039/80-07 on 800515-16. No noncompliance noted. STOHR, J. P. Region 2, Atlanta, Office of the Director. 80/06/23. 2pp. 0728B: 220
- --B012170575 Waste Packaging Insp Rept 15000039/80-07 on 800515-16. No noncompliance noted. Major areas inspected: shipping paper. DOT placarding, radiation levels, removable contamination, DOT marking & labeling for packages.
 MACARTHUR. T. C., TROUP. G. L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/06/23, App. 07288: 222.
- 8012170228 Forwards Waste Packaging Insp Rept 15000039/80-12 on 800617-20. No noncompliance noted. STOHR: J.P. Region 2, Atlanta. Fuel Facility & Materials Bafety Branch. 80/07/29. 2pp. 07282:116.
- --BD12190235 Waste Packaging Insp Rept 15000039/80-12 on 800617-20. No noncompliance noted. Major areas inspected: shipping paper requirements, BOT placards, radiation levels & removable contamination.

 MACATHUR, T. C., POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. BD/07/28. 7pp. 07282:119.
- B012100256 Ack receipt of B01010 & 16 ltrs informing NRC of steps taken to correct violation noted in IE Haste Packaging Insp Rept 15000039/80-16.
 BMITH.O.H. Region 1. Philadelphia: Fuel Facility & Materials Bafety Branch.
- --B012100264 Responds to NRC 800916 ltr re violation noted in IE Waste Packaging Insp Rept 15000039/80-16. Corrective actions: modifying existing procedures to provide more detail re checkoff of individual requirements.

 BDWCRB, C. E. United Nuclear Corp. 80/10/10. 2pp. 07217:329.
- --B012100273 Forwards response to 801010 itr re violation noted in IE Waste Packaging Insp Rept 15000039/80-16 Corrective action: driver instructed not to remove placards until completion of unloading.
 BOHERS.C.E. United Nuclear Corp. 80/10/16. 2pp. 07217:331.
- --B012100277 Forwards IE Waste Packaging Insp Rept 15000039/80-16 on B00730 & notice of violation.
 SHITH.O.H. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch. B0/09/16, 2pp. 07217:333.
- --BDI2100286 IE Waste Packaging Insp Rept 15000039/B0-16 on B00730.
 Noncompliance noted:no radioactive placard found on tractor
 or trailer.
 HACARTHUR.T.C., POTTER.J.P. Region 1, Philadelphia, Fuel Facility
 & Haterials Safety Branch. B0/08/20. 3pp. 07217:337.
- 8012090149 Ack receipt of B00918 ltr informing NRC of steps taken to correct violations nated in IE Waste Packaging Insp Rept i5000039/80-14.

 SMITH.0.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Brench. B0/10/28. 1p. 07200:101.
- --8012090135 Responds to NRC 800619 ltr re violations noted in IE Waste Packaging Insp Rapt 15000039/80-14. Corrective actions: Standing Order 18, Exhibit 9, 1, will be revised adding insp requirements. Revision issued by 801031. PABTERNAK, R. J. Power Authority of the State of New York. 80/09/18. 3pp. 07200:105.
- --8012090138 Forwards IE Waste Packaging Insp Rept 15000039/80-14 on 800619 & notice of violation. SKITH 9.H. Region 1. Philadelphia, Office of the Director. 80/09/03. 2pp. 07200:105.
- --8012090163 Notice of violation from insp on 800619.

 * Region 1. Philadelphia, Office of the Director. 80/08/07. 2pp. 07200:107.
- --B012090167 IE Waste Packaging Insp Rept 15000039/80-14 on 800619. Noncompliance noted; outside of Model 14-195-4, Number 10 shipping cask not stencilled or otherwise marked to identify as radioactive. MACARTHUR: T. C., POTTER, J. P. Region 2: Atlanta: Fuel Facility & Materials Bafety Branch. 90/08/07. 3pp. 07200:109.

- 8012110762 Trip rept of evictor visit to low level waste disposal facility. Evaluation of renewal application will proceed based on oral responses to NRC requests for data. Licenses must submit formal response by 801030.

 HAMKINS.E.F., PANOBURN.G.C. Low Level Haste Licensing Branch. 80/11/17. Epp. 07227:201.
- 8012190183 Forwards Waste Packaging Insp Rept 15000039/80-19 on B00923-26. No noncompliance noted. STOHR. J. P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. B0/11/12. ip. 07282:070.
- --B012190192 Waste Packaging Insp Rept 15000039/80-19 on 800923-26. No noncompliance noted. Major areas inspected: shipping paper, DOT placards, radiation Levels, removable contamination & DOT marking & labeling for packages.
 MACARTHUR, T. C. . FOTTER, J. F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/11/12, 5pp. 07282:071.
- DOCKET 27-048 RICHLAND, WA. NUCLEAR ENGINEERING CO.
- 8012030900 Responds to vendor 800820 ltr.transmitting preliminary site closure plan. NRC will amend renewed license to cover only closure & decommissioning of SNH disposal areas & to sliminate license conditions re site operations.

 SHITM, R. D. Low Level Haste Licensing Branch. 80/11/14. 2pp. 07147:240.
- B012010016 PNO-V-B0-77: on B01120, at Richland, MA, burial site, Nuclear Engineering Co received shipment from Todd Research Technical Div. Galvaston. TX. containing one leaking drum. Drum measured wino significant activity. Burial permit cancelled. THONAB-R.D. Region 5. San Francisco, Office of the Director. B0/11/20. ip. 04915:001.
- BOI21001BB PNO-V-BO-78: on BOI120: shipment of low level radwasts received at Richland. HA: burial site by Nuclear Engineering Co from Nuclear Metals, Inc. determined to have one leaking drum. State of WA has cancelled licenses burial paratt. THOMASR.D. Region 5. San Francisco, Office of the Director. BO/11/21. ip.
- DOMESTIC LICENSING OF SOURCE MATERIAL
- DOCKET 40-0299 UNION CARBIDE CORP.
- 8031180742 Forwards "Const Rept on Evaporation Ponds East Qas Hills. WY Plant Bite." Rept is condition to granting of agent to Source Hatl License SUA-648. Oversize drawings enci. PARIS, W. C. Union Carbide Corp. 80/10/31. 92pp. 07050:027.
- 8012010531 Trip rept of 800923-24 visit to Casper HY to review well monitoring & reporting requirements, examine mins being pumped dry & examine Federal-American Partners housing & tailings facilities.

 FREEMAN. J. D. Uranium Recovery Licensing Branch. 80/11/10. 2pp. 07098;114.
- 8012240073 Informs that Amend 16 to License BUA-648 is part of renewal review initiated in Sept 1977 & exempt from fee. KOT80H.J.L. Uranium Recovery Licensing Branch. 80/11/12. ip. 07324: 279.
- B0121800001 Responds to NRC 801014 ltr reviewing 800805 submittal, "A-9 Pit Leaky Aquifer Tests for Union Carbide Corp by Hydro-Engineering, " Submittal is satisfactory for determining insignificant mudstone unit leak rate, MONO, T. Union Carbide Corp. 80/11/13. 4pp. 03791:155.
- 8012170251 Responds to 801001 itr re FEB on Qas Hills U Project (NUREQ-0702). Basis for statement on Page 2-30 re background concentration of Ra-226 in soits of Gas Hills in WY is contained in Ref &B of section. 80ARANO.R.A. Uraniue Recovery Licensing Branch. 80/11/19. 4pp. 07268:226.
- DOCKET 40-0672 HUCLEAR HETALS, INC.
- 8012100188 PNO-V-80-78: on B01120, shipment of low level radwaste received at Richland, MA. burial site by Nuclear Engineering Co from Nuclear Metals. Inc. determined to have one leaking drum. State of WA has cancelled licensee burial permit. THOMARR.D. Region 5, San Francisco, Office of the Director. B0/11/21, ip. 07218:279.
- 8012110108 Ack receipt of 801003 ltr informing NRC of steps taken to correct violations noted in IE insp rept & payment of civil penalties.

 THOMPBON.D. Office of Inspection & Enforcement, Office of the Director. 80/12/04. 1p. 07223:155.

- 8012270378 PNO-I-80-173: on B01215, employee reported personal contamination w/green salt in his hair eyes & face. Employee showered & reported to physician. Urinalysis to follow. GLENN. J. CROCKER.H. M. Region i. Philadelphia, Office of the Director. B0/12/15. 2pp. 07339:078.
- DOCKET 40-1162 HESTERN NUCLEAR, INC.
- B012080233 Forwards Split Rock Mill Tailings insp rept for 801006-12 8030EN, O. Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.). 80/10/14. App. 07187:001.
- B012010199 Forwards Bplit Rock mill tailings dam insp rept for B01013-19. No abnormalities observed. Shore line was in excess of 150 ft from crest at all times. Results of weekly monument survey & tabulation of water elevations in piecometers encl. B002BN 9. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). B0/10/23. 4pp. 06916:001.
- 80:2010556 Forwards electrical resistivity survey. Objective 4 clarified. Methodology item 7 changed to reflect final decision emanating from Mestern Muclear Inc. Item 8 reflects total number of readings.
 BOODEN. O. Western Nuclear, Inc. 80/11/05, 4pp. 04916:001.
- BO12080785 Forwards tailings dam insp rept for B01027-1102. BOQDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). BO/11/05. 4pp. 06586:003.
- 8012020125 Fowards draft license conditions & safety evaluation for renewal of license. W/o enci. SCARAWO.R.A. Uranium Recovery Licensing Branch. 80/11/07. 2pp. 07148: 214.
- BO12240112 Requests J Kane assistance in review & comments on draft license conditions, weetly tailings dam monitoring data repts submitted since Jul 1980 & Nelson-Robinette rept. "Hagnetometer & Drilling Program Results."
 SCARANDIR. A. Uranium Recovery Licensing Branch. BO/11/13. 2pp. 07205:163
- 8012310528 Forwards Split Rock Mill Tailings Dam insp rept for B01103-09. B00DEM.O. Hestern Nuclear. Inc. (subs. of Phelps Dodge Corp.). 80/11/14. 4pp. 07365:314.
- 80:2160126 Forwards stipulations containing license conditions for facility as agreed to by NRC.Nestern Nuclear & NY Outdoor Council. LINERAN.J. J. Uranium Recovery Licensing Branch. 80/12/01. ip. 07262:240.
- DOCKEL 40-1341 EDGEMONT URANIUM MINE, TVA & MINEB DEVELOPMENT, INC.
- BO12080653 Informs that Natl Park Svc has reviewed TVA Edgemont U Mill decommissioning plan. Forwards earlier comments. No further comments. STRAIT.R. A. Interior. Dept. of, National Park Service. 80/10/17. 1p. 06586:003.
- --8012080679 Comments on Edgemont, SD U mill decommissioning plan & environ rept re geographical features of area & air quality, STRAIT, R.A. Interior, Dept. of, National Park Service. 79/10/23, 1p. 06586:003.
- 8012080725 Responds to ORNL request for meteorological & air quality info re Edgement Mills decommissioning project.Forwards tables of joint frequency distribution of 10-meter winds. MILLS.L.M. Tennessee Valley Authority, 80/10/22, 5pp. 06586:003.
- 8012010021 Notifies that util may upgrade decommissioning design to practically eliminate site runoff. In event that upgrade proves unfeasible program outlined in environ rept will be followed.

 HILLS L. N. Tennessee Valley Authority. 80/10/27. 1p. 07096:357.
- B0i2i00339 Responds to NRC 800918 request re cleanup action program.
 Submits stipulations for receipt & temporary storage of radioactive matls removed from offsite areas. Requests NRC acceptance of stipulations.
 MILLS, L. H. Tennessee Valley Authority. 80/11/06. 5pp. 07220:029.
- BO12080L61 Forwards "Fisheries Resources of Cheyenne River Basin." No minnow or aquatic vegetation located Burvey results should be reflected in DES. MILLS.L.M. Tennessee Valley Authority. 80/11/07. 2pp. 07188:233.

- --8012080664 "Fisheries Resources of Cheyenne River Basin." KOTH,R.M.: FORD,R.C. South Dakota: State of. 80-8, 80/07/09, 11pp. 07188: 235.
- DOCKET 40-2041 WEST CHICAGO FACILITY, KERR-MCGEE CORP.
- B012310379 Responds to NRC B01113 request for endangered species comments re proposed application to decommission. List of species which may be present in concerned area provided.
 BUMGARNER, D. H. Interior, Dept. of. B0/11/26. 4pp. 07369: 180.

DOCKET 40-2259 PATHFINDER MINES CORP.

- 8012020376 Forwards IE Insp Rept 40-2259/80-03 on 801002, No noncompliance moted, BROWN, Q.D. Region 4, Dallas, Fuel Facility & Materials Safety Branch, 80/10/28, 2pp. 07142:075.
- ---8012020383 IE Insp Rept 40-2259/80-03 on 801002. No noncompliance noted. Major areas inspected const activities re raising of tailings dam as authorized by Amend 7 of License 8UA-672. LANDSMAN,R. B. Region 9. Chicago. Reactor Construction & Engineering Support Branch. BRONN,O.D. Region 4. Dallas, Fuel Facility & Materials Bafety Branch. HALL.R.E. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/10/27. 3pp. 07142:077.
- 8012020003 Advises that Amend 8 to 8UA-672 was issued on 800626 & should be exempt from fees. Amend was initiated by NRC. GILLEN.D.M., LENEHAN.J.J. Uranium Racovery Licensing Branch. 8071706. 1p. 07148:305.
- 8012160305 Responds to request for add1 info on holding capacity of Tailings Pond 4 during embankment const phase. Total release of liquid stormed upstream of Embankment 4 during const will be contained.

 NUOENT.E.L. Pathfinder Mines Corp. 80/12/11. 2pp. 07263:043.

DOCKET 40-3392 ALLIED CHEMICAL CORP.

- 8012220073 Forwards IE Insp Rept 40-3372/80-03 on 801027-31.No noncompliance noted. DAVIS, A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/11/18. 2pp. 07306:356
- --B012220096 IE Insp Rept 40-3392/80-03 on 801029-31. No noncompliance noted. Major ereas inspected:low level waste packaging transport procedures & radiation protection program. PECK, C.C., FISHER, M.L., Region 3, Chicago, Office of the Director. 80/11/17. 4pp. 07306:398.

DOCKET 40-3453 ATLAS MINERALS

- 8012080217 Ack receipt of 800909.1tr re License SUA-917. Requests confirmation that vandor has up to nine months from 801117 to comply with referenced matters.
 FARLEY, E. R. Atlas Minerals. 80/10/17. ip. 07181:267.
- B012010074 Confirms 801027 telcon re hydrologic conditions rept. Vendor will respond w/completion date, pending agreement on scope of work involved.
 BHANBY, 0.T. Atlas Minerals. 80/10/31. ip. 07092:030.
- 8012080385 Forwards near site radiation readings for 8ept 1980, confirming 801103 discussion Question re QA procedures will be sent by separate ltr. SHANDY, O. T. Atlas Minerals. 80/11/04. 3pp. 07196:192.
- 8012080710 Confirms 800106 discussion re cancellation of NRC 801114 meeting in Washington DC. Requests rescheduling of meeting w/NRC for 801204 or 11. BWANBY O. T. Atlas Minerals. 80/11/07. 1p. 07196:138.
- BOIR190055 Submits info requested in BOI017 draft telex re hydrologic conditions at mill site. Water sampling procedure accepted as proper & will be used in future. Rept on increasing radionuctide concentrations encl. SWANEY, O. T. Atlas Minerals. 80/11/10. 7pp. 07279:032.
- B012240310 Requests clarification re in vivo testing & whether employee names should be submitted w/data.

 BMANBY, O. T. Atlas Minerals. 80/11/14. ip. 07328:183.

- 8012100665 Ack receipt of 801103 itr re increase in yellowcake production. Request requires amend to License BUA-917 & minor safety & environ amend fee per 10CFR170.31.
 WEISS.D. License Fee Management Branch. 80/11/18. ip.
- 8012160763 Responds to 801023 request for notification of meetings w/ U mill representatives or finalized policy decisions re surety arrangements mill operations & site reclamation. Meeting w/mill representatives scheduled on 801211. 8CARAND.R.A. Uranium Recovery Licensing Branch. 80/11/19. 1p. 072141-304.
- --8012160766 Requests notification of meetings w/U mill representatives or finalized policy decisions re surety arrangements, mill operations & site reclamation.

 ANDERSON.L.F. Utah. State of. 80/10/23. ip. 07261:307.
- 8012190046 Forwards instructions used in mill lab for QA & actual analytical procedures. Written procedure followed w/exception of Th-230 std which is presently unobtainable. SNANBY, Q. T. Atlas Minerals. BO/11/19. 13pp. 07278:311.
- 8012290216 Requests required data on soil sampling, background groundwater sampling, yellowcake dryer sampling & external radiation monitoring data by 801208.

 8CARAND, R. A. Uranium Recovery Licensing Branch. 80/11/25. 3pp. 07345:178.

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MININO)

- B011070245 Forwards corrected copy of map discussed in B01003 telcon. LANE, J. R. Federal American Partners. B0/10/14. 1p. 04918:100.
- B012010631 Trip rept of B00923-24 visit to Casper WY to review well monitoring & reporting requirements, examine mine being pumped dry & examine Federal-American Partners housing & tailings facilities. FREEMAN.J.D. Uranium Recovery Licensing Branch. 80/11/10. 2pp. 07098:114.
- 8012220134 Forwards "Rept on Alternate Evaporation Fond Bits Evaluations, West Oas Hills, My for Federal-American Partners," in response to NRC 801104 request. ANDRUS, N. J. Federal American Partners. 80/11/25. ip. 07303:192.
- --8012220137 "Rept on Alternate Evaporation Pond Site Evaluations, West Oas Hills, WY for Federal-American Partners." | HURDQCK, L. T. Dames & Hoore. 80/10/31, 38pp. 07303:193.

DOCKET 40-6622 PATHFINDER MINES CORP.

- BO1212037B Application to amend License BUA-442 replacing bag sampling technique w/Track-Etch continuous passive monitoring sys.

 New method will provide better monitoring data & make radon monitoring program easier to administer.

 MURDOCK. B. Pathfinder Mines Corp. B0/10/08. 2pp. 07236:257.
- --8012120382 "Passive Integrating Radon Monitor for Environ Monitoring." ALTER: M. W. Terradez Corp. FLEISCHER, R. L. General Electric Co. 80/06/30. 17pp. 07236:239.
- 8012160179 Bafety evaluation recommending approval of Amend 2 to License BUA-442 to upgrade effluent & environ monitoring program & incorporate OA program as outlined in Reg Ouide 4, 15. HEYER,R. S., LINEMAN, J. Urenium Recovery Licensing Branch. 80/11/21. 2pp. 07262:295.
- B012160548 Amend 2 to License SUA-442, adding Conditions 36 & 37 requiring submittal of complete specs for operational affluent & environ monitoring program & reporting of results of effluent & environ monitoring.

 BCARRADG.R.A. Uranium Recovery Licensing Branch. 80/11/21. 5pp. 07261:205.

DOCKET 40-6659 PETROTOMICS CO., GETTY OIL

B012010606 Notifies that review of Amends 4 & 5 requires post-const insp from Ofc of Nuclear Reactor Regulation Hanpower memo will follow pending rept of contractor expenses. KOTBCH.J.L. Uranium Recovery Licensing Branch. 80/11/05. 1p. 07098:109.

DOCKET 40-6940 KAWECKI BERYLCO INDUSTRIES, INC.

- BOOD130126 Responds to FDIA request for info re six separate companies. Forwards documents listed in Apps A & B. Portions of App B documents withheld:nemes of individuals esposed to radiation (ref FDIA Exemptions 6). FELTON.J.M. Division of Rule's and Records. BO/04/10. 4pp. 04/93: 184.
- --8005i30347 License SMB-920, authorizing possession & use of unlimited amounts of U & thorium in form of slags & ore residues by Kawacii Berylco Industries, Inc.
 LAYFIELD.R.L. Atomic Energy Commission. 72/10/24. 2pp.

DOCKET 40-7102 SHIELDALLOY CORP.

- B012190678 Act receipt of B01030 ltr informing NRC of steps taken to correct violations noted in HE Insp Rept 40-7102/80-01.
 KINNEMAN, J. D. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. S0/11/20. ip. 07287:323.
- --8012190483 Responds to NRC 801015 ltm re violations noted in IE Insp Rept 40-07102/80-01. Corrective actions: signs posted in slag dwnp area & columbium ore storage area at required. LONGAKER, J. B. Shieldalloy Corp. 80/10/30. 2pp. 07287:324.
- --8012190686 Discusses IE Insp Rept 40-7102/80-01 on 800926 & forwards notice of violation.
 KINNEMAR, J.D. Region 1, Philadelphia, Fuel Facility & Haterials Baraty Branch. 80/10/15. 2pp. 07287:326.
- --9012190690 Notice of violation from insp on 800926. Noncompliance noted: unauthorized personnel supervised use of licensed matl & air sample surveys in blending & fornace areas of Bldg 3 not performed.

 # Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch. 80/10/15. 1p. 07287:328.
- DOCKET 40-7402 ALLEGHENY LUDLUM INDUSTRIES, CHEMTRON CORP.
- B012310534 Forwards IE Investigation Rept 40-7402/80-01 on B00717-18, 0902-05 & 18-17 & notice of violation. KEPPLER, J. O. Region G. Chicago, Office of the Director. 80/11/07, 2pp. 07363:318.
- --8012310537 Notice of violation from insp on 800717-0919.
 4 Region 3. Chicago: Office of the Director. 80/11/06. ip. 07365:320.
- --B012310543 Informs that as result of review of 800718 assessment rept of McGean disposal dump in Newburgh Heights, OH, decontamination of disposal dump uill be required. KEPPLER, J.O. Region 3, Chicago, Office of the Director. 80/08/07, 2pp. 07365:321.
- --8012310550 IE Investigation Rept 40-7402/80-01 on 800717-18,0902-05 & 18-19, Moncompliance noted: failure to make adequate evaluation of licensed math prior to disposal to assure compliance w/10CFR20, 301 & 20, 304 requirements.

 WELL.C.H., SREMIAMSKI.D.J., NORELIUS.C.E. Region 3, Chicago, Office of the Director. 80/11/06. 29pp. 07365:323.
- --B012310573 Refers to 800624 telcon re radioactive matl disposed of at McDean disposal dump in Newburgh Haights, DH. Assessment to be made to determine source of matl discovered. KEPPLER. J. Q. Region 3. Chicago, Office of the Director. B0/06/24. 1p. 07365:353.
- --B012310577 Forwards technical consultant NL Industries assessment rept of HcGean disposal dump in Newburg Heights.OH. WILNER.B.K. Allegheny Ludium Industries, Inc. B0/07/24. 19pp. 07365:354.
- --8012310581 Transcript of CO Neilsen 800904 deposition re radioactive mat! disposal at McGean disposal dump in Newburgh Heights, OH. NEILBON, C. G. Chemtron Corp. 80/09/04. 1p. 07346:010.
- --B012310587 Transcript of JG Zindroski 800704 deposition re radioactive catl disposal at KcGesn disposal dump in Newburgh Heights, GH, ZINDROSKI, J. G. Chemtron Corp. 80/09/04. 4pp. 07366:011.
- --8012310592 Transcript of D Zeman 800703 deposition re radioactive matl disposal at McCean disposal dump in Neuburgh Heights, DM. ZEMAN, D. Affiliation Unknown. 80/09/03. 2pp. 07366:015.

- --8012310598 Transcript of D Zeman 800903 deposition re radioactive matl disposal at McGean disposal dump in Nauburph Heights, OH. ZEMAN, D. Affiliation Unknown. 80/09/03, 2pp. 07366:017.
- --8012310405 Transcript of PW Jones 800904 deposition re radioactive matl disposal at McGean disposal dump in Newburgh, Heights, OH.
 JOHES, P. W. Affiliation Uninown. 80/09/04. ip. 07364: 019.

DOCKET 40-7580 FANSTEEL HETALS

800513012& Responds to FDIA request for info re six separate companies.
Forwards documents listed in Apps A & B.Portions of App B
documents withheld: names of individuals exposed to radiation
(ref FDIA Exemptions 6).
FELTON.J.M. Division of Rules and Records. 80/04/10. 4pp.
04931:184.

DOCKET 40-7924 SCHOTT OPTICAL GLASS, INC.

- 8012240077 Act receipt of 801021 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 40-7924/80-01 & OO-09864/80-01.

 KINNEMAN, J. D. Region 1, Philodelphia, Fuel Facility & Materials Safety Branch. 80/11/18. 1p. 07324:281.
- --8012240082 Responds to NRC 801004 ltr re violations noted in IE Insp Repts 40-7924/80-01 & 30-09864/80 01. Corrective actions: relocated waste storage area to remote area & posted area as required. KALOMSKY.N. H. Bichott Optical Glass.Inc. 80/10/21. 2pp. 07324:282.
- --8012240087 Discusses IE Insp Repts 40-7924/80-01 & 30-09864/80-01 on 800915 & forwards notice of violation KINKEMAKI.J.D. Region 1. Philadelphia, Fuel Facility & Haterials Safety Branch. 80/10/06. 2pp. 07324:284.
- --8012240070 Notice of violation from insp on 800915. Noncompliance noted: gauges containing licensed math stored in unrestricted area & radiation area surrounding waste thorium storage area not posted as required.

 # Region i. Philadetphia, Fuel Facility & Materials Safety Branch. 80/10/06. 2pp. 07324:286.

DOCKET 40-8000 TRANSNUCLEAR, INC.

- 8012300293 Approves 800904 & 24 submittals describing export of SNM per 100FR73.25 & 100FR73.26. Appropriate state police should be contacted w/regard to road conditions before shipment commences. Arrangements & approved route forthcoming. MCCORKLE.O. H. Physical Security Licensing Branch. 80/10/14. 2pp. 07364.18D
- DOCKET 40-8064 EXXON MINERALS CO. USA, EXXON CORP.
- 80:2010229 Submits 1980 third quarter rept for solution mine pilot testing for Highland R&D program. Sample analysis results encl.
 TRUSSELL, H. H. Exxon Minerals Co., USA. 80/10/21, 9pp. 07097:307.
- 8012100106 Forwards amend fee for License SUA-1064 re use of sulfate as excursion parameter for leach sys.
 TRUSSELL.H.H. Exxon Minerals Co., USA, 80/11/17. 1p. 07187:001.
- --8012100110 Ack receipt of 801016 ltr re use of sulfate as excursion parameter. Minor safety & environ amend fee required.
 WEISG. D. License Fee Management Branch. 80/11/06. 1p. 07187:001.
- --8012100116 Requests deletion of sulfate as excursion parameter since groundwater analysis shows sulfate assay to be poor indicator dup to low sulfate levels of Highland leach sys. TRUSBELL.H.H. Exkon Minerals Co., USA. 80/10/16. 13pp. 07187:001.
- DOCKET 40-8084 LISBON MINE. RID ALODH CORP.
- 8012080788 Forwards "Review of Proposed Fifth Dam Raise, Upper Tailings Pond Embaniment Sys, Lisbon Valley Operations, Rio Algom Corp." NELEDN, J. D. Colorado State Univ. 80/10/01. 1p. 07187:080.

- --8012080798 "Review of Proposed Fifth Dam Raiss, Upper Tailings Pond Embankment Sys.Lisbon Valley Operations, Rio Algom Corp." NELSON, J. D., ABT, S. R. Colorado State Univ. 80/10/01. 24pp. 07187:081.
- B012080823 Forwards corrected copies of "Review of Proposed 5-Ft Dam Raise, Upper Tailings Pend Embankment Bys. Lisbon Valley Operations, Rio Algom Corp." Requests destruction of 801001 copies. NELSON, J. D. Colorado State Univ. 80/10/03. 1p. 07180:174.
- --B012080825 Revised "Review of Proposed 5-Ft Dam Raise, Upper Tailings Pond Embankment Bys, Lisbon Valley Operations, Rio Algom Corp." NELSON, J. D., ABT, S. R. Colorado State Univ. 89/10/01. 25pp. 07180: 175.
- 8012010031 Discusses NRC comments re status of groundwater program at mine which were based on Dames & Moore Jan 1980 rept re tailings mpt study. Addl analyses required on migration of groundwater contamination & on seepage pathways.

 HARLAN,R,L.: BODDY, J.R. Dames & Moore. 80/10/20. App. 07092:034.
- 8012020340 Forwards IE Insp Rept 40-8084/80-01 on 800625-27, BROWN, O. D. Region 4, Dallas, Fuel Facility & Materials Safety Branch. 80/10/23, 1p. 07142:050.
- --8012020349 IE Insp Rept 40-8084/80-01 on 800625-27. Noncompliance noted: failure to minimize dusting of tailings, failure to perform air sampling, failure to post airborne radioactivity areas & failure to implement engineering controls.

 CAIN.C. L., WILBORN.L. Region 4. Dallas, Office of the Director. BROWN, C.D. Region 4. Dallas, Fuel Facility & Materials Safety Branch. 80/07/09. 13pp. 07142:051.
- --8012020361 Discusses results of verification samples taken at facility during 1979 & analytical test samples supplied during Jan 1980. Forwards info re discrepancies between NRC air samples & vendor samples. Review of calculations requested.
 BROKN.O.D. Region 4. Dallas, Fuel Facility & Materials Safety Branch. 80/01/25. Spp. 07142:064.
- 8012010039 Responds on behalf of Rio Algom Corp. to NRC 801008 request for info re upper tailings pond 5-ft embankment raise. Piezometers will be placed at base of embankment upon completion of raise. BQDDy.J.R. Dames & Moore. 80/10/27, 12pp. 07092:082.
- 8012160184 Bafety evaluation re application for Amend 3 to License SUA-1119, authorizing 5-ft raise of upper tailings retention ambankment. Amend will not constitute undue risk to public. Recommends issuance subj to listed conditions. KOTSCHJ.L., LINEHAN, J.J. Uranium Recovery Licensing Branch. 80/11/07. 3pp. 07262:297.
- 8012160356 Amend 3 to License 8VA-1119, authorizing 5-ft raise of upper tailings dam, w/conditions added to maintain at least 5 ft of freeboard between embankment crest & max operating level of ponded liquid in upper tailings pond.
 8CARAND.R.A. Uranium Recovery Licensing Branch. 80/11/07. 2pp. 07261210.
- 8012080339 "Lisbon Mins Ambient Air Bamples 1978." * Rio Algom. Ltd. 80/11/19. 3pp. 07189:231.
- 8012160191 Bafety evaluation recommending approval of Amend 4 to License SUA-1119, revising environ monitoring program & radiation safety program, w/conditions requiring workers to wear protective clothing.
 KOTSCH.J.L., LINEHAN.J.J. Uranium Recovery Licensing Branch. 80/11/21. 7pp. 07262:300.
- 8012160287 Amend 4 to License SUA-1119, revising Condition 14 represention of Alpha contamination & adding Condition 36 requiring operational effluent & environ monitoring program submittal, SCARANO, R. A. Uranium Recovery Licensing Branch. 80/11/21, App. 07261:349.

DOCKET 40-8102 EXXON MINERALS CO USA, EXXON CORP.

B0120B0796 Forwards responses to questions & comments in NRC 801016 ltr re hydrogeologic sys at site. ORTLOFF, G. D. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/11/10. 7pp. 071BB:046.

DOCKE: 40-8104 MEDICAL CENTER OF VERHONT BURLINGTON, VT

- 8012080720 Ack receipt of 800912 & 1003 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-00509780-01,30-03289780-01,70-2286780-01 & 40-8106780-01. KINNEMAN,J.D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/30. 1p. 07181:157.
- --B009190463 Responds to NRC B00B19 ltr re evaluations of I-131 & I-125 concentrations. Evaluations of restricted area concentrations of I-131 & I-125 & thyroid monitoring will be conducted within 30 days, using Reg Ouide 8, 20, Table 1 criteria. JANNEY, C. D. Medical Genter of Vermont Burlington, VT. 80/09/12. 1p. 07181:158.
- --B012080735 Responds to NRC 800819 ltr re violations noted in IE Insp Rept 30-03289/80-01. Corrective actions: evaluations of restricted area concentrations & thyroid monitoring to be conducted. JANNEY, C. D., BERRY, J. F. Medical Center of Vermont Burlington, VT. B0/10/03. 1p. 07181:139.
- ---B012080742 Discusses IE Insp Repts 30-00309/80-01.30-03289/80-01. 70-2286/80-01 & 40-8106/80-01 on 800729-30 & forwards notice of violation. XINNEMAN.J.D. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 80/08/19. 2pp. 07181:160.
- --8017080757 Notice of violation from insp on 800729-30.

 * Region i, Philadelphia. Office of the Director. 80/08/19, ip. 07181:162.

DOCKET 40-8231 GENERAL ELECTRIC CO.

8012230254 Application for amend to export license extending expiration date to 840101.

HILSON, B. D. General Electric Co. 80/11/13. ip. 07317:320.

DOCKET 40-8304 WYDMING MINERAL CORP.

8012160175 Bubmits cost & menhours used in reviewing application for renewal of License SUA-1204. HILLER, H. J., BCARANO, R. A. Uranium Recovery Licensing Branch. BO/11/24. 1p. 07282:294.

DOCKET 40-8348 IN SITU URANIUM LEACHING PROJECT

- 8012120390 Confirms B01006 telcon granting permission for 30-day extension of License Condition 12 re rept on progress of pilot insitu project reclamation. Rept will be sent, pending receipt of add info.

 CARLOB, P. C. Union Gil Go. of California. B0/10/07. 1p. 07236:280.
- --8012120395 Forwards amend fee for 30-day extension re License Condition 12 requirement.
 CARLOB.P.C. Union Oil Co. of California. 80/11/12. ip. 07236:281.
- --8012120405 Nutifies of amend fee required for vendor 801007 application to extend License Condition 12. NEISS.D. License Fee Management Branch. 80/10/24. 1p. 07236:282.
- 8012010063 Advises that vendor must apply for RtD license to cover addl aquifer restoration work for License 17 in situ project. Internal meno encl. ENGELMANN.R. Wyoming, State of. 80/10/27. 3pp. 07098:200.
- 8012010550 Forwards progress rept on reclamation/restoration of research in situ U leaching project in Sweetwater County, MY per Condition 12 of License SUA-1223 renswal. Rept addresses OO Eadle 1977 concerns.
 CARLOS.P.C. Union 76 Minerals Exploration Co. 80/11/11. 18pp. 07005-030

DOCKET 40-8434 HOME STATE MINING CO. LA

8012140167 Bubmits cost & menhours used in reviewing application for renewal of License 8UA-1249. HEYER, B., LINEHAN, J.J. Uranium Recovery Licensing Branch. 80/11/21. lp. 07262:272.

DOCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP.

- 8012010592 Sunmary of 791011 meeting in Cheyenne, MY re communication w/MY Dept of Environ Quality. Cleanup plan for shallow monitor zone should be submitted within 2 wis Plan should not be implemented for at least 30 days. PETERSON.LR. Wyoming Mineral Corp. 79/10/11. 2pp. 07098:217.
- 8012080698 Advises that G field may be conditionally approved following raview & approval of listed items re leakage data Analysis should be submitted by 791029.

 MORROW, D. Wyoming, State of. 79/10/15. 2pp. 07196:131.
- 80:201034: Forwards weetly water quality analysis results from shallow monitor & shallow research well samples taken on 79:023 & 26.Pissometric contour map constructed from 79:023 static water levels in shallow zone encl.

 MICHERS, D. L. Hyoming Minerel Corp. 79/10/31. 5pp. 07098:219.
- 8012020027 Forwards baseline data packages for Well Fields B.C.D & F.in response to 791218 request. FORD.N.H. Hyoming Mineral Corp. 79/12/19, 145pp. 06916:001.
- 8012040722 Application to amend License SUA-1341, updating corporate organization & revising min position qualification of radiation protection officer & site licensing engineer. Revised license pages & prof qualifications of officer and. 8CHENDEL, X. R. Wyoming Kineral Corp. 80/10/31, 11pp. 07155:325.
- BO12110419 Bubmits shallow monitor zone status rept for License BUA-1341 Reduced number of shallow monitor wells sampled during wits of BO1027 & 1110.w/parmission of state. Supporting documentation L. oversize map encl. HICHERS, D. L. Wyoming Mineral Corp. B1/11/14. 60pp. 0724B: 177.
- 8012310527 Confirms 801107 & 10 telcons re status of chailow monitor wells 9R8-19 & 98M-7. Routine weekly camples indicated chloride & total alkelinity exceeded control limits for well 9R8-19.

 WICHERS.D.L. Hyoming Kineral Corp. 80/11/14. 2pp. 07345:312.
- BO12170562 Application to Amend License SUA-1341 to authorize surface discharge of leachate per NPDES Permit WY-0028801. Application to State of WY.permit.amend fee k two oversized drawings encl.
 SCHENOEL.K.R. Wyoming Mineral Corp. BO/11/20. 27pp. 07245:226.
- 8012240114 Advises that 800805 license data summarizing estimated Jan-June 1950 releases of radioactive matts in effluent into unrestricted area of facility are within acceptable limits. HEYER.R.B. Uranium Recovery Licensing Branch. 80/12/03. 1p. 07325:135.

DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO.

- 8012010036 Forwards "Supplementary Rept.insp & Testing of Compacted Fill Impoundment Cell C Embankment Sweetwater U Project. Sweetwater County, MY: "ACOSTA's.P. Hinerals Exploration Co. (subs. of Union Gil Co. of California). 80/10/06. ip. 07092:042.
- 8012020007 Submits costs incurred & manhours used in review of 800411 application for Amend 4 to License SUA-1350. OILLEN, D. M., LINEMAN, J. J. Uranium Recovery Licensing Branch. 80/11/06. ip. 07148:306.
- 8012020576 Forwards revised GC program re U in urine samples Vendor 800827 ltr should be ignored. ACGSTA.A.P. Union Minerais. 80/11/20. 4pp. 07148:226.
- 8012050332 Advises NRC of steps taken to protect PVC bottom liner in tails pond. Forwards Crestline Corp 801117 ltr outlining additions that should be taken to protect PVC bottom liner from ultraviolet rays in subsurface tailings pond.

 ACOSTA-A-P. Union 76 Minerals Exploration Co. 80/11/26. 2pp. 07175:058.
- B012300008 Informs that Minerals Exploration Corp submitted annual revision of first yr reclamation cost & copy of performance bond increase. Info provides acceptable basis for increased "Reclamation Performance Bond."

 HEYER, R. B. Uranium Recovery Licensing Branch. 80/12/04. 1p. 07338:338.

DOCKET 40-8585 WYOMING MINERAL CORP.

8012050095 Application to amend License SUA-1315, updating corporate compliance review board organization & revising min position qualifications of radiation protection officer Revised license pages & prof qualifications of current officer encl. SCHENDEL, K. R. Wyoming Mineral Corp. 80/10/29, 5pp. 07171:314.

DOCKET 40-8502 UNITED NUCLEAR CORP.

8012170262 Responds to 800829 ltr expressing puzzlement as to why FES for Morton Ranch U Mill (NUREG-0532) was received 17 months after publication. Submits comments on EPA response to FES. BCARAND.R.A. Uranium Recovery Licansing Branch. 80/11/24. 4pp. 07268:244.

DOCKET 40-8542 THIOKOL CORP.

8012040315 IE Insp Findings & Licensee Ack dtd 801007 of License SUB-1311. Insp findings: no noncompliance noted. CAIN.C.L. Region 4. Dallas. Office of the Director. 80/10/07. ip. 07162:361.

DUCKET 40-8681 ENERGY FUELS NUCLEAR, INC.

BO120B078D Forwards revised drawing of White Mesa Mill process flow diagram. Fee not encl.
BAKER.C.E. Energy Fuels Nuclear, Inc. 80/10/17. 2pp. 07187:063.

DOCKET 40-8693 DOLE PETROLEUM, INC.

8012100483 Submits insitu U solution mining operation quarterly rept for Aug-Oct 1980.
SAUNDERS, G. A., CATCHPOLE, O. J. Ogle Petroleum, Inc. 80/12/04. 69pp. 07187:001.

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO.

- 8012080786 Submits quarterly rept for Jul-Sept 1980. NEUMANN.H.R. Rocky Mountain Energy Co. 80/11/04. 7pp. 07188:036.
- 8012010416 Submits costs incurred & manhaurs used in evaluating 800423 application for Amend 1 to License SUA-1339. MILLER.H.J., SCARANG.R.A. Uranium Recovery Licensing Branch. 80/11/10. 1p. 07098:111.

DOCKET 40-8709 WESTERN ZIRCONIUM, INC.

- BOI2020237 Discusses IE insp of License SMB-1347 on 801008 & forwards notice of violation.
 BROWN-0.D. Region 4. Dailas. Fuel Facility & Materials Safety
 Branch. 80/10/20. ip. 07134:208.
- --8012020262 Notice of violation from insp on 801008.Noncompliance noted: licensed math under supervision of unauthorized individual on 801008 & surveys of surface contamination levels & airborne radioactive math not performed. Region 4. Dallas, Fuel Facility & Materials Safety Branch, 80/10/20. ip. 07134:207.
- 8012020238 Ack receipt of 801107 ltr informing NRC of steps taken to correct violations noted in IE insp on 801008.

 BROWN O.D. Region 4. Dallas: Fuel Facility & Materials Safety Branch. 80/11/18. 1p. 07134:202.
- --801202024B Responds to NRC 801020 ltr re violations noted in IE insp on 80100B. Corrective actions: application for license amend to change designee responsible for licensed matl was filed & total dust samples collected. Phosphor paper ordered. VAN DYKE, C. Western Zirconium, Inc. 80/11/07. 2pp. 07134: 203.
- --B012020252 Application for amend to License SMB-1947, changing designee responsible for licensed math. PRUS.L.B. Western Zirconium, Inc. B0/11/07. 3pp. 07134:205.

DOCKE: 40-8714 CLEVELAND CLIFFS IRON CO.

- 8011200186 Forwards quarterly rept for Jul-Sept 1980. One oversize drawing encl.
 LAMAN, J. T. Cleveland-Cliffs Iron Co. 80/10/16. 1p. 07044: 204.
- --B011200191 Quarterly rept for Jul-Sept 1980.
 4 Cleveland-Cliffs Iron Co. B0/09/30. 13pp. 07044:205.
- 8012180388 Provides written confirmation of 801121 telcon re completion of restoration in first pattern area during mining operations in second pattern area. Second pattern will be mined at max nominal rate of 100 gpm.
 LOUDERBACK, T.E. Cleveland-Cliffs Iron Co. 80/11/21. 2pp. 07272: 335.

DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP.

- 8012160171 Bubmits cost & manhours used in reviewing application for Amend 1 to License SUA-1378. HEYER,R.S., LINEHAN,J.J. Uranium Recovery Licensing Branch. BO/11/17. ip. 07262:293.
- DOCKET 40-8728 TETON EXPLORATION DRILLING CO . INC.
- 8012010531 Trip rept of 800923-24 visit to Casper WY to review well monitoring & reporting requirements, examine mine being pumped dry & examine Federal-American Partners housing & tailings facilities.
 FREMAN.J.D. Uranium Recovery Licensing Branch. 80/11/10. 2pp. 07098:114.

DOCKET 40-8743 CONDCO

- 8012010221 Advises of Land Quality Div regulations re U mill tailings. Public hearing to discuss regulations scheduled for 801105 in Chayenner WY. QUIOLEYT. W. CONGCO, Inc. (Continental Gil Co.). 80/10/23. 7pp. 04916:001.
- 8012010210 Comments on facility environ rept. No impact indicated on areas or resources associated w/agency programs. Recommends including State Historic Preservation Officer confirmation let in fraft EIS.
 ARKING.R.J. Interior.Dept.of. 80/10/29. ip. 07098:008.
- 8012050671 Forwards state agency comments on environ rept for project. Dept of Health & Social Svcs indicate need to address potential socioeconomic impacts. HERSCHLER, E. Wyoming, State of. 80/10/29. 9pp. 07171:190.
- G012010272 Comments on facility environ rept. Potantial conflicting interasts re land rights & U mining should be addressed in DES. Ragueed should be added to list of designated noxious weeds for WY.

 LIEURANCE. M. T. Interior. Dept. of, Bureau of Land Management.

 B0/10/30. 2pp. 07098:018.
- 8012020309 Ack receipt of info on U mill operation. FES should contain evidence of consulting Natl Register.

 WALL,L. S Advisory Council on Historic Preservation. 80/10/30. 1p.
 07148:191.
- 8012080657 Forwards environ rept in response to 801104 telcon. W/o encl. RICE, K. M. CONGCO, Inc. (Continental Gil Co.), 80/11/05, 1p. 07196:111.
- 8012120262 Comments on project environ rept. Army Corps of Engineers interest results from Section 404 of Clean Water Act. Any filling activity in waterway, lake or wetland must be authorized by Dept of Army.
 THOMSEN.A.L. Army. Dept. of. 80/11/06. ip. 07236:221.
- B012010025 Responds to B01022 request for documents re facility.Request has been forwarded to licenses.Environ rept contains more comprehensive info than license application.

 HAMILL.K.J. Uranium Recovery Licensing Branch. B0/11/10. ip. 07092-031.
- --B012010026 Requests NRC license application & environ rept re project. BEERS,R. Affiliation Unknown. 80/10/22. 1p. 07092:032.

- 8012160764 Forwards attendance list re 801016 scoping meeting on mill project, in response to 801022 request. Transcript of meeting will not be prepared, but scoping summary document will be issued. List not encl.

 HAMILL, K. J. Uranium Recovery Licensing Branch. 80/11/10. 1p. 07261:308.
- ---8012160767 Requests transcript & attendance list of 801016 scoping meeting on mill project.

 NUCSIJ. Powder River Basin Resource Council. 80/10/22, 1p. 07261:309.
- 8012180374 Forwards add1 info on EIS topics re water balance, discrepancies in distances between facilities & process flowsheets.

 QUIOLEY,T.H. Conoco Coal Development Co. 80/11/12. 2pp. 07272:339.
- 8012240508 Forwards draft of wildlife inventory to be portion of revised mine permit application. Western Resource Development Corp requested to submit repts furnished by ferret consultants.

 OUTOLEY, T.W. CONDCO, Inc. (Continental Oil Co.). 80/11/18. 54pp. 07324:118.
- B012240222 Act B01105 request for copy of environ rept for Band Rock mill project. RICE.K.M. CONOCO, Inc. (Continental Dil Co.). 80/11/20. 1p. 07328; 220.
- 8012240439 Forwards info re Sand Rock mill project.Flowsheets encl. OUIOLEY.T.W CONOCO.Inc. (Continental Oil Co.). 80/11/20. 5pp. 07328:055.
- B0i2240433 Forwards add1 info re black-footed ferret surveys,in response to F Sharples request. Also forwards AB.Crockett B01119 ltr. OUIOLEY, T.W. CONOCO, Inc. (Continental Dil Co.). B0/11/21. 3pp. 07328: 061.
- --8019240434 "CDHOCO Sand Rock Hill Project, Campbell County, HY: Black-footed Ferret Surveys, 800726-800729, " JAKSEN, C., BHATKOHSKI, S. Affiliation Unknown, 80/08/01, 9pp. 07328:064.

DOCKET 40-8745 DOLE PETROLEUM

- 8011170005 Forwards "Evaporation Ponds Suppl to Environ Rept." requested at NRC 800727 meeting. CATCHPQLE, G. J. Ogle Petroleum, Inc. 80/10/13. 2pp. 07050:002.
- --B011170007 "Evaporation Ponds Info Suppl to Environ Rept." d Ogle Petroleum, Inc. 80/10/31, 23pp. 07050:004.
- 8012170246 Orants exemption to requirements of 10CFR40.32(s) for purposes of drilling & completing no more than 100 wells in Mining Unit 1:as requested in 801008 ltr. MARTIN, J.S. Office of Nuclear Material Safety & Safeguards. 80/11/12. 2pp. 07268:213.
- B012240146 Recommends safety evaluation exemption from 10CFR40.32 (a) requirements for drilling & completing wells in Mining Unit 1, as requested in B0100B ltr.Postponment of well drilling might cause startup delay.

 MARTIN.D.E. Uranium Recovery Licensing Branch. B0/11/12. 3pp. 07324:189.
- 8012310573 Concurs w/801073 biological assessment that Bison Basin Project in Fremont County, WY will not affect bald eagles or black-footed ferret. STEUCKE, W. Interior, Dept. of, Fish & Wildlife Service, 80/i1/i7. ip. 07365:267.
- 8012170256 Confirms 801107 telcon rs NRC requests to include Well H-61 as shallow observation well to be monitored during two aquifer pumping tests when Wells H-19 & A-B are pumped. MILLER, H. J. Uranium Recovery Licensing Branch. 80/11/19. 3pp. 07268: 221.
- 8012300508 Forwards QA program for environ monitoring. BAUNDERB.Q.A. Ogie Petroleum. Inc. 80/12/24. ip. 07346:276.
- --8012300513 QA program for environ monitoring.
 4 Ogle Petroleum, Inc. 80/12/31, 5pp, 07346:277.

DOCKET 40-8771 NUCLEAR ASSURANCE CORP.

8012160627 Requests add1 info by 801219 re application for source matl license. HILLER/H.J. Uranium Recovery Licensing Branch. 80/11/21, 1p. 07261:255.

DOCKET 40-8783 URANERI USA, INC.

8012170235 Application for source matl license authorizing use of max of 5.000 kg yellowcake slurry for U absorption, lixiviant make-up, resin elution & yellowcake production. Sixteen oversize geological drawings encl.
FREE, B. Uranerz USA, Inc. 80/11/25, 140pp. 07273:050.

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV. OF MICHIGAN RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B012040288 Responds to NRC 801106 ltr re request for emergency plan. Facility emergency plan submitted to NRC for review & approval on 800612.

KERR.W. Michigan, Univ. of. 80/11/26. lp. 07160:312.

G. Inspection reports. IE Bulletins & correspondence

- B012180405 Forwards IE Insp Repts 50-002/B0-05 & 30-01988/80-02 on B01006-08 & notice of violation. DAVIB.A. S. Region 3, Chicago, Fuel Facility & Materials Safety Branch. B0/11/04. 2pp. 03794:257.
- ---8012180407 Notice of violation from insp on 801006-08.

 Region 3. Chicago, Office of the Director. 80/11/03. ip. 03794:259.
- --B012180408 IE Insp Repts 50-002/80-05 & 30-01988/80-02 on 801006-08.
 Noncompliance noted:complete certification & supporting analysis for Spec 7A package not maintained on file.
 PAUL.R.A. Region 3. Chicago. Office of the Director. FISHER, W.L. Region 3. Chicago, Fuel Facility & Materials Safety Branch.
 B0/11/03. 7pp. 03794:260.

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8012040632 Informs that certain mods will be made to emergency notification sys & health physics network equipment. NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operation facility. ORIER, B. H. Region I. Philadelphia. Office of the Director. 80/11/14. 2pp. 07170:079.
- 8012040701 Forwards public version of two FEMA repts entitled "Assessment of Evacuation Time Around Indian Point Nuclear Power Station." FELTON.J.N. Division of Rules and Records. 80/12/01. ip. 07155:173.
- --B012040704 Public version of draft final rept "Assessment of Evacuation Time Around Indian Point Nuclear Power Station," executive surmary, prepared for FEMA.

 ** CONEAD REGEARCH CORP. ** Center for Planning Research, Inc. B0/08/21. 34pp. 07135:174.
- --8012040710 Public version of final rept, "Assessment of Evacuation Time Around Indian Point Nuclear Power Station," prepared for FEMA, Public version of Consa6 Research Corp 800804 itr encl. 4 CONSAD RESEARCH CORP. 4 Center for Planning Research Inc. 80/06/23. 125pp. 07155:207.

Q. Adjudicatory correspondence

8012290217 Urges Commission to order ASLB to hold full adjudicatory hearing on contentions & hererds posed by reactors. WEISS.E.R. Sheldon, Harmon & Weiss. 80/11/25. 3pp. 07345:024.

H. General correspondence

- 8012030695 Requests that correspondence re facilities be directed to JD D'Toole.
 O'TOOLE, J. D. Consolidated Edison Co. of New York. 80/11/25, 1p. 07151:237
- 8012150169 Submits petition to that down reactors pending full investigation of safety issues.

 * Westchester Peoples Action Coalition, Inc. 80/12/12. ip. 07240: 024.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat fellowing earthquake. EISENHUT.D.O. Division of Licensing. 80/10/21. 4pp. 06916:001.
- B012160050 Ltr to operating plant licensees.QL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements, Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be ret. EISENHUT.D.O. Division of Licensing. B0/10/31. 7pp. 07250:080.
- --B012160147 "Clarification of TMI Action Plan Requirements." * Division of Licensing. NUREQ-0737. 80/11/30. 300pp. 07250:080.
- 8012220553 Ltr to all power reactor licensess forwarding NUREG-0619, "BNR Feedwater Norrie & Control Rod Drive Return Line Norrie Cracking." Confirmation that implementation dates will be met must be sent within 45 days. N/a enci. EISENHUT.D. G. Division of Licensing. 80/11/13. 1p. 07308:348.
- 8012080587 Forwards Amends 28 & 65 to Licenses DPR-5 & DPR-26, respectively & notice of issuance & availability.
 VAROA.S.A. Operating Reactors Branch 1. 80/11/18. 4pp. 07186: 340.
- --8012080593 Amends 28 & 65 to Licenses DPR-5 & DPR-26, respectively, adding requirements to maintain safeguards contingency plan & to follow guard training & qualification plan within 60 days of commission approval.

 VAROA.S. A. Operating Reactors Branch 1. 80/11/18. 4pp. 07186:344.
- --B012089598 Notice of issuance & availability of Amends 28 & 65 to Licenses DPR-5 & DPR-26, respectively. VAR94.6.A. Operating Reactors Branch 1. 80/11/18. 2pp. 07186:348.
- Q. Inspection reports, IE Builetins & correspondence
- 8012170367 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required, GRIER.B.H. Region i, Philadelphia, Office of the Director. 80/10/30. ip. 07269:040.
- 8012120080 Forwards IF. Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER, B. H. Region i. Philadelphia, Office of the Director. 80/11/06. 1p. 07230:262.
- B012190365 Informs util of issuance of new NRC personnel identification badges.effective after B01130.Example encl.
 MARTIN.M.J. Region 1, Philadelphia, Bafeguards Branch. B0/11/06.
 2pp. 07286:131.
- 8012030772 Forwards IE Info Notice 80-40, "Ercessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ORIER, B.H. Region i. Philadelphia, Office of the Director. BO/11/07. 1p. 07150:272.
- 8012080547 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. 1p. 07183:047.
- B012040066 Forwards IE Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B.H. Region i. Philadelphia, Office of the Director. B0/11/14. 1p. 07157:293.

- 8012220618 Advises that written response is required to IE Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER, B. H. Region i. Philadelphia. Office of the Director. 80/11/19. 1p. 07308:359.
- 8012040532 Forwards IE Bulletin HO-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required, Requests info on manpower expended. ORIER, B.H. Region I, Philadelphia; Office of the Director. BO/11/21. 2pp. 07169:144.
- 8012050546 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER,B.H. Region 1: Philadelphia, Office of the Director. 80/11/24, 1p. 07174:032.

R. Periodic operating reports & related correspondence

- 8012160476 Forwards data specified in Section 401 Certification for Nov 1980. MCNII.W.A. Consolidated Edison Co. of New York. 80/12/10. 14pp. 07263:114.
- 8012220399 Forwards tabulation of daily record of fish collections for Nov 1980, Daily species code list count & total weight encl, D'TOOLE, J. D. Consolidated Edison Co. of New York. 60/12/15. 5pp. 07304:105.
- T. Hearing transcripts on non-antitrust matters
- 8012270493 Transcript of 801215 public meeting in Washington, DC re AGLB instructions. Pp 1-54.

 * Commissioners. 80/12/15. 56pp.
- --8012270501 Responds to commissioner 801126 request re assessment of one-hearing vs two-hearing approach implications on safety issues' adjudication. BICKMITI.L. Office of the General Counsel. BECY-A-80-179E. 80/12/12, 3pp. 07335:276.
- --8012270507 Discusses & forwards redrafted B01126 order & clerifies commissioner resolutions. Excerpted ltr to EL Jorden and. BICKNIT.L. Office of the General Counsel. SECY-A-80-179D. 80/12/11. 21pp. 07335:279.

DOCKET 50-10 DREEDEN NUCLEAR POWER STATION, UNIT 1

- F. Becurity, medical, emergency & fire protection plans
- B012190342 Informs of recently approved revised 10CFR50.48 containing schedules for completion of all fire protection mods.No present implementation required as necessary addl info has not yet been approved.

 EISENHUT,D. O. Division of Licensing, 80/11/06. 6pp. 07286:101.
- 8012020167 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers.W/o encl health physics network manual.

 KEPPLER.J.O. Region 3: Chicago, Office of the Director. 80/11/19. 2pp. 07148:202.
- 8012120576 Resubmits security plan revisions in response to NRC 800910 & 1119 ltrs, Plan withheld from public disclosure (ref 10CFR2.790). W/o encl.

 ABEL, J. S. Commonwealth Edison Co. 80/12/09, 1p. 07227:292.

Q. Adjudicatory correspondence

- B0120B0533 Forwards withdrawal of NRC 800919 order re environ qualification at facility. CRUTCHFIELD, D. Operating Reactors Branch 5. 80/10/29, 2pp. 07184:312.
- --8012080537 Withdrawal of NRC B00919 order re environ qualification at facility. Licensee will be required to provide assurance re environ qualification of safety-related equipment prior to restart of facility.

 GASE.E.O. Office of Nuclear Reactor Regulation, Director. 80/10/29, ip. 07184:313
- BO12110345 Submits comments on behalf of util re petition for public hearings by citizens groups in opposition to proposed chemical cleaning of facility. Commission should allow chemical cleaning w/o further delay.

 STEPTOE, P. Isham, Lincoln & Beale. 80/11/14. 8pp. 07224:131.

- B012110606 Requests on behalf of util, NRC promptly establish licensing board to consider util license amend request for facility chemical cleaning project Cleaning should proceed prior to evidentiary bearings on basis of NRC safety evaluation.

 # Isham, Lincoln & Beale. 80/12/03. 2pp. 07225: 237.
- 8012170410 Requests refusal of util application to transfer spent nuclear fuel rods from Dresden units to Quad City units for storage. NRC should hold public hearings.

 # Citizens for Safe Energy. 80/12/11. 2pp. 07269:331.

H. General correspondence

- B009260776 Forwards chemical cleaning licensing submittal, supplementing 741219 licensing submittal. Suppl contains App I which describes extensive corrosion studies performed to demonstrate compatibility of cleaning solvent W/O encl. ABEL, J. 8, Commonwealth Edison Co. 75/04/16. 1p. 03598:044.
- 8012310401 Requests full public hearing on FES re proposed flushout. Util should not be authorized to proceed until public hearing is held. WIDRAN, J. Affiliation Unknown. 80/12/21. 2pp. 07369:154.
- P. Operating license stage documents & correspondence
- 8012110341 Notification of 750312 meeting w/util.Dow Chemical Co.GE.ANL & Buntac Nuclear Corp to discuss addl info on plan for chemical decontemination of primary coolant sys. G'CONNOR.P.W Operating Reactors Branch 2 (Pre 791030). 75/02/28. 5pp. 07223:200.
- 8012090459 Summary of 750312 meeting w/util re proposed facility chemical decontamination D'CONNOR.P.M. Operating Reactors Branch 2 (Pre 791030). 75/04/03. 4pp. 07203:060.
- 8012110276 Forwards safety evaluation by Ofc of Nuclear Reactor Regulation supporting authorization to chemically decontaminate primary coolant sys at facility. QCLLER.K.R. Diffice of Nuclear Reactor Regulation, Director. 75/12/09. 1p. 07224:073.
- B012110065 Requests addl info for review of Dow Chemical Co rept, "Technical Study for Chemical Cleaning of Dresden 1,"

 Outstanding areas: equipment installation & hookup, operation of decontamination sys & radionuclide inventory.

 HOENES, G. R., WAITE, D. A. Battelle Henorial Institute, Pacific Northwest Laboratory. 77/10/25, Spp. 07223:279.
- 8012110258 Confirms 771219 telcon re postponement of facility assessment pending util submittal for chemical cleaning. Work on general steam generator replacement document will begin.
 HOENES, G. R. Battelle Memorial Institute, Pacific Northwest Laboratory, 77/12/28. 2pp. 07224:091.
- 8012110063 Notifies that lab will evaluate proposed procedure reminimizing occupational exposure & release of radioactive effluents. Provides comments on program, based on preliminary documentation.
 HOENES.O.R. Battelle Memorial Institute, Pacific Northwest Laboratory. 78/01/24. Spp. 07223:276.
- 8012090260 Informs that staff has decided not to review PNL draft rept re chemical cleaning. Review would not have significant impact. KREGER. M. E. Radiological Assessment Branch. 78/09/11. ip. 07202:333.
- 8012090449 Informs of review of draft BNHL rept on facility chemical cleaning. Recommends rept be revised to include attached comments. LEE.J.Y. Effluent Treatment Systems Branch. 78/10/03. 2pp. 07203:050.
- 8012230256 Informs of review of util 771114 ltr requesting amend to DPR-2.App A for chemical decontamination of facility primary sys.Proposed changes acceptable.
 KNIGHTON.O.W. Reactor Systems Branch. 80/03/24. ip. 07317:321.
- --8012230258 Safety evaluation supporting amend to App A Tech Specs to perform primary sys chemical cleaning.

 a Office of Nuclear Reactor Regulation, Director. 80/03/24. 3pp. 07317:382.
- --8012230260 Amended Tech spac pages re conditions for operation, surveillance requirements & primary containment.

 Office of Nuclear Reactor Regulation, Director. 80/03/24. 5pp. 07317:325.

8012160232 Submits review of util 800327 info re chemical cleanup project. Thorough rinsing procedure should be established w/RRC concurrence. WEEKS, J.R. Brootheven National Laboratory, 80/05/05, 3pp. 07262:315.

- B012160245 Advises that util 800827 proposed procedure for rinsing of facility following decontamination u/MS-1 solvent is acceptable.

 MEEKS.J.R. Brookhaven National Laboratory. 80/09/03. 2pp. 07261:328.
- 8012080533 Forwards withdrawal of NRC 800919 order re environ qualification at facility.
 CRUICHFIELD.D. Operating Reactors Branch 5. 80/10/29. 2pp.
- -BD12080537 Withdrawal of NRC 800919 order re environ qualification at facility. Licensee will be required to provide assurance re environ qualification of safety-related equipment prior to restart of facility.

 CASE, E. O. Office of Nuclear Reactor Regulation, Director.

 B0/10/29. 1p. 07184:313.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl i implementation dates will be net.
 EISENHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BHRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE.Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT.D.G. Division of Licensing. 80/11/04. App. 07307:335.
- 8012010503 informs of decision to delay completion of SEP Topic 16. Tech Specs.until completion of all other SEP Topic reviews & integrated safety assessment.allowing for integrated evaluation of current Tech Specs. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/05. ip. 07008-274
- 8012220543 Ltr to all power reactor licensees forwarding NUREO-0619, "BWR Feedwater Norsle & Control Rod Drive Return Line Norsle Cracking." Confirmation that implementation dates will be met must be sent within 45 days W/o encl. EIGENHUT, D. O. Division of Licensing. 60/11/13. 1p.
- BO12180620 Forwards Amends 32,51 & 45 to Licenses DPR-2,DPR-19 & DPR-25,respectively,Amends 60 & 55 to Licenses DPR-29 & DPR-30,respectively & Amends 58 & 53 to Licenses BPR-39 & DPR-48,respectively,Safeguards contingency plans acceptable. CRUTCHFIELD,D. Operating Reactors Branch 5. SO/11/17. 5pp. 07271:324.
- --8012180633 Amends 32.51 & 45 to Licenses DPR-2.DPR-19 & DPR-25. respectively, requiring implementation of safeguards contingency plan. CRUICHFIELD.D. Operating Reactors Branch 5. IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/17. 4pp. 07271:329.
- --8012180640 Amends 60 & 55 to Licenses BPR-29 & DPR-30, respectively, requiring implementation of safeguards contingency plan. IPPOLITOIT. A. Operating Reactors Branch 2. 80/11/17. 4pp.
- -8012189668 Amends 58 & 55 to Licenses DPR-39 & DPR-48, respectively, requiring implementation of safeguards contingency plan. VAROA:8.A. Operating Reactors Branch 1. 80/11/17. 4pp. 07271:339.
- --BO12183671 Notice of issuance of Amends 32.51 & 45 to Licenses DPR-2. DPR-19 & DPR-25, respectively. Amends 60 & 55 to Licenses DPR-29 & OPR-30, respectively & Amends 58 & 55 to Licenses DPR-39 & DPR-48, respectively re safeguards contingency plan. CRUTCHFIELD. D. Operating Reactors Branch 5. BO/11/17. 2pp. 07271:343.
- 8012110426 Forwards F Rosa 790930 memo re SEP Topic VIII-3.B. "DC Power Sys Bus Voltage." CRUICHFIELD.D. Operating Reactors Branch 5. 80/11/18. 2pp.
- 8012020091 Confirms 801016 & 17 telcons re util commitments to perform well water sampling & analysis at locations around site.

 Analyses will be performed for gross alpha.gross beta & tritium. DAVIB.A.B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/11/19. 3pp. 07148:332.

- 8012030819 Forwards NEDC-12420-1, "Radiation Level Assessment of Dresden i Decontamination Pilot Locp-Final Rept." in response to portions of 801006 ltr to R Browning that have been referred to Division of Licensing. EISER:HUT.D.O. Division of Licensing. 80/11/19. 3pp. 07149:097.
- --8012030854 "Radiation Level Assessment of Drasdan 1 Decontamination Pilot Loop-Final Rept."
 ANSTINE, L.D., KENITZER, H.L. General Electric Co. NEDC-12620-1, 77/05/31, 42pp. 07147:100.
- 8012020301 Forwards tabulation of planned environ qualification testing programs, in response to NRC 801001 ltr.
 ABEL. J. S. Commonwealth Edison Co. 80/11/26. 4pp. 07148:193.
- 8012160099 Draft safety evaluation supporting 791114 application for amend to License DPR-2 re deletion of Yech Specs requirement far primary containment integrity during chemical cleaning of primary cooling sys.

 Office of Nuclear Reactor Regulation. Director. 80/11/26. Spp.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp. 07299:205.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity. BANDART.R.L. Effluent Treatment Systems Branch. B0/11/06. Bpp. 07279:207.
- --8012220534 Recommends that Ofc of Nuclear Reactor Regulation make ilcensees aware of new disposal site requirements for solid radwaste & dates they will go into effect. Draft memo encl. DAVIS.J.O. Office of Nuclear Material Safety & Safeguards. 80/09/11. 8pp. 07299:215.
- B012160172 Forwards 800709 & 10 chemical cleaning solidification sys-test results. JANECEK.R.F. Commonwealth Edison Co. B0/12/11. 4pp. 07262:062.
- 8012170488 Forwards response to NRC 801031 itr requesting confirmation that implementation dates indicated in NUREO-0737 will be met. Ability to meet required dates for major mods is contingent upon hardware availability & delivery.

 ABEL. J. S. Commonwealth Edison Co. 80/12/15. 37pp. 07270:294.
- 8012240158 Forwards confirmation that implementation dates per NUREO-0737 will be met & justification for exceptions. Generally dates are contingent upon hardware availability & delivery Comments on safety requirements in Tech Specs. ABEL. J. S. Commonwealth Edison Co. 80/12/19, 37pp. 07323:001.
- 8012240489 Notification of 901218 meeting w/BEP owners group in Bethesda,HD for discussions on SEP program, schedule for license topic completion & assignment of lead topics to plants. RUSSELL,N.T. Systemetic Evaluation Program Branch. 80/12/16. 2pp. 07324:104.
- Q. Inspection reports, IE Bulletins & correspondence
- B011190515 Forwards IE Insp Repts 50-010/80-14,50-237/80-17 & 50-249/80-21 on 800803-0906 & notice of violation. HEISHKAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/08. 2pp. 06998:120.
- --8011190518 Notice of violation from insp on 800803-0906. * Region 3, Chicago, Office of the Director. 80/09/29. 1p. 06998:122.
- 8012170510 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 KEPPLER.J.O. Region 3. Chicago. Office of the Director. 80/10/24.
 1p. 07268:099.
- 8012160085 FOIA request for documents re experimental use of Dow NB-1 solvent at Dresden 1 & Peach Bottom including disposals & MCCULLOUGH, E. R. McCullough: E. R. 80/10/31. ip. 07241; 334.
- 8012100389 Forwards IE Insp Repts 50-010/80-19,50-237/80-21 & 50-249/80-25 on 800907-1003 & notice of violation. HEISHMAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/04, 2pp. 07218:164.

- --8012100591 Notice of violation from insp on 800907-1003.

 * Region 3, Chicago, Office of the Director. 80/10/31. 1p. 07218: 166.
- --8012100597 IE Insp Repts 50-010/80-19.50-237/80-21 & 50-249/80-25 on B00907-1003. Noncompliance noted: failure to adhere to QA program requirements. TONOUE, T.M., JORDAN, M.J., SPESSARD, R.L., Region 3, Chicago, Office of the Director, 80/10/31, 7pp. 07218:167.
- 8012020308 Ack receipt of 801030 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/80-14, 50-237/80-17 & 50-247/80-21.
 HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/10. ip. 07143:105.
- --8012020312 Responds to NRC 601008 ltr re violations noted in IE Insp Repts 50-010/80-14.50-237/80-17 & 50-249/80-21. Corrective actions: potential radiological consequences to workers performing maint on control rod driveline pump evaluated, ABEL.J.S. Commonwealth Edison Co. 80/10/30. 3pp. 07143:106.
- 8012020/43 Forwards three Performance Appraisal Branch insp repts & mpt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. H/o encl.

 KEPPLER. J. O. Region 3. Chicago. Office of the Director. 80/11/18. 4pp. 07147:3345
- 8012040667 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required, KEPPLER.J. O. Region 3, Chicago, Office of the Director. 80/11/21. 2pp. 07166:358.
- 8012080087 Forwards IE Info Notice 80-42, "Effect of Rediation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:253.
- B012230223 Forwards new security badge numbers & clearance levels for Region 3 personnel Changes should be entered on Sept 1980 access lists.

 KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 80/11/25.6pp. 07317:081.
- 8012i60082 Responds to FOIA request for documents re experimental use of Dow NB-1 solvent at Dresden i & Peach Bottom including disposals & westes.Use of Dow NB-1 solvent wes not considered experimental. Forwards documents listed in App A. FELTON.J.M. Division of Rules and Records. 80/11/26. 2pp. 0726i:335.
- --B012160090 Responds to B01006 request for info re decontamination operations of experimental Dresden test loop & Peach Bottom regenerative heat exchangers DNL rapt re chelating agent study enci.

 BROWNING.R.E. Division of Waste Management. B0/10/24. 2pp.
- --8012160093 Requests info re decontamination operations of experimental Dresden test loop & Peach Bottom regenerative heat exchangers. Also requests BNL rept re chelating agent study. Related documentation encl. DREY.L.A. Affiliation Unknown. 80/10/06. 9pp.
- --8012160099 Draft safety evaluation supporting 791114 application for amend to License DPR-2, re deletion of Tech Specs requirement for primary containment integrity during chemical cleaning of primary cooling sys.

 # Office of Nuclear Reactor Regulation, Director, 80/11/26. Spp.
- 8012170552 Forwards IE Info Notice 80-29, Suppl i, "Broken Studs on Terry Turbine Steem Inlet Flange." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/26.

 2pp. 07244; 286.
- 8012110602 Ack receipt of 801112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/80-16, 50-237/80-19 & 50-249/80-23.

 HIND.J.A. Region 3, Chicago, Bafeguards Branch, 80/12/01, ip. 07226:175.
- --8012110608 Responds to NRC 801022 ltr re violations noted in IE Insp Repts 50-010/80-11, 50-237/80-19 & 50-249/80-23. Corrective action withheld (ref 10CFR2.790). ABEL, J. 8. Commonwealth Edison Co. 80/11/12, 1p. 07226:176.

All askers a Ast

- 8012230065 Responds to IE Bulletin 80-21, "Valve Yokes Bupplied by Malcolm Foundry Co.Inc." No valve parts cast by Malcolm Foundry planned for use or in use at facilities.
 RAUBCH.T.J. Commonwealth Edison Co. 80/12/05. 2pp. 07311:081.
- 8012310629 Ack receipt of 801125 Itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-010/80-19, 50-237/80-21 & 50-249/80-25.

 HEIBHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09. 1p. 07371:052.
- --8012310630 Responds to NRC 801104 ltr re violations noted in IE lnsp Repts 50-010/80-19, 50-237/80-21 & 50-249/80-25. Corrective actions: cleaned erwas & removed combustible matl. ABEC. J. S. Commonwealth Edison Co. 80/11/25. 4pp. 07371:053.
- 8012240427 Add1 response to FOIA request for documents re imposition of civil penalties. NRC requests for congressional authorization for more severe penalties & responsibilities & behavior of nuclear plant operators. Forwards investigation rept. FELTON. J. M. Division of Rules and Records. 80/12/12. 1p. 07324:310.
- --8017240432 "Investigation of Alleged Sleeping Control Room Operators at Dresden Nuclear Power Station Korris, IL, 800888." CUMMIN9S, J. J., BTRICKLER, L. J. Office of Inspector & Auditor. 80/09/17. 34pp.
- 8012300118 Discusses IE insp on 800723 & forwards notice of violation & notice of proposed imposition of civil penalty.

 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/12/19. 2pp. 97356:283.
- --8012300124 Notice of violation from insp on 800723. Noncompliance noted; waste math delivered in improper packaging w/no provision for securing lid.

 # Office of Inspection & Enforcement, Office of the Director. 80/12/19. 1p. 03810:174.
- --8012300130 Notice of proposed imposition of civil penalty in amount of \$4,000 for item of noncompliance noted in IE insp on 800723.

 * Office of Inspection & Enforcement, Office of the Director. 80/12/19, 1p. 07356:236.
- R. Periodic operating reports & related correspondence
- 8012140419 Forwards monthly operating repts for Nav 1980. SCOTT, D. J. Commonwealth Edison Co. 80/12/08. ip. 07254: 124.
- --B012160420 Monthly operating repts for Nov 1980. CIESTK1EWICZ, S. Commonwealth Edison Co. 80/12/01. 15pp. 07253:125.
- 8. Reportable occurrences, LERs & related correspondence
- 8012040270 Ack receipt of 801030 itr re investigation of alleged release of radioactively contaminated water. Requests addition on conclusions that flowpaths w/excess background levels have not & are not transporting contaminated water. REPPLER.J.O. Region 3. Chicago, Office of the Director. 80/j1/14. 2pp. 07162:335.
- --8012040333 Responds to Bept 1980 allegations re release of contaminated water into environ. Investigation noted no detactable threat to public & insp revealed no discrepancies which could result in leakage. Forwards detailed summary of results.

 REED.C. Commonwealth Edison Co. 80/10/30, 4pp. 07162:337.
- DOCKET 50-13 BABCOCK & WILCOX CO. CRITICAL FACILITY

 F. Security, medical, emergency & fire protection plans
- B0120202B6 Discusses NRC 801106 ltr requesting submittal of names of personnel responsible for smergency planning NRC should direct such requests to AF Olsen QLSEN,A.F. Babcock & Wilcox Co. B0/11/25. ip. 07141:355.
- DOCKET 30-20 MASSACHUSETTS INST. OF TECH. RES. REACTOR
 P. Operating license stage documents & correspondence
- 80:2110718 Forwards Amend 17 to License R-37 & safety evaluation. MILLER, J. R. Stendardization & Special Projects Branch. 80/11/21, 2pp. 07225:088.

- --8012110726 Amend 17 to License R-37 authorizing HIT to receive, possess & analyze byproduct math previously activated in other reactors.
 HILLER, J. R. Standardization & Special Projects Branch. 80/11/21.
 Spp. 07225:070.
- --8012110734 Safety evaluation supporting Amend 17 to License R-37.

 * Office of Nuclear Reactor Regulation, Director. 80/11/21, 3pp. 07225:075.
- S. Reportable occurrences, LERs & related correspondence
- S012030686 RO 50-020/79-4A: supplemental info re apparent fuel element cladding failure originally reported on 790702. Caused by off deficiency. Element continuously monitored.

 CLARKL. Massachusetts Institute of Technology. 80/11/26. Spp. 07151: 147.
- DOCKE: 50-27 WASHINGTON BTATE UNIV. RESEARCH REACTOR
 F. Security, medical, emergency & fire protection plans
- 8012300274 Forwards revised portions of physical security plan in response to comments in NRC 801216 ltr.Plan withheld (ref 10CFR2.790), WILSONAM.E. Washington State Univ. 80/12/23. 1p. 07349:361.
- DOCKET 50-27 YANKEE-ROWE NUCLEAR POWER STATION

 F. Security, medical, emergency & fire protection plans
- 80(2110308 Natifies of interim rule suspending completion dates for fire protection mods previously approved by NRC.FR notice encl. EISELHUY, D. O. Division of Licensing. 80/10/31. 5pp. 07224:123.
- 8012040177 Informs of review & resulting mods to emergency notification sys & health physics network MRC will have lamps installed on emergency telephones in all control rooms. ORIER, B.H. Region i, Philadelphia. Office of the Director. 80/11/14. 2pp. 07170:225.
- 8012080921 Forwards comments on emergency plan. Addl info is required to meet criteria in NUREG-0654.
 CRUICHFIELD, D. Operating Reactors Branch 5. 80/11/17. 25pp.
- 8012020111 Reaffirms belief in use of shift supervisor as fire brigade laader. As alternative proposes use of supervisors until Jul 1982. Clarifies BER commitment to control not prohibit smoking in safety-related & major fire hazard areas. KAY, J. A. Yankee Atomic Electric Co. BO/11/20, 2pp. 07141:077.
- R. General correspondence
- 80:2100072 Requests response to encl constituent E Permett 80:102 ltr re health & safety concerns of families near plant. CONTE, 8. O. House of Rep. 80/11/20, 5pp, 07:187:001.
- 8012270249 Informs of relocation of engineering of effective 801222. KAYJ.A. Yankee Atomic Electric Co. E0/12/18. ip. 07342:338.
- P. Operating license stage documents & correspondence
- 7810240095 Presents results of grout investigation described in 780925 ltr to MRC.Concludes that heavy metals are present which will affect pool water chemistry.

 JOHNSON, N. P. Yanker Atomic Electric Co. 78/10/18. ip.
- 7011280221 Submits design & safety class info applicable to parts of alternate shutdown methods mod Entire new sys piping designed per util Engineering Dept OA Hanual & components purchased & installed per Operational OA Manual VOCAP-1-A. OROCE, R. H. Yankee Atomic Electric Co. 78/11/21, 1p. 94012:090.
- 7909210287 Notifies that revisu of electric power systems & associated analyses are being conducted as indicated in 790808 ltr. Addl two months necessary to complete review. Completed analysis expected mid-Dec 1979.

 0800E-R.H. Yanker Atomic Electric Co. 79/09/14. 2pp. 00979:231.
- B012020753 Forwards seigmic qualifications of auxiliary feedwater sys in operating PMRs & describes program NRC is undertaking to review capability of operating PMRs to remove decay heat following earthquake.
 EIBENHUT.D.G. Division of Licensing. 80/10/21. App.

- 8012110377 Forwards final review of SEP Topic VI-4 re alectrical, instrumentation & control aspects of override of containment purge valve isolation. Evaluation will be basic input to integrated safety assessment for unit. CRUTCHFIELD. Operating Reactors Branch 5. 80/10/24. 8pp. 07224:153.
- 8012040188 Summary of 801009 meeting u/util re progress to date & further efforts in area of seismic evaluation. Seismic model expected to be completed by early 1981. Another meeting to be held in Nov re generation of NRC spectrum.

 CARUSO.R. Operating Reactors Branch 5. 80/10/27. App. 07158:096.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensue confirmation in 45 days that Encl 1 implementation dates will be met. EISEN-HUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 80:2220563 Ltr to all power reactor licensees forwarding NUREG-0619: "BKR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EISENHUT.D.G. Division of Licensing. 80/11/13. 1p.
- B012020242 Informs of currently assessing two parallel approaches to resolve pertinent SB LOCA applicable issues. One approach will mean mod & requalification of currently licensed model. Second approach will mean selection of newer codesRelap 5. KAY, J. A. Yantee Atomic Electric Co. 80/11/21. 2pp. 07148:185.
- 8012170274 Requests detailed description of turbine insp & repair efforts reported in 800827 & 0705 ltrs. Effects of accident on rotor spindle including damage, repair & mod also requested.

 CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/01. 3pp.
- B0121900B4 Notification of B01217 meeting w/util in Bathesda.MD to discuss facility SEP seismic evaluation. CARUSD.R. Operating Reactors Branch 5. B0/12/04. 2pp. 07279:094.
- 8012220485 Responds to 800911 memo requesting that Dfc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of 1E survey. DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors, Low level waste storage facilities have been expandedat 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANOART,R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- B012090423 Forwards preliminary probabilistic risk assessment, interim seismic design basis & preliminary structural evaluation, summarizing util position while detailed seismic analyses are performed.

 TRIBBLE, J. E. Vankee Atomic Electric Co. B0/12/05. 9pp. 07207:029.
- --8012070434 "Preliminary Probabilistic Risk Assessment for Yantee Nuclear Power Station."
 + Yankee Atomic Electric Co. 80/12/05. 29pp. 07207:038.
- --- BD12090443 "Interim Seismic Design Basis for Yankee Nuclear Power Station."
- Station." * Boston Edison Co. 80/12/05. 27pp. 07207:067.
- --8012070448 "Preliminary Structural Evaluation for Yankee Nuclear Power Station."

 * Yankee Atomic Electric Co. 89/12/01. Spp. 07207:094.
- B012240239 Forwards YAEC-1231, "Application for Lower Plenum Phase Separation Model to Yankee Rowe Large Break LUCA Analysis." KAY, J. A. Yankee Atomic Electric Co. B0/12/10. ip. 07322:168.
- --8012240262 "Application of Lower Plenum Phase Separation Model to Yankes Rowe Large Break LOCA Analysis." TURNAOE.J. C., BRGINN.G. J., HARVEY.R. C. Yankee Atomic Electric Co. YAEC-1231. 80/11/20. 104pp. 07322:149.
- 8012240174 Forwards commitment re implementation dates for post-TMI requirements per NRC 801031 ltr. Includes revised dates & justification for delays. Changes to Mestinghouse owners' group schedule may require changes to util commitments.
 HEIDER.L.H. Yankee Atomic Electric Co. 80/12/15. 14pp. 07323:038.

- B012240489 Notification of B01218 meeting w/BEP owners group in BethasdayMD for discussions on BEP program schedule for license topic completion & assignment of lead topics to plants.

 RUSBELL, N. T. Systematic Evaluation Program Branch, 80/12/16, 2pp. 07324:104.
- G. Inspection reports, IE Bulletins & correspondence
- 7812010146 Responds to IE Bulletin 78-12 Requests time extension until 790131 to provide record searches requested. OROCE.R.H. Yankee Atomic Electric Co. 78/11/13. 1p. 74418:088.
- 7904190132 Responds to IE Bulletin 79-02 requesting reassessment of design criteria utilized for design of pipe support base plates. Util proposes to defer response until systematic evaluation program design basis is established.

 MODDY, D. E. Yankee Atomic Electric Co. 79/03/20. 1p. 03142:223.
- 7706:130:106 Responds to IE Bulletin 79-04, "Incorrect Weights for Bwing Check Valves Mfg by Velan Engineering Corp." Velan valves are used in ECCB. Use of corrected weights is compensated for by design code inherent conservatism.

 ORGCE, R. H. Yankee Atomic Electric Co. 79/05/02. 2pp. 02427; 203.
- 7907070076 Responds to IE Bulletin 79-09. Undervoltage trip devices are not installed. AK-2 circuit breaker used in dissel generator incoming lines, emergency bus-bus tie, pump feeder circuit breakers & emergency motor control ctr circuit breakers. ORUCE, R. H. Yankee Atomic Electric Co. 79/05/18. 2pp. 00311:086.
- 7907050153 Responds to IE Bulletin 79-10 re examination of reactor operators.
 MOODY.D.E. Yankee Atomic Electric Co. 79/05/22, 3pp. 00287:101.
- 7907240626 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06.06A & 06.Amend 1.Meeting w/owners of operating plants having Hestinghouse-designed sys scheduled for 790530 in Bethesda.MD.

 8CHMENCER.A. Operating Reactors Branch i (Pre 790625). 79/05/22.
 4pp. 02546:238.
- 7907190684 Responds to IE Bulletin 79-06A (Ref 6).Lists ECCB cutback or termination criteria & endorses termination of main coolant sys pumped flow as core cooling method following accident. MODDY.D.E. Yankee Atomic Electric Go. 79/05/24. 2pp. 00536:239.
- 7908030172 Submits addl info in response to IE Bulletin 79-06a.
 Emergency procedures revised to address symptoms of loss of cooling & also direct operator to consult saturation pressure curve which is now part of affected procedures.
 MOGDY, D. E. Yankee Atomic Electric Co. 79/06/20. 4pp. 00580:343.
- 7908070673 Responds to IE Bulletin 79-11 re faulty overcurrent trip devices in Hestinghouse circuit breakers. Hestinghouse Type DB circuit breakers are not used in safety-related Class IE circuits.

 ORDER, R.H. Yankee Atomic Electric Co. 79/07/07. ip. 00539:321.
- 7908160563 Advises that util is presently compiling addl data to suppl response to IE Bulletin 79-02. Addl info will be submitted before 790720.

 MOODY, D. E. Yankse Atomic Electric Co. 79/07/11, lp, 00691:356.
- 7908070712 Responds to IE Builetin, Item 5. Steam generator feedwater norries shall be performed in mid-Sept 1979. Three emergency methods are available to provide diverse indications of leakage in case of feedwater leak in containment.

 MOODY, D. E. Vankee Atomic Electric Co. 79/07/16. 2pp. 00522: 266.
- 7708270311 Responds to IE Bulletin 79-14. Proper support location & design of piping sys is evidenced by lack of any piping or support distress when constantly loaded.
 QROCE:R.H. Yankee Atomic Electric Co. 79/07/18. ip. 02445:323.
- 7908200004 Responds to IE Bulletin 79-02 & 790621 request for add1 infore visual insps on hangers & restraints for ECCB vapor container long-term recirculation sys & pressurizer safety & relief valve discharge line.

 MUUDDY, D. E. Yankee Atomic Electric Co. 79/07/20. 2pp. 00771:348.
- 7909200110 Notifies that administering of operator & senior operator examinations will resume. Decision based on facility response to IE Bulletins 79-05.79-06.79-064. 79-068. COLLINS.P.F. Operator Licensing Branch. 79/07/27, ip. 00974:299.
- 7909200465 Responds to IE Bulletin 79-02. Provides supplemental info re 790813 start of testing program on concrete expansion anchors used on piping supports in safety class sys. MOODY.D.E. Yankee Atomic Electric Co. 79/08/13. 2pp. 00972:293.

- 7910030679 Responds to IE Bulletin 79-17. Welds were examined volumetrically. No evidence of cracking in safety-related stainless steel piping sys. Plant will shut down for one wk beginning 770908 to perform visual weld tests.

 ORDGER. H. Vantee Atomic Electric Co. 79/08/24. 4pp. 01091: 304.
- 7909100441 Responds to NRC 790807 request for additinfo re compliance w/IE Bulletins 79-06A & 79-06A, Revision i.on void formation in primary coolant sys & verification of operability of redundant safety-related sys.
 MODDY, D. E. Yantse Atomic Electric Co. 79/08/30, 2pp, 00933: 355.
- 7910040432 Responds to 1E Bulletin 79-03 Seam welded A312 pipe was not used at facility.

 GROCE.R.H. Yankee Atomic Electric Co. 79/09/07. 1p. 01095:337.
- 7910180149 Responds to IE Bulletin 79-04C. Procedures have been revised to assure manual tripping of reactor coolant pumps upon reactor trip & to assure presence of licensed operators in control room at all times.

 GROCE
- 7910310256 Responds to IE Bulletin 79-13. "Cracking in Feedwater Sys Piping." Item 6. All deficient welds repaired or replaced, then radiographed. Feedwater nozzie-to-elbow welds will be radiographically examined at next refueling outage. OROCE, R. H. Yankes Atomic Electric Co. 79/10/10. 2pp. 01247:355.
- 7911230340 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." No connection between exciter transformer & generator. Emergency generators have completed 24-h full-load test. OROCE,R.H. Yankee Atomic Electric Co. 79/10/29, ip. 01388:003.
- 7912140282 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Test program instituted to assure proper installation of expansion anchor bolts.

 ORDICE, R. H. Yankee Atomic Electric Co. 79/10/31, 2pp. 01573: 298.
- 8012020199 Forwards IE Insp Rept 50-029/80-15 on 800907-12 No noncompliance noted Insp summary only encl (ref 10CFR2.790). MARTIN.N.O. Region 1, Philadelphia, Safeguards Branch. 80/10/01. 2pp. 07142:090.
- --8012020205 IE Insp Rept 50-029/80-i5 on 800907-i2. No noncompliance noted. Hajor areas inspected: security plan, security program audit, security organization, physical barriers & access control. Details withheld (ref 10CFR2. 790).

 LADUN, R.H. Region i, Philadelphia, Office of the Director.
 DEVLIN, J. W. Region i, Philadelphia, Safeguards Branch. B0/09/25.
 ip. 07142:092.
- 8012240266 Forwards IE Insp Rept 50-029/80-14 on 800808-0915 & notice of violation.
 BRUNIER.E.J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/20. 2pp. 07325:118.
- --801224027i Notice of violation from insp on 80808-0915.

 * Region i, Philadelphia, Office of the Director. 80/09/26. ip. 07325:120.
- --8012240277 IE Insp 50-029/80-14 on B00808-0715. Noncompliance noted: failure to maintain barricade of high radiation area. FOLEY.T. Region I, Philadelphia, Office of the Director. HARTIN.T.T. Region I, Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/26. Spp. 07325:121.
- 8012090070 Ack receipt of 801006 itr informing NRC of steps taken to correct violations noted in IE Insp. Rept 80-029/80-12. BRUNN:CR.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/23. ip. 07198:109.
- --8012090074 Responds to NRC 800922 ltr re violations noted in IE Insp. Rept 50-029/80-12. Corrective actions withheld (ref 100FR2. 790).
 MODDY, D. E. Yankee Atomic Electric Co. 80/10/06. 2pp. 07198:101.
- --8012070074 Forwards IE Insp Rept 30-029/80-12 on 800714-0806 & notice of violation.
 BRNNNRR.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/22, 2pp. 07198:103.
- --80120700B1 Natice of violation from insp on 800714-0806.Portions withheld (ref 10CFR2.770).

 # Region i, Philadelphia, Office of the Director. 80/07/16. 1p. 07198:103.

- --B0120700B4 IE insp Rept 50-029/80-12 on 800714-0806. Noncompliance noted: failure to confirm that access controlled doors were physically secured. Portions withheld (ref 100FR2.790). FOLEY. T. Region 1. Philadelphia. Office of the Director. HARTIN. T.T. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 80/09/16. 10pp. 07198:106.
- 8012220004 Forwards IE Insp Rept 50-027/80-17 on 800922-24.No noncompliance noted, BRUNNER.E.J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/24. 2pp. 07306:271.
- --8012220006 IE insp Rept 50-029/80-17 on 800922-24. No noncompliance noted Hajor areas inspected containment integrated leak rate test 4 licensee actions on previous findings.
 REXITO, W.A. Region 1, Philadelphia, Office of the Director.
 CAPHTOH, D.L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/21. 5pp. 07306:273.
- B012170392 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/30, 1p. 07269:088.
- 8012120150 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 60/11/06. 1p. 07228:346.
- B012190353 Informs util of issuance of new NRC personnel identification badges effective after 801130 Example enci. MARTIN, M. J. Region i. Philadelphia. Safeguards Branch. 80/11/06. 2pp. 07286: 123.
- B0120B015B Forwards IC Info Notice 80-40. "Ercessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactar Depressurization." No written response required. GRIER, B. H. Region 1, Philadelphia. Office of the Director. B0/11/07. 1p. 071B1:208.
- ED12080483 Forwards IE Info Notice 80-14, "Failure of Swing Check Valve in Decay Heat Removal Eys at Davis Besse Unit 1." No response require6. GRIERRB.H. Region 1. Philadelphia. Office of the Director. 80/11/10. 1p. 07182:339.
- 8012040045 Forwards IE Builetin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, 8. H. Region i. Philadelphia, Office of the Director. BO/11/14. 19. 07167:352.
- 8012:20682 Advises that written response is required to IE Bulletin 80-23. "Failures of Solenoid Valves Rfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/19. ip. 07293:117.
- 8012040509 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Written response raquired. Requests info on manpower espended. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/21. 2pp. 07169:208.
- B012090610 Forwards Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER.B. H. Region 1. Philadelphia, Office of the Director. B0/11/24. lp. 07174:104.
- R. Periodic operating reports & related correspondence
- B012180270 Forwards monthly operating rept for Nov 1980. MODDY, D. E. Yankee Atomic Electric Co. 80/12/10. 1p. 03794:025.
- --8012180276 Monthly operating rept for Nov 1980. BERNARD, D. M. Yankee Atomic Electric Co. 80/12/10. 5pp. 02794:026.
- S. Reportable occurrences, LERs & related correspondence
- 7910190174 RO 50-29/79-21: during volumetric examination of steam generator feedwater nozzle areas, unacceptable celds were found. Welds will be corrected before plant startup.

 AUTIO, H. A. Yankes Atomic Electric Co. 79/09/11. 1p. 90169:362.
- 8012020470 Forwards LER 80-019/03L-0. AUTIO.H.A. Yankee Atomic Electric Co. 80/11/26. 1p. 07148:234.

- --BD12020475 LER 80-019/03L-0: on 801030, during turbine startup in Mode 2, left hand throttle valve failed to close tightly causing turbine to accelerate. Caused by pilot valve failure. Left hand throttle disassembled & pilot valve replaced. FRENCH, L. D. Yankee Atomic Electric Co. 80/11/28, ip. 07148:235.
- 8012050390 Forwards LER 80-020/03L-0. AUTIO. H. A. Yankee Atomic Electric Co. 80/12/01, 1p. 07173:243.
- --B012050378 LER B0-020/03L-0: on 801101, primary vent stack iodine monitor alarmed & was declared out of svc. Caused by moisture in sampled air exceeding capacity of unit air dryer. Detector dried out & reinstalled.

 MAY.E. L. Yankee Atomic Electric Co. B0/12/01. 1p. 07173:244.
- B012090292 Forwards LER 80-017/03X-0. AUTIO.H.A. Yankee Atomic Electric Co. 80/12/05. 1p. 07201:133.
- --8012090293 LER 80-017/03X-0: on 801012, during maint outage while performing recalibr of Steam Generator 2 narrow range level trip sys.low level scram setpoints found below Tech Bpec linits by 1.5 & 1.3 inches. Specific cause Unknown.
 STAU9. J. L. Yankee Atomic Electric Co. 80/12/05. 2pp. 07201: 134.
- 8012090301 Forwards LER 80-018/03X-0. AUTIO H.A. Yantse Atomic Electric Co. 80/12/05. 1p. 07201:126.
- --B012090304 LER 80-018/03X-0: on B01012.during recalibr of narrow range level trip sys.low level scram satpoints were found to operate below Tech Specs. Caused by recalibr process. Original LER should not have been submitted.

 BTAUB.J.L. Yankee Atomic Electric Co. 80/12/05. 2pp. 07201:127.
- 8012160509 Forwards LER 80-021/03L-0. AUTIO.M.A. Yankee Atomic Electric Co. 80/12/11. 1p. 07261:162.
- --B012160511 LER B0-021/03L-0: on B01111, plant trip & loss of Z-126 i18-kV transmission line occurred due to relay action. Caused by ground fault on E-131 i15-iV line. Line Z-126 re-energized after 10 minutes.

 FRENCH, L. D. Yankee Atomic Electric Co. 80/12/11. 1p. 07261: 163.
- 8012300595 Forwards LER 80-022/03L-0. AUTID.H.A. Yantee Atomic Electric Co. 80/12/26. 1p. 07362:318.
- --8012300600 LER 80-022/03L-0:on 801127, instrument air problems resulted in ecratic steam generator level control Caused by personnel error.Personnel reinstructed. HAY.E.L. Yankee Atomic Electric Co. 80/12/26. 1p. 07362:319.
- DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR

 G. Inspection reports, IE Bulletins & correspondence
- 8012190724 Forwards IE Insp Rept 50-047/80-01 on 801001.No noncompliance noted.
 SMITH, O. H. Region I, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/28. 2pp. 07288:044.
- --B012190728 IE insp Rept 50-047/80-01 on B01001.No noncompliance noted. Major areas inspected radiation monitoring access to facility, audits maint & records.
 CLEMONS.P. Region 1, Philadelphia, Office of the Director, WAPP.P.J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. B0/10/17. 3pp. 07288:046.
- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

 F. Security, medical, emergency & fire protection plans
- B012:90155 Releases public version of licensee emergency plan. FELTON J. M. Division of Rules and Records. B0/12/02. ip. 07285:041.
- --8012190159 Public version of emergancy plan, submitted in support of application for renewal of License R-81.

 4 Union Carbide Corp. 80/05/30. 24pp. 07285:042.
- ~-B012190165 EIS, submitted in support of application for renewal of License R-BI.Univ of WI emergency plan encl.

 + Union Carbide Corp. B0/05/31. 10pp. 07285:048.

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

Q. Adjudicatory correspondence

- 8012270145 Notice of 810106 second prehearing conference in San Francisco. CA re discussion of all pending matters, including re-examination of status of discovery & further scheduling. No limited appearance statements will be heard. OROSEMAN, H. Atomic Safety and Licensing Board Fanel. 80/12/10. ip. 07344:051.
- 8012310236 Motion for issuance of order containing ABLB rulings granting joint petition to intervene Notice of appearance & Certificate of Byc encl.
 TREBY.8.A. Hearing Branch 1. 80/12/24. 5pp. 07370:028.
- P. Operating license stage documents & correspondence
- 8012050149 Forwards "Analysis of Subgrade Rupture Mechanism at GETR." OILLILAND, D. L. General Electric Co. 80/12/03. 2pp. 07173:348.
- --8012050151 "Analysis of Subgrade Rupture Mechanism at GETR." MEEHAN,R.: TRAUBENIK.M. Earth Sciences Associates. 80/12/31. 26pp. 07173:350.

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

- P. Operating license stage documents & correspondence
- 8012120133 Advises that NRC 801105 ltr forwarding Amend 14 to License R-33 contained incorrect ref.License R-33 should be referenced in Paragraph 1. MILLER.J.R. Standardization & Special Projects Branch. 80/11/20. 2pp. 07240:006.

DOCKET 50-83 UNIV. OF FLORIDA TRAINING REACTOR

I. Financial information

- B012160107 Forwards financial qualifications for Univ of FL & Annual Financial Rept FY79.in response to NRC request for add1 info to support application for renewal of License R-56. JACOBB.A.M., CHEN, H., D. INZ.N. J. Florida, Univ. of, Gainesville, B0/12/08. 10pp. 07248:344.
- --8012160110 Annual Financial Rept FY79. ELMORE,W.E. Florida: Univ. of, Gainesville. 79/12/03. 21pp. 07248:334.
- P. Operating license stage documents & correspondence
- 8012300506 Requests extension for submittal of required documents for relicensing of Univ of FL teaching reactor. Entire package will be delivered for printing by 810115 W/expected i0-day turnaround & mailing by or prior to 810131. DIAT.N.J. Fiorida. Univ. of, Cainesvilla. 80/12/19. 2pp. 07346;282.
- R. Periodic operating reports & related correspondence
- 8012230344 Forwards "Annual Progress Rept of Univ of FL Training Reactor Sept 1979 - Aug 1980." DIAZ,N.U. Florida. Univ. of. Gainesville. 80/12/18. 1p. 07312:212.
- --8012230348 "Annual Progress Rept of Univ of FL Training Reactor: Sept 1979 - Aug 1980. " DIAZ-N.J. Florida Univ. of: Gainesville, DRO-4014-10. 80/11/30. 24pp. 07312: 213.

DOCKET 50-89 GENERAL ATOMIC CO.

- J. Insurance & indemnity information
- 8012020562 Forwards Endorsement 51 to MAELU Policy MF-59. CORREALM.A. Marsh & McLennan.Inc., M & M Nuclear Consultants, Inc. Div. 80/11/20, 2pp. 07148:071.

DOCKE1 50-97 CORNELL UNIV. ZERO POWER REACTOR
J. Insurance & indemnity information

B01203041B Executed Amend 10 to Indemnity Agreement E-4,increasing amount of financial protection.
SALTZMAN, J. Utility Finance Branch (formerly Antitrust & Indemnity).
DYMEK, E. J. Cornell Univ. 80/12/01. 1p. 07174:025.

DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR

F. Security, medical, emergency & fire protection plans

B012020286 Discusses NRC B01106 ltr requesting submittal of names of personnel responsible for emergency planning NRC should direct such requests to AF Olsen.

OLSENIA.F. Babcock & Wilcox Co. B0/11/25. 1p. 07141:355.

DOCKET 50-112 UNIV. DF OXLAHOMA RESEARCH REACTOR

- G. Inspection reports, IE Bulletins & correspondence
- 8012120539 Forwards IE Insp Rept 50-112/80-01 on B01103-04. No noncompliance noted. KELLY, J. A. Region 4, Dallas, Office of the Director. B0/11/25. 1p. 07237:134.
- --8012170562 IE Insp Rept SO-112/80-01 on 801103-04. No noncompliance noted. Major areas inspected: security plan & organization, access control, alarm sys, keys, locks & hardware. Details withheld (raf 10CFR2. 790).
 EVANB.C.A., KELLY, J.A. Region 4, Dallas, Office of the Director. 80/11/24. 1p. 07237:135.

DOCKET 59-124 VIRGINIA POLYTECH INST. TRAINING REACTOR
F. Security, medical, emergency & fire protection plans

- B012030690 Forwards security plan & application for renewal of License R-62. W/o ancls.
 CURTNERLA.P. Virginia Tech. 80/11/26. lp. 07151: 234.
- 8012230512 Releases public version of univ emergency plan. FELTON, J. M. Division of Rules and Records. 80/12/12. 1p. 07312:301.
- --B012230517 Forwards univ draft emergency plan. PARKINGON, T. F. Virginia Tech. 80/03/19. ip. 07312:302.
- --8012230518 Public version of draft emergency plan. * Virginia Tech. 79/09/30. 12pp. 07312:303.
- P. Operating license stage documents & correspondence
- 8012090025 Forwards Amend 4 to License R-62 & safety evaluation. MILLER.J.R. Standardization & Special Projects Branch. 80/11/21. 2pp. 07199:310.
- --B012070031 Amend 4 to License R-62, allowing testing of one 13-plate fuel element between 801201 & 3i, providing power level remains below 1 KW & max excess reactivity is limited to certain levels.
 MILLER.J.R. Standardization & Special Projects Branch. 80/11/21.
 4pp. 07199:313
- --B012090035 Safety evaluation supporting Amend 4 to License R-62.

 * Office of Nuclear Reactor Regulation, Director. 80/11/21. 3pp.
 07199:317.
- BO12030690 Forwards security plan & application for renewal of License R-62. W/o encls.
 CURTNER, A. P. Virginia Tech. BO/11/26. 1p. 07151; 234.

DOCKET 50-133 HUMBOLDT BAY POKER PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8012170372 Requests revised util emergency plan, addressing impact of earthquakes on emergency preparedness. Primary concern should be stored fuel, but availability of resources & personnel & transportation & communications links should be included. IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/19. 3pp. 07187:001.

- --80]2170392 Requests review of effects of earthquakes & volcanic eruptions on state & local emergency plans in areas nearby CA nuclear power plants. Licensee energency plans will be revised to address primary concerns. ORIMPS.B.K. Emergency Preparadorss Program Office (after Boilly see I&E). B0/11/03. 2pp. 07322:002.
- G. Adjudicatory correspondence
- 8012270518 Notice of intent to participate as interested state. Certificate of Svc enci. KERR.J.E. SIMPSON.J.C. DUMAS.G.T. California, State of. 80/12/01. Spp. 07332:292.
- P. Operating license stage focuments & correspondence
- B012160050 Ltr to operating plant licensees, DL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met.

 EISENHUT, D. O. Division of Licensing. B0/10/31. 7pp.
- 801222035B Ltr to all CP & OL holders for BURs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.
 EISENMUT, D. G. Division of Licensing. 80/11/04. App.
- B012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BMR Faedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," Confirmation that implementation dates will be met must be sent within 45 days. N/o encl. EISENMOT.D. G. Division of Licensing. BO/11/13 ip.
- B01209033B Responds to B0100! itr re environ qualification of safetyrelated equipment.Facility in cold shutdown mode until completion of ongoing geologic investigation. Environ testing schedulas will be submitted when seisnic issue is resolved. CRANE.P.A. Pacific Gas & Electric Co. 80/12/01. 1p. 07201:164.
- 8012220485 Responds to BOOP11 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of meed to comply w/revised Agreement State burial site conditions. Forwards results of EE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
 BO/12/04. 2pp.
- --8012220595 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed u/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Systems Branch. 80/11/06. Bpp.
- D. Inspection reports. IE Bulletins & correspondence
- 8012170/15 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No Hritten response required.
 ENCELEKFIIR.H. Region 5. San Francisco. Office of the Director.
 80/10/24.
- 8012170857 Forwards IE Info Notice 80-39. "Malfunction of Solemoid Valves Mfg by Valcor Engineering Corp." No written response is required. ENGELKFULR. H. Region S. San Francisco. Office of the Director. 80/19/3t. 1p. 07266:047.
- B052120247 Forwards IE Builetin 80-21, "Valve Yotes Supplied by Malcolm Foundry Co. Inc." Written response required. ENCELKEH.R.H Region 5, San Francisco. Office of the Director. B0/11/06. ip. 07227:322.
- 8012030934 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safaty Relief Valve Operation to Cause Reactor Depressurization." No written response required. EXDELECTION. Region 5. San Francisco. Office of the Director. 80/11/07. ip. 07150:183.
- 8012080532 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Bys at Davis Besse Unit 1." No response required. EMSELKFIRR H. Region 5. San Francisco. Office of the Director. B0/11/10. 1p. 07183:032.
- 8012040225 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions. EMSELKFN.R.H. Region 5. San Francisco. Office of the Director. 80/11/14. p. 07158:146.

- 8012310549 Forwards IE Insp Rept 50-133/80-03 on 801110.No noncompliance noted. CREMS.J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch, 80/11/15. 2pp. 07366:020.
- ~-8012310554 IE Insp Rept 50-133/80-03 on 801110. No noncompliance noted. Major areas inspected: effects of 801108 earthquake. JOHNSON, A. D. Region 5: San Francisco. Office of the Director. STERNBERO, D. Region 5: San Francisco, Reactor Operations Nuclear Support Branch. 80/11/17. 2pp. 07346;022.
- BO12040465 Forwards IE Bulletin BO-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required. Requests info on manpower expended. ENGLIKEM, R.H. Region 5. San Francisco, Office of the Director. BO/11/21. 1p. 07163:325.
- 8012160097 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No response required. ENGELKER.R.H. Region 5. San Francisco. Office of the Director. 80/11/24. ip. 07262:100.
- B012160124 Forwards Suppl 1 to IE Info Notice 80-27. "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. EMSELKEN.R.H. Region 5. San Francisco. Office of the Director. B0/11/26. 1p. 07262:076.
- R. Periodic operating reports & related correspondence
- SO12150946 Forwards monthly operating rept for Nov 1980. WEEKS, E. D. Pacific Gas & Electric Co. 80/12/05. 1p. 07237:241.
- --8012150047 Monthly operating rept for Nov 1980. BAUM P.W. Pacific Gas & Electric Co. 80/12/02. 4pp. 07237:242.
- DOCKET 50-142 UCLA TRAINING REACTOR
- G. Adjudicatory correspondence
- 8012120648 Forwards 801104 ltr re Director's decision awaiting 801107 Commission determination re review. Alerts to possible error in decision.

 HRSCM, D. Committee to Bridge the Gap. 80/11/04. 1p. 07227:304.
- --8012120655 Discusses erroneous radiation measurements employed in DD-B0-30.At issue is whether exposure at UCLA math sciences bldg is 1.4 millirems/yr or 70 millirems/yr on roof. HIRSCH.D. Committee to Bridge the Gap. B0/11/04. 1p. 07227:305.
- B012310515 Forwards Committee to Bridge the Gap supplemental contention re UCLA Argonant research reactor & NRC position on contentions. W/o encl. WILSON, J.H. Standardization & Special Projects Branch. 80/11/24. 1p. 07365:268.
- BD12020699 Notice of JH Laverty withdrawal from & CP Woodhead appearance in proceeding.Certificate of Svc encl. HODDHEAD.C.P. Hearing Branch 3. LAVERTY.J.H. Hearing Branch 1. B0/11/28. 2pp. 07147:289.
- 8012030433 Informs that signed stipulation of contentions will be forwarded upon receipt.
 WOODHEAD.C.P. Hearing Branch 3. 80/11/28. 1p. 07150:075.
- 8012300196 Requests special prehearing conference re admissibility of remainder of intervenor contentions re 801128 stipulation. Conference will allow opportunity to respond to arguments in opposition to admission.

 PDLLOCK.M.S. Committee to Bridge the Oap. POLLDCK.M.S. Pollack.M.S. 80/11/28. ip. 07356:333.
- --8012300203 Statement of position re admissibility of remainder of intervenor contentions re B01128 stipulation. All contentions in Attachment 8 are those which all parties agreed upon as far as wording. Certificate of Svc encl. POLLOCK,M.S. Committee to Bridge the Oap. POLLOCK,M.S. Pollack,M.S. 80/11/28, 23pp. 07356:334.
- B012300351 Statement of position re B01124 unstipulated contentions, Requests opportunity to restate position on Contention XXI re emergency planning requirements if ASLBP permits further intervention. Svc list encl. CORMITER: M. H. California, Univ. of, Los Angeles, B0/11/28. 18pp. 07357: 152.

- 8012100161 NRC position supporting Committee to Bridge the Gap unstipulated Contentions V. 3, V. 11, X. 2 (excluding Subpart 2), XV (for consolidation w/X), XVII (except Subpart 2), XVIII & XXI.List of contentions & status encl. WOODHEAD.C. Hearing Branch 1. 80/12/01. 19pp. 07219:297.
- --B012100171 Btipulation agreeing that sole contentions asserted are set forth in Attachment A (stipulated contentions) & Attachments B & C (unstipulated contentions). Supersedes intervenor B00828 suppl to getition to intervene. POLLOCK, M. Committee to Bridge the Gap. LAVERTY, J. H. Hearing Branch 1. CORMIER; W. California, Univ. of, Los Angeles. 80/12/01. 22pp. 07219:316.
- 80:12230011 Forwards Committee to Bridge the Gap 80:1106 submittal containing security contention. W/o encl. WOODHEAD, C. P. Hearing Branch 3. 80/12/03. ip. 07311:166.
- 8012300105 Memorandum in opposition to motion to compel further answer to interrogatories. Related correspondence.
 REIDHAAR.D.L., WODDS, G.R., HELWICK, C. California, Univ. of, Berkeley. 80/12/12. 10pp. 07358; 332.
- 8012290284 Order requiring Committee to Bridge the Gap to pursue all records offered to date re 801128 motion to compel further answers to Interrogatories 4.5.6 & 9.
 BOXERS.E.S. Atomic Safety and Licensing Board Panel. 80/12/22.
 5pp. 07341:188.
- H. General correspondence
- 8012300022 Informs of new LPDR in Los Angeles, CA. MDDDHEAD, C. P. Hearing Branch 3. 80/12/03. 1p. 07356: 103.
- J. Insurance & indemnity information
- 8012020537 Forwards executed Amends 8 to Indemnity Agreements E-16 & E-53. Amend 8 supersedes Amend 7, therefore execution of superseded amends not necessary.

 DENESS, S. J. California, Univ. of, Berkeley. 80/11/24. 3pp. 04914:001.
- 8012290302 Forwards Amend 9 to Indemnity Agreement E-16. DENESS-8.J. California, Univ. of, Berkeley. B0/12/17. 2pp. 07346:116.
- P. Operating license stage documents & correspondence
- 8012180322 Forwards FR notice re establishment of LPDR for proposed license renewal for facility. FELTON.J.H. Division of Rules and Records. 80/12/05. lp. 07272:347.
- --B012180323 Notice of establishment of LPDR at West Los Angeles Regional Library, Los Angeles, CA for proposed license renewal of facility. FELTON, J.M. Division of Rules and Records. B0/12/05. 2pp. 07272:348.
- 8. Reportable occurrences: LERs & related correspondence
- B01217043B Responds to D Hirsh.Committee to Bridge the Gap 801104 ltr alleging discrepancy between estimated yearly exposure levels re License R-71 renewal. Discusses TLD program dascribed in license renewal application. HE08T.M. California. Univ. of. Los Angeles. 80/12/08. 2pp. 07267:141.
- DOCKET 50-143 PHILIPPINES REBEARCH REACTOR
- C. Utility Environmental Report (ER), amends & correspondence
- B012300281 Staff requirements memo ra Commission 801201 briefing on environ releases at facility & other fuel cycle plants. CHILK, S. J. Office of the Secretary of the Commission. 80/12/10. ip. 07357:064.
- DOCKET 50-148 UNIV. OF KANSAS RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- B012100531 Advises that revised emergency plan was submitted w/ application for renewal of License R-78.No feedback on plan has been received. FRIESEN.B.S. Kansas, Univ. of. 80/12/01. 1p. 07219:354.

- DOCKET 50-150 OHIO STATE UNIV. RESEARCH REACTOR

 G. Inspection reports, IE Bulletins & correspondence
- B012110788 Ack receipt of B01117 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-150/80-03. DAVIS-A.B. Region 3. Chicago. Fuel Facility & Materials Safety Branch. B0/11/28. ip. 07225:095.
- --8012110796 Responds to NRC 801014 ltr re violations noted in IE Insp Rept 50-150/80-03. Corrective actions: procedure revised to include methods for personnel accountability during emergency evacuation. REDMOND.R.F. Ohio State Univ. 80/11/17. 2pp. 07225:096.
- DOCKET 50-151 UNIV. OF ILLINDIS RESEARCH REACTOR

 F. Security, medical, emergency & fire protection plans
- 8012040198 Forwards physical security plan. Plan withheld (ref 100FR2 790).
 BECK.O.P. Illinois, Univ. of, Urbana-Champaign. 80/11/26. 1p. 07170:064.
- G. Inspection reports, IE Bulletins & correspondence
- 8012240472 Immediate action ltr confirming 801205 telcon re NRC 801204 insp of inadvertant removal of fuel temp thermocouple channels from svc on 801126. Facility will modify fuel temp thermocouple circuitry power supply by 801205. KEPPLER. J. O. Region 3. Chicago, Office of the Director. 80/12/05. ip. 07324:314.
- S. Reportable occurrences. LERs & related correspondence
- 8012090303 RD: on 801126, reactor was operated for 20 minutes w/o fuel temp indications on mater. Caused by student & operator error. Mods will be made to relocate pilot strip receptable & power for fuel temp instrumentation.

 BECK, O. P., MILAVICKAS, L.R. Illinois, Univ. of, Urbana-Champaign. 80/12/05. 4pp. 07201:110.
- DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT
- F. Security, medical, emergency & fire protection plans
- 8012190338 Informs of recently approved revised 10CFR50. 48 containing schedules for completion of all fire protection mods. No present implementation required as necessary addl info has not yet been approved.

 EISENHUT, D. G. Division of Licensing. 80/11/06. 6pp. 07286: 093.
- 8012080627 Forwards Suppl 3 to fire protection safety evaluation. All incomplete items except design of alternative safe shutdown capability have been acceptably resolved. LAINAS, O.C. Assistant Director for Safety Assessment. 80/11/14. 4pp. 07189:215.
- --8012080630 Suppl 3 to fire protection safety evaluation.

 * Office of Nuclear Reactor Regulation, Director. 80/11/14. App. 07188:219.
- B012020155 Discusses planned mods to emergency notification sys & health physics network. NRC will pay for installation of output jacks to provide capability for adding one-way speakers. N/o encl health physics network manual. KEPPLER, O. O. Region 3, Chicago, Office of the Director, B0/11/19. 2pp. 07148:200.
- 801209096B Informs that statement in util 801114 ltr re Region 3 acceptance of addition of training position to plant staff incorrect. Staff has no regulatory basis to require offshift staffing. Health physics appraisal encl. KEPFLER.J. G. Region 3, Chicago. Office of the Director. 80/11/25. 2pp. 07187:001.
- --8012090474 Notice of violation from health physics appraisal on 800303-14,

 ** Region 3, Chicago, Office of the Director. 80/06/13. 1p. 07187:001,
- 8012150058 Forwards Revision 3 to security plan. Revision withheld (ref 100FR2.790). HDFFMAN.D.P. Consumers Power Co. 80/12/10. ip. 07239:354.

Q. Adjudicatory correspondence

- 8012030271 Request for 10-day extension to file answering brief re ASLAB review of ASLB order on NEPA review. Behedule proposed by Christa-Naria on 801113 should be adopted for all parties. Oranted for ASLAB. 801125.

 O'NEILL, J. Affiliation Unknown. 80/11/20. ip. 06586:003.
- 8012110001 Hotion to be included on 10-day filing extension re review of memorandum & order of NEPA review & need for power issue decided by ASLB. Certificate of Svc encl. LEITHAUSER. J. Affiliation Untnown. 80/11/20. 2pp. 07223:108.
- 8012050415 Motion to include J Leithauser in 10-day filing extension rereview of memorandum & order of NEPA review & need for power issue decided by ASLB, Granted for ASLAB on B01124. s Affiliation Unknown. 80/11/24. 1p. 07173:290.
- B012290516 Request for extension until 801205 to file answering brief. Add1 time necessary for intra-agency review. Certificate of Svc encl. OSHERENMO, 0. Council on Environmental Quality. 80/12/04. 3pp. 07335: 168.
- 8012300247 Brief supporting ASLB finding that NEPA EIS requirements apply to util request to increase capacity of spent fuel pool. LEITHAUSER, J. A. Affiliation Unknown. 80/12/04. 8pp. 07357: 353.
- 8012290142 Request for extension until 801205 to file amicus curiae brief in spent fuel pool mod proceeding. Motion granted for ASLAB 801205.

 OBHERENKO, G. Council on Environmental Quality. 80/12/05. 1p. 07/209-001
- BO12290336 Brief in support of ASLB memorandum & order on NEPA review. EIB should be prepared Certificate of Evc encl. KNIQHT, C.F., OSHERENKO, G. Council on Environmental Quality. BO/12/05, 19pp. 07343:113.
- B012300055 Forwards brief in support of ASLB 800912 memorandum & order on NEPA review Brief filed two days late.

 D'NEILL.J. Affiliation Unknown. 80/12/05. 1p. 07308:001.
- --8012300059 Brief in support of ASLB 800912 memorandum & order on NEPA review. ASLAB should affirm ASLB decision to order full EIS for facility spent fuel pool expansion.

 O'NEILL, J. Affiliation Unknown. 80/12/04. 32pp. 0/308:001.
- 8012230270 Order allotting time for argument on 810109.NRC & CPC should confer to avoid duplicate arguments. ASLB should be advised of counsel to participate in argument by 810107.
 BISHOP, C. J. Administrative Branch. 80/12/12. 2pp. 07317:332.
- 8012300072 Notice of hearing on 810109 in Bethesda MD to discuss ASLB 800912 referred ruling. BIBHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/12/15. ip. 07358:345.
- 8012290054 Order granting JA Leithauser share of 30 minutes of argument time allotted to intervenors, Christa-Maria, et al & J ("Neill, jointly.
 BISHOP.C. J. Atomic Safety and Licensing Appeal Panel. 80/12/19.
 2pp. 07344:232.
- 8012290241 Response in opposition to intervenors Christa-Maria, et al. J 040e111 & JA Leithauser briefs in support of ASLB 800912 order for EIS preparation. Doctrine of MEPA nonretroactivity precludes respening. Certificate of Svc encl. MOORE, J. E. Hearing Branch 2. 80/12/22. \$7pp. 07341:145.
- 8012300350 Brief in response to briefs supporting ASLB 800912 order to prepare EIS on application for mod of spent fuel pool. Order should be reversed. Certificate of Svc encl. GALLO, J. THORNTON, P. Consumers Power Co. GALLO, J. 1sham, Lincoln & Beale. 80/12/22. 28pp. 07359:302.
- 8012300617 Draft motion to postpone until 810121, oral argument on applicability of NEPA in spent fuel poul mod case & need for pouer issue.

 LEITHAUSER, J. Affiliation Unknown. 80/12/24. ip. 07308:001.

H. General correspondence

8012270035 Supports proposed preparation of EIS ordered in spent fuel pol mod proceeding Requests studies re affects of long-term continuous venting of redianuclides.

MENDRIX.E.J. Affiliation Unknown, 80/12/03. 2pp. 07344:225.

- --8012290038 Ack receipt of 801203 ltr re ASLAB 800912 order in spent fuel pool capacity expansion proceeding. Presently, questions re contents of EIS are not presented by ASLB referral of ruling to ASLAB.

 SISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/12/09.
 3pp. 07344:227.
- P. Operating license stage documents & correspondence
- 8012020381 Summary of 800320 meeting w/util & Science Applications, In re-proposal to defer centain mods related to TMI lessons learned & other issues until plant risk assessment is completed impact of deferrals not assessed.

 SILVER. D. Operating Reactors Branch 5. B0/10/16. App. 07143:142.
- 8012110009 Forwards request for add1 info re degraded grid voltage. Table 1 does not show set point of second level undervoltage relays as stated in Ref a. CRUECHIELD, D. Operating Reactors Branch 5. 80/10/24. 4pp. 07223:247.
- 8012110027 Forwards review of SEP Topic VIII-3, electrical, instrumentation & control sys required for safe shutdown. Evaluation will be basic input to integrated safety assessment for unit. CRUTCHIELD.D. Operating Reactors Branch 5. 80/10/29. 16pp. 07223:261.
- 8012160360 Ltr to operating plant licensees. CL applicants & CP holders. Forwards NUREO-0737 re TMT action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISENHUT. D. G. Division of Licensing. 80/10/31. 7pp.
- B012220358 Ltr to all CP & OL holders for BMRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & groposed amends including core reloads.

 EISENHUT, D. O. Division of Licensing. 80/11/04. App.
- 8012170356 Notification of 801113 meeting w/util in Bethesda, MD to discuss containment overtemp conditions resulting from steamline break. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/12. 2pp. 07236:317.
- B012220543 Ltr to all power reactor licensees forwarding NUREG-0619, "BWR Feeduater Nozzle & Control Rod Drive Return Line Nozzle Cracking," Confirmation that implementation dates will be met must be sent within 45 days, W/o encl. EISENHUT, D. G. Division of Licensing. B0/11/13. 1p.
- 8012020106 Confirms B01124 meeting in Jackson,MI to discuss regional evaluation of regulatory performance at facilities.

 KEPPLER. J. G. Region 3. Chicago. Office of the Director. B0/11/19.

 1p. 07148:339.
- 8012010189 Resubmits 800922 ltr transmitting corrected Tech Spec change request re operability & surveillance testing requirements for fire protection equipment.

 DEWITT, R B, Consumers Power Co. 80/11/21. 1p. 07097:066.
- B012020341 Withdraws request for Tech Spec changes re installation of new redundant line providing backup cooling water to core spray recirculation heat exchanger in place of existing fire hose-per util B01028 ltr.
 WITHROW.O.C. Consumers Power Co. B0/11/26. 1p. 07148:171.
- B012020477 Discusses NRC B01024 orders for mod of environ qualification of safety-rolated electrical equipment. Advises that mod for facilities is governed by SEP Topic III-12. All safety-related electrical equipment shall be qualified by 820430. VINCENT.R.A. Consumers Power Co. 80/11/26. 2pp. 07141:259.
- 8012240499 Informs of review of SEP Topic VI-4 re containment isolation sys. Addl info described in encl requested. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/12/02. 5pp. 07324:110.
- 8012080362 Requests extension until 800401 to install recirculation pump trip as required in NRC 800221 confirmatory order. Hods needed to assure that facility can safely respond to ATMS. Class III fee encl. HOFFMAN, D. P. Consumers Power Co. 80/12/03. 3pp. 07189: 249.
- --8012080365 "Probabilistic Risk Assessment of Automatic Recirculation Pump Trip." # Consumers Power Co. 80/12/31, 8pp. 07189:252.

- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENIDN.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Lnw level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- B012090419 Forwards application to amend License DPR-4 & Tech Spec change request re containment spray sys. WITHROW, O. C. Consumers Power Co. B0/12/05. 1p. 07207:102.
- ---8012070426 Application to amend License DPR-6 w/changes to Tech Spec Bections 3.5.1:11.3 3.4 % 11.4.3.4 % Table 11.4.3.4 allowing implementation of plant mods designed to mitigate effects of steam pipe breaks. DEWITT.R.B. Consumers Power Co. 80/12/05. 5pp. 07207:103.
- --8012090429 Proposed changes to Tech Specs to allow implementation of plant mods designed to mitigate affect of steam pipe breaks inside containment. # Consumers Power Co. 80/12/05. 14pp. 07207:108.
- 8012150285 Forwards info verifying adequacy of spent fuel transfer cask redundant support assembly. Results of verification confirm adequacy of redundant support assembly. WITHROW, O. C. Consumers Power Co. 80/12/05. 2pp. 07187:001.
- --8012150286 Analysis of facility spent fuel transfer cask redundant support assembly.
 JOHNBON: J. W. MPR Associates, Inc. 80/11/26. 130pp. 07187:001.
- 8012140182 Forwards response to 801024 request for add1 info re generic issus of onsite power sys. HOFFMAN, D. P. Consumers Power Co. 80/12/12, 5pp. 07262:057.
- 8012240489 Notification of 801218 meeting w/8EP owners group in Bethesda,MD for discussions on SEP program, schedule for license topic completion & assignment of lead topics to plants.

 RUSSELL.W.T. Systematic Evaluation Program Branch. 80/12/16. 2pp.
- B012230275 Forwards revision to Table 1.App C of B01205 request for amend to License DPR-6 re containment spray sys.

 MDFFMAN.D.P. Consumers Power Co. B0/12/19, 2pp. 07314:067.
- 8012300502 Forwards response to NUREO-0737, "Clarification of TMI Action Plan Requirements," Provides all requested evaluations, design & schedule info.including justification for deviations from recumendations & schedules. HOFFHAN.D.P., DEWITT,R.B. Consumers Power Co. 80/12/19, 128pp.
- Q. Inspection reports: IE Bulletine & correspondence
- 8012100167 Forwards IE Insp Rept 50-155/80-10 on 800804-0905. No noncompliance noted. HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/09/25. 2pp. 07219:340.
- --8012100176 IE Insp Rept 50-155/80-10 on 800804-0905 No noncompliance noted Major areas inspected operational safety, bulletin review, circular review & LER 80-23 initial followup. MRIOHTG. C. PARKERIN J. BOYO, D. Region i. Philadelphia, Office of the Director. 80/09/25. 6pp. 07219:342.
- 8012170597 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLCR.J. G. Region 3, Chicago, Office of the Director. 80/10/24.

 1p. 07268:124.
- 8012100430 Forwards IE Insp Rept 50-155/80-13 on 800904-1007. No noncompliance noted. HEISHMAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 80/11/05. 2pp. 07218:021.
- --8012100432 IE Insp Rept 50-155/80-13 on 800904-1007. No noncompliance noted Major areas inspected: operational safety. LER review & independent insp effort. MRIOHIT, O.C., 80070.D.C. Region 3, Chicago, Office of the Director. 80/11/03. 4pp. 07218:023.

- 8012010496 Corrects error in 800730 response to IE Bulletin 79-03 re longitudinal weld defects in ASME SA-312. Type 304 stainless steel pipe. Fusion welded stainless steel pipe used but not ASME SA-312. Type 304. No addi
- B012020743 Forwards three Performance Appraisal Branch insp repts & mgt avaiuation tree w/user guide so that facility can compare program to program already reviewed & mate appropriate adjustments, W/o ancl.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. B0/11/18. 4pp.
- 8012040674 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.
 KEPPLER J. G. Region 3, Chicago, Diffice of the Director. 80/11/21.
 2pp. 07169:079.
- 8012080044 Forwards Info Notice 80-42, "Effect of Radiation on Hydravlic Snubber Fluid." No written response required. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/24. 2pp. 07182:193.
- 8012090468 Informs that statement in util 801114 ltr re Region 3 acceptance of addition of training position to plant staff incorrect. Staff has no regulatory basis to require offshift staffing Health physics appraisal encl. KEPPLERIJ. 0. Region 3. Chicago, Dffice of the Director. 80/11/25. 2pp. 07187:001.
- --8012090474 Notice of violation from health physics appraisal on 800303-14. * Region 3. Chicago. Office of the Director. 80/06/13. ip. 07187:001.
- 8012190262 Forwards new security badge numbers & clearance levels for Region 3 personnel. Changes should be entered on Sept 1980 access lists. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/25. 6pp. 07282:130.
- 8012170361 Forwards IE info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER.J.O. Region 3. Chicago. Office of the Director. B0/11/26. 2pp. 07264:137.
- 8012270701 Responds to IE Builetin 79-018 re environ qualification of Class IE electrical equipment. Util enrolled in BEP. Electrical equipment qualification submittals sent to URC on B01007.30 & 31.

 HOFFHAN, D. P. Consumers Power Co. B0/12/01. 1p. 07293:125.
- B012180005 Submits supplemental info for response to IE Builetin 80-10 re contamination of nonradioactive sys & potential for environ release. All floor drains to environ plugged & routine sampling of air supply sys to be performed. HOFFMAN, D. P. Consumers Power Co. B0/12/02. 2pp. 03791:161.
- BO12180600 Ack receipt of 801112 ltr responding to noncompliance noted in IE Insp Rept 30-135/80-12. Forwards request for additinfo. Request withheld (ref 10CFR2.790). HIND.J.A. Region G. Chicago, Safeguards Branch. 80/12/04. 2pp. 07271: 348.
- --B012180603 Forwards response to noncompliance noted in IE Insp Rept 50-155/80-12. Response withheld (ref 10CFR2.790). HOFFMAN.D.P. Consumers Power Co. 80/11/12. 1p. 07271:350.
- R. Periodic operating reports & related correspondence
- B012170452 Forwards monthly operating rept for Nov 1980. HARTMAN, C. J. Consumers Power Co. 80/12/10. 1p. 07268:073.
- --8012170456 Monthly operating rept for Nov 1980. HINCHAUCH, N. Consumers Power Co. 80/12/10, 6pp. 07268:074.
- S. Reportable occurrences, LERs & related correspondence
- B012160494 Forwards LERs 80-036/03L-0,80-037/03L-0 & 80-038/03L-0. HDFFMAN, D. P. Consumers Power Co. 80/12/12. 1p. 07255:393.
- --8012160498 LER 80-036/03L-0: on 801118, output voltage did not reach normal 480-volt level. Probably caused by damage to two diodes (type 1N-1190) during annual maint checks. Diodes replaced & annual checks eliminated.

 4 Consumers Power Co. 80/12/12. ip. 07255:354.

- --B012160504 LER 80-037/03L-0: on 801118, engine cooling water pump coupling components overheated. Caused by coupling sleeve wearing on bearing seal of reduction gear unit due to loose set screw. Unit repaired.

 * Consumers Power Co. B0/12/12. tp. 07255:355.
- ---8012160508 LER 80-038/03L-0: on 801118, t0-inch feedwater check valve VFW 304 exhibited leakage. Caused by dirt & scale on valve seat & disc, Disc machined & seat lapped. Valve tested, 4 Consumers Power Co. 80/12/12, ip. 07255:356.
- 8012230341 Forwards LER 80-042/01T-0. HDFFMAN, D. P. Consumers Power Co. 89/12/18. ip. 07318:230.
- -8012230349 LER 80-042/017-0: on 801205, wall leakage observed during inservice insplactivity at weld in two-inch pips in sizes flow return from control rod drive sys. Probable cause related to marginal const. Repairs will be made.

 4 Consumers Power Co. 80/12/18. 2pp. 07318:231.
- 8012230529 Forwards LER 80-041/03L-0. HOFFMAN D. P. Consumers Power Co. 80/12/19. 1p. 07312; 317.
- B012310309 Forwards LER B0-039/03L-0. VINCENT, R. A. Consumers Power Co. B0/12/22. 1p. 07369:040.
- --B012310312 LER 80-039/03L-0: on B01127, check valve inside containment in 3-inch treated waste line found leaking in excess of test criteria. Caused by ercessive wear on disc pin of tilting disc check valve. Bust & disc components replaced.

 Consumers Power Co. B0/12/22. 1p. 07369: 041.
- 8012300422 Forwards LER 80-043/01T-0. KGFFMAN, D. P. Consumers Power Co. 80/12/23. ip. 07360: 330.
- --8012300427 LER 80-043/01T-0: on 801212, crack measuring 1/2-inch found in base metal of 3-inch line at 1/2-inch branch connection. Probably caused by stress corrosion. Defective parts replaced.

 4 Consumers Power Co. 80/12/23. 2pp. 07360:331.
- DOCKET 50-157 CORNELL UNIV. RESEARCH REACTER
- J. Insurance & indemnity information
- 8012050418 Executed Amend 10 to Indomnity Agreement E-4, increasing anount of financial protection.

 SALYZMAR, J. Utility Finance Branch (formerly Antitrust & Indomnity).

 DYNER, E. J. Cornell Univ. B9/12/01. 19. 07174:025.
- P. Operating license stage documents & correspondence
- B012010575 Forwards B01118 FR notice of consideration of 800527 application for renewal of License R-80.License will not expire until application finally determined.

 MILLER, J.R. Standardization & Special Projects Branch. B0/11/18.
 2pp. 07095:052.
- --B012010579 Notice of consideration of application for renewal of License R-80.
 HillER.J.R. Btandardization & Special Projects Branch. B0/11/19.
 4pp. 07(105:086.
- DOCKET 50-163 CENERAL ATOMIC COMPANY J. Insurance & intemnity information

j.

- 8012020562 Forwards Endorsement 51 to MAELU Policy MF-59. CORREALM A. Karsh & McLennan.Inc., M & M Nuclear Consultants.Inc. Div. 80/11/20. 2pp. 07148:071.
- DOCKET 50-166 UNIV. OF HARYLAND RESEARCH REACTOR F. Security, medical, emergency & fire protection plans
- B012230521 Releases sublic version of univ emergency plan. FELTON,J.H. Division of Rules and Records, E0/12/11. ip. 07312:319.

- --8012230525 Public version of emergency plan.
 4 Maryland, Univ. of. 80/06/30, 59pp. 07312:320.
- DOCKET 50-170 NATIONAL, NAVAL MEDICAL CENTER
- G. Adjudicatory correspondence
- 8012290588 Petition for leave to intervene Notice of appearance. Certificate of Svc & signed petition encl. ENTHISLE.E.B. Affiliation Unknown. B0/12/09. 146pp. 07308:001.
- 8012290402 Notice of ASLB establishment.LJ Carter appointed chairman, EE Hill & DR Schink members. COTTER.E.P. Atomic Safety and Licensing Board Panel. 80/12/11. 2pp. 07336:300.
- BO12310460 Response in opposition to Citizens for Nuclear Reactor Safety B01207 petition to intervene Petitioner lacks standing. No basis for discretionary standing. Notices of appearance & Certificate of Eve encl.
 BACHMANN.R.O. Defice of the Evecutive Legal Director. 80/12/24. 15pp. 07370:232.
- BO12310474 Response in apposition to Citizens for Nuclear Reactor Safety petition to intervene. Intervenor failed to establish standing. Contentions outside scope of action & contrary to manifest weight of evidence. W/Certificate of Svc. BRITTIOAN, R.L. Defense, Dept. of, Defense Nuclear Agency. BO/12/24. 12pp. 07370:260.
- H. General correspondence
- 8012020824 Responds to 800812 ltr re citizen concerns about facility. Armed Forces Radiology Inst has submitted request for upgrading & modifying Tech Specs. Facility application for license renewal will be announced in FR w/intervening rule. DIRCKS.W.J. Office of the Executive Director for Operations. 80/09/23. 4pp. 06916:001.
- --B0:12020B2B Discusses citizen concerns re operation of facility. Full public hearing should be held prior to decision on relicensing. EIS should be undertaken to assess impact on residential area.

 SARBANES-P.S. Senate. 80/08/12. 1p.
- B012120075 Responds to B00913 ltr re status of application for renewal of License R-B4. Application was received on B01003. Regulations do not require compulsory hearing for renewal of license for research reactor. Application available in PDR. DENTON. H.R. Office of Nuclear Reactor Regulation, Director. B0/10/23. 2pp. 07231:351.
- --80121200B1 Requests info on status of License R-84, whether application for renewal has been filed & if public hearing will be held.
 ENTHISLE, E. Affiliation Unknown. 80/09/15. 2pp. 07231:355.
- B012290270 Requests preparation of EIS & public hearings prior to extending facility license to yr 2,000. SPECTOR.R., OILCHREST, C.W. Montgomery County, MO. 80/12/16, ip. 07341:180.
- P. Operating license stage documents & correspondence
- B012010533 Forwards B01118 FR notice of consideration of B01003 application for renewal of License R-B4.License will not expire until application finally determined.
 MILLER.J.R. Standardization & Special Projects Branch. 80/11/18. 2pp. 07095:022.
- --8012010535 Notice of consideration of 801003 application for renewal of License R-B4. MILLER J.R. Standardization & Special Projects Branch. 80/11/18. 4pp. 07095:024.
- 8012080451 Requests correction of typographical error in FR notice reapplication for renewal of amended DL.
 TYLER, P.E. Defense, Dept. of, Defense Nuclear Agency. 80/12/03. 1p.
 07189:269.
- R. Periodic operating reports & related correspondence
- B0120B050B Forwards annual operating rept for yr ending B01001 & safety analysis of FBAR.
 TYLER,P.E. Defense.Dapt.of. Defense Nuclear Agency. B0/12/03. ip..
 07183:062.

- --8012080510 "Armed Forces Radiobiology Research Inst R-84,Annual Rept Oct 1980." "Defense,Dept.of, Defense Nuclear Agency. 80/12/03. 15pp. 07183:063.
- --8012080512 "Section VI Safety Analysis of FSAR." * Dames & Moore. 80/09/18 28pp. 07189:078.
- DOCKET 50-171 PEACH BOTTOM ATOMIC PORER STATION, UNIT 1
 F. Security, medical, emergency & fire protection plans
- B01224045B Informs of no objections to recording conversations on dedicated phone line connecting facility to NRC operations ctr in Bethesda. Detailed description of task to be accomplished required.

 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/12/02. 1p. 07324:174.
- P. Operating license stage documents & correspondence
- 8012220485 Responds to 800911 memo requesting that Lift of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- R. Periodic operating reports & related correspondence
- 8012300270 Forwards final post-operational Rapts 13 & 14 re Conowingo Pond ecology for Jul-Dec 1979 & Jan-Apr 1980, respectively, WILLSEY, W. B. Philadelphia Electric Co. 80/11/28. 1p. 07353:088.
- --B012300275 "Post-Operational Rept 13 on Ecology of Conowingo Pond, Jul-Dec 1977." Huddy Run Ecological Laboratory, RMC Ecological Div. 80/02/29. 207pp. 07353:059.
- --8012300282 "Post-Operational Rept 14 on Ecology of Conowingo Pond, Jam-Apr 1980." * Huddy Run Ecological Laboratory, RMC Ecological Div. 80/08/31. 166pp. 07353:267.

DOCKET 50-182 PURDUE UNIV. RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

- 8012160373 Forwards IE Insp Rept 50-182/80-02 on 801015-16. No noncompliance noted, DAVIB.A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. BO/11/04. 2pp. 07262:022.
- --8012160976 IE Insp Rept 90-182/80-02 on 801015-16. No noncompliance noted. Major areas inspected: emergency equipment supplies, tests, drills, training & postulated incident. OREGR.R.J., NICHOLSON.N.A., PAPERIELLO.C.J. Region 3, Chicago, Office of the Director. 80/11/03. 4pp. 07262:024.

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
K. Utility Final Safety Analysis Report (FSAR) & amends

- 8012080485 Application to amend License TR-5, increasing max power from 10 MH to 20 MH for 20 yrs. Forwards Addendum 1 to SAR & proposed Tech Bpec changes. CARTER.R.B. Commerce. Dept. of, National Bureau of Standards. 80/12/02. 1p. 07195:025.
- --8012080487 Addendum 1 to FSAR Oversize map encl. * Commerce Dept. of, National Bureau of Standards. NBSR 9 ADD 1. 80/11/30. 75pp. 07195:026.

- P. Operating license stage documents & correspondence
- 8012080485 Application to amend License TR-5, increasing max power from 10 MN to 20 MM for 20 yrs.Forwards Addendum 1 to 9AR & proposed Tach Spec changes.
 CARTER, S. Commerce, Dept. of, National Bureau of Standards.
 B0/12/02. 1p. 07195:025.
- --8012080487 Addendum 1 to FSAR Oversite map encl.

 * Commerce Dept. of. National Bureau of Standards. NBSR 9 ADD 1.
 80/11/30. 75pp. 07195:026.
- --8012080471 Proposed Tech Spec changes supporting amend to License TR-5 to increase authorized max power level from 10 MW to 20 MW for 20 yrs.
 Commerce, Dept. of, National Bureau of Standards. 80/11/30. 28pp. 07195:109.
- 8012190143 Clarifies 801202 ltr.NBS is requesting both license amend to increase authorized power level & license renewal for period of 20 yrs.

 CARTER, R. S. Commerce, Dept. of, National Bureau of Standards, 80/12/11. 1p. 07240:081.

DOCKET 50-184 UNIV. OF MISSOURI RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

- B012110737 Forwards IE Insp Rept 50-185/80-05 on 801008-10.No noncompliance noted. HEISHKAN,R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 80/10/29. 2pp. 07225:078.
- ---B012110753 IE Insp Rept 50-186/80-05 on 801008-10. No noncompliance noted Major areas inspected: records, logs & organization review audit functions requalification training & procedures.
 RID9WAY.K.R., CONNAUGHTON,K.A, BOYD,D.C., Region 3, Chicago, Office of the Director. B0/10/28. 6pp. 07225:080.

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

R. Periodic operating reports & related correspondence

- 8012170314 Forwards "Natural Environ Radioactivity Survey, Sept 1979 -Aug 1980." CRANDALL, N. E. Northrop Research & Technical Center. 80/11/26, 1p. 07270: 020.
- --B012170324 "Natural Environ Radioactivity Burvey, Sept 1979 Aug 1980." AVANT.D., COZENS.O., NDDDS.J. Northrop Research & Technical Center. 80/11/24, 11pp. 07270:021.

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT
F. Security, medical, emergency & fire protection plans

- 8012020484 Requests explanation of evacuation rumor & name of inspector involved in rumor.

 MONOERSON, C. West Valley Nuclear Wastes. 80/10/07. ip. 07148:128.
- 8012020735 Informs of existing emergency communications sys review & resulting mods to emergency notification sys & health physics network.NRC will have lamps installed on emergency telephones in all control rooms & technical support ctrs. GRIER.B.H. Region i. Philadelphia. Office of the Director. 80/11/14. 2pp. 07147:340.
- H. General correspondence
- B012010618 Requests repts re facility listed but not encl in NRC 790920 ltr.
 CLAUSON, M. K. Affiliation Unknown. B0/09/15. lp. 07098:113.
- B012020451 Expresses concern re B00917 ltr discussing leakage of radwaste at burial grounds. Sees better energy alternatives in development of solar energy & practice of conservation. GORE, A. Affiliation Uninown. B0/09/24. 2pp. 07259:258.

P. Operating license stage documents & correspondence

- 8012020727 Forwards review of NRC seismic study of NFS neutralized high level waste tank. Rept generally well done but does not address highly significant factors. Rept does not give reassurance re health & safety of public.
 RESNIKOFF, M. Bierra Club. 80/09/21. 9ep. 07147: 342.
- 8012020389 Concurs w/mod depicted in NFS drawings for head-end ventilation bldg.NFS should place mod on annual check list to assure shield has not shifted due to frost action. GOFFHAN.W.A. Wayne A. Coffmann P. E. 80/09/22. ip. 04916:001.
- 8012030689 Responds to 80081B Itr re installation of barrier to protect against tornado missiles at heat end ventilation (HEV) enci. Proposed mod will adequately protect filters within HEV enci in event of missile strike resulting from tornadic winds. ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 80/10/10. 1p. 07196:120.
- BD12220726 Natification of rescheduled Bi0107 meeting w/DOE in Silver Bpring.MD to discuss interagency agreement between DOE & NRC re West Valley Demonstration Project Act of 1980. Meeting originally scheduled for B01217. TIN9.H.M. Advanced Fuel & Spent Fuel Licensing Branch. B0/12/16. 2pp. 07293:113.
- B012300346 Summary of 801210 meeting u/NFS in Silver Spring, MD re progress of licensee efforts to process future decontentination & decommissioning technical data. MAUDHREY, C. J. Advanced Fuel & Spent Fuel Licensing Branch. B0/12/16. 33pp. 07359:036.
- 8012220722 Notification of Bi0211 meeting w/NFS & State of NY Energy R&D Authority in Silver Spring. MD to discuss NFS progress in processing info needed as basis for decontamination & decommissioning of facility.

 HAUCHEVIC, J. Advanced Fuel & Spent Fuel Licensing Branch.

 80/12/17. 2pp. 07293:114.

Q. Inspection reports. IE Bulletins & correspondence

- 8012010107 Requests that response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (EN3) W/Loss of Offsite Power," be resubmitted w/oath or affirmation within 10 days of receipt of ltr.per 10CFR50.34.

 GRIER,B.H. Region is Philadelphia. Office of the Director. 80/10/23. 1p. 07092:127.
- 8012190185 Forwards IE Insp Rept 50-201/80-05 on 800915-18.No noncompliance noted. SMITH, 0. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/30. 2pp. 07287:329.
- --8012190687 IE Insp Rept 50~201/80-05 on 800915-18. No noncompliance noted Major areas inspected: 100FR21.organization, and & changes to facility & sys.
 ROTH.J. Region 1. Philadelphia. Diffice of the Director.
 CROCKER.H.W. Region 1. Philadelphia. Fuel Facility & Materials Safety Granch. 80/10/27. 21pp. 07287:331.
- 8012090004 Responds to IE Bulletin 80-15 by resubmitting 800826 "Rept of NFS Nest Valley ENS Sys Tests & Investigation as Required by IE Bulletin 80-15." Affirmation encl. LEHIS, M.H. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.). 80/11/05. 3pp. 07199:339.

R. Periodic operating reports & related correspondence

- 8012040352 Forwards effluent discharge monitoring rept for Bept 1980. DUCKHORTH, J.P. Nuclear Fuel Services, Inc., Hest Valley Reprocessing Plant. 80/10/16. 19. 06915:001.
- --BD12040410 Raw data effluent discharge monitoring rept for Sept 1980. DUCKHORTH.J.P. Nuclear Fuel Services. Inc., Hest Valley Reprocessing Plant. 80/10/17. Spp. 06915:001.
- DOCKET 50-206 BAN ONOFRE NUCLEAR STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8012190335 Informs of recently approved revised 10CFR50.48 containing schedules for completion of all fire protection mode. No present implementation required as necessary addl into has not yet been approved. EISEUANT, D. G. Division of Licensing. 80/11/06. 6pp. 07286:088.

B012310092 Forwards physical security plan change involving specific response capabilities of US Harshals Svc. Encl withheld (ref 10CFR2.790). , DIETCH.R. Southern Celifornia Edison Co. B0/12/17. 4pp. 07369: 273.

H. General correspondence

- B012290262 Forwards constituent EK Johnson itr re location of facilities. Requests response. CRANSTON, A. Senate. B0/12/03 3pp. 07341:177.
- P. Operating license stage documents & correspondence
- B012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquaks.

 EISERMUT, D. Q. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensees.DL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012030379 "Review of Repts Dealing w/Simulation of Earthquake Ground Motions for San Onofre Nuclear Generators Station Unit 1 for MRC."

 BERNARUTER, D. L. Lawrence Livermore Laboratory. 80/11/05. 6pp.
- 8012220560 Ltr to all power reactor licensess forwarding NUREO-0619, "SWR Fasewater Norrle & Control Rod Drive Return Line Norrle Cracting," Confirmation that implementation dates will be met must be sent within 45 days.
- B012040122 Act receipt of B01028 ltr re revision of approvad routs for shipping spent fuel. Notes that request subj to NRC license fee schedule. NRC will notify of fee due after review. HEISS.D. License Fee Management Branch. B0/11/18. 1p. 07158:040.
- 8012110435 Forwards F Rosa 790930 memo re SEP Topic VIII-3.8, "DC Power Sys Bus Voltage."
 CRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/18. 2pp. 07225:167.
- --8012110439 Comments on 790925 memo re dc power sys monitoring & annunciation. Specific requirements for dc power sys monitoring derive from Reg Quide 1.47 general requirements. ROSA,F, Power Systems Branch. 79/09/30. 2pp. 07225:169.
- 8012110422 Immediate action ltr.confirming 801119 talcon re steam generator repairs. Util will not proceed w/production insertion phase w/o prior NRC review & approval. ENGELKFILR. H. Region 5. San Francisco. Office of the Director. 80/11/19. 1p. 07227:136.
- 8012090061 Notification of rescheduled 801205 meeting w/util in Bethesda, ND to discuss seismic re-evaluation program describing structures, methods & analysis. NGWICKL, B. Operating Reactors Branch 5. 80/11/20. 2pp. 07198:080.
- 8012020521 Forwards results of evaluation to determine effects of water hammers on feedwater piping sys per 800214 commitment & subsequent extension. Further corrective actions not considered warranted.

 8ASKIN.K.P. Southern California Edison Co. 80/11/25. 15pp. 07148:081.
- 8012020605 Forwards info re environ impact of current steam generator sleeving repair program.

 BASKIN.K.P. Southern California Edison Co. 80/11/26. 5pp.
- 8012270097 Requests billing of util for Dfc of Nuclear Reactor Regulation review of Amend 3 to SCE-1A, "QA Program," submitted 800331 & approved 800701. MILLER, N.D. License Fae Management Branch. 80/11/26, ip. 07345:250.
- 8012100068 Notification of 801204 meeting w/util in Bethesda: MD to address consultant comments resulting from review of util seismic model. NOWICKI-S.U. Operating Reactors Branch 5. 80/11/28. 2pp. 07219:104.

- 8012160255 Forwards EIA re sleeving project.
 OLSHINSKI, J. A. Operating Reactors Assossment Branch. 80/11/28. ip.
- --B012160260 EIA supporting proposed mods re sleeving project. * Office of Nuclear Reactor Regulation, Director, 80/11/28. 19pp. 07248:252.
- BO12120308 "Concentration & Speciation of Copper in Waters Collected Near San Goofre & Diablo Canyon Nuclear Power Stations." HARRISON, F.L.: BIBHOP, D.J.: EMERSON, R.R. Lawrence Livermore Laboratory, FIN A-D119. NUREO/CR-0750. B0/11/30. 66pp. Availab at NTIB. 07260:160.
- 8012030377 Forwards info re environ qualification tests to be performed within next two yrs, in response to IARC 801001 ltr. Tests for pressure & level transmitters apply to Units 1,2 & 3, All other tests apply to Units 2 & 3 only.

 BABKIN, N. P. Southern California Edison Co. 80/12/01, 3pp. 07191; 216.
- BO12030716 Forwards Amend 94 consisting of Proposed Change 96 to Tech Specs as App A of OL in response to NRC 800611 ltr requesting provision for redundancy in decay heat removal capability in all modes of operation. W/Certificate of Svc. DIETCH-R. Southern California Edison Co. 80/12/O1. 8pp. 07149;165.
- --8012030729 Amend 94 consisting of Proposed Change 96 to Tech Bacs as App A re decay heat removal capability.

 4 Southern California Edison Co. B0/12/01. 32pp. 07149:172.
- B012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director.
 B0/12/04, 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been espanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. Spp.
- B012100527 Requests extension until B10201 to evaluate impact of automating auxiliary feedwater sys on existing safety analysis & extension until B10115 to provide info re main steam line piping integrity evaluation.

 BABXIN.K.P. Southern California Edison Co. 80/12/05. 19. 07219:383
- 8012180098 Notification of 801218 meeting w/util in Bethesda,MD to discuss util comments re NRC case study of loss of salt water cooling sys. NGMICKI,B J. Operating Reactors Branch 5. 80/12/08, 2pp. 03794:045.
- B012120397 Forwards application to amend App A Tech Specs, Sections 2.1, 3.5.2 % 3.11. Westinghouse rept & Certificate of Svc encl.
 DIEFCH.R. Southern California Edison Co. 80/12/10. 1p. 07259:263.
- --B012120413 Application to amend App A Tech Specs 2.1 re reactor core involving limiting combination of power, pressure & temp; 3.5.2 re control group insertion limits & 3.11 re continuous power distribution monitoring. W/nept & Centificate of Svc. DIETCH.R. Bouthern California Edison Co. QILMAN.D.W., PIGOTT, D.R. San Diego Cas & Electric Co. B0/12/05. 7pp. 07259:264.
- --8012120426 Proposed Change 100 to App A Tech Spec Sections 2.1,3.5,2 & 3.11 re impact of core flow reduction resulting from steam generator mods.

 * Bouthern California Edison Co. 80/12/10, 4pp. 07259:275,
- --B012120434 Revision 1 to "Reload Safety Evaluation, San Onofre Nuclear Generating Station Unit 1, Cycle B." SKARITKA, J., ARLOTTI, M. G. Westinghouse Electric Corp., Nuclear Energy Bystems. B0/10/31. 49pp.
- B012240489 Notification of 801218 meeting w/SEP owners group in Bethesds HD for discussions on SEP program, schedule for License topic completion & assignment of lead topics to plants. RUBBELL, W. T. Bystematic Evaluation Program Branch. 80/12/16. 2pp.
- B012300544 Advises that response to NRC 801031 ltr requesting confirmation for implementation dates of TMI-related items will be submitted by B10105.
 BABKIN, P. Southern California Edison Co. 80/12/23. 1p. 07357; 836.

- Q. Inspection reports, IE Bulletins & correspondence
- 8012040313 Forwards IE Insp Rept 50-236/80-28 on 800904-26 & notice of Violation. CREMS.J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/10/24. 2pp. 07162:352.
- --8012040316 Notice of violation from insp on 800904-26. * Region 5, San Francisco, Office of the Director. 80/10/23. ip. 07162:354.
- --8012040319 IE Insp Rept 50-206/80-28 on 800904-26. Noncompliance noted: failure to observe reactor coolant chemistry limit & to follow radwaste discharge procedure.
 MILLER.L. Region 5, San Francisco. Office of the Director.
 FAULKENGERRY.B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/10/23. Spp. 07162:355.
- 8012170695 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 ENGELKFILR. H. Region 5, San Francisco. Office of the Director.
 80/10/24
- 8012170411 Forwards IE info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Diffice of the Director. 80/10/30. 1p. 07269:126.
- B012170852 Forwards IE Info Notice 80-39, "Malfunction of Solehoid Valves Mfg by Valcor Engineering Corp." No written response is required.
 ENGELKEN.R. H. Region 5, San Francisco, Office of the Director.
 B0/10/31. 1p. 07266:045.
- 8012090022 Forwards IE Insp Rept 50-206/80-30 on 801020-23. No noncompliance noted. CREMBIJ. L. Region 3, San Francisco: Office of the Director. 80/11/05. 2pp. 07197:303.
- --B012070027 IE Insp Rept 50-206/80-30 on B01020-23. No noncompliance noted Major areas inspected design changes & mods program. GA program. calibr. & IE bulletin/circular followup. HURN, A. J. Region 5, San Francisco, Office of the Director. FAULKENBERRY.D. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. B0/11/04. 4pp. 07197:305.
- 8012120240 Forwards IE Builetin 80-21, "Valve Yokes Supplied by Malcolm Foundry Collec." Written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/04. ip. 07227:330.
- 8012030916 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization " No written response required. ENGELKPIN.R.H. Region 5. San Francisco
- 8012080650 Forwards IE Info Notice 80-41: "Failure of Swing Check Valve in Decay Meat Removal Sys at Davis Hesse Unit 1." No response required. ENGELFRIR.H Region 5. San Francisco, Office of the Director. 80/11/10. 1p. 07183:038.
- B012040244 Forwards 1E Bulletin B0-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ENGELNERN.R.H. Region 5. Ban Francisco. Office of the Director. B0/11/14. 1p. 07158:173.
- B012040497 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." United response required Requests info on manpower expended. EXCELERN.R. H. Region 5, San Francisco, Office of the Director. 80/11/21. ip. 07163:313.
- BO12160087 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No response required. ENGELMEN.R. M. Region 5. San Francisco, Office of the Director. 80/11/24. 1p. 07262:116.
- 8012160130 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. ENGELMEN.R. H. Region 5, Ban Francisco, Office of the Director. 80/11/26. ip. 07262:070.

- R. Periodic operating reports & related correspondence
- B012140335 Forwards monthly operating rept for Nov 1980. CURRAN, J. K. Southern California Edison Co. 80/12/08. 1p. 07252:318.
- --801216033B Konthly operating rept for Nov 1980. JOY, J. 14. Southern California Edison Co. 80/12/08. 5pp. 07252:319.
- 8. Reportable occurrences, LERs & related correspondence
- 8012170619 Forwards LER 80-038/03L-0. HAYNES, J. O. Southern California Edison Co. 80/12/09. 2pp. 07264; 241.
- --B012170628 LER 80-038/03L-0: on 801122, ac power to all station auxiliaries was lost for 15-s due to breaker misslignment. Caused by opening 4 by bus tie breakers instead of opening auxiliary transformer C bus supply breaters. CURRANI-J. M. Bouthern California Edison Co. 80/12/09. 1p. 07264:243.
- T. Hearing transcripts on non-antitrust matters
- B012170434 Submits proprietary & conproprietary transcript of steam generator sleaving review board meeting.per 801119 ltr. Proprietary version withheld (ref 10CFR2.790).W/a encl. MCODY.W.C. Geuthern California Edison Co. 80/12/12. 2pp. 07269:346.
- DOCKET 50-213 HADDAM NECK FLANT
- F. Becurity, medical, emergency & fire protection plans
- BO12190015 Informs of recently approved revised 10CFR50.48 containing schedules for completion of all fire protection mods.No present implementation required as necessary addl info has not yet been approved. EISENHUT, D. Q. Division of Licensing. 80/11/06. App. 07278:200.
- B012110039 Notifies that 801101 deadline is invalid for fire protection program mods. Plans for installation of dedicated shutdown sys or alternate shutdown capability should be forwarded upon completion.

 CRUTCHFIELD. B. Operating Reactors Branch 5. B0/11/12. 2pp. 07227-355.
- 80:2080740 Informs that mods will be made to emergency notification sys & health physics network equipment NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operations facilities. ORIER.8. H. Region i. Philadelphia. Office of the Director. 80/11/14. 2pp. 07:98:159.
- 8012030872 Forwards public version of util emergency plan. FELTON, J. M. Division of Rules and Records. 80/11/19. 1p. 07150:365.
- --8012030884 Forwards public version of draft.Revision 8 of site smergancy plan. (Amend 22 to facility description & safety analysis). Final version will be submitted by 810102 & implemented by 810401. COURSIL.R G., FEE.W.I. Connecticut Yankee Atomic Power Co. 80/10/14. 3pp. 07150:316.
- --8012030889 Public version of draft Revision 8 to site emergency plan. (Amend 22 to facility description & safety analysis).
 4 Connecticut Yantee Atomic Power Co. 80/10/14. 150pp.
 07150:319.
- 8012040643 Transmits emergency planning info for placement in LPDR. SOUDER, J.L. Division of Rules and Records. B0/11/17, 1p. 07170:078.
- Q. Adjudicatory correspondence
- 8012080527 Forwards corrected page of 801024 order for mod of License DPR-61 to reflect correct plant name.
 GRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/13. 2pp.
- --B0120B0530 Corrected page to order for mod of License BPR-41, to reflec correct plant name. EISEMHUT.D.G. Division of Licensing. B0/10/24. 1p. 07184:311.

- 80:23:0638 Advises that Power Facility Evaluation Council for State of CT will proceed w/petition for declarative ruling rejurisdiction over proposed spent resin storage facility at site. NRC response requested by 80:0022.
 POND, O.D. Connecticut, State of. 80/09/17. 2pp. 07308:001.
- 8012310635 Responds to 860424 & 0717 ltrs re const of add1 low level waste storage facilities at site.NRC audit insp of licensee safety evaluation has determined acceptability of change. Change request & audit summary encl. DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/11/24. 16pp. 07308:001.
- BO12090172 Requests hearing to determine necessity of environ qualification of all safety-related electrical equipment at facilities, as required by NRC B01024 orders for mod of licenses.

 COUNSIL. M. O. Connecticut Yankee Atomic Power Co. B0/12/04. 3pp. 07200: 131.
- H General corvespondence
- BO121BO433 Responds to 800430 ltr re const of addl low level waste storage facilities at plant site. Change in plant design does not require prior NRC approval. Safety evaluation & summary of audit encl. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. BO/11/24. 17pp. 071B3:001.
- BOI21B0336 Responds to 800306 ltr opposing const of addi low level waste storage facilities on site Major changes at operating nuclear reactors require prior NRC approval Licensee evaluation of change request & NRC audit summany encl. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/11/24. 17pp. 07183:001.
- --8012180541 Opposes const of atomic waste storage facility on site.
 Townspeople have agreed to generation of electricity, not
 waste dump.
 NICHOLAS, L. H. Affiliation Unknown. 80/05/06. ip. 07183:001.
- 8012190260 Responds to 800508 itr re const of add1 low level waste storage facilities at site. Change in plant design does not require prior NRC approval. Util evaluation of design change & RRC audit summary encl.
 DENION, H.R. Office of Nuclear Reactor Regulation, Director. 80/11/24, 17pp. 07183:001.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of autiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat follouing earthquake.
 EISENSHUT.D. Q. Division of Licensing. 80/10/21. 4pp.
- 8012080672 Forwards evaluation of SEP Topic VI-4, "Electrical, Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation." Assessment compares facility w/criteria currently used for new OLs.
 CRUICHFIELD.D. Operating Reactors Branch 5. 80/10/24. 9pp. 07188:246.
- BO12160050 Ltr to operating plant licensees.OL applicants & CP holders, Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met.

 EISERMUT.D.O. Division of Licensing. BO/10/31, 7pp.
- 8012170476 Informs of Div of Litensing generic bounding review of inadvertent safety injection during cooldown. No further licensing action necessary, Safety evaluation encl. CRUICMFIELD, D. Operating Reactors Branch 5. 80/11/05. 2pp. 07264:227.
- --8012170477 Safety evaluation re inadvertent safety injection during cooldown. No addl licensing action required, but frequency of events should be monitored.

 4 Operating Reactors Branch 5. 80/11/09. ip. 07264:229.
- 8012220543 Ltr to all power reactor licensees forwarding NUREO-0619, "BWR Feedcater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. Wo encl. EISERMUT.D. G. Division of Licensing. 80/11/13. 1p.

- 8012010070 Responds to NRC 801031 ltr forwarding NUREG-0737. Util has consulted w/B&W on revisions to small break LOCA model. B&W will advise NRC re scope & schedule of revisions. Util is developing in-house capability to perform LOCA analyses. COUNBIL.W. O. Connecticut Yankee Atomic Power Co. 80/11/14. 2pp. 07098:208.
- 8012110076 Forwards request for info re containment sumps & insulation. Info from operating reactors is needed to develop range of test parameters & evaluate significance of debris formation. CRUTCHFIELD, D. Operating Reactors Branch 5. 80/11/18. 4pp. 07223:311.
- B012050272 Advises that 90% of required mods re anchorage & support of safety-related electrical equipment will be completed by B01231. Util will complete mods by B11031. Requests response by B01208 if NRC does not concur.
 COUNSIL, W. O. Connecticut Yankee Atomic Power Co. B0/11/21. 2pp. 07175:040.
- B012090041 Forwards evaluation of SEP Topic VIII-3 re electrical instrumentation & control features of sys required for safe shutdown. Evaluation will be basic input to integrated safety assessment for facility.

 CRUTCHFIELD, D. Operating Reactors Branch 5. 80/11/21, 15pp. 07198:063.
- 8012090531 Informs that immediate plant shutdown to install override to close capability on pressurizer power operated relief valves, as requested in 800930 ltr, is unwarranted. Commitment to install new switches prior to startup acceptable. CRUICHFIELD. D. Operating Reactors Branch 5. 80/11/21. 2pp. 07206-214.
- 8012190660 Forwards evaluation of SEP Topic VIII-3.8 re dc power sys bus, revised to reflect comments in 800704 ltr. CRUTCHFIELD, D. Operating Reactors Branch 5. 80/11/21. 7pp. 07183:001.
- 8012240441 Responds to 800424 ltm re const of addl low level waste storage facilities at plant. Change found acceptable from safety standpoint & no NRC action planned.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
 80/11/24. 4pp. 07328:048.
- 8012310635 Responds to 800424 & 0917 ltrs re const of addl low level waste storage facilities at site.NRC audit insp of licansee safety evaluation has determined acceptability of change. Change request & audit summary encl. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 80/11/24. 16pp. 07308:001.
- B012190314 Forwards Amend 36 to License DPR-61, safety evaluation & notice of issuance & availability. CRUICHFIELD, D. Operating Reactors Branch 5, 80/12/02, 2pp. 07284-052.
- --8012190321 Amend 36 to License DPR-61, revising reactor vessel mati surveillance capsule withdrawal schedule & changing administrative controls section of Apps A & B to reflect current names & titles. GRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/02. 22pp. 07286:054,
- --8012i90325 Safety evaluation supporting Amend 36 to License DPR-61.

 * Office of Nuclear Reactor Regulation: Director. 80/12/02. 4pp 07286:074.
- --8012190330 Notice of issuance & availability of Amend 36 to License DPR-61.
 CRUICHFIELD.D. Operating Reactors Branch 5. 80/12/02. 2pp. 07286:078
- 8012090172 Requests hearing to determine necessity of environ qualification of all safety-related electrical equipment at facilities, as required by NRC 801024 orders for mod of licenses.

 COUNBIL, N. 9. Connecticut Yankee Atomic Power Co. 80/12/04. 3pp. 07200:131.
- B012220485 Responds to B00911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. B0/12/04, 2pp.

- ~-8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012310059 Notifies of fee determination for util B00222 & 0421 requests for route change approvals re shipments of spent fuel to Battelle Columbus Lab. Ofc of Controller has been notified to issue invoice. MILLER. II. O. License Fee Management Branch. B0/12/08. ip. 07371:147.
- 8012160117 Submits info comparing facility to criteria used for licensing new facilities re SEP Topic III-10.8, "Reactor Coolant Pump Flywheel Integrity," in response to NRC 800926 ltr. In-place ultrasonic exam will be conducted. COUNSIL,N.O. Connecticut Yankee Atomic Power Co. COUNSIL,N.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/09. 2pp. 07262:194.
- 8012230262 Forwards response to NUREO-0737 re implementation status of TMI-related requirements.
 COUNBIL, W. G. Connecticut Yankee Atomic Power Co. COUNBIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
 80/12/15. 41pp. 07314:023.
- 8012240487 Notification of 801218 meeting w/SE7 owners group in Bethesda, MD for discussions on SEP program, schedule for license topic completion & assignment of lead topics to plants.

 RUSSELL, W. T. Systematic Evaluation Program Branch. 80/12/14. 2pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012040139 Responds to 1E Bullotin 80-15. Existing emergency notification sys has battery backup & includes inverter & battery charger. No add mods required per Item 2 nor any notification per Item 4.
 CDUNBIL.N. 0. Connecticut Yankee Atomic Power Co. 80/08/27. 3pp. 07170:235.
- 8012010389 Requests that response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) M/Loss of Offsite Power," be resubmitted w/oath or affirmation within 10 days of raceipt of ltr.per 10CFR50. 54. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/23. 1p. 07091:303.
- B012170370 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. @RIER.B.H. Region 1: Philadelphia, Office of the Director. 80/10/30. ip. 07269:045.
- 8012120077 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230: 268.
- 8012170340 Informs util of Issuance of new NRC personnel identification badges, effective after 801130. Example enci. MARTIN.N.J. Region 1, Philadelphia, Safaguards Branch. 80/11/06. 2pp. 07286:127.
- B0120307/1 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurisation." No written response required. 9RIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/07. 1p. 07150:208.
- B012040067 Forwards IE Bullstin 80-23, "Failures of Bolsnoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.
 ORIER, B.H. Region 1, Philadelphia, Office of the Director.
 80/11/14. 1p. 07157: 288.
- B012220633 Advises that written response is required to IE Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp. " First paragraph erroneously stated no written response required.

 GRIER.B.H. Region t. Philadelphia, Office of the Director. 80/11/17. 1p. 07273:136.
- 8012040500 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response raquired.Requests info on manpower expended. ORIER,8-H. Region 1. Philadelphia. Office of the Director. 80/11/21. 2pp. 07169:184.

- B012050547 Forwards Info Notice B0-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER, B. M. Region 1, Philadelphia, Office of the Director. 80/11/24. 19. 07174:035.
- R. Periodic operating reports & related correspondence
- B012190524 Forwards monthly operating rept for Nov 1980. GRAVES.R.H. Connecticut Yankee Atomic Power Co. 80/12/12. ip. 07287:098.
- --B012190526 Monthly operating rept for Nov 1980.
 4 Connecticut Yankee Atomic Power Co. 80/12/12, 10pp. 07287: 099.
- S. Reportable occurrences. LERs & related correspondence
- 8012090361 Forwards LER 80-D16/03L-0. ORAVE5.R.H. Connecticut Yantes Atomic Power Co. 80/12/03. 1p. 07202:359.
- --8012090364 LER 80-016/03L-0: on 801116, audible & visual alarms indicated two dropped rods & initiation of turbine load runback. Caused by badly burnt arc chuts & auriliary contacts on one side of type MK310 contactor rubbing & impeding operation.

 LEVING. J. M. Connecticut Yankse Atomic Power Co. 80/12/03. 2pp. 07202:360.

DOCKET 50-219 OYSTER CREEK NUCLEAR PORER PLANT

- F. Security, medical, emergency & fire protection plans
- 8012110298 Notifies of interim rule suspending completion dates for fire pretection mods previously approved by NRC.FR notice encl.
 EISELMOT.D.G. Division of Licensing. 80/10/31, 3pp. 07224:113.
- 8012050456 Informs that mods will be made to emergency notification sys & health physics network equipment.NRC will have lamps installed on emergency telephones in all control rooms technical support ctrs & emergency operations facilities. CRIER.B.H. Region 1. Philadelphia, Office of the Director. B0/11/14. 2pp. 07175:311.
- 8012090204 Requests delay in emergency preparedness esercise until Mar 1981 to direct resources towards upgrading emergency plan in meeting addi criteria of NEREO-0554 & 0596. Proposed changes & training are needed to implement new plan. FINEROCK, I.R. Jersey Central Power & Light Co. 80/12/01. 1p. 07200:343.
- G. Adjudicatory correspondence
- B012160144 Forwards SEC Form 10-0.Quarterly Financial Rept & supporting mgt comments, in response to IRC 790921, 1109 & 802011 requests for info re significant financial developments affecting utils in restart proteering.

 CONDUN.V. H. General Public Utilities. 80/11/26. 3pp. 07262:246.
- --B012160154 Quarterly Financial Rept.Sept 1980 & supporting mgt comments.
 * Gameral Public Utilities. 80/11/14, 44pp. 07262:249.
- H. General correspondence
- 80:2150422 Responds to FBIA request for documents re five categories of info re spent fuel shipments through Commonwealth of PA. Forwards documents listed in App A. Info partially withheld: local law enforcement capabilities (ref FDIA Exemption 3). FELTON. J. N. Division of Rules and Records. 80/12/03. 3pp. 07261:310.
- --BD12160431 Provides add1 info re proposed spent fue) route from Forked River:NJ to Hest Jefferson.CH. Add1 security will be provided when shipment crosses urbantized area. Travel will be on interestate & major highways & will be nonstop. FINFROCK.I.R. Jersey Central Power & Light Co. BO/04/10. 1p.
- --B012160439 Denies 790921 & 1004 requests for approved route for shipment of spent fuel Primary & alternate secondary routes do not meet code requirements, info partially withheld (ref FOIA Exemption 3). MCCORKLE O.N. Physical Security Licensing Branch. B0/04/18, 100s.

- --B012160457 Discusses amend to interio rule for physical protection of irradiated spent fue) in transit. Forwards NUREG-0561 & listing of routes previously approved for util, w/two newly designated heavily populated areas. H/o encl NUREG-0561, MCGCGRKLE, O. W. Physical Security Licensing Branch. B0/07/07. 2pp.
- --B012160462 Advises of review & approval of 791004 changes to approved spent fuel route. In view of changes, 7-day advance notification requirements are waived. List of changes encl. MCCORKLE, 0. W. Physical Security Licensing Branch. 80/07/25. 2pp.
- P. Operating license stage documents & correspondence
- 8003170023 Submits info re advance route approval. NUREO-0561, App 2-A used as quide.
 CARROLL.J.T. Jersey Central Power & Light Co. # General Public Utilities. GPU Service Corp. 79/09/21. 1p. 04200:360.
- 8003120301 Provides advance route info re 10CFR73 requirements for review & approval. * Jersey Central Power & Light Co. 79/10/04. 1p. 04176:123.
- 8012110060 Notifies of acceptability of util 800731 ltr re analysis of core spray line break LOCA w/failure of cracks in unbroken spray sparger.
 CRVICHFIELD. D. Operating Reactors Branch 5. 80/10/21. 3pp. 07223:273.
- 8012080574 Forwards request for addl info for review of generic issue re onsite power sys. Response requested within 45 days.
 CRUICHFIELD. D. Operating Reactors Branch 5. 80/10/24. 4pp.
- 8012040081 Summary of 801021 meeting w/util in Bethesda, MD re proposed naw overhead grid sparger design. Proposal due to discovery of cracks on core spray sys spargers. Submits features of new design. PAULSON, M.A. Operating Reactors Branch 5. 80/10/29. 30pp. 07157:308.
- 8012110018 Forwards review of SEP Topic III-8.C re irradiation.damage, use of sensitized stainless steel & fatigue resistance. Review will be basic input to integrated safety assessment for facility. CRUTCHFED D.D. Operating Reactors Branch 5. 80/10/30. 7pp. 07223:25i.
- BO12160050 Ltr to operating plant licensees, QL applicants & CP holders, Forwards NURLO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012220338 Ltr to all CP & QL holders for BHRs re requirement for implementation of QDYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.
 EISE/HUT. D. O. Division of Licensing. 80/11/04. 4pp.
- BO12220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BMR Feedwater Nozzle & Control Red Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EISERMUT, D. G. Division of Licensing. BO/11/13. 1p.
- BO120B0135 Informs that review of B00926 request for delay in certain implementation dates of TMI action plans will be deferred until response received to NRC B01031 ltr. CRUTCHFIELD.D. Operating Reactors Branch 5. B0/11/20. 2pp. 071B1:163
- B012090363 Informs that util Jan 1980 itr meets NRC 800924 request for commitment & schedule re Class IE protection installation of interface between non-Class IE power supply & reactor protection sys. GE design previously approved. FINFROCK, I. R. Jersey Central Power & Light Co. 80/12/04. 1p. 07201:171.
- BD12220485 Responds to BO0911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENION.H.R. Defice of Nuclear Reactor Regulation, Director.
 BO/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. Bpp.

- 8012090177 Forwards responses addressing items identified in NRC 790B14 itr re GA program. Additime is needed to update commitments on reg guides & ANSI stds. Responses & revised organization will be discussed at 801211 meeting. FINRROCK, I.R. Jersey Central Power & Light Co. 80/12/05. 11pp. 07200:134.
- B012160634 Notification of 801211 meeting w/util in Bethesda, MD to discuss licensee responses to concerns re OA plan. PAULSON, M.A. Operating Reactors Branch 5. 80/12/05. 1p. 07234:328.
- 8012240489 Notification of 801218 meeting w/SEP owners group in Bethesda. HD for discussions on SEP program, schedule for license topic completion & assignment of lead topics to plants.
 RUSSELL, N. T. Systematic Evaluation Program Branch. 80/12/16. 2pp.
- 8012230188 Forwards evaluation requested in 801001 ltr re BWR scram sys. Existing scram sys evaluated re addl design & performance criteria developed by BWR owners group. Modified sys scheduled to be operational by 820501. FINFROCK, I.R. Jersey Central Power & Light Co. 80/12/17. 2pp. 07317:022.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012110082 Forwards IE Insp Rept 50-217/80-27 on 800902-1001.No noncompliance noted. BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/07. 2pp. 07223:315.
- --B012110070 IE Insp Rept 50-219/80-29 on 800902-1001. No nancompliance noted Major areas inspected: log & record review. LER review. onsite LER followup & review of periodic repts.
 BRIOOS, L. E., THOMAS, J. A. Region 1, Philadelphia, Office of the Director, KEIMIG, R. R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/04. 8pp. 07223:317.
- B012050019 Requests that response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power," be resubmitted w/oath of affirmation within 10 days of receipt of ltr.per 100FR30.54.

 ORIER, B. H. Region i, Philadelphia, Office of the Director. 80/10/23, ip. 07173:071.
- 8012110054 Forwards request for add1 info for review of inservice insp program.Proposes 801117 meeting.Vessel weld examination info required. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/10/30. Spp.
- 8012040162 Forwards staff requirements memos for closed Commission meetings. Transcripts for all meetings have been released in entirety to PDR. BROWN, J. Office of the Secretary of the Commission. 80/11/06. 1p. 07170:035.
- --B01204020B Btaff requirements memo from B00521 closed meeting to discuss results of performance appraisal team insp of facility & upcoming Congressional testimony to be delivered by I&E.

 CHILK, B. J. Office of the Secretary of the Commission, B0/05/28. 1p. 07170:041.
- 8012120089 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230:251.
- 8012190369 Informs util of issuance of new NRC personnel identification badges, effective after 801130. Example encl. MARTIN.RJ. . Region 1. Philadelphia. Safeguards Branch. 80/11/06. 2pp. 07286:133.
- 8012030767 Forwards IE Info Notice 80-40; "Excessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ORIER, B.H. Region i. Philadelphia, Office of the Director. 80/11/07. ip. 07130:276.
- 8012080542 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Bys at Davis Besse Unit 1." No response required. ORIER, 8 H. Region 1. Philadelphia, Office of the Director, 80/11/10. 1p. 07182-357.

18

- 801231041B Forwards response to 1E Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power," Lack of oath was due to administrative oversight in original response. If/o encl. FINFROCK, I.R. Jersey Central Power & Light Co. B0/11/10. ip. 07369:229.
- 8012040102 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Meg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 ORIER, 8. H. Region I, Philadelphia, Office of the Director.
 80/11/14, ip. 07158:025.
- 8012220665 Advises that written response is required to IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER, B. H. Region 1. Philadelphia, Office of the Director. 80/11/19. 1p. 07293:130.
- 8012040529 Forwards IE Builetin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Unitten response required.Requests info on manpower expended. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07169:232.
- 8012050961 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER.D.H. Region i, Philadelphia, Office of the Director. 80/11/24. ip. 07174:047.
- R. Periodic operating reports & related correspondence
- 8012220404 Forwards monthly operating rept for Nev 1980. FINEROCK, I. R. Jarsey Central Power & Light Co. 80/12/10. ip. 07307:346.
- --B012220408 Monthly operating rept for Nov 1980. 6KLAR.J.B. Jersey Central Power & Light Co. 80/12/09. 9pp. 07307:347.
- 8. Reportable occurrences: LERs & related correspondence
- 8012040489 RD 80-049/01P: on 801103, while removing isolation condenser B from svc to repair steam leak, vent isolation valves V-14-1 & V-14-19 for condenser failed to close. Cause unknown. Operability check performed & valves closed.

 * Jerssy Central Power & Light Co. 80/11/06. 3pp. 06915:001
- 8012010319 Nonroutine Environ Operating Rept 50-219/80-10:on 801111. dilution pump 1-2 tripped Caused by debris in Barnegat Bay clogging pump seal water strainers, reducing pressure. Lines cleared Long-term corrective action being reviewed. FINRROCK, I.R. Jersey Central Power & Light Co. 80/11/21. 3pp. 07092:150.
- B012040445 Nonroutine Environ Operating Rept 50-219/80-10:on B01111,ETS limiting condition exceeded when less than two dilution pumps worked for 25 minutes w/ambient intake water temp at less than 40 F. Caused by unusual svc condition. FINFROCK 1.R. Jersey Central Power & Light Co. B0/11/21. 4pp. 07158:200.
- 8012100205 PNO-T-80-169: on B01121; licenses will commence cold shutdown condition to repair hinge pin leak on feedwater check valve & to investigate suspected tube leak in high pressure feedwater heater. Shutdown to last five days.
 THOMASI J.A.; KEIMIG.R.R.; BRUNNER.E. J. Region 1; Philadelphia, Office of the Director. B0/11/21, 2pg. 07218: 296.
- 8012010318 Nonroutine Environ Operating Rept 80-219/80-11: on 801118, fish were found dead in creek. Caused by apparent distraction from fall migration due to warm water from facility. Installation of blocking devices under review. FINRROCK I.R. Jersey Central Power & Light Co. 80/11/25. 3pp. 07098:026.
- 8012020532 Forwards LER 80-047/03L-0. FINEROCK, I. R. Jersey Central Power & Light Co. 80/11/25. 3pp. 07148:073.
- --8012020556 LER 80-047/03L-0: on 801101, while performing core spray sys instrument channel calibr & test, high drywell pressure switches tripped above Tech Spec limit. Cause attributed to instrument repeatability. Buitches adjusted. CROSBY.P. J. Jersey Central Power & Light Co. 80/11/R5. 1p. 07148:076.

- 8012080420 Nonroutine Environ Operating Rept 50-219/80-12: on 801122 during reactor shutdown w/three circulating pumps in svc. water temp in discharge canal fell below lower lethal temp, resulting in fishkill Blocking devices considered. FINFAOCK I.R. Jersey Central Power & Light Co. 80/12/02. 4pp. 07183: 058.
- 8012070466 Forwards LER 80-050/03L-0. FINFRDCK.I.R. Jersey Central Power & Light Co. 80/12/02. 3pp. 07203:066.
- --8012090471 LER 80-050/03L-0: on 801105, containment spray sys drywell pressure switches IP-15A.IP-15B.IP-15C & IP-15D found to trip at greater than allowable Tech Spec values. Caused by instrument represtability. Switchez adjusted.
 FITIGERALD.M. J. Jersey Central Power & Light Co. 80/12/02. 10.
- 8012160546 Forwards LER 80-051/03L-0. FINROCK/I.R. Jersey Central Power & Light Co. 80/12/04. 3pp. 07262:015.
- --8012160554 LER B0-051/03L-0:on 801109.daily surveillance checks not made of linear heat generation rate average planar linear heat generation rate & max critical power ratio. Caused by personnel error. Insps performed. BHAIAR. Jersey Central Power & Light Co. 80/12/04, 1p. 07262:018.
- 8012160482 Forwards LER 80-052/03L-0. FINFROCK,I.R. Jersey Central Power & Light Co. 80/12/08. 3pp. 07255:339.
- --8012160491 LER 80-052/03L-0: on 801118, reactor triple low water level indicator switches RE-t8A & RE-18D tripped at manometer readings higher than Tech Spec limit. Caused by sensor repeatability. Switches reset. FITICERALD, M. J. Jersey Central Power & Light Co. 80/12/09. lp. 07295: 342.
- 8012230468 RO 50-219/80-13:on 801204.plant intake water level reached critically low elevation, affecting supply of cooling water to main condenser reactor & turbine bldgs. Caused by environ & svc conditions. Dilution pumps 1-2 & 1-3 restarted. FINFROCK, I.R. Jarsey Central Power & Light Co. 80/12/17. 4pp. 07318: 292.

V. Operator Examinations

- 8012160461 Responds to NRC 800731 ltr re interim criteria for shift staffing.NRC requirements met.\(\varphi\)/exception of ltem b requiring licensed senior reactor operator to be in control room at all times.
 FIN-ROCK.I.R. Jersey Central Power & Light Co. 80/12/09. 2pp. 07243;353.
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8012040651 Informs that certain mods will be made to emergency notification sys & health physics network equipment.NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operation facility. GRIER, B. H. Region I. Philadelphia, Office of the Director. 80/11/14. ipp. 07170:076.

O. Adjudicatory correspondence

- 8012100108 Discusses IE insp on 801009-10.20-31.1101 & 18 & forwards notice of violation & order modifying License DPR-63. STELLD.Y. Office of Inspection & Enforcement. Office of the Director. B0/11/26. 2pp. 07219:191.
- --8012100125 Order modifying Litense DPR-63 forbidding TJ Perkins from involvement w/nuclear matters & directing implementation of naw reporting procedures.

 SELLOV. Office of Inspection & Enforcement. Office of the Director. 80/11/26. 9pp. 07219:157.
- 8012310394 Motion to dismiss proceeding w/respect to Allegation B of 80125 notice of violation. Concerns operation w/o lead cave shield & portable survey instrument. Requirement of law allegedly violated is impermissibly vague.
 THOMAS.E.B. Niagara Mohawi Power Corp. THOMAS.E.B. LeBosuf. Lamb. Leiby & MacRae. 80/12/29. 3pp. 07370:165.

- P. Operating license stage documents & correspondence
- B012160030 Ltr to operating plant licensees.QL applicants & CP holders. Forwards NUREG-0737 re-TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EIGENHUT.D.G. Division of Licensing. B0/10/31. 7pp.
- 8012220358 Ltr to all CP & DL holders for BMRs re requirement for implementation of ODYN code for licensing basis calculations performed by OE. Applicable to all license applications & proposed amends including core reloads.

 EISEKHUT.D.G. Division of Licensing. 80/11/04. 4pp.
- 8012010460 Forwards request for add1 info re adequacy of station electric distribution sys voltages in order to complete review of 791003 submittal Response due in 45 days. IPPOLITO, T. A. Operating Reactors Branch 2. 80/11/10. 3pp. 07095:107.
- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BWR Fredwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EISENHUT.D.G. Division of Licensing. 80/11/13. 1p.
- 8012040424 Advises that revised inservice testing program for pumps & valves will be submitted by 810106. Revision will incorporate all info agreed to at 801007 & 08 meetings.

 DISE, D.P. Niggara Mohawk Power Corp. 80/11/26. 1p. 07160:356.
- 8012040438 Informs that licensed plans to install Class IE protection sys by Epring 1983 refueling outage to meet requirements per 800924 ltr. Dasign info & proposed Tech Specs will be provided prior to refueling outage.

 DISE, D. P. Niagara Mohawk Power Corp. 80/11/26. 1p. 07158:197.
- B012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.M.R. Office of Nuclear Reactor Regulation, Director., B0/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Lnw level waste storage facilities have been expanded at 37% of reactors surveyed W/71% planning or considering increasing storage capacity.

 8ANYART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012150076 Requests acceptance criteria for TMI Lessons Learned Category A. Item 2. 1.8.b re stack monitor. Util needs info to prepare response to NRC 801126 ltr.
 TMDMAS, E. B. Le80euf, Lamb, Leiby & MacRae. 80/12/05. 2pp.
- 8012130155 Requests affidavits from Dfc of Nuclear Reactor Regulation to TMI Lessons Learned Category A, Itam 2.1.8. b re stack monitor.
 THOMAS.E.B. LeBocuf, Lamb. Leiby & HacRae. 80/12/05. 2pp. 07241:159.
- 8012230321 Responds to NRC request for info re electrical distribution sys valtages at facility. Info is contained in util 761018, 1130,770714 & 791207 itrs.

 DISE.D.P. Niagara Mohawk Power Corp. 80/12/10. ip. 07311:138.
- 8012190379 Advises that info requested re environ qualification tests will be included as necessary in future responses to IE Bulletin 79-018 per 801001 request.

 DISE, D. P. Niagara Hohawk Power Corp. 80/12/12. 1p. 07282:142.
- 8012190514 Notifies that owner's sub-group has revised design & performance criteria to proposed scram discharge sys mods. Further review of criteria required prior to licensee commitment to compliance. Results will be sent by B10115.

 LEMPGES.T.E. Niagara Mohawk Power Corp. 80/12/12. 1p. 07285:321.
- 8012300640 Forwards Amend 38 to License DPR-63, safety evaluation & notice of issuance & availability.

 IPPOLITO,T.A. Operating Reactors Branch 2. 80/12/12, 2pp.

 07362:340.
- --8012300447 Amend 38 to License DPR-63, permitting plant operation for 4-h w/increased secondary containment allowable leakage. JPPOLITO.T.A. Operating Reactors Branch 2. 80/12/12. 7pp. 07352:342.

- --8012300649 Bafety evaluation supporting Amend 38 to License DPR-63.

 * Office of Nuclear Reactor Regulation, Director. 80/12/12. 3pg 07362:349.
- --8012300653 Notice of issuance & availability of Amend 38 to License DPR-63. IPPOLITO.T.A. Operating Reactors Branch 2. 80/12/12. 2pp. 07362:332.
- 8012190475 Advises that info re 801031 request to commit to implementation dates for TMI action plan will not be provided until 801217.

 LEMPGES.T.E. Miagara Mohawk Power Corp. 80/12/15. 1p. 07282:150.
- 8012300503 Forwards addl info re crack in reactor bldg wall, per NRC 800821 request. Photographs & oversize drawings encl. DISE, D. P. Niagara Mohawk Power Corp. 80/12/15, 16pp. 07374:001.
- B012230472 Forwards lists of implementation dates re TMI action plan items per B01031 request in compliance w/identified dates except those indicated in attached Table 1. DISE,D.P. Niagara Mohawk Power Corp. 80/12/17, 20pp. 07318:296.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012020327 Requests that response to IE Bulletin 80-15, "Possible Loss of Emergency Notification 8us (EN8) W/Loss of Offsite Power," be resubmitted w/oath or affirmation within 10 days of receipt of ltr.per 100FR50.54.
 ORIER, B. H. Region i, Philadelphia, Office of the Director. 80/10/23. ip. 07143:125.
- B012220065 Forwards IE Insp Rept 50-220/80-12 on 800922-26. No nencompliance noted. MARTIN, N. O. Region in Philadelphia, Safeguards Branch. 80/10/28. 2pp. 07306:334.
- --8012220069 IE Insp Rept 50-220/80-12 on 800922-26. No noncompliance noted Major areas inspected; physical security plan implementation. Details withheld (ref 10CFR2, 790).

 BAILEY,R.J., SMITH,M. Region 1, Philadelphia, Office of the Director. DEVLIN.J.W. Region 1, Philadelphia, Safeguards Branch. 80/10/23. 1p. 07306:336.
- 8012040577 Forwards resubmitted response to IE Bulletin 80-15, "Pogsible Loss of Emergency Notification Sys (ENB) W/Loss of Offsite Power," & required oath of affirmation.
 LEMPGEB.T.E. Niagara Mohawk Power Corp. 80/10/29. 1p. 07170:099.
- --8012040592 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification 8ys (ENS) W/Loss of Offsite Power." Required cath of affirmation encl. LEMPOSE: T.E. Niagara Mohawk Power Corp. 80/09/03, 4pp. 07170:100.
- 8012120637 Responds to IE Bulletin 79-018 re environ qualification of electrical equipment. Qualification documentation for components lacking documentation will be completed by 810201.

 LEMPOES, T. E. Niagara Mohawk Power Corp. 80/11/03. 4pp. 07227:346.
- B012120117 Forwards IE Bulletin 80-21, "Valve Yokes Bupplied by Malcolm Foundry Co. Inc." Written response required. ORIER.B.H. Region i. Philadelphia. Office of the Director. B0/11/06. 1p. 07230:216.
- 8012190373 Informs util of issuance of new NRC personnel identification badges: effective after 801130. Example encl. MARTIN, H. J. Region 1, Philadelphia, Safeguards Branch. 80/11/06. 2pp. 07286:137.
- 8012030785 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ORIER, B.H. Region I. Philadelphia, Office of the Director. 80/11/07. ip. 07150:203.
- 8012080447 Forwards IE Info Notice 80-41, "Failure of Ewing Check Velve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. ip. 07182:324.
- 8012090013 Responds to IE Bulletin 80-11. Re-evaluation of masonry walls demonstrates that continued operation of facility presents no undue safety hazard to public.

 LEMPOES, T. E. Niagara Mohauk Power Corp. 80/11/10. 9pp. 07199:320.

- 801204009B Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Hig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B. H. Region 1. Philadelphia, Office of the Director. 80/11/14. ip. 07158; 020.
- 8012220645 Advises that written response is required to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. ORIER, B.H. Region i, Philadelphia, Office of the Director. 80/11/19, 1p. 07293:132.
- B012040519 Forwards IE Bulletin B0-24. "Prevention of Damage Due to Water Leakage Inside Containment." Uritten response required Requests info on manpower expended. ORIER, B.H. Region 1, Philadelphia, Office of the Director. B0/11/21. 2pp. 07169: 220.
- 8012050578 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Boubber Fluid." No written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/24. 1p. 07174:058.
- B01203000B EN-B0-52 on 801126 notice of violation & notice of proposed imposition of civil penalties to be issued to licensee.

 Action based on mail false statement submitted under oath on B00122 re completed work under NUREO-057B.

 THOMPSIN, D., STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/11/26. 2pp. 07151:141.
- 801210010B Discusses IE insp on 801008-10,20-31,1101 & 18 & forwards notice of violation & order modifying License DPR-63. STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/11/26. 2pp. 07219.151.
- --8012100121 Notice of violation from insp on 801008-10,20-31,1101 & 18.

 Noncompliance noted:operation of facility w/o lead cave shield or survey gamma instrument & false statement re completion of Category A. Item 2.1.8b.

 * Office of Inspection & Enforcement, Office of the Director. 80/11/26. 4pp. 07219:153.
- --8012130125 Order modifying License DPR-63 forbidding TJ Perkins from involvement w/nuclear matters & directing implementation of new reporting procedures.

 STELLO,V. Office of Inspection & Enforcement, Office of the Director. 80/11/26, 7pp. 07219:157.
- 8012290401 Forwards IE Insp Rept 50-220/80-18 on 801008,10,20-31 & 1112 & 13 & IE Investigation Rept 50-220/80-17 on 801020-1101 & 18. ORIER: B.H. Reption 1, Philadelphia, Office of the Director. 80/12/02. 2pp. 07329:270.
- --8012270407 IE Insp Rept 50-220/80-18 on 801008,10,20-31 & 1112-18. Noncompliance noted valve position & elarm not indicated in control room.
 HUDSDIM.S.D., HHITE.J.R., KISTER, H.B. Regton 1, Philadelphia, Office of the Director. 80/11/26. 23pp. 07327:272.
- --80122Y0420 IE Investigation Rept 50-220/80-17 on 801020-1101 & 18. Investigation determined that basis for licensee conclusion that mods re increased radiation monitor range & post-accident sampling were completed in compliance w/NUREG-0578. CHRISTOPHER.R., KISTER.H.B., WHITE, J.R. Region i, Philadelphia, Office of the Director. 80/11/21, 21pp. 07329:295.
- --8012290426 Ltr to all operating nuclear power plants forwarding discussion of TMI Lessons Learned short-term requirements to implementation schedule.

 DENTON H.R. Office of Nuclear Reactor Regulation, Director. 79/10/30. 9pp. 07329.316.
- --8012270431 Forwards show cause order re short-term Lessons Learned requirements implementation.

 DENTON H. R. Office of Nuclear Reactor Regulation, Director, 80/01/02. 2pp. 07329: 326.
- ---8012270434 Order to show cause why util should not implement all Category A requirements of NURCO-0578 by 800131. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/01/02. 4pp. 07327:328.
- --8012290446 Answer to NRC 800102 show cause order re TMI lessons learned short-term requirements implementation dates. All but one Catetory A item will meet implementation dates. Necessary equipment for last requirement will be received by 810229. BARTLETT J. Niagara Mohawk Power Corp. 80/01/22. 10pp. 07329:332.

- --B012290450 Forwards evaluation of Category A corrective actions. All requirements satisfactorily met.

 IPPOLITO.T.A. Operating Reactors Branch 3. 80/03/21. 58pp. 07329:342.
- 8012270491 Responds to 801126 ltr.TJ Perkins shall no longer be involved w/nuclear matters for util pending final resolution. DDN.ON.H.J. Niagara Mohauk Pover Corp. 80/12/03. 2pp. 07335:157.
- R. Periodic operating reports & related correspondence
- 6012160474 Forwards monthly operating rept for Nov 1980. LEMPOES, T. E. Niagara Mohawk Power Corp. 80/12/08. 1p. 07255:330.
- --8012160480 Monthly operating cept for Nov 1980. ROMAN, T. H. Niagara Mohawk Power Corp. 80/12/08. 4pp. 07255:331.
- S. Reportable occurrences, LERs & related correspondence
- B012100477 Forwards LER 80-025/03L-0. LEMPGES, T.E. Niagara Mohawk Power Corp. 80/11/24. ip. 07219:094.
- --Bol2i304Bi LER 80-025/03L-0: on Bol02B, stack gas monitoring sys rendered inoperable when inadvertently left in purge operation mode for 9.5-h. Caused by technician failing to return sys to normal operation. Monitor returned to operation. HARRISON, P. Niagara Mahawk Power Corp. 80/11/24. 2pp. 07218: 089.
- 8012100472 Forwards LER 80-026/01T-0. LEMP0ES.T.E. Niagara Mohawi Power Comp 80/12/02. 1p. 07187:001.
- --8012100475 LER HO-026/OIT-O: on B01118, input prror discovered which resulted in reduction in calculated pressure margin to reactor safety valve setpoints during possible transients. HARREDN.P. Niagara Mohawk Power Corp. 80/12/02. 2pp. 07187:001.
- DOCKET 50-224 UNIV. OF CALIFORNIA RESEARCH REACTOR
 P. Operating license stage documents & correspondence
- 8012010561 Forwards Amend 3 to License R-101 & safety evaluation. MILLER, J.R. Standardization & Special Projects Branch. 80/11/19. 2pp. 04916:001.
- --8012010564 Amend 3 to License R-101, permitting possession of up to 25 g enriched U other than fuel elements & use of 1 & 10 Ci PuBe sources & correcting discrepancy in max allowable rod drop time.

 MILLER, J. R. Standardization & Special Projects Branch. BO/11/19.
 Ann. 05916:001.
- --B012010571 Safety evaluation supporting Amend 3 to License R-101.

 Office of Nuclear Reactor Regulation. Director. 80/11/19. 2pp. 04914:001.
- DOCKET 50-226 TARAPUR ATOMIC PROJECT
 P. Operating license stage documents & correspondence
- 8012110008 Forwards application by GE for license to export replacement parts to India. #ILSON.B.D. General Electric Co. 80/11/14. 3pp. 07223:114.
- --8012110015 Application by GE for license to export replacement parts to India. WILSUNG D. General Electric Co. 80/11/14. ip. 07223:117.
- DOCKET 50-227 TRIGA THERMIONIC PROTOTYPE REACTOR

 J. Insurance & indemnity information
- 8012020562 Forwards Endorsement S1 to MAELU Policy MF-59. CORREALM.A. Marsh & McLennan.Inc., H & M Nuclear Consultants, Inc. Div. 80/11/20. 2pp. 07148:071.

- DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

 G. Inspection reports, IE Bulistins & correspondence
- 8012310411 Forwards 1E Insp Rept 50-228/80-02 on 801007-08. No noncompliance noted. CREWS.J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/11/19. 2pp. 07370:184.
- --B012310415 IE Insp Rept 50-228/80-02 on B01107-08. No noncompliance noted Hajor areas inspected organization, logs & records, review & auditorequalification training & surveillance. HORN, A.J., CHAFFEE, A.E., Region 5, San Francisco, Office of the Director. FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/11/18, App. 07370:186.
- DOCKE: 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 8012190342 Informs of recently approved revised 10CFR50.48 containing schedules for completion of all fire protection mode.No present implementation required as necessary add1 info has not yet been approved.

 EISERWUT.D. O. Division of Licensing. 80/11/06. 6pp. 07286:101.
- BD12020167 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers.W/o enci health physics network manual.

 KEPPLERJ. G. Region 3. Chicago. Office of the Director. B0/11/19. 2pp. 0714B:202.
- 8012120576 Resubmits security plan revisions, in response to NRC 800910 & 1119 ltrs. Plan withheld from public disclosure (ref. 100FR2.790). We encl.
 ADEL.J. S. Commonwealth Edison Co. 80/12/08. 1p. 07227: 292.
- G. Adjudicatory correspondence
- 8012020581 Request for reconsideration of ASLB 801120 order granting continuance or, alternatively, for certification to Commission. Certificate of Svc encl. MURRAY, M. J. Illinois, State of. 80/11/26. 4pp. 07147:271.
- 8012170669 Forwards Director's decision under 100FR2.206 & FR notice danging 801024 patition to shot down facilities, panding installation of required scram discharge vol munitoring equipment.

 DENTOK H.R. Office of Nuclear Reactor Regulation, Director.
 80/11/26. 1p. 07269:216.
- --8012170678 Director's decision under 100FR2.206, denying Pollution & Environ Problems. Inc 801024 petition to shut down facilities, pending installation of required scram discharge vol monitoring equipment.

 DEMIDM.H.R. Office of Nuclear Reactor Regulation, Director. 80/11/26. 7pp. 07269:218.
- --8012170693 Notice of issuance of Director's decision under 10CFR2, 206, denying Poliution & Environ Problems 801024 petition. CASE.E. 9. Office of Nuclear Reactor Regulation, Director. 80/11/26. 2pp. 07269: 225.
- 8012300324 Forwards applicant motion to strike intervenor. State of IL. cross-examination of ML Wohl, applicant brief in support of motion to strike & applicant corrections to 801119-21 hearing transcript.
 FITZOIBEONS,R. Isham, Lincoln & Beale. 80/12/01, 1p. 07357:118.
- --B012300333 Motion to strike cross-examination of ML Wohl by intervenor, State of IL Cross-examination has no relevance to intervenor Contention & re accident consequences considered in FBAR, SER & FES.
 STEPTOE, P. P. Commonwealth Edison Co. STEPTOE, P. P. Isham, Lincoln & Beale. B0/12/01. 1p. 07357:119.
- --8012300341 Brief in support of applicant motion to strike cross-examination of MH Wohl by intervenor. State of IL re Contention 6. Supporting documentation & Certificate of Svc encl.
 STEPTOE, P. P. Commonwealth Edison Co. STEPTOE, P. P. Isham, Lincoln & Beale. 80/12/01 14pp. 07357:120.
- --BD12300345 Corrections to transcript of B01119-21 spent fuel pool mod hearings in Morris. IL. a Commonwealth Edison Co. B0/12/01. 18pp. 07357:134.

- 80:21:10540 Forwards Olympic Associates checklist documents re Leckenby audit par 80:118 request. Internal Nuclear Bycs Comp audit, requested 80:203, re Lasalle work is being located Related correspondence. N/o enci.
 FITZOIBBONS, R. Isham, Lincoln & Beale. 80/12/05. 1p. 07222:359.
- 8012270659 Response in opposition to State of IL 801126 motion for reconsideration of ASLB decision to grant continuance or in alternative, for certification. Certification should not be granted for scheduling matters. Certificate of Svc encl. STEPTOE, P. P. Commonwealth Edison Co. STEPTOE, P. P. Isham, Lincoln & Beale. 80/12/10. 6pp. 07333:082.
- B012300090 Response in opposition to applicant motion to strike crossexamination of ML Wohl Wohl testimony shows that NRC did not consider multiple failure analyses in SER. FAHNER,T.C., MURRAY,M. J. lilinois, State of, 80/12/10. Spp. 07359:007.
- --8012300093 Draft, "Sys Interaction & Single Failure Criterion," App A. Certificate of Svc enci.

 * MHB Technical Associates. 80/11/30. 21pp. 07359:015.
- BO12160332 Notifies that 801203 request for "Internal Audit of La Salle Pipe Stress Analysis & Support Design (SAR-0303) -- Internal Audit Rept 80-3," cannot be honored Document is not relevant to spent fuel rack proceeding for facilities, STEPTOE,P. Isham, Lincoin & Beale. 80/12/11. ip. 07262:009.
- 8012170410 Requests refusal of util application to transfer spent nuclear fuel rods from Dresden units to Quad City units for storage.NRC should hold public hearings. * Citizens for Bafe Energy. 80/12/11. 2pp. 07269:351.
- B012230284 Order granting NRC motion for extension until 801219 to respond to applicant motion to strike State of IL crossexamination of ML Wohl. MOLF.J. Atomic Safety and Licensing Board Panel. 80/12/11. 1p. 07317:362.
- 8012300081 Forwards cover page for response in opposition to applicant motion to strike cross-examination of ML Wohl.
 MURRAY, M. J. Illinois, Etate of. 80/12/11. ip. 07358:342.
- --B0123000B4 Cover page to response in opposition to applicant motion to strike cross-examination of ML Wohl. FAHNER, T.C., MURRAY, M. J. Illinois, State of. B0/12/11. ip. 07338: 343.
- 8012300122 Forwards closeout documents re Nuclear Svc Corp audit of Brooks & Perkins on 791212 & 13.Applicant will request permission from ASLB during 801218 conference call to file proposed findings of fact on 801222.

 S
- --8012300129 Corrections to transcript of 801119-21 hearings.

 + Atomic Safety and Licensing Board Panel. 80/12/11. 6pp. 07358:318.
- 8012230019 Response in opposition to intervenor 801126 motion for reconsideration or certification to Commission re spent fuel pool mod Certificate of Svc encl.

 GDDDARU.R. Hearing Branch 2. 80/12/15. 5pp. 07311:185.
- 8012290149 Order requesting applicant to file proposed findings of fact on or before 801222: intervenors. State of 1L. on or before 810130 & NRC on or before 810213. HDLF-J.F. Atomic Sefety and Licensing Board Panel. 80/12/19. 2pp. 07344:053.
- 8012290213 Response in support of applicant 801201 request to strike State of IL crossexamination of ML Wohl Role of ASLB in license amend proceeding is limited by scope of contentions. Certificate of Svc encl. ODDDARD.R.J. Hearing Branch 2. 80/12/19. 7pp. 07344:253.
- B012310288 Forwards applicant proposed findings of facts per 801218 telcon. Incomplete sections & omissions noted. STEPTUE, P. P. Isham, Lincoln & Beale. 80/12/22. 1p. 07370: 065.
- --8012310289 Proposed findings of facts. Matters in controversy include criticality. OA: transportation damage, corrosion, radwaste treatment, radiation monitoring & accidents. Certificate of 8vc encl.

 * Commonwealth Edison Co. * Isham, Lincoln & Beale. 80/12/22. 85pp. 07370:066.

- 8012310419 Order denying 801126 motion for reconsideration of util motion for continuance of hearing or alternatively for cartification. No merit in contention that requiring further evidence adversely affected intervenor case.

 MOLF, J. F. Regulations Division, 80/12/22, 3pp. 07370:190.
- P. Operating license stage documents & correspondence
- 8012110923 Forwards request for addl info for review of SEP Topic VII-1.A re isolation of reactor protection from nonsafety devices. Util must provide acceptance criteria for each identified isolator.

 LAINAG. G. C. Assistant Director for Safety Assessment. 80/10/22. 3pp. 07223: 258.
- B012160050 Ltr to operating plant licensees. CL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Enci 1 implementation dates will be met. EISENHUT.D. Q. Division of Licensing. 80/10/31. 7pp.
- B012220358 Ltr to all CP & OL holders for BNRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing. B0/11/04. App.
- B012010503 Informs of decision to delay completion of SEP Topic 16. Tech Specs.until completion of all other SEP Topic reviews & integrated safety assessment.allowing for integrated evaluation of current Tech Specs. CRUICHFIELD.D. Operating Reactors Branch 5. 80/11/05. ip. 07098.234.
- 8012080089 Forwards Amends 50.59 & 54 to Licenses DPR-19.DPR-29 & DPR-30, respectively, safety evaluation & notice of issuance & availability.

 1PPOLITO, T. A. Operating Reactors Branch 2. 80/11/12. 2pp. 07180:352.
- --8012080075 Amends 80.59 & 54 to Licenses DPR-19, DPR-29 & DPR-30, respectively, establishing max average planar linear heat generation rate limits for std 8X8 fuel types for exposure values.

 IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/12. 23pp.
- --B0120B0102 Safety evaluation supporting Amends 50.59 & 54 to Licenses PR-19, PR-29 & PR-30 respectively. ** Office of Nuclear Reactor Ragulation, Director. 80/i1/12. 4pp. 07181:016.
- --8012080106 Notice of issuance & availability of Amends 50.59 & 94 to Licenses DPR-19.DPR-29 & DPR-30.respectively. IPPOLITE, T. A. Operating Reactors Branch 2. 80/11/12. 2pp. 07181:020.
- B012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," Confirmation that implementation dates will be mot must be sent within 45 days. (4/o encl. EIBENHUT, D. G. Division of Licensing. 80/11/13. ip.
- 8012090580 Forwards Revision i to "SEP Review of Safe Shutdown Sys for Dreaden Unit 2 Nuclear Power Plant." Requests notification within 90 days of receipt of ltr if as-built facility differs from licensing basis. CRUTCHFIELD.D. Derating Reactors Branch 5. 80/11/14. 90pp. 07206; 223.
- 8012180620 Forwards Amends 32.51 & 45 to Licenses DPR-2.DPR-19 & DPR-25.respectively. Amends 60 & 55 to Licenses DPR-27 & DPR-30.respectively & Amends 58 & 55 to Licenses DPR-37 & DPR-4B.respectively. Safeguards contingency plans acceptable. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/17. 5pp. 07271:324.
- --8012180633 Amends 32,51 & 45 to Licenses DPR-2, DPR-19 & DPR-25, respectively, requiring implementation of safeguards contingency plan GRUTCHFIELD, D. Operating Reactors Branch 5. IPPOLITO, T. A. Operating Reactors Branch 2. 80/ii/i7. 6pp. 07271:329.
- --B012180671 Notice of issuance of Amends 32.51 & 45 to Licenses DPR-2 DPR-19 & DPR-25 respectively Amends 60 & 55 to Licenses DPR-29 & DPR-30 respectively & Amends 58 & 55 to Licenses DPR-39 & DPR-49(respectively re safeguards contingency plan. CRUTCHFIELD, D. Operating Reactors Branch 5. 80/11/17. 2pp. 07271:343

- 8012110426 Forwards F Rosa 790930 memo re SEP Topic VIII-3.8."DC Power Sys Bus Voltage." CRUICHFIELD.D. Operating Reactors Branch 5. 80/11/18. 2pp. 07225;138.
- 8012020091 Confirms 801016 & 17 beloons rejutil commitments to perform well water tampling & analysis at locations around site. Analyses will be performed for gross alpha, gross beta & tritium.

 DAVIS,A.B., Region 3, Chicago, Fuel Facility & Materials Bafety Branch, 80/11/19. 3pp. 07148:352.
- 8012090400 Informs that info requested re SEP Topic VI-3 was submitted to NRC in 801103 ltr to DG Eisenhut.

 JANECER.R.F. Commonwealth Edison Co. 80/11/20. 1p. 07207:136.
- 8012160510 Comments on NRC 800812 ltr evaluating SEP Topic VI-10.8, "Shared Engineered Safety Features." Operating procedures dictate proper position of normal/bypass switch Forwards GE "Bir Power Plant Training." Revision 5. JANECEM.R.F. Commonwealth Edison Co. 80/11/24. 3pp. 07187:001 80/11/24. 3pp. 07187:001.
- --8012160512 "BWR Power Plant Training," Revision 5.
 4 General Electric Co. 74/10/14. 28pp. 07187:001.
- --8012160517 DOP 6600-8: "Diesel Generator Normal-Bypass Switch Operation." 4 Commonwealth Edison Co. 76/07/31. 29p. 07187:001.
- ---8012160519 DOP 6900-1, Revision 3, "250 VDC Electrical Sys."
 Commonwealth Edison Co. 79/07/31. 4pp. 07187:001.
- --8012160522 DDP 6900-2. Revision 4, "125 VDC Electrical Sys."

 * Commonwealth Edison Co. 79/07/31. Spp. 07187:001.
- --B012160525 DOP 4900-9. Revision 1. "Station Battery Isolation & Return to Normal for Discharge Testing Unit 2 or U3 24/48 VDC Battery." Commonwealth Edison Co. 79/08/31. Spp. 07(87:001.
- --8012160528 DOP 6900-10, Revision 2, "Station Battery Isolation & Return to Normal for Discharge Testing US 125 VDC Battery." + Commonwealth Edison Co. 79/08/31. Spp. 07187:001.
- --8012160532 DDF 6900-11, Revision 2. "Station Battery Isolation & Return to Normal for Discharge Testing U2 125 VDC Battery."

 + Commonwealth Edison Co. 79/08/31. 6pp. 07187:001.
- --Bol2160537 DOP 6900-12.Revision 1. "Station Battery Isolation & Return to Normal for Discharge Testing U2 250 VDC Battery."

 a Commonwealth Edison Co. 79/07/31. 5pp. 07187:001.
- --R012160539 DUP 6900-13.Revision 1, "Station Battery isolation & Return to Normal for Discharge Testing U3 250 VDC Battery."

 + Commonwealth Edison Co. 79/07/31. 5pp. 07187:001.
- 8012070301 Forwards tabulation of planned environ qualification testing programs in response to NRC 801001 ltr.
 ABEL.J.S. Commonwealth Edison Co. 80/11/26. 4pp. 07148:193.
- 8012110274 Forwards Revision 4 to "Licensing Rept,Dresden Nuclear Power Plant Units 2 & 3 Spent Fuel Rack Mod." originally submitted w/780511 proposed OL amend. JANECEK.R.F. Commonwealth Edison Co. 80/12/02. 2pp. 07225:173.
- --8012110283 Revision 4 to "Licensing Rept.Dresden Nuclear Power Plant Units 2 & 3 Spent Fuel Rack Mod." * Quadrex Corp. GUAD-1-77-234 R4. 80/10/31. 4pp. 07225:175.
- 8012190657 Forwards request for add1 info re 800822 rept entitled, "Evaluation of 18 Inch Containment Isolation Valves for Dresden 2 & 3 & Quad Cities 1 & 2." LAINAS.Q.C. Assistant Director for Safety Assessment. 80/12/02.3pp. 07273:290.
- BD12180002 Immediate action itr confirming actions discussed in 801204 telcon re-problems w/scram discharge vol level monitoring sys. Daily checks of scram discharge vol to be performed until operability of monitoring sys demonstrated. KEPPLER.J.C. Region 3. Chicago. Office of the Director. 80/12/04. 20p. 03791:159.
- 8012220485 Responds to 800911 memo requesting that Dfc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions Forwards results of IE survay.

 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.

- -8012220506 Forwards tabulation & summary of IE survey on low level waste at 31 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012150052 Application to amend Licenses DPR-19 & DPR-25, changing Tech Bpecs. Section 3.8 re limiting conditions for operation of chimney gas sampling sys. Class I & III fees encl. JANECEK, R. F. Commonwealth Edison Co. 80/12/05, 2pp. 07240:331.
- ---8012150054 Proposed Tech Specs, Section 3. B. changing limiting conditions for operation re-chimney gas sampling sys.

 # Commonwealth Edison Co. 80/12/05. 2pp. 07240:333.
- B012120301 Forwards Tech Specs Page 3.2/4.2-15, inadvertently omitted from util 800918 ltr to NRC.
 JANEGEK.R.F. Commonwealth Edison Co. 80/12/10. 2pp. 07234:249.
- --8012120341 Proposed Tech Specs.Page 3.2/4.2-15, incorporating TMI Lessons Learned Requirements.
 + Commonwealth Edison Co. 80/12/10. 1p. 07236:250.
- 8012160136 Responds to ARC 800924 request re mode for provision of redundant Class IE protection at interface of Nonclass IE power supply & reactor protection sys. Installation scheduled for refueling outages occurring after June 1981.

 JANECEK, R. F. Commonwealth Edison Co. 80/12/11. 2pp. 07262:244.
- 801217048B Forwards response to NRC 801031 1tr requesting confirmation that implementation dates indicated in NUREO-0737 will be met. Ability to meet required dates for major mods is contingent upon hardware availability & delivery.

 ABEL, J. S. Commonwealth Edison Co. 80/12/15. 37pp. 07270:294.
- B01224015B Forwards confirmation that implementation dates per NUREO-0737 will be met & justification for exceptions. Generally dates are contingent upon hardware availability & delivery. Comments on safety requirements in Tech Specs. ABEL, J. 8 Commonwealth Edison Co. B0/12/15. 37pp. 07323;001.
- 8012240489 Notification of 801218 meeting w/8EP coners group in Bethasds MD for discussions on BEP program, schedule for license topic completion & assignment of lead topics to RUSSELL.W.T. Systematic Evaluation Program Branch., 80/12/16. 2pp.
- 8012310282 Requests amend of Confirmatory Order re installation of recirculation pump trip by 801231. Amend extends required implementation date to 810104.
 REED, C. Commonwealth Edison Co. 89/12/24. 2pp. 07361:310.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012170510 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 KEPPLER.J. G. Region 3. Chicago. Office of the Director. 80/10/24.
 19. 07268:099.
- 8012170546 Forwards IE Investigation Repts 50-237/80-16 & 50-249/80-20 on 800998-10.

 KEPPLER.J. G. Region J. Chicago, Office of the Director. 80/10/24, 2pp. 07269:159.
- --8012170554 IE Investigation Repts 50-237/80-16 & 50-249/80-20 on 800708-10. Noncompliance noted: two reactor operators apparently asleep on duty.
 PHILI IP.O.A. NORELIUS, C.E., SPESSARD, R.L. Region 3, Chicago, Office of the Director. 80/10/23. 41pp. 07249:141.
- 8012100587 Forwards IE Insp Repts 50-010/80-19.50-237/80-21 & 50-249/80-25 on 800907-1003 & notice of violation. HEIBHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/11/04. 2pp. 07218:144.
- --8012103591 Notice of violation from insp on 800907-1003. * Region 3, Chicago, Office of the Director. 80/10/31, ip. 07218:166.
- --8012100597 IE Insp Repts 50-010/80-19,50-237/80-21 & 50-249/80-25 on 800907-1003.Noncompliance noted: failure to adhere to GA program requirements. TONGUE, T.M., JORDAN, M. J., SPESSARD, R. L. Region 3, Chicago, Office of the Director. 80/10/31. 7pp. 07218: 167,

- 8012020308 Ack receipt of 801030 ltr informing NRC of steps taken to correct violetions noted in IE Insp Repts 50-010/80-14, 50-237/80-17 & 50-249/80-21. HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Brench. 80/i1/10. 1p. 07143:105.
- --8012020312 Responds to NRC 801008 ltr re violations noted in IE Insp. Repts 50-010/80-14.50-237/80-17 & 50-249/80-21. Corrective actions; potential radiological consequences to workers performing maint on control rod driveline pump evaluated. ABEL. J. B. Commonwealth Edison Co. 80/10/30. 3pp. 07143:106.
- 8012290458 Confirms 801110 telecopy requesting extension for response to 801020 notice of violation & proposed imposition of civil penalty until 801124.

 ABEL, J. S. Commonwealth Edison Co. 80/11/12, 2pp. 07335:040.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. W/o encl.

 KEPPLER. J. O. Region 3. Chicago. Office of the Director. 80/11/18, 4pp. 07147:336,
- 8012040667 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/21, 2pp. 07166:358.
- 8012080087 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J. G. Region 3. Chicago: Office of the Director. 80/11/24. 2pp. 07182:252.
- 8012170408 Forwards monthly status rept of evaluations performed in response to IE Bulletin 79-14. "Beismic Analysis for As-Built Safety-Related Piping Sys." No sys identified w/strass erceeding 1/2 math ultimate stress at UBE loadings. JANECEK, R. F. Commonwealth Edison Co. 80/11/24. 14pp. 07187:001.
- 8012290466 Protests civil penalty imposed in 801020 ltr & notice of violation. NRC failed to use appropriate enforcement criteria in classifying severity level of noncompliance. REEO, C. Commonwealth Edison Co. 80/11/24. 6pp. 07338:044.
- 8012290470 Refutes item of noncompliance re two on-duty operators allegedly found asieep on 800808. Operators were present at prescribed stations & able to perform all required functions.

 REEO.C. Commonwealth Edison Co. 80/11/24. 8pp. 07335:052.
- 8012230223 Forwards new security badge numbers & clearance levels for Region 3 personnel. Changes should be entered on Sept 1980 access lists.

 KEPPLER.J. O. Region 3. Chicago. Office of the Director. 80/11/25.6pp. 07317:081.
- 8012100661 Ack receipt of 800919 response to NRC 800818 ltr requesting add1 info re IE Bulletin 79-14 evaluations. Dresden & Guad Cities responses to Items 1 & 3 unacceptable, since requested info was not included.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/26, 300
- 8012170552 Forwards IE Info Notice 80-29, Suppl 1: "Broken Stude on Terry Turbine Steam Inlet Flange," No written response required. KEPPLER J. O. Region 3: Chicago: Office of the Director. BO/11/26. 2pp. 07264:286.
- B012110602 Ack receipt of 801112 ltr informing NRC of steps taken to correct violations noted in IE. Insp Repts 50-010/80-16, 50-237/80-19 & 50-249/80-23. HIND. J. A. Region 3. Chicago, Bafeguards Branch. 80/12/01. 1p. 07226:175.
- --8012110608 Responds to NRC 801022 ltr re violations noted in IE Insp Repts 50-010/80-11,50-237/80-19 & 50-249/80-23, Corrective action withheld (ref 10CFR2,790). ABEL.J. 8. Commonwealth Edison Co. 80/11/12. 1p. 07226:176.
- 8012090044 Notification of 801209 meeting w/util in Bethesda,MD to discuss acceptance criteria used for evaluation of piping sys under review for IE 8011etin 79-14. MONGH.J. Office of Inspection & Enforcement, Office of the Director. 80/12/04. 2pp. 07198:078.

and the second second

- 8012230065 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." No valve parts cast by Malcolm Foundry planned for use or in use at facilities.

 RAUSCH.T.J. Commonwealth Edison Co. 80/12/05. 2pp. 07311:081.
- 8012310629 Ack receipt of 801123 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-010/80-19, 50-237/80-21 & 50-249/80-25.
 HEISIMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09. ip. 07371:052.
- -8012310630 Responds to NRC 801104 ltr re violations noted in IE Insp Rapts 50-010/80-19,50-237/80-21 & 50-249/80-25. Corrective actions:cleaned arsas & removed combustible matl. ABEL, J. S. Commonwealth Edison Co. 80/11/25. 4pp. 07371:053.
- 8012240427 Addi response to FOIA request for documents re imposition o civil penalties.ARC requests for congressional authorization for more severe penalties & responsibilities & behavior of nuclear plant operators. Forwards investigation rept. FELTON.J.N. Division of Rules and Records, 80/12/12. 1p. 07324:310.
- --8017240432 "Investigation of Alleged Sleeping Control Room Operators Drasden Nuclear Power Station Morris, IL, 800808." CUMMINOS, J. J., 8TRICKLER, L. J. Office of Inspector & Auditor, 80/09/17. 34pp.
- 8012300118 Discusses IE insp on 800723 & forwards notice of violation : notice of proposed imposition of civil penalty.

 STELLO, V. Defice of Inspection & Enforcement, Office of the Director. 80/12/19. 2pp. 07356:253.
- --8012300124 Notice of violation from insp on 800723. Noncompliance not waste mat1 delivered in improper packaging w/no provision for securing lid.

 d Office of Inspection & Enforcement, Office of the Director, 80/12/19. ip. 03810:174.
- --8012300130 Notice of proposed imposition of civil penalty in amount of 1000 for item of noncompliance noted in IE insp on 800723.

 4 Office of Inspection & Enforcement, Office of the Director. 80/12/19. 1p. 07356:236.
- R. Periodic operating reports & related correspondence
- 8012140419 Forwards monthly operating repts for Nov 1980. SCOTT.D.J. Commonwealth Edison Co. 80/12/08. 1p. 07254:12
- --8012160420 Konthly operating repts for Nov 1980. CIEBIKIEW102.8. Commonwealth Edison Co. 80/12/01, 15pp. 07234:125.
- S. Reportable occurrences, LERs & related correspondence
- 8012040270 Ack receipt of 801030 itr re investigation of alleged release of radioactively contaminated water. Requests add1 info on conclusions that flowpaths w/excess background levels have not & are not transporting contaminated water. KEPPLERIJ. O. Region 3, Chicago, Office of the Director. 80/11/14. 2pp. 07162:333.
- --8012040333 Responds to Sept 1980 allegations re release of contaminat water into environ. Investigation noted no detectable threat to public & insp revealed no discrepancies which could result in leakage. Forwards detailed summary of results.

 REED.C. Commonwealth Edison Co. 80/10/30. App. 07162:33
- 8012160538 Forwards LER 60-043/03L-0, 800TT, D. J. Commonwealth Edison Co. 80/12/03. ip. 07261:1
- --8012160543 LER 80-043/03L-0: on 801113, found pressure switch low trip point. Caused by instrument drift. Pressure switch reset.
 ROHLEY.E. Commonwealth Edison Co. 80/12/05. ip. 07261:170.
- 8012230500 Forwards LER 80-044/03L-0. 8COTT, D. J. Commonwealth Edison Co. 80/12/12, 2pp. 07316:244.
- --8012230506 LER 80-044/03L-0: on 801124, target rack safety relief valvinoperable pressure alarm 2A annunciated, indicating target rack not operable in safety mode, Cause unknown, Contined operation permissible due to overpressurization analysis.

 GPEROFF, R. D. Commonwealth Edison Co. 80/12/15. ip. 07316:246.

T. Hearing transcripts on non-antitrust matters

- 8012010518 Transcript of 601119 hearing in Morris.lL re spent fuel pool mod.Pp 73-270. + Atomic Safety and Licensing Board Panel. 80/11/19. 200pp. 07093:314.
- 8012070614 Transcript of 801120 hearing in Horris, IL re spent fuel pool nod. Pp 271-503.

 * Atomic Safety and Licensing Board Panel. 80/11/20. 350pp. 07131: 197.
- B012080038 Transcript of 801120 hearing evening session in Morris 1L re spent fuel pool mod.Pp 504-573. # Atomic Safety and Licensing Board Panel. 80/11/20. 69pp. 07180:222.
- B012010523 Transcript of B01121 hearing in Morris. LL re spent fuel pool mod. Pp 571-721.

 a Atomic Safety and Licensing Board Panel. B0/11/21, 195pp. 07093:155.
- 8012300324 Forwards applicant motion to strike intervenor. State of IL. cross-examination of HL Wohl, applicant brief in support of motion to strike & applicant corrections to 801119-21 hearing transcript.
 FITZQIBSONS.R. Isham, Lincoln & Beale. B0/12/01, 1p. 07357:118.
- --8012300345 Corrections to transcript of 891119-21 spent fuel pool mod hearings in Morris, IL.
 Commonwealth Edison Co. 80/12/01, 18pp. 07357: 134.
- 8012290404 Forwards NRC proposed corrections to transcripts of 801119-21 hearings. GDDARD, R. J. Hearing Branch 2. 80/12/10. 1p. 07336:302.
- --8012290412 Proposed transcript changes. Certificate of Svc encl.

 * Atomic Safety and Licensing Board Panel. 80/12/10. 12pp.
 07336: 303

V. Operator Examinations

- 80:2160510 Comments on NRC 800812 ltr evaluating SEP Topic VI-10.8. "Shared Engineered Safety Features." Operating procedures dictate proper position of normal/bypass switch Forwards GE "Buy Power Plant Training," Revision 5.

 JANECER, R. F. Commonwealth Edison Co. 80/11/24. 3pp. 07187:001.
- --8012160512 "BWR Power Plant Training," Ravision 5.
 General Electric Co. 74/10/14. 28pp. 07187:001.
- DOCKET 50-243 OREGON STATE UNIV. RESEARCH REACTOR
 S. Reportable occurrences, LERs & related correspondence
- 8012300453 RG: on 801212. reactor operated for approx 1-h u/ nonfuctioning air pump on reactor top continuous air particulate radiation nonitor. Caused by loosely fitting power plug k/or loose fuse holder connaction. WANG.C.H. Oregon State Univ. 80/12/19. 3pp. 07357:201.
- DOCKET 50-244 ROSERT EMHET GINNA NUCLEAR PLANT. UNIT 1 F. Security, majical, emergency & fire protection plans
- 8012190011 Informs of recently approved revised ICCFR50.48 containing schedules for completion of all fire protection mods.No present implementation required as necessary addl info has not yet been approved.

 EISENRUT, D. O. Division of Licensing. 80/11/06 6pp. 07278:195.
 - Informs of review & resulting mods to emergency notification with physics natuors. NRC will have lamps installed you telephones in all control rooms & technical

viladelphia, Office of the Director.

w/selection of basement of Wayne hool as emergency offsite tans for util emergency

tric Corp. 80/11/24. Spp.

- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake.

 EISENHUT, D. O. Division of Licensing. 80/10/21. 4pp.
- B012160050 Ltr to operating plant licensees.DL applicants & CP holders. Forwards NUREO-0737 re THI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISENHUT.D. O. Division of Licensing. 80/10/31. 7pp.
- B012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BMR Feedwater Notale & Control Rod Drive Return Line Notale Cracking, " Confirmation that implementation dates will be not must be sent within 45 days.
- B012090038 Forwards current evaluation of GEP Topics V-10.B, V-11.A, V-11. B, VI1-3 & IX-3 re safe shutdown sys. Evaluation will be basic input to integrated safety assessment, CRUTCHFIELD.D. Operating Reactors Branch 5. B0/11/14. 10ipp. 07197:319.
- 8012190329 Submits concerns identified during reviews of license applications re-containment sump design & effect on long-term cooling following LOCA Debris could potentially block sump screen & core passages in ECCS & core.
 CRVICHFIELD, D. Operating Reactors Branch 5. 80/11/20. App. 07286:084.
- B012010297 Forwards Amend 11 to application to convert provisional OLto full-term OL. Amend constitutes Revision 7 to Buppi 4 to technical suppl accompanying application for full-term OL. Certificate of Svc encl. LEBDEUF, R. J., LAMBIH. R., LEIBY, A. C. LeBoeuf, Lamb, Leiby & MacRae. B0/11/21. 4pp. 07097:214.
- --B012D10259 Amend 11 to application to convert provisional GL to full-term GL. Amend constitutes Revision 7 to Suppl 4 to technical suppl accompanying application for full-term GL. Revision encl. MAIER.J.E. Rochester Gas & Electric Corp. 80/11/14. -22pp. 07097:218
- 8012010784 Requests completed SEP topic assessments for Topic VI-8 re control room habitability & Topic II-1.C re potental offsite hazards. Work on five addl THI-2 related requirements will not start util SEP topic assessments issued. HHITE.L.D. Rochester Gas & Electric Corp. 80/11/24. 2pp. 06915:001.
- 8012010397 Informs NRC that responses to BEP Topics VI-7. A. 3 & VI-10. A were provided on 800910. Addi copies can be supplied, if necessary.
 MHITE, L. D. Rochester Qas & Electric Corp. 80/11/24. 1p. 07098: 063.
- 8012160429 Forwards info re util 791206 rept on adequacy at station electric distribution sys voltages. Info provided to assure reviewers of rept that analyses are consistent w/NRC guidelines for voltage drop calculations. MAIER. J.E. Rochester Gas & Electric Corp. 80/12/04. ip. 07248: 343.
- 8012220485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENION, H.R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at Bi reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w//1% planning or considering increasing storage capacity.
 BANGART-R.L. Effluent Treatment Systems Branch. B0/11/06. Bpp.
- 8012290497 Informs of completion of generic review of inadvertent safety injection during cooldown. No further licenting action necessary since facility could probably withstand more than 50 inadvertent ECCS actuations.

 CRUTCH-FIELD.D. Operating Reactors Branch 5. 80/12/05. 2pp. 07335: 298.
- --8012290503 Safety evaluation of inadvertent safety injection during cooldown. Facility could withstand more than 50 inadvertent ECCS actuations since not all actuations will result in cold water injection into hot RCS.

 * Operating Reactors Branch 5. 80/12/05. 1p. 07335:300.

- B012160240 Forwards add1 info providing qualification of certain electrical equipment.per commitment in 801031 ltr responding to NRC 800919 revised order for mod of license.
 MAIER.J.E. Rochester Gas & Electric Corp. 80/12/08. 18pp. 07248:271.
- 8012160540 Forwards Pages 3.10-6 to 3.10-10 of Tech Blees re control rod misalignment.to facilitate review.
 MAIER.J.E. Rochester Gas & Electric Corp. 80/12/10. ip. 07263:074.
- --8012160547 Tech Specs 3.10.4.4 re cantrol rod misalignment. # Rochester Gas & Electric Corp. 80/12/10. 9pp. 07263:095.
- 8012180391 Forwards add1 info concerning rock anchors for containment re tenden insp & lift off verification in response to NRC request at 801021 meeting. Post-tensioning field records enc1. HAIER, J. E. Rochester Gas & Electric Corp. 80/12/11. 164pp. 07244:215.
- --B012180394 "Addl Info on Ginna Rock Anchor Design."
 PAGES,R.E., FULTON, J.F., MOREADITH, F.L. Gilbert/Commonwealth Cos. 80/11/26. 200pp. 07245:017.
- 801222027 Forwards visual aids used during 801107 meeting re plans to install test sleeves in several steam generator tubes. Affidavit supporting proprietary nature of visual aids encl. Blides withheld (ref 10CFR2.790). MAIER, J.E. Rochester Gas & Electric Corp. 80/12/12. App. 07304:058.
- B012220329 Forwards responses to NRC B01031 ltr re clarification of TMI action plan requirements. Util intends to comply w/NRC requirements & implementation dates, Execptions are discussed in encl. Deviations will be communicated. MAIER, J. E. Rochester Gas & Electric Corp. 80/12/15, 11pp. 07301:193.
- 8012220341 Suppls 801031 submittal re "Environ Qualification of Electrical Equipments." Possible effects of motor driven auxiliary feedwater pumps failure due to high energy line break on Class IE sys provided.
 MAIER.J.E. Rochester Gas & Electric Corp. 80/12/15. 2pp. 03797:047.
- B012240489 Notification of 801218 meeting w/8EP owners group in Bethesda. MD for discussions on SEP program, schedule for license topic completion & assignment of lead topics to plants.

 RUSSELL, M. T. Systematic Evaluation Program Branch. 80/12/16. 2pp.
- 8012300093 Forwards util 801231 final rept, "Anchorage & Beismic Support of Safety-Related Electrical Equipment." All safety-related electrical equipment & permanently mounted ancillary assemblies have acceptably engineered anchorage sys. MAIER, J. E. Rochester Qas & Electric Corp. 80/12/22. lp. 07357:256.
- ---8012300397 "Anchorage & Seismic Support of Sefety-Related Electrical Equipment," final rept. * Rochester Gas & Electric Corp. B0/12/31. 30pp. 07357:257.
- Q. Inspection reports. IE Bulletins & correspondence
- B012080072 Forwards IE Insp Rept 50-244/80-12 on 800915-17. No nancompliance noted. BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch, 80/10/09. 2pp. 07189:178.
- --8012080099 IE Insp Rept 50-244/80-12 on 800915-17. No noncompliance noted Major areas inspected:licensed operator requalification training program & independent plant tour. WIGGINS, J. T. Region i, Philadelphia, Office of the Director. CAPHION, D. L. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/07. 7pp. 07189:180.
- 8012170394 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. GRIER.B.H. Region i, Philadelphia, Office of the Director. 80/10/30, ip. 07269:093.
- B012090043 Responds to IE Bulletin B0-11, "Mesonry Wall Design." W/o encl. HAIER, J.E. Rochester Cas & Electric Corp. B0/11/04, ip. 07199:296.

- 8012120097 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER,B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230:240.
- 8012190382 Informs util of issuance of new NRC personnel identification badges, effective after 801130, Example encl. MARTIN, W. J. Region 1, Philadelphia, Safeguards Branch. 80/11/06. 2pp. 07286:143.
- 8012030799 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. GRIER, B. H. Region I. Philadelphia, Office of the Director. 80/11/07. 1p. 07150:228.
- 8012080486 Forwards IE Info Notice 80-41, "Failure of Bwing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. ORIER, B. H. Region i, Philadelphia, Office of the Director. 80/11/10. 1p. 07182:342.
- 8012040060 Forwards IE Bulletin 80-23. "Failures of Sciencid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, B. H. Region 1. Philadelphia, Office of the Director. 80/11/14. lp. 07170:012.
- 8012270671 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.
 GRIER.B.H. Region 1. Philadelphia, Office of the Director.
 80/11/19. 1p. 07293:127.
- 8012040499 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water-Leakage Inside Containment." Uritten response required.Requests info on manpower expended. ORIER. B. H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07169:178.
- 8012050599 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/24. 1p. 07174:095.
- 8012090278 Forwards corrected Pages 1 & 9 to 801105 revision to inservice insp program for 1980-89. WHITE.L.D. Rochester Gas & Electric Corp. 80/12/01. 1p. 07201:081.
- --8012090280 Corrected Pages 1 & 9 to B01105 revision to inservice insp program for 1980-89. ANDERGDN, C. R. Rochester Gas & Electric Corp. 80/11/10. 2pp. 07201: 082.
- R. Periodic operating reports & related correspondence
- 8012270440 Forwards monthly operating rept for Nov 1980. SNOW, B. A. Rochester Oas & Electric Corp. 80/12/10. 1p. 07308:342.
- --8012220443 Monthly operating rept for Nov 1980. MCNAMARA:A E. Rochester Gas & Elactric Gorp. 80/12/11. 5pp. 07308: 343.
- 8. Reportable occurrences, LERs & related correspondence
- 8012300522 Forwards LER 80-010/03L-0. MAIER, J. E. Rochester Oas & Electric Corp. 80/12/23. 1p. 07361; 326.
- --B012300525 LER B0-010/03L-0: on B01125, pinhole leak found in weld on RHR thermowell. Caused by poor quality weld. Weld repaired. BPECTOR, S. M. Rochester Gas & Electric Corp. B0/12/29. 19. 07361: 327.
- POCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F. Sacurity, medical, emergency & fire protection plans
- B012040186 Public version of "Independent Assessment of Evacuation Times for Millstone Nuclear Power Plant," Vol B. prepared for FEHA. COSBY, J. C., SHEPPARD, W. V., LAMAGNA, F. Wilbur Smith & Associates, 80/06/30. 72pp. 07161:289.

- 8012190015 Informs of recently approved revised 10CFR50.48 containing schedules for completion of all fire protection mods. No prasent inflementation required as necessary add1 info has not yet been approved.

 EISENHUT, D. O. Division of Licensirg. 80/11/06. 6pp. 07278:200.
- 8012080716 Informs that mods will be made to emergency notification sys & health physics network equipment. NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operations facilities. GRIER.8.H. Region i. Philadelphia, Office of the Director. BO/11/14. 2pp. 07196:142.
- 8012040639 Transmits emergency planning info for placement in LPDR. W/o encl. SCUDER, J.L. Division of Rules and Records. BO/11/19. 1p. 07170:056.
- 8012049065 Forwards public version of "Evacuation Time Assessment of Mins Nuclear Power Plants Emergency Planning Zones." erecutive summary. FELTON-J.H. Division of Rules and Records. 80/12/03. 1p. 04915-001
- ---8017040088 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEMA,

 * Wilbur Smith & Associates. 80/06/30. 17pp. 06915:001.
- --B012040155 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol 1, prepared for FEMA. COSSY.J.C., EMERPARD.W.V. Wilbur Smith & Associates. B0/06/30. 43pp. 07160:313.

G. Adjudicatory correspondence

- 8012090172 Requests hearing to determine necessity of environ qualification of all safety-related electrical equipment at facilities as required by NRC 801024 orders for mod of licenses.

 COUNSILAR.O. Connecticut Vantee Atomic Power Co. 80/12/04. Jpp. 07200:131.
- P. Operating license stage documents & correspondence
- 8012110337 Forwards request for add1 info for review of SEP Topics III-2. III-4A. III-4B & III-4C. Dutstanding info: location of missile barriers.description of physical characteristics & criteria used for design.

 LAIRAS. G.C. Assistant Director for Safety Assessment. BO/10/24. 3pp. 07224:161.
- 8012110290 Forwards review of SEP Topic VIII-4 re electrical penetrations of reactor compartment Evaluation will be basic input to integrated safety assessment for unit. CRUTCHFIELD.D. Operating Reactors Eranch 5. 80/10/30. 17pp. 07224:098.
- 80:2070012 Follows up original 800331 ltr.providing status & revised schedules for completing additional section anchor evaluations formerly identified. Results of Items 4 & 8 portions of Item 1.2 scheduled for submittal by 810228.

 COUNBIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/10/31. 2pp. 07179: 329.
- 8012160350 Ltr to operating glant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl i implementation dates will be net. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- B012220358 Ltr to all CP & OL holders for BWRs re requirement for implementation of GDYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISERHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- B012220563 Ltr to all power reactor licensees forwarding NUREQ-0619, *BUR Feedwater Norzle & Control Rod Drive Return Line Nazzle Cracking. *Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EISENMUT, D. Q. Division of Licensing. B0/11/fg. ip.
- 8012010101 Forwards add1 info re station electric distribution sys voltages.completing NRC 800627 request Data sheets surmarizing cases analysed in studies & voltage analysis for accident of visualitaneous shutdown included. COUNSIL.N. 9. FEE.N. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/11/14. 20pp 07098:214.

- B012020573 Notifies that B01031 updated NUREO-0737, "TMI Action Plan" re revised analyses models for small break LUCA will be handled by GE. 9E will discuss approach to analysis on B01215.
 COUNSII. N. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B0/11/14. 2pp. 07141:274.
- B012040211 Forwards Revision 1 of SEP reviaw of safe shutdown sys for facility & NRC positions re review.Evaluation will be basic input to integrated safety assessment for unit. CRUTCHFIELD.D. Operating Reactors Branch 5.
- 801211080B Forwards Amend 70 to License DPR-21, safety evaluation & notice of issuance & availability.

 CRUTCHFIEL D. D. Systematic Evaluation Program Branch. 80/11/19.

 2pp. 07223: 126.
- --8012110B12 Amend 70 to License DPR-21 revising License Condition 3.F in conjunction w/issuance of tuppl to Pire protection SER resmoke detection systests.
 CRUTCHFIELD.D. Systematic Evaluation Program Branch. 80/11/19.
 2pp. 07225:12B.
- --8012110817 Safety evaluation supporting Amend 70 to License DPR-21.

 * Office of Nuclear Reactor Regulation, Director. B0/11/19. 3pp. 07225:130.
- --B012110B19 Notice of issuance & availability of Amend 70 to License DRR-21.

 CRUTCHF1ELD.D. Systematic Evaluation Program Branch. 80/11/19. 200. 07225:133.
- B012050202 Responds to NRC 800924 ltr re commitments & schedules for installing reactor protection sys power supply isolation devices. Class IE protection will be installed during next refueling outage scheduled for Spring 1982.

 COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B0/11/24. ip. 07175:042.
- 8012240047 Informs of review of 800808 submittal providing results of operability review of purge/vent valves. Forwards request for addl info.

 LAINAS. O. C. Assistant Director for Safaty Assessment. 80/11/26.

 3pp. 07324:276.
- 8012070172 Requests hearing to determine necessity of environ qualification of all safety-related electrical equipment at facilities, as required by NRC 801024 orders for mod of licenses.

 CDUNSIL.H.O. Connecticut Yankee Atomic Power Co. 80/12/04, 3pp. 07200:131.
- B012220485 Responds to B00911 memo raquesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION-H.R. Office of Nuclear Reactor Regulation, Director, B0/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. B0/11/06. Opp.
- B012180451 Forwards add1 info re SEP Topics III-2, III-4A, III-4B & fil-4C, GE rept, "Analysis of Turbine Hissiles Resulting From Last Stage Wheel Failure." & 9 aperture cards of structural drawings.per NRC 801024 request One illegible drawing encl. CQUNSIL.11.0. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/05. 2pp. 07308:001.
- --8012180464 "Analysis of Turbine Missiles Resulting From Last Stage Wheel Failure." ZMICK, E. E. General Electric Co. TR-675L211. 80/12/31. 79pp. 07308: 001.
- B012160371 Provides info in response to NRC B00B20 request for comparison of onsite amergency power sys diesel generator to licensing basis assumed in assessment of SEP Topic VIII-2. COUNSILM. C. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B0/12/09. 3pp. 07243:347.
- 8012230262 Forwards response to NUREO-0737 re implementation status of TMI-related requirements.
 COUNSIL.H.O. Connecticut Yankee Atomic Power Co. COUNSIL.H.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
 80/12/15. 41pp. 07314:023.

- 8012240489 Notification of 801218 meeting w/SEP owners group in Bathesda, MD for discussions on SEP program, schedule for license topic completion & assignment of lead topics to plants.

 RUSSELL, W. T. Systematic Evaluation Program Branch. 80/12/16. 2pp.
- B012270270 Bubmits Class III fee previously omitted from 801112 ltr. CDUNSIL, M. G., FEE, W. F. Northeast Utilities. 80/12/16. 1p. 07346:122.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012020320 Requests that response to IE Bulletin 80-i5, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power," be resubmitted w/oath or affirmation within 10 days of receipt of Itr.per 10CFR50.54.

 GRIER.B. H. Region 1. Philadelphia, Office of the Director. 80/10/23, Ip. 07143:114.
- 8012220071 Forwards IE Insp Repts 50-245/80-17 & 59-336/80-19 on 800907-1004. No noncompliance noted. BRUNNERS.U. Region 1: Philadelphia. Reactor Operations Nuclear Support Branch. 80/10/24. 2pp. 07306:337.
- --B012220077 IE Insp Repts 50-245/80-17 & 30-336/80-19 on 800907-1004. No noncompliance noted. Major areas inspected:control room & accessible portions of Unit I reactor, turbine, radwaste & gas turbins generator.

 SHEDLOSKY, J. T., ZIMMERMAN, R. P. Region 1, Philadelphia, Office of the Director. KEIMIO, R. R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/27, 12pp. 07306:339.
- 8012120113 Forwards 1E Bulistin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/04. 1p. 07230:221.
- 8012190377 Informs util of issuance of new NRC personnel identification badges, effective after 801130. Example encl. MARTIN, N. J. Region 1, Philadelphia, Safeguards Branch. 80/11/06. 2pp. 07286:139.
- 8012030787 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. BO/11/07. 1p. 07150:207.
- 8012080474 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIERIB. H. Region i, Philadelphia, Office of the Director. 80/11/10. 1p. 07182:330.
- 8012040092 Forwards IE Bulletin 80-29, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B.M. Region 1, Philadelphia, Office of the Director. 80/11/14. 1p. 07157:353.
- 8012310389 Responds to IE Bulletin 80-13, "Cracking in Core Spray Spargers." Exam of upper & lower core spray spargers on 801017 confirms that no cracks or adverse indications were observed. Exam rept enci.
 COUNBIL.H.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/11/17. 8pp. 07369:205.
- 8012130117 Forwards safety evaluation & notice granting relief from Inservice insp requirements of Section XI ABME Code to allow postponement of Category B-L-2 exam beyond insp interval ending 80122B.

 CRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/17. 2pp. 07241:180.
- --8012150120 Safety evaluation supporting relief from inservice insprequirements of Section XI ABME Code to allow postponement of Category B-L-2 exam beyond insprinterval ending 801228.

 * Operating Reactors Branch 5. 80/11/19. 2pp. 07241:182.
- --8012150123 Notice of granting of relief from inservice inspreduirements of ASME Code Section XI to allow postponement of Category B-L-2 exam beyond insprinterval ending 801228. CRUICHFIELD.D. Operating Reactors Branch 5. 80/11/19. 2pp. 07241:184.
- 8012220616 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. ORIER, B. H. Region i. Philadelphia, Office of the Director. 80/11/19. jp. 07308:358.

- B012040475 Forwards IE Dulletin B0-24, "Prevention of Damage Due to Mater Leakage Inside Containment." Unitten response required Requests info on manpower expended. ORIER, B.H. Region i, Philadelphia, Office of the Director, 80/11/21. 2pp. 07169:166.
- 8012050573 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/24, jp. 07174:062,
- 8012220123 Informs NRC that results from re-evaluation of scram discharge sys per IE Bulietin 80-17 & schedule for implementation of any required mods will be provided by 810115.

 COUNSIL, U.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W.O. Northeast Utilities. 80/12/15. ip 07200-191
- R. Periodic operating reports & related correspondence
- B012230342 Forwards monthly operating rept for Nov 1780. MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/15. 1p. 07318:233.
- --8012230343 Monthly operating rept for Nov 1980. HARRAN.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/04. 5pp. 07318:234.
- 8. Reportable occurrences, LERs & related correspondence
- 8012230487 ETS-NR/50-245/80-03 & 50-334/80-03: on 801105, Ag-110m activity exceeded control station average by factor greater than ten. Caused by oyster trays being maintained within quarry bondaries & plant liquid vol increase.

 MRDCZKA,E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 80/12/15, 5pp. 07318:322.
- B012300635 ETB-NR/50-245/50-336/80-03: on B01105, levels of Ag-110m activity observed in fourth quarter sample of oysters exceeded control station average by factor of ten. Caused by increase in plant liquid discharges. New Tech Specs proposed. MROCZKA, E. J. Northeast Utilities. 80/12/15. 3pp. 07346:182.
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 8012040673 Forwards NRC sponsored proprietary vital area analysis of facility. Requests review of existing security plan & response within 60 days of receipt of itr describing results of review. Info withheld (ref 10CFR2.790). VAROA. 6. A. Operating Reactors Branch 1. 80/11/04. 2pp. 07170:057.
- 8012040632 Informs that certain mods will be made to emergency notification sys & health physics network equipment NRC will have lamps installed on emergency telephones in all control rooms, technical support ctra & emergency operation facility. ORIER, B. H. Region i, Philadelphia, Office of the Director. 8D/11/14. 2pp. 07170:079,
- 8012050172 Informs of interim IOCFR50.4B suspending completion dates for previously approved fire protection mods. Revised IOCFR50.4B will contain schedules for completion of all fire protection mods. EISENMUT.D. O. Division of Licensing. BO/11/17. Spp. 07175:015.
- 8012040701 Forwards public version of two FEMA repts entitled "Assessment of Evacuation Time Around Indian Point Nuclear Power Station." FELTON, J. R. Division of Rules and Records. 80/12/01. 1p. 07155:173.
- --8012040704 Public version of draft final rept "Assessment of Evacuation Time Around Indian Point Nuclear Power Station: " elecutive summary, prepared for FEMA.
 4 COMBAD RESEARCH CORP. 4 Center for Planning Research, Inc. 8D/08/21. 34pp. 07195:174.
- --8012040710 Public version of final rept. "Assessment of Evacuation Time Around Indian Point Nuclear Power Station," prepared for FEMA. Public version of Consad Research Corp 800804 ltr encl. COMBAD RESEARCH CORP. * Conter for Planning Research, Inc. 80/06/23. 125pp. 07159: 207.

Q. Adjudicatory correspondence

- 80:2110480 Excerpt from staff requirements memo re 80:114 IE briefing re current facility status.Ofc of General Counsel must revise draft order to include input from Ofc of Policy Analysis. CHILK, S. J. Office of the Secretary of the Commission. 80/11/24. 1p. 07227:135.
- 8012290217 Urges Commission to order ASLB to hold full adjudicatory hearing on contentions & hazards posed by reactors. HEISS, E.R. Sheldon, Harmon & Weiss, 80/11/25, 3pp. 07345:024.
- 8012300278 Staff requirements meno re Commission 801126 meeting on instructions to Board on facility proceeding. CHILK.S.J. Office of the Secretary of the Commission. 80/12/05. 1p. 07357-063.
- 8012150138 Forwards comments on 801124 revised draft order being prepared for ASLB refuture of facility. Order should explain why hearings are being held. NRC should declare intention to reconsider question of interim operation in June 1981.

 HCLT. J. Public Interest Research Group, New York. 80/12/10. 5pp. 07241:161.
- --8012150140 Comments on NRC 800530 order establishing informal proceeding to define scope of ASLB adjudication re UCS petition & criteria for facility. Criteria for decisions should be in terms of worst-case accidents. HDLT.J. Public Interest Research Group, New York. B0/09/26. 9pp. 07241:166.
- B012290236 Status rept recommending no action be taken in Hudson River pawer plant case re closed cycle cooling sys pending further filings by parties. Certificate of Svc encl. MODRE, J. E. Hearing Branch 2. 80/12/22. Spp. 07341:141.

H. General correspondence

- 8012040371 Opposes continued operation of facility we recent findings of rust on inner & outer layers of vessel resulting from Saline River accident. Requests name be added to mailing list to receive info re emergency procedures & public hearings. MACNULTY, J. J. Affiliation Unknown. 80/10/25. [p. 06915:001.
- 8012030/03 Urges permanent shutdown of facilities. Shutdown costs should be assumed by utilinot consumers. BALLILIK. Affiliation Unknown 80/11/24. 1p. 06985:003.
- B012030710 Urges that facilities be shutdown & that customers not pay for util disastrous mistakes which could pose potential danger to public health & safety.

 WEBER.M.S. Affiliation Uninown. B0/11/24. Ip. 06585:003.
- B012030650 Expresses concern on nuclear energy. Con Ed & PASNY should be refused permission to resume facility operations until safety hearings have been held.
 CDNSTUBL L. Affiliation Unknown. 80/t1/25. 1p. 06586:003.
- 8012030695 Requests that correspondence re facilities be directed to JD 0'Toote 0'TOOLE.J.D. Consolidated Edison Co. of New York. 80/11/25. 1p. 07151:237.
- 2012040375 Opposes continued operation of facility until promised safety bearings re recent accidents at plants.

 KUND.H.J. Affiliation Unknown. 80/11/25, 1p. 07159:178.
- 8012040401 Urges immediate establishment of firm natl policy to prohibit plant siting near densely populated areas. Protests ASLAB ruling to consider plant location after const Cites negative factors re nuclear const near Late MI.

 BUSHEMI. J. Indiana. State of. 80/11/25. 1p. 07158:181.
 - 12030254 Demands facility be shot down & that util bear cost. BALL, H. L. Affiliation Unknown 80/11/26. 1p. 06586:003.
- 8012030715 Requests that facilities be permanently shut down. ANGOLOSE, G. Affiliation Unknown. B0/12/01. 1p. 05586:003.
- 8012030718 Requests that facilities be permanently shut down to prevent further accidents. BELDTIJM. Affiliation Unknown. 80/12/01. 1p. 06586:003.

- 8012110539 Requests that NRC revote util OL because of negligence in operating procedures. Extensive tests should be made to determine damage or contamination of environ. All wastes must be sufficiently shielded.

 WEIRS, E. Affiliation Unknown. 80/12/03. 2pp. 07225:293.
- 8012130181 Urges revocation of util license & complete shutdown of facilities in light of saltwater leakage & seismic location. MEISS, E. Affiliation Unknown 80/12/03. 2pp. 07240:357.
- 8012160441 Comments on inept operation of facility. DUFFEE,R. Affiliation Unknown. 80/12/03. 1p. 07243:354.
- 8012110625 Requests that NRC refuse to restart plants until after safety hearings have been held re water leak.
 MIELE.A. Affiltation Unknown. 80/12/04. 1p. 07187:001.
- 8012270049 Forwards constituent J Barrows 801118 ltr re 801017 discovery of water in reactor bldg. Requests response. EMERY, D.F. House of Rep., Armed Services, 80/12/04. 2pp. 07308: 001.
- 8012150169 Submits petition to that down reactors pending full investigation of safety issues.

 * Westchaster Peoples Action Coalition Inc. 80/12/12. ip. 07240: 024.
- 8012290023 Requests Commission deny utils permission to resume operations pending full investigation of safety issues to be adjudicated during forthcoming hearings. LENAHAN.E., LOTOCKI, D., BAKER, E. H. Affiliation Unknown. 80/12/19. 1p. 07344:214.
- 8012300085 Requests that Commission deny utils permission to resume operation of facilities.
 SEIO.M., CARTER,D., PESTCOE,S. Affiliation Untnown. 80/12/23. 2pp. 07395:191.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- B01202006B Summary of Subcommittee on Class 9 Accidents 800702 meeting in Inglewood.CA re possible mitigation features. a ACRS Advisory Committee on Reactor Safeguards. 80/09/17. Spp. 07147: 237.
- P. Operating license stage documents & correspondence
- BO12020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PkRs & describes program NRC is undertating to review capability of operating PkRs to remove decay heat following earthquake.

 EISEKM-UT, D. G. Division of Licensing. 80/10/21. 4pp.
- B012160950 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net.
 EISERHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BKR Feeduater Notile & Control Rod Drive Return Line Natile Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EISEMHUT, D. C. Division of Licensing. 80/11/13. 1p.
- 8012030587 Forwards Amends 28 & 65 to Licenses DPR-5 & DPR-26, respectively & notice of issuance & availability.
 VAROA.S.A. Operating Reactors Branch 1. 80/11/18. 4pp. 07186:340.
- --8012080593 Amends 28 & 65 to Licenses DPR-5 & DPR-26, respectively, adding requirements to maintain safeguards contingency plan & to follow guard training & qualification plan within 60 days of commission approval. VARGA.S A. Operating Reactors Branch 1. 80/11/18. 4pp. 07(86:344.
- --8012080598 Notice of issuance & availability of Amends 28 & 65 to Licenses DPR-5 & DPR-26, respectively. VARCA.S.A. Operating Reactors Branch 1, 60/11/18, 2pp. 07186:348
- 8012160276 Discusses analysis performed for ioss of main feedwater. Results demonstrate that reduced auxiliary feedwater flow rate profile of 300 gpm for first 10 minutes, followed by 400 gpm uill satisfy auxiliary feedwater design basis. O'TODLE, J. D. Consolidated Edison Co. of New York, 80/11/26, 2pp, 07263:146.

- 8012100489 Responds to NRC 800905 request for documentation re actions taken to satisfy TMI action plan Item II.K.3.9. Derivative action has been removed from controller. No derivative function associated w/PORV 456 exists.

 0/TOOLE.J.D. Consolidated Edison Co. of New York. 80/12/01. 1p. 07218:308.
- 80120902B1 Confirms status of steam generator tube examination program for current refueling & maint outage.Evaluations based on profilometry to justify not plugging tube will be submitted for approval. Steam generator tube examination program encl. O'TOOLE, J. D. Consolidated Edison Co. of New York. 80/12/02. 2pp. 07201:084.
- --8012090282 Steam generator tube examination program for 1980-81 refueling & maint outage.

 * Consolidated Edison Co. of Neu York. 80/11/30. 11pp. 07201:086.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B01222050A forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012290315 Expresses opinion that RCS, w/mods described in WCAP-9117, could withstand effects of asymmetric LOCA loads. Detailed safety evaluation is forthcoming.
 VAROA:B.A. Operating Reactors Branch 1. 80/12/09. 3pp. 07346:099.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012300001 Forwards IE Insp Rept 50-247/80-09 on 800629-0823.No noncompliance noted. BRUNNER.E.J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/21. 2pp. 07356:069.
- --B012300003 IE Insp Rept S0-247/B0-07 on 800429-0823. No noncompliance noted. Major areas inspected; shift logs & records, physical security & verification of radwaste sys controls implementation.

 KIBTER: H. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. REBELDHSKI.T. KENNY.T. Region i, Philadelphia, Office of the Director. 80/10/17. 11pp. 07356:071.
- 8012170367 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. CRIER, B.H. Region i, Philadelphia, Office of the Director. 80/10/30. ip. 07269:040.
- 8012120080 Forwards IE Bullatin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required, GRIER, B.H. Region i, Philadelphia, Office of the Director. 80/11/06. 1p. 07230:262.
- 8012190365 Informs util of issuance of new NRC personnel identification badges: effective after 801130. Example encl. MARTIN: N. J. Region 1, Philadelphia, Safeguards Branch. 80/11/06. 2pp. 07286:131.
- 8012030772 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. GRIER, B.H. Region i. Philadelphia, Office of the Director. 80/11/07. 1p. 07150; 292.
- 8012080547 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removel Sys at Davis Besse Unit 1." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. 1p. 07183:047.
- 8012040066 Forwards IE Bulletin 80-23, "Failures of Splenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, B.H. Region i, Philadelphia, Office of the Director. 80/11/14. 1p. 07137;283.
- 8012220618 Advises that written response is required to IE Bulletin BO-23. "Failures of Bolenoid Valves tifg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.

 ORIER.B.H. Region I. Philadelphia, Office of the Director. 80/11/19, 1p. 07308:359.

- 8012040532 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required. Requests info on manpower expended. ORIER, B.H. Region f, Philadelphia, Office of the Director. 80/11/21. 2pp. 07169:144.
- 8012050546 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. B0/11/24. 1p. 07174:032.
- 8012180351 Forwards IE Investigation Rept 50-247/80-19 & IE Mgt Meeting Rept 50-247/80-19A on 801022-1121. GRIER, B.H. Region i, Philadelphia, Office of the Director. 80/12/04. 2pp. 03794:077.
- --Boi2180353 IE Investigation Rept 50-247/80-19 on Boi022-1121.

 Noncompliance noted failure of nuclear safety committee to review potential safety hazards prior to reactor startup.

 MARTIN.T. T. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. REBELONSKI.T.A., HIOCINS.J.C. Region 1, Philadelphia, Office of the Director. 80/11/28, 112pp. 03794:079.
- --8012180357 IE Mgt Meeting Rept 50-247/80-19A on 801203. Major areas discussed:addl info not previously made available to NRC investigation team re maint work requests, failure analysis rept & proposed Tech Specs.
 ALLAN
- 8012300087 Discusses IE insp on 801022-1121 & forwards notices of violation & proposed imposition of civil penalty & notice of deviation.

 STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/12/11. 3pp. 07356:193.
- ---B012306091 Notice of violation & proposed imposition of civil penalty in amount of \$210,000 for item of noncompliance noted in IE insp on B01022-1121. # Office of Inspection & Enforcement, Office of the Director. B0/12/11. 9pp. 07356:196.
- ---8012300097 Notice of deviation from insp on 801022-1121. Noncompliance noted: containment sump pump float rods not attached or guided on 801017-20, causing pump inoperability.

 # Office of Inspection & Enforcement, Office of the Director. 80/12/11. 1p. 07356:205.
- 8012310096 Forwards notice of violation & proposed imposition of civil penalty & notice of deviation based on NRC 801022-1121 investigation of 801017 event re leakage in fan cooler unit resulting in svc water flooding of reactor vessel pit.
 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/12/11. 3pp. 07371:164.
- --8012310102 Notice of violation & proposed imposition of civil penalty based on NRC 801022-1121 investigation of 801017 event releasage in fan cooler unit resulting in water flooding of reactor vessel pit.

 STELLO, V. Office of Inspection & Enforcement, Office of the Director, 80/12/11, 9pp. 07371:147.
- --8012310106 Notice of deviation from insp on 801022-1121.

 # Office of Inspection & Enforcement, Diffice of the Director.
 80/12/11. ip. 07371:176.
- 8012300104 Discusses IE insp on 800924-27 & forwards notice of violation & notice of proposed imposition of civil penelty. 8TELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/12/19, 2pp. 07336:231.
- --8012300109 Notice of violation from insp on 800924-25. Noncompliance noted: procedure changed w/o NRC approval, rendering automatic startup feature of containment spray sys inoperable & reducing margin of safety.

 → Office of Inspection & Enforcement, Office of the Director. 80/12/19, 2pp, 07356:233.
- --8012300113 Notice of proposed imposition of civil penalty in amount of \$5,000 for item of noncompliance noted in IE insp on 800924-25.

 ** Diffice of Inspection & Enforcement, Office of the Director, 80/12/19, ip. 07354:235.
- R. Periodic operating reports & related correspondence
- B012160476 Forwards data specified in Bection 401 Certification for Nov 1980.
 MONI1.W.A. Consolidated Edison Co. of New York, 80/12/10, 16pp. 07263:114.

- 8012220397 Forwards tabulation of daily record of fish collections for Nav 1780. Daily species code list count & total usight encl. O'TOOLE.J.D. Consolidated Edison Co. of New York. 80/12/15. Spp. 07304:105.
- 8012230303 Forwards monthly operating rept for Nov 1980. O'TOOLE, J.D. Consolidated Edison Co. of New York. 80/12/15. 1p. 07318:067.
- --8012230305 Monthly operating rept for Nuv 1980. EIGH, E. Consolidated Edison Co. of New York. 80/12/11. 9pp. 07318:068
- 5. Reportable occurrences. LERs & related correspondence
- 8012100239 PNS-I-80-24: on 801118.13th Precinct.NY City Police Dept received ghone call from anonymous person threatening to book Con Ed sys.Licensee notified all stations.Bomb search procedures initiated w/o results.

 JONES,E., DEVLIN.J. Region t. Philadelphia, Office of the Director. 80/11/19. 2pp. 07218:274.
- B012020564 Nonroutine 30-6ay rept:on B01024, while in cold shutdown condition, oil collected in 5 ft elevation conventional plant sump & w/water from sump, was automatically pumped into circulating water discharge canal.

 0/100LE,J.D. Consolidated Edison Co. of New York. B0/11/20. 2pp. 07148:049.
- B012040597 Nonroutine 30-day rept:on B01024 during cold shutdown condition of collected in conventional sump & approx 4 gallons were pumped into river. Caused by maint activities on 15-ft elevation. Sump pump shut & of 1 removed.

 O'TOOLE. J. D. Commonwealth Edison Co. 60/11/20. 2pp. 07157:269.
- B012080444 Forwards revised LER 80-010/04X-1. B*TOOLE, J.B. Consolidated Edison Co. of New York. 80/11/28. 1p. 07186:316.
- --8012030450 Revised LER 80-010/04X-1:on 800910, Teledyne Isotopes informed util that activity of leafy green vegetation sample exceeded 10 times historical level for site. Caused by disposal of low level matl in sink used for std preparation. MARP.F.B. Consolidated Edison Co. of New York. 80/11/28. 4pp. 07186:317.
- T. Hearing transcripts on non-antitrust matters
- 8012150026 Forwards statement re 801017 maifunction at facility. Statement was intended for presentation at MRC 801105 public hearing. YODOROVICH.M.M. Scientists & Engineers for Secure Energy. 80/11/07. ip. 07240:352.
- --8012150028 Statement re 801017 malfunction at facility.

 + Scientists & Engineers for Secure Energy, 80/11/05, ip.
 07240:353.
- --B012150030 Commends V Stello for accommodating speakers at 801105 public hearing. HTLNER, M. C. Affiliation Unknown. 80/11/07. ip. 07240:354.
- B012120365 Transcript of B01126 public meeting in Hashington,DC rainstructions to ASLB on facility proceeding.Pp 1-39.

 Commissioners. B0/11/26. 39pp. 07236:324.
- --8012120373 Forwards draft order reflecting divergent positions on certain questions re principal focus of adjudication.
 BICKNIT.L. Commissioners. SECY-A-80-179G. 80/11/26. 14pp.
 07237:003.
- 1212020B Transcript of ACRS 248th general meeting on 801205 in Washington.DC re-waste mgt activities & operating experience at Indian Foint Unit 2.

 ACRS Advisory Committee on Reactor Safeguards. 80/12/05. 304pp. 07187:001.
- 8012290493 Transcript of 801215 public meeting in Washington.DC re ASLB instructions.Pp 1-54.

 * Cormissioners. 80/12/15. 56pp.
- --8012290501 Responds to commissioner 801126 request re assessment of one-hearing vs two-hearing approach implications on safety insues' adjudication.
 BICKUIT.L. Office of the Ceneral Counsel. SECY-A-80-179E.
 B0/12/52. Jpp.

- --8012270507 Discusses & forwards redrafted B01126 order & clarifies commissioner resolutions. Excerpted ltr to EL Jordan encl. BICKWIT.L. Office of the General Counsel. SECY-A-80-179D. B0/12/11. 21pp.
- U. Congressional/Executive Correspondence
- B01205008B Forwards questions to 801017 shutdown following discovery of major leak in secondary cooling sys. Bubsequent events indicate incident may be more serious than believed & independent inquiry finitiated. Responses requested by 801231. FINK, B., KOPPELL, D. New York, State of. 80/11/25, 3pp. 07173:324.
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F. Sacurity, medical, emergency & fire protection plans
- 8012040010 Forwards interim 10CFR50.48 suspending completion dates for fire protection mods.effective upon 801029 publication in 45FR71569.Rule will be superseded by revised rule when effective.
 EISERPUT, D. O. Division of Licensing. 80/11/07. 5pp. 07152:083.
- BD12020167 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speaters. Who enci health physics network manual. KEPPLER. J. O. Region 3. Chicago. Office of the Director. BO/11/19. 2pp. 07148: 202.
- 8012150126 Notifies that 800421 Revision B to facility security plan is unacceptable. Specific changes must be properly identified & plan resubmitted.

 1PPOLITO.T.A. Operating Reactors Branch 2. 80/11/19, 2pp. 07241:178.
- B012120576 Resubmits security plan revisions, in response to NRC 800910 t 1119 ltrs. Plan withheld from public disclosure (ref 16CFR2, 790). M/o encl. ABEL, J.S. Commonwealth Edison Co. 80/12/08. 1p. 07227: 292.
- C. Adjudicatory correspondence
- BD120206B1 Request for reconsideration of ASLB B01120 order granting continuance or alternatively for certification to Commission.Certificate of Svc encl. MURRAY.M.J. Illinois. State of. B0/11/26. 4pp. 07147:271.
- B012170669 Forwards Director's decision under 10CFR2.206 & FR notice denging B01024 petition to shut down facilities, pending installation of required scram discharge vol monitoring equipment.

 DENTON. H. R. Office of Nuclear Reactor Regulation, Director.

 B0/11/26. 1p. 07269:216.
- --8012170678 Director's decision under 10CFR2.206.denying Pollution & Environ Problems. Inc. 801024 petition to shut down facilities pending installation of required scram discharge vol manitoring equipment.

 DENTORINH.R. Diffice of Nuclear Reactor Regulation, Director.

 80/11/26. 7pp. 07269:218.
- --B012170493 Notice of issuance of Director's decision under 10GFR2,206, denying Pollution & Environ Problems B01024 petition. GASE.E. G. Office of Nuclear Reactor Regulation, Director. B0/11/26. 2pp. 07269:225.
- 8012300324 Forwards applicant motion to strike intervenor, State of IL.cross-examination of ML Wohl.applicant brief in support of motion to strike & applicant corrections to 80i119-21 hearing transcript.
 FITZO18BONS.R. Isbam, Lincoln & Beale. 80/12/01. 1p. 07357:118.
- --8012300333 Motion to strike cross-examination of ML Wohl by intervenor. State of IL.Cross-examination has no relevance to intervenor Contention 6 re accident consequences considered in FSAR, SER & FES.
 STEPIDE:P.P. Commonwealth Edison Co. STEPTOE:P.P. Isham, Lincoln & Beale. 80/12/01. 1p. 07357:[19]
- --B012300341 Brief in support of applicant motion to strike cross-examination of MH Wohl by intervenor. Btate of IL re Contention 6. Supporting documentation & Certificate of Bvc encl.
 STEPTOE.P.P. Commonwealth Edison Co. STEPTOE.P.P. Isham, Lincoln & Beale. B0/12/Ol. 14pp. 07957:120.

- --8012300345 Corrections to transcript of 801119-21 spent fuel pool mod hearings in Morris. IL.

 * Commonwealth Edison Co. 80/12/01. 18pp. 07357:134.
- 8012110540 Forwards Olympic Associates checklist documents re Leckenby audit per BO1118 request. Internal Nuclear Svcs Corp audit, requested 801203, re Lasalle work is being located. Related correspondence. W/o encl. FITZOIBBONS, R. isham, Lincoin & Beale. 80/12/05. ip. 07222; 359.
- 8012290657 Response in opposition to State of IL 801126 motion for reconsideration of ABLB decision to grant continuance or in alternative, for certification. Certification should not be granted for scheduling matters. Certificate of Svc encl. STEPTOE, P. P. Commonwealth Edison Co. STEPTOE, P. P. Isham, Lincoln & Beale. 80/12/10. App. 07333:082.
- B012300090 Response in opposition to applicant motion to strike crossexamination of ML Wohl. Wohl testimony shows that NRC did not consider multiple failure analyses in SER. FAHMER.T.C., MURRAY.M.J. Illinois, State of
- --8012300093 Braft, "Sys Interaction & Single Failure Criterion," App A. Certificate of Syc encl.

 * MHB Technical Associates. 80/11/30. 21pp. 07359:015.
- B012160332 Notifies that B01203 request for "internal Audit of La Balle Pipe Stress Analysis & Support Design (SAR-0303) -- Internal Audit Rept 80-3." cannot be honored Document is not relevant to spent fuel rack proceeding for facilities.

 STEPTOE.P. Isham, Lincoln & Beale. 80/12/11. ip. 07262:009.
- 8012170410 Requests refusal of util application to transfer spent nuclear fuel rods from Dresden units to Guad City units for storage.NRC should hold public hearings. * Citizens for Safe Energy. 80/12/11. 2pp. 07269:351.
- 8012230284 Order granting NRC motion for extension until 801219 to respond to applicant motion to strike State of IL crossexaminetion of HL Wohl. WOLF.J. Atomic Safety and Licensing Board Panel. 80/12/11. 1p. 07317:342.
- 8012300081 Forwards cover page for response in opposition to applicant motion to strike cross-examination of fil. Wohl.
 MURRAY, M. J. Illinois, State of, 80/12/11. ip. 07358:342.
- --8012300084 Cover page to response in opposition to applicant motion to strike cross-examination of ML Wohi. FAHRER:T.C.; MURRAY:M.J. Illinois: State of. 80/12/11. ip. 07359:343.
- 8012300122 Forwards closeout documents re Nuclear Svc Corp audit of Brob's & Perkins on 791212 & 13. Applicant will request permission from ABLB, during B01218 conference call, to file proposed findings of fact on 801222.

 BIEPTOE, P. P. Isham, Lincoln & Beale. 80/12/11. 10pp. 07358:308.
- --B012300129 Corrections to transcript of B01117-21 hearings.

 * Atomic Safety and Licensing Board Panel. B0/12/11. App. 07398-318.
- 8012230019 Response in apposition to intervenor 801126 motion for reconsideration or certification to Commission re spent fuel pool mod. Certificate of Svc encl.
 OGDDARD.R. Hearing Branch 2. 80/12/15. 5pp. 07311:185.
- 8012290149 Order requesting applicant to file proposed findings of fact on or before 801222 intervenors. State of IL, on or before 810130 & NRC on or before 810213. WDLF.). F. Atomic Safety and Licensing Board Panel. 80/12/19. 2pp. 07344:053.
- 8012290213 Response in support of applicant 801201 request to strike State of IL crosssxamination of ML Wohl Role of ASLB in license amend proceeding is limited by scope of contentions. Certificate of Svc encl.

 GDDDARD, R. J. Hearing Branch 2, 80/12/19, 7pp. 07344:253.
- 801231028B Forwards applicant proposed findings of facts per 801218 telcon Incomplete sections & omissions noted.
 BTEPIDE, P. P. Isham, Lincoln & Beals. 80/12/22. 1p. 07370:065.

- B012310419 Order denying B01126 motion for reconsideration of util motion for continuance of hearing or alternatively for certification. No merit in contention that requiring further evidence adversely affected intervenor case.

 MOLF, J. F. Regulations Division. B0/12/22, 3pp. 07370:190.
- P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, DL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to aii CP & OL holders for BliRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core rel
- 8012290363 Ltr to all power reactor licensess forwarding NUREO-0619, "BUR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. H/o encl. EISENHUT, D. Q. Division of Licensing. 80/11/13. 1p.
- 8012180620 Forwards Amends 32.51 & 45 to Licenses DPR-2.DPR-19 & DPR-25.respectively. Amends 60 & 55 to Licenses DPR-29 & DPR-30.respectively. Examines 58 & 55 to Licenses DPR-39 & DPR-49 & DPR-48.respectively. Safeguards contingancy plans acceptable. CRUTCHFIELD. D. Operating Reactors Branch 5. 80/11/17. 5pp. 07271:324.
- --B012180433 Amends 32,51 & 45 to Licenses DPR-2,DPR-19 & DPR-25, respectively, requiring implementation of safeguards contingency plan.
 GRUTCHFIELD. D. Operating Reactors Branch 5. IPPOLITO, T. A. Operating Reactors Branch 2. 80/11/17. 6pp. 07271:329.
- --B0121B0671 Notice of issuance of Amends 32.51 & 45 to Licenses DPR-2, DPR-19 & DPR-25, respectively, Amends 60 & 55 to Licenses DPR-27 & DPR-30; respectively & Amends 58 & 55 to Licenses DPR-37 & DPR-48; respectively as a safeguards contingency plan. CRUTCHFIELD, D. Operating Reactors Branch 5. 80/11/17, 2pp. 07271:343
- 8012020091 Confirms 801016 & 17 telcons re util commitments to perform well water sampling & analysis at locations around site. Analyses will be performed for gross alpha, gross beta & trittum.

 DAVIS,A,B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/11/19. 3pp. 07148:352.
- 8012020301 Forwards tabulation of planned environ qualification testing grograms, in response to NRC 801001 ltr.
 ABEL.J.S Commonwealth Edison Co. 80/11/26. 4pp. 07148:193.
- 8012110274 Forwards Revision 4 to "Licensing Rept.Dresden Nuclear Power Plant Units 2 & 3 Spent Fuel Rack Mod." originally submitted w/780511 proposed OL amend. JANECEK.R.F. Commonwealth Edison Ca. 80/12/02. 2pp. 07225:173.
- ---8012110283 Revision 4 to "Licensing Rept.Dresden Nuclear Power Plant Units 2 & 3 Spent Fuel Rack Mod." * Quadrex Corp. QUAD-1-79-234 R4. 80/10/31. 4pp. 07225:175.
- 8012190657 Forwards request for add1 info re 800822 rept entitled, "Evaluation of 18 Inch Containment Isolation Valves for Dresden 2 & 3 & Guad Cities 1 & 2." LAINAS, Q. C. Assistant Director for Safety Assessment. BQ/12/02. 3pp. 07273:290.
- 8012180002 Immediate action itr confirming actions discussed in 801204 teicon re problems w/scram discharge vol level monitoring sys. Daily checks of scram discharge vol to be performed until operability of monitoring sys demonstrated. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/12/04. 2pp. 03791:159.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level wasts at 51 reactors.Low level wasts storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANOART,R.L. Effluent Treatment Systems Branch, 80/11/06. Spp.

- 8012150052 Application to amend Licenses DPR-19 & DPR-25, changing Tech Specs, Section 3.8 To limiting conditions for operation of chimney gas sampling sys. Class 1 & III fees encl.

 JANECEK, R.F. Commonwealth Edison Co. 80/12/05. 2pp. 07240:331.
- --B012150054 Proposed Yech Specs, Section 3. B, changing limiting conditions for operation re chimnsy gas sampling sys. * Commonwealth Edison Co. 80/12/05. 2pp. 07240:333.
- Bol2120301 Forwards Tech Specs Page 3.2/4.2-15, inadvertently omitted from util 860918 ltr to NRC.

 JANECEK, R. F. Commonwealth Edison Co. 80/12/10. 2pp. 07236:249.
- --BD12120341 Proposed Tech Specs, Page 3.2/4.2-15, incorporating TMI Lessons Learned Requirements.
 Commonwealth Edison Co. 80/12/10. ip. 07236:250.
- B012140136 Responds to NRC 800924 request re mods for provision of redundant Class IE protection at interface of Monclass IE power supply & reactor protection sys. Installation scheduled for refueling outages occurring after June 1981.

 JANECEK, R. F. Commonwealth Edison Co. 80/12/11. 2pp. 07262:244.
- BO1217048B Forwards response to NRC 801031 ltr requesting confirmation that implementation dates indicated in NUREQ-0737 will be met. Ability to meet required dates for major mode is contingent upon hardware availability & delivery.

 ABEL. J. S. Commonwealth Edison Co. 80/12/15. 37pp. 07270:294.
- BO12240138 Forwards confirmation that implementation dates per NUREG-0737 will be met & justification for exceptions. Generally dates are contingent upon hardware availability & delivery. Comments on safety requirements in Tech Specs. ABEL, J. 8 Commonwealth Edison Co. 80/12/15, 37pp. 07323:001.
- G. Inspection reports: IE Builetins & correspondence
- B012170510 Forwards lE info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 KEPPLER.J.O. Region 3. Chicago, Office of the Director. 80/10/24.
 ip. 07268:079.
- B012170546 Forwards IE Investigation Repts 50-237/80-16 & 50-249/80-20 on 800908-10.

 KEPPLER. J. O. Region 3. Chicago, Office of the Director. 80/10/24.

 2pp. 07269:159.
- --8012170554 IE investigation Repts 30-237/80-16 & 50-249/80-20 on 800908-10. Noncompliance noted two reactor operators apparently asleep on duty.
 PHILLIP, G. A., NGRELIUS, C. E., SPESSARD, R. L., Region 3, Chicago, Office of the Director, 80/10/23, 41pp. 07269:161.
- 8012100589 Forwards IE Insp Repts 50-010/80-19.50-237/80-21 & 50-249/80-25 on 800907-1003 & notice of violation. HEISHMAN,R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/11/04. 2pp. 07218:164.
- --8012100591 Notice of violation from insp on 800907-1003.

 Region 3, Chicago, Office of the Birector. 80/10/31. lp. 07218:166.
- -8012100397 IE insp Repts 50-010/80-19,50-237/80-21 & 50-249/80-25 on 800407-1003. Noncompliance noted:failure to adhere to GA program requirements.
 TONGUE. T. M. . JORDAN. M. J. . SPESSARD. R. L. Region 3. Chicago, Office of the Director. 80/10/31. 7pp. 07218:167.
- 3012020308 Ack receipt of 801030 ltr informing NRC of steps taten to correct violations noted in IE lnsp Repts 50-010/80-14, 50-247/80-21.
 HEISHKAN R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/10. ip. 07143:105.
- --B012020312 Responds to NRC 801008 ltr re violations noted in IE Insp Repts 50-010/80-14.50-237/80-17 & 50-249/80-21. Corrective actions:potential radiological consequences to workers actions:potential radiological consequences to performing maint on control red driveline pump evaluated. ASEL.J.S. Commonwealth Edison Co. 80/10/30. 3pp. 07143:106.
- 8012290458 Confirms 801110 telecopy requesting extension for response to 801020 notice of violation & proposed imposition of civil penalty until 801124.

 ABEL, J. S. Commanwealth Edison Co. 80/11/12. 2pp. 07335:040.

- B012020743 Forwards three Performance Appraisal Branch insp repts & most evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. U/o encl. KEPPLER.J.O. Region 3. Chicago, Diffice of the Director. B0/11/18. 4pp. 07147:336.
- BD12040557 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER.J. G. Region 3, Chicago, Office of the Director. 80/11/21.

 2pp. 07166: 358.
- 8012080087 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Brubber Fluid." No written response required. KEPPLER.J. 9. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182: 253.
- 801217040B Forwards monthly status rept of evaluations performed in response to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Bys." No sys identified w/stress exceeding 1/2 mati ultimate stress at OBE loadings.

 JANECEK, R.F. Commonwealth Edison Co. 80/11/24. 14pp. -07187:001.
- B012290466 Protests civil penalty imposed in B01020 ltr & notice of violation. NRC failed to use appropriate enforcement criteria in classifying severity level of noncompliance. REED.C. Commonwealth Edison Co. B0/11/24. 6pp. 07335:044.
- B012290470 Refutes item of noncompliance of two on-duty operators allegedly found asleep on B0080B. Operators were present at prescribed stations & able to perform all required functions.
 REED.C. Commonwealth Edison Co. 80/11/24. Bpp. 07935:052.
- 8012230223 Forwards new security badge numbers & clearance levels for Region 3 personnei. Changes should be entered on Sept 1980 access lists.

 KEPPLER.J. G. Region 3, Chicago, Office of the Director. 80/11/25, App. 07317:081.
- 8012100661 Ack receipt of 800919 response to NRC 800818 ltr requesting addl info re IE Bulletin 79-14 evaluations. Dreaden & Quad Cities responses to Items 1 & 3 unacceptable, since requested info was not included.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director., 80/11/26, 300
- 8012170592 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
 KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/26.
 2pp. 07264:286.
- 8012110602 Ack receipt of 801112 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 30-010/80-16, 50-237/80-19 & 50-249/80-23. HIND.J.A. Region 3, Chicago, Bafeguards Branch. 80/12/0i. ip. 07228:175.
- --Boi2110403 Responds to NRC 801022 ltr re violations noted in IE Insp Repts 50-010/80-11.50-237/80-19 & 50-249/80-23. Corrective action withheld (ref 10CFR2. 790). ABEL.J.S. Commonwealth Edison Co. Bo/11/12. lp. 07226:176.
- 8012090044 Notification of B01209 meeting w/util in Bethesda,MD to discuss acceptance criteria used for evaluation of piping sys under review for IE Bulletin 79-14.
 NONO,H.J. Office of Inspection & Enforcement, Office of the Director. 80/12/04. 2pp. 07198:078.
- 8012230065 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.inc." No valve parts cast by Malcolm Foundry planned for use or in use at facilities. RAUSCH.T.J. Commonwealth Edison Co. 80/12/05. 2pp. 07311:081.
- 8012190210 Forwards third bimonthly status rept on IE Builetin 79-018 re environ qualification of Class IE equipment. HAYES,D.W. Region 3: Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp. 07282:108.
- 8012310629 Ack receipt of 801125 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-010/80-19, 50-237/80-21 & 50-249/80-25.
 HEISHIANN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09. 1p. 07371:052.
- --8012310630 Responds to NRC 801104 itr re violations noted in IE Insp Repts 50-010/80-19,50-237/80-21 & 50-249/80-25. Corrective actions: cleaned areas & removed combustible mati. ABEL, J. S. Commonwealth Edison Co. 80/11/25, 4pp. 07371:053.

- 8012240427 Add1 response to FOIA request for documents re imposition of civil penalties.NRC requests for congressional authorization for more severe penalties & responsibilities & behavior of nuclear plant operators. Forwards investigation rept. FELTON.J.M. Division of Rules and Records. 80/12/12. 1p.
- --8012240432 "Investigation of Alleged Bleeping Control Room Operators at Dresden Nuclear Power Station, Morris, IL, 800808." CUMMINOS, J. J. Office of Inspector & Auditor. 80/09/17. 34pp.
- 8012300118 Discusses IE insp on 800723 & forwards notice of violation & notice of proposed imposition of civil penalty.

 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/12/19. 2pp. 0/356:233.
- --8012300124 Notice of violation from insp on 800723. Noncompliance noted: waste math delivered in improper packaging w/no provision for securing lid.

 « Office of Inspection & Enforcement, Office of the Director, 80/12/19. 1p. 03810:174.
- ---B012300130 Notice of proposed imposition of civil penalty in amount of 44,000 for item of noncompliance noted in IE insp on B00723. * Office of Inspection & Enforcement, Office of the Director. B0/12/19. 1p. 07356: 256.
- R. Periodic operating reports & related correspondence
- BO12160419 Forwards monthly operating repts for Nov 1980. BCOTT, D. J. Commonwealth Edison Co. 80/12/08. 1p. 07254: 124.
- --B012160420 Monthly operating repts for Nov 1980. CIEBIXIEWICZ, B. Commonwealth Edison Co. B0/12/01. 15pp. 07294:125.
- S. Reportable occurrences, LERs & related correspondence
- B012040270 Ack receipt of B01030 itr re investigation of alleged release of radioactively contaminated water. Requests add1 info on conclusions that flowpaths w/excess background levels have not & are not transporting contaminated water. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/14. 2pp. 07162:333.
- --B012040333 Responds to Sept 1980 allegations re release of contaminated water into environ. Investigation noted no detectable threat to public & insp revealed no discrepancies which could result in leakage. Forwards detailed summary of results. REED, C. Commonwealth Edison Co. 80/10/30. 6pp. 07162:337.
- 8012020583 Forwards LER 80-041/03L-0. 800TT.D.J. Commonwealth Edison Co. 80/11/20. 1p. 07145:263.
- --8012020591 LER 80-041/03L-0: on 801027; isolation valve 3-1301-20 in isolation condenser vent to main steam line found closed & inoperable. Caused by open conductor in neutral side of power source to valve operator. Bide jumpered to redundant sys.

 BERGAN, O. Commonwealth Edison Co. 80/11/17. 2pp. 07145:264.
- T. Hearing transcripts on non-antitrust matters
- 8012010518 Transcript of 801119 hearing in Morris. IL re spent fuel pool mod. Pp 73-270.

 * Atomic Sefety and Licensing Board Panel. 80/11/19. 200pp. 07093:314.
- B012020614 Transcript of B01120 hearing in Morris, IL re spent fuel pool mod.Pp 271-503, * Atomic Bafety and Licensing Board Panel. 80/11/20. 350pp. 07131:197.
- 8012080038 Transcript of 801120 hearing evening session in Morris, IL respent fuel pool mod.Pp 504-573 * Atomic Bafety and Licensing Board Panel, 80/11/20. 69pp. 07180:222.
- B012010523 Transcript of B01121 hearing in Morris, IL re spent fuel pool mod. Pp 571-721,

 # Atomic Safety and Licensing Board Panel. B0/11/21. 155pp. 07093:155.
- 8012300324 Forwards applicant motion to strike intervenor, State of IL. cross-examination of ML Hohl, applicant brief in support of motion to strike & applicant corrections to 80119-21 hearing transcript.
 FITZOIBBONS, R. Isham, Lincoln & Beale. 80/12/01. 1p.

- --8012300345 Corrections to transcript of 801119-21 spent fuel pool mod hearings in Morris, IL.

 * Commonwealth Edison Co. 80/12/01. 18pp.
- 8012290404 Forwards NRC proposed corrections to transcripts of B01119-21 hearings.
 GDDDARD.R.J. Hearing Branch 2. 80/12/10. 1p. 07336:302.
- --B012290412 Proposed transcript changes Certificate of Svc encl.

 Atomic Safety and Licensing Board Panel. B0/12/10. 12pp.
 07336:303.
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F. Security, medical, emergency & fire protection plans
- 8012030190 Informs of interim 10CFR30.48 suspending completion dates for previously approved fire protection mods.Revised 10CFR30.48 will contain schedules for completion of all fire protection mods. EISENHUT.D.G. Division of Licensing. 80/11/17. 5pp. 07175:025.
- 8012040085 Forwards info re security plan. Info withheld (ref 10CFR2. 790). UHR10, R. E. Florida Power & Light Co. 80/11/26. 1p. 07170:065.
- 8012080213 Releases public version of util smergency plans. FELTON.U.M. Division of Rules and Records. 80/12/05. 1p. 07189:294.
- --8012080220 Forwards public version of util emergency plans. Revision 5. UHR16: R. E. Florida Power & Light Co. 80/11/07. 2pp. 07189: 297.
- --8012080225 Public version of util emergency plans.Revision 5.

 4 Florida Power & Light Co. 80/10/28, 150pg. 07189: 299.
- G. Adjudicatory correspondence
- 8012290400 Request that intervenor & designated experts be allowed to enter site to measure, survey, test & photograph based on racent & continuing steam generator problems. Certificate of Svc encl.
 CHONIN, N. Oncavage, Mark. CHONIN, N. Chonin, N. 80/11/09. 5pp. 07336:275.
- 8012230047 Notice of Comptroller General 801203 opinion disallowing procedural assistance in adjudicatory licensing proceedings. Comptroller General 801203 ltr to J Ahearne & Congressman M McCormac; encl.

 BOWERS.E.S. Atomic Safety and Licensing Board Panel. 80/12/16. 1p.
- 8012300516 Response in opposition to Oncavage 801209 mption to permit intervenor & experts to enter site for insp.measuring & tasting property or objects & for production of documents. Entry is irrolevant. Certificate of Svc encl. COLL.N.A. Florida Power & Light Co. COLL.N.A. Steel, Hector & Davis. 80/12/24. 17pp. 07340:343.
- P. Operating license stage documents & correspondence
- 8012020733 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake.

 EISENHUT.D.O. Division of Licensing. 80/10/21. 4pg.
- 8011210443 Forwards request for add1 info generated from review of "Asymmetric LOCA Loading." WCAP-7628 & 9748.dtd Nov 1979 & June 1980, respectively.

 LAINAB.O.C. Assistant Director for Safety Assessment. 80/10/29.
- 8012160090 Ltr to operating plant licensees, GL applicants & CP holders. Forwards NUREC-0737 re TMI action plan requirements, Requests operating reactor licensee confirmation in 45 days that Encl i implementation dates will be met. EISENHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- 80:2220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BWR Feedwater Noirle & Control Rod Drive Return Line Noirle Cracking." Confirmation that implementation dates will be met must be sent within 45 days W70 entl. EISENHUT, D. O. Division of Licensing. 80/11/13. 1p.

- 8012010131 Forwards addl info re steam generator decontamination alternatives & weld strength for sealing of steam generator lower assemblies after removal, per 80ii10 telcon. Info re doses resulting from postulated drop of lower assembly encl. UHRIG.R.E. Florida Power & Light Co. 80/11/21. Spp. 07091:251.
- 8012010091 Forwards info re mans & endangered species occurring at facility or vicinity, in response to 800822 ltr.
 UHR10.R.E. Florida Power & Light Ca. 80/11/24. lipp. 07091:243.
- 8012020079 Forwards info re air lock leakage testing per 790312 requests.
 UHRID-R.E. Florida Power & Light Co. 80/11/26. 8pp. 07142:102.
- 8012070121 Forwards final rept on low fracture taughness in response to NRC 800729 ltr.
 UPRIO.R.E. Florida Power & Light Co. 80/11/26. 1p. 06914:001.
- --8012020127 "Rept on Fracture Toughness of Steam Generator & Reactor Coolant Pump Supports." * Bechtel Power Corp. (subs. of Bechtel Corp.). 80/11/30. 28pp. 06916:001.
- 8012190069 Forwards Amends 61 & 52 to Licenses DPR-31 & DPR-41, respectively & notice of issuance & availability. VAROA, S. A. Operating Reactors Branch 1. 80/11/28, 3pp. 07279:076.
- --B012190075 Amends 61 & 52 to Licenses DPR-31 & DPR-41 respectively, requiring safeguards contingency plan to be fully implemented within 30 days of Commission approval. VAROA.B.A. Operating Reactors Branch 1. 80/11/28. 10pp. 07279:079.
- --B012190079 Notice of issuance & availability of Amends 61 & 52 to Liceuses DPR-31 & DPR-41, respectively. VARGA.S. A. Operating Reactors Branch 1. B0/11/2B. 2pp. 07279:089.
- BO122704B5 Responds to BO0911 memo requesting that OPc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENION.H.R. Office of Nuclear Reactor Regulation. Director.
 BO/12704. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at SI reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed W/71% planning or considering increasing storage capacity.
 BANOART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012270364 Forwards evaluation of 801007 submission of info re reactor coolent pump oil collection sys. Sys deemed acceptable.
 VAROA.S.A. Operating Reactors Branch 1. 80/12/09. 4pp. 07349:254.
- 8012290375 Informs that commitments to "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability" found acceptable & most remain in effect pending completion of long-term review VAROA.8.A. Operating Reactors Branch 1. 80/12/09. 3pp. 07345:181.
- BO12160145 Advises that containment purge valve torque & stress analysis has been completed by Henry Pratt Co. Mods to limit valve disc openings for Unit 3 completed Mods to Unit 4 will be completed during current refueling autage.

 UHRIO,R.E. Florida Power & Light Co. 80/12/09. 1p. 07262:066.
- 012290321 Forwards Revision 3 to QA manual. URRIGRE. Florida Power & Light Co. 80/12/17. 1p. 07346:007.
- --B012290324 Revision 3 to GA Manual.

 4 Florida Power & Light Co. 80/09/30. 89pp. 07346:008.
- 8012240430 Forwards add1 info re distribution sys voltages, in response to MRC 800817 itr. Since safety injection signal initiates automatic fast transfer from auxiliary transfermer to startup transfermer, only connection via startup analyzed. UHRIO,R.E. Fiorida Power & Light Co. 80/12/18. 27pp. 07328; iOS.
- 8012290651 Forwards NUREG-0743.DES re steam generator repair at facilities & updated safety evaluation GDLDBERG.S.C. Hearing Branch 2. 80/12/22. ip. 07332:339.
- --B012290655 DES re steam generator repair at facilities.

 # Dffice of Nuclear Reactor Regulation, Director. NUREG-0743.
 B0/12/31. 48pp. 07332:340.

- --8012290657 Updated safety evaluation supporting proposed steam generator repairs at facilities.

 + Office of Nuclear Reactor Regulation, Director. 80/12/17. 36pp. 07333:037.
- B012300320 Application to amend Licenses DPR-31 & DPR 41 authorizing proposed changes to Tech Specs per TH1 lessons learned. UHRIG.R.E. Florida Power & Light Co. 80/12/23. 4pp. 07350:023.
- --8012300334 Tech Spec Pages 3.3.3.5.3.5-2.3.5-4.4.1-1.4.10.6.3 & 6.4 re containment integrity, accident monitoring instrumentation, engineered safety features actuation & setpoints, suxiliary feedwater sys & facility staff qualifications & training.
 4 Florida Power & Light Co. 80/12/23. 12pp. 07350:027.
- G. Inspection reports, IE Bulletins & correspondence
- B012180023 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. B0/10/30. ip. 03790:105
- 8012170422 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/31. 1p. 07264:128.
- 8012230063 Forwards IE Circular 80-23, "Potential Defects in Deloit Power Sys Emergency Generators." No written response required. O'REIUly, J.P. Region 2. Atlanta, Office of the Director. 80/10/31. 1p. 07313:232.
- 8012110626 Forwards IE Insp Rept 50-250/80-32 on 801008-10. No noncompliance noted. MURPHY.C.E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/11/03. 2pp. 07226:190.
- --BD12110627 IE Insp Rept 50-250/80-32 on B01008-10. No noncompliance noted Major areas inspected installed equipment w/respect to IE Bulletin 79-018.
 GIBBORS,T.D. Region 2. Atlanta, Office of the Director CONLON-T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/03. 3pp. 07226:192.
- 8012110736 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.inc." Written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/06. 1p. 07225:211.
- 8012030268 Forwards IE Info Notice 80-40, "Excassive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. D'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/07. ip. 07150:117.
- 8012080194 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/10.

 1p. 07182:261.
- B012040183 Forwards 1E Bulletin B0-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. B0/11/14. lp. 07158:091.
- B012040477 Forwards IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required Requests info on manpower expended. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/21, lp. 07163:339.
- 8012080229 Ack receipt of 801020 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-250/80-19 & 50-251/80-20.

 HURPHY. C.E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 80/11/21. 1p. 07181:213.
- --8012080234 Responds to NRC 809627 ltr re violations noted in IE Insp. Repts 50-250/80-19 & 50-250/80-20. Requests extension of compliance date from 801015 to 801115 for revisions to fire training procedures.

 UHR10.R.E. Florida Power & Light Co. 80/10/20. 2pp. 07181:214.
- 8012080024 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24, .

 1p. 07182:145.

- 8012170512 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26. 1p. 07268:103.
- 8012170067 Notification of 801219 meeting w/util in BethesdarMD to discuss upcoming steam generator insp rept for facility, GROTEHHUIS.M. Operating Reactors Branch 1, 80/12/12, 2pp.

R. Periodic operating reports & related correspondence

- 8012160466 Forwards monthly operating repts for Nov 1980, SCHMIDT.A.D. Florida Power & Light Co. 80/12/06. 1p. 07254:216.
- --8012140468 Monthly operating repts for Nav 1980, CHIL30N, V.T. Florida Power & Light Co. 80/12/06, 17pp. 07254:217,
- 8012180258 Forwards monthly operating repts for Nov 1980, BCHMIDT, A. D. Florida Power & Light Co. 80/12/06. 1p. 10. 03794: 004.
- ---8012180265 Monthly operating repts for Nov 1980. CHILSON, V.T. Florida Power & Light Co. 80/12/06, 16pp. 03794:007.

S. Reportable occurrences, LERs & related correspondence

- 8012020538 Forwards LER 80-020/03L-0. 8CHMIDT, A.D. Florida Power & Light Co. 80/11/14. 1p. 07143:275.
- -8012020544 LER 80-020/03L-0: on 801018, periodic test of RHR pump 3A not completed within prescribed time interval. Gaused by personnel being unaware that 3A 4160-volt bus returned to svc. Scheduling sys modified.
 PACE.P.L. Florida Power & Light Co. 80/11/14. ip. 07143:276.

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

- F. Becurity, medical, emergency & fire protection plans
- 8012030190 Informs of interim iOCFR30.48 suspending completion dates for previously approved fire protection mods.Revised 10CFR30.48 will contain schedules for completion of all fire protection mods, EISENHUT, D.O. Division of Licensing. 80/11/17. 5pp. 07175:025.
- 8012040085 Forwards info re security plan. Info withheld (ref 100FR2.790). UHRIG.R.E. Florida Power & Light Co. 80/11/26, 1p. 07170:065.
- 8012080213 Releases public version of util emergency plans FELTON.J.M. Division of Rules and Records. 80/12/05. 07189:294.
- --B012080220 Forwards public version of util emergency plans, Revision 5. UHRIG, R.E. Florida Power & Light Co. 80/11/07. 2pp. 07189: 297.
- --8012080225 Public version of util emergency plans. Revision 5.
 * Florida Power & Light Co. 80/10/28. 150pp. 07189: 299.

G. Adjudicatory correspondence

- 8012270400 Request that intervenor & designated experts be allowed to enter site to measure survey test & photograph based on recent & continuing steam generator problems. Certificate of Svc ancl.
 CHONIN.N. Oncavage, Mark. CHONIN.N. Chonin.N. 80/11/09. 5pp. 07336: 295.
- 8012230047 Notice of Comptroller General 801203 opinion disallowing procedural assistance in adjudicatory licensing proceedings. Comptroller General 801203 ltr to J Ahearne & Congressman M McCormack encl. BONERS, E. S. At 07311:246. ci. Atomic Bafety and Licensing Board Panel. 80/12/16. ip.
- 8012300516 Response in opposition to Uncavage 801209 motion to permit intervenor & experts to enter site for insp.measuring & testing property or objects & for production of documents. Entry is irrelevant. Certificate of Bvc encl. COLL.N. A. Florida Power & Light Co. COLL.N. A. Steel, Hector & Davis. 80/12/24. 17pp. 07360:343.

P. Operating license stage documents & correspondence

- B012020753 Forwards seismic qualifications of autiliary feedwater sys in operating PMRs & describes program NRC is undertaking to review capability of operating PMRs to remove decay heat following earthquake.

 EISENHUT, D. C. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISERHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be mat must be sent within 45 days Myc encl. EISENHUT.D.Q. Division of Licensing. 80/11/13. 1p.
- 8012010131 Forwards add1 info re steam generator decontamination alternatives & weld strength for scaling of steam generator lower assemblies after removal.per 801110 telcon. Info re does resulting from postulated drop of lower assembly encl. UHRIG.R.E. Florida Power & Light Co. 80/11/21. Spp. 07091:251.
- B012010091 Forwards info re rare & endangered species occurring at facility or vicinity, in response to 800822 ltr.
 URRIG.R.E. Florida Power & Light Co. 80/11/24. 11pp. 07091:263.
- 8012020079 Forwards info re air lock leakage testing per 790312 request. UHRIG.R.E. Florida Power & Light Co. 80/11/26. 8pp. 07142:102.
- 8012020121 Forwards final rept on low fracture toughness in response to NRC 800729 ltr. UHRIG.R.E. Florida Power & Light Co. 80/11/26. lp. Q6916:001.
- --B012020129 "Rept on Fracture Toughness of Steam Generator & Reactor Coolant Pump Supports." * Bechtel Power Corp. (subs. of Bechtel Corp.). 80/11/30, 28pp. 06916:001.
- 8012190369 Forwards Amends 61 & 52 to Licenses DPR-31 & DPR-41, respectively & notice of issuance & availability. VAROA.8.A. Operating Reactors Branch 1. 80/11/28. 3pp. 07279:076.
- --8012190075 Amends 61 & 52 to Licenses DPR-31 & DPR-41, respectively, requiring safeguards contingency plan to be fully implemented within 30 days of Commission approval, VAROA,8 A. Operating Reactors Branch 1. 80/11/28. 10pp. 07279:079.
- -8012190079 Notice of issuance & availability of Amands 61 & 52 to Licenses DPR-31 & DPR-41, respectively, VAROALS A. Operating Reactors Branch 1. BO/11/28, 2pp. 07279:089.
- 8012220483 Responds to 800911 memo requesting that Oft of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANGART.R.L. Effluent Treatment Systems Branch. B0/11/06. Bpp.
- B012290364 Forwards evaluation of 801007 submission of info re reactor coolant pump oil collection sys. Bys deemed acceptable.
 VAROA/S.A. Operating Reactors Branch 1. B0/12/08, 4pp. 07345:254.
- 8012290375 Informs that commitments to "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability" found acceptable & must remain in effect panding completion of long-term review.

 VAROA.S.A. Operating Reactors Branch 1. 80/12/08. 3pp. 07345:181.
- 8012160145 Advises that containment purps valve torque & stress analysis has been completed by Henry Prott Co. Mods to limit valve disc openings for Unit 3 completed Mods to Unit 4 will be completed during current refe
- 8012270321 Forwards Revision 3 to GA manual. UHRIO,R.E. Florida Fower & Light Co. 80/12/17. 1p. 07346:007.

- --8012290326 Revision 3 to 0A manual. -- Florida Power & Light Co. 80/09/30. 89pp. 07346:008.
- B012240430 Forwards addl info re distribution sys voltages, in response to NRC B00B19 ltr. Since safety injection signal initiates automatic fast transfer from auxiliary transformer to startup transformer, only connection via startup analysed. UREIO. R.E. Florida Power & Light Co. B0/12/18. 27pp. 07328:105.
- 8012290651 Forwards NUREG-0743.DE8 re steam generator repair at facilities & updated tafety evaluation GOLDBERO, S.C. Hearing Branch 2. 80/12/22. 1p. 07332:339.
- --8012290555 DES re steam generator repair at facilities.

 4 Office of Nuclear Reactor Regulation, Director. NUREG-0743, 80/12/31, 48pp. 073J2:340.
- --8012290657 Updated safety evaluation supporting proposed steam generator repairs at facilities.

 + Office of Nuclear Reactor Regulation, Director. B0/12/17, 36pp. 07333:037.
- B012300320 Application to amend Licenses DPR-31 & DPR 41 authorizing proposed changes to Tech Specs per TMI lessons learned. UHRIO.R.E. Florida Power & Light Co. 80/12/23. 4pp. 07350:023.
- --B012300334 Tech Spec Pages 3.3.3.5,3.5-2.3.5-4,4.1-1,4.10,6.3 & 6.4 re containment integrity, accident monitoring instrumentation, engineered safety features actuation & setpoints, auxiliary feedwater sys & facility staff qualifications & training.
 4 Florida Power & Light Co. B0/12/23. 12pp. 07350:027.
- Q. Inspection reports. IE Bulletins & correspondence
- B012180023 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. 0'REILLY.J.P. Region 2. Atlanta. Office of the Director. B0/10/30. 1p. 93790:106.
- 8012170422 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. G'REEL/Y,J.P. Region 2, Atlanta, Office of the Director. 80/10/31. 1p. 07264:128.
- 8012230063 Forwards IE Circular 80-23, "Potential Defects in Beloit
 Power Sys Emergency Generators." No unitten response
 required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012110736 Forwards IE Builetin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. BO/11/06. 1p. 07225:211.
- 8012030868 Forwards IE Info Notice 80-40. "Ercessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'ARILLY.J.P. Region 2. Atlanta, Office of the Director. BO/11/07. 1p. 07150:117.
- 8012080194 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Becay Heat Removal Sys at Davis Besse Unit 1." No response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10.
 10. 07182:261.
- 8012040183 Forwards [E Bulletin 80-23, "Failures of Solemoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Birector. 80/11/14.
 10.
- 8012040477 Forwards IE Bullotin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required Requests into on manpower expended. O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/11/21. 1p. 07163:339.
- B012080229 Ack receipt of B01020 ttr informing NRC of steps taken to correct violations noted in IE inso Repts 50-250/80-19 & 30-251/80-20. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch.

- --8012080234 Responds to NRC 800627 ltr re violations noted in 16 Insp Repts 50-250/80-19 & 50-250/80-20. Requests extension of compliance date from 801015 to 801115 for revisions to fire training procedures. UMRIO,R. E. Florida Power & Light Co. 80/10/20. 2pp. 07181: 214.
- B012080024 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required.
 O'REILLY, J.P. Region 2, Atlanta. Office of the Director. 80/11/24.
 1p. 07182:165.
- 8012170512 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.
- BO12190067 Notification of B01219 meeting w/util in Bathesda.MD to discuss upcoming steam generator insp rept for facility. OROTENHUIS.M. Operating Reactors Branch 1. 80/12/12. 2pp. 07279:074.
- BD12220301 Forwards steam generator insp.results from current outage. Results show no new phenomena & verify general denting pattern within predictable limits consistent w/previous insp. Requests permission to return to full power operation. UHR19, R.E. Fiorida Power & Light Co. 80/12/18. 2pp. 07304:064.
- --B012220307 Inservice insp in Nov 1980. Describes gauging of steam generator but & cold legs, measurement of visible flow slots, eddy current insp of small radius U-bends & preventive plugging.

 4 Florida Power & Light Co. B0/12/18. 35pp. 07304:066.
- R. Periodic operating reports & related correspondence
- 8012160466 Forwards monthly operating repts for Nov 1980. SCHMIDT, A. D. Florida Power & Light Co. B0/12/06. ip. 07254:216.
- --B01216046B Monthly operating repts for Nov 1980. CH1LBON, V. T. Fiorida Power & Light Co. 80/12/06. 17pp. 07294;217.
- B012180258 Forwards monthly operating repts for Nov 1980. SCHMIDT.A.D. Florida Power & Light Co. 80/12/06. 1p. 03794:006.
- ---B012180265 Monthly operating repts for Nav 1980. CHILSON, V. T. Fhorida Power & Light Co. B0/12/06. 16pp. 03794:007.
- S. Reportable occurrences, LERs & related correspondence
- 8012020469 Forwards LER 80-012/03L-0. SCHMIUT.A.D. Florida Power & Light Co. 80/11/12. ip. 07143:247.
- --8012020474 LER 80-012/03L-0; on 801013, excassive leakage past primary packing in charging pump 4A caused pump to be removed from svc. Caused by loose packing. Packing replaced. PACE, P. E. Florida Power & Light Co. 80/11/12. 1p. 07143: 248.
- DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8012040010 Forwards interim 10CFR50.4B suspending completion dates for fire protection mods, effective upon 801029 publication in 45FR71869. Rule will be superseded by revised rule when effective.

 EISENHUT.D.G. Division of Licensing. 80/11/07. 5pp. 07152:083.
- 8012020167 Discusses planned mods to emergency notification sys & health physics network HRC will pay for installation of output jacks to provide capability for adding one-way speakers. H/o encl health physics network manual.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/19, 2pp.
- 8012120576 Resubmits socurity plan revisions, in response to NRG 800910 & 1119 ltrs. Plan withheld from public disclosure (ref 10CFR2 790). W/o enci.
 ABEL, J. B. Commonwealth Edison Co. 80/12/08. 1p.

G. Adjudicatory correspondence

- 8012170269 Forwards Director's decision under 10CFR2.206 & FR notice denuing 801024 petition to shut down facilities pending installation of required scram discharge vol monitoring equipment.

 DENION: H.R. Office of Nuclear Reactor Regulation, Director. 80/11/26, ip. 07269:216.
- --8012170678 Director's decision under iOCFR2.206, denying Poilution & Environ Problems. Inc 801024 petition to shut down facilities, pending installation of required scram discharge vol monitoring equipment.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/11/26. 7pp. 07269:218.
- --8012170493 Notice of issuance of Director's decision under 10CFR2.206, denying Pollution & Environ Problems 801024 petition. CABE.E.O. Office of Nuclear Reactor Regulation, Director. 80/11/26. 2pp. 07269:225.
- 8012170410 Requests refusal of util application to transfer spent nuclear fuel rods from Dresden units to Quad City units for storage.NRC should hold public hearings. * Citizens for Safe Energy. 80/12/11. 2pp.

P. Operating license stage documents & correspondence

- 8012140090 Ltr to operating plant licenses, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements, Requests operating reactor licenses confirmation in 45 days that Encl i implementation dates will be met. EISEKHUT, D. Q. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to ali CP & OL holders for BWRs re requirement for implementation of GDYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. O. Division of Licensing. 80/11/04. 4pp.
- 8012080089 Forwards Amends 50.59 & 54 to Licenses DPR-19.DPR-29 & DPR-30.respectively.safety evaluation & notice of issuance & availability.

 IPPOLITO.T.A. Operating Reactors Branch 2, 80/11/12. 2pp. 07180:352.
- --8012080095 Amends 50.59 % 54 to Licenses DPR-19.DPR-27 & DPR-30. respectively, establishing max average planar linear heat generation rate limits for std 8X8 fuel types for exposure valves.

 IPPOLITO.T.A. Operating Reactors Dranch 2. 80/11/12. 23pp. 07180:354.
- ~-8012080102 Safety evaluation supporting Amends 50,57 & 54 to Licenses PPR-17, PPR-27 & PPR-30 respectively.

 * Office of Nuclear Reactor Regulation, Director. 80/11/12, 4pp. 07181:016.
- --801208010A Notice of issuance & availability of Amends 50.59 & 54 to Licenses DPR-19.DPR-29 & DPR-30.respectively. IPPDLITO.T.A. Operating Reactors Branch 2. 80/11/12. 2pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0617.
 "BHR Feedwater Nozzle & Control Rod Drive Return Line
 Nozzle Cracking." Confirmation that implementation dates
 will be met must be sent within 45 days.
- 8012180620 Forwards Amends 32.51 & 45 to Licenses DPR-2.DPR-19 & DPR-25.respectively. Amends 60 & 55 to Licenses DPR-29 & DPR-35.respectively & Amends 58 & 55 to Licenses DPR-39 & DPR-48.respectively. Safeguards contingency plans acceptable. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/17. 3pp.
- --8012180640 Amends 60 & 55 to Licenses DPR-29 & DPR-30, respectively, requiring implementation of safeguards contingency plan. IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/17. 4pp. 07271:335.
- ~~8017180671 Notice of issuance of Amends 32,51 & 45 to Licenses DPR-2. DPR-19 & DPR-23, respectively, Amends 60 & 55 to Licenses DPR-27 & DPR-30, respectively & Amends 58 & 55 to Licenses DPR-39 & DPR-44B, respectively re safeguards contingency plan. CRUICHFIELD.D. Operating Reactors Branch 5. 80/11/17. 2pp.

- 8012010343 Advises of util review & plans re Cycle & reload core. Reload does not involve unreviewed safety questions. Summary of major parameters for reload & OE 801111 ltr re gadolinia rods specs encl.

 JANECER, R. F. Commonwealth Edison Co. 80/11/25, 7pp. 07098:035.
- 8012020301 Forwards tabulation of planned environ qualification testing programs. In response to NRC 801001 ltr.
 ABEL.J.S. Commonwealth Edison Co. 80/11/26, 4pp.
- 8012160479 Forwards listing of changes tests & experiments completed during Nov 1980. Summary of safety evaluation encl. ALIVIAKKIS.N. Commonwealth Edison Co. 80/12/01. 4pp. 07263:110.
- 8012190657 Forwards request for add1 info re 800822 rept entitled, "Evaluation of 18 Inch Containment Isolation Valves for Dresden 2 & 3 & Guad Cities 1 & 2."

 LAINAS, Q.C. Assistant Director for Safety Assessment. 80/12/02. 3pp. 07273:290.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06, 8pp.
- 8012300786 Forwards Amend 61 to License DPR-29; safety evaluation & notice of issuance & availability. IPPOLITO, T.A. Operating Reactors Branch 2. 80/12/05, 2pp. 07308:001.
- --B012300790 Amend 61 to License DPR-29, revising min critical power ratio safety limit to apply to new fuel types & making minor editorial change.

 IPPOLITO.T.A. Operating Reactors Branch 2. 80/12/05. Sipp. 07308:001.
- --8012300793 Safety evaluation supporting Amend 41 to License DPR-29.

 # Office of Nuclear Reactor Regulation, Director. 60/12/05. 5pp.
- --8012300795 Notice of issuance & availability of Amend 61 to License DPR-29.
 IPPOLITO.T.A. Operating Reactors Branch 2. 80/12/05. 2pp.
- 8012120301 Forwards Tech Specs Page 3 2/4.2-15, inadvertently omitted from Util 800918 ltr to NRC.
 JANECCK, R. F. Commonwealth Edison Co. 80/12/10. 2pp. 07236: 249.
- --8012120341 Proposed Tech Specs, Page 3.2/4.2-15, incorporating TNI Lessons Learned Requirements. * Commonwealth Edison Co. 80/12/10. 1p. 07236:250.
- 8012160136 Responds to NRC 800924 request re mads for provision of redundant Class IE protection at interface of Nonclass IE power supply & reactor protection sys. Installation scheduled for refueling outages occurring after June 1981.

 JANECEK.R.F. Commonwealth Edison Co. 80/12/11. 2pp. 07262:244.
- 8012170488 Forwards response to NRC 801031 ltr requesting confirmation that implementation dates indicated in NUREG-0737 will be met. Ability to meet required dates for major mods is contingent upon hardware availability & delivery.

 ABEL.J.S. Commonwealth Edison Co. 80/12/15. 37pp.
- 8012240158 Forwards confirmation that implementation dates per NUREO-0737 will be met & justification for exceptions. Generally dates are contingent upon hardware availability & delivery, Comments on safety requirements in Tech Specs. ABEL, J. B. Communwealth Edison Co. 80/12/15. 37pg.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012090039 Ack receipt of 800509 itr informing NRC of steps taken to correct violations noted in Naste Packaging Insp Ropt 15000039/79-0BE.
 DAVIS, A.B. Region 3, Chicago, Office of the Director. 80/10/03.
 1p. 07198:060.
- --B012070045 Responds to NRC B00421 ltr re violations noted in Waste Packaging Insp Rept 13000039/79-08E. Disputes NRC findings. All applicable requirements met. PEDPLES, D.L. Commonwealth Edison Co. 80/05/09. 2pp. 07198:061.

- 8012170510 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2," No written response required.

 KEPPLER.J.Q. Region 3, Chicago, Office of the Director, 80/10/24.
- 8012180131 Forwards IE insp Repts 50-254/80-22 & 50-265/80-24 on 800901-1017 & notice of violation.
 HEIBHMAN,R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch, 80/11/06. 2pp. 03791:271.
- --8012180153 Natice of violation from insp on 800701-1017.

 * Region 3. Chicago, Office of the Director. 80/10/31. 1p. 03791:273.
- --B012180157 IE insp Repts 50-294/80-22 & 50-265/80-24 on B00901-1017.
 Noncompliance noted: charging water isolation valves not
 closed as required. Fuel assembly removed w/source range
 monitor indicating less than 3 counts per seconé.
 CHRISSOTIMOS, N. DUPONI, S. Q., SPESBARD, R. L. Region 3, Chicago,
 Dffice of the Director. 80/10/31, lipp. 03791:274.
- 8012020099 Ack receipt of 801103.0509 & 0318 ltrs informing NRC of steps taken to correct violations noted in Waste Packaging Insp Rept 15000039/79-08E.
 DAVIS,A.B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/11/14. 1p. 07147:268.
- --8012020110 Responds to ARC 800222 ltr re violations noted in Waste Packaging Insp Rapt 15000039/79-08E. Corrective actions: shipping casks in use & all casks leaving station labeled "Radioactive LSA."

 ABELLJ. B. Commonwealth Edison Co. 80/11/03. 2pp. 07147: 269.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt svaluation tree w/user guide so that facility can compare program to program already reviewed & mate appropriate adjustments. W/o encl.
 KEPPLER, J. O. Region 3: Chicago, Office of the Director. 80/11/18.
- 8012040667 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21.
- B0120B0087 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J. C. Region 3. Chicago, Office of the Director. 80/11/24.
- B012120415 Ack receipt of B01106 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-19 & 50-265/80-21.
 HEIBHRANR.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. B0/11/24. 1p. 07236:017.
- --8012120425 Responds to RRC 801015 ltr re violations noted in IE Insp. Repts 50-254/80-19 & 50-265/80-21. Corrective actions: reactor core isolation cooling controller returned to normal operating configuration & investigation conducted.

 ABEL.J. 8. Commonwealth Edison Co. 80/11/06. 2pp. 07236:018.
- E01217040B Forwards monthly status rept of evaluations performed in response to IE Bulletin 79-14. "Beisnic Analysis for "Built Bafety-Related Piping Bys." No sys identified htress exceeding 1/2 math ultimate stress at OBE loadings. CEK.R.F. Commonwealth Edison Co. 80/11/24. 14pp. 07187:00: 07187:001.
 - 0223 Forwards new security badge numbers & clearance levels for on 3 personnel. Changes should be entered on Sept 1980
 Ass lists.
 PLCR.J.G. Region 3. Chicago: Office of the Director. BD/11/25.
 - 2100661 Ack receipt of 800919 response to NRC 800818 ltr requesting ddl info re lE Bulletin 79-14 evaluations. Dresden & Guad ities responses to Items 1 & 3 unacceptable, since equested info was not included.

 EPPLER. J. O. Region 3. Chicago, Office of the Director. 80/11/26.
 - 12170552 Forwards IE Info Notice 80-27. Suppl 1, "Broken Stude on stry Turbine Steam Inlet Flange." No written response equired.

 EMPLER. J. O. Region 3. Chicago. Office of the Director. 80/11/26.

- 8012070044 Notification of 801209 meeting w/util in Bethesda.MD to discuss acceptance criteria used for evaluation of piping sys under review for IE Bulletin 79-14.

 HONO.H.J. Office of Inspection & Enforcement, Office of the Director. 80/12/04. 29p. 07198:078.
- 8012230065 Responds to IE Sulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No valve parts cast by Malcolm Foundry planned for use or in use at facilities. RAUSCH,T. J. Commonwealth Edison Co. 80/12/05. 2pp.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-01B re environ qualification of Class IE equipment. HAYES, D. H. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp. 07282:108.
- R. Periodic operating reports & related correspondence
- 8012170446 Forwards monthly operating repts for Nov 1980. KALIVIANAXIS.N. Commonwealth Edison Co. 80/12/01. 1p. 07268:047.
- --8012170449 Monthly operating repts for Nov 1980. TUBBB.R.C. Commonwealth Edison Co. 80/12/01, 25pp. 07268:048.
- S. Reportable occurrences. LERs & related correspondence
- 8012010374 Forwards LER 80-028/03L-0. KALIVIANAKIS,N. Commonwealth Edison Co. 80/11/18. 1p. 07091:286.
- --8012010382 LER 80-028/03L-0: on 801023 diesel generator cooling water pump motor 1/2 found two-thirds submerged in water. Caused by inadequate vault sump pump sys. Vault drained & cooling water pump motor replaced.

 HANRUM, D. Commonwealth Edison Co. 80/11/18. 2pp. 07091:287.

DOCKET 50-255 PALISADES NUCLEAR PLANT

- F. Security, medical, emergency & fire protection plans
- 8012110303 Notifies of interim rule suspending completion dates for fire protection mods previously approved by NRC.FR notice encl. EISEKHUT, D. G. Division of Licensing. 80/10/31. 5pp. 07224:118.
- 8012020199 Discusses planned mods to emergency notification sys & health physics network. NRC will pay for installation of output jacks to provide capability for adding one-way speakers. N/o encl health physics network manual. REPPLER. J. O. Region 3, Chicago, Office of the Director. 80/11/19. 2pp. 07148:200.
- 8012150058 Forwards Revision 3 to security plan. Revision withheld (ref 100FR2, 790). HOFFMAN, D. P. Consumers Power Co. 80/12/10. ip. 07239:354.
- Q. Adjudicatory correspondence
- 8012290333 Response to NRC 801107 requests for admissions. Admits that two manual containment isolation valves in Containment Bldg Penetration 4a were found locked open on 790911. Certificate of Syc encl. BIELANSKI, A. P. Consumers Power Co. 80/12/01. 8pp. 07343:105.
- 801222027B Informs that V Stello & B Jorgenson will be available for deposition on dates suggested in BOI112 notics. JO Keppler will not be made available absent showing of exceptional circumstances. Rulemaking & Enforcement Division. 80/12/02. 1p. BURNS, S. C. 07306: 220.
- B0122202B7 Provides status of prehearing matters per 800229 order. Supplemental responses to CPC second round of interrogatories filed on B01107. CPC representatives will be deposed in Jan 1981.
 BURNS, B. O. Rulemaking & Enforcement Division. 80/12/02. 2pp. 27304:230
- 80:2270226 Confirms 80:12:1 conversation re CPC deposition of NRC personnel. B Jorgansen deposition will take place on 8:00:13. JO Kappler on 8:00:14 & V Stello on 8:00:15, in Covert, HI, Olen Ellyn, It. & Bethesda, MD, respectively. BURNS, S. O. Rulemaking & Enforcement Division, 80/12/17. 2pp.
- 8012290106 Corrects deposition date contained in 801219 ltr to 1981. LIEBERMAN, J. Rulemaking & Enforcement Division. 80/12/22. 2pp. 07342:361.

- 8012290522 Notice of appearance in proceeding. Certificate of Svc encl. MOUNT.R.E. Rulemaking & Enforcement Division. 80/12/22. 2pp. 07335:174
- 8012270214 Response to util third round of interrogatories. Includes info re items of noncompliance where noncomplying condition continued for more than 1 day & whather imposition of civil penalty was proposed. Certificate of Svc encl. MOUNT, R. E. Rulemaking & Enforcement Division. 80/12/23. 136pp. 07344:260.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake. EISENHUT, D. G. Division of Licensing. 80/10/21. 4pp.
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT.D. Q. Division of Licensing. 80/10/31. 7pp.
- 8012040128 Forwards Oct 1980 revision to BEF review of safe shutdown sys for facility & NRC positions re review. Evaluation will be basic input to integrated safety assessment for unit. CRUICHFIELD, D. Operating Reactors Branch 5. 80/11/05. 104pp. 07158:320.
- 8012110414 Confirms 801117-19 meeting at site to observe site specific features of facility re SEP structural electrical & topical reviews. Open items & request for addl info encl. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/10. 13pp. 07224:179.
- B0120B0/4B Forwards NRC evaluations of SEP Topics III-1, VI-7. A. 3. VI-7, B. VI-7, F. VI-10. A. VII-1. A. & VII-2. Assessments compare facility w/criteria used for new OLs. CRUTCHFIELD, D. Operating Reactors Branch 5. B0/11/12. 114pp. 071BB: 2BB.
- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BUR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days 470 encl. EIBENHUT, D. O. Division of Licensing. 80/11/13. 1p.
- 8D12120417 Forwards evaluation of SEP Topic VI-7.C.1, "Independence of Redundant Onsite Power Sources." Requests that NRC be informed within 30 days of receipt of 1tr if as-built facility differs from licensing basis assumed in assessment. CRUICHFIELD.D. Operating Reactors Branch 5. 80/11/18. 18pp. 07227:274.
- 8012020106 Confirms 801124 meeting in Jackson MI to discuss regional evaluation of regulatory performance at facilities.

 KEPPLER, J. O. Region G. Chicago, Office of the Director. 80/11/19. ip. 07148:395.
- B012110440 Forwards safety evaluation re extreme meteorological conditions & severe weather phenomena in facility site area. Also forwards TX Tech Univ rept on wind & tornado loadings. I/O TX Tech rept. CRUICHFIELD, D. Bystematic Evaluation Program Branch. B0/11/21. 7pp. 07225:257.
- 801201013B Forwards proposed Tech Spec changes in response to NRC 770806 request re undervoltage protection requirements. Changes do not constitute unreviewed safety question. HOFFMAN, D. P. Consumers Power Co. 80/11/24.
- --8012010160 Proposed Tech Spec changes in response to NRC 790606 request re undervoltage protection requirements. Changes consist of limiting conditions for operation & setting limits for preferred relays. DEWITT, R. B. Consumers Power Co. 80/11/24. 4pp. 07097:321.
- 8012010286 Forwards request for Tech Spec changes re containment spray initiation time.

 HOFFMAN.D.P. Consumers Power Go. 80/11/24. ip. 07097:300.
- --8012010287 Application for Tech Spec changes to License DPR-20 re containment soray initiation time. DEWITT, R. B. Consumers Power Co. 80/11/24. 3pp. 07097;301.

- 8012020479 Discusses NRC 801024 orders for mod of environ qualification of safety-related electrical equipment. Advises that mod for facilities is governed by SEP Topic III-12. All safety-related electrical equipment shall be qualified by 820430.
 VINCENI.R. A. Consumers Power Co. 80/11/26. 2pp. 07141; 259.
- 8012030702 Forwards description of proposed mods to auxiliary feedwater sys & implementation schedule. Mods will reduce potential for water hamner during auxiliary feedwater operation & assure sufficient flow to steam generators.

 HOFFMAN. D. P. Consumers Power Co. 80/12/01. 5pp. 07149:226.
- 8012080354 Forwards proposed changes to Tech Specs.Section 4.0 for administrative controls. Changes reflect organizational changes; clarify existing requirements & brings Tech Specs into closer agreement w/those of other nuclear plants. HOFFMAN. D. P. Consumers Power Co. 80/12/03. 2pp. 07189: 234.
- ---8012080397 Proposed changes to Tech Specs, Section 6.0 for administrative controls. 4 Consumers Power Co. 80/12/03. 13pp. 07189:236.
- 8012080460 Forwards application to amend Tech Specs, revising limiting conditions for operation & setting limits for undervoltage protection relays.

 HOFFMAN, D. P. Consumers Power Co. 80/12/03. 1p. 07189:270.
- --8012080464 Application to amend Tech Specs, Bections 3.16,3.17,4.1.2 & 4.7.1.b.revising limiting conditions for operation & setting limits for undervoltage relays.

 4 Consumers Power Co. 80/12/03. 3pp. 07189:271.
- 80:2080325 Forwards "Containment Bldg Tendon End Anchorage Concrete Surveillance," list of plants w/similar configurations, list of rotating equipment & 17 oversize drawings per 80:117-19 site meetings. Drawings on aperture cards in FDR. KUEMIN.J.L. Consumers Power Co. 80/12/94. 2pp. 06586:003.
- ---8012080529 "Containment Bldg:Tendon End Anchorage Concrete Survaillance." MINKONSKI,H.O., PUSHECK.B.N. Bechtel Associates Professional Corp. 73/09/30. 192pp. 06586:003.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANOART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012240496 Forwards comments on util concerns expressed in 801028 itr. Revision 2 of loss of offsite power survey status rept adequately addresses comments raised for facility. CRUTCHFIELD. Deprating Reactors Branch 5. 80/12/04. 4pp. 07324:106.
- B012170453 Forwards complete list of rotating equipment in plant spent fuel pool area to replace previous submittal. KUEMIN.J. L. Consumers Power Co. 80/12/99. 3pp. 07269:343.
- B012240489 Notification of B01219 meeting w/BEP owners group in Bathesda, MD for discussions on BEP program, schedule for license topic completion & assignment of lead topics to plants. RUSSELL, W. T. Systematic Evaluation Program Branch. B0/12/16. 2pp.
- 8012230205 Forwards request to change facility Tech Bpecs, in direct response to NRC 800702 ltr requesting submission of license amend application to incorporate specs addressing actions taken in response to items from TMI-2 lessons learned. HOFFMAN, D. P. Consumers Power Co. 80/12/18. 2pp. 07317:037.
- --8012230207 Request for Tech Spac change in direct response to NRC 800702 itr requesting submission of license amend application to incorporate spacs addressing actions taken in response to Category A items from TMI-2 lessons learned. DEWITT-R.B. Consumers Power Co. 80/12/18. 3pp. 07317:041.
- B012300499 Forwards response to NUREO-0737. "Clarification of TMI Action Plan Requirements." HOFFMAN D.P. Consumers Power Co. 80/12/19. 300pp. 07354:071.

@ inspection reports, IE Builetins & correspondence

- 8012170527 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/10/24.
 1p. 07268:124.
- 8012310426 Forwards IE Insp Rept 50-255/80-18 on 800901-1003.No noncompliance noted. HEISHKAN,R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/11/04. 2pp. 07370:200.
- --8012310433 IE Insp Rept 50-255/80-18 on 800901-1003 No noncompliance noted Major areas inspected operational safety, maint, surveillance, facility changes & procedures.

 JURGENSON, B.L., HELLER, J.K., PESCHEL, J.M. Region 3, Chicago, Office of the Director. 80/10/31, 9pp. 07370:202.
- 8011250069 Responds to IE Bulletin 79-18. "Audibility Problem Encountered on Evacuation of Personnel from High Roise Areas." Survey/test will be conducted upon completion of repairs to evacuation aliarm sys. FROST.S.R. Consumers Power Co. 80/11/07. 1p. 07048:289.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program aiready reviewed & mate appropriate adjustments M/o enci.

 KEPPLER.J. 0. Region 3. Chicago, Office of the Director. 80/11/18.
- 8012040674 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. KEPPLER.J.G. Region 3, Chicago, Office of the Director. 80/11/21. 200. 07169:079.
- 8012090044 Forwards Info Notice 80-42, "Effect of Radiation on Mydraulic Snubber Fluid." No written response required. KEPPLER, J. O. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:193
- 8012190262 Forwards new security badge numbers & clearance levels for Region 3 personnel. Changes should be entered on Sept 1980 access lists. MEPPLER, J. C. Region 3, Chicago, Office of the Director. 80/11/25. 6pp. 07282:130.
- 8012170561 Forwards IE Info Notice 80-29, Suppl 1. "Broken Stude on Terry Turbine Steam Inlet Flange." No written response required.

 KEPPLER. J. G. Region 3, Chicago, Office of the Director. 80/11/26.
 200. 07264:137.
- 8012310202 Responds to IE Bulletin 80-23 re failure of solenoid valves mfg by Valcor Engineering Corp. No Valcor solenoid valves in use or storage at site.

 HOFFMAN, D. P. Consumers Power Co. 80/11/26. 1p. 07369: 281.
- 8012220701 Responds to IE Sulletin 79-018 re environ qualification of Class IE electrical equipment Util enrolled in SEP.
 Electrical equipment qualification submittals sent to NRC on 801007,30 & 31.
 HOFFMAN, D. P. Consumers Power Co. 80/12/01. 1p. 07293:125.
- 8012270278 Informs that V Stello & B Jorgenson will be available for deposition on dates suggested in 801112 notice. JO Keppler uill not be made available absent showing of exceptional circumstances.

 BURNS, S. G. Rulemaking & Enforcement Division. 80/12/02. 1p. 07306:220.
 - t2220237 Provides status of preheating matters per 800227 order. uplemental responses to CPC second round of terrogatories filled on 801107.CPC representatives will be posed in Jan 1981. RNIS.S.O. Rulemaking & Enforcement Division. 80/12/02. 2pp. 306:230.
 - 2290226 Confirms 801211 conversation re CPC deposition of NRC versonnel. B Jorgensen deposition will take place on 810113. JO Reppler on 810114 & V Stello on 810115 in Covert MI. Glen Elley, SL & Bethesda, MD. respectively.
 BURNS. S. G. Rulemsking & Enforcement Division. 80/12/17. 2pp. 07345:041.
- 2012270243 Responds to NRC 801125 request for info re inservice insp program for pressressed concrete containment structures. Info discusses containment tendon surveillance program. FROST, S.R. Consumers Power Co. 80/12/23. 2pp. 07345:145.

- R. Periodic operating reports & related correspondence
- BO12160425 Forwards monthly operating rept for Nov 1780. KENYEDY. D. M. Consumers Power Co. 80/12/08. ip. 07254:140.
- --8012160426 Monthly operating rept for Nov 1980. BODTKE.P.J. Consumers Power Co. 80/12/08. 4pp. 07254:141.
- S. Reportable occurrences, LERs & related correspondence
- BO12020580 Forwards corrected App C. "Calculations of Radiological Effects as Results of Hypothetical Accident W/CV-3030 Open," to 809820 LER 80-021. Revision 1. Corrected Apps E & F also encl. MGFFMAN, D. P. Consumers Power Co. 80/11/24. 17pp. 07141: 276.
- 8012010384 Forwards LER 80-043/01T-0. HDFFHAN, D. P. Consumers Power Co. 80/11/25. 1p. 07091: 298.
- --8012010372 LER 80-043/01T-0: on 801105 measured leakage through containment penetration 14 exceeded Tech Spec limit. Cause under evaluation. Check valve & butterfly valve seat replaced.

 2 Gorsumers Power Co. 80/11/25. 1p. 07091: 279.
- B012300406 Forwards LER 80-044/03L-0. FR081.S.R. Consumers Power Co. 80/12/23. 1p. 07359:397.
- --B012300410 LER B0-044/03L-0: on B01125, closure head fasteners on return head flange of letdown heat exchanger found corroded. Caused by contact w/borated water leaking from flange due to improper assembly of closure head. Damaged studs replaced. Consumers Power Co. B0/12/23. 1p. 07359:358.
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- B012040007 Notification of B01202 meeting w/util in Bethesda, MD to discuss fire replication tests for fire protection sys. CLARK, R. J. Operating Reactors Branch 2. 80/11/19. 2pp. 07169:290.
- B012080835 Notification of B01121 meeting w/util in Bethesda.MD to discuse util position on central emergency response ctr & plans for emergency mgt.

 STAHLE.C. Licensing Branch 2 B0/11/19. App. 07175:331.
- B012090209 Advises that util has instituted interim procedures to handle conversion of release rates to emergency classifications for State of AL.as discussed in B01027 meeting W/NRC & util B01105 ltr to State of AL. HILLS.L.K. Tennessee Valley Authority. B0/12/03. ip. 07200:344.
- B012300A4B Requests comments by B10115 re plans to install prompt notification sys within 5-mile emergency planning zone. Util assessments on fission product releases are consistent w/ info presented at NRC 801118 meeting.
 MILLS, L.M. Tennessee Valley Authority. 80/12/24. 2pp. 07308:001.
- P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.GL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISENHUT.D. O. Division of Licensing. 80/10/31. 7pp.
- 8012270358 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE.Applicable to all license applications & proposed amends, including core roloads, EISENHUT, D. O. Division of Licensing. 80/11/04. 4pp.
- 8012220563 Ltr to all power reactor licensess forwarding NUREG-0619, "BMR Feedwater Norths & Control Rod Drive Return Line Northe Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EISENNUT.D.G. Division of Licensing. 30/11/13. 19.
- 8011250423 Forwards partial response to NRC 800708 request for info re containment purging & venting sys. Addl info to complete response will be submitted by 810401. Drawings available in Central Files, apperture cards in PRR. MILLS.L.M. Tennessee Valley Authority. 80/11/19. 21pp. 07065:332.

- 8012090231 Forwards proposed change to util rept TVA-TR75-1 re GA program as ref in App D. Section D. 4 of FSAR.

 MILLS,L.M. Tennessee Valley Authority. 80/12/01. 2pp. 07201:131.
- B012160633 Forwards NRC review of fish impingement data collected at facility from Bept 1976 Aug 1979, in response to util request to terminate study as required by ETS. Request should be granted.
 BALLARD.R. L. Environmental Engineering Branch. 80/12/02. 33pp. 07261:256.
- 8012230510 Forwards Amends 63.59 & 35 to Licenses DPR-33,DPR-52 & DPR-68 respectively, safety evaluation & notice of issuance & availability.

 1PPDLITO, Y. A. Operating Reactors Branch 2. 80/12/02. 2pp. 07316:247.
- --8012230515 Amends 63,59 % 35 to Licenses DPR-33, DPR-52 % DPR-68, respectively, changing Tech Specs to resolve auxiliary electrical sys ambiguities in Section 3.9. IPPOLITO, T. A. Operating Reactors Branch 1. 80/12/02. 11pp. 07316:249.
- --8012230519 Safety evaluation supporting Amends 63,59 & 35 to Licenses DPR-33.DPR-52 & DPR-68,respectively.

 * Dffice of Nuclear Reactor Regulation, Director. 80/12/02. 5pp. 07316:283.
- --8012230523 Notice of issuance & availability of Amends 63,59 & 35 to Licenses DPR-33,DPR-52 & DPR-68,respectively. IPPOLITO,T.A. Operating Reactors Branch 1. 80/12/02. 2pp. 07316:288.
- 8012190627 Forwards list of applications for Tech Spec changes, fees paid, fees due & basis for each fee determination. Requests remission of fees due.

 10005, R. H. License Fee Management Branch. 80/12/03. 2pp. 07273:293.
- 8012090344 Responds to NRC 800924 request for info re reactor protection sys power supplies. Commits to install Class IE sys & provides schedule for completion of mode & for submission of design info & proposed Tech Specs.

 MILLS, L, M. Tennessee Valley Authority. 80/12/04. 2pp. 07199:349.
- 8012220485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agraement State burial site conditions. Forwards results of IE survey.
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04, 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed u/71% planning or considering increasing storage capacity.
 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- B012300713 Forwards Amends 64 & 60 to Licenses DPR-33 & DPR-52, respectively, safety evaluation & notice of issuance & availability.

 IPPOLITO, T. A. Operating Reactors Branch 2. B0/12/10. 2pp. 07340: 009.
- --8012300716 Amends 64 & 60 to Licenses DPR-33 & DPR-32, respectively, allowing facility operation w/standby coolent supply capability inoperable for period not to exceed 10 days. IPPOLITO.T.A. Operating Reactors Branch 2. 80/12/10, 16pp. 07360:011.
- --8012300721 Bafety evaluation supporting Amends 64 & 60 to Licenses DPR-33 & DPR-52, respectively. • Office of Nuclear Reactor Regulation, Director. 80/12/10. 3pp, 07360:029.
- --8012300724 Notice of issuance & availability of Amends 64 & 60 to Licenses DPR-33 & DPR-32, respectively. IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/10. 2pp. 07360:032.
- 8012230237 Forwards brief summary of planned mods to BHR scram sys.in response to NRC 801001 ltr.Addl info regarding implementation schedule will be provided by 810201. MILLS.L.M. Tennessee Valley Authority. 80/12/15. 3pp. 07314:018.
- 8012240265 Responds to 801203 ltr re final fee determination for facility Tech Spec changes. Fee determination for Changes TS 133.TB 143 & TB 148 not contested Disagreements w/determination for TS 145 & TS 151 discussed in encl. MILLB.L.M. Tennessee Valley Authority. 80/12/17. 2pp. 07324:337.

- 8012300289 Advises that in Jan 1981 util will provide addl info re reactor bldg crane to assist NRC review of generic subj of moving heavy loads near fuel.Pending resolution.continued caution will be exercised.

 MILLS.L.M. Tennessee Valley Authority. 80/12/22. ip. 07349:335.
- 8012290237 Forwards response to clarification items in NRC 801031 ltr re post-TM1 requirements. Enci contains list of ECC8 outages for past 5 yrs & training program requirements for shift technical advisors.

 MILLS.L.M. Tennessee Valley Authority. 80/12/23. 100pp. 07338:327.
- 8012300276 Requests extension of concurrent cycle start date from 800101 to 800701.
 MILLS.L.M. Tennessee Valley Authority. 80/12/24. 2pp. 07308:001.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012190201 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
 0'REILLY,J.P. Region 2. Atlanta, Office of the Director. 80/10/24.
 1p. 07240:279.
- 8012170004 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required. D'REILLY, J. P. Region 2. Atlanta, Diffice of the Director. 80/10/31. 19. 07264: 132.
- 8012230030 Forwards IE Circular 80-23. "Potential Defects in Deloit Power Sys Emergency Generators." No written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
 1p. 07311:214.
- 8012110266 Requests assessment & corrective actions taken re-control room ceiling constructed w/apparently flammable tiles within 20 days.

 TEDESCO.R.L Assistant Director for Licensing. 80/11/04. Opp.
- 8012110807 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Maicolm Foundry Co. Inc." Written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.
 1p. 07225:180.
- 8012180220 Forwards IE Insp Repts 50-257/80-38, 50-260/80-32 & 50-276/80-32 on 801014-15.No noncompliance noted. MURPHY, C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/06. 2pp. 03792:019.
- --8012180223 IE Insp Repts 50-259/80-38,50-260/80-32 & 50-296/80-32 on B01014-15.No noncompliance noted Major areas inspected; settling of structural backfill under RHR svc water tunnels. LENAHAN, J. J. Region 2. Atlanta, Office of the Director. COLON, T. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/05. 3pp. 03792:021.
- 8012030837 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p. 07150:085.
- 8012180055 Forwards 1E Insp Repts 50-259/80-37, 50-260/80-31, 50-296/80-31 & 50-327/80-40 on 801006-07, No noncompliance noted. KENNA, M. B. Region 2, Atlanta, Bafeguards Branch. 80/11/07, 2pp. 03791:173.
- --B012180069 IE Insp Repts 50-259/80-37, 50-260/80-31, 50-296/80-31 & 50-327/80-40 on 801006-07. No noncompliance noted Major areas inspected unescorted access clearances & intrusion of plant protected area. Details withheld (ref 10CFR2.790). TOBIN, W. J. Region 2, Atlanta, Office of the Director. MCGUIRE, D. Region 2, Atlanta, Bafeguards Branch. 80/11/06, ip. 03791:175.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'RETILLY, J.P. Region 2, Atlanta, Office of the Director. BO/11/10. ip. 07182:285.
- B0120B0773 Forwards monthly status rept for Nov 1980 re work performed per IF Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys." Drawing configuration pips support & floor 4: wall penetration insps included. MILLS.L.M. Tennessee Valley Authority. 80/11/10. 29pp. 07188:008.

- 8012340143 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/14. 1p. 07158:066.
- 8012020339 Ack receipt of 801105 ltr informing NRC of steps taken to correct violations noted in IE Insp Regts 50-259/80-34, 50-260/80-27 & 50-26/80-28.
 LEWIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/11/20. ip. 07143:126.
- --B012020345 Responds to NRC 801009 ltr re violations noted in 1E Insp Repts 50-259/80-34.50-260/80-27 & 50-296/80-28. Corrective actions: administrative instructions modified to ensure fire watch assigned to vital area issued key card for access. MILES.L.M. Tennessee Vailey Authority. B0/11/05. 20p. 07143:127.
- --8012020348 Forwards IE Insp Repts 50-259/80-34,50-260/80-27 & 50-296/80-28 on 800801-31 & notices of violation & deviation LEURS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/10/09. 2pp. 07143:127.
- --B012020334 Notice of violation from insp on 800801-31.

 Region 2. Atlanta, Office of the Director. 80/10/07. 1p. 07143:131.
- --8012020355 Notice of deviation from insp on 800801-31.

 a Region 2. Atlanta, Office of the Director. B0/10/07. lp. 07143:132.
- --B012020364 IE Insp Repts 50-259/80-34,50-260/80-27 & 50-296/80-28 on B00801-31. Noncompliance noted: no fire catch in cable spreading room w/inoperable carbon dioxide sys & failure to monitor scram discharge header level as prescribed.

 SULLIVAN.R.F., CHASE, J. W. Region 2. Atlanta, Office of the Director. DANCE, H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/10/07. 9pp. 07143:133.
- 8012050067 Forwards IE Bulletin 80-24, "Prevention of Danage Due to Water Leakage Inside Containment." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/21. 1p. 07173:225.
- 8012080004 Forwards IE Info Notice 80~42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24. ip. 07182:157.
- B012170359 Forwards lE Info Notice 80-29. Suppl 1: "Broten Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY.J.F. Region 2: Atlanta, Office of the Director. B0/11/26. tp. 07269:022.
- 8012220395 Forwards response to IE Bulletin 80-06. "Engineered Safety Features (ESF) Reset Controls." Results of supplemental drawling review, devices to be tested & testing schedule encl. HILLS, L. H. Tennassee Valley Authority. 80/12/03. 6pp. 07299: 226.
- 8012310111 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." No valve parts cast by foundry used at facilities.
 HILLB.L.M. Tennessee Valley Authority. 80/12/05. 1p. 07370:019.
- 8012190466 Ack receipt of 801113 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-239/80-28. S0-260/80-21 & 50-296/80-22. Confirms teleon that maint on valve will be completed before entering aperable mode. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/12/10. 1p. 07287:026.
- --8012190472 Responds to NRC 801027 ltr re violations noted in IE Insp Repts 50-259/80-28, 30-260/80-21 & 50-296/80-22. Corrective actions: testing of subj pressure switch accomplished as soon as 30% automatic bypass interlock cleared. MILSJ.L.M. Tennessee Valley Authority. 80/11/13. 3pp. 07287:037.
- --8012190481 Act receipt of 800704 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-28, 50-269/80-21 & 50-296/80-22 More info requested on subj pressure switch.

 O'REILLY, J.P. Region 2: Atlanta, Office of the Director.
 80/10/27. ip. 07287:040.

- --B012170492 Responds to NRC 800815 ltr re violations noted in IE Insp Repts 50-259/80-28.50-260/80-21 the 50-296/80-22. Disputes finding of noncompliance. MILLS, L.M. Tennessee Valley Authority. 80/09/04. 3pp. 07287:041.
- --8012190499 Forwards IE insp Repts 50-259/80-28.50-260/80-21 & 50-296/80-22 on 800601-30 & notice of violation. LENIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/08/15. 2pp. 07287:044.
- --E012190504 Notice of violation from insp on B00601-90.

 * Region 2. Atlanta. Office of the Director. 80/08/15. ip. 07287:046.
- --B012190512 IE Insp Repts 50-259/80-28,50-260/80-21 & 50-296/80-22 on 800601-30. Noncompliance noted: failure to test Control Valve 2 pressure sensor after maint & before returning to svc. SULLIVAN, R.F., CHASE, J. H. Region 2. Atlanta, Office of the Director. DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Eupport Branch. 80/08/15. 6pp. 07287:047.
- R. Periodic operating reports & related correspondence
- B012160317 Forwards monthly operating repts for Nov 1980. ABERCROMSIE: N. Tennessee Valley Authority. 80/12/10. 1p. 07252: 269.
- --8012160321 Monthly operating repts for Nov 1980. THDM: T. Tennessee Valley Authority. 80/12/01. 33pp. 07252:270.
- S. Reportable accurrences. LERs & related correspondence
- 8012090410 RO 50-239/8085: on 801123 reservoir water temp exceeded max allowable temp. Caused by influence of colder water upstream. Load on Unit 3 reduced in four stages to shutdown & water flows increased.

 MILLS.L.H. Tennessee Valley Authority. 80/12/03. 2pp. 07187:001.
- 8012100497 Forwards LERs identified as missing in 801104 memo. Encl LERs cancelled. LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/12/03. 1p. 07218:078.
- --801210050\$ LER 80-009 has been cancelled. a Duke Power Co. 80/12/03. ip. 07218:099.
- --8012100506 LER 80-067 has been cancelled. 4 Duke Power Co. 80/12/03. ip. 07218:100.
- --8012100510 LER 80-062 has been cancelled. * Dute Power Co. 80/12/03. ip. 07219:101.
- --8012100513 LER 80-051 has been cancelled.
 -- Carolina Power & Light Co. 80/12/03. ip. 07218:102.
- 8012120466 Forwards LER 80-083/03L-0. CREEN.H.J. Tennessee Valley Authority. 80/12/05. ip. 07236:022.
- --B012120477 LER 80-083/03L-0: on 801107.HPCI steam line space high temp switch TS-73-2E found to trip at 235 F, erceeding limit. Caused by Fenwal Model 17023-6 temp switch drift. Switch recallbr.

 # Tempesse Valley Authority. B0/12/05. 2pp. 07236:023.
- B012120502 Forwards LER B0-085/01T-0. GREEN.H.J. Tennessee Vailey Authority. B0/12/05. ip. 07236:040.
- --8012120506 LER 80-085/01T-0: on 801123 river temp lowered causing differential temp of less than 5 F. Caused by heavy rainfall. Unit 3 load reduced & river flow increase requested.

 * Tennessee Valley Authority. 80/12/05. ip. 07236:041.
- B012120510 Forwards LER 80-084/03L-0. GREEN.H. J. Tennessee Valley Authority. B0/12/09. 1p. 07237:046.
- --B012120514 LER 80-084/03L-0: on B01112. Alternate feeder breaker 1930 failed to close. Causef by lack of contact between fuse clip & breaker fuse & dirty auxiliary contacts. Fuse clip adjusted & contacts cleaned.

 * Tennessee Valley Authority. 80/12/09. 2pp. 07237: 047.
- 8012300577 Forwards updated LER 80-065/03L-1. GREEN.H.J. Tennesses Valley Authority. 80/12/23. ip. 07362:312.

- --8012300582 Updated LER 80-065/03L-1: on 800828, wind direction indication at elevation 887 mean sea level was lost & 7-day limiting condition of operation entered, Caused by noisy potentiometer. Instrument replaced.

 ** Tennessee Valley Authority. 80/12/23. 2pp. 07362:313.
- 8012300634 Forwards LER 80-076/03L-1. OREEN.H.J. Tennessee Valley Authority. 80/12/23. 1p. 07359:088.
- --B012300643 LER 80-076/03L-1; on 801007, during normal operation, air differential temp recorders TDR-90-103 & FDR-90-104, channel A elevation 620 to 737 MSL. & channel B elevation 620 to 887 MSL failed. Caused by component failure in digital voltmeter. * Tennessee Valley Authority. 80/12/23. 2pp. 07359:089.
- 8012300428 Forwards LER 80-086/03L-0. OREEN:H.J. Tennessee Valley Authority. 80/12/24. 1p. 07349:351.
- 8012300432 LER 80-086/03L-0: on 801129, during scram time testing, control rods were moved in conformance w/8I 4.3.8.1.a. Overtravel alarm received when control rod 14-ii was fully withdrawn, indicating rod uncoupied. Cause unknoun. Instructions revised.

 * Tennessee Valley Authority. 80/12/24. 2pp. 07349:352.
- 8012300615 Forwards LER 80~074/03L-1. OREEN, H. J. Tennessee Valley Authority. 80/12/24. 1p. 07357:326.
- --8012300625 LER 80-074/03L-1: on 800924; during normal operation, seismic monitor SMA2 found inoperable. Caused by failure of printed wiring board 100935. Assembly repaired, functionally tested & returned to svc.

 * Tennessee Valley Authority. 80/12/24. 2pp. 07346; 188.

V. Operator Examinations

- 8012290237 Forwards response to clarification items in NRC 801031 ltr re-post-TMI requirements. Encl contains list of ECCS outages for past 5 yrs & training program requirements for shift tachnical advisors.

 MILLS.L.M. Tennessee Valley Authority. 80/12/23. 100pp.
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- B012040007 Notification of B01202 meeting w/util in Bethesda.MD to discuss fire replication tests for fire protection sys. CLARK,R.J. Operating Reactors Branch 2. 80/11/19, 2pp, 07169:290.
- 8012080835 Notification of 801121 meeting w/util in Bethesda: MD to discuss util position on central emergency response ctr & plans for emergency mgt.

 8TAHLE: C. Licensing Branch 2. 80/11/19. 4pp. 07175:331.
- 8012090209 Advises that util has instituted interim procedures to handle conversion of release rates to emergency classifications for State of AL, as discussed in 801027 maeting w/NRC & util 801103 ltr to 8tate of AL. MILLS,L. M. Tennessee Valley Authority, 80/12/03. 1p. 07200:344.
- 8012300648 Requests comments by 810115 re plans to install prompt notification sys within 5-mile emergency planning rone. Util assessments on fission product releases are consistent w/ info presented at NRC 801118 meeting.

 MILLS.L.M. Tennessee Valley Authority, 80/12/24, 2pp. 07308:001.
- P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISEKHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- 8012220338 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. O. Division of Licensing. 80/11/04. 4pp.
- G012080290 Forwards Amend 59 to License DPR-52, safety evaluation & notice of issuance & availability.
 IPPOLITO, T.A. Operating Reactors Branch 2. 80/11/12, 2pp. 06986:003.

- --80120B0295 Amend 58 to License DPR-52, changing Tech Specs to permit operation in Cycle 4. IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/12. 34pp. 04594:003.
- --8012080301 Safety evaluation supporting Amend 58 to License DPR-52. # Office of Nuclear Reactor Regulation, Director. 80/11/12, 11pp. 06586:003.
- ~-8012080306 Notice of issuance & availability of Amend 58 to License DPR-52.

 IPPOLITO, T. A. Operating Reactors Branch 2. 80/11/12. 2pp.
- 8012220543 Ltr to all power reactor licensees forwarding NUREO-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days.
- 8011290423 Forwards partial response to NRC 800708 request for info re containment purging & venting sys. Addl info to complete response util be submitted by 810401. Drawings available in Central Files, aperture cards in PDR. MILLS, L. H. Tennessee Valley Authority. 80/11/19, 21pp. 07065:332.
- 8012090231 Forwards proposed change to util rept TVA-TR75-; re QA program as ref in App D. Section D. 4 of FSAR.
 MILLS.L.K. Tennessee Valley Authority. 80/12/01. 2pp. 07201:151.
- 8012160633 Forwards NRC review of fish impingement data collected at facility from Sept 1976 Aug 1979, in response to util request to terminate study as required by ETB. Request should be granted.

 BALLARD,R.L. Environmental Engineering Branch. 80/12/02. 33pp. 07261: 256.
- 8012230510 Forwards Amends 63.59 & 35 to Licenses DPR-33.DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability.

 1PPOLITO.T.A. Operating Reactors Branch 2. 80/12/02. 2pp. 07316: 247.
- --8012230515 Amends 63.59 & 35 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs to resolve auxiliary electrical sys ambiguities in Section 3.9. IPPOLITO.T.A. Operating Reactors Branch 1. 80/12/02. [1pp. 07316:249.
- --8012230519 Safety evaluation supporting Amends 63,59 & 35 to Licenses DPR-33.DPR-52 & DPR-68, respectively.

 # Office of Nuclear Reactor Regulation, Director, 80/12/02. Spp. 07316:283.
- --8012230523 Notice of issuance & availability of Amends 63,57 & 35 to Licenses DPR-33,DPR-52 & DPR-68,respectively. IPPOLITO,T.A. Operating Reactors Branch i. 80/12/02. 2pp.
- 8012190527 Forwards list of applications for Tech Bpec changes, fees paid fees due & basis for each fee determination. Requests remission of fees due.
 DIOOS.R.M. License Fee Management Branch. 80/12/03. 2pp. 07273: 293.
- 8012090344 Responds to NRC 800924 request for info re reactor protection sys power supplies.Commits to install Class IE sys & provides schedule for completion of mods & for submission of design info & proposed Tech Specs.

 MILLS, L. M. Tonnessee Valley Authority. 80/12/04. 2pp. 07179:349.
- 8012220485 Responds to 800911 memo requesting that Dfc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey.

 DENTON.H.R. Defice of Nuclear Reactor Regulation, Director. 80/12/04, 2pp.
- ~~8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANDARI,R.L. Effluent Treatment Systems Branch, 80/11/06, 8pp.
- 8012300713 Forwards Amends 64 & 60 to Licenses DPR-33 & DPR-52; respectively, safety evaluation & notice of issuance & availability. IFPGLITG.T.A. Operating Reactors Branch 2. 80/12/10, 2pp. 07360:009.

- --B012300716 Amends 64 & 60 to Licenses DPR-33 & DPR-52, respectively, allowing facility operation w/standby coolant supply capability inoperable for period not to exceed 10 days. IPPOLITO.T.A. Operating Reactors Branch 2, 80/12/10, 16pp. 07360:011.
- --8012300721 Bafety evaluation supporting Amends 64 & 60 to Licenses
 DPR-33 & DPR-52, respectively.

 **Office of Nuclear Reactor Regulation, Director. BD/12/10. 3pp.
 07360:027.
- --B012300724 Notice of issuance & availability of Amends 64 & 60 to Licenses DPR-33 & DPR-52 respectively. TPPDLITD.T.A. Operating Reactors Branch 2. B0/12/10. 2pp.
- 8012230257 Forwards brief summary of planned mods to BWR scram sys. in response to NRC 801001 [tr. Addl info regarding implementation schedule will be provided by 810201.
 MILLS.L.B. Tennessee Valley Authority. 80/12/15. Spp. 07314:018.
- 8012240745 Responds to 801203 ltr re final fee determination for facility Tech Spec changes. Fee determination for Changes T8 153, TS 143 & TS 148 not contested. Disagreements utility termination for TS 145 & TS 151 discussed in encl. HILLS.L.M. Tennessee Valley Authority. 80/12/17. 2pp. 07324:337.
- B012300289 Advises that in Jan 1981 util will provide addl info re reactor bidg crane to assist NRC review of generic subj of moving heavy loads near fuel Pending resolution, continued caution will be exercised.

 MRLLS,L.M. Tennessse Valley Authority. 80/12/22. lp. 07349:335.
- B012270237 Forwards response to clarification items in NRC 801031 ltr re-post-TMI requirements. Encl contains list of ECCS outages for past 3 yrs & training program requirements for shift technical advisors.

 MILLSI. M. Tennessee Valley Authority. 80/12/23. 100pp. 07338:327.
- 8012300276 Requests extension of concurrent cycle start date from 800101 to 800701.

 MILLS.L.H. Tennessee Valley Authority, 80/12/24. 2pp. 07308:001.
- G Inspection reports, 1E Bulletins & correspondence
- 8012150201 Forwards IE Info Notice BO-37. "Containment Cooler Leats & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY-J.P. Region 2. Atlanta, Office of the Director. 80/10/24.
- 8012170004 Forwards IE info Notice 80-39. "Malfunction of Solenoid Valves Mig by Valcor Engineering Corp." No specific action or response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012230030 Forwards IE Circular 80-23, "Potential Defects in Deloit Power Bys Emergency Generators." No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31.
 1p.
- B012110966 Requests assessment & corrective actions taken re control room ceiling constructed e/apparently flammable tiles within 20 days.

 TEDFSCO.R.L. Assistant Director for Licensing. B0/11/04. 3pp.
- B012110807 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.inc." Uritten response required. UrELLLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/06.
- Oi2180220 Forwards IE Insp Repts 50-259/80-38,50-260/60-32 & 50-296/60-32 on 801014-15 No noncompliance noted. RUMPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/06. 2pp. 03792:019.
- --8012160223 IE Insp Repts 50-257/80-38.50-260/80-32 & 50-296/80-32 on 801014-15. No noncompliance noted Major areas inspected: settling of structural backfill under RHR swc water tunnels. LENAHAM: J. Region 2. Atlanta. Office of the Director. COLONIT. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/05. Spp. 03792:021.

- 8012030837 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p.
- B0121B0055 Forwards IE Insp Repts 50-257/80-37, 50-260/80-31, 50-296/80-31 & 50-327/80-40 on B01006-07.No noncompliance noted.

 KENNALU.B. Region 2. Atlanta, Bafeguards Branch. 80/11/07. 2pp.
- --8012180069 IE Insp Repts 50-259/80-37,50-260/80-31,50-296/80-31 & 50-327/80-40 on 801006-07. No noncompliance noted Major areas inspected; whescorted access clearances & intrusion of plant protected area. Details withheld (ref 100FR2.790). TOBIN: M. J. Region 2. Atlanta. Office of the Director, MCGUIRE, D Region 2. Atlanta. Safeguards Branch. 80/11/06. ip. 03791:179.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Swing Chack Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/11/10.

 ip. 07182:285.
- 80120807/3 Forwards monthly status rept for Nov 1980 re work performed per IF Bulletin 79-14. "Beismic Analysis for As-Built Safety-Related Piping Sys." Drawing configuration.pips support & floor & wall penetration inps included. MILLS.L.M. Tennessee Valley Authority. 80/11/10. 29pp. 07188:00B.
- B012040143 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves
 Hfg by Valcor Engineering Corp." Requires estimate of
 manpower associated w/corrective actions.
 O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/14.
 1p. 07158:064.
- 8012020339 Ack receipt of 801105 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/80-34. 50-226/80-28. LEWIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/11/20. 1p. 07143:126.
- --8012020345 Responds to NRC 801009 ltr re violations noted in IE Insp. Repts 50-259/80-34, 50-260/80-27 & 50-296/80-28. Corrective actions: administrative instructions modified to ensure fire watch assigned to vital area issued key card for access. MILLB:L.M. Tennessee Valley Authority. 80/11/05. 2pp. 07143:127.
- --8012020348 Forwards IE insp Repts 50-259/80-34,50-260/80-27 & 50-296/80-28 on 800801-31 & notices of violation & deviation.

 LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/10/09, 2pp. 07143:129.
- --8012020354 Notice of violation from insp on 800801-31.

 ** Region 2. Atlanta. Office of the Director. 80/10/07. ip. 07143:131.
- --8012020356 Notice of deviation from into on 800801-31.

 * Region 2, Atlanta, Office of the Director. 80/10/07. ip. 07143:132.
- --8012020364 IE Insp Repts 50-259/80-34,50-260/80-27 & 50-296/80-28 on 800801-31. Noncompliance noted:no fire watch in cable spreading room w/inoperable carbon dioxide sys & failure to monitor scram discharge header level as prescribed. SULLIVAN, R. F., CHASE, J. W. Region 2, Atlanta, Office of the Director. DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. BO/10/07. 9pp. 07143:133.
- B012050967 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21.
 1p. 07173:225.
- 8012080004 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. Hydraulic Snubber Fluid." No written response required. G'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/24. ip. 97182:157.
- B012170359 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange," No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.

- 8012180089 Ack receipt of 801110 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-260/80-28.
 MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/28. 1p. 03791:176.
- --B012180097 Responds to NRC B01017 ltr re violations noted in IE insp Rept 50-260/80-28. Corrective actions: preliminary & final liquid penetrant examinations performed. MILLS,L.M. Tennessee Valley Authority. B0/11/10. 3pp. 03791:177.
- --8012180099 Forwards IE Insp Rept 50-260/80-28 on 800916-22 & notice of violation. HURPLY.C.E. Region 2- Atlanta. Reactor Construction & Engineering Support Branch. 80/10/17. 2pp. 03791:180.
- --8012180109 Natice of violation from insp on 800916-22.

 * Region 2. Atlanta, Office of the Director. 80/10/14. ip. 03791:182.
- --8012180112 IE lnsp Rept 90-260/80-28 on 800916-22. Noncompliance noted: inadequate liquid penetrant examination. OIRARD.E.H. Region 2. Atlanta. Office of the Director. HERDT.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/14. App. 03791:183.
- 8012220595 Forwards response to 1E Bulletin 80-06, "Engineered Safety Features (ESF) Reset Controls." Results of supplemental drawing review.devices to be tested & testing schedule encl. MILLS.L.M. Tennessee Vailey Authority. 80/12/03. 6pp. 07299:226.
- B012310111 Responds to IE Bulletin B0-21, "Valve Yokes Bupplied by Malcolm Foundry Co.Inc." No valve parts cast by foundry used at facilities.
 Mill8.L.M. Tennessee Valley Authority. B0/12/05. ip. 07370:019.
- 8012190466 Ack receipt of 801113 ltr informing NRC of ateps taken to correct violation noted in 1E Insp Rapts 50-259/80-28, 50-269/80-21 ½ 50-276/80-22. Confirms teleon that maint on valve will be completed before entering operable mode. LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/12/10. 1p. 07287:036.
- --8012190472 Responds to NRC 801027 itr re violations noted in IE Insp Repts 30-259/80-28.50-260/80-21 & 30-296/80-22, Corrective actions: testing of subj pressure switch accomplished as soon as 30% automatic bypass interlock cleared, MILLS, L. M. Tennessee Valley Authority, 80/11/13, 3pp. 07287:037.
- --8012170481 Ack receipt of 800704 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 30-257/80-28, 50-260/80-21 & 50-276/80-22. More info requested on subj pressure switch.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/27. ip. 07287:040.
- --8012190492 Responds to NRC 800815 ltr re violations noted in 1E Insp Repts 50-259/80-28,50-260/80-21 & 50-296/80-22. Disputes finding of noncompliance. MILLS.L.M. Tennessee Valley Authority. 80/09/04. 3pp. 07287:041.
- ~-8012190499 Forwards IE Insp Repts 50~259/80~28,50~260/80~21 & 30~296/80~22 on 800601~30 & notice of violation. LEHIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/08/15. 2pp. 07287:044.
- --8012170504 Natice of violation from insp on 800601-30.

 * Region 2. Atlanta. Office of the Director. 80/08/15. ip. 07287:044.
- --8012190512 IE insp Repts 50-259/80-28, 50-260/80-21 & 50-296/80-22 on 800601-30. Noncompliance noted: failure to test Control Valva 2 pressure sensor after maint & before returning to svc. SULLIVAN, R. F., CHASE, J. H. Region 2. Atlanta, Office of the Director. DANCE, H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/08/15. 6pp. 07287:047.
- R. Periodic operating reports & related correspondence
- 8012160317 Forwards monthly operating repts for Nov 1980. ABERCROMBIE, H. Tennessee Vallay Authority. 80/12/10, 1p 07252:269.
- --8012140321 Monthly operating repts for Nov 1980. THOM: T. Tennessee Valley Authority. 80/12/01. 33pp. 07252:270.

- S. Reportable occurrences. LERs & related correspondence
- B012030599 RD 50-260/80-47: on B01107, chloring residual reached 0.49 mg/1 exceeding max allowable of 0.05 mg/1. Caused by failure of main condenser cooling water pumps to provide adequate dilution. Chlorination stopped Procedures revised.

 MILLS, L. K. Tennessee Vailey Authority. B0/11/26. 4pp. 07151:165.
- 8012020418 Forwards LER 80-048/03L-0. ORECH.H.J. Tennessee Valley Authority. 89/11/28. 1p. 07148:300.
- ---8012020421 LER 80-048/03L-0: on 801031, drywell pressure transmitter 2-PT-64-67 found not qualified for radiation environ fallowing LOCA Caused by transmitter GEMAC model 556 not qualified to meet environ conditions. Transmitter replaced.

 * Tennessee Valley Authority. 80/11/28. 2pp. 07148:301.
- 8012100523 Forwards LER 80-049/03L-0. OREEN.H. J. Tennessee Vailey Authority. 80/12/03. 1p. 07218:119.
- ---8012100534 LER 80-049/03L-0: on 801104, while in cold shutdown, total leakage found to erreed allawable rate.Caused by deterioration of valve seats.Valves repaired & tested. # Tennessee Valley Authority, 80/12/03. 4pp. 07218:120.
- 8012170558 Forwards LER 80-052/03L-0. GREEN.H. J. Tennessee Valley Authority. 80/12/12. 1p. 07264:134.
- ---8012170583 LER 80-052/03L-0: on 801115, scram discharge vol tank 3-gallon level alarm switch 2-L8-85-45F found stuck & inoperable.

 Caused by stuck Robert Shaw Model BL-305-EI-X switch float.

 Buitch backFlushed.

 * Tennessee Valley Authority. 80/12/12. 3pp. 07264:135.
- 8012170642 Forwards LER 80-050/03L-0.
 OREEN.H. J. Tennessee Vailey Authority. 80/12/12. 1p. 07264: 332.
- ---8012170447 LER 80-050/03L-0: on HOI119, intermediate range monitors B, D & H did not respond during initial startup, creating less than allowable number of operable instrument channels in trip sys B. Caused by open time wire RO il4 a/v cables. Cables repaired # Tennessee Valley Authority. B0/12/12. 2pp. 07264: 333.
- 8012220455 Forwards LER 80-051/03L-0. OREEN/H. J. Tennessee Vailey Authority, 80/12/12, 1p. 07308: 336.
- --B012220460 LER 80-051/03L-0: on 801121, reactor water level switch 2-LIB-3-58C switch 4 found inoperable at proper setpoint. Caused by dirty switch contacts. Contacts cleaned & checked at proper setpoint.

 * Tennessee Valley Authority, 80/12/12, 2pp. 07308:337.
- 8012300514 Forwards LER 80-054/03L-0. OREEN.H. J. Tennessee Valley Authority. 80/12/23. 1p. 07360:340.
- --8012300520 LER 80-054/03L-0: on 801004 refuel interlocks switch 2 jammed in overtravel position rendering switch inoperable & allowing movement toward core in startup mode. Gaused by switch operating arm rotating 180 degrees.

 # Tennessee Vailey Authority. 80/12/22, 2pp. 07360:341.
- V. Operator Examinations
- 8012290237 Forwards response to clarification items in NRC 801031 ltr re post-THI requirements. Encl contains list of ECC8 outages for past 5 yes & training program requirements for shift technical advisors. MILLS.L.M. Tennesses Valley Authority. 80/12/23. 100pp.
- DOCKET 50-261 H. B. ROBINSON PLANT, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8012080750 Informs of interim 10CFR50.48 suspending completion dates for previously approved fire protection mode. Revised 10CFR50.48 will contain schedules for completion of all protection mode.

 EIGERHUT, D. G. Division of Licensing, 80/11/17. 5pp. 07196:161.
- 8012080835 Notification of 801121 meeting w/util in Bethesda, MD to discuss util posttion on central emergency response ctr & plans for emergency mgt.

 STAHLE.C. Licensing Branch 2. 80/11/19. App. 07175:331.

- 8012090189 Forwards draft final rept, "Penetration Seals," by Southwest Inst. Evaluation indicates problem may exist. After final rept is received & results analysed outil will forward plan w/corrective action. UTLEY.E.E. Carolina Power & Light Co. 80/12/05. 1p. 07246:181.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PMRs & describes program NRC is undertaking to review capability of operating PMRs to remove decay heat following earthquake.

 EISENHUT.D.O. Division of Licensing. 80/10/21. 4pp.
- BO12160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Enci 1 implementation dates will be net. ELSENHUT.D.G. Division of Licensing. BO/10/31. 7pp.
- 8012220563 Ltr to all power reactor licensess forwarding NUREG-O619, "BUR Fredwater Nozzle & Control Rod Drive Return Lina Nazzle Gracking." Confirmation that implementation dates will be met must be sent within 45 days. H/O encl. EISERMUT.D.Q. Division of Licensing. 80/11/13. 19.
- 8012020643 Forwards BHR owners group design & operational criteria for scram discharge sys.Criteria viewed as being responsive to requirement of providing assurance of reliable & safe operation of sys.

 MATERS.D. 8. Carolina Power & Light Co. BO/11/24. 4pp. 07148:013.
- 8012170694 Notifies that util 791107 response re inadvertent safety injection during surveillance testing resolves item for facility. VAROA.5. A. Operating Reactors Branch 2. 80/11/26. 2pp. 07269:207.
- 8012030679 Forwards proposed change to Tech Specs, requesting mod of spent fuel pool for increased spent fuel storage & spent fuel storage supansion rept. describing mods & supporting safety analyses. Class 4 amend fee encl. UTLEY.E.E. Carolina Power & Light Co. 80/12/01. 2pp. 07151:280.
- --B0120306B1 Proposed Tech Specs 5.4 for spent fuel storage.

 yantee Atomic Electric Co. 80/12/01. 2pp. 07151:282.
- --B012030684 "HB Robinson Unit 2 Spent Fuel Storage Expansion Rept," supporting proposed Tech Specs changes.

 > Yantee Atomic Electric Co. 80/12/01. 65pp. 07151:284.
- 8012050275 Application for amend of License DPR-23.changing Tech Specs 3.16 & 4.17 re dedicated shutdown sys. UTLEY.E. E. Carolina Power & Light Co. B0/12/02. 2pp. 07171:203.
- --B012050278 Proposed changes to Tech Specs 3.16 & 4.17 re dedicated shutdown sys.

 Carolina Power & Light Co. 80/12/02. 6pp. 07171:205.
- 8012080479 Requests revision to Tech Specs reflecting changes & additions to plant as result of NRC required fire protection sys mods.Proposed revisions encl.
 UTLEY.E.E. Carolina Power & Light Co. 80/12/03. 2pp. 07194:345.
- --80i2080482 Proposed revisions to Tech Specs reflecting changes & additions to glant as result of NRC required fire protection sys mods.

 * Carolina Power & Light Co. 80/12/03. 13pp. 07i94:347.
- R012070405 Application to amend License DPR-23 Requests Tech Spec change re operability requirements for heat tracing channels. UTLEY.E.E. Garolina Power & Light Co. B0/12/03. 2pp. 07207: 133.
- --8012070409 Proposed revision to Tech Spec Page 3.3-4 re operability requirements for heat tracing channels.

 * Carolina Power & Light Co. 80/12/03. 1p. 07207:135.
- 8012100450 Forwards revised Page ii correcting error on proposed Tech Specs submitted as license amend for radiological affluent on B01110. UTLEY,E.E. Carolina Fower & Light Co. 80/12/03 2pp. 07219:030.
- 012100195 Informs NRC that util will attempt to meet 820630 deadline re qualification of safety-related electrical equipment, in response to NRC 801024 orders.
 UTLEY.E.E. Carolina Power & Light Co. 80/12/04. 2pp. 07218:309.

- B0122204B5 Responds to B00911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of naed to comply w/revised Agreement State burial site conditions. Forwards results of IF survey.

 DENTON-H.R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --B012220505 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. B0/11/06. App.
- 8012160464 Advises of delay in complation date of seismic & environ qualification of installed safety valve position indication sys. Planned environ qualification now scheduled for completion in third quarter of 1981.

 UTLEY, E. E. Carolina Power & Light Co. 80/12/10. 2pp. 07263:131.
- BO12190402 Forwards Amend B3 to License DPR-23, safety evaluation & notice of issuance & availability. VARGA.S.A. Operating Reactors Branch 1. 80/12/10. 2pp. 07284:214.
- --8012190408 Amend 53 to License DPR-23.increasing mini low-low generator water level reactor trip point from 5% to 14% of nerrow range instrument scale. VAR9A.S.A. Operating Reactors Branch 1, 80/12/10. 4pp. 07286:216
- --8012170411 Safety evaluation supporting Amend 53 to License DPR-23.

 * Office of Nuclear Reactor Regulation, Director. 80/12/10. 2pp.
 07286:221.
- --8012190412 Notice of issuance & availability of Amend 53 to License DPR-23. VAROALS A. Operating Reactors Branch 1. 80/12/10. 2pp. 07285: 223.
- B012220472 Forwards commitments for completion of items contained in NUREO 0737, "Clarification of TMI Action Plan Requirements." UTLEY.E.E. Carolina Power & Light Co. 80/12/15. 24pp. 07304:112.
- 8012300671 Forwards util responses to NRC 800301 questions entitled, "Clarification of 790927 Ltr to Licensees re Demonstration of Operability of Purge & Vent Valves" & Allis-Chalmers test rept which provides supporting info to responses. UTLEY.E. E. Caroline Power & Light Co. 80/12/24: 26pp. 07359:245.
- G. Inspection reports, IE Bulletins & correspondence
- 8012090201 Forwards IE Insp Repts 50-325/80-39,50-324/80-36 & 30-261/80-27 on 800904.No noncompliance noted. STORM.J.P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/10/21. 2pp. 07202:264.
- --8012090210 IE Insp Rept 50-325/80-39, 50-324/80-36 & 50-261/80-27 on 800904. No noncompliance noted, Major areas inspected: circumstances surrounding erroneously recorded personnel exposures. NRAY, J. R., GIBSON, A. F. Region 2, Atlanta, Office of the Director. 80/10/21. 5pp. 07202:266.
- 8012090222 Forwards IE Insp Rept 50-261/80-25 on 800922-26.No noncompliance noted. LEMIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/10/21, 2pp. 07202:290.
- --8012090228 IE lnsp Rept 50-261/80-25 on 800922-26. No noncompliance noted Major areas inspected: corrective action on previous deviations. GA program annual review & personnel qualification program.

 BELISLE.O.A. Region 2. Atlanta. Office of the Director. UPRIGHT.C.M. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/10/15. 5pp. 07202: 292.
- B012150190 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24.

 1p. 07240:287.
- 8012180027 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required, 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/30. ip. 03790:104.

- 8012170785 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Vaives Mfg by Valcor Engineering Corp." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/10/31.

 1p. 07264:122.
- B012230045 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
 1p. 07311:244.
- 8012110767 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Maicolm Foundry Co. Inc." Written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/06.

 1p. 07225:191:
- 8012030887 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization "No written response required. O'REILLY, J. P. Region 2: Atlanta. Office of the Director. 80/11/07. 1p. 07150:147.
- 8012080316 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Bys at Davis Besse Unit 1." No response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/10. 1p. 0/182:294.
- B012180032 Forwards IE Insp Rept 50-261/80-29 on B01014-17, No noncompliance noted.

 LEWIS.R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. B0/11/10. 2pp. 03791:167.
- --B012180039 IE Insp Rept 50-261/80-29 on 801014-17. No noncompliance noted Major areas inspected: IE bulletins & reactor operations.

 HARDIN, A. K. Region 2, Atlanta, Office of the Director.

 KELL000, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/11/10. App. 03791: 169.
- 8012040187 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. C'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/14. lp. 07158:071.
- 801204046B forwards IE Bulletin BO-24, "Prevention of Damage Due to Water Leakage Inside Containment." Britten response required Requests info on manpower expended. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/21. 1p. 07163:394.
- 8012180079 Ack receipt of 801030 ltr responding to IE Bullatin 79-018, Suppl 2, "Environ Qualification of Class IE Equipment." MURPHY.C.E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 80/11/21. ip. 07240:351.
- B012310239 Forwards IE Insp Rept 50-261/80-32 on 801020-24.No noncompliance noted. LEWIS.R.G. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. B0/11/21. 2pp. 07370:045.
- ---B012310242 IE Insp Rept 50-261/80-32 on 801020-24. No noncompliance noted. Major areas inspected: restart.criticality & zero-power physics tests.

 BURNETI, P. T. Region 2. Atlanta, Office of the Director.

 OUICK, D. R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. B0/11/21. 6pp. 07370:047.
- 8012050621 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snybber Fluid." No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24. lp. 07174: 111.
- B012110127 Ack receipt of 801119 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/80-26. MURPHY.C.E. Region 2, Atlanta Reactor Construction & Engineering Support Branch, 80/11/25. ip. 07223:327.
- --8012110133 Responds to NRC 801027 ltr re violations noted in IE Insp. Rept 50-261/80-26. Corrective actions: permits describing locations were posted & personnel required to review const procedures.

 STARKEY, R. B. Carolina Power & Light Co. 80/11/19. 5pp.
- --B012110137 Forwards IE Insp Rept 50-261/80-26 on 800929-1002 & notice of violation.
 MURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch. B0/10/27 2pp. 07223:335.

- --8012110141 Notice of violation from insp on 800929-1002.

 * Region 2, Atlanta, Office of the Director. 90/10/24. 2pp. 07223:337.
- --8012110144 IE Insp Rept 50-261/80-26 on 800929-1002. Noncompliance noted: inadequate storage of fire protection equipment & components & failure to follow fire prevention welding procedures.

 KILLER.H. H. Region 2, Atlanta, Office of the Director, CONLOH, T. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/24. 7pp. 07223.339.
- B012170496 Forwards 1E Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Fiange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/11/26, ip. 07268:078.
- 8012180165 Ack receipt of 801112 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/80-24.

 MURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch. 60/11/26. 1p. 03791:033.
- --B0121B01B3 Responds to NRC B01016 itr re violations noted in IE Insp Rept 30-261/B0-24. Corrective actions: addendum to procedure issued to provide criteria for dimensional tolerances re pipe & support clearances. STARKEY. R. B. Carolina Power & Light Co. B0/11/12. 2pp. 03791: 334,
- --8012180185 Forwards IE Insp Rept 50-261/80-24 on 800908-11 & notice of violation.

 HURPHY, C. E. Region 2, Atlanta, Office of the Director. 80/10/16.

 2pp. 03791:336.
- --8012180187 Notice of violation from insp on 800908-11.
 4 Region 2, Atlanta, Office of the Director. 80/10/10. ip. 03791:338.
- ---8012180154 IE Insp Rept 30-261/80-24 on BC0908-11. Noncompliance noted: procedure for pipe stress review & analysis had no ref of acceptance criteria on dimensional tolerances for safety-related supports.
 KODE/ROS, L. Region 2, Atlanta, Office of the Director. HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. B0/10/10. 4pp. 03791;339.
- 801205033B Confirms commitments re-steam generator insp-program. Objects to proposal that operation should not be resumed until eddy current examinations have been found acceptable by NRC.
 UTLEY.E.E. Carolina Power & Light Co. 80/12/02. 3pp. 07175:060.
- 8012160242 Forwards IE Insp Rept 50-261/80-34 on 801027-30. No noncompliance moted. KENNA: W. B. Region 2: Atlanta: Safeguards Branch. 80/12/03. ip. 07232:236.
- --8012160236 IE Insp Rept 50-261/80-34 on 801027-30. No noncompliance noted Major areas inspected security organization & protected & vital area barriers. Details withheld (ref 10CFR2. 790).
 HOMELL, J. C., MCOUIRE, D. R. Region 2, Atlanta, Office of the Director, 80/12/02. 1p. 07252:237.
- B012310194 Submits supplemental response to IE Bulletin 80-18. "Maint of Adequate Min Flow Thru Centritugal Charging Pumps Following Secondary Side High Energy Line Rupture." Required testing will be completed by 801219. FURR.B.J. Carolina Power & Light Co. 80/12/04. 2pp. 07369:170.
- B012310396 Responds to IE Bulletin 80-21. "Valve Yokes Bupplied by Malcolm Foundry Co.inc." No active safety-related valves at facility have yokes mfg by Kalcolm Foundry Co.inc. FURR.B. J. Carolina Power & Light Co. B0/12/08. 1p. 07369: 223.
- B012310404 Responds to 1E Bulletin B0-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." No solenoid valves or valve parts mfg by Valcor Engineering Corp are in use at facility. FURR, B. J. Carolina Power & Light Co. B0/12/08. 1p. 07369: 224.
- R. Periodic operating reports k related correspondence
- 8012160434 Forwards monthly operating rept for Nov 1980. STARKEY.R. B. Carolina Power & Light Co. 80/12/09. 1p. 07254:168.
- --8912160438 Monthly operating rept for Nov 1980. NATFORD, M. L. Carolina Power & Light Co. 80/12/01, 3pp. 07254: 169.

- S. Reportable occurrences, LERs & related correspondence
- 8012050422 Forwards revised LER 80-024/017-1. STARKEY.P.B. Carolina Power ა Light Co. 80/12/02. ip. 07173:302.
- --B012050429 Revised LER 80-024/017-1: on 801014, containment personnel airlocks opened simultaneously on two occasions. Caused by removing interlocks from swc for maint. Vendor inspected airlocks & recommended improvements.
 STARKEY, R. B. Carolina Power & Light Co. 80/12/02. 2pp. 07173: 303.
- 8012090457 Forwards LER 80-027/01T-0. STARKEY R.B. Carolina Power & Light Co. 80/12/05. 1p. 07203:057.
- --B012090462 LER 80-027/01T-0 on 801122 reactor protection relay RT-9 in reactor protection train A failed Caused by de-energized relay coil resulting in continuous reactor trip signal Relay replaced.
 STARKEY, R B. Carolina Power & Light Co. 80/12/05. 2pp. 07203:058.
- 8012150222 Forwards LER 80-028/017-0. STARKEY, R. B. Carolina Power 2 Light Co. 80/12/11. ip. 07240:128.
- --8012150229 LER 80-028/017-0:en 801127 primary sys leak was discovered. Caused by failure of carbon steel packing gland stude from boric acid corrossion due to erroneous installation of carbon steel stude to replace stainless steel stude. STARKEY.R.B. Carolina Power & Light Co. 80/12/11. 3pp. 07240:129.
- 8012300411 Forwards LER 80-029/017-0. STARKEY.R.B. Carolina Power & Light Co. 80/12/24. ip. 07359:354.
- --8012300415 LER 80-029/017-0: on B01212, leat calculated to be between 8 to 16 gpm developed in RHR pump suction isolation valve RHR-750. Caused by normal wear. Leak stopped & repair made. STARKEY, R. B. Carolina Power & Light Co. B0/12/24. 2pp. 07389: 35%.
- DOCKET 50-263 MONTICELLO MUCLEAR GENERATING FLANT
 F. Security, medical, emergency & fire protection plans
- 8012020063 Discusses planned mods to emergency notification sys & health physics network.iRC will pay for installation of output packs to provide capability for adding one-way speakers to sys.W/o encl health physics network manual. KEPPLER.J.G. Region 3. Chicago, Office of the Director. 80/11/19. ip. 07148:343.
- 8012120437 Forwards NRC comments on emergency plan submitted by 800821 lts. Add1 info & commitments required before NRC can approve. Onsite emergency preparedness program. Plan should be revised to address comments per revised 10CFR50. 1PPOLITO.T. A. Operating Reactors Branch 2. 80/11/19. 17pp. 0727:257.
- 8012010351 Ack reciept of NRC 801119 ltr commenting an upgraded emergency plan. Implementing procedures will be forwarded by 810301. State & local govt radiological emergency response plans will be forwarded by 810102 MAYER.L.D. Northern States Power Co. 80/11/25, 1p. 07098:043.
- 8052080353 Releases public version of "Evacuation Time Estimates from Areas Near Monticella Nuclear Generating Plant." FELTON J. H. Division of Rules and Records. 80/12/01. 1p. 06586:003.
- --8012080360 Forwards public version.Revision 1 to "Evacuation Time Estimates from Areas Near Menticello Nuclear Generating Plant." MAYER.L.D. Northern States Power Co. 80/08/25. ip. 06586:003.
- --8012080364 Revision 1 to "Evacuation Time Estimates from Areas Near Honticello Nuclear Generating Plant." • Northern States Power Co. 80/03/31, 18pp. 06586:003.
- G. Adjudicatory correspondence
- 8012290129 Requests preparation of appropriate documents & required findings re ASLAB B01124 memorandum & order converting provisional OL to full-term OL. SHAPARH.X. Office of the Executive Legal Director. 80/12/02. 2pp. 07308:001.

- P. Operating license stage documents & correspondence
- B012160090 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREG-0737 re TM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISERHUT, D. G. Division of Licensing. B0/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads. EISERWAY. D. G. Division of Licensing. 80/11/04. App.
- B012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BWR Feedwater Nozzle 2 Control Rod Drive Return Line Nozzle Cracking," Confirmation that implementation dates will be met must be sent within 45 days N/o encl. EISENNUT, D. O. Division of Licensing, BO/11/13, 1p.
- BO12220485 Responds to BOG911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. BO/12/04. 2pp.
- --Bol2220505 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/7% planning or considering increasing storage capacity.

 BANOARY,R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012230278 Submits licensing fee determination re 801212 request to amend License DPR-22.authorizing TMI Lessons Learned Category A Tech Spec changes.

 * Northern States Power Co. 80/12/12. 1p. 07314:069.
- 8012230285 Forwards application for amend of License DPR-22.
 MAYER.L.O. Northern States Power Co. 80/12/12. 1p. 07314:072.
- --B012230287 Application for amend of License DPR-22 authorizing changes in Tech Spec App A re sys integrity measurement program; reactor water level instrumentation to safety relief valve position indication.

 MAYER.L. O. Northern States Power Co. 80/12/12., 3pp. 07314:073.
- --B012230289 Revised Tech Specs for TMI Lessons Learned Category A re fire detection & protection systection monitoring instrumentation design features & administrative controls, Northern States Power Co. 80/12/12. 15pp. 07314:076.
- 8012303246 Forwards license amend Class 3 fee for amend re change in mai average planar linear heat generation rate for Cycle 8.

 Northern States Power Co. 80/12/22. 1p. 07362:303.
- 8012300598 Forwards request to amend License DPR-22 & supporting documentation.

 MAYER.L. D. Northern States Power Co. 80/12/22. ip. 07346:195.
- --B012300605 Request to amend License DPR-22 to extend table of max average planar linear heat-generation rate limits for one fuel type to cover exposures during Cycle B. MAYER.L.O. Northern States Power Co. B0/12/22. 1p. 07346:196.
- --8012300611 Proposed revision to Tech Spor Page 187E, extending table of mac average planar linear heat-generation rate limits for one fuel type to cover exposures during Cycle B.

 **Northern States Power Co. 80/12/22. 4pp. 07346:197.
- --8012300613 Addenda 1 to NEDD-24050. "LOCA Analysis Rept for Monticelle Nuclear Generating Plant." * General Electric Co. NEDD-24050 ADD 1. 80/10/31. 4pp. 07346:199.
- Q. Inspection reports, IE Bulletins & correspondence
- 80:2170544 Forwards IE Info Notice BD-37: "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEMPLER. J. G. Region 3. Chicago, Office of the Director. BD/10/24.

 1p. 07864:192.
- B012020767 Forwards IE Insp Rept 50-263/80-18 on B00902-30.No noncompliance noted. HEISH::N.R.F. Region 3, Chicago, Reactor Operations Nuclear Bupport Branch. 80/10/30. 2pp. 07145:284.

- --8012020793 IE Insp Rept 50-263/80-18 on 800902-30. No noncompliance noted Major areas inspected routine operations, logs & records bulletins, circulars, LERs, housekeeping & radiation protection. BROWN, C. H., MADIBON, A. L., LITTLE, K. S. Region 3, Chicago, Office of the Director. B0/10/29, Spp. 07145:286.
- B012040633 Forwards IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. B0/11/2 red. CR.J.G. Region 3. Chicago. Office of the Director. 80/11/21. 07145:330.
- 8012080070 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No Written response required. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 80/11/24. 2pp. 07182: 223.
- B012180910 Responds to IE Bulletin 80-23 re Valcor solonoid valves in safety-related functions. No valves used. QILBERTS, D. E. Northern States Power Co. 80/11/25. ip. 03791: 165.
- 8012190270 Forwards new security badge numbers & clearance levels for Region 3 personnel. Changes should be entered on Sept 1980 access lists. KEPPLER.J. O. Region 3, Chicago, Office of the Director. B0/11/25, 6pp. 07286:020.
- 8012170531 Forwards 1E Info Notice 80-29, Suppl 1, "Broken Btuds on Terry Turbins Steam Inlet Flange." No written response required. KEPPLER.J.O. Region 3, Chicego, Office of the Director. 80/11/26. 2pp. 07268:132.
- 8012220182 Responds to Item i of 1E Builetin 60-21, "Valve Yokes Bupplied by Malcolm Foundry Co.inc." No active valves are used at facility. OLLBERTS.D.E. Northern States Power Co. 80/12/05. 1p. 07303:242.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-01B re environ qualification of Class IE equipment. HAYES,D.W. Region 3, Chicago. Reactor Construction & Engineering Support Branch. 80/12/09. 2pp.
- R. Periodic operating reports & related correspondence
- 8012150049 Ferwards monthly operating rept for Nov 1980. MAYER, L. O. Northern States Power Co. 80/12/11. 1p. 07237:246.
- --8012150051 Monthly operating rept for Nov 1980. KYRABO, A.L. Northern States Power Co. 80/12/11. 4pp. 07237:247.
- S. Reportable occurrences, LERs & related correspondence
- 8012020476 Supple 801112 ltr re failure of recirculation pump discharge bypass valve motor. Event not reportable. Motor failure could not have resulted in reduced LPCI flow.
 SHAMLArM. A. Northern States Power Co. 80/11/24. jp. 07143:337.
- DOCKET 50-265 QUAD-CITIES STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8012040019 Forwards interim 10CFR50.48 suspending completion dates for fire protection mods.effective upon 801029 publication in 45FR71369, Rule will be superseded by revised rule when effective. EISEKHUT.D.O. Division of Licensing. 80/11/07. 5pp. 07152:083.
- 8012020167 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers.N/O encl health physics network manual.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/19.
- B012120576 Resubmits security plan revisions, in response to NRC B00910 & 1119 ltrs.Plan withheld from public disclosure (ref 10CFR2.790).W/o encl.
 ABEL,J.B. Commonwealth Edison Co. B0/12/08. 1p.

- G. Adjudicatory correspondence
- B012170569 Forwards Director's decision under 100FR2.205 & FR notice decying 801024 petition to shut down facilities, pending installation of required scram discharge vol monitoring equipment. DENTOW.H.R. Office of Nuclear Reactor Regulation, Director. 80/11/26. lp.
- --B01217067B Director's decision under 100FR2,206, denying Pollution & Environ Problems, Inc. 801024 petition to shut down factitities, pending installation of required scram discharge vol monitoring equipment.
 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director. 80/11/26. 7pp.
- --8012170693 Notice of issuance of Director's decision under 10CFR2.206, denying Pollution & Environ Problems 801024 petition CASE.E.G. Office of Nuclear Reactor Regulation, Director. 80/11/26. 2pp.
- 8012170410 Requests refusal of util application to transfer spent nuclear fuel rods from Dresden units to Quad City units for storage. NRC should hold public hearings.

 * Citizens for Safe Energy. 80/12/11. 2pp.
- H. General correspondence
- 8012290396 Requests that cracked core spray injection piping be packaged & sent to EG&O idaho. Inc.
 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/12/05.
 2pp. 07346:350.
- P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Enci 1 implementation dates will be met. EISENHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012270358 Ltr to all CP & OL holders for BHRs re requirement for implementation of DDYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends including core reloads.

 EISERHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012010433 Forwards evaluation of NEDO-24257, "Generic Info for Barrier Fuel Demonstration Bundle Licensing," including addlinfo transmitted in 800911 ltr.Rept serves as acceptable ref providing generic description of program.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/12. 2pp. 07098:236.
- --B0120104B9 Topical rept evaluation of NEDD-24259. "Generic Info for Barrier Fuel Demonstration Bundle Licensing." Rept acceptable. Core Performance Branch. 80/10/31. App. 07078:238.
- B012080089 Forwards Amends 50.59 & 54 to Licenses DPR-19.DPR-29 & DPR-30, respectively, safety evaluation & notice of issuance & availability.

 IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/12. 2pp. 07180:352.
- --8012080075 Amends 50,59 & 54 to Licenses DPR-19, DPR-27 & DPR-30, respectively, establishing max average planar linear heat generation rate limits for std 8X8 fuel types for exposure valves. IPPOLITO,T.A. Operating Reactors Branch 2. 80/11/12. 23pp. 07180:354.
- --8012080102 Safety evaluation supporting Amends 50,59 & 54 to Licenses DPR-19, DPR-29 & DPR-30 respectively.

 ** Office of Nuclear Reactor Regulation, Director. 80/11/12. 4pp. 07181:016.
- --8012080196 Notice of issuance & availability of Amends 50,59 & 54 to Licenses DPR-19,DPR-29 & DPR-30.respectively. iPPOLITO.T.A. Operating Reactors Branch 2. 80/11/12. 2pp. 07181:020.
- B01220863 Ltr to all power reactor licensees forwarding NUREQ-0619, "BWR Feedwater North & Control Rod Drive Return Line North Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o enci. EISERMUT, D.O. Division of Licensing. B0/11/13. 1p.

DOCKETED ITEMS

- 8012180620 Forwards Amends 32.51 & 45 to Licenses DFR-2, DFR-19 & DFR-25, respectively, Amends 60 & 55 to Licenses DFR-29 & DFR-30, respectively & Amends 58 & 55 to Licenses DFR-37 & DFR-48, respectively & Amends 58 & 55 to Licenses DFR-37 & CRUTCYFIELD, D. Operating Reactors Branch 5. 80/11/17. 3pg.
- --8012180640 Amends 60 & 55 to Licenses EPR-29 & DPR-30, respectively, requiring implementation of safeguards contingency plan. IPPOLITO, T. A. Operating Reactors Branch 2. 80/11/17. 4pp. 07271:335.
- B012020301 Forwards tabulation of planned environ qualification testing programs in response to NRC 801001 ltr.
 ABEL.J.S. Commonwealth Edison Co. 80/11/26. 4pp.
- B012160479 Forwards listing of changes tests & experiments completed during Nov 1980. Summary of safety evaluation encl. ALIVIANKIS.N Commonwealth Edison Co. 80/12/01. 4pp. 07263:110.
- 8012190657 Forwards request for add1 info re 800822 rept entitled. "Evaluation of 18 Inch Containment Isolation Valves for Brasden 2 & 3 & Guad Cities 1 & 2."
 LAINAS.O.C. Assistant Director for Safety Assessment. 80/12/02.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220505 Forwards tabulation & summary of IE survey on low level waste at Si reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANOART, R. L. Effluent Treatment Systems Branch. B0/11/06. Bpp.
- B012120301 Forwards Tech Specs Page 3 2/4.2-15, inadvertently omitted from util B00918 ltr to NRC.

 JANECEK, R. F. Commonwealth Edison Co. 80/12/10. 2pp.
- --8012120341 Proposed Tech Specs.Page 3.2/4.2-15, incorporating TMI Lessons Learned Requirements. * Commonwealth Edison Co. 80/12/10. ip.
- 8012160136 Responds to NRC 800924 request re mods for provision of redundant Class IE protection at interface of Nonclass IE power supply & reactor protection sys. Installation scheduled for refueling outages occurring after June 1981.

 JANECEK, R. F. Commonwealth Edison Co. 80/12/11. 2pp.
- 8012170488 Forwards response to NRC 801031 ltr requesting confirmation that implementation dates indicated in NUREG-0737 will be met. Ability to meet required dates for major mods is contingent upon hardware availability & delivery.

 ABELLJ. B. Commonwealth Edison Co. 89/12/15. 37pp.
- B012240158 Forwards confirmation that implementation dates per NUREG-0737 will be met & justification for exceptions. Generally, dates are contingent upon hardware availability & delivery. Comments on safety requirements in Tech Specs. ABEL. J. S. Commonwealth Edison Co. 80/12/15. 37pp.
- G. Inspection reports, TE Bulletins & correspondence
- 80:2170510 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/24.

 1p.
- 8012180151 Forwards IE Insp Repts 50-254/80-22 & 50-265/80-24 on 800901-1017 & notice of violation, HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Eupport Branch. 80/11/06. 2pp. 03791:271.
- --8012180153 Notice of violation from insp on 800701-1017.

 4 Region 3, Chicago, Office of the Director. 80/10/31. 1p. 03771: 273.

- ---B0121B0157 IE Insp Repts 50-254/80-22 & 50-265/80-24 on B0090i-1017. Noncompilance noted: charging water isolation valves not closed as required. Fuel assembly removed w/source range monitor indicating less than 3 counts per second. CHRISSOTINGS.N., DUPONT.B.O., SPESSARD.R.L. Region 3, Chicago, Office of the Director. 80/10/31. 11pp. 03791:274.
- B012020/43 Forwards three Performance Appraisal Branch inspirepts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. W/o encl.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/18.
- 8012040647 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/21.
- 8012080087 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER, J. G. Region G. Chicago, Office of the Director, 80/11/24. 2pp.
- 8012120415 Ack receipt of 801105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-19 & 50-265/80-21. HEIBHMAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 80/11/24. 1p. 07236:017.
- --8012120425 Responds to NRC 801015 ltr re violations noted in IE Insp Repts 50-254/80-19 & 50-265/80-21. Corrective actions: reactor core isolation cooling controller returned to normal operating configuration & investigation conducted. ABEL. J. S. Commonwealth Edison Co. 80/11/06. 2pp. 07296: 019.
- B012170408 Forwards monthly status rept of evaluations performed in response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." No sys identified wystress exceeding 1/2 matl ultimate stress at OBE loadings. JANECEK, R. F. Commonwealth Edison Co. 80/11/24, 14pp.
- B012230223 Forwards new security badge numbers & clearance levels for Region 3 personnel Changes should be entered on Bept 1980, access lists.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/25.
- 8012100661 Ack receipt of 800919 response to NRC 800818 ltr requesting add1 info re IE Bulletin 79-14 evaluations Dresden & Guad Cities responses to Items 1 & 3 unacceptable, since requested info was not included.

 KEPPLER, J. O. Region 3. Chicago, Office of the Director. 80/11/26. 3pp.
- 8012170552 Forwards IE Info Notice 80-29, Suppl i, "Broken Studs on Terry Turbino Steam Inlet Flange." No written response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/11/26.
- 8012070044 Notification of 801207 meeting w/util in Bethesda.MD to discuss acceptance criteria used for evaluation of piping sys under review for IE Bulletin 79-14.

 MDNO.H.J. Office of Inspection & Enforcement, Office of the Director. 80/12/04. 2pp.
- B012230065 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcola Foundry Co.Inc." No valve parts cast by Malcolm Foundry planned for use or in use at facilities. RAUSCH.T.J. Communwealth Edison Co. 80/12/05. 2pp.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-01B re environ qualification of Class IE equipment. HAYES.D.W. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 80/12/09. 2pp. 07282:108.
- R. Periodic operating reports & related correspondence
- B012170446 Forwards monthly operating repts for Nov 1980.

 KALIVIANAXIS.N. Commonwealth Edison Co. B0/12/01. 1p. 07268:047.
- --8012170449 Konthly operating repts for Nov 1980. TUBBS, R. C. Commonwealth Edison Co. 80/12/01. 25pp. 07268: 048.

- S. Reportable occurrences, LERs & related correspondence
- 8012090407 Forwards LER 80-030/03L-0.
 KALIVIANAKIS,N. Commonwealth Edison Co. 80/11/20. ip. 07203:028.
- --8012090416 LER 80-030/03L-0: on 801031; primary containment valve A0-2-1601-63 required 30-s to close, Caused by malfunction of pilot solenoid 50-2-1601-71. Solenoid replaced & tested, HURRAY, R. Commonwealth Edison Co. 80/11/20. 2pp. 07203:029.
- 8012090446 Forwards LER 80-031/01T-0.
 KALIVIANAKIS,N. Commonwealth Edison Co. 80/11/24. 1g. 07203:047.
- --8012090452 LER 80-031/01T-0:on 801116, reactor core isolation cooling discharge isolation valve MD-2-1301-49 would not open from control room. Caused by faulty torque switch. Torque & limit switches cleaned, checked & exercised. MENDERHALL, E.E. Commonwealth Edison Co. 80/11/24, 2pp. 07203:048.
- B012090451 Forwards LER 80-032/01T-0.
 KALIVIANAKIS, N. Commonwealth Edison Co. 80/11/24. 1p. 07203:052.
- -8012070458 LER 80-032/017-0:on 801116.HPCI sys declared inoperable.
 Caused by oil leak on HPCI stop valve cover Cover replaced & tasted. TUBBS.R.C. Commonwealth Edison Co. 80/11/24. 2pp. 07203:053.
- 8012150250 Forwards updated LER 80-026/03L-1, KALIVIANAKIS:N. Commonwealth Edison Co. 80/11/25, 1p. 07240:117.
- ---8012150254 Updated LER 80-026/03L-1: on 801017, while performing manual operation of relief valves, relief valve 2-203-3C failed to open Gaused by excessive steam leak past retainer plus threads info vol below main disc. Valve replaced w/spare. HUNDERLICH J.R. Communwealth Edison Co. 80/11/25, 2pp. 07240:118.
- 8012300414 Forwards LER 80-034/017-0.
 KALIVIANAKISIN. Gommonwealth Edison Co. 80/12/15. ip. 07359:359.
- --8012300420 LER 80-034/0LT-0: on 801203, HPCI injection MO-2-2301-8 found inoperable Caused by shorted motor on valve operator. Motor replaced.
 TUBB8, R. C. Commonwealth Edison Co. 80/12/15, 2pp. 07359: 360.
- DDCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1
- F. Security, medical, emergency & fire protection plans
- B012090516 Forwards interim lOCFR50. 48, suspending completion date for previously approved effective fire protection mods, effective 801029, Role will be superseded by pending revision. EIBENHUT, D. O. Division of Licensing. 80/11/18. 5pp. 07207:011.
- 8012020122 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys. W/o encl health physics network manual. KEPPLER. J. O. Region 3, Chicago, Office of the Director. 80/11/19. 2pp. 07149:003.
- 8012050693 Forwards public version of draft revision of emergency plan. FELTON-J.M. Division of Rules and Records. 80/12/01, ip. 07172-029.
- --8012050642 Forwards public version of draft revision of emergency plan. FAY.C.W. Wisconsin Electric Power Co. 80/05/07. 1p. 07172:030.
- ~-8012030651 Public version of draft revision of emergency plan.

 → Wisconsin Electric Power Co. 80/05/31, 300pp. 07172;032.
- 8012090378 Informs that revision of 800725 draft emergency plan per NRC 800929 comments will be delayed until 801231. Objects to NRC direction to begin implementing partially approved plan. Schedules implementation for 810401 per NRC 801113 ltr. FAY.C.W. Wisconsin Electric Power Co. 80/12/01. ip. 07201:173.
- Q. Adjudicatory correspondence
- 8012310065 Forwards corrected Page 15.6.10-2 to Tech Spec changes transmitted w/801024 order for mod of license re environ qualification of safety-related electrical equipment. CLARK, R. A. Operating Reactors Branch 3. 80/12/04. 2pp. 07371:148.

- --B012310071 Corrected Tech Spec Page 15.6.10-2,adding footnote indicating that starred items re records will be permanently retained.

 # Operating Reactors Branch 3. 80/12/04. 2pp. 07371:150.
- 8012110399 Requests on behalf of util extension until 810108 for hearing on 801118 order for mod of license to allow more reasoned determination.

 SILPERO, J. E. Shaw, Pittman, Potts & Trowbridge. 80/12/05. 2pp.
- 8012270306 Notifies that Lakeshore Citizens for Safe Energy is being disbanded per 781208 agreement. BAST.S.A. Lakeshore Citizens for Safe Energy, 80/12/09. ip. 07308:001.
- P. Operating license stage documents & correspondence
- BO12020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PHRs & describes program NRC is undertaking to review capability of operating PURs to remove decay heat following earthquake.

 EISENHUT.D.G. Division of Licensing. 80/10/21. 4pp.
- 8012160350 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- B012010140 Trip rept of B01027-28 site visit to introduce plant mgt personnel to project manager. COLBURN, T.O. Operating Reactors Branch 3. B0/11/13. 4pp. O70972:128.
- 8012220363 Ltr to all power reactor licensees forwarding NUREG-0619, "BWR Feedwater Noille & Control Rod Drive Return Line Noille Gracking." Confirmation that implementation dates will be met must be sent within 45 days Wo encl. EISENHUT.D.Q. Division of Licensing. 80/11/13. 1p.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220806 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Lnw level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012310011 Forwards request for add1 info for Tech Spec change request re removal of rod bow penalty at facility. Util must describe margins used to offset reduction in DNDR due to fuel rod howing. CLARK.R.A. Operating Reactors Branch 3. 80/12/04. 3pp. 07371:091.
- 8012310065 Forwards corrected Page 15.6.10-2 to Tech Bpec changes transmitted w/801024 order for mod of license re environ qualification of safety-related electrical equipment.
 CLARK.R.A. Operating Reactors Branch 3. 80/12/04. 2pp. 07371:148.
- --B012310D71 Corrected Tech Spec Page 15.4.10-2.adding footnote indicating that starred items re records will be permanently retained.

 4 Operating Reactors Branch 3. 80/12/04. 2pp. 07371:150.
- 8012130077 Discusses lack of NRC action re comments submitted in 800504 ltr concerning consolidation of reporting requirements. Clarification & consolidation of all licensee reporting requirements urged. FAY.C.W. Wisconsin Electric Power Co. 80/12/08. 1p. 07239:358.
- 8012290131 Submits info re hydrostatic testing & insp of steam generator tubes, per 800805 & 22 ltrs. Review & concurrence requested by 801231.
 BURSTEIN 8. Wisconsin Electric Power Co. 80/12/18. 5pp. 07342:344.
- 8012300593 Advises of 801207-12 reinsp of low pressure turbine rotor discs for indications of keyway & bore cracks. Indications noted on two LP-1 rotor discs as found in Nov 1977 inap. Rept will be forwarded when received from Westinghouse. FAY.C.W. Wisconsin Electric Power Co. 80/12/22. 3pp. 07346:205. 07344: 205.

- 8012380404 Forwards response to NUREC-0737, "Clafification of TMI Action Plan Requirements." Implementation of desired mods will cause unavoidable matl & personnel shortages, which may result in delays in implementation schedules.

 FAY, C. W. Misconsin Electric Power Co. 80/12/23. 29pp. 07357:287.
- 8012300586 Submits info re postulated uncontrolled boron dilution at cold shutdown in response to NRC 800930 ltr. Boron dilution event for cold shutdown recalculated based on return to criticality 15 minutes after wave front reaches core inlet. FAY.C.W. Wisconsin Electric Power Co. 80/12/23. 5pp. 07346:210.
- Q. Inspection reports: 1E Bulletins & correspondence
- B012170624 Forwards IE Info Notice B0-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. B0/10/24. 1p. 07264:173.
- 8012220642 Forwards IE Health Physics Appraisal Repts 50-266/80-16 & 50-301/80-16, notice of violation & significant appraisal findings. KEPPLER.J. O. Region 3. Chicago. Office of the Director. 80/11/14. 3pp. 07307:001
- --B012220045 Notice of violation from health physics appraisal on B0070B-19. * Region 3. Chicago. Office of the Director. B0/11/10. ip. 07307:004.
- --8012220056 IE Health Physics Appraisal Repts 50-266/80-16 & 50-301/80-16. Noncompliance noted: two persons received excessive whole body radiation doses & raduaste shipped inproperly.

 MILLER, D. E., GESTMANN, M. J., MURPHY, D. W. Region 3, Chicago, Office of the Director. 80/11/10. 24pp. 07307:005.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. W/o encl. KEPPLER. J. O. Region 3. Chicago. Office of the Director. 80/11/18. Ann.
- 801231049B Forwards IE Insp Repts 50-266/60-19 & 50-301/80-19 on 801103-04. No nencompliance nated. HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/20. 2pp. 07365:229.
- --GO:2310500 IE Insp Repts 50-266/60-19 & 50-301/80-19 on 801103-04.No noncompliance noted. Major areas inspected: implementation of TMI task action plan Category A requirements.

 GULDEMOND. U. G., HAOVE. R. L., WARNICK. R. F. Region 3, Chicago, Office of the Director. 80/11/18. App. 07365:231.
- 8012040559 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Nater Leakage Inside Containment." No written response required. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 80/11/21. 2pp. 07166:339.
- 8012080030 Forwards IE Info Notice 80-42, "Effect of Rediation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J. 6. Region 3: Chicago. Office of the Director. 80/11/24. 2pp. 07182:243.
- 8012170522 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER. J. G. Region 3, Chicago, Office of the Director. 80/11/26. 2pp. 07268:116.
- 8012230069 Responds to IE Bulletin 80-23, "Failure of Solenuid Valves Mfg by Valcor Engineering Corp." No Valcor sciencid valves w/Parts V70900-21-1 or V70900-21-3 installed in safety-related applications. FAY, C. N. Wisconsin Electric Power Co. 80/12/02. 1p. 07311:083.
- 8012150278 Forwards IE Insp Repts 50-266/80-18 & 50-301/80-18 on 801027-31.No noncompliance noted. KEPPLER.J. C. Region 3. Chicago, Diffice of the Director. 80/12/04. 2pp. 07237:324.
- --8012150281 IE Insp Repts 50-266/80-18 & 50-301/80-18 on 801027-31. No noncompliance noted Major areas inspected security plan, access control & physical barriers. Details withheld (ref 10CFR2. 790).
 CREFO.J. A., KNICELEY, J. R. Region 3. Chicago, Diffice of the HIND, J. A. Region 3. Chicago, Safeguards Branch.
 2 2pp. 07237:326.

- B012240473 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Manufacturers contacted for verification phase of investigation.
 FAY, C. W. Wisconsin Electric Fower Co. B0/12/04. 2pp. 07323:055.
- 8012240409 Affirms util 801030 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." FAY.C.W. Wisconsin Electric Power Co. 80/12/05. 1p. 07324:309.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-018 re environ qualification of Class IE equipment.

 HAYES,D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp.
- B012290131 Submits info re hydrostatic testing & insp of steam generator tubes.per 800805 & 22 Itrs.Review & concurrence requested by 601231.
 BURSTERIN S. Wisconsin Electric Power Co. 80/12/18. 5pp. 07342:344.
- R. Periodic operating reports & related correspondence
- 8012160427 Forwards monthly operating rapts for Nov 1980.
 FAY, C. H. Wisconsin Electric Power Co. 80/12/11. 1p. 07254:145.
- --8012160428 Monthly operating rept for Nov 1980. FAY.C.W. Wisconsin Electric Power Co. 80/12/08. 10pp. 07259:146.
- S. Reportable occurrences, LERs & related correspondence
- 8012010354 Forwards LER 80-013/017-0. FAY, C. H. Misconsin Electric Power Co. 80/11/21. ip. 07091:274.
- --B012010372 LER B0-013/017-0: on B01113, suction to 1P4B boric acid transfer pump isolated, rendering pump inoperable. Probably caused by personnel error in returning valve lineup to normal following recirculation & sampling.

 FAY.C. W. Wisconsin Electric Power Co. B0/11/21. 3pp. 07091:275.
- DOCKE: 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION
 F. Security, medical, emergency & fire protection plans
- 8D120B0677 Confirms 8D1107 telcon re QA program effect on security programs. Util will rewrite Chapter 14 of amended security plan to provide for QA audit of security program every 12 months.

 SEYHRIT, K. V. Region 4, Dallas: Office of the Director. 80/11/13. 19. 0718B: 255.
- 8012110122 Notification of 801210 meeting w/util in Dethesda, MD to discuss status of emergency response plan & exemptions to NRC guidelines. NUZMYCZ. G. Blandardization & Special Projects Branch. 80/11/26. 3pp. 07223:106.
- O. Adjudicatory correspondence
- 8012040182 Ack receipt of 801020 ltr withdrawing previous request for hearing re NRC 800827 order. There are no pending requests for hearings re 800917 revised order. TEDESCO.R.L. Assistant Director for Licensing. 80/11/18. 2pp. 07138:087.
- P. Operating license stage documents & correspondence
- B012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISERHUT, D. G. Division of Licensing. B0/10/31. 7pp.
- 8012120152 Updates util 800731 itr re proposed instrument bus mods. Undervoltage alarm to 120 VAC Rominterruptible Bus 3 will be installed as soon as plant conditions allow. SMART.F.E. Public Bervice Co. of Colorado. 80/11/04. 2pp. 07240:008.
- 8D12220563 Ltr to all power reactor licensess forwarding NUREO-0619, "DWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. M/o encl. EIBERSHUT, D.O. Division of Licensing. 80/11/13. 1p.

- HO12030B26 Forwards Performance Appraisal Branch repts & mgt evaluation tree & user's guide. Info provided to ensure that licensees have opportunity to review strengths & weaknesses for program applicability. W/o encls.

 SEYFRIT.K. V. Region 4, Dallas, Office of the Director. 80/11/14.

 1p. 07149: 262.
- BO12270267 Discusses fees due per provisions of 10CFR170.List of applications encl. MAREMBOURG.D. Public Service Co. of Colorado. BO/11/21. 3pp. 07342:325.
- --8012270272 Requests processing & distribution of util 801121 ltr D1605.R. License Fee Management Branch. 80/12/24. lp. 07342:328.
- B012040404 Forwards QA-C15767, "Investigations of Fort 8t Vrain Cycle 2 Reactor Fluctuations Through 791026." SHART.F.E. Public Service Co. of Colorado. B0/12/02. 2pp. 07152:088.
- --B012040407 "Investigations of Fort St Vrain Cycle 2 Reactor Fluctvations Through 791026." HACKNEY.R., SAEGER.J. General Atomic Co. (subs. of Gulf Oil Co.), GA-C15747. B0/03/31. 400pp. 07152:090.
- 8012100414 Forwards "Fort St Vrain Initial Approach to Power Tests (8-Series)." Interim Rept 17 for 800823-1122.
 WAREMBOURD, Public Service Co. of Colorado. 80/12/04. 1p. 07200:186.
- --8012100445 "Fort St Vrain Initial Approach to Power Tests (B-Series),"
 Interim Rept 17 for 800823-1122.

 * Public Service Co. of Colorado. 80/12/04. 2pp. 07220:157.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreemant State burial site conditions. Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% or reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. Bpp.
- 8012190419 Advises that 801112 request for exemption from performance of surveillance test for steam pipe rupture is Class III amend fee. Table 5, 4-2 of SR 5, 4, 1 encl.
 WAREMBOURG, D. Public Service Co. of Colorado. 60/12/05. ip. 07273:278.
- --B012190422 Tech Spec Table 5.4-2. "Min Frequencies for Checks, Calibr & Testing of Loop Shutdown Sys."

 * Florida Power & Light Go. 74/05/17. 2pp. 07273:279.
- 8012230486 Requests addI extension until 810301 to submit application to change Tech Specs re electrical power sys. HAREMBOURG.D. Public Service Co. of Colorado. 80/12/05. 2pp. 07313:221.
- 8012160146 Advises that contents & requirements of NUREO-0619 are not applicable to facility.

 BHART.F.E. Public Service Co. of Colorado. 80/12/10. 1p. 07255:023.
- 8012240237 Bubmits revised installation schedule for primary coolant auxiliary sys loop split mod. Plant shutdown required for installation of loop split mod & licensee planning delay in completion of installation to coincide w/refueling shutdown. SMART.F.E. Public Service Co. of Colorado. 80/12/17. 1p. 07321:208.
- 8012300591 Informs of revised implementation dates for post-accident sampling capacity & onsite technical support ctr. Changes necessary due to delays in mati shipments from vendors.

 Lab & technical support ctr will be ready by 810301.

 BMARTIFLE. Public Bervice Co. of Colorado, 80/12/19. 2pp. 07346:208.
- 8012290231 Forwards response to applicable requirements of NUREO-0737 rs TMI action plan Progress of response impeded due to lack of guidance re applicability of requirements to gas cooled reactor.

 WAREMOUND, D. M. Public Service Co. of Colorado. 80/12/20. 69pp. 07338:258.

- G. Inspection reports: IE Bulletins & correspondence
- B012170312 Forwards Buppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required. BEYFRIT.K.V. Region 4, Dallas, Office of the Director, B0/10/24. In. 07269-333.
- 8U12160058 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/10/27.

 1p. 07262:159.
- 8012170417 Submits supplemental response to IE Dulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Audit phase of seismic review program for Class I piping & pipe supports is complete.
 SHART.F.E. Public Service Co. of Colorado. 80/10/28, 3pp. 07270:190.
- 8012170806 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.

 SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 80/10/31.

 1p. 07266: 105.
- 8012230028 Forwards IE Circular 80-23, "Potential Defects in Beloit Power 8ys Emergency Generators." No written response required. 8EYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/10/31. ip. 07311:208.
- 8012100623 Forwards IE Bulletin 80-21, "Valve Yotes Supplied by Malcolm Foundry Co.inc." Written response required. SEYFRIT.K.V. Region 4. Dailas, Office of the Director. 80/11/06. lp. 07220:088.
- 8012010417 Ack receipt of 800901 itr dtd in error informing NRC of steps taken to correct violation noted in IE Insp Rept 50-267/80-18.
 MADSEN.O.L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. 80/11/07. 1p. 07098:067.
- --8012010434 Responds to NRC 800709 ltr re violation noted in IE Insp Rept 30-267/80-18 Corrective actions trouble rept written to have defective recorder repaired. LEE.O.R. Public Service Co. of Colorado. 80/09/01. 1p. 07098:068.
- 8012170802 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Gause Reactor Depressurization No written response required. SEYFRII.X.V. Region 4, Dallas, Office of the Director. 80/11/07. ip. 07265:101.
- 8012080611 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 SEYFRIT'S.V.V. Region 4, Dailas, Office of the Director. 80/11/10.

 1p. 07183:020.
- 8012040027 Forwards IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. SEYFRIT.K. V. Region 4, Dallas, Office of the Director. 80/11/14. ip. 07169:306.
- 801211078D Forwards IE Insp Rept 50-267/80-22 on 801020-24.No noncompliance noted. KELLY.J.A.F. Region 4. Dallas. Office of the Director. 80/11/26. 2pp. 07285:098
- --8012110784 IE Insp Rept 50-267/80-22 on 801020-22. No noncompliance noted. Major areas inspected: security program & organization, protected area physical barriers & access control. Details withheld (ref 10CFR2. 790).

 GALDWELL.R.A., KELLYJ.A.F. Region 4, Dallas, Office of the Director. 80/11/25. 1p. 07225:100.
- 8012120130 Submits 180-day response to Item 2B of IE Bulletin 80-11, "Masonry Wall Design." Sixteen walls found in need of reinforcing, Completion is scheduled for 810201. SHART,F.E., Public Service Co. of Colorado. 80/10/28. 3pp. 07240:003.

R. Periodic operating reports & related correspondence

- 80i1250201 Forwards monthly operating rept for Oct 1980. WAREMBOURO.D. Public Service Co. of Colorado. 80/11/20. 1p. 07036:278.
- 8012100332 Forwards monthly operating rept for Nov 1980. WAREMEDURG, D. Public Service Co. of Colorado. 80/12/05. 2pp. 07217:345.
- --8012100337 Monthly operating rept for Nov 1980. QANS.J.V. Fublic Service Co. of Colorado. 80/12/01. Spp. 07217:347.

S. Reportable occurrences. LERs & related correspondence

- BO11250495 Forwards LER 80-067/01T-0. HAREHBOURG.D. Public Service Co. of Colorado. BO/11/20. Spp. 07068:276.
- --B011250501 LER B0-067/01T-0: on B01107.tritium concentration exceeded limit specified in LC04.B.24.B.26a). Caused by inadequate deviation 80-445 to surveillance procedure ER 5.B.26c-M. Procedure & design changes under investigation. GAHM.J.H. Public Service Co. of Colorado. B0/11/20. 1p. 07068:284.
- B012020554 Forwards LER 80-068/03L-0. WAREM30URG, D. Public Service Co. of Colorado. 80/11/25. 4pp. 07130:315.
- --B012020563 LER B0-06B/O3L-0:on B01105, during normal operation, 480 volt switchgear room smoke detectors were taken out of svc for approved mod to local alarm panel. Caused by disabling of 480 volt smoke detectors. Enoke detectors were returned to svc. OARM, J. W. Public Service Co. of Colorado. 80/11/25. ip. 07130:319.
- 801202056B Forwards LER 80-070/03L-0.

 WAREMBOURO.D. Public Service Co. of Colorado. 80/11/25. 3pp.
 07148: 230.
- --B012020575 LER 80-070/03L-0:on 801110.during normal operation, emergency fire water pump removed from svc to repack leaking pump gland. Pump repacked & returned to svc.

 OARM.J. W. Public Service Co. of Colorado. 80/11/25. ip.
 O7148: 233.
- B01203040B Forwards LER 80-D44/O3L-O. HAREMBDURG.D. Public Service Co. of Colorado. B0/11/26. 5pp. 07173.280.
- --B012050419 LER B0-064/03L-0: on B01103, diesel engine 18 on diesel generator 14 found to have inoperable exhaust temp trip circuit. Caused by faulty exhaust temp thermcouple. Thermcouple replaced. CANK, J. W. Public Service Co. of Colorado. 80/11/26. ip. 07173:285.
- 8012100485 Forwards LER 80-069/03L-0. WAREMBOURO, D. Public Service Co. of Colorado. 80/12/05. 5pp. 07218:092.
- --8012100491 LER 80-069/03L-0: on 801107, two circulator 1D high speed trip channels, one for steam turbine & one for water turbine, found to have trip points higher than max allowable. Caused by bistable instrument drift. Bistables adjusted.

 QARH.J. U. Public Service Co. of Colorado. 80/12/05. ip. 07218:097.
- 012100503 Forwards LER 80-071/03L-0.
 WAREMBOURD, D. Public Service Co. of Colorado. 80/12/05. 5pp.
 17218-103.
- 3012100509 LER 80-071/03L-0: on 801106, malfunction of helium circulator 18 speed modifier caused loss of plant protective sysfunction of high speed trips to one of three channels. Caused by resistance change in speed element cable assembly. QAHH.J. U. Public Service Co. of Colorado. 80/12/05. 1p. 07218:108
 - 'wards LER 80-064/03L-0.
 . Public Service Co. of Colorado. 80/12/05. 7pp.

- --8012190521 LER 80-066/03L-0: on sleven occasions during 801105-18, plant operated w/primary coolant oxidants greater than 10 ppm & average core outlet temp greater than 1,200 F. Caused by residual moisture & leakage past HV-21392.

 OAHM.J. H. Public Service Co. of Colorado. 80/12/05. 1p. 07218:116
- 8012100524 Forwards LER 80-065/03L-0.
 WAREMBOURO, D. Public Service Co. of Colorado. 80/12/05. 4pp.
- --8012100537 LER 80-065/03L-0; on 801105; five class 1 hydraulic snubbers removed from svc when reactor was not in shutdown phase. Caused by requirement to verify bleed rate zero, Snubbers tested & replaced.

 GAHHAU, W. Public Service Co. of Colorado. 80/12/05, 1p. 07218:128.
- 8012290435 Forwards LER 80-072/03L-0. WAREHBOURG, D. Public Service Co. of Colorado. 80/12/17. 5pp. 07334:272.
- --B012270442 LER BD-072/03L-0: on B01117, three helium circulator seal malfunction pressure differential switch units discovered to have trip point outside Tech Bpec limits. Caused by dirt accumulation in electrical switches. Switches readjusted. GAMM.J. W. Public Service Co. of Colorado. B0/12/17. ip. 07336: 277.
- 8012300562 Forwards LER 80-073/03L-0. WAREMBOURG.D. Public Service Co. of Colorado. 80/12/19. 4pp. 07362:295.
- --B012300567 LER 80-073/03L-0:on 801121, effluent discharge antifoam concentration exceeded Tech Spec limit for 3-h period. Caused by high blowdown flow rate. Procedure will be implemented to prevent recurrence.

 QAIM.J. W. Public Service Co. of Colorado. 80/12/19. 1p. 07362:299.
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- G. Adjudicatory correspondence
- 8011200241 Suggests obtaining B Spitalny assistance in preparing appeal brief of initial decision re McQuire/Oconse spent fuel transportation CHRISTERISURY.E. Hearings Division. 80/11/18. 1p.
- B012090367 Requests hearing per 10CFR50 on issue of whether all safety-related electrical equipment should be environ qualified by 8206030 per NUREG-0588. In interim, util will attempt to resolve concerns w/NRC. PORTER, H. L. Dute Power Co. 80/12/03. 1p. 07201:172.

H. Antitrust correspondence

- 8012300013 Comments on & request for approval of encl settlement license conditions.
 CHANAMIA.F. D. . HODODON. A. Antitrust Division. 80/12/03. 65pp.
- --8012300030 Order granting attached licensed commitments, agreed to by util, DOJ & RRC.
 TUBRIDY, J. F., HALL, G. R., FARMAKIDEB, J. B. Atomic Safety and Licensing Board Panel. 74/09/24. 21pp. 07352:015.
- --B012303040 Request for order directing licenses be amended per attached conditions. DOJ & util join in motion. Order would terminate NRC prosecutorial role but NRC would remain as party. Certificate of Svc ancl. VOGLER.B.H. Atomic Energy Commission. LECKIE.B.A., LEVIN.M.H. Justice: Dept. of, 74/05/13. 9pp. 07382:034.
- P. Operating license stage documents & correspondence
- 8012020793 Forwards seismic qualifications of auxiliary feedwater sys in operating PKRs & describes program NRC is undertaking to review capability of operating PKRs to remove decay heat following earthquake.
 EISERHUT, D. G. Division of Licensing, 80/10/21, App.
- B012030847 Requests fee, par 10CFR170, for application for Tech Spec changes re term "operable" for facilities.
 MILLER, M.O. License Fee Hanagement Branch. 80/10/29. ip. 07149:075.

- B012100311 Forwards nonproprietary & proprietary responses t licensing Questions 1-5 re fuel rack & proposed spent fuel rerack in response to NRC 801024 request Application & affidavit for withholding encl. PARKER, H. O. Duke Power Co. 80/10/31. 25pp. 07220:001.
- 8012160050 Ltr to operating plant licensess.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licenses confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012020036 Forwards Amends 88,88 & 85 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
 REID,R.W. Operating Reactors Branch 4. 80/11/07. 3pp. 07148:311.
- --8012020042 Amends 88.88 & 85 to Licenses DPR-38.DPR-47 & DPR-55. respectively revising Tech Specs re inservice insp program. REIO.R.W. Operating Reactors Branch 4. 80/11/07. 7pp. 07148:317.
- --8012020051 Safety evaluation supporting Amands 88,88 & 85 to Licenses DPR-3B, DPR-47 & DPR-55, respectively.

 * Operating Reactors Branch 4, 80/11/07, 9pp. 07148:330.
- --B012020057 Notice of issuance & availability of Amends 88,88 & 85 to Licenses DPR-38,DPR-47 & DPR-35,respectively. REID,R. M. Operating Reactors Branch 4. B0/11/07. 2pp. 07148:339.
- BOIROZO807 Ack receipt of BOO818 ltr re safety-grade upgrade of existing control grade anticipatory reactor trips.Forwards request for add1 info to complete environ review of switches.
 REID.R.W. Operating Reactors Branch 4. BO/11/12. 5pp. 07145:319.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BMR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days.
- 8012030845 Informs of review of emergency feedwater sys against NUREO-0660 criteria. Forwards request for add1 info necessary to complete review. Requests response within 60 days. REID,R.W. Operating Reactors Branch 4. 80/11/14, 14pp. 07150:089.
- 8012020592 Forwards addl info re seismic analysis of spent fuel racks proposed for use in spent fuel pool shared by units. Info provides simplified calculation of sliding of Westinghouse free-standing racks.
 PARKER. M. D. Duke Power Co. 80/11/25. 4pp. 07148:041.
- 8012240137 Ack receipt of 801020 application proposing Tech Spec 6.6.2.1.a(7).Class III fee required for one unit-Class I fee for other two units.
 MILLER,H.O. License Fee Management Branch. 80/11/26. ip. 07324:183.
- 8012050448 Requests extension until 810115 to respond to NRC 801027 ltr re standby shutdown facility. Time needed to gather input & assemble info into presentable form.
 PARKER, N. D. Duke Power Co. 80/12/01. ip. 07171:347.
- 8012100374 Application to amend Licenses DPR-38, DPR-47 & DPR-55, deleting Tech Spec 4.20, as requirements are contained in inservice insp program submitted 770515. Info re reactor yeasel internals vent valve encl.
 PARKER.W.O. Duke Power Co. 80/12/04. 5pp. 07219:052.
- 8012220485 Responds to 8007ii memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANOART.R.L. Effluent Treatment Bystems Branch. B0/11/06. Bpp.
- 8012290480 Informs that safety-grade design of anticipatory reactor trip sys is acceptable. Environ qualification review of applicable components incomplete. Safety evaluation providing basis for installation & operation of sys encl.

 REID,R.W. Operating Reactors Branch 4. 80/12/04. 2pp. 07935:129.

×.

- ~-8012270484 Safety evaluation re final design & implementation of safety grade anticipatory reactor trip on turbine trip or loss of main fædwater. Proposed mods satisfactory,

 # Operating Reactors Branch 4, 80/12/04, Spp. 07335:131.
- B012270230 Natification of 801216 meeting w/B&W owners group in Bethesda.MD re resolution programs & schedules of TMI-2 task action plan items. THROM.E.D. Reactor Systems Branch. 80/12/09. 2pp. 07:307:15B.
- B012240474 Notification of 801216 meeting w/B&W owners group for small break LOCAs in Bethesda-MD for presentation of programs & schedules for resolutions of TMI-2 task action plan items. THROM.E.D. Reactor Systems Branch. 80/12/09. 2pp. 07324:178.
- B012160325 Responds to NRC B01126 request for license fees as suppl to util B01020 ltr re addl reporting requirement. Inclusion of requirement was administrative action & does not warrant fee imposition.

 PARKER. M. O. Duke Power Co. 80/12/10. 1p. 07262:008.
- B012190482 Tech Specs correcting administrative errors for 3.5.2-1A2. 3.5.2-2A2.3 5.2-2A2. 3.5.2-4A2. Formal proposed Tech Specs to be submitted by separate correspondence.
 PARKER, M. G. Duke Power Co. B0/12/12. 2pp. 07282:151.
- 8012230488 Forwards add1 info re seismit analysis of spent fuel racks proposed for use in spent fuel pool at facilities. PARKER, N. O. Duke Power Co. 80/12/12. 5pp. 07313:216.
- 8012230450 Forwards status of implementation of NUREG-0737 items in response to NRC 801031 ltr.
 PARKER, N. C. Duke Fower Co. 80/12/15. 8pp. 07314:123.
- 8012230435 Forwards add1 fee for 800519 application for amend to licenses re disposal of contaminated oil by burning. PARKER,N.O. Duke Power Co. 80/12/17. 1p. 07312:265.
- G. Inspection reports, IE Bulletins & correspondence
- 8012160042 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
 0'REILUY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24.
 ip. 07262:176.
- 8012170281 Forwards Suppl 3 to 1E Bulletin 79-01B. "Environ Qualification of Class 1E Equipment." No written response required. 0'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/10/24, 1p. 07268:265.
- 8012170813 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30. ip. 07266:271.
- 8011210440 Forwards 801101 Revision 5 to util 70-day response to IE Bulletin 79-018 replacing Revision 4 in entirety. THIES A.C. Duke Power Cq. 80/10/31. 2pp. 07029:168.
- --8012120610 Revision 5 dtd 801101 to util 90-day response to IE Bulletin 79-018, "Environ Gaulification of Class IE Electrical Equipment."

 * Duke Power Co. 80/11/01. 450pp. 07229:001.
- 8012170571 Forwards IE Info Notice 80-39, "Malfunction of Sciencid Valves Mfg by Valcor Engineering Corp." No written response required.

 0'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31.
 19, 07264:124.
- 8012230050 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Bys Emergency Generators." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 90/10/31. 1p. 07311:248.
- 8012110749 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Maltolm Foundry Co.inc." Written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/06. 1p. 07224:199.
- 8012030873 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p. 07180:121.

- 8012080603 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Desse Unit 1." No response required.

 O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/10.

 1p. 07183:017.
- 8012080596 Forwards supplemental response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II. Two-inch. Tray Adsorber Cells."

 Trays used at facility are not susceptible to degradation mechanism.

 PARKER, N. O. Duie Power Co. BO/11/11 4pp. 07188: 204.
- 8012040172 Forwards IE Bulletin 80-23, "Failures of Splengid Valves Még by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/14. tp. 07158:084.
- 8012040482 Forwards IE Sulletin SO-24, "Prevention of Damage Due to Nater Leakage Inside Containment." United response required Requests info on manpower expended. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/21. 1p. 07163:347.
- 8012180591 Forwards responses to action Items 1 & 2 of 1E Bulletin 80-23, "Faujure of Solenoid Valves Hig by Valcor Engineering Corp." Facility has had three failures of Valcor solenoids. PARKER, W. D. Duke Fower Co. 80/11/24. 8pp. 07271:351.
- 8012170509 Forwards IE Info Notice 80-29. Suppl 1, "Brolen Studs on Terry Turbine Steam Inlet Flange." No written response required.

 D'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/26.
 18. 07248:096.
- BD123:0167 Responds to IE Bulletin 80-21, "Valve Yotes Supplied by Malcolm Foundry Co. Inc." No described Anchor Darling valves in use at facilities. Manufacturers being contacted revalve parts.

 PARKER: N. O. Dute Power Co. 80/12/05. 1p. 07370:023.
- 8012160435 Forwards addl info re insp of fuel assembly holddown springs at facility & safety evaluation of operation w/broken springs in core.
 PARKER, U. O. Duke Power Co. 80/12/09. Spp. 07263:049.
- 8012310085 Forwards safety evaluation re util actions taken in response to NRC 790525 ltr re cracking in feedwater sys piping at facilities.
 REID.R.W. Operating Reactors Branch 4. 80/12/09. 2pp. 07371:160.
- ---B012310091 Safety evaluation re util actions taken in response to NRC 790525 ltr on cracking in feedwater sys piping at facilities Augmented insps per IE Bulletin 79-13 may be discontinued.

 Operating Reactors Branch 4. 80/12/09. 2pp. 07371:162.
- R. Periodic operating reports & related correspondence
- 8012190619 Forwards munthly operating repts for Nov 1980. PARKEN, N. D. Duke Fower Co. 80/12/15. 1p. 07288:245.
- --8012190619 Monthly operating repts for Nov 1980. REAVIS.J.A Duke Power Co. 80/12/15. 16pp. 07288:246.
- S. Reportable occurrences, LERs & related correspondence
- 8012230479 RO correcting 801209 rept of broken holddown springs. Five springs brote not four as originally reported. Assembly 1030 identified as having broken spring. All other info in 801209 ltr is valid. PARKER. W. Q. Buke Power Co. 80/12/15. 2pp. 07318: 320.
- B012300493 Forwards LER 60-034/03L-0. PARKER.N. 0. Duks Power Co. 80/12/23. 3pp. 07357:349.
 - lo12300498 LER 80-034/032-0: on 801124.level indication was lost to station elevated water storage tank.Caused by water collecting in air compressor.HPSN pumps placed in manual mode normal instrumentation checked & air receiver drained. JONES.J. L. Duke Power Co. 80/12/23. ip. 07357:352.

- DOCKET 50-270 DCGNEE NUCLEAR STATION, UNIT 2
- 8012090367 Requests hearing per 10CFR50 on issue of whether all safety-related electrical equipment should be environ qualified by 820630 per NUREG-0588. In interim, util will attempt to resolve concerns w/NRC.
 PORTER, N. L. Duke Power Co. 80/12/03. 1p. 07201:172.
- M. Antitrust correspondence
- 8012300030 Order granting attached licensee commitments, agreed to by util, DOJ & LRC.
 TUBRIDY, J. F., HALL, G. R., FARMAXIDES, J. B. Atomic Safety and Licensing Board Panel. 74/05/24. 21pp. 07352:015.
- --8012360040 Request for order directing licenses be amended per attached conditions. DDJ & vist join in motion. Order would terminate NRC prosecutorial role, but NRC would remain as party. Certificate of Svc encl.
 VDDLER.B.H. Atomic Energy Commission. LECKIE, D. A., LEVIN, M. M. Justice, Dept. of. 74/05/13. 7pp. 07352:034.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PNRs & describes program NRC is undertaking to review capability of operating PNRs to remove decay heat following earthquake.
 EIBENHUT, D. O. Division of Licensing. 80/10/21. 4pp.
- B012030347 Requests fee.per 10CFR170.for application for Tech Spec changes re term "operable" for facilities.
 MILLER.W.O. License Fee Management Branch. B0/10/29. 1p.
- 80:21003i1 Forwards nonproprietary & proprietary responses to licensing Questions 1-5 re fuel rack & proposed spent fuel rerack in response to NRC 80:024 request Application & affidavit for withholding encl. PARKER, N. O. Duke Power Co. 80/10/31. 25pp. 07220:Q01.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISERHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012020036 Forwards Amends 88,88 % 85 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availability.
 REID.R.W. Operating Reactors Branch 4, 80/11/07, 3pp. 07148:311,
- --8012020042 Amends 88.88 & 85 to Licenses DPR-38.DPR-47 & DPR-59, respectively, revising Tech Specs re inservice insp program. REID: R. H. Deprating Reactors Branch 4. 80/11/07. 7pp. 07(48:317.
- --8012020051 Safety evaluation supporting Amends 88,88 & 85 to Licenses DPR-38,DPR-47 & DPR-55,respectively. • Operating Reactors Branch 4. 80/11/07. 9pp. 07148:330,
- --8012020057 Notice of issuance & availability of Amends 88.88 & 85 to Licenses DPR-38.DPR-47 & DPR-95.respectively. REID. R. M. Deerating Reactors Branch 4. 80/11/07. 2pp. 07148:339.
- B012020B07 Ack receipt of B00B1B ltr re safety-grade upgrade of existing control grade anticipatory reactor trips. Forwards request for add1 info to complete environ review of switches.

 REID.R. M. Operating Reactors Branch 4. B0/11/12. 5pp. 07145:319.
- 8012220363 Ltr to all power reactor licensees forwarding NUREO-0617, "BWR Feedwater Noirle & Control Rod Drive Return Line Norrie Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o enci. EISENHUT, D. O. Division of Licensing. 80/11/13. ip.
- 8012030845 Informs of review of emergency feedwater sys against NUREO-0660 criteria.Forwards request for add1 info necessary to complete review. Requests response within 60 days.
 REID.R.W. Operating Reactors Branch 4. 80/11/14. 16pp. 07150:089.

- 8012020592 Forwards addl info re seismic analysis of spent fuel racks proposed for use in spent fuel pool shared by units. Info provides simplified calculation of sliding of Westinghouse free-standing racks.
 PARKER, N. O. Duke Power Co. 80/11/25. 4pp. 07148:041.
- 8012240137 Ack receipt of 801020 application proposing Tech Spec 6.6 2.1.a(9).Class III fee required for one unit.Class I fee for other two units.
 MILLER.N.O. License Fee Management Branch. 80/11/26. 1p. 07324:183.
- 801205044B Requests extension until B10115 to respond to NRC 801027 ltr re standby shutdown facility. Time needed to gather input & assemble info into presentable form. PARKER. N. O. Duke Power Co. 80/12/01. ip. 07171:347.
- 8012100374 Application to amend Licenses DPR-38, DPR-47 & DPR-55, deleting Tech Spec 4.20, as requirements are contained in inservice insp program submitted 790515. Info re reactor vessel internals vent valve encl.
 PARKER, N.O. Duke Power Co. 80/12/04. 5pp. 07219:052.
- 8012220485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 200.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Lnw level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Systems Dranch. 80/11/06. Spp.
- B012270480 Informs that safety-grade design of anticipatory reactor trip mys is acceptable. Environ qualification review of applicable components incomplete. Safety evaluation providing basis for installation to operation of mys encl.
 REID.R.W. Operating Reactors Branch 4. 80/12/04. 2pp. 07335: 127.
- --80122904B4 Bafety evaluation re final design & implementation of safety grade anticipatory reactor trip on turbine trip or loss of main feeduater. Proposed mods satisfactory.
 4 Operating Reactors Branch 4. 89/12/04. 3pp. 07335:131.
- 8012220930 Notification of 801216 meeting w/B&H owners group in Bathssds,MD re resolution programs & schedules of TMI-2 task action plan items. THROM.E.D. Reactor Systems Branch. 80/12/09. 2pp. 07307:158.
- 8012240474 Notification of 801216 meeting w/B&W owners group for small break LGCAs in Bethesda, MD for presentation of programs & schedules for resolutions of TMT-2 task action plan Items. THROM, E. D. Reactor Systems Branch. 80/12/09. 2pp. 07324:175.
- 8012160325 Responds to NRC 801126 request for license fees as suppl to util 801020 ltr re addl reporting requirement. Inclusion of requirement was administrative action & does not warrant fee imposition.

 PARKER, N. G. Duke Power Co. 60/12/10. 1p. 07262:008.
- 8012230488 Forwards addl info re seismic analysis of spent fuel racks proposed for use in spent fuel popl at facilities.
 PARKER.W.O. Duke Power Co. 80/12/12. 5pp. 07313:216.
- B012230450 Forwards status of implementation of RUREO-0737 items in response to NRC B01031 ltr.
 PARKER, N. D. Duke Power Co. 80/12/15. Bpp. 07314:123.
- B012230435 Forwards addl fee for 800519 application for amend to licenses re disposal of contaminated oil by burning. PARKER, N. D. Duke Power Co. 80/12/17. 1p. 07312;265.
- G. Inspection reports, 1E Bulletins & correspondence

Zalki7:

- B012t60042 Forwards IE Info Natice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 G'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.
- 8012170281 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.

 0'REILLY,J.P. Region 2: Atlanta. Office of the Director. 80/10/24, ip. 07268:265.

- B012170813 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, P. Region 2, Atlanta, Office of the Director. B0/10/30. 1p. 07266:271.
- B011210440 Forwards B01101 Revision 5 to util 90-day response to LE Bulletin 79-018 replacing Revision 4 in entirety.
 THIEB.A.C. Duke Power Co. 80/10/31 2pp. 07029:168.
- 8012170571 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Kifg by Valcor Engineering Corp." No written response required.
 O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/10/31, 1p. 07264: 124.
- 8012230950 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators," No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012110749 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc." Writton response required.

 D'RETLLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/06.
- B012030B73 Forwards IE Info Notice B0-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. B0/11/07. ip. 07150: 121.
- 8012080603 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/11/10. 1p. 07183:017.
- 80:2040172 Forwards IE Bulletin 80-23. "Failures of Solemoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. D'RETLLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/14. In.
- B012040482 Forwards IE Builetin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required Requests info on manpower expended. O'REIU'Y, J.P. Region 2. Atlanta. Office of the Director. 80/11/21. lp. 07163:349.
- BD121B0591 Forwards responses to action Items 1 & 2 of IE Bulletin 80-23, "Faulure of Bolenoid Valves Mfg by Valcor Engineering Corp." Facility has had three failures of Valcor solenoids. PARKER, M. O. Duke Power Co. 8D/11/24. 8pp. 07271: 351.
- 8012170309 Forwards IE Info Notice BD-29/Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.
- B012310167 Responds to IE Bulletin 80-25. "Valve Yokes Supplied by Malcolm Foundry Co, Inc." No described Anchor Darling valves in use at facilities. Manufacturers being contacted revalve parts.

 PARKER. H. D. Duke Power Co. 80/12/05. ip. 07370:023.
- 8012160435 Forwards add1 info re insp of fuel assembly holddown springs at facility & safety evaluation of operation w/broken springs in core.
 PARKER, H. O. Duke Power Co. 80/12/09. 6pp. 07263:049.
- 8012310088 Forwards safety evaluation re-util actions taken in response to NRC 790825 ltr re-cracking in feedwater sys piping at facilities.
 REID.R.W. Operating Reactors Branch 4. 80/12/09. 2pp. 07371:160.
- --8012310071 Safety evaluation re util actions taken in response to NRC 790325 ltr on cracking in feedwater sys piping at facilities. Augmented insps per IE Bulletin 79-13 may be discontinued.

 * Operating Reactors Branch 4. 80/12/09. 2pp. 07371:162.
- R. Periodic operating reports & related correspondence
- B012190615 Forwards monthly operating repts for Nov 1980. PARKER.W.O. Duke Power Co. B0/12/15. ip. 07288:245.

- --8012190619 Monthly operating repts for Nov 1980. REAVIB.J.A. Duke Power Co. 80/12/15. 16pp. 07288;246.
- 8. Reportable occurrences, LERs & related correspondence
- 8012020392 Forwards LER 80-011/03L-0. PARKER, N. D. Duke Power Co. 80/11/26. Spp. 07143: 257.
- --8012020543 LER 80-011/03L-0:on 800726.HPl pump 28 declared inoperable due to high upper bearing temp on motor causing limited axial pump lift.Probably caused by upward pressure of motor against upper guide bearing.Pump rebuilt.

 JONES.J.L. Dute Power Co. 80/11/26. ip. 07143:262.
- B012100497 Forwards LERs identified as missing in 801104 memo.Encl LERs cancelled. LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/12/03. 1p. 07218:098.
- --8012100501 LER 80-009 has been cancelled. a Duke Power Co. 80/12/03 ip. 07218:079.
- B012100466 Ferwards LER 80-024/03L-0. PARKER.U.O. Duke Pawer Co. 60/12/05. 3pp. 07218:039.
- --B012100469 LER B0-024/03L-O: on B01105.HP1 pump 28 declared inoperable due to high upper bearing temp. Caused by isolation of normal coaling water supply to Unit 2 HPI pumps.personnel error. equipment maifunction & design deficiency.

 JOKES, J. L. Duke Power Co. 80/12/05. 1p. 07218:042.
- B012230479 RO correcting 801209 rept of broken holddown springs.Five springs broke, not four as originally reported. Assembly 1D30 identified as having broken spring. All other info in 801209 for is valid. PARKER, N. O. Buke Power Co. 80/12/15, 2pp. 07318: 320.
- DOCKE: 50-27: VERHOUT YANKEE NUCLEAR POWER STATION
 F. Sacurity, medical, emergency & fire protection plans
- B012040077 Forwards interim 10CFR50.48 suspending completion dates for fire protection mods.effective upon B01027 publication in 45FR71549.Rule will be superseded by revised rule when effective.
 E18ERHUND, D.O. Division of Licensing. B0/11/07. App. 07170:263.
- 8012030596 informs of eristing amergency communications sys review & resulting mode to emergency notification sys & health physics network. NRC will have lamps installed on emergency telephones in all control rooms & technical support ctrs. ORIER, B. H. Region i, Philadelphia, Office of the Director. BO/11/14. 2pp. 07174:266.

R. General correspondence

- B012100461 Requests investigation & public hearings re environ impact involved in restart of facility. Ltr to State of VT public officials encl. RICHARDSON.C., CALLAN.V. Vermont Yanise Decommissioning Alliance. B0/11/27.
- 8012150192 Urges that facility be closed until investigation is conducted into safety & mgt of facility, investigation findings are published & adequate measures are taken to improve plant safety.
 LAMORT, L. DETMOLD, D. OREENNALD, R. Affiliation Unknoun. 80/11/30. 4pp. 07241:138.
- Rol2150183 Urges full & public investigation of plant accident history & failure to meet safety stds. Requests closure until safety guaranteed. Concerns include water cleanup sys & reactor discharge & turbine generator decay.

 DOWLINGLE J. Vermont Vankee Decommissioning Alliance. BO/12/03. ip. 07237:222.
- 8012150157 Requests NRC have all completed sys reviewed & tested by independent, competent technicians prior to facility startup, LEVENGEOD. M. Vermont Yankes Decommissioning Alliance. 80/12/03. ip. 07167:COI.
- 1012290249 Informs of relocation of engineering ofc affective 801222. KAY.J.A. Yankee Atomic Electric Co. 80/12/18. ip. 07342:338.

- 8012310263 Protests planned 810101 facility restart. Requests investigation re-cracked piping, corrosion of steam crossover lines, defective turbines & operation u/o water discharge permit.
 MAPLES, A. Affiliation Unknown. 80/12/21. 1p. 07308:001.
- 8012310260 Protests reopening of facility. Cites deficiencies in spent fuel storage pool, piping support sys, reactor water cleanup pipe welds & drywell borus. LEVEN.P. Affiliation Unknown. 80/12/23. 1p. 07370:006.
- 8012310268 Expresses concern re planned facility restart in view of reactor eater cleanup pipe cracking & spent fuel storage paol overcrowding. Plant should remain closed until safety of storage facilities is assured.

 CONNELLY, E. B. Affiliation Unknown. 80/12/23. ip. 07308:001.
- B012310272 Requests that NRC consider investigation of facility safety & mgt due to technical difficulties occurring at facility. NGDA.L. Affiliation Unknown. B0/12/23. 1p. 07308:001.
- P. Operating license stage documents & correspondence
- BD12160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation of dates will be met. EISENHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012080313 Forwards Amend 89 to License DPR-28, safety evaluation & notice of issuance & availability.

 1PPDLITO.T.A. Operating Reactors Branch 2. 80/11/10. 3pp. 07186: 252.
- --8012080322 Amend 39 to License DPR-28, changing count rate in source range monitor to drop below three counts per second when entire core is removed or raplaced.

 [PPDL[TG.T.A. Operating Reactors Branch 2. 80/11/10. 12pp. 07186: 255.
- --80120B0326 Safety evaluation supporting Amend 59 to License DPR-28. # Office of Nuclear Reactor Regulation, Director, 80/11/10, 2pp. 07186:265.
- --8012080331 Notice of istuance & availability of Amend 59 to License DPR-28.

 IPPOLITO, T.A. Operating Reactors Branch 2. 80/11/10. 2pp. 07/184-247
- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619.
 "BUR Feedwater Norrie & Control Rod Drive Return Line
 Norrie Cracking." Confirmation that implementation dates
 will be met must be sent within 45 days. We encl.
 EISEKHUT.D.O. Division of Licensing. 80/11/13. 1p.
- 8012300704 Forwards Amend &O to license DPR-28 & notice of issuance & availability.
 IPPOLIID.T.A. Operating Reactors Branch 2. 80/11/21. 4pp.
 07360:001.
- --8012309707 Amend 60 to License DPR-28, requiring safeguards contingency plan to be implemented within 30 days of Commission approval.

 IPPELITO.T.A. Operating Reactors Branch 2. 80/11/21. 2pp. 073-0708.008
- --8012300710 Natice of issuance & availability of Amend 60 to License DPR-28. IPPOLITO, T.A. Operating Reactors Branch 2. 80/11/21. 2pp. 07340:007.
- 80120100B9 Responds to 800924 1tr requesting that util commit to installing Class IE protection at interface of reactor protection sys motor generator sets. Response will be submitted by 810123. SMITH.L. Vermont Yankee Nuclear Power Corp. 80/11/24. 1p. 07091:262.
- 8012070190 Application for Proposed Change 93 to License DPR-28, changing App A Tech Specs to reflect revised reactor vessel water lovel setpoint scale values & provide common ref for vessel level instrumentation. Class II fee encl. CRUCE.R.H. Vermont Vankee Nuclear Power Corp. 80/12/01. 2pp. 07200:152.

- --8012090195 Proposed Change 93 to App A Tech Specs, Sections 1.1.2.1.3.1 & 3.2 re reactor vessel water level setpoint scale values.

 * Vermont Yankee Nuclear Power Corp. 80/12/01. 12pp. 07200:154.
- 8012030112 Forwards response to 800307 & 801031 ltrs requiring all licensees to submit rept detailing outage dates & lengths of outages for all ECCS. No new changes proposed. SMITH,R.L. Vermont Yankee Nuclear Power Corp. 80/12/02. 7pp. 07174:014.
- 8012220485 Responds to 800911 mamo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENION, H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expandedat 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012310004 Forwards proposed wording for Tech Specs re sys integrity & iodina monitoring per TMI-2 Lessons Learned Category A requirements.

 IPPOLITG.T.A. Operating Reactors Branch 2. 80/12/10. 4pp. 07371:065.
- 8012230219 Forwards itemized tabulation of requirements specified in NRC 801031 itr re TMI-related items approved for implementation. Util has committed to meet implementation schedule.

 HEIDER, L. H. Vermont Yankee Nuclear Fower Corp. 80/12/15. 14pp.
- 8012230192 Responds to alleged potential problems re fire barrier penetration seals installed by Chemtrol Corp. Investigation underway to assess seal acceptability.

 CONMAY.M.F. Vermont Yankee Nuclear Power Corp. 80/12/19. 3pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7905070693 Responds to IE Bulletin 79-03 re waiding defects. No further action required since seam weld insp requirement is ABME III. Only plants fabricated under these rules are affected. MODDY D.E. Vermont Yankes Nuclear Power Corp. 79703/30. 1p.
- 8012120145 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Halcolm Foundry Co. Inc." Kritten response required. ORIER.B.H. Region i, Philadelphia, Office of the Director. 80/11/06. 1p. 07228:332,
- B0121903B4 Informs util of issuance of new NRC personnel identification badges: effective after B01130. Example encl. MARTIN. H. J. Region I. Philadelphia, Safeguards Branch. B0/11/06. 2pp. 072B6:145.
- B012030759 Forwards IE Info Notice B0-40, "Excessive Nitrogen Bupply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Dupressurization." No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. B0/11/07. ip. 07150:268.
- E0120B04i9 Forwards IE Info Notice 80-41. "Failure of Swing Check Valva in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. B0/11/10. ip. 071B2:306.
- 8012090595 Forwards response to IE Bulletin 80-ii. "Masonry Hall Design." including as-built info criteria to be used for final evaluation & justification for criteria used. HEIDERIL.H. Vermont Yankee Nuclear Power Corp. 80/ii/10. 58pp. 07187:001.
- 8012040078 Forwards IE Builetin 80-23, "Failures of Sciencid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/14, 1p. 07157:303.
- BO12220689 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER, B. H. Region i, Philadelphia, Office of the Director. 80/11/19. ip. 07293:121.

- B012040454 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Nritten response required. Requests info on manpower expended. GRIER.8 H. Region i. Philadelphia, Office of the Director. 80/11/21. 2pp. 07163:307.
- 8012050608 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B. H. Region i, Philadelphia, Office of the Director, 80/11/24. ip. 07174:101.
- BO12100505 Submits results of core spray sparger insp performed per IE Builetin 80-13. Single indication was observed on end cap. One oversize drawing withheld (ref 100FR2, 790). CONMAY.M.F. Vermont Yankee Nuclear Power Corp. B0/12/01. 7pp. 07220:119.
- R. Periodic operating reports & related correspondence
- B012160430 Forwards monthly operating rept for Nov 1980. CONMAY.H.F. Vermont Yantee Nuclear Power Corp. 80/12/09. 1p. 07234:156.
- --8012160432 Monthly operating rept for Nov 1980. BURGER, F. J., BERNARD, D. Vermont Yankee Nuclear Power Corp. 80/12/09. Bpp. 07254:157.
- B. Reportable occurrences. LERs & related correspondence
- B012290543 Part 21 rept re failure of fire penetration seals to pass fire test Cause undetermined Tested mat1 will be analyzed. BHUFE.S. Chemtrol Corp. 80/11/03. 14pp. 07308:001.
- 8012020420 Responds to NRC 801030 requests for add1 info re leaker fuel bundles identified in 1978 & 1979, & wear observed on water rod lower and plugs. Analysis of Item 490. 1 found failures in Reload 3 were result of anomalous metallurgical condition. SMITH-R. L. Vermont Yanyse Nuclear Power Corp. 80/11/21. 2pp. 07141:245.
- 8012010379 Forwards LER 80-039/03L-0. MURPHY.N.P. Vermont Yankee Nuclear Power Gorp. 80/11/24. 1p. 07091:275.
- --8012010403 LER 80-039/03L-0: on 801025, valves V16-20-20 & LRW-83 found to have seat leakage in excess of Tech Specs, Gause not stated. Valves repaired. MURPHy, M. P. Vermont Yankee Nuclear Power Corp. 80/11/24. 2pp, 07091:296.
- 8012020435 Forwards LER 80-03B/03L-0. HURPHY.M.P. Vermont Yankee Nuclear Power Corp. B0/11/26. 1p. 07148:245.
- --8012020439 LER 80-038/03L-0: on 801027, during refueling operations LIB-2-3-72A isolated from svc during installation of analog trip sys. Cause not stated. New analog instrument installed.

 NURPHY. N. P. Vermont Yankee Nuclear Power Corp. 80/11/26. 1p. 07148:266.
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- BO120B0734 Informs that mods will be made to emergency notification sys & health physics network equipment.NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operations facilities. GRIER.B.H. Region (, Philadelphia, Office of the Director. BO/11/14. 2pp. 07196:197.
- G. Adjudicatory correspondence
- 8012300358 Request for extension to 810131 to file brief in support of exceptions to ASLB 801027 initial decision re spent fuel pool proceeding. Certification of Svc encl. COLEMAN.A.C., COLEMAN.E.C. Affiliation Unknown, 80/11/30, 4pp. 07357:170.
- 8012290397 Appeal from ASLB initial decision granting util right to increase spent fuel pool storage capacity. NEPA requires detailed analysis of safety & health problems posed by reracking. Certificate of Svc enci.
 VALORE, C. J. Lower Alloways Creek, NJ. 80/12/04. 9pp. 07336: 227.

- 8012300071 Response to intervenors EG & A Coleman motion for extension until 810131 to file brief in suggert of exceptions. Opposes motion but would not object to 2 wk extension. Certificate of Svc encl.

 NETTERHAIM.H.J.

 Public Service Electric & Oas Co. of New Jersey.

 NETTERHAMM.M.J.

 Conner. Moore & Corber. 80/12/08. 7pp. 07/356:184.
- 8012220310 Response to Coleman 801130 motion for 7-wk extension to file brief in support of twelve exceptions to ASLB 801011 initial decision. Three-wk extension acceptable. Certificate of 8vc entl. MODRE-J.E. Hearing Branch 2. 80/12/09. 5pp. 07307:310.
- 8012230268 Motion granting in part Colemans' motion for 51-day estension to file brief. Brief must be filed by 810112. Times for filing licensees & NRC responses shall run from date of Colemans' filing.
 BISHOF.C.J. Administrative Branch. 80/12/10. 2pp. 07317:330.
- B0122903Bi Response in support of licensee 80120B request for 30-day extension to file consolidated reply to all parties' exceptions provided NRC also be permitted to file consolidated reply within 40 days. Certificate of Svc encl. MGORE.J.E. Hearing Branch 2. 80/12/11. 4pp. 07331:315.
- J. Insurance & indemnity information
- B012010360 Forwards Endorsement 41 to ANI Policy NF-230. CORREA,M.A. Marsh & McLennan.Inc., K & M Nuclear Consultants.Inc. Div. 80/11/24. 2pp. 07098:046.
- P. Operating liceuse stage documents & correspondence
- B012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PKRs & describes program NRC is undertaking to raview capability of operating PVRs to remove decay heat following earthquake. EISEMHUT.D.G. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensess,OL applicants & CP holders. Forwards NUREO-0737 to TMI action plan requirements,Requests operating reactor licenses confirmation in 45 days that Encl 1 implementation dates will be met.
 EISENHUT,D.G. Division of Licensing. 80/10/31. 7pp.
- 8012220563 Ltr to all power reactor licensess forwarding NUREG-0619, "BUR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. H/V encl. EISENHUT, D. O. Division of Licensing. 80/11/13. ip.
- B012100250 Notification of B01120 meeting w/util in Hancock's Bridge,NJ to discuss NRC criteria for reinforcement of masonry ualls. KERRIGAN,J. Licensing Branch 3. 80/11/18. 3pp. 07217:325.
- 8012240182 Forwards Amend 27 to License DPR-70.safety evaluation & notice of issuance & availability.
 VAROA.8.A. Operating Reactors Branch 1. 80/11/28. 3pp. 07183:001.
- --B012240184 Amend 27 to License DPR-70, revising Tech Specs re use of term operability. VARCA: S.A. Operating Reactors Branch 1. 80/11/28, 22pp. 07183:001.
- --8012240187 Safety evaluation supporting Amend 27 to License DPR-70.

 Diffice of Nuclear Reactor Regulation, Director. 80/11/28. 7pp. 07183:001.
- --B012240191 Notice of issuance & availability of Amend 27 to License PRR-70. VAROA.S.A. Operating Reactors Branch 1. 80/11/28. 2pp. 07183:001.
- S012220485 Responds to 800911 mamo raquesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions Forwards results of IE survey.

 BENION.H.R. Diffice of Nuclear Reactor Regulation, Director. 80/12/04. 2pg.
- -8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.

- 8012170237 Notification of 801205 meeting w/util in Bethesda.MD to discuss licensee proposal to perform low power tests while seismically underdesigned walls are being upgraded. ROSB.W.J. Operating Reactors Branch 1. 80/12/05. 2pp. 07268:209.
- B012290363 Requests logic diagrams % electrical schematic drawings re dasign & operation of auxiliary feedwater sys at facility.
 VARGA.S.A. Operating Reactors Branch 1, 80/12/08, 4pp. 07337:078,
- SO(2190216 Forwards application for amend of License DPR-70, changing Tech Spec re mod to limits on surveillance flow test of sodium hydroxide from containment spray additive tank. Class III fee encl.
 UDERITZ.R.A. Public Barvice Electric & Gas Co. of New Jersey.
 BO/12/11. 1p. 07285:299.
- --BO12170225 Application for amend of License DPR-70, changing Tech Bpec 4.6.2.2.d., modifying limit on survaillance flow test of sodium hydroxide from containment spray additive tank. SCHNEIDER.F.N. Pacific Gas & Electric Co. BO/12/12, 2pp. 07985-296.
- --801219023D Proposed change to Tech Spec 4.6.2.2 d.modifying limit on surveillance flow test of sodium hydroxide from containment spray additive tank.

 * Public Service Electric & Gas Co. of New Jersey. 80/12/12.
 2pp. 07285;298.
- 8012170413 Responds to NRC 801031 request for confirmation that implementation dates in NUREG-0737 can be met. Implementation schadule for post-TK1 requirements encl.
 MITIL.R.L. Public Service Electric & Gas Co. of New Jersey.
 80/12/15. 10pp. 07269:131.
- 8012310284 Informs of submission of proposed TMI-related Tech Spec revisions by B10114.per telcon request. MITTL.R.L. Public Service Electric & Gas Co. of New Jersey. 80/12/19. 2pp. 07341:308.
- G. Inspection reports, IE Bulletins & correspondence
- 8012090540 Forwards IE Enforcement Meeting Rept 50-272/80-12, discussing adoption & implementation of mods to physical security program re order modifying license. ORIER.8 H. Region 1, Philadelphia, Office of the Director. B0/10/09. 2pp. 07207:903.
- --8012090345 IE Enforcement Meeting Rapt 50-272/80-12. Noncompliance noted: procedure adopted & implemented failed to meet requirement of order.

 DEVLIN.J. H., MARTIN.K. O. Region 1, Philadelphia, Bafeguards Branch. BRUNNER,E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/05/23. 5pp. 07207:005.
- 8012080116 Ack receipt of 800707 & 1007 ltrs informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50-272/80-03. GRIER, B.H. Region i, Philadelphia, Office of the Director. 80/10/28 ip. 07181:026.
- --8012080122 Responds to NRC 800613 ltr re violations noted in IE Health Physics Appraisal Rept 50-272/80-03. Proposes expanded personnel training program & complete reorganization of performance dept. SCHMEIDER.F.M. Public Service Electric & Gas Co. of New Jersey. 80/07/07. 11pp. 07181:027.
- --B012080131 Provides add1 info to B00707 itr re violations noted in IE
 Insp Rept 30-272/80-03, Discusses commitment to replace
 contractor personnel, status of radiation protection group
 reorganization & contractor personnel training.
 SCHNEIDER, F. H. Public Service Electric & Gas Co. of New Jersey,
 80/10/07. 4pp. 07181:038.
- --8012080186 Forwards IE Health Physics Appraisal Rept 30-272/80-03 & notice of violation % significant appraisal findings.
 GRIER B. H. Region 1, Philadelphia, Office of the Director.
 80/06/13. 6pp. 07181:075.
- --8012080189 Notice of violation from health physics appraisal on 800128-0208. W Region 1. Philadelphia, Office of the Director. 80/05/16. 2pp. 07181:081.
- --8012080175 IE Health Physics Appraisal Rept 50-272/80-03. Noncompliance noted: inordinate reliance on contracted personnel, lack of technical proficiency among staff & weaknesses in emergency plan procedures.

 WHITE-J.R., DONALDSON, D.E., HOSEY, C.M. Region 1, Philadelphia, Office of the Director. 80/05/16. 11pp. 07181:083.

- 8012170397 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ORIER.8.H. Region 1, Philadelphia, Office of the Director. 80/10/30, 1p. 07269:098.
- 8012190703 Forwards IE Insp Repts 50-272/80-21 & 50-311/80-17 on 800901-1011. No noncompliance noted. BRUNNER, E. J. Region 1: Philadelphia. Reactor Operations Nuclear Support Stanch. 80/10/30. 2pp. 07287:359.
- ---B012190707 IE Insp Repts 50-272/80-21 & 50-311/80-17 on 800901-1011. No noncompliance noted Major areas inspected: logs & records, licensee events, operational safety verification & IE bulletins.

 NORROLH, L. J., HILL, M. M. Region 1, Philadelphia, Office of the Director, KEIMIO.R.R. Region 1, Philadelphia, Reactor Operations, Nuclear Support Branch. 80/10/28. 17pp. 07288:001.
- B012040621 Forwards proprietary & nonproprietary versions of environ qualification review repts for IE Bulletin 79-018. Repts supersade previous info submitted on 800307. 21. 0414 & 0604. Proprietary version withheld (ref 100FR2. 790). W/o encl. BCHNEIDER, F. M. Public Service Electric & Oas Co. of New Jersey. 80/10/31. 13pp. 06915:001.
- 8012300173 Forwards IE Insp Repts 50-272/80-27 & 50-311/80-20 on 801014-17 & notice of violation.

 GARLSON, R. T. Region I, Philadelphia, Reactor Construction & Engineering Support Branch. 80/11/05. 2pp. 07356:273.
- --B012330177 Notice of violation from insp on B01014-17.

 * Region i, Philadelphia, Office of the Director. B0/11/04. ip. 07356:275.
- --8012300185 IE Insp Repts 50-272/80-27 & 50-311/80-20 on 801014-i7. Noncompliance noted:1/2 of fire brigade members not trained in fire fighting & use of emergency breathing equipment & no continuous fire watch posted or fire doors. KOLTAY.P.S. Region i. Philadelphia: Office of the Director. EENETER.S.D. Region i. Philadelphia: Reactor Construction & Engineering Support Branch. 80/11/04. 6pp. 07356:276.
- 8012120060 Forwards IE Bulletin 80-21, "Velve Yokes Supplied by Malcolm Foundry Co.inc." Written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230:279.
- B012190355 Informs util of issuance of new NRC personnel identification badges: effective after B01130. Example encl. MARTIN. H. J. Region 1, Philadelphia, Bafeguards Branch. 80/11/06. 2pp. 07286:125.
- BO12030796 Forwards 1E Info Notice BO-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ORIER, B. H. Region i, Philadelphia, Office of the Director. BO/11/07. 1p. 07:50:224.
- 8012080426 Forwards IE Info Notice 80-41: "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit i." No response required. GRIER, B. H. Region 1: Philadelphia, Office of the Director. 80/11/10. ip. 07182:309.
- 9012040047 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER'S.H. Region i. Philadelphia, Office of the Director. 80/11/14. 1p. 07169:357.
- 8012220679 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." First peregraph erroneously stated no written response required. ORIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/19. 1p. 07293:116.
- 8012040497 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Written response required Requests info on manpower expended, GRIER, B.H. Region i, Philadelphia, Office of the Director. 80/11/21. Epp. 07169:172.
- 8012050595 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid," No written response required. ORIER, B. M. Region 1, Philadelphia, Office of the Director. 80/11/24. 1p. 07174:006.

- 8012010304 Forwards to NJ Dept of Public Advocate "Sample Piping Stress Analysis Calculations & Pipe Bupport Re-Evaluation," in response to 770827 itr. CODEY, L.R. Public Service Electric & Gas Co. of New Jersey. 80/i1/25
- --B012010398 "Bample Piping Stress Analysis Calculations & Pipe Support Re-Evaluation." * Public Service Electric & Gas Co. of New Jersey. 79/08/17, 61pp. 07091:305.
- --8012010313 Responds to 1E Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Bulletin concerns are not applicable to loop & Class 1 piping analysis of plant in vendor scope of supply.
 Nestinghouse Electric Corp. 79/04/23. 1p. 07092:013.
- 8012020137 Forwards proprietary & nonproprietary versions of Revision i,Vols 1 & 2. "Environ Qualification Review Rept." Applications & affidavit for withholding info (ref 10CFR2, 770). MITTL.R.L. Public Service Electric & Gas Co. of New Jersey. 80/11/25, 12pp. 07321:330.
- --B012020148 Nonpropriatary version, Revision 1, Vol 1, "Environ Qualification Review Rept." * Public Service Electric & Gas Co. of New Jersey. B0/12/01. 260pp. 03754:185.
- --8012020158 Nonproprietary version. Revision i.Vol 2, "Environ Qualification Review Rept."

 * Public Service Electric & Gas Co. of New Jersey. 80/12/01. 420pp. G3755:074.
- B012020570 Forwards info re Hestinghouse ultrasonic test turbine disc insp of facility. Info includes summarization of util analysis of discs found to have developed cracks in keyway areas & critical crack sizes from disc info sheets.

 SCHNEIDER: F. W. Public Service Electric & Gas Co. of New Jersey.

 B0/12/01. 5pp. 07148:064.
- R. Pariodic operating reports & related correspondence
- 8012140445 Forwards monthly operating rept for Nov 1780, MIDURA, H. J. Public Service Electric & Cas Co. of New Jersey, 80/12/11. 1p. 07254, 176.
- --8012160450 Monthly operating rept for Nov 1780. MILLER, L. K. Public Service Electric & Gas Co. of New Jersey. 80/12/11. 25pp. 07234:177.
- 8. Repartable occurrences. LERs & related correspondence
- 8012010398 RO 80-55/01P: on 801029 during radiographic testing of steam generator i1.12.13, & 14 feedwater nazzle to pipe welds, indications found in weld areas of steam generator i3. Cause unknown. Welds are undergoing exam.
 MIDURA.H.J. Public Service Electric & Oas Co. of New Jersey.
 80/10/29. 1p. 07098:064.
- 8012040447 RD 80-56/01P: on 801107.util discovered that three mesonry wells not erected per design. Analysis in progress & detailed rept will be submitted.

 MIDURA.H.J. Public Service Electric & Oas Co. of New Jersey.

 80/11/10. 2pp. 0715B:204.
- 80:120:1040:1 RD 80-6:1/0:P: on 80:123. Fire Pump 2 failed to start on receipt of automatic initiation signal & was inoperable per Tech Specs. Operator was assigned to standby unit & start pump; if necessary. Detailed rept will be provided. MIDURA.H.J. Public Service Electric & Gas Co. of New Jersey. 80/11/24. ip. 07078:065.
- 8012020645 Forwards LER 80-056/01T-0. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. 80/11/24. 3pp. 07130:328.
- ---B012020652 LER 80-056/01T-0: on 801107, during investigation of masonry walls, per IE Bulletin 80-1; discrepancy found between const spec & design drawing for auxiliary wall at 122-ft elevation & deficiency in corridor wall at 100-ft elevation.

 GBUCH, J. G. Public Service Electric & Oas Co. of New Jersey.

 80/11/24, 1p. 07130:331.
- 8012020485 Forwards LER 80-059/03L-0. LIBRIZZI.F.P. Public Bervice Electric & Oas Co. of New Jersey. 80/11/26. 2pp. 07130:281.

- --8012020488 LER 80-059/03L-0: on 801028, action statement 3.9.2 was entered due to loss of audio count rate. Caused by broken card holder in count rate drawer due to cables catching edge of circuit board. Card holder replaced & warning issued. OSUCH.J.C. Public Service Electric & Gas Co. of New Jersey. 80/11/26. 1p. 07130:283.
- B012020655 Forwards LER 90-057/03L-0. LIBRIZZI,F.P. Public Service Electric & Qas Co. of New Jersey. 80/11/26. 2pp. 07130:332.
- --8012020663 LER 80-057/03L-0: on 801028, while valves 13M3169 & 13M8171 uere disassembled for maintrontainment integrity lost due to grinding out of weld at steam generator 13 feedwater nozzia. Caused by personnel error. CSUCH.J.C. Public Service Electric & Oas Co. of New Jersey. 80/11/26. 1p. 07130-334.
- 8012020540 Forwards LER 79-056/01X-2. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. 80/11/28. 4pp. 07130:308.
- --B012020550 LER 79-056/01X-2: on 790B31, tests performed on facility indicated that RHR pump flow would exceed design runout flow. Caused by sys resistance being lower than desired. Flow instruments recalibr to meet functional requirements. RANDDLPH.J.M. Public Service Electric & Qas Co. of New Jersey. 80/11/28, 1p. 07130: 312.
- E012050382 Forwards LER 80-060/03L-0. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. E0/11/28. 2pp. 07173:240.
- --8012050385 LER 80-060/03L-0:on 801008 nuclear HOR 11SN taken out of svc.All diesel generators found overheating & declared inoperable. Caused by valve positioner & indicators incorrectly aligned w/valve. Positioner realigned. OSUCH, J.C. Public Service Electric & Gas Co. of New Jersey. 80/11/28. 1p. 07173:242.
- B012110403 Forwards LER 80-061/017-0. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. B0/12/05. 3pp. 07225:149.
- --8012110409 LER 80-061/01T-0: on 801123, w/fire pump 1 out of svc.fire pump 2 failed to run over 90-s. Caused by failed alternator. Alternator replaced. GSUCH.J.C. Public Service Electric & Gas Co. of New Jersey. 80/12/95. 1p. 07225:152.
- 8012150121 Forwards updated LER EO-009/03X-1. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. 80/12/09. 2pp. 07240:114.
- --B012150124 Updated LER 80-009/03X-1: on B00117, during inspired spent fuel pit.small leak discovered at tell tale drain. Caused by leaking welded seams. Half-round channels welded over leaking welds.

 OSUFH.J.C. Public Service Electric & Cas Co. of New Jersey.

 80/12/09. 19. 07240:116.
- 8012190634 Forwards LER 80-007/03X-1. UDERITZ.R A. Public Service Electric & Gas Co. of New Jersey. 80/12/11. 3pp. 07287:281.
- --801219040 LER 80-007/03X-1: on 800128, design deficiency found in deminaralized water supply check valve to auxiliary feeduater storage tank 1087. Gaused by failure to include valve in piping spec break. Valve seismically qualified. OSUCH.J.C. Public Service Electric & Gas Co. of New Jersey. 80/12/11. 1p. 07287: 284.
- 8012230379 Forwards LER 80-063/01T-0. UDERITZ.R.A. Public Service Electric & Gas Co. of New Jersey. 80/12/18. 1p. 07318:254.

--8012230392 LER 80-063/01T-0: on 801208, discovered auxiliary feedwater pumps 11 % 12 could be atopped from control console, upon receipt of low-low level signal. Caused by design error. Design change request issued & implemented 801206. USUCH, J. C. Public Service Electric & Oas Co. of New Jersey. 80/12/18. 1p. 07318: 256.

- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 A. Application/construction stage documents & correspondence
- BOOB150060 Submits interim criteria for shift staffing to all OL & CP licensees & applicants; per NRC 800507 ltr. Discusses administrative provisions for emergency & overtime work. Development & implementation to be reviewed within 70 days. EISENRUT, D. O. Division of Licensing. 80/07/31. 10pp.
- B012160050 Ltr to operating plant licensees, DL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT, D. Q. Division of Licensing. 80/10/31. 7pp.
- 8011260125 Forwards info re evaluation of environ qualification program for safety-related electrical & Class IE equipment, in response to 791102 ltrs. CRANE,P. A. Pacific Oas & Electric Co. 80/11/13. 45ppp. 01741:019.
- 8012110835 Forwards ACRS 801112 ltr re review of util study re interactions of failure of nonsafety sys on plant safety as result of earthquake. KIRAOLIA.F. J. Licensing Branch 3. 80/11/17. 5pp. 07227:214.
- 8012050430 Forwards response to NRC 800827 ltr re containment pressure boundary fracture toughness. Info certifying that fracture toughness acceptance stds have been met is available at plant site.

 CRANE.P.A. Pacific Oas & Electric Co. 80/11/21. 41pp. 07171:272.
- 8012080335 Forwards response to NRC 780125 ltr re long-term overpressure transient protection. Includes description of long-term sys to be employed at facilities.

 CRANE.P.A. Pacific Gas & Electric Co. 80/11/21. 10pp. 07190:285.
- 8012040520 Forwards responses to NRC 800108 ltr re implementation of recommendations of NUREO-0660. "Enhancement of Onsite Emergancy Diesel Generator Reliability."

 CRANE.P.A. Pacific Gas & Electric Co. 80/11/25. 3pp. 07157:271.
- 8012090329 Informs of planned temporary shutdown of basic seismic instrumentation sys at facility. Shutdown required to enable licensee to install panels for post-accident monitoring sys in control room.

 CRANE, P. A. Pacific Gas & Electric Co. 80/11/25. 1p. 07201:161.
- 8012120308 "Concentration & Speciation of Copper in Waters Collected Near San Onofre & Diablo Campon Nuclear Power Stations." HARRISDN,F.L. Lawrence Livermore Laboratory. FIN A-0119. NURE9/CR-0750. 80/11/30. 66pp. Available at NTIS.
- 8012090360 Provides info on environ qualification of safety-related equipment per 801001 request. Description of valve flow monitor sys & power supply cable presented in detail. CRANE, P.A. Pacific Oas & Electric Co. 80/12/01. 2pp. 07201:119.
- 8012D50273 Responds to requirements specified in Buppl 10 to NUREQ-0675. Mods addressed: procedure for dissemination of operating experience, vendor review of low power program, agreements to pool resources w/utils & inadequate core cooling. CRANE, P. A. Pacific Gas & Electric Co. 80/12/02. 60pp. 07171:211.
- 8012090235 Responds to NRC 800827 ltr re Review Guestion 5. Response provides commitments & completion schedule for upgraded meteorological program & is organized to address four essential elements in NUREG-0554.App 2.

 CRANE, P. A. Pacific Oas & Electric Co. 80/12/02. 3pp. 07201:148.
- B012110526 "Forwards procedure for dissemination of operating experience, vendor review of low power test program procedures & low power test program safety analysis rept, per Suppl 10 to NUREO-0675, facility SER.
 CRANE, P. A. Pacific Qas & Electric Co. 80/12/02. 4pp. 07225:327.
- --8012110530 Nuclear Plant Administrative Procedure W-100, "Dissemination of Operating Experience." Westinghouse review of special low power test procedures encl.

 * Pacific Oas & Electric Co. 80/11/26, 7pp. 07225:331.
- --8012110533 "Diablo Canyon I Special Low Power Tests Final Safety Evaluation Rept." * Pacific Gas & Electric Co. 80/10/31. 49pp. 07225:338.

- 8012100470 Discusses field audit of electrical separations conducted in response to NRC 791130 ltr. Audit demonstrated that electrical equipment & sys have been installed in manner which provides independence & separation per FSR. CRANE, P. A. Pacific Oas & Electric Co. 80/12/04. 2pp. 07219:025.
- BO12180132 Describes actions taken as result of TMI accident re safety requirements of near-term GLs.All requirements must be met, applicant must appear before ABLB & record must be reviewed by Commission before low power testing.

 MIRAGLIA.F. Licensing Branch 3. 89/12/04. 2pp. 07272:284.
- 8012220485 Responds to 800711 mamo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey.

 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012290136 Responds to J Stolz 791130 ltr re field audit of electrical separations. Audit indicated equipment & sys installed per FBAR requirements. Audit results contained in Amend 51 to OL application.

 CRANE, P. A. Pacific Gas & Electric Co. 80/12/04. 2pp. 07344:049.
- B012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Committee.

 MIRAGLIA:F. Licensing Branch 3. 80/12/05. 3pp. 07266:098.
- 8012160158 Forwards preliminary emergency operating procedures, incorporating handwritten changes made during NRC review in conjunction wifactilities operations staff. CRANE.P.A. Pacific Gas & Electric Co. 80/12/08. 94pp. 07254:001.
- BO12290086 Forwards proposed license authorizing util to load fuel, proceed to initial criticality, perform startup testing & operate at 5% rated power. List of exemptions to Tach Space enc.l. Related correspondence.

 CRANE.P.A. Pacific Gas & Electric Co. BO/12/16 9pp. 07343:001.
- 8012290075 Unexecuted license for fuel loading & low power testing. List of exemptions to Tech Spacs for low power test program and. BENTON, H.R. Office of Nuclear Reactor Regulation, Director. 80/12/19. 8pp. 07342:349.
- F. Security, medical, emergency & fire protection plans
- BO121103B6 Responds to NRC BO0B27 ltr re Review Question 5. Response provides commitments & corresponding completion schedule for upgraded meteorological program. Commitments may be altered upon final promulgation of draff NNEGO-0684. CRANE.P.A. Pacific Oas & Electric Co. 80/12/02. 3pp. 07223:096.
- 8012240118 Releases public version of util emergency plan. FELTON, J. M. Division of Rules and Records. 80/12/12. ip.
- --8012240129 Forwards public version of App 1 to Revision 2 of corporate emergency response plan.
 CRANE,P. A. Pacific Gas & Electric Co. 80/03/21. ip.
- --8012240134 Public version of App i to Revision 2 of corporate emergency response plan.
 * Pacific Gas & Electric Co. 80/03/20, 7ipp.
- 8012270464 Releases public version of "Evacuation Times Assessment for Diable Campon Nuclear Power Plant, Sept 1980." FELTON, J. M. Division of Rules and Records. 80/12/16. ip. 07338:051.
- --8012290469 Forwards public version of "Evacuation Times Assessment for Diablo Canyon Nuclear Power Plant: Sept 1980: " in response to NRC 800702 request Includes App A re evacuation times for designated sub-areas.

 CRANC.P. A. Pacific Gas & Electric Co. 80/11/25. 1p. 07338:053.
- --8012290473 Public version of "Evacuation Times Assessment for Diable Canyon Nuclear Power Plants Sept 1980."

 * PRC Planning & Economics: Alan M. Voorhees & Associates Div. B0/09/30. 190pp. 07338:054.

- 8012300545 Advises that util agrees to assume responsibility for installation of early warning sys required by applicable federal regulations. Commitment will terminate on permanant cessation of operations at facility.

 BCHUYLER.J.O. Pacific Gas & Electric Co. 80/12/24. 3pp. 07346:265.
- Adjudicatory correspondence
- B011250100 Submits DS Fleischaker 801017 ltr to HR Denton as comments on proposed rule 10CFR50, "Domestic Licensing of Production & Utilization Facilities: Consideration of Degraded or Melted Core in Safety Regulations."

 REYNOLOGIJ. Center for Law in the Public Interest. 80/10/31. 1p. 07056:157.
- --8011250108 Requests; on behalf of Joint Intervenors to Diablo Canyon OL proceeding, that NRC prepare supplemental EIS considering environ consequences of Class 9 accidents. FLEISCHAKER, D. Fieischaker, D. 8. 80/10/17. 4pp. 07056:158.
- 8012020020 Ack receipt of 801017 requestion behalf of joint intervenors in OL proceeding for NRC action to prepare supplemental EIB re Class 9 accidents. Request will be treated under 10CFR2, 206.
 DENTON: H. R. Office of Nuclear Reactor Regulation, Director. 80/11/19. 1p. 07148: 307.
- ---BO12020023 Notice of D Fleischater request, on behalf of joint intervenors, for action under 10CFR2, 206, DENTON, H. R. Defice of Nuclear Reactor Regulation, Director. BO/11/19. 2pp. 07148:308.
- B012050453 Notifies that ASLAB has received encl ACRS B01i12 ltr to JF Ahearne re POLE studies on possible adverse interactions of nonsafety sys on plant safety Requests study status & relevance to current issues.
 BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/11/24, ip. 07173:316.
- B012290002 Request for extension to 801215 for filing Governor EO Brown findings of fact & conclusions of law re seismic proceedings. Granted for ABLAB on 801203 GEORGIOU.B. B. BROWN, H.H., LANPHER.L.C. California, State of, 80/12/02. ip. 07344:189.
- B012290161 Request for 1-wk extension to 801215 for filing Governor Brown findings of fact & conclusions of law NRC Ban Luis Obispo Mothers for Peace & PO&E agreed to extension NRC & PO&E also granted 1-wk extensions. OEGROIOU, B. S., BROHN, H. H., LAMPHER, C. California, State of. 80/12/02. 4pp. 07344:140.
- 8012080513 Submits contentions re motion for license to load fuel & conduct low power testing. Neither short nor long-term requirements of NUREO-0594 nor implamentation measures sufficient. Certificate of Svc ancl.
 FLEISCHAKER, D. Fleischaker, D. S. PHILLIPS, J. R., REYNOLDS, J. R. Center for Law in the Public Interast. 80/12/03, 16pp. 07183:106
- B012290120 Request for directed certification re application of NRC B00620 statement of policy re guidance for power reactor OLs. Bafety issues not included in NUREO-0694 should be admitted as contentions. H/Certificate of Byc. REYNOLOS, J. R.; FLEISCHAKER, D. Center for Law in the Public Interest, FLEISCHAKER, D. Fleischaker, D. S. B0/12/03. 33pp. 07344:010.
- 8012270662 Statement of subjs on which CA Governor Brown intends to participate per ASLB 801024 & 1105 orders. Concerns util motion for licenses for fuel loading & low power testing. Certificate of Svc encl.

 OEOROIOU, B. S. : DROWN, H. H. California, State of. BROWN, H. H. Hill Christopher & Phillips. 80/12/03 9pp. 07333:088.
- B012090286 Forwards I Aditya B01119 ltr to NRC, for placement in FDR & for svc on parties to proceeding.
 BISHOP,C.J. Atomic Safety and Licensing Appeal Panel. B0/12/04.
 19. 07201:0970
- --8012070287 Opposes licensing of facilities on basis of poor seismic design. 8=n Francisco Chronicle B01110 article encl.
 ADITYA. I. Affiliation Unknown. 80/11/19. 2pp. 07201;100.
- 8012290392 Notice of corrections to Joint Intervenors' statement of contentions & request for directed certification. Certificate of Svc encl. REYNOLDB.J.R. Center for Law in the Public Interest. 80/12/08. Spp. 07336:224.

- B012300(17 Hotion to stay proceeding on PQ&E motion for licenses for fuel loading & low power testing until NRC prepers EIS or alternatively, EIA & util submits environ rept. Certificate of Svc encl.
 GEORGIOU, E.S., BROWN.H.H. California, State of, BROWN.H.H. Hill Christopher & Phillips. 80/12/08. 7pp. 07356: 243.
- 8012110578 Rubmits resulution passed at erecutive board 800922 meeting. Resolution urges const expenditures be redirected toward conversion to safer-more societly acceptable fuel sources. CONRAD.C. Affiliation Unknown. 80/12/10. ip. 07223:107.
- B012290427 Forwards NUREG-0660; "NRC Action Plan Developed As Result of THI-2 Accident," Vols 1 & 2.W/o encl.
 KETCHEN, E. G. Hearing Branch 4. B0/12/10. 1p. 07337:005.
- B012290417 Response to ABLAB B01124 request for info re status of applicant studies on sys interactions & relevance to seismic issues in proceeding. Util sys interaction program is acceptable. Certificate of Svc encl.

 OLHSTEAD, W. J. Hearing Branch 2. 80/12/12. App. 07336:248.
- 8012170440 Forwards joint intervenors' proposed findings of fact & conclusions of law for reopened seismic evidentiary hearing before ASLAP.
 FLEISCHAMER.D. Fleischaker, D. S. 80/12/15, 1p. 07270:224.
- --B012170442 Joint intervenors' proposed findings of fact & conclusions of law for reopened seismic evidentiary hearing before ASLAB. Certificate of Svc encl. FLEIBCHAKER. D. Fleischaker. D. S. PHILLIPB. J. R., REYNOLDB. J. Center for Law in the Public Interest. B0/12/15. 45pp. 07270:225.
- 8012270407 Proposed findings of fact & conclusions of law re ASLAB Overtions 1-9 in seismic proceeding. DL should be denied, since util has not designed facility to withstand max vibratory accelerations. Certificate of Svc encl. BROW. E. Q. BROWN. H. H. California. State of. EROWN. H. H. Hill Christopher & Phillips. 80/12/15. 92pp. 07337:099.
- 8012300029 Forwards Comptroller General 801203 opinion disallowing procedural assistance in adjudicatory licensing proceedings. BOWERS.E.S. Atomic Safety and Licensing Board Panel. 80/12/16. ip. 07356:104.
- 8012290387 Forwards Commission 801117 rulemaking decision, "Authority for Access to or Control Over SNM (RM 50-7)." W/o encl. SWARTZ.L.L. Antitrust Division. 80/12/17. 1p. 07332:174.
- 8012300364 Joint Intervenors' response in support of CA Governor Brown motion to stay proceeding pending compliance w/MEPA EIB requirements. NEPA requires EIS re application to operate at less than full power. Certificate of Svc enci. REYMOLOS. J. R. FLEIBCHAKER. D. Center for Law in the Public Interest. FLEISCHAKER. D. Fleischater. D. 8. 80/12/18. 9pp. 07399:330.
- 8012290375 Response to intervenors' contentions re fuel loading & low power testing. Contentions 1 & 2 acceptable. All others unacceptable due to lack of specificity & subj matter beyond scape of proceeding. Certificate of Svc encl.

 JONES, B. H. Hearing Branch 2, 80/12/23, 17pp. 07332: 251.
- 8012300007 Notice of appearance in proceeding Certificate of Svc encl. JONES.B.H. Hearing Branch 2. 80/12/23 3pp. 07356:098.
- BO12300065 Response in apposition to CA Governor Brown 801208 motion to stay proceeding Motion fails to address legal requirements & prior court & Commission procedents directly contrary to intervenor position. W/Certificate of Svc. OLMSTEAD. N. J. Hearing Branch 4. 80/12/23, 11pp. 07356:173.
- 8012300183 Response to 801203 statement of subjs on which CA Governor Brown intends to participate. Only Subjs 3-5 & 12-15 appropriate. Certificate of Svc encl.

 JON-8.B.W. Hearing Branch 2. 80/12/23 12pp. 07356:290.
 - 12300352 Response to CA Governor Brown B01208 motion to require preparation of EIS. Opposes motion on grounds of untimeliness k noncompliance w/procedural requirements. Certificate of Byc encl.
 PURBUSH.H. H., NORTON.B. Pacific Oas & Electric Co. NORTON.B. Bruce Norton. B0/12/23. 12pp. 07359:071.
- 3012310283 Errata to joint intervenors' proposed findings of fact & conclusions of law Certificate of Syc encl. FLEISCHAKER.D. Fleischaker.D. S. 80/12/23. 7pp. 07370:058.

- 8012300403 Motion for extension to 810106 to file proposed brief & proposed findings of facts & conclusions of law in reope::ed seismic proceedings. Granted for ASLAB on 801224, KETCHEN.E. G. Hearing Branch 4. 80/12/24, 2pp. 07357:182.
- 8012310274 Forwards tables of authorities for util responses to joint intervenors statement of contention & request for directed certification. CRANE.F.A. Pacific Gas & Electric Co. 80/12/26. 10pp. 07341:316.

H. General correspondence

- 8012290010 Responds to 800601 ltrs to President Carter re const deficiencies at facilities & recent earthquake activity in area. Description of NRC role in plant const & info re ability of facilities to withstand earthquake encl. MIRAOLIA.F.J. Licensing Branch 3. 80/10/20. Spp. 07330:252.
- 8012040354 Responds to 801001 ltr expressing concerns re lack of evacuation plans & escape routes from South Bay area, in light of TMI accident & event of flooding. Util must complete TMI safety-related requirements prior to full power license, MIRAGLIA.F.J. Licensing Branch 3. 80/11/17, 3pp. 06915:001.
- 8012080416 Responds to 800430 postcard to JF Ahearne re licensing matters concerning facilities. Bafety issues resulting from THI accident will need to be resolved before licenses are issued. Discusses licensing procedures.

 MIRAGLIA, F. J. Licensing Branch 3, 80/11/20, 3pp. 06596:003.
- 8012070005 Responds to 790407 postcard to J Hendrie re concerns about facility & nuclear power in general NRC required to prepare detailed statement on listed environ issues Hearings held as part of licensing process. Forwards FEB. W/o encl. MIRAGLIA, F. J. Licensing Branch 3. 80/11/20. 3pp. 07187:001.
- --8012090011 Requests support for legislation to prevent const of nuclear power plants, Supports alternative energy development. HOGLMAN.J. Affiliation Unknown. 79704/09. ip. 07187:001.
- 8012120203 Responds to 800315 ltr opposing operation of facility due to lack of proper emergency preparedness & evacuation plans. NRC has reacted positively to improve safety of nuclear plants following THI accident.

 MIRAGLIA, F. J. Licensing Branch 3. 80/11/20. 4pp. 07187:001.
- --8012120212 Forwards map indicating weather & geography downwind from facility. Expresses concern re improper evacuation routes in case of meltdown. Facility should be converted to gas operation. M/o map.

 ANSDN.W.B. Affiliation Unknown. 80/03/31. 4pp.
- B01219030B Responds to 790329 request to reopen licensing hearings for facilities. Safety evaluation of plant compliance w/NUREG-0694 criteria performed. ABLB decision on Class 9 accidents will be made after submittal of supplemental SER. MIRAGLIA, F. Licensing Branch 3. 80/12/04. 2pp. 07183;001.
- --B012190316 Requests add1 investigation & hearing for licensing facilities following TMI-2 accident Expresses concern rapassibility of similar accident at facility. CLUCAS.J. Sierra Club. 79/03/29. 1p. 07183:001.
- 8012310588 FOIA request for all documents re-potential environ impacts associated w/fuel loading &/or low power testing of facilities.

 BROWN, H. M. Hill Christopher & Phillips. 80/12/08. 2pp. 07370:014.
- 8012310178 Responds to 790402 ltr expressing concern re-safe operation of facility.NRC requires all applicants to modify design & operation of facilities to conform to TMI-related requirements.

 MIRAGLIA/F. Licensing Branch 3. 80/12/11. 2pp. 07371:184.
- BOI2310584 Responds to FOIA request for all documents re-potential environ impacts associated w/fuel loading &/or low power testing of facilities.EI8 prepared in relation to request is available in PDR. FELTON-J.H. Division of Rules and Records. 80/12/22. 1p. 07370:013.

Q. Inspection reports, IE Bulletins & correspondence

- 8012170715 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No Written response required.
 ENGELKEM,R.H. Region 5, San Francisco, Office of the Director.
 80/10/24. 1p. 07266:085.
- BO12170416 Forwards IE Info Notice BO-3B, "Cracking in Charging Pump Casing Cladding." No written response required. EMBELKEN.R.H. Region 5, San Francisco, Office of the Director. BO/10/30. ip. 07264:053.
- 8012170857 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
 ENGELKEN.R.H. Region 5, San Francisco, Office of the Director.
 80/19/31. 1p. 07266:047.
- 8012120236 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ENCELKEN.R.H. Region 5. San Francisco, Office of the Director. 80/11/06. ip. 07227:334.
- 8012030934 Forwards lE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 80/11/07. ip. 07150:183.
- B012080632 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
 EMOELKFIR.R. H. Region 5, San Francisco, Office of the Director.
 B0/11/10. 1p. 07183:032.
- 8012090034 Forwards IE Insp Rept 50-275/80-20 on 801001-31.No noncompliance noted. GREMBIJL. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/11/13. 2pp. 07197:312.
- --8012090036 IE Insp Rept 50-275/80-20 on 801001-31. No noncompliance noted Major areas inspected preoperational testing operator training fire protection/prevention & fuel loading.
 YOUNO, T., BAGAQLIO, M. Region 5. San Francisco, Office of the Director. STERNBERO, D.M. Region 5. San Francisco, Reactor Operations Nuclear Support Branch, 80/11/12, 5pp. 07197:314.
- B012040230 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.
 EMPELKEN.R.H. Region 5, San Francisco, Office of the Director.
 80/11/14, 1p. 07158:151.
- 8012040487 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required.
 EMPELMEN.R.H. Region 5, San Francisco, Office of the Director.
 80/11/21. 1p. 07167:123.
- 8012160097 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraviic Snubber Fluid." No response required. ENGELKFN.R.H. Region 5, San Francisco, Office of the Director. 80/11/24. ip. 07262:100.
- 8012290008 Responds to IE Bulletin 80-15, "Possible Loss of Emargency Notification Sys W/Loss of Offsite Power." Administrative Procedure NPAP C-11 will be revised to incorporate Item 5. Related correspondence.

 CRANE, P. A. Pacific Gas & Electric Co. 80/11/25. 2pp. 07344; 201.
- BO12160124 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. ENGELKEN.R.H. Region 5, Sen Francisco, Office of the Director. BO/11/26. 1p. 07262:076.
- B012270542 Completes response to IE Bulletin 79-02 re concrets expansion anchor bolts used in pips support base plate design. Rept on insp. tests, analysis & rework of seismic Category 1 pips supports encl. Related correspondence. GRANE, P. A. Pacific Gas & Electric Co. 80/12/03. 475pp. 07333:144.
- B012300466 Requests relief from 10CFR50.53a(g)(4), by specifying that ASME boiler & pressure vessel code, Section XI, 1977 edition w/addenda through Bummer 1978, effective B01101; be applicable code for first lo-yr inservice insp Interval, CRANE, P.A. Pacific Oas & Electric Co. 80/12/23, 2pp. 07347:066,

- S. Reportable occurrences, LERs & related correspondence
- 8012160382 Finel deficiency report re cracks in Pullman field welds, originally reported 790503. Cause attributed to improper control of welding parameters. Unacceptable welds repaired or entire joint modified improved welding procedures now used. CRANE, P. A. Pacific Gas & Electric Co. 80/12/09. 3pp. 07187:001.
- DOCKET 50-277 PEACH SOTTOM ATOMIC POWER STATION, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 9012050489 informs that mods will be made to emergency notification sys & health physics network equipment. NRC will have lamps installed on emergency telephones in all control rocos, technical support ctrs & amergency operations facilities. GRIER. B. H. Region 1. Philadelphia, Office of the Director. 90/11/14. 2pp. 07174:255.
- 8012170579 Forwards Suppl 4 to safety evaluation of facility fire protection program.
 REID.R.W. Operating Reactors Branch 4. 80/11/24. 2pp. 07269: 202.
- --80121704B7 Suppl 4 to safety evaluation of fire protection program for facility. List of open items encl.

 4 Operating Reactors Branch 4. 80/11/24, Gpp. 07269: 204.
- B012010249 Forwards revised cover, title page & pages to Hay 1978 physical security plan. Revisions withheld (ref 10CFR2, 790). Afrikavit enci.
 BRADLEY, E. J. Philadelphia Electric Co. 80/11/25, App. 95097: 125.
- 8012240438 Informs of no objections to recording conversations on dedicated phone line connecting facility to NRC operations ctr in Bethesda. Detailed description of task to be accomplished required.

 STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/12/02. 1p. 07324:174.
- 8012290488 Ack receipt of 801005 ltr transmitting changes in facility security plan. Changes are consistent w/10CFR50.54(p) & do not decrease plan safeguard effectiveness.

 REID/R.W. Operating Reactors Branch 4. 80/12/05. 2pp. 07335:140.

9. Adjudicatory correspondence

- 80i2t60i44 Forwards 8EC Form 10-0, Quarterly Financial Rept & supporting mgt comments, in response to NRC 790921, 1109 & 800811 requests for inform resignificant financial developments affecting utils in restart proceeding.

 CONDON, V. H. General Public Utilities. 80/11/26. 3pp.
- --8012160154 Quarterly Financial Rept Bept 1980 & supporting mgt comments 4 General Public Utilities. 80/11/14. 44pp.
- 8012190488 Notice of reconstitution of AGLAB. TS Moore appointed chairman & JH Buck & WR Johnson, members.

 BIGHOP, C. J. Atomic Safety and Licensing Appeal Panel. 80/12/05. ip. 07287:036.
- P. Operating license stage documents & correspondence
- 8012160090 Ltr to operating glant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be not. EISERHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012220338 Ltr to all CP & OL holders for BURs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENMUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012220563 Ltr to all power reactor licensess forwarding NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be mat must be sent within 45 days. W/o encl. EISERMUT.D. G. Division of Licensing. 80/11/13. 15,
- 8012010074 Forwards Amends 75 & 74 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability.

 REID.R.W. Operating Reactors Branch 4, 80/11/19, 2pp. 06916:001.

DOCKETED ITEMS

- --8012010078 Amends 75 & 74 to Licenses DPR-44 & DPR-56, respectively, adding operability & surveillance requirements for new seismic annitoring instrumentation sys being installed at facility.

 REID.R.H. Operating Reactors Branch 4. BO/11/19, 20pp. 04916:001.
- --8012010081 Safety evaluation supporting Amends 75 & 74 to Licenses PPR-44 & DPR-56 respectively.

 Office of Nuclear Reactor Regulation, Director. 80/11/19. 2pp. 06916:001.
- --8012010083 Notice of issuance & availability of Amenés 75 & 74 to Licenses DPR-44 & DPR-36, respectively. REIO.R.M. Operating Reactors Branch 4. 80/11/19. 2pp. 06916:001.
- B012020398 Proposes revised schedule for upgrading accustic sys for power operating relief valves & safety valves, consistent w/order amending OLs BPR-44 & DPR-55 per IE Builetin 79-018. DALTRUFF,S.L. Philadelphia Electric Co. B0/11/26. 2pp. 07149:303.
- 8012040393 Forwards "Primary Reactor Containment Integrated Leak Rate Test." ALDEN. N. M. Philadelphia Electric Co. 80/12/01, 1p. 06915:001.
- --8012040377 "Primary Reactor Containment Integrated Leak Rate Test."
 4 Philadelphia Electric Co. 80/07/28. 200pp. 06915:001.
- 8012220485 Responds to 800711 memo requesting that Ofr of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION, M.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & surmary of iE survey on iow level waste at 51 reactors Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012150141 Forwards addl amend fee for 800930 amend application.per NRC BO1103 ltr. BRADLEY.E.J. Philadeiphia Electric Co. BO/12/05. 2pp. 07240:082.
- BO12240196 Forwards Amends 76 & 75 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability.
 REID,R.W. Operating Reactors Branch 4. 80/12/10. 3pp. 07325:039.
- --8012240202 Amends 76 & 75 to Licenses DPR-44 & DPR-56 respectively, revising Tech Specs for reactor protection sys response time for both units & operating limit min critical power ratio for Unit 2. REID, R.W. Operating Reactors Branch 4. B0/12/10. 7pp. 07325:041.
- --8012240207 Gafety evaluation supporting Amends 76 & 75 to Licenses DPR-44 & DPR-56, respectively. * Office of Nuclear Reactor Regulation, Director, E0/12/10, 3pp. 07325:049.
- --8012240210 Notice of issuance & availability of Amends 76 & 75 to Licenses DPR-44 & DPR-56, respectively.
 REID-R.U. Operating Reactors Branch 4. 80/12/10. 2pp. 07325:052
- 80(2230493 Responds to 80(00) itr requesting results of scram system-evaluation re design & performance criteria developed by BNR owners group. Mode required: extension of scram discharge vois & provision of redundant isolation valves.

 DALTROFF, D. 9. Philadelphia Electric Co. 80/12/16. 2pp. 07313:212.
- 8012310310 Responds to NUREC-0737. "Clarification of THI Action Flan Requirements." Schedule of implementation dates & proposed adjustments in NUREC-0737 schedule or criteria enci. "ALTROFF.S.L. Philadeiphia Electric Co. 80/12/22, 12pp. "309:00].
 - 310327 Responds to NRC 801113 ltr requesting confirmation that plementation dates in NUREC-0619 will be met. Response will submitted 810122. Mods have been implemented to feedwater tile & control rod drive return line norzle.

 _TROFF, 8.1. Philadelphia Electric Co. 80/12/24. 2pp. 07369:172.

- Q. Inspection reports, IE Bulletins & correspondence
- 8012160085 FOIA request for documents re experimental use of Dow NB-1 solvent at Dresden 1 & Peach Bottom including disposals & wastes. MCCULLCOUGH, E. R. McCuilaugh, E. R. 80/10/31. 1p. 07261: 336.
- 8012300045 Ack receipt of 801014 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-03 & 50-278/80-03.
 BRUNNERS.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/05. lp. 07356:112.
- --8012300051 Responds to NRC 800919 ltr re violations noted in IE Insp Repts 50-277/80-03 & 50-278/80-03. Corrective actions: procedural change to startup checklist. App 8 uithheld (ref 10CFR2, 790). DALTROFF, E. L. Philadelphia Electric Co. 80/10/14. 3pp. 07356:113.
- --8012300058 Forwards IE Insp Repts 50-277/80-03 & 50-278/80-03 on 800201-29 & notice of violation. Apps A & B. App B withheld (ref 10CFR2. 790).

 RHWNER.E.J. Region 1, Philadeiphia, Reactor Operations Nuclear Support Branch. 80/09/19. 3pp. 07356:116.
- --B012300063 Notice of violation from insp on 800201-29.

 Region i. Philadelphia, Office of the Director. 80/09/16. ip. 07386:119.
- --B012300070 Notice of violation from insp on 800201-29. Details withheld (ref 10CFR2.790).

 ** Region i. Philadeiphia. Office of the Director. B0/09/16. ip. 07395:120.
- --8012300080 IE Insp Repts 50-277/80-03 & 50-278/80-03 on 800201-29. Noncompliance noted:failure to use temporary monitors or initiate orderly shutdown w/offgas monitoring sys out of syc. Portions withheld (ref 10CFR2, 790).
 ORICHNAM, E. O., COMOILL, C. J., BLOUGH, A. P. Region 1, Philadelphia, Office of the Director. 80/09/16 11pp. 07336:121.
- 8012120093 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230:245.
- B0121903:0 Informs util of issuance of new NRC personnel identification hadges, effective after 801130. Example encl. MARTIN. H. J. Region 1, Philadeiphia, Safeguards Branch. 80/11/06. 2pp. 07286:110.
- 8012030790 Forwards IE Info Notice 80-40, "Excessive Nitrogen Bupply Pressure Actuates Safety Reliaf Valve Operation to Cause Reactor Depressurization " No written response required. ORIER. B. H. Region 1. Philadelphia, Office of the Director. 80/11/07. 1p. 07150:211.
- B0120B0434 Forwards IE Info Notice B0-41, "Failure of Buing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. B0/11/10, 1p. 07182:327.
- 8012040053 Formards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, 8. H. Region I. Philadelphia. Office of the Director. 80/11/14. p. 07170:006.
- 8012220626 Advises that written response is required to IE Bulletin 80-23, "Failures of Solenoid Vaives Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.

 GRIER, B. H. Region i, Philadelphia, Office of the Director. 80/11/19. ip. 07293:134.
- 8012040488 Forwards IE Builetin 80-24, "Prevention of Damage Due to Hater Leakage Inside Containment," Unitten response required. Requests into an manpower expended. ORIER. B. H. Region i. Philadelphia. Office of the Director. 80/11/21. 2pp. 07169:160.
- 8012030388 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER, B.H. Region i, Philadelphia, Office of the Director, 80/11/24. ip. 07174:077.

- B012020358 Proposes revised schedule for upgrading acoustic sys for power operating reliaf valves & safety valves.consistent w/order amending OLs DPR-44 & DPR-55 per IE Bulletin 79-018. DALTROFF,B.L. Philadelphia Electric Co. 80/11/26. 2pp. 07148:303.
- 8012160332 Responds to FOIA request for documents re experimental us of Dow NS-1 solvent at Dresden 1 & Peach Bottom including disposals & wastes. Use of Dow NS-1 solvent was not considered experimental. Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 80/11/26. 2pp. 07261:335.
- ---8012160090 Responds to 801006 request for info re decontamination operations of experimental Dresden test loop & Peach Bottom regenerative heat exchangers BNL rept re chelating agent study encl.

 BROWKING.R.E. Division of Waste Management. 80/10/24. 2pp.
- --8012160093 Requests info re decontamination operations of experimental Drasdan test loop & Peach Bottom regenerative heat exchangers. Also requests BRL rept re chelating agent study. Related documentation encl.

 DREY, L. A. Affiliation Unknown. 80/10/05. 9pp.
- --B012160103 Submits info in response to TI 2515/8 re cleanup sys component contamination. Lists components decontaminated by site personnel & Dow Nuclear Sucs following physical removal from Peach Bottom reactor cleanup sys.

 MCCARE, E.C. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/05/19. 2pp.
- --8012160198 Forwards IE Insp Repts 50-277/78-06 & 50-278/78-06 on 780329 & 30.No noncompliance nobed.

 BRUNNER, E. J. Reglon I, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/05/03. 2pp.
- --B012160113 IE Insp Repts 50-277/78-06 & 50-278/78-06 on 780329 & 30. No noncompliance noted. Major areas inspected: chemical decontamination of reactor water cleanup sys regenerative heat exchangers & plant operations.

 GREENMAN.E. O. Region i, Philadelphia, Office of the Director, MCCABE, E.C. Region i, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/05/02. 6pp.
- --B012160119 Discusses 780519 request for determination of acceptabllity re lack of info on decontamination solutions used at Peach Bottom, Licensee lack of info on NB-1 solution concentration & composition is unacceptable, WOODRUFF,R.W. Office of Inspection & Enforcement, Office of the Director. 78/07/25. 2pp.
- R. Periodic operating reports & related correspondence
- B012300070 Forwards final post-operational Repts 13 & 14 re Conowingo Pond ecology for Jul-Dec 1979 & Jan-Apr 1980, respectively. WILLSEY, W. B. Philadelphia Electric Co. B0/11/28. ip. 07353:058.
- --8012300275 "Post-Operational Rept 13 on Ecology of Conceings Pond, Jul-Dec 1977." A Moddy Run Ecological Laboratory, RMC Ecological Div. B0/02/29. 207pp. 07353:059.
- --8012300282 "Post-Operational Rept 14 on Ecology of Concuingo Pond, Jan-Apr 1980." * Muddy Run Ecological Laboratory, RMC Ecological Div. 80/08/31. 166pp. 07353:267.
- B012160267 Forwards "Thermal Mapping Rept 80-12 for 801107" & "Thermal Mapping Rept 80-13 for 801113." WILLEEY, W. B. Philadelphia Electric Co. 80/12/05, ip. 07261:338.
- --8012160272 "Thermal Mapping Rept 80-12 for 801107."

 * Philadelphia Electric Co. 80-12. 80/12/05. 4pp. 07261:339.
- --8012160276 "Thermal Mapping Rept 80-13 for 801113."

 * Philadelphia Electric Co. 80-13. 80/12/05. 4pp. 07261:343.
- 8012140472 Forwards monthly operating repts for Nov 1980. CODNEY.M.J. Philadelphia Electric Co. 80/12/10. 1p. 07255:320.
- --8012160475 Monthly operating rapts for Nov 1980.
 ALDEN, W. M. Philadelphia Electric Co. 80/12/10. 9pp. 07255;321.
- 8012300618 Forwards "Thermal Mapping Rept 80-14 for 801121 for Thermal Monitoring Requirements."
 WILLSEY, W. B. Philadelphia Electric Co. 80/12/17. 1p. 07346:187.

- --B012300624 "Thermal Mapping Rept 80-14 for B01121 for Thermal Manitoring Requirements."

 * Philadelphia Electric Co. 80/12/19. 4pp. 07346:188.
- S. Reportable occurrences, LERs & related correspondence
- BO12040439 RO 2-80-29/1P: on BO113, while operating at full power reactor core isolation cooling sys declared inoperable due to inability to trip turbine. Caused by misadjustment of valve limit switch. Switch readjusted & turbine tested.

 ULLRICH. W. T. Philadelphia Electric Co. 80/11/14. 3pp. 06915:001.
- 8012010440 Forwards LER 80-027/017-0.
 GOONEY, M. J. Philadelphia Electric Co. 80/11/20. 3pp. 06915:001.
- --B012010455 LER B0-027/01T-0: on B01106, main steam bypass valve 3 exhibited erratic operation. Caused by broken lug connector in wiring from bypass valve linear variable differential transformer to valve control circuitry.

 COUNEY, M. J. Philadelphia Electric Co. 80/11/20. 1p. 06915:001.
- 8012010472 LER 80-025/03L-O: on 801103, setpoints on DPIS 2-13-83 & DPIS 2-13-84 (redundant reactor core isolation cooling turbing steam line high flow DPIS instrumentation) exceeded Yech 8pecs. Caused by setpoint drift. Instruments recalibr. COUNEY, M. J. Philadelphia Electric Co. 80/11/20, 1p. 06915:001.
- 8012010289 RG 3-80-27/IP: on 801124 while operating at 97% power during HPCI surveillance, steam to turbine valve continued driving in close direction causing fuses to blow. Caused by torque switch failure. Closing switch readjusted.

 ULLRICH.W.T. Philadelphia Electric Co. 80/11/24. 2pp. 06915:001.
- 8012040429 RD 2-80-31/IP:on 801122.minor pressure variations in offgas processing & sampling sys resulted in gradual flooding of sample piping leading to offgas radiation monitors. Caused by power reduction. Offgas radiation monitoring sys installed.

 ULLRICH:N.T. Philadelphia Electric Co. 80/11/26. 3pp. 06915:001.
- 8012090464 Forwards LER 80-029/01T-0. CODNEY, M. J. Philadelphia Electric Co. 80/11/26. 2pp. 07206: 221.
- --8012090470 LER 80-029/01T-0:on 80ill3-reactor core isolation cooling sys declared inoperabla. Caused by turbine trip valve switch being out of adjustment. Switch readjusted & tested.

 COONEY, M. J. Philadelphia Electric Co. 80/11/26. 1p. 07206:223.
- 8012070455 LER 80-028/03L-O:on 801121, setpoint of main steam low pressure switch PS 2-2-1348 dropped below Tech Spec requirements. Caused by drift of Barksdale model B2T-A1288. Instrument recalibr & tested.

 COONEY, M. J. Philadelphia Electric Co. 80/12/03. 1g. 07202; 355.
- 8012040419 RG 80-030/BIP: on 801124, annunctator, "Turus Vent Valves Open," alarmed. Caused by closed needle valve in supply to boot seal. Needle valve was inadvertently brushed against & closed. Needle valve reopened.

 ULLRICH. N.T. Philadelphia Electric Co. 80/12/04. 2pp. 06915:001.
- 8012180247 Forwards LER 80-030/017-0. COONEY: M. J. Philadelphia Electric Co. 80/12/07. 3pp. 03794:001.
- --B0121B0250 LER 80-030/01T-0:on B01124, needle valve in air supply to boot seal of inboard isolation valve A0-2511 found closed. Gaused by damage during const work. Valve reopened & full boot seal pressure restored.

 CODREY, H. J. Philadelphia Electric Co. B0/12/09. ip. 03794:004.
- 8012230352 Forwards LER 80-031/01T-0. COUNEY, M. J. Philadelphia Electric Co. 80/12/12. 3pp. 07318: 247.
- 8012230359 LER G0-019/03X-1: on 800904, during surveillance testing at full power, reactor core isolation cooling outboard steam supply isolation valve MO-2-13-16 failed to close Caused by improperly functioning switch on Linitargue operator. CGONEY, M. J. Philadelphia Electric Co. 80/12/17. 1p. 07183:00i.

- DOCKEL 30-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
 F. Becurity, medical, emergency & fire protection plans
- 8012050489 Informs that mods will be made to emergency notification sys 2 health physics network equipment, NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs 2 emergency operations facilities. GRIER, B. H. Region i, Philadelphia, Office of the Director. 80/11/14. 2pp. 07174:255.
- 8012170679 Forwards Suppl 4 to safety evaluation of facility fire protection program.
 REID.R.W. Operating Reactors Branch 4. 80/11/24. 2pp. 07269:202.
- --8012170687 Suppl 4 to safety evaluation of fire protection program for facility. List of open itoms encl.

 * Operating Reactors Branch 4. 80/11/24. 3pp. 07269:204.
- BO12010249 Forwards revised cover title page & pages to May 1978 physical security plan.Revisions withheld (ref 10CFR2.790). Affidavit encl. BRADLEY, E. J. Philadelphia Electric Co. B0/11/25. 4pp. 95097: 125.
- 801224045B Informs of no objections to recording conversations on dedicated phone line connecting facility to NRC operations ctr in Bethesda. Detailed description of task to be accomplished required.

 STELLO.V. Office of Inspection & Enforcement. Office of the Director. 80/12/02. ip. 07324:174.
- G012270488 Ack receipt of B01006 ltr transmitting changes in facility security plan. Changes are consistent w/10CFR50, 54(p) & do not decrease plan safeguard effectiveness.

 REID.R.W Operating Reactors Branch 4. B0/12/05. Zpp. 07395:140.
- G. Adjudicatory correspondence
- 8012160144 Forwards SEC Form 10-0 Quarterly Financial Rept & supporting mgt cumments, in response to NAC 790921, 1109 & 800811 requests for info re significant financial developments affecting utils in restart proceeding.

 COUNDN, V. H. General Public Utilities. 80/11/26. 3pp.
- --8012160154 Quarterly Financial Rept Sept 1980 & supporting mgt comments.

 * Qeneral Public Utilities. 80/11/14. 44pp.
- 8012190488 Notice of reconstitution of ASLAB.TS Moore appointed chairman & JH Buck & MR Johnson, members. BISHOP.C. J. Atomic Safety and Licensing Appeal Panel. 80/12/05. ip. 07287:036.
- P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensess,OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl i implementation dates will be set. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP & QL holders for BiRs re requirement for implementation of QDYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISEKHUT.D. G. Division of Licensing. 80/11/04. 4pp.
- B012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BNR Feedvater Novice & Control Rod Drive Return Line Navile Cracking." Confirmation that implementation dates will be net must be sent within 45 days. N/O encl. EISENRUT, D. G. Division of Licensing. 80/11/13. 1p.
- 8012010074 Forwards Amends 75 & 74 to Licenses DPR-44 & BPR-56, respectively, safety evaluation & notice of issuance & availability.

 {EID.R.W. Operating Reactors Branch 4. 80/11/17. 2pp. 06916:001.
 - 3012010078 Amends 75 & 74 to Licenses BPR-44 & BPR-56, respectively, adding operability & surveillance requirements for new seismic monitoring instrumentation sys being installed at facility.

 REID,R W. Operating Reactors Branch 4, 80/11/19, 20pp. 06916:001.

- --80120100B1 Bafety evaluation supporting Amends 75 & 74 to Licenses DPR-44 & DPR-56, respectively.

 4 Office of Nuclear Reactor Regulation, Director. 80/11/19, 2pp. 06916:001.
- --B0120100B5 Notice of issuance & availability of Amends 75 & 74 to Licenses DPR-44 & DPR-56 respectively. REID.R.W. Operating Reactors Branch 4. B0/11/19. 2pp. 06916:001.
- 801202033B Proposes revised schedule for upgrading accustic sys for power operating reliaf valves & safety valves consistent w/order amending GLs DPR-44 & DPR-36 per IE Bullattin 79-01B. DALTROFF,S.L. Philadelphia Electric Co. 90/11/26. 2pp. 07148:303.
- B012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IF survey, DENIGN. H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 299.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Systems Branch. 80/11/06. Spp.
- 8012150141 Forwards add1 amend fee for 800730 amend application.per NRC 801103 ltr. 8RADLEY, E. J. Philadelphia Electric Co. 80/12/05, 2pp. 07240:082,
- 8012240196 Forwards Amends 76 & 75 to Licenses DPR-44 & DPR-56, respectively safety evaluation & notice of issuance & availability, REID.R.M. Operating Reactors Branch 4. 80/12/10. 3pp. 07325:039.
- --B012240202 Amends 76 & 75 to Licenses DPR-44 & DPR-56, respectively, revising Yech Specs for reactor protection sys response time for both units & operating limit nin critical power ratio for Unit 2.

 REID,R. N. Operating Reactors Branch 4. B0/12/10. 7pp: 07323:041.
- --B012240207 Safety evaluation supporting Amends 76 & 75 to Licenses DPR-44 & DPR-56 respectively. 4 Office of Nuclear Reactor Regulation, Director, 80/12/10, 3pp. 07325:049.
- --8012240210 Notice of issuance & availability of Amends 76 & 75 to Licenses DPR-44 & DPR-56, respectively. REIO.R.U. Operating Reactors Branch 4. 80/12/10. 2pp. 07325:052.
- 8012230493 Responds to 801001 ltr requesting results of scram system-evaluation re design & performance criteria developed by BIR owners group. Mods required: extension of scram discharge vols & provision of redundant isolation valves.

 DALTROFF, D. O. Philadelphia Electric Co. 80/12/16. 2pp. 07313: 212.
- 8012310310 Responds to NUREQ-0737. "Clarification of TMI Action Plan Requirements." Schedule of implementation dates & proposed adjustments in NUREQ-0737 schedule or criteria encl. DALTROFF.S.L. Philadelphia Electric Co. 80/12/22. 12pp. 07309:001.
- B012310327 Responds to NRC 801113 ltr requesting confirmation that implementation dates in NUREG-0619 will be met.Response will be submitted 810122.Mods have been implemented to feedwater nozzle & control rod drive return line nozzle.

 DALTROFF, S. L. Philadelphia Electric Co. 80/12/24. 2pp. 07369:172.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012160085 FOIA request for documents re experimental use of Dow NE-1 solvent at Dresden i & Peach Bottom including disposals & wastes.

 MCCULLOUGH, E. R. McCullough, E. R. 80/10/31. 1p.
- 8012300045 Ack receipt of 801014 1tr informing NRC of steps taken to correct violations noted in IE insp Repts 50-277/80-03 & 50-278/80-03. BRUNNIER,E.J. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch. 80/11/05. 1p. 07354:112.

- --8012300051 Responds to NRC 800919 1tr re violations noted in IE Insp Repts 50-277/80-03 & 50-278/80-03. Corrective actions: procedural change to startup checklist. App B uithheld (ref 10CFR2, 790). DALTROFF/B. L. Philadelphia Electric Co. 80/10/14. 3pp. 07356:113.
- --8012300058 Furwards IE Insp Repts 50-277/80-03 & 50-278/80-03 on 800201-29 & notice of violation.Apps A & B.App B withheld (ref 10CFR2.770).
 BROWNER,E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/19. 3pp. 07356:116.
- --8012300063 Notice of violation from insp on 800201-29, * Region i, Philadelphia, Office of the Director. 80/09/16. ip. 07356:119.
- --8012300070 Notice of violation from insp on 800201-29. Details withheld (ref 10CFR2. 790).

 Region 1: Philadelphia: Office of the Director. 80/09/16. 1p. 07396:120.
- --8012300080 IE Insp Repts 50-277/80-03 & 50-278/80-03 on 800201-29.
 Noncompliance noted: failure to use temporary monitors or initiate orderly shutdown w/offgas monitoring sys out of syc.Portions withheld (ref 10CFR2.790).
 GREEN/ANI.E. O., CONVILL.C. J., BLOUGH.A. P. Region 1, Philadelphia, Office of the Director. 80/09/16 11pp. 07336:121.
- 8012120393 Forwards IE Builetin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ORIER.B.H. Region 1. Philadelphia, Office of the Director. 80/11/06. 1p. 07230:245.
- 8012190330 Informs util of issuance of new NRC personnel identification badges: effective after 801130. Example encl. MARTIN.N. J. Region i, Philadelphia, Safeguards Branch. 80/11/06. 2pp. 07286:110.
- 8012030790 Forwards IE Info Notice 80-40, "Excessive Nitragen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. GRIER, B. H. Region i. Philadelphia, Office of the Director. 80/11/07. 1p. 07150:211.
- 8012080454 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/10. 1p. 07182:327.
- 8012040093 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/14. 1p. 07170:006.
- 8012220526 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.
 GRIER, B. H. Region i. Philadelphia, Office of the Director. 80/11/19. ip. 07293:134.
- 8012040488 Forwards IE Bulletin 80-24, "Prevention of Damage Duo to Water Leakage Inside Containment." Unitten response required Requests info on manpower expended. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07167:160.
- B012050588 Forwards Info Notice B0-42, "Effect of Radiation on Hydraulic Bnubber Fluid." No written response required. ORIER, B.H. Region i. Philadelphia, Office of the Director. B0/11/24. 1p. 07174:077.
- 8012020398 Proposes revised schedule for upgrading acoustic sys for gower operating relief valves & safety valves.consistent w/order amending OLs DPR-44 & DPR-56 per IE Bulletin 79-018. DALTROFF, S. L. Philadelphia Electric Co. 80/11/26. 2pp.
- 8012160092 Responds to FQIA request for documents re experimental use of Dow NS-1 solvent at Dresden 1 & Peach Bottom including disposals & wastes. Use of Dow NS-1 solvent was not considered experimental. Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 80/11/26. 2pp.
- --B012160070 Responds to B01006 request for info re decontamination operations of experimental Dresden test loop & Peach Bottom regenerative heat exchangers BNL rept re chelating agent study encl.

 BROWNING.R.E. Division of Naste Management. B0/10/24. 2pp.

- --B012160093 Requests info re decontamination operations of experimental Dresden test loop & Peach Bottom regenerative heat axchangers, Also requests BNL rept re chelating agent study. Related documentation encl. DREY*L.A. Affiliation Unknown. B0/10/05. 9pg.
- --B012160105 Submits info in response to TI 2515/8 re cleanup syscomponent contamination. Lists components decontaminated by site personnel & Dew Nuclear Svcs following physical removal from Peach Sottom reactor cleanup sys. MCCABE.E. C. Region 1, Philadelphia, Resctor Operations Nuclear Support Branch. 78/05/19. 2pp.
- --8012160108 Forwards IE Insp Repts 50-277/78-06 & 50-278/78-06 on 780329 & 30 No noncompliance noted. BRU.NER.E J. Region I. Philadelphia. Reactor Operations Nuclear Bupport Branch. 78/03/03. 2pp.
- ---8012160113 IE Insp Repts 50-277/78-05 & 50-278/78-06 on 780329 & 30.No noncompliance noted Major areas inspected: chemical decontamination of reactor water cleanup sys regenerative heat exchangers & plant operations.

 OREENMAN.E. G. Region 1. Philadelphia, Office of the Director. MCCABE.E.C. Region t. Philadelphia, Reactor Operations Nuclear Support Branch. 78/05/02. 6pp.
- --8012160119 Discusses 780519 request for determination of acceptability re lack of info on decontamination solutions used at Peach Bottom. Licensee lack of info on NS-1 solution concentration & composition is unacceptable. WOODHUFF.R.W. Office of Inspection & Enforcement, Office of the Director. 78/07/25. 2pp.
- R. Periodic operating reports & related correspondence
- 8012300270 Forwards final post-operational Repts 13 & 14 re Conowingo Pond acology for Jul-Dec 1979 & Jan-Apr 1980, respectively. WILLSEY, W. B. Philadelphia Electric Co. 80/11/28. 1p. 07353:058.
- --8012300275 "Post-Operational Rept 13 on Ecology of Conowingo Pond, Jul-Dec 1979." * Muddy Run Ecological Laboratory, RMC Ecological Div. 80/02/29, 209pa. 07353:059.
- --8012300282 "Post-Operational Rept 14 on Ecology of Conowingo Pond, Jan-Apr 1780." • Muddy Run Ecological Laboratory, RMC Ecological Div. 80/08/31, 164pp, 07353:267.
- B012i60267 Forwards "Thermal Kapping Rept 80-12 for 801107" & "Thermal Mapping Rept 80-13 for 801113."
 WILLSEY.W.B. Philadelphia Electric Co. 80/12/05. ip. 07261:338.
- --8012160272 "Thermal Mapping Rept 80-12 for 801107."

 * Philadelphia Electric Co. 80-12. 80/12/05. 4pp. 07261:339.
- --8012160276 "Thermal Happing Rept 80-13 for 801113."

 * Philadelphia Electric Co. 80-13. 80/12/05. 4pp. 07261:343.
- B012160472 Forwards monthly operating ropts for Nov 1980. COONEY, M. J. Philadelphia Electric Co. 80/12/10. 1p. 07255:320.
- --8012160475 Monthly operating repts for Nov 1980.
 ALDEN, M. M. Philadelphia Electric Co. 80/12/10, 9pg. 07255;321,
- 8012300618 Forwards "Thermal Mapping Rept 80-14 for 801121 for Thermal Monitoring Requirements."
 WILLSEY, M. B. Philadelphia Electric Co. 80/12/19. 1p. 07346:187.
- --8012300624 "Thermal Mapping Rept 80-14 for 801121 for Thermal Monitoring Requirements."

 * Philadelphia Electric Co. 80/12/19. 4pp. 07346:188.
- S. Repartable occurrences. LERs & related correspondence
- 80120404ii RO 3-80-26/IP: on 801114, operating at full power HPCI flow controller revealed downscale output & declared inoperable.

 Caused by unidentified electronic failure in controller.

 Controller replaced & tested satisfactorily.

 ULLRICH.W.T. Philadelphia Electric Co. 80/11/14, 3pp. 06915:001.
- 8012100490 Forwards LER 80-026/01T-0. GUDNEY, M. J. Philadelphia Electric Co. B0/11/26, 2pp. 07187:001.

- --8012100499 LER 80-024/017-0: on 801114. HPC1 flow controller showed downscale output, HCP1 doclared inoperable. Caused by failed zoner diode & resistor regulating in output drift. Parts replaced.
 CODIECV. IS. J. Philadelphia Electric Co. 80/11/26. 1p. 07187:001.
- 8012090441 LER 80-018/03X-1: on B00802, reactor water cleanup sys return isulation valve M0-3-12-68 failed to close by control switch. Caused by valve pressure seal leak in motor of Limitorque operator SMS-0-10. Motor replaced & seal repaired. COUNEY, N. J. Philadelphia Electric Co. B0/12/01. ip. 07203: 070.
- 8012170633 Forwards LER 80-027/017-0. CD0NEY.N.J. Philadelphia Electric Co. 89/12/09. 2pp. 07264:335.
- --B012170541 LER B0-027/01T-0: an B01124-HPC1 velve Hd-3-23-14 kept driving in closed direction causing valve fuses to blow. Probably caused by improper adjustment of valve closing torque switch. Valve disassambled inspected & bested. COCHEV.M. J. Philadelphia Electric Co. B0/12/09. 1p. 07264; 337.
- 8012310320 Forwards LER G0-028/01T-0. COONEY, M. J. Philadelphia Electric Co. 80/12/17. 2pp. 07369: 048.
- --B012310323 LER B0-028/01T-0: on 801293, HPCI steam supply valve, 1(0-3-23-14, failed to fully close. Caused by HPCI sys being inoperable for valve insp. Valve reassembled & tested. CCC(REY, H. J. Philadelphia Electric Co. 80/62/17. 1p. 07369: 050.
- POCKET 80-280 SURRY POWER STATION, UNIT 1 F. Beturity, medical, emergency & fire protection plans
- B012030B12 Requests add1 info & commitments re emergency plan submitted B00630 to complete onsite emergency program. VARQA:G.A. Uperating Reactors Branch 1. B0/11/13. 19pp. 07149:143.
- E012050180 Informs of interim 10CFR50.48 suspending completion dates for proviously approved fire protection mods. Revised 10CFR50.48 will contain schedules for completion of all fire protection mods. EIEEE/AUT.D.O. Division of Licensing. 80/11/17. 5pp. 07175:020.
- B012110652 Bummary of B01107 mosting w/util in Dethesda, MD re emergency plans. NEIGHBORS, J. D. Operating Reactors Branch 1. 80/11/19. 2pp.
- B012020276 Informs that emergency response exercise will be performed at facility on B01202 Scenario of exercise and Full scale joint exercise w/State Ofc of Energy & Emergency Svcs will be performed in Fall 1981.

 SYLVIA.B.R. Virginia Electric & Power Co. B0/11/24. Spp. 07134:214.
- G012050320 Forwards amended pages to approved security plan. Encl withheld (ref 100FR2.790). SYLVIA.B.R. Virginia Electric & Pawer Co. 80/12/02. lp.
- B012230986 Forwards draft NUREG-0696. "Implementation Plan" for establishment of emergency response facilities. Details on emergency operations facility establishment.not included in plan being finalised & with be submitted at later data. SYLVIA.B.R. Virginia Electric & Power Co. 80/12/18. 1p. 07311-270.
- --8012230293 Draft NUREG-0676, "Implementation Plan" for establishment of emergency response facilities.

 6 Virginia Electric & Power Co. NUREG-0696. 80/12/18. 47pp. 07311:271.
- 8012220363 Submits proposed schedule for emergency preparedness exercises. Proposed schedule meets NUREG-0654 requirements per tOCFR30 & 10CFR70 outline.

 BAUM.E.A. Virginia Electric & Power Co. 80/12/19. 2pp. 07304:101.
 - 12220373 Requests to be excluded from submitting Btats of NC emergency plan as part of Surry emergency plan. Facility 50-nile emergency planning zone intrudes only four miles into 10 & incident would not affect NC food chain or public.
 3AUM.S.A. Virginia Electric & Power Co. 90/12/17. 2pp. 07304:103.
- O12290274 Forwards alternate shutdown sys design description refire protection.per NRC 801224 ltm.Util review of App R to 10CFR50 concludes that plants are in compliance w/exception of 8-h smergency lights in agress routes. 8YLVIA.B.P., Virginia Electric & Power Co. 80/12/23. Spp. 07345:133.

- Q. Adjudicatory correspondence
- B012170819 Requests, on behalf of util, extension until 810108 for hearing on 801208 order for mod of licenses re environ qualification of safety-related electrical equipment to Tech 8pecs of facilities.

 CHRISTIAN, J. N. Hunton & Williams. 80/12/08, 2pp. 07269: 227.
- 8012170819 Requests, on behalf of util, extension until 810108 for hearing on 801208 order for mod of licenses re environ qualification of safety-related electrical equipment to Tuch Specs of facilities.

 CHRISTMAN, J. N. Affiliation Unknown. 80/12/08. 2pp.
- P. Operating license stage documents & correspondence
- BO12020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake.

 EIBERHUT, D. G. Division of Licensing. 80/10/21. 4pp.
- BO12160050 Ltr to operating plant licensees.QL applicants & CP holders. Forwards NUREG-0737 re TMI action plan.requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISERMUT.D.Q. Division of Licensing. 80/10/31. 7pp.
- 8011200397 Notification of 801203 meeting w/util in Bethesda.MD to discuss util plans in area of core reload licensing in upcoming yr. BERGOREN.J.S. Standardization & Special Projects Branch. 80/11/04. 2pp. 07020:068.
- B012220563 Ltr to all power reactor licensess forwarding NUREG-0419.
 "BWR Feeduater Nozzle & Control Rod Drive Return Line
 Nozzle Cracking." Confirmation that implementation dates
 uill be mat must be sent within 45 days. W/o encl.
 EISERWUT.D.G. Division of Licensing. 80/11/13. 1p.
- 8012010291 Forwards "Surry Unit 1.Cycle 5 Core Performance Rept." THOMAS.N. N. Virginia Electric & Power Co. 80/11/19. 1p. 07097: 240.
- --8012010275 "Burry Unit i.Cycle 5 Core Performance Rept."
 LECENSTEIN. J. H., ROSS. T. K. Virginia Electric & Power Go.
 VEP-FRD-38. 80/11/30. 49pp. 07097:241.
- B012170493 Advises that util 791018 response re inadvertent safety (njection during surveillance testing is acceptable. VAROA, B. A. Operating Reactors Branch 1, 80/11/26 2pp. 07270:332.
- 8012080413 Forwards general evaluation of reactor operation to extended fuel burnups possible w/kigher enrichment fuel.per 800923 ltr.

 8YLVIA, B. R. Virginia Electric & Power Co. 80/12/04, 11pp. 07196: 178.
- 8012090179 Responds to 801204 request for info re 741203 ltr re analysis of potential flooding of safety-related equipment from non-Category I sources. Emergency svc water sys design eliminates intake structure as target for flooding damage. SYLVIA.B.R. Virginia Electric & Power Co. 80/12/04. 1p. 07200:145.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation Inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 BENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANDART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012160142 Forwards suppl info re auxiliary feedwater sys automatic initiation for facility, per 801029 ltr. SYLVIA, B.R. Virginia Electric & Power Co. 80/12/12. 7pp. 07253:024.
- 8012170454 Resubmits program for inservice insp & testing of pumps & valves for last 40 month period of first 10 yr interval. Encl program datails request for relief from ASME inservice insp requirements for Class 1.2 & 3 components.

 BYLVIA: E. R. Virginia Electric & Pouer Co. 80/12/15. 74pp. 07269: 269.

- 8012190354 Forwards response to NUREG-0737 post-TMI requirements. SYLVIA, E. R. Virginia Electric & Power Co. B0/12/15. 430pp. 07282: 262.
- 8012240154 Application to amend Licenses DPR-32 & DPR-37, revising Tech Spec 6.6.1.App C to reflect requirement to document all challenges to RCS power operated relief or safety valves monthly. Proposed change suppls 801114 request. FEROUSON, J.H. Virginia Electric & Power Co. 80/12/23. 3pp. 07345:183.
- --8012290157 Proposed Tech Spec 6.6.1.App C re testing frequency of RCS power-operated relief valves.
 4 Virginia Electric & Power Co. 80/12/23. 1p. 07345:186.
- 8012290248 Forwards addl info re auxiliary feedwater sys, per NRC 801117 request.
 SYLVIA, B.R. Virginia Electric & Pouer Co. 80/12/23. 3pp.
- 8012300585 Forwards response to NRC 790925 request for info re Surry auxiliary feedwater sys design basis info & pump flow verification Documents North Anna 1 pump test verification of 340 gpm delivered to steam generator.

 SYLVIA,E.R. Virginia Electric & Power Co. 80/12/26. 15pp.
- 8012310286 Forwards response to 770925 request for info re auxiliary feedwater sys design basis & pump flow verification. Discrepancy discovered during North Anna review addressed in LER 80-061/017-0 prior to 801006 response. BYLVIA, B.R. Virginia Electric & Power Co. 80/12/26. 15pp. 07361: 273.
- O Inspection reports, IE Gulletins & correspondence
- B012160036 Forwards TE Info Notice B0-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLYJ,P. Region 2. Atlanta, Office of the Director. B0/10/24.

 1p. 07262:180.
- 8012170821 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/10/30. lp. 07866:266
- 80:2180020 Forwards IE Info Notice 80-37, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
 O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/10/31.
 19. 03790:120.
- 8012230070 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
 O'NEILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31, 1p. 07313:236.
- 8012110794 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/11/06. ip. 07225:187.
- B012030B49 Forwards IE Info Notice B0-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY,J.P. Region 2. Atlenta, Office of the Director. B0/11/07. ip. 07150:105.
- 8012080259 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLIY.J.P. Region 2, Atlanta, Office of the Director. 80/11/10. ip. 07182:282.
- B012040135 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/14. ip. 07158:061.
- 8012050070 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 D'REILLY, J. P. Region 2, Atlanta: Office of the Director. 80/11/21, 1p. 07173:230.

- 801208001B Forwards IE Info Notice 80~42. "Effects of Radiation on Hydraulic Snubber Fluid." No written response required. D'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/24, 1p. 97182:161.
- 8012170939 Forwards original 801101 ltr.apparently lost in mail sys, responding to IF Bulletin 79-01B re environ qualifications of Class IE equipment. HUNTER.R.H. Virginia Electric & Power Co. 80/11/24, ip. 07266:027.
- 8012170387 Forwards IE Info Notice 80-29. Suppl 1, "Broken Btuds on Terry Turbine Steam Inlet Flange." No written response required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/26. ip. 07269:080.
- BOI2110543 Forwards response to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Two Valcor valves exist for each North Anna unit & Surry does not have solenoid valves described in bulleting.

 BYLVIA.B.R. Virginia Electric & Power Co. 80/12/04. 3pp.
- 8012230081 Forwards response to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Specified valves are not in use at facilities.

 BYLVIA, B.R. Virginia Electric & Power Co. 80/12/04. 3pp.
- 8012240503 Forwards response to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Two Valcor valves in use do not have cited part number.

 BYLVIA. 2.R. Virginia Electric & Power Co. 80/12/04. 3pp.
- B012120467 Forwards response to IE Bulletin B0-21, "Valve Yokes Bupplied by Malcolm Foundry Co.Inc." No subj valve used or planned for use in safety-related sys at facilities. SYLVIA.B.R. Virginia Electric & Power Co. B0/12/05. 3pp. 07230:325.
- BD12170013 Ack receipt of BD1117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-35 & 50-281/80-38.
 MURPHY.C.E. Region 2, Atlanta Reactor Construction & Engineering Support Branch. 80/12/05. ip. 07268:150.
- --8012170021 Responds to NRC 801017 ltr re violations noted in IE Insp. Repts 50-280/80-35 & 50-281/80-38. Corrective actions: approved welding procedure reviewed to be used in future & weld insp will be conducted by new procedure. SYLVIA-8.R. Virginia Electric & Power Co. 80/11/17. 3pp. 07268:151.
- --8012170028 Forwards IE Insp Repts 50-280/80-35 & 50-281/80-38 on 800909-10 & notice of violation. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/17. 2pp. 07268:154.
- --8012170034 Notice of violation from insp on 800909-10.

 * Region 2. Atlanta, Office of the Director. 80/10/15. ip.
 07268: 136
- -8012170039 IE Insp Repts 50-280/80-35 & 50-281/80-38 on 800909-10.

 Noncompliance noted:failure to document OA surveillance activities & to have documented weld insp procedure.

 ECDNOMOS,N. Region 2. Atlanta, Office of the Director. HERDT,A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/15. 4pp. 07268:157.
- 8012170454 Resubmits program for inservice insp & testing of pumps & valves for last 40 month period of first 10 yr interval Enci program details request for relief from ASME inservice insprequirements for Class 1.2 & 3 components.

 SYLVIA, B. R. Virginia Electric & Pawer Co. 80/12/15. 74pp. 07269:269.
- R. Periodic operating reports & related correspondence
- 8012040304 Forwards "Radiological Progress Rept 1 for Period 800914-1031." Rept describes occupational exposure expended, dose reduction techniques employed & effectiveness & radioactive effluents & solid waste generated. BYLVIA:B.R. Virginia Electric & Power Co. 80/12/01. ip. 07170:175.
- --8012040308 "Radiological Progress Rept 1 for Period 800914-1031;" * Virginia Electric & Power Co. 80/12/01. 3ipp. 07170:176.

- 8012190532 Forwards monthly operating rapts for Nov 1980. SYLVIA: B.R. Virginia Electric & Power Co. 80/12/15. ip. 07288:059.
- --8012190535 Kanthly operating repts for Nov 1980.

 DURN. 8.D. Virginia Electric & Power Co. 80/12/04. 33pp.
 07288:040.
- S. Reportable occurrences. LERs & related correspondence
- BO12040669 Part 21 rept re SAN notification that out-of-phase transfer might occur when emergency buses are transferred from offsite power source to emergency diesel generators after reaching rated speed & voltage. Originally reported 801114.

 SYLVIA, B. R. Virginia Electric & Power Co. BO/11/17. App. 07149-072
- 8012030709 Forwards LER 80-070/01T-0.
 WILEON J.L. Virginia Electric & Power Co. 80/11/26. ip.
 07150:300.
- --8012030717 LER 80-070/01T-0: on 801114.5&W informed util that out of phase transfer might occur when emergency buses transferred from offsite source. Caused by undeterminable design error. Time delay circuit installed.

 WILSOW, J. L. Virginia Electric & Power Co. 80/11/26. 3pp. 07150:301.
- 8012050364 Forwards LERs 80-063/017-0 & 80-039/03L-0. HILBOR, J. L. Virginia Electric & Power Co. 80/12/02. 1p. 07173:235.
- --8012030370 LER 80-063/01T-0: on 801119.during disassembly of steam generator A leveling pads. Vascomax cap screw was broken.
 Cause unknown. Vascomax matl used in steam generator supports will be replaced during repair project.
 MILSON. J. L. Virginia Electric & Power Co. 80/12/02. 2pp.
 07173-274
- --8012050378 LER 80-039/03L-0: on 801102, satisfactory control room pressure envelope test could not be established. Caused by slippage of clamp holding operating arm of damper preventing full closure. Arm adjusted. WILSON, J.L. Virginia Electric & Power Co. 80/12/02. 2pp. 07173: 238.
- 8012230395 Forwards LER: 80-043/03L-0 & 80-071/03L-0. WILSON.J.L. Virginia Electric & Pover Co. 80/12/18. 1p 07318:241.
- --8012230499 LER 80-071/03L-0: on 801119, primary grade water discharged while releasing contaminated drains tank. Caused by performing two procedures simultaneously. Release terminated & water samples.

 WILSON.J.L., Virginia Electric & Power Co. 80/12/18. 2pp. 07318: 264.
- DOCKET 50-281 SURRY POHER STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8012030812 Requests addl info & commitments re emergency plan submitted 800630 to complete onsite emergency program. VAROALS. A. Operating Reactors Branch 1. 80/11/13. 19pp. 07149:143.
- B012050180 Informs of interim ICCFR50.48 suspending completion dates for previously approved fire protection mods. Revised 10CFR50.48 will contain schedules for completion of all fire protection mods.

 EISENHUT.D.O. Division of Licensing. 80/(1/17. 5pp. 07175;020.
- 8012110652 Summary of 801107 meeting u/util in Bethesda.ND re emergency plans. NEIQHBORB.J.D. Operating Reactors Branck 1. 80/11/19, 2pp.
- 8012020276 Informs that emergency response erercise will be performed at facility on 801202. Scenario of exercise encl. Full scale joint exercise w/State Ofc of Energy & Emergency Sycs will be performed in Fall 1901.

 SYLVIA.B.R. Virginia Electric & Power Co. 80/11/24. 5pp. 07134:214.
- B012030328 Forwards amended pages to approved security plan. Encl withheld (ref 10CFR2 790). SYLVIA'S.R. Virginia Electric & Power Co. 80/12/02. ip. 07172:033.

- 9012230286 Forwards draft NUREO-0696, "Implementation Plan" for establishment of emergency response facilities. Details on emergency operations facility establishment not included in plantbeing finalized & will be submitted at later date. SYLVIALE.R. Virginia Electric & Power Co. 80/12/18. 1p. 07341-270.
- --8012230293 Draft NUREG-0696, "Implementation Plan" for establishment e emergency response facilities, * Virginia Electric & Power Co. NUREO-0696, 80/12/18, 47pp, 07311:271.
- B012220353 Submits proposed schedule for emergency preparedness exercises. Proposed schedule meets NUREO-0654 requirements per 100FR50 & 100FR70 outline.

 BAUM.E.A. Virginia Electric & Power Co. 80/12/19. 2pp. 07304: 101.
- B012220373 Requests to be excluded from submitting State of NC emergency plan as part of Surry emergency plan. Facility 30-mile emergency planning zone intrudes only four miles into NC & incident would not affect NC food chain or public.

 BAUM: S. A. Virginia Electric & Power Co. B0/12/19. 2pp. 07304: 103.
- 8012290274 Forwards alternate shutdown sys design description refire protection.per NRC 801124 ltr.Util review of App R to 10CFR30 concludes that plants are in compliance w/exception of 8-h emergency lights in agress routes. SYLVIA.B.P. Virginia Electric & Power Co. 80/12/23. Spp. 07245-132.
- P. Operating license stage documents & correspondence
- 8012020793 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs. & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following marthquake. EISEXMUT.D.O. Division of Licensing. 80/10/21. 4pp.
- B012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISERMUT, D. Q. Division of Licensing. B0/10/O1. 7pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within +5 days. W/o encl. EISERNUT, D. O. Division of Licensing. 80/11/13. 1p.
- 8012170493 Advises that util 791018 response re inadvertent safety injection during surveillance testing is acceptable. VAROA.8. A. Operating Reactors Branch 1. 80/11/26. 2pp. 07270: 392.
- 8012080413 Forwards general evaluation of reactor operation to extended fuel burnups possible w/higher enrichment fuel.per 800723 ltr.
 8YLVIA.B.R. Virginia Electric & Power Co. 80/12/04. 11pp. 07196:178.
- 8012090179 Responds to 801204 request for info re 741203 ltr re analysis of potential flooding of safety-related equipment from non-Category i sources. Emergency sec water sys design eliminates intake structure as target for flooding damage. SYLVIA.B.R. Virginia Electric & Power Co. 80/12/04. ip. 07200:145.
- B012270485 Responds to B00911 memo requesting that Dfc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTOR H.R. Dffice of Nuclear Reactor Regulation, Director. B0/12/04, 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BAH9ART, R. L. Effluent Treatment Systems Branch. 80/11/06. Spp.
- B012160142 Forwards suppl info re auxiliary feedwater sys automatic initiation for facility.per 801029 ltr. BYLVIA.B.R. Virginia Electric & Power Co. 80/12/12. 7pp. 07255:024.
- 8012170557 Forwards requested relief from inservice insp & testing requirements. Program w/dstailed specific relief required from ASMC Code requirements per inservice insp & testing of pumps & valves outlined in Attachments A, B & C. SYLVIA, E.R. Virginia Electric & Power Co. 80/12/15, 73pp. 07264:181.

- 8012190354 Forwards response to NUREG-0737 post-TMI requirements. BYLVIA.S.R. Virginia Electric & Power Co. 80/12/15. 430pp. 07282:242.
- 8012270154 Application to amend Licenses BPR-32 & DPR-37, revising Tech Spec 6.6. Is App C to reflect requirement to document all challenges to RCS power operated relief or safety valves monthly. Proposed change suppls 801114 request. FEROUSDM. J. H. Virginia Electric & Power Co. 80/12/23. 3pp. 07345:183.
- --8012290137 Proposed Tech Spec 6.6.1.App C re testing frequency of RCB power-operated relief valves.

 * Virginia Electric & Power Co. 80/12/23. 1p. 07345:186.
- 8012290268 Forwards add1 info re auxiliary feedwater sys.per NRC 801117 request. SYLVIA, B.R. Virginia Electric & Power Co. 80/12/23. 3pp. 07345:138.
- 8012300585 Forwards response to NRC 790925 request for info re Surry auxiliary feedwater sys design basis info & pump flow verification Documents North Anna 1 pump test verification of 340 gpm delivered to steam generator. SYLVIA, B. R. Virginia Electric & Power Co. 80/12/26, 15pp. 07346:134.
- 8012310286 Forwards response to 770725 request for info re auxiliary feedwater sys design basis & pump flow verification. Biscrepancy discovered during North Anna review addressed in LER 80-061/017-0 prior to 801006 response. 8Y.V.M.B. R. Virginia Electric & Power Co. 80/12/26. 13pp. 07361:293.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012160036 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY,J.P. Region 2. Atlanta, Office of the Director. 80/10/24.

 1p. 07262:180.
- B012(7082) Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30, 19. 07286:286.
- 8012180020 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valvas Mfg by Valcor Engineering Corp." No written response is required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/10/31, ip. 03790:120.
- 8012230070 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31, ip.
- 8012110794 Forwards IE Bulletin 80-21, "Valve Yokes Bupplied by Malcolm Foundry Co.Inc," Written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.

 1p. 07225:187.
- 8012030849 Forwards IE Info Notice 80-40, "Excessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization," No written response required. 6'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/07. 1p. 07150:105.
- 8012080259 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1," No response required, O'REILLY, J. P. Region 2, Atlanta, Diffice of the Director. 80/11/10. 1p. 07182: 282.
- 8012190583 Forwards IE Insp Rept 50-281/80-39 on 800916-19.No noncompliance noted. LEHIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/11/1d. 2pp. 07288:214.
- --B0121903B5 IE lnsp Rept 50-281/80-39 on 800916-19. No noncompliance noted, Hajor areas inspected: startup test results including integrated leak rate: local leak rate, thermal expansion & load rejection testing.

 HHTTENER; H.L., OUICK, D.R., BUTCHER; R. Region 2, Atlanta, Office of the Director, 80/11/12, App. 07288:216.

- 8012040135 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/14.

 1p. 07158:061.
- 8012050070 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/21.
- 8012080018 Forwards IE Info Notice 80-42. "Effects of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 80/11/24. ip. 07182:161.
- 8012170839 Forwards original 80110(ltr.apparently lost in mail sys, rasponding to IE Bulletin 79-018 re environ qualifications of Class IE equipment. HUNIER,R. H. Virginia Electric & Power Co. 80/11/24. Sp. 07266:027.
- 8012170397 Forwards IE Info Notice 80-29, Suppl 1, "Broken Stude on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/26. ip.
- 8012110543 Forwards response to 1E Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Two Valcor valves exist for each North Anna unit & Burry does not have solenoid valves described in bulleting. BYLVIA.B.R. Virginia Electric & Pauer Co. 80/12/04. 3pp. 07225:245.
- 8012230081 Forwards response to IE Sultatin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Specified valves are not in use at facilities. SYLVIA.B.R. Virginia Electric & Power Co. 80/12/04. 3pp. 07311-084.
- B012240503 Forwards response to 1E Bulletin 80-23. "Failures of Solenoid Valves Hig by Valcor Engineering Corp." Two Valcor valves in use io not have cited part number, SYLVIA, B.R. Virginia Electric & Pouer Co. B0/12/04. 3pp. 07324:320.
- 8012120447 Forwards response to IE Bulletin 80-21, "Valve Yoles Supplied by Malcolm Foundry Co.Inc." No subj valve used or planned for use in safety-related sys at facilities, SYLVIA, E.R. Virginia Siectric & Pouer Co. 80/12/05, 3pp. 07230:325.
- 8012170013 Ack receipt of 801117 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-280/80-35 & 50-281/80-39. MURPHY: C.E. Region 2: Atlanta: Reactor Construction & Engineering Support Branch. 80/12/05. 1p. 07268:150.
- --8012170021 Responds to NRC 801017 ltr re violations noted in IE Insp. Repts 50-280/80-35 & 50-281/80-38. Corrective actions: approved welding procedure reviewed to be used in future & weld insp will be conducted by neu procedure. 8YLVIALE.R. Virginia Electric & Pawer Co. 80/11/17. 3pp. 07268: 151.
- --801217002B Forwards IE [nsp Repts 50-280/80-35 & 50-281/80-38 on B00909-10 & notice of violation. HURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/17. 2pp. 07268:154.
- --8012170034 Notice of violation from insp on 800909-10.

 * Region 2: Atlanta: Office of the Director. 80/10/15. 1p. 07268:156.
- 8012170559 Forwards requested relief from Inservice insp & testing requirements. Program w/debatled specific relief required from ABME Code requirements per inservice insp & testing of pumps & valves outlined in Attachments AsB & C. SYLVIA: E.R. Virginia Electric & Power Co. 80/12/15. 73pp. 07266:181.

- R. Periodic operating reports & related correspondence
- 8012190532 Forwards monthly operating repts for Nov 1980. SYLVIA: B.R. Virginia Electric & Power Co. BO/12/15. 1p 07288: 059
- --8012190533 Monthly operating repts for Nov 1980.
 DUNNAS D. Virginia Electric & Pauer Co. 80/12/04. 33pp07288:040.
- S. Reportable occurrences, LERs & related correspondence
- 8012040649 Part 21 rept re S&W notification that out-of-phase transfer might occur when emergency buses are transferred from officts power source to emergency diesel generators after reaching rated speed & voltage. Originally reported 801114. SYLVKA, E. R. Virginia Electric & Power Co. 80/11/19. App. 07169:070.
- 8012030720 Forward4 LER 80-036/03L-0. WILSOR, J.L. Virginia Electric & Power Co. 80/12/01. ip. 07150; 304.
- --B012030723 LER B0-036/03L-0: on B01101, discovered that MDV-FM-2518 could not be closed from control room. Caused by misplacement of Limitorque cover & three broken control wires. Cover & wires replaced.

 HILSON, J. L. Virginia Electric & Power Co. B0/11/01, 2pp. 07150:303.
- 8012050364 Forwards LERs 80-063/01T-0 & 80-039/03L-0. WILSBN.O.L. Virginia Electric & Power Co. 80/12/02. ip. 07173: 235.
- 8012110378 Forwards LERs 80-037/03L-0 & 80-038/03L-0. WILSON: J.L. Virginia Electric & Power Co. 80/12/05, 1p. 0723: 231.
- --B012110393 LER B0-037/03L-0: on B01105, high temp on charge gump A (2-CH-P-1A) revealed low svc water flow Low discharge pressure alarm failed to annunctate. Caused by clogged pump inlat strainar & clogged pressure switch sensing line. WILSUM, J. L. Virginia Electric & Power Co. B0/E2/05, 2pp. 07223:232.
- --8012110378 LER 80-038/03L-0: on 8D1105.on-svc boric acid storage tank & boron injection tank concentration found less that 11.5%.
 Caused by improper valve lineup. Boric acid concentration increased.
 HILSON.J.L. Virginia Electric & Power Co. 60/12/05. 2pp.
 07223:234.
- 8012170611 Forwards LERs 80-040/03L-0,80-041/03L-0 & 80-042/03L-0, WILSON.J.L. Virginia Electric & Pouer Co. 80/12/11. (p. 07264:177.
- --8012170627 LER 80-040/03L-0: an B01114 found charging pump svc water pump 2-5K-P10A developed law discharge pressure of 10 psig. Gaused by matl entrained in water & being deposited on pump impeller. Pump disassembled cleamed & returned to svc. HIL50M, J. L. Virginia Electric & Power Co. 80/12/11. 2pp. 07264:178
- --8012170636 LER 80-041/03L-0: on 801112; snubber 2: NFPD-H89-18 found to have bent rod-eye & was declared imperable. Caused by improper alignment of pipe clamp to snubber. Snubber replaced.
 WILBOW. J. L. Virginia Electric & Power Co. 80/12/11. 2pp. 07264:180.
- --8012170646 LER 80-042/03L-0: on 801115, found emergency diesel generator 3 failed to start manually from control room. Caused by vanes on air motor worn beyond acceptance limits. Vanes repaired. HILSTRIJ. L. Virginia Electric & Power Co. 80/12/11. 3pp. 07264: 182.
- 8012230395 Forwards LERs 80-043/03L-0 & 80-071/03L-0. WILSDN.J.L. Virginia Electric & Power Co. 80/12/18. ip. 07318:261.
- --8012230403 LER 80-043/03L-0: on 801122,PT-33 failed to meet required criterion of 0.05 inches of water. Caused by excessive leakage from 2B battery room door. Battery room door repaired.
 HILSON J. L. Virginia Electric & Power Co. 80/12/18. 2pp. 07318: 262.

- 8012270448 Forwards LERs 80-034/03L-0 & 80-044/03L-0, WILEON, J. L. Virginia Electric & Power Co. 80/12/19, 1p. 07336: 290.
- --8012290495 LER 80-034/03L-0: on 801122, valve MOV-CM-200A failed 75% open. Caused by corroded torque switch stuck in open position. Switch replaced.
 WILSON, J. L. Virginia Electric & Power Co. 80/12/19. 2pp. 07336: 291.
- --8012290460 LER 80-044/03L-0: on 801124, pump 2-81-P-1A declared inoperable due to low resistance. Caused by connection box grounded out by ratinwater. Box dried out, roof hatch repaired & pump & motor tested.
 HILSON-J.L. Virginia Electric & Power Co. 80/12/19, 2pp. 07536:273.
- BOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8012020063 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys. W/o encl health physics network manual. KEPPLER.J. 9. Region 3. Chicago. Office of the Director. BO/11/19. ip. 07148:343.
- 8012020332 Ack receipt of NRC 801114 itr commenting on 800815 upgraded emergency plan. Revisions to plan will be completed by 810201. Implementing procedures will be submitted by 810201. MAYER-L.O. Northern States Power Co. 80/11/26. ip. 07142:049.
- P. Operating license stage documents & correspondence
- 8012010593 Notification of 800521 meeting w/util in Bethesda.MD to discuss installation of four & forty Exxon fuel assemblies containing gadolinia in forthcoming reload. MARTIN.R.E. Operating Reactors Branch 3. 80/05/14.
- BD12020753 Forwards seismic qualifications of auxiliary feedwater system operating PNRs & describes program NRC is undertaking to review capability of operating PNRs to remove decay heat following warthquake.

 EISENHUT.D.O. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licenses, OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements, Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISE(HNUT, D. G. Division of Licensing, 80/10/31, 7pp.
- BO12220563 Ltr to all power reactor licensees forwarding NUREQ-Q&IP.
 "BNR Feedwater Nozzle & Control Red Drive Return Line
 Nozzle Cracking." Confirmation that implementation dates
 will be met must be sent within 45 days. W/o enci.
 EISENHUT. D. Q. Division of Licensing. BO/11/13. 1p.
- 8012040333 Forwards Amends 43 & 37 to Licenses DPR-42 & DPR-40, respectively, safety evaluation & notice of issuance & availability.

 CLARK.R.A. Operating Reactors Branch 3. 80/11/14. 3pp. 07163:223.
- --B01204035B Amends 43 & 37 to Licenses DPR-42 & DPR-60, respectively, revising Tech Specs to replace current inservice insp Tech Specs w/Inservice program meeting requirements of 10CFR50. 55. CLARK R. A. Operating Reactors Branch 3. B0/11/14. Spp. 07163: 226.
- --8012040364 Safety evaluation supporting Amends 43 % 37 to Licenses DPR-42 & DPR-60, respectively. * Office of Nuclear Reactor Regulation, Diroctor. 80/11/14. 2ipp. 07163:231.
- --8012040369 Notice of issuance & availability of Amends 43 & 37 to Licenses DPR-42 & DPR-60 respectively. CLARM.R.A. Operating Reactors Branch 3. 80/11/14. 2pp. 07163:232.
- 8012010070 Responds to questions raised by Chemical Engineering & Effluent Treatment Sys Branches re facility fuel storage mod/in connection w/800131 DL amend request.
 MAYER/L.D. Northern States Power Co. 80/11/21. 5pp. 07097:331.

- 8012080319 Forwards Revision i to 800506 application for amend to Licenses DPR-42 & DPR-60 changing Tech Specs. Section 3. 10 resafety injection actuation power distribution limits.

 MAYER, L. C. Northern States Power Co. 80/12/02. 1p. 07189: 223.
- --8012080323 Revision 1 to 800506 application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs, Section 3.10 re safety injection actuation & power distribution limits. MAYER, L. O. Northern States Power Co. 80/12/02. 3pp. 07189: 224.
- --8012080329 Proposed changes to Tech Specs, Section 3.10 re safety injection actuation & power distribution limits.

 * Northern States Power Co. 80/12/02. 4pp. 07189: 227.
- B012220485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012309265 Responds to NRC 801024 request for add1 auxiliary feedwater sys info.8pecific responses, related tables & drawings & correction to util 791221 itr encl. HAYER,L.O. Northern States Power Co. 80/12/18. 13pp. 07357:243.
- B012300214 Submits licensing fee determination for B01217 amend request for Licenses DPR-42 & DPR-40 re TMI Lessons Learned Category A Tech Specs changes. Class III & Class I fees encl. * Northern States Power Co. B0/12/19, lp. 07357:056.
- 8012300302 Forwards application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs re TMI Lessons Learned Category A procedural & equipment requirements.Fee enc1.
 MAYER.L.O. Northern States Power Co. 80/12/19. 19. 07357:065.
- --8012300305 Application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs re THI Lessons Learned Category A procedural & equipment requirements. HAYER.L.O. Northern States Power Co. 80/12/19. 3pp. 07357:066.
- ---BO12300310 Proposed changes to Tech Specs Sections 3.4 & 6 re TMI Lessons Learned Category A procedural & equipment requirements. 4 Northern States Power Co. BO/12/19, 28pp. 07357:069.
- G. Inspection reports, IE Bulletins & correspondence
- 8012170644 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 KEPPLER.J. G. Region 3, Chicago, Office of the Director. 80/10/24.
 1p. 07264:192.
- 8012110641 Forwards IE Insp Rept 50-282/80-11 on 801008-09. No noncompliance noted. HEISHMAN,R.F. Region 3, Chicago: Reactor Operations Nuclear Support Branch. 80/11/05. 2pp. 07226:203.
- --B012110445 IE Insp Rept 50-282/80-16 on 801008-09. No noncompliance noted Major areas inspected:containment integrated leak rate test.

 BIREETER, J. F., BOONE, J. M. Region 3, Chicago, Office of the Director. HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/30. 5pp. 07226:205.
- B012010566 Forwards IE Insp Repts 50-282/80-17 & 50-306/80-17 on 801020-24 & notice of violation Notice of violation withheld (ref 10CFR2.790). HIND. A. Region 3, Chicago, Bafaguards Branch. 80/11/18, 2pp. 07075:048
- --B012010586 IE Insp Repts 50-282/80-17 & 50-306/80-17 on B01020-24. Noncompliance noted access available to two vital areas w/o controlled access points. Details uithheld (ref 10CFR2.790). PIRILE, 0.L., AMDEDA, T. J. Region 3, Chicago, Uffice of the Director. HIND.J.A. Region 3, Chicago, Bafeguards Branch. B0/11/17. 2pp. 07095:050.

- 8012020/43 Forwards three Performance Appraisal Branch insp repts & mpt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. W/o encl.
 KEPPLER, J. O. Region 3, Chicago. Office of the Director. B0/11/18. 4pp.
- 801204633 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment:" No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21.

 2pp. 07165: 330.
- 8012080070 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required.
 KEPPLER.J.G. Region 3, Chicago, Office of the Director. 80/11/24.
 2pg. 07182:223.
- 8012070006 Responds to IE Bulletin 80-23 increased surveillance not warranted. Solenoid valves do not present safety or plant reliability concern.
 OILBERTS.D. E. Northern States Power Co. 80/11/24. 1p. 07199:338.
- 8012190770 Forwards new security badge numbers & clearance levels for Region 3 personnel.Changes should be entered on Sept 1980 access lists.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/25. App. 07286:020.
- 8012170531 Forwards IE Info Notice 80-27, Suppl 1. "Broken Stude on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/26. 2pp. 07268:132.
- 8012270177 Responds to IE Builetin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Facilities do not use specified valves.
 OLLBERTS, D. E. Northern States Power Co. 80/12/05. 1p. 07303:241.
- 8012220734 Forwards revised data sheets in response to IE Bulletin 79 018, "Environ Qualification of Class IE Equipment." Q1LBERTB, D. E. Northern States Power Co. 80/12/05. 7pp. 07299:241.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-01B re environ qualification of Class IE equipment.
 MAYEG.D.W. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp.
- 8012240290 Forwards inservice insp examination summary for facility from 800902-1013. MAYER.L.O. Northern States Power Co. 80/12/19. 1p. 07325:146.
- ---8012240294 Inservice insp rept for 800902-1013.Refueling Dutage 5.Insp Period 2. Discusses examination of pressure retaining components & supports of reactor coalant & associated sys classified as ASME Class 1 & Class 2
 DAHLMAN, L. D., KRUMPOS.P. J., ANDERSON, R. W. Northern States Power Co. 80/12/01. 95pp. 07325:147.
- R. Periodic operating reports & related correspondence
- 8012160453 Forwards monthly operating repts for Nov 1780. MAYER,L.D. Northern States Power Co. 80/12/11. 1p. 07254:204.
- --8012160458 Monthly operating repts for Nov 1980. | November 1980 | November
- 8. Reportable occurrences, LERs & related correspondence
- BOI2010477 Forwards LER 80-033/03L-0. MAYER.L.O. Northern States Power Co. 80/11/26. ip. 07095:136.
- --B012010493 LER 80-033/03L-0:on 801028, steam flow transmitter 1FT-464 observed reading low Caused by zero adjustment shift in Barton Hodel 384 differential pressure transmitter. Device recalibr.
 HUNSTAD.A.A. Northern States Power Co. 80/11/26. 1p. 07095:137.
- 8012070376 Forwards LER 80-036/03L-0. MAYER, L. D. Northern States Power Co., 80/12/03. ip. 07203:007.
- ---B012090391 LER 80-036/03L:on 801105, battery charger 12 failed to provide normal output. Caused by firing card B not providing pulses to fire B phase BCR. Card replaced. HUMSTAD. A. A. Northern States Power Co. B0/12/03. 1p. 07203:008.

- 80(2:50183 Supplemental LER 80-025.on 800904, during mounting bolt insp. three defective Vascoma: 250 CVM bolts were discovered in steam generator 22 Caused by stress corrosion cracking. New bolts were inskalled & tensioned to 50 ft lb. MAYER.L.O. Northern States Power Co. 80/12/03. 7pp. 07241:148.
- 8012170540 RO 80-25. Revision 1: on 800904, during investigations re Ceneric Technical Activity A-12.CVM steam generator mounting bolts found defective. Caused by stress corrosion cracking. New steam generator mounting bolts installed & tensioned. MAYER.L.O. Northern States Power Co. 80/12/03. App. 07266:277.
- 8012150191 Forwards LER 80-037/03L-0. MAYER.L.D. Northern States Power Co. 80/12/11. 1p. 07241:084.
- ---8012150197 LER 80-037/03L-0: on 801117, during raview for upgrading environ qualification of safety-related electrical equipment; it was determined that NAMOO switches were not hermetically sealed. Caused by installation error. NUKSTAD, A. A. Northern States Power Co. 80/12/11. 2pp. 07241:089.
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8012090306 Forwards interim 10CFR30 48 suspending completion date for previously approved fire protection mods effective 801029. Rule will be superseded by pending revision. EISNEHUT, D. 0. Division of Liesnsing. 80/11/18. 5pp. 07207:021.
- 8012290418 Forwards revised 10CFR50.48 & App R to 10CFR50 re five protection features of nuclear power plants.Rules take effect 810217. Summary listing of open items re fire protection features of facility encl. EISEXMUT.D.O. Division of Licensing. 80/11/24. 2ipp. 07345:287.
- O. Advisory Committee on Reactor Bafeguards reports & correspondence
- 8012010611 Summary of Subcommittee on Reactor Operations 800804 meeting in Washington, DC re util application for power level increase.

 ACRS Advisory Committee on Reactor Safeguards. 80/09/12. App. 07073:074.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertating to raview capability of operating PWRs to remove decay heat following earthquate. EISENMUT.D.G. Division of Licensing. 80/10/21, 4pp.
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TRI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISEKHUT.B.O. Division of Licensing. B0/10/31. 7pp.
- 8012220863 Ltr to all power reactor licensees forwarding NUREO-0619, "BNR Fredwater North & Control Rod Drive Return Line North Cracking." Confirmation that implementation dates will be met must be sent within 45 days. H/O encl. CISCHMUT, D. G. Division of Licensing. 80/11/13. ip.
- B012030B44 Forwards Performance Appraisal Branch repts & mgt evaluation trae & user's guide. Info provided to ensure that licensees have opportunity to review strengths & weaknesses for program applicability. N/o encls.

 SEYFRIT.X. V. Region 4, Dalias, Office of the Director. 80/11/14.

 1p. 07149:257.
- 8011180361 Forwards util application for amend of License DPR-40 to Certificate of Svc.
 PROBABLE DELETE: DUPE OF 8011180435.
 LEBOEUF, R. J., LANG, H. R., LEIBY, A. C. LeBoeuf, Lamb, Leiby & MacRae. 80/11/17. 2pp. 06988: 301.
- --8011180569 Tech Spec 2.1.1 for operable components.
 PROBABLE DELETE: DUPE OF 8011180461.
 * Dmahe Public Power District. 80/11/14. 9pp. 06988:305.
- 8012010524 Act reciept of 801027 ltm re aquatic blota impact of facility operation, in response to NRC 800929 request info will facilitate review of util 790508 request to delete App B Tech Spect.

 MAONER,P.C. Operating Reactors Branch 3. 80/11/17. 2pp.

- B012110826 Forwards Amend 53 to License DPR-40, safety evaluation & notice of issuance & availability.
 CLARK.R.A. Operating Reactors Branch 3. 80/11/17. 2pp. 07225; iol.
- --8012110828 Amend 53 to License DPR-40, changing Tech Specs to include add1 fire protection requirements.
 CLARK, R.A. Operating Reactors Branch 3 80/11/17, 12pp. 07225: 103.
- --B012110B31 Safety evaluation supporting Amend 53 to License DPR-40.

 # Office of Nuclear Reactor Regulation, Director. B0/11/17, 9pp
 07225:115.
- --B012110B32 Notice of issuance & availability of Amend 52 to License BPR-40. CLAMKR.A Operating Reactors Branch 3. 80/11/17. 2pp. 07225:124.
- 8012110429 Ack receipt of 801107 ltr re QC of emergency diesel generator fuel oil Proposed program is acceptable. Generic issue is closed.

 CLARK.R.A. Operating Reactors Branch 3. 80/11/19. 2pp. 07227:197.
- 8012140515 Notifies that util 791106 ltr re multiple equipment failures & surveillance errors at facility provides adequate response to NRC concerns.

 CLARK, R. A. Operating Reactors Branch 3. 80/11/21. 2pp. 07241:185.
- B012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENION-H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANDART.R.L. Effluent Treatment Systems Branch. 80/11/06. Bpp.
- B012220379 Forwards detailed summary of tasks progress, proposed revised date; justification for delay & planned compensating measures in response to 801031 ltr transmitting NUREO-0737 to all licansees. UCNES.W.C. Omaha Public Power District. 80/12/12. 10pp. 03797:053.
- G. Inspection reports, IE Bulletins & correspondence
- 8012220607 Forwards response to IE Bulletin 79-03A, "Longitudinal Held Defects in ASME SA-312 Type 304 Stainless Steel Pipe," No applications of specified pipe at greater than 85% max allowable stress at facility. JONES, K. C. Gmaha Public Power District. 80/08/04. 2pp. 07299:202.
- 8012120710 Forwards responses to IE Bulletin 80-15, "Possible Loss of Emergency Nutification Sys (ENB) w/Loss of Offsite Power." Local telephone company will not cooperate in required test due to momentary loss of power to entire sys.

 JONES, W. C. Omaha Public Power District. 80/08/25, 3pp. 07236:189.
- B012020190 Forwards IE Insp Rept 50-285/80-17 on 800901-30. No noncompliance noted.

 MADSEN, G. L. Region 4. Dailas, Reactor Operations Nuclear Support Branch. B0/10/21. 2pp. 07148:204.
- --8012020194 IE insp Rept 50-285/80-17 on 800901-30. No noncompliance noted Major areas inspected operational safety verification surveillance test maint activities & LER & IE bulletin follow-up.
 KELLEY, D. L., HUNNICUTT, D. M. Region 4. Dallas, Office of the Director. 80/10/20. Spp. 07148:206.
- 8012120567 Forwards IE Insp Rept 50-285/80-18 on 800930-1003.No noncompliance noted.

 MADBEN.O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 80/10/23. 2pp. 07237:136.
- --B012120570 IE Insp Rept 50-285/80-18 on B00930-1003.No noncompliance noted Hajor areas inspected document control program & surveillance of pipe support & restraint sys.
 HUNDICUTT. D. M. . YANDELL. L. A. Region 4, Dallas, Office of the Director. B0/10/22. App. 07237:138
- 8012170318 Forwards Suppl 3 to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/10/24. ip. 07268:344.

- B012160062 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/10/27.

 1p. 07262:149.
- 8012170365 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. SEYFRIT.K.V. Region 4, Dallas. Office of the Director. 80/10/30. 1p. 07269:035.
- B012150024 Forwards updated response to IE Bulletin 79-018, "Environ Owalification of Class IE Equipment," addressing util positions on radiation qualification outside containment to main steam line break analysis W/o encl. UDN48.W.C. Omaha Public Power District. 80/10/31. 2pp. 07241:040.
- 8012170809 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/10/31. 19. 07266:107.
- 8012230024 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Bys Emergency Generators." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/10/31. 19. 07311:206.
- 8012100628 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malculm Foundry Co. Inc." Written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/06. ip. 07220:975.
- B012030706 Forwards IE Info Notice B0-40, "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. B0/11/07. ip. 07150:171.
- 8012080618 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. SEYFRIT-K.V. Region 4, Dallas, Office of the Director. 80/11/10. ip. 07183:023
- B012240043 Forwards IE Insp Rept 50-285/80-19 on 801021-24. No noncompliance noted. MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch, B0/11/12. 2pp. 07324: 234.
- --8012240045 IE Insp Rept 50-285/80-19 on 801021-24. No noncompliance noted Major areas inspected surveillance testing & calibr control program.
 YANDELL, L. A. HUNNICUTT, D. M. Region 4, Dallas, Office of the Director. 80/11/10. App. 07324: 236.
- B012040014 Forwards IE Bulletin B0-23. "Failures of Bolenoid Valves tig by Valcor Engineering Corp." Requires estimate of manpawer associated w/corrective actions. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/14. 1g. 07169:271.
- R. Periodic operating reports & related correspondence
- 8012190538 Forwards monthly operating rept for Nov 1980. JONES, N. C. Omaha Public Power District. 80/12/09. 1p. 07288:049.
- --B012190542 Monthly operating rept for Nov 1980. PATTERBON.T.L. Dmaha Public Power District. 80/12/09. 9pp. 07288:050.
- 8. Reportable occurrences. LERs & related correspondence
- 8012020670 Forwards LER 80-028/03L-0. STEVENB.8.C. Omaha Public Power District. 80/11/19. ip. 07148:027.
- --8012020479 LER BO-02B/03L-0: on B01105, while diesel generator DO-1 was started & run to operating speed, burser which tests for DO-1 "ready-to-load" within 10 seconds failed to sound within required time limit. Cause unknown. Diesel retested & started. MULLER, R. Omaha Public Power District. B0/11/12. 4pp. 07148: 028.
- B012100480 Forwards LER 80-029/03L-0. STEVENS, S. C. Omaha Public Power District. B0/11/21, 1p. 07218:087.

- --8012100484 LER 80-029/03L-0: on 801106, outboard motor bearing on containment spray pump SI-3C motor frund severely degraded & motor shaft scored. Probably caused by lack of oil to bearing. Bearing replaced & rotor shaft repaired. MUELLER.R. Omaha Public Power District. 80/11/07. 4pp. 07218:088.
- 8012020507 Forwards LER 80-025/03L-0. STEVENS, S. C. Omaha Public Power District. 80/11/25, 1p. 0714B: 215.
- --8012020616 LER 80-025/03L-0:on 801027 during power operation while completing repairs on C charging pump. A charging pump became inoperable. Caused by leak in weld joining sys to flushing line. Weld repaired & pump returned to syc. QATES, W. MUELLER, R. Gmeha Public Power District. B0/11/14. 4pp. 07148:216.
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3

 F. Security, medical, emergency & fire protection plans
- 80120B0726 Informs that mods will be made to emergency notification sys & health physics network equipment NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operations facilities. ORIER, B. H. Region I. Philadelphia, Office of the Director, 80/11/14, 2pp. 07196:152.
- 8012050205 Informs of interim 10CFR30.48 suspending completion dates for previously approved fire protection mods. Revised 10CFR30.48 will contain schedules for completion of all fire protection mods. EISENHUT.D.O. Division of Licensing. 80/11/17. 5pp. 07175:035.
- 8012040701 Forwards public version of two FEMA repts entitled "Assessment of Evacuation Time Around Indian Point Nuclear Power Station." FELTON, J. M. Division of Rules and Records. 80/12/01. 1p. 07159: 173.
- --8012040704 Public version of draft final rept "Assessment of Evacuation Time Around Indian Point Nuclear Power Station," executive summary, prepared for FEMA.

 -- COURAD RESEARCH CORP. * Center for Planning Research, Inc. 80/08/21. 34pp. 07195:174.
- --B012040710 Public version of final rept. "Assessment of Evacuation Time Around Indian Point Nuclear Power Station," prepared for FEMA.Public version of Consad Research Carp 800804 ltr encl. 4 CONSAD RESEARCH CORP. 4 Center for Planning Research, Inc. 80/06/23, 129pp. 07155:207.
- B012290353 Requests submittal of changes to physical security plan within 30 days of receipt of ltr.Encl details withheld (ref 10CFR2.790). VAROA, B.A. Operating Reactors Branch 1. B0/12/09. 2pp. 07345:340.
- Q. Adjudicatory correspondence
- 8011170738 Informs that 800611 response to Item E. 2 of 800211 confirmatory order re assessment of facility control rooms lacks details & specificity needed to conduct thorough review. Forwards NRC 801031 ltr to Con Ed re control room, VAROA, S. A. Operating Reactors Branch 1. 80/10/31. 3pp. 07001:171.
- 8012110480 Excerpt from staff requirements memo re 801114 IE briefing re-current facility status. Of of General Counsel must revise draft order to include input from Ofc of Policy Analysis.

 CHILK, 8. J. Office of the Secretary of the Commission. 80/11/24.

 1p. 07227: 135.
- 8012290217 Urges Commission to order ASLB to hold full adjudicatory hearing on contentions & hazards posed by reactors. WEISS-E.R. Sheldon, Harmon & Weiss. 80/11/25. 3pp. 07345:024.
- 8012300278 Staff requirements memo re Commission B01126 meeting on instructions to Board on facility proceeding.

 CHILM, 8. J. Diffice of the Becretary of the Commission. B0/12/05. ip. 07357:063.
- BO12150282 Discusses IE insp on B00624-26 & forwards order imposing civil penalty.
 STELLO, V. Office of Inspection & Enforcement, Office of the Director. B0/12/08. 3pp. 07237:328.

- --B012150284 Order imposing civil penalties in amount of \$11,000 for item of noncompliance noted in 1E insp on 800624-26.
 STELLOV. Office of Inspection & Enforcement. Office of the Director. 80/12/08 4pp. 07237:331.
- 8012150138 Forwards comments on 801124 revised draft order being prepared for ASLB re future of facility. Order should explain why hearings are being held.N9C should declare intention to reconsider question of interim operation in June 1981. HOLT. J. Public Interest Research Group, New York. 80/12/10. Spp. 07241:161.
- --8012150140 Comments on NRC B00530 order establishing informal proceeding to define scope of ASLB adjudication re UCS patition & criteria for facility. Criteria for decisions should be in terms of worst-case accidents.

 HDLT.J. Public Interest Research Group, New York. B0/09/26. 9pp. 07241:166.

H. General correspondence

- B012040371 Opposes continued operation of facility re recent findings of rust on inner & outer layers of vessel resulting from Saline River accident Requests name be added to mailing list to receive info re emapency procedures & public hearings.

 MACNULTY, J. J. Affiliation Unknown, 80/10/25, Ip. 06915:001.
- 8012030703 Urges permanent shutdown of facilities. Shutdown costs should be assumed by utilinot consumers. BALLIL.H. Affiliation Unknown. 80/11/24, ip. 06586:003.
- B012030/10 Urges that facilities be shutdown & that customers not pay for util disastrous mistakes which could pose potential danger to public health & safety. WEBER, M. S. Affiliation Unknown. B0/11/24. 1p. 06586:003.
- B012030600 Expresses concern on nuclear energy. Con Ed & PABNY should be refused permission to resume facility operations until safety hearings have been held. CONSTUM, L. Affiliation Unknown. B0/11/25. 1p. 06586:003.
- 8012040375 Opposes continued operation of facility until promised safety hearings re recent accidents at plants.

 KUND.M.J. Affiliation Unknown. 80/11/29, 1p. 07158:178.
- 8012040401 Urges immediate establishment of firm natl policy to prohibit plant siting near densely populated areas. Protests ASLAB ruling to consider plant location after const. Cites negative factors re nuclear const. near Lake HI.

 BUSHEMI. J. Indiana. State of. 50/11/25. 1p. 07158:181.
- 8012030254 Demands facility be shot down & that Util Bear cost. BALL.H.L. Affiliation Unknown. 80/11/26. Ip. 06595:003.
- 8012030715 Requests that facilities be permanently shut down. ANODLOSE, O. Affiliation Unknown. 80/12/01. 1p. 06586:003.
- 8012030718 Requests that facilities be permanently shut down to prevent further accidents. BELOTTI.M. Affiliation Unknown. 80/12/01. 1p. 06596:003.
- 8012150181 Urges revocation of util license & complete shutdown of facilities in light of saltwater leakage & seisnic location. NEISS.E. Affiliation Unknown. 80/12/03, 2pp. 07240:357.
- 8012270045 Forwards constituent J Barrows 801118 ltr re 801017 discovery of water in reactor bidg.Requests response. EMERY, D. F. House of Rep., Arned Services. 80/12/04, 2pp. 07308:001.
- 8012150169 Submits petition to shut down reactors pending full investigation of safety issues.

 * Westchester Peoples Action Coalition, Inc. 80/12/12. ip. 07240:024.
- 80f2270023 Requests Commission deny utils permission to resume operations pending full investigation of safety issues to be adjudicated during forthcoming hearings.
 LENAHAM, E., LOTOUCKI, D., BAKER, E. H. Affiliation Unknown. 80/12/19, ip. 07344: 216.
- 8012300085 Requests that Commission dony utils permission to resume operation of facilities.
 SEIO.M., CARTER.D., PESICOE.S. Affiliation Unknown. 80/12/23, 2pp. 07356:191.

- D. Advisory Committee on Reactor Safeguards reports & correspondence
- B01202006B Summary of Subcommittee on Class 9 Accidents 800702 meeting in Inglewoof, CA re posalble mitigation features.

 + ACRS Advisory Committee on Reactor Safeguards. B0/09/17. Bpp. 07147: 237.
- P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISERHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012220563 Ltr to all power reactor licenses forwarding NUREO-0619, "BUR Feedwater Nozzie & Control Rod Drive Return Line Nazzie Cracking." Confirmation that implementation dates will be mat must be sent within 45 days. W/o enci. EISENNUT.D. G. Division of Licensing. 80/11/13. 1p.
- 8012030592 Responds to NRC 801009 ltr re min flow requirements of auxiliary feedwater sys. Util will increase preset throttled position of auxiliary feedwater sys flow control valves to deliver 400 gpm.

 BAYNE, J. P. Power Authority of the State of New York. 80/11/26.

 Zpp. 07151:165.
- 8012030707 Provides add1 info in response to NRC 801106 telcon request. Info in form of chart schedules for items to be installed during next scheduled outage of sufficient duration to complete mod but not later than next refueling outage. WILLVERDING.O.M. Power Authority of the State of New York. 80/11/26. 17pp. 07149:205.
- 8012090375 Informs of completion of mods in response to Item II.K.3.9 of TMI-2 related requirements. Mods included: sliminating derivative feature on pressure controller PC-445 K & increasing setpoint of power operated relief valve bistable. HILVERDING.O.M. Power Authority of the State of New York. BO/11/26. ip. 07207: 144.
- E012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220505 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012170352 Forwards response to NRC 801031 Itr re human factors review of control room. Each corrective action is addressed & addl items are included.

 8AYNE.J.P. Power Authority of the State of New York. 80/12/12.

 8pp. 07270:178.
- B012190464 Responds to Franklin Inst concerns re environ qualifications of electrical equipment contained in facility SEP.

 ZULLA:S. Power Authority of the State of New York. 80/12/12.

 2pp. 07282:143.
- 8012300502 Advises that backup communication link.committed to in response to B00211 confirmatory order Item F.2.has been rescheduled for completion in June 1981. Backup tellephone link will be retained for remote interrogation capability. BAYNE, J. P. Power Authority of the State of New York. 80/12/22. 1p. 07397:335.
- G. Inspection reports. IE Bulletins & correspondence
- 8012160049 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2," No written response required.
 GRIER, B. M. Region 1, Philadelphia, Office of the Director.
 80/10/24. ip. 07262:168.
- 801217039B Forwards IE Info Notice 80-3B, "Cracking in Charging Pump Casing Cladding." No written response required. CRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/30. ip. 07269:103.
- 8012120924 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER.B.H. Region 1, Philadelphia. Office of the Director. 80/11/06, ip. 07230:303.

- BO12190346 Informs util of issuance of new NRC personnel identification badges.effective after 801130.Example encl. MARTIN.H.J. Region I. Philadelphia. Safeguards Branch. 80/11/06. 2pp. 07286:108
- 8012030791 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization " No written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/07. p. 07150:215.
- B0120B0824 Responds to IE Bulletin 80-ii, "Masonry Wall Design." Requests delay in 180-day response to bulletin to resolve comments on final rept received B01103 from A/E. BAYNE, J.P. Power Authority of the State of New York. 80/11/07. 2pp. 07196:273.
- BO12080310 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
 ORIER, B.H. Region 1, Philadelphia, Office of the Director.
 BO/11/10. 1p. 07182:291.
- 8012040082 Forwards IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B.H. Reyion in Philadelphia, Office of the Director. 80/11/14. 1p. 07197:338.
- B012270676 Advises that written response is required to IE Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. ORIER. B. H. Region 1. Philadelphia, Office of the Director. 80/11/19. 1p. 07293:129.
- 8012190282 Forwards safety evaluation of results of midcycle insp of one steam generator submitted in 801031 ltr.Plant can be brought critical & operate for duration of Cycle 3. VARGA: 8.A. Operating Reactors Branch 1. 80/11/20. 2pp. 07222:096.
- --8012160684 Safety evaluation supporting midcycle insp of steam generator tubes.

 * Office of Nuclear Reactor Regulation, Director. 80/11/20. 3pp. 0722:098.
- B012040502 Forwards IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required. Requests info on manpower expended. GRIER, B.H. Region i, Philadelphia, Office of the Director. B0/11/21. 2pp. 07169:190.
- BO12050583 Forwards info Notice 80-42, "Effect of Radiation on Mydraulic Bnubber Fluid." No written response required. ORIER, B.H. Region i, Philadelphia, Office of the Director. BO/11/24. ip. 07174:074.
- 8012150282 Discusses IE insp on 800624-26 & forwards order imposing civil penalty.

 8TELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/12/08. 3pp. 07237:328.
- --B012150284 Order imposing civil penalties in amount of \$11,000 for item of noncompliance noted in IE insp on 800624-26.
 STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/12/08, 4pp. 07237:331.
- 8012140360 Forwards demineralizer water sus valve drawing & Revision 1 to "Inservice Insp Testing Program: Held & Pipe Supports Pumps & Valves." Revision includes commitments made during 800401 meeting & 801002 telcon & resolution of open items. BAYNE, J.P. Power Authority of the State of New York. 80/12/12. 2pp. 07256: 146.
- --8012160348 "Inservice Insp Testing Program:Weld & Pipe Supports, Pump & Valves," Revision 1.
 SURRENTINO.A.V., JACOBS.K. Power Authority of the State of New York. BUKES, P.E. Westinghouse Electric Corp. 80/11/25. 120pp. 07296:171.
- R. Periodic operating reports & related correspondence
- BD12160476 Forwards data specified in Section 401 Certification for Nov 1980. MDNII,W.A. Consolidated Edison Co. of New York, 80/12/10. 16pp. 07263:114.
- BO12220316 Forwards monthly operating rept for Nov 1980. IVI.1A:8.8. Power Authority of the State of New York. BO/12/12. ip. 07307:315.

- --8012220321 Monthly operating rept for Nov 1980. CONNELL.C. Power Authority of the State of New York. 80/12/01. 7pp. 07307:316
- 8012220099 Forwards tabulation of daily record of fish collections for Nov 1980. Daily species code list count & total weight encl. O'TOOLE. JD. Consolidated Edison Co. of New York. 80/t2/15. Spp. 07304:105.
- S. Reportable occurrences, LERs & related correspondence
- B012010410 Forwards LER 60-014/03L-0. ZULLA, S. B. Power Authority of the State of New York. B0/11/24. 1p. 07095:090.
- --8012010415 LER BO-014/03L-0: on B01025, level transmitters LT934B & LT935B found outside procedural limits in nonconservative direction. Caused by instrument drift. Transmitters reset. GUMBLE,F.W. Power Authority of the State of New York. 80/11/24. 2pp. 07095:091.
- 8012170361 Confirms telcon re leak identified in fan cooler unit at facility.Leak is approx i/4 pint per minute.Leak will be repaired prior to startup from cold shutdown.
 ZULLA, S. B. Power Authority of the State of New York. 80/12/05. ip. 07270:186.
- B012150107 RO: on B01107, while in cold shutdown, retest for engineered safety features sys revealed that two Westinghouse M0-6 relays in train A failed to latch upon safety injection activation signal. Caused by screw out of adjustment. ZULLA.8. S. Power Authority of the State of New York. B0/12/08. 3pp. 07241:186.
- 8012180261 EN-80-038A: on 801208, notices of violation & of proposed imposition of civil penalties in amount of \$11,000 to be issued to licensee. Action based on alleged noncompliance repersonnel exposures.

 RIESLAND, J. . THOMPSON, D. Office of Inspection & Enforcement, Office of the Director. 80/12/08. ip. 03794:024.
- 8012130132 Forwards LER 80-015/03L-0. ZULLA.S.S. Power Authority of the State of New York. 80/12/11. ip. 07237: 273.
- --8012150135 LER 80-015/03L-0: on 801115, pressure transmitter PT-4548 was out of spec in nonconservative direction. Caused by instrument drift. Transmitter adjusted to within spec requirements. GUISELE.F.W. Power Authority of the State of New York. 80/12/Li. 1p. 07237: 294.
- 8012290425 Forwards LER 80-016/01T-0. ZULLA.S.S. Power Authority of the State of New York. 80/12/17. 1p. 07337:003.
- --B012290429 LER 80-016/017-0: on B01205; leak of 0. 25 pints per minute discovered in fan cooler unit 35, reported per IE Bulletin 80-24. Caused by leak in tube of cain cooling coil. Leaking tube repaired, unit tested & returned to svc. CUMBLE, F. W. Power Authority of the State of New York. 80/12/17. 1p. 07337:004.
- T. Hearing transcripts on non-antitrust matters
- 8012170345 Transcript of 801126 public meeting in Washington.DC re instructions to ASLB on facility proceeding.Pp 1-39. * Commissioners. 80/11/26. 39pp. 07236:324.
- --g0[2120373 Forwards draft order reflecting divergent positions on certain questions re principal focus of adjudication. BICKMIT.L. Commissioners. SECY-A-80-179C. 89/11/26., 14pp. 07237:003.
- B012290493 Transcript of 801215 public meeting in Washington, DC re ASLB instructions, Pp 1-54.

 * Commissioners. B0/12/15 56pp.
- --8012270501 Responds to commissioner 801126 request re assessment of one-hearing vs two-hearing approach implications on safety issues' adjudication.
 BICKHIT.L. Office of the General Counsel. SECY-A-80-179E.
 80/12/12. 3pp.
- --8012270597 Discusses & forwards redrafted 801126 order & clarifies commissioner resolutions. Excerpted 1tr to EL Jordan encl. BICKWIT.L. Office of the General Counsel. SECY-A-80-179D. 80/12/ii. 21pp.

J. Congressional/Executive Correspondence

B0120500BB Forwards questions re B01017 shutdown following discovery of major leak in secondary cooling sys. Subsequent events indicate incident may be more serious than believed & independent inquiry initiated. Responses requested by B01231. FINK.S., KOTPELL.O. New York, State of. B0/11/25. 3pp. 07173:324.

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

G. Adjudicatory correspondence

B012070367 Requests hearing per 10CFR50 on issue of whether all safety-related electrical equipment should be environ qualified by 820630 per NUREO-0388. In interim. util will attempt to resolve concerns w/NRC. PORTER.H.L. Dute Power Co. 80/12/03. 1p. 07201:172.

M. Antitrust correspondence

- 8012300030 Order granting attached licensee commitments, agreed to by util, DDJ & NRC.
 TUBRIBY, J. F. Atomic Bafety and Licensing Board Panel. 74/05/24.
- --8012300040 Request for order directing licenses be amended per attached conditions.DOJ & util join in motion.Order would terninate NRC prosecutorial role but NRC would remain as party, Certificate of Svc encl. VOGLER, B. H. Atomic Energy Commission. 74/05/13. 9pp.

P. Operating license stage documents & correspondence

- B012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PHRs & describes program NRC is undertaking to review capability of operating PHRs to remove decay heat following earthquake.

 EISENHUT, D. O. Division of Licensing. B0/10/21. 4pp.
- 8012030847 Requests fee.psr 10CFR170.for application for Tech Spec changes re term "operable" for facilities. MILLER.W.G. License Fee Hanagement Branch. 80/10/29. 1p. 07149:075.
- BOIR100311 Forwards nonproprietary & proprietary responses to licensing Questions 1-5 re fuel rack & proposed spent fuel rerack in response to tRC 801024 request Application & affidavit for withholding encl.
 PARKER.N.D. Dute Power Co. 80/10/31. 25pp. 07280:001.
- 8012160050 Ltr to operating plant licensees, QL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating tractor licensee confirmation in 45 days that Enci 1 implementation dates will be met. EISENHUT, B. C. Division of Licensing. 80/10/31. 7pp.
- 8012020036 Forwards Amends 88,88 & 85 to Licenses DPR-39, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
 REID.R.W. Operating Reactors Branch 4. 80/11/07. 3pp. 07148:311.
- --8012020042 Amends 88.98 % 85 to Licenses DPR-38.DPR-47 & DPR-55, respectively, revising Tech Specs re inservice insp program. REID.R.W. Operating Reactors Branch 4. 89/11/07. 799. 07148:317.
- --8012020051 Safety evaluation supporting Amends 83.88 & 85 to Licenses DPR-38.99R-47 & DPR-55, respectively. * Operating Reactors Branch 4. 60/11/07. 9ap. 07148:330,
- --8012070057 Notice of issuance & availability of Amends 88.88 & 85 to Licenses DPR-38.DPR-47 & DPR-55-respectively. REID.R.W. Operating Reactors Branch 4. 80/11/07. 2pp. 07148:339.
- 8012020807 Ack receipt of 800818 ltr re safety-grade upgrade of existing control grade anticipatory reactor trips. Forwards request for addl info to complete environ review of switches.

 REID.R.W. Operating Reactors Branch 4. 80/11/12. 5pp. 07145:319.
- B012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BNR Feedwater Norsie & Control Rod Driva Return Line Norsie Cracking," Confirmation that implementation dates will be mat must be sent within 45 days, M/O enci. EISERMUT, D. O. Division of Licensing. 80/11/13. ip.

- 8012030845 Informs of review of emergency feedwater sys against NUREO-0660 criteria.Forwards request for add1 info necessary to complete review.Requests response within 60 days.
 REID.R. N. Operating Reactors Branch 4. BO/11/14, 16pp. 07150:089.
- B012240137 Ack Teceipt of B01020 application proposing Yech Spec 6.6.2.1.a(9). Class III fee required for one unit, Class I fee for other two units.
 MILLER.W.D. License Fee Management Branch. 80/11/26. 1p.
- 8012050448 Requests extension until 810115 to respond to NRC 801027 ltr re standby shutdown facility. Time needed to gather input & assemble info into presentable form. PARKER. N. O. Duke Power Co. 80/12/01. 1p. 07171:347.
- 8012100374 Application to amend Licenses DPR-38, DPR-47 & DPR-55, deleting Tech Spec 4, 20, as requirements are contained in inservice insp program submitted 790515. Info re reactor vessel internals vent valve encl. PARKER, N.D. Dute Power Co. 80/12/04. 3pp. 07219; 032.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State buriel site conditions. Forwards results of IE survey. BENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220396 Forwards tabulation & summary of IE survey on low level waste at 31 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BAKSARTIR.L. Effluent Treatment Systems Branch. B0/11/06. Opp.
- B012290480 Informs that safety-grade design of anticipatory reactor trip sys is acceptable. Environ qualification review of applicable components incomplete. Safety evaluation providing basis for installation & operation of sys encl. REID, R. H. Operating Reactors Branch 4. 80/12/04, 2pp. 07335; \$29.
- --8012290494 Safety evaluation re final design & implementation of safety grade anticipatory reactor trip on turbine trip or loss of main feedwater. Proposed mods satisfactory.

 + Operating Reactors Branch 4. 80/12/04, 3pp. 07335:131.
- 8012220230 Hotification of 801216 meeting w/BSM owners group in Bethasda. MD re resolution programs & schedules of TMI-2 task action plan items. THROM, E.D. Reactor Systems Branch. 80/12/09. 2pp. 07307:158.
- 8012240474 Notification of 801216 meeting w/B&W owners group for small break LOCAs in Bethesda. MD for presentation of programs & schedules for resolutions of TMI-2 task action plan items. THROM, E.D. Reactor Systems Branch. 80/12/09. 2pp. 07324:175.
- 8012160325 Responds to NRC B01126 request for license fees as suppl to util B01020 ltr re addl reporting requirement. Inclusion of requirement was administrative action & does not warrant fee inposition. PARKER, N. O. Duke Power Co. 80/12/10. 1p. 07262:008.
- B012230450 Forwards status of implementation of NUREG-0737 items in response to NRC B01031 itr. PARKER, W. G. Duke Power Co. 80/12/15. 8pp. 07314:123.
- B012230435 Forwards add1 fee for 800519 application for amend to licenses re disposal of contaminated oil by burning. PARKER, H.O. Duke Power Co. 80/12/17. lp. 07312:265.

Q Inspection reports, IE Bulletins & correspondence

- B012160042 Forwards IE Info Notice 80-97, "Containment Cooler Leats & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
 O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/24.
 1p. 07262:176.
- BO12:7028: Forwards Suppl 3 to IE Builetin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
 O'REILLY,J.P. Region 2, Atlanta, Office of the Director. BO/10/24.
 Ip. 07268:265.
- B012170B13 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. 0'REILLY,J.P. Region 2: Atlanta, Office of the Director. 80/10/30, 1p. 07266: 271.

- 8011210440 Forwards 801101 Revision 5 to util 90-day response to IE Bulletin 79-018, replacing Revision 4 in entirety.
 THIES.A.C. Duke Power Co. 80/10/31, 2pp. 07029:168.
- 8012170571 Forwards IE Info Notice 80-39, "Melfunction of Bolenoid Valves Mfg by Valcor Engineering Corp." No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Diffice of the Director. 80/10/31.

 1p. 07264:124.
- 8012230050 Forwards IE Circular 80-23, "Potential Defects in Baloit Power Sys Emergency Generators." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- B0i2110749 Forwards IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. B0/i1/06. ip. 07224:199.
- B012030B73 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07.
- 8012080503 Forwards IE info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Bease Unit 1." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. BO/11/10. 1p. 07183:017.
- 8012040172 Forwards IE Bulletin 80-23, "Failures of Bolenoid Valvas M/g by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. D'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/14. ip. 07158:084.
- 80120404B2 Forwards IE Sulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Unitten response required. Requests info on manpower expended. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/21. ip. 07163:349.
- 8012180591 Forwards responses to action Items 1 & 2 of IE Bulletin BO-23, "Faulure of Bolenoid Valves Mfg by Valcor Engineering Corp." Facility has had three failures of Valcor solenoids. PARKER.M.O. Duke Power Co. BO/11/24. Bpp. 07271:351.
- 8012170309 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Tarry Turbine Steam Inlet Flange." No written response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/26. io.
- B012310167 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." No described Anchor Darling valves in use at facilities. Manufacturers being contacted revalve parts.

 PARKER. N. G. Duke Power Co. 80/12/05. 1p. 07370:023.
- 8012160435 Forwards add1 info re insp of fuel assembly holddown springs at facility & safety evaluation of operation w/broken springs in core.

 PARKER, W. O. Duke Power Co. 80/12/09. App. 07263:049.
- 8012310085 Forwards safety evaluation re util actions taken in response to NRC 790528 ltr re cracking in feedwater sys piping at facilities.
 REID, R. W. Operating Reactors Branch 4. 80/12/09. 2pp. 07371:160.
- ****B01231009! Bafety evaluation re util actions taken in response to NRC 790525 ltr on cracking in feedwater sys piping at facilities. Augmented insps per IE Bulletin 79-13 may be discontinued.

 4 Operating Reactors Branch 4. 80/12/09. 2pp. 07371:162.
- R. Periodic operating reports & related correspondence
- 8012190615 Forwards monthly operating repts for Nov 1980. PARKER.N.O. Duke Power Co. 80/12/15. 1p. 07288:245.
- --8012190619 Monthly operating repts for Nov 1980. REAVIS, J. A. Duke Power Co. 80/12/15. 16pp. 07288: 246.

- S. Reportable occurrences, LERs & related correspondence
- B012100477 Forwards LERs identified as missing in B01104 memo.Encl LERs cancelled. LENIS.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. B0/12/03. ip. 07218:090.
- B012230479 RO correcting B01209 rept of broken holddown springs. Five springs broke not four as originally reported. Assembly 1D30 identified as having broken spring. All other info in 801209 itr is valid.
 PARKER, N. D. Dute Power Co. 80/12/15. 2pp. 07318: 320.
- B012230514 Forwards LER 80-015/03L-0. PARKER, N. O. Duke Power Co. 80/12/17. 2pp. 07316: 293.
- --8012230520 LER 80-015/03L-0: on 801117, borated water storage tank level channel B declared inoperable due to erractic indication in Unit 3 control room. Caused by transmitter malfunction. Transmitter replaced.

 JDNES. J. L. Duke Power Co. 80/12/17. 1p. 07316: 295.
- 8012300471 Forwards LER 80-016/03L-0. PARKER, N. D. Duke Power Co. . 80/12/23. 2pp. 07349:344.
- --8012300475 LER 80-016/03L-0: on 801123, fire detector string B-2 went into alarm condition. Investigation revealed no fire. Caused by dust buildup in detector. Detector cleaned & varified operable.

 JONES, J. L. Duke Power Co. 80/12/23. 1p. 07349: 346.
- 8012300485 Forwards LER 60-017/63L-0. PARKER: H. O. Duke Power Co. 80/12/26. 2pp. 0730B: 001.
- DOCKE: 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8012040180 Public version of "Independent Assessment of Evacuation Times for TMI Nuclear Power Plant," Vol 10, prepared for FEMA. GOSBY, J. C., BHEPPARD, W. V., THOMPSON, W. E. Wilbur Smith & Associates. 80/06/30. 51pp. 07161: 238.
- B012010446 Forwards comments on 790815 guard training & qualification plan. Revisions & addl info required. Requests response within 30 days of receipt of ltr. Encl withheld (ref 10CFR2, 790). REID.R.W. Operating Reactors Branch 4. 80/11/07. 4pp. 07097:009.
- B012050477 Informs that mode will be made to emergency notification sys & health physics network equipment, NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operations facilities. ORIER, B.H. Region i, Philadelphia, Office of the Director. B0/11/14. 2pp. 07174: 253.
- B012170645 Notifies of interim rule suspending completion dates for fire protection mods previously approved by NRC FR notice encl.
 EIBERHUT, D. O. Division of Licensing. 80/11/18. 7pp. 07269:195.
- 8012170499 Forwards Suppl 5 to 780919 fire protection safety evaluation in response to licenses 780612.0929.790914.800319 & 0930 itrs. Suppl presents position on mods needed to resolve open items.
 REID.R.W. Operating Reactors Branch 4. 80/11/19. 5pp. 07270:342.
- --8012170503 Fire protection safety evaluation Suppl 5, re licensee 780612,0929,790914.800319 & 0530 submittals on open items & plant mods.Fire protection program review status enci.

 d Operating Reactors Branch 4. 78/09/19. 5pp. 07270:347:
- 8012040065 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summery. FELTON.J.H. Division of Rules and Records. 80/12/03. ip.
- --B0120400BB Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEMA. 4 Wilbur Baith & Associates. 80/06/30. 17pp.

- --8012040159 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol 1.prepared for FEMA. COSBY.J.C. Wilbur Smith & Associates. 80/06/30, 43pp.
- 8012(6042) Requests extension until 801230 to provide results of vital area analysis review & description of proposed changes to THI security plan.
 HUMILL.H.D. Metropolitan Edison Ca. 80/12/10. 1p. 07252:102.
- 8012190036 Releases public version of revised util emergency plan. FELTOR J.M. Division of Rules and Records. 80/12/10. 1p. 07281:087.
- --8012190094 Public version of emergency plan. Revision 2. * General Public Utilities. 80/05/30. 200pp. 07281:088.
- e012290456 Releases 1tr discussing status of emergency planning. FELTON J. M. Division of Rules and Records. 80/12/17. 1p. 07336:238.
- --8012290461 Public version of response to NRC 801105 ltr re current status of emergency planning & implementation of revised plan. Revision 3 represents significant upgrade to site emergency preparedness. Plan will be submitted by 810102. HUKILL, H. D. Metropolitan Edison Co. 80/12/10, 1p. 07336:240.
- B012290187 Forwards Revision 1 to guard training & qualification plan. Plan withheld (ref 100FR2.790). MUKILL-H.D. Metropolitan Edison Co. B0/12/19. 2pp. 07344:£85.
- G. Adjudicatory correspondence
- 8012070660 Forwards util 801107 rept to Securities & Exchange Commission for use in restart proceeding per 790721 request. CONDON,V.H. General Public Utilities - GPU Service Corp. 80/11/17. 1p. 07141:293.
- --8012020A68 Forwards 801107 rept re TMI-2 accident & aftermath. CONDON. V. H. General Public Utilities GPU Service Corp. 80/11/07. 9pp. 07141-294.
- --8012020674 Pstition to implement early determination of complaint against temporary rates per PA Public Util Commission 800523 order.
 SMITH.F.J. Metropolitan Edison Co. 80/10/27. 10pp. 07141:303.
- --B012020487 Decision denying util patition for increase in levelized energy adjustment clause.
 BARBOUR, C. H. New Jersey, State of. 80/10/02. 34pp. 07141; 321.
- 8012040418 Ack receipt of notice of 801124 hearing re THI-1 restart. Discusses radiological emergency planning. THI-1 restart poses threat to public health & property. THI-1 conversion to non-nuclear fuel would reduce rists. Press clippings encl. METCALF, K. K. Neu Hampshire Clamshell. 80/11/24. 14pp. 07158:185.
- 8012240014 Order adopting agreement reached at 801124 meeting rereporting on emergency planning contentions. Parties will meet again on 801219. SMITH, I.W. Atomic Safety and Licensing Board Panel, 80/11/25. 2pp. 07324:200.
- S012160144 Forwards SEC Form 10-0.Quarterly Financial Rept & supporting not comments, in response to NRC 770921.1107 & 800811 requests for info re significant financial developments affecting utils in restart proceeding. CONDON, V. H. General Public Utilities. 80/11/26. 3pp.
- --8012:60154 Quarterly Financial Rept Sept 1980 & supporting mgt comments. 4 Gameral Public Utilities. 80/11/14. 44pp.
- 8012120544 Forwards IE Insp Repts 50-289/80-19, 50-289/80-21, 50-320/79-10, 50-289/80-23 & 50-289/80-27. Health Physics Appraisal 50-289/80-22 to be distributed after util proprietary review. H/o enci.
 SNANSUN, D. T. Hearing Stanch 1. 80/11/28. 2pp. 07227:302.
- 8012050384 Requests mod of 790702 & 0809 orders re restart as natl & regional interests are needlessiv sacrificed by continued delay in developing & implementing procedures for expeditions authorization, DIECKAMP, H. General Public Utilities GPU Bervice Corp. 80/12/01.11pp. 07173:327.

- 8012110410 Forwards General Public Utils 801201 itr to Commissioner Ahearne ra TMI-1 shutdown. BLAME, E. L. Shaw, Pittman, Potts & Trowbridge. 80/12/03. 2pp. 07224:166.
- ---B012110417 Requests mod of NRC 790702 & 0809 orders re TMI-1 shutdown. Bases for making suspension orders have been satisfactorily resolved.

 DIECKAMP.H. Oeneral Public Utilities. B0/12/01. 11pp.
- 8012290914 Order directing Environ Coalition on Nuclear Power (ECNP) to rept on or before 801215 whether or not ECNP intends to appear & prosecute remaining contentions. Excerpts from 801203 transcript & Certificate of Svc encl. SMITH.I.M. Atomic Safety and Licensing Board Panel. 80/12/04. 7pp. 07444:209.
- B012170610 Submits revised first page of 801201 ltr,which incorrectly identified Feb 1980 as anticipated date for completing hearings on factlity. Feb 1980 was anticipated date for initiating hearings.

 DIECKAMP.H. General Public Utilities GPU Service Corp. B0/12/05. 2pp. 07187:001.
- ~-8012170513 Requests startup due to hardship on stockholders. SCHNARTZ, H. H. Affiliation Unknown. 80/12/14. 2pp. 07187:001.
- 8012270198 Notice of appearance in proceeding.Certificate of Byc encl. ADLER.R.W. Pennsylvania, State of. 80/12/08. 2pp. 07344:183.
- 80:2170748 Response in support of 8C Sholly 80:124 spec of emergency planning contention re reliance of county plans on municipal resources. Although further spec would be useful contention is litigable in present form. Certificate of Svc encl. GRAY, J. R. Hearing Branch 1. 80/12/09. Spp. 07265:354.
- 8012150172 Informs that page one of itr from E Waiss re TMI-1 restart hearings was inadvertently undated. Date should be 801207. EHRMANN, E. Union of Concerned Scientists. 80/12/10. ip. 07240:023.
- 8012150175 Forwards util 801205 ltr to Commissioner Ahearne. BLAKE,E. L. Shaw, Pittman, Potts & Trowbridge. 80/12/16. 2pp. 07241:155.
- --8012150178 Forwards corrected excerpt of util 801201 ltr re anticipated restart hearing dates. Hearings will begin Feb 1981.
 DIECKAMP, H. General Public Utilities. 80/12/05. 2pp. 07241:157.
- 8012290028 Forwards amended Page 2 to Chairman Ahearne separate views contained in 801205 Order CLI-80-37 re treatment of psychological stress issue in restart hearing.

 * Docteting & Services Branch. 80/12/10. ip. 07344:223.
- --8012270031 Modified Page 2 of Cheirman Ahearne separate views contained in 801205 memorandum & order re-treatment of psychological stress issue in TMI-1 restart proceeding. AHEARNE, J. P. Commissioners, 80/12/10, ip. 07344:224.
- B012290134 Requests identification of contentions mentioned in t. Bickwit 801114 statement re relevancy of UCB contentions. Requests to be informed of nature of discussions w/Ofc of General Counsel. Transcript of 801114 briefing encl. MEISS.E.R. Union of Concerned Scientists. B0/12/10. 2pp. 07344:044.
- 8012290416 Forwards NUREO-0746, "Emergency Preparedness Evaluation for TMI-1," which constitutes NRC evaluation of licensee smergency plan against NUREG-0654 stds. GRAY, J. R. Hearing Branch 1. 80/12/10. 1p. 07336; 326.
- --8012290421 "Emergency Preparadness Evaluation for TMI-1."

 d Office of Inspection & Enforcement, Office of the Director.
 NUREO-0746. 80/12/31. 35pp. 07336:327.
- 8012230300 Memorandum & order supplementing 801125 memorandum & order. Parties may serve interrogatories at 801219 meeting. Time for 301219 meeting re further emergency planning discussions rescheduled.
 SMITH J. Atomic Safety and Licensing Board Panel. 80/12/11. 4pp. 07318: 063.
- 8012290335 Forwards CT Johnson 801124 ltr to PA Emergency Mgt Agency requesting info re state & local emergency planning around TMI facility.

 CRAY, J. R. Hearing Branch 1. 80/12/12. 8pp. 07332:175.

- 8012230282 Notice of withdrawal from proceeding effective 801215. Certificate of Svc encl. PATON.M.B. Hearing Branch 4. 80/12/15. 3pp. 07318:036.
- B012290514 Response in opposition to ASLB B01125.1204 & 1211 memoranda & orders. Intervenors intend to prosecute remaining emergency planning contentions. Certificate of Byc encl. JOHNSRUD. H. Environmental Coalition on Nuclear Power. B0/12/15.
- B012300161 Requests to make limited appearance statement at TMI-1 restart hearing. FREEDMAN, P. F. Affiliation Unknown. 80/12/15. 1p. 07356:228.
- 8012310405 Requests that date for submittal of testimony on training & testing issue be extended until 810202.NRC approval of new Met Ed training & testing procedures lacks scientific basis. Related correspondence.

 AKKODT.M. Affiliation Unknown. 80/12/15. 7pp. 07369:156.
- BO12300264 Opposes licensee request for reconsideration of NRC 790702 & OB09 orders re restart. Motion is untimely & contains no new info. Orders suspended facility operation until bases for suspension were resolved. W/Certificate of Svc. CUNNINGHAM. J. Newberry Township TMI Steering Committee. BHOLLY, S. C. Affiliation Unknown, HARTNETT, M. Three Mile Island Alert. B0/12/18 45pp. 07358.135.
- --B012300269 Revises 801201 request for mod of NRC 790702 & 0809 orders re THI-1 shutdown. Public hearings must be initiated by Feb 1980. Apeture cards only in PDR. DIECKAMP.H. General Public Utilities. B0/12/05. 11pp. 07398:212.
- --B012300273 Discusses hearings on THI-1 restart. Full adjudicatory proceeding is required, including opportunity for full Gommission review of Board decisions. No review process is required prior to restart.

 BICKHIT.L. Office of the General Counsel. 79/07/26. 10pp.
- 8012270003 Forwards PA Emergency Mgt Agency 801204 response to FEMA re offsite emergency planning contentions for TMI-1 restart hearings, List of documents initially submitted to Regional Assistance Committee encl. Related correspondence. ADLER, R. M. Pennsylvania, State of, 80/12/22. App. 07344:190.
- 8012290592 Forwards testimony on CLI-80-5 & "Rept of TMI-1 Operator Accelerated Retraining Program Review Committee." W/o attachments. Certificate of Bvc encl. BLAME, E. L. Bhaw, Pittman, Potts & Troubridge. 80/12/22. 8pp.
- BO12310307 Notice that PA Emergency Mgt Agency map, "TMI Nuclear Plant Evacyation Plan," (May 1980) was made available at B01219 amergency planning meeting, ADLER,R.W. Pennsylvania, State of. B0/12/22. 3pp. 07370:181.
- B012300449 Requests NRC response to 10 questions re need for reactor vessel level instrumentation, per Board 801217 memorandum & order allowing informal discovery in restart hearing. BAYER, T.A. Shaw, Pittman, Potts & Trowbridge. B0/12/23. 5pp. 07357:188.
- H. General correspondence
- B012010411 Responds to B01027 postcard re nuclear power & resulting radwaste. Hearing on resumption of Unit 1 started on B01015. President's 791207 statement on Kemany Commission & B00212 statement to Congress encl. DENTON, R. Office of Nuclear Reactor Regulation, Diractor. B0/11/07. 10pp. 06916:001.
- B012230003 Requests restart of facility due to energy need & knowledge gained after accident.
 TUCKER, J. J. Pennsylvania Voice of Energy. B0/11/15. 2pp.
 07311:146.
- BO12110413 Supports restart of TMI-1. MCINTOSH, J. Affiliation Unknown. 80/11/17. 2pp, 07223:001.
- 8012030774 Responds to 801021 referral of Douglass ltr re adequacy of hearing room for facility restart hearing Adequate space not available in federal bldg Space had to be in convenient location in Harrisburg.PA & sasily accessible to public. DIRCKS.W. J. Office of the Executive Director for Operations. 80/11/18, ip. 07149:285.

And the second of the second o

- --8012030781 Forwards M Douglass 801019 ltr re fumes in garage being used for facility restart hearings. GDDU_INO.B. House of Rep. 80/10/21. 2pp. 07149:289.
- 8012030698 Requests support in proceeding NRC ordered THI-1 to shutdown but allows similar plants to operate Nuclear power is needed due to world instability of fossil fuel prices. TERRELLIO.D. Affiliation Unknown. 80/11/20. ip. 07151:219.
- 8012039441 Urges swift restart of facility due to need for energy. JAKOBCIN.N.D. General Electric Co., Nuclear Energy Products Div. B0/11/21. 2pp. 07149: 356.
- 8012030700 Urges restart of TMI-1. Facility meets stds of reactors licensed by NRC.
 MCGARTHY, L. H. Affiliation Unknown. 80/11/21. 1p. 07:51:220.
- 8012030704 Requests that facility be permitted to restart. Unit was not damaged has operated satisfactorily & has no reason to remain shut down. To continue to import oil or pollute landscape w/coal is unthinkable.

 CAMPBELL.R.M. Massachusetts Voice of Energy. 80/11/25. lp. 07151:231.
- 8012040398 Urges restart of facility due to other B&W PWRs w/identical design being permitted to continue operation.
 LAIRD: S. W. Affiliation Unknown. 80/11/25. ip. 07159:179.
- 8012040375 Requests immediate restart of undamaged reactor. Alleges NRC attempt to punish General Public Utils through shutdown.
 Cites drastic greenhouse effect of fossil fuel burning.
 TBCHAECHE.A.N. Affiliation Unknown. 80/11/25. 1p. 07158:180.
- BO12040476 Supports facility restart Lists reasons why facility should be allowed to resume operation including implementation of safety features, sconomic well-being & assistance to national energy program. Further delays should be eliminated, HUNTLEY, H. M. Affiliation Unknown. 80/11/25. 1p. 07157:263.
- 8012110360 Urges that facility be returned to evc. Nation cannot afford to remove nuclear option from energy future.
 FLORRETCH, C. New Orleans Editon League. 80/11/26. 1p. 07224:143.
- 8012030712 Urges restart of THI-1.in light of domestic energy supply situation.

 MALLACE.J.J. Affiliation Unknown. 80/11/28. 1p. 07151:232.
- 8012050368 Expresses disapproval of Unit i startup. ESTEB.C., HAND.A., BOWERB.J.R. Affiliation Uninown. 80/11/28. 3pp. 05915:001.
- 8012030705 Urges restart of TMI-i. COMOVER.W.K. Affiliation Unknown. 80/12/01. 1p. 06586:003.
- 8012100438 Requests TMI-1 restart Action will make money available for speedy & safe cleanup of TMI-2.
 VEKUQIZIR.J. Affiliation Unknown. 80/12/01. 1p. 07187:001.
- 8012110370 Requests expeditious restart of TMI-1 to reduce reliance on foreign oil. FISCHER, D. L. Affiliation Unknown. 80/12/01. ip. 07223:075.
- 8012070285 Urges restart of THI to alleviate growing cost of electricity. MARCH.R.N. Affiliation Unknown. 80/12/02. 2pp. 07201:097.
- 8012100492 Desires restart of TMI-1 so that util rates will be lower. SMITH.E.R. Affiliation Unknown. 80/12/02. ip. 07187:001.
- B012110374 Bupports restart of TMI-1. Fact sheet supporting use of nuclear power enci.

 QQULD, W. Affiliation Unknown. 80/12/02. 2pp. 07223: 073.
- 8012110400 Urges restart of TMI-i on behalf of Nomen in Energy. Delay is unreasonable at time when nation is striving for energy independence. DILBAVER.D. Women in Energy. 80/12/02. ip. 07224:164.
- 8012150163 Bubmits comments urging Yill-i restart. STROUP, S. R. Affiliation Unknown. 80/12/02. 1p. 07237:225.
- 8012170668 Advises that research shows that facility meets all TMI Lessons Learned requirements.

 DUBGSE-D.S. Duke Power Co. 80/12/02. 1p. 07187:001.

- 8012290520 Requests TMI-1 restart. MUDCE.E. Affiliation Unknown. 80/12/02. 1p. 07335:173.
- 8012100431 Requests expedited restart of facility. SMITH.B.C. Affiliation Unknown. 80/12/03. 1p. 07218:288.
- 8012100434 Supports NRC proceeding to authorize restart of TMI-1. FORT, J. E. Affiliation Unknown. 80/12/03, ip. 07218:287.
- 8012110357 Requests support of unit restart provided all identified safety ends are completed.

 MCCARTER-J.T. Affiliation Unknown. 80/12/93. 1p. 07223:101.
- B012110405 Urges restart of TMI-1 to ease financial burden of util & customers & to reduce nat! dependence on foreign oil.
 BAYLOR, J. S. Affiliation Unknown. B0/12/03. ip. 07224:165.
- 8012100498 Expresses opinion that psychological stress issue should be addressed before any other issue re-restart of TMI-1.

 HOSSLER.D. Affiliation Unynown. 80/12/04. ip. 07220:043.
- 80:21:0402 Requests action to expedite restart as facility was not involved in TMI-2 accident.
 LANG.9. Affiliation Unknown. 80/12/04. ip. 07223:004.
- 8012150105 Questions NRC decision to keep TMT-1 inoperable during mods. WISKUS, A. T. Affiliation Unknown. B0/12/04. 1p. 07187:001.
- 8012150160 Requests that THI-1 be brought up to present stds & restarted.
 WILLIAMS.S.B. Affiliation Unknown. 80/12/04, 1p. 07187:001.
- 6012170654 Requests action to return TMI-1 since unit was not damaged during accident.
 MIYCHELL.R.C. Arkansas Power & Light Co. 80/12/05. ip. 07187:001.
- B012190104 Requests restart of TMI-1. OCHITELL.M. Affiliation Unknown. B0/12/08. ip. 07187:001.
- B012150115 Urges NRC to support TMI-1 restart. Inequities caused by levelized ratemaking do not account for major accidents. NRC response to cleanup has been unnecessarily, unjustly & illegally delayed.

 ANZELONE, S. Affiliation Uninown. B0/12/08. 2pp. 07187:001.
- 80(2)50(50 Discusses penalties imposed by not restarting TMI-1. Urges TMI-1 restart.
 DILLON.J. J. Affiliation Uninown. 83/12/09. 1p. 07237:221.
- 8012150186 Opposes TMI-1 restart. DBUGLAS, M.H. Affiliation Unknown. BO/12/08 ip. 07187:001.
- 80:2170643 Requests that facility be returned to svc immediately in order that power needs in area may be served & confidence in nuclear industry may be preserved.

 CARTHRIGHT.M. Affiliation Uninown. 80/12/08. 1p. 07:87:001.
- B012170650 Requests that unit be restarted immediately. SCHULZE,R. Affiliation Unknown. B0/12/08. ip. 07187:001.
- B012170674 Requests extension until B01218 to respond to Met Ed ltr requesting that Commission reconsider 770809 order & permit restart. MEISS,E.R. Union of Concerned Scientists. 80/12/09. 1p. 07187:001.
- BO12150164 Requests that TMI-1 be returned to svc.
 BRAUN,L., RICHARDSGN.D. Long (sland Committee for Jobs & Energy Independence. 80/12/09. 1p. 07237:226.
- 8012170517 Requests startup due to hardship on stockholders. MALKER, F. T. Affiliation Unknown. 80/12/09, lp. 07107:001.
- B012170632 Advises that facility provides necessary power source & should be restarted.

 TROUTMAN.H. A. Affiliation Unknown. B0/12/09. ip. 07187:001.
- 8012170635 Opposes any action other than prompt decontamination & decommissioning of facility.

 ODRKLEY, J.F. Affiliation Unknown. 80/12/09. ip. 07187:001.
- 8012170658 Comments, by Marion Plywood Corp in Marion, WI. on facility restart. Facility should be restarted due to necessity of nuclear power.
 ROCERS. J. O. Affiliation Uninown. 80/12/09. 1p. 07187:001.

- B012170264 Discusses util 801201 request that Commission reconsider & modify 790702 & 0809 orders re facility restart. Util should not be permitted to restart facility.

 PICKERING. K. Affiliation Unknown. 80/12/09. 1p. 07187:001.
- 80:21:10523 Informs that Liberty Bass Club is greatly concerned over TMI issue & effects on fishing grounds. Requests halt to disposal of radvaste in Susquehana river.

 HAILE-L. Affiliation Unknown. 80/12/10. 1p. 07222:358.
- 8012170620 Urges startup. Hysteria resulting from accident was inspired by media America desperately needs electrical power.

 HADEIRA, R. L. American Association of Meat Processors. 80/12/10.
 1p. 07187:001.
- G01217064B Requests help in getting NRC action for facility startup. Startup urgently needed to replace expensive oil fuel. KENDALL B. L. Affiliation Unknown. 80/12/10. 1p. 07187:001.
- --801217045; Requests startup of facility due to hardship on stockholders. SUFLESKI.C. Affiliation Unknown. 80/12/15, 2pp. 07187:001.
- --8012170653 Supports nuclear power & urges restart. REED. H. R. Affiliation Unknown. 80/12/09. 1p. 07187:001.
- ~-B012170655 Supports facility restart.
 BESHORE.M. Affiliation Unknown. B0/10/21. 1p. 07187:001.
- --8012170660 Expresses concerns re future of nuclear power. Unit should be restarted. KRIZAN.P. Affiliation Unknown. 80/10/22. 2pp. 07187:001.
- --8012170673 Urges that facility be restarted. * Affiliation Unknown. 80/10/25. 1p. 07187:001.
- --8012170681 Supports nuclear power.Facility should be returned to svc. FERWICK.A.J. Affiliation Unknown. 80/12/03. 2pp. 07187:001.
- --B0121706B6 Opposes efforts by util to reopen facility.
 PRATT.D., ANDERSON.E. Affiliation Unknown. 80/12/09, 1p.
 07187:001.
- --B012170688 Opposes facility restart due to psychological stress on area residents.
 CHARLES M. A. Affiliation Unknown. B0/12/09, '2pp, 07187:001.
- --8012170691 Urges restart of plant to full operational status. ZAAYENGA,R. Affiliation Unknown. 80/12/15. 1p. 07187:001.
- --8012170696 Urges restart of plant & nondiscriminatory policies that will insure energy future for generations to come.
 VEOA.D.U. Affiliation Unknown. 80/12/09, ip. 07187:001.
- ---8012170498 Urges restart of plant. WILD.A.A. Affiliation Unknown. 80/12/11. 1p. 07187:001.
- --8012170704 Urges NRC to support & vote for immediate restart of plant. IREDALE, J. R. : IREDALE, A. Affiliation Unknown. 80/12/10. 1p. 07187:001.
- --B012170707 Comments on restart of plant.NRC has obligation of returning Unit 1 to svc in order to avoid setting dangerous precedent of keeping operable plant out of svc.
 WACKER, H. Affiliation Unknown. B0/12/10. 2pp. 07187:001.
- --8012170714 Comments on behalf of Pioneer Nuclear, Inc on facility restart.NRC should place situation in realistic perspective & allow plant to return to svc.
 STEWART.R. 8. Affiliation Unknown. 80/12/08. 1p. 07187:001.
- --8012170717 Requests affirmative NRC decision re restart of plant. COLLINS.M.P. Iowa Electric Light & Power Co. 80/12/11. ip. 07187:001.
- --8012170722 Comments on restart of plant. Approval should be forthcoming at earliest possible date.

 CARLSQN, M. E. Affiliation Unknown. 80/12/11. 2pp. 07187: 001.
- --8012170724 Urgss NRC to recommend startup of plant. WANNER.D. J. Wisconsin, Univ. of, Madison. 80/12/07. 2pp. 07187:001.
- --B012170726 Urges that facility be returned to power. TRIBBLE.M. Gulf States Utilities Co. B0/12/11, 1p. 07187:001,

- --8012170730 Urges NRC to take necessary action to return plant to operation.
 BARCLAY, A. G. Affiliation Unknown. 80/12/05. 1p. 07187:001.
- --8012170733 Encourages NRC to allow unit to reopen.
 BLANCHETTI.V. Affiliation Unknown. 80/12/13. ip. 07187:001.
- ---B012170736 Requests that operation of facility be resumed.
 BEREDETTI.F.P. Affiliation Unknown. 80/12/11. 1p. 07187:001.
- --8012170742 Urges that facility remain closed. DAVIS-B.S. Affiliation Unknown. 80/12/08. 1p. 07187:001.
- 8012290174 Requests reopening of facility. SAYER8,E.D. Affiliation Unknown. SO/12/12. ip. 07308:00i.
- --8012290179 Requests facility restart. WILLIAMS.J. Affiliation Unknown. 80/12/15. 1p. 07308:001.
- --8012290184 Requests facility restart.
 JOHNSON, R. H. Affiliation Unknown. 80/12/09. 1p. 07308:001.
- --8012290189 Requests facility restart. LAHRENCE, R. M. Affiliation Unknown. 80/12/15. 1p. 07308:001.
- --8012270171 Requests facility restart. HENOGELER, J. T. Affiliation Unknown. 80/12/15. 1p. 07308:001.
- --8012270195 Requests facility restart. MARXET.J.A. Affiliation Unknown, 80/12/10. ip. 07308:001.
- --8012270200 Requests facility restart. FAULKNER.R. Affiliation Unknown. 80/12/08. 1p. 07308:001.
- --BD12290202 Requests facility restart.
 NEAVER.G.A. Affiliation Unknown. 80/12/15. ip. 07308:001.
- B012300108 Requests THI-1 restart. KRAVOTIL,E.J. Affiliation Unknown. 80/12/12. 1p. 07356:211.
- S012300125 Requests TMI-1 restart. BITNER, E. L. Affiliation Unknown, 80/12/12, ip. 07356; 217.
- 8012300132 Requests TMI-1 restart. MYERS.R.V. Puget Sound Pawer & Light Co. 80/12/12. 1p. 07356;220.
- 8012300448 Forwards Resolution 81, passed by City of York,PA on 790501, requesting that facilities not be reactivated until safety measures are taken & public hearings held.
 8R00KB,E.L. York, PA. 80/12/12. 4pp. 07357:184.
- 8012300119 Requests TMI-1 restart. EMENS:F.M. Affiliation Unknown. 80/12/13. 7pp. 07356:212.
- 8012170624 Requests that facility be restarted. Goal-burning to replace electricity source results in two premature deaths per wk. LAMBERT, J. B. Affiliation Unknown. 80/12/15. 1p. 07187:001.
- B012300101 Requests TMI-1 restart. SKLEDAR,F. Affiliation Unknown. B0/12/15. 1p. 07356:210.
- 8012300141 Requests TMI-1 not be restarted. BRINK, T. Affiliation Unknown. 80/12/16. ip. 07356:223.
- 8012300136 Requests TMI-1 restart. OTT, W. Q. Affiliation Unknown. 80/12/17. 2pp. 07356:221.
- 8012300154 Requests TMI-1 restart. SHARP.W. Affiliation Unknown. 80/12/17. 1p. 07356;227.
- 8012300172 Informs of disappointment about decision to ignore psychological stress as contention in restart hearings. LYM9.T. Affiliation Unknown. 80/12/17. ip. 07356;229.
- 8012300145 Requests TMI-1 restart. PALMETER.S.B. Affiliation Unknown, 80/12/18. 1p. 07356:224:

e ayaya ee ee ee ee ee ee

8012300151 Requests TMI-1 hearings be conducted as quickly as possible. ROSSIN, A.D. Commonwealth Edison Co. 80/12/18. 1p. 07356:226.

- B012300147 Requests TMI-1 restart. * Affiliation Unknown. 80/12/22. 1p. 07356:225.
- 8012300180 Requests TMI-1 restert. MELFRECHT.D.J. Affiliation Unknown. 80/12/22. ip. 07356;230.
- I. Financial information
- 8012020660 Forwards util 801107 rept to Securities & Exchange Commission for use in restart proceeding per 790721 request. CONDON.V.H. General Public Utilities - OPU Service Corp. 80/11/17. Ip. 07141:293.
- --8012020L68 Forwards 801107 rept re TMI-2 accident & aftermath. CONDON, V. H. General Public Utilities GPU Service Corp. 80/11/07. 9pp. 07141: 294.
- --B012020674 Petition to implement early determination of complaint against temporary rates per PA Public Util Commission 800523 order.

 SHITH.F. J. Metropolitan Edison Co. B0/10/27. 10pp. 07141:303.
- --8012020687 Decision denying util petition for increase in levelized energy adjustment clause.

 BARSOUR.O.H. New Jersey, State of. 80/10/02, 34pp. 07141:321.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8012150066 Submits status rept on TMI-1 restart, as reviewed at 248th ACRB maeting on 801204-06. NRC must issue policy on how & when action plan items are to be applied in restart evaluation. Licensee should conduct reliability assessments. PLESSET, M. B. . ACRS Advisory Committee on Reactor Safeguards, 80/12/11. App. 07240:019.
- 8012310384 Submits status rept on proposed restart of facility per ACRS 248th meeting on 801204-06. NRC statement of policy on how & when various components of action plan.near-term OL list & 770809 order will be applied needed.
 PLE888T.M.S. ACRS Advisory Committee on Reactor Bafeguards. 80/12/11. 4pp. 07369:186.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following sarthquake.

 EISERHUT.D.Q. Division of Licensing. 80/10/21. 4pp.
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that EncI I implementation dates will be net. EIGENHUT.D.Q. Division of Licensing. 80/10/31. 7pp.
- B012220563 Ltr to all power reactor licensess forwarding NUREO-0619, "BWR Feedwater Noizle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days.
- 8012090213 Ack receipt of 800411 Tech Spec Change Request 92 Class III fee required. DIOQS.R.M. License Fee Management Branch. 80/11/17. ip. 07202: 283.
- 8012080706 Informs of 800603 issuance of Amend 55 to License DPR-50, deleting redundant Toch Spec 4.14 re air treatment sys. REID, R.W. Operating Reactors Branch 2. 80/11/21. 4pp. 07187:055.
- 8012170699 Forwards add1 prorequisites for TMI-1 restart per NURE9-0694 & NURE9-0737. Required items include control room, design, NB98 vendor review of procedures, shift manning & training for mitigating core damage.

 EISENHUT, D. O. Division of Licensing. 80/11/25, 7pp. 07269: 209,
- 8012020464 Requests mod to Tech Specs Change Request 34A, App B, Page 7, re radiological & nonradiological ETS for chlorine monitoring.

 HUKILL-H. D. Metropolitan Edison Co. 80/11/26. ip. 07141:255.
- --8012020468 Proposed ETS 2.2 i re chlorine monitoring. * Metropolitan Edison Co. 80/11/26. ip. 07141;256.

- 8012040293 Forwards two sets of add1 microfilm reels of TMI data collected by util contractor.Data Hgt & Reduction Group. H/o ancl.
 REED,E.C. Hetropolitan Edison Co. 80/11/26. 1p. 07169:254.
- 8012290377 Forwards Suppl 1 to evaluation of licensee compliance w/short & long-term items of Section II of NRC 800809 drder, NUREC-0680, re TMi-1 restart. Suppl updates Section C, order Item & & describes licensee compliance.
 REID.R.N Operating Reactors Branch 3. 80/11/28. 7pp. 07330;312.
- --B012290380 Notice of availability of Suppl 1 to evaluation for TMI-1 restart.NUREG-0680.
 REID.R.W. Operating Reactors Branch 3. 80/11/28. 2pp. 0730:318
- --8012270383 "TM1-1 Restart:Evaluation of Licensee Compliance W/Short & Long-Term Items of Section II of NRC Order Dtd 770807.Met Ed Co.et al." Suppl 1.

 * Division of Licensing. NUREC-0680 81. 80/11/30, 200pp. 07380-520.
- B012090348 Bubmits mod to Tech Specs Change Request 53 re nomenclature describing radioactive contamination analysis. Tech Bpecs Change Request 53.2 received in Amend 29.

 HUKILL, H. D. Metropolitan Edison Co. B0/12/03. 1p. 07201:169.
- B0121704B1 Advises that fuel assembly holddown spring exam was completed on fuel assemblies in spent fuel pool No failed springs were found.

 HUKILL, H. D. Ketrogolitan Edison Co. B0/12/09. 1p. 07270: 290.
- 8012220730 Notification of 801216 meeting w/8&W owners group in BethesdarMD re resolution programs & schadules of TMI-2 task ection plan items. THROM.E.D. Reactor Systems Dranch. 80/12/09. 2pp.
- 8012240474 Notification of 801216 meeting w/B&W owners group for small break LOCAs in Bethesda./MD for presentation of programs & schedules for resolutions of FMI-2 test action plan items. THROM, E. D. Reactor Systems Branch. 80/12/09. 2pp.
- 80:2160521 Forwards info re environ qualification of safety-related equipment per 80:001 request. HUKILL.H.D. Metropolitan Edison Co. 80/12/12, 2pp. 07263:091.
- B012220235 Forwards listing of outstanding Tech Specs change requests availing NRC review & approval & respective implementation period requests.

 HUKILL.H.D. Hetropolitan Edison Co. B0/12/16. 2pp. 07303:250.
- 8012300398 Forwards response to Items 3 & 4 of 800811 ltr.providing add1 financial info & comments on 801107 programmatic EIS. HUKILL.H.D. Metropolitan Edison Co. 80/12/22. 4pp. 07330:001.
- 801230060B Informs that licensee response to NUREC-0737 will be delayed until 810109. HUKILL, H.D. Metropolitan Edison Co. 80/12/24. ip. 07357;329.

Q. Inspection reports. IE Bulletins & correspondence

- 8012020210 Forwards IE Insp Rept 50-289/80-26 on 800710-12. No noncompliance notes.

 CARLSGIAR. T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/02. 2pp. 07142:093.
- --B012020216 IE Insp Rept 50-289/80-26 on 800910-12.No noncompliance noted Hajor areas inspected work activities & quality records re rattart program.
 PAOLING R. J. Region i, Philadelphia, Office of the Director. EBNETER B. D. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/01. 4pp. 07142:095.
- 8012160304 Forwards IE Insp Rept 50-289/80-27 on 800910-30. No noncompliance noted. BRUNNERE.J. Region 1. Philadelphie. Reactor Operations Nuclear Support Branch. 80/10/09. 2pp. 07261:335.
- --8012160307 IE Insp Rept 50-287/80-27 on 800710-30. No noncompliance noted. Major areas inspected; maint activities re concerns expressed in prehearing proceedings of ABLB.
 BETTERMAUSEN. L. Region 1: Philadelphia, Office of the Director.
 KEIMIO.R.R. Region 1: Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/08 11pp. 07261:357.
- 8012300145 Forwards' IE Insp Rept 50-289/80-28 on 800923-25. No nencompliance noted.
 CARLBON, R. T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/14. 2pp. 07336:284.

Burney State of the State of

- --8012300169 IE Insp Rept 50-287/80-28 on 800923-25. No noncompliance noted Hajor areas inspected installations associated w/fire protection program mods under Task NM-40.
 KOLTAY-P. Region 1. Philadelphia Office of the Director, ERNETER-S. Region 1. Philadelphia Reactor Construction & Engineering Support Branch. 80/10/10. 3pp. 07356:286.
- 8012020321 Requests that response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENB) W/Loss of Diffsite Power," be resubmitted w/oath or affirmation within 10 days of receipt of itr,per 10CFR50.54.

 GRIER, B. H. Region i, Philadelphia, Office of the Director. 80/10/23. 1p. 07143:115.
- 8012170404 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/30. ip. 07269: 116.
- B012020791 Forwards resubmitted response to IE Bulletin 80-15 & required oath of affirmation per NRC 801023 ltr.
 HUKILL.H. D. Metropolitan Edison Co. 80/10/31. 1p. 07147:332.
- ~-8012020777 Submits response to IE Bulletin 80-15 w/required oath of affirmation per NRC 801023 ltr.Review of amergency motification sys conducted in conjunction w/Bell of PA. Bys ufil remain functional in event of loss of off-lite power. HUKILL, H. D. Metropolitan Edison Co. 80/09/27. 3pp. 07147:333.
- 8012120141 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcola Foundry Co. Inc." Written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230: 200.
- 8012190386 Informs util of issuance of new NRC personnel identification badges: effective after 801130. Example encl. MARYIN: N. J. Region 1, Philadelphia, Bafeguards Branch. 80/11/06. 3pp. 07286:147.
- 8012030764 Forwards IE Info Notice 80-40, "Excessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response raquired. ORIER. B.H. Region 1, Philadelphia, Office of the Director. 60/11/07. ip. 07150: 272.
- 8012080547 Forwards IE Info Notice 80-41, "Failure of Bwing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. lp. 07182:340.
- 8012040095 Forwards IE Bulletin BD-23. "Failures of Sciencid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. QRIER.B.#. Region 1. Philadelphia, Office of the Director. 80/11/14. 1p. 07158:015.
- 8012220077 Ack receipt of 801103 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/80-24.
 MARTIN.H.O. Region 1, Philadelphia, Safeguards Branch. 80/11/18.
 1p. 07306:351.
- --8012220080 Responds to NRC 801008 ltr re violations noted in IE Insp. Rept 50-2297/80-24. Corrective actions withheld (ref. 100FR2.790).

 NUKILL.H. D. Metropolitan Edison Co. 80/11/03, 1p. 07306:352.
- --8012220082 Forwards IE Insp Rept 50-289/80-24 on 800828-27 & notice of violation, Notice of violation withheld (ref 10CFR2, 790). HARTIN, W. Q. Region 1, Philadelphia, Safeguards Branch. 80/10/08. 2pp. 07304:353.
- --8012220085 IE Insp Rept 50-209/80-24 on 800825-29. Noncompliance noted: isolation zone not maintained as required Details withheld (ref 100FR2.790).
 SHEPHERD, R. E. Region 1. Philadelphia, Office of the Director. DEVLRI, J. W. Region 1. Philadelphia, Safeguards Branch. 80/10/06. ip. 07306:355.
- 8012220651 Advises that written response is required to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.

 GRIER, B. H. Repion i, Philadelphia, Office of the Director. 80/11/19. ip. 07295:050.
- 8012040242 Discusses plans for shift staffing per IE Insp Rept 50-289/80-19 on 800725-25, Questions plans for replacement operators following any authorization for restart Requests info re training plans 90 days prior to scheduled restart. REID.R.W. Operating Reactors Branch 4. 80/11/20. 4pp. 07158:169.

- 8012040508 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required Requests info on manpower expended. ORIER, 8H. Region 1, Philadelphia, Office of the Director, 80/11/21. 2pp. 07169:202.
- 8012050569 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B. H. Region i. Philadelphia. Office of the Director. 80/11/24. ip. 07174:036.
- 8012220338 Forwards IE Health Physics Appraisal Rept 50-289/80-22, natice of violation & significant appraisal findings. ORIER, B.H. Region i, Philadelphia, Office of the Director. 80/11/26 5pp. 07308:036.
- --8012220342 Notice of violation from health physics appraisal on 800728-0808. * Region i. Philadelphia, Office of the Director. 80/11/19. 4pp. 07308:041.
- --801222034B IE Health Physics Appraisal Rept 80-289/80-22. Noncompliance noted: lack of effective mgt oversight in assuring radiological controls, training & radwaste organization not clearly defined.
 NEELY, D. R., NIMITZ, R. L., DONALDSON, D. E. Region 1, Philadelphia, Office of the Director. 80/11/19. 279pp. 07308:045.
- 8012160446 Submits interim rept in response to IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Six welds remain on repair/replacement list & will be completed by end of yr.
 HUKILL, H. D. Metropolitan Edison Co. 80/12/12. 2pp, 07263:055.
- R. Periodic operating reports & related correspondence
- 8012020482 Forwards observation wells data sheet inadvertently omitted from 801119 rept.

 RIETHLE, H. E. Oeneral Public Utilities OPU Service Corp. 80/11/24.

 3pp. 07148: 127.
- 8012160473 Forwards "TMI Aquatic Study, Monthly Rept for Oct 1980."
 Requests NVREO-0596 re nonradiological consequences of facility accident on aquatic biota & fisheries of Busgehanna River.
 TEITT, T.R. General Public Utilities OPU Service Corp. 80/12/09.
 19. 07249:011.
- --8012160486 "THI Aquatic Study, Monthly Rept for Oct 1980."
 MARDACCI.G.A. Ichthyological Associates, Inc. 80/12/09. 27pp.
 07249:012.
- 8012190517 Forwards monthly operating rept for Nov 1980. HUKILL, H.D. Metropolitan Edison Co. 80/12/15. 1p. 07287:091.
- --8012170517 Monthly operating rept for Nov 1980. MITCHELL.D.G. Metropolitan Edicon Co. 80/12/15, 6pp. 07287:092.
- S. Reportable occurrences, LERs & related correspondence
- 8012190092 PNO-TMI-80-53: on B01208, util issued press release stating that claim of four billion dollars was filed against NRC for neglience re performance before TMI-2 incident & based on estimated cost of TMI-2 cleanup.
 CONIE,R., BHANBAKY,M., COLLINS,J. TMI Program Office. B0/12/08.
 2pp. 07282:136.
- 8012190110 PND-TMI-80-54: on 801709, fire started in reactor bldg containment sump apparently from sparks from air-arch cutting operations on grating above sump. Fire extinguished w/o damage.

 HAVERKAIP, D., SHANBAKY, M., COLLINS, J. TMI Program Office. 80/12/09. 2pp. 07282:138.
- T. Hearing transcripts on non-antitrust matters
- 8012040576 Transcript of 801117 hearing in Harrisburg, PA re restart. Pp 5,740-6,140.

 * Atomic Bafety and Licensing Board Panel. 80/11/19. 200pp. 07168:208.
- 8012040571 Transcript of B01120 hearing in Harrisburg, PA re restart. Pp 6,141-6,351.

 * Atomic Bafety and Licensing Roard Panel. 80/11/20, 210pp. 07182-001

- 8012040564 Transcript of 801121 hearing in Harrisburg, PA ra restart. Pp 6,352-6,456.

 * Atomic Safety and Licensing Board Panel. B0/11/21, 104pp. 07167:001.
- 8012040366 Transcript of E01124 hearing in Harrisburg.PA re restart. Pp 6:457-6:576. * Atomic Safety and Licensing Board Panel. B0/11/24. 139pp. 07164:278.
- 8012040556 Transcript of B01125 hearing in Harrisburg.PA re restart. Pp 6,597-6.823.
 # Atomic Safety and Licensing Board Panel. 80/11/25. 226pp. 07164:001.
- 8012100177 Supplemental testimony in response to ASLB Question 6 re emergency fredwater reliability. Prof qualifications & Certificate of Svc encl. KEATEN.R.W. General Public Utilities - OPU Service Corp. COLITZ.J.J., ROSS.M.J. Metropolitan Edison Co. 80/11/25. 25pp. 07218: 208.
- 8012040578 Transcript of 801126 hearing in Harrisburg.PA re restart Pp 6.824-6.937. * Atomic Safety and Licensing Board Panel, 80/11/26. 113pp. 07168:081.
- 8012040560 Transcript of Subcommittee on TMI-1 Restart 801128 meeting in Washington: DC re NRC status rept on evaluation of licensee compliance w/790809 order or NUREG-0680. Pp 1-260. Viewgraphs encl. ACRS Advisory Committee on Reactor Safeguards. 80/11/28. 260pp. 07166:001.
- B012040572 Transcript of ACRS Subcommittee on TMI-1 B01129 meeting in Washington, DC. Pp 261-430.

 * ACRS Advisory Committee on Reactor Bafeguards. 80/11/29. 149pp. 07155: 002.
- B012040594 Transcript of Bubcommittee on TMI-1 801129 meeting in Washington, DC, Pp. 431-516. Afternoon session.

 4 ACRS Advisory Committee on Reactor Safeguards. B0/11/29. 85pp. 07165:057.
- 8012120444 Transcript of ASLB 801202 evidentiary hearing in Harrisburg, PA re restart.Pp 6.938-7.143.

 * Atomic Bafety and Licensing Board Panel. 80/12/02. 206pp. 07255:091.
- 8012110492 Transcript of 801203 meeting in Harrisburg, PA re restart. Pp 7, 144-7, 332. * Commissioners. 80/12/03. 158pp. 07826:210.
- 8012070098 Transcript of 248th ACRS general meeting on 801204 in Washington DC re facility restart Pp 1-176. Vieugraphs encl. * ACRS Advisory Committee on Reactor Safeguards. 80/12/04. 176pp. 07198: 328.
- 8012290947 Testimony re UCS Contention 7. Absence of direct indication of core water level presents undue risk to public health & safety. Prof qualifications & Certificate of Svc encl. POLLARD.R.D. Union of Concerned Scientists. 80/12/04. 22pp. 07333:102.
- B012220152 Transcript of B01209 restart hearing in Harrisburg.PA. Pp 7.534-7.731.

 4 Atomic Safety and Licensing Board Panel. B0/12/09. 198pp. 07308:001.
- 8012270938 Forwards corrected testimony of DF Ross & RA Capra in response to ABLB question on UCS Contention 8. Certificate of 8vc enc). CUTCHIN.J.M. Hearing Branch 3 80/12/09. 3pp. 07332:183.
- --8012290562 Testimony in response to ASLB questions on UCB Contention 8. Prof qualifications encl. ROSB, D.F., CAPRA,R.A. Division of Bystems Integration, 80/12/09. 63pp. 07332:186.
- 8012290286 Transcript of 801210 restart hearing in Harrisburg, PA. Pp 7, 732-7, 946.

 * Atomic Safety and Licensing Board Panel. 80/12/10. 215pp. 07331:319,
- 8012270361 Transcript of 801211 hearing in Harrisburg.PA re TMT-1 restart.Pp 7,947-8,139.

 * Abomic Safety and Licensing Board Panel. 80/12/11. 94pp. 07343:148.

- B012220297 Transcript of 801212 restart hearing in Harrisburg.PA. Pp 8.140-8.258.

 4. Atomic Safety and Licensing Board Panel. 80/12/12. 120pp. 07307:162.
- 8012300604 Transcript of B01216 meeting in Harrisburg,PA re restart. Pp 8,239-8,479. * Atomic Safety and Licensing Board Panel. B0/12/16. 220pp. 07335:163.
- 8012300592 Transcript of 801217 mesting in Harrisburg PA re restart. Pp 8.480-8.656.

 * Atamic Safety and Licensing Board Panel. 80/12/17. 176pp. 07355:004.
- B012310014 Transcript of B01218 hearing in Harrisburg,PA re restart, Pp B.657-8.857. * Atomic Safety and Licensing Board Panel. B0/12/18. 202pp. 07360:067.
- 8012310222 Advises that requested documents will be placed in LPBR for insp & copying. Includes DDE rept E00-SSDC-5223, NUREO/CR-0110.V Stello B01020 itr.L Bickwit 790726 memo & recent operator license evams.
 SWANSUN.D.T. Hearing Branch i. 80/12/24. 2pp. 07369:289.
- --8012310228 Forwards NRC proposed testimony re licensee mgt capability. Includes testimony by LP Crocker,FR Allenspach,EA Boger & RR Keinig. SHANSON,D.T. Hearing Branch 1. 80/12/24. 2pp. 07369:291.
- --B012310232 Transcript of BA Boger testimony re licensed operator training (Amoudt Contention 2). Prof qualifications encl. B0088, B. A. Operator Licensing Branch. B07/2/24. 9pp. 07369:293.
- --8012310238 Transcript of RR Keimig testimony re mgt capability to operate nuclear generating station (Antinuclear Group Representing York Contention 4). Prof qualifications encl. KEIMIO.R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/12/24. 17pp. 07369:302.
- --8012310244 Transcript of BA Boger testimony re licensed operator training (Chesapeake Energy Alliance Contention 13). Prof qualifications enct. BOCER, B.A. Operator Licensing Branch. 80/12/24. 12pp. 07369: 319.
- --8012310249 Transcript of LP Crocker & FR Allenspach testimony re Asmost Contention 2. Prof qualifications encl. CROCKER, L. P., ALLENSPACH, F. R. Licensee Qualifications Branch. 80/12/24. 21pp. 07349:331.
- U. Congressional/Executive Correspondence
- 8012040406 Requests that meeting be scheduled G/CW Mellinger of Lebanon Steel Foundry to discuss TMI situation. MALKER.R.S. House of Rep., Government Operations. 80/11/26, ip. 07158:182.
- V. Operator Examinations
- 8012040242 Discusses plans for shift staffing per IE lnsp Rept 50-289/80-19 on 800723-25 Questions plans for replacement operators following any authorization for restart Requests info re training plans 90 days prior to scheduled restart. REID.R.W. Operating Reactors Branch 4. 80/11/20. 4pp. 07158:169.
- 8012170699 Forwards addi prerequisites for THI-1 restart per NUREQ-0694 & NUREQ-0737. Required items include control room design, NSSS vendor review of procedures, shift canning & training for mitigating core damage.

 EISERHUT, D. O. Division of Licensing. 80/11/25, 7pp. 07269:209.
- 8012290382 Informs that revised licensed operator qualification & requalification training program submitted in response to NRC 800328 ltr found unacceptable. Program must be revised, incorporating items listed in encl. COLLINS.P.F. Operator Licensing Branch. 80/12/01. 6pp. 07345:120.
- 8012310975 Notifies that licensee revised licensed operator qualification & requalification training program is unacceptable Open book quirzes for periodic evaluation of operator knowledge are inappropriate, Comments encl.

 COLLINS, P. F. Decator Licensing Branch. 80/12/01. 6pp. 07371:152.

- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1 A. Application/construction stage documents & correspondence
- 8012020815 Responds to WA Caswell conterns to monitoring of radiation received by residents living near nuclear power plants. No simple device can measure internal radiation. TLDs used to measure external radiation around facility.

 DIRCKS.W.J. Office of the Executive Director for Operations.

 80/11/06. 3pp. 07141:053.
- --8012020821 Tech Spec Pages 181-188 re environ monitoring & surveillance requirements. Radiation Policy Council agenda item re nonitoring & surveillance encl. + Beston Edison Co. 72/09/30. 10pp. 07141:055.
- F. Security, medical, emergency & fire protection plans
- 8012050938 Informs of existing relegancy communications sys review & resulting mods to emerg may accification sys & health physics network. NRC will have lamps installed on emergency telephones in all control rooms & technical support ctrs. GRIER. B. X. Region 1. Philadelphia. Office of the Director. 80/11/14. 2pp. 07174:248.
- 8012010455 Forwards comments resulting from review of 800701 emergency plan against NUREG-0654 criteria. Add1 info required addressing stds in 10CFR50, effective 801103. Plan should be subsitted within 45 days.

 IPPOLITO 07075: 110.
- 8012120592 Notification of 801208 meeting w/util in Bethesda.MD to discuss results of review of emergency plan. WILLIAMS.M.H. Operating Reactors Branch 2. 80/12/04. 2pp.
- G. Adjudicatory correspondence
- 8012190588 Request for hearing on 801024 re order for mod of license. DIGNAN, T. O. Boston Edison Co. DIGNAN, T. O. Ropes & Gray. 80/12/04, 2pp. 07286: 158.
- H. Oeneral correspondence
- 8012090255 Forwards HA Caswell 800825 proposal that citizens residing within 5 miles of nuclear power plants have right to annual monitoring of radiation in bodies. Honitoring should be financed by govt & utils.Requests response.
 STUDDS-0.E. House of Rep. 80/09/26. 2pp. 07201:076.
- 8012020815 Responds to WA Caswell concerns re-monitoring of radiation received by residents living near nuclear power plants. No simple device can measure internal radiation. TLDs used to measure external radiation around facility.

 DIRCKS, W. J. Office of the Executive Director for Operations. 80/11/06. 3pp. 07141:033. 80/11/06. 3pp.
- --8012020821 Tech Spec Pages 181-188 re environ monitoring & surveillant requirements. Radiation Policy Council agenda item re monitoring & surveillance encl.

 4 Boston Edison Co. 72/09/30. 10pp. 07141:055.
- P. Operating license stage documents & correspondence
- 8012160950 Ltr to operating plant licensess OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements Requests operating reactor licenses confirmation in 45 days that Encl 1 implementation dates will be pet. E16ENMUT.D.O. Division of Licensing. 80/10/31, 7pp.
- 8012220358 Ltr to all CP & OL holders for BMRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISERMUT,D.O. Division of Licensing, 80/11/04, 4pp. 07307;335.
- 8012010096 Responds to NRC 800702 ltr re-model Teth Specs for implementation of NUREG-0578.Category A requirements.No Tech Spec changes are necessary.Lists reasons to support final decision. MORIBI.A.V. Boston Edison Co. 80/11/04, 4pp. 07098:210.

- BO12010453 Confirms B01031 oral authorization to amend Tech Specs. Requirements of 3.5.B limiting conditions for operation waived until B01107 if only reason for sys inoperability is missile damage to screen wash pumps due to tornado. NOVAN.T.M. Assistant Director for Licensing. B0/11/07. 2pp. 07095:105.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0619.
 "BHR Feedwater Nozzle & Control Rod Drive Return Line
 Nozzle Cracking." Confirmation that implementation dates
 will be met must be sent within 45 days.
- 8012080377 Forwards Amend 44 to License DPR-35, safety evaluation & notice of issuance & availability.

 IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/17. 2pp.
- --8012080573 Amend 44 to License DFR-35 modifying Tech Specs for temporary relief from limiting condition of operation in Section 3.5.B re operability of selt svc water sys, IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/17, Spp.
- --8012080578 Safety evaluation supporting Amend 44 to License DPR-35.

 * Office of Nuclear Reactor Regulation, Director. 80/11/17. 2pp.
 07186:290.
- --8012030582 Notice of issuance & availability of Amend 44 to License DPR-35. IPPOLITO T. A. Operating Reactors Branch 2. 80/11/17. 2pp. 07186: 292.
- 8012010233 Proposed Change 80-6, amending License DPR-35, re Tech Space for single loop operation. Safety evaluation & Class III fee encl. HOWARD, J. E. Boston Edison Co. 80/11/21. 14pp. 07097:336.
- --8012010241 Proposed Tech Specs, Sections 2.0 & 3.0 re single loop operation.

 * Boston Edison Co. 80/11/21. 13pp. 07097:348.
- 8012170483 Responds to NRC 800924 ltr requesting mods to power supply for reactor protection sys. Enginearing evaluation for changes will be completed by Mar 1981. Proposed pods will be submitted by Apr 1981 & installed during refueling outage. MCRISI,A.V. Boston Edison Co. 80/11/26. ip. 07270:291.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial sits conditions. Forwards results of 1E survey.

 DENTON, M.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220906 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Bystems Branch. 80/11/06. 8pp.
- 8012230354 Discusses development of continuous monitoring program to detect movement of & damage to breakwater armor stone. Requests rept be considered part of regular reporting requirement. HORISI, A. V. Boston Edison Co. 80/12/05. 3pp. 07311:142.
- 8012300691 Forwards Amend 49 to License DPR-35 & notice of issuance & availability.

 IPPDLITO.T.A. Operating Reactors Branch 2. 80/12/10. 3pp.
 07363:016.
- --8012300697 Amend 45 to License DPR-35, revising Tech Spec provisions re high radiation areas to provide more comprehensive treatment of requirements. IPPDLITO.T.A. Operating Reactors Branch 2. 80/12/10. 8pp. 07363:020.
- --B012300700 Notice of issuance & availability of Amend 45 to License DFR-05. TPPOLITO,T.A. Operating Reactors Branch 2. 80/12/10. 2pp. 07363:027.
- B012240272 Informs that review process is continuing to compare various aspects of new criteria contained in NUREG-0737 w/existing positions. Comments on positions identified in NUREG-0737 encl.
 MORISI.A.V. Boston Edison Co. 80/12/15. 95pp. 07323:057.

- G. Inspection reports. IE Bulletins & correspondence
- 8012020316 Requests that response to IE Bulletin B0-15, "Possible Loss of Emergency Notification Sys (ENS) N/Loss of Offsite Power," be resubmitted w/oath or affirmation within 10 days of receipt of ltr,per 10CFR50 54. GRIER, B.H. Region 1, Philadelphia, Office of the Director, 89/10/23. ip. 07143:109.
- 8012120072 Forwards IE Builetin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co-Inc." Written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. jp. 07230:273.
- 8012190340 Informs util of issuance of new NRC personnel identification badges effective after 801130. Example encl. HARTINI.U. J. Region I. Philadelphia, Safeguards Branch. 80/11/06. 2pp. 07286:099.
- 8012030770 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization." No written response required. GRIER. B. H. Region I. Philadelphia. Office of the Director. 80/11/07. 19. 07150:284.
- 8012240242 Resubmits responses to IE Bulletin BO-15, "Possible Loss of Emergency Notification Sys (ENS) W/Lass of Offsite Power," under oath of affirmation.
 MDRISI:A.V. Boston Edison Co. 80/11/07. 1p. 07328:212.
- --8012240256 Responds to IE Bulletin 90-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power." Audio circuits of ENS failed to have uninterrupted power supply for emergency backup power.

 MORISI, A. V. Boston Edison Co. 80/11/07. 3pp. 07328:213.
- --8012240270 Provides supplemental response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power." Mods & testing of ENS ring circuits in NRC ofc trailer extension phones completed on 800930.

 MORISI,A.V. Boston Edison Co. 80/11/07. ip.(. 07328: 216.
- 8012080477 Forwards IR Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 GRIER, B.H. Region 1, Philadelphia, Office of the Director.
 80/11/10. ip. 07
- 8012040050 Forwards IE Bulletin 80-23. "Failures of Bolenoid Valves Hig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B. H. Region 1. Philadelphia, Office of the Director. B0/11/14. 1p. 07170:001.
- B012220627 Advises that written response is required to IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." First paragraph arronoducity stated no written response required.

 GRIER.B.H. Region I. Philadelphia. Office of the Director. 80/11/17. 1p. 07293:135.
- 8012040504 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Ifritten response required. Requests info on manpower expended. ORIER. B.H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07169: 196.
- 8012050528 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B. H. Region 1. Philadelphia, Office of the Director, 80/11/24. jp. 07174:026.
- R. Periodic operating reports & related correspondence
- 8012160416 Forwards monthly operating rept for Nov 1980, MACHON, R D. Boston Edison Co. 89/12/01, lp. 07254:117.
- --8012160418 Monthly operating rept for Nov 1980. WHITNEY 9. 9. 9. Beston Edison Co. B0/12/05. App. 07254:118.
- 8012270172 Forwards revised monthly operating rept for Oct 1980, MACHONGR. D. Boston Edison Co. 80/12/17. ip. 07344:166.
- --8012290176 Revised monthly operating mept for Oct 1980. INHITNEY, G. G. Boston Edison Co. 80/12/17. 1p. 07344:167.

- S. Reportable occurrences, LERs & related correspondence
- 8012070536 Responds to 801031 telcon re reactor conjunt system depressurization at facility on 801031. Enumerates actions taken by util & requests response if such actions differ from actions actually planned by util.

 GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p. 07207:010
- 8012020599 Forwards LER 80~085/03L=0. MACHQNLR D. Boston Edison Co. 80/11/20. 1p. 07145:269.
- --8012020606 LER 80-085/03L-0:on 801023 HPCI sys turbine reached 150X of 4,000 rpm full flow speed rendering sys importable. Caused by failure of turbine governor & resistor in speed control circuitty Governor & resistor replaced, MCLQUOHLIN.M.T. Boston Edison Co. 80/11/20, 1p. 07145:269.
- 8012010341 Forwards LER 80-086/04L-0. MACHON, R. D. Boston Edison Co. 80/11/24. 1p. 07092: 161.
- --8012010347 LER 80-086/04L-0: on 801024; candenser delta T exceeded Tech Spec libit. Caused by increasing see water temp & lowering tide level. HCLOUGHLIR! N. T. Boston Edison Co. 80/11/24. 1p. 07092:162.
- 8012020615 Forwards LER 80-084/01X-0.
 MACHON, R. D. Boston Edison Co. 80/11/28. 1p. 07145:276.
- --B012020522 LER 80-084/01x-0 on 801113, leak discovered in 2-inch reactor vessel drain line connected to reactor water cleanup sys.

 Caused by slag inclusions in pipe coupling weld due to fabrication defect. Reactor shot down & weld repaired.

 * Boston Edison Co. 80/11/28. 2pp. 07145:277.
- 8012080409 Forwards LER 60-082/03L-1, MACHON, R. D. Boston Edison Co. 80/12/01, 1p. 07186; 314.
- --8012080417 LER 80-082/03L-1: on 801030; review of 801010 event re overcurrent trip of 480-volt breaker 892-204 revealed similar events occurred in June 1979 & Apr 1980. Cause unknown. Review of current loading requested, MCLOUGH_IR: M. T. Boston Edison Co. 60/12/01. Ip. 07186: 315.
- 8012100573 Forwards LER 80~084/01X-1. MACHOR: R. D. Boston Edison Co. 80/12/01, 1p. 07218:159.
- --8012100976 LER 80-084/01X-1:on B01113.water leat discovered from 2-inch reactor vessel death line. Caused by faulty weld. Neld isolated & ground out. Coupling revelded.
 MCL0U3HL]N.-8. Y Boston Edison Co. 80/11/28. 2pp. 07218:160.
- 8012150071 Forwards LER 50~087/03L~0.
 MACHON, R. D. Baston Edison Co. 80/12/05. 1p. 07237:285.
- --8012180072 LER RO-087/O3L-O on 801105 leak rate in dryuell calculated at 5.95 gpm. Caused by leaking packing on B recirculation pump discharge motor operated valve 202-58. Valve repacked, MCLOVOHLINIM.T Beston Edison Co. 80/12/O5. 1p. 07237:286.
- 8012220442 Forwards LER 80-088/03L-0. HACHON, R D. Boston Edison Co. 80/12/16. 1p. 07307:358.
- --8012220457 LER 80-088/03L-0: on 801116, found low deisel fire pump (P-140) flow rate during surveillance test B. B. 1, Caused by diasel generator operating at approx 1650 rpm. Diesel governar control adjusted.

 MCLOVOHLTN.M.T. Sosten Edison Co. 60/12/16. 1p. 07397: 359.
- 8012230351 Forwards LER 80-089/03L-0. MACHON, R. D. Soston Edison Co. 80/12/17, ip. 07311;256.
- --8012230355 LER 80-089/03L-O on 801117, torus water level indicator LR 5033 on panel 0903 in control room began to oscillate irradically. Instrument declared inogerable, Gaused by failure of forced balanced motor boyancy level transmitter. KCLOUORLIN.M.T. Soston Edison Co. 80/12/17. 19. 07311:257.
- 8012300401 Forwards LER 80~090/04T~0. MACHON,R.D. Boston Edison Cq. 80/12/19. 1p. 07359:352.
- --8012300407 LER 80-090/04T-0:on 80t215 analysis rept received indicating excessive mustel sample Caused by facility operation.
 MCLQUOBLIN.H.T. Boston Edison Cb. 80/12/19. 1p. 07359:353.

- 80122YC331 Forwards LER 80-091/03L-0. MACHON,R.D. Boston Edison Co. 80/12/23. 1p. 07343:103.
- --8012270345 LER 80-091/03L-0: on 801122, air operated valve 5045K did not operate during routine surveillance testing for drywell to torus vacuum breaker operability. Cause yet to be determined. Investigation scheduled, rept to be issued.

 MCLQUGHLIN-M. T. Boston Edison Co. 80/12/22. ip. 07343: 104.
- U. Congressional/Executive Correspondence
- 8012300176 Inquires about plant containment dome & questions raised redesign stds at facility. TSONOAS.P.E. Senate. 80/12/16. ip. 07356:289.
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1
 F. Security, modical, emergency & fire protection plans
- B01204024B Informs of no present implementation requirement re fire protection mods. Completion of items will be governed by schedules in revised 1gCFR50.4B to be published in FR notice.

 EISENHUT.D.G. Division of Licensing. 80/11/17. 5pp. 07170:207.
- 8012020167 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers. M/o encl health physics network manual.

 KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/19.
- B012120576 Resubmits security plan revisions in response to NRC B00910 & 1119 ltrs. Plan withheld from public disclosure (ref 100FR2.790). W/o encl.

 ABEL. J. B. Commonwealth Edison Co. 80/12/08. 1p.
- 8012290346 Forwards evaluation of fire protection items provided in 800430 & 791031 ltrs. Smoke detection sys.gas suppression sys.CER suppression sys & water suppression sys found acceptable.

 VARQA.S.A. Operating Reactors Branch 1. 80/12/09., 5pp. 07/346:001.
- H. General correspondence
- 8012020642 Responds to 800915 ltr to President Carter Forwards favorable presidential position on nuclear energy Notes efforts to insure safeguards. DENTON. H.R. Office of Nuclear Reactor Regulation, Director, 80/10/27.
- 8012240403 F0IA request for four categories of documents re cracks in containment of facility reactors. SHINEFLU9.M. Illinois Bafe Energy Alliance. 80/11/18. ip. 07323:132.
- 8012240400 Responds to FOIA request for four categories of documents recracks in containment of facility reactors. Forwards NURED/CR-1411 & 800730 summary & presentation from 800617 technology exchange meeting w/utils. II/o encl NURED/CR-1411. FELTON. J. M. Division of Rules and Records. 80/12/15. 1p. 07324:304.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8012020068 Summary of Bubcommittee on Class 9 Accidents 800702 meeting in Inglewood.CA re possible mitigation features.

 * ACRS Advisory Committee on Reactor Safeguards. 80/09/17. Bpp.
- P. Operating license stage documents & correspondence
- 8012020/53 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquate.

 EISENHUT, D. O. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensess.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests aperating reactor licenses confirmation in 45 days that Encl I implementation dates will be net. EISENHUT.D.O. Division of Licensing. 80/10/31. 7pp.

- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BNR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days.
- 8012180620 Forwards Amends 32.51 & 45 to Licenses DPR-2.DPR-19 & IPR-25.respectively. Amends 60 & 55 to Licenses DPR-29 & IPR-30.respectively & Amends 50 & 55 to Licenses DPR-39 & IPR-48.respectively. Safeguards contingency plans acceptable. GRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/17. 5pp.
- --8012180668 Amends 58 & 55 to Licenses DPR-39 & DPR-48, respectively, requiring implementation of safeguards contingency plan. YARGA, S. A. Operating Reactors Branch 1, 80/11/17, 4pp. 07271:339.
- ~-8012180671 Notice of issuance of Amends 32.31 & 45 to Licenses DPR-2, DPR-19 & DPR-25, respectively, Amends 60 & 55 to Licenses DPR-27 & DPR-30, respectively & Amends 58 & 55 to Licenses DPR-39 & DPR-48, respectively to safeguards contingency plan. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/11/17. 2pp.
- E012020105 Reaffirms util commitments re request to replace spent fuel racks. ASLAB concluded that inclusion of commitments in GL unnecessary. Commitments to be included in updated FSAR. TRAMM. T.R. Commonwealth Edison Co. 80/11/20. 1p. 07130:362.
- 8012170497 Forwards request for add1 info re containment purge & vent valve operability to complete review of util 800808 submittal. Description of seismic qualification of valve assembly required.

 VARQA/S.A. Operating Reactors Branch 1. 80/11/25. 4pp. 07270:338.
- 8012020301 Forwards tabulation of planned environ qualification testing programs, in response to NRC 801001 ltr.

 ABEL, J.S. Commonwealth Edison Co. 80/11/26. App.
- B012110P54 Application to amend Licenses DPR-39 & DPR-48 to permit use of max of four extended burnup fuel assemblies in facility Cycle 6 reload.
 TRAMMIT.R. Commonwealth Edison Co. 80/12/03. 3pp. 07225:309.
- --8012/10267 Proposed revision to Tech Spec Figure 9.2-6 & Page 70 to permit use of max of four extended burnup fuel assemblies in facility Cycle 6 reload.

 « Commonwealth Edison Co. 80/12/03. 3pp. 07225:312.
- 8012220483 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENTOWN.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220506 Forwards tabulation to summary of IE survey on low level maste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANDART,R.L. Effluent Treatment Systems Branch. 80/11/06. Spp.
- 8012290342 Informs that low pressure gross leak test of containment must be performed prior to any startup from cold shutdown. Different gross leak test ensuring containment integrity & mainimiling personnel exposure might be allowed. VAROA, 8. A. Operating Reactors Branch 1. 80/12/08. 3pp. 07346:005.
- B012290210 Responds to B00506 itr requesting guidance on testing mathods of wedge-opening-loading specimens from facilities. NUREO on subj will be issued by end of 1980 & made available to utils by mid-1981.

 VAR9A:8.A. Operating Reactors Branch 1. 80/12/09. 3pp. 07343:356.
- 8012170447 Bubmits schedule for transmitting proposed Tech Specs changes covering 10 THI-2 Lessons Learned Category A items per 800702 request. Alternata schedule also proposed. TRANN: T. R. Commonwealth Edison Co. 80/12/11. 3pp. 07269:148.
- B012170498 Forwards response to NRC 801031 ltr requesting confirmation that implementation dates indicated in NUREG-0737 will be met. Ability to meet required dates for major mods is contingent upon hardware availability & delivery.

 ABEL. J. B. Commonwealth Edison Co. 80/12/15. 37pp.
- B01224015B Forwards confirmation that implementation dates per NUREO-0737 will be met & justification for exceptions. Ownerally dates are contingent upon hardware availability & delivery. Comments on safety requirements in Tech Specs. ABEL, J. B. Commonwealth Edison Co. 80/12/15, 37pp.

- B012290247 Suppls B00623 response to NRC request for info re adequacy of station electric distribution sys voltages.
 TRAMKIT.R. Commonwealth Edison Co. B0/12/19. 1p. 07345:141.
- 8012300639 Forwards Bethlehem Steel Corp "Rept of Mechanical & Chemical Test." re 700515 Shipment 160-1749, Rept discusses Zion reactor coolant pump support rods.
 TRAMM.T.R. Commonwealth Edison Co. 80/12/23, 2pp. 07346:167.
- 0. Inspection reports, IE Bulletins & correspondence
- 8012170510 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. C. Region 3. Chicago, Office of the Director. 80/10/24.
- 8012020/43 Forwards three Performance Appraisal Branch insp repts & mgt avaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments H/o encl.
 KEPPLER. J. G. Region 3, Chicago, Office of the Director. 80/11/18. 4pp.
- 8012040274 Ack receipt of 801001 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-09 & 50-304/80-09.

 HIND, J. A. Region 3, Chicago, Safeguards Branch. 80/11/18. 1p. 07163:245.
- --8012040284 Suppls 800703 ltr re violations noted in IE Insp Repts 50-275/80-09 & 50-304/80-09. Corrective actions: draft to be completed stating contractor screening guidelines in more precise language.

 ABEL, J. S. Commonwealth Edison Co. 80/10/01, 13pp. 07163:266.
- 8012040057 Ack receipt of 801015 ltr providing results of Bergen-Patterson steam generator snubber testing. Provides list of comments. More detail should be provided for stiff spring mod which altered original valve block design.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/20. 2pp. 07170: 282.
- --8012040064 Forwards "Results of Unit 2 Steam Generator Shubber Testing at NH Testing Lab (NHTL) Hay,1980." in response to JO Reppier 800117 ltr request. Pased on rept. util has concluded that shubbers successfully completed tests. ABEL. J. S. Commonwealth Edison Co. 60/10/19. 2pp. 07170:284.
- --8012040068 "Results of Unit 2 Steam Generator Shubber Testing at NH Testing Lab (NHTL) May, 1780."

 * Commonwealth Edison Co. 80/10/15, 12pp. 07170: 286.
- 8012040667 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21.
 2pp.
- 8012080087 Forwards IE Info Notice 80~42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J. G. Region G. Chicago. Office of the Director. 80/11/24. 2sp.
- 8012170408 Forwards monthly status rept of evaluations performed in response to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys." No sys identified w/stress exceeding 1/2 matl ultimate stress at DUE loadings. JANECCH.R.F. Commonwealth Edison Co. 80/11/24. 14pp.
- 8012230223 Forwards new security badge numbers & clearance levels for Region 3 personnel. Changes should be entered on Sept 1980 access lists.

 KEPPLER, J. O. Region 3. Chicago, Office of the Director. 80/11/25.6pp.
- 8012100461 Acr receipt of 800719 response to NRC 800818 ltr requesting add1 info re IE Bulletin 79-14 evaluations. Dresden & Quad Cities responses to Items 1 & 3 unacceptable, since requested info was not included.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/26, 3pp.
- 8012170552 Forwards IE Info Notice 80-29, Suppl 1, "Brolen Stude on Tarry Turbine Steam Inlet Flange." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/26. Zpp.

- 8012310212 Supple S01106 response to IE Bulletin 80-11 re masonry wall design deficiency. Necessary repairs to 16 walls not meeting acceptance criteria to be completed by 810101.
 RAUSCH.T. J. Commonwealth Edison Co. 80/12/01. 2pp. 07369:282.
- 8012100579 Ack receipt of 801119 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Repts 50-295/80-05 & 50-304/80-04. KEPPLER. J. G. Region G. Chicago, Diffice of the Director. 80/12/02. 1p. 07218.162
- --B0171G05E2 Responds to NRC B00627 ltr re violations noted in IE Health Physics Appraisal Repts 50-295/80-05 & 50-304/B0-04.
 Corrective actions: present key control of access to high radiation areas will be maintained.
 ABEL, J. S. Commonwealth Edison Co. B0/11/18. 1p. 07218:163.
- BO12230065 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." No valve parts cast by Malcolm Foundry planned for use or in use at facilities.
 RAUSCH.T.J. Commonwealth Edison Co. 80/12/05. 2pp.
- 8012270374 Responds to BOISI4 ltr re change in insp plans for charging pump casing suction and plats. Plans will be evaluated for potentially generic problem FIORELLI.G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. BO/12/09. 1p. 07345:108.
- 8012310593 Act receipt of B01113 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-09 & 50-304/80-09. HIND, J.A. Region 3, Chicago, Safeguards Branch. 80/12/09. 1p. 07366:031.
- --B012310590 Responds to MRC B01001 ltr re violations noted in IE lnsp Repts 50-295/B0-09 & 50-304/B0-09.W/a encl updated screening guidelines & implementing itr. ABEL, J. S. Gommonwealth Edison Co. B0/I1/13. 1p. 07366:032.
- R. Periodic operating reports & related correspondence
- 8012110358 Forwards monthly operating repts for Nov 1980. GRAFSSER, K. L. Commonwealth Edison Co. 80/12/05, 1p. 07223:215.
- --8012110363 Monthly operating rapts for Nov 1780. CODK, J.H. Commonwealth Edison Co. 80/12/05. 11pp. 07223:216.
- S. Reportable occurrences, LERs & related correspondence
- B012090461 Forwards LER 80-049/03L-0. GRAFESER: X. L. Commonwealth Edison Co. 80/11/26. 1p. 07203:064.
- --8012070473 LER 80-047/03L-0: on 801027, component cooling liquid monitor IRE-017 had no response to installed check sources, Caused by bad electrical contacts between detector & socket assembly. Socket replaced, monitor calibr & tested.

 AKER.R. E. Commonwealth Edison Co. 80/11/26. 1p. 07203:065.
- 80121502t1 Forward: LER 80-050/03L-0, GRAESSER.K.L. Commonwealth Editon Co. 80/12/02. 1p. 07240:126.
- --B012150218 LER 80-050/03L-0:on B01117 during normal operation fire sump gracess radiation monitor DRT-PR25 increased to high alarm. Cause Undetermined Monitor tested & returned to svc. AKER, R. E. Commonwealth Edison Co. 80/12/02. 1p. 07240:127.
- 8012230322 Forwards LER 80-051/03L-0. ORAFSSER, K. L. Commonwealth Edison Co. 80/12/15. 1p. 07318:215.
- --8012230327 LER 80-051/03L-0:on B01115.high PP air flow on zone 2 caused tone pressure to fall below 47 psig.putting PP sys in degraded mode. Caused by hole in purge duct allowing cold air to sater purge exhaust valve.causing mat1 to contract. PANACOS. A. Commonwealth Edison Co. B0/12/15, 1p. 07318:216.
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3
 F. Sacurity, medical, emergency & fire protection plans
- 8012040209 Notification of 801202 meeting w/util in Bethesda.MD to discuss fire replication tests for fire protection sys. CLARK.R.J. Operating Reactors Branch 2. 80/11/19. 2pp. 07169:290.

- 8012090209 Advises that util has instituted interim procedures to handle conversion of release rates to emergency classifications for State of AL.as viscussed in 801027 meeting w/NRC & util 801005 ltr to State of AL. HILLS.L.M. Tennessee Valley Authority. 80/12/03. ip. 07200:344.
- 801230064B Requests comments by 810115 re plans to install prompt notification sys within 5-mile emergency planning zone. Util assessments on fission product releases are consistent w/ info presented at NRC 80111B meeting.
 MILLS.L.B. Tennossee Valley Authority. 80/12/24. 2pp. 0730B:001.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake. EISENMUT.D.O. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUMEG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT.D.O. Division of Licensing: 80/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BMRs Te requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EIBERHUT, D. O. Division of Licensing. 80/11/04. 4pp.
- 8012270843 Ltr to all power reactor licensees forwarding NUREO-0419. "BUR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. H/O encl. EIGENHUT, D. G. Division of Licensing. 80/11/13. 1p.
- 8011250423 Forwards partial response to NRC 800708 request for info re containment purging & venting sys.Addi info to complete response will be submitted by 810401. Drawings available in Central Files.aperture cards in PDR. HILLS.L.H. Tennessee Valley Authority. 80/11/19. 21pp. 97065:332.
- 80:2070231 Forwards proposed change to util rept TVA-TR75-1 Te GA program as ref in App D.Section D.4 of FBAR.
 MILLS.L.M. Tennessee Valley Authority. 80/12/01, 2pp. 07201:151.
- 8012160633 Forwards NRC review of fish impingement data collected at facility from Sept 1976 Aug 1979, in response to util request to terminate study as required by ETS.Request should be granted.

 BALLARD, R. L. Environmental Engineering Branch. 80/12/02. 33pp. 07241:256.
- 8012230510 Forwards Amends 63,59 % 35 to Licenses DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability.

 IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/02. 2pp. 07316:247.
- --8012230519 Amends 63,59 & 35 to Licenses DPR-33,DPR-52 & DPR-68, respectively, changing Tech Specs to resolve auxiliary electrical sys ambiguities in Section 3 9, IPPOLITO, T. A. Dperating Reactors Branch 1. 80/12/02. 11pp. 07316:249.
- --8012230517 Safety evaluation supporting Amends 63,57 & 35 to Licenses DPR-33:DPR-52 & DPR-6B respectively. * Office of Nuclear Reactor Regulation, Director. 80/12/02. 5pp. 07316:283
- --8012230529 Notice of issuance & availability of Amends 63.59 & 35 to Licenses DPR-33, DPR-52 & DPR-68, respectively. IPPOLITO, T. A. Operating Reactors Branch 1. 80/12/02. 2pp. 07316:288
- 8012190627 Forwards list of applications for Tech Spec changes, fees paid, fees due & basis for each fee determination. Requests remission of fees due.
 DIGGS.R.H. License Fee Management Branch. 80/12/03. 2pp. 07273:293.
- 8012090344 Responds to NRC 800924 request for info re reactor protection sys power supplies. Commits to install Class IE sys & provides schedule for completion of mods & for submission of design info & proposed Tech Specs.
 MILLS-L.M. Tennessee Valley Authority, 80/12/04, 2pp. 07199:349.

- B012270485 Responds to B00911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey.

 DENION: H.R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --8012220596 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planming or considering increasing storage capacity.

 BAN9ART,R.L. Effluent Treatment Bystems Branch. 80/11/06. Bpp.
- 8012230257 Forwards brief summary of planned mods to BWR scram sys, in response to NRC 801001 itr.Addl info regarding implementation schedule will be provided by 810201.
 MILLB.L.M. Tennesses Valley Authority. 80/12/15. 3pp. 07314:018.
- 80:12240245 Responds to 80:1203 ltr re final fee determination for facility Tech Spec changes. Fee determination for Changes TB 153. TS 143 & TS 148 not contested. Disagreements u/datermination for TS 145 & TS 151 discussed in encl. MILLS, L.M. Tennessee Valley Authority. 80/12/17. 2pp. 07324:337.
- 8012300289 Advises that in Jan 1981 util will provide addl info re reactor bldg crane to assist NRC review of generic subj of asying heavy loads near fuel.Pending resolution.continued caution will be exercised.

 MILLB,L.M. Tennessee Valley Authority, 80/12/22, 1p. 07349:335.
- 8012290237 Forwards response to clarification items in NRC 801031 ltr re post-THI requirements. Encl contains list of ECCS outages for past 5 yrs & training program requirements for shift technical advisors.
 MICLE, L. H. Tennesses Valley Authority. 80/12/23. 100pp.
 07338:327.
- B012300296 Requests extension of concurrent cycle start date from B00101 to B00701.
 MILLB.L.M. Tennessee Valley Authority. B0/12/24, 2pp. 07308:001.
- G. Inspection reports: IE Bulletine & correspondence
- 80:2150:201 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required. "AFELLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24. ip. 07240:279.
- B012170004 Forwards IE Info Notice 80-39, "Maifunction of Bolenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required. 6'REILLY, J.P. Region 2, Atlanta, Office of the Director. B0/10/31. 19.
- 8012230030 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators," No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31.
 1p.
- BO12110066 Requests assessment & corrective actions taken re control room celling constructed w/apparently flammable tiles within 20 days.

 TEGESCO, R. L. Assistant Director for Licensing. BO/11/04. 3pp.
- 8012110807 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Halcolm Foundry Co.inc." Written response required. G'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/06. 1p. 07225:180.
- B012190220 Forwards IE Insp Repts 30-259/80-38, 50-260/80-32 & 50-276/80-32 on B01014-15. No noncompliance noted. MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch, B0/11/06, 2pp. 03792:019.
- --8012180223 IE Insp Repts 50-259/80-38, 50-260/80-32 & 50-296/80-32 on 801014-15. No noncompliance noted. Hajor areas inspected: settling of structural backfill under RHR svc water tunnels. LENAHAN, J.J. Region 2, Atlanta. Office of the Director. COLON, T. E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 80/11/05. 3pp. 03792:021.
- BD12030B37 Forwards IE info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. BO/11/07. 1p.

- 8012180055 Forwards IE Insp Repts 50-259/80-37, 50-260/80-31, 50-296/80-31 & 50-327/80-40 on 801006-07. No noncompliance noted. KENNA, M. B. Region 2, Atlanta, Safeguards Branch. 80/11/07. 2pp. 03791:173.
- --80121800A9 IE Insp Repts 50-259/80-37, 50-260/80-31, 50-296/80-31 to 50-327/80-40 on 801004-07. No noncompliance noted, Major areas inspected unescorted access clearances to intrusion of plant protected area. Details withheld (ref 10CFR2, 790).
 TOBIN, N. J. Region 2, Atlanta, Défice of the Director. MCOUIRE, D. Region 2, Atlanta, Safeguards Branch. 80/11/06. tp. 03791:175.
- 8012080276 Forwards 1E Info Notice 80-41, "Failure of Bwing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/10. ip. 07182:285.
- B012030773 Forwards monthly status rept for Nov 1980 re work performed per IE Bulletin 79-14. "Seismic Analysis for As-Bullt Bafety-Related Piping Sys." Drawing configuration, pipe support & floor & wall penetration insps included. MILLB.L.M. Tennessee Valley Authority. B0/11/10. 29pp. 07188:008.
- 8012040143 Forwards IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/14. ip. 07158:066
- 8012020339 Ack receipt of 801105 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-34, 50-260/80-27 & 50-296/80-28. LENIG.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Br
- --8012020345 Responds to NRC 801009 ltr re violations noted in IE Insp. Repts 30-259/80-34, 50-260/80-27 & 30-276/80-28, Corrective actions: administrative instructions modified to ensure fire watch assigned to vital area issued key card for access. MILLG, L. M. Tennessee Valley Authority. 80/11/05. 2pp. 07143:127.
- --8012020348 Forwards IE Insp Repts 50-259/80-34,50-260/80-27 & 50-276/80-28 on 800801-31 & notices of violation & deviation.
 LEMISAR.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/10/09. 2pp. 07143:129.
- --8012020354 Notice of violation from insp on 800801-31. # Region 2. Atlanta, Office of the Director. 80/10/07. ip. 07143:131.
- --8012020356 Natice of deviation from insp on 800801-31.

 * Region 2, Atlanta, Office of the Director. 80/10/07. 1p. 07143:132.
- --8012020364 IE Insp Repts 30-239/80-34, 50-260/80-27 & 30-296/80-28 on 800801-31. Noncompliance noted:no fire watch in cable spreading room w/inoperable carbon dioxide sys & failure to monitor scram discharge header level as prescribed.

 5ULLIVANIR.F.. CHABEJ. J.H. Region 2. Atlants. Office of the Director. DANCE.H.C. Region 2. Atlants. Office of Nuclear Support Branch. 80/10/07. 7pp. 07143:133.
- B012050067 Forwards IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. B0/11/21, 1p. 07173:225.
- 8012080004 Forwards IE Info Notice 80-42, "Effect of Radiation on Mydraulic Snubber Fluid." No written response required. O'REILLY,J.P. Region 2. Atlanta, Office of the Director. 80/11/24. 1p. 07182:157.
- 8012170359 Forwards IE Info Notice 80-27.8uppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange," No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Diffice of the Director. 80/11/26.
- 8012220595 Forwards response to IE Bulletin 80-06, "Engineered Safety Features (ESF) Reset Controls." Results of supplemental drawing review devices to be tested & testing schedule encl. MILLS, L. M. Tennessae Valley Authorit:

012310111 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." No valve parts cast by foundry used at facilities. MILLS.L.K. Tennessee Valley Authority. 80/12/05. 1p. 07370:019.

8

- 012190466 Ack receipt of 801113 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-28, 50-269/80-21 & 50-276/80-22 Confirms telcon that maint on valve will be completed before entering operable mode. LEMIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/12/10. 1p. 07287:036.
- -8012190472 Responds to NRC 801027 ltr re violations noted in IE Insp Repts 50-259/80-28, 50-260/80-21 & 50-296/80-22. Corrective actions: testing of sub, pressure sultch accomplished as soon as 30% automatic bypass interlock cleared. MILLS, L.M. Tennessee Valley Authority. 80/11/13. 3pp. 07287:037.
- -8012190481 Ack receipt of 800904 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-28. 50-260/80-21 & 50-296/80-22 More info requested on subj pressure switch. O'RELLEY.U.P. Region 2, Atlanta, Office of the Director. 80/10/27. 1p. 07287:040.
- -8012190492 Responds to NRC 800815 ltr re violations noted in IE Insp Repts 50-259/80-28.50-260/80-21 & 50-296/80-22. Disputes finding of noncompliance. HILLSL.IK Tennessee Valley Authority. BO/09/04. 3pp. 07287:041.
- -8012190499 Forwards IE Insp Repts 50-259/80-28,50-260/80-21 & 50-296/80-22 on 800601-30 & notice of violation.
 LEUIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/08/15. 2pp. 07287:044.
- --8012190504 Notice of violation from insp on 800601-30.

 * Region 2, Atlanta, Office of the Director. 80/08/15, 1p.
 07287:046.
- --8012170512 IE Insp Repts 50-259/80-23,50-260/80-21 & 50-296/80-22 on 800601-30. Noncompliance noted: failure to test Control Valve 2 pressure sensor after maint & before returning to svc. 5UL119A**ΔR.F., CHASE.J.W. Region 2, Atlanta, Office of the Director. DANCE.H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/08/15. Δpp. 07287:047.
- R. Periodic operating reports & related correspondence
- B012160317 Forwards mentally operating repts for Nov 1980. ABERCROMBIE.H. Tennessee Valley Authority. 80/12/10. 1p. 07252:269.
- --8012160321 Monthly operating repts for Nov 1980. THOM, T. Tennessee Valley Authority. 80/12/01. 33pp. 07252:270.
- S. Reportable occurrences. LERs & related correspondence
- 8012020514 Forwards LER 80-046/03L+0. OREEN.H.J. Tennessee Valley Authority. 80/11/28. lp. 07130:297.
- --8012070518 LER 80-046/O3L-0: on 801030, during steady state oper w/unit at 92% power, 3amaged standby liquid control hydraulic accumulator air valve resulted in loss of charge while performing MH-40. Caused by worker tightening valve.

 Tennessee Valley Authority. 80/11/28. 2pp. 07130:298.
- 8012020444 Forwards LER 80-047/03L-0. GREEN.H.J. Tennessee Valley Authority. 80/12/01. 19. 07148:258.
- 8012020499 Forwards LER 80-045/03L-0. ORECN H. J. Tennessee Valley Authority. 80/12/01. 1p. 07130:294.
- --801202050B LER 60-045/03L-0: on 801105, during normal operation, while performing 81 4.2. A. 6. setpoint for 3-PS-1-76 found below Tech Bpac limits. Caused by model B2TA1258 switch setpoint drift. Suitch recalibr. verified & 81 4.2. A. 6 completed.

 * Tennessee Valley Authority. 80/12/01. 2PP. 07130:275.
- 8012120509 Forwards LER 80-048/03L-0. OREEN.H.J. Tennessee Valley Authority. 80/12/05. 1p. 07236:043.

- --B012170517 LER B0-04B/03L-0; on B0110B throttling valve to RHR seal heat exchanger 3B on emergency equipment cooling water sys found shut & could not be opened manually preventing adequate flow Caused by excessive crud entrapped in valve mechanism.

 * Tennsssee Valley Authority. B0/12/05. 2pp. 07236:044.
- 8012160542 Forwards LER 80-049/03L-0. GREEN.H.J. Tennesses Valley Authority. 80/12/11. 1p. 07262:012.
- --8012160549 LER 80-049/03L-0: on 801114.RHR pump 3D tripped on instantaneous overcurrent while starting Caused by loose relay adjustment locknut Locknut tightened & relay adjusted.

 a Tennessee Valley Authority. 80/12/11. 2pp. 07262:013.
- 8012170565 Forwards LER 80-050/03L-0. OREEK.H. J. Tennessee Valley Authority. 80/12/11. 1p. 07264:141.
- -8012170396 LER 80-050/03L-0; on 801115, breaker for standby liquid control pump B motor tripped when pump started. Caused by overcurrent tripping device on B phase tripping at lower value than other phases. Breaker replaced.

 * Tennessee Valley Authority. 80/12/11. 2pp. 07264:142.
- 8012160553 Forwards LER 80-051/03L-0. GREFN.M.J. Tennessee Valley Authority. 80/12/15. 1p. 07262:019.
- -8012160559 LER 80-051/03L-0:on 801116, redundant drywell hydrogen sensor 3-H2E-76-39A would not calibr to ref gas. Sensor declared inoperative. Caused by sensor 47E22642802 failure. Unit shut down for refueling 801123 & sys replaced. a Tennessee Valley Authority. 80/12/15. 2pp. 07262:020.
- B012170603 Forwards LER 80-052/03L-0. GREEN,H.J. Tennesses Valley Authority. B0/12/15. 1p. 07264:244.
- --8012170612 LER 80-052/03L-0: on 801118 recirculation discharge valve activation pressure switch 3-P8-68-95, switch 1, found below Tach Spec limit by 8%. Caused by instrument drift. Switch recalibr & tested. Switch to be replaced.

 * Tennessee Valley Authority. 80/12/15. 2pp. 07264:245...
- 801230053i Forwards LER 80-053/03i.-0. OREEN.H.J. Tennessee Valley Authority. 80/12/24. ,ip. 07361:33i.
- --8012300537 LER 80-053/03L-0: on 801127; refuel platform limit switch failed to prevent platform movement over core during functional test. Caused by normal wear. Buitch replaced.

 ***Tennessee Valley Authority.** 80/12/24. 2pp. 07361:332.
- V. Operator Examinations
- 8012290237 Forwards response to clarification items in NRC 801031 ltr re post-Titl requirements. Encl contains list of ECC8 outages for past 5 yrs & training program requirements for shift technical advisors. MILLB, L. M. Tennessee Valley Authority. 80/12/23. 100pp.
- DOCKET 50-298 COOPER NUCLEAR STATION
- F. Security, medical, emergency & fire protection plans
- 8012040096 Forwards interim 10CFR50. 48 suspending completion dates for fire protection mods, effective upon 801029 publication in 45FR71569. Rule will be superseded by revised rule when effective. EISERHUT, D. Q. Division of Licensing. BO/11/07. App. 07170; 251.
- G. Adjudicatory correspondence
- 8012010396 Ack receipt of 801022 ltr re 801002 confirmatory order. Installation of acram discharge monitoring sys not within requirements of order. Further mods necessary. SEYFRIT.K.V. Region 4, Dailas, Office of the Director. 80/11/06. ip. 07095:082.
- --B012010405 Ack receipt of B01002 confirmatory order. Bys to monitor water level continuously in north screm discharge vol installed, tested & considered operable on 801010. PILANT, J. H Nebraska Public Power District. B0/10/22. 2pp. 07095:083.

- P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensees. OL applicants & CP holders, Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012270358 Ltr to all CP & OL holders for BWRs re requirement for implementation of CDYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012010396 Ack receipt of 801022 itr re 801002 confirmatory order. Installation of acram discharge monitoring sys not within requirements of order Further mods necessary. SEYFRIF.K.V. Region 4, Dallas, Office of the Director. 80/11/06. ip. 07095:082.
- --8012010405 Ack receipt of B01002 confirmatory order Bys to monitor water level continuously in north scram discharge vol installed tested & considered operable on B01010.
 PILANT, J.M. Nebraska Public Power District. 80/10/22. 2pp. 07099:083.
- 8012080048 Forwards Amend 65 to License DPR-46 & notice of issuance & availability.
 IPPOLITO,T.A. Operating Reactors Branch 2. 80/11/13. 3pp.
 07180:342.
- --B012080053 Amend 65 to License DPR-45, modifying App B of Tech Specs to delete Section 2.1.2/3.1.2 rs max discharge temp. IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/13. 5pp.
- --8012080057 Notice of issuance & availability of Amend 65 to License DPR-46. IPPOLITO T. A. Operating Reactors Branch 2. 80/11/13. 2pp.
- 8012080389 Forwards Amend 64 to License DPR-46 & notice of issuance & IPPOLITO,T.A. Operating Reactors Branch 2. 80/11/13. 3pp. 07186:306.
- --8012080395 Amend 64 to License DPR-46, requiring approved safeguards contingency plan be fully implemented.

 IPPOLITO, T. A. Operating Reactors Branch 2, 80/11/13, 2pp.
- --B0120B0403 Notice of issuance & availability of Amend 64 to License PR-46. IPPOLITO.T.A. Operating Reactors Branch 2. B0/11/13. 2pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BUR Feedwater Nozzle & Control Rod Driva Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EISENHUT. D. G. Division of Licensing. 80/11/13. ip.
- 8012030820 Forwards Performance Appraisal Branch repts & mgt evaluation tree & users's guide. Info provided to ensure that licensees have opportunity to review strengths & weaknesses for program applicability. W/o encls.

 BEYFRIT. K. V. Region 4. Dallas, Office of the Director. 80/11/14.

 1p. 07149:263.
- B012300614 Forwards Amend 66 to License DPR-46, suppl to fire protection safety availability. a Uperating Reactors Branch 2. 80/11/21. 2pp. 07362:320.
- --8012300622 Amend 66 to License DPR-46, changing Tech Specs to provide add1 limiting conditions of operation & surveillance requirements for fire protection squipment. IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/21, 12pp. 07362:322.
- --8012300631 Suppl 1 to fire protection safety evaluation supporting Amend 66 to License DPR-46. * Office of Nuclear Reactor Regulation, Director. 80/11/21. App. 07362:334.
- --8012300633 Notice of issuance & availability of Amend 66 to License DPR-46.
 IPPOLITO, T. A. Operating Reactors Branch 2. 80/11/21. 2pp.

- 8012090335 Informs of commitment to install Class IE sys & submits schedules for completion of mods, design info & proposed Tech Specs, per 800924 request. PILANT, J. M. Nebraska Public Power District. 8D/12/02, 1p. 07201:163.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revisad Agraement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage Pacilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANDART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012240287 Responds to Item 3 of NRC 801001 ltr to all BWR licenses re DWR scram sys. Preliminary evaluation of scram sys has been performed. Listed mods are being evaluated. Mods will be installed during first outage after receipt of matt. PILANT.J.M. Nebraska Public Power District. 80/12/15. 2pp. 07324:347.
- 8012230334 Advises that facility will maintain standing re IOCFR50.55a per ASME Section XI 1974 through Summer 1975 Addenda. Submits justification for relief requests re frequency tests, vibration measurement & examination & bearing tamp. PILANT.J.M. Nebraska Public Power District. 80/12/18. 3pp. 07314:101.
- 8012300623 Forwards replacement pages for NEDO-24045, "LOCA Analysis Rept for Cooper Nuclear Station," reflecting extended exposures per B00120 & 1010 revised max average planar linear heat generation rate curves. PILANI,J. H. Nebrasta Public Power District. B0/12/19, 2pp. 07346:155.
- Q. Inspection reports, IE Bulletins & correspondence
- B012170315 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required. BEYFRIT,K.V. Region 4, Dallas, Office of the Director. 80/10/24. ip. 0724B:339.
- 8012160059 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 SEYFRIT.K. V. Region 4. Dallas. Office of the Director. 80/10/27.

 1p. 07262:154.
- 8012180122 Ack receipt of 801011 ltr informing NRC of steps taken to correct violations noted in Health Physics Appraisal Rept 50-298/80-07.
 SEYERIT, K. V. Region 4, Dalias, Office of the Director. 80/10/27. 2pp. 03791:212.
- --8012180128 Responds to NRC 800908 itr re violations noted in Health Physics Appraisal Rept 30-298/80-07. Corrective actions: procedures revised to include necessary guidance in choosing personnel & training program restructured. PILANT, J. K. Nebraska Public Power District. 80/10/11, 13pp. 03791; 214.
- B012170B12 Forwards IE Info Notice 80-37, "Maifunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.

 8EYFRIT.K. V. Region 4, Dallas, Office of the Director. B0/10/31.

 1p. 07266:107
- 8012230092 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. 8EYFRIT.K.V. Region 4. Dallas, Office of the Director. 80/10/31. 1p. 97311:204.
- 8012100629 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.inc." Written response required. SEFRIT.K.V. Region 4, Dailas. Office of the Director. B0/11/06. ip. 07220:070.
- 8012030704 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuriation " No written response required. SEVFRIT.K. V. Region 4. Dallas, Office of the Director. 80/11/07. ip. 07150:167.

- 2030743 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve n Decay Heat Removal Sys at Davis-Besse Unit 1." No esponse required. EYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/10.
 - NIT,K.V. Region 4. Dallas. Office of the Director. 80/11/10. 07180:307.
- 2040018 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves fg by Valcor Engineering Corp." Requires estimate of ampower associated w/corrective actions. EYFRIT.K.V. Region 4, Dallas, Office of the Director. 60/11/14. p. 07169:296.
- 2180926 Ack receipt of 801011 & 1117 ltrs informing NRC of steps aten to correct violations noted in Health Physics praisal Rept 50-278/80-07. EYFRIT.K. V. Region 4. Dallas, Office of the Director. 80/12/08. p. 03792:024.
- р.
- 012180232 Responds to NAC 801027 ltr re violations noted in Health Physics Appraisal Rept 50-278/80-07. Corrective actions: procedures will reflect more explicit use of frisker. PILANT.J.M. Nebraska Public Power District. 80/11/17. 2pp. 03792:025.
- 2230334 Advises that facility will maintain standing re 10CFR50.35a er ABME Bection XI 1974 through Summer 1975 Addenda. Bubmits sustification for relief requests re frequency tests; sibration measurement & examination & bearing temp.
 ILANT.J.H. Nebraska Public Power District. 80/12/18, 3pp.
 **17314:101.
- Periodic operating reports & related correspondence
- 2130079 Forwards monthly operating rept for Nov 1980. E680R.L.C. Nebraska Public Power District. 80/12/03. ip. 17237:278
- 0121500B1 Monthly operating rept for Nov 1980. BALLINGER.P.L. Nebrasia Public Power District. 80/12/03, App. 07237: 277.
- Reportable occurrences, LERs & related correspondence
- 3012030713 LER 80-038/03L-0: on 801011, switch on NBI-LI8-101A found set at lower level than Tech Spec limit. Caused by excessive drift. Buitch returned to normal setting & will be replaced. CONVERSE, M.E. Nebraska Public Power District, 80/11/10, ip. 07149: 346.
- CHEL SO-301 POINT BEACH NUCLEAR PLANT, UNIT 2 Becurity, medical, emergency & fire protection plans
- 12090Bi6 Forwards interim 10CFR50.48, suspending completion date for previously approved affective fire protection mods, affective Bollo29, Rule will be superseded by pending revision.
 EIBERHUT.D.O. Division of Licensing. 80/11/18.5pp. 07207:011.
- 12020192 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys.W/o encl health physics network manual. KEPPLERFJ. 0. Region 3. Chicago, Office of the Director. 80/11/19.2pp. 07149:003.
- 12050633 Forwards public version of dreft revision of emergency plan. FELTON J. K. Division of Rules and Records. 80/12/01. 1p. 07172:029.
- 8012030642 Forwards public version of draft revision of emergency plan. FAY.C.W. Wisconsin Electric Power Co. 80/05/07. ip. 07172:030.
- 8012050651 Public version of draft revision of emergency plan.

 Wisconsin Electric Power Co. 80/05/31. 300pp. 07172:032.

All may be a facility

12070378 Informs that revision of 800728 draft emergency plan per NRC 800727 comments will be delayed until 801231. Objects to NRC direction to begin implementing partially approved plan. Schadules implementation for 810401 per NRC 801113 ltr. FAY.C. U. Wisconsin Electric Power Co. 80/12/01. 1p. 07201:173.

Adjudicatory correspondence

- B012310065 Forwards corrected Page 15.6.10-2 to Tech Bpec changes transmitted w/801024 order for mod of license re environ qualification of safety-related electrical equipment. CLARK, R. A. Operating Reactors Branch 3. 80/12/04. 2pp.
- --B012310071 Corrected Tech Spec Page 15.6.10-2.adding footnote indicating that starred items re records will be permanently retained.
 4 Operating Reactors Branch 3. 80/12/04. 2pp.
- 8012110379 Requests, on behalf of util, extension until 810108 for hearing on 801118 order for mod of license to allow more reasoned determination.
 SILBERO, J. E. Shaw, Pittman, Potts & Trowbridge. 80/12/05. 2pp. 07223:005.
- 6012290306 Notifies that Lakeshore Citizens for Safe Energy is being distanded per 781208 agreement. BAST, B. A. Lakeshore Citizens for Safe Energy. 60/12/09. 1p. 07308:001.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PMRs & describes program NRC is undertaking to raview capability of operating PMRs to remove decay heat following earthquake.
 EISERHUT, D. O. Division of Licensing. 80/10/21. 4pp.
- 8012160030 Ltr to operating plant licensees. CL applicants & CP holders. Forwards NUREO-0737 re THI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be not. EISENHUT, D. Q. Division of Licensing. 80/10/31. 7pp.
- B012010140 Trip rept of B01027-28 site visit to introduce plant mgt personnel to project manager. COLBURN, T. G. Operating Reactors Branch 3. 80/11/13. 4pp. 07092:128.
- BOIR220543 Ltr to all power reactor licensees forwarding NUREG-0419, "BWR Feedwater Norzle & Control Rod Drive Return Line Norzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. 4/o encl., EIGENHUY.D.O. Division of Licensing. BO/11/13. 1p.
- B012220485 Responds to 800911 memo raquesting that Ofc of Nuclear Reactor Regulation Inform licensees of need to comply w/revised Agreement State buriel site conditions.Forwards results of IE survey. DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- -8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity. BANDART.R.L. Effluent Treatment Bystems Branch. 80/11/06. 8pp.
- 8012310011 Forwards request for addl info for Tech Spec change request re removal of rod bow penalty at facility. Util must describe margins used to offset reduction in DNSR due to fuel rod bouling. CLARK.R.A. Operating Reactors Branch 3. 80/12/04, 3pp. 07371:091.
- B012310065 Forwards corrected Page 15.6. 10-2 to Tech Bpec changes transmitted w/801024 order for mod of license re environ qualification of safety-related electrical equipment. CLARK, R.A. Operating Reactors Branch 3 80/12/04. 2pp. 07371:148.
- --8012310071 Corrected Tech Spec Page 15.6.10-2.adding footnote indicating that starred items re records will be permanently retained.

 d Operating Reactors Branch 3. 80/12/04. 2pp. 07371:150.
- 8012130077 Discusses lack of NRC action re comments submitted in 800604 itr concerning consolidation of reporting requirements. Clarification & consolidation of all licensee reporting requirements urgad. FAY.C.W. Wisconsin Electric Power Co. 80/12/08. ip. 07237:358.
- 8012300404 Forwards response to NUREO-0737, "Clafification of THI Action Plan Requirements." Implementation of desired mode will cause unavoidable meth & personnel shortages, which may result in delays in implementation schedules.
 FAY.C.W. Wisconsin Electric Power Co. 80/12/23, 29pp. 07357; 267.

- 8012300386 Submits info re postulated uncontrolled boron dilution at cold shutdown in response to NRC 800930 ltr. Boron dilution event for cold shutdown recalculated based on return to criticality 15 minutes after wave front reaches core inlet. FAY:C.N. Wisconsin Electric Power Co. 80/12/23, 5pp. 07346:210.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012170624 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/10/24. ip. 07264:173.
- 8012220042 Forwards IE Health Physics Appraisal Repts 30-266/80-16 & 50-301/80-16, notice of violation & significant appraisal findings.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/14.
 3ns. 07307:001.
- --8012220045 Notice of violation from health physics appraisal on BOO908-19. * Region 3, Chicago, Office of the Director. 80/11/10. ip. 07307:004.
- --8012220056 IE Health Physics Appraisal Repts 50-266/80-16 & 50-301/80-16. Noncompliance noted: two persons received excessive whole body radiation doses & radwaste shipped improperly.

 MILLER: D. E. . GESTMANN, M. J. . MURPHY, D. W. Region 3, Chicago, Office of the Director. 80/11/10. 24pp. 07307:005.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program already reviewed & make appropriate adjustments. H/o ancl. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/18. 4pp.
- 8012310498 Forwards IE Insp Repts 50-266/80-19 & 50-301/80-19 on 801103-04. No moncompliance noted. MEIBHMAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 80/11/20. 2pp. 07365:229.
- --8012310300 IE Insp Repts 50-266/80-19 & 50-301/80-19 on 801103-04. No noncompliance noted Major areas inspected implementation of TMI task action plan Category A requirements. OULDEHOND, W. G., HAOUE, R. L., WARNICK, R. F. Region 3, Chicago, Office of the Director. 80/11/18. 4pp. 07365:231.
- B012040639 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/21. 2pp. 07166:339.
- B012080090 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/24, 2pp. 07182, 243.
- 8012170522 Forwards IE Info Notice 80-29, Suppl 1, "Broken Stude on Terry Turbine Steam Inlet Flange." No written response raquired. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/26. 2pp. 07268.116.
- B012230067 Responds to IE Bulletin 80-23, "Failure of Bolenoid Valves Mfg by Valcor Engineering Corp." No Valcor solenoid valves w/Parts V70900-21-1 or V70900-21-3 installed in safety-related applications.

 FAY. C. W. Wisconsin Electric Power Co. B0/12/02. ip. 07311:083.
- 8012150278 Forwards IE Insp Repts 50-266/80-18 & 50-301/80-18 on 801027-31. No noncompliance noted. KEPPLER, J. G. Region G. Chicago, Office of the Director. 80/12/04. 2pp. 07237:824.
- --8012150281 IE Insp Repts 50-26A/80-18 & 50-301/80-18 on 801027-31.No noncompliance noted Major areas inspected security plan, access control & physical barriers. Details withheld (ref 10cFR2, 790), GREED, J. R., KNIGELEY, J. R., Region G., Chicago, Diffice of the Director. HIND, J. A., Region G., Chicago, Safeguards Branch. 80/12/03, 2pp. 07237:326.
- 8012240473 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Manufacturers contacted for verification phase of investigation.
 FAY.C. W. Wisconsin Electric Power Co. 80/12/04. 2pp. 07323:055.

- 8012240407 Affirms util 801030 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." FAY.C.U. Wisconsin Electric Power Co. 80/12/05. 1p. 07324:309.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-018 re environ qualification of Class IE equipment.
 HAYES.D.W. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp.
- R. Periodic operating reports & related correspondence
- 8012160427 Forwards monthly operating repts for Nov 1980. FAY:C.W. Wisconsin Electric Power Co. 80/12/11, 1p. 07254:149.
- --801216042B Monthly operating rept for Nov 1780. FAY.C.W. Wisconsin Electric Power Co. 80/12/08. 10pp. 07294:146.
- S. Reportable occurrences, LERs & related correspondence
- 8012090306 Forwards LER 80-009/03L-0. FAY.C. H. Wisconsin Electric Power Co. 80/11/25, 1p. 07201:124.
- --B012070314 LER B0-009/03L-0: on B01101. during normal operation.
 performance of ICP 2.14 found PB permissive bistable from
 charnel N44 to be set at 50.5%. Caused by Instrument drift.
 Bistable adjusted & tested satisfactorily.
 FAY.C.W. Wisconsin Electric Power Co. B0/11/25. 1p. 07201:125.
- 8012170369 Forwards LER 80-011/03L-0. FAY, C. W. Wisconsin Electric Power Co. 80/12/11. 1p. 07264:253.
- --B012170604 LER B0-011/03L-0: on B01118 axial flux difference deviated from target band. Caused by improper interpretation of Tech Specs resulting in Failure to lower high neutron flux setpoint. Instruction clarified. FAY.C. N. Wisconsin Electric Power Co. B0/12/11. 3pp. 07264:254.
- 8012170598 Forwards LER 80-012/03L-0. FAY.C.U. Wisconsin Electric Power Co. 80/12/11. 1p. 07264:250.
- ---B012170605 LER 80--012/03L--0: on 801202. slippage found in shaft driven seal water pump impeller resulting in overheating of throttle bushing. Caused by reduced seal water flow due to loosening of pumping ring. Shaft sleeve & bushing replaced. FAY.C.U. Wisconsin Electric Power Co. B0/12/11. 2pp. 07264: 251.
- DUCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3
 F. Sacurity, medical, emergency & fire protection plans
- B01215023B Forwards util response to unresolved items in 790727 fire protection SER. Discusses fire detection signaling systetem driven emergency feedwater pump. & evaluation & corrective action for fire consequences in certain areas.

 BAYNARD.P. Y. Florida Power Corp. B0/12/11. App. 07237; 235.
- J. Insurance & indemnity information
- 8012010355 Forwards Endorsement 44 to ANI Policy NF-195. FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/11/24. 2pp. 07098:044.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PNRs & describes program NRC is undertaking to review capability of operating PNRs to remove decay heat following earthquake.

 EISENHUT, D. G. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating roactor licensee confirmation in 45 days that Encl I implementation dates will be mot. EIBERMUT.D.O. Division of Licensing. 80/10/31. 7pe.
- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BWN Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days, I/O encl, EISERMUT, D. G. Division of Licensing. 80/11/13. 19.

- 012090535 Forwards Amend 36 to Licente DPR-72, safety evaluation.EIA & notice of issuance & availability. REID.R.W. Operating Reactors Branch 4. 89/11/17. 2pp. 07196:067.
- -8012080553 Amend 36 to License DPR-72.revising Tech Specs authorizing increase in capacity of spent fuel storage pools at facility.

 REID.R.W. Operating Reactors Branch 4. 80/11/17. 9pp. 07196:069.
- -8012080544 Safety evaluation supporting Amend 36 to License DPR-72.

 ** Office of Nuclear Reactor Regulation, Director, 80/11/17. 9pp.
 07196:087.
- -8012080551 EIA supporting Amend 36 to License DPR-72.

 # Office of Nuclear Reactor Regulation. Director. 80/11/17. 9pp.
- -8012080555 Notice of issuance & availability of Amend 36 to License DPR-72.
 REID,R.W. Operating Reactors Branch 4, 80/11/17. 2pp.
 07176:096.
- Ol2010077 Forwards nonproprietary version of "Nuclear Safety Review Task Force," final rept.Nuclear Safety Task Force was established to identify areas that indicate potential for improvement in safety of facility.
 BAYNARU,P.Y. Florida Power Corp. 80/11/26. 3pp. 07097;076.
- -8012010098 Nonproprietary version of. "Nuclear Safety Task Force," final rapt.
 BAYNARD, P. Y. Florida Power Corp. 80/11/26. 124pp. 07097:079.
- 012090211 Application to amend Apps A & B of License DPR-72 to expand Plant Review Committee & to revise procedure review process. BAYNARD.P.Y. Florida Power Corp. BD/12/03. 3pp. 07207:15B.
- -8012070212 Tech Spec change amending Apps A & B to OL re administrative controls. → Florida Power Corp 80/12/03. 25pp. 07207:161.
- OS2270485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey. DEN100.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- -8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp
- 012090220 Forwards supporting documentation for Tech Spec Change Request 27 re reactor coolant pump power monitors. BAYNARD,P.Y. Florida Power Corp. BO/12/05. 4pp. 07187:001.
- -8012070225 Procedures & calculations re pump monitor isolation aubsystem. Vitro Seismic & high voltage tasts & pump monitor response time. Submitted in support of Tech Spec Change Request 27.
 4 Babcock & Wilcox Co. 80/12/05. 150pp. 07187:001.
- 012270230 Notification of 801216 meeting w/B&W coners group in BethesdarMD re resolution programs & schadules of TMI=2 task action plan items. THROM,E.D. Reactor Bystems Branch. 80/12/09. 2pp.
- O12240474 Notification of 801216 meeting w/8kW owners group for small break LOCAs in Bethesda.MD for presentation of programs & schedules for resolutions of FKI-2 task action plan items. THROM, E. D. Reactor Systems Branch. 80/12/09. 2pp.
- 012170505 Responds to NRC 801031 ltr requesting confirmation re implementation dates for IMI-related items. Summary listing of applicable NuRGe-0737 items encl. BAYNARU.P.Y. Florida Power Corp. 80/12/15. 25pp. 07266:307.
- O12240274 Requests approval for use of BUNA-N seal math in hydraulic snubber until refueling outage. Insp of snubbers requires unit shutdown, Use of seal math to date has not caused imperability of snubbers.
 BAYNARO, P. Y. Florida Power Corp. BO/12/19, 3pp. 07324;339.
- 012240328 Forwards "Preliminary Sys Description Emergency Feedwater Sys," per licensing response commitment re Item II, 3, 1, 2 of NURCO-0737. NUREG-0737. BAYHARD,P.Y. Florida Power Corp. 80/12/17. 3pp. 07322:276.

- -8012240332 "Preliminary Sys Description Emergency Feedwater Sys." Eleven oversize drawings encl. 4 Florida Power Corp. 80/12/19. 36pp. 07322:279.
- B0123004B1 Forwards Revision 1 of facility electrical distribution sys review summary. BAYNARD.P.Y. Florida Power Corp. 80/12/22. 25pp. 07359:157.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012160026 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24.

 1p. 07252:359.
- B012170284 Forwards Suppl 3 to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment." No written response raquired. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24. Ip. 0/268:291.
- 801214003B Forwards IE Insp Rept 50-302/80-32 on 80090B-12.Ne noncompliance noted. LEWIS/R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/10/30. 2pp. 07263:022.
- --8012160041 IE Insp Rept 50-302/80-32 on 800708-12. No noncompliance noted Major areas inspected: precritical activities & initial criticality for Cycle 3 & zero pauer physics teste.

 BURESTIP. T., FORD, E. J., FALCOMER, D. P. Region 2, Atlanta, Office of the Director, 80/10/30. App. 07263:024.
- 8012180019 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/10/30. 1p. 03790:122.
- 8012010511 Forwards responses, prepared by Gilbert Associates, to IE Bulletin 79-018 re environ qualification of safety-related electrical equipment, to 800523 Order 80-CLI-21 & to 800919 order for mod of license.

 BAYNARD, P. Y. Florida Power Corp. 80/10/31. 275pp. 07092:182.
- 8012180014 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/31. lp. 03790:108.
- 8012230043 Forwards IE Circular 80~23, "Potential Defects in Beloit Power 8ys Emorgency Generators." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31. 1p. 07311:235.
- B012110743 Forwards IE Bulistin 80-21. "Valve Yokes Supplied by Malcolm Faundry Co.Inc." Written response required.

 O'REILLY.J.P. Region 2. Atlanta, Office of the Director. B0/11/06.

 tp. 07225:207.
- 8012030092 Forwards IE Info Notice 80-40. "Excessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/07. 1p. 07150:191.
- 8012080206 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/10.
 1p. 07182:267.
- B012180302 Forwards IE Insp Rept 50-302/80-34 on B00716-19.No noncompliance noted. BTCHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. B0/11/10. 2pp. 03794:046.
- --B012180308 IE Insp Rept 50-302/80-34 on 800914-19. No noncompliance noted. Major areas inspected: mgt control, enforcement matters, LERs, nonradwaste releases % chemical-industrial waste water treatment sys. CURNINUHAM, A.L., JENKINS, Q.R. Region 2, Atlanta, Office of the Director, 80/11/10. 4pp. 03794:048.
- B012040202 Forwards 1E Bulletin B0-23. "Failures of Bolanoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REIULY.J.P. Region 2. Atlanta, Office of the Director. 80/11/14. 1p. 07158:116.

- 8012120573 Act receipt of 801024 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/80-35.
 KENNA,W.S. Region 2, Atlanta, Safeguards Branch. 80/11/14. ip. 07237:142
- ~~8012120375 Forwards IE Insp Rept 50-302/80-35 on 800914-17 & notice of violation Notice of violation withheld (ref 10CFR2, 790). KENNA, H. B. Region 2, Atlanta, Safeguards Branch, 80/10/01. 2pp. 07237:143.
- --B012120577 IE Insp Rept 50-302/B0-35 on 800914-17. Noncompliance noted: two sections of vital area barrier not constructed w/proper mati & failure to search packages entering protected area.

 Details withheld (ref 10CFR2 790).

 MOORE, D. E. . HGCUIRE, D. R. Region 2, Atlanta, Office of the Director. 80/09/30. 1p. 07237:145.
- 8012080738 Responds to IE Builetin 80-11, Itam 2b, "Masonry Wall Design." Evaluation indicates that walls comply w/FSAR & Tach Spec requirements. BAYNARD, P. Y. Florida Power Corp. 80/11/17. 32pp. 07188:256.
- B012240232 Responds to IE Bulletin B0-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Valcor solenoid valves V70700-21-1, V70700-21-2 & V70700-21-3 not used at facility. BAYNARD, P. Y. Florida Power Corp. B0/11/19, ip. 07328:218,
- 8012040479 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required, Requests info on manpower expended. O'REILLY.J.P. Region 2, Atlanta. Office of the Director. 80/11/21. 1p. 07163:344.
- 8012030654 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Spubber Fluid." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24. Ip. 07174: 115.
- 8012170516 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26. ip. 07268:106.
- 8012300740 Advises that util response to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc," will be submitted by 801219.

 BAYNARD, P. Y. Florida Power Corp. 80/12/08. 2pp. 07359:273.
- R. Periodic operating reports & related correspondence
- 8012140483 Forwards monthly operating rept for Nov 1980. BAYNARD, P. Y. Florida Power Corp. 80/12/12. ip. 07255:343.
- --B012160489 Monthly operating rept for Nov 1980. CULVER.M.M., BRONN,J.A. Florida Power Corp. 80/12/02. 7pp. 07253:344.
- 8. Reportable occurrences, LERs & related correspondence
- 8012020524 Forwards LER 80-043/04L-0. HANCOCK, J. A. Florida Power Corp. 80/10/31. 1p. 07143:268.
- --8012020531 LER 80-043/04L-0: on 801001/difference of more than two std deviations discovered to exist between preoperational & operational studies in metabolic function of discharge salt marshes. Probable cause is natural or seasonal variations.

 4 Florida Power Corp 80/10/31. 4pp. 07143:269.
- 8012020635 Forwards LER 80-043/041-1.

 HANCOCK, J. A. Florida Power Corp. 80/11/26, 1p. 07143:291.
- --8012020646 LER 80-049/04L-1: on 801001, difference of more than two std deviations discovered between preoperational & operational studies in metabolic function of discharge salt marshes. Probably caused by natural or seasonal variations. HERNANDEZ, V. A. Florida Power Corp. 80/11/26, 4pp. 07143:292.
- 8012220304 Forwards LER 80-048/03L-0. HANCOCK, J. A. Florida Power Corp. 80/12/16. 1p. 07307:307.

12.39

--8012220312 LER 80-048/03L-0: on 801116 % 18.containment isolation valve CAV-3 did not close while sampling pressurizer water space. Caused by inadequate closing torque. Valve closed, deactivated & maint performed.

HERNANDEZ.V. Florida Power Corp. 80/12/16. 2pp. 07307:308.

- B012290448 Forwards LER 80-049/03L-0. HANCOCK, J. A. Florida Power Corp. B0/12/16. 1p. 07318: 282.
- --B012230454 LER 80-049/03L-0: on 801119, containment isolation valve CFV-12 uould not close after bubbling nitrogen to CFT-18.

 Caused by broken can in torque switch. New switch installed & adjusted.

 HERNANDEZ, V. A. Fibrida Power Corp. 80/12/16. 2pp. 07318:283.
- B012230513 Forward's LER 80-040/04L-2. HANCOCK, J. A. Florida Power Corp. B0/12/16. 1p. 07316:290.
- --B012230524 LER 80-040/04L-2:on 800915 discovered that samples not obtained for month of Aug from test well 4. Caused by elimination of test well sites due to canal mod const. Test well 4B established on 800816 to replace well 4. 06 HERNANDEZ, V. A. Florida Power Corp. 80/12/16. 2pp. 07316:291.
- 8012230433 Forwards LER 80-050/03L-0. HANCOCK, J. A. Florida Power Corp. 80/12/18, 1p. 07318:271.
- --8012230437 LER 80-030/03L-0:on 801119, found that level indication for sodium hydroxide tank BST-2 was erratic & displaying incurrect indication. Caused by water in sensing lines. Engineering investigation is being conducted.
 HERNANDEZ, V. A. Florida Power Corp. 80/12/18. 2pp. 07318: 272.
- 8012230440 Forwards LER 80-047/04L-0. HANCOCK, J. A. Florida Pawer Corp. 80/12/18. 1p. 07318:274.
- --B012230446 LER 80-047/04L-0:on B01118 difference of more than two std units discovered between preop study & operational study in metabolic function of discharge salt marshes. Possibly caused by plant thermal output or matural phenomena.

 Fiorida Power Corp. 80/12/18. 3pp. 07318:275.
- 8012300501 Forwards LER 80-051/01T-0. HANCOCK, J. A. Florida Power Corp. 80/12/26. 1p. 07357: 346.
- --B012300512 LER 80-051/01T-0: on 801214, during traubleshooting operations while isolating leak in fire svc sys, FSV-107 was shut, isolating fire svc from aux bldg deluge contrary to Tech Specs. Caused by failure to interpret design function. HERNANDEZ.V.A. Florida Power Corp. 80/12/26. 2pp. 07357:347.
- V. Operator Examinations
- B012170597 Approves util B00627 request to revise requirements for operators & backup licenses presented on Pages 12C-11 & 12C-12 of FSAR, COLLINS.P.F. Operator Licensing Branch. B0/11/28. 2pp. 07269:192.
- DOCKET 50-303 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4

 A. Application/construction stage documents & correspondence
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of JE survey.

 DENION. H. R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --9012220504 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANCART.R.L. Effluent Treatment Systems Branch. B0/11/06. Opp.
- DOCKET 50-304 210N NUCLEAR POWER STATION, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 801204024B Informs of no present implementation requirement re fire protection mods. Completion of items will be governed by schedules in revised IOCFR50.4B to be published in FR notice.

 EISERMUT, D. G. Division of Licensing. 80/11/17. 5pp. 07170: 207.
- 8012020167 Discusses planned mods to emergency notification system health physics network NRC will pay for installation of output jacks to provide capability for adding one-way speakers. 170 enci health physics network manual.

 KEPPLER, J. O. Region G. Chicago, Office of the Director. 80/11/19. 2pp.

- 8012120576 Resubmits security plan revisions, in response to NRC 800910 & 1119 ltms.Plan withheld from public disclosure (ref 100FR2.790).W/o encl.
 ABEL.J.S. Commonwealth Edison Co. 80/12/08 lp.
- 8012290346 Forwards evaluation of fire protection items provided in 800430 & 791031 ltrs. Smoke detection sys.gas suppression sys.CSR suppression sys & water suppression sys found acceptable.

 VAROA, S. A. Operating Reactors Branch 1. 80/12/09. 5pp. 07346:001.

H. General correspondence

- 8012020642 Responds to BOD913 ltr to President Carter.Forwards favorable presidential position on nuclear energy.Notes efforts to insure safeguards.

 DEN108.H.R. Office of Nuclear Reactor Regulation, Director.

 BO/10/27. 5pp. 07256:318.
- 8012240403 FOIA request for four categories of documents re cracks in containment of facility reactors.
 SHINEFLUD.M. Illinois Safe Energy Alliance. 80/11/18. 1p.
 07283:132.
- 8012240400 Responds to FDIA request for four categories of documents recracks in containment of facility reactors. Forwards NUREO/CR-1411 & 800730 summary & presentation from 800617 technology exchange meeting w/utils.U/o ancl NUREO/CR-1411. FELTON.J.M. Division of Rules and Records. 80/12/15. 1p. 07324:306.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8012020968 Summary of Subcommittee on Class 9 Accidents 800702 meeting in Inglewood.CA re possible mitigation features. * ACRS Advisory Committee on Reactor Safeguards. 80/09/17. Spp.

P. Operating license stage documents & correspondence

- e012020753 Forwards seismic qualifications of auxiliary feadwater sys in operating PWRs & describes program MRC is undertaking to review capability of operating PURs to remove decay heat following earthquake. EISENHUT.D.O. Division of Licensing. 80/10/21. 4pp.
- 2012160050 Ltr to operating plant licensees. CL applicants & CP holders. Forwards NUREQ-0737 to TML action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be not. EISEINHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- B012220563 Ltr to all power reactor licensess forwarding NUREG-0619, "BHR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," Confirmation that implementation dates will be sent within 45 days. H/o encl. EISENHUT, D. O. Division of Licensing. B0/11/13. 1p.
- 8012180620 Forwards Amends 32.51 & 45 to Licenses DPR-2, DPR-19 & DPR-25, respectively. Amends 60 & 55 to Licenses DPR-29 & DPR-30, respectively & Amends 58 & 55 to Licenses DPR-39 & DPR-48, respectively. Safeguards contingency plans acceptable. CRUTCHFIELD, D. Operating Reactors Brench 5. 80/11/17. 5pp.
- --8012180668 Amends S8 % 55 to Licenses DPR-37 & DPR-48, respectively, requiring implementation of safeguards contingency plan. VARGA. B. A. Operating Reactors Branch 1. 80/11/17. 4pp. 07271:339.
- --8012189671 Notice of issuance of Amends 32:51 & 45 to Licenses DPR-2, DPR-19 & DPR-25, respectively, Amends 60 & 55 to Licenses DPR-29 & DPR-30, respectively & Amends 58 & 55 to Licenses DPR-39 & DPR-48, respectively to safeguards contingency plan. CRUICHFIELD.D. Operating Reactors Branch 5. 80/11/17. 2pp.

re request to replace spent fuel to commitments in DL. Jed in updated FSAR. 60/11/20. ip. 97130:362.

b purge & vent

pp. 07270: 338.

lication testing

- 8012119254 Application to amend Licenses DPR-39 & DPR-48 to permit use of max of four extended burnup fuel assemblies in facility Cycle 6 reload.
 TRAMM,T.R. Commonwealth Edison Co. 80/12/03 3pp. 07225:309.
- --8012110267 Proposed revision to Tech Bpec Figure 3.2-6 & Page 70 to permit use of mar of four extended burnup fuel assemblies in facility Cycle 6 reload.

 **Commonwealth Edison Co. 80/12/03 3pp. 07225:312.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION, H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANDARTIR.L. Effluent Treatment Systems Branch. B0/11/06. Spp.
- 8012290342 Informs that low pressure gross leak test of containment must be performed prior to any startup from cold shutdown. Different gross leak tast ensuring containment integrity & minimizing personnel exposure might be allowed, VAROA, S. A. Operating Reactors Branch 1. 80/12/08, 3pp. 07346:008.
- B012290210 Responds to 800506 ltr requesting guidence on testing methods of wadge-opening-loading specimens from facilities. NUREO on subj will be issued by end of 1980 % made available to utils by mid-1981. VARQA, S.A. Operating Reactors Branch 1. 80/12/09, 3pp. 07343:356.
- 8012170447 Submits schedule for transmitting proposed Tech Specs changes covering 10 TMI-2 Lessons Learned Category A items per 800702 request Alternats schedule also proposed. TRAMM.T.R. Commonwealth Edison Co. 80/12/11.
- 8012170488 Forwards response to NRC 801031 ltr requesting confirmation that implementation dates indicated in NUREO-0737 will be met. Ability to mest required dates for major mods is contingent upon hardware availability & delivery.

 ABEL.J.S. Commonwealth Edison Co. 80/12/15. 37pp.
- 8012240150 Forwards confirmation that implementation dates per NUREO-0737 will be met & justification for exceptions. Generally dates are contingent upon hardware availability & delivery. Comments on safety requirements in Tech Specs. ABEL, J. S. Commonwealth Edison Co. 80/12/15. 37pp.
- 8012290247 Suppls 800623 response to NRC request for info re adequacy of station electric distribution sys voltages.
 TRAMM, T.R. Communwealth Edison Co. 80/12/19. 1p. 07345:141.
- BD12300637 Forwards Bethlehem Steel Corp "Rept of Machanical & Chemical" Test." re 700315 Shipment 160-1749. Rept discusses Zion reactor coolant gump support rods.
 TRAMM.T.R. Commonwealth Edison Co. 80/12/23. 2pp. 07346:167.
- Q. Inspection reports, IE Bulletins & correspondence
- B012170510 Forwards IE Info Notice B0-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. B0/10/24.
- B012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. W/o encl. KEPPLCR.J. Q. Region 3. Chicago, Office of the Director. B0/11/18.
- B012040274 Ack receipt of B01001 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/80-09 & 50-304/80-09. HINOLJA. Region 3, Chicago, Bafeguards Branch. 80/11/18. ip. 07163:265.
- --8012040284 Suppls 800703 ltr re violations noted in IE Insp Repts 30-295/80-09 & 50-304/80-09. Corrective actions: draft to be completed stating contractor screening guidelines in more practice language.

 ABEL, J. B. Communication Edison Co. 80/10/01, 13pp. 07163:266.

- B012040037 Ack receipt of B01015 ltr providing results of Bergen-Patterson steam generator snubber testing. Provides list of comments. More detail should be provided for stiff spring mod which altered original valve block design.

 KEPPLER, J. O. Region 3. Chicago, Office of the Director. 80/11/20. 2pp. 07170: 282.
- --8012040064 Forwards "Results of Unit 2 Steam Cenerator Snubber Testing at NH Testing Lab (NHTL) May 1980." in response to JG Keppler 800117 1tr request. Based on rept. util has concluded that snubbers successfully completed tests. ABEL. J. B. Commonwealth Edison Co. 80/10/13. 2pp. 07170: 284.
- --8012040068 "Results of Unit 2 Steam Generator Snubber Testing at NH Testing Lab (NHTL) May, 1780." * Commonwealth Edison Co. 80/10/15, 12pp. 07170;286.
- 8012040667 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21.
- 8012080087 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER. J. O. Region 3. Chicago. Office of the Director. 80/11/24. 2pp.
- 8012170408 Forwards monthly status rept of evaluations performed in response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." No sys identified w/stress exceeding 1/2 math ultimate stress at DBE loadings. JANECEK.R.F. Commonwealth Edison Co. 80/11/24. 14pp.
- B012230223 Forwards new security badge numbers & clearance levels for Region 3 personnel. Changes should be entered on Bept 1780 access lists. KEPPLER, J. O. Region 3, Chicago, Dffice of the Director. 80/11/25.
- 8012100661 Ack receipt of 800919 response to NRC 800818 ltr requesting addl info re IE Bulletin 79-14 evaluations. Dresden & Guad Cities responses to Items 1 & 3 unacceptable, since requested info was not included. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/26.
- 8012170532 Forwards IE Info Notice 80-27, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/26.
- 8012310212 Suppls 801106 response to 1E Bulletin 80-11 re masonry wall design deficiency. Necessary repairs to 16 walls not meeting acceptance criteria to be completed by 810101.
 RAUSCH.T.J. Commonwealth Edison Co. 80/12/01. Rpp. 07369: 282.
- 8012100379 Ack receipt of B01118 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Repts 30-295/80-05 & 50-304/80-04. KEPPLER.J.O. Region 3. Chicago. Office of the Director. B0/12/02. ip. 07218:162.
- --8012100582 Responds to NRC 800627 ltr re violations noted in IE Health Physics Appraisal Repts 50-298/80-05 & 50-304/80-04, Corrective actions: present key control of access to high radiation areas will be maintained.

 ABEL.J. B. Commonwealth Edison Co. 80/11/18. 1p. 07218:163.
- 8012230045 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." No valve parts cast by Malcolm Foundry planned for use or in use at facilities, RAUSCH.T.J. Commonwealth Edison Co. 80/12/05, 2pp.
- 8012290394 Responds to 801114 ltr re change in insp plans for charging pump casing suction end plate. Plans will be evaluated for potentially generic problem.
 FIORELLIO. Region 3. Chicago: Reactor Construction & Engineering Support Branch. 80/12/09. 1p. 07345:108.
- 8012310583 Ack receipt of 801113 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 30-295/80-09 & 50-304/80-09. HIND, J. A. Region 3, Chicago, Safeguards Branch. 80/12/09. 1p. 07346:031.
- --8012310590 Responds to NRC 801001 ltm re violations noted in IE Insp. Rapts 50-295/80-09 & 50-304/80-09. W/o encl updated screening guidelines & implementing ltm.
 ABEL.J. 8. Commonwealth Edison Co. 80/11/13, lp. 07366:032.

- R. Periodic operating reports & related correspondence
- B012110398 Forwards monthly operating rapts for Nov 1980. ORAFSSER, K. L. Commonwealth Edison Co. 80/12/05. 1p. 07223:215.
- --8012110363 Monthly operating repts for Nov 1980, CDOK, J. H. Commonwealth Edison Co. 80/12/05. 11pp. 07223:216.
- S. Reportable occurrences, LERs & related correspondence
- 8012090433 Forwards LER 80-027/03L-0, ORAESSER.K.L. Commonwealth Edison Co. 80/11/26. 1p. 07203:043.
- --B012090444 LER 80-027/03L-0: on 801029; channel 2L-461 found out of tolerance. Caused by zero shift on zmtr 2L-461. Adjustments made to zmtr k channel returned to svc.

 JENKINS-R.V. Commonwealth Edison Co. 80/11/26. 1p. 07203:044.
- 8012150093 Forwards LER 80-026/99X-0, ORAESBER, K. L. Commonwealth Edison Co. 80/12/02. 1p. 07237: 287.
- --8012150094 LER 80-026/99X-0: on 800930: inadvertent safety injection occurred. Caused by faise steam pressure differential signal in loops 2A & 2C. Mods underway to install J tubes in feedwater rings of steam generators.

 BINGCELI-B.L. Commonwealth Edison Co. 80/12/02, 3pp. 07237:288.
- --B01217061B LER 80-028/03L-0: on B01110, steam generator 2B feed flow channel 2F-540 out of tolerance. Caused by zero shifting of Fisher Porter transmitter. Transmitter zero adjusted & channel returned to svc.

 JENKINS, R. V. Commonwealth Edison Co. B0/12/10. 1p. 07264: 233.
- 8012230316 Forwards LER 80-029/01T-0. ORAESSER, K. L. Commonwealth Edison Co. 80/12/15. 1p. 07318:211.
- ---8012230318 LER 90--029/01T-0: on 800119; outlet damper on hydrogen purge sys 2B found inoperable during constant speed drive & not repaired prior to startup. Caused by failure of normal operability surveillance to include verification.

 STAHMER, F. Commonwealth Edison Co. 80/12/15. 3pp. 07318:212.
- DOCKEI 50-305 KEWAUNEE NUCLEAR POWER PLANT

 F. Security, medical, emergency & fire protection plans
- B012020102 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys.W/o enci health physics network manual. KEPPLER.J. G. Region G. Chicago. Office of the Director. B0/11/19. 2pp. 07148:357.
- 8012100368 Submits info re emergency offsite facility, in response to NRC telex received 801201.
 MATHEMB.E.R. Wisconsin Public Service Corp. 80/12/01. 2pp. 07219:057.
- 8012300254 Forwards industrial security manual Revision 2. Plan withheld (ref 100FR2.790).
 MATHEMB.E. R. Wisconsin Public Service Corp. 80/12/22. 2pp. 07357:231.
- P. Operating license stage documents & correspondence
- B012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PMRs & describes program NRC is undertaking to review capability of operating PMRs to remove decay heat following earthquake.
 EISENHUT.D. O. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensess. GL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Enci i implementation dates will be ret. EISERHUT: D. O. Division of Licensing. 80/10/31. 7pp.
- 8012020112 Confirms 801030 plans for 801120 meeting at facility to discuss NRC evaluation of regulatory performance.

 KEPPLER, J. G. Region 3. Chicago. Office of the Director. 80/11/10. 3pp. 07148:360.

- B012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BNR Feedwater Noizle & Control Rod Drive Return Line Noizle Cracking." Confirmation that implementation dates will be mat must be sent within 45 days N/o encl. EISENRUT.D.G. Division of Licensing. B0/11/13. 1p.
- 8012160194 Confirms 801114 telcon authorizing Tech Spec change to License DPR-43. Tech Spec 3.2. C. 4 permits two boric acid pumps to be out of svc on 801114. NOVAW. T.M. Assistant Director for Operating Reactors. 80/11/24. 2pp. 07262:307.
- B012020372 Ack reneipt of NRC 801031 ltr transmitting NUREO-0737, "Clarification of TM1 Action Plan Requirements," Info on implementation schedules & design for requirements will be subnitted by 810101.
 MATHERS, E. R. Wisconsin Public Service Corp. 80/11/26. 1p. 07142:074.
- B012220485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012150764 Proposed Amend 42a, superseding proposed Amend 42 to License DPR-43. Forwards proposed Tech Specs to clarify some sections, cornect inconsistencies & cornect arganization charts submitted in Tech Specs w/proposed Amend 42. MATHEMS, E. R. Wisconsin Public Service Corp. 80/12/09. 2p. 07240:311.
- --8012150267 Proposed revisions to Tech Specs submitted 800908 u/proposed Amend 42.Changes reflect Nuclear Dept reorganization which became effective 800301.

 # Wisconsin Public Service Corp. 80/12/09. 11pp. 07240:313.
- 8012140314 Responds to NRC 800814 request for add1 info re loss of offsite power survey. Facility has not experienced offsite loss of power resulting from grid failures such as severed power lines.
 MATHEMBLE.R. Wisconsin Public Service Corp. 80/12/09. 1p. 07245-006.
- B012290354 Forwards request for add3 info re auxiliary feedwater automatic initiation & flow sys.
 VAROA:S.A. Operating Reactors Branch 1. 80/12/09. 4pp. 07345:397.
- 8012300416 Forwards response to 800821 request for add1 info re adequacy of station electrical distribution sys voltage analyses performed by util. MATHEMBLE.R. Wisconsin Public Service Corp. 80/12/22. 4pp. 07357:320.
- 8012300413 Advises that NAC 801113 ltr requesting confirmation of implementation dates in NUREC-0619 does not apply to facility.

 MATHRIS.E.R. Wisconsin Public Service Corp. 80/12/23. lp. 07349:357.
- 8012300474 Discusses proposed Yech Specs, incorporating lessons learned items re emergency power supply requirements, valve position, instrumentation for inadequate core cooling, containment isolation, auxiliary feedwater & sys integrity monitoring, MATHEMS, E. R. Wisconsin Public Service Corp. 80/12/23, 4pp. 07346; 128
- 8012300559 Responds to NRC 800410 ltr re use of term operable. Since Tech Specs do not follow 8T6 format. revisions to Tech Specs deemed unnacessary.

 MATHEMBLE. R. Wisconsin Public Service Corp. 80/12/23. 3pp. 07346:253.
- Q. Inspection reports: IE Bulletins & carrespondence
- 8012190567 Forwards IE Mgt Meeting Rapt 50-305/80-22 on 800919. No nonconpliance noted.

 KEPPLER, J. C. Region 3. Chicago, Office of the Director. 80/10/22. 2pp. 07273:286.

- --B012190692 IE Mgt Meeting Rept 50-305/80-22 on 800919. No noncompliance noted. Major areas discussed: NRC perception of serious interface problem at corporate level & avenues to resolve matter.

 KEPPLER, J. O. Region 3. Chicago, Office of the Director. B0/10/21, 2pp. 07273: 288.
- 60:2170901 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLCR.J. G. Region 3, Chicago, Office of the Director. 80/10/24, 1p. 07268:088.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. If/o enci.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/18, 4pp.
- B012040299 Ack receipt of B01024 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/80-18. HEIBHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. B0/11/20. ip. 07170:064.
- --8012040302 Responds to NRC 801002 ltr re violations noted in IE Insp. Rept 50-305/80-18. Corrective actions:all A & B valves in noncompliance w/IMV-3410 tested immediately & administrative controls increased.

 MATHEMB.E. R. Wisconsin Public Service Corp. 80/10/24. 3pp. 07170:067.
- 8012040561 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER.J. O. Region 3. Chicago. Office of the Director. 80/11/21, 2pp. 07166:344.
- 8012080378 Notification of 801201 meeting w/util in Dethesda.MD to discuss NRC orders & bulletins re qualification of safety-related electrical equipment & facility response to 800717 revised order for mod of license.

 LICCIARDO.R.D. Operating Reactors Branch 1. 80/11/21. 2pp. 07196:190.
- BO120B00B3 Forwards IE Info Notice BO-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLCR. J. O. Region 3. Chicago. Office of the Director. BO/11/24. 2pp. 071B2:248.
- 8012120389 Ack receipt of 800820 & 1103 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/80-15.
 KEPPLER, J. G. Region G. Chicago, Office of the Director. 80/11/24. ip. 07237:162.
- ---8012120407 Responds to NRC 801006 ltr re violations noted in IE Insp Rept 50-305/80-15. Corrective actions: insp rept to be discussed w/personnel re requirements for approved specific rapair procedures, MATHEMS. E. R. Wisconsin Public Bervice Corp. 80/11/03. 2pp. 07237: 143.
- 8012170320 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER J. O. Region 3, Chicago, Office of the Director. 80/11/26. 2pp. 07268:112.
- B012310421 Repends to NRC 800818 ltr requesting clarification of response to IE Bulletin 80-11, "Masonry Wall Design." Equipment listing encl.
 MATHEWS, E.R. Wisconsin Public Service Corp. 80/12/08, 97pp. 07340-279
- BO12190210 Forwards third bimonthly status rept on IE Bulletin 79-01B re environ qualification of Class IE equipment. HAYES,D.W. Region 3. Chicago. Reactor Construction & Engineering Support Branch. B0/12/09. 2pp.
- 8012240058 Forwards IE Insp Rept 50-305/80-25 on B01117-21 & notice of violation. Notice of violation withheld (ref 10CFR2.790). HIND, J. A. Region G. Chicago, Bafeguards Branch. B0/12/12. 2pp. 07324:266.
- --8012240061 IE Insp Rept 50-305/80-25 on 801117-21. Noncompliance noted: packages not searched prior to entering protected area. Details withheld (ref 10CFR2, 790).

 CREED, J. R. KNICELEY, J. R. Region 3. Chicago, Office of the Director. HIND, J. A. Region 3. Chicago, Bafeguards Branch. 80/12/10. 2pp. 07324:268.

- R. Periodic operating reports & related correspondence
- 8012100324 Forwards monthly operating rept for Nov 1980. MATHENS, E. R. Wisconsin Public Service Corp. 80/12/05. 07217:340.
- --8012100328 Monthly operating rept for Nov 1980. RUITER.O.H. Wisconsin Public Service Corp. 80/12/01. 3pp. 07217:342.
- S. Reportable occurrences, LERs & related correspondence
- 8012020428 Forwards LER 80-035/03L-0. MATHEMS.E.R. Wisconsin Public Service Corp. 80/11/26. 1p. 07148: 272.
- --8012020431 LER B0-035/03L-0: on 801030 during normal operation at 100% power, IB2 svc water pump failed to start after routine maint. Caused by defective solid state device. Device replaced per Tech Spac & returned to svc.
 SMOKER.C. S. Wisconsin Public Service Corp. 80/11/26. 1p. 07148-272 07148: 273
- 8012170576 Forwards LERs 80-036/03L-0,80-019/03X-3,80-037/03L-0 & 80-038/03L-0. MATHEHB.E.R Wisconsin Public Service Corp. 80/12/11. 1p. 07266:007.
- --80121705Bi LER 80-036/03L-0: on 801114.both BA transfer pumps taken out of svc in violation of Tech Specs. Caused by need to repair leaking diaphragm shared by pumps. Valve repaired & pumps returned to svc.

 SMOXER, C. S. Wisconsin Public Service Corp. 80/12/12, 1p. 07266: 008.
- ~-8012170588 LER 80-019/03X-3: on 800326; check damper 88V-10A failed to open causing sys inability to create vacuum in annulus. Caused by controller setpoint drift, faulty component & transistor. Parts repaired.

 NALEPKA, D. B. Wisconsin Public Bervice Corp. 80/12/14. 1p. 07266:010.
- --B012170592 LER 80-037/03L-0:on 800611; check damper SBV-10A failed to open causing sys inability to create vacuum in annulus. Caused by controller setpoint drift; faulty component & transistor. Parts repaired. MALEPKA: D. B. Wisconsin Public Service Corp. 80/12/14. 1p. 07266:011.
- --B012170600 LER B0-03B/03L-0: on B00713; check damper BBV-10A failed to open causing sys inability to create vacuum in annulus. Caused by controller setpoint drift, faulty component & transistor. Parts repaired.
 NALEPKA: D. B. Wisconsin Public Service Corp. B0/12/14. 1p. 07266:012.
- 8012230035 Forwards LERs 80-039/01T-0 & 80-040/03L-0. MATHEWS, E.R. Wisconsin Public Service Corp. 80/12/19. ip. 07316:232.
- --8012230339 LER 80-039/01T-0:on 801210.during surveillance of spent fuel pool rack samples, two smaled specimens exhibited swelling. Caused by gaseous product of radinlysis of matls used in boron carbide plate. Rearranged spent fuel bundles. SHOKER, C. S Wisconsin Public Service Corp. B0/12/19. ip. 07316:233.
- --B012230397 LER 80-040/03L-0: on 801125, while recirculating boric acid storage tank A prior to sampling. iA BA transfer pump motor tripped on overload Cause unknown. Pump returned to svc within time limit of Tech Specs 3, 2, c, 2, 840KER, C, 8 Wisconsin Public Service Corp. 80/12/19. 2pp. 07316:234.
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2 F. Becurity, medical, emergency & fire protection plans
- 8012020063 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys.H/o encl health physics natwork manual, KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/19. ip. 07148:343.
- 8012020332 Ack receipt of NRC 801114 ltr commenting on 800815 upgraded emergency plan. Revisions to plan will be completed by 810201. Implementing procedures will be submitted by 810301. MAYER, L. O. Northern States Power Co. 80/11/26. Ip. 07142:049.

- P. Operating license stage documents & correspondence
- B012010593 Notification of B00521 meeting w/util in Bethesda, MD to discuss installation of four & forty Erron fuel assemblies containing gadolinia in forthcoming reload. MARTIN.R.E. Operating Reactors Branch 3. B0/05/14, 2pp. 07095:065.
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PHRs & describes program NRC is undertaking to review capability of operating PHRs to remove decay heat following earthquake.

 EISER-UT, D. G. Division of Licensing, 80/10/21, 4pp.
- BD12160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREQ-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl t implementation dates will be net. EISERMUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BUR Feedwater Notile & Control Rod Drive Return Line Notile Cracking." Confirmation that implementation dates will be met must be sent within 45 days. [Vo encl. EISENHUT, D. 9. Division of Licensing. 80/11/13. 1p.
- 8012040353 Forwards Amends 43 & 37 to Licenses DPR-42 & DPR-40, respectively, safety evaluation & notice of issuance & availability.
 CLARK, R. A. Operating Reactors Branch 3. 80/11/14. 3pp. 07163:223.
- --8012040358 Amends 43 & 37 to Licenses DPR-42 & DPR-60, respectively, revising Tech Space to replace current inservice insp Tech Space w/inservice program meeting requirements of 10CFR50.55.
 CLAR& R. A. Operating Reactors Branch 3. 80/11/14. 5pp. 07163:226.
- --8012040364 Safety evaluation supporting Amends 43 & 37 to Licenses DPR-42 & DPR-60, respectively. 4 Office of Nuclear Reactor Regulation, Director. 80/11/14. 21pp. 07163:231.
- -8012040369 Notice of issuance & availability of Amends 43 & 37 to Licenses DPR-42 & DPR-60, respectively. CLARK.R.A. Operating Reactors Branch 3 80/11/14, 2pp. 07163:252.
- 8012010070 Responds to questions raised by Chemical Engineering & Effluent Treatment Sys Branches re facility fuel storage mod in connection w/800131 OL amend request. MAYER.L.O. Northern States Power Ca. 80/11/21. Spp. 07097:331.
- 8012080319 Forwards Revision 1 to 800506 application for amend to Licenses DPR-42 t DPR-60 changing Tech Specs.Section 3.10 resafety injection actuation power distribution limits. MAYER.L.O. Northern States Power Co. 80/12/02, 1p. 07189: 223.
- -8012080323 Revision i to 800506 application for amend of Licenses DPR-42 & DPR-60 changing Tech Spacs. Section 3. 10 re safety injection actuation & power distribution limits. MAYER.L.O. Northern States Power Co. 80/12/02. 3pp. 07189:224.
- --8012080329 Proposed changes to Tech Bpecs, Section 3.10 re safety injection actuation & power distribution limits. # Northern States Power Co. 80/12/02. 4pp. 07189:227.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation Inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04, 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANDART, R. L. Effluent Treatment Systems Branch. B0/11/06. Spp.
- 8012300265 Responds to NRC 801624 request for add1 auxiliary feedwater sys info Specific responses related tables & drawings & correction to util 791221 ltr encl, MAYER.L.O. Northern States Power Co. 80/12/18. 13pp. 07357:243.
- B012300214 Bubmits licensing fee determination for 801219 amend request for Licenses DPR-42 & DPR-60 re TMI Lessons Learned Category A Tech Specs changes Class III & Class I fees encl. * Northern States Power Co. 80/12/19

- BO12300302 Forwards application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs re TMI Leysons Learned Category A procedural & equipment requirements. Fee encl.
 MAYER.L.D. Northern States Power Co. 80/12/19. Ip. 07357:065.
- --8012300305 Application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs re TMI Lessons Learned Category A procedural & equipment requirements. MAYER, L. D. Northern States Power Co. 80/12/19, 3pp. 07357:066.
- --8012300310 Proposed changes to Tech Specs Sections 3,4 & 6 re TMI Lassons Learned Category A procedural & equipment requirements. * Northern States Power Co 80/12/19, 28pp. 07357:069.
- 9. Inspection reports. IE Bulletins & correspondence
- 6012170544 Forwards 1E Info Notice 80-37, "Containment Cooler Leaks & Reactor Covity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER,J. G. Region 3, Chicago, Office of the Director. 80/10/24.

 12. 07264:192.
- B012010566 Forwards IE Insp Repts 50-282/80-17 & 50-306/80-17 on B01020-24 & notice of violation. Notice of violation withheld (ref 10CFR2.770).

 MIMD.J.A. Region 3, Chicago, Safeguards Branch. B0/11/18. 2pp. 07075:048.
- 3012020743 Forwards three Performance Appraisal Branch insp repts & mgt svaluation tree w/user guide so that facility can compare program to program already reviewed & nake appropriate adjustments N/o encl. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/18.
- 3012040633 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment:" No written response required.

 KEPPLER.J. G. Region 3. Chicago: Office of the Director, 80/11/21.

 2pp. 07163:330.
- 3012080070 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J.G. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:223.
- 3012070006 Responds to IE Bulletin 80-23 Increased surveillance not warranted Solenoid valves do not present safety or plant reliability concern.
 GILBERTS D.E. Northern States Power Co. 80/11/24, 1p. 07179:33B.
- 2012190270 Forwards new security badge numbers & clearance levels for Region 3 personnel Changes should be entered on Sept 1980 access lists. KEFFLCR.J. G. Region 3. Chicago, Office of the Director. 80/11/25. App. 07286:020.
- 3012170531 Forwards IE Info Notice 80-29. Suppl 1: "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER, J. G. Region 3: Chicago: Office of the Director. 80/11/26. 2pp. 07268: 132.
- 8012220177 Responds to IE Bulletin 80-21, "Valve Yokes Bupplied by Malcolm Foundry Co.lnc." Facilities do not use specified valves.
- GILBERTS, D. E. Northern States Power Co. 80/12/05, 1p. 07303:241.
- 8012220734 Forwards revised data sheets in response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." 00170777, D. E. Northern States Power Co. 80/12/05, 7pp. 07299:261.

rept on IE Bulletin 79-018 ipment. natruction & Engineering

mary for facility 1p. 07325: 146.

- ---8012240274 Inservice insp rept for 800902-1013.Refueling Outage S. Insp Period 2. Discusses examination of pressure retaining components & supports of reactor coolant & associated sys classified as ASME Class': & Class 2. DARLMAU, L. D. KRUMPOS, P. J. , ANDERSON, R. W. Northern States Power Co. 80/12/01, 95pp. 07325:147.
- R. Periodic operating reports & related correspondence
- 8012160453 Forwards monthly operating repts for Nov 1980.
 MAYER, L. O. Northern States Power Co. 80/12/11. ip. 07254: 204.
- ---8012160438 Monthly operating repts for Nov 1980. HUNSTAD.A.A. Northern States Power Co. 80/12/01. 8pp. 07254:206.
- S. Reportable occurrences, LERs & related correspondence
- 8012090396 Forwards LER 80-035/03L-0.

 MAYER, L. D. Northern States Power Co. 80/12/03. ip. 07203:026.
- --8012090402 LER 80-035/03L-0: on 801103, remote/local control switch on containment spray pump 21 found not in remote position.

 Caused by contractor workman bumping switch. Switch returned to remote position.

 HURSTAD
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT F. Security, medical, emergency & fire protection plans
- BOI2040149 Public version of "Independent Assessment of Evacuation Times for ME Yankee Nuclear Power Plant," Vol 6 prepared for FEMA. COSBY.J.C., SHEPPARD.H.V., JURASIN, R.P. Wilbur Smith & Associates. 80/06/30. 51pp. 07161:138.
- 8012080/30 Informs that mods will be made to emergency notification sys & health physics network equipment.NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operations facilities. ORIER,B.H. Region i. Philadelphia, Office of the Director. 80/11/14. 2pp. 07196:154.
- 8012070311 Forwards interim iOCFR30. 48, suspending completion date for previously approved fire protection mods, effective 801029. Rule will be superseded by panding revision. EISERHUT.D. O. Division of Licensing. 80/11/14. 5pp. 07207:014.
- B012040065 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, FELTQR-J.M. Division of Rules and Records. 80/12/03, 1p,
- -8012040089 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary,prepared for FEMA. + Ulibur Smith & Associates. 80/06/30. 17pp.
- --B012040155 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol 1, prepared for FEMA.
 COSBY, J. C. Wilbur Smith & Associates. B0/06/30, 43pp.
- 8012150082 Informs that util has installed hose stations referenced in fire protection safety evaluation Hose stations are installed to meet capacity requirements of NFPA 14, standpipe & hose stations. GROCE, R. H. Maine Yankee Atomic Power Co. 80/12/05, 1p. 07239:357.
- O. Adjudicatory correspondence
- 8012150070 Criticizes remarks by NRC official to Portland Press Herald on 801201.backing util plan for long-term storage of nuclear waste in existing fuel pool. Remarks before prehearing conference are unprofessional. Newspaper article encl. TUPPER.S.R. Tupper.S.R. 80/12/04. 3pp. 07240:014.
- 8012110516 Requests hearing by 820630 re environ qualification of safety-related electrical equipment per 801024 order.Util will clarify 801024 order requirements & review 8ERs scheduled for 810201 issuance.

 JOHNBOW H. P. Maine Yankee Atomic Power Co. 80/12/08, 1p. 07222:337.

- H. General correspondence
- 8012290249 Informs of relocation of engineering ofc effective 801222. KAY-J.A. Vankee Atomic Electric Co. 80/12/18. 1p. 07342:338.
- P. Operating license stage documents & correspondence
- B012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following aarthquake.

 EISENHUT, D. 9. Division of Licensing. 80/10/21. 4pp.
- 8012160030 Ltr to operating plant licensees. DL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT, D. G. Division of Licensing, 80/10/31, 7pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREQ-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o enci. EISEKHUT, D. Q. Division of Licensing. 80/11/13. 1p.
- 8012020288 Discusses scope & schedule of program to be pursued in resolving ECGB model concerns re NRC action plan Item II.K. 3.30 on revised small break LQGA methods. Decision on approach will be made by 810215.

 GARRITY.J.H. Maine Yankee Atomic Power Co. 80/11/21. 2pp. 07141:356.
- 8012110133 Bummary of 801007 plant visit to inspect spent fuel pool, main feedwater sys & auriliary feedwater sys.
 REGUA, G. Operating Reactors Branch 3. 80/11/21. 4pp. 07223:163.
- 8012270485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level wasts at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANJART.R.L. Effluent Treatment Bystems Branch. 80/11/06. Bpp.
- B012310043 Forwards request for add1 info for review of radiological aspects of util B00929 proposed spent fuel bin storage mods. Description of method used to remove & dispose of old racks is required.

 CLARK.R.A. Operating Reactors Branch 3. 80/12/08. 3pp. 07371:110.
- 8012190467 Forwards info re commitment to implementation schedule for TMI-related items specified in NUREO-0737. Revised dates & justification for delays provided for implementation dates that will not be met. RANDAZZA.J.B. Maine Yankee Atomic Power Co. 80/12/15. 12pp. 07204:082.
- 8012230430 Advises that util does not intend to submit any applications or requests to NRC from now until 831231. in response to 801205 request. RANDAZA.J. 8. Maine Yankes Atomic Power Co. 80/12/16. 1p. 07312:263.
- 8012310278 Informs of impact of steam driven feedwater pump on util plans for Cycle 6 reload analysis requirements to commence on or about \$10701 Application of RETRAN code best solution to evaluate impact.

 JOHNBON.M.P. Maine Yenkee Atomic Power Co. 80/12/23, App. 07361:312.
- O. Inspection reports. IE Bulletins & correspondence
- 8012170376 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. ORIER.B.H. Region 1. Philadelphia. Office of the Director. 80/10/30. ip. 07269:033.
- BOIR100319 Responds to IE Sulletin 80-11. "Masonry Well Design." Provides details re function of masonry walls.const specs & re-evaluation methodology. JOHNSON, N. P. Maine Yankee Atomic Power Co. 80/11/04. 27pp. 07187:001.

- 8012120100 Forwards IE Bulletin 80-21. "Valve Yotes Supplied by Malcolm Foundry Co. Inc." Written response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 80/11/06. 1p. 072-30:234.
- 8012190372 Informs util of issuance of new NRC personnel identification badges; effective after 801130. Example encl.
 MARTIN, R. J. Region i, Philadelphia, Safeguards Branch. 80/11/06, 2pp. 07286: 135.
- 8012030813 Forwards IE Info Notice 80-40. "Excessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Dayressurization." No written response required. ORIER, B.H. Region 1. Philadelphia, Office of the Birector. 80/11/07. (p. 07150:260.
- 8012080536 Forwards IE Info Notice 80-41, "Failure of Buing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 ORIER, B.H. Region i. Philadelphia. Diffice of the Director.

 80/11/10. 1p. 07182:354.
- B012040040 Forwards IE Bulletin B0-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER.B.H. Region 1, Philadelphia, Office of the Director. B0/11/14. 1p. 07169:342.
- 80:2220667 Advises that written response is required to IE Bulletin 80-23. "Failures of Solenois Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.
 QRIER, B. H. Region i. Philadelphia, Office of the Director, 80/11/19. 1p. 07293:131.
- 8012040536 Forwards IE Bulletin 80-24, "Prevention of Demage Due to Water Leakage Inside Containment." Written response required. Requests info on manpower expended. ORIER.B.H. Region i. Philadelphia, Office of the Director. 80/i1/21. 2pp. 07169:150.
- 8012050572 Forwards Info Natice 80-42, "Effect of Radiation on Hydraulic Bnubber Fluid." No written response raquired. ORIER.8.H. Region 1, Philadelphia, Office of the Director. 80/11/24. ip. 07174:057.
- R. Periodic operating reports & related correspondence
- BO12020589 Forwards discharge munitoring rept for Oct 1980, submitted to State of ME, Dept of Environ Protection.

 QARRITY, J. H. Maine Yankee Atomic Pouer Co. 80/11/24, 2pp. 06916:001.
- --8012020597 Discharge monitoring rept for Oct 1980. FLANDERS, W. L. Maine Yankee Atomic Power Co. 80/11/24. 5pp. 06916:001.
- 8012300526 Forwards discharge manitoring rept for Nov 1980. Ltr to ME Bept of Environ Protection encl. OARRITYJ. H. Maine Yanzee Atomic Power Co. 80/12/22. 2pg. 07308:001.
- --8012300529 Discharge monitoring rept submitted to ME Dept of Environ Protection for Nov 1980. FLANDERS, W. Maine Yankee Atomic Power Co. 80/12/22. 5pp.
- S. Reportable occurrences, LERs & related correspondence
- 8012300478 Forwards LER 80-019/03L-0.
 WDDDrE.C. Maine Yankee Atomic Power Co. 80/12/19. 1p. 07349:342.
- --8012300483 LER 80-019/63L-0: on 801202: during routing surveillance on reactor protection sys.channel C positive symmetric offset gretrip function discovered not available. Caused by failed comparator module. Spare unit installed & returned to svc. BRINKLER: J. E. Mains Yankee Atomic Power Co. 80/12/19, 1p. 07349:343.
- DUCKE) 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2
 F. Security, medical, emergency & fire protection plans
- BO120B0734 Informs that mods will be made to amergency notification sys & health physics network equipment.NRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & amergency operations facilities. GRIER.B.H. Region i. Philadelphia, Office of the Director, BO/11/14. 2pp. 07196:157.

- B012940161 Requests evaluation of vote by Lower Alloway Creek Fire Conot to honor 1976 ltr of agreement. Evaluation should include impact on existing fire protection program & emergency preparadness efforts.
 TEOESCO.R.L. Assistant Director for Licensing. B0/11/17. 2pp. 07170:227.
- 8012030620 Advises that vote of local fire company re response to fires at facility has no impact on fire protection program & emergency preparedness efforts. Facility fire protection sys & brigade are completely self-sufficient.

 MITTL.R.L. Public Service Electric & Gas Co. of New Jersey.
 80/12/01. 2pp. 07149:236.
- 8012030624 Advises of plans for implementation of mods, in response to NRC fire protection rule & App R published in 801117 FR. Rule applies to plants licensed prior to 770101 & becomes effective on 810219.

 MITTLAL. Public Service Electric & Gas Co. of New Jersey.
 80/12/01. 2p. 07149:235.
- 6012180126 Forwards request for add1 info re NUREO-0654. "Criteria for Preparation & Evaluation of Emergency Response Plans & Preparation in Support of Nuclear Power Plants." Info previously discussed at B01121 meeting.

 IEDESCO.R.L. Assistant Director for Licensing. 80/12/04. App.
- 8012190324 Forwards request for add1 info re emergency planning for full power license review. Info is necessary as result of publication of NUREO-0654.

 TEDESCO.R.L. Assistant Director for Licensing. 80/12/04. App.

H. General correspondence

- 8012090416 Responds to 800430 postcard to JF Ahearne re licensing matters concerning facilities. Safety issues resulting from TMI accident will need to be resolved before licenses are issued. Discusses licensing procedures.

 KIRAGLIA:F. J. Licensing Branch 3. 80/11/20. 3pp. 06596:003.
- --8012080435 Supports NRC enthusiasm re licensing of nuclear plants & expresses desire for NRC to move ahead on licensing plants which presently meet stds. VAUSHN.C. Affillation Unknown, 80/04/30. ip. 06586:003.

J. Insurance & indemn'ity (information

- 8012010360 Forwards Endorsement 41 to ANI Policy NF-230, CORREA,M.A. Karsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 60/11/24. 2pp. 07078:046
- P. Operating license stage documents & correspondence
- 8012310130 Requests revisions to util 800707 feedwater hammer test procedure. Procedure should be revised to provide info re test prerequisites, precautions, special test equipment & instrumentation.

 TEDESCO.R.L. Assistant Director for Licensing. 80/f1/07. 2pp. 07371:177.
- 8012030998 Notification of 801121 mgt meeting w/util in Hancocks Bridge, NJ to discuss outstanding licensing issues.

 KERRIGAN, J. Licensing Branch 3. 80/11/13. 5pp. 07149:067.
- 8012040156 Requests add1 info re containment boundary fracture taughness.Fracture taughness data for A 106 Orade C piping used in steam generator feedstater sys required. TEDESCO, R. L. Assistant Director for Licensing. 80/11/17. 2pp. 07170:231.
- 8012080784 Discusses issues which must be resolved prior to issuance of full power license. Outstanding issues include: fire protection. General Design Criteria Si-masonry walls, equipment qualification & emergency planning.

 KERRIGAN, J. Licensing Branch 3. 80/11/18. 3pp. 07194:283.

ing w/util in Hancock's Oridge, NJ -ment of masonry walls. - Opp. 07217: 325.

> ire toughness redwater

Jersey.

- B012150004 Notification of 801203 meeting w/util in Bethesda,MD to discuss alternate means of complying w/General Design Criteria 51. KERRIOAN,J. Licensing Branch 3. 80/12/01. 2pp. 07241:072.
- B012220485 Responds to B009t1 memo requesting that Dfc of Nuclear Reactor Regulation inform licensees of need to comply w/revisad Agreement State burial site conditions. Forwards results of IE survey. DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220595 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. BO/11/06, Opp.
- 8012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Committee. MIRAQUIA:F. Licensing Branch 3. 80/12/05. 3pp. 07266:098.
- 8012190396 Forwards Amend 4 to License DPR-75, safety evaluation & notice of issuance & availability.

 MIRAGLIA:F. J. Licensing Branch 3. '80/12/08. 3pp. 07286:190.
- --8012190400 Amend 4 to License DPR-75, approving organizational change to facility operation & support staff & revising related Tech Bpacs.
 MIRAGLIA, F. J. Licensing Branch 3. 80/12/08. 16pp. 07286:193.
- --8012170403 Safety evaluation supporting Amend 4 to License DPR-75, # Office of Nuclear Reactor Regulation, Director. 80/12/08. 3pp. 07286:209.
- --8012190409 Notice of issuance & availability of Amend 4 to License DPR-75. MIRAOLIA, F. J. Licensing Branch 3. 80/12/08. 2pp. 07286:212.
- B012230259 Submits addl info re containment boundary fracture toughness in response to B01117 ltr. Integrity of containment boundary will be contained under normal conditions & is in compliance w/General Design Criteria 81.
 MITIL.R. L. Public Borvice Electric & Gas Co. of New Jersay. B0/12/19. Spp. 07314:021.
- O. Inspection reports, IE Bulletins & correspondence
- 8012170397 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. ORIER, B. H. Region 1. Philadelphia. Office of the Director. 80/10/30. ip. 07267:098.
- B012190703 Forwards IE Insp Repts 50-272/80-21 & 50-311/80-17 on 800901-1011. No noncompliance noted. BRUNKER.E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/30. 2pp. 07287:359.
- --8012190707 IE Insp Repts 50-272/80-21 & 50-311/80-17 on 800901-1011.No noncompliance noted Major areas inspected:logs & records, licensee events, operational safety verification & IE bulletins.

 NORRHOLM, L. J., HILL, W. M. Region 1, Philadelphia, Office of the Director, KEIMIG.R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/28. 17pp. 07288:001.
- 8012300173 Forwards IE Insp Repts 50-272/80-27 & 50-311/80-20 on 801014-17 & notice of violation. CARLSON.R.T. Region i. Philadelphia, Reactor Construction & Engineering Support Branch. 80/11/05. 2pp. 07356:273.
- --8012330177 Notice of violation from insp on 801014-17.

 * Region 1, Philadelphia, Office of the Director. 80/11/04. 1p. 07356:275.
- ~-8012300185 IE Insp Repts 50~272/80~27 & 50~311/80~20 on 801014~17.
 Noncompliance noted: I/Z of fire brigade members not trained in fire fighting & use of owergency breathing equipment & no continuous fire watch posted on fire doors.
 KOLTAY.P.S. Region i. Philadelphia: Office of the Director. EDNETER.B D. Region i., Philadelphia: Reactor Construction & Engineering Support Branch. 80/11/04. 6pp. 07356: 276.
- 8012120040 Forwards IE Builetin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER. B.H. Region 1. Philadelphia. Office of the Director. 80/11/06. 1p. 07230: 279.

- B012190355 Informs util of issuance of new NRC personnel identification badges: effective after B01130. Example encl. MARTIN. H. J. Region 1, Philadelphia, Safeguards Branch. B0/11/06. 2pp. 07286:125.
- 8012030794 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Dupressurization." No written response required. ORIER, B. H. Region 1. Philadelphia, Office of the Director. 80/11/07. 1p. 07150:224.
- 8012080426 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/10. 1p. 07182:309.
- B012040047 Forwards IE Bulletin B0-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, B.H. Region i, Philadelphia, Office of the Director. B0/11/14. ip. 07169:357.
- 8012220679 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER.B. H. Region i, Philadelphia, Office of the Director. 80/11/19. ip. 07293:116.
- 8012040497 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." Written response required, Requests info on manpower expended. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07169:172.
- 8012030595 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fivid." No written response required. CRIER, B. H. Region i, Philadelphia, Office of the Director. 80/11/24, ip. 07174:036.
- 8012020197 Forwards proprietary & nonproprietary versions of Revision 1, Vols 1 & 2, "Environ Qualification Review Rept." Applications & affidavit for withholding info (ref 10CFR2.790), MITTL.R.L. Fublic Service Electric & Qas Co. of New Jersey. 80/11/26. 12pp. 07321:330.
- --8012020148 Nonproprietary version, Revision (.Vol 1, "Environ Qualification Review Rept." * Public Barvice Electric & Gas Co. of New Jersey. 80/12/01, 260pp. 03754:185.
- --8012020158 Nonproprietary version. Revision i.Vol 2. "Environ Qualification Review Rept." * Public Bervice Electric & Gas Go. of New Jersey. 80/12/01. 420pp. 03755:074.
- R. Periodic operating reports & related correspondence
- 8012160340 Forwards monthly operating rept for Nov 1980, MIDURA.H. J. Public Bervice Electric & Gas Co. of New Jersey, 80/12/11. 1p. 07252: 324.
- --8012160343 Monthly operating rept for Nov 1980. MILLER, L. K. Public Service Electric & Gas Co. of New Jersey. 80/12/11. 6pp. 07252:325.
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

 F. Sacurity, medical, emergency & fire protection plans

- B012300274 Requests revision of emergency plan to include description of potential complicating factors caused by earthquakes which might initiate accidents. Concerns should include availability of support to onsite staff. REID, R.W. Operating Reactors Branch 4, 80/11/24, 3pp. 07358:289.
- B012090331 Confirms that util will respond to NRC B01024 comments re safeguards contingency plan (Amend 7 to security plan) when submitting Amend 8 to security plan on B01215. WALRRIDDE.W C. Bacramento Municipal Utility District. B0/12/02. ip. 07201:162.

The state of the second second

- BD12090411 Responds to NRC B01105 ltr indicating need for add1 revisions to guard training plan. Comatement will be contained in revised pages to guard training plan & will be submitted B01215.

 MALBRIDGE M.C. Sacramento Municipal Utility District. 80/12/02.
 1p. 07207:132.
- B012170309 Forwards security plan, including revised safeguards contingancy plan. Plan withheld (ref 10CFR2,790).
 MATTIKOE.J.J. Bacramento Municipal Utility District. B0/12/12.
 2pp. 07264:111.
- B012170339 Forwards Amend 2 to guard training & qualifications plan, consisting of revised Page 3-1. Page withheld (ruf 10CFR2,770).
 MATTIMOE,J. J. Sacramento Municipal Utility District. B0/12/12, ip. 07270:172.
- 8012180306 Forwards updated 1979-1980 engineering & const schedule for plant security mods dtd 801024 Schedule withheld (ref 10CFR2.790).
 MATTINDE.J.J. Sacramento Municipal Utility District. 80/12/12. 1p. 07272:355.
- 8012290204 Forwards corrected Revision 2 to guard training & qualification plan to include revision bars omitted from pages sent B01212. Encl withheld (ref lOCFR2. 790). MODRE, R.C. Sacramento Municipal Utility District. 80/12/17. ip. 07344:169.
- 9. Adjudicatory correspondence
- BD12110351 Requests, on behalf of util, extension until B1010B to request hearing re NRC B01118 order for mod to license. Requested extension would allow for better understanding of order requirements.

 BILBERO, J. E. Shaw, Pittman, Potts & Trowbridge. B0/12/05. 2pp. 07224:139.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8012020784 Responds to 790787 requests that ACRS address consistency of actual component failure experience w/that projected in WASH-1400 & that ACRS dotermine probabilities of accurrence re Davis-Besse 770924 & Rancho Seco 780320 events. PLESBET, N.S. ACRS Advisory Committee on Reactor Safeguards. 80/02/20. Bpp. 07130:348.
- --8017020797 Forwards "Analysis of Feedwater Transient Sequences in B&W NBES." to aid in formulating response to M Udall 790729 ltm.
 Using WASH-1400 event trees & data directly gives meaninglass results.
 ABBOTT, E., BICKEL, J., KABTENDERO, N. ACRS Advisory Committee on Reactor Safeguards. 80/02/07. 1p. 07141:015.
- --B012020804 "Analysis of Feedwater Transient Sequences in ILW NBSS."
 ABBOTT.E.E., BICKEL, J., KABTENBERG, H. E. ACRS Advisory Committee
 on Reactor Safeguards. B0/02/07. 2ipp. 07141:016.
- --8012020811 "Evaluation of Davis-Besse & Rancho Seco Feedwater Transients on 770924 & 780320 Using WASH-1400 Data." * Commissioners. 80/02/20. 16pp. 07141:037.
- P. Operating license stage documents & correspondence
- B012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake.

 EIBENHUT.D.O. Division of Licensing, 80/10/21, 4pp.
- 8012160050 Ltr to operating plant licensers, CL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISENHUT.D. O. Division of Licensing. 80/10/31. 7pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implamentation dates will be mat must be sent within 45 days. Wo encl.
 EISENHUT, D. G. Division of Licensing. 80/11/13. 1p.
- 8012120260 Forwards Amend 30 to License DPR-54, safety svaluation & notice of issuance & availability.
 REID.R.W. Operating Reactors Branch 4. 80/11/21. 3pp. 07237:201.

- --8012120266 Amend 30 to License DPR-54 revising safety limits & limiting safety sys settings section of Tech Specs to permit operation at flux-to-flux ratio of 1.08.
 REID,R.W. Operating Reactors Branch 4. 80/11/21. 12pp. 07237: 204.
- --8012120272 Bafety evaluation supporting Amend 30 to License DPR-54.

 * Office of Nuclear Reactor Regulation, Director. 80/11/21, 3pp. 07237:216.
- --8012120278 Notice of issuance & availability of Amend 30 to License DPR-54.
 REIO.R.M. Operating Reactors Branch 4. 80/11/21. 2pp. 07237;219.
- 8012070415 Provides info describing proposed bldgs at facility in response to Padovan request. Three addibldgs will house addirequired equipment required to conform w/NUREO-0737. WALBRIDGS.W.C. Sacramento Municipal Utility District. 80/11/26.4pp. 07207:122.
- B012190547 "Bafety Evaluation Rept, Inservice Testing Program, Rancho Seco Nuclear Generating Station:" 791018-810618. ROCKHOLD, H. C., FEHRINGER, J. M. 16aho Netional Engineering Laboratory. FIN A-6258. 8012190547. B0/11/30. 52pp. 07288:129.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement Btate burial site conditions. Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director, 80/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. BO/11/06. Bpp.
- 8012160507 Clarifies position expressed in 760722 committal re QA program Mgt audit now covered by annual joint util audit, MATTHOE, J. J. Sacramento Municipal Utility District. 80/12/09. 1p. 07263:104.
- 6012170458 Forwards nonproprietary & proprietary updated calculations re turbine disc integrity in response to NRC 800225 request. Application for withholding encl (ref 10CFR2.790). Proprietary calculations available in Central Files only, MATTIMOS.J.J. Sacramento Municipal Utility District. 80/12/09. 29pp. 07269:240.
- 8012220730 Notification of 801216 meeting w/8£W owners group in Bethasda.MD re resolution programs & schedules of TMI-2 task action plan items. THROM.E.D. Reactor Systems Branch. 80/12/09. 2pp.
- 8012230375 Forwards Bechtel 801201 ltr detailing remote sensing imagery used in foothills fault sys study, in response to I Alterman 801224 telcon request.

 MATFIRDE, J. Sacramento Municipal Utility District. 80/12/09. 4pp. 07312:242.
- B012240474 Notification of B01216 meeting w/B&H owners group for small break LOCAs in Bethesda. HD for presentation of programs & schedules for resolutions of TNI-2 tesk action plan items. THROM.E.D. Reactor Systems Branch. B0/12/09. 2pp.
- 8012140487 Forwards revised plant organizational chart for proposed Amend 72, per 801210 telcon. COLOMBORN W Sacramento Municipal Utility District. 80/12/11. Ip. 07263:108.
- --8012160492 Tech Epecs chart re plant organization, + Sacramento Municipal Utility District, 80/12/11, ip. 07280;109.
- 80:12:1803:10 Requests assistance in locating specific details or boundary conditions needed for simulating overcooling transfent. SAHA: P. Brookhaven National Laboratory. 80/12/11, 2pp. 07273:048.
- 8012220309 Forwards commitments for implementation of items in NUREO-0737, "Clarification of TMI Action Flan Requirements." MATTIORE.J.J. Bacramento Municipal Utility District. 80/12/15. 11pp. 07303:256.

- 8012290301 Forwards proposed Amend 73 re miscellaneous water evaporator designed to operate w/o interfering w/safe plant operations. Schematic & Table 2.6-1 re radioactive liquid sangling & analysis encl.
 MATTIMOE.U.J. Sacramento Municipal Utility District. 80/12/17. 3pp. 07346:111.
- --B012270303 Proposed revision to Tech Spec Table 2.6-1 for radioactive liquid sampling & analysis, submitted in connection w/proposed Amend 73.

 * Sacramento Municipal Utility District. 80/12/17. 2pp. 07346:114.
- 8012300619 Notifies that info requested in NRC 801125, "Inservice Insp Programs for Prestressed Concrete Containment Structure," furnished in Aug 1975, Feb 1976 & June 1978, in "Containment Structure Post-Tensioning Sys Surveillance Test" repts. MATTINGE.J. J. Bacramento Municipal Utility District. 80/12/17, 1p. 07346:155.
- 8012290228 Forwards water evaporator P&ID. in response to 801219 convergation re proposed Tech Spec Amend 73. COLDM8D.R.W. Bacramento Municipal Utility District. B0/12/19. 1p. 07042:341.
- Q. Inspection reports, IE Bulletins & correspondence
- B01212024B Forwards IE Insp Rept 50-312/80-29 on B00901-30. No noncompliance noted. CREMS, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. B0/10/17. 2pp. 07236:207.
- --8012120253 IE Insp Rept 50-312/80-29 on 800901-30. No noncompliance noted Major areas inspected monthly maint & surveillance observation; review of plant operations & LERs. CANTER, H. L. O'BRIEN. J. Region 5, San Francisco, Office of the Director. FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/10/17. 11pp. 07236:209.
- 8012040336 Forwards IE Insp Rept 50-312/80-27 on 800929-1003. No noncompliance noted. CREMSU.L. Region 3. Ban Francisco. Reactor Operations Nuclear Support Branch. 80/10/23. 2pp. 07163:211.
- --8012040309 IE Insp Rept 50-312/80-27 on 800929-1003. No noncompliance noted. Major areas inspected: design change control program & followup on previous insp findings.
 ZWETZTG.O.B. Region 5, San Francisco. Office of the Director.
 FAULKENGERRY.B. Region 5, San Francisco. Reactor Operations Nuclear Support Branch. 80/10/22, 8pp. 07163:213.
- 8012170/00 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 ENDELKEN.R.H. Region S. Gan Francisco, Office of the Director.
 80/10/24. ip. 07266:077.
- 8012170414 Forwards IE Info Notice 80-38, "Gracting in Charging Pump Casing Cladding." No written response required. ENCELKENJR. H. Region 5, San Francisco, Office of the Director, 80/10/30. 1p. 07268:042.
- 8012170836 Forwards IE Info Notice 80-39, "Malfunction of Sciencid Valves Mfg by Valcor Engineering Corp." No written response is required.

 ENGELMENTR.H. Region 5, San Francisco, Office of the Director. 80/10/31. 1p. 07266:025.
- 80/2120216 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.inc." Written response required.
 ENGELKEN, R. H. Region S. Ban Francisco, Office of the Director.
 80/11/06. 1p. 07228:28H.
- 8012030936 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required, EMPELKEHJR.H. Region 5. San Francisco, Office of the Director, 80/11/07. 1p. 07150:187.
- 8012080621 Forwards IE Info Notice 80-41, "Failure of Bwing Check Valva in Decay Heat Removal Sys at Davis Besse Unit i." No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/10. 1p. 07183:026.
- 8012040220 Forwards IE Builetin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ENGELWEBHR.H. Region 5, San Francisco, Office of the Director, 80/11/14, 1p. 07158:136.

- 8012100051 Forwards IE Insp Rept 50-312/80-33 on 801001-31.No noncompliance noted. CREMS,J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/11/17. 2pp. 07219.077.
- --B012100056 IE Insp Rept 50-312/80-33 on 801001-31, No nancompliance noted. Major areas inspected: plant operations & plant trips. CANTER, H. L., O'BRIEN, J. P. Region 5: San Francisco, Office of the Director. FAULKENBERRY, B. Region 5: San Francisco, Reactor Operations Nuclear Support Branch. 80/11/14. 8pp. 07219:079.
- 8012040461 Forwards IE Bulletin BO-24, "Prevention of Damage Due to Water Leakage Inside Containment." Nritten response required Requests info on manpower expended. ENGELKERIR. H. Region 5, San Francisco, Office of the Director. BO/11/21. 1p. 107163:317.
- 8012160098 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydravlic Snubber Fluid." No response required. ENGELKEN,R.H. Region 5. San Francisco, Office of the Director. 80/11/24. lp. 07262:112.
- 8012160118 Forwards Suppl 1 to IE Info Notice 80-27, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/26. 1p. 07262-082.
- R. Periodic operating reports & related correspondence
- 8012120480 Forwards monthly operating rept for Nov 1980. RODRIGUEI,R.J. Sacramento Municipal Utility District. 80/12/04. ip. 07236:025.
- --8012120484 Monthly operating rapt for Nov 1780. COLOMBO.R Sacramento Municipal Utility District, 60/11/30. 7pp. 07236:026.
- B. Reportable occurrences, LERs & related correspondence
- 8012090390 Forwards LER 80-044/03L-0. MATTIKOE, J. J. Sacramento Municipal Utility District. 80/12/03. 2pp. 07200:004.
- --8012070378 LER 80-046/03L-0: on 801104 & 1128, overspeed trip lever on turbine for automatic feedwater pump P-318 was found in apparent tripped condition. Cause could not be determined. Daily visual checks initiated. GLOMBG.R.W. Sacramento Municipal Utility District. 80/12/03. ip. 07200:005.
- 8012290016 PNS-V-80-010:on 801205, two security guards on patrol heard what was believed to be 3-5 shots & initiated security alert. Security force & local police responded & initiated search w/negative results.

 MORTEMBEN.H., SCHUSTER.K. D., NORDERHAUG.L., Region 5, Ban Francisco: Office of the Director. 80/12/08. 1p. 07339:077.
- 8012300467 RO 80-47: documentation search for flow transmitter FT-20001 determined instrument not qualified for svc environ. Continued operation justified since alternate flow path exists through auxiliary spray line. COLUMBD, R W. Sacramento Municipal Utility District. 80/12/22. 2pp. 07357:208.
- DOCKET 50-313 ARKANSAS NUCLEAR UNE, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8012150039 Discusses util 800619 response to NRC fire protection safety evaluation. Item 3, 12, cable penetration fire stops, is acceptable based on tests performed & commitment to replace seals.

 REID, R. W. Operating Reactors Branch 4, 80/10/24, 2pp. 07240:340.
- B012230105 Notifies of Commission approval of encl interim rule suspending previously approved completion dates for fire protection mods. Specific schedules for mods will be effective pending publication of final rule.

 EISENHUT, D. G. Division of Licensing. 80/11/18. 5pp. 07311:087.
- 8012290433 Releases public version of util emergency plan. FELTON, J. M. Division of Rules and Records. 80/12/16. 1p. 07339:084.
- --8012290438 Public version of amended smergency plan Revision 58.

 * Arkansas Power & Light Co. 79/04/16. 200pp. 07339:085.

Adjudicatory correspondence

- 80120B0472 Requests hearing on issue of whether all safety-related electrical equipment should be environmentally qualified in accordance w/Ofc of Nuclear Reactor Regulation guidelines or NUREO-05BB.
 REYNOLDS: N. S. Debevoise & Liberman. 80/12/04. 2gp. 07184:282.
- P. Operating license stage documents & correspondence
- 8012020783 Forwards seismic qualifications of auxiliary feedwater system operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following sarthquake.

 EISENHUT, D. O. Division of Licensing. 80/10/21. 4pp. 06916:001.
- B012220763 Ltr to all power reactor licensees forwarding NUREG-0619, "BNR Feedwater Noizle & Control Rod Drive Return Line Noizle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. N/o encl. E1SEKHUT, D. G. Division of Licensing. B0/11/13. 19. 07308:348.
- 8012030839 Forwards Performance Appraisal Branch repts & mgt evaluation tree & user's guide. Info provided to ensure that licensees have opportunity to review strengths & weaknosses for program applicability. W/o encls. SEYFRIT. K. V. Region 4, Dallas, Office of the Director. 80/11/14, 1p. 07149:008.
- 8012070106 Forwards Amends 48 & 18 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability. REID,R.W. Operating Reactors Branch 4. 80/11/19. 3pp. 07197:190.
- --8012090110 Amends 48 & 18 to Licenses DPR-51 & NPF-6, respectively, including requirement to maintain safeguards contingency glan to be implemented within 30 days of Commission approval.
 REID.R.W. Operating Reactors Branch 4. 80/11/19. 4pp. 07199:193.
- --B012090115 Notice of issuance & availability of Amends 48 & 18 to Licenses DPR-31 & NPF-6, respectively. REID.R.W. Operating Reactors Branch 4. 80/11/19. 2pp. 07199:197.
- 8012100055 Forwards Parameter, Inc final rept, "Metallurgical Analysis of Failed Turbine Casing Bolt From AR Power & Light-Unit 1." JORDANIE L. Office of Inspection & Enforcement. Office of the Director. 60/11/25, 1p. 07217:054.
- ---8012100073 "Metallurgical Analysis of Failed Turbine Casing Holt From AR Power & Light-Unit 1."
 PROFT.T.L. Parameter, Inc. PROFT.T.L. Technimet Corp.
 NRC-05-80-251. 80/09/09. 29pp. 07217:055.
- 8012080399 Forwards proposed changes to Tech Specs incorporating NRC STS definition of "operable" & adding generically applicable 11 miting condition of operation & actions required for degraded condition. Affidavit encl.

 CAVAMAUGH, W. Arkansas Power & Light Co. 80/11/28, 2pp. 07182:154.
- 8012090180 Forwards figures referenced in 801031 submittal of proposed Tach Spec changes re hydrogen-oxygen concentration limits in waste gas sys. Figures were inadvertently omitted at time of submittal.

 TRIMBLE.D.C. Ariansas Power & Light Co. 80/12/02. 3pp. 07207: EBB.
- B012190174 Forwards drawing & response to NRC B01125 questions re util B01203 proposal concerning emergency feedwater sys upgrade. TRIMBLE, D. C. Arkansas Power & Light Co. B0/12/03. 12pp. 07236:159.
- B0122204B5 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Appeament State burial site conditions. Forwards results of IF survey.

 DENION.H.R. Office of Nuclear Reactor Regulation. Director.

 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BAKDART, R. L. Effluent Treatment Systems Branch. 80/11/06. Spp.
- 8012270496 Informs that 800919 topical rept re qualification of reactor physics methods for application to PURs has been determined to contain proprietary info & will be withheld as requested. REID.R.W. Operating Reactors Branch 4, 80/12/05, 3pp. 07395:159.

- BOI2:30049 Forwards supporting data to util 790309 application to amend License DPR-51.changing Tech Specs for frequency of fish impingement samples in response to RRC request Util HO1:25 internal memn to Tech Spec change entl. TRIMBLE, D. C. Arkansas Power & Light Co. 80/12/09. 5pp. 07240:335.
- 8012220230 Notification of 801216 meeting w/B&W owners group in Bethesda.HD re resolution programs & schedules of TM1-2 task action plan items. THROM:E.B. Reactor Systems Branch, 80/12/09, 2pp.
- B012249474 Notification of B01214 meeting w/D&W owners group for small break LOCAs in Bethesda.MD for presentation of programs & schedules for resolutions of TMI-2 task action plan items. THROM.E.D. Reactor Systems Branch. B0/12/09. 2pp.
- B012300340 Agrees to estonsion until B01205 for plant safety committee to become operational.

 CLARK.R.A. Operating Reactors Branch 3. REID.R.W. Operating Reactors Branch 4. 80/12/10. 2pp. 07358:361.
- 8012230482 Summarizes util concerns re NRC 801024 order for mod of licenses requiring environ qualification of Class (E electrical equipment by 820630, Requests hearing to resolve concerns re implementation methods.

 CAYAKAUOH. N. Arkansas Fower & Light Co. 80/12/16. 5pp. 07312:287.
- E01229018B Forwards commitments to Itil action plan requirements per NUREO-0737. Shift technical advisor training program & procedures to verify correct performance of operating activities will be completed by B10101. CAVARAUGH.W. Arkansas Power & Light Co. 80/12/19. 12pp. 07338: 242.
- Q. Inspection reports, IR Bulletins & correspondence
- 8012120174 Responds to IE Bulletin 80-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." Util does not use specific raisy in logic matrices.

 TRIMBLE, D. C. Arkansas Power & Light Co. 80/08/08. 1p. 07236:185.
- 8012120196 Responds to IE Bulletin 60-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Fellowing Secondary Side High Energy Line Rupture." Facilities are adequately designed to maintain HPI pump cooling.

 TRIMBLE D.C. Arkansas Power & Light Co. 80/09/22. 3pp. 07240:010.
- BO12220587 Requests extension until 810101 for response to IE Bulletin 79-018. Suppl 2. "Environ Qualification of Class IE Equipment." If request cannot be granted informally, NRC requested to treat live as application to amend OL. CAVANAUOH, W. Arkansas Power & Light Co. 80/10/09. 4pp. 07299: 222.
- 801212059? Responds to Item 2 of IE Bulletin 79-17.Revision I, "Pipe Cracks in Stagnant Borated Nater Sys at PUR Plants."
 Required piping insps completed 801010. Written rept will be submitted by 801109.
 TRIMBLE, D. C. Arkansas Power & Light Co. 80/10/16. ip. 07231: 357.
- B012120305 Forwards IE Insp Repts 50-313/80-18 & 59-368/80-18 on 800922-26 & notice of deviation. KADBEN.O.L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. 80/10/20. 2pp. 07231:297.
- --8012120311 Notice of deviation from insp on 800922-26.
 * Region 4, Dallas, Office of the Director, 80/10/17. ip. 07231:299.
- --B012120326 iE Insp Repts 50-313/80-18 & 50-368/80-18 on B00922-26.
 Noncompliance noted tampling program not established per IE
 Bulletin 80-10 response complement.
 DEAM: B. HURMICUTT, D. K. Region 4, Dalias, Office of the Director, 9A0LIARDD, J. E. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 80/10/17. 4pp. 07231:300.
- B012120191 Responds to IE Bullstin 80-15; "Possible Loss of Emergency Notification Bys (ENS) w/Loss of Offsite Power." Test verified that all extensions remained fully operable from facility to NRC upon loss of offsite power.

 CAVANAUGH.W Arkansas Power & Light Co. 80/10/22, 3pp. 07236:186.
- 8012080829 Forwards IE Insp Repts 50-319/80-12 & 50-368/80-12 on 800617-20 & 6714-18. MADBEM.O.L. Region 4. Dallas, Reactor Operations Nuclear Bupport Branch. 80/10/23. 2pp. 07180:200.

- --B012080834 IE Insp Repts 30-313/80-12 & 50-368/80-12 on 800617-20 & 0714-18. Noncompliance noted: failure to take prompt corrective action & failure to meet requalifications training program.
 ANESHANSLEY.M., DEAN.S.R., JAUDON, J.P. Region 4, Dellas, Office of the Director. 80/10/21, 20pp. 07180:202.
- B012170322 Forwards Suppl 3 to 1E Builetin 79-01B, "Environ Qualification of Class 1E Equipment," No written response required.

 SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/10/24.

 1p. 07268:348.
- 8D12160565 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required SEYFRIT.K.V. Region 4, Dallas. Office of the Director. 80/10/27. 1p. 07262:144.
- 8012120106 Revises 800702 response to Item 2 of IE Bulletin 80-10, "Contamination of Nonradioactive Sys..." Routine sampling program uill be established by 810801 for condensate storage tanks & instrument air sys. TRIMBLE, D. C. Arkansas Power & Light Co. 80/10/30. 1p. 07231:358.
- 8012170362 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. SEYPRIT.K.V. Region 4. Dallas. Office of the Director. 80/10/30. 1p. 07269:030.
- BO12020144 Forwards response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" & 800919 revised orders for mod of licenses. Remaining open items refer to changing requirements rather than actual deficiencies.
 CAVANIAUOH. W. Arkansas Power & Light Co. 80/10/91. 700pp. 06916:001.
- 8012120224 Forwards IE Insp Repts 50-313/80-17 & 50-369/80-17 on 800822-0921 & notice of violation.

 HADREN, G. L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 80/10/31. 2pp. 07237:184.
- --8012120231 Notice of violation from insp on 800822-0921.
 4 Region 4. Dalias. Office of the Director. 80/10/31, 2pp. 07237:386.
- --B012120237 IE Insp Repts 30-313/80-17 & 50-368/80-17 on 800822-0921.
 Noncompliance noted: inoperable containment cobling units,
 failure to submit LER & inadequate control of containment
 bldg purge.
 JOHNBON W. D., CALLAN, L. J., HUNNICUIT, D. M. Region 4, Dallas, Office
 of the Director. 80/10/31. i3pp. 07237:188.
- 8012130021 Forwards response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," fulfilling NRC 800919 orders for mod of license. Util is currently evaluating each component to determine documentation status. Myo encl. CAVANAUSH, W. Arkansas Power & Light Co. 80/10/31. 8pp. 07241:044.
- 8012170816 Forwards IE Info Notice 80-37, "Malfunction of Bolenoid Valves Mfg by Valcor Engineering Corp." No written response is required. GEYFRIT.X. V. Region 4. Dallas, Office of the Director. 80/10/31. 1p. 07266:013
- 8012230028 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Cenerators." No written response required. BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/10/3i. ip. 07311:210.
- 8012100625 Forwards IE Bulletin 80-21, "Vaive Yokes Supplied by Malcolm Foundry Co. Inc." Kritten response required. BEYFRIT.K. V. Region 4, Dallas, Office of the Director. 80/11/06, ip. 07220:080.
- 8012030707 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Gause Reactor Depressur(ization " No written response required. SEYFRII.K. V. Region 4, Dallas, Office of the Director. 80/11/07. ip. 07150:175.
- GO12080595 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/i1/10. ip. 07183:014.

- 8012040024 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. SE/FRIT, K. V. Region 4, Dallas, Office of the Director. 80/11/14. 10. 07167;301.
- B012240323 Ack receipt of B01030 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-313/80-18 & 50-366/80-18. MADBEN,O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. B0/11/23. ip. 07325:138.
- --8012240331 Responds to NRC B01020 ltr re violations noted in IE Insp Repts 30-313/80-18 & 50-368/80-18. Corrective actions: Bampling analysis or monitoring program established on B00801:revised. TRIMBLE, D. C. Arkansas Power & Light Co. 80/10/30. 2pp.
- 8012080342 Responds to NRC 800613 ltr re suceptions to IE Bulletins 79-05,79-05A & 79-05B, "Nuclear Incident at TMI." Cold shutdown defined & method clarified Manual trip on loss of offsite power is unnecessary.

 TRIMBLE, D. C. Arkansas Power & Light Co 80/11/28, 2pp. 07182:121.
- --8012080347 Proposed Tech Specs. Sections 1.0 & 3.0, incorporating NRC std definition of "operable" & changing limiting conditions for operation, respectively.

 ** Arkansas Power & Light Co. 80/11/28. 30pp. 07182;123.
- 8012240033 Ack receipt of 801121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-17 & 50-328/80-17. MADSEN,O.L. Region 4. Dalles, Reactor Operations Nuclear Support Branch. 80/12/02.
- --8012240038 Responds to NRC 801031 ltr re violations noted in IE Insp Repts 50-313/80-17 & 50-368/80-17. Corrective action: shift supervisor counselled re proper coordination & control of all operations. TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/21. 7pp. 07324:223.
- B012110384 Ack receipt of B01112 ltr informing NRC of steps taken to correct violations noted in IE insp rept & of payment of civil panalties.
 THOMPSON, D. Office of Inspection & Enforcement, Office of the Director. B0/12/04. 1p. 07223:296.
- R. Periodic operating reports & related correspondence
- 8012050517 Forwards intake impingement data for Oct 1980. TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/28. ip. 06915:001.
- --8012050523 Intake impingement data for Oct 1980.
 4 Arkansas Power & Light Co. 80/11/26 16pp. 06915:001.
- 8012150409 Forwards monthly operating rapt for Nov 1980. TRIMBLE, D. C. Arkansas Power & Light Co. 80/12/12. 1p. 07252:347.
- --8012160411 Monthly operating rept for Nov 1980. BRANLETT.L. 8 Arkansas Power & Light Co. 80/12/12. 5pp. 07252:348
- 8. Reportable occurrances, LERs & related correspondence
- 8012010354 Forwards updated LER 79-013/03X-1.
 TRIMBLE,D.C. Arkansas Power & Light Co. 80/11/21. 1p. 07092;174.
- --8012010361 Updated LER 79-013/03X-1: on 790808, decay heat boron concentration not monitored during prescribed interval. Gaused by personnel error. Radiochemistry dept instructed to verify sample lineup through operations. SHIVELY.C.N. Arkansas Power & Light Co. 80/11/21. 1p. 07092:175.
- 8012010079 Forwards updated LER 80-016/03X-2.
 TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/21. ip. 07095: 085.
- --8012010404 Updated LER 80-016/03X-2; on 800611, proper flow through flydrogen purge sys could not be obtained. Caused by rust scale being lodged in check valves HPA-4,-10 & -128, Valves cleaned. Svc water sclenoid valves added to ventilation fans. BHIVELY, C. N. Arkensas Power & Light Co. 80/11/21. 1p. 07093-084.
- 8012090431 Forwards LER 80-039/93L-0. TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/25. 1p. 07203:040.

- --8012090445 LER 80-039/03L on 801028, exhaust fan VEF-37A on lead hydrogen purge sys tripped. Caused by short in control sys due to high registance connections at solenoid valve terminals. Rectifier & control fuse replaced & leads cleaned. BRAMLETI.L.S. Arkansas Power & Light Co. 80/11/25. 2pp. 072/3:041.
- 8012020463 Forwards updated LER 80-011/03X-8.
 TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/26 1p. 07143:244.
- --8012920466 Updated LER 80-011/03X-8: on 800401, IE Bulletin 79-14 review revealed 44 hangers inoperble, Hanger design change prepared & hangers modified. List of affected hangers encl. SHIVELLY.C.N. Arkansas Power & Light Co. 80/11/26. 2pp. 07143: 249.
- DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1
 F. Security, medical, emergency & fire protection plans
- 8012040587 Responds to RS Hunter 801010 ltr re use of health physics network Requests that encl info be considered as official document on how health physics network is to be used & who may activate it.

 KEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/11/14. 3pp. 07170:091.
- --8012040598 Expresses concern & uncertainty re intended purposes & circumstances re use of health physics network.

 HUNTER:R.8 Indiana & Michigan Electric Co. 80/10/10. 3pp.
- B012020977 Discusses planned mods to emergency notification sys & health physics network. NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys. W/o encl health physics network manual. KEPPLER. J. Q. Region J. Chicago. Diffice of the Director. B0/11/19. 2pp. 07148:345.
- 8012100533 Responds to NRC 801031 itr requiring resubmittal of contingency plan within 30 days. Requests 45-day extension due to nature of info.

 HUNIER, R. B. Indiana & Michigan Electric Co. 80/12/04. ip. 07222:104.
- P. Operating license stage documents & correspondence
- B012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PKRs & describes program NRC is undertaking to review capability of operating PKRs to remove decay heat following earthquake.

 EIBENHUT, D. O. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 inplementation dates will be met. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012040320 Forwards "Estimate of Ultimate Pressure Capacity of Containment Btructure," for comment.Requests that meeting be arranged after review.
 VAROA,S.A. Operating Reactors Branch 1. 80/11/06. 2pp. 06915:001.
- --8012040325 "Estimates of Ultimate Pressure Capacity of Containment Structure." HARSTEAD, O. A. Harstead Engineering Associates, Inc. 80/09/26. 47pp. 05915:001.
- 80122v0563 Ltr to all power reactor licensees forwarding NUREG-0619, "BWR Feedwater Norsle & Control Rod Drive Return Line Norsle Cracking." Confirmation that implementation dates will be met must be sent within 45 days M/o encl. EISENHUT, D. G. Division of Licensing. 80/11/13. 1p.
- B012220489 Responds to B00911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions Forwards results of IE survey. DENION-H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220505 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.

2310002 Confirms 801229 meeting w/util at site to discuss evaluation f regulatory performance. EPPLER.J.O. Region 3, Chicago, Office of the Director. 80/12/05. p. 07371:064.

2180312 Forwards addl info re automatic initiation & flow indication or auxiliary feedwater sys. Flow indicators fed from balance if plant inverter uninterruptable power source fed from balance D battery of Unit 2.
UNIER, R. S. Indiana & Michigan Electric Co. 90/12/10. 4pp. 7273:044.

218-315 Application to amend Licenses DPR-58 & DPR-74, consisting of ropused Tech Specs & license conditions incorporating lategory A Lessons Learned requirements, in response to NRC 1007-02 ltr.
UNTER.R.S. Indiana & Michigan Electric Co. 80/12/10. 7pp.
17272:356

012180317 Progosed changes to Tech Specs 3/4 for Unit i, incorporating Category A Lessons Learned automatic initiation requirements into engineered safety feature actuation sys.

Indiana & Michigan Electric Co. 80/12/10. 23pp. 07273:001.

012:8032: Proposed changes to Tech Specs 3/4 for Unit 2.incorporating Category A Lessons Learned automatic initiation requirements into engineered safety feature actuation sys. * Indiana & Michigan Electric Co. 80/12/10. 20pp. 07273:024.

2310259 Notification of 801218 meeting w/vtils in Bethesda.HD to Useuss ultimate strength of containments & hydrogen control weasures. UNRR.S. Operating Reactors Branch 1. 80/12/11. 3pp. 07370:035.

Inspection reports. IE Bulletins & correspondence

2110117 Forwards IE Insp Repts 50-315/80-13 & 50-316/80-11 on 190616-0727. No noncompliance noted. IEISIMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Iranch. 80/10/22. 2pp. 07224:204.

0012110124 IE Insp Repts 50-315/80-13 & 50-316/80-11 on 800616-0927. No noncompliance noted Major areas inspected operational safety verification, surveillance observation, safety sys challenges & refueling activities. MASSER.E., SMANSON.E.R., DUSRY, N.E. Region 3, Chicago, Office of the Director. 80/10/22. 4pp. 07224:206.

2170506 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & teactor Cavity Flooding at Indian Point Unit 2." No written esponse required.
LEPPLER.J.G. Region 3, Chicago, Office of the Director. 80/10/24.
19. 07268:072.

2020743 Forwards three Performance Appraisal Branch insp repts & order of the second o

12020566 Forwards info re access of HRC & NRC contractor personnel for health physics program appraisal scheduled for approx two was beginning 801220. LEPPLER.J.G. Region 3. Chicago. Office of the Director. 80/11/21.

12040678 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. (EPPLER.J.O. Region 3: Chicago, Office of the Director. 80/11/21. 2pp. 07169:099.

1208003: Forwards IE Info Notice 80-42. "Effect of Radiation on dydraulic Enubber Fluid." No written response required. KEPPLER, J. Q. Region 3. Chicago, Office of the Director. BO/11/24.

s & clearance levels for i on Sept 1980

he Director. 80/11/25.

roken Studs on

ector. 80/11/26.

- 8012180414 Corrects 801121 ltr re health physics appraisal Onsite phase of appraisal to begin 801208 not 801220. & L.J Heuter should be added to Encl 1.

 KEPPLER.J. Q. Region 3. Chicago. Office of the Director. 80/12/01.

 1p. 07271:160.
- 8012160174 Forwards IE Insp Rept 50-315/80-18 on 801118-21.No noncompliance moted. HING.J.A. Region 3, Chicago, Safeguards Branch. 80/12/04. 2pp. 07263:039.
- --BD12160192 IF Insp Rept 50-315/80-18 on 80118-21. No noncompliance noted. Major areas inspected: Pacility organization, operation, measurement, controls & shipping, receiving, storage & internal controls. Details withheld (ref 10CFR2.790).
 FIRLEY,A.G., PATTERSON.J.P. Region 3. Chicago, Office of the Director. HIND, J. A. Region 3. Chicago, Safeguards Branch. 80/12/03. 2pp. 07263:041.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-01B re environ qualification of Class IE equipment. HAYES, D. W. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp.
- 8. Reportable occurrences, LERs & related correspondence
- B012160493 Forwards LER 78-070/03L-0. SHALLER, D. V. Indiana & Michigan Electric Co. 80/12/10. 1p. 07255:351.
- --B012160496 LER 78-070/03L-0:on 781230.containment isolation valve VCR-010 failed to close completely. Caused by dirt buildup in valve gland area. Valve cycled several times until valve upuld fully close.
 BEILMAN.T.P. Indiana & Michigan Electric Co. 80/12/10, ip. 07235:352.
- 8012180281 Forwards LER 80-026/03L-0. SHALLER, D. V. Indiana & Michigan Electric Co. 80/12/12. ip. 03794: 032.
- --B012180292 LER 80-026/03L-0: on 801113; glycol return containment isolation valve failed to close during surveillance test & during investigation. Caused by stem & lower guide bush , sticking. Stem polishes & bushed honed.

 WIZNER-D. G. Indiana & Michigan Electric Co. 80/12/12. 2pp.
- DOCKET 50-314 DONALD C. COOK NUCLEAR FOWER PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8012040589 Responds to RS Hunter 801010 ltr re use of health physics network Requests that encl info be considered as official document on how health physics network is to be used & who may activate it.

 KEPPLER.J. O. Region 3. Chicago, Office of the Director. 80/11/14.

 3pp. 07170:091.
- --B01204059B Expresses concern & uncertainty re intended purposes & circumstances re use of health physics network.
 HUNTER.R.B. Indiana & Michigan Electric Co. B0/10/10. 3pp.
 07170:094.
- 8012020077 Discusses planned mods to emergency notification sys & health physics network.NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys. W/o encl health physics network manual. KEPPLER.J.Q. Region 3. Chicago, Office of the Director. 80/11/19. 2pg. 07148:345.
- 8012100533 Responds to NRC 801031 ltr requiring resubmittal of contingency plan within 30 days, Requests 45-day extension due to nature of info. HUNTER,R.S. Indiana & Michigan Electric Co. 80/12/04. ip. 07222:104.

- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PHRs & describes program NRC is undertaking to review capability of operating PHRs to remove decay heat following earthquake.
 EISENHUT.D.G. Division of Licensing. 80/10/21. 4pp.

- B012160050 Ltr to operating plant licensees. OL applicants & CP holders. Forwards NURE9-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISENHUT, D. G. Division of Licensing. B0/10/31, 7pp.
- 8012040320 Forwards "Estimate of Ultimate Pressure Capacity of Containment Structure:" for comment Requests that meeting be arranged after review. VARGA.S.A. Operating Reactors Branch 1. 80/11/06, 2pp. 06915:001.
- ---B012040325 "Estimates of Ultimate Pressure Capacity of Containment Btructure." HARBTEAD, G.A. Harstead Engineering Associates, Inc. 80/09/26, 47pp. 06915:001.
- BO12220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BNR Feedwater Nozzle & Control Rud Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EISENHUT, D. O. Division of Licensing. B0/11/13. 1p.
- BD122204B5 Responds to BOO911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON, H. R. Office of Nuclear Reactor Regulation, Director.

 BO/12/04. Zpp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012310002 Confirms 801227 meeting w/util at site to discuss evaluation of regulatory performance.
 KEPPLER.J.O. Region 3. Chicago: Office of the Director. 80/12/05.
 1p. 07071:064.
- 8012180312 Forwards add1 info re automatic initiation & flow indication for auxiliary feedwater sys. Flow indicators fed from balance of plant inverter uninterruptable power source fed from CD battery of Unit 1 & AB battery of Unit 2.
 HUNTER.R. S. Indiana & Michigan Electric Co. 80/12/10. App. 07273:044.
- B0121B0315 Application to amend Licenses DPR-58 & DPR-74, consisting of proposed Tech Specs & license conditions incorporating Category A Lessons Learned requirements in response to NRC B00702 ltr.
 HUNTER-R. S. Indiana & Michigan Electric Co. 80/12/10. 7pp. 07272:336.
- --8012180321 Proposed changes to Tech Specs 3/4 for Unit 2. Incorporating Category A Lessons Learned automatic initiation requirements into engineered safety feature actuation sys.

 * Indiana & Michigan Electric Co. 80/12/10. 20pp. 07273:024.
- B012310259 Notification of R01218 meeting w/utils in Bethesda, MD to discuss ultimate strength of containments & hydrogen control measures.

 MINER, B. Operating Reactors Branch 1. 80/12/11. 3pp. 07370:035.
- G. Inspection reports, IE Bulletins & correspondence
- B012040J91 Forwards IE Insp Rept \$0-316/8D-12 on B00827-28.No noncompliance noted. HEIBHMAN, R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. B0/10/02. 2pp. 07169:127.
- --8012040498 IE Insp Rept 50-316/80-12 on 800827-28. No noncompliance noted Major areas inspected; reactor shutdown margin determination; power & isothermal temp coefficients & control rod worth measurement.
 CHOULEB.N. C., HOPKINS, J. B., ROBINSON, D. L. Region i, Philadelphia, Office of the Director, 80/10/01, 4pp. 07169:127.
- 8012110117 Forwards IE Insp Repts 50-315/80-13 & 50-316/80-11 on 800616-0927. No noncompliance noted. HEIBHMAN,R.F. Region 3, Chicagon Reactor Operations Nuclear Support Branch. 80/10/22. 2pp. 07224:204.
- --8012110124 IE Insp Repts 50-315/80-13 % 50-316/80-11 on 800616-0927. No noncompliance noted, Major areas inspected: operational safety verification, surveillance observation, safety sys challenges & refueling activities.
 MASSER, R.E., BWANSON, E.R., DUBRY, N.E., Region 3, Chicago, Office of the Director. 80/10/22. App. 07224:206.

- 8012170506 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/24.

 1p. 07268:092.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments I/o encl.

 MEPPLER.J. G. Region 3. Chicago. Office of the Director. 80/11/18.
- 8012020666 Forwards info re access of NRC & NRC contractor personnel for health physics program appraisal scheduled for approx two was beginning 801220.

 KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/11/21.

 4pp. 07145:325.
- 8012040678 Forwards IE Builetin 80-24, "Prevention of Damage Bue to Water Leakage Inside Containment." No written response required.

 KEPPLER.J.O. Region 3, Chicago. Difice of the Director. 80/11/21.
 2pp. 07169:099.
- B012080931 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Bnubber Fluid." No written response required. KEPPLER.J.O. Region 3. Chicago, Office of the Director. B0/11/24. 1p. 07182:173.
- 8012270606 Forwards new security badge numbers & clearance levels for Region 3 personnel. Changes should be entered on Sept 1980 access lists.

 KEPPLER. J. O. Region 3. Chicago. Office of the Director. 80/11/25.
 Ann. 07309:013.
- 8012170549 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER. J. O. Region 3, Chicago, Office of the Director. 80/11/26. 2pp. 07264:282.
- BD12180414 Corrects B01121 ltr re health physics appraisal Onsite phase of appraisal to begin B01208.not B01220. & LJ Heuter should be added to Enci 1.

 KEPPLER.J. G. Region 3. Chicago. Office of the Director. B0/12/01.

 ip. 07271:160.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-018 re environ qualification of Class IE equipment.
 HAYEB, D. W. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp.
- R. Periodic operating reports & related correspondence
- 8012190500 Forwards monthly operating rept for Nev 1980. BHALLER, B. V. Indiana & Michigan Electric Co. 80/12/11. lp. 07287: 059
- --8012190505 Monthly operating rept for Nov 1980. O'LLETT.W.T. Indiana & Michigan Electric Co. 80/12/03. App. 07287:060.
- DOCKET 90-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
 F. Security, medical, emergency & fire protection plans
- 801202068B Informs of existing emergency communications sys review & resulting mods to emergency notification sys & health physics network.NRC will have lamps installed on emergency telephones in all control rooms & technical support ctrs. ORIER.B.H. Region i. Philadelphia, Office of the Director. 80/11/14, 2pp. 07148:004.
- 8012150072 Forwards emergency response plan implementation procedures superseding present site emergency plan implementation procedures. N/o encl. RUBBELL-L. B. Baltimore Gas & Electric Co. B0/12/08. ip. 07239: 359.
- BD12190053 Releases public version of utll emergency plan. FELTON, J.M. Division of Rules and Records. BO/12/16. lp. 07279:147.
- --B012190057 Forwards public version of emergency response plan implementation procedures. REIMER.E.T. Baltimore Gas & Electric Co. B0/12/01, 2pp.

- --- B012190064 Public version of emergency response plan implementation procedures.
 - procedures. * Baltimore Gas & Electric Co. 80/11/28. 300pp. 07279:152.
- 801229023 Ack receipt of 801024 & 1113 ltrs commenting on emergency response plan. Responses to comments will be factored into revised plan to be submitted 801231 dyplans for Btates of & VA & Annes Q & App Q-1 for State of ND. QLSQN,R.C. Baitimore Gas & Electric Co. 80/12/22. 1p. 07342:343.
- J. Insurance & indemnity information
- 8012160313 Forwards Endorsement 43 to NELIA Policy NF-216 & Endorsement 35 to MAELU Policy MF-76. SHOEMAKER.C.L. Baltimore Gas & Electric Co. 89/12/10. 3pp. 07243:360.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquats.

 EISENRUT.D.O. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements, Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be set. EISENNUT.D.C. Division of Licensing. 80/10/31. 7pp.
- BOIR220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. W/o encl. EIGENHUT.D.O. Division of Licensing. BO/11/13. ip.
- 8012020425 Forwards results of ECCS analysis for Cycle 5. Independent verification has determined that specific results for peak clad temp & clad oxidation require ninor revision per 10CFR50, 46. Revised Section 8 enct.
 LUNOVALLA.E. Baltimore Gas & Electric Co. 80/11/25. 16pp. 07148: 279.
- 8012020429 Clarifies design features & const re independent third auxiliary feedwater train per NRC 800214 ltr.
 LUNDVALL.A.E. Baltimore Gas & Electric Co. 80/11/25. 3pp.
- 8012030248 Forwards attachments to util 801110 response to NRC 800712 itr re THI-2 Lessons Learned Category A items. Attachments were omitted due to administrative error.

 ASH.R.F. Baltimore Gas % Electric Co. 60/11/25. 12pp. 07151: 239.
- 8012020432 Forwards responses to NRC questions re fifth cycle license application. LUNDVALLA.E. Baltimore Gas & Electric Co. 80/11/26. 3pp. 07141:247.
- 801202043B Forwards responses to NRC questions on fifth cycle license application.
 LUNDVALL,A.E. Baltimore Gas & Electric Co. 80/11/28, 3pp. 07141:250.
- 8012050454 Forwards response to NRC questions re application to amend license DPR-53 for fifth cycle operation. Values for core average heat flux & average liner heat rate clarified. LUNDVALLIA E Baltimore Gas & Electric Co. 80/12/03 2pp. 07171:349.
- 8012280485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering (acreasing storage capacity.

 BANJART.R.L. Effluent Treatment Systems Branch. 80/11/06. Spp.
- B0:2170275 Application to amend Licenses DPR-53 & DPR-69, changing Tech Spec Tables 3,7-4 & 4.7-4 to identify snubbers served by common reservoir & to require insp for reservoir hydraulic fluid within 7 days after startup following major outage. LUNDVALL.A.E. Baltimore Oas & Electric Co. 80/12/12. 2pp. 07266:118.

- --8012170299 Proposed changes to Tech Spec Table 3.7-4, "Safety-Related Hydraulic Snubbers" & Table 4.7-4, "Hydraulic Snubber Insp Schedule."

 4 Baltimore Qas & Electric Co. 80/12/12, 3pp. 07266; 120.
- B012190117 Forwards response to NUREG-0737, "Clarification of TMI Action Plan Requirements." LUKDVALL.A.E. Baltimore Gas & Electric Co. 80/12/15, 7pp. 07284:210.
- 8012220375 Application for amend to License DPR-53 to change Tech Specs re operation of containment spray sys during DBE. Summary piping flexibility analysis encl. LUNDVALLA.E. Baltimore Gas & Electric Co. 80/12/17. 3pp. 03797:063.
- 8012230481 Informs of intended control of reactor coolant vent sys during operation prior to review & approval of procedures.

 New method superior as continuous valve position indication is maintained while isolating power from solenoids.

 LUHDVALLIA.E. Baltimore Gas & Electric Co. 80/12/18. ip. 07314: i31.
- 8012290285 Submits for review comments re high energy line break analysis for third train to auxiliary feedwater sys. High energy line break analysis not required provided third train only used for emergencies.

 ASH.R.F. Baltimore Gas & Electric Co. 80/12/19. 4pp. 07342:319.
- G. Inspection reports, IE Bulletins & correspondence
- 80(2020325 Requests that response to IE Bulletin 80-15, "Possible Loss of Emargency Notification 8ys (ENS) W/Loss of Offsite Power," be resubmitted w/oath or affirmation within 10 days of receipt of ltr.per 10CFR50.54.

 GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/23. 1p. 07143:120.
- 8012220028 Forwards IE Insp Repts 50-317/80-17 & 50-318/80-16 on 800916-19. No noncompliance noted. BRUNNER, E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/23. 2pp. 07306:318.
- --8012220031 IE Insp Repts 50-317/80-17 & 50-318/80-14 on 800916-19.No noncompliance noted Major areas inspected: GA program implementation, auditing, design changes & mods.
 NAPUDA, O. Region 1. Philadelphia, Office of the Director.
 ORECMMAN, E. O. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/21. 7pp. 07306:320.
- 801201036B Responds to IE Bulletin 80-19 "Failures of Mercury-Wettad Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plant Designed by C-E." Surveillance testing has been increased. Relays will be replaced on as-failed basis. LUNDVALL. A.E. Baltimore Gas & Electric Co. 80/10/30. ip. 07098:062.
- 8012170375 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. ORIER.B.H. Region 1. Philadelphia. Office of the Director. 80/10/30. 1p. 07249:030.
- 8012220035 Ack receipt of 800722 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-317/80-12 & 50-318/80-11.

 MARTIN, W. G. Region i, Philadelphia, Safeguards Branch. 80/10/3i. 2pp. 07306:327.
- --B012220037 Responds to NRC B00829 ltr re violations noted in IE Insp Repts 50-317/80-12 & 90-318/80-i1. Corrective actions: withheld (ref 10CFR2.790). EVANS, V.R. Baltimore Gas & Electric Co. 80/09/22. ip. 07306: 329.
- --8012220040 Forwards IE Insp Repts 59-317/80-12 & 50-318/80-11 on B00713-18 & notice of violation Notice of violation withheld (vef 10CFR2,790).
 MARTIN.U.O. Region 1, Philadelphia, Bafeguards Branch. 80/08/29, 2pp. 07306:330.

- 8012120105 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. BO/11/06. ip. 07230: 227.
- 8012190344 Informs util of issuance of new NRC personnel identification badges, effective after 801130. Example encl. MARTIN, M. J. Region 1. Philadelphia. Safeguards Branch. 80/11/06. 2pp. 07286:106.
- BO12030768 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ORIER, B. H. Region i. Philadelphia, Office of the Director. 80/11/07. ip. 07150:280.
- BO12080481 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Bys at Davis Besse Unit 1." No response required.
 ORIER, B.H. Region 1, Philadelphia, Office of the Director.
 BO/11/10. 1p. 07182:334.
- 8012040037 Forwards IE Builetin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, B. H. Region I, Philadelphia, Office of the Director. 80/11/14. 1p. 07169:337.
- B012030558 Requests relief from ASME Code Section 9 requirement.Code deamed impractical Insorvice insp program request deals w/hydrostatic pressure testing of Class 2 steam & feedwater sys.

 LVNDVALL,A.E. Baltimore Gas & Electric Co. 80/11/19. 4pp.
- BO12220621 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. ORIEG.B.H. Region i, Philadelphia, Office of the Director. 80/11/19. 1p. 07308:360.
- B012040522 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." Written response required Requests info on mannower expended. ORIER, B.H. Region 1. Philadelphia. Office of the Director. B0/11/21. 2pp. 07167:226.
- BO12050943 Forwards Info Notice BO-42, "Effect of Radiation on Hydraulic Bnubber Fluid." No written response required. GRIER.B.H. Region i, Philadelphia, Office of the Director. BO/11/24. ip. 07174:029.
- B012070430 Submits comments on IE draft circular re common cause failure of svc water sys. Modified replacement Page 1 & other miscellaneous changes encl. NDVAK.T.M. Assistant Director for Licensing. 80/11/24. 6pp. 07203:034.
- R. Periodic operating reports & related correspondence
- 8012190626 Forwards monthly operating repts for Nov 1980. MERSON S.D. Baltimore Gas & Electric Co. 80/12/15. 1p. 07288:268.
- --BD12190630 Monthly operating repts for Nov 1980. MERSON, S. D. Baltimore Gas & Electric Co. 80/12/15. 16pp. 07288:269.
- 8. Reportable occurrences, LERs & related correspondence
- 8012010356 Forwards LER 80-061/03L-0. RUSSELL.L.B. Baltimore Gas & Electric Co. 80/11/24. 1p. 07/092:176.
- --B012010369 LER B0-061/03L-0: on 801024; emergency dissel generator it would not carry greater than 2.500 kW for greater than 60 minutes. Caused by high cylinder temp due to fouling of injector tips. Tips replaced. LA01EWBKI.J.S.: HUSEBY.D.E. Baltimore Qas & Electric Co. 80/11/24. ip. 07092:177.
- 8012020612 Forwards LER 79-019/03L-1. RUBBELL.L.B. Baltimore Oas & Electric Co. 80/11/25. 1p. 07149:274.

- --8012020619 LER 79-019/03L-1:on 790606/control room air conditioning 11 unit breaker tripped. Caused by open circuit in one or more parallel paths of phase winding resulting in unbalanced phase to phase resistance. Stator rewound.

 LAGIEMBAI, J. S. . UMSTED, J. M. Baltimore Gas & Electric Co. 79/06/25. 1p. 07145-275.
- B012020596 Forwards LER 80-056/03L-0. RUSSELL,L. B. Baltimore Gas & Electric Co. 80/11/28. 1p. 07143:263.
- --8012020530 LER 80-056/U3L-0: on 801028, performance of BTP M-13-1, inaccessible snubber visual intp, revealed five snubbers, 1-54-6, -6A. -7. -7A & 1-60-27 inoperable. Caused by loss of hydraulic oil Mods completed.
 MENDERLICH.R. MIERNICKI.M. J. Baltimore Oas & Electric Co. 80/11/28. 2pp. 07143:244.
- B012100551 Forwards LER 80-062/03L-0. RUSSELL, L. B. Baltimore Gas & Electric Co. B0/12/03. 1p. 07218:151.
- --8012100566 LER 80-062/03L-0: on 801103 & 04,LPSI pump 12 tripped officausing temporary loss of shutdown cooling. Apparently caused by spurious reactor analysis & safety signals received while re-energizing actuation sys.

 WENDERLICH R. L., 91850N. W. S. Baltimore Gas & Electric Co. 80/11/03. 1p. 07218:152.
- 8012100557 Forwards LER 80-063/03L-0. RUSSELL.L.B. Baltimore Cas & Electric Co. 80/12/05. 1p. 07218:149.
- --8012100565 LER 80-063/03L-0: on 801105; control room air conditioning unit failed to start. Cause undetermined, Simulation of control imputs to breaker 52-1108 & initiation of shutdown sequencer performed.

 LAGIENSXI, J. S., RIZZO, P. G. Baltimore Gas & Electric Co. 80/11/05. 1p. 07218:150.
- 8012160390 Forwards LER 80-058/03L-0. RUSSELL.L B. Baltimore Gas & Electric Co. 80/12/12. 1p. 07282:335.
- --8012160374 LER 80-058/03L-0: on 801112, found 4 kV bus 11 normal break feeder (152-1115) opened & 120-volt ac vital bus 11 voltage went low. Cause undetermined. Diesel generator 11 re-energized 4 kV bus.

 DAVIS,8.M., R12ZO,P.O. Baltimore Cas & Electric Co. 60/12/12.
- B012230478 RO B0-65: on B01215, charging pumps not verified de-energized & charging flow paths not verified closed during local leak rate test on penetration 41. Dmission corrected. No dilution resulted.

 * Baltimore Gas & Electric Co. 80/12/16 lp.
- B012230351 Forwards LER 79-017/03L-1. RUSSELL-L.B. Baltimore Gas & Electric Co. B0/12/19. 1p. 07311:263.
- --G012230366 LER 79-017/03L-1:en 790515, during performance of overspeed testing, diesel generator 12 auriliary blower failed. Returned to svc 790523. Cause of failure due to thermal growth & subsequent contact between lobes & power housing.
 LAGIEMSKI, J. S., UMSTED, J. M. Baltimore Gas & Electric Co. 79/06/21. 1p. 07311:264.
- E012230405 Forwards LER 80-064/03L-0. RUSSELL, L. B. Beltimore Gas & Electric Co. 80/12/19. 1p. 07312:283.
- --B012230409 LER 80-064/03L-0: on 801121, during piping sys supports walkdown, seismic restraint for auxiliary spray control valve found not installed. Three supports required redesign & relocation Caused by error during initial const. HEBEL.R.P. Baltimore Gas & Electric Co. B0/12/19. ip. 07312:254.
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 8012020689 Informs of existing emergency communications sys review & resulting mods to emergency notification sys & health physics network.NRC will have lamps installed on emergency telephones in all control rooms & technical support ctrs. GRIER.B.H. Region 1, Philadelphia. Office of the Director. BO/11/14. 2pp. 07148:004.

- 8012150072 Forwards emergency response plan implementation procedures superseding present site emergency plan implementation procedures. M/o encl. RUSSELL.L.B. Baltimore Gas & Electric Co. 80/12/08. [p. 07239:359.]
- B012190053 Releases public version of util emergency plan. FELTON J. M. Division of Rules and Records. B0/12/14. 1p. 07279:147.
- --8012193097 Forwards public version of emergency response plan implementation procedures. REIMER.E.T. Baltimore Cas & Electric Co. 80/12/01. 2pp. 07279:150.
- --8012190064 Public version of emergency response plan implementation ocedures. Baltimore Gas & Electric Co. 80/11/28. 300pp. 07279:152.
- 8012270223 Act receipt of 801024 & 1113 ltrs commenting on emergency response plan. Responses to comments will be factored into revised plan to be submitted 801231 w/plans for States of & VA & Annex Q & App Q-1 for State of MD.

 QLSON, R. C. Baltimore Gas & Electric Co. 80/12/22. ip. 07342:343.
- J. Insurance & indemnity information
- 8012160313 Forwards Endorsement 43 to NELIA Policy NF-216 & Endorsement 35 to MAELU Policy MF-76.
 SHDEMAMER.C.L. Baltimore Gas & Electric Co. 80/12/10. 3pp. 07243:360.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PHRs & describes program NRC is undertaking to review capability of operating PHRs to remove decay heat following earthquake.

 EISERHUT, D. O. Division of Licensing. 80/10/21. 4pp.
- 8012160050 Ltr to operating plant licensees.GL applicants & CP holders. Forwards NUREQ-0737 re TAI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Enci 1 implementation dates will be net. EISENBUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BVR Feedwater Norrie & Control Rod Drive Return Line Nazzie Cracking." Confirmation that implementation dates will be met must be sent within 45 days. U/o encl. EISERHUT.D.O. Division of Licensing. 80/11/13. ip.
- 8012020429 Clarifies design features & const re independent third auxiliary feedwater train per NRC 800214 ltr. LUNDVALL, A.E. Baltimore Gas & Electric Co. 80/11/25. 3pp. 07148:269.
- 8012030248 Forwards attachments to util 801110 response to NRC 800712 ltr re Tff-2 Lessons Learned Category A items. Attachments were omitted due to administrative error.

 AGH.R.F. Baltimore Qas & Electric Co. 80/11/25. 12pp. 07151:239.
- 8012070277 Requests amend to License DPR-69, to allow operation for fourth cycle. Refueling outage scheduled for 810102, approach to criticality on 810212 % return to power operation immediately thereafter.
 LUXUVALLA.E. Baltimore Oas & Electric Co. BO/12/04, 2pp. 07206.315.
- --8012070271 Proposed changes to STS se Cycle 4.

 * Boston Edison Co. 80/12/04. 48pp. 07206:317.
- 8012270485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation Inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENTOWH.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- -8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed \(\text{\text{W}} \) 71% planning or considering increasing storage capacity.

 BANDARTER.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012170450 Submits fourth cycle OL Class 4 amend application fee. ASH.R.F. Baltimore Gas & Electric Co. 80/12/09. 1p. 07269:151.

- B0121702795 Application to amend Licenses DPR-93 & DPR-67 changing Tech Spec Tables 3.7-4 & 4.7-4 to identify soubbers served by common reservoir & to require insp for reservoir hydraulic fluid within 7 days affer startup following major outage.

 LUNDYALL & Baltimore Qas & Electric Co. B0/12/12. 2pp.
- --B012170299 Proposed changes to Tech Spec Table 3.7-4, "Bafety-Related Hydraulic Snubbers" & Table 4.7-4, "Hydraulic Snubber Insp Schedule." Baltimore Gas & Electric Co. 80/12/12. 3pp. 07266:120.
- 8012190117 Forwards response to NUREG-0737, "Clarification of TMI Action Plan Requirements." LUNDVALL, A.E. Baltimare Gas & Electric Co. 80/12/15. 7pp. 07284:210.
- 8012290285 Submits for review comments re high energy line break analysis for third train to auxiliary feedwater sys. High energy line break analysis not required provided third train only used for emergencies.

 ASH:R.F. Baltimore Gas & Electric Co. 80/12/19. 4pp. 07342:319.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012020325 Requests that response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power," be resubmitted w/oath or affirmation within 10 days of receipt of ltr.per 10CFR50.54.

 ORIER,B.M. Region 1, Philadelphia, Office of the Director. 80/10/23. 1p. 07143:120.
- B012220028 Forwards 1E insp Repts 50-317/80-17 & 50-318/80-16 on B00916-19. No noncompliance noted.
 BRUNNER,E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 80/10/23. 2pp. 07306:318.
- --B012220031 IE Insp Repts 50-317/80-17 & 50-318/80-16 on 800916-19. No noncompliance noted Major areas inspected: QA program implementation auditing, design changes & mods. NAPUA. G. Region I. Philadelphia, Office of the Director. QREENMAN.E.O. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/21. 7pp. 07306: 320.
- 8012010368 Responds to 1E Bulletin BO-19 "Failures" of Mercury-Watted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plant Designed by C-E. " Surveillance testing has been increased. Relays will be replaced on as-failed basis. LUNDVALL, A.E. Baltimore Gas & Electric Co. 80/10/30, 1p. 07098:062.
- 8012170375 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/30, ip. 07269:050.
- B012220035 Ack receipt of 800922 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/80-12 & S0-318/80-11. N.W. O. Region i, Philadelphia, Safeguards Branch. 80/10/31. 07306:327 HARTIN, W. O.
- --8012220037 Responds to NRC 860829 ltr re violations noted in IE Insp Repts 50-317/80-12 & 90-318/80-11. Corrective actions: withheld (ref 100FR2.790). EVANS.V.R. Baltimore Oas & Electric Co. 80/09/22. ip. 07306:329.
- --8012220040 Forwards IE Insp Repts 50-317/80-12 & 50-318/80-11 on 800713-18 & notice of violation.Notice of violation withheld (ref 10CFR2.790).
 MARTIN,N.O. Region i, Philadelphia, Safeguards Branch. 80/08/29, 2pp. 07306:330.
- --8012220062 IE insp Repts 50-317/80-12 & 50-318/80-11 on 800713-18. Noncompliance noted: failure to issue written procedure & failure to maintain continuous communications. Details withheld (ref 10CFR2.770).

 MADDEN, N. Region i, Philadelphia, Office of the Director.
 DEVLIK, J. M. Region i, Philadelphia, Safeguards Branch. 80/08/27, 2pp. 07306:332.
- 801212010B Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. BO/11/06. ip. 07230:227.
- B012190344 Informs util of issuance of new NRC personnel identification badges, effective after B01130. Example encl. MARTIN, M. J. Region 1, Philadelphia, Safeguards Branch. B0/11/06. 2pp. 07286:106.

- 9012030/68 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/07. 1p. 07150: 280.
- 8012080481 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. 1p. 07182:336.
- BO12040037 Forwards IE Bulletin BO-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 ORIER, B. H. Region 1, Philadelphia, Office of the Director, BO/11/14. 1p. 07169: 337.
- BO12030658 Requests relief from ASME Code Section 9 requirement.Code deemed impractical.Inservice insp program request deals w/hydrostatic pressure testing of Class 2 steam & feedwater sys. LUNDVALL.A.E. Baltimore Gas & Electric Co. BO/11/19. 4pp. 06586:003.
- 8012270621 Advises that written response is required to IE Bulletin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." First paragraph erronsously stated no written response required.

 ORIER, B. H. Region i, Philadelphia, Office of the Director. 80/11/19. 1p. 07308:360.
- BO12040522 Forwards IE Bulletin BO-24. "Prevention of Damage Due to Mater Leakage Inside Containment." Noitten response required. Requests info on manpower expended. ORIER. B.H. Region 1, Philadelphia, Diffice of the Director. BO/11/21. 2pp. 07169:226.
- 8012030543 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/24, 1p. 07174:029.
- 8012120479 Forwards revised proprietary & nonproprietary versions of Wastinghouse low pressure turbine disc insp data. Data supersedes 800318 submittal. Proprietary version withheld (ref 10CFR2.790).
 UNDVALL. A.E. Baltimore Gas & Electric Co. 80/12/09. 37pp. 07227: 221.
- R. Periodic operating reports & related correspondence
- BO12170626 Forwards monthly operating repts for Nov 1980. MERBON, S. D. Baltimore Gas & Electric Co. BO/12/15. 1p. 07288: 268.
- --8012190630 Manthly operating repts for Nov 1980. MERSON: S.D. Baltimore Gas & Electric Co. 80/12/15. 16pp.
- S. Reportable occurrences, LERs & related correspondence
- 8012010322 Forwards LER 80-046/03L-0. RUSBELL, L. B. Baltimore Gas & Electric Co. 80/11/24. ip. 07092:154.
- --B012010336 LER 80-046/03L-0: on 801024, containment pressure signal to reactor protection sys channel A found out of calibr in nonconservative direction. Caused by output of Transmation Isolator 2-E/E-5313A being 0.2 VDC low over range. DAVIES M., RIZZO,P.O. Baltimora Gas & Electric Co. 80/11/24. ip. 07092:195.
- 8012020593 Forwards LER 80-050/03L-0. RUBBELL, L. B. Baltimore Gas & Electric Co. 80/11/26. 1p. 07145:266.
- --8012020600 LER 80-050/03L-0: on 801027, wide range ex-core nuclear instrument channel 8 failed. Caused by greater than or equal to 15-volt dc power supply having low supply w/ac ripple. Fower supply replaced. LIOIEMBXI, J. S., RIZZO, P. O. Baltimore Oas & Electric Co. 80/11/26. 1p. 07145:267.
- 8012030731 Forwards LER 80-051/03L-0. RUSBELL, L. B. Baltimore Gas & Electric Co. B0/12/01. ip. 07149:163.

- --8012030733 LER 80-051/03L-0:on 801101.CTMT 21 air cooler tripped off.
 Caused by terminal shorting block in air cooling fan
 controller flashing over causing trip. No cause of flashover
 determined. No prevention action necessary.
 NENDERLICHER.L., RIZZO.P.O. Baltimore Gas & Electric Co.
 80/12/01. ip. 07149:164.
- 8012100553 Forwards LER 80-053/03L-0. RUBSELL,L.B. Baltimore Gas & Electric Co. 80/12/01. ip. 07218:144.
- --B012100557 LER B0-053/03L-0: on 801101 & 07, containment atmosphere particulate monitor failed. Caused by loosened channel field cable heads due to improper crimping. New connectors properly installed.

 LA01EMSXI, J. S. & RIZZD, P. Q. Baltimore Gas & Electric Co. 80/12/01.

 2pp. 07218: 145.
- 8012160381 Forwards LER 80-054/03L-0. RUBSELL.L. B. Baltimore Gas & Electric Co. 80/12/10. 1p. 07252:333.
- --B012160337 LER 80-054/03L-0: on 801110, failure of 81-661-CV caused 21A safety injection tank level to decrease to less than 187 inches. Caused by solenoid valve 2-CV-661 leat. Bolenoid valve (ASCO-NP8320A175V) replaced w/spare. WENDERLIGH.R. L., RIZZO, P. G. Baltinore Gas & Electric Co. 80/12/10. 1p. 07252: 334.
- 8012220401 Forwards LER 80-056/03L-0. RUSBELL.L.B. Baltimore Oas & Electric Co. B0/12/16. 1p. 07307:344.
- --8012220414 LER 80-056/03L-0:on B01116.control element assembly 1 dropped into core. Cause undetermined. Power reduced to less than 70% & control element assembly returned to group height.

 LAOIENEKI, J. G. Baltimore Gas & Electric Co. B0/12/16. 1p. 07207.745
- DOCKET 30-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8012040180 Public version of "Independent Assessment of Evacuation Times for TMI Nuclear Power Plant," Vol 10, prepared for FEMA, COSBY, J. C., SHEPPARD, W. V., THOMPSON, W. E. Wilbur Smith & Associates, 80/06/30. 5ipp. 07161:238.
- BO12050477 Informs that mods will be made to emergency notification sys & health physics network equipment. FRC will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operations facilities. ORIER, B. M. Region 1, Philadelphia, Office of the Director. BO/11/14. 2pp. 07174:253.
- 8012040063 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary. FELTON, J.M. Division of Rules and Records. 80/12/03. 1p.
- --8012040088 Public version of "Evacuation Time Assassment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FeIfA. * Wilbur Smith & Associates. 80/06/30. 17pp.
- --8012040155 Public version of program rept, "Evacuation Time Assessment of Nina Nuclear Power Plants Emergency Planning Zones," Vol. 1. prepared for FEMA. COSBY, J. C. Wilbur Smith & Associates. 80/06/30. 43pp.
- 8012290440 Releases public version of "NRC Headquarters Incident Response Plan." FELTON.J.M. Division of Rules and Records. 80/12/17. 1p. 07308-001.
- --8012270445 Public version of "NRC Headquarters Incident Response Plan." # Commissioners. 79/01/15, 100pp. 07308:001.
- 8012290449 Releases public version of Dauphin County emergency plan, FELTON, J.M. Division of Rules and Records. 80/12/17. 1p. 07308:001.
- --8012290452 Public version of Commonwealth of PA. Dauphin County emergency plan for communities near TMI facility.
 MOLLOY.K.J. Dauphin County, PA. 75/06/30. 100pp. 07308:001.

- 8012290477 Releases public version of "Federal Response Plan for Paccetine Nuclear Emergencies," interim guidance, FELTON-J.M. Division of Rules and Records, 80/12/17, 1p. 07398:001.
- --B012290402 Public version of "tederal Rosponse Plan for Peacatime Nuclear Emergencies," interim guidance, Includes Annex I & Annex II. * General Services Administration. 77/04/30, 125pp.
- B012290490 Releases public version of "NRC Headquarters Incident Response Plan." FELICON J. M. Division of Rules and Records. 80/12/17. 1p.
- 8012290497 Releases public version of "Region 1 Incident Response FELTON J. M. Division of Rules and Records. 80/12/17. (p.
 - -8012270500 Public version of "Region & Incident Response Plan." Revision 4. # Region 1. Philadelphia. Office of the Director. 79/02/28. 150pp. 07308:001.
- 8012270504 Releases public version of Defense Civil Preparedness Agency emergency handbook. FELTON, J. M. Division of Rules and Records. 80/12/17, 1p. 07308:001.
- ---801229050A Public version of "Disaster Operations: Handbook for Local E Defense Civil Preparedness Agency. CPO 1-6. 72/07/31. 07308:001. DAVIS, J. E
- --8012290510 Public version of Change i entitled "Nuclear Facility Accidents," to "Disaster Operations: Handbook for Local Covts." Defense Civil Preparodness Agency. CPO 1-6 R1. 74/06/30. pp. 07308:001. 13pp.
- B012290187 Forwards Revision 1 to guard training & qualification plan. Plan withheld (ref 10CFR2, 790). HUKILL:H.D. Matropolitan Edison Co. B0/12/19. 2pp. 07344:185.
- O. Adjudicatory correspondence
- 8012160144 Forwards GEC Form 10-0. Quarterly Financial Rept & supporting mgt comments. In response to NRC 790721, 1107 & 800811 requests for info re significant financial developments affecting utils in restart proceeding.

 CONUCH. V. H. General Public Utilities 80/11/26. 3pp. 07262: 246.
- --8012160154 Quarterly Financial Rept. Sept 1980 & supporting mgt comments.

 * General Public Utilities. B0/11/14. 44pp. 07262:249.
- 8012290663 Response to NRC 800211 motion to conform proposed Tech Specs w/amend of order-Licensee does not appose motion w/ understanding that formal license amend would await outcome of hearing Centificate of Byc oncl. RIDOMAY.D.A. Metropolitan Edison Co. RIDOMAY.D.A. Shaw, Pittman, Potts & Trowbridge. 80/12/04. Spp. 07333:097.
- 8012240009 Forwards radiation protection plan submitted on 800725 for consideration of stipulation of withdrawal of Contention 5 & DC Circuit Court 801119 decision in Shoily case, W/o encls. LEWIB, S. H. Hearing Branch 2. 80/12/05. ip. 07324:199.
- 8012270175 Forwards notice of appearance in proceeding. LEMIS, S. H. Hearing Branch 2. 80/12/05. 2pp. 07344: 169.
- 8012160604 Claim for damages in amount of \$4,010,000,000 based on NRC alleged negligence of failure to inform util of previous similar occurrence at Davis-93330. KLINOSDERO, D., LIBERMAN, J. B. General Public Utilities OPU Service Corp. KLINOSDERO, D. Kaye, Scholer, Fierman, Hays & Handler. 80/12/08, 33pp. 07284:279.
- 8012230036 Responds to 801210 teleon & forwards documents re Contention 2 (neutron monitors).Contention 3 (containment sump water) & 800725 TMI-2 radiation protection plan.W/o encis. LEWIG.S.H. Hearing Branch 2. GO/12/12. 2pp. 07311:231.

- 8012300189 Forwards jointly proposed stipulation for dismissal of BC Sholly from proceeding & dismissal of MA Lochstet Contention I. Requests review of Environ Coalition on Nuclear Power Contention 5. Draft order & amend also encl. LEWIS.8.H. Hearing Branch 2. 80/12/17. 14pp. 07356:307.
- --8012300195 Safety evaluation re RCS pressure safety limit mods. Mod does not authorize change in effluent types or total amounts nor increase in power level.

 4 Office of Nuclear Reactor Regulation, Director. 80/12/17, App. 07396:321.
- ~-801230177 Draft Tech Specs re safety limits for RCB pressure, limiting conditions for operation & administrative controls.
 # Office of Nuclear Reactor Regulation, Director. 80/12/17. 6pp. 07336:327.
- B012290519 Responds to B01207 ltr.Ltr & encls transmitting stipulations & related motion papers have been sent General effect of bankruptky default by util eramined in NUREG-0689.
 LEMIS.8. H. Hearing Branch 2. 80/12/19. 2pp. 07335:171.
- H. General correspondence
- B012020/27 Responds to B00920 ltr to President Carter re responsibility for accident cleanup. Util not allowed to charge consumers for accident, but may charge for purchasing power to replace power that would have been provided by facility.

 SNYDER.B. J. TMI Program Office. B0/10/24. 5pp. 06916:001.
- 8012030853 Responds to 801013 ltr re radiation releases into air & Busquehanna River from TMI-2. Levels of radiation released into air not extremely high. Water processed by EPICOR-II water treatment sys not currently permitted into river. SNYDER. E. J. TMI Program Office. 80/10/27. 2pp. 07149:072.
- --8012030856 Expresses concern re radiation releases into air & Susquehanna River & states opinion that plants should use coal rather than nuclear sneegy.

 AULTHDUSE.D. L. Affiliation Unknown. 80/10/13. 2pp. 07149:074.
- B0120B0B03 Ack receipt of B00926 ltr to President Carter re funding for cleanup at TMI-2.NRC ordered Unit 1 to remain in cold shutdown until further orders.NRC has authority to ensure public safety should util be unable to do so. SNYDER.B.J. TMI Program Office. 80/10/30. 3pp. 07175:337.
- B012310504 Ack receipt of B01001 itr to WJ Dircks re formation of Krupton & ontry into reactor bldg Technical capability for recombining high atomic number fission products does not yet exist. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/10/30. 1p. 07365: 255.
- -8012310510 Express approciation for document re TMI-2 reactor bldg atmospheric decontamination Questions reversal of krypton gas creation & risk of reactor bldg entry. FLICKLR. Affiliation Unknown. 80/10/01. 1p. 07365:296.
- 8012010411 Responds to 801027 postcard re-nuclear power & resulting radwaste. Hearing on resumption of Unit 1 started on 801015. President's 791207 statement on Kenany Commission & 800212 statement to Congress encl. DENIGN.H.R. Office of Nuclear Reactor Regulation, Director. 80/11/07. 10pp. 08916:001.
- 8012020B17 Ack receipt of 800330 ltr requesting info on nuclear waste disposal Discusses NRC licensing authority & DOE responsibilities. Forwards info on decontamination & disposal of radwaste. W/o encl. SNYDER, B. J. TMI Program Office. 80/11/18. 2pp. 07145: 314.
- --B012020835 Requests info on nuclear waste disposal, agency responsible for waste disposal, number of facilities in operation & background of nuclear industry.
 ROBERTE, M. Affiliation Univoum. B0/03/30. 2pp. 07145:316.
- 8012030786 Responds to 801021 ltr re encl 0 Trust 801017 ltr expressing concern re health effects of accident & reactor bldg purgs. Dosimstry in place during accident was sufficiently sensitive to Xe-133 radiation. DIRCKS, M.J. Office of the Executive Director for Operations, 80/11/18. Bpp. 07149:278.
- 801204016B Ack receipt of 800319 ltr re facility.Forwards NUREQ-0647, "Bafety Evaluation & Environ Assessment," & proposed Tech Specs reflecting present condition of facility.
 SNYDER, B. J. TMI Program Office. 80/11/18, 1p, 06915:001.

- --8012040176 Requests NUREG-0647 re combined safety evaluation & environ assessment for TMI-2 in shutdown mode. Forwards 800318 article from Wall Street Journal & requests info on evacuation FRIESEMALH.P. Northwestern Univ. 80/03/19. 3pp. 06915:001.
- 8012090274 Requests computer terminal at program ofc for development of capability to store & retrieve data in timely fashion.

 WELLER,R. TMI Program Office. 80/11/25. ip. 07202:346.
- B012120227 Responds to encl 800929 ltm to President Carter requesting public hearings on draft EIS & meeting w/residents re NRC role in decontamination. Transcripts of meetings w/MD & PA officials will be considered in final EIS.

 DENION.H.R. Diffice of Nuclear Reactor Regulation, Director. B0/11/25, 5pp. 07236:192.
- 80i2i20693 Responds to 800922 request for public hearings on issues raised in draft EIS. Transcripts of meetings w/state officials listed on encl schedule will be considered in preparation of final EIS. W/o encl.
 DENION, H.R. Office of Nuclear Reactor Regulation, Director. 80/11/25, 2pp. 07230:189.
- --B012120657 Requests public hearings on draft programmatic EIB re decontamination & disposal of radwaste from 790328 accident. Ltr to President Carter encl. SHOLLY.B.C. Three Hile Island Public Interest Resource Center. B0/09/22. Bpp. 07230:192.
- 8012150022 Responds to 801113 postcard to Chairman Ahearme re establishment of citizens advisory group to oversee cleanup at facility. Advisory panel was formed to consult w/ Commission on cleanup activities at facility. SNYDER.B.J. TMI Program Office. 80/11/26. ip. 07241:042.
- ---8012150023 Requests establishment of citizens advisory group to oversee cleanup at facility.
 LOGAN, A. Affiliation Unknown. 80/11/13. ip. 07241:043.
- 8012160253 Responds to 801028 ltr to Commissioner Henérie re improvement of nuclear power safety. Use of infrared photoelectric detectors to detect flow changes has inherent disadvantages. MINOQUE, R. B. Office of Standards Development, Director. 80/12/01. 2pp. 07261:330.
- --8012160258 Recommends improved methods for nuclear power safety. KOCEN.B. Affiliation Unknown. 80/10/28. 3pp. 07261:332.
- 8012080816 Ack receipt of 800215 ltr requesting info on TMI-2 accident. Informs of amount of radiation released forwards NUREG-0558 re doses & health effects of releases & explains permissible dose rates, Wo encl.
 SNYDER, B. J. TMI Program Office. 80/12/03. 3pp. 07183: 122.
- --8012080822 Requests info on TMI-2 accident including amount of radiation released, isotopes released, time of release, background radiation level in Lancaster, PA & max safe level of exposure for public CORD, E. Affiliation Unknown. 80/02/15. 2pp. 07(83:125.
- 8012220237 Responds to 801031 ltr by forwarding programmatic EIS on documentation & disposal of radwaste resulting from TMI-2 accident.

 SNYDER, B. J. TMI Program Office. 80/12/09. 1p. 07303:253.
- --B012220244 Requests info on environ impact of TMI-2 790329 incident. CALHOUN, J. Affiliation Uninawn. B0/10/31. ip. 07303:254.
- 8012270356 Forwards NUREC-0689 re NRC staff evaluation of financial responsibility for cleanup of TMI-2. Authorization by Congress needed for federal govt to assume cost N/o NUREO encl.
 SNYDER, B. J. TMI Program Office. 80/12/11. 2pp. 07345: 353.
- --8012290357 Expresses concern that THI may go bankrupt & believes that federal govt should assume financial responsibility. Forwards editorial dealing w/financial situation. GRABB.H.H. Affiliation Unknown. 80/11/23, 3pp. 07345:355.
- 8012290368 Forwards transcripts of 801029 & 1117 public meetings re decontamination & disposal of wastes at TMI-2. W/o encl. SNYDER, B. J. TMI Program Office. 80/12/11. 1p. 07345:257.
- --8012270370 Requests transcripts of 801027 & 1114 public meetings redecontamination of TMI-2.
 HELTON, A. H. Maryland, State of, 80/11/26, 1p. 07345:258.

- 8012300448 Forwards Resolution 81.passed by City of York,PA on 790501. requesting that facilities not be reactivated until safety measures are taken & public hearings held. BROOMS.E.L. York, PA 80/12/12 4pp. 07357:184.
- 8012300263 Requests that period for public review of programmatic EIS be extended. Revised draft should now be issued instead of final version.
 PETERSON, R. W. National Audubon Society. 80/12/16. 1p. 07358:154.
- I. Financial information
- 8012270513 Informs that evaluation of current & near-term financial condition of Met Ed reveals inability to fund cleanup costs at TMI-2. If ratepayers do not bear cost, util cannot meet cleanup cost on schedule.
 CURTIE.C.B. Faderal Energy Regulatory Commission. 80/11/10. 2pp. 07333:162.
- B012110497 "Potential Impact of Licensee Default on Cleanup of THI-2." * Division of Engineering, NURE9-0689, B0/11/30, 145pg. Available at NTIS, 07256:001.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8012020958 Summary of Ad Hoc Subcommittee on TMI-2 Accident Action Plan B00107 meeting in Washington.DC re NRC draft plan for implementing recommendations of President's commission. * ACRS - Advisory Committee on Reactor Bafeguards. 80/02/01. 32pp. 07147:178.
- 8012020/84 Responds to 790727 requests that ACRS address consistency of actual component failure experience w/that projected in MASH-1400 & that ACRS determine probabilities of occurrence re Davis-Besse 770924 & Rancho Seco 780320 events.
 PLESSETIM S. ACRS Advisory Committee on Reactor Safeguards.
 80/02/20. 8pp.
- --BD12D2D797 Forwards "Analysis of Feedwater Translant Bequences in B&W NSSS:" to aid in formulating response to M Udal1 790729 itr.
 Using WASH-1400 event trees & data directly gives
 meaningless results.
 ABBUTIE. ACRS Advisory Committee on Reactor Bafeguards.
 B0/02/07. 1p.
- --8012020804 "Analysis of Feedwater Transient Sequences in B&W NSSS." ABBUTT,E.E. ACRB - Advisory Committee on Reactor Safeguards. 80/02/07. 21pp.
- B0111B0072 Transcript of ACRB 247th general meeting on 801107 in Washington, DC. Pg. 145-291. Viewgraphs encl. * ACRB - Advisory Committee on Reactor Safeguards. B0/11/07. 258pp. 06928:201.
- P. Operating license stage documents & correspondence
- B012230066 "Analysis of TMI Accident & Alternative Sequences."
 WD0TCN.R.O., DENNINO.R.S., CYBULSKIS.P. Battelle Memorial Institute,
 Columbus Laboratories. NRC-04-76-293-08. NUREO/CR-1219. B0/01/31.
 117pp. Available at NTIB. 07314:001.
- 8012230335 "Psychological Stress for Alternatives of Decontamination of TM1-2 Reactor Bldg Atmosphere."
 BAUM A., OATCHEL,R., STREUFERT,S. Human Design Oroup, FIN B-6892.
 NUREO/CR-1584. 80/08/31 34pp. Available at NTIS. \$2.00.
 07321:013.
- B012020753 Forwards seismic qualifications of auxiliary faedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake. EISENMUT.D.O. Division of Licensing. B0/10/21. 4pp.
- 8011200546 Recommends approval of publication & distribution of encl NUREQ-0689, "Potential Impact of Licensee Default on Cleanup of TMI-2." W/o rept. DENION, N.R. Office of Nuclear Reactor Regulation, Director. BECY-80-416A, 80/10/31. 3pp. 03743:087.
- 8012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISERHUT. D. O. Division of Licensing. 80/10/31. 7pp.

- 8012690501 Responds to 801009 ltr re obtaining adequate input to draft programmatic EIS for decontamination of facility. NRC has ongoing program of meetings u/public elected officials & interested organizations.

 AHEARKE, J. F. Commissioners. 80/11/06. 2pp. 07174:257.
- --8012090530 Forwards list of meetings NRC has held or has planned w/public & local officials & interested organizations.

 Verbatim transcripts of meetings are available in EPDR.

 SNYDER.B.J. TMI Program Office. 80/10/03. 3pp. 07174:259.
- --8012050535 Urges NRC to schedule & conduct public hearings re EIS on decontamination of facility.

 SPETH-O. Council on Environmental Guality. 80/10/09. 2pp. 07174:262.
- 8012040136 Expresses gratitude for willingness to serve as chairman of advisory penel for decontamination of facility. Panel should consider specifically, evestion of disposition of processed water. List of panel members encl.

 AHEARKE, J. F. Commissioners. 80/11/07. 3pp. 07170: 238.
- 8012220563 Ltr to all gower reactor licensees forwarding NUREG-0419, "BHR Feedwater Norzie & Control Rod Drive Return Line Norzie Cracking." Confirmation that implementation dates will be set must be sent within 45 days (I/O encl. EISENHUT, D. C. Division of Licensing. 80/11/13. lp.
- 8012050096 Forwards EPICOR-11 resin solidification svc procurement spec for review & comment W/o encl. HOVEY, O. K. Metropolitan Edison Co. 80/11/17. 2pp. 07174:021.
- 8012020598 Expresses concerns as chairman of Advisory Panel for Dacontamination of TMI-2. Panel will be unable to effectively deal w/subsequent matters by 810131. York & Lebanon Counties do not have representation on panel, MINNICH, J.F. Harrisburg, PA. 80/11/18. 1p. 07148:040.
- BOIRO10105 Answers NRC B01006 & 15 ltrs requesting response to draft programmatic EIS comments by MD Ad Hoc Committee on TMI.Dept of Army.Chesapeate Bay Foundation & Commonwealth of VA. HOVEY.O.X. Metropolitan Edison Co. 80/11/20. 4pp. 07097:061.
- 8012020532 Provides initial response to NRC 801027 request for info re disposal of EPICOR-II & low activity SDS ion exchange media. Final response will be transmitted by 801215, HQVEY, O. K. Metropolitan Edison Co. 80/11/21. ip. 07130:307.
- BO12120122 Responds to question on error limits associated w/potential health effects indicated in draft programmatic EIS. Estimates are based on 1972 rept of Natl Academy of Sciences Advisory Committee on Biological Effects of Ignited Radiations.

 SNYDER, B. J. THI Program Office. BO/11/21. 2pp. 07236:277.
- 8012020515 informs that EPICOR 2 liner metallurgical evaluation being finalised. Meeting scheduled w/MRC on 801203 to discuss rept.Rept will be available 801215.

 HOVEY, O. X. Metropolitan Edison Co. 80/11/24. ip. 07141:266.
- 8012080345 Intends to obtain NRC approval of facility recovery projects in two-step process.Design criteria will be submitted for comments & approval. Technical evaluation rept will then be submitted later for approval.

 HOVEY, O. K. Metropolitan Edison Co. 80/11/25. 2pp. 07175:063.
- 8012080079 Informs that NRC will possibly approve all applications for changes or amends to facility license as mod to NRC 800211 order, until hearings are complete, due to unique nature of THI-2.

 HILLER.H. G. License Fee Hanagement Branch. 80/11/25. 1p. 07187:001.
- B012120011 Advises that review of util B0020B & 25 ltrs requesting changes to Tech Specs.Section 6 has been terminated.due to util requests to take no further action on mods. Requests for mods is considered withdrawn.

 SNYDER.E.J. IMI Program Office. 80/11/25, 1p. 07231:343.
- 8012120027 Forwards comments received from federal, state & local agencies re draft programmatic EIS on decontamination & disposal of raduaste from THI accident. Review of comments & responses requested by 801215 M/v encl.

 SHYDER.E.J. THI Program Office. 80/11/25. 1p. 07231:345.
- 8012040293 Forwards two sets of add1 microfilm reels of TMI data collected by util contractor, Data Hyt & Reduction Group. W/o enel.
 REED, E. C. Metropolitan Edison Co. 80/11/26, ip. 07167:254.

- B012050113 Forwards comments on draft programmatic EIS re decontamination & disposal of radwaste resulting from TMI-2 accidentias specified in CEG regulations, W/o Bncl. SNYDER.B.J. TMI Program Office. 80/11/26. 4pp. 07181:022.
- 8012100646 "Recriticality Potential of TMI~2 Core." submitted as summary paper for ANS meeting re transactions for Nov 1980. MAROTTA.C.R. Transportation Branch. 80/11/30. Врр. 07220:060.
- 8012160615 Forwards draft FR notice that two meetings of Advisory Panel for Decontamination of TMI-2 will be held on 801218 & 30.
 TRAVERS,W TMI Program Office. B0/12/01. 4pp. 07261:248.
- B012050412 Fulfills util B01013 commitment for safety evaluation of submarged demineralizer sys. Technical evaluation rept serves as both safety evaluation & environ impact evaluation. No Tech Specs changes required.

 HOVCY, O. K. Metropolitan Edison Co. 80/12/02. 1p. 07174:024.
- 8012110562 Responds to 80*121 for to UE Minnich re questions concerning error limits indicated in draft programmatic EIB. TMI-2 Advisory Panel should be notified of NRC disagreements Westinates prior to 801218 or 30 mosting. COCKRAN.T.B. Natural Resources Defense Council. 80/12/02. 4pp. 07225:241.
- 8012240495 Requests responses to comments on draft programmatic EIB redecontamination & cleanup of facility.corrections & suggested changes in Chapter 12 & summary by 810112.
 SNYDER, B. J. THI Program Office. 80/12/02. ip. 03808:251.
- 8012100458 Forwards Revision 1 to "Evaluation of Liner Integrity of TMI Unit 2 EPICOR-II Radwaste Bys." Worst credible situation has been assumed for parameters which might contribute to possibility of corrosion HOVEY.O.K. Metropolitan Edison Co. 80/12/04. 6pp. 07220:126.
- ---B012100458 Revision I to "Evaluation of Liner Integrity of TMI Unit 2 EPICOR-II Radwaste Sys." Attachments I & II to rept ancl, 07AC08BE,F. S., FREDERICKS,K.H. Metropolitan Edison Co. B0/12/02, 24pp. 07220:132.
- B012110407 Advises of adequate storage available for handling wastewater from continuing decontamination work EPICOR-II will not operate in near future.

 H0VEY.O.K. Metropolitan Edison Co. 80/12/04, 1p. 07223:003.
- B012110507 Responds to NRC 801107 ltr re submorged demineralizar sys. Specific processing options & associated dotails will be provided in revised environ rept. Responses to one question encl.
 HOVEY, O. K. Metropolitan Edison Ca. 80/12/04. 3pp. 07225:247.
- 8012310081 Forwards list of comments on draft programmatic EIS received after NRC 801126 ltr to util.Response should be submitted by 801219.

 8NYDER-B.J. TMI Program Office. 80/12/05. 2pp. 07371:158.
- BO12160273 Advises that sys configuration re reactor decay heat removal was improperly stated in 801204 ltr. Isolation valve remained closed in loss-to-ambient mode of core cooling until 801209, when switched to once-through Steam Generator A. HOVEY, G. K. Metropolitan Edison Co. 80/12/10. 2pp. 07261:347.
- 8012160367 Corrects error in util 801204 ltr re EPICOR-II liner evaluation status. Stated isotopic concentration release on Page 5 re staging module sump water applies to unrestricted areas only.

 HDVEY.O.K. Metropolitan Edison Co. 80/12/ii. 1p. 07261:184.
- 8012140452 Responds to 801023 & 1105 ltrs addressing concerns of Banator P Barbanes re public participation in cleanup review process & impacts on MD drinking water & Chesapeake Bay. No impact on downstream water users expected. HOVEY.O. K. Metropolitan Edison Co. 80/12/11, 3pp. 07269:133.
- 8012270411 Informs that EPICOR radwaste sys documents undergoing review by Ofc of Executive Legal Director to datermine if info is considered proprietary per 10CFR2.790.

 COLLINS.J.T. TMI Program Office. 80/12/11. 4pp. 03807:073.
- 8012190918 Submits description of cork seel contamination action taken to date & plans for future actions to mitigate effects of contamination Followup rept describing program for resolving problem will be submitted by 810116.

 HDVLY.O.K. Metropolitan Edison Co. 80/12/15. 7pp, 07273:271.
- 8012220237 Requests extension until 801231 to respond to public comments re draft programmatic EIS, HOVEY.O.K. Matropolitan Edison Go. 80/12/15. 1p. 07303:252.

- 8012220383 Forwards "Methodology & Calculation of Integrated Dose to EPICOR-II Prefilter-29." Revision 1. supplementing 801203 initial avaluation of potential corrosive effects to resin liners.
 HOVEY, G.K. Metropolitan Edison Co. 80/12/15. 2pp. 03797:008.
- --8012220388 "Methodology & Calculation of Integrated Dose to EPICOR-II Prefilter-29," Revision 1. DANIEL.J.A., SRASHE,J.W., SCHLOKER,E.A. Metropolitan Edison Co. 80/12/15, 44pp. 03797:010.
- 8012300621 Forwards corrected figures for programmatic EIB. One oversize drawing encl.
 HOVEY.O.K. Metropolitan Edison Co. 80/12/18, 3pp. 07374:017.
- 8012300629 Supplements 801215 ltr re evaluation of cork seal contamination problem % contamination concentrations of cork samples. Provides sample results for Location EU-3. No sample available at 36-inch depth due to cork deterioration. HOVEY, O. K. Metropolitan Edison Co. 80/12/19. 1p. 07346:164.
- 8012300641 Discusses resin solidification requirements of ANBI/ANS-53, 1-1979 & SRP Section 11.4. Bid for temporary cament solidification sys will ref requirements to alert bidders to available options. MOVEY, O.K. Metropolitan Edison Co. 80/12/19. 2pp. 07346:185.
- BOI2310318 Provides analyses of sample results for Location EH-3 recork seal contamination problem at facility. Cork in location has deteriorated to extent that no sample was available at 36-inch depth.

 HOVEY, O. K. Metropolitan Edison Co. BO/12/19. 1p. 07369:167.
- B012310324 Discusses resin solidification requirements presented at B01218 meeting w/NRC. Revised bid spec for temporary cement solidification sys will ref specified documents & contain options for assuring lack of free water in containers. HOVEY, O. K. Metropolitan Edison Co. 80/12/19. 2pp. 07369:168.
- BOI2300645 Forwards design criteria for mod for closure of reactor bldg Penetration 401. Mod to provide more permanent closure due to flooding potential caused by increase in reactor bldg water level. Mod to be performed prior to 810/31. HOVEY, Q. K. Metropolitan Edison Co. 80/12/23. 3pp. 07346:169.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012020321 Requests that response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) W/Lose of Offsite Power," be resubmitted w/oath or affirmation within 10 days of receipt of ltr.per 10CFR50.54.

 GRIER, B. H. Region in Philadelphia, Office of the Director. 80/10/23. 1p. 07143:115.
- B012170404 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. ORIER.B.H. Region i. Philadelphia. Office of the Director. 80/10/30. ip. 07269:116.
- 8012020791 Forwards resubmitted response to IE Bulletin 80-15 & required oath of affirmation per NRC 801023 itr. HUKILL, H. D. Metropolitan Edison Co. 80/10/31. 1p. 07147;332.
- --B012020799 Submits response to 1E Bulletin B0-15 w/required oath of affirmation per NRC B01023 ltr. Review of emergency notification sys conducted in conjunction w/Bell of PA. Bys will remain functional in event of loss of offsite power. HUKILL, H. D. Metropolitan Edison Co. B0/09/29. 3pp. 07147:333.
- 8012040613 Informs that installation of interlocks to upgrade protective features per IE Bulletin 80-05 will be completed by 801201, instead of 801101 as previously indicated. HQVEY.O. Metropolitan Edison Co. 80/10/31. 1p. 07170:090.
- S01230D153 Ack receipt of 801009 ltr informing NRC of steps taken to correct violation noted in IE Insp Rapt 50-320/77-29.

 GRIER, B. H. Region I. Philadelphia, Office of the Director.

 80/11/05. ip. 07356:27u.
- --8012300160 Responds to NRC 800726 ltr re violations noted in IE Insp. Rept 50-320/77-29, Updated corrective actions: implementation of 53-gallon frum color coding sys.
 HOVEY, G. K. Hetropolitan Edison Co. 80/10/09, 2pp. 07356: 271.
- 8012120141 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc. " Written response required. ORIER.B.H. Region 1. Philadelphia, Office of the Director. 80/11/04. 1p. 07230:200.

- 80f2190386 Informs util of issuance of new NRC personnel identification badges: effective after 801130. Example encl.
 MARTIN.It. J. Region 1, Philadelphia, Safeguards Branch. 80/11/06.
 3pp. 07286: 147.
- 8012030764 Forwards IE Info Notice 90-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/97. 1p. 07150:272.
- 8012080549 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. 1p. 07182:360.
- 8012040095 Forwards IE Bulletin BO-23, "Failures of Bolenoid Valves Mfg by Valtor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER. B.H. Region 1, Philadelphia, Office of the Director. BO/11/14. ip. 07158:015.
- 8012270651 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Hig by Valcor Engineering Corp." First paragraph erroneously stated no written response required.

 GRIER.B.H. Region 1. Philadelphia, Office of the Director. 80/11/19. 1p. 07295:050.
- 8012120398 Ack receipt of 791205.800519 & 0721 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/79-10. Forwards App A containing final evaluations of 800721 supplemental response.

 BTELLO.V. Office of inspection & Enforcement, Office of the Director. 80/11/20. 38pp. 07230:329.
- 8012040598 Forwards IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment." Unitten response required Requests info on manpower expended. GRIER, B.H. Region 1. Philadelphia. Office of the Director. B0/11/21. 2pp. 07149:202.
- 8012150025 Forwards response to util 791205 & 800519 ltrs re items of noncompliance noted in IE Investigation Rept 50-320/79-10. Unresolved items still remain. Addit commitments agreed to in App A must be completed on dates specified. App A enci. STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/11/21. 39pp. 07241:001.
- 8012090569 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B. H. Region i, Philadelphia, Office of the Director. 80/11/24. 1p. 07174:056.
- 8012150260 Requests relief from ASME Builer & Pressure Vessel Code, Section 11, of recovery operations plan for specific minidecay heat removal sys inservice insp criteria, Proposed surveillance requirements encl. HDV&Y, O.K. Metropolitan Edison Co. 80/12/09, 5pp. 07237:228.
- R. Periodic operating reports & related correspondence
- 8012020072 Forwards status rept for whof 801107-15. CDLLING, J. T. TMI Program Office. 80/11/17. 5pp. 07147:168.
- 8012(10425 Forwards weekly status rept for wk of 801116-22. COLLINS.J.T. TMI Program Office. 80/11/21. 5pp. 07225: 153.
- B012020482 Forwards observation wells data sheet inadvertently omitted from B01119 rept.
 RIETHLE, H. E. General Public Utilities QPU Service Corp. 80/11/24.
 3pp. 07148:129.
- 8012160473 Forwards "TMI Aquatic Study, Monthly Rept for Oct 1980."
 Requests NOREG-0596 re nonradiological consequences of facility accident on aquatic biota & fisheries of Susgehanna River.
 TEITT,T.R. General Public Utilities OPU Service Corp. 80/12/09.
 1p. 0/249:011.
- --8012160486 "TMI Aquatic Bludy, Monthly Rept for Dct 1980." NARDACCI.G.A. ichthyological Associates, Inc. 80/12/09. 27pp. 07849:012.

- 3. Reportable occurrences, LERs & related correspondence
- 3012040441 RO 80-50/1P:on 801f08.incore thermocouple 9-H failed.Further details to follow. HOVEY.O.X. Metropolitan Edison Co. 80/11/10. 2pp. 07158:198.
- 3012090383 Forwards LER 80-049/01L-0. HOVEY.O.X. Metropolitan Edison Co. 20/11/26. 1p. 07203:012.
- -B012090394 LER B0-049/Q1L-0: on B01027. ASME code stamped UV valve LTB-V171 discovered stamped by unauthorized valve supply house. Caused by unauthorized use of ABME UV code stamp by North American Safety Valve Industries. Inc. CHAPLIN. B. D. Metropolitan Edison Co. B0/11/25. 3pp. 07203:013.
- 3012100179 PNO-TMI-80-052: on 801127, survey of auxiliary bldg revealed unexpected levels of contamination in expansion joint (seam) which runs between svc bldg on one side & auxiliary bldg & air intabe tunnel on other side.

 THONUS, L. H., FASANO, A. N. Region 1, Philadelphia, Office of the Director, COLLINS, J. T. TMI Program Office, 80/11/28, 2pp. 07218:300.
- 3012130185 Forwards LER 80-050/01L-0. HOVEY, O. K. Metropolitan Edison Co. 80/12/08, 1p. 07241:142.
- --8012150183 LER 80-030/01L-0: an 801108; incore thermocouple H-9 exhibited stratic behavior Cause unknown & may not be possible to determine due to condition of core relative to incore instrumentation. Evaluation is in progress.

 CHAPLIN, S. D. Metropolitan Edison Co. 80/12/08. 2pp. 07241:143.
- BO12190092 PND-TMI-80-53:on BO1208.util issued press release stating that claim of four billion dollars was filed against ARC for negliprice re performance before TMI-2 incident & based on estimated cost of TMI-2 cleanup. CONTE.R., SHANBAKY.M., COLLINS.J. TMI Program Office. BO/12/08. 2pp. 07282:136.
- 3012160495 Forwards LER 80-031/03L-0. HGVEY.G.K. Metropolitan Edison Co. 80/12/ii. 1p. 07255:357.
- --9012160500 LER 80-051/G3L-0: on 801110, deficient fire barrier seal found, Caused by crack in seal number 3-484-51 which penetrated seal, Seal repaired & hourly fire watch maintained during repair period. CHAPLIM, 8. D. Metropolitan Edison Co. 80/12/10. 3pp. 07255:358.
- BO12190591 LER 80-056/01P-0:on B01212, level indication for A core flood tank failed. No cause stated. HOVEY, O. %. Metropolitan Edison Co. 80/12/15, 2pp. 07286: 156.
- 3012230475 Forwards LER 80-053/01L-0. HGYEY.O.K. Metropolitan Edison Co. 80/12/17. 1p. 07318:317.
- --8012230480 LER 80-053/03L-0: on 801117, incore thermocouples N-8 & N-9 exhibited erratic behavior. Cause undetermined. Bituation being evaluated. CHAPLIR. S D. Metropoliten Edison Co. 80/12/17. 2pp. 07318;318.
- 8012390490 Forwards LER 80-054/03L-0. HOVEY, O. K. Metropolitan Edison Co. 80/12/18. 1p. 07349:33B.
- --8012300493 LER 80-054/03L-0:on 801117 emergency diesel generator failed to start. Caused by heater failure due to magnetic contactor malfunction, Ambient shutdown temp maintained until heater & contactor replacement completed on 801216.
 CHAPLIN.S. D. Metropolitan Edison Co. 80/12/17. 3pp. 07349:339.
- T. Hearing transcripts on non-antitrust matters
- B012020330 Transcript of B01118 meeting in Washington DC re iodine release from accidents & estimates of consequences of nuclear accidents. Pp 1-102 > Commissioners. 80/11/18. 152pp. 07144:020.
- 8012040561 Forwards transcript of B01110 meeting in Harrisburg.PA re TMI-2 preliminary EIS. SNYDER.B.J. TMI Program Office. B0/11/24. 2pp. 07157:276.
- --8012040557 Transcript of 801110 public meeting in Harrisburg, PA re TMI-2 preliminary EIS. Pp 1-118 # Commissioners. 80/11/10 120pp.
- 8012110454 Forwards transcript of 801117 public maeting in Middletown: FA ra draft EIS, SNYDER.B.J. TMI Frogram Office. 80/11/24, 2pp. 07224:212.

- --8012110461 Transcript of 801119 meeting in Middletown,PA re draft programmatic EIS. Pp 1-95.

 d Commissioners. 80/11/19. 95pp. 07224:214.
- 8012110590 Forwards transcript of 801117 meeting in Baltimore,MD re programmatic EIS: SNYDER,B,J, TMI Program Office, 80/12/08, 2pp. 07222;219.
- --B0[21:0502 Transcript of B01:17 public meeting in Baltimore, MD recleanup on TM1-2, Pp 1-117.
 4 Commissioners. B0/11/17. 119pp. 07222; 221.
- U. Congressional/Executive Correspondence
- 8010300535 Advises that info contained in 800910 ltr has been incorporated into IE investigation of info flow from facility on 790328.

 AHEARNELJ.F. Commissioners. 80/10/16 1p. 06836:038.
- --8010300539 Advises that info contained in 800910 ltr has been incorporated into IE investigation of info flow from facility on 790328.

 AHEARKE.J.F. Commissioners. 80/10/16. lp. 06836:039.
- --B010300544 Submits add1 questions re info flow from facility on 790326 to be considered in current IE investigation. Requests info re util reporting requirements for uncovered core. HART, O., SIMPSON,A.K. Senate, Environment & Public Horks. B0/09/10. 3pp. 06936:040.
- 8012030/48 Discusses 801117 public meeting in Baltimore, MD re draft programmatic EIS re TMI-2 cleanup in response to 801016 ltr. Meeting utli be third conducted in HO. AHEARNE, J. F. Commissioners. 80/11/04. 1p. 07149:300.
- 8012030762 Responds to 800828 ltr expressing concern re estimated health effects of facility cleanup on workers. Risks for cleanup workers are generally less than or commensurate w/ hazards experienced by workers in other fields.

 AHEARNE, J. F. Commissioners. 80/11/17. 2pp. 07149:293.
- --8012030769 Expresses concerning health effects of facility cleanup on workers. Safer cleanup methods should be developed to protect workers & public.
 ERTELIA.E. House of Rep. 80/08/28. 1p. 07149:295.
- 8012030814 Responds to 801004 ltr urging public hearings re draft programmatic EIS on TMI-2 cleanup. Meetings have been held in PA & MO u/state & local officials & verbatim transcripts have been made, M/o encl NUREGS & related info. DIRCKS: M. J. Office of the Executiva Director for Operations. BO/11/19. 2pp. 07149:266.
- --B012030B27 Urges holding of public hearings re TMI-2 cleanup. Hearings only way to restore public confidence in NRC. Advisory Panel on TMI-2 cleanup should include substantial percentage of private citizens.
 HEINZ, J. Senate. 80/10/14. ip. 07149: 268.
- B012100664 Responds to B01003 ltr re draft programmetic EIS on TMI-2 cleanup. Keetings instituted w/MD & PA officials as one means of assuring adequate public input. Transcripts made to ensure record is available for final EIS.

 SNYDER, B. J. TMI Program Office. 80/11/26. 2pp. 07222:177.
- ---B012100668 Comments on NUREO-0683, draft programmatic EIS on TMI-2 cleanup, Public hearings should be held to restore public confidence.

 GUDDLING, B. House of Rep. B0/10/03. 1p. 07222:179.
- DOCKET 50-321 EDHIN I. HATCH NUCLEAR PLANT, UNIT 1
 P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISENHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- 8012220338 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by OE Applicable to all license applications & proposed amends, including core reloads.

 EISERHUT, D. O. Division of Licensing. 80/11/04, 4pp.

- 80:2220563 Ltr to all power reactor licensees forwarding NUREO-0619. "BUR Feedwater Nottle % Control Rod Drive Return Line Nottle Gracking." Confirmation that implementation dates will be mat must be sent within 45 days. M/o encl. EIBENHUT.D.O. Division of Licensing. 80/11/13. 1p.
- 8012080507 Informs that refund has been authorized for 801015 Classes I & II license amend application fees. Review of FSAR revisions not necessary.

 MILLER.W. D. License Fee Management Branch. 80/11/25. ip. 07194.330
- BO12090383 Advises of compliance w/order for mod of licenses concerning environ qualification of safety-related electrical equipment. Complete & auditable records file of environ qualification method per IE Bulletin 79-01B established.

 KELLY.R. J. Georgia Power Co. B0/12/01. 1p. 07207:143
- BD12220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION. M.R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. Bpp.
- 8012230364 Forwards confirmation of compliance re items in NUREO-0737, "Clarification of TMI Action Plan Requirements," per NRC 801031 request. WIDNER, M.A. Georgia Power Co. 80/12/15. 9pp. 07314:104.
- G. Inspection reports, IE Builetins & correspondence
- B012090513 Forwards IE Insp Repts 50-321/80-40 & 50-366/80-40 on B00924-25. No noncompliance noted. MURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. B0/10/22. 2pp. 07206:203.
- --B012090517 IE insp Repts 50-321/80-40 & 50-366/80-40 on 800924-25. No noncompliance noted Major areas inspected: containment liner penetration welds, followup of noncompliances re inservice insp & certification of inspectors.
 ZAJAC, L. D. Region 2, Atlanta, Office of the Director. HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/17. 4pp. 07206:205.
- 8012030817 Forwards util 801015 ltr to Director of Nuclear Reactor Regulation requesting approval of exceptions to ANSI stds to correct infractions noted in IE Insp Repts 50-321/80-28 & 50-366/80-28 WIDNER, M. A. Georgia Power Co. 80/10/23. 1p. 07149:264.
- 80:2130198 Forwards IE info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24.

 1p. 07240:283.
- BO12170286 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.
- 8012170286 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
 O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/24.
 1p. 07268:295.
- 8012170016 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/31. ip. 07264:130.
- 8012230067 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators," No written response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31. ip. 07313:234.
- 8012110732 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06. 1g. 07229:215.

- 8012030897 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Causa Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. BO/11/07. 1p. 07150:109.
- 8012080333 Forwards IE Info Notice 80-41, "Failure of Swing Check Valva in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/10. 1p. 07182:288.
- B012040189 Forwards IE Bulletin 80-23. "Failures of Splenoid Valves M/g by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. B0/11/14. 1p. 07158:100.
- 8012020803 Ack receipt of 801013 itr & check in payment of civil penalty imposed by NRC 800924 order.
 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/11/17. 2pp. 07145:312.
- 8012040474 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Written response required. Requests info on manpower expended. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/21. 1p. 07163:334.
- 8012240235 Responds to IE Bulletin 80-23 re solenoid valves V70900-21-1,V70900-21-2 & V70900-21-3,mfg by Valcor Engineering Corp. Valves not used at facilities. WIDNER, U. A. Georgia Power Co. 80/11/21. ip. 07328:217.
- B012080029 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, P. Region 2. Atlanta, Office of the Birector. 80/11/24. 1p. 07182:169.
- B012110329 Ack receipt of 801113 itr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-321/80-36 & 50-366/80-36 MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch.
- --8012110532 Responds to NRC 801027 ltr re violations noted in IE Insp Repts 50-321/80-36 & 30-366/80-36. Corrective actions: fire protection & loss prevention audit conducted & fire watch established. WIDNAR, U. A. Georgia Power Co. 80/11/13. 2pp. 07226: 154.
- --8012110534 Forwards IE Insp Repts 50-321/80-36 & 50-366/80-36 on 800916-19 & notice of violation. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/27. 2pp. 07226:136.
- --8012110537 Notice of violation from insp on 800916-19.

 * Region 2, Atlanta, Office of the Director. 80/10/21, ip. 07226:158.
- --8012110539 IE lnsp Repts 50-321/80-36 & 50-366/80-36 on 800916-19.
 Noncompliance noted failure to conduct annual audit of fire protection program & presence of nonfunctional fire doors.
 MILLER, W. H. Region 2. Atlente. Office of the Director.
 CCNLON, T. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/21. 8pp. 07226:139.
- 8012170517 Forwards IE Info Notice 80-29.Suppl 1. "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/26. lp. 07268:109.
- 8012090085 Advises of compliance w/order for mod of licenses concerning environ qualification of safety-related electrical equipment. Complete & auditable records file of environ qualification method per IE Bulletin 79-018 established. KELLY.R. J. Georgia Power Co. 80/12/01. 1p. 07207:143.
- SO12230064 Responds to IE Builetin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17,1980 Indian Point 2 avent)." Containment imsp for water leakage will be perforced at first cold shutdown KELLY,R.J. Georgia Power Co. 80/12/01. ip. 07311:080.
- R. Periodic operating reports & related correspondence
- 8012230792 Forwards monthly operating rept for Nov 1980. MAMMY.M.. Georgia Power Co. 80/12/10. 1p. 07318:042.

- --8012230295 Monthly operating rept for Nov 1980. UNDERWOOD, P. R. Georgia Power Co. 80/12/10. 8pp. 07318:043.
- S. Reportable occurrences, LERs & related correspondence
- 8012010325 Forwards LER 80-114/03L-0. MANRY, M. Georgia Power Co. 80/11/20. 1p. 07092:155.
- --B012010346 LER B0-114/03L-0: on 801027-HPCI steamline low pressure switches LE41-N001A-D actuated outside Tech Specs. Caused by setpoint drift. Instruments recallbr. NIX-R.T. Georgia Power Co. 80/11/20. 2pp. 07092:157.
- 8012010377 Forwards LER 80-111/09L-0. MARRY.M. Georgia Power Co. 80/11/24, [p. 07091:289.
- --8012010394 LER 80-111/03L-0:on 801105 automatic depressurization systemation water level switch 1821-N042A actuated above Tech Specs. Caused by component failure due to galling of range adjusting screen.Level switch replaced.

 MIX.R.T. Georgia Fower Co. 80/11/24. 2pp. 07091:290.
- 6012090379 Forwards LER 80-117/031-0.
 MANAY, N. Georgia Power Co. 80/12/02. ip. 07203:009.
- --B0[2090334 LER B0-]17/03L-0: on B0[104-no transfer authorizations discovered for receipt of two shipments of low power range monitors & one shipment of source range & radiation monitors. Caused by misinterpretation of procedures. COGOIM.C.L. Georgia Power Co. B0/[2/02. 2pp. 07203:010.
- 8012290240 RO: on 801031, at 1400~h it was determined that smake detectors were not installed per NFFA Code 72D. Cause not stated. Analysis being made of all detection sys & design work for affected sys Initiated. HANRY, M. Georgia Power Co. 80/12/04. 2pp. 07942:339.
- 8012240244 Forwards LER 80-113/03L-0. MANRY, M. Georgia Power Co. 80/12/16. 1p. 07325:115.
- --8012240248 LER 80-113/03L-0: on 801201, nitrogen storage tank inventory found reduced to less than Tech Spec requirements. Caused by addition of nitrogen to drywell to reduce oxygen to level required by HNP-1-1030 survestilance checks. Tank refilled.

 BAXLEY, S. X. Georgia Power Co. 80/12/16 2pp. 07325:116.
- 80(2290325 Forwards LER 80-(20/03L-0. MANNY, M. Oeorgia Power Co. 80/12/19. 1p. 07332: 289.
- --BO(22903:35 LER BO-120/03L-0: on BO(214 nitrogen storage tank contents found to be less than Tech Spec requirements. Caused by primary containment inerting. Nitrogen tank level restored. BAXLEY.S. X. Georgia Fower Co. BO/12/19. 2pp. 07332: 290.
- DOCKET 50-322 SHOREHAN NUCLEAR POWER STATION
- A. Application/construction stage documents & correspondence
- 8012160030 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREC-0737 rs Thi action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates with be met. EISELOHUT.D. 0. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP % OL holders for BKRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends including core reloads.

 EISENHUT. D. O. Division of Licensing. 80/61/04. 4pp.
- 8012010484 Forwards Suppl 1 to NURLO-0487, "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria."
 Deviations along w/bases for deviations, are to be documented in design assessment rept during review of FBAR, YOUN031GOD, B. J. Licensing Branch 1. 80/11/10. 2pp. 07092:015.
- 8012100214 Notification of 801202 meeting w/SWR licensing review group in Bethesda ND to discuss status of group issues.
 WILSON J. M. Licensing Branch 1. 80/11/20. 8pp. 07217:304.
- 8012040075 Forwards requests for add1 info resulting from OL application review. Info needed in areas of core performance, chemical:nechanical, hydrologic & melis engineering & power sys. Requests preliminary control room assessment. TEOESCO.R.L. Assistant Director for Licensing. 80/11/21. https://doi.org/10.1201/10.11/21.

- BO12040717 Discusses NRC review of schedular requirements for special low power test program & emergency procedures. Lists schedular requirements to be met. Evaluation to be completed in conjunction w/facility full power ascension program. TEDESCO.R.L. Assistant Director for Licensing. BO/11/21. 2pp. 07170:046.
- 8012010080 Requests extension of CP until 830331 for completion of facility.Lists reasons for extension. Fuel load date scheduled for 820531.

 NOVARRO, J. P. Long Island Lighting Co. 80/11/26. 3pp. 07098: 203.
- B012020706 Forwards util B01126 request to extend completion date from B01201 to B30031. GILMARIIN.D.H. Atomic Safety and Licensing Board Panel. 80/11/28. Ip. 07147:291.
- --B012020723 Requests extension until 830331 to complete facility due to new regulatory requirements, late equipment delivery & unexpected difficulties in completing mods. NGVARRD, J. P. Long Island Lighting Co. 80/11/26.
- 8012100276 Forwards proprietary NEDC-24753, "Final Test Rept for Safety/Relief Valve Cold Water Flow Tests." Valves can be used to establish & maintain alternate cooldown path from reactor pressure vessel to suppression chamber. H/o encl. NOVARRO, J. P. Long Island Lighting Co. 80/12/01. 1p. 07219:357.
- 8012110768 Notification of 801216 meeting w/util in Bethesde.MD reorganization for managing & operating facility, MILSON.J.N. Operating Reactors Branch 1. 80/12/01. 3pp. 07225:089.
- 8012160150 Notification of 801210 meeting w/Mark II owners group in Bethasda, MD to discuss status of improved chugging load program. ANDERSON.C. Generic Issues Branch. 80/12/02. ip. 07263:029.
- B012150P16 Forwards Amends 3B to GL application consisting of Revision 20 to FBAR, providing response to NRC Request 420, 45, revisions to see water sys design & controls & minor corrections & clarifications. Affidavit encl.
 NOVARRO, J. F. Long Island Lighting Co. 80/12/05. 2pp. 07240:132.
- --8012150220 Amend 38 to application for OL. consisting of Revision 20 to FSAR, NOVARRO, J.P. Long Island Lighting Co. 80/12/05. 44pp. 07240:134.
- 8012160032 Notification of 801212 meeting w/Hark II owners group in Bethasda:ND to discuss suppression pool temp limit, SU.T.K. Generic Essues Branch. 80/12/05, 1p. 07263:021.
- 8012170283 Summary of 801202 meeting u/DWR licensing review group. Bechtel & 8%W in Bethesda.MD re current status of issues & fire protection concerns. Rept on LaSalle specific issues encl.
 WILSON, J. M. Licensing Stanch 1. 80/12/05, 21pp. 07268: 264.
- 8012220131 Summary of 800514-0828 meetings w/BKR Licensing Review Ordup in Bethesda. MD re identification of generic issues, formation of consensus positions & resolutions that will apply to all six plants. Draft working paper encl.
 WILSON, J. N. Licensing Branch 1. 80/12/05, 99pp. 07307:055.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8012300477 Discusses facility SER & NRC first monthly status rept to Bevill Bubcommittee.dtd 801121.NRC should complete & issue SER within next few wks.Further delays will cause pointless harm to nat! energy pointly & util customers.
 POLLOCK.M.S. Long Island Lighting Co. 80/12/22, 3pp. 07347:061.
- F. Security, medical, emergency & fire protection plans
- 8012040141 Public version of "Independent Assessment of Evacuation Times for Shoreham Nuclear Power Plant," Vol 9, prepared for FEISA. COSBY, J. C. . SKEPPARD, W. V. , BROWNER, H. D. Wilbur Bmith & Associates. 80/06/30, 47pp. 07161:001.
- 8012040004 Summary of 800801 meeting w/util in Silver Spring, MD reconcurns w/recent revisions to security plan. Details withheld (ref 100FR9, 12). WILEON, J.N. Operating Reactors Branch 1. 80/11/21. 4pp. 07169:276.

- 8012040045 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," eracutive summary. FELIDK.J.H. Division of Rules and Records. 80/12/03. 1p.
- --Boi20400BB Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive surmary, prepared for FEMA. # Wilbur Smith & Associates. 80/06/30. 17pp.
- --8912040155 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol 1.prepared for FEMA. COSBY. J. C. Wilbur Smith & Associates. 80/06/30. 43pp.

G. Adjudicatory correspondence

- 8012300049 Order granting 801208 joint motion for extension to complete particularization of Contention 19 due to vol of matls to be reviewed.

 BOWERS.E.S. Atomic Safety and Licensing Board Panel. 80/12/09. 1p. 07336:147.
- 8012290001 Notice that parties will stipulate to submit redrafted Contention 19 subj to further particularization. LATHAM,S B. Twomey, Latham & Schmitt. 80/12/10, 2pp. 07344:187.
- BO12290244 Notice of Comptroller General B01203 opinion re NRC 800725 notice of cost reduction program. Procedural assistance in adjudicatory licensing proceedings is unlawful. BOHERS.E.S. Atomic Safety and Licensing Board Panel. B0/12/16. 1p. 07308:001.
- 8012300138 Responds to T Earley 801209 & 11 ltrs.Forwards draft of fifth stipulation re certain Suffolk County contentions. BORDENICK, B. M. Hearing Branch 4. 80/12/17. 5pp. 07347:187.
- BO12300556 Position re contideration of Class 7 accidents in license proceeding. No special circumstances exist. Under Commission interim policy Class 7 accidents will not be considered. Certificate of Svc encl.
 BORDENICK.B.M. Hearing Branch 4. B0/12/24, Spp. 07361:359.

H. General correspondence

- BD12050373 Forwards summary of functional responsibilities within util nuclear organization.Organization chart encl. PDLLOCK.M.S. Long Island Lighting Co. 80/11/25. 4pp. 07175:065.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012150216 Forwards Amends 3B to OL application, consisting of Revision 20 to FBAR, providing response to NRC Request 420, 45, revisions to svc water sys design b controls & minor corrections & clarifications. Affidavit encl. NOVARRO, J. P. Long Island Lighting Co. 80/12/05, 2pp. 07240:132.
- --8012150220 Amend 38 to application for DL consisting of Revision 20 to FSAR. NOVARRO, J. P. Long Island Lighting Co. 80/12/05. 44pp. 07240: 134.

M. Antitrust correspondence

- 8012180348 Advises of util 800930 ltr submitting updated info for antitrust review of OL application.FR notice encl. YOUNGGLOOD, B. J. Licensing Branch 1. 80/12/03. 2pp. 07271:261.
- --8012150067 Notice of receipt of updated info for antitrust review of OL application.
 YOUNGBLOOD, B. J. Licensing Branch 1. 80/12/03. 3pp. 03779: 165.
- 8012190265 Forwards FR notice re receipt of updated info for antitrust review of OL application.
 YOUNGRLGOD, B. J. Licensing Branch 1. 80/12/03, 2pp. 07285:304.
- 8012240294 Forwards FR notice of receipt of updated info for antitrust review of OL application.
 YOUNGELOOD, B. J. Licensing Branch 1. BO/12/03. 4pp. 07325:071.

- O. Inspection reports, IE Bulletins & correspondence
- 8012110389 Forwards IE Insp Rept 30-322/80-14 on 800811-0914 & notice of violation BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/08. 2pp. 07227:156.
- --B012110594 Notice of violation from insp on B00811-0914.

 * Region 1, Philadelphia, Office of the Director. B0/10/08. 1p. 07227:158
- ---BO12110597 IE lnsp Rept 50-322/80-14 on BO0811-0914.Noncompliance noted vent lines & valves installed ω/ο authorizing engineering & design coordination repts.
 HIGGINS-J.C. Region 1. Philadelphia, Office of the Director.
 KISTER-H.B. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. BO/10/08 10pp.
- 8012240717 Ack receipt of 801020 ltr informing NRC of steps Eaken to correct violations noted in IE insp Rept 50-322/80-15. CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/11/04. 1p. 07325:054.
- --8012240221 Responds to NRC 800717 ltr re violations noted in IE Insp Rept 50-322/80-15. Corrective actions: preparation of supplemental insp rept verifying implementation of stroking requirement on safety-related snubbers. POLLOCK, M. S. Long Island Lighting Co. 80/10/20. 2pp. 07325:055.
- --8012240226 Forwards IE Insp Rept 50-322/80-15 on 800825-28 & notice of violation.
 CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/17. 2pp. 07325:057.
- --8012240228 Notice of violation from insp on 800825-28.

 * Region 1, Philadelphia, Office of the Director. 80/09/16. 1p. 07325:059.
- --8012240233 IE Insp Rept 50-322/80-15 on 800825-28. Noncompliance noted: lack of evidence snubbers had been stroked in accordance w/ specified requirements during receiving insp. MARRON.L., MEBREARTY, R.A. Region i, Philadelphia, Office of the Director. MCGAUGHY, R.W. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/16. 8pp. 07325:060.
- 8012310414 Submits follows response to IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes." Transmitters will be replaced by June 1981.
 NOVARRO, J. P. Long Island Lighting Co. 80/11/05. 3pp. 07349:226.
- 8012120167 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06 1p. 07228:329.
- 8012030815 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuriation "No written response required. CRIER, B. H. Region I. Philadelphia, Office of the Director. 80/11/07. ip. 07150:065.
- 8012080446 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Bosse Unit 1." No response required. ORIER, B.H. Region I, Philadelphia, Office of the Director. 80/11/10. ip. 07182:321.
- B012040C96 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 ORIER. B. H. Region 1. Philadelphia, Office of the Director.

 80/11/14. 1p. 07157:343.
- 80:2270686 Advises that written response is required to IE Bulletin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.

 ORIER, B. H. Region I. Philadelphia, Office of the Director.
 80/11/19. 1p. 07293:117.
- 8012040395 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Nater Leakage Inside Containment." No written response required. GRIER. B. H. Region i, Philadelphia, Office of the Director. 80/11/21. 2pp. 07165:195.

- BD12050563 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snobber Fluid " No Unitten response required GRIER, B. H. Region 1. Philadelphia, Office of the Director BO/(1/24, 1p. 07174:050
- 8012180301 Forwards Revision 4 to Procedure 80A0481,Revision 8 to Procedure 80A2741 & Revision 4 to Procedure 80A0482 for preservice insp program.

 NOVARRO, J. P. Long Island Lighting Co. 80/12/09. 1p. 07271:219.
- --8012:80304 Preservice Insp program.Procedure B0A0481.Revision 4 to "Ultrasonic Exam Procedures For Piping Butt Welds & Longitudinal Nelds." # Nuclear Energy Service, Inc. 80/07/11. 31pp. 07271:220.
- --B012183309 Preservice insp program,Procedure B0A2941,Revision B,
 "Master Document List,"
 4 Nuclear Energy Service, Inc. B0/09/05. 2pp. 07271:251.
- --8012183311 Procedure 8040482.Revision 4. "Preservice Insp Program
 - Plan." * Nuclear Energy Service, Inc. BD/09/05. Spp. 07271:255.
- S. Reportable occurrences, LERs & related correspondence
- B012240127 Part 21 rept re jamming of 4-inch & 6-inch swing valves into open position. Caused by disc nut lock-wire jammed against machined relief in body. Velan has replaced 4-inch valves & re-oriented lock-wire on 6-inch valve.

 VELAM P. D. Velan Valve Co. 80/11/05, 4pp 07187:001.
- 3012120618 Deficiency rept re inoperable GE circuit breaker limit switches resulting in failure of suitch contacts to close. Causes by loosened limit switches. Screws will be tightened & Lock-tite applied.

 HILD.P.A. Stone & Webster Engineering Corp. 80/12/02. 4pp. 07236: 297.
- S01212053B Part 21 rept re dofective Square D Co starters Armature bumpers tend to stick inside starter case resulting in failure of starter or contactor to close. Caused by misapplication of lubricant Defective units to be replaced. HILD.P.A. Stone & Webster Engineering Corp. 80/12/02. 4pp. 07230:185.
- OCKET 50-323 DIABLO CANYON NUCLFAR PERER PLANT, UNIT 2 A. Application/construction stage documents & correspondence
- 3012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 (applementation dates will be net. EISENHUT, D. O. Division of Licensing, 80/10/31, 7pp.
- 2012110835 Forwards ACRR 831112 ltr re review of util study re interactions of failure of nonsafety sys on plant safety as result of carthquake. MIRAGLIA:F.J. Licensing Branch 3. 80/11/17. Spp. 07227:214.
- B012050430 Forwards response to NRC B00B27 ltm re containment pressure boundary fracture toughness. Info certifying that fracture toughness acceptance stds have been met is available at plant site.

 GRANE, P. A. Pacific Gas & Electric Co. B0/11/21, 41pp, 07171:272,
- B0120B0335 Forwards response to NRC 7B0125 ltr re long-term overpressure transient protection. Includes description of long-term sus to be employed at facilities.

 CRANE-P.A. Pacific Gas & Electric Co. B0/11/21. 10pp. 07190:285.
- S012040520 Forwards responses to NRC 800108 itr re implementation of recommendations of NUREG-OA60. "Enhancement of Onsite Emergency Diesel Generator Reliability." CRANEP.A. Parific Gas & Electric Co. 80/11/25. 5pp. 07157:271.
- BO12090329 Informs of planned temporary shutdown of basic seismic instrumentation sys at facility. Shutdown required to enable licensee to install panels for post-accident monitoring sys in control room, CRANE.P.A. Pacific Gas & Electric Co. 80/11/25. ip. 07201:161.
- BO12120308 "Concentration & Speciation of Copper in Waters Collected Near San Chofre & Diablo Canyon Nuclear Power Stations." HARRISON,F.L. Lawrence Livermore Laboratory. FIN A-0119. NUREO/CR-0750. 80/11/30. 66pp. Available at NTIS.

- 8012090350 Provides info on environ qualification of safety-related equipment per 801001 request Description of valve flow monitor sys & power supply cable presented in detail. CRANE, P. A. Pacific Gas & Electric Co. 80/12/01. 2pp. 07201:119.
- 8012050293 Responds to requirements specified in Suppl 10 to NUREO-0675 Mods addressed:procedure for dissemination of operating experience, vendor review of low power program, agreements to pool resources w/utils & inadequate core cooling.

 CRANE, P. A. Pacific Gas & Electric Co. 80/12/02. 60pp. 07171:211.
- 8012090235 Responds to NRC 800827 ltr re Review Question 5. Response provides commitments & completion schedule for upgraded meteorological program & is organized to address four essential elements in KUREO-0554.App 2
 CRANE.P.A. Pacific Gas & Electric Co. 80/12/02. 3pp. 07201:148.
- 8012110524 "Forwards procedure for dissemination of operating experience, vendor review of low power test program procedures & low power test program safety analysis rept. per 8uppl 10 to NUREC-0475, facility SER.
 CRANE.P.A. Pacific Oas & Electric Co. 80/12/02. 4pp. 07225:327.
- --8012110539 Nuclear Plant Administrative Procedure W-100, "Dissemination of Operacing Experience." Westinghouse review of special low power test procedures encl.

 * Pacific Gas & Electric Co. 80/11/26. 7pp. 07225:331.
- --8012110533 "Diablo Canyon I Special Low Power Tests Final Bafety Evaluation Rept." * Pacific Gas & Electric Co. 80/10/31. 49pp. 07225:338.
- 8012100470 Discusses field audit of electrical separations conducted in response to NRC 791130 itr. Audit demonstrated that electrical equipment & sys have been installed in manner which provides independence & separation per FSBA. CRANE, P. A. Pacific Cas & Electric Co. 80/12/04. 2pp. 07219:025.
- 8012180132 Describes actions taken as result of TMI accident re safety requirements of near-term OLs.All requirements must be met, applicant must appear before ASLB & record must be reviewed by Commission before ion power testing.

 MIRAGLIA.F. Licensing Branch 3. 80/12/04. 2pp. 07272:284.
- 8012270485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON-H.R. Diffice of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220505 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANOART, R. L. Effluent Treatment Systems Branch. B0/11/06. Bpp.
- 8012290136 Responds to J Stol: 791130 ltr re field audit of electrical separations. Audit indicated equipment & sys installed per FEAR requirements Audit results contained in Amend 51 to GL application.

 CRANE: P. A. Pacific Gas & Electric Co. 80/12/04. 2pp. 07344:049.
- 8012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Committee. MIRAGLIA.F. Licensing Branch 3. 80/12/05. 3pp.
- 8012160158 Forwards preliminary emergency operating procedures, incorporating handwritten changes made during NRC review in conjunction w/facilities operations staff. GRANE,P.A. Pacífic Oas & Electric Co. 80/12/08. 94pp. 07254:001.
- 8012290086 Forwards proposed license authorizing util to load fuel, proceed to initial criticality perform startup testing & operate at 5% rated power. List of exemptions to Tech Specs encl. Related correspondence.

 CRANE.P.A. Pacific Oas & Electric Co. 80/12/16. 9pp. 07343:001.
- 8012290077 Unexecuted license for fuel loading & low power testing. List of stemptions to Tech Specs for low power test program DEMIGN.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/19. 8pp. 07336:317.

- F. Security, medical, emergency & fire protection plans
- 8012110384 Responds to NRC 800827 ltr re Review Question 5 Response provides commitments & corresponding completion schedule for upgraded meteorological program. Commitments may be altered upon final promulgation of draft NUREG-0654. CRANE, P. A. Pacific Gas & Electric Co. 80/12/02. 3pp. 07223:096.
- 8012240118 Releases public version of util emergency plan. FELTON, J. M. Division of Rules and Records. 80/12/12. 1p.
- --B012240129 Forwards public version of App 1 to Revision 2 of corporate emergency response plan.
 CRANE, P. A. Pacific Cas & Electric Co. 80/03/21. 1p.
- --8012240134 Public version of App 1 to Revision 2 of corporate emergency response plan.

 + Pacific Oas & Electric Co. 80/03/20. 9ipp.
- 8012290464 Releases public version of "Evacuation Times Assessment for Diable Canyon Nuclear Power Plant Sept 1980." FELTOK J. M. Division of Rules and Records. B0/12/16. 1p. 07338:001.
- --8012290469 Forwards public version of "Evacuation Times Assessment for Diable Canyon Nuclear Power Plant, Bept 1980," in response to MRC 800702 request Includes App A re evacuation times for designated sub-areas. CRANE, P. A. Pacific Gas & Electric Co. 80/11/25, 1p. 07338:053.
- --B012270473 Public version of "Evacuation Times Assessment for Diablo Canyon Nuclear Power Plant. Sept 1980."

 + PRC Planning & Economics, Alan M. Voorhees & Associates Div. B0/09/30. 190pp. 07338:054.
- 8012300345 Advises that util agrees to assume responsibility for installation of early warning sys required by applicable federal regulations. Commitment will terminate on permanent cassation of operations at facility.

 SCHUYLER, J. O. Pacific Gas & Electric Co. 80/12/24. 3pp. 07346: 268.
- Q. Adjudicatory correspondence
- BO11250100 Submits DS Fleischaker B01017 ltr to HR Denton as comments on proposed rule 10CFR30, "Domestic Licensing of Production & Utilization Facilities: Consideration of Degraded or Melted Core in Bafety Regulations."
 REYNOLOS, J. Center for Law in the Public Interest. B0/10/31. 1p. 07034:157.
- --B01125010B Requests on behalf of Joint Intervenors to Diablo Canyon OL proceeding that NRC prepare supplemental EIS considering environ consequences of Class 9 accidents. FLEISCHAKER, D. Fleischaker, D. S. 80/10/17. 4pp. 07056:158.
- 8012020020 Ack receipt of 801017 request, on behalf of joint intervenors in OL proceeding for NRC action to prepare supplemental EIS re Class 9 accidents. Request will be treated under 10CFR2. 206.
 DENION, H. R. Office of Nuclear Reactor Regulation, Director. 80/11/19. 1p. 07148:307.
- --8012020023 Notice of D Fleischaker request on behalf of joint intervenors, for action under 10CFR2.206.
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/11/19. 2pp. 07148:308.
- 8012050453 Notifies that ASLAB has received encl ACRS 801112 ltr to JF Ahearne re PO&E studies on possible adverse interactions of nonsafety sys on plant safety. Requests study status & relevance to current issues BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/11/24. 1p. 07173:316.
- 8012290002 Request for extension to 801215 for filing Governor EG Brown findings of fact ½ conclusions of law re seismic proceedings. Granted for ASLAB on 801203. OEDROIDU, 8.S., BROWN, H. H., LANPHER, L. C. California, State of, 80/12/02. 1p. 07344:109.
- B012290161 Request for 1-wk extension to B01215 for filing Governor Brown findings of fact & conclusions of law NRC. San Luis Obispo Mothers for Peace & PG&E agreed to extension NRC & PG&E also granted 1-wk extensions.

 QEOROIOU, B. S. GRONN, H. H. , LANPHER, C. California, State of B0/12/02, 4pp. 07344:140.

- 8012080513 Submits contentions re-motion for license to load fuel & conduct low power testing Neither short nor long-term requirements of NVREO-0694 nor implementation measures sufficient. Certificate of Svc encl.
 FLEISCHAMER, D. Fleischaler, D. S. PHILLIPS, J. R., REYNOLDS, J. R. Center for Law in the Public Interest. 80/12/03 16pp. 07183:106.
- 8012270120 Request for directed certification re application of NRC 800620 statement of policy re guidance for power reactor OLs. Safety issues not included in NY3EC-0674 should be admitted as contentions. NYCertificate of Svc. REYNOLDS, J. R., FLEISCHAKER, D. Center for Law in the Public Interest. FLEISCHAKER, D. Fleischaker, D. S. 80/12/03. 33pp. 07344:010
- B012270662 Statement of subjs on which CA Governor Brown intends to participate per ASLB 801024 & 1905 orders. Concerns util motion for licenses for fuel loading & low power testing. Certificate of Svc encl.

 GEOROIOU, B. S. . BROWN, H. H. California, State of BROWN, H. H. Hill Christopher & Phillips. 80/12/03. 9pp. 07333:088.
- 8012090286 Forwards 1 Aditya 803119 ltr to NRC, for placement in PDR & for svc on parties to proceeding.
 BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/12/04.
 15. 072031097.
- --B012090287 Opposes licensing of facilities on basis of poor seismic design. San Francisco Chronicle B01110 article encl.
 ADITYA, I. Affiliation Unknown. B0/11/19. 2pp. 07201:100.
- 8012290392 Notice of corrections to Joint Intervenors' statement of containtions & request for directed certification. Certificate of Svc ancl.

 REYNOLDSI.J.R. Center for Law in the Public Interest. 80/12/08.

 Spp. 07336:224.
- 8012300117 Hotion to stay proceeding on PG&E motion for licenses for fuel loading & low power testing until NRC prepares EI8 or, alternatively, EIA & util submits environ rept. Certificate of Svc encl.
 GEGROIOU, B. S., BRONN, H. H. California, State of, BROWN, H. H. Hill Christopher & Phillips. 80/12/08. 9pp. 07356:243.
- 8012110578 Submits resolution passed at executive board 800922 meeting. Resolution process const expenditures be redirected toward conversion to safery.more socially acceptable fuel sources. COMRAD.C. Affiliation Unknown. 80/12/10. 1p. 07223:107.
- 8012270417 Response to ASLAB 801124 request for info re status of applicant studies on sys interactions & relevance to seismic issues in proceeding. Util sys interaction program is acceptable. Certificate of Svc encl.
 QLMBTEAD, N. J. Hearing Branch 2. 80/12/12. App. 07336: 248.
- 8012170440 Forwards joint intervenors' proposed findings of fact & conclusions of law for reopened seismic evidentiary hearing before ASLAP. FLEISCHAKER.D. Fleischaker.D. S 80/12/15. 1p. 07270:224.
- --8012170442 Joint intervenors' proposed findings of fact & conclusions of law for reopened seismic evidentiary hearing before ASLAB. Certificate of Svc encl.
 FLE18CHAMER.D. Fleischaker. D. S. PHILLIPB.J.R., REYNOLDS.J. Center for Law in the Public Interest. 80/12/15. 45pp. 07270:225.
- 8012290407 Proposed findings of fact & conclusions of law re ASLAB Questions 1-9 in seismic proceeding QL should be denied, since util has not designed facility to withstand may vibratory accelerations. Cartificate of Svc encl.

 BROWLE.G., BROWN.H.H. California, State of, BROWN.H.H. Hill Christopher & Phillips. 80/12/15, 92pp. 07337:099.
- 8012300027 Forwards Comptroller General 801203 opinion disallowing procedural assistance in adjudicatory licensing proceedings. BOWERS, E. S. Atomic Safety and Licensing Board Panel. 80/12/16. 1p. 07356: 104.
- 8012290337 Forwards Commission 801117 rulemaking decision, "Authority for Access to or Control Over 9NM (RM 50-7)." N/o encl. SNARTZ.L.L. Antitrust Division. 80/12/17. 1p. 07332:174.
- 8012300364 Joint Intervenors' response in support of CA Governor Brown motion to stay proceeding pending compliance w/REPA EIS requirements. NEPA requires EIS re application to operate at less than full power. Certificate of Svc encl. REYNOLDS, J. R. FLEISCHAKER, D. Center for Law in the Public Interest. FLEISCHAKER, D. Fleischaker, D. 8. 80/12/18. 9pp. 07359: 330.

- 90575 Response to intervenors' contentions re fuel loading & low for testing.Contentions 1 & 2 acceptable.All others cceptable due to lack of specificity & subj matter beyond pe of proceeding Certificate of Suc enci. FB.B.H. Hearing Branch 2. 00/12/83. 17pp. 07832; 281.
- 00007 Notice of appearance in proceeding.Cortificate of Syc encl. (FS.B.U. Hearing Branch 2. 60/12/23. 3pp. 07396:098.
- 100065 Response in opposition to CA Governor Brown BD1208 motion to 14 proceeding Motion fails to address legal requirements 2 for court & Commission procedents directly contrary to revenue position. W/Certificate of Byc. 1881EAD.N.J. Hearing Branch 4. 80/12/29. [1pp. 07956:179.
- 300183 Response to 801203 statement of subjs on which CA Governor own intends to participate Daly Subjs 3-5 & 12-19 propriate Certificate of 8vc encl. 1888 B.W. Hearing Branch 2. 80/12/23 12pp. 07396: 290.
- 100352 Response to CA Governor Brown 601208 motion to require paration of EIS. Opposes motion on grounds of untimeliness incompliance w/procedural requirements. Certificate of Svc. 1.
- :i. DUSH.H.H. H. NORTON.B. Pacific Oas & Electric Co. NORTON.B. Bruce ton. 80/12/23. 12pp. 07359:071.
- DiD283 Errata to joint intervenors' proposed findings of fact & notwins of law Certificate of Bvc encl. EISCHAKER, D. Floischaker, D. 8. 80/12/23. 7pp. 07370:058.
- 300403 Hotion for extension to 810106 to file proposed brief proposed findings of facts & contiusions of law in opened seismic proceedings Granted for ASLAS on 801224. TCHEM.E.G. Hearing Branch 4. 80/12/24. 2pp. 07357:182.
- 310274 Forwards tables of authorities for util responses to point tervanors statement of contention & request for directed rtification. NNE.P.A. Pacific Oas & Electric Co. 80/12/26. 10pp. 07361:316.

eneral correspondence

- 290010 Responds to 800601 ltrs to President Carter re constiticiencies at facilities & recent earthquake activity in ea. Description of NRC role in plant const & info re litty of facilities to withstand earthquake encl. RAGULA.F. J. Licensing Branch 3. 80/10/20. 3pp. 07330:252.
- DB04(A Responds to B00430 postcard to UF Ahearne re licensing tears concerning facilities. Safety issues resulting from I accident will need to be resolved before licenses are sued. Discusses licensing procedures. RAGNIA.F. J. Licensing Brench 3. B0/11/20. 3pp. 06586:003.
- 12080435 Supports NRC enthusiasm re licensing of nuclear plants & expresses desire for NRC to move ahead on licensing plants which presently meet stds. which presently meet stds. vAUSHN C. Affiliation Unknown. G9/04/30. Ip. 04586:003.
- 090005 Responds to 790407 postcard to J Hendrie re concerns about citity & nuclear power in general NRC required to prepare tailed statement on Listed environ issues. Hearings td as part of licensing process Forwards FEB. N/o encl. RAGLIA.F.J. Licensing Branch 3. 80/11/20. 5pp. 07187:001.
- 12090011 Requests support for legislation to prevent const of nuclear power plants. Supports alternative energy development. kdDLNAN. J. Affiliation Unknown. 79/04/09. ip. 07187:001.
- 120203 Responds to 800315 htr opposing operation of facility due to cV of proper amergency preparedness & evacuation plane. NRC s reacted positively to improve safety of nuclear planes Illuwing TMI accident. RAGLIA.F.J. Licensing Branch 3. 80/11/20. 4pp. 07187:001.
- 12120212 Forwards map indicating weather & geography downwind from facility. Expresses concern re improper evacuation routes in case of melidoun facility should be converted to gas operation M/a map.

 ANSONON B. Affiliation Unknown. 80/02/21, 4pp.
- 19030B Responds to 790329 request to reopen licensing hearings for cilities. Safety evaluation of plant compliance NOREO-0594 criteria performed, ASLD decision on Class 9 cidents will be aske after submittal of supplemental BER. RAGLIA.F. Licensing Branch 3. 80/12/04. 2pp. 07163: 001.

- B012190316 Requests add1 investigation & hearing for licensing facilities following TMI-2 accident.Expresses concern repossibility of similar accident at facility.
 CLUCAS.J. Sierra Club. 79/03/29. ip. 07183:001.
- B012310588 FDIA request for all documents repotential environ impacts associated w/fuel loading &/or low power testing of facilities.
 BRDMH.H. Hill Christopher & Phillips. 80/12/08. 2pp. 07370:014.
- 8012310178 Responds to 770402 ltr expressing concern re safe operation of facility. NRC requires all applicants to modify design & operation of facilties to conform to TMI-related requirements.

 MIRAGLIA,F. Licensing Branch 3. 80/12/11. 2pp. 07371:184.
- B012310594 Responds to FDIA request for all documents re potential environ impacts associated w/fuel loading &/or low power testing of facilities. EIS prepared in relation to request is available in PDR.
 FELTOR, J. M. Division of Rules and Records. 80/12/22. 1p.
- 8012040354 Responds to 801001 ltr expressing concerns re lack of evacuation plans & escape routes from South Bay area, in light of TM1 accident & event of floading. Util must complete TM1 safety-related requirements prior to full power license. MIRAOLIA, F. J. Licensing Branch 3. 80/11/17. 3pp. 06915:001.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012170715 Forwards IE Enfo Notice BO-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No Written response required. ENCELKFUR. H. Region 5. San Francisco, Office of the Director. 80/10/24.
- 8012170416 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ENGELKFN,R.H. Region 5, San Francisco, Office of the Director. 80/10/30. ip. 07264:053.
- 8012170897 Forwards IE Info Notice 80-39, "Malfunction of Bolenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
 ENGELKFIRR.H. Region 5, Ban Francisco, Office of the Director, 80/10/31. 1p. 07266:047.
- 8012120236 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ENGELKEDIR.H. Region 5. San Francisco, Office of the Director. 80/11/06. 1p. 07227:334.
- 8012030734 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ENGELEGIAR. Region 5, San Francisco, Office of the Director. 80/11/07. ip. 07150:183.
- 8012080632 Forwards IE Info Notice 80-41, "Failure of Bwing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1," No response required. ENGELKEN.R. M. Region 5, Ban Francisco, Office of the Director. 80/11/10, 1p. 97183:932.
- 8012040230 Forwards IE Dulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. EMSELKEN.R.H. Region 5. San Francisco, Office of the Director. 80/11/14. 1p. 07158:151.
- 6012940687 Forwards 1E Bulletin 80-24, "Prevention of Damage Due to Mater Leatage Inside Containment." No written response required. ENGELKELIR. H. Region 5, San Francisco, Office of the Director. 80/11/21. 1p. 07169:123.
- 8012160097 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No response required. ENGELKEH,R.H. Region 5, San Francisco, Office of the Director. 80/11/24. 1p. 07262:100.
- 801229000B Responds to IE Builetin 80-15, "Possible Loss of Emergency Notification Sys W/Loss of Offsite Power." Administrative Procedura NPAP C-11 will be revised to incorporate Item 5. Related correspondence.

 CRANE.P.A. Pacific Qas & Electric Co. 80/11/25. 2pp. 07344:201.

- 8012160124 Forwards Suppl 1 to [E Infa Notice 80-27, "Broken Studs on Terry Turbine Steem Inlat Flange." No written response required. EMSELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/26. 1p. 07262:076.
- 8012290542 Completes response to IE Bullatin 79-02 re concrete expansion anchor bolts used in pipe support base plate design. Rept on insp. tests, analysis & rework of seismic Category 1 pipe supports encl Related correspondence. CRANE, P. A. Pacific Gas & Electric Co. 80/12/03. 475pp. 07333:144.
- B012300466 Requests relief from 10CFR50.55a(g)(4), by specifying that ASNE boiler & pressure vessal code, Section XI, 1977 edition w/addenda through Summør 1978, effective B0110I, be applicable code for first 10-yr inservice insp interval. CRANE, P. A. Pacific Oas & Electric Co. 80/12/23. 2pp. 07347:066.
- S. Reportable occurrences, LERs & related correspondence
- 8012140382 Final deficiency report re cracks in Pullman field welds, originally reported 790503. Cause attributed to improper control of welding parameters. Unacceptable welds repaired or entire joint modified. Improved welding procedures now used. CRANE, P. A. Pacific Gas & Electric Co. 80/12/09. 3pp. 07187:001.
- DOCKET 50-324 BRUNSNICK STEAM ELECTRIC PLANT, UNIT 2
 H. General correspondence
- BO1223032B Advises of facility personnel change re appointment of MD Hill as maint manager. Training & experience discussed. UTLEY.E.E. Carolina Power & Light Co. B0/12/19. 2pp. 07314:093.
- P. Operating license stage documents & correspondence
- B012020489 Responds to 800926 ltr & 801008 telcon w/Hillman requesting approval of route to be used for transporting irradiated reactor fuel Route approved. MCCORKLE, O. W. Physical Security Licensing Branch. 80/10/14. 1p. 07148: 127.
- BO12140050 Ltr to operating plant licensees OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- BO12270358 Ltr to all CP & OL holders for BKRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISEKHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0619.
 "BWR Feedwater Norrie 3: Control Rod Drive Return Line
 Norrie Cracking." Confirmation that implementation dates
 will be met must be sent within 45 days. W/o encl.
 EISENHUT.D.O. Division of Licensing. 80/11/13. 1p.
- 8012020643 Forwards BWR owners group design & operational criteria for scram discharge sys.Criteria viewed as being responsive to requirement of providing assurance of reliable & safe operation of sys.

 WATERS, D. 8. Carolina Power & Light Co. 80/11/24. 4pp. 07148:013.
- 8012030721 Notifies that on 801025, to install modifire barrier penetration limiting condition for operation was generated on portion of diesel generator intake ventilation sys. Mork completed beyond designated time frame.

 TOLLIBON.A.C. Carolina Power & Light Co. 80/11/26. 1p. 07151:233.
- 8012030436 Advises that schedule for testing adequacy of electrical distribution sys voltage, as detailed in 801015 ltr.will not be complated until 810131 Data will be compared to analysis, w/results submitted to NRC by 810331, UTLEY.E.E. Carolina Power & Light Co. 80/12/02. ip. 07171;313.
- 8012100495 Informs NRC that util will attempt to meet 820630 deadline re qualification of safety-related electrical equipment, in response to NRC 801024 orders.
 UTLEY, E. E. Carolina Power & Light Co. 80/12/04. 2pp. 07218:309.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 80/12/04. 2pp.

- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANJART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- BO12110552 Responds to NUREG-0737, "Clarification of TMI Action Plan Requirement." Item II.K 3.30.re small break LCCA methods to show compliance w/100FR50 App K.GE.vendor for BKR.will discuss w/NRC approach to requirement by 801215. UTLEY.E.E. Carolina Power & Light Co. 80/12/10. ip. 07223:104.
- BO12160319 Responds to NRC 800924 request for commitment to install GE design package to provide Class IE power supply to reactur protection sys at facility Package uili be installed during next refueling outage.

 UTLEY, E. E. Carolina Power & Light Co. 80/12/10. 1p. 07262:007.
- 8012160460 Responds to request for info re effect of spillage on ECCS performance Also responds to 1E Bulletin 79-01B, "Environ Qualification of Class IE Equipment."
 UTLEY.E.E. Carolina Power & Light Co. 80/12/10. 2pp. 07263:045.
- BO12290256 Forwards Amends 31 & 52 to Licenses DPR-71 & DPR-62, respectively & notice of issuance & availability. IPPOLITO T.A. Operating Reactors Branch 2. B0/12/10. 3pp. 07306-221
- --B012220265 Amends 31 & 52 to Licenses 71 & 62, requiring maint of safeguards contingency plan to be implemented within 30 days of Commission approval.

 IPPOLITO, T. A. Operating Reactors Branch 1. 80/12/10. 2pp. 07306: 224.
- --8012220271 Natice of issuance & availability of Amends 3i & 52 to Licenses DPR-71 & DPR-62 respectively. IPPOLITO,T.A. Operating Reactors Branch 1. 80/12/10, 2pp. 07306:228.
- B012230470 Forwards commitments for completion of items in NUREC-0737, "Clarification of TMI Action Plan Requirements," in response to B01031 request. UTLEY, E. E. Carolina Power & Light Ca. B0/12/15. 22pp. 07314:141.
- 8012290975 Advises that util will provide schedule for required BHR scram sys mods within 30 days of receipt of final SER. UTLEY, E. E. Carolina Power & Light Co. 80/12/16. ip. 03797:071.
- Q. Inspection reports, IE Bulletins & correspondence
- B012090201 Forwards IE Insp Repts 50-323/80-39,50-324/80-36 & 50-261/80-27 on 800904 No noncompliance noted.
 STONR.J.P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/10/21. 2pp. 07202:264.
- --8012090210 IE Insp Rept 50-325/80-37.50-324/80-36 & 50-261/80-27 on 800704. No noncompliance noted Major areas inspected: circumstances surrounding erroneously recorded personnel exposures.

 HRAY.J.R. GIBSON.A.F. Region 2. Atlanta, Office of the Director. 80/10/21. 3pp. 07208:266.
- 6012150190 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No unition response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.
- 8012040551 Forwards Vols 1 & 2 to Revision 1 of 90-day rept re IE Bulistin 79-018. "Environ Qualification of Electrical Equipment." Rept contains data of original rept plus addl data developed since 805019. FURR.B.J. Carolina Power & Light Co. 80/10/30. 600pp. 07153:103.
- 8012170/85 Forwards IE Info Notice 80-39. "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/31. 1p. 07264:122.
- 8012230049 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sus Emergency Generators," No written response required, 0'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31, 1p. 07311:244.
- 8012110767 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/06.

- 012030337 Faruards IF. Info Natice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/07 1p 07150:147.
- O12080314 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required O'REFL(Y.J.P. Region 2. Atlanta, Office of the Director. 80/11/10. ip. 07182:254
- 012080047 Submits immediate rept per IE Bulletin 80-17.0n 801112, while performing periodic test 2.1.8P, determined that channels A & C usuld not trip turbine on high exhaust pressure. Channels A & C recalibr & sys returned to syc. TOLLISON, A C Carolina Power & Light Co. 80/11/13. 1p. 07189 svc. 3. 1p. 07189:177.
- G12040157 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves 14fg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 80/11/14.
- 012040468 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Unitten response required. Requests info on manpower expended. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/21.
- D12180029 Act receipt of 801030 ltr responding to IE Bulletin 79-018, Suppl 2, "Environ Qualification of Class IE Equipment."
 MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/21, p. 07240:351.
- 012050521 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. D'REILLY, J.P. Region 2. Atlanta. Office of the Director. 80/11/24. lp. 07!74:III.
- 0122300:8 Suppls 801105 response to IE Bulletin 80-11 re masonry wall design deficiencies.All multiple wythe walls will behave as composite walls (Item Editi(1a) FURR, 3. J. Carolina Power & Light Co. 80/11/25. 4pp. 07311:181.
- 012170496 Forwards IE Info Notice 80-29, Suppl 1, "Broten Studs on Terry Turbine Steam Inlet Flange." No written response required. D'REELCY, J.P. Region 2, Atlanta, Office of the Director. 80/11/26. 1p. 07268-078
- 012310490 Responds to IE Bulletin BO-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Valve parts mig by Malcolm Foundry Co. Inc. are not in use at facility.

 FURR.B. J. Carolina Power & Light Co. 80/12/08. 1p. 07370:024.
- 12310494 Responds to I6 Bulletin BC-23. "Failures of Sciencid Valves Mfg by Valcor Engineering Corp." No valves or valve parts mfg by Valcor Engineering Corp are in use at facility. FURR.B.J. Carolina Power & Light Co. B0/12/08. 1p. 07370:025.
- 12:60450 Responds to request for info re effect of spillage on ECCS performance. Also responds to IE Bulletin 79-018, "Environ Guallfication of Class IE Equipment" UTLEY, E. E. Carolina Power & Light Co. 80/12/10. 2pp. 07263:045.
- 12190414 Act receipt of 801030 ltm informing NRC of steps taken to correct violations noted in 16 lnsp Repts 50-325/80-35 & 50-324/80-33. STORR J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/12/10. 1p. 07265:246.
- BD12190426 Responds to NRC 80/010 ltr re violations noted in IE Insp. Repts 50-325/80-36 & 50-324/80-33. Corrective actions: evaluation implemented for comparison & documentation of TLD & pocket dosimeter results.

 TOLLISON-A.C Carolina Power & Light Co. 80/10/30. 2pp. 07226:247.
- 80121/0490 forwards IE Insp Repts 50-325/80-34 & 50-324/80-33 on 800902-04 & notice of violation 8TOHR/J.P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 60/10/10 2pp. 07286:249.
- BO12190434 Notice of violation from insp on 800902-04.

 * Region 2, Atlanta, Office of the Director. 80/10/09. ip.
 07286:251.

- -8012190440 IE Jnsp Repta 50-325/80-35 & 50-324/80-33 on 800902-04. Noncompliance noted: failure to determine whole body radiation dose.

 PUCKETIJ M. Region 2. Atlanta, Diffice of the Director.

 GISSON, A.F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/10/09. Spp. 07286: 252.
- R. Periodic operating reports & related correspondence
- 8012150935 Forwards monthly operating repts for Nov 1980. TOLLISONA.C. Cerolina Power & Light Co. 80/12/08. 1p. 07187:001.
- --8012150085 Monthly operating repts for Nov 1980. WILLIS,E. Carolina Power & Light Co. 80/12/02. 13pp. 07187:001.
- S. Reportable occurrences, LERs & related correspondence
- 8012020571 Forwards LER 80-083/01T-0. TOLLISGN.A.C. Carolina Power & Light Co. 80/11/20. 1p. 07145:258.
- --8012020578 LER 80-083/01T-0: on 801110, cracked weld found in structural steel beam in reactor bldg. Caused by lack of fusion on welds of angle clips attaching beam to imbedded wall plate. Beam rewalded using larger clips.

 TOLLISONA C. Carolina Power & Light Co.** 80/11/20, 4pp.
- 8012020496 Forwards LER 80-093/03L-0. TOLLISON.A.C. Caroline Power & Light Co. 80/11/21. 1p. 07143:249.
- --8012020520 LER 80-093/03L-0: on B01102, control rad 30-11 discovered not to have full-in indication when fully inserted. Caused by failure of reed switch in rod position indicator probe. Problem to be corrected during next outage. TDLL150N.A C. Carolina Power & Light Co. 80/11/21. 1p. 07143:250.
- 8012090352 Forwards LER 80-092/03L-0.
 TOLLISON, A.C. Carolina Power & Light Co. 80/12/03. ip. 07202:396.
- -8012090395 LER 80-092/03L-0: on 801105,08,12,15,18,22 & 23, containment atmospheric monitor 2-CAC-AY-1259, Beckman model F3, tripped due to loss of sample flow. Caused by water accumulation in torus sample line to monitor. Noter removed.

 4 Carolina Power & Light Co. 80/12/03. 2pp. 07202:357.
- 8012100497 Forwards LERs identified as missing in 801104 memo.Encl LENS cancelled LENIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. B0/12/03. 1p.
- --8012100513 LER 80-051 has been cancelled. 4 Carolina Power & Light Co. 80/12/03 ip. 07218:102.
- B012100453 Forwards LER 80-095/03L-0.
 TOLI ISON, A.C. Carolina Power & Light Co. 89/12/04. ip. 07218:029.
- --8012100455 LER 80-095/03L-0: on 801107 & 1108, primary containment oxygen concentration exceeded 4% limit. Caused by lack of operable primary containment atmospheric monitoring equipment. Concentration reduced.
 TOLLISCN.A.C. Carolina Power & Light Co. 80/12/04. 2pp. 07218: 030.
- 8012100455 Forwards LER 80-076/03L-0. TOLLISON, A.C. Carolina Power & Light Co. 80/12/04. ip. 07218:032.
- --8012100459 LER 80-096/03L-0: on 801107, primary containment atmospheric monitor 2-CAC-AT-1263 doclared inoperative due to erratic indications. Caused by instrument drift & defective monitor photohelic unit. Analyzer calibr & unit replaced. TOLLIBON, A. C. Carolina Power & Light Co. 80/12/04. 2pp. 07218: 033.
- 8012100567 Forwards LER 80~094/03L~0. TOLLISON, A.C. Carolina Power & Light Co. 80/12/04. ip. 07218:156.
- -8012100372 LER 80-094/03L-0: on 801111.primary containment atm monitor.2-CAC-ATH-1263.Beckman model F3.observed indicating upscale Caused by defective oxygen analyzer & defective monitor photohelic unit. Analyzer & unit replaced. TOLLIBON.A.C. Carolina Power & Light Co. 80/12/04. 2pp. 07218:157.
- 80:2150251 Forwards LER 80-097/03L-0. TOLLISON, A.C. Carolina Pawer & Light Co. 80/12/08, 1p. 07240:324.

- --8012150254 LER 80-097/03L-0 on 801112 suppression pool level exceeded max allowable limits Caused by failure of 20 RHR pump discharge check valve ZEII-F031 to fully reset following operation of pump Check valve reset 2 returned to svc. TOLLISON.A.C. Carolina Power 2 Light Co. 80/12/08. 2pp. 07240/329.
- 8012170614 Forwards LER 80-082/03L-0. TQLL15UN.A.C. Carolina Power & Light Co. 80/12/08. 1p. 07264:234.
- --8012170625 LER 80-082/03L-0: on 801114, Unit 2 reactor scrammed During subsequent startup, coolant activity exceeded Tech Spaces. Caused by leaking fuel element Fuel bundles will be sipped during next refueling & leaking bundles removed. FQLLISON, A.C. Carolina Power & Light Co. 80/12/08. 6pp. O7264:235.
- 8012220351 Nonroutine 30-day radiological environ event rept: on 801110, radiologina analysis results detected I-131 increase in milk samples at Bample Stations 35 ½ 37. Caused by apparent fuel element leaks in Unit 2 reactor core.
 TOLLISON A.C. Carolina Power ½ Light Co. 80/12/09. Spp. 07309:002.
- 80:2160433 Forwards LER 80-101/03L-0. TOLLISON, A.C. Carolina Pawer & Light Co. 80/12/10. ip. 07254:165.
- --BOIRI60440 LER 80-101/03L-0: on BOIII5, reactor core isolation cooling turbine tripped due to high turbine exhaust pressure. Caused by turbine exhaust swing check valve. 2-E51-F040, failing in closed position. Valve repaired.
 TOLLISON, A.C. Carolina Power & Light Co. 80/12/11. 2pp.
- B012140449 Forwards LER B0-079/03L-0.
 TOLL150N.A.C. Carolina Power & Light Co. 80/12/11. 1p. 07254:234.
- --8012160477 LER 80-079/03L-0: on 801115 primary containment atmospheric monitor indicated erratically. Caused by instrument drift. Both monitor oxygen analyzer & transmitter recalibr. This & similar monitors to be replaced in future. TULLISON.A.C. Carolina Power & Light Co. 80/12/11. 1p. 07254:235.
- 8012190925 Forwards updated LER 80-075/03L-1.
 TOLL180N.A.C. Carolina Power & Light Co. 80/12/12. ip. 07287:192.
- --B012170536 Updated LER 80-073/03L-1:on B01022,A loop RHR Svc water sys low suction pressure annuciator alarmod despite normal pressura. Caused by cracked pressure sensing line on A loop RHR Svc water sys pressure switch i-SW-PB-1176. TOLLISON.A.C. Carolina Power & Light Co. B0/12/12, 2pp. 07287:193.
- 8012220349 RO: on BOili7 Unit 2 fire barrior limiting conditions of operation generated on two inoperable fire doors in diesel generator bidg to allow repair. Due to unavailability of replacement hardware, fire door DB 125 presently inoperable. TOLL ISON A.C. Carolina Power & Light Co. 80/12/15. 1p. 03797; 066.
- 8012220425 Forwards LER 80-076/03L-0.
 TOLL ISON. A. C. Carolina Power & Light Co. 80/12/15. 1p. 07307:356.
- --8012220434 LER GO-076/031.-0: on 801119, switch 1 of 2-821-PS-NO21D found out of calibr. Caused by instrument drift. Switch recalibr & returned to operation. Instrument to be replaced. TOLLISON: A.C. Carolina Power & Light Co. 80/12/15. 1pp. 07307:357.
- 8012220483 RO:special rept per Tech Spec 3.7.8a.On 801ii1, Unit 2 fire barrier limiting condition for operation generated on two fire doors in diesal generator 4-day tank room area. Work not completed within time frame due to complexity of mod.
 TOLLISON.A.C. Carolina Power & Light Co. 80/12/15. 1p. 07304:111.
- 8012220490 Special rept on 801111 fire barrier limiting condition for operation was generated on two fire doors in diesel generator 4-day tank room area to facilitate routing uelding cables used for work required by plant mod. TOLLISON.A.C. Carolina Power & Light Co. 60/12/15. 1p. 07304:110.
- 8012220324 Forwards LER 80-051/03L-0, TOLL159N.A.C. Carolina Power & Light Co. 80/12/16. 1p. 07307:332.
- ---8012220330 LER 80-051/03L-0 on 801116, discovered monitor particulate collector unit w/two missing 0 rings & misaligned particulate filter support surface. Caused by loose screws. Rings replaced & screws properly tensioned. TOLLISON.A.C. Carolina Power & Light Co. 80/12/16. 2pp. 07307:339

- 8012230434 Forwards updated LER 80-049/03%-1 IOLLISON A C Carolina Power & Light Co. 80/12/17. 1p. 07314:114.
- --8012230443 Updated LER 80-069/03L-1: on 800907, during testing after refueling w/reactor core isolation cooling turbine running & pump at 250 paig discharge pressure no flow indicated on reactor core isolation cooling flow 2-65-FFC-R60.
 TGLLISCR.A.C. Carolina Power & Light Co. 80/12/17. 20pp.
- 8012230059 Forwards LER 80-103/09L-0. TOLLISOR: A.C. Carolina Power & Light Co. 80/12/18. ip. 07311:258.
- --8012230373 LER 80-103/03L-0.on 801118 during reactor startup while investigating cause of speed indication problems w/reactor recirculation pump 2A pump motor generator unit tripped. Caused by technician inadvertently shorting electrical lead. TOLLISON.A.C. Carolina Power & Light Co. 80/12/18. lp. 07311:259.
- 8012230501 Forwards LER 80-089/03L-0. TOLLISON A.C. Carolina Power & Light Co 80/12/18. 1p. 07316:229.
- --8012230505 LER 80-089/03L-0 on 801120 emergency recirculation fan 18-14-3450 would not start during control bldg emergency filters ventilation sys functional test Caused by fan motor thermal overloads trapping. Thermal overloads reset. TOLLISCN.A.C. Carolina Pouer & Light Co. 80/12/18. 2pp. 07314-250
- 8012300398 Forwards updated LER 80-075/03L-2.
 TOLL ISSN A.C. Carolina Power & Light Co. 80/12/19. 1p. 07359:350.
- --B012300402 Updated LER 80-075/03L-2 on 801022, loop A RHR svc water sys lou suction pressure annunciator alarmed despite normal sys pressure. Caused by cracked pressure sensing line on pressure switch 2-5U-PS-1176. Assembly replaced TQLL150N.A.C. Carolina Power & Light Co. 80/12/19. 1p. 07399: 351.
- 8012300472 RO 2-80-112: on 801209, while performing maint on water pump discharge check valve, heatup to approx 212 F resulted.

 STS change request being considered to accommodate similar maint needs in future.

 TOLLISON, A.C. Carolina Pawer & Light Co. 80/12/22. 3pp. 07357:141.
- 8012300575 Forwards LER 80-104/63L-0. TGLLISON A.C. Carolina Power & Light Co. 80/12/23. ip. 07362:309.
- --8012390579 LER 80-104/03L-0 on 801128 containment atmospheric monitor 2-CAC-AT-1263 tripped due to low sample flow Caused by moisture accumulation in monitor sample inletiair dryer & photohelic unit, Moisture drained & purged. TOLLISONA C. Carolina Power & Light Co. 80/12/23. 2pp. 07348-310
- 8012300583 Forwards LER 80-091/03L-0. TQLLISUR A.C Carolina Power & Light Co. 80/12/23. ip. 07362:315.
- --8012300589 LER 80-091/03L-0. on 801126, hydraulic snubber 2-8W-14255169 on conventional syc water sys antisiphoning stucture found w/loose pipe clamp allowing snubber to slide down pipe & become inoperable. Caused by vibration loosening clamp bolt. TGLLISON.A C. Carolina Power & Light Co. 80/12/23. 2pp. 07362:316
- U. Congressional/Executive Correspondence
- 8012010584 Responds to 800927 request that study be conducted re effects of oil spill near intake structure. Study initiated on 800915. When util completes analysis of oil refinery, NRC evaluation will be performed & results will be forwarded. DIRCKS, N. U. Office of the Executive Director for Operations. 80/11/10. 4pp. 07093.040.
- --8012010587 Requests study of offects of oil spill be conducted due to Brunswick Energy Corp plans to erect oil refinery in plant vicinity. ROSS.C. House of Rep. 80/07/27. 1p. 07095:064.
- DOCKET 59-329 BRANSHICK STEAM ELECTRIC PLANT. UNIT 1
- H. General correspondence
- 8012230328 Advises of facility personnel change re appointment of MD Hill as maint manager.Training & experience discussed. UTLEY.E.E. Carolina Power & Light Co. 80/12/19. 2pp. 07314:093.

- P. Operating license stage documents & correspondence
- BOI2160050 Ltr to operating plant licensees.QL applicants & CP holders. Forwards MUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISERMUT.D.O. Division of Licensing. BO/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BkRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENMUT.D. G. Division of Licensing. 80/11/04. 4pp. 07307:335.
- 8012220553 Ltr to all power reactor licensess forwarding NUREO-0619, "BUR Feedwater Noisie & Control Rod Drive Return Line Nossle Cracking." Confirmation that implementation dates will be net must be sent within 45 days 11/a encl. EISENRUT, D. C. Division of Licensing. 80/11/13. 1p.
- 8012020543 Forwards BMR owners group design & operational criteria for scram discharge sys.Criteria viewed as being responsive to requirement of providing assurance of reliable & safa operation of sys.

 NATERS.D.B. Carolina Fower & Light Co. 80/11/24. 4pp. 07148:013.
- B012030721 Notifies that on B01925, to install modifire barrier penetration limiting condition for operation was generated on portion of diesel generator intake ventilation sys. Hork completed beyond designated time frace.

 TOLLISON.A.C. Carolina Power & Light Co. 80/11/26. 1p. 07151:233.
- 8012050436 Advises that schedule for testing adequacy of electrical distribution sys voltage as detailed in 801015 ltr.will not be completed until 810131. Data will be compared to analysis. w/results submitted to RNC by 810331.
 UTLEY.E. E. Carolina Power & Light Co. 85/12/02. 1p. 07171:313.
- 8012100495 Informs NRC that util will attempt to meet 820630 deadline re qualification of safety-related electrical equipment, in response to NRC 601024 orders.
 UTLEY.E. E. Carolina Power & Light Co. 80/12/04. 2pp. 07218:309.
- 8012220485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of noed to comply w/revised Agreement State burial site conditions.Forwards results of IE survey.

 DENION:H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220505 Forwards tabulation & summary of IE survey on tow level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity. BANGART, R. L. Effluent Treatment Systems Branch. E0/11/06. Spp.
- 8012110552 Responds to NUREG-0737, "Clarification of TMI Action Plan Requirement," Item 11.K 3.30, re small break LDCA methods to show compliance witoGFR50 App K.GE.vendor for BNR-will discuss w/NRC approach to requirement by 801215.
 UTLEY, E. E. Carolina Power & Light Co. 80/12/10. 1p. 07223:104.
- 8012160319 Responds to NRC 800924 request for commitment to install GE design package to provide Class IE power supply to reactor protection sys at facility Package uill be installed during next refueling outage.

 UTLEY.E.E. Carolina Power & Light Co. 80/12/10. ip. 07262:007.
- B012160460 Responds to request for info re effect of spillage on ECCS performance. Also responds to IE Builtetin 79-018, "Environ Qualification of Class IE Equipment."

 UTLEY, E. E. Carolina Power & Light Co. B0/12/10, 2pp. 07263:045.
- 8012220256 Forwards Amends 31 % 52 to Licenses DPR-71 & DPR-62, respectively & notice of issuence & availability. PPDLITG.T.A. Operating Reactors Branch 2. 80/12/10. 3pp. 07306:221.
- --B012220265 Amends 31 & 52 to Licenses 71 & 62, requiring maint of safeguards contingency plan to be implemented within 30 days of Commission approval.

 IPPOLITO.T.A. Operating Reactors Branch 1. 80/12/10. 2pp. 07396: 224.
- --801222027; Notice of issuance & availability of Amends 31 & 52 to Licenses DPR-71 & DPR-62 respectively. IPPOLITO.T.A. Operating Reactors Branch 1. B0/12/10. 2pp. 07306:228.

- B012220332 Advises of extension of containment water level monitoring mod to B20101, UTLEY.E.E. Carolina Power & Light Co. B0/12/12, 2pp. 03797:049.
- B012230470 Forwards commitments for completion of items in NUREO-0737, "Clarification of YMI Action Plan Requirements," in response to B01031 request.

 UTLEY.E.E. Carolina Power & Light Co. 80/12/15, 22pp. 07314; 141.
- 8012220275 Advises that util will provide schedule for required BWR scram sys mods within 30 days of receipt of final SER.
 UTLEY.E.E. Carolina Power & Light Co. 80/12/16. 1p. 03797:071.
- G. Inspection reports, IE Bulletins & correspondence
- B012090201 Forwards IE Insp Repts 50-325/80-39,50-324/80-36 & 50-261/80-27 on 800904 No noncompliance noted. STGHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. B0/10/21, 2pp. 07202:264.
- --B012070210 IE (nsp Rept 50-325/80-39,50-324/80-36 & 50-261/80-27 on 800904.No noncompliance noted Major areas inspected: circumstances surrounding arroneously recorded personnel exposures.

 NRAY, J. R., OIBSON, A. F. Region 2, Atlanta, Office of the Director. 80/10/21. 5pp. 07202:266.
- B012190190 Forwards IE Info Natice 80-37, "Containment Codler Leaks & Reactor Cavity Flooding At Indian Point Unit 2," No written response required.
 0'REILLY,U.P. Region 2. Atlanta. Office of the Director. 80/10/24.
 1p. 0/240:287.
- BO12040551 Forwards Vols 1 & 2 to Revision 1 of 90-day rept re IE Bulletin 79-018, "Environ Qualification of Electrical Equipment." Rept contains data of original rept plus addl data developed since BO0919. FURR.B.J. Carolina Power & Light Co. 80/10/30. 600pp. 07153:103.
- 8012170785 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required.
 O'REILLY.J.P. Region 2: Atlanta: Office of the Director. 80/10/31.
 ip. 07264:122
- 8012230045 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31. 1p.
- 8012110767 Forwards IE Bulletin 80-21, "Valve Yakes Supplied by Malcolm Foundry Co. Inc." Written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/06 pp. 07225:191.
- 8012030387 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuritation " No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/07. 1p. 07150:147.
- 8012080316 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Basse Unit 1." No response required.

 0'RELLLY-J.P. Region 2, Atlanta, Office of the Director. 80/11/10.
 1p. 07182:274.
- BO12080047 Submits immediate rept per IE Bulletin 80-17. On 801112, while performing periodic test 2.1. SP. determined that channels A & C would not trip turbine on high exhaust pressure. Channels A & C recalibr & sys returned to avc. TOLLISON, A. C. Carolina Power & Light Co. 80/11/13. ip. 07189:177.
- BO12040157 Forwards IE Builetin 80-23, "Failures of Bolenoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. BO/11/14. ip. 07159:071.
- B01204046B Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Written response required. Requests info on manpower expended. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. B0/11/21. 1p. 07163:334.
- B012150029 Ack receipt of B01030 ltr responding to IE Bulletin 79-018, Suppl 2, "Environ Qualification of Class IE Equipment." MURPHY,C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/21. ip. 07240:351.

- 8012050621 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24. 1p. 07174:111.
- B012230018 Supple 801105 response to IE Bulletin B0-11 re masonry wall design deficiencies. All multiple wythe walls will behave as composite walls (item 2b(iii))a. FURR.B.J. Carolina Power & Light Co. B0/11/25. 4pp. 07311:181.
- B012170496 Forwards IE Info Notice 80-29. Suppl i, "Braken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/26. ip. 07268:078.
- 8012310490 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Valve parts mfg by Malcolm Foundry Co.Inc are not in use at facility. FURR.B.J. Carolina Power & Light Co. 80/12/08. 1p. 07370:024.
- 8012310494 Responds to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." No valves or valve parts mfg by Valcor Engineering Corp are in use at facility. FURR.B. J. Carolina Power & Light Co. 80/12/08. 1p. 07370:025.
- 8012160460 Responds to request for info re effect of spillage on ECCB performance. Also responds to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment."

 UTLEY, E. E. Carolina Power & Light Co. 80/12/10, 2pp.
- 8012190414 Ack receipt of 801030 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-325/80-36 & 50-324/80-33.

 STOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 80/12/10.
- --B012190426 Responds to NRC 801010 ltr re violations noted in IE Insp Repts 50-328/80-36 & 50-324/80-33. Corrective actions: evaluation implemented for comparison & documentation of TLD & pocket dosimeter results. TOLLISION.A.C. Carolina Power & Light Co. 80/10/30. 2pp. 07284:247.
- --8012190430 Forwards IE Insp Repts 50-325/80-36 & 50-324/80-33 on 800902-04 & notice of violation. BTOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/10, 2pp. 07286:249.
- --8012190434 Notice of violation from insp on 800902-04.

 * Region 2, Atlanta, Office of the Director, 80/10/09. ip.
 07284:251.
- --8012190440 IE Insp Repts 30-325/80-34 & 50-324/80-33 on 800902-04. Noncompliance noted: failure to determine whole body radiation dose.
 PUCKETT.J.M. Region 2. Atlanta. Office of the Director.
 OIBSON.A.F. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/10/09. 9pp. 07286:252.
- R. Periodic operating reports & related correspondence
- 8012150985 Forwards monthly operating repts for Nov 1980. TOLLISON, A. C. Carolina Power & Light Co. 80/12/08. ip. 07187:001.
- --8012150086 Monthly operating repts for Nov 1980.
 WILLIS.E. Carolina Power & Light Co. 80/12/02. 13pp. 07187:001.
- 8. Reportable occurrences. LERs & related correspondence
- 80i1180692 Forwards LER 80-084/03L-0. TOLLISON.A.C. Carolina Power & Light Co. 80/11/11. ip. 06991:279.
- --8011180703 LER 80-084/03L-0: on 801016, during normal surveillance, containment atmospheric monitor oxygen analyser 1-CAC-AT-1259-2 was indicating upscale. Caused by instrument drift. Monitor was recalibr & will be replaced during outage. TOLLIBON, A. C. Carolina Power & Light Co. 80/11/11. 1p. 06991:280.
- 8012100449 Forwards LER 80-088/03L-0. TOLLISON, A. C. Carolina Power & Light Co. 80/11/18. 1p. 07219: 358.

- --B012100452 LER B0-088/03L-0 on B01020 during normal surveillance, containment atmospheric monitor oxygen analyter observed indicating downscale Caused by loss of sample flow to analyter unit due to excessive condensate in air dryer. TOLLISON A.C. Carolina Power & Light Co. 80/11/18. 2pp. 07219:359.
- 8012020565 Forwards LER 80-085/03L-0. TOLLISON, A.C. Carolina Power & Light Co. B0/11/26. 1p. 07145: 255.
- --8012020569 LER 80-085/03L-0: on 801030; switch 3 of 1-821-LIS-N0318 & D activated out of tolerance. Caused by instrument drift.
 Instruments recallor.
 TOLLISON A. C. Caroling Power & Light Co. 80/11/26. 2pp.
 07145: 236.
- 8012220351 Nonroutine 30-day radiological environ event rept:on 80k110, radioiodine analysis results detected I-135 increase in milk samples at Sample Stations 35 & 37. Caused by apparent fuel element leaks in Unit 2 reactor core.
 TOLLISON, A. C. Carolina Power & Light Co. 80/12/09. Spp. 07309:002.
- 8012220349 RO: on 801117 Unit 2 fire barrier limiting conditions of operation generated on two inoperable fire doors in dissel generator bidg to allow repair. Due to unavailability of replacement hardware, fire door DG 125 presently inoperable. TOLLISON, A. C. Carolina Power & Light Co. 80/12/15. 1p. 03797: 066.
- 8012220483 RO: special rept per Tech Spec 3.7.8a. On 801111.Unit 2 fire barrier limiting condition for operation generated on two fire doors in diesel generator 4-day tank room area. Mork not completed within time frame due to complexity of mod.

 TOLLISON.A.C. Carolina Power & Light Co. 80/12/15. 1p. 07304:111.
- 8012220490 Special rept:on 801111 fire barrier limiting condition for operation was generated on two fire doors in diesel generator 4-day tank room area to facilitate routing welding cables used for work required by plant mod.

 TOLLISON A.C. Carolina Power & Light Co. 80/12/15. 1p. 07304:110.
- B012230401 Forwards LER 80-089/03L-0. TQLL180N, A. C. Carolina Power & Light Co. B0/12/14. 1p. 07311: 265.
- --B012230406 LER 80-087/03L-0: on B01120, during visual insp of snubbers on safety-related sys. Bergan Paterson H59A3. Located on conventional svc water header anti-siphon piping structure, determined inoperable. Caused by excessive wear on piston. TOLLTSON, A. C. Carolina Power & Light Co. B0/12/16. Ip. 07311: 266.
- 8012300425 Forwards LER 80-073/03L-0. TOLLISON, A.C. Carolina Power & Light Co. B0/12/19. ip. 07360:333.
- --B012300433 LER B0-073/03L-0: on B01122, RHR flow indicator signal converter 1-E11-FY-3338 would not respond to input signal. Gaused by remote shutdown panel RHR sys flow indicator 1-E11-FT-3338 loading converter to give inaccurate response. TOLLISON A C. Carolina Power & Light Co. B0/12/19. 2pp. 07360:334.
- 8012300571 Forwards LER B0-077/03L-0. TOLLISUN, A.C. Carolina Power & Light Co. B0/12/19. 1p. 07359:082.
- --8012300590 LER 80-077/03L-0: on 801120, snubber 1-E41-288105 found not to be connected to pipe clamp on HPCI sys main pump discharge piping. Caused by personnel error. Personnel to be reinstructed.
 TGLL18DN,A.C. Carolina Power & Light Co. 80/12/19. 2pp. 07359: 083.
- U. Congressional/Executive Correspondence
- BO12010584 Responds to 800929 request that study be conducted re effects of oil spill near intake structure. Study initiated on 800913, (Shen util completes analysis of oil refinery. NRC evaluation will be performed & results will be forwarded. DIRCKS: N. J. Office of the Executive Director for Operations. 80/11/10. 4pp. 07095:060.
- ---B012010589 Requests study of effects of oil spill be conducted due to Brunswick Energy Corp plans to erect oil refinery in plant vicinity. ROSE.C. House of Rep. 80/09/29. ip. 07095:064.

- DOCKET 50-326 UNIV. OF CALIFORNIA AT INVINE RES. REACTOR
 J. Insurance & indemnity inforcation
- 8012020537 Forwards executed Amends 8 to Indemnity Agreements E-16 & E-53 Amend 8 supersedes Amend 7, therefore execution of superseded amends not necessary.

 DENESS, S. J. California Univ. of, Berkeley. 80/11/24. 3pp. 06716:001.
- DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT | A. Application/construction stage documents & correspondence
- B012040187 Informs of approving B00623 request to perform only peak pressure containment integrated leak rate test & performance of full pressure preoperational containment integrated leak test before ice is loaded into condenser. SCHMENCER, A. Licensing Branch 2 B0/[[/17. 2pp. 07170:219]
- 8012160301 Ack receipt of 801105 ltr requesting addl info re RCS vent sys.RCS vent sys design & analysis & response to 801105 ltr will be submitted by 810701.

 MILLS.L.K. Tennessee Valley Authority. 80/12/10. 1p. 07263:143
- F. Security, medical, emergency & fire protection plans
- B0120B0B35 Notification of B01121 meeting w/util in Bethesda,MD to discuss util position on central emergency response ctr & plans for emergency mgt.

 STAMLE.C. Licensing Branch 2. B0/11/19. App.
- 8012080545 Releases public version of FEMA certification findings & determination re State of TN multi-purisdictional radiological emergency response plan. FELTON.J.M. Division of Rules and Records. 80/12/01. 1p. 07188:057.
- --8012080550 Forwards public version of certification of findings & determination re TN multi-jurisdictional radiological energency response plan for facility.

 CAMMF. A. Federal Emergency Management Agency. 80/08/07. 27pp. 07187:060.
- --8012080555 "Bequayah Nuclear Power Facility Exercise,800616-17," testing State of TN.m.lti-jurisdictional radiological emergency response plan.

 * Tennessee, State of. 80/06/17. 45pp. 07188:087.
- --8012030563 "Evaluation of TN Multi-Jurisdictional REP-Plan, Plant Sequayah: Related into encl. NEMTON, F. Federal Emergency Management Agency. 80/08/04, 58pp. 07188:134.
- 8012040391 Forwards public version of State of TN emergency plan. FELTON J. N. Division of Rules and Records. 80/12/03. ip. 07155:039.
- --8012040398 Public version of State of TN multi-jurisdictional radiological emergency response plan for Sequoyah Nuclear Power Facility.

 4 Tennessee, State of 80/06/02, 686pp. 07156:040.
- 8012230163 Forwards status of emergency plan items addressed in util 803801 ltr. Prompt notification sys for public will be operational by 810701 Z will meet requirements of final rule re emergency planning.

 CROSS, J. L. Tennessee Valley Authority, 80/12/17. 3pp. 07314:015.
- G. Adjudicatory correspondence
- 8012050376 Informs that time within which Commission may act to review Directors decision per 10CFR2.206 has expired. Commission has declined review. Becision became final agency action on 801112.
 CHILK.S. J. Office of the Secretary of the Commission. 80/12/04.
 1p. 07173:337.
- 8012290314 Requests notification of final order re intervenor 801016 exceptions to NRC 801008 initial decision denying petition to revoke CL. BATES.A. The Nuclear Regulatory Commission. 80/12/05. 1p. 07303:255.

- J. Insurance & indemnity information
- B012020473 Forwards Endorsement 13 to MAELU Policy MF-102. FIELDFR, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. B0/11/25 2pp. 07141: 257.
- B012100511 Forwards Endorsement 17 to ANI Policy NF-247.
 FIELDER, J. Harsh & McLennan, Inc., H & M Nuclear Consultants, Inc.
 Div. 80/12/04. 2pp. 0/218: 285.
- B012160307 Forwards Endorsement 14 to MAELU Policy MF-102. FIELD:N, J. American Nuclear Insurers. 80/12/09. 6pp. 07248:243
- Q. Advisory Committee on Reactor Safeguards reports & correspondence
- 8012020931 Summary of Subcommittee on Structural Engineering 800902 meeting in 'Mashington.DC re facility containment capacity when subjected to static or quasistatic uniform internal pressure caused by hydrogen burn.

 # ACRS Advisory Committee on Reactor Safeguards. 80/09/22. 12pp. 07147:173.
- 8012020097 Bummary of Subcommittee on Sequoyah Nuclear Plants 800602 meeting w/util-Westinghouse & ORNL in Washington, DC re OL application.

 * ACRS Advisory Committee on Reactor Safeguards. 80/10/03. 50pp. 06916:001.
- 8012020033 Summary of Subcommittee on Sequoyah Nuclear Plant 800709 meeting w/Westinghouse re status of open review items, hydroyen control & implementation of near-term DL requirements.

 * ACRS Advisory Committee on Reactor Safeguards. 80/10/10. 24pp. 06916:001.
- P. Operating license stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, DL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISENHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- 8012030800 Forwards requests for add1 info re core degrading program, Vol 2, from Containment Sys Branch discussed at 801016 meeting. Requests response by 801107. TEDESCO.R. L. Assistant Director for Licensing. 80/11/04.
- 8012020701 Discusses facility hydrogen control program. Allocates various areas of review to appropriate Nuclear Reactor Regulation branches. SER inputs to project manager required by 801205.
 EIBENHUT, D. O. Division of Licensing. 80/11/20. 12pp. 06916:001.
- BO12010334 Notifies that util maintains central file for safety-related equipment qualification repts. Requirements per License Condition 2. C. i2. b have been met.

 MILLS.L.M. Tennessee Valley Authority. B0/11/25. ip. 07098:030.
- 8012050397 Responds to NRC 801104 ltr requesting add1 info re NRC staff review of util rept, "Sequoyah Core Degradation Program, Vol 2." Facility containment would prevent resultant pressure from failing during hydrogen burn akin to that at TMI-2.
 MILLS.I.M. Tennessee Valley Authority, 80/12/01. 200pp.
- 8012080314 Forwards draft changes to FSAR Section 17, iA. ii. 3, clarifying util control of const & preliminary testing Math will be incorporated into Amend 48
 MILLS, L. K. Tennessee Valley Authority. 80/12/01. 3pp. 07189:291.
- 9012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept, TVA-TR75-1 re const & preliminary testing.
 MILLS,L,K. Tennessee Valley Authority. 80/12/01, 3pp. 07201:174.
- 8012180148 Forwards 801119 FR notice of revised 10CFR50.48 & new App R re fire protection program requirements. Rule effective on 810217 & Uill supersede effective dates for previously approved mods given in license conditions (45FR71549).
 TEUESCO.R.L. Assistant Director for Licensing. 80/12/03. 2pp. 07272:246
- B012190065 Summary of B01127 meeting w/util re settlement monitoring of emergency raw cooling water pipes & conduits. Damaged settlement markers examined & ERCW facility visited. Util position on matter discussed & engineer info reviewed, KERYON, T. J. Licensing Branch 2. B0/12/04. 3pp. 07279:039.

- 8012220485 Responds to 800911 nemo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON.M.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level wasts at 51 reactors. Low level wasts storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANDART, R. L. Effluent Treatment Systems Branch. B0/11/06. Spp.
- 8012290413 Forwards document rebutting J Mathews 801111 op-ed piece, "Despite TMI" in Washington Post.Requests that encl be considered for op-ed page or as 1tr to editor.

 HENDRIE, J. M. Commissioners. 80/12/04. 5pp. 07345:330.
- 8012090311 Forwards "Natural Circulation Test." Info fullfills requirement of Section 5.3.2 of Suppl 1 to SER.
 MILLS, L. K. Tennessee Valley Authority, 80/12/05. 1p. 07207:150.
- --8012090312 "Natural Circulation Fest." * Tennessee Valley Authority. 80/12/05. 3pp. 07207:151.
- BO12150280.Notifies of plans to provide mobile liquid radwaste demineralization facility to increase processing capacity of existing plant liquid radwaste sys.
 MILLS,L.H. Tennessee Valley Authority. B0/12/08. 1p. 07240:295.
- 8012160327 Responds to NRC 801031 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201.

 MILLS,L.M. Tennessee Valley Authority. 80/12/09. ip. 07243:359.
- B012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah. Watts Bar & Bellefonte & TVA-TR75-1A. Changes supersede B01201 ltr. Changes will be included in application for OL for Hartsville. Phipps Bend & Yellow Creek plants.
 MILLS.L.H. Tennessee Valley Authority. B0/12/09. 5pp. 07266:132.
- 80J2170306 Forwards Revision 3 of response to NUREO-057B, "TMI-2 Lessons Learned Task Force Status Rept & Short-term Recommendations." Revision changes response to Item 2.1.8a re improved post-accident sampling. MILLS.L.M. Tannessee Valley Authority. 80/12/10. 5pp. 07270:015.
- B012150107 Forwards documents re TVA program on hydrogen effects & control in facility containment per HG Parris B01104 request. CROSS, J. L. Tennesses Valley Authority. B0/12/11. 2pp. 07298:001.
- --B012150108 "Research Program on Hydrogen Combustion & Control," quarterly progress rept. Draft program plan for hydrogen control studies encl.

 * Tennessee Valley Authority. 80/12/15. 127pp. 07238:003.
- --8012150110 "Proposed Research on Methods of Analysis for Core Meltdown Accidents." Prepared for TVA.

 * Battelia Memorial Institute, Columbus Laboratories. 80/06/19. 60pp. 07238:130.
- --8012150111 "Core Degradation Program, Vol 2. Rept on Safety Evaluation of Interim Distributed Ignition Sys." * Tennessee Valley Authority. 80/12/15. 200pp. 07238:187.
- --8012150112 "Evaluation of Phase 1 & 2 Tests Performed W/IDI8 Igniter at Fenual.inc Labs."
 WILDER, J. J., TURNBULL, K. R., LAU, L. H. Tennessee Valley Authority.
 80/11/26. 88pp. 07209:044.
- --B012130113 "Determination of Ignition Performance Characteristics of Olow Plug Hydrogen Ignitor." Prepared for Westinghouse. DALZELL.W.O., OILLIS, J.P. Walter Kidde & Co., Inc., Fenwal, Inc. PBR-914. 80/11/10. 175pp. 07239:131.
- --8012150114 "Progress Rept on Verification of CLASIX."
 4 Offshore Power Systems (subs. of Westinghouse Electric Corp.).
 80/08/27. 18pp. 07239:334.
- 8012230158 Forwards add1 info re local detonation pressure profile & analysis of survivability of air return fan sys.in response to NRC 801209 request Info re CLABIX calculations will be documented by 801219.

 CROSS.J.L. Tennessee Valley Authority. 80/12/17. 5pp. 07314:008.

- 8012230451 Forwards draft Tech Spec 3/4.6.4.3 re hydrogen control interim distributed ignition sys in response to NRC 801209 request. CROSS, J. L. Tennessee Valley Authority. 80/12/18. ip. 07312:269.
- --B012230453 Draft Tech Spec 3/4.6.4.3 re hydrogen control interim distributed ignition sys limiting condition for operation & survaillance requirements. # Tennossee Valley Authority. 89/12/18. 2pp. 07312:270.
- 8012270238 Forwards discussion of remaining open items of NUREG-0737 requirements. Excluded items have been resolved by util as documented in earlier correspondence. Proposed license amends forthcoming. MILLS, L.M. Tennessee Valley Authority. 80/12/19. 28pp. 07345:147.
- 8012300566 Forwards info re equipment survivability for facility,per commitment made at 801218 meeting u/NRC on hydrogen issue. MILLS.L.M. Tennessee Valley Authority. 80/12/24. 13pp. 07346:222.
- Q. Inspection reports, IE Bulletins & correspondence
- B012150201 Forwards IE Info Notice B0-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 D'REILLY, J. P. Region 2. Atlanta, Office of the Director. B0/10/24.
- 8012180035 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30. tp. 03770:098.
- 8012170004 Forwards IE Info Notice 80-37. "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012230030 Forwards IE Circular 80-23, "Potential Defects in Beloit Power 8ys Emergency Generators." No written response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012110066 Requests assessment & corrective actions taken re-control room ceiling constructed w/apparently flammable tiles within 20 days.

 TEDEBOOR.L Assistant Director for Liconsing. 80/11/04. 3pp.
- B012110807 Forwards IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. B0/11/06.
- 8012030837 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. Q'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07.
- 8012180095 Forwards IE 1nsp Repts 50-259/80-37,50-260/80-31, 30-296/80-31 % 50-327/80-40 on 801006-07, No noncompliance noted. KENNA, M. B. Region 2, Atlanta, Safeguards Branch. 80/11/07. 2pp.
- --8012180069 IE insp Repts 50-259/80-37.50-260/80-31.50-296/80-31 & 50-327/80-40 on 801002-07. No noncompliance noted Major areas inspected: unascorted access clearances & intrusion of plant protected area. Details withheld (ref 100FR2.790). TOBIN, N. J. Region 2. Atlanta, Office of the Director. 50-296/80-31. 80/11/06. 1p.
- 8012080276 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILIY, J.P. Region 2. Atlanta, Office of the Director. B0/11/10.
- 8012040143 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/14.
- 8012080610 Advises that mods described in util 800722 & 1016 responses to IE Bulletin 80-18 re min flow through centrifugal charging pumps, constitute unreviewed safety question. Resolution in progress.

 MILLS, L. M. Tennessee Valley Authority. 80/11/17. ip. 07188:211.

- 8012080616 Forwards updated response to 18 Bulletin 80-09, "Hydramotor Actuator Deficiencies." Util will contact major valve suppliers to determine if adol deficient actuators were
 - supplied. MILL5-1.H. Tennessee Valley Authority. 80/11/17. 3pp. 07188:212.
- 8012050057 Forwards IE Bullstin 80-24, "Prevention of Damage Due to Hater Leakage Inside Containment." No written response
- 8012980034 Forwards IE Info Notice 89-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24.
- 8012170359 Forwards IE Info Notice 80-29.Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REICLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/26.
- 8012190574 Act receipt of 801007 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/80-30 & 50-328/80-17.
 STGHR,J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 60/12/08.
- --B012190575 Responds to NRC 800917 itr re violations noted in Insp. Repts 50-327/80-30 & 50-328/80-17. Corrective actions: shipments secured w/tie-down chains & shipping casks braced. MILLS.L.M. Tennessee Valley Authority. 80/10/09. 2pp. 07288: 206.
- --8012190576 Forwards IE Insp Repts 50-327/80-30 & 50-328/80-17 on 800729 & notice of violation STONR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/09/17. 2pp. 07288: 208.
- --8012190578 Nutice of violation from insp on 800729. → Region 2, Atlanta, Office of the Director. 80/09/16. ip. 07288:210.
- --8012190592 IE Insp Repts 50-327/80-30 & 50-328/80-17 on 800729.
 Noncompliance noted: two shipments received found w/o requires bracing.
 HACARTHUR, T.C., POTTER, J.P. Region 2, Atlanta, Fuel Facility & Saterials Safety Branch. 80/09/16. 3pp. 07288:211.
- 8012310104 Responds to IE Bulletin 80-21, "Valve Yokes Bupplied by Malcolm Foundry Co. Inc." No active valves at facility have parts cast by foundry.

 MILLB.L.K. Tennessee Valley Authority. 80/12/09. 1p. 07370:018.
- R. Periodic operating reports & related correspondence
- 8012020256 "NPDES Discharge Monitoring Rept.Aug 1780." EL-ASHRY.H. T., STEINER.G.R. Tennessee Valley Authority. 80/11/28. 87pp. 04586:003.
- G012160330 Forwards monthly operating rept for Nov 1980. BALLENTING. J.M. Tennessee Valley Authority. B0/12/10. ip. 07252:363.
- --8012160333 Monthly operating rept for Nov 1980. DUPREE.D. Tennessee Valley Authority. 80/12/03. 14pp. 07252:304.
- S. Reportable occurrences, LERs & related correspondence
- BD12240127 Part 2t rept re jamming of 4-inch & 6-inch suing valves into open position. Caused by disc nut lock-wire jammed against machined relief in body. Velan has replaced 4-inch valves & re-oriented lock-wire on 6-inch valve.

 VELAN.P. G. Velan Valve Co. 80/11/05. 4pp. 07187:001.
- 8012020625 Forwards LER 80-179/03L-0. OREEN.H. J. Tennessee Valley Authority. 80/11/21. 1p. 07145:279.
- --B012020633 LER B0-179/03L-0:on 801023, review of surveillance instructions revealed that SI-137.2, RCS water inventory, performed prior to entering Hode 4 & not again until 801015. Caused by failure to revise 8I-137.2 Instruction revised. COTTLE, W. T., KIRK, G. B. Tennessee Valley Authority. 80/11/2 2pp. 07145:280. 80/11/21

- 8012040399 Fourth interim deficiency rept re environ qualification of Class IE equipment initially reported on 800616. Several Class IE components lacking documentation re ability to operate in ambient conditions.

 MILLS.L.M. Tennessee Valley Authority. 80/11/21. 5pp. 07170:147.
- 8012020610 Forwards LER 80-174/03L-0. GREEN, H. J. Tennessee Valley Authority. 80/11/26. 1p. 07145:272.
- -8012020621 LER 80-174/03L-0: on 801027 during Mode 3 auxiliary control room containment pressure indicator 1-P1-30-300 observed to be erroneous when compared to other pressure indicators. Caused by incorrect installation of sense line. COTTLE-N.T., WILKEY.A.M. Tennessee Valley Authority. 80/11/26. ip. 07145:273.
- 8012030569 Forwards LER 80-180/01T-0. GREEN,H.J. Tennessee Valley Authority. 80/11/26, 1p. 07149:353.
- --8012030674 LER 80-180/017-0: on 801114, determined that both containment spray pumps could be jeopardized by blockwall failurs during seismic event. Caused by nonreinforced concrete block walls not being designed for seismic events.
 COTTLE, H. T., WILKEY, A. M. Tennesses Valley Authority. 80/11/26, 2pp. 07149: 354.
- B012080423 Forwards LER 80-182/03L-0. CREEN.H.J. Tennessee Valley Authority, 80/11/28, 1p. 06586:003.
- --8012080430 LER 80-182/03L-O; on 801031, containment hydrogen analyzer 1-HZAN-43-210 (train b) declared inoperable after failing weekly functional test Caused by improper reagent flow Flow readjusted COTTLE, N. T., WILKEY, A. M. Tennessee Valley Authority. 80/11/28. 1p. 06586: 003.
- 8012020629 Forwards LER 80-186/03L-0. GREEN.H.J. Tennessee Valley Authority. 80/12/01. 1p. 07145:282.
- --B012020636 LER B0-186/03L-0; on B01102, during Mode 1, rod position indicator E-13, SD bank A, became stratic then failed low.

 Caused by defective connector on indicator E-13, Bpare connector F-12 used until defective connector repaired.

 * Tennessee Valley Authority. B0/12/01. 1p. 07145:283.
- 8012040392. Forwards LER 60-181/03L-0. GREEN.H.J. Tennessee Valley Authority. 80/12/01. 1p. 07169:136.
- --8012040396 LER 80-181/03L-0: on 801101, loop 1 OT delta T & OP delta T bistables, T8-68-2D/E & -2Q/F, found out of tolerance. Caused by shift in calibr resulting form elevated room temp. Room temp returned to normal & recalibr performed.

 COTTLE, U. T., WILKEY, A. M. Tennessee Valley Authority, 80/12/01, 1p. 07169:137.
- 8012090355 Farwards LER 80-184/01T-0. OREEN, H. J. Tennessee Valley Authority. 80/12/02, 1p. 07199:355.
- -8012070358 LER 80-184/01T-0: on 801120, in mode 1, at 94% power, auxiliary bldg gas treatment sys was declared inoperable. Caused by nitrogen supply line being run under railroad door to cask loading area, preventing door from completely closing.
 CUTTLE, W. T., KIRK, G. B. Tennessee Valley Authority. 80/12/02.
 2pp. 07199: 356.
- 8012150165 Forwards LER 80-183/03L-0. OREEN,H.J. Tennessee Vallay Authority, 80/12/08. 1p. 07237:298.
- --B012150170 LER 80-183/03L-0: on 801115, found diesel generator surveillance schedule not in compliance w/Tech Bpecs. Caused by inadequate procedural guidance. Engineer assigned to review generator starts & surveillance frequency increased. COTTLE, M. T. MADDOX, S G. Tennessee Valley Authority. 80/12/08, 8pp. 07237:276
- 8012160447 Forwards LER 80-185/03L-0. OREEN.H.J. Tennessee Valley Authority. 80/12/10. 1p. 07254:202.
- -8012160454 LER 80-189/03L-0: on 801111; output breaker for vital inverter 1-1 tripped & vital instrument power board declared inoperable. Caused by blown output fuses on inverter, Fuses replaced.
 COTILE, N. T., MADDOX, S. G. Tennessee Valley Authority, 80/12/10, 1p. 07254:203.
- 8012170602 Forwards LER 80-187/03L-0. GREEN.H.J. Tennessee Valley Authority. 80/12/15. 1p. 07264:257.

- --8012170605 LER 80-187/03L-0: on 801118, found vital instrument power board 2-111 being powered from maint power supply. Caused by failure of vital invertor 2-111. Invertor restored. COTTLE,N.T. MADDOX, S. G. Tennessea Valley Authority. 80/12/15. 4pp. 07264:258.
- 8012230362 Forwards LER 80-188/03L-0. GREEN.H.J. Tennessee Valley Authority. 80/12/16. 1p. 07318:251.
- --B012230365 LER B0-188/O3L-0: on B01117, determined that refueling water storage tank boron concentration was too high. Caused by excessive addition of boron. Boron free makeup water added to restore boron concentration to allowable limits. COTTLE, W. T., KIRK, G. B. Tennessee Valley Authority, B0/12/16. 29p. 07318: 252.
- 8012230386 Forwards LER 80-187/03L-0. OREEN, H. J. Tennessee Valley Authority. 80/12/16. ip. 07318; 259.
- --B012230393 LER 80-189/03L-0: on 801119, containment sump valve to containment spray pump IB-B.1-FCV-72-20, failed to open.
 Caused by dirty contacts on valve switch. Contacts cleaned & valve tested.
 COTTLE, U.T., KIRK, O.B. Tennessee Valley Authority. 80/12/16. 1p. 07318: 260.
- 8012300419 Forwards LER 80-196/017-0. GREEN, H. J. Tennessee Valley Authority. 80/12/23. 1p. 07349:354.
- B012300424 LER 80-196/01T-0: on 801211, during IE 8011etin 79-14 review, discovered heat transfer coment installed in area of pipe hangers could restrict relative movement between pipe & hanger. Error made during const. Cement removed. COTTLE.N.T., GELSTON, A.H. Tennessee Valley Authority. 80/12/23. 1p. 07349:355.
- 8012300541 Forwards LER 80-171/03L-0. GREEN.H.J. Tennessee Valley Authority. 80/12/23. 1p. 07361:339.
- --8012300548 LER 80-191/03L-0: on 801124.component cooling water pump C-8 motor breaker failed to close, rendering B train component cooling water inoperable. Caused by blown fuse in control circuit. Fuse replaced.
 COTTLE, N. T., WILKEY, A. M. Tonnessue Valley Authority. 80/12/23.
 1p. 07361:340.
- 8012300438 Forwards LER 80-197/01T-0. GREEN, H. J. Tennessee Valley Authority. 80/12/24. 1p. 07349:349.
- --B012300444 LER B0-197/01T-0:on 801212, during Mode 5, notification received that solenoid valves for valve operators on six containment isolation valves not qualified for accident environ. Affected valves replaced by valves qualified. COTYLE, N. T., OELBTON, A. H. Tennessee Valley Authority. B0/12/24, 1p. 07349:350.
- 8012300518 Forwards LER 80-195/017-0. OREEN.H.J. Tennessee Valley Authority. 80/12/24. 1p. 07360:360.
- --8012300535 LER 80-195/01Y-0: on 801212, util notified that interlocks on emergency feeder breakers to 6.9-kV shutdown boards could allow diesel generators to connect to shutdown boards w/o operating load stripping relays & cause generator overload. GOTTLE, N. Y. GELSTON, A. H. Tennessee Valley Authority. 80/12/24. ip. 07360.361.
- 8012300555 Forwards LER 80-190/03L-0. GREEN,H.J. Tennessee Valley Authority. 80/12/24. 1p. 07361:356.
- --8012300564 LER 80-190/03L-0: on 801126, containment purge isolation valves found not leak rata tested within 24-h of stroking. Gausad by delayed maint request. Valves tested within 41-h & personnel reinstructed. COTTLE.W.T., KIRK, O.B. Tennessee Valley Authority. 80/12/24. 1p. 07361:357.
- DOCKET 50-328 SECUDYAH NUCLEAR PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012140050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISENHUT.D.O. Division of Licensing. 80/10/31. 7pp.

- B012040187 Informs of approving B00623 request to perform only peak pressure containment integrated leak rate test & performance of full pressure preoperational containment integrated leak test before ice is loaded into condenser. SCHWENCER.A. Licensing Branch 2 80/11/17. 2pp. 07170:219.
- 8012080314 Forwards draft changes to FSAR, Section 17. 1A. 11.3. clarifying util control of const & preliminary testing. Matl will be incorporated into Amend 68. MILLS, L. N. Tennessee Valley Authority. 80/12/01. 3pp. 07189: 291.
- 8012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept. TVA-TR75-1 re const & preliminary testing. MILLS, L. M. Tennessee Valley Authority. 80/12/01. 3pp. 07201:174.
- 8012120597 Notification of 801211-12 meeting w/util in Soddy Daisy.TN for performance of caseload forecast to determine priorities for allocation of NRC manpower. 1
 KENYON.T.J. Licensing Branch 2. 80/12/02. 6pp. 07237:154.
- 8012190065 Summary of 801127 meeting w/util re settlement monitoring of omergancy raw cooling water pipes & conduits. Damaged sattlement markers examined & ERCW facility visited. Util position on matter discussed & engineer info reviewed. KENYON, T. J. Licensing Branch 2. 80/12/04. 3pp. 07279:039.
- B012220485 Responds to B009ti memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions Forwards results of IE survey.

 DEN10N.H.R. Office of Nuclear Reactor Regulation, Director.

 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. Bpp.
- 8012090311 Forwards "Natural Circulation Test." Info fullfills requirement of Section 9.3.2 of Suppl 1 to SER.
 MILLS.L.H. Tennessee Valley Authority. 80/12/05. 1p. 07207:150.
- --8012090312 "Natural Circulation Test."

 * Tennessee Valley Authority. 80/12/05. 3pp. 07207:151.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201.
 MILLS.L.M. Tannessee Valley Authority. 80/12/09. ip. 07243:359.
- 8012160301 Ack receipt of 801105 ltr requesting addl info re RCS vent sys.RCS vent sys design & analysis & response to 801105 ltr will be submitted by 810701.
 MILLS, L.H. Tennessee Valley Authority. 80/12/10. lp. 07263:143.
- B012170306 Forwards Revision 3 of response to NUREO-0578, "TMI-2 Lessons Learned Task Force Status Rept & Short-term Recommendations." Revision changes response to Item 2.1.8a re improved post-accident sampling. MILLS.L.M. Tennessee Valley Authority. 80/12/10. 5pp. 07270:015.
- 8012190125 Informs NRC that leakage measurements required by task action plan ltem III.D.1.1 will be made before full power operation. Test results will be provided within 30 days of campletion. Test procedures have been transmitted.
 MILLS.L.M. Tennessee Valley Authority. 80/12/15. ip. 07284:217.
- 8012190503 Notifies that licensee has completed mods to allow air testing of containment isolation valves per SER, Suppl i. MILLB.L.M. Tennossee Valley Authority. 80/12/15. ip. 07285:320.
- F. Becurity, medical, emergency & fire protection plans
- BO12080835 Notification of BO1121 meeting w/util in Bethesda.MD to discuss util position on central emergency response ctr & plans for emergency mgt.

 BTAMLE,C. Licensing Branch 2. BO/11/19. 6pp.
- 8012040391 Forwards public version of State of TN emergency plan. FELTON.J.M. Division of Rules and Records. 80/12/03. 1p. 07156:039.
- --8012040378 Public version of State of TN multi-jurisdictional radiological emergency response plan for Sequoyah Nuclear Power Facility.

 * Tennessee, State of. 80/06/02. 686pp. 07156:049.

- 8012230163 Forwards status of emergency plan items addressed in util 800801 ltr.Prompt natification sys for public will be operational by 810701 & will meet requirements of final rule re-energency planning CRGSS-J-L. Tennessee Valley Authority. 80/12/17. 3pp. 07314:015.
- G. Adjudicatory correspondence
- 8012220314 Requests notification of final order re intervenor 801016 streptions to MRC 801008 initial decision denying petition to revole D. BATES, A. The Nuclear Regulatory Commission. 80/12/03. 1p. 07303:255.

J. Insurance & Indemnity information

- B012020473 Forwards Endorsement 13 to MAELU Policy MF-102. FIELDER.J. Marsh & McLonnan Inc., 에 & M Nuclear Consultants, Inc. Div. B0/11/25. 2pp. 97141:257.
- BOI2100511 Forwards Endorsement 17 to ANI Policy NF-247. FIELDER, J. Marsh & McLennan Inc., 비호 M Nuclear Consultants, Inc. Div. 80/12/04. 2pp. 0/218:285.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8012020031 Summary of Subcommittee on Structural Engineering 800902 meeting in Washington.DC refacility containment capacity when subjected to static or quasistatic uniform internal pressure caused by hydrogen burn.

 4 ACRS Advisory Committee on Reactor Safeguards. 80/09/22. 12pp. 07147:173.
- 8012020087 Summary of Subcommittee on Sequoyah Nuclear Plants 800402 meeting v/vtil. Westinghouse & ORNE. in Washington, DC re OL application

 # ACRS Advisory Committee on Reactor Safeguards. 80/10/03. 50pp.
 - 04916: 001
- 8012020033 Summary of Subcommittee on Sequoyah Nuclear Plant 800709 meeting u/Westinghouse re status of open review items.

 hydrogen control & implementation of near-term CL requirements ACRS - Ad Advisory Committee on Reactor Safeguards. 80/10/10. 24pg.

P. Operating license stage documents & correspondence

04914-001

- 8012030800 Forwards requests for additinfo we come degrading program, Vol 2, from Containment Sys Branch discussed at 801016 meeting, Requests response by 801107.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/04.
- 8012020701 Discusses facility hydrogen control program Allocates various areas of review to appropriate Nuclear Reactor Regulation branches SER inputs to project manager required 6g 801205. EISERHUT, B. G. Division of Licensing, 80/11/20, 12pp. 04914:001.
- 8012150020 Confirms 801117 meeting re resumption of preoperational & related const tests, under mutually agreed upon controls. Lists points of understanding Addl controls will be applicable to other plants owned by util. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/20, 2pp. 07241:052.
- S012180148 Forwards 801117 FR notice of revised 10CFR50.48 & new App R re fire protection program requirements. Rule effective on 810217 & uill supersede effective dates for previously approved nods given in license conditions (45FR71569). TEDESCO.R.L. Assistant Director for Licensing. 80/12/03. 2pp. 07272:245.
- G. Inspection reports, IE Bulletins & correspondence
- 8012150201 Forwards IE Info Natice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required. O'REILLY, J. P. Region 2: Atlanta: Office of the Director. 80/10/24,
- 8012180035 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response requirad. 8'REILLY,J P. Region 2. Atlanta, Office of the Director. 80/10/30. 1p. 03770:098.

- 8012170304 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012230030 Forwards IE Circular BD-23, "Potential Defects in Beloit Power Sys Emergency Cenerators." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. BD/10/31.
- 8012110066 Requests assessment & corrective actions taken re control room celling constructed w/apparently flammable tiles within 20 days.

 TEDESCO.R.L Assistant Director for Licensing. 80/11/04. 3pp.
- B012110807 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. B0/11/04,
- 8012030837 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/11/07.
- B0120B0276 Forwards IE Info Notice B0-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REIU'Y, J. P. Region 2, Atlanta, Office of the Director. B0/11/10.
- 80:2040:43 Forwards IE Bulietin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions, D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/14, 10
- 8012080616 Forwards updated response to IE Bulletin 80-07, "Hydramotor Actuator Deficiencies." Util will contact major valve suppliers to determine if addl deficient actuators were supplied. MILLS, L. H. Tennessee Valley Authority. 80/11/17. 3pp. 07188:212.
- 8012050023 Forwards 1E Builetin 80-24, "Pravention of Damage Due to Water Leakage Inside Containment." No written response required.

 6'REIULY, J.P. Region 2, Atlanta, Office of the Director. 80/11/21, 1p. 07173:072.
- 8012080604 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24.
- 8012170359 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REPLLY, J. P. Region 2, Atlenta, Office of the Director, 80/11/24.
- 8012190574 Ack receipt of 801009 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/80-30 & 50-328/80-17.

 BTCRR,J,P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/12/08.
- --9012190575 Responds to NRC 860917 ltr re violations noted in Insp Repts 50-327/80-30 & 50-328/80-17 Corrective actions: shipments secured w/tie-down chains & shipping casks braced. HILLS.L.M. Tennessee Valley Authority. 80/10/09, 2pp. 07288: 206.
- --B01219057& Forwards IE Insp Repts 50-327/80-30 & 50-328/80-17 on 800729 & notice of violation.
 STCHR.J.P. Region 2: Atlanta, Fuel Facility & Materials Safety Branch. 80/09/17. 2pp. 07288: 208.
- -B01219057B Notice of violation from insp on 800729.

 * Region 2, Atlanta, Office of the Director. 80/09/16. 1p. 07288:210.
- --8012190582 IE Insp Repts 50-327/80-30 % 50-328/80-17 on 800729.
 Noncompliance noted: two shipments received found w/o required bracing.
 MACARTHUR. T.C., POTTER. J. P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/09/16. 3pp. 07288:211.

į.

- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah. Watts Bar & Bellefonle & TVA-TR75-iA. Changes supersede B01201 ltr. Changes will be included in application for OL for Hactsville. Phipps Bend & Yellou Creek plants.
 MILLS.L.K. Tennessee Valley Authority B0/12/07. 5pp. 07266:132.
- R. Periodic operating reports & related correspondence
- 8012020256 "NPDES Discharge Monitoring Rept.Aug 1980." EL-ASHRY,M.T., STEINER,G.R. Tennessee Valley Authority. 80/11/28. 87pp. 06586:003.
- S. Reportable occurrences, LERs & related correspondence
- B012040359 Fourth interim deficiency rept re environ qualification of Class IE equipment initially reported on 800616. Several Class IE components lacking documentation re ability to operate in ambient conditions.

 MILLS.L.M. Tennessee Valley Authority. 80/11/21. 5pp. 07170:147.
- 8012040416 First interim deficiency rept re inadequate documentation to verify qualification levels for harsh environs initially reported on 801024. Environ documentation on components still being gathered. Next rept by 810123.

 MILLS, L. M. Tennessee Valley Authority. 80/11/25. Spp. 07170:126.
- 8012030.094 Revised final deficiency rept re safety insection sys train flow, initially reported on 800822. RHR heat exchanger outlet valves opened at 79 degrees, allowing flow rate to fall in acceptable 4, 500-5.000 gpm range.
 MILLB.L.M. Tennessee Valley Authority. 80/11/26. 2pp. 07151:235.
- 8012100548 Final deficiency rept re broken spring in pressurizer safety valve, initially reported 801027. Part 21 is also applicable. Failure apparently caused by quench cracks in spring matl. Replaced u/Crosby Valve & Cauge Co spring. MILLS.L.K. Tennessee Valley Authority. 80/11/26. 2pp. 07220: 115.
- 8012150257 Part 21 rept re Crosby Valve & Gage Co defective 2-RV-6B-565 pressurizer safety valve.Caused by broken spring.Spring replaced.Preoperational testing will be completed by 810301. HILLS,L.M. Tennossee Valloy Authority. 80/11/26. 3pp. 07237:354.
- 8012100460 Second interim deficiency rept re analysis of intermediate breat locations. Evaluation of possible consequences of the postulated breaks has not been completed. Next rept will be submitted by 810121.

 MILLS.L.M. Tennessee Valley Authority. 80/12/02. 1p. 07219:027.
- BO12170513 Final deficiency rept, initially reported B00407, re environ qualifications of valve room Class IE instruments. Differential pressure switches will be modified to upgrade qualification level & transmitters will be replaced. MILIS.L.H. Tennessee Valley Authority. B0/12/10. 5pp. 07269:229.

V. Operator Examinations

- 8012230390 Advises that results of Unit i special test program re operator training compared to simulator program showed agreement w/plant parameters that existed in natural circulation mode under varying conditions.

 MILLS,L.M. Tennessee Valley Authority. 80/12/16. 1p. 07314:113.
- DOCKET 50-329 MIDLAND PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8012160090 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements, Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met.

 EISERMANT, D. G. Division of Licensing. 80/10/31. 7pp.
- G012070133 Notification of B01205 meeting w/util & consultants in Bethasda-MD to discuss seismological input for site pursuant to NRG B01014 enc1 ltr.W/o enc1.

 HDQD,D. Licensing Branch 3. G0/11/14. 4pp. 07199:202.
- 8012020106 Confirms 801124 meeting in Jackson.MI to discuss regional evaluation of regulatory performance at facilities.

 MEPPLER.J.G. Region 3. Chicago Office of the Director. 80/11/19.

 1p. 07148:359.

- 8012030266 Forwards request for add1 info & clarifications needed to complete independent confirmatory piping analysis. Requests justification of several stress intensity values for piping compenants & sys reported in FSAR Tables 3 9-15 & 3.9-15A TEDESCO.R.L. Assistant Director for Licensing. 80/11/20. App. 07196:199.
- B012080805 Forwards add1 info & clarifications needed to complete independent confirmatory piping analysis at facility, request justification for several stress intensity values for piping components & sys reported in FSAR tables AUGE, L. J. Energy Technology Engineering Center. 80/11/20. 6pp. 07187:074.
- 8012020323 Forwards "Site Specific Response Spectra for SSE," providing preliminary info for presentation 2 discussion at util 801205 meeting w/RRC.

 CGCM, J. W. Consumers Power Co. 80/11/28. p. 07142:029.
- --8012020328 Preliminary rept. "Site Specific Response Spectra for SSE."

 * Nestern Geophysical. 80/11/28. 19pp. 07142:030.
- B012050322 Forwards affidavit confirming distribution of Amend 85 to OL application BUDZIK, D. M. Consumers Power Co. 80/12/02 5pp. 07175:053.
- BO12080480 Advises that Amend 85 to util application for CPs & CLs was sent under separate cover.
 BUDZIK.D.H Consumers Power Co. B0/12/02. 1p. 07184:281.
- B0121707/5 Forwards request for addl info re turnado missile protection & containment soismic analyses for FSAR reviaw.
 TEUESOO,R.L. Assistant Director for Licensing. 80/12/04. 3pp. 07264.050.
- 8012100679 Confirms 801202 meeting in Olen Ellyn/IL to discuss recently reorganized GA unit. FIORELLIQ. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 80/12/09. Ip
- 8012160443 Responds to 800613 & 0825 meetings between util & NRC retimely resumption of formal docket review of plant.OL application is ready for post-TKI review. Proposes expeditious review & requests comment.

 COOK, J. W. Consumers Pacer Co. 89/12/10. 3pp. 07263:136.
- F. Security, medical, emergency δ fire protection plans
- BO12040114 Public version of "Independent Assessment of Evacuation Times for Midland Nuclear Power Plant." Vol 7. prepared for FEMA. CUSBY, J. C., SHEPPARD, M. V., BANGROFT, J. R. Wilbur Smith & Associates. BO/06/30. 58pp. 07198-206.
- B012040065 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, FELTRN.J.M. Division of Rules and Records, B0/12/03. 1p.
- The second secon
- --8012040088 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEMA. 4 Nilbur Emith & Associates 80/06/30. 17pp.
- --8012040195 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol Liprepared for FEMA COSBY, J. C. Wilbur Smith & Associates 80/06/30. 43pp.
- G. Adjudicatory correspondence
- 8012020649 Appeal from ASLR 801027 order.Order stands moot re jurisdiction.Too many factors have not been reported re drainage & groundwater pressure.Contificate of Syc encl. MARSH4LL.U.H. Mapleton Intervenors. 80/11/19. 17pp. 07143:296.
- 8012050432 Notice of ASLAS constitution.RS Saliman chairman & JH Buck & CN Kohlipanel members.
 BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/11/24.
 1p. 07173:305.
- 8012050443 Notice of 601209-11 depositions of W Ferris.B Dahr & T Thiruvengadam all of Bechtel Associates. Sub; will concern issues in ASLS 791202 order modifying CPs. Certificate of Svcencl.
 PATON.W.D. Hearing Smanch 2. 80/11/25. 4pp. 07173:309.

- B012090420 Interrogatories including requests for documents directed to CPC addressing seismic 2 structural issues plus remedial actions. Certificate of Svc encl.
 PATON, U. Hearing Branch 2 B0/11/26, t1pp. 07173:291.
- 8012050562 Forwards uncorrected transcript of D Haad 801008 deposition & G Dallagher 801117-18 deposition. Wo encis. JGNFS, B. W. Hearing Branch 2. 80/11/26. 2pp. 07173:320.
- E012050670 Confirms B01124 telcon informing that MRC will attempt to answer B01122 interrogatories, although not technically in compliance w/Commission rules.

 JONES, B. W. Hearing Branch 2. G0/11/26. 1p. 07173:319,
- 8012070694 Request for extension until 810123 for termination of discovery dua to complexity of issues. Prehearing conference should be held on 810126-30. Certificate of 8vc enci. PATON. R. D. Hearing Branch 4. 80/11/28. 3pp. 07147:286.
- 8012290107 Forwards to Midland Technical hearing participants listing of forcal requests for info re soil settlement problem. Date corresponds to issuance of NRC order prohibiting certain const activaties until amend to CPs is granted. HOOD, D. Licensing Branch 3. 80/12/01. 11pp. 07337:087.
- --8012293107 Confirms E01124 conversation at Bechtel that NRC will attempt to answer E01112 interrogatories Responses will be provided as soon as possible.
 JOHES, B. W. Office of the General Counsel. E0/11/26. 1p. 07337:098.
- 8012270170 Notice of ASLB constitution RS Saliman appointed Chairman & JH Buck & CN Kohl.members. BISHDP.C.J. Administrative Branch. 80/12/01. 1p. 07343:362.
- 8012230016 Informs that info re effect of change in NRC position concerning seismic design requirements on other structures in Mi Basin: is now available.

 MARREN.S.K. Actomic Safety and Licensing Board Panel. WARREN.S.K. Atomic Safety and Licensing Board Panel. 190/12/02. 1p. 07311:178.
- 8012230233 Order granting NRC B01128 motion to extend discovery to 810123 Prehearing conference set for 810105-09 will be reschaduled at later date. BCCHHORFERA.C. Atomic Sofety and Licensing Board Panel. B0/12/04. 2pp. 07317:270.
- 8012290140 Document requests to util for Interim Rept 1 (MCAR 24) & info re soil settlement issue & interrogatories reconsultant role in soil settlement matters. Related correspondence.

 STAMIMIS, 2. Affiliation Unknown. 80/12/04, 3pp. 07308:001.
- 8012290305 Brief in opposition to WH Harshall B01117 appeal from ASLE B01024 order denying petition to intervene Moves ASLAB to affirm denial of petition in mod order proceeding. Certificate of Svc encl. PATOU.N.D. Hearing Branch 2. 80/12/04. 12pp. 07341;214.
- 8012300233 Hotion for protective order re further deposition of J Kane. In alternative, further discovery should be conducted via unitten interrogatory. Draft protective order & Certificate of Svc encl.

 JCNFS, B. H. Hearing Branch 2. 80/12/04. 6pp. 07357:050.
- B012240016 Notice of G Gallagher, 9 Figrelli & H Singh B01216, 17 & 18 depositions, respectively, re issues contained in 791206 order & contentions in 801024 order app. FARNELL, A. S. Consumers Power Co. B0/12/09, 4pp. 07324: 202.
- 8012230304 Notice of 3 Dahr of Bechtel 801217 deposition re issues sat forth in ASLB 701205 order modifying CPs & Stamiris & Warren contentions Certificate of 8vc enci. PATON N.D. Hearing Branch 4. 80/12/11. 4pp. 07318:077.
- 8012290148 Forwards Comptroller General ltr informing that transcripts will no longer be provided to intervenors but will be available at PDR.W/o encl.
 JDN=8.B.H. Hearing Branch 2. 80/12/15. 1p. 07344:052.
- 8012300068 Order directing prehearing conference to commence 810128 in Hidland.HI.
 BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 80/12/15.
 3pp. 07358:346.
- 8012290242 Motion for extension to 810109 to file reply in apposition to NRC motion for protective order. Draft order & Certificate of Svc encl.
 ZAMARIN.R. Consumers Power Co. ZAMARIN.R. Isham, Lincoln & Beale. 80/12/17. Spp. 07341:162.

- 8012290345 Memorandum & order affirming ASLB 801024 order denying NH Marshall potition for leave to intervene in mod order proceeding instituted to ameno CPs.

 BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/12/17. Spp. 07343:136.
- 8012300P05 Request for documents including record of CPC 801107 telcon concerning soil settlement matters, IE Insp Repts 50-329/77-05 & 50-330/77-08 & Region III 790508-11 mid-const QA (nep rept. Related correspondence. STAMIRIS, B. Affiliation Unknown. 80/12/18. 2pp. 07356:357.
- B012290867 Responds to B01112 questions on dowatering. Mater from dewatering sys is not being pumped into Tittabawasse River, but into facility cooling pond.

 JCNFS, B. W. Hearing Branch 2. B0/12/23, 2pp. 07332: 249.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012300557 Forwards affidavit of svc of Amend 86.Revision 31 to FSAR, to application for CPs & OLs.
 BUDZIK, D. M. Consumers Power Co. 80/12/22. ig. 07357: 333.
- G. Inspection reports, IE Bulletins & correspondence
- 8012170271 Forwards Suppl 3 to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/24.

 1p. 07268:251.
- 80:2170537 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/24.

 1p. 07268:144.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments if/o enci.

 KEPPLER. J. G. Region 3, Chicago, Office of the Director. 80/11/18.
- 8012040649 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLEN.J.G. Region 3, Chicago, Office of the Director. 80/11/21.

 2pp. 07169.104.
- 8012080741 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Shubber Fluid." No written response required. KEPPLER.J.G. Region 3, Chicago, Office of the Director. 80/11/24. 2pp. 07182:168.
- 8012170545 Forwards 1E Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.

 KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/26.
 2pp. 07264: 278.
- 8012230338 Forwards response to items of noncompliance noted in IE Investigation Repts 50-329/80-13 & 50-329/80-14. Failure of anchor bolts indicative of quality problem. Ongoing remedial actions necessary for correction COSK. J. W. Consumers Power Co. 80/12/16. 11pp. 07318:219.
- R. Periodic operating reports & related correspondence
- 8012310225 Forwards monthly rept per ALAB-104, Bechtel nonconformance repts, Bechtel nonconformance rept log. Bechtel quality action requests. B&H repts of nonconformity, B&W inservice insp nonconformance repts & util nonconformance repts encl. COCK. J. W. Consumers Power Co. 80/12/23. 350pp. 07308:001.
- 5. Reportable occurrences. LERs & related correspondence
- 8012180292 Part 21 rept re potential defect in ASTM A-540, Or E23, C1 3 heavy hex bolts, supplied by Southern Bolt Festening Corp. Caused by use of faulty matls during forging operation. Final rept will be sent. pending replacement part GC. HARBISUN, D. NPS Industries, Inc. 80/11/14, 14pp. 07240:055.
- 8012020577 Interim deficiency rept re HELBA restraint design. First reported in JW Cook 800919 ltr. Civil group has initiated reanalysis of pipe whip restraints using peak thrust forces. Interim rept will be provided by 810402.

 COUK. J. W. Consumers Power Co. 80/12/01. 12pp. 07148:052.

- 8012100502 Interim deficiency rept re companent qualification test documentation, initially reported on 781128. Status of Bechtel component qualification program & Bechtel final rept encl. Next rept will be forwarded by 810327.

 COOK, J. N. Consumers Power Co. 80/12/05. 49pp. 07218:311.
- B012160353 Interim deficiency rept re reactor vessel anchor bolt failure, completing design package of proposed mods. Prestress levels of studs have been lowered. Next rapt will be sent by Bi0331.

 CCOK. J. N. Consumers Power Co. BALLEY. K. D. Bechtel Power Corp. (subs. of Dechtel Corp.). B0/12/10. 54pp. 07235:037
- 8012230277 Deficiency rept re emergency core coaling actuation sys, first reported on 801117. Wiring inconsistencies exist in four decay heat valve automatic closure interlock trip buffer analog subsys. Next rept will be filed by 810227. COOK. J. W. Consumers Pawer Co. 80/12/17. Spp. 07317:357.
- 8012300440 Deficiency rept.originally reported on B01117, confirming anomalies identified in NSSS seismic & LOCA analysis of primary sys. Reactor pressure vessel supporting sys being modified due to reactor vessel bulting problems. CODX.J.W. Consumers Power Co. B0/12/18. 2pp. 07344:125.
- T. Hearing transcripts on non-antitrust matters
- B012240001 Forwards transcript of JD Kane 801014-16 deposition. W/o encl. PATOU. W. D. Hearing Branch 4. 80/12/05. 1p. 07324:193.
- B012270104 Proposed corrections to JD Kane B01015-16 deposition. Certificate of Svc encl. PATON.W.D. Hearing Branch 4. B0/12/05. 11pp. 07343:074.
- V. Operator Examinations
- 80120203B8 Summary of 801027 meeting u/util in Bethesda. HD re operator training & qualification. Lists variations approved by NRC & notes request for 70 cold liceuse examinations.

 JABBOUR, K. N. Licensing Branch 3. WILSON, B. Operator Licensing Branch. 80/11/17. 6pp. 07143:173.
- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREQ-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISEKHUT,D.G. Division of Licensing. 80/10/31. 7pp.
- 8012090133 Notification of 801205 meeting w/util & consultants in Sethesda.MD to discuss seismological input for site pursuant to NRC 801014 encl ltr.U/o encl. HQOD.D. Licensing Branch 3, 80/11/14, 4pp. 07199:202.
- 8012020106 Confirms 801124 meeting in Jackson MI to discuss regional evaluation of regulatory porformance at facilities.

 XEPPLER, J. C. Region 3. Chicago, Office of the Director. 80/11/19.

 1p.
- 8012080366 Forwards request for addl info & clarifications needed to complete independent confirmatory piping analysis. Requests justification of several stress intensity values for piping components & sys reported in FSAR Tables 3.9-15 & 3.9-15A. TEDEECO.R.L. Assistant Director for Licensing. 80/11/20. App. 07196:199.
- 8012080805 Forwards add1 info & clarifications needed to complete independent confirmatory piping analysis at facility, request justification for several stress intensity values for piping components & sys reported in FSAR tables. AUCE.L.J. Energy Technology Engineering Center. 80/11/20. App. 07187:074.
- 8012020323 Forwards "Site Specific Response Spectra for SSE," providing preliminary info for presentation & discussion at util 801205 meeting w/NRC.
 CODK, J. R. Consumers Power Co. 80/11/29, ip. 97142:029.
- --8012020328 Preliminary rept, "Site Specific Response Spectra for SSE."

 4 Kestern Geophysical. 80/11/28. 19pp. 07142:030.
- 8012050322 Forwards affidavit confirming distribution of Amend 85 to OL application.
 BUDZIK, D. K. Consumers Power Co. 80/12/02. 5pp. 07175:053.

- 8012080480 Advises that Amend 85 to util application for CPs & OLs was sent under separate cover.
 BUDZIK.D.M. Consumers Power Co. 89/12/02 1p. 07884:281.
- 8012170775 Forwards request for add1 info re tornado missile protection & containment seismic analyses for FSAR review.
 TEORESCO.R.L. Assistant Director for Licensing. 80/12/04. 3pp.
 07264:050.
- 8012100679 Confirms 801202 meeting in Olen Ellyn, IL to discuss recently reorganized OA unit. FIORELLI.O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 1p
- 8012160443 Responds to 800613 & 0825 meetings between util & NRC retimely resumption of formal docket review of plant.OL application is ready for post-TMI review. Proposes expeditious review & requests comment.
 CDUK, J. W. Consumers Power Co. 80/12/10. 3pp. 07263:136.
- F. Security, medical, emergency & fire protection plans
- 8012040114 Public version of "Independent Assessment of Evacuation Times for Midland Nuclear Power Plant." Vol 7, prepared for FERIA. COSBY, J.C., SHEPPARD, W.V., BANCROFT, J.R. Wilbur Smith & Associates. 80/06/30. 58pp. 07158: 206.
- BO12040065 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, FELTOW, J. H. Division of Rules and Records. BO/12/03, 1p.
- --8012040088 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEMA.

 Wilbur Smith & Associates. 80/06/30. 17pp.
- --8012040155 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol 1. prepared for FEMA. COSEY. J. C. Wilbur Smith & Associates. BO/O6/30. 43pp.
- Q. Adjudicatory correspondence
- BO12020649 Appeal from ASLB 801027 order.Order stands moot re jurisdiction.Too many factors have not been reported re drainage & groundwater pressure.Certificate of Svc encl MARBHALL,N.H Mapleton Intervenors. 80/11/19. 17pp. 07143:296.
- BO12050432 Notice of ASLAB constitution.RS Salzman.chairman & JH Buck & CN Kohl, panel members. BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/11/24. ip. 07173:305.
- BO12050443 Notice of B01209-11 depositions of W Ferris, B Dahr & T Thiruvengadam all of Bechtei Associates, Sub; will concern issues in ASLB 791204 order modifying CPs. Certificate of Svc encl. PATOK. W. D. Hearing Branch 2. B0/11/25. 4pp. 07173:309.
- 8012050420 Interrogatories, including requests for documents, directed to CPC, addressing seismic & structural issues plus remedial actions. Certificate of Svc encl.
 PATON, W. Hearing Branch 2. 80/11/26. 11pp. 07173:291.
- 8012050462 Forwards uncorrected transcript of D Hood 801008 deposition & G Gallagher 801117-18 deposition W/o encis.

 JONES B. W. Hearing Branch 2. 80/11/26. 2pp. 07173:320.
- 8012050670 Confirms B01124 telcon informing that NRC will attempt to answer B01112 interrogatories although not technically in compliance w/Commission rules.

 UNNES.B. N. Hearing Branch 2. 80/11/26 ip. 07179:319.
- B012020694 Request for extension until B10123 for termination of discovery due to complexity of issues Prehearing conference should be held on B10126-30 Certificate of Svc encl. PATON, W. D. Hearing Branch 4. B0/11/28 3pp. 07147:286.
- 8012290107 Forwards to Midland Technical hearing participants listing of formal requests for info re soil settlement problem. Date corresponds to issuance of NRC order prohibiting certain const activities until amend to CPs is granted. HODD. D. Licensing Branch 3. 80/12/01 11pp. 07337:087.

- --8012270109 Confirms 801124 conversation at Bechtel that NRC will attempt to answer 801112 interrogatories Responses will be provided as soon as possible.
 30:62,8 W. Office of the General Counsel. 80/11/26. ip. 07337:078
- 8012290170 Notice of ASLB constitution.RS Salzman appointed Chairman & JH Buck & CN Kohl, members. BISHOP, C. J. Administrative Branch, 80/12/01, 1p. 07343:362.
- 8012230016 Informs that info re effect of change in NRC position concerning seismic design requirements on other structures in Al Basinis now available. WARREN,S K. Atomic Safety and Licensing Board Panel. WARREN,S, K. Atomic Safety and Licensing Board Panel. 19. 07311:178.
- B012230233 Order granting NRC B01128 motion to extend discovery to B10123.Prehearing conference set for B10105-07 will be rescheduled at later date.
 BECHHOZEEK.C. Atomic Safety and Licensing Beard Panel. B0/12/04.
 2pp. 07317:270.
- 8012370140 Document requests to util for Interim Rept 1 (MCAR 24) & thio re soil settlement issue & interrogatories re consultant role in soil settlement catters. Related correspondence. STAMIRIS.S. Affiliation Unknown. 89/12/04. 3pp. 07308:001.
- 8012290305 Brief in opposition to kH Marshall B01119 appeal from ASLB B01024 order denying petition to intervene Hoves ASLAB to affirm denial of petition in mod order proceeding. Certificate of Svc encl. PATON.W. D. Hearing Stanch 2. 80/12/04. 12pp. 0/341:214.
- 8012300233 Motion for protective order re further deposition of J Kane. In alternative further discovery should be conducted via unitten interrogatory Brait protective order & Certificate of Svc enct.

 JBNS.B. N. Hearing Branch 2. 80/12/04. 6pp. 07357:050.
- 8012230304 Notice of B Dahr of Sechtel 801217 deposition re issues set forth in ASLB 791206 order modifying CPs & Stamiris & Warren contentions. Certificate of Svc encl. PATOR: U. D. Hearing Branch 4. B0/12/11. 4pp. 07318:077.
- 8012290148 Forwards Comptroller General ltr informing that transcripts will no longer be provided to intervenors but will be available at PDR.W/o encl.

 JONES.B. (f. Mearing Branch 2. 80/12/15. ip. 07344:052.
- 8012300048 Order directing prehearing conference to commence 810128 in RECHIDEFER.C. Atomic Safety and Licensing Board Panel. 80/12/15.
- 8012290242 Motion for extension to 810169 to file reply in opposition to NRC notion for protective order. Draft order & Certificate of Svc enci.

 ZAMARINAR. Consumers Power Co. ZAMARINAR. Isham, Lincoln & Beale. 80/12/17. 5pp 07341:162. Consumers Power Co. ZAMARIN,R. Isham, Lincoln & Beale. Spp 07341:162.
- 8012290365 Memorandum & order affirming ASLB 801024 order denying UH Marshall petition for leave to intervene in mod order proceeding instituted to amend CPs.
 BISHOP.C. J. Atomic Safety and Licensing Appeal Panel. 80/12/17. Spp. 07343:136.
- 8012300705 Request for documents including record of CPC 801107 telcon concerning soil settlement matters, IE insp. Repts 50-327/77-05 & 50-330/77-08 & Region III 790508-11 mid-const QA insp. rept.Related correspondence.
 STAMINIS, B. Affiliation Unknown. 80/12/18, 2pp. 07396:357.
- 8012290557 Responds to 801112 questions on dewatering Water from dewatering sys is not being pumped into Tittabawasse River, but into facility cooling pond.
 JCMES.B. W. Hearing Branch 2. 80/12/23 2pp. 07332:249.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012300557 Forwards affidavit of svc of Amend 86,Revision 31 to FSAR, to application for CPs & DLs. BUDZIM.D.H. Consumers Power Co. 80/12/22. [p. 07357:333.

- O. Inspection reports, IE Bulletins & correspondence
- 80:2170271 Forwards Suppl 3 to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required.

 KEPPLER, J. G. Region 3. Chicago, Office of the Director. B0/10/24, 1p. 07268:251.
- 8012170537 Forwards 1E Info Notice 80-37, "Containment Coeler Leats & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER.J. O. Region 3. Chicago. Office of the Director. 80/10/24. 07269: 144
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. W/o encl.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/10.
- 8012040649 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response Required.

 KEPPLER.J. G. Region 3. Chicago. Office of the Director. 80/11/21.
- B01208004: Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response raquired. KEPPLER.J. Q. Region 3, Chicago, Office of the Director. 80/L1/24. 2pp. 07182:188.
- 80:2170545 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/26. 07264: 278 2pp.
- 8012230338 Forwards response to items of noncompliance noted in IE Investigation Repts 30-329/80-13 & 50-330/80-14. Failure of anchor boilts indicative of quality problem. Ongoing remedial actions necessary for correction COOK, J. W. Consumers Power Co. 80/12/16, 11pp. 07318: 219.
- R. Periodic operating reports & related correspondence
- 8012310225 Forwards monthly rept per ALAB-106. Bechtel nonconformance repts. Bechtel nonconformance rept log. Bechtel quality action requests. BEN repts of nonconformity. BEN inservice insp nonconformance repts & util nonconformance repts encl. COOK-J.W. Consumers Power Co. 80/12/23, 350pp. 07308:001.
- S. Reportable occurrences, LERs & related correspondence
- 8012150252 Part 21 rept re potential defect in ASTM A-540, Or B23, Cl 3 hoavy hex bolts, supplied by Southern Bolt Fastening Corp. Gaused by use of faulty matls during forging operation. Final rept will be sent, panding replacement part GC.
 HARBISON, D. NPS Industries, Inc. B0/11/14. 14pp. 07240:055.
- 8012020577 Interim deficiency rept re HELBA restraint design. First reported in JW Cook 800919 ltr.Civil group has initiated reanalysis of pipe whip restraints using peak thrust forces. Interim rept will be provided by 810403. COCK.J.W. Consumers Power Co. 80/12/01. 12pp. 07148:052.
- B012100502 Interim deficiency rept re component qualification test documentation initially reported on 781128. Status of Bechtel component qualification program & Bechtel final rept encl. Next rept will be forwarded by 810327.

 CGDK. J. W. Consumers Power Co. 80/12/05. 69pp. 07218:311.
- 8012160353 Interim deficiency rept re reactor vessel anchor bolt failure.completing design package of proposed mods.Prestress levels of studs have been lowered Hext rept will be sent by H10331. B10331. COCK.J.U. Consumers Power Co. BAILEY.K.D. Bechtel Power Corp. (subs. of Bechtel Corp.). 80/12/10. 54pp. 07255:037.
- B012230277 Deficiency rept re amergency core cooling actuation systems of the reported on B01117 Wiring inconsistencies exist in four decay heat valve automatic closure interlock trip buffer analog subsys. Next rept will be filed by 810227.

 COCK. J. U. Consumers Power Co. 80/12/17. 5pp. 07317:357.
- 8012300460 Deficiency rept originally reported on 801117, confirming anomalies identified in NSSS swismic & LOCA analysis of primary sys. Reactor pressure vessel supporting sys being modified due to reactor vessel bolting problems.

 CGDK, J. W. Consumers Power Co. 80/12/18. 2pp. 07346:125.

- T. Hearing transcripts on non-autitrust matters
- HO12240C01 Forwards transcript of JD Kane B01014-16 deposition.W/o encl. PATON N.D. Hearing Branch 4. B0/12/05. 1p. 07324:193.
- 8012290104 Proposed corrections to JD Kane 801015-16 deposition. Certificate of Syc encl. PATUH.W.D. Hearing Branch 4. 80/12/05. 11pp. 07343:074.

V. Operator Examinations

B01202038B Bummary of B01027 meeting w/util in Bethesda.HD re operator training & qualification.Lists variations approved by NRC & notes request for 70 cold license examinations. JAUBOUR.K. N. Licensing Branch 3. (ITLSON.B. Operator Licensing Branch. 80/11/17. 6pp. 07143:173.

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

- F. Becurity, medical, emergency & fire protection plans
- 8012040099 Forwards interim 10CFR50.48 suspending completion dates for fire protection mode, affective upon 801029 publication in 45FR71549. Rule will be superseded by revised rule when affective.
 EISERHAUT.D.O. Division of Licensing. 80/11/07. 6pp. 07170:244.
- 8012010481 Forwards list of deficiencies found in 800730 emergency plan.per review against NUREO-0654 criteria.Plan must be revised to address 10CFR30 provisions.effective 801103. IPPOLITO.T.A. Operating Reactors Branch 2. 80/11/13. 11pp.
- 8012020052 Discusses planned mode to emergency notification sys & health physics network NRC will pay for installation of output jacks to provide capability for adding one-way speaters to sys, Wo encl health physics network manual. KEPPLER, J. 0. Region 3, Chicago, Office of the Director. 80/11/19. 288. 07148:341.
- 8012310006 Ltr to all power reactor licensees w/plants licensed prior to 790101. Forwards revised Section 10CFR50.48 & App R refire protection features in nuclear power plants & list of requirements for resolution of open issues. W/o and1.
 EISELECTIO. 0. Division of Licensing. 80/11/24. 3pp. 07371:069.
- ~-801231000B Ltr to all power reactor licensees w/plants licensed prior to 790101.FR notice forwarded w/801124 ltr contains typographical error in effective date Correct date is BLO217.FR notice & summary of facility open items encl. EISE/MUT.D. 0. Division of Licensing. 80/11/25. 18pp. 07371:072.
- 8012100632 Releases public version of State of IA.Linn County & Benton County evacuation time estimates. FELTON.J.K. Division of Rules and Records. 80/12/02. 1p.
- --8012100635 Public version of State of IA,Linn County & Benton County
 "Evacuation Time Estimates."

 4 Linn County,IA. * Affiliation Unknown. 80/01/31. 30pp.
 07222:181.

1. Financial information

- 8012010366 Forwards certified projected cash flow for 1980 & actual cash flow for 12 months ending Sept 1980. Nov 1980 shareholder's bulletin & util cooperative ltrs guaranteeing premium encl.
 REHNSTROM. J. B. Iowa Electric Light & Power Co. 80/11/20. 7pp. 07998-048.
- --B012010376 Forwards Natl Rural Utils Cooperative Finance Corp B0103i Itr approving line of credit for 12-month term. Ability to respond to call for restrospective premium is guaranteed in compliance w/Price-Anderson Act.

 VILLIANS, E. H. Central lowa Power Cooperative. B0/11/07. 3pp. 07398-074.
- P. Operating license stage documents & correspondence
- B012160050 Ltr to operating plant licensess.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licenses confirmation in 45 days that Encl I implementation dates will be net. EISE(MUT.D.G. Division of Licensing. 89/10/31. 7pp.

- 8012220358 Ltr to all CP & OL holders for 8HRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENMAT.D. G. Division of Licensing. 80/11/04. App.
- 8012090318 Forwards revised ASKE inservice testing submittal, incorporating answers to 801002 teleon questions & addinevisions necessary for safe & efficient operation. ROUT.L.D. I gwa Electric Light & Pawer Co. 80/11/11. 4pp. 07201:177.
- --8012090321 "ASKE Inservice Testing Program for Pumps & Valves for Period 780601-820701," Revision 3.

 + Iowa Electric Light & Power Co. 80/11/01, 163pp. 07201:181.
- 8012270563 Ltr to all power reactor licensees forwarding NUREG-0619, "BMR Feedwater Norrle & Control Rod Drive Return Line Norrle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. M/O encl. EISERMUT, D. G. Division of Licensing. 80/11/13. 1p.
- 8012050399 Intends to respond to NUREQ-0737 requirement II.K. 3.30, revised small break LOCA methods to show compliance w/CFR59 App K. through GE Requests schedule & scope of questions be directed to GE.
 ROOT. L. D. I awa Electric Light & Power Co. 80/11/25. 1p. 07174:023.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENIDN:H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BARGART, R. L. Effluent Treatment Systems Branch. 80/11/06. Bap.
- 8012230297 Responds to 801031 ltr re post-TMI requirements. Schedule extensions for some reuirements may be needed as hardware availability has affected TMI related schedules. ROOT.L.D. Iowa Electric Light & Power Co. 80/12/15. 1p. 07314:092.
- 8012230457 Advises that results of re-evaluation of scram sys & necessary mods to design & performance criteria will be provided by 810114.
 ROOT, L. D. Iowa Electric Light & Power Co. 80/12/15. ip. 07314:120.
- G. Inspection reports, IE Bulletins & correspondence
- 8012170634 Forunds IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER. J. O. Region 3, Chicago, Office of the Director. 80/10/24.

 ip. 07244:188.
- 8011190078 Forwards final response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," & responds to NRC 801001 ltr re equipment testing Outstanding components will be tasted, shielded & relocated by June 1982. ROOT.L.D. Iowa Electric Light & Power Co. 80/10/31. 2pp. 06916:001.
- --8012010527 "Duane Arnold Energy Ctr Response to IE Bulletin 79-010, Environ Qualification of Class IE Equipment." * Dechtel Corp. 80/10/31, 100pp. 07094:248.
- 8012040255 Forwards IE Insp Rept 50-331/80-16 on 800908-11 & 1015-16 & notice of violation.
 DAVIS.A.B. Region 3. Chicago, Fuel Facility & Materials Safety
 Branch. 80/10/31. 2pp. 07162:320.
- --8012040257 Notice of violation from insp on 800708-11 & 1015-16.
 * Region 3, Chicago, Office of the Director. 80/10/30. lp. 07162:322.
- --B012040263 IE Insp Rept 50-331/80-16 on B00908-11 & 1015-16.
 Noncompliance noted: failure to rept required nuclides in effluent.
 GRANT, N. B., JANUSKA, A. G., PAPERIELLO, C. Region 3, Chicago, Office of the Director. B0/10/30. 12pp. 07162:323.

- 8012110093 Forwards IE Insp Rept 50-331/80-15 on 800901-30. No noncompliance noted. HEISHMAN.R.F. Region 3- Chicago: Reactor Operations Nuclear Support Branch. 80/11/05 2pp. 07225.033.
- --8012110703 IE Insp Rept 50-331/80-15 on 800901-30. No noncompliance noted Major areas inspected:plant operations maint, procedures, documentation & work performed. CHRISTIANSON N. CLARDY.L.S. LITYLE.N.S. Region 3, Chicago, Office of the Director. 80/10/24. 8pp. 07225:055.
- 8012150265 Forwards IE Insp Rept 50-331/80-20 on 801014-16.No noncompliance noted.

 MEISHMAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 80/11/06. 2pp. 07237:317.
- --8012150268 IE Insp Rept 50-331/80-20 on 801014-16.No noncompliance noted. Major areas inspected: licensee implementation of GA program in areas of receiptistorage & procurement control. JACKIII, I.N., SCHULZ, R.D. Region 3, Chicago, Office of the Director. BAKER, K.R. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/06. 5pp. 07237:319.
- 8012190271 Forwards IE Insp Rept 50-331/80-19 on 800929-1002 & 21-23.No nancompliance noted.
 FIGRELLI,O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/(1/13. 2pp. 07286:026.
- --8012190277 IE Insp Rept 50-331/80-19 on 800929-1002 & 1021-23. No noncompliance noted Major areas inspected: torus support reinforcement installation, welfoing & nondestructive examinations & IE Bulletins 80-07 & 80-08 actions.

 KEY. N. J. Region 3, Chicago, Office of the Birector.

 DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/12. 5pp. 07286:028.
- 8012320743 Forwards three Performance Appraisal Branch insp repts & mgt avaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments N/o encl.

 KEPPLER. J. G. Region 3. Chicago. Office of the Director. 80/11/18. 4pp.
- B012020557 Immediate action ltr re health physics appraisal exit meeting. Notes understanding that portable survey (instruments will be calibr by B01121 to meet requirements of emergency assignment board tag duties.

 MEPPLER.J. G. Region 3. Chicago. Office of the Director. B0/11/21.

 1p. 07143:313.
- 8012040653 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER J. C. Region 3. Chicago, Office of the Birector. 80/11/21.

 2pp. 07166:316.
- 8012310442 Forwards IE Insp Rept 50-331/80-18 on 801001-31 No noncompliance noted. HEISHMAUR.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/11/21. 29p. 07370:221.
- --8012310447 IE Insp Rept 30-331/80-18 on 801001-31. No noncompliance noted Hajor areas inspected plant operations maint & procedure.

 CHRISTIANSON, W., CLARDY, L.S., LITTLE, W.S. Region 3, Chicago, Office of the Director. 80/11/21. 4pp. 07370; 223.
- 8012080057 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:208.
- 8012110763 Ack receipt of 801024 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-313/80-13. HEISHWAM R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/11/24. p. 07225:086.
- ---8012110769 Responds to MRC 801003 ltr re violations noted in IE Insp. Rept 50-331/80-13 Corrective actions: exhaust vacuum breakers tested u/satisfactory results. ROOT-L. D. Iowa Electric Light & Power Co. 80/10/24. 2pp. 07225:087.
- 8012220594 Forwards new security badge numbers & clearance levels for Region 3 personnel Changes should be entered on Sept 1980 access lists KEPPLER.J. C. Region 3. Chicago, Office of the Director. 80/11/25, 6pp. 07309:007.

- 8012170535 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flango." No written response required. KEPPLER. J. G. Region 3, Chicago, Office of the Director. B0/11/26, 2pp. 07268:140.
- 8012090274 Forwards effluent rapt data for 1979 & 1980.in response to NRC ltr re IE insp on 800908-11. RBDT,L.D. Fowa Electric Light & Power Co. 80/12/01, ip. 07201:105.
- --8012070296 Effluent rept data for 1979 % 1980. * Iowa Electric Light & Power Co. 80/12/01. 2pp. 07201:106.
- 8012240°54 Ack receipt of 801118 ltr informing NRC of steps taken to correct violation noted IE Insp Rept 50-331/80-17.
 HIND, J. A. Region 3, Chicago, Safeguards Branch, 80/12/01, 1p. 07325:113.
- --8012240263 Responds to NRC 801003 ltr re violations noted in IE Insp Rept 50-331/80-17. Corrective actions withheld (ref 13CFR2,790). RODT.L.B. lowa Electric Light & Power Co. 80/11/24. 1p. 07325:114.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-018 re moviron qualification of Class IE equipment. HAYES,D.W. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp.
- R. Periodic operating reports & related correspondence
- 8012070794 Forwards effluent rept data for 1979 & 1980.in response to NRC ltr re IE insp on 800908-11. 'R00T.L.D. lows Electric Light & Power Co. 80/12/01. ip. 07201:105.
- --8012090296 Effluent rept data for 1979 & 1980. * Iowa Electric Light & Power Co. 80/12/01. 2pp. 07201:106.
- 8012230311 Forwards monthly operating rept for Nov 1980. MINECK, D. L. Jowa Electric Light & Power Co. 80/12/15. 1p. 07318:084.
- ~~8012230314 Monthly operating rept for Nov 1780. VAN BICKEL J. Towa Electric Light & Power Co. 80/12/15. 7pp. 07318:085.
- 8. Reportable occurrences. LERs & related correspondence
- 801201040B Informs NRC that RO initially reported on 801111 re reactor wassel exessive cooldown rate was not in violation of Tech Spec requirements. Reportable conditions did not exist. No further rept will be provided.

 MINECK, D. L. Iowa Electric Light & Power Co. 80/11/19. 1p. 07098:066.
- 8012020492 Forwards LER 80-055/01T-0. MINECK, D. L. Jowa Electric Light & Power Co. 80/11/24, 1p. 07148:120.
- --8012020495 LER 80-055/01T-0: on 801110 main steam relief valve stuck open resulting in Rx scram. Caused by wiring error during 1980 design change work & inadequate post-installation testing. Error corrected & test procedure revised.
 TOCKER, D. N. I lowa Electric Light & Power Co. 80/11/24. 3pp. 07148: 121.
- 8012020541 Forwards LER 80-053/03L-0. MINECK.D.L. Iowa Electric Light & Power Co. 80/11/24. ip. 07148:077.
- --8012020546 LER 80-053/03L-0: on 801106 discovered that monthly functional test of turbine control valves fast closure for reactor protection sys trip & recirculation pump trip initiation logic had not been run for Oct. RAGER(N. 8. lowe Electric Light & Power Co. 80/11/24. ip. 07148:078.
- 8012020593 Forwards LER 80-054/017-0, MINECK.O.L. Towa Electric Light & Power Co. 80/11/24, ip. 07148:037.
- --8012020613 LER 80-054/01T-0: on 801110, during startup, relief valve P8U-4405 began leaking. Cause unknown. Spare relief valve was setpoint tested, re-worked & installed.
 TOCKER.D.W. lowa Electric Light & Power Co. 80/11/24. 2pp.
 07148: 038.

- 8012190593 Forwards LER 80-057/03L-0. MINECK.D.L. lows Electric Light & Power Co. 80/12/12. 1p. 07286:154.
- --8012190599 LER 80-057/03L-0: on 801114.drywell pressure recorder PR 4384A found failed downscale.Caused by defective amplifier board.Board replaced & serve motors cleaned prior to recorder startup.

 RAGER.M.S. I dwa Electric Light & Power Co. 80/12/12. ip. 07286:155.
- 8012190643 Forwards LER 80-056/03L-0. MINECK.D.L. Iowa Electric Light & Power Co. 80/12/12. 1p. 07287: 297.
- --8012170650 LER 80-056/03L-0: on 801114, drywell high pressure switch P8 4312C tripped above Tech Spec Caused by instrument drift. Switch recalibr, tested & returned to svc. RAGER, M. S. Iowa Electric Light & Power Co. 80/12/12, 1p.
- 8012240241 RO: on 801217, during testing of suppression chamber level transmitters LT 43638 % LT 2325, calibr error by technicians led operations personnel to believe suppression chamber was filled to 1,200 cubic ft above Tech Specs limit. MINECK, D. L. lowa Electric Light & Power Co. 80/12/17. 1p. 07323; 209.
- B012300465 Forwards LER G0-05B/03L-0. MINECK.D.L. Iowa Electric Light & Power Co. B0/12/18. 1p. 07349:347.
- --8012300468 LER 80-058/03L-0: on 801117; during annual testing of instrument ac & battery bus undervoltage relays relay 27-Y11 (240 volt instrument ac undervoltage relay) dropout voltage determined under Tech Spec setpoint. Cause unknown. RAGER, M. S. Iowa Electric Light & Power Co. 80/12/18. ip. 07349:348.
- B012290410 Forwards LER 80-059/03L-0. HINECK.D.L. lowa Electric Light & Power Co. B0/12/19. §p. 07336:315.
- --8012270414 LER 80-059/G3L-0: on 801120, reactor coolant isotopic analysis not completed within scheduled time limit. Caused by germanium-lithium counting sys being inoperative. Spectrum amplifter replaced & coolant test completed. RAOER, M. S. lowa Electric Light & Power Co. 80/12/19. ip. 07336:316.
- 8012290422 Forwards LER 80-060/03L-0. MINECK.D.L. Iowa Electric Light & Power Co. 80/12/19. 1p. 07336;361.
- --8012270428 LER 80-060/03L-0: on 801128, discharge vol high water level instrument functional test was not run before going to power operation Caused by operator error.Personnel will be reinstructed.

 RACER.M.S. I lowa Electric Light & Power Co. 80/12/19. ip.
- DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR PONER PLANT
 F. Security, medical, emergency & fire protection plans
- B012040091 Forwards interim 10CFR50.48 suspending completion dates for fire protection mods.effactive upon 801029 publication in 45FR71369.Rule will be suppressed by revised rule when effective.
 EISENHUT, D. Q. Division of Licensiry. 80/11/07. App. 07170:296.
- 8012050550 Informs that mods will be made to emergency notification sys & health physics network equipments. ARC will have lamps installed on smergency telephones in all control rooms, technical support ctrs & emergency operations facilities.

 ORIER, B. H. Region I. Philadelphia, Office of the Director.

 80/11/14. 2pp. 07174:271.
- P. Operating license stage documents & correspondence
- 8012160030 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be ret. EISENHUT.D.O. Division of Licensing. 80/10/31. 7pp.

- 8012220358 Ltr to all CP 3 GL holders for Bids re requirement for implementation of ODYN code for licensing basis calculations parformed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing. 80/11/04. App.
- G012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BMR Feeduater Nozzle & Control Rod Drive Return Line Nozzle Cracking," Confirmation that implementation dates will be met must be sent within 45 days U/o encl. EISENUT.D.6. Division of Licensing. B0/11/13. 1p.
- B0122904B5 Responds to B00911 memo requesting that Ofc of Nuclear Reactor Regulation inform Licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DEMIGN.H.R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% or reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. Opp.
- 8012230391 Discusses implementation of NUREO-0737. "Clarification of TMI Action Plan Requirements." Lists actions to be taken when required equipment is unavailable.
 BAYNE, J.P. Power Authority of the State of New York. 80/12/16.
 4pp. 07312:247.
- 8012300584 Submits supplemental info per 801024 ltr & provides addlinfo in response to 801001 ltr re plans to modify plant to mest design & performance criteria by end of 1982.

 BAYNE, J.P. Power Authority of the State of New York. 80/12/16, 2pp. 07357: 330.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012090149 Ack receipt of 800918 ltr informing NRC of steps taken to correct violations noted in IE Waste Packaging Insp Rept 15000039/80-14.
 SMITH.O.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/28. 1p. 07200:101.
- --8012090155 Responds to NRC 800519 ltr re violations noted in IE Waste Packaging Insp Ropt 15000039/80-14 Corrective actions: Standing Order 18 Exhibit 9.1 will be revised adding insp requirements. Revision issued by 801031 PASTERNAW. R. J. Power Authority of the State of New York, 80/09/18. 3pp. 07200:105.
- --8012090158 Forwards IE Waste Packaging Insp Rept 15000039/80-14 on 800619 & notice of violation SMITH.O.H. Region 1. Philadelphia. Office of the Director. 80/09/03. 2pp. 07200:109.
- --8012090163 Natice of violation from insp on 800619.

 * Region 1, Philadelphia: Office of the Director. 80/09/07. 2pp. 07200:107.
- ---8012070167 IE Waste Packaging insp Rept 15000039/80-14 on 800619.
 Noncompliance noted: outside of Model 14-195-4. Number 10
 shipping cask not stencilled or otherwise marked to identify as radioactive.
 MACARTHUR.T.C., POTTER.J.P. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 80/08/07. 3pp. 07200:109.
- 8012190710 Forwards IE Insp Rept 50-333/80-16 oπ 800908-12.No honcompliance noted. BRUNKER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. B0/10/31. 2pp. 07288:018.
- 8012030933 Forwards response to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment." Components, where qualification data is incomplete or missing, will be tested or replaced & in full compliance by 820630. W/o encl. PASTERNAN.R.J. Power Authority of the State of New York. 80/11/01. 2pp. 07149:065.
- 8012070003 Responds to IE Bulletin 80-11. "Masonry Wall Design."
 Re-evaluation program will be completed by 810413,
 PASTERNAK,R J. Power Authority of the State of New York. 80/11/04.
 2pp. 07197.342.

- 8012120048 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. GRIER-8.H. Region I. Philadelphia. Office of the Director. 80/11/06. ip. 07230:286.
- 8012190362 Informs util of issuance of new MRC parsonnel identification badges, effective after 801130. Example encl. MARTIN.N. J. Region 1. Philadelphia, Safeguards Branch. 80/11/06. 2pp. 07286:129.
- 8012030774 Forwards IE Info Hotice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." Ho written response required. CRIER.B.H. Region 1. Philadelphia, Office of the Director. 80/11/07. 1p. 07150:220.
- 8012090433 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Gys at Davis Besse Unit 1." No response required.

 ORIER, B. H. Region 1. Philadelphia. Office of the Director.

 80/11/10. 1p. 07192.312.
- 8012040052 Forwards IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valco: Engineering Corp." Requires astimate of manpoder associated w/corrective actions. GRIER, B. H. Region 1. Phyladelphia, Office of the Director. 80/11/14. 1p. 07157:278.
- 8012220575 Advises that written response is required to IE Bulletin 80-23, "Failures of Balenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. CRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/19. 1p. 07293:128.
- 8012040514 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Lealage Inside Containment." (Iritten response required Requests info on manpower expended. GRICE, B.H. Region 1. Philadelphia, Office of the Director. 80/11/21. 2pp. 07149:214.
- 8012050580 Forwards Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER, B.H. Region 1. Philadelphia. Office of the Director. 80/11/24. 1p. 07174:073/
- 8012100224 Forwards "Inservice Insp Supmary & NIS-1 Data Rept for Spring/Sunner 1780 Outage." Includes results of welf & pipe support erams & inservice insp of reactor pressure vessel internals, core spray spanger & jet pump beams, BAYKE, J.P. Power Authority of the State of New York. 80/12/05. 1p. 07246:196.
- --8012103229 "Inservice Insp Susmary & NIS-1 Data Rept for Spring/Summer 1980 Outage." NVIZOD.6. - SAWICKY.W. Ebasco Sarvices, Inc. (subs. of Enserch Corp.). 80/10/10. 425pp. 07246:197.
- R. Periodic operating reports & related correspondence
- 8012160502 Forwards monthly operating rept for Nov 1980.

 PASTERMAN.R.J. Power Authority of the State of New York. 80/12/09.
 1p. 07261:153
- -8012160505 Honthly operating rept for Nov 1980. ZUFELT, E. Power Authority of the State of New York. 80/12/09. 8pp. 07261:154.
- S. Reportable occurrences, LERs & related correspondence
- 8012010409 Forwards LER 80-083/01T-0.

 PASTERNAKUR. J. Power Authority of the State of New York. 80/11/25.

 1p. 07095:087.
- --E012010427 LER 80-063/017-0: on B01118, average power range monitor sys operated w/iess than min allowed channels operable. Caused by inedvertent wiring error inside primary containment. Problem to be corrected during next containment entry.

 * Power Authority of the State of New York. 80/11/25. 3pp.
- 8012050431 Forwards LER 80-082/03L-0.
 PASTERMAX.R.J. Power Authority of the State of New York. 80/12/02.
 19. 07173:306.

- --8012050444 LER B0-082/03L-0: on B01102, solenoid pilot valve 16-1-90V-101 B, associated w/containment isolation valve 16-1-A0V-101B, failed causing AOV to fail. Caused by worn plunger & dirt in valve. Parts cleaned & replaced. CHILDS.N. V. Power Authority of the State of New York. B0/12/02. 1p. 07173:307.
- B012080455 Forwards LER 80-084/03L-0. PASTERNAM.R.J. Power Authority of the State of New York. B0/12/03. 1p. 07186: 321.
- --8012080459 LER 80-084/03L-0: on three occasions during 801103-25; reactor water level switch 02-3-LIS-1018 or 1010 found set less conservative than Tech Specs. Probably caused by personnel error.

 CHILDS.U. V. Power Authority of the State of New York. 80/12/03. 2pp. 07186-332.
- B012150127 Forwards LER 80-050/03X-1.
 PASTERNAX.R.J. Power Authority of the State of New York. 80/12/09.
 1p. 07237:291.
- --8012150130 LER 80-050/03x-1:cn 800507.four MSIVs failed leak rate requirements or needed repair. Caused by normal wear. Valves repaired & tested.
 CHILDS, N. V. Power Authority of the State of New York. 80/12/05.
 1p. 07237:292.
- 8012160530 Forwards LER 80-086/03L-0. PASTERNAR. J. Power Authority of the State of New York. 80/12/10. 1p. 07261:167.
- --8012160536 LER 80-086/03L-0: on 801110, fire detection sys for reactor core made inoperable to allow required electrical conduit rerouting. Caused by implementation of required fire protection mod. Fire watch established while sys repaired. CHILDS. U. V. Power Authority of the State of New York. 80/12/10. 1p. 07261: 168.
- 8012290432 Forwards LER 80-089/03L-0.
 PASTERNAX.R. J. Power Authority of the State of New York. 80/12/17.
 1p. 07337:006.
- --8012290437 LER 80-088/03L-0: on 801124, water level instrument 02-3-LIS-72D switches 3 & 4 were found set outside Tech Spec limits. Caused by instrument drift. Instrument calibr & surveillance frequency increased, CHILDS.(R.V. Power Authority of the State of New York, 80/12/17, 1p. 07337:007.
- 8012290439 Forwards LER 80-089/03L-0, PASTERNAK, R. J. Power Authority of the State of New York. 80/12/17. 1p. 07334:284.
- --8012290447 LER 80-089/03L-0: on 801126, reactor core isolation cooling steam line low pressure switch 13-PS-878 found set outside Tech Spec limits. Caused by instrument drift. Switch adjusted & surveillance frequency increased. CHILDS, M. V. Power Authority of the State of New York. 80/12/17. 1p. 07336: 285.
- B012290441 Forwards LER 80-090/03L-0. PASTERNAM, R. J. Power Authority of the State of New York. B0/12/17. 1p. 07336:286.
- --8012270451 LER 80-090/03L-0: on 801130, MSIV 29-A0V-80A 90% open limit switch did not reset when valve was fully opened Cause undetermined Fuses for follower relay pulled to keep channel tripped while being repaired. CHILDS. N.V. Power Authority of the State of New York. 80/12/17. ip. 07336:287.
- 8012290443 Forwards LER 80-041/04X-1.
 PASTERNAK.R.J. Power Authority of the State of New York. 80/12/17.
 1p. 07394:288
- --8012270453 LER 80-041/04X-1: on 800513, I-131 release 30% in excess of Tech Specs occurred. Cause not stated. Isolated normal ventilation & operated standby gas treatment to limit release.

 4 Power Authority of the State of New York. 80/12/17. ip. 07336: 287.
- 8012290468 Forwards LER 80-085/017-0. PASTERNAK, R. J. Power Authority of the State of New York. B0/12/17. 1p. 07335:050.

- --B012290474 LER B0-0B5/01T-0: on B01203.HPCI steam supply outside IV operator motor failed. Caused by mechanical failure of torque switch assembly. Notor rewound & assembly parts replaced. CHILDS. N. V. Power Authority of the State of New York. 80/12/17. 1p. 07335:051.
- B012300655 Forwards LER 80-038/03X-1.

 PASTERNAX.R.J. Power Authority of the State of New York. B0/12/17.
 1p. 07359:282.
- --B012300A62 LER B0-038/03X-1:on B0041B during normal operation & as result of surveillance testing primary containment isolation valve 10-M6V-57 was found incapable of fully closing in response to close signal Caused by worn & galled seats.

 # Power Authority of the State of New York. B0/12/17. 1p. 07359: 283.
- 8012300542 Forwards LER 80-070/03X-1.
 PASTERNAM.R.J. Power Authority of the State of New York. 80/12/18.
 1p. 07361:336.
- --8012300546 LER 80-078/03x-1: during B00810-15, at various times during plant shutdown, number of intermediate range confitor sys problems encountered. Problems detailed in encl. CHILDS, M.V. Power Authority of the State of New York. B0/12/18, 3pp. 07361:337.
- 8012300630 Forwards LER 80-091/04T-O.

 PASTERNAK.R.J. Power Authority of the State of New York. 80/12/23.
 1p. 07359:284.
- --80123D0638 LER 80-091/04T-0: on 801211, during normal operation, as result of environ radiological monitoring, radioactive 1-131 was detected in milk. Apparently caused by atmospheric weapons test conducted by China on 801016.

 4 Fouer Authority of the State of New York. 80/12/23. 4pp. 07359: 285.

V. Operator Examinations

- 8012100457 Responds to NRC 800731 ltr re amended MUREO-0737 re shift staffing & overtime restrictions. Administrative procedures will be revised to meet new restrictions. Add1 operating positions created. Revisions will be completed by 821103. BAYNE, J.P. Power Authority of the State of New York. 80/12/04. 3pp. 07218: 289.
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8012040118 Public version of "Independent Assessment of Evacuation Times for Beaver Valley Nuclear Pouer Plant," Vol 3, prepared for FEMA. COSBY.J.C., SHEPPARD.W.V., DAY,R.A. Wilbur Smith & Associates. BO/06/30. 56pp. 07158:264.
- 8012290006 Notifies of mods required refacility emergency notification sys & health physics network, as result of NRC review. NRC will install lamps near emergency & telephones & output jacks in compunication lines.

 ORIER, B. H. Region I, Philadelphia, Office of the Director.
 80/11/14. 2pp. 07330:231.
- 8012050197 Informs of interim 100FR50. 48 suspending completion dates for previously approved fire protection mods. Revised 100FR50. 48 will contain schedules for completion of all fire protection mods.
 E18ERHUT. D. O. Division of Licensing, 80/11/17. 5pp. 07175:030.
- 8012080456 Requests extension until 800131 to provide complete description of changes to security plans in response to NRC 801001 request re vital area analysis. DUNN.C.N. Duquesne Light Co. 80/12/02. 1p. 07194:174.
- B012040049 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary. FELTON.J.H. Division of Rules and Records. B0/12/03. 1p. 08915:001.
- --8012040088 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FERA. 4 Wilbur Emith & Associates. 80/06/30. 17pp. 06915:001.

- --8012040155 Public version of program rept, "Evacuation Time Assessment of Rine Nuclear Power Plants Emergency Planning Zones," Vol. 1, prepared for FEMA. COCBY.J.C., SHEPPARD.W.V. Wilbur Smith & Associates. 80/06/30. 43p. 07160:313.
- 8012290312 Forwards review of facility 800310 amergency plan. Addl info & commitments required before onsite emergency preparedness program meets criteria. Plan revisions requested. VAROA, S. A. Operating Roactors Branch 1. 80/12/04, 11pp. 07346, 101.
- 8012170463 Discusses NRC 801007 site visit to observe progress of emergency operations facilities const & details of site layout re conduct of emergency operations. Emergency operations facility drawing earl.

 DUCN, C. R. Duquesne Light Co. 80/12/12. 3pp. 07269: 236.
- P. Operating license stage documents & correspondence
- 8012029/53 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake.

 EISEKNUT, D. Q. Division of Licensing. 80/10/21. 4pp.
- 80:2090486 Responds to 80:031 telcon. Enumerates actions taken by util & requests response if such actions differ from actions actually planned by util. GRIER. B.H. Region 1. Philadelphia, Office of the Director. 80/10/31. 2pp. 07207:027.
- B0121ACOSO Ltr to operating plant licensees.DL applicants & CP holders. Forwards NUREC-0737 re TM1 action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 inplementation dates will be net. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012220543 Ltr to all power reactor licensees forwarding NUREG-0619.
 "BUR Feedwater Nozzle & Control Rod Drive Return Line
 Nozzle Cracting." Confirmation that implementation dates
 will be met must be sent within 45 days. N/o encl.
 EISENHUT, D. O. Division of Licensing. 80/11/13. 1p.
- 80:2120012 Forwards Amend 35 to License BPR-66, safety evaluation & notice of issuance & availability.
 VARGA.S.A. Operating Reactors Branch 1. 80/11/15. 2pp. 07237:145.
- --8012120020 Amend 35 to License DPR-64, modifying Tech Specs re operatio & surveillance of control rod indicator channels. VARCA,S.A. Operating Reactors Branch 1. 80/11/15. 10pp. 07237:167.
- --8012120025 Safety evaluation supporting Amend 35 to License DPR-66.

 d Office of Nuclear Reactor Regulation Director. 80/11/15. 5pp.
 07237:177.
- ---BO1212002B Notice of issuance & availability of Amend 35 to License BPR-66 VARSA.S.A. Operating Reactors Branch 1. 60/11/15. 2pp. 07237:182
- 8012120363 Summary of 801112 meeting u/util at site re safe operation of pressurizer relief & safety valves.
 ROSS.N.J. Operating Reactors Branch 1. 80/11/21. 5pp. 07236:319.
- 8012020355 Forwards results of testing performed on check valves installed in Event 5 configuration per NRC 800223 ltr & util 800317 response. Valves tested on 801111-14 & retested on 801118 following plant trip & safety [njection. DUNN.C.N Duquesne Light Co. 80/11/25. 5pp. 07148:146.
- 8012240135 Forwards Amend 36 to License DPR-66, safety evaluation & notice of issuance & availability.
 VARCA.S.A. Operating Reactors Branch 1. 80/11/26. 4pp. 07187:001.
- --8012249142 Amand 36 to License DPR-65 revising radiological Tech Specs on installation of hydraulic snubbers surveillance of auxiliary feedwater pumps & auxiliary feedwater flou indicators. VARSA,S.A. Operating Reactors Branch 1. 80/11/28. 21pp. 07187:001.
- --8012240145 Safety evaluation supporting Amend 36 to License DPR-66.

 ** Office of Nuclear Reactor Regulation, Director. 80/11/28. Spp. 07187:001.

- 8012240148 Notice of issuance & availability of Amend 36 to License DRR-66. VARGA.S.A. Operating Reactors Branch i. 80/11/28. 2pp. 07167:001.
- 12220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON. H. R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp. 07299:205.
- 8012220505 Forwards tabulation & summary of IE survey on low level waste at 31 reactors Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity, BANGART.R.L. Effluent Treatment Systems Branch. 80/11/05. 8pp. 07279:207.
- 12230799 Responds to 801031 ltr re confirmation of commitment to meet implementation dates contained in KUREG-0737. Requests extension for proposed mads re auto trip of reactor contant purps.

 DUNN.C.W. Duquesne Light Co. 80/12/17. 4pp. 07311:099.
- 12300409 Sutmits list of Westinghouse documents to be marked as proprietary & removed from PDM. Documents also identified in Nestinghouse 801003 itr.

 DUNN.C. N. Duquesna Light Co. 60/12/19. 2pp. 07349: 358.

Inspection reports, IE Bulletins & carrespondence

- 0G210481 Requests delay to 800701 commitment for implementation of revised administrative procedures, required by Enforcement Conference 79-21.

 DUMN, C. R. Duquesne Light Co. 80/08/06. 2pp. 06384:117.
- 12100077 Ack receipt of 801013 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50-334/80-16.

 Region 1. Philadelphia. Reactor Operations Nuclear Jupport Branch. 80/10/20. 1p. 07219:108.
- 3012100083 Responds to NRC 803717 itr re violations noted in IE 1nsp Rept 50-334/80-16. Corrective actions: shift supervisors directed to notify operations of ref future safeguards events.

 DUNNIC. N. Duquesne Light Co. 80/10/13. Spp. 07219:109.
- 10121900B7 Ack receipt of 801609 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/80-16. BRURNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 80/11/07. 1p. 07219:114.
- IO12100090 Requests proprietary status be accorded to portions of IE Insp Rapt 50-334/80-16 per 10CFR2.790 due to security nature. KOOLEVER.E.J. Duquesne Light Co. 80/10/09. 3pp. 07219:115.
- OI2130094 Forwards IE Insp Rept 50-334/89-16 on 800601-30 & notice of violation. BRUNKER,E.J. Region i, Philadelphia, Reactor Sperations Nuclear Support Branch. 80/09/17. 2pp. 07219:118.
- 012100076 Notice of violation from insp on 800601-30.

 * Region 1, Philadelphia, Office of the Director. 80/09/12. 2pp. 07217:120.
- Q12100102 IE insp Rept 50-334/80-16 on 800601-30. Noncompliance noted: failure to notify NRC of immediately reportable event. Portions withheld (ref IOCFR2.770).
 BECMIAM, D. A., HEGNER, J. D., MÜZREARTY, R. A. Region 1, Philadelphia, Office of the Director: 80/09/12, 22pp. 07219:122.
- 2170405 Forwards IE Info Notice 80-38, "Cracking in Charging Pumpasing Cladding." No written response required. RIER, B. B. Region i. Philadelphia, Office of the Director. 0/10/30. jp. 07269:121.
- 2240048 Forwards IE Insp Rept 50-334/80-24 on 800825-29 No oncompliance noted, RUMIERE, J. Region I. Philadelphia. Reactor Operations Nuclear upport Branch. 80/10/30. 2pp. 07324:245.
- 012240049 IE Insp Rept 50-334/80-24 on 800825-29. No noncompliance noted Major areas inspected; design change approvals: GA & GC interface w/design changes & onsite safety committee meeting minutes.

 TROSKOSKI: H. Region 1. Philadelphia. Office of the Director. CAPHTON. D. L. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 80/10/28. App. 07324:247.

- B012090001 Responds to 1E Bulletin 80-11, "Masonry Wall Design."
 Util unable to meet bulietin schedule for completion of re-evaluation. Portion of work should be completed by 810131.

 BUNN.C.N. Duquesne Light Co. 80/10/31. ip. 07199:346.
- 8012100057 Immediate Action Ltr 80-43; discusses util 800814,0911 & 1020 ltrs re IE Bulletin 79-14. Enumerates actions taken or planned by util Requests response if actions differ from actions described.

 GRIER, B. H. Region 1. Philadelphia. Office of the Director. 30/11/03 3pp. 07217:016.
- 8012190485 Ack receipt of 800805 itr re IE Enforcement Conference 30-334/79-21 Proposed schedule extension of implementation of new station administrative procedures acceptable. GRIER.B.H. Region I. Philadelphia, Office of the Director, 80/11/04. 1p. 07287:093.
- 8012120084 Forwards IE Bullotin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230;287.
- 8012190379 Informs util of issuance of new NRC personnel identification badges: effective after 801130. Example, encl. MARTIN. M. J. Region I. Philadelphia, Safeguards Branch, 80/11/06, 2pp. 07286: 141.
- 8012030776 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurfiation." No written response required. GRIER.D.H. Region 1. Philadelphia, Office of the Director, 80/11/07. 1p. 07150: 276.
- 8012090010 Submits supplemental response to IE Bulletin 79-018 repressurizer level transmitter LT-RC-459 failure & replacement transmitter failure. Sys component work sheet encl.

 DUNN.C.N. Duquesne Light Co. 80/11/07. 3pp. 07199:331.
- BO12080539 Forwards IE Info Notice BO-41, "Failure of Bwing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER,B.H. Region 1, Philadelphia, Office of the Director. BO/11/10. 1p.
- 8012040104 Forwards IE Bulletin 80-23. "Failures of Bolenoid Valves
 Mfg by Valcor Engineering Corp." Requires estimate of
 manpower associated w/corrective actions.
 GRIER, B.H. Region 1. Philadelphia. Office of the Director.
 80/11/14. 1p. 07158:030.
- 8012220647 Advises that written response is required to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.
 GRIER, B. H. Region i. Philadelphia, Office of the Director. 80/11/19. 1p. 07295:049.
- 8012040531 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." Unitten response required Requests info on manpower expended. GRIER,8 H. Region 1. Philadelphia, Office of the Director. 80/11/21. 2pp. 07149:138.
- 8012050595 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Bnubber Fluid." No written response required. GRIER.8.H. Region 1. Philadelphia. Office of the Director. 80/11/24. 1p. 07174:041.
- 8012110937 Notification of 801202 meeting w/util in Bethesda.MD to discuss deficiencies in licensee responses to IE Bulletin 79.018. "Environ Qualification of Class IE Equipment." ROSS.M.J. Operating Reactors Branch 1. 80/11/26. 2pp. 07223:277.
- R. Periodic operating reports & related correspondence
- 8012030588 Submits NPDES rept for Oct 1980. MDDRE.O.U. Duquesne Light Co. 80/11/28. 13pp. 07151:171.
- 8012150273 Forwards "Semiannual Effluent Rept:Offsite Dose Estimates, First & Second Quarters 1980," DUNN.C.H. Duquesne Light Co. 80/12/10. ip. 07240:307.
- --8012130277 "Semiannual Effluent Rept:Offsite Dose Estimates, First & Second Guarters 1980."
 4 Duquesne Light Co. 80/12/10. 3pp. 07240:308.

- B012170567 Forwards monthly operating rept for Nov 1980. DUNN:C.N. Buquesne Light Co. B0/12/12 1p. 07264:144.
- --8012170572 Monthly operating rept for Nov 1980. TIMKO.D. R. Duquesne Light Co. 80/12/03. 8pp. 07264: 145.
- S. Reportable occurrences, LERs & related correspondence
- B012020527 Followup rept re RO on B00225, two frequencies on peak shock annunciator sys actuated visual alarms. Caused by transmitter reed switches within containment. Bys checked & calibr by vendor. Frocurement request submitted for more reliable sys.

 WERLING, J. A. Duquesne Light Co. B0/11/21. 2pp. 07130:305.
- B012070769 RD followup on B00403 rept: on B00225, two frequencies on peak shock annunciator sys actuated visual alarms w/o occurrence of seismic event. Problem traced to reed switches in containment transmitter. Sys checked & recalibr.
 WERLING, J. A. Duquesne Light Co. 80/11/21. 2pp. 07187:001.
- B012010300 RO B0-085/01P: on B01120 operator observed that N-41 & N-42 channels read 3%, power, while N-43 & N 44 read 0%. Caused by lack of high voltage to detectors of N-43 & N-44 channels. Circuit re-energized.
 WERLING, J. A. Duquesne Light Co. B0/11/24. 2pp. 06915:001.
- 8012010303 RO 80-086/01P: on 801121, overstress condition found on seal injection header from discharge of high head safety injection pumps. Mod of pipe support completed prior to entering Mode 1 on 801122.

 WERLING, J. A. Duquesne Light Co. 80/11/24. 2pp. 06915:001.
- B012020526 RD 80-086/OIP: on B01121. Tech Specs 6.9, 1.8, 1 analysis of structures has less conservatism than originally calculated. Experters condition exists on seal injection header from discharge of high head safety injection pumps.
 WERLING, J. A. Duquesne Light Co. 80/11/24. 3pp. 07141:267.
- 8012030652 Forwards updated LER 80-073/01T-1. WERLING, J. A. Duquesne Light Co. 80/11/24. 2pp. 07149:222.
- --8012030459 Updated LER 80-073/01T-1:on 801003, vendor advised util of potential unreviewed safety question involving blowdown of all three steam generators due to single line break in steam supply to turbine driven auxiliary feedwater pumps. LACEY, N. S Duquesne Light Co. 80/11/24. 2pp. 07149:224.
- 8012040645 Part 21 rept re B&W installation of synthetic insulated switchboard cable inside containment w/o proper documentation possibly affecting pressurizer power operated relief valves. Originally reported on 770817. WILD.P. A. Stone & Webster, Inc. 80/11/24. 4pp. 07165:350.
- 8012100452 Forwards LER 80-080/03L-0. HERLING, J. A. Duquesne Light Co. 80/11/25. 2pp. 07218:035.
- --8012100463 LER 80-080/03L-0: on 801029, channel B refueling water storage tank level indicator found reading high. Channel declared inoperable Caused by indicator drifting out of calibr. Indicator repaired.

 LACEY, W. B. Duquesne Light Co. 80/11/25. 2pp. 07218: 037.
- 8012080436 Forwards LER 80-079/03L=0. WERLING, J. A. Duquesne Light Co. 80/11/26. 2pp. 07183: 127.
- --8012080439 LER 80-079/03L-0: on 801028, low level annuciator on safety injection sys alarmed. Caused by running pumps on recirculation while maintaining reactor coolant pump seal injection flow.
 LACEY, N. S. Duquesne Light Co. 80/11/26. 2pp. 07183: 129.
- 8012080469 LER 80-088/01P-0: on 801126. evaluation & reanalysis required by IE Bulletin 79-14 showed overstress condition exists on low head safety injection pumps SI-P-1A & SI-P-1B discharge lines at relief valve branch lines.
 WERLING. J. A. Duquesne Light Co. 80/11/26. 3pp. 07184:252.
- 8012050402 Forwards LER 80-083/03L-0. WERLING, J. A. Duquesne Light Co. 80/11/28. 2pp. 07173:274.
- --B012050407 LER 80-083/03L-0: on 801030, low pressure in 10 safety injection accumulator SI-TK-10 indicated. Caused by small nitrogen leak & nitrogen regulator on supply header grayenting repressuritation.

 LACFY.W S. Duquesne Light Co. 80/11/26. 2pp. 07173:278.
- 8012050413 Forwards LER 80-081/03L-0. WERLING, J. A. Duquesne Light Co. 80/11/28. 2pp. 07173:286.

- --8012050416 LER 80-081/031-0 on 801027, three MSIVs failed surveillance testing of valve closure time Probably caused by valve sitting idle for 11 months prior to test Packing adjusted. RERLING, J. A. Duquesne Light Co. 80/11/28, 2pp. 07173:288.
- 8012090389 Forwards LER 80-087/03L-0. WERLING, J. A. Duquesne Light Co. 80/12/01. 2pp. 07203:018.
- --B012090392 LER B0-087/03L-0 on B01113 sperator attempted to perform operation surveillance test on intermediate range nuclear instrument while reactor was critical Caused by operator error & possible inadequate situational analysis guidance. LACEV.W. S Duquesne Light Co. 89/11/25. App. 07203:020.
- 8012120522 Forwards LERs 80-085/01T-0 & 80-086/01T-0. WERLING, J. A. Buquesne Light Co. 89/12/05. 2pp. 07237:049.
- --BO12120530 LER 80-085/01T-0. on 801124 two nuclear power range instruments indicated zero power. Caused by actuation of high voltage protection circuit de-energizing detectors. Shift turnover checklist changed to increase checking frequency. LACEY.W. S. Duquesne Light Co. 80/12/05. 2pp. 07237:051.
- --B012170535 LER 80-086/01T-0:on 801121.pipe support on seal injection header from discharge of high head safety injection pumps determined to be in overstrassed condition. Cause unknown. Support mods made. LACEY.N. S. Duquesne Light Co. B3/12/05. 2pp. 07237:053.
- B012120539 Forwards LER 80-084/03L-0. WERLING, J. A. Duquesne Light Co. B0/12/05. 2pp. 07227:298.
- --B012120945 LER B0-084/03L-0: on B01107, boron injection tank low temp ennunciation received, Caused by ground in inservice heat trace circuit, Ground eliminated. LACEY, N. S. Duquesne Light Co. B0/12/05. 2pp. 07227: 300.
- BO12160481 Forwards LER 80-088/01T-0. NERLING, J. A. Duquesne Light Co. 80/12/10. 2pp. 07255:335.
- --8012160488 LER B0-088/01T-0 on B01126 IE Bulletin 79-14 review revealed low head safety imjection pumps discharge relief lines overstressed Cause unknown. Temporary mods to remove restrictions on pipe thermal expansion completed. LACEY, U. S. Duquesne Light Co. 80/12/10. 2pp. 07255:337.
- 8012170501 Forwards LER 80-089/03L-0. WERLING, J. A Duquesne Light Co. 80/12/12. tp. 07287:065.
- --B012170507 LER B0-0B9/03L-0 on B01024, pressurized level transmitter LT-RC-457 & spare failed. Cause uninown. Original plant equipment reinstalled. Addl review resulted in Mestinghouse submittal re IE Bulletin 79-018.

 LACEY, N. B. Duquesne Light Co. B0/12/12, 2pp. 07287:067.
- B012190587 Forwards LERS 80-090/03L-0,80-091/03L-0,80-092/03L-0, B0-093/03L-0 & 80-103/03L-0 WERLINO, J. A. Duquesne Light Co. 80/12/12, 2pp. 07286:140.
- --B012190590 LER B0-090/OSL-0: on B01112, two of three chlorine detectors failed surveillance tests Caused by dirt on wicks & glass orifices preventing flow of electrolyte, Detectors cleaned & returned to svc.

 LACEY, N. S. Duquesne Light Co. B0/12/12. 2pp. 07286: 162.
- --8012170572 LER 80-071/03L-0: on 801113, sampling of boron injection tank indicated low boron concentration After adding 100 lbs of boron, high concentration indicated. Low concentration thought to be caused by inleakage through isolation valves.

 LACEY, U.S. Duquesne Light Co. 80/12/12 2pp. 07286: 144.
- --B012170576 LER 80-092/03L-0: on B01114 radiation monitor:RM-LW-104, alarmed high, cleared, then realarmed. Caused by failure of printed circuit board, making high alarm input to control room annunclator inoperable. Printed circuit board replaced. LACEY, W. S. Duquesne Light Co. B0/12/12. 2pp. 07286:166.
- --8012170600 LER 80-093/03L-0: on 801116, during surveillance test on fire protection systemer in west cable vault found defective. Fire watch posted & defective timer replaced. LACEY.W.S. Duquesnc Light Co. 82/12/12. 2pp. 07286: 168.
- --8012190602 LER 80-103/03L-0; on 801203, beron injection tank determined to be out of spec high. Plant shutdown initiated & tank diluted. Caused by temp controllers for tank set too high. Temp controllers set to lower temp.

 LACEY, N. S. Duquesne Light Co. 80/12/12. 2pp. 07286: 170.

- 8012230528 Forwards LERs 80-095/03L-0 % 80-096/03L-0. WERLING, J. A. Duquesne Light Co. 80/12/15. 2pp. 07316: 296.
- ~-8012230553 LER 80-095/03L-0 on 801121, during safety injection accomplator 1A level channel 1 test. but level alarm setpoint at comparator LC-91-9≥03 found one gallon below Tech Spection. Caused by setpoint drift. Comparators recallibr. LACEY.N.S. Duquesne Light Co. 80/12/15. 2pp. 07316:278.
- --8012230533 LER 80-096/03L-0: on 801121: control problem w/bypass & main feed regulating valves caused transient in RCS that could not be controlled within limits Caused by improperly tuned control mod for feed bypass valves.

 LACEY, N S Duquesne Light Co. 80/12/15 2pp. 07316:300.
- 8012230441 Forwards LER 80-116/03L-0. WERLING, J. A. Duquesne Light Co. 80/12/16, 2pp. 07318:27B.
- --8012239445 LER 80-110/03L-0: on 801201, charcoal test cell in 18 main filter bank found passing flow over Tech Spec limit. Caused by workeen error in not replacing cell in June 1980, Cell replaced.

 LACEY, N. S. Duquesne Light Co. 60/12/16. 2pp. 07318:280.
- 8012300659 Forwards LERs 80~097/03L-0, 80-098/03L-0, 80~099/03L-0, 80-109/03L-0 & 80-101/03L-0.

 MERLING.J.A Duquesne Light Co. 80/12/18 2pp 07362: 354.
- --8012303667 LER 80-097/031-C rm 801121; containment airlock doors failed seal leakage surveillance test Caused by wood sliver adhering to door sealing face & Inner door D-rings improperly making Seals greased Wood sliver removed.

 LACEY, R. S. Duquesns Light Co. 80/12/18 2pp. 07362:056.
- --8012300A70 LER 80-098/03L-0: on 801122; main steam flow indicator FI-MS-484 was pegged low. Caused by transmitter bypass valve FT-MS-484 not being fully closed. Valve closed. LACEY, W. S. Duquesne Light Co. 807/12/18. 2pp. 07262: 358.
- --- 8012300676 LER 80-099/03L-0 on 801125.RCS loop 2 channel I flow indicator FI-RC-024 showed reading above surveillance requirement. Caused by isolation amplifier drift. Isolation amplifier repaired LACEY.U.S. Duquesne Light Co 80/12/18. 2ap. 07362:360.
- --B012300681 LER 80-100/03L-0: on B01125.RCS leakage exceeded Tech Spec limit.Caused by faulty soal Dater injection filters & drain valves.Valves replaced LACEY.M.S. Duquesne Light Co. 80/12/18 2pp. 07362:362.
- --B0123004PA LER B0-101/03_-0 on B01126, control room chlorine detector CLA-VS-101A failed to meet operating surveillance requirement for drip rate. Caused by clogged fetector wick & tank vent failure. Vent filter replaced & wick cleaned. LACEY, H.S. Duquesne Light Co. B0/12/18 2pp. 07363:002.
- DOCKET 50-335 St. LUCIE PLANT, UNIT 1
 F. Security, medical, emergency & fire protection plans
- 8012:10034 Advises of interim 10CFRSO. 48 suspending completion dates for fire protection mods previously approved by NRC. Rule became affective upon publication in 801029 FR (45FR71569). Revised 10CFRSO. 48 & App R will supersede interim rule. EISENHUT, B. G. Division of Licensing. 80/11/14. 5pp. 07226:060.
- 801202037: Informs that fire protection mods in svc & operational per 801003 ltr.Licensee considers Item 3.13.3 operational & oil collection tanks still to be added. Sys provides for oil to be callected & piped from ignition sources.

 UHRIG.R.E. Florida Power & Light Co. 80/11/26. [p. 07142:101.
- J. Insurance & indemnity information
- 8012020478 Forwards Endorsement 36 to NELIA Policy NF-227. FIELDER, J. Marsh & McLennan Inc., M & M Nuclear Consultants, Inc. Div. 80/11/25. 2pp. 07130:278
- P. Operating license stage documents & correspondence.
- 8012020753 Forwards seismic qualifications of auxiliary feedwater systim operating PURS & describes program MRC is undertaking to review capability of operating PURS to remove decay heat following earthquake.

 EISELECT.D.G. Division of Licensing 80/10/21, 4pp.

- BO1216G050 Ltr to operating plant licensees, UL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met.

 EISELBUT, D. G. Division of Licensing. BO/10/31. 7pp.
- BO12220563 Ltr to all power reactor licensees forwarding NUREG-O617.
 "BMR Feedwater Norzle & Control Rod Drive Return Line
 Norzle Cracking." Confirmation that implementation dates
 will be net must be sent within 45 days. N/o encl.
 EISENHUT, D. G. Division of Licensing. BO/11/13. 1p.
- B012010106 Responds to NRC B01017 request for add1 info re 800611 natural circulation cooldown event. Util is developing cooldown method capable of achieving cold shutdown w/o upper head voiding. Results will be submitted by 801230. UHRIO, R. E. Florida Power & Light Co. 80/11/20. 1p. 07097:065.
- 8012220495 Responds to BG0911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. BD/12/04. 2pp.
- --B012220595 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/7% planning or considering increasing storage capacity.

 BANDART.R.L. Effluent Treatment Systems Branch. B0/11/06. Bpp.
- 80.12150233 Provides results of containment valve torque & stress analysis completed by Henry Fratt. Co. valve manufacturer. Containment purge valves operable under DBA-LOCA conditions. Forwards completion of containment purging justification. UHRIG.R.E. Florida Power & Light Co. 80/12/09. 3pp. 07240:123.
- 8012240179 Submits suppl to util 801118 response to NRC 801010 ltr re loss of power clarifying Reg Guide 1.108 testing criteria & incorporation into facility procedures. URR10.R.E. Florida Power & Light Co. 80/12/16. 3pp. 07323:052.
- 8012300216 Forwards description of cases where plans & schedules do not coincide u/post-TMI requirements of NUREG-0737.

 UHRIG, R. E. Florida Power & Light Co. 80/12/23. App. 07357:057.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012180023 Forwards IE Info Notice 80-3B, "Cracking in Charging Pump Casing Cladding." No written response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30. ip. 03790:106.
- 8012170422 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. D'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/10/31.
- 8012230063 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012110736 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc." Written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.

 1p. 07225: 211.
- 8012030068 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No unitten response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. B0/11/07. 1p. 07150:117.
- 8012080194 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Becay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/10.
 1p. 07162:261.
- 8012040183 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 80/11/14.

- B012120579 Ack receipt of 801004 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/80-29. KENNA, M. B. Region 2, Atlanta, Safeguards Branch. 80/11/14. ip. 07237:146.
- --8012120580 Forwards IE Insp Rept 50-335/80-29 on 800819-22 & notice of violation.Notice of violation withhold (ref 10CFR2.790).

 KENNA, H.B. Region 2. Atlanta, Safeguards Branch. 80/09/12. 2pp. 07237:147.
- --B012120384 IE Insp Rept 50-335/80-27 on B00819-22. Noncompliance noted, inadequate procedures for searching packages & failure to control access points at vital areas. Details withheld (ref 10CFR2. 790).
 PERNY, C. D., MCGUIRE, D. R. Region 2, Atlanta, Office of the Director. 86/09/10. 2pp. 07237: 149.
- 8012040477 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Unitten response required. Requests info on manpower expended. G'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/21. 1p. 07163:339.
- 8012080024 Forwards Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. D'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/24. ip. 07182:165.
- 8012170512 Forwards IE info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J.P. Rogion 2, Atlanta, Office of the Director, 80/11/26. to. 07248:103.
- 8012310410 Responds to 1E Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No Valcor Engineering Corp valves or parts are in use at facility. UHR10,R.E. Florida Power & Light Co. 80/12/09. 1p. 07369:225.
- R. Periodic operating reports & related correspondence
- 8012160466 Forwards monthly operating repts for Nov 1980. SCIM10T.A.D. Florida Power & Light Co. 80/12/06. 1p. 07254: 216.
- --8012160468 Monthly operating repts for Nov 1980. CHILBORLV.T. Florida Power & Light Co. 80/12/06. 17pp. 07254:217.
- 8012180258 Forwards monthly operating repts for Nov 1780. SCHMIDT, A. D. Florida Power & Light Co. 80/12/06. 1p. 03794: 006.
- --8012180265 Monthly operating repts for Nov 1980. CHILSON.V.T. Florida Power & Light Co. B0/12/06. 16pp. 03794:007.
- S. Reportable occurrences, LERs & related correspondence
- B012100592 Forwards LER 80-037/03L-0. SCHMIDT, A. D. Florida Pouer & Light Co. B0/09/11. ip. 07187:001.
- --8012190528 LER 80-037/93L-0: on 800812.during normal full power operation containment radiation channed MD failed low. Caused by failure of two capacitors in -6.8 volt power supply Capacitors replaced.

 PACE,P.L. Florida Power & Light Co. 80/09/11. 1p. 07187:001.
- 8012100532 Forwards LER 80-038/03L-0. SCHMIDT, A. D. Florida Power & Light Co. 80/09/12. 1p. 07219: 355.
- --B012100538 LER 80-03B/03L-0: on 800813. during normal operation; CEDM 7 failed, dropping dual control element assembly to full insertion. Caused by failed timing module. Module was replaced. CEDM 7 was operationally tested & returned to svc. PACE, P.L. Florida Power & Light Co. 80/09/12. 1p. 07219:356.
- 80:2100476 Forwards LER 80:039/03L-0. 8CH410T, A. D. Florida Power & Light Co. 80/09/15, 1p. 07219:020.
- ---8012100479 LER 80-039/03L-0: on 800814, dose equivalent iodine exceeded Tech Spec 3. 4. 8s limit. Caused by dropped control element assembly. I-131 level decreased to nominal levels after 76-h.
 PACE.P. L. Florida Power & Light Co. 80/09/15. 4pp. 07219: 021.
- 8012100404 Forwards LER 80-043/03L-0. SCHMIDT.A.D. Florida Power & Light Co. 80/09/18. 1p. 07219:044.

- --Bol2109407 LER BO-043/63L-O on B00821 during narnal operation.CEDM 39 failed, dropping CEA to full insertion Cause of failure undetermined Power supply unit replaced CEDM 39 returned to nornal operations.

 PACE.P.L. Florida Power & Light Co. B0/09/18. 1p. 07219:045.
- 8012020551 Forwards LER 80-057/03L-0. SCHMIDT.6 D. Florida Power & Light Co. 89/11/05. Ip. 07143:289.
- --8012020557 LER 80-057/032-0: on 801008, 3-inch rip noted in fire hose & equivalent capacity hose not routed to unprotected area within 1-h. Caused by procedural deficiency. Procedure modified.

 PACE, P. L. Florida Power & Light Co. 80/11/05. 1p. 07143:270.
- B012020541 Forwards LER 80-059/G3L-0. SCHMIDT.A.D. Florida Power & Light Co. 89/H1/18. 1p. 07145:252.
- --8012020567 LER 80-038/03L-0. on 801019, target A-16 alarned (diesel generator IB failure to start) Caused by open feeder breaker to PF-112. Feeder breaker closed.
 PACE, P. L. Florida Power & Light Co. 80/11/18. 2pp. 07145: 253.
- 8012020534 Forwards updated LER 80-046/03L-1.
 SCIMIDT.A.D. Florida Power & Light Co. 80/11/19. ip. 07143:273.
- --8012020542 Updated LER 80-046/03L-0:on 800827. while at 100% power, control element assembly 33 dropped to fully inserted position. Caused by failed 15-volt doc pacer supply in coil power programmer. Power supply replaced.
 PACE.P.L. Florida Power & Light Co. 80/11/19. 1p. 07143:274.
- 8012020501 Forwards LER 80-059/03L-0. SCHM1DT.A.D. Florida Poyer & Light Co. 80/11/24. 1p. 06586:003.
- --8012020507 LER 80-059/03t-0 on 801024 primary ROPS computer failed, causing loss of control element assembly position indication. Caused by program software error. Position infomanually reloaded into backup computer.
 PACE,P.L. Florida Power & Light Co. 80/11/24. 1p. 06586:003.
- 8012020548 Forwards revised LER 79-014/07L-1. SCHMIDT, A.D. Florida Power & Light Co. 80/11/24. 1p. 07143:287.
- ---8012020555 Revised LER 79-014/09L-1: on 790409, dissel generator vendor notified util of potential feilure of crantshaft coupling for coaling fans on diesel generators. Cause unstated. Couplings replaced w/couplings of improved design. PACF,P.L. Florida Power & Light Co. 89/11/24. 1p. 07143:288.
- 8012050452 Forwards LER 60-061/03L-0. SCHMIDT, A. D. Florida Power & Light Co. 80/11/26. 1p. 07173:313.
- --8012050470 LER 80-061/93L-0 an 801027.dc electric buses were switched into configuration such that one dc bus provided control power for both component cooling water loops. Caused by electrical maint activity.

 PACE.P.L. Florida Power & Light Co. 80/11/26. 2pp. 07173: 314.
- DOCKET 50-336 MILLSTONE RUCLEAP POWER STATION. UNIT 2
 F. Security, medical. emergency & fire protection plans
- BO12040186 Public version of "Independent Assessment of Evacuation Times for Millstone Nuclear Power Plant," Vol B. prepared for FEH4. COSBY, J. C., SHEPPARD, N. V., LAMAGNA, F. Wilbur Smith & Associates, BO/06/30. 72pp. 07161:289.
- 8012990716 Informs that mods will be rade to emergency notification sys & health physics network equipment.NRG will have lamps installed on emergency telephones in all control rooms, technical support ctrs & emergency operations facilities. GRIER.B.H. Region 1. Philadelphia, Office of the Director. BO/11/14. 2pp. 07196:142.
- B012110012 Advises of interim ICCFRSO.4B suspending completion dates for fire protection mods previously approved by NRC.Rule became affective upon publication in B01029 FR (45FR71549). Revised 10CFRSO.48 & App R will supersede interim rule. EISENHUT.D.G. Division of Licensing. 80/11/14. Spp. 07226:055.
- BD12040639 Transmits emergency planning into for placement in LPDR. W/o encl.
 SQUDER.J.L. Division of Rules and Records. 80/11/19. 1p. 07170:056.

- 8012290415 Forwards revised 100FR50.48 & App R to 100FR50 re five protection features of nuclear power plants.Rulas take effect 810217.Summany listing of open items re fire protection features of facility encl. EISE/HUT.D.O. Division of Licensing. 80/11/24. 22pp. 07345:308.
- B012040065 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary FELTON.J.T. Division of Rules and Records. B0/12/03. 1p.
- --8012040088 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEMA. # Wilbur Smith & Associates. 80/06/30. 17pp.
- --8012040155 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol 1. prepared for FEMA.
 CDSV.J.C. Wilbur Smith & Associates. 80/06/30. 43pp.
- Q. Adjudicatory correspondence
- 8012090172 Requests hearing to determine necessity of environ qualification of all safety-related electrical equipment at facilities, as required by NRC 801024 orders for mod of licenses.

 CGUNSIL-N.G. Connecticut Yantee Atomic Power Co. 80/12/04. 3pp. 67200-123
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PMRs & describes program NRC is undertaking to review capability of operating PMRs to remove decay heat following earthquale.

 EISEMMUT.D.G. Division of Licensing. 80/10/21. 4pp.
- 8012140050 Ltr to operating plant licensess.DL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licenses confirmation in 45 days that Encl I inplementation dates will be net. EISENMUT.D.G. Division of Licensing. 80/10/31. 7pp.
- B012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. (1/o encl. EISENHUT. D. G. Division of Licensing. B0/11/13. 1p.
- B012020336 Informs that current fuel supplier more suited to handle small break LOCA model upgrade Expects simulation changes by B20101 & completion by B30101. COURSELLI G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B0/11/14. 2pp. 07148:172.
- 8012120521 Forwards Amend 62 to License DPR-65 & notice of issuance & availability.

 NOVAN-T.H. LAINAS.C.C. Assistant Director for Operating Reactors. 1 80/11/19. 4pp. 07237:055.
- --8012120528 Amend 62 to License DPR-65, clarifying meaning & actions to be talen re use of term operable in definitions, limiting conditions for operation & related bases. A Assistant Director for Operating Reactors. 80/11/19. 10pp. 07237:059.
- --8012120533 Notice of issuance & availability of Amend 62 to License DPR-65. CLASK.R.A. Operating Reactors Branch 3. 80/11/19. 2pp. 07237:069.
- 8012020253 Advises of error in ECN 111 code used for feedline break analysis submitted 80061c in response to NRC 791022 request for add1 info re auxiliary feedwater sys flow requirements. Forwards reanalysis using SGN 111 code. CGUNSIL.N. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/11/20. 6pp. 07148:177.
- 8012090172 Requests hearing to determine necessity of environ qualification of all safety-related electrical equipment at facilities as required by NRC 801024 orders for mod of licenses.

 COUNSILIE. Connecticut Yantee Atomic Power Co. 80/12/04, 3pp. 07200.131.

- B0122204B5 Responds to B00911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENION.H.R. Office of Nuclear Reactor Regulation, Director, B0/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BARGART.R.L. Effluent Treatment Systems Branch. 80/11/06. Bpp.
- 8012230262 Forwards response to NUREC-0737 re implementation status of TMI-related requirements.
 CDUNBIL-8. Connecticut Yankee Atomic Power Co. CDUNBIL, N. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
 80/12/15. 41pp. 07314:023.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012190592 Forwards IE Insp Rept 50-335/80-18 on 800923-26.No noncompliance noted. CARLSDN.R.T. Region I. Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/14. 2pp. 07287:300.
- --Bol2190655 IE Insp Rept 50-336/80-18 on 800923-26. No noncompliance noted Hajor areas inspected auxiliary bldg ventilation system that handling fan & reactor bldg component cooling water reactor coolant pumps.

 PAOLINOR. J. Region 1. Philadelphia, Office of the Director. EBMETER, S.D. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/09. 3pp. 07287:302.
- 8012190673 Forwards IE Insp Rept 50-336/80-12 on 800826-28.No noncompliance noted. SMITH.0.H. Region i. Philadelphia. Fuel Facility & Materials Safety Branch. 80/10/17. 2pp. 07287:314.
- --8012170680 IE Insp Rept 50-336/80-12 on 800826-28. No noncompliance noted Major areas inspected: Unit 2 refueling outage including radiation protection program, procedures, planning & preparation.

 LOVENDALE, P. C. Region 3, Chicago, Office of the Director, KNNPP, J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/14. 7pp. 07287:316
- 8012230044 Forwards IE Insp Rept 50-336/80-21 on 800930-1003.No noncompliance noted. CARLEGRUR. T. Region 1, Philadelphia. Reactor Construction & Engineering Support Branch. 80/10/17. 2pp. 07311:237.
- --8012230047 IE Insp Rept 50-336/80-21 on 800930-1003. No noncompliance noted Major areas inspected inservice insp activities. HACTON.O.A., TRIPP.L.E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/15. 5pp. 07311:239.
- BO12040151 Submits add1 response to IE Bulletin 80-06. "Engineered Safety Features Reset Control." Circuit mads to reset logic associated w/Items 6.48, 132, 136, 180 & util 800613 ltr not required. Mods far other items will be completed by 810101. COUNSIL. W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/10/20. 2pp. 07170:233
- 8012020320 Requests that response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power." be resubmitted w/oath or affirmation within 10 days of receipt of Itr.per 10CFR50.54.

 QRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/23. ip. 07143: 114.
- 8012223071 Forwards IE Insp Repts 50-245/80-17 & 50-336/80-19 on 800907-1004. No noncompliance noted.
 BRUNNER/E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/29. 2pp. 07306:337.
- --8012220077 IE Insp Repts 50-245/80-17 % 50-336/80-19 on 800707-1004.
 No noncompliance noted Major areas inspected:control room & accessible portions of Unit I reactor turbine radwaste & gas turbine generator.
 EMEDLOSKY, J. T. ; ZIMMERMAN, R.P. Region I: Philadelphia, Office of the Director. KEIMIG.R.R. Region I: Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/27. 12pp. 07306:339.
- 8012170402 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director, 80/10/30. 1p. 07267:111.

- R012080230 Responds to IE Bulletin BO-11, "Masonry Wall Design." Re-evaluation of concrete masonry ualls & any resulting mods will be completed by 810501. COUNSII, H. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/11/04. 200pp. 07194:237.
- BO12120113 Forwards IE Bulletin BO-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. BO/11/06. 1p. 07230:221.
- 8012190377 Informs util of issuance of new NRC personnel identification badges, effective after 801130. Example encl.
 MARTIN. M. J. Region 1, Philadelphia, Safeguards Branch. 80/11/06.
 2pp. 07286:137
- B012030787 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Fressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. CRIER, B.H. Region i. Philadelphia, Office of the Director. B0/11/07. 1p. 07150:207.
- 8012080474 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
 ORIER, B.H. Region i. Philadelphia, Office of the Director.
 80/11/10. ip. 07182:330.
- 8012040092 Forwards IE Builetin BO-23, "Failures of Bolenoid Valves Nfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, B. H. Region i, Philadelphia, Office of the Director. BO/11/14. 1p. 07157:353.
- 8012270616 Advises that written response is required to IE Bulletin 80-23, "failures of Solenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER, B. H. Region I, Philadelphia, Office of the Director. 80/11/19. ip. 07308:35w.
- 8012040495 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Unitten response required. Requests into on manpower expended. ORIER. B.H. Region i. Philadelphia, Office of the Director. 80/11/21. 2pp. 07169:166.
- 8012050573 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. CRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/24, ip. 07174:062.
- 8012170224 Notification of 801212 meeting w/util in Bethesda.MD to discuss 1980 steam generator insp results. CONMER.E.L. Operating Reactors Branch 3. 80/12/09. 3pp. 07268:200.
- R. Periodic operating reports & related correspondence
- 8012230346 Forwards monthly operating rept for Nov 1980. MRDCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/12. 1p. 07318:239.
- --8012230347 Monthly operating rept for Nov 1980. HONLETT.O.H. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/08. App. 07318:240.
- 8. Reportable occurrences, LERs & related correspondence
- 8012020529 Forwards LER 80-037/03L-0. MRGCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/11/24. 1p. 07149:079.
- 8012100164 PNS-1-80-25; on 901126. Unit 2 supervisory control room operator (licensed senior reactor operator) fatally shot individual three times w/shotgun. Operator in custody. Edentification badge & site access lifted. MCKEDWAL., DEVLIN.J., MARTIN.M. Ragion 1, Philadelphia, Office of the Director. 80/12/01. 2pp. 07218:303.

- 8012230384 Forwards LER 80-038/03L~0. MRDCZKA4 E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/15. 1p. 07318:257
- --8012230389 LER 80-038/031-0:on 801116.leak found in C svc water strainer.Caused by corrosion.Strainer bodies scheduled for replacement. 4 Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/15, 1p. 07318:258.
- 8012230489 ETS-NR/50-245/80-03 % 50-336/80-03: on 801105. Ag-110m activity exceeded control station average by factor greater than ten. Caused by oyster trays being maintained uithin quarry bondaries & plant liquid vol increase. MRDCZKA, E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/15. 5pp. 07318: 322
- B012300635 ETS-NR/50-245/30-336/B0-03: on B01105, levels of Ag-110m activity observed in fourth quarter sample of bysters exceeded control station average by factor of ten. Caused by increase in plant liquid discharges. New Tech Bpecs proposed. MROCZKA, E. J. Northeast Utilities. B0/12/15. 3pp. 07346: 182.
- B012230465 Forwards LER 80-039/03L-0. MRGCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B0/12/17. 1p. 07318:270.
- --8012230471 LER 80-039/03L-0: on 801117/hydrogen analyzer 8 declared inoperable Caused by failure of operational analyzer amplifier (Struthers-Dunn, Inc. Model 12A). Maifunction isolated corrected & surveillance completed.

 Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 89/12/17. 1p. 07318-291.
- DOCKE: 50-338 NORTH ANNA POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8012010602 Notifies of completion of privacy review of emergency plan documentation. Encl info may be made publicly available. FELTON, J. M. Division of Rules and Records. 80/11/13. ip. 07091: 202.
- --B012010607 Forwards public version of response to NRC review of emergency plan. Section 4 re emergency action levels.

 SYLVIA.B.R. Virginia Electric & Power Co. B0/10/27. 12pp.
- --B0i2010614 Public version of emergency plan, revised Tables 4.1A through 4.1D changing initiating conditions for notification.

 4 Virginia Electric & Power Co. 80/10/29. 16pp. 07091:216.
- 8012070007 Informs of approval of revised final version of 10CFR50.58 & App R containing schedules for completion of all fire protection mods. No present implementation required.
 EISERHUT, D. G. Division of Licensing. 80/11/14. 5pp. 07197:218.
- 8012110652 Summary of 801107 meeting u/util in Bethesda-MD re emergency plans.
 NEIGHBORS.J.D. Operating Reactors Branch 1. 80/11/19. 2pp.
- 8012270419 Forwards revised 10CFR50.48 & App R to 10CFR50 re five protection features of huclear power plants. Rules take effect 810217. Summary listing of open items re fire protection features of facility encl. EISENMUT, D. G. Division of Licensing. 80/11/24. 20pp. 07345:267.
- 8012050421 Forwards amended pages to approved security plan. Encl withheld (ref 10CFR2. 790). SYLVIA. E.R. Virginia Electric & Power Co. 80/12/02. ip.
- 8012230286 Forwards draft NUREG-0696, "Implementation Plan" for establishment of emergency response facilities. Details on emergency operations facility establishment not included in plan, being finalized & will be submitted at later date. SYLVIA.2.R. Virginia Electric & Pouer Co. 80/12/18. 1p. 07311:270.
- --8012230273 Draft NUREG-0696, "Implementation Plan" for astablishment of emergency response facilities.

 * Virginia Electric % Power Cq. NUREG-0696. 80/12/18. 47pp. 07311:271.

- 80(2290274 Forwards alternate shutdown sys design description re fire pratection.per NRC 80(124 ltr.Util review of App R to 10CFR50 concludes that plants are in compliance w/exception of B-h emergency lights in egress routes. SYLVIA: E.P. Virginia Electric & Power Co. 80/12/20. 5pp.
- G. Adjudicatory correspondence
- 8012170819 Requests on behalf of utiliestension until 810108 for hearing on 801208 order for mod of licenses re environ qualification of safety-related electrical equipment to Tech Specs of facilities. Hunton & Killiams. 80/12/08. 2pp. 07269:227.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PKRs & describes program NRC is undertaking to review capability of operating PKRs to remove decay heat following earthquate.

 EISERHUT.D.G. Division of Licensing. 80/10/21. 4pp.
- 80120720050 Notification of 801107 meeting W/S&W & util in Bethesda.MD to discuss resolution of amplified response spectrum concerns. ENGLE.L. Operating Reactors Branch 3. BO/10/31. 2pp. 07147:195.
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 to TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012220953 Ltr to all power reactor licensees forwarding NUREG-0619. "BUR Feedwater Noisle & Control Rod Drive Return Line Nozzie Cracking." Confirmation that implementation dates will be met must be sent within 45 days. Myo encl. EISERMUT, D. Q. Division of Licensing. 80/11/13, 1p.
- 8012050036 Trip rept of 801113 visit to site to inspect LPDR discuss, update & provide continuity on active ongoing actions & tour plant.

 ENGLE, L. Operating Reactors Branch 3. 80/11/19. 4pp. 07173:087.
- B012230121 Forwards Amend 21 to License NFP-4, safety evaluation & notice of issuance & availability.
 CLARK, R. A. Operating Reactors Branch 3. 80/11/19. 2pp. 07316:338.
- ---B012230127 Amand 21 to License NPF-4, requiring certain Barton Lot 1 transmitters inside containment be modified or replaced as soon as practicable. CLARAGE. Operating Reactors Branch 3. B0/11/19. 2pp. 07316: 340.
- --8012230134 Safety evaluation supporting Amend 21 to License NPF-4.

 * Office of Nuclear Reactor Regulation, Director. E0/11/19. 2pp.
 O7316:342.
- ---8012230139 Notice of issuance & availability of Amend 21 to License [GF-4] CLARK, R. A. Operating Reactors Branch 3. 80/11/19. 2pp. 07316:344.
- 50121.70492 Confirms licensee commitments to HRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Esolution Valve Operability." Commitments are adequate & uill remain in effect pending long-term review.

 CLARK.R.A. Dperating Reactors Branch 3. 80/11/21. 2pp. 07270:330.
- 8012170494 Forwards safety evaluation re operational steam generator chemistry. Proposed long-term corrective actions are acceptable. Inservice insp results must be reported. CLARK: R. A. Operating Rejectors Branch 3. 80/11/21. 2pp. 07270:334.

memo requesting that Ofc of Nuclear censees of need to comply -'-' site conditions.Forwards

sctor Regulation, Director.

- --8012220906 Forwards tabulation & summary of IE survey on low level waste at 91 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06, 8pp.
- 8012150083 Advises that extension of Cycle 2 in coastdown mode for approx 13 effective full power days beyond licensed end of cycle burnup will not require changes to Tach Specs. SYLVIA.B.R. Virginia Electric & Power Co. 80/12/08. 1p. 07237:356.
- 8012310015 Forwards safety evaluation re installation of steam generator upper inspirarts during second refueling outage at facility. Licensee should commit to installation during third refueling outage.

 NOVAK.T.M. Assistant Director for Operating Reactors. 80/12/08, 2pp. 07371:074.
- --8012310019 Safety evaluation re installation of steam generator upper insp ports during second refueling outage. Licensee should commit to installation during third refueling outage. Assistant Director for Operating Reactors. 80/12/08. 3pp. 07371:096.
- 8012190354 Forwards response to NUREO-0737 post-TMI requirements, SYLVIA.E.R. Virginia Electric & Power Co. 80/12/15. 430pp. SYLVIA, B. R. 07282: 262.
- 8012230214 Requests ref to Item 7 in 800924 ltr.Dacuments completion of referenced work on both 34.5 kV buses during Nov 1980.
 SYLVIA.B.R. Virginia Electric & Power Co. 80/12/17. 1p. 07317: 056.
- B012290264 Supple B01015 request for CL amend. Requests Tach Spec change for nonradiological ETS to be revised to latest environ protection plan. FEROUSON.J.H. Virginia Electric & Power Co. B0/12/R3. 3pp.
- 8012270230 Confirms there is sufficient conservatism in calculations to permit continued operation of turbines until 810101 w/o . undue risk of failure. Major areas of conservatism provided." Unit util not be subjected to cyclic operation. SYLVIA. B.R. Virginia Electric & Power Co. 80/12/23. 2pp. 07342:323.
- B012290292 Requests anend to License NPF-4 supplementing 801015 amend request & providing documentation methodology for establishment of operational history data base on challenges to relief & safety valves. FERGUSON.J.H. Virginia Electric & Power Co. 80/12/23. 3pp. 07345:126.
- --8012290297 Proposed revisions to Tech Spec 5.9.1.5, providing documentation methodology for establishment of operational history data base on challenges to rollef & safety valves.

 * Virginia Electric & Power Co. 80/12/23. 2pp. 07345:129.
- 8012310633 Notification of 801227 meeting w/util in Bethesda.MD re potential turbine cracking. ENGLE.L.B. Operating Reactors Branch 3. 80/12/24, 2pp. 07371:057.
- B012300585 Forwards response to NRC 790925 request for info re Burry auxiliary feedwater sys design basis info & pump flow verification. Documents North Anna 1 pump test verification of 340 gpm delivered to steam generator.

 SYLVIA.B.R. Virginia Electric & Power Co. B0/12/26. 15pp.
- 8012310286 Forwards response to 790925 request for info re auxiliary feedwater sus design basis & pump flow verification. Discreparcy discovered during North Anna review addressed in LER 80-061/01T-0 prior to 801006 response. SYLVIA-B.R. Virginia Electric & Power Co. 80/12/26, 15pp. 07361:273.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012160336 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2," No written response required.

 0'REILLY.J.P. Region 2- Atlanta, Office of the Director. 80/10/24, 19. 07262: 180.
- B012170821 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30, 1p. 07266:266.

- 8012180020 Forwards IE Info Notice 80-39, "Malfunction of Solengid Valves Mfg by Valcor Engineering Corp." No written response is required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
 10.
- 8012230070 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31. ip.
- BD12110794 Forwards IE Bulletin BO-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Hritten response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/06. 1p. 07225:187.
- 8012030849 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization." No written response required. U'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/07. 1p. 07150:105.
- 8012080259 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
 D'REIU-Y-J.P. Region 2. Atlanta, Office of the Director. 80/11/10.
 1p. 07182:202.
- B0121B0219 Forwards IE Insp Repts 50-338/80-36 & 50-339/80-34 on 801021-24 No noncompliance noted. MURPHY,C.E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch. 80/11/10. 2pp. 03792:012.
- --B012180222 IE Insp Repts 50-339/80-36 & 50-339/80-34 on 801021-24. No noncompliance noted Major areas inspected: Installed equipment review w/respect to IE Bulletin 79-018.
 01080NS.T.D. Region 2. Atlanta. Office of the Director. COLON.T.E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/10. Spp. 03792:014.
- 8012040135 Forwards IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of mangower associated w/corrective actions.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/14, 1p. 07158:061.
- BO12080&52 Forwards response to NRC request for addl info re IE Bulletin 79-02. "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts." Dvarview of engineering analysis sys & finite element modeling technique included. BYLVIA: B.R. Virginia Electric & Power Co. BO/11/17. 3pp. 07188: 230.
- 8012050070 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 D'REILLY. J. P. Region 2, Atlanta, Office of the Director. 80/11/21.

 1p. 07173:230.
- 8012080018 Forwards IE Info Notice 80-42. "Effects of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/24. lp. 07182:161.
- 8012170839 Forwards original 801101 ltr.apparently lost in mail sys, responding to 1E Bulletin 79-01B re environ qualifications of Class IE equipment.
 HUNIER,R.H. Virginia Electric & Power Co. 80/11/24. 1p.
- BO12170387 Forwards IE Info Notice 80-29, Suppl 1, "Brolen Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26. lp. 07269:080.
- 8012180140 Ack receipt of 801024 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-339/80-30 & 50-339/80-29. LENIS.R.G. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/11/28.
- --8012180142 Responds to NRC 801002 ltr re deviations noted in IE Insp Repts 50-338/80-30 & 50-339/80-29. Corrective actions: add1 radios assigned to control room. SYLUTA: B.R. Virginia Electric & Power Co. 80/10/24. 2pp. 03791: 249.

- --B012180145 Forwards (E Insp Repts 50-338/80-30 & 50-339/80-29 on 800712-0820 & notice of deviation. LEMISR.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. B0/10/02. 2pp. 03791:251.
- --B012180146 Notice of deviation from insp on 800712-0820.

 * Region 2, Atlanta, Office of the Director. 80/09/30. 1p. 03791:253
- --8012180149 IE Insp Repts 50-332/80-33 & 50-339/80-29 on 800712-0820. Noncompliance noted: failure to maintain portable radios for fire brigade use. REBSIER.E.H., IATTERSALL.A.P. Region 2. Atlanta, Office of the Director. KELLOGG.P.J. Region 2. Atlanta, Reactor Operations Ruclear Support Branch. 80/09/30. 17pp. 03791:254.
- 8012080541 Forwards Revision 2 to response to IE Bulletin 79-018, "Environ Qualification of CLass IE Equipment" & NRC 800827 order for mod of license. SYLVIA.2.R. Virginia Electric & Payer Co. 80/12/01. 1590pp. 07184:314.
- 8012180188 Ack receipt of 800923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/80-19 & 50-339/80-20. LEMIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/12/01.
- --8012180192 Forwards revised response to remaining open item re violations noted in IE Insp Repts 50-338/80-19 & 50-339/80-20.Corrective actions:review made of const QA manual station QA manual & QC Procedure 26 1. SYLVIA.8.R. Virginia Electric & Power Co. 80/09/23. 2pp. 03791:297.
- --8012180195 Act receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-338/80-19 & 30-339/80-20. Supplemental response will be submitted by 800919.
 LEMIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/09. 1p. 03791:299.
- --8012180201 Forwards IE Insp Repts 50-338/80-19 & 50-339/80-20 on 800414-0330 & notices of violation & deviation. LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/07/21. 2pp. 03791:301.
- --B012180204 Notice of violation from insp on 800414-0530, * Region 2, Atlanta, Office of the Director. B0/07/21. 1p. 03791:303.
- --B012180205 Notice of deviation from insp on 800414-0530.

 * Region 2. Atlanta, Office of the Director. 80/07/21. lp.
 03791:304.
- --8012180209 IE Insp Repts 50-338/80-19 & 50-339/80-20 on 800414-0530. Noncompliance noted failure to conduct surveillance test at required frequency & to provide instructions for resestablishing ventilation flow after seismic event. KIDD, M.S., TATTERSALL, A.P., Region 2, Atlanta, Office of the Director. KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/07/21, 22pp. 03791:305.
- 8012110943 Forwards response to IE Bulletin 80-23, "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." Two Valcor valves exist for each North Anna unit & Surry does not have solenoid valves described in bulleting. SYLVIA.S.R. Virginia Electric & Pauer Co. 80/12/04. 3pp. 07225:245.
- 8012170023 Act receipt of 801107 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-338/80-33. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Sranch. 80/12/04. ip. 07268.161.
- --B012170031 Responds to NRC 801014 1tr re violations noted in IE Insp Rept 50-338/80-33. Corrective actions: welding procedures involving combination processes amended to include weld metal thickness range. SYLVIA.E.R. Virginia Electric & Power Co. 80/11/07. 2pp. 07268: 162.
- --8012170036 Forwards IE Insp Rept 50-338/80-33 on 800911-12 % notice of violation MURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch. 80/10/14. 2pp. 07268:164.
- --8012170041 Notice of violation from insp on 800911-12.

 * Region 2, Atlanta, Office of the Director. 80/10/09. ip. 07268:166.

- --8012170048 IE Insp Rept 50-338/80-33 Noncompliance noted:commitment to corrective action per 800315 notice of violation not accomplished.

 ECONOMOS.N. Region 2. Atlanta. Office of the Director. HERDT.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/99. 42p. 07269:167.
- 8012230091 Forwards response to IE Bulletin 80-23. "Failures of Solenoid Valves Kfg by Valcor Engineering Corp." Specified valves are not in use at facilities.
 SYLVIA.B.R. Virginia Electric & Power Co. B0/12/04. 3pp. 07311:084.
- 8012240503 Forwards response to IE Bulletin 80-23, "Failures of Solemoid Valves Hfg by Valcor Engineering Corp." Two Valcor valves in use do not have cited part number. SYLVIA.E.R. Virginia Electric & Power Co. 80/12/04. 3pp. 07324:320.
- 8012120467 Forwards response to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." No subj valve used or planned for use in safety-related sys at facilities. SYLVIA.B.R. Virginia Etectric & Power Co. 80/12/05. 3pp. 07230:328.
- 6012310033 Act receipt of 801008 ltr responding to NRC 800915 ltr re Maste Packaging Insp Rept 50-338/80-31. Notice of violation withdraws. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/12/18. 1p. 07369:057.
- --8012310038 Act receipt of Waste Packaging Insp Rept 50-338/80-31 on 800519. No preprietary info Disagrees w/NRC re notice of violation. Licensed mati was properly labeled. 8YLVIA.S.R. Virginia Electric & Power Co. 80/10/08. 3pp. 07359:058.
- --8012310042 Forwards Waste Packaging Insp Rept 50-338/80-31 on 800619 & notice of violation STOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/09/15. 2pp. 07369:061.
- --8012310044 Notice of violation from insp on 800619. * Region 2, Atlanta, Office of the Director. 80/09/19. 1p. 07369:063.
- --8012310047 Waste Packaging Insp Rept 50-338/80-31 on 800619. Noncompliance noted: radwaste shipment not properly labeled. MACARTHUR, T. C., POITER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/09/15. 3pp. 07369:064.
- R. Periodic operating raports & related correspondence
- 8012190508 Forwards monthly operating repts for Nov 1980. SYLVIA.E.R. Virginia Electric & Power Co. B0/12/15. ip. 07287:078.
- --8012190513 Monthly operating repts for Nov 1980. FELLOWS-M.E. Virginia Electric & Power Co. 89/12/09. 9pp. 07287:079.
- S. Reportable occurrences, LERs & related correspondence
- B012040569 Part 21 rept re S&W notification that out-of-phase transfer might occur when emergency buses are transferred from offsite power source to emergency diesel generators after reaching rated speed & voltage. Uriginally reported 800114. SYLVIA/B.R. Virginia Electric & Power Co. B0/11/19. 4pp. 07169:070.
- 8012010363 Forwards LER 80-076/01T-0. CARTWRIGHT, W R. Virginia Electric & Power Co. 80/11/21. 1p. 07072:178.
- ---8012010373 LER 80-096/01T-0: on 801114,8%W determined significant out-of phase transfer cauld occur when emergency buses transferred to emergency diesel generators. Cause not determined. Time delay circuit installed on generators. GARTHARIGHT,W.R. Virginia Electric & Power Co. 80/11/21. 3pp. 07052:179.
- 8012010378 Forwards LER 80-095/03L-0. CARTHRIGHT W.R. Virginia Electric & Power Co. 80/11/24. 1p. 07091: 292.

- --8012010390 LER 80-093/03L-0: on 801027, fire doors 871-7,-17 % -19 found nonfunctional due to inability to fully close & latch on free swing from full open. Caused by excessive use. Doors temporarily repaired % new design submitted. CARIMRIOHT.W R. Virginia Electric & Power Co. 80/11/24. 2pp. 07091: 293.
- 8012020623 Forwards LER 80-092/03L-0. CARTHRIGHT, M.R. Virginia Electric & Power Co. 80/11/24. 1p. 07147:005.
- --B012020631 LER BO-092/03L-0: on B01030, water found leaking from weld joint connecting drain valve 1-CH-497 to piping that tees into suction line of charging pump 1-CH-P-1A. Caused by bad weld. Held ground out & rewellded per approved procedures. CARTHRIGHT.W. R. Virginia Electric & Power Ca. B0/11/24. 2pp. 07148-005.
- 8012020682 Forwards LER 80-089/03L-0. CARTWRIGHT.W.R. Virginia Electric & Power Co. 80/11/25. 1p. 07147:275.
- --8012020712 LER 80-089/03L-0:on 801029, while investigating cause of high steam flow line setpoint drift, setpoint instrument calibr schadule error discovered. Caused by improper scheduling of surveillance testing. CARTMRIGHT, M. R. Virginia Electric & Power Co. 80/i1/29. 3pp. 07147:276.
- 8012150033 Part 21 rept re design of emergency bus residual voltage bus transfer. Caused by lack of definitive phase relationship between onsite & offsite sys. Timers were installed. MILD.P.A. Brane & Webster Engineering Corp. 80/12/02. 4pp. 07240:347.
- 8012090401 Forwards LER 80-097/03L-0. CARTHRIGHT, W. R. Virginia Electric & Power Co. B0/12/03, 1p. 07200:007
- ---B012090408 LER 80-097/03L-0: on 801114, while operating in Mode 1, LI-1474 indicated greater than 5% higher than average of three channels. Caused by high transmitter output, due to leaking isolation valve. Valves furmanited. Channel check performed. CARTMRIGHT. H. R. Virginia Electric & Power Co. 80/12/03. 2pp. 07200-008
- 8012070315 Forwards LER 80-078/03L-0. CARTWRIGHT.N.R. Virginia Electric & Power Co. 80/12/04. 1p. 07201:121.
- --8012090319 LER 80-098/03L-0: on 801123, while operating in Mode 1, neutron flux distribution exceeded axial flux difference target band. Caused by renon transient. Control rods inserted, causing flux distribution to shift downward.

 CARTMRIGHT. M. R. Virginia Electric & Fower Co. 80/12/04, 2pp. 07201:122.
- 8012070350 Forwards LER 80-077/03L-0. CARTURIGHT, W. R. Virginia Electric & Power Co. 80/12/04. ip. 07197:352.
- --8012090351 LER 80-099/03L-0: on 801124, while operating in Mode 1, at 83X power, sample analysis of safety injection accumulator iC revealed boron concentration in excess of Tech 8pec. Caused by stagnant solution stratification in accumulator. CARTWRIGHT. M. R. Virginia Electric & Power Co. 80/12/04. 2pp. 07199:353.
- 8012090362 Forwards LER 80-093/01T-0. CARTMR10HT/M.R. Virginia Electric & Power Co. 80/12/04. ip. 07199: 358.
- --8012090365 LER 80-093/01T-0:on 801126.util learned that manufacturer gave erroneous value for weights of two valves in RHR sys. Caused by manufacturer error. Support will be modified to increase safety factor of anchor bolts to correct value. CARTMRIGHT.W.R. Virginia Electric & Power Co. 80/12/04. 2pp. 07199:339.
- 8012230423 Forwards LER 80-101/03L-0, CARIMRIOHT, M. R. Virginia Electric & Power Co. 80/12/17, 1p. 07311:267.
- --8012230428 LER 80-101/03L-0: on 801207 while operating in Mode 1 at 70% puwer, containment HiHi pressure alarm channel 2 was received. Caused by signal comparator card failing low out of tolerance. New card installed.

 CARTURIOHT. W. R. Virginia Electric & Power Co. 80/12/17. ip. 07311:268.

- 8012310316 Forwards LER 80-100/03L-0. CARTURIGHT W. R. Virginia Electric & Power Co. 80/12/22. ip. 07349:042.
- --8012310333 LER 80-100/03L-0: on 801201.LI-1474 steam generator A level channel 1 indicated higher than average of three channels. Caused by high transmitter output due to leaking root isolation valve. Will be repaired in next refueling outage. CARTHRIGHT.W.R. Virginia Electric & Power Co. 80/12/28. 2pp.
- 8012310325 Forwards LER 80-103/03L-0. CARTHRIGHT W. R. Virginia Electric & Power Co. 80/12/22. 1p. 07369:054.
- --8012310330 LER 80-103/03L-0: on 801113. containment matl seismic recorder ER-002 failed periodic test PT-39. 5. Caused by electronic fault in field sending unit. Total component replaced.
 GARTHRIGHT. W. R. Virginia Electric & Power Co. 80/12/22. 2pp.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2 F. Becurity, mudical, emergency & fire protection plans

- B012010602 Notifies of completion of privacy review of emergency plan documentation. Encl info may be made publicly available. FELTON, J. M. Division of Rules and Records. 80/11/13. 1p. 07091: 202.
- --B012010614 Public version of amargency plan, revised Tables 4.1A through 4.1D, changing initiating conditions for notification.

 d Virginia Electric & Power Co. B0/10/29. 16pp. 07091:216.
- 8012110652 Summary of 801107 meeting w/util in Bethesda,MD re emergency plans. NEIOHBORS, J. D. Operating Reactors Branch 1. 80/11/19. 2pp.
- 8012110178 Forwards FR notice re revision to 10CFR50.48 & new App R to 10CFR50 re fire protection features at nuclear power plants. TEDESCO, R. L. Assistant Director for Licensing. 80/11/26. 16pp. 07224:060.
- 8012050421 Forwards amended pages to approved security plan. Encl withheld (ref 10CFR2.790). SYLVIA.B.R. Virginia Electric & Power Co. 80/12/02. 1p.
- 8012230226 Forwards draft NUREO-0696, "Implementation Plan" for establishment of emergency response facilities. Details on emergency operations facility establishment not included in plan, boing finalized & will be submitted at later date. BYLVIA, E.R. Virginia Electric & Power Co. 80/12/18. 1p.
- --8012230293 Draft NUREO-0696, "Implementation Plan" for establishment of emergency response facilities.

 * Virginia Electric & Power Co. NUREO-0696. 80/12/18. 47pp.
- 8012290274 Forwards alternate shutdown sys design description refire protection.per NRC 801124 ltr.Util review of App R to 100FRSO concludes that plants are in compliance w/exception of 8-h emergency lights in egress routes.

 SYLVIA.B.P. Virginia Electric & Power Co. 80/12/23. 3pp.

Q. Adjudicatory correspondence

- B012170B19 Requests, on behalf of util, extension until B1010B for hearing on B0120B order for mod of licenses re environ qualification of safety-related electrical equipment to Tach Bpecs of facilities.

 CHRISTMAN, J. N. Affiliation Unknown. B0/12/08. 2pp.
- P. Operating license stage documents & correspondence
- 8012020050 Notification of 801107 meeting w/8kN & util in Bethesda.MD to discuss resolution of amplified response spectrum concerns.

 ENGLE.L. Operating Reactors Branch 3. 80/10/31, 2pp. 07147:195.

- 8011200377 Notification of 801203 meeting w/util in Bethesda, MD to discuss util plans in area of core reload licensing in upcoming yr
 BERGGGEN, J.S. Standardization & Special Projects Branch. 80/11/06.
- 8012040414 Submits addl info re low head safety injection & outside recirculation spray pump operability, per 1980 801105 request. Package of 12 illegible oversize drawings encl. SYLVIA.B.R. Virginia Electric & Power Co. 80/11/26. App. 06915-001.
- B012170432 Responds to NUREG-0528. "Environ Qualification of Safety-Related Electrical Equipment." Forwards package revising B01101 submittal.providing evaluation results of equipment qualification w/insufficient info. I/o encl. SYLVIA.S.R. Virginia Electric & Power Co. B0/12/01. 3pp. 07245-223.
- B012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions Forwards results of IE survey.

 DENIGN-H.R. Office of Nuclear Reactor Regulation, Director.
 80/12/04. 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANGART.R.L. Effluent Treatment Systems Branch. B0/11/06. Bpp.
- B012310162 Advises that results of endurance test for steam driven auxiliary feedwater pump are acceptable & that license condition has been met.

 TEDESCO,R.L. Assistant Director for Licensing. 80/12/09. 2pp.
- BD12190076 Notification of B10107 meeting w/util in Bethesda.MD to discuss isolation valve leak testing. DROMERICK.A W. Licensing Branch 1. B0/12/11. 3pp. 07279:144.
- 8012190354 Forwards response to NUREO-0737 post-TMI requirements. SYLVIA.B.R. Virginia Electric & Pouer Co. 89/12/15. 430pp.
- 8012190378 Forwards add1 info re util 801120 proposed amend to License NPF-7; in response to NRC request lapact of changes & equipment delays on implementation dates for TMI requirements & plant mods per IE Sulletin 79-27 discussed. SYLVIA.B.R. Virginia Electric & Power Co. 80/12/15. 7pp. 07284:048.
- B012230439 Application for amend to License NPF-7, changing I tem (ii) of Condition 2. C. 21. i of B01120 application re NUREG-0737 implementation date requirements. Change involves containment water level. FEROUSTRI, J. H. Virginia Electric & Power Co. B0/12/18. 3pp. 07312-264.
- 8012290316 Application to amend License NPF-7. changing App B Tech Specs, to provide for consistency w/latest environ protection plan. Class I fee encl. PERGUSON, J. H. Virginia Electric & Power Co. 80/12/23. 3pp. 07339:081.

Q. Inspection reports. IE Builetins & correspondence

- 8012140036 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.

 1p.
- 8012170821 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. O'REELLY.J.P. Region 2. Atlanta. Office of the Director. 80/10/30. 10.
- B012180020 Forwards IE Info Notice B0-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. H0/10/31.

 19.
- B012230070 Forwards IE Circular 80-23. "Potential Defects in Seluit Fower Sys Emergency Generators." No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.

 1p. 07313:236.

- 8012110794 Forwards [E Sulletin 80-21, "Yalve Yokes Supplied by Malcolm Foundry Co.lnc." Written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.
 lp.
- 8012030849 Forwards IE Info Notice BO-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. BO/11/07. 1p.
- 8012080259 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besso Unit 1." No response required.

 O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/10.
- 8012180219 Forwards IE Insp Repts 50-338/80-36 & 50-339/80-34 on 801021-24. No noncompliance noted.
 MURPHY.C.E. Region 2- Atlanta, Reactor Construction & Engineering Support Branch. 60/11/10 2pp. 03792:012.
- --8012180222 JE Insp Repts 50-338/80-36 & 50-339/80-34 on 801021-24.No noncompliance noted Major areas inspected installed equipment review w/respect to IE Bulletin 79-018.
 013800NS.T.D. Region 2. Atlanta, Office of the Director. CGLON.T.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/10 5pp 03792:014.
- 8012040135 Forwards IE Bulletin 80-23. "Failures of Solemoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/14. 1p.
- 8042050070 Forwards IE Sulletin 80-24. "Prevention of Damage Due to Mater Leakage Inside Containment." Ho written response required.

 O'REIU(1y.J.P. Region 2, Atlanta, Diffice of the Director. 80/11/21.
 1p. 07173:230.
- 8012080018 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24.
- B012170397 Forwards 1E Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange," No written response required. O'RE(LLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26, ip. 07269:080.
- 8012180140 Ack receipt of 801024 ltr informing NRC of steps taken to correct deviations noted in 1E Insp Repts 50-338/80-30 & 30-339/80-29. LEUIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/11/28. 1p. 03791:248.
- --8012180142 Responds to NRC 801002 ltr re deviations noted in IE Insp. Repts 50-338/80-30 & 50-339/80-29. Corrective actions: addl radios assigned to control room. SKLVIA.S.R. Virginia Electric & Power Co. 80/10/24. 2pp. 03791: 249.
- --8012180145 Forwards IE Insp Repts 50-338/80-30 & 50-339/80-29 on 800712-0820 & notice of deviation. LENIG.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. B0/10/02: 2pp. 03791:251.
- --8012180146 Notice of deviation from insp on 800712-0820.

 # Region 2, Atlanta, Office of the Director. 80/09/30. 1p. 03791:253.
- -8012180149 IE Insp Repts 50-328/80-33 & 50-339/80-29 on 800712-0820. Noncompliance noted: failure to maintain portable radios for fire brigade use MEBSTERLE H. TATTERSALL A.P. Region 2. Atlanta. Office of the Director. KELLOOG.P J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/09/30. [7pp. 03791:254.
- 8012180198 Ack receipt of 800923 ltr informing NRC of steps taken to correct violations noted in It. Insp Repts 90~338/80-19 & 50-339/80-20. LEMIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/12/01. 1p. 03791:296.

- --8012180192 Forwards revised response to remaining open item re violations noted in IE Insp Repts 50-338/80-19 & 50-339/80-20. Corrective actions: review made of const GA manual.station QA manual & GC Procedure 26. 1. SYLVIA.B.R. Virginia Electric & Power Co. 80/09/23. 2pp. 03791:297.
- --8012180195 Ack receipt of 800520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/80-19 & 50-339/80-20 Supplemental response will be submitted by 800919.

 LENIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 60/09/09. ip. 03791:299.
- --8012180201 Forwards IE Insp Repts 50-338/80-19 & 50-339/80-20 on 800414-0530 & notices of violation & deviation. LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/07/21 2pp. 03791:301.
- --B012180204 Notice of violation from insp on 800414-0530.

 * Region 2, Atlanta, Office of the Director. B0/07/21. ip. 03791:303.
- --8012180205 Notice of deviation from insp on 800414~0530. # Region 2, Atlanta, Office of the Director. 80/07/21. tp. 03791:304.
- ---8012180208 IE Insp Repts 50-338/80-19 % 90-339/80-20 on 800414-0530.

 Noncompliance noted failure to conduct surveillance test at required frequency % to provide instructions for reseatablishing ventilation flow after seismic event.

 KIDD.M.S., TATTERSALL.A.P. Region 2. Atlanta, Office of the Director. KELLOGS,P.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/07/21. 22pp. 03791:305.
- B012110543 Forwards response to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Two Valcor valves exist for each North Anna unit & Burry does not have solenoid valves described in bulletin. SYLVIA, B.R. Virginia Electric & Power Co. B0/12/04. 3pp.
- 801223009i Forwards response to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Specified valves are not in use at facilities. SYLVIA,E.R. Virginia Electric & Pawer Co. 80/12/04. 3pp.
- 8012240503 Forwards response to 1E Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Two Valcor valves in use do not have cited part number. SYLVIA.B.R. Virginia Electric & Power Co. 80/12/04. 3pp.
- 8012120467 Forwards response to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No subj valve used or planned for use in safety-related sys at facilities. SYLVIA.E.R. Virginia Electric & Power Co. 80/12/05. 3pp.
- R. Periodic operating reports & related correspondence
- 801219050B Forwards monthly operating repts for Nov 1980. SYLVIA.B.R. Virginia Electric & Power Co. 80/12/15. ip. 07287:078.
- --8012190513 Monthly operating repts for Nov 1980. FELLOUS M.E. Virginia Electric & Power Co. 80/12/09. 9pp. 07287:079.
- S. Reportable occurrences, LERs & related correspondence
- 8012010277 Forwards LER 80-084/03L-0. CARTWRIGHT W. R. Virginia Electric & Power Co. 80/11/19. 1p. 07092:139.
- --8012010230 LER 80-084/03L-0: on 801027-29, differential of greater than 12 steps discovered between rod position indication for rod cluster J-3 & demand position. Caused by instrument drift. Channel recalibr.
 Channel recalibr.
 CARTHRIGHT, M. R. Virginia Electric & Power Co. 80/11/19. 2pp. 07092: 140.
- 8012010333 Forwards LER 80-083/03L-0, CARTHRIGHT.N.R. Virginia Electric & Power Co. 80/11/19, 1p. 07092:171,
- --B012910362 LER 80-083/03L-0: on 801027.F(Q) limit exceeded twice. Caused by rod movement at beginning of core life when F(Q) limit mangins in core ctr are at min. Power reduced. CARTWRIGHT, W. R. Virginia Electric & Power Co. 80/11/19. 2pg. 07092: 172.

- 8012040669 Part 21 rept re S&W notification that out-of-phase transfer might occur when emergency buses are transferred from offsite power source to emergency diesel generators after reaching rated speed & voltage. Originally reported 801114.

 SYLVIA B. R. Virginia Electric & Power Co. 80/11/19. 4pp.
- 8012010352 Forwards LER 80-076/03L-0. CARTHRIGHT, W. R. Virginia Electric & Power Co. 80/11/24. 1p. 07072:168.
- --8012010359 LER 80-076/03L-O. on 801104 steam generator level transmitter LT-486 gave high indication of 4.7% Caused by instrument drift. Transmitter recalist. CARTMRIGHT, W.R. Virginia Electric & Pauer Co. 80/11/24. 2pp. 07072:169.
- 8012020423 Forwards LER 80-093/03L-0. CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/24, 1p. 07148: 297.
- --8012020426 LER 80-093/03L-0: on 801101, diesel 2H room fire door had been non-functional more than seven days. Caused by using door while room was under vacuum from operation diesel. Door replaced.

 GARTHRIGHT, W. R. Virginia Electric & Power Co. 80/11/24. 2pp.
- 8012020581 Forwards LER 80-090/03L-0. CARTWRIGHT, W. R. Virginia Electric & Power Co. 80/11/24. ip. 07148: 223.
- B012020594 Forwards LER 80-092/03L-0. CARTHRIGHT, W. R. Virginia Electric & Power Co. B0/11/24. 1p. 07148: 220.
- --8012020602 LER 80-072/03L-0: on 801103, train 8 of safety injection systailed to reset following functional test. Caused by binding in latching mechanisms resulting in failure of relays to reset. Relays cleaned & tosted satisfactority. CARTMRIGHT. M.R. Virginia Electric & Power Co. 80/11/24. 2pp. 07148: 221.
- 8012100563 Forwards LER 80-087/03L-0. CARTNRIGHT, W.R. Virginia Electric & Power Co. 80/11/24. 1p. 07218: 153.
- --B012100570 LER 80-087/03L-0: on 801029 axial flux difference twice deviated greater than 5% from target Caused by 10% load swing & 50% load rejection from 10% power for startup testing Power & control rod manipulations performed.

 CARTWRIGHT, N. R. Virginia Electric & Power Co. 80/11/24. 2pp.
- 8012190033 Part 21 rept re design of emergency bus residual voltage bus transfer. Caused by lack of definitive phase relationship between ansite & offsite sys. Timers were installed. MILD.P.A. Stone & Webster Engineering Corp. 80/12/02. 4pp. 07240:347.
- 8012150173 Forwards LER 80-075/03L-0. CARTHRIGHT.W.R. Virginia Electric & Power Co. 80/12/04. ip. 07237: 304.
- --Bol2130176 LER 80-075/O3L-0:cn G01123.loop A flow transmitter FT-2415 found to be 2.39% higher than Tech Spec requirement. Caused by instrument drift. Transmitter recalibr & verified. CARTMRIGHT. W.R. Virginia Electric & Power Co. B0/12/04. 2pp. 07237:305.
- 8012160459 Forwards LER 80-088/03L-0. CARTKRIGHT, M.R. Virginia Electric & Power Co. 80/12/10. ip. 07254:213.
- --8012160467 LER 80-088/03L-0 on 801127 containment pressure channel III failed high: Caused by defective card in circuit. Circuit card replaced & channel III restored to operation.

 CARTHRIGHT W. R. Virginia Electric & Power Co. 80/12/10. 2pp. 07284-214
- 8012160514 Forwards LER 80-085/03L-0. CARTURIGHT.W.R. Virginia Electric & Power Co. 80/12/10. ip. 07261:164.

- --8012160524 LER 80-085/030-0 on 801127, while operating in Mode G, steam flow indications on loop B.F1-2484 & F1-2485, differed from each other by 2.75 E+5 lb/hr Caused by circuit card being out of calish Card replaced & calish
 + Virginia Electric & Power Co. 80/12/10. 2pp. 07261:165.
- 8012230371 Forwards LER 80-691/03L-0. CARTHRIGHT.W.R Virginia Electric ව Power Co. 80/12/17. 1p 07312.235.
- --8012230376 LER 80-091/03L-0 on 801130 while operating in Mode 3 rod position indication for rods 603 & J03 in bank A & 607 & 609 in bank B differed from demand position by greater than 12 steps. Caused by instrument drift Channel adjusted. CARTMRIGHT. W. R. Virginia Electric & Power Co. 80/12/17. 2pp. 07312-237.
- 8012230412 Forwards LER 80-082/03L-0. CARTWRIGHT:W R. Virginia Electric & Power Co. 80/12/17. 1p. 07312:255.
- --8012230416 LER 80-082/031-0.on 801125 during degraded voltage test, breaker 24JI-2 failed to open upon receiving undervoltage test signal & 2-RSP-P-18 was inoperable for 3-h. Caused by stuck linkage arm. Linkage pivot points oiled. CARTWRIGHT. N. R. Virginia Electric & Pauer Co. 80/12/17. 2pp. 07312: 236
- 8012230419 Forwards LER 80-095/03L-0. CARTIRIOHT W.R. Virginia Electric & Power Co. 80/12/17. 1p. 07312:258.
- --8012233424 LER 80-095/03L-0. on 801202; while operating in Mode 3, rod position indication for rod cluster 0-13 differed from demand position by greater than 12 steps. Caused by instrument stift due to change in temp af control rod drive. CARTMRIGHT. W. R. Virginia Electric & Power Co. 80/12/17. 2pp. 0210-2358
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT. UNIT 2

 A. Application/construction stage documents & correspondence
- 80(2160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TM1 action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 inplementation dates will be met. EISERMUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP & GL holders for SGRs re requirement for implementation of GDYN code for licensing basis calculations performed by OE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing 80/11/04. 4pp.
- B012100214 Notification of B01202 meeting w/BWR licensing review group in Bethesda, MD to discuss status of group issues.
 WILBON-J. N. Licensing Branch 1 80/11/20. 8pp. 07217:304.
- 8012220131 Summary of 800514-0028 meetings w/BRR Licensing Review Group in BethesdarKD religentification of generic issues, formation of consensus positions & resolutions that will apply to all six plants. Draft working paper each.
 WILSON, J. N. Licensing Branch 1. 80/12/05. 99pp.
- BO12190071 Notification of 501223 meeting w/util in Bethesda.MD to discuss scope & schedule for completion of review of application to operate facility KINTMEN.L.L. Licensing Branch & H3/12/09. 3pp. 07279:091.
- F. Security, medical, emergency & fire protection plans
- BO12040171 Public version of "Independent Assessment of Evacuation Times for Enrico Fermi Nuclear Power Plant," Vol 4, prepared for FEMA. COSBY, J.C., GHEPPARD, W.V., WATERS, E.L. Wilbur Smith & Associates, BO/06/30, 47pp. 07161, 167.
- B012160014 Summary of B01125 meeting u/util at site me plans for emergency response facilities. Viewgraphs encl. KINTHEM.L.L. Licensing Stanch 2. B3/12/02. Spp. 07262: 334.

- 8012040365 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Energency Planning Zones," executive summary. FELTON J. N. Division of Rules and Records 80/12/03, 1p.
- --8012040023 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Iones," executive summary, prepared for FEMA 4 Hilbur Smith & Associates. 80/06/30. 17pp.
- --8012040155 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol 1. prepared for FEKA. COSBY.J.C. Wilbur Smith & Associates. 80/06/30. 43pp.
- Q. Inspection reports, 1E Bulletins & correspondence
- E012310514 Forwards IE Investigation Rept 50-341/89-13 on 800728-31. No noncompliance noted.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/21.

 2pp. 07355:269.
- --8012310518 IE Investigation Rept 50-341/80-13 on 800728-31. No noncompliance noted. Major areas inspected: allegations reingroper gipe & structural stepl welding 90. FOSIER. J.E. MARD.K. D., NORELIUS.C.E. Region 3, Chicago. Dffice of the Director. 80/10/14. 25pp. 07365:271.
- 8012040682 Forwards IE Insp Rept 50-341/80-17. on 801006-09. No noncompliance noted! FIDRELLI, G. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/10/24. 2pp. 07169:114.
- -B012040668 IE Insp Rept 59-341/89-17 on B01006-09. No noncompliance noted. Major areas inspected: RCPB piping work activities & safety-related piping welding activities. LEE.E.N.X., DANIELEGND, D.H. Region 3, Chicago, Office of the Director. B0/10/23. 3pp. 07169:116.
- EG12170671 Forwards IE Info Notice 90-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit-2." No written response required.

 KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/10/24.

 1p 07266:065.
- 8012110636 Forwards IE Insp Rept 90-341/80-15 on 800901-30. No noncarpliance noted HEISHMAN R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/10/30 2pp. 07227:194.
- --8012i10646 IE Insp Rept 50-341/80-15 on 800901-30. No noncompliance noted Hajor areas inspected: IE Bulletin & circular followup. & itemsee action on previous insps. LITTLE:B.H. BYRON.P N. LITTLE:U.B. Region 3. Chicago, Office of the Director. 80/10/27 3pp. 0/227, 196.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that #acility can compare program at program already reviewed & make appropriate adjustments 1870 enci.

 KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/11/18. Ann
- 8012310506 Forwards IE Insp Rept 50-341/80-18 on B01001-31, No noncompliance noted. HEISHMM.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/20. 2pp. 07355.262.
- --8012310511 IE Insp Rept 50-341/80-16 on 801001-31. No noncompliance noted Major areas inspected previous insp findings followup, safety uori activities review & instrumentation review. LITILE.B.H. SPRON.P.H. LITTLE.B.H. SPRON.P.H. LITTLE.B.H. SPRON.P.H. O7365:264.
- 8012040647 Forwards IE Builatin 80-24. "Prevention of Damage Due to Water Lealage Inside Containment." No written response required. MEPPLER J. O. Region 3. Chicago. Office of the Director. 80/11/21. 2pp. 07169:109.
- 8012080056 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snobber Fluid." No Enitten response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:203.
- B012170540 Forwards IE Info Natice 80-29.Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KCPPLER.J.G. Region 3: Chicago, Office of the Director. 80/11/26. 2pp. 07264:266.

- S. Reportable occurrences, LERs & related correspondence
- 8012120459 Interim deficiency rept re defective GE-185E welds, initially reported 801024. Util is analyring problem. Final rept will be submitted G10224. HINES.E. Detroit Edison Co. 80/11/25, 1p. 07230:328.
- DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC F. Security, medical, emergency & fire protection plans
- 8012300267 Requests that site emergency plan be revised to address volcanic activity. Evacuation plans should consider such adverse conditions as ashfall mudflow floods & landslides. CLARK. R. A. Operating Reactors Branch 3. 80/11/24. 3pp. 07358:204.
- --8012300272 Requests FEMA review state & local planning efforts for areas around CA nuclear power plant sites w/respect to complications arising in event of extreme natural phenomena. ORIMES.B.K. Emergency Preparedness Program Office (after 801119 see I&E). 80/11/03. 2pp. 07358:287.
- 8012310051 Forwards "Emergency Preparedness Evaluation Rept" for facility. Revised plan addressing volcanic activity & connitments must be implemented.

 CLARK.R.A. Operating Reactors Branch 3 80/12/02. 2pp. 07371:121.
- --8012310055 "Emergency Preparedness Evaluation Rept."

 d Office of Inspection % Enforcement, Office of the Director, 89/11/30. 24pp. 07371:123.
- 8012300297 Forwards physical security plans. Plan withheld (ref 10CFR2.790). HITHERS, E. D. Portland General Electric Co. 80/12/23. 2pp. 07349: 336.
- G. Adjudicatory correspondence
- 8012300188 Forwards JL Crew 801014 ltr & encl setting forth results of first systematic appraisal of licenses performance. NOVAK, T. II. Assistant Director for Licensing. 80/11/24. 3pp. 07356:302.
- 8012020446 Forwards brief in opposition to exceptions filed by State of OR.

 AKELRAD, M. Lowenstein, Newman, Reis, Axelrad & Toll. BO/11/26. 1p.
 07148: 137.
- -8012020450 Brief in opposition to exceptions filed by State of OR asserting that control room design mods require accelerated reporting for adequate review. License conditions & 10CFR57 provide significant constraints. Certificate of Svc encl. JOHHSON-R. W. . AXELRAD. M. Portland General Electric Co. AXELRAD Lowerstein, Neuman, Reis, Axelrad & Toll. 80/11/26. 28pp. 07148: 138
- 8012090325 Notifies of typographical error in licensee brief in opposition to State of OR exceptions Footnote 13 on Page 19 should road, "fire protection Conditions (d) & (t)," Certificate of Syc enct. AKELRAD, M. Lowenstein, Neuman, Reis, Axelrad & Toll. 80/12/04. 3pp. 07201:116.
- 8012150231 Response in support of State of GR 800723 motion for reconsideration of ASLS 800711 order modifying OL & 801022 amended exceptions. New info showing licensee change review process favors accelerated reporting WGertificate of 8vc. GRAY, J. R. Hearing Branch 1. 80/12/08. 27pp. 07240:029.
- 8012300128 Order directing MRC to file supplemental mamorandum on question of Board authority to decide appeal on basis of matter not included in record underlying ASLB decision.

 Memorandum due by 801218.

 BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/12/09, 2pp. 07356:257.
- 801227004B Requests that ASLAB defer filing of responsive pleadings by State of DR & licensee until ASLAB has had opportunity to review encl unexecuted stipulation re accelerated reporting requirements. W/Certificate of Svc.
 AXELRAD. ft. Lowenstein, Newman, Reis, Axelrad & Toll. 80/12/18. 9pp. 07344:001.
- 8012300110 Supplemental memorandum per ASLAB 801209 order re question of Board authority to decide State of GR appeal on basis of matter not included in record underlying decision. ASLAB lacks such authority. Certificate of Svc encl. GRAY, J. R. Hearing Branch 1. 80/12/18. Spp. 07356: 236.

- 8012290275 Order extending time for filing of responses to ASLAB 801209 order due to representations contained in licensee 801218 ltr.
 BISHDP.C.J. Atomic Safety and Licensing Appeal Panel. 80/12/19. tp. 07341: 182.
- B012300451 Forwards stipulation & motion re accelerated reporting requirements. AXELRAD.M. Lowenstein, Newman, Rois, Axelrad & Toll. B0/12/24. 1p. 07357:193.
- --8012300497 Stipulation & motion on accelerated reporting requirements re State of OR 800923 exceptions & brief on exceptions. Parties agree to modify License Condition 2.C. (12) recontrol bldg mod. Certificate of Svc encl. AXELRAD.M. Lowenstein, Newman, Reis, Ayelrad & Toll. (ISTRANDER, F. H. Organ, State of, ORAY, J. R. Hearing Branch 1, 80/12/22, 7pp. 07397:194.
- P. Operating license stage documents & correspondence
- 8012920753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to revious capability of operating PWRs to remove decay heat following parthquake.
 EISENHUT.D.G. Division of Licensing. 80/10/21, 4pp,
- 8012160050 Ltr to operating plant licensess OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licenses confirmation in 45 days that Encl I implementation dates will be net. EISEURUT. D. G. Division of Licensing. 80/10/31. 7pp.
- 8012220343 Ltr to all power reactor licensees forwarding NUREG-0419, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. Wo encl. EISENHUT, D. O. Division of Licensing. 80/11/13. 1p.
- 8012020550 Responds to NRC 801001 request for info re environ equipment qualification tests. Prossure transmitter tests conducted by Util Transmitter Qualification Group, & safety valve flow monitoring tested by Technology for Energy Corp. WITHERS B. D. Portiand General Electric Co. 80/11/25. 2pp. 07141-272
- 8012080461 Forwards response to actions requested in NRC 800930 ltr re inadvertent boron dilution. Return to criticality due to boron dilution event during operational Modes 4 & 5 will not accur. No revision to plant procedures are necessary. WITHERS, E. D. Portland General Electric Co. 80/11/26. 5pp. 07189:274.
- B012220483 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of EE survey.
 DENION, H. R. Office of Nuclear Reactor Regulation, Director. 80/12/04. Spp.
- --8012220906 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANSART.R.L. Effluent Treatment Bystems Branch. 80/11/06. 8pp.
- 8012090213 Forwards Amend 1 to PGE-1022, "Inservice Testing Program for Pumps & Valves." Amend incorporates resolution of internal & NRC comments on program.
 WITHERS, E. D. Portland Coneral Electric Co. 80/12/08. 1p. 07200:345.
- --E012090217 "Inservice Testing Program for Pumps & Valves." Constitutes Amend 1 to PGE-1022. GERLT.D. H. Portland General Electric Co. 80/12/31. 92pp. 07200:346.
- 8012160437 Responds to 801104 ltr. Util intends to amend FBAR to include control bldg mod & masonry wall design criteria by 810325. WITHERS, B. D. Portland General Electric Co. 80/12/10. 2pp. 07263:139.
- 8012230313 Forwards supplemental response to NRC 801023 request for info re auxiliary feedwater sys. Condensate storage tank level instrumentation & alarm switches installed & are now in syc.

 MITHERS, B. D. Portland General Electric Co. 80/12/12. App. 07311: 120.

- 8012300551 Responds to NRC 801031 ltr requesting response to NUREO-0737 re implementation of TMI-2 action items. Util intends to meet requirements & schedules eacept where stated Hardware availability problems could cause delays.
 HITHERS. E. D. Portland General Electric Co. 80/12/23. 18pp. 07346:235.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012170708 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 ENGELKEN.R.H. Region 5, Ean Francisco, Office of the Director.
 80/10/24. 1p. 07266:081.
- 8012170415 Forwards IE. Info Notice 80-38; "Cracking in Charging Pump Casing Cladding." No unitten response required. ENGELKEN.R. H. Region 5, San Francisco, Office of the Director. 80/10/30. 1p. 07264:058
- 8012090087 Forwards IE Health Physics Appraisal Rept 50-344/80-16 & notice of violation & significant appraisal findings. ENGELKEIJAR. H. Region 5. San Francisco. Office of the Director. 80/10/31. 5pp. 07198:116.
- --B012070070 Notice of violation from health physics appraisal on 800707-18.

 * Region 5, San Francisco, Office of the Director. 80/10/31. 1p. 07198-121.
- --8012070075 IE Health Physics Appraisal Rapt 50-344/80-16 Noncompliance noted:RCS degassed & no evaluation made of change to determine existence of unreviewed safety question.

 NORTH.H.S., YUHAS.G.P. Region 5, San Francisco, Office of the Director. SMATHERS.J.S. California, Univ. of, Los Angeles.

 80/10/31. 96pp. 07198:122.
- 8012170841 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
 ENGELMENTH.R. H. Region 9, San Francisco, Office of the Director, 80/10/31. 1p. 07264:031.
- 8012100128 Forwards IE Insp Rept 50-344/80-25 on 831020-23 No noncompliance noted. CREMS.J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 60/11/05. 2pp. 07219.261.
- --8012100134 IE Insp Rept 50-344/80-25 on 801020-23 No noncompliance noted Major areas inspected:maint, design & organization administration.
 STERNBERG, D. M. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. CARLSON, J. O., WILLETT, D. J. Region 5. San Francisco, Office of the Director. 80/11/03. App. 07219:263.
- 8012120232 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ENGELKFN,R.H. Region 5, San Francisco, Office of the Director. 80/11/06. 1p. 07227:338.
- 8012030935 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization "No written response required. ENGELKFIJ.R.H. Region 5, San Francisco, Office of the Director. 80/11/07. 1p. 07130:141.
- 8012080625 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Basse Unit 1." No response required. ENCELKELL, R. M. Region 5, San Francisco, Office of the Director. BO/11/10. ip. 07183;029.
- 8012040221 Forwards IE Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ENGELKFUR. H. Region 5. San Francisco. Office of the Director. BO/11/14. ip. 07158:141.
- 8012310227 Forwards IE losp Rept 50-344/80-27 on 801027-31.No noncompliance noted.
 SPENCER.O.S. Region 5. San Francisco: Reactor Construction & Engineering Support Branch. 80/11/19. 2pp. 07369:352.
- --8012310227 IE Insp Rept 50-344/80-27 on 801027-31 No noncompliance noted Major areas inspected: activities re IE Bulletin 79-018.
 ELIN.J.D. Region 5. San Francisco, Office of the Director, DODDS, R. T. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 80/11/18. 4pp. 07349:354.

- 8012310535 Forwards IE Insp Rept 50-344/80-26 on 801001-31.No nonctripliance noted CREMS.J.L. Region 5. Son Francisco, Reactor Operations Nuclear Support Branch. 807/11/20. 2pp 07345.299.
- --8012310538 IE Insp Rept 50-344/80-26 on 801001-31.No noncompliance noted. Mayor areas inspected plant operations, surveillance testing, physical security & procurement.
 MALKROS. M. H., JÜHMSTCM. G. W. Region 5; San Francisco, Diffice of the Director STERNSERG. D. M. Region 5; San Francisco, Reactor Operations Nuclear Support Branch 80/11/18. 7pp. 07365:301.
- 2012040463 Forwards IE 3911etin 60-24, "Prevention of Damage Due to Water Leakage Inside Containment." Unitten response required Requests info on manpower expended. ENGELKEN.R. H. Region 5, San Francisco, Défice of the Director. 20/11/21. 1p. 07163.321.
- 6012160092 Forwards IE Info Natice 80-42, "Effect of Radiation on Hydraulic Srubber Fluid." No response required. EM3ELKFM.R.H. Region S. San Francisco. Office of the Director. 80/11/24. 1p. 07262:108.
- 8512165121 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Stude on Terry Turbine Steam Inlet Flange " No written response required. EXOSEMENTRY Region 5: San Francisco. Office of the Director. 80/11/26. 1p. 07262:079.
- E012180313 Ack receipt of 801126 ltr informing NRC of steps taken to correct violations noted in IE health physics appraisal rept.
 ENGELMEN.R.H. Region 5. San Francisco. Office of the Director. 90/12/04. 1p. 03794:054.
- --8012189325 Responds to NRC 801031 ltr re violations noted in IE health physics appraisal on E00707-18 Corrective actions: jumper between pressurized vapor space & coolant vol control sysholdup tanks disconnected & training program revised. MITHERS, B.D. Portland General Electric Co. 80/11/26. 9pp. 03794:055.
- B012180032 Forwards marked-up portions of IE Health Physics Appraisal Pept 50-344/80-16 notice of violation & significant appraisal findings highlighting apparent weaknesses. NOVAN, T.M. Assistant Director for Operating Reactors. B0/12/05. 16pp. 03768:001.
- R. Periodic operating reports & related correspondence
- 8012150036 Forwards monthly operating rapt for Nov 1980. VUNDT.C.P. Portland General Electric Co. 60/12/02. 1p. 07237:258.
- --8012150057 Monthly operating rept for Nov 1980. SAIR-0.G. Portland General Electric Co. 80/12/03. 4pp. 07237:259
- S. Reportable occurrences, tERs & related correspondence
- 8012150951 Special CO-day rept re penetrations through O-h fire barriers protecting safety-related areas rendered nonfunctional for more than seven days. Personnel are being trained re installation & insp techniques.

 VDNDT,C.P. Portland Gameral Electric Co. 80/12/04. 3pp.
- 8012230446 RO: limiting condition for operation re-nonfunctional fire barrier Temporary barriers to be provided for addl protection as combustion smake detectors are operable. Barrier should be functionally operable in seven wis. YUNDT.C.P. Portland General Electric Co. 80/12/10. 1p. 07314:140.
- E012230305 RO: on B01210, break occured in Fire sys yard loop header, resulting in partial inoperability of fire suppression sys. Caused by const personnel error. Firauatch was stationed in emergency diesel generator room.

 YUNOT, C.P. Portland General Electric Co. 80/12/11. 1p. 07311: 103.
- 8012230452 Forwards LER 80-025/03L-0. VUNDT.C.P. Portland General Electric Co. 80/12/11. 2pp. 07314:117.
- --8012230455 LER 80-025/03L-0 on 801112, during periodic test, found vital preferred 120 volts ac instrument buses Y11, Y13 & Y24 powered from same emergency power source train. Caused by failure in determining alternate electrical supply lineup. 8AFR.O. G. Portland General Electric Co. 80/12/11. 1p. 07314:119.

- 80122300469 RO: on B01212, leak occurred in fire sys yard loop header, resulting in part of fire suppression sys being inoperable. Caused by expansion joint slippage on hydrant exposed during excavation. Problem previously occurred B01211. YUNDT.C.P. Portland General Electric Co. 89/12/15, ig. 07183:001.
- B012300405 RG: on B01212, leak occurred in fire sys yard loop header, rendering in part of fire suppression sys inoperable.
 Caused by expansion joint slippage on fire hydrant which was exposed during excavation. Pipe repaired.
 YUNOT, C. P. Portland General Electric Co. B0/12/15. 1p. 07347:360.
- 8012300616 RO: sys operability per Limiting Condition for Operation 3.7.8.1 will not be mot during relocation of yard hydrant, espected to require three days during which yard loop header will be out of svc. Work to be completed by 801224.
 YUNDT, C. P. Portland General Electric Co. 80/12/17. ip. 07357:325.
- 8012300593 Forwards updated LER 80-019/03L-1. YUNOT.C.P. Portland General Electric Co. 80/12/19. 3pp. 073/1:352.
- --8012300559 Updated LER 80-019/03L-1: on 800924, reactor trip setpoints for high steam flow found set incorrectly. Caused by error in manual. Setpoints readjusted. Manual checked for similar errors.

 PERRY, J. C. Portland General Electric Co. 80/12/19. ip. 07361:355.
- 8012300560 Forwards LER 80-027/03L-0. YUNDT.C.P. Portland General Electric Co. 80/12/19. 2pp. 07352:292.
- --8012303565 LER 80-027/03L-0: on 801127, discovered that generator loctout relay apparently tripped on east emergency diesel generator. No cause determined. Relay reset & request for design change to add relay to alarm submitted.

 PERRY.J. C. Portland General Electric Co. 80/12/19. 1p. 07362:294.
- 8012300568 Forwards LER 80-026/03L-0. YUNDT.C.P. Portland General Electric Co. 80/12/22. 2pp. 07362:300.
- --8012309573 LER 80-026/03L-0; on 801126, during engineering review of POT-25-2f, closure of containment hydrogen sample valves KO-5677/5678 was not verified upon receiving containment isolation signal. Caused by drafting error.
 BAIK.0. 0. Portland General Electric Co. 80/12/22, ip. 07362:302.
- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8012020118 Discusses planned mods to emergency notification sys & health physics network NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys. Wo encl health physics network manual. KEPPLER. J. G. Region 3, Chicago, Office of the Director. BO/11/19. 2pp. 07149:001.
- 8012020270 Forwards revised guard training plan & response to NRC 800826 comments re plan.Plan & response withheld (ref 1007R2.790).

 CRGUSE.R.P. Toledo Edison Co. 80/11/24, 1p. 07134:219.
- G. Adjudicatory correspondence
- 8012110334 Requests on behalf of util, extension until 810108 to request hearing re RRC 801118 order for mod to license. Requested extension would allow for better understanding of order requirements.

 SILBERO, J. E. Shaw, Pittman, Potts & Trowbridge. 80/12/05. 2pp. 07224:141.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- B012020784 Responds to 790727 requests that ACRB address consistency of actual component failure experience w/that projected in MASH-1400 & that ACRS determine probabilities of occurrence re Davis-Besse 770924 & Rancho Seco 780320 events. PLESSET.M.S. ACRS Advisory Committee on Reactor Safeguards. 30/02/20. Epp. 07130:348.

- --8012020797 Forwards "Analysis of Feedwater Transient Sequences in B&W MSSS," to aid in formulating response to M Udall 790729 ltr.
 Using WASH-1400 event trees & data directly gives meaningless results.
 ABBOTT,E., BICKEL,J., KASTENJERG,W., ACRS ~ Advisory Committee on Reactor Safeguards. 80/02/07. 1p. 07141:015.
- --8012020804 "Analysis of Feedwater Transient Sequences in B&W NSSS."

 ABBOTT, E. E., BICKEL, J., KASTENBERG, W. E. ACRB Advisory Committee on Reactor Safeguards. 80/02/07. 21pp. 07141:016.
- --8012020B11 "Evaluation of Davis-Besse & Rancho Seco Feedwater Transients on 770924 & 780320 Using WASH-1400 Data." • Commissioners. 80702720. 16pp. 07141:037.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PHRs & describes program NRC is undertaking to review capability of operating PNRs to remove decay heat following parthquake. EISENHUT.D.G. Division of Licensing. 80/10/21. 4pp.
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Farwards NUREC-0737 re TML action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISENHUT.D. Q. Division of Licensing. B0/10/31. 7pp.
- BO12220563 Ltr to all gower reactor licensees forwarding NUREO-0619, "BKR Feedwater No.:le & Control Rod Drive Return Line Nor:le Cracking, " Confirmation that implementation dates will be met must be sent within 49 days.
- B012070047 Requests addl info needed to complete review of B01009 ltr re adequacy of station electric distribution sys voltages. Also requests that info be submitted within 45 days of receipt of ltr. REID.R.W. Operating Reactors Branch 4. 80/11/14. 3pp. 07199:292.
- 8012240093 Forwards Amend 34 to License NPF-3 & notice of issuance & availability.
 REID.R.W. Operating Reactors Branch 4. 80/11/18, 3pp. 07324:294.
- --8012240096 Amand 34 to License NPF-3, modifying Tech Specs to include fire detection instrumentation mods. REID,R W. Operating Reactors Branch 4. BO/11/18. 10pp. 07324: 296.
- --8012240100 Notice of issuance & availability of Amend 34 to License (AFF-3. REID:R.U. Operating Reactors Branch 4. 80/11/18. 2pp. 07324:304.
- 8012180314 Confirms NRC 601117 oral authorization to temporarily amend Tech Spec.Table 4.3-2 by adding that provisions of Section 3.0.3 are not applicable for first test of each channel following first refueling outage NOVAK.T.M. Assistant Director for Operating Reactors. 80/11/20. 1p. 07183:001.
- --8012180318 Discusses emergency Tech Spec change requested & granted on 801117.adding to Table 4.3-2 that provisions of Section 3.0.3 are not applicable for first test of each channel following first refueling outage.

 GARKER.D. J. Operating Reactors Branch 4. 80/11/18. 2pp. 07183:001.
- G012020430 Responds to NRC B00524 ltr re development & installation of instrumentation sys to detect inadequate core cooling. Util B0090B ltr concluded that acceptable instrumentation is installed. Further response will be made by B10101.
 CROUSE, R. P. Taledo Edison Co. B0/11/25. 1p. 07142:086.
- 8012190/09 Confirms 801205 meeting in Toleds, DH to discuss evaluation of regulator performance re facility.

 KEPPLER, J. C. Region 3, Chicago, Office of the Director, 80/11/26, ip. 07273:281.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions Forwards results of IE survey.

 DENTON H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.

- --8012220595 Forwards tabulation & summary of IE survey on tow level caste at 51 reactors.Lou level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012220230 Notification of 801216 meeting w/B&N owners group in Bathesda.MD re resolution programs & schedules of TMI-2 task action plan items.
 THROM.E.D. Reactor Systems Branch. 80/12/09, 2pp.
- 8012240474 Notification of 801216 meeting w/B&W owners group for small break LBCAs in Bethesda.40 for presentation of programs & schedules for resolutions of TMT-2 task action plan items. THROM:E.D. Reactor Systems Branch. 80/12/09. 2pp.
- 8012310406 "Power Plant Siting & Design: Case Study of Minimal Entrainment & Impingement Impacts at Davis-Bosse Nuclear Power Station." HICKEY,C.R. Division of Engineering, NUREG-0720, 80/12/31, 72pp. 07371:013.
- Q. Inspection reports, IE Bulletins & correspondence
- B012040073 Forwards IE Inep Rept 50-346/80-23 on 890714-0815 & notice of violation
 HEIBHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. B0/09/26. 2pp. 07157:398.
- --8012040100 Notice of violation from insp on 800714-0815. 4 Region 3. Chicago, Office of the Director. 80/09/24. 1p. 07158:360.
- --8012040115 IE. Insp. Rept. 50-346/60-23 on 800714-0815. Noncompliance noted: failure to log unit tours by operations engineer & failure to keep records of entry & exit to vital areas. Details withheld (100CR2. 799).

 REVES.L.A., WARNICK.R.F. Region 3. Chicago, Office of the Director. 80/09/24, 15pp. 07158:001.
- 8012170542 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/24, 1p. 07264:274.
- 8012020549 Ack receipt of 801103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/80-26. HIND, J. A. Region 3. Chicago, Safeguards Branch. 80/11/18. 1p. 07130:313.
- --8012020559 Responds to NRC 801009 ltr re-violations noted in 1E Insp Rept 50-344/80-24. Corrective actions withheld (ref-10CFR2. 790). CROUSE.R.P. Toledo Edison Co. 80/11/03. 1p. 07130:314.
- 8012020743 Forwards three Performance Appraisal Branch inspirepts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments U/o encl.

 KEPPLER.J.G. Region 3. Chicago, Diffice of the Director. 80/11/18.
- 8012310478 Forwards 1E Insp Rept 90-345/80-27 on 800922-1010 & 14-17. No noncompliance moted. HEISHK-MI.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 80/11/18. 2pp. 07365:213.
- --8012310492 IE Insp Rept 50-346/80-27 on 800922-1010 & 14-17. No noncompliance noted. Major areas inspected: previous insp findings followup.monthly maint observation & LER followup. REYES.L.A. ROOSRS. M.O., MARKICK, R.F. Region 3. Chicago, Office of the Director. 80/11/10. Spp. 07365:215.
- 8012020587 Ack receipt of 801103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/80-23.

 KEISHMANLR.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 80/11/19. 1p. 07130:322.
- ---B012020594 Responds to NRC BC0926 ltr re violations noted in IE Insp Rept 50-344/B0-23. Corrective actions withheld (ref 10CFR2.790). CROUSE, R. P. Toledo Edison Co. B0/11/03. 19. 07130:323.
- 8012310493 Forwards IE Insp Rept 50-346/80-16 on 800609-11 & 1020-24. No nor-compliance noted. HEISHMAN,R.F., Region 3. Chicago, Reactor Berations Nuclear Support Branch. 80/11/19. 2pp. 07370:227.

- --8012310459 IE Insp Rept 50-346/80-16 on 800609-11 & 1020-24. No noncompliance noted. Major areas inspected: refueling outage caint, plant operations review & equipment calibr. SHANSON, E.R. Of ELDNER, M.L., BAKER, M.R. Region 3, Chicago, Diffice of the Director. 80/11/18. 3pp. 07370:229.
- 8012040656 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 80/11/21. 2pp. 07166:332.
- 8012080074 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Enubber Fluid." No written response required. **KEPPLCR.J.O. Region 3: Chicago, Office of the Director. 80/11/24. 2pp. 07182:233.
- B01222059: Forwards new security badge numbers & clearance levels for Region 3 personnel.Changes should be entered on Sept 1980 lists.

 KEPPLER, J. C. Region 3, Chicago, Office of the Director. B0/11/25.6bb. 07308:352.
- 80/2310559 Forwards revised response to IE Bulletin 80-06 re engineered safety feature reset controls. Reset alone will not automatically remove any component from required safety position.

 CROUSE.R.P. Toledo Edison Co. 80/11/25: 5pp. 07366:024.
- 8012170525 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER, J. G. Region 3, Chicago. Office of the Director. 80/11/26. 2pp. 07268: 120.
- E012310422 Forwards resubmittal of response to IE Bulletin 80-15, "Possible Loss of Emergency Natification Sys (EMS) w/Loss of Offsite Power," w/signature under oath as required. Revision to Special Order 22 was issued detailing use of phones. CRGUSE.R.P. Toledo Edison Co. 80/12/08. App. 07369:247.
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-018 re environ qualification of Class IE equipment. HAYES.D.W. Region 3: Chicago, Reactor Construction & Engineering Support Branch. E0/12/09. 2pp.
- R. Periodic operating reports & related correspondence
- 8012130353 Forwards monthly operating rept for Nov 1980. MURRAY, T. D. Toledo Edison Co. 80/12/08. ip. 07237:251.
- --8012150053 Monthly operating rept for Nov 1980. SARSOUR.B. Foledo Edison Co. 80/12/08. 6pp. 07237:252.
- S. Reportable occurrences, LERs & related correspondence
- E012020525 Forwards LER 80-078/03L-0. MURRAY.T.D. Toledo Edison Co. 80/11/26. ip. 07130:301.
- --8012020533 LER 80-078/03L-0: on 801027, reactor protection sqs channel 1 tripped on shutdown/bypars high pressure trip. Caused by loose solder connection in lead from pressure detector element & loose lock nut. Connection repaired.

 WERNER, J. Toledo Edison Co. 80/11/26. 3pp. 07130:302.
- 8012040385 Forwards LER BO-079/01T-0. MURRAY, T. D. Toledo Edison Co. 80/12/01, 1p. 07169: 133.
- --B012040389 LER B0-079/01T-O. on 801117.NRC resident inspector notified facility that Tech Spec requiring pressure to be applied to containment pressure transmitters during monthly test was not met. Causad by procedure deficiency. WERNER, J. Toledo Edison Co. 80/12/Ol. 2pp. 07169:134.
- 80(2)20490 Forwards LER 80-053/01T-1. NURRAY-T. D. Toledo Edison Co. 80/12/01. 1p. 07236:032.
- --8012170496 LER 80-053/OfT-1: on 800709, logic modules on sequencer steps 2-5 tripped before being blocked by sequencer. Caused by design deficiency. Design of controls has been modified. IBLEY, T. Toledo Edison Co. 80/07/22. 3pp. 07236: 033.
- 8012120501 Forwards LER 80-064/03L-1. MURRAY, T. B. Toledo Edison Co. 80/12/01. 19. 07234:036.

- --8012120512 LER 80-064/03L-1: on 800822, station experienced loss of essential instrument ac panel Y2. Caused by failure of YV-2 inverter input fuse & other undetermined causes. Failed fuse replaced.
 ISLEY.T. Toledo Edison Co. 80/09/18. 3pp. 07236:037.
- B012120514 Supplements LER 80-058 re loss of decay heat flow. Caused by personnel error & procedural inadequacy. Tech Specs were revised to eliminate requirement for maintaining power on valves DH11 & DH12.
 MURRAY, T. D. Toledo Edison Co. 80/12/01. 3pp. 07236:294.
- 8012170536 Supplemental info re RO NP-32-80-12 on 800724 w/unit in Mode 5, loss of decay heat flow observed. No indication for valve position of decay heat isolation valve DH12. Revision replaces supplemental info for RO 80-058.
 MURRAY, T. D. Toledo Edison Co. 80/12/01. 4pp. 07266:284.
- 8012090380 Forwards LER 80~080/03L-0.
 MURRAY, T. D. Toledo Edison Co. 80/12/02. ip. 07200:001.
- --8012090387 LER 80-080/03L-0:on 801103, during testing control rod drive trip breaker C did not trip. Cause could not be determined. Breaker was manually put in tripped position within 5 minutes of failure. RUDDLPH, J. Tolede Edison Co. 80/12/02. 2pp. 07200:002.
- 8012180136 Advises that 791107 response to NRC 790921 ltr re inadvertent safety injection during surveillance testing adequately addresses concerns Issue considered closed. REID.R.M. Operating Reactors Branch 4. 80/12/02. 2pg. 07272:282.
- 9012150116 Forwards LER 80-081/03L-0.
 MURRAY, T. D. Foledo Edison Co. 80/12/10. ip. 07240:327.
- 80:2150168 Forwards LER 80-082/03L-0. MURRAY, T. D. Toledo Edison Co. 80/12/11. 1p. 07240:025.
- --801215017; LER 80-082/03L-0: an 80111; & 1203, control room operator noticed simultaneous open & closed indication for main steam isolation warmup valve MS100-1. Caused by mechanical binding of valve. Stem cleaned, lubricated & packing loosened. D'HETLL, J. 9 STOTI, J. Toledo Edison Co. 80/12/11. 3pp. 07240: 026.
- 8012220446 Forwards LER 80-083/93L-0. MURRAY, T. D. Toledo Edison Co. 80/12/15. tp. 07307:360.
- --8012220451 LER 80-083/03L-0:on 801116, feedwater swing caused steam generator 1-1 level to exceed Tech Spec limits. Caused by bad relay in integrated control sys. Relay 86/MBV-8 replaced. Relay 33X charged on 801206.

 WHITESELL, B. Toledo Edison Co. 80/12/15. 2pp. 07307:361.
- B012310319 Forwards LER 80~084/03L~0.
 MURRAY, T. D. Toledo Edison Co. 80/12/26. 1p. 07369:045.
- --8012310337 LER 80-084/03L-0:on 801128; switch PGL107D would not reset after actuating on low steam pressure & auxiliary feedwater sys declared inoperable.Caused by defective actuation switch & actuator in PSL107D, Parts replaced.
 TRAUFMAND. Toledo Edison Co. 80/12/26. 2pp. 07369:046.
- 8012310321 Forwards LER 90-085/031-0. MURRAY.T.D. Toledo Edison Co. 80/12/26. 1p. 07369:051.
- --8012310328 LER 80-085/03L-0: on 801128 borated water storage tank low level bistable tripped. Apparently caused by loose connection at borated water storage tank level transmitter, Lead tightened.

 fBLEY-T. Toledo Edison Co. 80/12/26. 2pp. 07369:052.
- DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1
 F. Security, medical, emergency & fire protection plans

TO THE WAR TO SERVICE THE PARTY OF THE PARTY

800103044B Forwards upgraded emergency plan in response to NRC 791010 request.

CLAYTON: F. L. Alabama Power Co. 79/12/28. 1p. 01678:064.

- --8001030454 Facility emergency plan. Revision 3.
 4 Alabama Power Co. 79/12/31. 600pp.
- BO12080753 Informs of interim 102FR50.48 suspending completion dates for previously approved fire protection mods. Revised 102FR50.48 will contain schedules for completion of all protection mods. EISEKHUT, D. G. Division of Licensing. BO/11/17. 5pp. 07196:146.
- 8012110515 Forwards emergency planning info for placement in LPDR.W/o encl. SOUDER.J.L. Division of Rules and Records. 80/12/02. 1p. 07226:150.
- 8012070107 Releases public version of util emergency plan. FELTON, J. M. Division of Rules and Records. 80/12/08, 1p 07204:133.
- --B012090113 Forwards public version of util emergency plan, Revision 4.
 Includes States of FL & QA plans & QA county plans.
 CLAYION, F. L. Alabama Power Co. 80/10/28. 11pp. 07204:135.
- --8012090118 Public version of Revision 4 to emergency plan.

 -- Alabama Power Co. 80/10/28. 400pp. 07204:145.
- --8012090119 Public version of Revision 1 to State of GA radiological emergency operations plan. # Georgia, State of. 80/10/28. 400pp. 07205:038.
- --8012070125 Public version of State of GA,Blakely-Early County civil defense emergency operations plan Oreat Southern Paper Co emergency disaster plan encl.

 4. * Affiliation Unknown. 80/06/30. 200pp. 07206:008.
- --8012070130 Public version of Revision 2 of State of FL radiological emergency plan for fixed nuclear facilities.

 4 Florida, State of. 79/04/30. 250pp. 07204:109.
- 8012230594 Responds to NRC 801105 position re alternate hot shutdown capability. Mods will be performed re fire protection safe shutdown capability, emergency lighting & oil collection sys for reactor coolant pump.

 CLAYTON, F. L. Alabama Power Co. 80/12/08. 2pp. 07312:315.
- BO12230476 Forwards addl info to 801028 ltr re prompt notification sysmeterological criteria for emergency preparedness at operating nuclear plants & clarification of min staffing requirements.

 CLAYTON, F. L. Alabama Power Co. 80/12/16. App. 07312:295.
- P. Operating license stage documents & correspondence
- BO12020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PWRs & describes program NRC is undertaking to review capability of operating PWRs to remove decay heat following earthquake. EISENMUT, D. Q. Division of Licensing. 80/10/21. 4pp. 06916:001.
- 8012160050 Ltr to operating plant licensees, DL applicants & CP holders. Forwards NVREQ-0737 re TMI action plan requirements, Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT, D. O. Division of Licensing. 80/10/31. 7pp. 07250:080.
- 8012220563 Ltr to all power reactor licensees forwarding NUREO-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days.
- 8012100424 Provides commitment to implementation of mods to auxiliary feedwater initiation in response to NRC 801105 ltr.Unit operating procedures will be revised. CLAYTON F. L. Alabama Power Co. 80/12/04. 2pp. 07219:036.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220806 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity, SANSARTIR.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.

- 8012230461 Responds to 801105 ltr re alternate hot shutdown capability. Results of design evaluation to meet 10CFR50 App R requirements will be provided for review & concurrence. CLAYTON F. L. Alabama Power Co. 80/12/05. ip. 07312-28t.
- 8012170484 Supersedes 801126 response to NRC 801031 request for clarification re NUREO-0737 TMI action plan requirements. Util util submit Tech Specs by 801211 & remaining items by 810105.
 CLAYTON, F. L. Arkansas Fower & Light Co. 80/12/09. ip. 07270:292.
- 8012310370 Proposed amend to License MPF-2 to incorporate administrative changes required by NUREY-0737. Forwards Tech Spec changes & Class III amend fees. CLAYTON, F. L. Alabama Power Co. 80/12/15. 2pp. 07369: 091.
- --8012310395 Proposed Tech Spec changes to Sections 3.0,4.0 % 6.0, incorporating administrative changes required by NUREG-0737. Supporting safety evaluation encl. + Alabama Power Co. 80/12/15 61pp. 07349:093.
- G. Inspection reports: IE Bulletins & correspondence
- 8012360031 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Savity Flooding At Indian Point Unit 2." No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/10/24. ip. 07262:184.
- 8012170279 Forwards Suppl 3 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment." No written response required.

 D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 60/10/24.
- B012170B33 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, P. Region 2, Atlanta, Office of the Director. B0/10/30. 1p. 0/266:261.
- 8012180017 Forwards IE Info Notice 80-39, "Malfunction of Bolenoid Valves Mfg by Valcor Engineering Corp." No written response is required. G'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/31. ip. 03790:124.
- 8012230077 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31. ip. 07313:249.
- 8012110614 Forwards IE Insp Repts 50-349/80-29 & 50-364/80-41 on 800901-30. No nancompliance noted.
 LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/11/03. 2pp. 07226:177.
- --8012110620 IE Insp Repts 50-349/80-27 & 50-364/80-41 on 800901-30. No noncompliance noted. Major areas inspected: plant tours, preoperational testing. Unit 2 plant testing status & Unit 1 plant operations.

 BRADFORD. N. H. MULKEY, J. P. Region 2. Atlanta, Office of the Director. MARTIN.R. D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/10/31. 11pp. 07226:179.
- 8012110745 Forwards IE Builetin 80-21, "Valve Yokes Supplied by Halcolm Foundry Co. Inc." Hritten response required.
 O'REILLY.J.P. Region 2. Atlanta: Office of the Director. 80/11/06.
 19. 0/225:203.
- 8012030830 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p. 07150:077.
- 8012080212 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/11/10, 1p. 07182:270.
- 8012040706 Forwards IE Bulletin 80-23, "Failures of Sciencid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLYJ.P. Region 2. Atlanta, O'ffice of the Director. 80/11/14. 1p. 07158:12).

- 2012190708 Forwards IE Insp Rept 50-348/80-28 on 800916-19.No noncompliance noted. LEMIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. B0/11/14. 2pp. 07286:179.
- --8012190711 IE Insp Rept 50-348/80-20 on 800916-19 No nancompliance noted Major areas inspected : certrifugal charging/safety injection pumps mfg by Pacific Pump Div of Dresser Industries.
 FOSTER, L. E. . SHAFER, M. D. Region 2. Atlanta. Office of the Director. 80/11/14. 9pp. 07826:181
- E012110207 Advises that referral in B01031 cover 1tr to IE Insp Repts 50-348/50-34 & 50-368/50-40 should be corrected to 50-348/B0-34 & 50-364/E0-40.

 STGHR, J. P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/11/18. ip. 07223:174.
- --8012110213 Foruards IE Insp Repts 50-348/50-34 & 50-364/50-40 on 801096-10 No nancompliance noted.
 STOPR, J. P. Region 2: Atlanta: Fuel Facility & Materials Safety Branch. 80/10/31. 2pp. 07223:076.
- --8012110222 IE Insp Repts 50-349/80-34 & 50-364/80-40 on 801006-10.No noncompliance noted. Major areas inspected: emergency planning, coordination \(\psi / \text{off} \) its support groups & emergency facilities equipment \(\text{procedures} \). PEROTTI. D. J. \(\text{JENKINS, G. R. Region 2- Atlanta, Office of the Director. \(\text{SO}/10/30. \) 10pp. \(\text{O7223:178} \).
- 8012110371 Provides info re health physics appraisal beginning B01201. List of NHC personnel & contractors requiring access to protected areas entl. D'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/11/19. 3pp. 07224:147.
- 8012040472 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Unitten response required Requests info on manpower expended. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/21. tp. 07163:322.
- 8012050614 Forwards Info Notice 80-42. "Effect of Radiation on Mydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/24. 1p. 07174:107.
- 8012170400 Forwards IE Info Notice 80-29. Suppl 1: "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY.J.P. Region 2: Atlanta. Office of the Director. 80/11/26. 1p. 07269:108.
- 8012180595 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co,inc." No valve parts cast by Malcolm Foundry have been used at facilities.
 CLAYTON, F.L. Alabama Power Co. 80/12/03. 1p. 07271: 359.
- 8012180511 Responds to IE Bulletin 80-23, "Failures of Bölenoid Valves Mig by Valcor Engineering Corp." No Valcor valves used in safety-related functions at facilities.

 CLAYTON, F. L. Alabama Power Co. 80/12/03, ip. 07271:347.
- R. Periodic operating reports & related correspondence
- 6012160403 Forwards monthly operating rept for Nov 1980. CLAYTON:F.L. Alabama Power Co. 80/12/10, 1p. 07252:342.
- --B012160406 Monthly operating rept for Nov 1980. HAIRSTON, W. G. Alabama Power Co. B0/12/01. 5pp. 07252:343.
- S. Reportable occurrences, LERs & related correspondence
- 8512100516 Forwards LERs 80-038/03L-0 & LER 80-039/03L-0. LER 80-039/03L-0 not encl. CLAYTON.F. L. Alabama Power Co. 80/08/08. 1p. 07218:117.
- --8012100520 LER 80-038/03L-0 on 800712, bistable associated w/pressurizer pressure transmitter 457 failed to meet low pressure trip setpoint requirements b one pressure channel declared inoperable. Caused by dirty electric contacts.
 4 Alabama Power Co. 80/08/08. 1p. 07218:118.
- 8012010348 Forwards LER 80-065/03L-0. CLAYTON F. L. Alabama Power Co. 80/11/24. 1p. 07092:163.

- --8012010367 LER 80-065/03L-0:on 801022, total controlled leakage during reactor coolant pump seal controlled leakage test, FNP-1-ETP-8. O, exceeded Tech Spec limit. Caused by failure to verify total flow after adjustment. Operating procedure changed. HAIRSTON, W. G. Alabama Power Co. 80/11/24. 1p. 07092:164.
- B012020545 Forwards LERs 80-069/01T-0,80-066/03L-0,80-068/03L-0,80-070/03L-0,80-071/03L-0, 80-072/03L-0, CLAYION,F.L. Alabama Power Co. 80/11/26, 1p. 07143:277.
- --8012000559 LER 80-069/01T-0: on 801112, water for lubrication & cooling of A train svc water pumps found to be provided by B train water header & vice versa Caused by design error. Design change to provide correct separation completed.

 HAIRSTON, K. G. Alebama Power Co. 80/11/26. 2pp. 07143:278.
- --8012020556 LER 80-066/03L-D; on 801026, containment atmosphere particulate & gaseous radioactivity monitoring sys (RLI & R12) declared inoperable. Caused by clugged filter paper from stuck filter paper takeup reel causing pump low flow trips. H41RSTON M. G. Alabama Power Co. 80/11/26. 1p. 07143:280.
- --8012020574 LER 80-068/03L-0: on 801031.8 train river water pumps declared inoperable due to inadequate lube & cooling water flow. Caused by dirty strainers. Strainers blown down & cleaned.

 HAFRSTON, H. G. Alabama Power Co. 80/11/26. 1p. 07143: 281.
- --8012920585 LER 80-070/O3L-0: on 801028; svc water bldg train A battery sys declared inoperable due to low cell specific gravity. Caused by close terminal proximity & poor post seal design allowing formation of acid residue which shunted current. HAIRSTON, W. G. Alabama Power Co. 80/11/26. 2pp. 07143: 282.
- --8012020595 LER 80-071/03L-0: on 801027 & 28, containment atmosphere particuolate & gaseous radioactivity monitoring sys (R11 & R12) declared inoperable due to low flow pump trips. Caused by failing bearings & partially opened isolation valve. HAIRSTON, W. G. Alabama Power Co. 80/11/26, 2pp. 07143:284.
- ~-8012020601 LER 80-072/03L-0: on 801031, river water train B declared inoperable when pump 5 tripped & would not restart. Caused by breaker HEA 86 lockout relay & 500 instantaneous overcurrent relay actuation.

 HAIRSTON, M. G. Alabama Power Co. 80/11/26. 1p. 07143: 286,
- 8012100919 Forwards LER 60-073/01T-0. CLAYTON,F. L. Alabama Power Co. 80/12/04, 1p. 07219:350.
- --8012190526 LER 80-073/01T-0: on 801126, during insp of MBIVs, damage to valve disc bolt holes & disc arm bolting on three valves was revealed. Caused by design deficiency & inadequate locking devices on bolting. Discs will be repaired or replaced. HAIRSTON.W. G. Alabama Power Co. 80/12/04. 2pp. 07219:351.
- 8012160345 Forwards LER 80-074/03L-0. CLAYTON.F.L. Alabama Power Co. 80/12/09. ip. 07252;331.
- --8012160351 LER 80-074/03L-0: an 801109, found pump 1B running & 1A & 1C breakers racked in m/RCS cold leg temp less than 180 F. Caused by procedural deficiency. Charging pump breakers 1A & 1C racked out & procedure change made.

 4 Alabama Power Co. 80/12/09. 1p. 07252:332.
- 80i2300627 Amends commitment in LER 79-0i7/0iT to allow automatic rod control during any rapid load reduction event. Probability is extremely low that multiple red drop event will occur w/o reactor trip concurrent w/rapid load reduction event. CLAYTON, F. L. Alabama Power Co. 80/12/12, 2pp. 07357:242.
- B012300533 Forwards LER 80-075/03L-0. CLAYTON; F. L. Alabama Power Co. B0/12/22. 1p. 07361:334.
- ~-8012390539 LER 80-075/03L-0: on 801121, charging pump aligned for operation found to be lacking smergency power source. Caused by personnel error in performing nod on svc water sys. Potential consequences to be discussed.

 HAIRSTON, W. G. Alabama Power Co. 80/12/22. ip. 07361: 335.
- 8012300523 Forwards LER 80-076/01T-0. CLAYTON,F.L. Alabama Power Co. 80/12/23. 1p. 07361:328.
- --8012303530 LER 80-076/01T-0:on 801209, wall sampling tests revealed unission of vertical reinforcing &/or accompanying grout. Caused by const activities not performed in accordance w/design drawings. Block walls to be tested.

 HAIRBTON, W. G. Alabama Power Co. 80/12/23. 2pp. 07361:329.

V. Operator Examinations

× ...

- 8012230476 Forwards addl info to 801028 ltr re prompt notification sys, meterological criteria for emergency preparedness at apperating nuclear plants & clarification of min staffing requirements.

 CLAYTON, F. L. Alabama Power Co. 80/12/16. 6pp. 07312:295.
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

 A. Application/construction stage documents & correspondence
- GO12160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISERHUT.D.G. Division of Licensing. 80/10/31, 7pp.
- BO12220358 Ltr to all CP & OL holders for BURs re requirement for implementation of ODYN code for licansing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISERHUT.D.G. Division of Licensing, 80/11/04, 4pp.
- B012020165 Notification of 801207 meeting w/applicant in Pottstown. PA to receive verbal presentation of results of util risk evaluation study. Agenda encl. SELLS.D. Licensing Branch 2. 80/11/14. 4pp. 07148:197.
- B012010-004 Forwards Suppl 1 to NUREO-0487, "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria..." Deviations: along w/bases for deviations, are to be documented in design assessment rept during FSAR review. VOUNCE: COD. B. J. Licensing Branch 1. 80/11/17. 2pp. 07098:009.
- 8012020471 Notifies of plan to perform tests on 801213-14 to quantify assumptions re determination of loads on adjacent structures due to bydrodynamic loads in containment.
 VOLLMER, H. W. Philadelphia Electric Co. 80/11/25, ip. 07142:088.
- 8012080424 Forwards info re scheduled environ qualification testing, in response to 801001 ltr.
 KEMPER.J.S. Philadelphia Electric Co. 80/12/01. 3pp. 07183:055.
- 8012160150 Notification of B01210 meeting w/Mark II owners group in Bethasda, MD to discuss status of improved chugging load program.

 ANDERBUN.C. Generic Issues Branch. 80/12/02. ip. 07263:029.
- 8012100493 Advises that ECCS analysis can not be firmly established since GE has not been required under NRC direction to davelop model changes suggested by NCREG-0630.
 KEHPER, J. S. Philadelphia Electric Co. 80/12/04. 2pp. 07220:041.
- 8012140032 Notification of 801212 meeting w/Mark II owners group in Bethasda,MD to discuss suppression pool temp linit. SU,T.M. Generic Issues Branch. 80/12/05. 1p. 07263:021.
- B012300549 Forwards info supporting preliminary risk assessment & visuagraphs from 801209 presentation. Supporting info not anci. LOOUE, R. H. Philadeiphia Electric Co. 80/12/11. 1p. 07346: 261.
- D. HRC Draft/Final Environmental Statements, suppls & correspondence
- 80:2220375 Requests confirmation that NRC plans to prepare EIS on GL aspect of facility as soon as possible DE River Basin Commission intends to act on Point Pleasant pumping station project within near future.

 HANGLER.G.M. New Jersey. State of. 80/12/15. 1p. 07304:141.
- F. Becurity, medical, emergency & fire protection plans
- B012040145 Public version of "Independent Assessment of Evacuation Times for Limerick Nuclear Power Plant," Vol 5, prepared for FEMA. COBBY. J. C., SHEPPARD. W. V., COULTER. G. S. Wilbur Smith & Associatos. B0/06/30. 68pp. 07161:070.
- BO12040065 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Flants Emergency Planning Zones," executive summary. FELTON, J.H. Division of Rules and Records. 80/12/03. 1p.

- --8012040063 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Energency Planning Zones," executive success, prepared for FEMA. 4 Nilbur Smith & Associates. 80/06/30. 17pp.
- --8012040155 Public version of program rept. "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Iones." Vol l. prepared for FEMA.
 CDSBY.J. C. Wilbur Smith & Associates. 80/06/30. 43pp.

G. Adjudicatory correspondence

- 8012140144 Forwards SEC Form 10-0 Quarterly Financial Rept & supporting mpt comments in response to NRC 790721:1107 & 800811 requests for info re significant financial developments affecting utils in restart proceeding. COHODA: V. H. General Public Utilities. 80/11/26. 3pp.
- --B012160154 Quarterly Financial Rept Sept 1980 & supporting mgt comments. * General Public Utilities. 80/11/14. 44pp.
- 8012290444 Submits questions arising from preliminary risk analysis hearing in Pottstown.PA Util should incorporate possible lowered concrete strength into probabilistic risk analysis. LEWIS.M. I. Affiliation Unknown. 80/12/19. 3pp. 07308:001.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012230034 Forwards IE Insp Repts 50-352/80-i8 & 50-353/80-i4 on 800918.19.22-24.No noncompliance noted. CARLEGUAR.I. Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/15. 2pp. 07311:223.
- --B012230041 IE Insp Repts 50-332/80-18 & 50-353/80-16 on B00918,19, 22-24. No noncompliance noted Major areas inspected: work activities & records associated w/OE OA program. GAGE.L. Region 1, Philadelphia, Office of the Director. EDNETER.S D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/07. 6pp. 07311:225.
- 8012120184 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. GRIER.B.H. Region 1, Philadelphia. Office of the Director. 80/11/06 1p. 07228:312.
- 8012030805 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization "No written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/97. p. 07150:248.
- E012080493 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besso Unit 1." No response required. GRIER, B.H. Region 1. Philadelphia. Office of the Director. 80/11/10. 1p. 07182:348.
- B012040033 Forwards IE Bulletin B0-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, B.H. Region 1, Philadelphia, Office of the Director. B0/11/14. 1p. 07169:332.
- 8012080581 Requests addl info re piping 2 instrumentation diagrams for review of application re inservice insplot pressure isolation valves.Conformance to encl Mechanical Engineering Branch position should be discussed. TEOEECO.R.L. Assistant Director for Licensing. 80/11/17. App. 07188:200.
- 8012220660 Advises that written response is required to IE Bulletin 80-23. "Failures of Solenoid Valves Kfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/19. ip. 07294:223
- 8012040625 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment," No written response required. GRIER, B. H. Region (, Philadelphia, Office of the Director. 80/11/21, 2pp. 07165:312.
- 8012090585 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 80/11/24. 1p. 07174:089.

S. Reportable occurrences, LERs & related correspondence

- B012310454 Part 21 rept re emergency diesel generators Model 38TD8-1/8, first reported B00116. Insp & mod completed. Units now free of potential defect.

 MGRIARTY, J. M. Colt Industries, Inc. 80/12/04. 2pp. 07308:001.
- 8012240039 Part 21 rept re reactor protection sys flexible conduit defect causing hat shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel survaces where termination modules are mounted. SHERNOAD, 0.0. General Electric Co. 80/12/08. 3pp. 07324:291.
- 8012300527 Final deficiency rept, originally reported by 801819 telcon, re violations of separation criteria in power generation control camples. Final separation insp will be documented for each panel containing safety-related components. KEMPER, J. S. Philadelphia Electric Co. 80/12/17. 5pp. 07357:338.

COCKET 50-353 LIMERICK GENERATING STATION, UNIT 2 A. Application/construction stage documents & correspondence

- B012140950 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TM1 action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISERRAUT.D.O. Division of Licensing. 80/10/31. 7pg.
- 8012220358 Ltr to all CP & GL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISENRUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012020165 Notification of 801209 meeting w/applicant in Pottstown, PA to receive verbal presentation of results of util risk evaluation study, Agenda enci. SELLS-D. Licensing Branch 2. 80/11/14. 4pp. 07148; 197.
- 8012010006 Forwards Suppl 1 to NUREO-0487, "Mary II Containment Lead Plant Program Load Evaluation & Acceptance Criteria..."
 Deviations along w/bases for deviations are to be documented in design assessment rept during FSAR review.
 YOUNOBLOOD, B. J. Licensing Branch 1. 80/11/17. 2pp. 07098:009.
- 80i2020471 Notifies of plan to perform tests on 80i213-i4 to quantify assumptions to determination of loads on adjacent structures due to hydrodynamic loads in containment.

 VOLLMER, H. W. Philadelphia Electric Co. 80/11/25. 1p. 07i42:088.
- B012080424 Forwards info re scheduled environ qualification testing, in response to B01001 ltr. KEMPER, J. B. Philadelphia Electric Co. B0/12/01, 3pp. 07183:055.
- B012160150 Notification of 801210 meeting w/Mark II cuners group in Bethesda.MD to discuss status of improved chugging load program. ANDERSON.C. Generic Issues Branch. 80/12/02. 1p.
- B012100493 Advises that ECCB analysis can not be firmly established since GE has not been required under NRC direction to develop model changes suggested by NUREO-0630. XEMPER.J.S. Philadelphia Electric Co. 80/12/04. 2pp. 07220:041.
- B012160/32 Notification of B01212 meeting w/Mark II owners group in Bethasda MD to discuss suppression pool temp limit. SU.T.M. Generic Essues Branch. 80/12/05. lp.
- 8012300549 Forwards info supporting preliminary rist assessment & viewgraphs from 801209 presentation Supporting info not enci. LOCUE.R.H. Philadelphia Electric Co. 80/12/11. 1p. 07346:261.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 8012220075 Requests confirmation that NRC plans to prepare EIS on QL aspect of facility as soon as possible. DE River Basin Commission intends to act on Point Pirasant pumping station project within near future.

 HANGLER, C. K. New Jersey. State of. 80/12/15. 1p. 07304:141.

F. Security, medical, emergency & fire protection plans

- 9012040145 Public version of "Independent Assessment of Evacuation Times for Limerick Nuclear Power Plant." Vol 5,prepared for FEMA. COSBY, J. C. i SHEPPARD, W. V. , COULTER, O. S. Wilbur Smith & Associates, 80/06/30. 68pp. 07161-070.
- B012040065 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary.

 FELTON, J. M. Division of Rules and Records. B0/12/09. ip.
- --8012040088 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEMA. 4 Wilbur Smith & Associates. 80/06/30. 17pp.
- --8012040155 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol I. prepared for FEMA.
 CD89Y, J. C. Wilbur Smith & Associates. 80/06/30. 43pp.

Q. Adjudicatory correspondence

- 8012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting mgt comments, in response to NRC 770921, 1109 & 800811 requests for info re significant financial developments affecting utils in restart proceeding. CONDON, V. M. General Public Utilities. 80/11/26. 3pp.
- --8012160154 Quarterly Financial Rept Sept 1780 & supporting mgt comments. * Genaral Public Utilities, 80/11/14, 44pp.
- 8012290444 Submits questions arising from preliminary risk analysis hearing in Pottsbum.PA Util should incorporate possible lowered concrete strength into probabilistic risk analysis. LEWIS.M. I. Affiliation Unknown. 80/12/19. 3pp. 07308:001.

Q. Inspection reports, IE Bulletins & correspondence

- 8012230034 Forwards IE Insp Repts 50-352/80-18 & 50-353/80-16 on 800718.17.22-24. No noncompliance noted. CARLSUN.R.T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/15. 2pp. 07311:223.
- -8012230041 IE Insp Repts 50-352/80-18 & 50-353/80-16 on 800918,19, 22-24. No noncompliance noted, Major areas inspected:work activities & records associated w/OE GA program. GAGE.L. Region 1. Philadelphia, Office of the Director. ERNETER, S. D. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/07. 4pp. 07311:225.
- 8012120184 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Helcolm Foundry Co. Inc." Written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director, 80/11/06. 1p. 07228:312.
- 8012030805 Forwards 1E Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization." No written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director, 80/11/97. 1p. 07150:248.
- 8012/80493 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit i." No response required. GRIER, B. H. Region I, Philadelphia, Office of the Director. 80/11/10. 1p. 07182:348.
- BD12040035 Forwards IE Bulletin 80-23, "Failures of Golenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B. H. Region 1. Philadelphia, Office of the Director. 80/11/14. 1p. 07169:332.
- 8012080581 Requests add1 info re piping & instrumentation diagrams for review of application re inservice insp of pressure isolation valves. Conformance to encl Mechanical Engineering Branch position should be discussed. TEDESCO. R. L. Assistant Director for Licensing. 80/11/17. 4pp. 07188:200.

- 8012220660 Advises that written response is required to IE Bulletin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER B.H. Region 1. Philadelphia. Office of the Director. 80/11/19. 1p. 07294:223.
- 8012040629 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Maker Leakage Inside Containment." No written response required. GRIER, B.H. Region i, Philadelphia, Office of the Director. 80/11/21. 2pp. 07165:312.
- 8012050989 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER.B.H. Region 1, Philadelphia. Office of the Director. 80/11/24. 1p. 07174:009.
- S. Reportable occurrences, LERs & related correspondence
- 8012310454 Part 21 rept re emergency diesel generators Model 38TD8-1/B, first reported 800116. Insp & mod completed Units now free of potential defect.
 MORIARTY, J. M. Colt Industries, Inc. 80/12/04. 2pp. 07308:001.
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel survaces where tormination modules are mounted.
 BHERNOOD, G. G. General Electric Co. 80/12/08 3pp. 07324:291.
- 8012300527 Final deficiency reptroriginally reported by 801119 telcon, re violations of separation criteria in power generation control complex. Final separation insp will be documented for each panel containing safety-related components.

 KEMPER, J. B. Philadelphia Electric Co. 80/12/17. 5pp. 07357:338.
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EIBERSHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. O. Division of Licensing. 80/11/04. 4pp.
- 8012240282 Forwards info re environ qualification test program for preselected equipment, in response to NRC 801001 request. Includes listing of equipment type, manufacturer, location in plant.test location & test schedule.
 MITTL-R.L. Public Service Electric & Gas Co. of New Jersey. 80/12/15. 3pp. 07324:344.
- O. Adjudicatory correspondence
- 8012190545 Notice of reconstitution of ASLAB.RS Saliman appointed chairman & WR Johnson & CN Kohl members. BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. B0/12/05. lp. 07288:128.
- 8012290196 Notice of reconstitution of ASLAB.R8 Saltzman, chairman, WR Johnson & TS Moore, members. BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 80/12/18. 1p. 07344:182.
- Q. Inspection reports, IE Bulletins & correspondence
- B012120190 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Faundry Co.Inc." Written response required. CRIER.B.H. Region 1, Philadelphia, Office of the Director. B0/11/06 ip. 07228:396.
- 8012030804 Forwards LE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ORIER, 8.H. Region i, Philadelphia, Office of the Director. 80/11/07. 1p. 07150:244.

- 8012030237 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER, B.H. Region i. Philadelphia. Office of the Director. 80/11/10. 1p. 07182:276
- 8012040090 Forwards 1E Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/14. 1p. 07157:348.
- 8012310674 Submits addl response to IE Bulletin 80-16. "Potential Misapplication of Rosemount. Inc Models 1151 & 1152 Pressure Transmitters w/Either A or D Output Codes." Tuo suppliers indicate no problems exist re transmitter. MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 80/11/14. 1p. 07370: G26.
- 8012310636 Submits add1 response to IE Bulletin BO-20, "Failures of Westinghouse Type N-2 Spring Return to Neutral Control Switches." Bechtel has received response indicating no problem u/five contracts.
 MARTIN.T.J. Public Service Electric & Gas Co. of Neu Jersey.
 80/11/14. 1p. 07370:027.
- 8012270661 Advises that written response is required to 1E Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Enginaering Corp." First paragraph erroneously stated no written response required.
 GRIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/19. 1p. 07274:224.
- 801204062B Forwards IF Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. ORISER.D.H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07165:318.
- 8012050593 Forwards Info Nutice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. BO/11/24, ip. 07174:083.
- S. Reportable occurrences. LERs & related correspondence
- 8012230492 Interim deficiency rept re two pieces of carbon steel pipe found to be lacking radiography of longitudinal weld seam. Investigation expected to be completed 810123 instead of 801209.

 MARTIR: T.J. Public Service Electric & Gas Go. of New Jersey. 80/12/10. 2pp. 07318:327.
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8012160050 Ltr.to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates uill be ret. EISENMUT.D. 0. Division of Licensing. 80/10/31. 7pp.
- 801222039B Ltr to all CP & OL holders for BMRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.
 EISEMHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 80(2240282 Forwards info re environ qualification test program for preselected equipment in response to NRC 801001 request. Includes listing of equipment type manufacturer, location in plant, test location & test schedule.

 MITTL.R.L. Public Service Electric & Oas Co. of New Jersey.
 80/12/15 3pp. 07324:344
- G. Adjudicatory correspondence
- 8012190545 Notice of reconstitution of ASLAB.RS Saliman appointed chairman & RR Johnson & CN Kohl members.
 BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. BO/12/05.
 1p. 0728B:128.
- 8012290196 Notice of reconstitution of ASLAB.RS Saltzman, chairman, MR Johnson & TS Moore, mambers.
 BIGHOP,C, J. Atomic Safety and Licensing Appeal Panel. B0/12/18.
 1p. 07344:182.

- P Operating license stage documents & correspondence
- 8012270521 Forwards Revision 3 to QA manual. UHRIG:R E. Florida Power & Light Co. 80/12/17, 1p. 07344:007.
- --8012270326 Revision 3 to QA manual. 4 Florida Pauer & Light Co. 80/09/30. 69pp. 07346:008.
- G inspection reports. If Bulletins & correspondence
- 8012120190 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER, B.H. Region I, Philadelphia, Office of the Director. 80/11/06 1p. 07228 306.
- 8012030804 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Gause Reactor Depressurization" No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 60/11/07. 1p. 07150.244.
- BD12080237 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. 1p. 07182:276.
- 801204C090 Forwards IF. Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of managuer associated w/corrective actions. GRIER.B.H. Region I. Philadelphia. Office of the Director. 80/11/14. 1p 07197:348.
- B012310434 Submits add1 response to IE Bulletin 80-16. "Potential Misapplication of Rosencunt Inc Models 1151 & 1152 Pressure Transmitters w/Either A or D Output Codes." Two suppliers indicate no problems exist re transmitter. MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 80/11/14. 1p. 07370:026.
- 8012310436 Submits add1 response to IE Bulletin 80-20. "Failures of Hestinghouse Type N-2 Spring Return to Neutral Control Suitches." Bechtel has received response indicating no problem u/five contracts. MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. E0/11/14. ip. 07370:027.
- 80(227055: Advises that unitten response is required to IE Bulletin 80-23. "Failures of Solenoid Valves lift by Valcor Engineering Corp." First paragraph erroneously stated no written response required.
 GRIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/19. 1p. 07294:224.
- 8012040528 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 GRIER. B.H. Region 1. Philadelphia. Office of the Director.
 80/11/21. Zpp. 07165: 318
- 8012050593 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluit." No written response required. CRIER.B.M. Region 1. Philadelphia. Office of the Director. 80/11/24. 1p. 07174:083.
- S. Reportable occurrences, LERs & related correspondence
- E012230492 Interim deficiency rept re two pieces of carbon steel pipe found to be lacking radiography of longitudinal weld seam Investigation expected to be completed B10123 instead of 801209.

 MARTIN-T. J. Public Service Electric & Gas Co. of New Jersey. 80/12/10 2pp. 07318: 327.
- BOCKET 50-356 UNIV. OF ILLINGIS LOPRA RESEARCH REACTOR

 F. Security, medical, emergency & fire protection plans
- 6012040198 Forwards physical security plan Plan uithheld (19f 100FR2, 790).
 BECK.O.P. Illinois Univ. of Urbana-Champaign. 80/11/26. 1p. 07170:064.

- DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1
 A. Application/construction stage documents & correspondence
- BOI2160050 Ltr to operating plant licensess. QL applicants & CP holders. Forwards NUREC-0737 re TKI action plan requirements. Requests operating reactor licensee confirmation in 45 days that ERCL 1 implementation dates will be met. EISENMUT.D. Q. Division of Licensing. 80/10/31. 7pp.
- BO1222035B Ltr to all CP & OL holders for BWAs re requirement for implementation of ODYN code for licensing basis calculations performed by QE. Applicable to all license applications & proposed amends, including core reloads.

 EISEMHUT, D. G. Division of Licensing. B9/11/04. 4pp.
- BO12010007 Forwards Suppl 1 to NUREO-0487, "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria..."
 Deviations along w/bases for deviations are to be documented in design assessment rept during FSAR review YOUNG81000, B. J. Licensing Branch 1. 80/11/14. 2pp. 07097:015.
- 8012080442 Requests to be advised of when corporate & plant staffing plans will be submitted so that status rept can be scheduled & IE insp date establised.

 **EDESCO.R.L. Assistant Director for Licensing. 80/11/20. 2pp. 07195:003.
- BO12080462 Advises of requirements that must be mat re NRC review of special law power test program & emergency procedures for selected transients & accidents.
 TEDESCO.R.L. Assistant Director for Licensing. BO/11/20. 2pp. 07195:001.
- 8012100214 Notification of 801202 meeting w/BkR licensing review group in Bethesda.MD to discuss status of group issues.
 WILSON, J. N. Licensing Branch 1. 80/11/20. 8pp. 07217:304.
- 8012100555 Forwards request for add1 info required to complete review of Sargent & Lundy Rept SAD-348. "Investigation of Effects of Linear Leak Chase Channel Attachments."
 TEDESCO,R.L. Assistant Director for Licensing. 80/11/20. 3pp.
- 8012020249 Forwards Cortificate of Svc for 801119 submittal of update of financial info & amend to CP.
 BORGMANN.E.A. Cincinnati Gas & Electric Co. 80/11/24. 2pp.
 07148: 183.
- 8012030232 Forwards response to NUREO-0694, "TMI-Related Requirements for New DLs."

 BURGMANN.E.A. Cincinnati Gas & Electric Co. 80/11/26. SOpp. 07151:353.
- 8012050389 Forwards proprietary version of computer printout re low pressure turbine disc info. Printout withheld (ref 10CFR2 790). Vendor affidavit for withholding info encl. BCRGKANIA.E.A. Cincinnati Gas & Electric Co. 80/12/01. 9pp.
- 8012160190 Notification of 801210 meeting w/Mark II owners group in Bethesda. MD to discuss status of improved chugging load program. ANDERSON.C. Generic Issues Branch. 60/12/02. 1p. 07263:029.
- 8012170289 Forwards request for addl info re soil structure analysis per review of util response to Question 130.28. TEDESCO.R L. Assistant Director for Licensing. 80/12/03, 3pp. 07268:303.
- 8012080520 Forwards Amend 111 to CPPR-88, containing Revision 68, to FSA9.
 BDRGMANN&E.A. Cincinnati Gas & Electric Co. 80/12/05. 2pp. 07190:297.
- --8012030523 Amend 111 to CPPR-68 submitted as Revision 68 to FBAR. * Cincinnati Gas & Electric Co. 80/12/31. 561pp. 07192: 103.
- 8012160032 Notification of 801212 meeting w/Mark II owners group in Bethesda.HD to discuss suppression pool temp limit. SU.T.M. Generic Issues Branch. 80/12/05. ip. 07263:021.
- 8012170283 Summary of 801202 meeting u/BliR licensing review group. Bechtal & StU in Bethesda.MD re current status of issues & fire protection concerns. Rept on LaSalle specific issues encl.
 HTLSOH. J. N. Licensing Sranch 1. 80/12/05. 2ipp. 07268:264.

- 8012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Dversight Committee. KIRAGLIA.F. Licensing Branch 3. 89/12/05. 3pp.
- 8012270131 Summary of 800514-0828 meetings w/BWR Licensing Review Group in Bethesda-MD re identification of generic issues formation of consensus positions & resolutions that will apply to all six plants. Braft working paper encl.
 WILSON, J. N. Licensing Branch 1. 80/12/05. 99pp. 07307:055.
- 8012100305 Forwards add1 info re containment pressure boundary fracture toughness & cladding swelling & rupture models for LOCA analysis, in response to NRC 800910 & 1008 requests, respectively.

 BOROMANN, E.A. Cincinnati Gas & Electric Co. 80/12/08. 4pp. 07220.025
- B012170260 Forwards Certificate of Svc of Amend III, in form of Revision 6B to FBAR, filed w/NRC on 801205.
 BDROMANN.E.A. Cincinnati Gas & Electric Co. B0/12/11. 2pp. 07266: 162.
- 8012230291 Forwards Revision 69 to FSAR, constituting Amend 112 to OL application BOROMANN& E.A. Cincinnati Gas & Electric Co. 80/12/19. 2pp. 07316; 004.
- --8012230294 Revision 69 to FSAR providing change out pages. Revision constitutes Amend 112 to QL application.

 * Cincinnati Gas & Electric Co. 80/12/19. 214pp. 07316:006.
- E. NRC Safety Evaluation Report (SER), supply & correspondence
- 8012010033 Forwards Geosciences Branch request for add1 info for EER suppl re seismology section as result of 800727 earthquaks near site.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/18. 3pp. 07078.191.
- O. Adjudicatory correspondence
- E012040412 Submits correction to applicants' E01119 motion, requiring justification for NRC inability to proceed Deadline for submission of detailed explanation is E01217, not B01107. METTERHAHN, M. J. Conner, Moore & Corber. 80/11/26. 2pp. 07158:183
- 8012110346 Ack receipt of encl Gillman 801026 itr on behalf of Woliver client D Fankhauser. Suggests Fankhauser contact Univ of Cincinnati chemical & nuclear engineering dept re BWR designs & foreign reactor data.

 BARTH.C.A. Hearing Branch 2. 80/12/01. 1p. 07223:205.
- --B012110352 Submits questions re Mark II suppression pool on behalf of intervenor D Fankhauser.
 OILMAN.D. Affiliation Unknown. 80/10/25. ip. 07224:312.
- 8012190586 Response in opposition to applicant 801119 motion to require staff to provide justification for inability to proceed w/financial qualification hearings. Dutstanding issues not resolved. Certificate of Svc encl.

 BARTIM C.A. Hearing Branch 3. 80/12/09. 5pp. 07286:172.
- B012190549 Discusses review schedule re financial capability of applicants to construct & operate facility.Review completion expected during last half of Jan 1981.
 BARTH.C.A. Hearing Branch 3. 80/12/09. 1p. 07287:299.
- B012270457 Becond interrogatories directed to applicants re encl "Preliminary Evacuation Time Study of Plume Exposure Emergency Planning Zono Around WH Zinmer Nuclear Power Station, Unit 1." W/Certificate of Svc. BARTH. C. A. Hearing Branch 3. 60/12/09. 8pp. 07336:241.
- 8012300494 Memorandum & order denying applicant 800108 & 0225 motions for dismissal of Contention 13 re financial ability & dismissaling applicant motion for surnary disposition. Hearing tantatively scheduled for last wk in Feb. BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 80/12/24.10pp. 07359:202.
- B012310271 Request for extension until B10126 to respond or object to NRC second interrogatories. Certificate of Svc encl. CONNER, T. S., WETTERHAHMIN J. Cincinnet Oas & Electric Co. WETTERHAHMIN J. Cincinnet Oas & Cons. B0/12/24. 4pp. 07370:151.

- I. Financial information
- B012020249 Forwards Certificate of Svc for B01119 submittal of update of financial info & amend to CP.
 BCRCMANN.E.A. Cincinnati Gas & Electric Co. 80/i1/24. 2pp.
 07148-183
- BOI2190649 Discusses review schedule re financial capability of applicants to construct & operate facility.Review completion expected during lest half of Jan 1931 BARTH.C.A. Hearing Branch 3. 80/12/09. 1p. 07287:299
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 0012080520 Forwards Amend 111 to CPPR-88, containing Revision 68, to FBAR. BORDMAIN, E. A. Cincinnati Gas & Electric Co. 80/12/05. 2pp.
- --8012080523 Amend 111 to CPPR-E3 submitted as Revision 68 to FSAR. * Cincinnati Gas & Electric Co. 80/12/31, 551pp, 07192:103.
- 8012170260 Forwards Certificate of Svc of Amend III, in form of Revision 68 to FSAR, filed W/NRC on 801205.
 BORRMANN.E.A. Cincinnati Gas & Electric Co. 80/12/11. 2pp. 07266; 162.
- B012230271 Forwards Revision 69 to FSAR, constituting Amend 112 to OL. application.
 BDROMANM.E.A. Cincinnati Gas & Electric Co. B0/12/19. 2pp. 07316:004.
- --8012230294 Revision 69 to FSAR providing change out pages. Revision constitutes Amend 112 to OL application.

 * Cincinnati Cas & Electric Co. 80/12/19. 214pp. 07:316:006.
- 8012290286 Forwards Certificate of Svc confirming distribution of Amend 112 to license application consisting of Revision 69 to FEAR.

 80RGMANN.E.A. Cincinnati Gas & Electric Co. 80/12/22. 2pp. 07345:131.
- M. Antitrust correspondence
- B012010582 Forwards request to update 770427 antitrust info to address impacts of acquisition of Columbus & Southern CH Electric Co by American Electric Power Co. Info & public comments will be considered in supplementary antitrust review. SALTZMAW.U. Utility Finance Branch (formerly Antitrust & Indemnity). B0/11/19. 2pp. 07098:107.
- 0. Inspection reports, IE Bulletins & correspondence
- 8012110104 Forwards IE Insp Rept 50-359/80-21 on 800902-05,08-10,15-19 & 22-26.No noncompliance noted. HEISHMAN,R.F. Region 3, Chicago, Reartor Operations Nuclear Support Branch. 80/10/21. 2pp. 07224:192.
- --8012110110 IE Insp Rept 50-358/80-21 on 800902-05.08-10.15-19 & 22-26. No noncompliance noted Major areas inspected: IE builetin & circular followup, fire prevention & protection special test witnessing & plant tours.

 DANIELG.F.T., GWYNN.T.P., NARNICK.R.F. Region 3. Chicago, Office of the Director. 60/10/20. 10pp. 07224:194.
- 8012170661 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/10/24.

 1p. 07266:057.
- 8012180130 Forwards IE Insp Rept 50-358/80-22 on 801001-02 & notice of deviation. KEPPLCR, J. C. Region 3: Chicago, Office of the Director. 80/10/31. 2pp. 03791:240.
- --8012180133 Notice of deviation from insp on 801001-02.

 4 Region 3. Chicago, Office of the Director. 80/10/16. 1p. 03791:242
- --8012180135 IE Insp Rept 50-353/80-22 on B0100t-02 Noncompliance noted: failure to implement response to noncompliance items identified in IE Insp Rept 50-358/80-05.
 YIM.1.Y. Region 3. Thicago. Office of the Director.
 DANIFLSON, D.H. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 80/10/16. 5pp. 03791:243.

- 8012080304 Requests add1 info re util application for inservice insp of pressure isolation valves Outstanding info:list of tested valves & Ptl diagrams showing RCS isolation valves. NRC position encl.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/17. 3pp. 07188:053
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree u/user guide so that facility can compere program to program already reviewed & rake appropriate adjustments. N/o encl. KEPPLEN.J.O. Region 3. Chicago, Bifice of the Director. 60/11/18. App.
- 8012040676 Forwards IE Bulletin 80-24, "Prevention of Danage Due to Hater Leakage Inside Containment." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21. 2pp. 07169:084.
- 8012080936 Forwards IE Into Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:178.
- B012170555 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required KEPPLER.J.G. Region 3, Chicago. Office of the Director. 60/11/26. 2pp. 07264:294.
- 8012170502 Forwards previously submitted 790808 response to IE Bulletin 79-14. Seismic emalysis applies to actual piping configuration as part of facility const program. FLYNIA J. D. Cincinnati Gas & Electric Co. 80/12/09. ip. 07266:234.
- 6. Reportable occurrences: LERs & related correspondence
- 8012230497 Interim deficiency rept re 1-inch diameter Hilli Kwik-bolt anchors, first reported on 801117. Problem evaluated by AE. Requests rept date extension to 810116.

 BOROMANU, E. A. Cincinnati Gas & Electric Co. 80/12/12, ip. 07314:241.
- B012300609 Interim deficiency rept re accelerated wear of svc water pump impallers due to internal recirculation. Flow elements, min ficu control valves 2 more rugged, redesigned impellers being added to sys.

 BGRGMANGE A. Cincinnati Gas & Electric Co. B0/12/17. 2pp. 07346-152.
- 8012310357 Updates 601024 interin deficiency rept re springs on ITT AH/NH 90 Series actuators, supplied by American Warming & Ventilating, Inc. Rework on site by ITF is advised. Engineering rept has been approved.
 BERDMANIA.E.A. Cincinnati Gas & Electric Co. 80/12/22. 1p. 07359:178.
- BO12310058 Updates BD1104 interin deficiency rept re heating ventilation 2 air conditioning damper actuator mounts. Rework will not be completed by B01231, due to Bargent & Lundy authorization delay pending vendor seismic rept. BDRCKENNU. E. A. Cincinnati Gas & Electric Co. B0/12/22. 1p. 07355:179.
- DUCKE: 50-350 SATFELLE MEMORIAL INST. CRITICAL FACILITY

 Q. Inspection reports: 1E Bulletins & correspondence
- 801231054t Forwards IE Insp Rept 50-350/80-01 on 80(020-21.No noncompliance noted. BOCK.H E. Region 5. San Francisco. Fuel Facility & Materials Safety Branck. 80/11/13. 2pp. 67355:307.
- --8012310546 IE Insp Rept 50-360/60-01 on 801020-21.No noncompliance noted. Major areas inspected: Po recycle critical facility status in long-term shutdown CURITS. J.R., MENSLAWSKI.F. Region 5, San Francisco, Office of the Director. 800K.H.E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 60/11/13, 3pp. 07365:309.

- DOCKET 50-341 SAN ONOFRE NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Enc1 i implementation dates will be met. EISENHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012030379 "Review of Repts Dealing u/Simulation of Earthquake Oround Mottons for San Onofre Nuclear Generaturs Station Unit 1 for NRC."

 BERNREUTER D. L. Laurence Livermore Laboratory. 80/11/09. App. 07180 069
- 8011210010 Forwards request for add1 info needed as result of review of FEAR. Revised emergency plan meets requirements but needs revision addressing new rule & 10CFRSO schedula. Emergency response exercise must be conducted prior to CL (sevence. TEDEBCO.R.L. Division of Licensing. 80/11/07. 62pp.
- BD11250285 Advises that completion of CCCA qualification testing of cable u/fnsvlated repairs identified in significant deficiency rept now scheduled for 810415.

 NUKN.D.E. Southern California Edison Co. B0/11/14. 1p. 07056:083.
- 8011250547 Forwards participation agreement among Southern CA Edison Co. Ban Diego Gas & Electric Co & Cities of Riverside & Anaheim: CA re owernship of facilities for amend to CP. BASS/IN. A.P. Gouthern California Edison Co. BO/11/14. tp. 07058:017.
- --3011250557 Participation agreement among Southern CA Edison Co.Ban Diego Gas & Electric.City of Riverside.CA & City of Anahelm. CA re cumership of facilities. BJCRMLUNDIJ. Southern California Edison Co. BO/10/23. 300pp.
- 8012010776 Forwards review of geologic & seismologic data submitted by Southern CA Edison Co in support of position re facilities Units 2 & 3.

 MEMARD, N. U. Interior, Dept. of, Geological Survey, 80/11/26, 10pp. 07077:270.
- 8012020247 Forwards proposed App A Tech Specs.Proposel is represented in marked up version of STB. Approved Tech Specs will be incorporated in FSAR. BASKIN-K.P. Southern California Edison Co. 80/11/26. 1p. 07133:154.
- --8012020251 Proposed App A Tech Specs, Sections 1.0,2.0,3,0,4,0,5.0 k
 6.0 re safety limits & limiting safety sys settings.
 + Southern California Edison Co. GO/11/20. 200pp. 07133:155.
- 8012020232 Forwards partial response to NRC 801107 questions re spent fuel storage. Responses to remaining questions & schedule for commitment for any unanswered questions will be submitted on 801205.

 BASKIN, K. P. Southern California Edison Co. 80/11/26. 83pp. 07132: 839.
- B012040420 Advises that description of revised organization will be submitted. In response to NRC 801120 request, Address correction requested for util addresses. GlLMAN, D. W. Sen Diego Gas & Electric Co. 80/11/26. ip, 07140:357.
- 8012120308 "Concentration & Speciation of Copper in Waters Collected Near San Onofre & Diablo Canyon Nuclear Power Stations."

 HARRISON,F.L., BIEHOP,D.J., EMERSON,R.R. Lawrence Livermore Laboratory. FIN A-0119. NUREG/CR-0750, B0/11/30. 66pp. Available at NTIS. 07260:160.
- 8012030577 Forwards info re environ qualification tests to be performed within next two yes; in response to NRC 801001 ltm. Tests for pressure & level transmitters apply to Units 1,2 & 3.All other tests apply to Units 2 & 3 only.

 BASKIN.R.P. Southern California Edison Co. 80/12/01. 3pp. 07151; 216.
- 8012100099 Notification of B01215-18 meeting w/util.Bechtel & QE in Betheséa.MD to discuss THI & non-THI open items. RDDD.H. Licensing Branch 3. 80/12/02 6pp. 07219:145.
- 8012290485 Responds to 800911 memo requesting that DPc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of EE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. Epp.

- --8012220505 Forwards tabulation? summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANBART.R.L. Effluent Troatment Bystems Branch. 80/11/06. 8pp.
- 8012090202 Forwards "Pressurizer Brittle Fracture Evaluation" & addl responses to questions & schedule commitments in NRC 801107 ltr. Review of responses will be discussed w/NRC during wk of 801215, FSAR will be revised in Amend 22. BASKIN, N. P. Southern Celifornia Edison Co. 80/12/08, 4pp. 07200, 172.
- -8012070214 "Pressurizer Brittle Fracture Evaluation. "Addl responses to questions in NRC 801107 ltr encl. + Combustion Engineering, Inc. PRS-705. 80/11/19. 167pp. 07230:176.
- 8012100536 Forwards clarifications, refs & revised Section 4.0 of rept. "Water Tight Reliability of Condensate Storage Tank & Concrete Encl Walls Under DBE & Tornado Event." in response to NRC request for add1 info.

 BASKIN, K. P. Southern California Edison Co. 80/12/09, 1p. 07222:105.
- --8012100539 Supplemental info to "Water Tight Reliability of Condensate Storage Tank & Concrete Encl Walls Under DBE & Tornado Event." Southern California Edison Co. 80/12/31. 39pp. 07222:106.
- --8012100542 "Validity of Cubic Law for Fluid Flow in Deformable Rock Fracture."

 Fracture."

 WITHEREPOON.P., WANG.S.Y. Lawrence Livermore Laboratory.

 LDL-9557. 79/10/31. 33pp. 07222:144.
- B012230490 Notifies of NRC B00911 approval to terminate preoperational water monitoring program at facility & of interim monitoring program implementation. Table swmmarling transition encl. THIERER, I. Southern California Edison Co. 80/12/09. 2pp. 07313:214.
- BD1224010B Requests that branch chiefs attend meeting to discuss open items, Agenda enci.

 TEDESCO.R.L. Assistant Director for Licensing. 80/12/12. 2pp.
- 8012310314 Comments on WESTEC Svcs 800730 rept entitled "Natl Register Assessment Program of Cultural Resources of 230 kV Transmission Line ..." Sites which should be included: CA-Dra-495. Ora-496. Ora-497. CA-Dra-496. Dra-197. CA-Dra-496. Ora-197. CA-Dra-496. Ora-197. CA-Dra-496. Ora-197. CA-Dra-496. Ora-197. CA-Dra-496. Ora-197. Ora69: 163.
- C. Utility Environmental Report (ER), amonds & correspondence
- B012240425 Forwards Amend 6 to environ rept for facility. Affidavit will fallow within 10 days of amend docketing.

 DIETCH.R. Bouthern California Edison Co. 80/12/22, 1p. 07328:132.
- --8012240427 Application to amand GL updating, correcting, clarifying & revising ETS.
 DIETGH.R., DEGLETTO, J. A. Southern California Edison Co.
 COTTON, O. D. San Diego Gas & Electric Co. 80/12/19. 3pp.
 07328: 133.
- ~-8012240428 Proposed Amend 6 to environ rept.

 # Southern California Edison Co. # San Diego Gas & Electric Co.

 #B0/12/19. 49pp. 07328:136
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 9012020684 Informs that DEB was published in Nov 1978 & FEB delayed until revised TMI accident write-up is completed. Completion of accident evaluation scheduled for 801201.

 MIRAGLIA, F. Licensing Branch 3. 80/11/21. 1p. 07148:006.
- E. NRC Bafety Evaluation Report (SER), supple & correspondence
- 8012080687 Requests submittal of revised organization description & how organization meets NUREU-0731 guidelines re util mfg structure & technical resources in order to expedite review prior to issuance of final SER. TEDESCOUR.L. Assistant Director for Licensing. 80/11/20. 3pp. 04586:003.
- 8012300085 Forwards discussion of SER open items identifying actions to be taken by util & NRC per meetings held wk of 801215.

 BABKIN-K.P. Southern California Edison Co. 80/12/23. 13pp. 07308:001.

- F. Security, medical, emergency & fire protection plans
- 8012100046 Summary of 801020 menting W/FEKA in Los Angeles.CA re emergency planning. ROOD.H. Licensing Branch 3 80/11/24. 4pp. 07187:001.

G. Adjudicatory correspondence

- 8011250549 Forwards participation agreement among Southern CA Edison Co.San Diego Gos & Electric Co & Cities of Riverside & Anaheim.CA re owernship of facilities for amend to CP.
 8ASKIN,K.P. Southern California Edison Co. 80/11/14. 1p. ...
 07058:017.
- ---8011250557 Participation agreement among Southern CA Edison Co.San Diego Gas & Electric.City of Riverside.CA & City of Anaheim. GA re ownership of facilities BUMRKUND, J. Southern California Edison Co. 80/10/23. 300pp. 07058:018
- 8012030306 Second set of interrogatories to Friends of the Earth requesting info re Christianitos Fault.ione of deformation & effects of Imperial Valley 791015 earthquake.Proof of svc encl. PlOQTT,D.R. Bouthern Celifornia Edison Co. PlOOTT,D.R. Chickering & Gregory. Bo/t1/24. 27pp. D7150.001.
- 8012110578 Submits vesolution passed at executive board 800922 meeting. Resolution urges const expenditures be redirected toward conversion to sefer more socially acceptable fuel sources. CCPRAD.C. Affiliation Unknown. 80/12/10. 1p. 07223:107.
- B012270389 Informs that Comptroller General notified Commission on B01203 that NRC may not provide procedural assistance to intervenors in adjudicatory proceedings. CHANDLER.L.J. Hearing Branch (80/12/17, 1p. 07308:001.
- 8012290254 Notice of appearance in proceeding Proof of svc encl. MENDEZ, J. A. Southern California Edison Co. MENDEZ, J. A. Chickering & Gregory. 80/12/18. 4pp. 97341:170.
- 8012300509 Stipulation extending time for answers to applicants' second set of interrogatories to 810126. Certificate of Svc encl. CASEY, S. B. Southern California Edison Co. WHATON, R. J. Friends of the Earth. WHARTON, R. J. Wharton & Pogalies. 80/12/22. 4pp. 07360: 336

H. General correspondence

- 8012270262 Forwards constituent EK Johnson 1tr re location of facilities. Requests response. CRANSTON. A. Senate. 80/12/03 3pp. 07341:177.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012300369 Forwards Amend 22 to FSAR Amend 4 to "Fire Hazards Amalysis." Includes 23 oversize drawings Dne illegible Analysis." Indrawing encl DIETCH.R. S ci. Southern California Edison Co. 80/12/19. 1p. 07372:001.
- -B012303374 Amend to application for DL submitted as Amend 22 to FSAR.
 DIETCH.R. Southern California Edison Co. COTTON, O. D. San Diego
 Oas & Electric Co. G0/12/19 3pp. 07372:002.
- --8012300377 Amend 22 to FSAR.

 # Southern California Edison Co. 4 San Diego Gas & Electric Co.
 80/12/31. 240pp 07372-005.
- --8012300381 Amend 4 to "Fire Hazards Analysis "
 * Southern California Edison Co. * San Diego Gas & Electric Co.
 80/12/31. 33pp. 07373:155.
- --8012300334 "Pressurizer-Brittle Fracture Evaluation." JOHNSON.R.E.: HALLIDAY Combustion Engineering, Inc. 71370. 80/11/19. 26pp. 07373:188.
- Q Inspection reports, IF Bulletins & correspondence
- 8012170695 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 ENGELERIAR H. Region 5, San Francisco, Office of the Director.
 80/10/24

- 8012040323 Forwards IE Insp Rept 50-351780-16 on 800814-0918 No noncompliance mated CREWS, J.L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/10/27 Zep. 07163:258
- --8012040327 IE Insp. Rept 50-361/80-16 on 809816-0718. No nancompliance noted Major areas inspected preoperational test programs, procedures 6 independent insp effort.

 MILLER.L. F. PATEUR J. Region 5. San Francisco, Office of the Director FAULKENBERY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/10/24. 5pp. 07163:280.
- 8012170441 Forwards IE Info Notice 80-38, "Gracking in Charging Pump Casing Cladding." No written response required. ENGELMENTP H Region 5, San Francisco, Office of the Director. 80/10/30. 1p. 07249 iF6.
- E012170352 Forwards IE Info Notice 80-39. "Malfunction of Solemoid Valves Kig by Valcor Engineering Corp." No written response is required ENSELFER.R.H. Region 5. San Francisco. Office of the Director. 80/10/31. 1p 07266-045
- ED12120244 Forwards IE Bulletin BO-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. ENSELKEY.R H. Region 5. San Francisco. Office of the Director. 80/11/06. ip. 07227-326
- 8012030716 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. EM3ELKEN.R.H. Region 5. San Francisco. Office of the Director. 80/11/07. 1p. 07150:137.
- 8012100140 Forwards IE Insp Rept 50-351/80-17 on 800919-1016. No noncompliance noted CREMS, J.L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. 80/11/07. 2pp. 07219.269.
- --B012100147 IE Insp Rept 50-361/80-17 on 800919-1016. No noncompliance noted Major areas inspected preoperational test program & procedures.
 JCHN80N.A.D., PATE.R.J., CHAFFEE.A.E. Region 5, San Francisco, Office of the Director. B0/11/06. 6pp. 07219:271.
- 8012080550 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Eys at Davis Basse Unit 1." No response required ENGELKEN.R.M. Region 5, San Francisco, Office of the Director. 80/11/10. sp. 07183:038.
- 8012040241 Forwards IE Bullatin 80-23. "Failures of Solenoid Valves
 Mfg by Valcor Engineering Corp." Requires estimate of
 manpower associated u/corrective actions.
 ENGELMER.R.H. Region 5. San Francisco. Office of the Director.
 80/11/14. 1p. 07158:164.
- 8012040695 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. EROCELEGIR. H. Region 5, San Francisco, Office of the Director. 80/11/21. 1p. 07169:119.
- E012160097 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid" No response required. EKZELKEN.R H. Region 5. San Francisco. Office of the Director. 80/11/24. ip 07262.116.
- E012160130 Forwards Suppl 1 to IE Info Notice 80-27, "Broken Studs on Terry Turbine Steam Inlet Fiange" No written response required. ENCELAFILA H Region 5. San Francisco. Office of the Director. 80/11/26. 1p. 07262-070.
- S. Reportable occurrences, LERs & related correspondence
- 6011210432 Part 21 rept re DSRV standby diesel generator component defect. Util unable to meet schedule for insp due to incomplete const Svc engineers will witness final detailed installation & prestart checking. Util 801009 1 fc encl. MARTINI. 0. Transamerica Delaval, Inc. 80/11/11 3pp. 07034:001.
- 8012300521 Final deficiency rept re undersized ASME code welding dimensions for certain socket weld connections, initially submitted 80107, Program to reinspect socket welds in all ASM: Saction III piping will be completed by 810315, PAPAY,L.I. Southern California Edison Co. 80/12/16. 3pp. 07357,343.

8012310365 Final deficiency rept re cracking in coil spool insulators of HFA relays, initially reported on 801125. Defective relays will be replaced w/Century Series HFA relays. HFA relays w/nu cracks will be given force tensile test.

ARENAL.A. Southern California Edison Co. 80/12/23. 3pp. 07369:175.

V. Operator Examinations

- 80:2170447 Clarifies TMI~related min requirement for new OLs retraining during low power testing. Each licensed reactor operator should be able to control saturation margin & RCS pressure.
 TEOESCO.R.L. Assistant Director for Licensing. 80/11/14. 3pp. 07231:339.
- DOCKET 90-962 SAN ONDERE NUCLEAR STATION, UNIT 3

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees, CL applicants & CP holders. Forwards NURLG-0737 re TMI action plant requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISERHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012030377 "Review of Repts Dealing u/Simulation of Earthquake Ground Motions for San Onofre Nuclear Generators Station Unit 1 for NRC."

 BERREUTER D. L. Lawrence Livermore Laboratory. 80/11/05. App.
- 8012010276 Forwards review of geologic & seismologic data submitted by Southern CA Edison Co in support of position re facilities Units 2 & 3 HENARD, H. N. Interior, Dept. of, Geological Survey. 80/11/26. 10pp. 07097: 290.
- 8012020247 Forwards proposed App A Tech Specs. Proposal is represented in marked up version of STS. Approved Tech Specs will be incorporated in FSAR.

 BASKIN, P. Southern California Edison Co. 80/11/26. 1p. 07133:154.
- --8012020251 Proposed App A Tech Specs, Sections 1.0,2.0,3.0,4.0,5.0 & 6.0 ra safety limits & limiting safety sys settings.

 + Southern California Edison Co. 80/11/20. 200pp, 07133:155.
- 8012020282 Forwards partial response to NRC 801107 questions respent fuel storage. Responses to remaining questions & schedule for commitment for any unanswered questions will be submitted on 801205. BASKIN. K. P. Southern California Edison Co. 80/11/26. 83pp. 07132:259.
- 8012040420 Advises that description of revised organization will be submitted; in response to NRC 801120 request. Address corraction requested for util addresse. 01LMAN.D.W. Sen Diego Gas & Electric Co. 80/11/26. 1p. 07160:357.
- B012120308 "Concentration & Speciation of Copper in Waters Collected Near San Onofre & Diablo Canyon Nuclear Power Stations," HARRISON,F.L. Lawrence Livermore Laboratory. FIN A-0119. NUREO/CR-0750. B0/11/30. 66pp. Available at NTIS.
- 8012030577 Forwards into re environ qualification tests to be performed within next two yrs, in response to NRC 801001 ltr. Tests for pressure & level transmitters apply to Units 1,2 & 3, All other tests apply to Units 2 & 3 only.

 BASKIN.R.P Southern California Edison Co. 80/12/01. 3pp. 07151;216.
- 8012100079 Notification of 801215-18 meeting w/util,Bechtel & GE in Bethesda,MD to discuss THI & non-THI open items, ROOD,H. Licensing Branch 3. 80/12/02. 6pp. 07219:145.
- 8012229085 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220505 Forwards tabulation & surmary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Bystems Branch. BO/11/06. Bpp.

- 8012090202 Forwards "Pressurizer Brittle Fracture Evaluation" & add1 responses to questions & schedule commitments in NRC 801107 ltm. Review of responses will be discussed w/NRC during wk of 801215.FSAR will be revised in Amend 22.

 BASKIN.K.P. Bouthern California Edison Co. 80/12/08. App. BASK IN. K. P. 07200: 172.
- -8012070214 "Pressurizer Brittle Fracture Evaluation. "Add) responses to questions in NRC 801107 ltr encl.

 * Combustion Engineering, Inc. PRS-705. 80/11/19. 167pp. 07200: 176.
- B012100536 Forwards clarifications, refs % revised Section 4.0 of rept, "Nater Tight Reliability of Condensate Storage Tank & Concrete Enc1 Walls Under DEE & Tornado Event." in response to NRC request for add1 info.
 BASKIN, K.P. Southern California Edison Co. B0/12/09. 1p. 07222:105.
- ---8012100539 Supplemental info to "Water Tight Reliability of Condensate Storage Tank & Concrete Encl Walls Under DBE & Tornado Event."
 - Southern California Edison Co. 80/12/31. 39pp. 07222:104
- 8012230490 Nutifies of NRC 800911 approval to terminate preoperational water monitoring program at facility & of interim monitoring program implementation. Table summarizing transition encl. THIERER.I. Southern California Edison Co. 80/12/09. 2pp. 07313:214.
- 8012240108 Requests that branch chiefs attend meeting to discuss open items. Agenda encl.
 TEDESCO.R.L. Assistant Director for Licensing. 80/12/12. 2pp. 07325: 131
- B012310314 Comments on WESTEC Svcs 800930 rept entitled "Natl Register Assessment Program of Cultural Resources of 230 kV 'Transmission Line ..." Bites which should be included: CA-Ora-495, Ora-496. Ora-496. Ora-496. Ora-725. MELLON. K. California. State of. 80/12/18. 4pp. 07369:143.
- G. Utility Environmental Report (ER), amends & correspondence
- 8012240425 Forwards Amend 6 to environ rept for facility. Affidavit will follow within 10 days of amend docketing.
 DIEICH,R. Southern California Edison Co. 80/12/22. 1p. 07328: 132.
- --B012240427 Application to amend OL updating,correcting,clarifying & revising ETS.
 DIETCH.R., BECLETTO,J.A. Bouthern California Edison Co.
 COTTON,O.D. San Diego Gas & Electric Co. B0/12/19. 3pp. 07328: 133
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- B012020684 Informs that DES was published in Nov 1978 to FEB delayed until revised TMI accident write-up (s completed Completion of accident evaluation scheduled for 801201.
 MIRAGLIA.F. Licensing Granch 3. 80/11/21, 1p. 07148:006.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- E012080689 Requests submittal of revised organization description & how organization meets NUREO-0731 guidelines re util mfg structure & technical resources in order to expedite review prior to issuance of final SER. TEDESCO.R.L. Assistant Director for Licensing. B0/11/20. 3pp. 06586:003.
- 8012300385 Forwards discussion of SER open itams identifying actions to be taken by util & NRC per meetings held wk of 801215.
 BASKIN.K.P. Southern California Edison Co. 80/12/23. 13pp.
- F. Security, medical, emergency & fire protection plans
- B012100046 Summary of B01020 meeting w/FEMA in Los Angeles.CA re energency planning. R000.H. Licensing Branch 3. 90/11/24. 4pp. 07187:001.

- Adjudicatory correspondence
- 8011250549 Forwards participation agreement among Southern CA Edison Co. San Diego Gas & Electric Co & Cittes of Riverside & Anaheim.CA re awarnship of facilities for amend to CP.
 BASKIN, W.P. Southern California Edison Co. 80/11/14. 1p 0705B: 017
- -8011250557 Participation agreement amony Southern CA Edison Co.San Diego Gas & Electric.City of Riverside, CA & City of Anaheim. CA re ownership of facilities BURKLURD, J. Southern California Edison Co. 80/10/23. 300pp. 0705B: 01B
- 8012030306 Second set of interrogatories to Friends of the Earth requesting info re Christianitos Fault, some of deformation & effects of Imperial Valley 791015 earthquake.Proof of svo enci. P190TT.D.R. Southern California Edison Co. P100TT.D.R. Chickering & Oregory. 80/11/24. 27pp. 07150:001.
- 8012110578 Submits resolution passed at executive board 800922 meeting. Resolution urges const expenditures be redirected toward conversion to safer-more socially acceptable fuel sources. CONRAD.C. Affiliation Unknown. 80/12/10. 1p.
- B012290399 Informs that Comptroller General notified Commission on 801203 that NRC may not provide procedural assistance to intervenors in adjudicatory proceedings.

 CHANDLER(L. J. Hearing Branch I. 80/12/17. 1p. 07308:001.
- 8012270254 Notice of appearance in proceeding Proof of svc encl.

 MENDEZ, J. A. Southern California Edison Co. MENDEZ, J. A. Chickering
 & Gregory. 80/12/18. 4pp. 07341:170.
- 8012300509 Stipulation extending time for answers to applicants' second set of interrogatories to 810126.Certificate of Evc encl. CASEY, S. B. Southern California Edison Co. WHARTON.R.J. Friends of the Earth. WHARTON.R.J. Wharton & Pogalies. 80/12/22. 4pp. 07360:336.
- H. General correspondence
- 8012270262 Forwards constituent EK Johnson 1tr re location of facilities. Requests response. CRANGTON A. Senate. 80/12/03 3pp. 07341:177.
- f. Financial information
- 8011250547 Forwards participation agreement among Southern CA Edison Co.Ban Diego Gas & Electric Co & Cities of Riverside & Anahoim, CA re owernship of facilities for amend to CP. BASKIN, M. P. Southern California Edison Co. 80/11/14. ip. 0705B: 017
- -8011250557 Participation agreement among Southern CA Edison Co.San Diego Cas & Electric.City of Rivarside.CA & City of Anaheim, CA re ownership of facilities BJCRALUND.J. Southern California Edison Co. 80/10/23. 300pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012300349 Forwards Amend 22 to FSAR, Amend 4 to "Fire Hazards Amalysis." includes 29 oversize drawings, One illegible drawing encl DIETCH.R. Southern California Edison Co. 80/12/19, 1p. 07372:001.
- --8012303374 Amend to application for OL; submitted as Amend 22 to FSAR.
 DIETCH, R. Sauthern California Edison Co. COTFON, Q.D. San Diego
 Gas & Electric Co. 80/12/19, 3pp. 07372:002.
- --8012300377 Amend 22 to FSAR.

 # Southern California Edison Co. # San Diego Gas & Electric Co.
 80/12/31. 240pp. 07372:005.
- --8012309381 Amend 4 to "Fire Harards Analysis."

 * Southern California Edison Co. * San Diego Gas & Electric Co.
 *80/12/31. 33pp. 07373:155.
- --8012300384 "Pressurizer-Brittle Fracture Evaluation." JDF4:30N.R.E., HALLIDAY Combustion Engineering, Inc. 71370. 80/11/19. 26pp. 07373:188

- P. Operating license stage documents & correspondence
- B012240489 Notification of B01218 meeting w/SEP owners group in Bethesda. MD for discussions on SEP program, schedule for license topic completion & assignment of lead topics to plants.

 RUSSELL, N. 1. Systematic Evaluation Program Branch. B0/12/16. 2pp.
- G. Inspection reports, [E Bulletins & correspondence
- 8012170595 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required ENGELMFM.R.H. Region 5. San Francisco. Office of the Director. 80/10/24.
- B012170411 Forwards IE Into Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ENSELMEN.R. H. Region 5, San Francisco, Office of the Director. B0/10/30. ip. 07269:126.
- 8012170852 Forwards IE Into Notice 80-39, "Malfunction of Solenoid Valves High by Valcor Engineering Corp." No written response is required. ENGELKFIJR. H. Region 5, San Francisco, Office of the Director. 80/10/31. | Ip. 07266:045.
- 8012120044 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Halcolm Foundry Co.Inc." Written response required. ENCELERIAR. H. Region 5: San Francisco, Office of the Director. 80/11/06. 1p. 07227:326.
- 8012030916 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. ENDELXEM.R.H. Region 5. San Francisco, Office of the Director. 80/11/07. 1p. 07150:137.
- 8012080650 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
 ENGELHER, R. H. Region 5, San Francisco, Office of the Director.
 80/11/10. 1p. 07183:038.
- 8012040241 Forwards 1E Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ENSELMEN.R.H. Region 5. San Francisco. Office of the Director. 80/11/14. [p. 07158:164.
- 8012040585 Forwards [E Bu]letin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. ENGELEGIAR H. Region 5, San Francisco. Office of the Director. 80/11/21. 1p. 07169:119.
- 8012140087 Forwards 1E Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No response required. ENSELKEN,R.H. Region 9, San Francisco, Office of the Director. 80/11/24, 1p. 07262:116.
- 8012160130 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Ferry Turbine Steam Inlet Flange." Mo written response required. ENGELMEN.R.H. Region 5, San Francisco. Office of the Director. 80/11/26. 1p. 07262:070.
- S. Reportable occurrences, LERs & related correspondence
- 8011250285 Advises that completion of LOCA qualification testing of cable u/insulated repairs identified in significant deficiency rept now scheduled for 810415.

 NUNNED E. Southern California Edison Co. 80/11/14. ip. 07056:083.
- 8012300521 Final deficiency rept re undersized ASMS code welding dimensions for certain socket ueld connections, initially submitted 801107 Program to reinspect socket welds in all ASM Section III piging will be completed by 810315. PAPAV.L.T. Southern California Edison Co. 80/12/16. 3pp. 07397:243.
- 8012310355 Final deficiency rept to cracking in coil spool insulators of HFA relays initially reported on 801125 Defective relays will be replaced w/Century Series HFA relays HFA relays w/no cracks will be given force tensile test.
 AREMAL-A. Southern California Edison Co. 80/12/23, 3pp. 07369:175.

V. Operator Examinations

- 8012120447 Clarifies TMI-related min requirement for new QLs rebraining during low power testing. Each licensed reactor operator should be able to control saturation margin & RCS pressure. TEDESCO.R.L. Assistant Director for Licensing. 80/11/14. 3pp. 07231:339
- DOCKEL 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISEXMUT. D. G. Division of Licensing. 80/10/31. 7pp.
- G. Adjudicatory correspondence
- 8012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting mpt comments, in response to NRC 790921,1109 & BOOB11 requests for info re significant financial developments affecting utils in restart proceeding. COMDON, V. H. General Public Utilities. 80/11/26. 3pp. 07262;246.
- ~-8012160154 Quarterly Financial Rept.Sept 1980 & supporting mgt comments. * General Public Utilities. 80/11/14. 44pp. 07262:249.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012170339 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required, GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/30. 1p. 07269:083.
- 8012120161 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcola Foundry Co.Inc." Written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07228:224.
- 8012030321 Forwards IE Info Notice 80-40, "Excessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/07. jp. 07150:264.
- 8012080490 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Becay Heat Removal Sys at Davis Besse Unit 1." No response required.

 GRIER, B. H. Region 1, Philadelphia, Office of the Director, 80/11/10. 1p. 07182:345.
- 8012040012 Forwards IE Bulletin 80-23, "Failures of Solenaid Valvas Kig by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions. GRIER, B. H. Region 1. Philadelphia, Office of the Director. 80/11/14. 1p. 07169; 285.
- B012020/43 Forwards three Performance Appraisal Branch insp repts & mgt avaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments.if/o encl.

 KEPPLER.J. G. Region 3. Chicago. Difice of the Director. B0/11/18.4pp.
- 8012220691 Advises that written response is required to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.

 GRIER.B.H. Region 1, Philadelphia, Office of the Director.
 80/11/19. 1p. 07293:122.
- 8012040612 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. GRICA.B.H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07165:284.
- 8012050557 Forwards info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/24. 1p. 07174:044.

- DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

 E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8012020440 Forwards responses to 800903 memo re draft Suppl 4 to SER answaring util 800825 ltr discussing compliance w/NRC regulation.

 DENTON.H.R. Diffice of Nuclear Reactor Regulation, Director. 80/11/20. 20pp. 06586:003.
- --8012020443 Forwards list of util compliances w/10CFR20,50 & 100. AMEARNE,J. Commissioners. 80/09/03 95pp. 06586:003.
- F. Security, medical, emergency & fire protection plans
- 8001030448 Forwards upgraded emergency plan in response to NRC 791010 request.
 CLAY10N.F.L. Alabama Power Co. 79/12/28 1p. 01678:064.
- --8001030454 Facility emergency plan.Revision 3. * Alahama Power Co. 79/12/3t. 600pp.
- 8012110515 Forwards emergency planning info for placement in LPDR.W/o encl.
 80UDER.J.L. Division of Rules and Records. 80/12/02. 1p. 07226:150.
- 8012180143 Forwards 801119 FR notice of revised 10CFR90.48 & new App R re fire protection program requirements.Rule effective on 810217 & uill supersede effective dates for previously approved mads given in license conditions (43FR71569).
 TEDESCO.R.L. Assistant Director for Licensing. 80/12/03. 2pp.
- 8012090107 Releases public version of util emergency plan. FELTON, J. M. Division of Rules and Records. 80/12/08 1p. 07204:133.
- --8012070113 Forwards public version of util emergency plan, Revision 4. Includes States of FL & GA plans & QA county plans. CLAYTON, F. L. Alabama Power Co. 80/10/28. 11pp. 07204:135.
- --8012070118 Public version of Revision 4 to emergency plan. * Alabama Power Co. 80/10/28, 400pp. 07204:145.
- --8012090119 Public version of Revision 1 to State of QA radiological emergency operations plan.

 4 Georgia: State of. 80/10/28. 400pp. 07205:038.
- --8012070125 Public version of State of GA.Blakely-Early County civil defense emergency operations plan. Great Southern Paper Co emergency disaster plan encl.
 **, * Affiliation Unknown. 80/06/30. 200pp. 07206:008.
- --8012070130 Public version of Revision 2 of State of FL radiological emergency plan for fixed nuclear facilities.

 → Florida: State of. 79/04/30. 250pp. 07206:109.
- 8012230504 Responds to NRC 801105 position re alternate hot shutdown capability. Mods will be performed re fire protection safe shutdown capability, emergency lighting & oil collection sys for reactor coolant pump.

 CLAYTON, F. L. Alabama Power Co. 80/12/08, 2pp. 07312:315.
- 8012230476 Forwards add1 info to 801028 ltr re prompt notification sys, meterological criteria for emergency preparadness at operating nuclear plants & clarification of min staffing requirements.

 CLAYTON, F. L. Alabama Power Co. 80/12/16. 6pp. 07312:275.
- P. Operating license stage documents & correspondence
- B012150194 Forwards Revision 1 of "Farley Unit 2 Special Low-Power Tests Safety Evaluation." performed by Westinghouse. Incorporates changes of Ref 1 & min temp for criticality. CLAYTON,F.L. Alabama Power Co. B0/11/18. ip. 07241:070.
- --8012150196 Revision 1 of, "Farley Unit 2 Special Low-Power Tests Safety Evaluation." * Westinghouse Electric Corp. 80/11/18. 47pp. 07241:091.

- 8012080729 Informs that review of procedures submitted for conducting special low power test program has been completed & approval is expected prior to program start. License uill be conditioned to require results of special low power test. TEDESCO.R.L. Assistant Director for Licensing. 80/11/19. 2pp. 04594:003.
- 8012190146 Forwards add1 info requested by NRC re Reactor Sys Branch Question 210.2. Concerns possibility of small break LOCA & time frame available to mitigate consequences during startup or shutdown. CLAYTON, F. L. Alabama Power Co. 80/11/21. 3pp. 07240:078.
- B012050426 Advises that util response to NUREQ-0737 is scheduled for B10102. CLAYTCN.F.L. Alabama Power Co. B0/11/26. 1p. 07171:271.
- BOI2120515 Summary of BO1030 meeting w/util & Bechtel re means by which power cables in containment are protected from overcurrent. Draft response to NRC Position 040.15 encl.

 KINTNER.L. Licensing Branch 2. BO/11/28. 54pp. 07187:001.
- 8012190723 Forwards trip rept of 800707-10 site visit re review of seismic qualification methods, procedures & results for mechanical & alectrical squipment.
 KINTNER, L. L. Licensing Branch 2. 80/11/28. 2pp. 07288: 041.
- 8012160007 Summary of 800831.0901 & 1016 meetings w/util at site to review selected emergency operating procedures.
 KININGK.L. Licensing Branch 2 80/12/01. 3pp. 07262:325.
- B012170409 Forwards "Process Control Program for Sample Collection Analysis & Test Solidification using Cement," FNP-0-RCP-B00, App A.per Section 2.C.8 of License NPF-B. CLAYTON.F.L. 'Alabama Power Co. 80/12/03. 1p. 07269:353.
- --B012170412 "Process Control Program for Sample Collection Analysis & Test Bolidification Using Cament," FNP-O-RCP-800, App A.

 * Alabama Power Co. FNP-O-RCP-800. 80/11/28. 11pp. 07269:354.
- 8012100424 Provides commitment to implementation of mods to auxiliary feedwater initiation.in response to NRC 801105 ltr.Unit operating procedures will be revised.
 CLAYTON.F.L. Alabama Power Co. 80/12/04. 2pp. 07217:036.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENION-H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% plenning or considering increasing storage capacity.

 BANGART.R.L. Effluent Troatment Systems Branch. 80/11/06. 8pp.
- 8012230309 Forwards list of fire detection instruments & sprinkler sys to be included in App A Tech Specs issued w/Pull power license. CLAYTON, F. L. Alabama Power Co. 80/12/04. 2pp. 07311:110.
- --8012230312 Proposed App A Tech Specs Tables 3.3-12 & 3.7-8, re fire detaction instrumentation & sprinkler sys, respectively.

 * Arkansas Power & Light Co. 80/12/04. 9pp. 07311:112.
- B012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Committee. MIRA9LIA:F. Licensing Branch 3. 80/12/05. 3pp.
- 8012230461 Responds to 801105 ltr re alternate hot shutdown capability. Results of design evaluation to meet 10CFR50 App R requirements will be provided for review & concurrence. CLAYTON.F.L. Alabama Power Co. 80/12/05. ip. 07312:281.
- 8012240151 Notification of 801205 meeting w/Bechtel in Gaithersburg MD, to review drawings & design date for piping sys that penetrate containments as part of facility OL review.
 KININER, L. L. Licensing Branch 2. 80/12/05. 3pp. 07324: 350.
- 8012230463 Responds to request re max allowable leakage limits for sysoutside containment that may carry radioactive fluids fallowing accident.Limit of 5 gpm proposed.

 CLAYTON.F.L. Alabama Power Co. 80/12/08. 2pp. 07312:282.

- B012290294 Submits fees required for Tech Spec change & amend to License RPF-8 CLAYTON.F.L. Alabama Power Co. 80/12/10. 2pp. 07346:120.
- 8012230422 Responds to S Varga 800421 ltr re masonry walls in Category 1 structures.Util commits to re-evaluation of walls by 801215 to determine significance of design deviations. CLAYTON.F.L Alabama Forer Co. 80/12/12. 1p. 07312:261.
- BO12290314 Forwards add1 info re operability of 18-inch containment mini-purge valves in response to NRC BO1215 telcon CLAYTON.F. L. Alabama Power Co. BD/12/19. 2pp. 07346: 118.
- G. Inspection reports, IE Bulletins & correspondence
- 8012160031 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 0'REILLLY.J.P. Region 2. Atlanta. Office of the Director. 80/10/24.

 1p. 07242:184.
- 8012170300 Forwards Suppl 3 to 1E Bulletin 79-018, "Environ Qualification of Class 1E Equipment." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/24. lp. 07268:315.
- 8012]10701 Forwards IE Insp Rept 50-264/80-38 on 800915-17.No nonco-pliance noted. MURPHY, C.E. Region 2: Atlanta: Reactor Construction & Engineering Support Branch. 80/10/28. 2pp. 07225:063.
- --8012110709 IE Insp Rept 50-364/80-38 on 800915-17. No noncompliance noted Major areas inspected previous insp findings re IE Bulletins 79-02 & 79-14.

 ANO.M.P. Region 2. Atlanta. Office of the Director. HERDT.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/27. 3pp. 07225:065.
- 8012170833 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/30. ip. 07266:261.
- 8012180017 Forwards IE Info Notice 80-39, "Malfunction of Solenold Valves Mfg by Valcor Engineering Corp." No written response is required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/31. lp. 03790:124.
- 8012230077 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No unitten response required. O'REJLLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31. 1p. 0/313:249.
- 8012110614 Forwards IE Insp Repts 50-348/80-29 & 50-364/80-41 on 800901-30 No noncompliance noted LEWIS,R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/11/03. 2pp. 07226:177.
- --8012110420 IE Insp Repts 50-348/80-27 & 50-364/80-41 on 800901-30.No nancompliance noted Major areas inspected: plant tours, preoperational testing, Unit 2 plant testing status & Unit 1 plant operations.

 BRADFORD. M. H., MULKEY. J. P. Region 2. Atlanta, Office of the Director. MRTIN.R. D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/10/31. 11pp. 07226:179.
- B012110745 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. B0/11/06. 1p. 07225:203.
- 8012030830 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required, D'AREILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/07. lp. 07150:077.
- 80(21802)4 Forwards IE Insp Rept 50-344/80-44 on 80(014-17.No noncompliance noted. 8TOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/11/07. 2pp. 03792:006.

- --8012180215 IE Insp Rept 50-364/80-44 on 801014-17.No noncompliance noted Major areas inspected: radiation protection & radwaste not.

 TROUP.9.L. Region 2, Atlanta, Office of the Director, GIBSON,A.F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 80/11/95, 4pp. 03792:008.
- 8012080212 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Basse Unit 1." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/10, ip. 07182:270.
- 8012190194 Forwards IE Insp Rept 50-344/80-47 on 801028-30. No noncompliance noted. STOHR.J.R. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. BO/11/13. 2pp. 07282:079.
- --8012190202 IE Insp Rept 50-364/80-47 on 801028-30, No noncompliance noted. Major areas inspected: radiation protection & raduaste agt including preoperational testing & filter & adsorber testing.
 TROUP,O.L. Region 2, Atlanta, Office of the Director. GIBSUN.A.F. Region 2, Atlanta, Fuol Facility & Materials Safety Branch.
- B012040206 Forwards IE Bulletin B0-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. 0'REIIIY.J.P. Region 2, Atlanta, Office of the Director. B0/11/14. lp. 07158:121.
- 8012080642 Requests add1 info re inservice insp of pressure isolation valves.List of valves included in testing program should be provided.Mechanical Engineering Branch position on inspenct.

 TEDESCO.R. L. Assistant Director for Licensing. 80/11/17. 3pp. 07188:227.
- 8012110207 Advises that referral in 801031 cover ltr to IE Insp Repts 50-348/50-34 % 50-364/50-40 should be corrected to 50-348/80-34 % 50-364/80-40.
 STONRA, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/11/18. 1p. 07223:174.
- --8012110213 Forwards IE Insp Repts 50-348/50-34 & 50-364/50-40 on 801006-10. No noncompliance noted. STORR.J.P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/10/31. 2pp. 07223:076.
- --80)2110222 IE Insp Repts 50-348/80-34 & 50-364/80-40 on 801004-10. No noncompliance noted. Major areas inspected: emergency planning, coordination: w/offsite support groups & emergency facilities equipment & procedures. PEROTTI.D. J., JENNING.G.R. Region 2, Atlanta, Office of the Director. 80/10/30. 10pp. 07223:178.
- BO12110371 Provides info re health physics appraisal beginning 801201. List of HRC personnel & contractors requiring access to protected areas encl. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 90/11/19. 3pp. 07224:147.
- 8012020375 Ack receipt of 801015 ltr taking exception to violation noted in IE Insp Rept 50-364/80-33. Disagrees w/interpretation of requirements for normal weld radiography per IE Bulletin 79-13.
 MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch, 80/11/20. 2pp. 07143:210.
- --8012020397 Responds to NRC 860718 ltr re violations noted in IE Insp. Rept 50-364/80-33. Refutes NRC allegation of deficiency. Density tolerance for weld acceptable since reading not indicative of general weld area. CLAYION.F., L. Alabama Power Co. 80/10/15. 2pp. 07143:212.
- --BD12020400 Forwards IE Insp Rept 50-364/80-33 on 800825-27 & natice of violation.
 MURPHY.C.E. Region 2. Atlanta, Office of the Director. 80/09/10.
 2pp. 07143:214.
- --8012020402 Notice of violation from insp on 800825-27.

 * Region 2. Atlanta, Office of the Director. 80/09/16. 1p. 07143:216.
- --8012020404 IE Insp Rept 50-364/80-33 on 800825-27. Noncompliance notes: for Held C-1, radiographed to meet IE Bulletin 79-13, film density through base mat! next to weld was more than 30% darker than density through darkest penetrameter. CROMEY/B.R. Region 2. Atlanta, Office of the Director. HERDI.A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/16. 4pp. 07143:217.

- E012180016 Ack receipt of IE Insp Rept 50-364/80-38 on 801028. No proprietary info. CLAYTON:F.L. Alabama Power Co. 80/11/20. lp. 03791:166.
- 8012040472 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." Written response required, Requests info on manpower expended. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/21. 1p. 07143:329.
- 8012050064 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Hater Leakage Inside Containment." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/1 tp. 07173:220: Region 2. Atlanta, Office of the Director. 80/11/21.
- 8012030614 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Bnubber Fluid." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/24. tg. 07174:107.
- 8012170400 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26. 1p. 07269:108.
- 8012180595 Responds to IE Builetim 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.inc." No valve parts cast by Malcolm Foundry have been used at facilities, CLAYTDN:F.L. Alabama Power Co. 80/12/03. ip. 07271:359.
- B012180611 Responds to IE Bulletin 80-23, "Failures of Sciencid Valves Mfg by Valcor Engineering Corp." No Valcor valves used in safety-related functions at facilities. CLAYTON:F.L. Alabama Power Co. 80/12/03. ip. 07271:347.
- 8012180379 Ack receipt of 801202 ltr informing NRC of steps taken to correct violations moted in 1E insp Rept 50-364/80-33.

 MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/12/11. 1p. 03774:226.
- -8012180384 Responds to NRC 801120 ltr re violations noted in IE Insp Rept 50-364/80-33.Corrective actions:Held C-l radiographed w/acceptable results.Remaining portions of feedwater welds will be radiographed per IE Bulletin 79-13. MCDUNALD.R.P. Alabama Power Co. 80/12/02. 3pp. 03794:227.
- R. Periodic operating reports k related correspondence
- 8012160398 Forwards monthly operating rept for Nov 1980. CLAYTON:F, L. Alabama Power Co. 80/12/10. 1p. 07252:337.
- --8012160400 Monthly operating rept for Nav 1980. HAIRSTON, W. O. Alabama Power Co. 80/12/01. 4pp. 07252:339.
- S. Reportable occurrences. LERs & related correspondence
- B012020512 Forwards LER 80-001/01T-0. CLAYTGN.F. L. Alabama' Power Co. 80/11/26. 1p. 07143:266.
- --8012020519 LER 80-001/01T-0: on 801112, water for lubrication & cooling of A train svc water pumps found to be provided by B train svc water header & vice versa. Caused by design error. Design change to provide correct separation completed.

 HAIRBTON, N. O. Alabama Power Co. 80/11/26. 1p. 07143: 267.
- 8012100554 Forwards LER 80-002/01T-0. CLAYTON, F. L. Alabama Power Co. 80/12/04, 1p. 07219:018.
- --8012100562 LER 80-002/0)T-0: on 801126, during insp on MSIVs, damage to valve disc bolt holes & disc arm bolting on three dounstream MSIVs discovered. Caused by design deficiency. Design change will be implemented prior to initial startup.

 HAIRSTON.W. O. Alabama Power Co. 80/12/04. lp. 07219:019.
- 8012190235 Initial deficiency rept ra 800814 hydrogen dilution fan 28 trip. Caused by blade mounting bolt fracture. Fan hubs & blades returned to Joy Mfg Co for testing. CLAYTON: F. L. Alabama Power Co. 80/12/08. 3pp. 07240: 276.
- 8012300627 Amends commitment in LER 79-017/01T to allow automatic rod control during any rapid load reduction event.Probability is stremmily low that multiple rod drop event will occur w/o reactor trip concurrent w/rapid load reduction event.

 CLAYTON,F.L. Alabama Power Co. 80/12/12. 2pp. 07359:242.

- 8012300943 Forwards LER 80-003/017-0. CLAYTON:F.L. Alabama Power Co. 80/12/23. 1p. 07361:341.
- -8012300547 LER 80-003/017-0 on 801209 concrete block walls found not to meet seismic operational requirements Caused by uniasion of portions of vertical reinforcing &/or accompanying grout per original drawing Corrections to be approved the ALESTON W. G., Alahama Power Co. 80/12/23 2pp. 07361:342.
- V. Operator Examinations
- 8012230476 Forwards add1 info to 801028 ltr re prompt notification systematerological criteria for emergency preparedness at operating nuclear plants & clarification of min staffing requirements.

 CLAYTON.F. L. Alabama Power Co. 80/12/16. 6pp.
- DOCKET 59-344 EDWIN I HATCH NUCLEAR PLANT, UNIT 2 P. Operating license stage documents & correspondence
- 8012120066 Requests add1 fees re 801010 ltr transmitting test confirmation rept on seismic qualification & 801017 ltr requesting Tech Spec changes
 MILLER, M. License Fee Management Branch. 80/10/30. 2pp. 07231:346.
- 8012160050 Ltr to operating plant licensees, QL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012270378 Ltr to all CP & OL holders for BHRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends including core reloads.

 EISENHUT, D. G. Division of Licensing. 80/11/04, 4pp.
- 8012010421 Forwards Amend 19 to License NPF-5, safety evaluation & notice of issuance & availability.
 REID,R.W. Operating Reactors Branch 4. 80/11/12. 2pp. 07095:093.
- -8012010431 Amend 19 to License NPF-5 revising Tech Specs for fire protection sys to reflect addition of neuly installed sys at facility as required by prior licensing actions. REID, R. W. Operating Reactors Branch 4. 80/11/12. 7pp. 07095:095.
- ---8012010435 Safety evaluation supporting Amend 19 to License NPF-5.

 * Office of Nuclear Reactor Regulation, Director. 80/11/12. 207095:101.
- --8012010441 Notice of issuance & availability of Amend 19 to License NPF-5. REID.R.U. Operating Reactors Branch 4. 80/11/12. 2pp. 07095:103
- G012220563 Ltr to all power reactor licensees forwarding NUREG-0619, "BNR Feedwater Nozzle & Control Rad Drive Return Line Nozzle Cracking." Confirmation that implementation dates will be met must be sent within 45 days. N/O encl. EIBENHUT, D. O. Division of Licensing. 80/11/13. lp.
- B012080607 Informs that refund has been authorized for B01015 Classes I & II liconse amend application fees.Review of FSAR revisions not necessary.
 MILLER.W.O. License Fee Management Branch. 80/#1/25. 1p.
- 8012090385 Advises of compliance w/order for mod of licenses concerning environ qualification of safety-related electrical equipment Complete & auditable records file of environ qualification method per IE Bulletin 79-018 established.
 KELLY,R. J. Georgia Power Co. 80/12/01. 1p. 07207:143.
- 8012220485 Responds to 809913 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of mand to comply w/revised Agreement State burial site conditions.Forwards results of IE survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director.

 80/12/04, 2pp.
- --8012220505 Forwards tabulation & summary of IE survey on low level waste at 51 reactors Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. Spp.

- B012230364 Forwards confirmation of compliance relitems in NUREG-0737, "Clarification of TKI Action Plan Requirements." per NRC 801031 request WIDNER, D. A. Georgia Power Co. 80/12/15. 9pp. 07314:104.
- G. Inspection reports. IE Bulletins & correspondence
- 8012090513 Forwards IE Insp Repts 50-321/80-40 & 50-356/80-40 on 800924-25. No noncompliance noted MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/22 2pp. 07206: 203.
- --8012090517 lE Insp Repts 50-321/80-40 & 50-366/80-40 on 800924-25.No noncompliance noted. Major areas inspected: containment liner penetration welds, followup of noncompliances re inservice insp & certification of inspectors.

 ZAJAC.L. D. Region 2, Atlanta, Office of the Director. HERDI, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/17 4pp 07206:205.
- 8012030317 Forwards util 801015 ltr to Director of Nuclear Reactor Regulation requesting approval of exceptions to ANSI stds to correct infractions noted in IE Insp Repts 50-321/80-28 & 50-326/80-28. WIDNER, N. A. Georgia Power Co. 80/10/23. 1p. 07149:264
- 80:2150198 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written respaise required O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/24. 1p. 07240:283
- 8012170266 Forwards Suppl 3 to IF Sulletin 79-018, "Environ Gualification of Class IE Equipment." No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.
 19. 07268: 295.
- 8012020752 Forwards Vols 1 & 2 of response to Items 1-6 of IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." Response demonstrates that equipment is capable of satisfying safety requirements.
 WIDNER.W.A. Georgia Power Co. 80/10/31. 800pp. 07134:220.
- 8012170016 Forwards IE Info Notice 80-39, "Malfunction of Sciencid Valves Mfg by Valtor Engineering Corp." No specific action or response required.

 O'REIULY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.

 1p. 07264:130.
- 8012230057 Forwards 1E Circular 80-23, "Potential Defects in Heloit Power Sys Emergancy Generators." No written response required. 0'REILLY.J.F. Region 2. Atlanta, Office of the Director. 80/10/31. 1p. 07313:234
- 8012110732 Forwards IE Builetin 80-21. "Valve Yotas Supplied by Malcolm Foundry Co. Inc." Hritten response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06. pp. 07225:215.
- 8012030857 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. 0'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/07. 1p. 07150:109.
- 8012080303 Forwards IE Info Notice 80-41, "Failure of Suing Check Valve in Decay Reat Removal Sys at Davis Besse Unit 1." No response required. G'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/10. 1p. 07182:288.
- 8012010189 Forwards IE Bulletin 80-23, "Failures of Splengid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/14. tp. 07158:100.
- 8012020803 Act receipt of 801015 ltr & check in payment of civil penalty imposed by NRC 500924 order.
 STELLO,V. Office of Inspection & Enforcement, Office of the Director. 80/11/17. App. 07145:312.
- 8012040474 Forwards IE Builetin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Unition response required. Requests into on manpower expended. O'REILLY.U.P. Region 2. Atlanta, Office of the Director. 80/11/21. 1p. 07163:334.

- 8012240235 Responds to IE Bulletin 80-23 re solenoid valves V70903-21-1.V70900-21-2 & V70900-21-3,mfg by Valcor Engineering Corp. Valves not used at facilities. WIDNER, (J. A. Georgia Power Co 80/11/21, 1p. 07328:217.
- 8012030029 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Shubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24. ip. 07182:164
- E012110529 Ack receipt of 801113 ltr informing NRC of steps taken to correct violations noted in 15 Insp Repts 50-321/80-36 & 50-366/80-36 MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/26 ip. 07226:153.
- --8012110532 Responds to NRC 801027 ltr re violations noted in IE Insp Repts 50-321/80-36 & 50-366/80-36. Corrective actions: fire protection & loss prevention audit conducted & fire watch established. WIDNER.W.A Georgia Power Co. 80/11/13. 2pp. 07226: 154.
- --8012110534 Forwards IE Insp Repts 50-321/80-36 & 50-366/80-36 on 800916-19 & notice of violation O'RETLLY, J. P. Region 2, Atlanta, Office of the Director, 80/10/27, 2pp. 07226:156.
- --8012119537 Notice of violation from insp on 800914-19.
 ** Region 2, Atlanta, Office of the Director. 80/10/21. 1p. 07226:158
- --8012110539 IE Insp Repts 50-321/80-36 & 50-366/80-36 of 800916-19.
 Noncompliance noted:failure to conduct annual audit of fire protection program & presence of nonfunctional fire doors.
 MILLER.W. H. Region 2. Atlanta. Office of the Director.
 CONLOW, T. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/21. 8pp. 07226:159.
- 8012170517 Forwards (E Info Notice 80-29, Suppl 1, "Broken Studs on Tarry Turbine Steam inlet Flange," No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. . 80/11/26. 1p. 07268: 109.
- B012090385 Advises of compliance w/order for mod of licenses concerning environ qualification of safety-related electrical equipment. Complete & auditable records file of environ qualification method per IE Bulletin 79-018 established. KELLY.R. J. Georgia Power Co. 80/12/01. 1p.
- 8012230064 Responds to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17,1980 Indian Point 2 event)." Containment insp for water leakage will be performed at first cold shutdown.

 KELLY, R. J. Georgia Power Co. 80/12/01. 1p. 07311:080.
- R. Periodic operating reports & related correspondence
- 8012230278 Forwards monthly operating rept for Nov 1980. MANKY.M. Georgia Power Co. 80/12/10. 1p. 07318:053.
- ~-8012230301 Monthly operating rept for Nov 1980. UNDERNOOD, P.R. Georgia Power Co. 80/12/10, 9pp. 07318: 054.
- S. Reportable occurrences. LERs & related correspondence
- 8012010307 Ferwards LER 80-138/03L-0. MANRY,K. Georgia Power Co. 80/11/20. 1p. 07092:142.
- --8012010314 LER 80-138/03L-0: on 801027, leakage on torus purge inlet outboard isolation valve 2748-F324 found such that test vol could not be pressurized. Caused by worn O rings. Shaft & housing for O rings cleaned. O rings replaced. COGOIN.C.L. Georgia Power Co. 80/11/20. Zpp. 07092:143.
- 8012010371 Forwards LER 80-150/03L-0. MANNY,M. Georgia Power Co. B0/11/20. 1p. 07071:283.
- --8012010383 LER 80-150/03L-0: on 801102.HPCI steam line pressure A logic did not autoisolate until Tech Specs exceeded. Cause unknown. Further investigation planned. NIX, R. T. Gaorgia Power Co. 80/11/20. 2pp. 07091: 284.
- 8012010386 Forwards LER 80-147/03L-0. MANRY,N. Georgia Power Co. 80/11/20. 1p. 07091:300.

- --B012010393 LER B0-147/03L-0: on 801027, drywell hydrogen dioxide analyzers 2-P33-P001A & B found imperative Cause unknown. Vendor & util investigating failure.
 NIX,R.T. Georgia Power Co. 80/11/20. 2pp. 07091;301.
- 8012010349 Forwards LER 60-146/03L-0. MANRY.M. Georgia Power Co. 80/11/24. 1p. 07092:165.
- --8012010357 LER 80-146/03L-0: on 801029, excessive noise & vibration observed from 1R43-50018, emergency diesel generator. Caused by scavenging air blower. Blower replaced. PLX, R. T. Georgia Power Co. 80/11/24. 2pp. 07092:166.
- 8012023500 Forwards LER 80-145/03L-0. MARRY.N. Georgia Power Co. 80/11/26. 1p. 07148;117.
- --8012020507 LER 80-145/CGL-O on 801029, standby svc water pump flow & dynamic head data found out of compliance w/ASME Code Section 11.1able IMP-3100-2 Cause not stated. Corrective maint performed & pump retested.
 CODGIN.C.L. Georgia Power Co. 80/11/26 2pp. 07148:118.
- 8012020511 Forwards LER 80-149/03L-0. MANRY,M. Ocorgia Power Co. 80/11/26. ip. 07148:114.
- --8012070516 LER 80-149/03L-0: on 801101, leaking RHR pump suction isolation valve 2E11-F0048 prevented test vol pressurization. Caused by scratches on seat of valve, Valve seat polished to remove scratches.

 G00014, C. L. Georgia Power Co. 80/11/26. 2pp. 07148:115.
- 8012090371 Forwards LER 80-152/03L-0. MAPRY, M. Georgia Power Co. 80/12/02. 1p. 07203:004.
- --8012090377 LER 80-152/03L-0: on 801104, review of test results indicated excessive leakage from RHR min flow valve 2E11-F007A & HPCI turbine exhaust valve 2E41-F049. Caused by faulty closing of valve 2E11-F007A. Valve 2E41-F049 leak cause undetermined. C006IN.C.L. Georgia Power Co. 80/12/02 2pp. 07203:005.
- 8012290240 RD: on 801031, at 1400-h it was determined that smoke detectors were not installed per NFPA Coda 720. Cause not stated. Analysis being made of all detection sys & demign work for affected sys initiated. MANNY, M. Georgia Power Co. 80/12/04. 2pp. 07342:339.
- 8012150184 Forwards LER 80-154/03L-0. MAYRY, M. Opergia Power Co. 80/12/05. 1p. 07241:145.
- --8012150187 LER 80-154/03L-0 on 801106, during cold shutdown, tests of primary feedwater isolation valves 2821-F010A & 2821-F077A revealed that total leavages ercseded Tech Spec limits. Caused by scratches on valve seat. Valve seat polished. C0001N.C.L. Georgia Power Co. 80/12/05. 2ap. 07241:146.
- 8012150189 Forwards LER 80-153/03L-0. AANRY,M. Georgia Power Co. 80/12/05. ip. 07241:087.
- --B012150195 LER 80-153/03L-0: on 801107, during cold shutdown, test of reactor core isolation cooling turbine exhaust isolation valve ZEB1-F040 revealed that leakage exceeded 10CFR50, App Jacceptance criteria Caused by scratches on valve seat.

 COG01N.C.L. Georgia Power Co. B0/12/05. 2pp. 07241:088.
- 8012170629 Forwards LER 80-155/03L-0. MANRY, M. Georgia Power Co. 80/12/09. 1p. 07264:185.
- --B012170637 LER 80-155/03L-0: on 801111;RHR test line isolation valve 2F11-F0248 & condensate drain isolation valve 2B21-F16 found to be leaking. Cause unknown. Investigation underway. Valves will be repaired prior to startup.
 C00CIN.C.L. Georgia Power Co. 80/12/09. 2pp. 07264:186.
- 8012230542 Forwards LER 8C-156/03L-0.
 MARRY, M. Georgia Power Co. 80/12/11. 1p. 07316:304.
- --B012230549 LER 80-156/03L-0: on 801113 determined RHR return inboard & outboard thermal expansion bellous leaking in excess of spec. Caused by cracks in test connection tubing. Retest to be performed.

 C000111.C.L. Ocorgia Power Co. 80/12/11. 3pp. 07314:305.
- 8012240280 Forwards LER 80-151/03L-0. MANKY,M. Georgia Power Co. 80/12/16. ip. 07183:001.

- --8012240285 LER 80-151/03L-0 on 801120 coordinator reviewed data from 801118 LLRT on primary feeduater isolation valve 2831-F0108 & determined leakage rate exceeded lech Specs. Caused by scratches on valve seat. Seat polished. CDGGIN C. L. Georgia Power Co. 80/12/16 2pp. 07183:001.
- B012240297 Forwards LER 80-161/03L-0. MANNY, M. Georgia Power Co. 80/12/16. 1p. 07187:001.
- --8012240304 LER 80-161/03.-0 on 801126.eight relief valves.2021-F013A-M. failed due to pilot seat leakage & high set pressure. Cause undetermined. Valves repaired & retested. CD3G1N.C. L. Georgia Power Co. 80/12/16 lp. 07187:001.
- 801229024B Forwards LER 80-158/03L-0. MARRY,M. Georgia Power Co. 80/12/19. 1p. 07341:147.
- --8012290253 LER 80-158/03L-0 on 801126 drywell pneumatic return isolation valve 2P70-F020 found leaking at 6587 acco. Caused by scratches on seat of valve probably due to valve closing on debris. Scratches removed. Retest successful. CDG01M.C.L. Georgia Power Co 80/12/19. 2pp. 07341:168.
- 8012290258 Forwards LER 60-159/03L-0. MARRY,M. Georgia Power Co. 89/12/19. 1p. 07341:174.
- ---8012290266 LER 80-159/03L-0 on 801126 engine for diesel generator 20 failed during testing. Caused by broken catter pins which lock connecting rod nuts in place. Followup rept to be submitted when generator repaired.

 HIX,R.T. Georgia Power Co. 80/12/19. 2pp. 07341:175.
- DOCKET 50-367 BAILLY GENERATING STATION

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.CL applicants & CP holders. Forwards NUREC-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be ret. EISENMUT.D.O. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP & OL halders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amonds, including core reloads.

 EISERHUT, D. Q. Division of Licensing, 80/11/04, 4pp.
- B012020695 Forwards balance of documents discoverable pursuant to 800718 request for production. Privileged communications not included.
 GDL.DBERO, S. C. Hearing Branch 2. GD/11/29. 3pp. 06586:003.
- --8012020703 Forwards 780330 rept. "Hydrogeological Evaluation of Const Dewatering." H/o enci. BOIN/R. J. Northern Indiana Public Service Co. 78/04/03. 2pp. 06586:003
- --801202071B Discusses revisions to dauatering program.Proposed plan provides reasonable approach to dewatering problem. BALLARD, R. L. Environmental Projects Branch 1, 79/10/17. 1p. 06586:003.
- --B012020728 Discusses proposed const dewatering monitoring program transmitted by Nati Part Svc.IN Dunes National Lake Shore. BALLARD.R.L. Environmental Projects Branch 1. 79/11/06. 2pp.
- --8012020750 Ack receipt of 791001 ltr & attached documents re proposed plan for Lakeshore const & dewatering activities. W/o enci evaluations.

 BALLARD, R. C. Environmental Projects Branch 1, 79/12/14. ip. 04584-003
- --7907030173 Seeks approval of plan to formalize interim organizational structure to deal w/impacts of TMI incident, using resources & priorities within office Forwards task description, & chart of organization structure.

 DEITOM.H.R. Office of Nuclear Reactor Regulation, Director.

 EECY-79-344, 79/05/19, 33pp. 03273:193.
- ~-8002220053 Submits comments & recommendations re util 791227 ltr & 800131 maeting w/Nati Park Svcs. USCS & util in Indianapolis IN. Util proposed changes to monitoring & mitigation program should be disapproved.

 RULMAN.L. O. Hydrology Meteorology Branch. 80/02/09. 2pp. 02404:335.

- 8012080311 Forwards request for addl info in order to complete evaluation of request for extension of facility CP.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/21. 5pp.
 07194:268.
- 8012230532 Forwards request for add1 info re CP extension request to update evaluation of need for power E socioeconomic effects of const activity during period of requested extension. TEDESCO.R L. Division of Licensing. 80/11/21. Epp. 07381:216.
- 8012020427 Requests that latest date for completion of const be extended to 891201 Certificate of Svc enci.
 SHERB.E.M. Northern Indiana Public Service Co. 80/11/26. 6pp. 07148: 274.
- B012300536 "Effects of Decistering on IN Dunes Natl Lakeshore."
 WILLARD, D. Indiana Univ GEIS, J W. Hew York State Univ. of, College of Environ Sci & Forestry. DLSON, J. Cak Ridge National Laboratory.
 B0/11/26. 16pp. 07358:051.
- --2012300644 Forwards, 801202 ltr for info. Copies of any response made to the requested.

 VOLLEN.R.J. Businesamen for the Public Interest, 80/12/12, 1p.
 07358:067.
- E012090340 Requests status of Commission review of util revised devastering plan t proposed use of shorter pilings at const site & status of bearing re CP reneual.

 DICKEMSON.R.E. Interior.Dept. of, Mational Park Service. 80/12/02.
 19. 97201:115.
- 8012160150 Notification of 501210 meeting w/Mark II owners group in Bethesda,MD to discuss status of Improved chugging load program. ANGERSONAC. Generic Issues Branch. 80/12/02. 1p.
- 8012140032 Notification of 801212 m-eting w/Mark II owners group in Bethesda.ND to discuss suppression pool temp limit. SU.T.M. Generic Issues Branch. 80/12/05. 1p.
- B012240150 Forwards response to NRC B01121 questions re CP extension request Responses predicated upon 1989 completion date per util B01126 ltr.
 SMORS,E.M. Northern Indiana Public Service Co. B0/12/18. 57pp.
- F. Security, medical, emergency & fire protection plans
- 8012040PUR Public version of "Independent Assessment of Evacuation Times for Pailly Nuclear Power Plant," Vol 2.prepared for FEMA.
- FEMA. COSBY,J.C., SHEPPARD.N.V., BANCROFT,J.R. Wilbur Smith & Associates. 80/06/20. 5800. 07155-336 ₹Bpp.
- 8012040055 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, FELTON, J.M. Division of Rules and Records. 80/12/03, 1p.
- --B012040089 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEKA. 4 Wilbur Smith & Associates. 80/06/30. 17pp.
- --8012040155 Public version of program rept. "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones." Vol 1. prepared for FEMA. COSBY, J. C. Hilbur Emith & Associates. 80/06/30. 43pp.

Adjudicatory correspondence

- 012020095 Forwards balance of documents discoverable pursuant to 300918 request for production Privileged communications not noticed. OCLOBERO.S.C. Hearing Granch 2. 80/11/20. 3pp. 06586:003.
- 012020703 Forwards 780330 rapt. "Hydrogeological Evaluation of Const Decataring." N/o encl. BBC#2.R.J. Northern Indiana Public Service Co. 78/04/03. 2pp. 06596:003.
- -8012020718 Discusses revisions to depatering program Proposed plan provides reasonable approach to dewatering problem BALLARD.R.L. Environmental Projects Branch 1. 79/10/17. 1p. 76596:003.

- -8012020728 Discusses proposed const dewatering monitoring program transmitted by Natl Park Svc. IN Dunes National Lake Shore. BALLARD, R. L. Environmental Projects Branch 1. 79/11/06. 2pp. 06596: 003.
- 06586: 003
- --7907030173 Seeks approval of plan to formalize interim organizational structure to deal w/impacts of TMI incident using resources & priorities within office.Forwards task description, & chart of organization structure.

 DENTON, H. R. Diffice of Nuclear Roactor Regulation, Director.

 SECY-79-344, 79/05/19, 33pp. 00273:193.
- --8002220053 Submits comments & recommendations re util 791227 ltr & 800131 Recting w/Matl Park Svcs.U305 & util in Indianapolis [N. Util proposed changes to monitoring & mitigation program should be disapproved. HUMANIL 0. Hydrology Meteorology Branch. 80/02/08. 2pp. 02404:335.
- 8012100066 Response to QE motion for protective order w/respect to notice of deposition. Motion should be denied & O'Rourke required to appear for deposition. Certificate of Byc encl. VOLLEN.R.J. Porter County Chapter Intervenors. VOLLEN.R.J. Vollen, R.J. 80/11/24. 6pp. 07219:098.
- 8012110014 Response in apposition to Porter County Chapter Intervenors' motion to suspend litigation proceedings. Single legitimate concern re discovery does not justify deferral. Certificate of Svc encl.

 SHEA, K. H. Lowenstein, Newman, Reis, Axelrad & Toll. SHEA, K. H.

 Northern Indiana Public Service Co. 80/11/25. 6pp. 07223: 118.
- BO120206AS Response supporting Porter County Chapter motion to suspend further litigation proceedings, pending ASCB order. Certificate of Svc encl. RAPKIN.A. Illinois, State of. 80/11/26. 3pp. 07147:279.
- 8012020570 Notice of appearance in proceeding Certificate of Svc uncl. RAPKIN.A. Illinois, State of. 80/11/26. 4pp. 07147:282.
- 8012190543 Response in opposition to Porter County Chapter Intervenors (PCCI) motion to suspend CP extension proceedings. PCCI will be gravited opportunity to conduct full prehearing preparation. Certificate of Svc and 1. GOLDBERO, S. C. Hearing Branch 2. 80/12/02. 10pp. 07288:118.
- B012230009 Corrects NRC 801202 response to Porter County Chapter Intervenors' motion to suspend litigation proceedings. Date in last line of Page 4 should read 1987 not 1979. CLKSTEAD.U.J. Hearing Branch 4. 80/12/03. 1p. 07311:165.
- 8012290181 Response to ASLB 801120 order re discovery. Adopts GE response & objections per vendor 801014 motion & 801111 opposing answer to Porter County Chapter second motion to compel. IV/Certificate of Svc. Related correspondence. EICHRORI, N. H. Northern Indiana Public Service Co. EICHHORN, H. H. Eichhorn, Eichhorn & Link. 80/12/03. 4pp. 07344:172.
- BO12290535 Fowards suppl to 800605 request for CP suspension or revocation based on necessity of consideration of whether surrounding population can be evacuated in time in event of nuclear accident.

 COMN.D.B. Gary.IN COMN.D.B. Public Citizen Litigation Group.
 BO/12/04. 1p. 07932:276.
- ---B012290538.Suppl to B00505 requests to suspend or revoke CP.
 Evacuation issues are especially suited to site feasibility
 determination for case by case consideration.Certificate
 of Bvc encl.
 CCHt, D. B., SCHULTZ, W. B. Gary, IN. CCHN, D. B. Public Citizen
 Litigation Group. 80/12/04. 12pp. 07332:277.
- 8012290235 Response in opposition to petition for review of ABLB 801120 decision denying petition to intervene filed by City of Cary, IN. United Steelworkers of America Local 6787 & Save the Dunes Council et al. H/Certificate of Svc. SHEA.K. H. Northern Indiana Public Service Co. SHEA.K. H. Lowenstein, Newman, Reis, Axelrad & Toll. 80/12/18. 11pp. 07345; 058.
- 8012310439 Addi comments on City of Dary IN request for action under 10CFR2 206. Since nuclear accident is impossible in const stage deficiency in emergency planning could not constitute threat to public Certificate of Svc encl. EICHHORN. M. H. Northern Indiana Public Service Co. EICHHORN, W. H. Eichhorn, Eichhorn & Link, 80/12/22. 6pp. 07370:215.

- Di2300011 Forwards Comptroller General B01203 opinion stating procedural assistance in adjudicatory licensing proceedings was not permissible under law.

 GCLBERG(S.C. Hearing Branch 2. 80/12/23 1p. 07356:101.
- 312270089 Memorandum & order denying State of IL & Porter County Chapter Intervenors newly filed Contentions R-I 1-9 & 13 re need for EIS & contention re merits of short pilings re need for proposal. GROSSMAN, H. GROSSMAN, H. Atomic Safety and Licensing Board Panel. 80/12/24. 7pp. 07343:041.
- . Inspection reports, IE Bulletins & correspondence
- 012170636 Forwards lE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/10/24.
 1p. 07266:053.
- 012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. N/o encl. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/18.
- Di2049644 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER.J. O. Region 3, Chicago, Office of the Director. 80/11/21.

 29p. 07165:345.
- 0;2080066 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J.G. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:218.
- IO12300/OB Responds to IE Builetin 80-21, "Valve Yotes Supplied by Malcoim Foundry Co. Inc." No active valves w/parts cast by foundry in use in safety-related sys of facility. Response will be completed by 820104. SHORB.
- OL2170533 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director, 80/11/26, 2pp. 07268: 136.
- Periodic operating reports & related correspondence
- 3012030583 Forwards info re well charts for 801112-19 & Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USOS wells for 801119. Sump pumps turned off for routine maint on 801113 BOHM, R. J. Northern Indiana Public Service Co. 80/11/25. 32pp. 07151;184.
- 3012090182 Forwards well charts for 801117-26. Bailly wells w/o recorders, pond lovels, pneumatic pressure transducers, water meter readings & USOS wells for 801125.
 BGHN.R.J. Northern Indiana Public Service Co. 80/12/05. 32pp. 07187:001.
- B012190130 Forwards "Summer 1980 Quarterly Rept: Bailly Nuclear-1 Site Encompassing Jul-Sept 1980." No discernible effects to environ found due to const of facility. PURCELL.J.F. Northern Indiana Public Service Co. 80/12/05. 1p. 07274:072.
- --8012190134 "Bummer 1980 Quarterly Rept;Bailly Nuclear-1 Site Encompassing Jul-Sept 1980." * Teras Instruments, Inc. 80/11/30. &00pp. 07274:073.
- G012160513 Forwards well charts for 801126-1203. Bailly utils w/o recorders, pand levels, pneumatic pressure transducers, water meter readings, & USGB wells for 801203. Clock stopped for Well 20.

 BDMN.R.J. Northern Indiana Public Service Co. B0/12/12 32pp. 07263:059.
- 8012240431 Forwards well charts for 801203-10.Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USOS wells for 801210. BDSMRR.J. Northern Indiana Public Service Co. 80/12/19, 32pp. DOM R. J. 07328: 073.

- U. Congressional/Executive Correspondence
- 8012020834 Responds to 761216 ltr expressing concern re const of facility adjacent to IN Dunes Nat? Lakeshore. AELB 740405 decision concluded that const would not result in substantial environ harm ROHDEN/K.A. Commissioners. 77/02/09. 3pp. 07130:359.
- --B012020B39 Expresses concern re const of facility adjacent to IN Dunes Matl Lateshore. Serious concern exists re adverse impact of facility on Coules Bog. RUPTE. P.E. House of Rep., Interior & Insular Affairs. 76/12/16. 2pp. 07141:013.
- DOCKET 50-368 ARKANSAS NUCLEAR ENE. UMIT 2 F. Security, medical, emergency & fire protection plans
- 8012100694 Advises of interim inCFR50.48 suspending completion dates for fire protection mods previously approved by NRC.Rule became effective upon publication in 801029 FR (49FR71569). Revised 10CFR50.48 & App R will supersede interim rule. EISEKMUT.D.G. Division of Licensing. 80/11/14. 5pp.
- 8012240101 Submits status of NRC review of facility fire protection. Updated status of fire protection items is needed for application of App R. Schedules for implementation encl. #ARTIN.R.E. Operating Reactors Branch 3. 80/12/04. 4pp. 07324:330
- 8012290433 Releases public version of util emergency plan. FELTON.J.B. Division of Rules and Records. B0/12/16. 1p. 07339:084.
- --8012290438 Public version of amended emergency plan. Revision 58.

 Ariansas Power & Light Co. 79/04/16. 200pp. 07339: 085.
- G. Adjudicatory correspondence
- 8012080472 Requests hearing on issue of whether all safety-related electrical equipment should be environmentally qualified in accordance w/Ofc of Nuclear Reactor Regulation guidelines or NUREO-0998.
 REYNOLDS:N.S. Debevoise & Liberman. 80/12/04. 2pp. 07184:282.
- P. Operating license stage documents & correspondence
- 8012020753 Forwards seismic qualifications of auxiliary feedwater sys in operating PURs & describes program RRC is undertaking to review capability of operating PURs to remove decay heat following earthquake.
 EISECHUT, D. O. Division of Licensing. 80/10/21. 4pp.
- BOIR160050 Ltr to operating plant licensees,OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be not. EISERMUT.D. G. Division of Licensing. B0/10/31. 7pp.
- 8012220563 Ltr to all power reactor licensees forwarding NUREG-0617, "BNR Feedwater Notile ½ Control Rod Drive Return Line Norile Cracking." Confirmation that implementation dates will be met must be sent within 45 days.
- 8012030839 Forwards Performance Appraisal Branch repts & mgt evaluation trae & oser's guide info provided to ensure that licensees have opportunity to review strengths & weaknesses for program applicability. M/O encis.

 SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/14. 07149: 009
- 80:2090106 Forwards Amends 49 & 18 to Licenses DPR-5: & NPF-6, respectively & notice of issuance & availability. REID.R.W. Operating Reactors Branch 4. 80/11/19. 3pp. 07:199:190.
- --8012090110 Amends 48 & 18 to Licenses DPR-51 & NPF-6, respectively, including requirement to maintain safeguards contingency plan to be implemented within 30 days of Commission approval. Operating Reactors Branch 4. 80/11/19. 4pp. 07199:193.
- -8012090115 Notice of issuance & availability of Amends 48 & 18 to Licenses DPR-51 & NPF-6-respectively. REID.R.W. Operating Reactors Branch 4. 80/11/19. 2pp. 07199:197.

- 8012160507 Forwards requests for add1 info & positions resulting from review of util 800131 response to ERC 791106 ltm on auriliary feedwater sys. Questions based on NRC review of recent operating experience encl. CLARK.R.A Operating Reactors Branch 3 89/11/24. 10pp. 07261: 239.
- 8012080515 Forwards drawings indicating mods to low temp overpressuritation sys design & logic.per 771011 ltr re Amend 1.5ection 2F to License NPF-6. TRIMBLE.D.C. Artansas Power & Light Co. 80/12/01. 4pp. 07182:109.
- GO12150097 Forwards proprietary & nunproprietary versions of CEN-123(A)
 "Statistical Combination of Uncertainties." Describes
 methods used to combine sys parameter uncertainties in
 thermal margin analyses for Cycle 2.
 TRIMBLE, D. C. Arkansas Power & Light Co. BO/12/01. 2pp. 07241: 228.
- --8012150078 Affidavit supporting proprietary treatment for CEN-139(A)-P,
 "Statistical Combination of Uncertainties.."
 SCHERER, A.E. Combustion Engineering, Inc. 80/11/13. 5pp.
 07241:230.
- --B01215010] "Statistical Combination of Uncertainties: Combination of Sys Parameter Uncertainties in Thermal Margin Analyses for AR Nuclear One Unit 2." Proprietary version withheld (ref 10CFR2.790.) 4 Combustion Engineering, Inc. CEN-139(A)-NP. 80/11/30. 65pp. 07241:235.
- 8012090174 Submits info re flushing operations on containment cooling units. Includes max water temp used during high temp flushing, duration of flush, description of how water temp was monitored & description of flushing sequence used.

 IRIMBLE.D.C. Arkansas Power & Light Co 80/12/02, 2pp, 07200:129.
- B012070180 Forwards figures referenced in B01031 submittal of proposed Tech Spec changes re hydrogen-orggen concentration limits in waste gas sys. Figures were inadvertently omitted at time of submittal.

 TRIMBLE, D. C. Arkansas Power & Light Co. 80/12/02. 3pp. 07207: 188,
- 8012100074 Notification of 801203 meeting w/util in Bethesda. HD to discuss requirements for environ qualification of safetyrelated electrical equipment. MARTIN. R.E. Operating Reactors Branch 3. 80/12/02. 2pp. 07219:106
- 8012220485 Responds to 80091t mema requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION. H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp. 07299:205.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expended at 37% of reactors surveyed w/7% planning or considering increasing storage capacity, BANGARI.R.L. Effluent Treatment Bystems Branch. 80/11/06. 8pp. 07299:207.
- 8012290496 Informs that 200919 topical rept re qualification of reactor physics methods for application to PURS has been determined to contain proprietary info & will be withheld as requested.
 REID.R. N. Operating Reactors Branch 4. 80/12/05. 3pp. 07335:159.
- 8012300738 Requests Plant Sys & Core & Containment Sys Branch review of encl info re util core reload application, to identify potential problem areas. Feedback should be provided reidentity of reviewers & meeting of listed schedules.

 NGVAN.T.M. Assistant Director for Operating Reactors. 80/12/08, 7pp. 07359:273
- 8012300340 Agrees to extension until 801205 for plant safety committee to become operational.

 CLARK.R.A. Operating Reactors Branch 3. REID.R.W. Operating Reactors Branch 4. 80/12/10. 2pp. 07358:361.
- N2230200 Submits add1 info requested in 800805 ltr re fracture truphness of steam generator & reactor conlant gump supports Nill test repts on grade of ASTM A-283 used for lugs not available.

 RRIMBLE, D. C. Arkansas Power & Light Co. 80/12/16. 7pp.
- H2230482 Summarizes util concerns to NRC 801024 order for mod of licenses requiring environ qualification of Class IE electrical equipment by 820530. Requests hearing to resolve concerns to implementation methods.

 CAVANA

- 8012290168 Forwards commitments to TMI action plan requirements per NUREO-0737. Shift technical advisor training program & procedures to verify correct performance of operating activities will be completed by 810101.
 CAVAMAUGH. W. Arkansas Power & Light Co. 80/12/19, 12pp. 07338.242.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012120174 Responds to IE Bulletin 80-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." Util does not use specific relay in logic matrices.

 TRIMBLE.D.C. Arkansas Power & Light Co. 80/08/08. 1p. 07236:185.
- 8012120156 Responds to 1E Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Becondary Bide High Energy Line Rupture." Facilities are adequately designed to maintain HPI pump cooling.

 TRIMBLE.D.C. Arkansas Power & Light Co. 80/09/22. 3pp. 07240:010.
- B012270587 Requests extension until B10101 for response to IE Bulletin 79:018. Suppl 2, "Environ Qualification of Class IE Equipment." If request cannot be granted informally. NRC requested to treat 1tr as application to amend GL. CAVARAUGH. W. Arkansas Power & Light Co. 80/10/09. 4pp. 07299:222.
- 8012120099 Responds to Item 2 of IE Bulletin 79-17.Revision 1, "Pipe Cracis in Stagnant Borated Water Sys at PWR Plants."
 Required piping insps completed 801010.Written rept will be submitted by 801109.
 TRIMBLE, D. C. Arkansas Power & Light Co. 80/10/16. lp. 07231:357.
- B012120305 Forwards IE Insp Repts 50-313/80-18 & 50-368/80-18 on B00922-26 & notice of deviation. MAUSEN.O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. B0/10/20. 2pp. 07231:297.
- --B012120311 Notice of deviation from insp on B00922-26.

 * Region 4. Dallas. Office of the Director. B0/10/17. ip.
 07231:299.
- --8012120326 IE Insp Repts 50-313/80-18 & 50-368/80-18 on 800922-26.
 Noncompliance noted:sampling program not established per IE
 Builetin 80-10 response commitment.
 DEAN.8. HUNNICUTT, D.M. Region 4. Dallas, Office of the Director.
 GAGLIARDO.J.E. Region 4. Dallas, Reactor Operations Nuclear
 Bupport Branch. 80/10/17. 4pp. 07231:300.
- 8012120191 Responds to 1E Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power." Test verified that all extensions remained fully operable from facility to NRC upon loss of offsite power.

 CAVANAUGH.W. Arkansas Power & Light Co. 80/10/22, 3pp. 07236:186.
- 8012080827 Forwards IE Insp Repts 50-313/80-12 & 50-368/80-12 on 800617-20 & 0714-18.

 MADSEN, O.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 80/10/23. 2pp. 07180:200.
- --8012080834 IE Insp Repts S0-313/80-12 & 50-368/80-12 on 800617-20 to 0714-18. Noncompliance noted: failure to take prompt corrective action & failure to meet requalifications training program.

 ANESHANSLEY, M., DEAN, S. R., JAUDON, J. P. Region 4, Dallas, Office of the Director. 80/10/21. 20pp. 07180: 202.
- 8012170322 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.

 SEYFRIT. & V. Region 4. Dallas, Office of the Director. 80/10/24.

 1p. 07268:348.
- 8012160345 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 EEYFRII.K.V. Region 4. Dallas, Office of the Director. B0/10/27, 1p. 07262:144.
- 8012120106 Revises 800702 response to Item 2 of IE Bulletin 80-10, "Contamination of Nonradioactive Sys..." Routine sampling program will be established by 810801 for condensate storage tanks & instrument air sys.

 TRIMBLE, D. C. Arkansas Power & Light Co. 80/10/30. 1p. 07231:358.
- 8012170362 Forwards IE Info Notice 80-38, "Gracking in Charging Pump Casing Cladding." No written response required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/10/30. ig. 07269:030.

- 8012020144 Forwards response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" & 800919 revised orders for mod of licenses. Remaining open items refer to changing requirements rather than actual deficiencies. CAVANAUGH. W. Arkanses Power & Light Co. 80/10/31. 700pp. 06916:001.
- 8012120224 Forwards IE Insp Repts 50-313/80-17 & 50-348/80-17 on 800822-0921 & notice of violation. HADBEN.O.L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. 80/10/31. 2pp. 07237:184.
- --8012120231 Notice of violation from insp on 800822-0921. # Region 4, Dallas, Office of the Director. 80/10/31. 2pp. 07237: 186.
- --8012120237 IE Insp Repts 90-313/80-17 % 50-368/80-17 on 800822-0921.
 Noncompliance noted; inoperable containment cooling units,
 failure to submit LER & inadequate control of containment
 bldg purge.
 JUHNSDM, M. D., CALLAN, L. J., HUNNICUIT, D. M. Region 4, Dallas, Office
 of the Director. 80/10/31. 13pp. 07237:188.
- 8012150021 Forwards response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," fulfilling NRC 800919 orders for mnd of license.Util is currently evaluating each component to determine documentation status.W/o encl. CAVARRAUGH, W. Arkansas Power & Light Co. 80/10/31. 8pp. 07241:044.
- 8012170816 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/10/31. lp. 0/266:013.
- 8012230028 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. SEYFRIT. K.V. Region 4. Dallas, Office of the Director. 80/10/31. ip. 07311:210.
- B012100625 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. B0/11/06. 1p. 07220:080.
- 8012030709 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required, SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/07. 1p. 07150:175.
- 8012080595 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 SEYFRII.K.V. Region 4, Dallas, Office of the Director. 80/11/10, 1p. 07183:014.
- 8012040024 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 80/11/14. 1p. 07169:301.
- 8012240323 Ack receipt of 801030 ltr informing NRC of steps taken to correct violation noted in IE lnsp Repts 50-313/80-18 & 50-365/80-18.

 HADBEN.C.L. Region 4, Ballas, Reactor Operations Nuclear Support Branch, 80/11/25, 1p. 07325:138.
- ~-8012240331 Responds to NRC 801020 ltr re violations noted in IE Insp Repts 50-313/80-18 & 50-348/80-18, Corrective actions: Sampling analysis or monitoring program established on 800801 revised. TRIMBLE,D.C. Arkansas Power & Light Co. 80/10/30. 2pp. 07325:139.
- 8012240033 Ack receipt of 801121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-17 & 50-368/80-17. MADEEN.G.L. Region 4, Dalles, Reactor Operations Nuclear Support Branch. B0/12/02 ip. 07324: 222.
- --8012240038 Responds to NRC 801031 ltr re violations noted in IE Insp Repts 50-313/80-17 & 50-368/80-17. Corrective action: shift supervisor counsalied re proper coordination & control of all operations. TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/21. 7pp. 07324:223.

- 8012110284 Ack receipt of 801112 itr informing NRC of steps taken to correct violations noted in IE insp rept % of payment of civil penalties.

 THEMPERON, D. Office of Inspection & Enforcement, Office of the Director. 80/12/04. 1p 07223:236.
- R. Periodic operating reports & related correspondence
- 8012160414 Forwards monthly operating rept for Nov 1980. TRIMBLE, D.C. Arkansas Power & Light Co. 80/12/12. ip. 07252; 353.
- --8012160415 Monthly operating rept for Nov 1980. PENDERGRAFT, R. Arkansas Power & Light Co. 80/12/12. 5pp. 07292:354.
- S. Reportable occurrences. LERs & related correspondence
- 8012030697 Forwards revised LER 80-009/03X-1.
 PROBABLE DELETE: DUPE OF 8011210584.
 TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/17. 1p. 07151:143.
- B012010370 Forwards updated LER 79-022/99X-1.
 TRIMBLE, D. C. Arkansas Power & Light Co. B0/11/19, tp. 07091: 278.
- --8012010381 Updated LER 79-022/99X-1: on 790322, changes in control circuitry of containment cooling Pans discovered inadvertently omitted Caused by oversight Mods completed. SHIVELY, C. N. Arkansas Power & Light Co. 80/11/19. 4pp. 07091: 279.
- 8012010315 Forwards updated LER 79-033/01X-1. TRIMBLE.D.C. Arkansas Power & Light Co. 80/11/20. ip. 07092:145.
- --8012010324 Updated LER 79-033/01X-1: on 790514, unisolatable leak discovered at seal cavity pressure sensing line to 2PT-6004 For reactor coolant pump 2P32A. Caused by mechanical fatigue resulting from low stress cyclic loading. Mods complete. SHIVELY.C.N. Arkansas Power & Light Co. 80/11/20. 4pp. 07792: 14A
- 8012010331 Forwards updated LER 79-067/04X-1. TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/20. 1p. 07092:159.
- --8012010340 Updated LER 79-047/04X-1: on 79080B, auxiliary bldg radwaste area radiation monitor 2RE-8542 sample pump found to have broken pump/motor coupling. Cause unstated. Qualified coupling replacements installed.

 SHIVELY.C. N. Artansas Power & Light Co. B0/11/20. 1p. 07092: 140.
- 8012010402 Forwards updated LER 80-019/03X-1.
 TRIMBLE, D. C. Arkanses Power & Light Co. 80/11/21. 1p. 07097:037.
- --B012010406 Updated LER B0-019/03X-1: on 800410, leak found on reactor makeup water tank supply to charging pump section. Caused by cracking induced by vibration. Pipe spool piece w/defect replaced & addl supports installed.
 SHIVELY, C. N. Arkamsas Power & Light Co. 80/11/21. 1p.
- 801203063B Forwards LERs 80-082/03L-0 & 80-083/03L-0. TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/24. ip. 07151: 152.
- --B012030441 LER 80-082/03L-0:en 801030; during Mode 1 operation plant computer failed. Caused by grounding problems due to voltage spikes. Neiding grounds relocated & computer returned to syc. PENDERORAFT, R. Arkansas Pouer & Light Co. 60/11/25. 1p. 07151:153.
- --8012030443 LER 80-083/03L-0: on 801103.during Mode 1 operation Sigma indicators on remote shutdown panel 2080 discovered inoperable. Caused by machanically stuck indicator. Barva motor replaced & indicator calibr. PEHOERDRAFT.R. Arkansas Power & Light Co. 80/11/25, 1p. 07151:154.
- 8012020458 Forwards LER 60-081/03L-0.
 TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/25. 1p. 07143:242.
- --8012020461 LER 80-081/03L-D: on 801030, fire watch not maintained continuously while pipe to 2VUC-21 through fire barrier replaced. Caused by iradequate written specs. New control of maint procedures addresses problem. PENDERGRAFT.R. Arkansas Power & Light Co. 80/11/25. ip. 07143: 243.
- 8012090368 Forwards revised LER 80-045/04X-2.
 TRIMBLE, D.C. Arkansas Power & Light Co. 80/12/02. ip. 07203:014.

- --B012090395 Revised LER 50-045/04X-2:on 800702, 0823 & 1102, condenser offgas radiation monitor ZRE-0645 found inoperable. Caused by poisture buildup in piping & subsequent damage to condenser. No cause found for latest event. SHIVELY, C. N. Artansas Power & Light Co. B0/12/02. 1p. 07203:017.
- 8012090420 Forwards LER 80-086/03L-0. TRIMBLE, D. C. Arkansas Power & Light Co. 80/12/03. ip. 07203:032.
- --8012090428 LER 80-086/03:-O on 801103, leak discovered on sensing line of reactor coolant pump delta p transmitter for 2P328. Caused by vibration induced fatigue due to binding in heli-coil adjacent to valve. Line replaced & repositioned.

 SMIVELY.C.N. Arkansas Power & Light Co. 80/12/03. 1p. 07203:033.
- 8012090453 Forwards LER 80-076/03L~0.
 TRIMBLE, D. C. Arbansas Power & Light Co. 80/12/03. 1p. 07203:055.
- --8012070463 LER 80-076/03L-0:cn 801103, emergency feedwater pump 2P7A found inoperable due to broken terminal connection screw. On 800723, pump declared inoperable due to loss of control power. Caused by excessive use & incorrect recorder hookup. SHIVELY.C.N. Arkansas Power & Light Co. 80/12/03. 1p. 07203:056.
- 8012100555 Forwards revised LER 80-078/03x-1. TRIMBLE.D.C. Arkansas Fower & Light Co. 80/12/04. 1p. 07218:147.
- --8012100560 Revised LER 80-078/03X-1: on 801014,B MPST pump 2P89B tripped on overcurrent Caused by motor bearing misalignment on inboard motor bearing, Rotor balanced & notor bells replaced. PENDERGRAFT, R. Arkansas Power & Light Co. 80/12/04. 1p. 07218: 148.
- 8012150037 Forwards LER 80-085/03L-0. IRIMBLE D.C. Arkansas Power & Light Co. 80/12/09. 1p. 07237:281.
- --8012159088 LER 80-085/03L-0: on 801111, core protection calculator (CPC)
 A link failed Caused by data link failure between CPC
 channel & operator console. Data link card replaced &
 bypasses removed.
 SHIVELY.C.N. Arkansas Power & Light Co. 80/12/09. Ep.
 07237: 282.
- 8012150087 Forwards updated LER 80-040/03X-1.
 IRIMBLE.D.C. Arkansas Power & Light Co. 80/12/09. 1p. 07237: 283.
- --B012150090 Updated LER S0-060/03X-1: on B00730, core protection calculator D failed & on B01120 calculator C failed Cause undertermined. Watchdog timor timed out preventing communications. Says reinitialized & bypasses removed. SHIVELY, C. N. Arkansas Power & Light Co. 80/12/09, 1p. 07237: 284.
- 80122Y0020 PNO-IV-80-40:cn 801205, shaft coupling emergency feedwater pump to electric motor twisted in two when emergency feedwater pump bearings soized. Event followed natural scram when main feedwater valve failed to open. Repair underway. JOHNEON: M. D. RUNNICUTT, D. K. MADSEN: 6. L. Region 4, Dallas, Office of the Director. 80/12/09 1p. 07337:076.
- 8012170623 Forwards LER 80-084/03L-0.
 TRIMPLE, D. C. Arkansas Power & Light Co. 80/12/11. 1p. 07264:230.
- --B012170630 LER 80-084/031-0:on B01118; valve strate time of MSIV 20V-1010 exceeded limit. Caused by valve internal damper adjustment drift. Valve adjusted & retested, PENGERGRAFT.R. Arvansas Power & Light Co. B0/12/11. 1p. 02264:231
- 8012180240 Forwards revised LER 80-031/03X-1. TRIMBLE D.C. Arkansas Power & Light Co. 80/12/15, ip. 03793:361.
- --8012180243 Revised LER 60-031/03X-1: on 800527, condenser offgas radiation monitor 2RITS-0645 found inoperable. Caused by sample notor bearing failure. Bearing replaced, SHIVELY, C. N. Arkansas Power & Light Co. 80/12/15, ip. 03793: 362.
 - TR 79-006/03X-1. ht Co. 80/12/15, 1p. 0730B: 334.

- 801229C025 PNO-IV-80-40A: Unit 2 remains in cold shutdown following manual scram on 801205. Pump components replaced in emergency feedwater pump including rotating assembly. Test indicated pump curve drapped off at upper end. Evaluation continues. JOHNSON W.D., HUNNICUTT.D.M., MADBER, G.L., Region 4, Dallas, Office of the Director. 80/12/15. ip. 07339:075.
- DOCKET 50-949 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 5 implementation dates will be pet. EISENHUT.D.G. Division of Licensing. B0/10/31. 7pp.
- 8012010422 Denies 800813 request that proprietary versions of info re electrical equipment qualification & Westinghouse affidavit CAM-80-91 be withheld (ref 10CFR2 790).
 YOUNGBLOOD B.J. Licensing Branch 1. 80/11/12. 4pp. 06916:001.
- 8012010536 Requires submittal of plans & schedule for installation of appropriate hydrogen control sys for degraded core accident situations & detailed description of tests needed to demonstrate effectiveness of proposed sys.

 EISELPAUT.D. G. Division of Licensing, 80/11/14, 3pp. 07098:224.
- 8012020717 Notification of 801124 meeting w/util in Mecklemburg.NC to develop fracture toughness data re General Design Criteria 51.
 BIRKEL.R.A. Licensing Branch 1. 80/11/20, 3pp. 04916:001.
- 8012090127 Notification of 801203-05 meeting w/util in Charlotte.NC to discuss piping sys & support criteria implementation. BIRKEL.R.A. Licensing Branch 1. 80/11/20. 3pp. 07199:199.
- 8012040721 Discusses NRC review of schedular requirements for special low power test program & emergency procedures. Lists schedular requirements to be met. Evaluation to be completed in conjunction w/facility full power ascension program. TEDESCO.R.L. Assistant Director for Licensing. 80/11/21. 2pp. 07170:044.
- 8012090208 Summary of 801117 meeting w/util at site re OL application review.
 BIRKEL, R.A. Licensing Branch 1. 80/11/21. 5pp. 07202:278.
- 8012180501 Summary of B01111-12 sits trip by NRC, util, BMI & XYZYX Info Corp to conduct simulator & control room walk-throughs of emergency procedures. List of review team members & meeting attendess enci.
 CLAYTON-B. Procedures & Test Review Branch. B0/11/21. 7pp. 07272: 001.
- 8012010201 Forwards draft Tech Specs 3.4.7.2.4.4.7.2.2 & Table 3.4-1 re operational leakage for RCS & list of RCS pressure isolation valves, in response to NRC 801006 request. PARKER, N. D. Duke Power Co. 80/11/24. 4pp. 07098;001.
- --8012010225 Proposed Tech Specs 3.4.7.2.4.4.7,2.2 & Table 3.4-1 re RCS operational leakage.
 4 Duke Power Co. 80/11/24. 3pp. 07098:005.
- 8012120229 Forwards summary of 801028-29 meeting w/util in Charlotte,NC re-auxiliary feedwater sys reliability evaluation.
 YOUN031 000, B.J. Licensing Branch 1. 80/11/25. 2pp. 07236:197.
- --B012120238 Summary of 801028-29 meeting w/util in Charlotts,NC reauxiliary feedwater sys reliability evaluation.
 PARR,O.D. Auxiliary Systems Branch. 80/11/20. 5pp. 07236:199.
- 8012050290 Enumerates events contributing to delay in facility fuel loading schedule. Deficiency repts encl. PARKER, N. D. Duke Power Co. 80/11/26. 3pp. 07175:043.
- ---B012050302 Significant Deficiency Repts SD 369/80-20 & SD 370/80-15 re improper loads for design of pipe support/restraints initially reported 801028 Comprehensive program initiated to correct problems. PARKER.H.O. Duke Power Co. 80/11/26. 4pp. 07175:046.

- --8012050314 Significant Deficiency Repts SD 369/80-21 & SD 370/80-14 re LOCA pressure effects not considered in analysis of piping w/cold penetrations initially reported 801031. Comprehensive program initiated to correct problems. PARKER/R. D Duke Power Co. 80/11/26. 3pp. 07175:050.
- 8012050391 Responds to NRC 801105 ltr requesting addl info re effect of split breaks on peak clad temp. Forwards analysis of results of double-ended cold leg break.
 PARKER.W.O. Duke Power Co. 80/12/02. 3pp. 07175:072.
- 8012050446 Informs NRC that structural mods will be made to Category I masoncy walls if results of spectrum reanalysis program identifies walls which do not comply w/specified design criteria.

 PARKER, N. D. Duke Power Co. 80/12/02. 1p. 07171:348.
- B0122204B5 Responds to B00911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENION, H.R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --8012220506 Forwards tabulation % summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANSART.R.L. Effluent Treatment Systems Branch. 80/11/06 8pp.
- 8012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Committee. MIRAQLFA.F. Licensing Branch 3. 80/12/09. 3pp. 07266:098.
- 8012150069 Informs that re-evaluation of schedule indicates Unit 1 could be ready for fuel loading by 810128 instead of 810216 as previously submitted. Reduced number of pipe hangers requiring mods is primary reason for rescheduling. PARKER, W. G. Duke Power Co. 80/12/09. ip. 07239:360.
- 8012220344 Notification of 801217 meeting w/util to discuss auxiliary feedwater sys reliability.
 BIRKEL,R.A. Licensing Branch 1, 80/12/09, 3pp. 07308:339.
- 8012230530 Releases public version of util emergency procedures. FELTON, J. N. Division of Rules and Records. 80/12/12. 1p. 07313:136.
- --8019230535 Forwards public version of revised util emergency procedures. PARKE,N.O. Duke Power Co. 80/12/03. 2pp. 07313:138.
- --B012230537 Public version of revised Emergency Procedure EP/I/A/5000/01, "Immediate Actions & Diagnostics." + Dule Power Co. B0/12/03, 14pp, 07313:140.
- --8012230541 Public version of revised Emergency Procedure EP/1/A/5000/02, "Loss of Reactor Coolant." 4 Duke Power Co. 80/12/03 27pp. 07313:154.
- --8012230543 Public version of revised Emergency Procedure EP/1/A/5000/04. "Steam Generator Tube Rupture."

 → Dule Power Co. 80/12/03. 22pp. 07313:181.
- --8012230546 Public version of revised Abnormal Operating Procedure AP/1/A/5500/05, "Inadequate Core Cooling." + Duke Power Co. 80/12/03. 3pp. 07313:203.
- --8012230548 Public version of revised Abnormal Operating Procedure AP/1/A/5500706, "Loss of Steam Generator Feeduater."
 + Duie Power Co. 80/12/03. 3pp. 07313:206.
- 8012230345 Suppls 801124 ltr re RCS pressure isolation valves in response to NRC 801210 request Valves listed in encl list will be defined as Category A.List includes addl valves in cold leg accumulator discharge lines.

 PARKER.N.C. Duke Power Co. 80/12/18. 3pp. 07311:139.
- 8012300601 Forwards Charlotte-Mecklenburg Environ Coalition leaflet distributed to participants during 801205 & 05 emergency planning drill at facilities. Document may have initiated recent itrs to ASLB requesting reopened hearings. PORTER.N.L. Duke Power Co. 80/12/22. 2pp. 07359: 240.

- F Security, medical, emergency & fire protection plans
- 8012240259 Releases public version of util draft emergency plan. Includes State of NC radiological response plan. FELTON J. N. Division of Rules and Records 80/12/12. 1p. 03768:001.
- --B012240372 Forwards public version of util draft emergency plan & State of NC radiological response plan in support of fixed nuclear facilities.
 PARKER, N. Q. Dute Power Co. 80/03/20. ip. 03768:001.
- --8012240377 Public version of State of NC draft radiological emergency response plan in support of fixed nuclear facilities.
 + North Carolina, State of. 79/10/11. 125pp. 03768:001.
- --8012240381 Public version of util draft emergency plan.

 Duke Power Co. 80/03/20, 100pp. 03768: 001.
- 801.2230330 Outlines health physics program. Concludes that program is effective in reducing radiation exposure to levels ALARA, per util 800804 & 1010 meeting w/MC.
 PARKER, W. O. Duke Power Co. 60712719. 6pp. 07314:095.
- G. Adjudicatory correspondence
- 8012120551 Order granting Carolina Environ Study Group 800815 revised motion to reopen hearing record to consider contentions rehydrogen generation control Matter has obvious safety implications. Revised Contentions 1-4 to be adjudicated. LAZO.R.M. Atomic Safety and Licensing Board Panel. 80/11/25. Spp. 07237: 123.
- B012120535 Order granting in part applicant 800930 motion for summary disposition to allow Commission to issue license for fuel loading, initial criticality & zero power physics test. ASLB will hear evidence re hydrogen generation issue. LAZOLR.M. Atomic Safety and Licensing Board Panel. 80/11/25. 6pp. 07237:128.
- 8012230014 Response in opposition to M Fennel 800926 request to reopen hearing if viewed as late petition to intervene. Certificate of Svc encl.
 MCGARRY.J.M. Duke Power Co. MCGARRY.J.M. Debevoise & Liberman.
 80/12/02. dpp. 07311:174.
- 8012270209 Response to intervener Carolina Environ Study Group 801107 add1 contentions re hydrogen generation control. Contentions 5 & 4 should not be admitted in proceedings. Certificate of Svc ancl.
 CURTISS: J. R. Regulations Division. 80/12/15. | 11pp. 07344: 242.
- 8012300066 Response to Carolina Environ Study Group motion to add further contentions Carolina Environ Study Group add1 Contentions 5 & 6 found factually & logally flawed & merit denial Certificate of Svc encl. MCGARRY, J. M. Duke Power Co. MCGARRY, J. M. Debevoise & Liberman. 80/12/15. 7pp. 07358:347.
- H. General correspondence
- BOI2040COB Ack receipt of BOO911 itr requesting hearing re low pressure containment & danger of hydrogen explosion. Forwards Cormission mat1 addressing concerns. NRC reviewing evacuation plans to determine compliance w/10CFR50. N/o encl. KETCHEN, E. G. Hearing Branch 4. BO/11/14. 3pp. 04915:001.
- --B012040022 Ack receipt of 800525 ltr requesting hearing re low pressure containent & danger of hydrogen explosion. Forwards Commission matl addressing concerns. NRC reviewing evacuation plans to determine compliance w/100FRS. W/o encl. KETCHEN. E. G. Rearing Branch 4. 80/11/14. 2pp. 06915:001.
- 8012150158 Requests hearings be reopened to facility ref SECY 80-107 dtd 800626 re containment thickness.
 NUMNERRAMP.T.W. Affiliation Unknown. 80/12/09. ip. 07187:001.
- 8012190594 Ack receipt of 801015 ltr requesting reopening of hearing to consider problems associated w/TMI-2-type accident. ASLB issued 801125 order reopening operating proceeding rehydrogen generation issue. KETCHEN,E.G. Hearing Branch 4. 80/12/10. 2pp. 07286:177.
- 8012220390 Expresses opinion that emergency evacuation procedures should be improved before OL is granted to facility.
 PRIMM.L.W. Affiliation Unknown. 60/12/10. 4pp. 07304:142.

- 8012290293 Expresses concern re opening of facilities. SPARROW N. Affiliation Uninown. 80/12/19. ip. 07308:001.
- M Antitrust correspondence
- B012300030 Order granting attached licensee commitments, agreed to by util.COJ & NRC.
 TUBRIDY, J. F. Atomic Safety and Licensing Board Panel. 74/05/24.
 21be
- -- GO12300040 Request for order directing licenses be amended per attached conditions. DOJ & util join in motion. Order would terminate NRC prosecutorial role, but NRC would remain as party. Certificate of Svc encl. VOSLER, B. H. Atomic Energy Commission 74/05/13. 9pp.
- @ Inspection reports. IE Bulletins & correspondence
- 8012160042 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Fluoding At Indian Point Unit 2." No written response required. D'AEINY, J.P. Region 2. Atlanta, Office of the Director. 80/10/24. 1p. 07262:176.
- 8012170813 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30,
- 8012170571 Forwards IE Into Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required.
 D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012230050 Forwards IF Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/31. ip. 0/311:248.
- 8012110749 Forwards IÉ Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. G'ABILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/06. 1p. 07224:199.
- 8012030873 Forwards IE info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reacto: Depressurisation." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p. 07150:121.
- 8012080603 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REULLY, J.P. Region 2. Atlanta. Office of the Director. 80/11/10. ip.
- 8012010172 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mig by Valcov Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/14. 1p. 07158:084.
- 8012080645 Ack receipt of 1E Insp Rept 50-369/80-29 on 800924-26.No proprietary info.
 PARKER, N. D. Duke Power Co. 89/11/14. ip. 07187:034.
- --8012080649 Forwards IE Insp Rept 50-369/80-29 on 800924-26.No noncompliance noted.
 MURPHY,C.E. Region 2. Atlanta, Office of the Director. 80/10/27.
 2pp. 07187:035.
- --8012089656 iE Insp Rept 50-369/80-29 on 800924-26 No nancompliance noted Major areas inspected pipe support base plate designs & setsmic analysis for as-built safety-related piping sys.
 ANG.N.P. Region 2. Atlanta. Office of the Director. HERDI.A. R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/20. Spp. 07(87:037.
- 8012020117 Ack receipt of 801024 itr informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-369/80-25 & 50-370/80-15.

 MXRPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. E0/11/20. 1p 07142:110.

- --B012070127 Responds to NRC 800930 ltr re violations & Seviations noted in IE Insp Repts 50-369/80-25 & 50-370/80-15. Corrective actions: fire protection requirements during cutting & welding operations will be revised for clarification. PARKER, N. O. Duke Power Co. 80/10/24. 8pp. 07142: 111.
- --8012020133 Forwards IE Insp Repts 50-369/80-25 & 50-370/80-15 on 800902-05 & notices of violation & deviation. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/30. 2pp. 07142:119.
- --8012020141 Natice of violation from insp on 800902-05.

 * Region 2. Atlanta. Office of the Director. 80/09/25. 2pp. 07142:121.
- ~-8012020147 Notice of deviation from insp on 800902-05. → Region 2, Atlanta, Office of the Director. 80/09/25. 1p.
 07142:123
- --8012020159 IE Insp Repts 50-369/80-25 & 50-370/80-15 on 800902-05.

 Moncompliance noted: welding operations conducted in cable spreading room of Unit 1 over combustible trash & fuel day tanks stored in same room as diesel generator.

 MILLER.U.H. Region 2. Atlanta, Office of the Director.

 CDRLON.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/25. 13pp. 07142:124.
- 8012050055 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Nater Leakage Inside Containment." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/21. 1p. 07173:210.
- 8012170509 Ferwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/26. 1p. 07268:096.
- BO121BO351 Ack receipt of [E Insp Repts 50-369/80-28 & 50-370/80-10 on B00725-1002. No preprietary info. PARKER, M. Cl. Duke Power Co. B0/12/02. 1p. 03794:205.
- --8012180366 Forwards IE Insp Repts 50-367/80-28 & 50-370/80-10 on 800529-1602. No noncompliance noted. STG:R, J. P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. B0/11/12. 2pp. 03794:206.
- --8012180375 IE Insp Repts 50-369/80-28 & 50-370/80-10 on 800929-1002. No noncompliance noted Major areas inspected: emergency planning drill exercise observation & environ protection.

 OIBS014.0.T. Region 2. Atlanta, Office of the Director.
 JENXINS.G.R. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/11/04. 5pp. 03794: 208.
- 8012180674 Forwards Revision 3 of response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts," Results of statistical evaluation of anchor bolt safety features encl. PARKER, H. O. Duke Power Co. 60/12/03, 59pp. 07271:265.
- 8012180397 Ack receipt of IE Insp Repts 50-349/80-31 & 50-370/80-17 on 801020-22. No propriectary info. PARKER, H. D. Dute Power Co. 80/12/04. 1p. 03794: 248.
- --8012180379 Forwards IE Insp Repts 50-369/80-31 & 50-370/80-17 on 801020-22. No noncompliance noted. MURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/14. 2pp. 03794: 249.
- --8012180401 IE Insp Repts 50-369/80-31 & 50-370/80-17 on 801020-22. No noncompliance noted Major areas inspected: IE Bulletins 79-02 & 79-14 & GA training & qualifications.

 AN, N.P. Region 2. Atlanta. Office of the Director. HERDT. A. R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/12. 4pp. 03794:251.
- 8012230458 Discusses status of preservice insp of facility & forwards two addl requests for relief from ABME code requirements resafety & relief nozzles & containment spray heat exchangers. PARKER, U. O. Duke Power Co. 80/12/15. 7pp. 07312:274.
- 8012230459 Informs of insp program developed to demonstrate lack of hole formation in guida thimble tubes of Westinghouse 17X17 fuel assembly array. Insp results provided prior to startup after first Unit 1 refueling gutage.
 PARKER.W.O. Duke Power Co. 80/12/19. 1p. 07314:121.

- 8. Reportable occurrences. LERs & related correspondence
- 8012240083 Part 21 rept re improper operation of E-max isolator part Number 1750115. Single channel isolators 1750141 & 1750115 will be changed out w/Part 1750146. PARKER.W. D. Duke Power Co. 80/11/18. 3pp. 07324: 288.
- BO12040403B Deficiency rept re improper loads used for support/restraint design (LOCA: valve discharge: mismatch). Comprehensive program initiated to identify support/restraints affected.revise design skatches & perform hardware changes.
 PARKER: U. D. Duke Power Co. B0/11/26. 4pp. 07161:35B.
- 8012050270 Enumerates events contributing to delay in facility fuel loading schedule. Deficiency repts encl. PARKER, N. D. Duke Power Co. G0/11/26. 3pp. 07175:043.
- --8012050302 Bignificant Deficiency Repts SD 369/80-20 & SD 370/80-15 re improper loads for design of pipe support/restraints initially reported 801028. Comprehensive program initiated to correct problems. PARXER.H.O. Duke Power Co. 80/11/26. 4pp. 07175:046.
- --B012050314 Bignificant Deficiency Repts SD 369/80-21 & SD 370/80-16 re LDCA pressure effects not considered in analysis of piping w/cold penetrations initially reported B01031. Comprehensive program initiated to correct problems. PARKER.U.O Duke Power Co. B0/11/26. 3pp. 07175:050.
- 8012300606 Forwards supplemental response to Significant Deficiency Repts SD 329/80-18 & 370/80-13 re defective coils in Valcor solenoid valves.per NRC 801114 request.Coils in valves of sys required for fuel loading will be replaced by 810109. PARKER.W D. Duke Pawer Co. 80/12/17. 3pp. 07346:192.
- DOCKE) 50-370 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TML action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISEKHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- B012010422 Denies 800813 request that proprietary versions of info re electrical equipment qualification & Nestinghouse affidavit CAH-BD-31 be withheld (ref 100F82.790). YDUNGGLOOD, 8.J. Licensing Branch 1. 80/11/12, 4pp. 06916:001.
- 8012010336 Requires submittal of plans & schedule for installation of appropriate hydrogen control sys for degraded core accident situations & detailed description of tests needed to demanstrate effectiveness of proposed sys.

 EISENHUT, D. G. Division of Licensing. 80/11/14. 3pp. 07098:224.
- 8012020717 Natification of 801124 meeting w/util in Mecklenburg.NC to devotop fracture toughness data re General Design Criteria 51.
 BIRKEL.R.A. Licensing Branch 1. 80/11/20. 3pp. 06916:001.
- 8012090127 Notification of 801203-05 meeting w/util in Charlotte,NC to discuss piping sys & support criteria implementation. BIRKEL,R.A. Licensing Branch 1. 80/11/20. 3pp. 07199:199.
- BO1204072! Discusses NRC review of schedular requirements for special low power test program & emergency procedures. Lists schedular requirements to be met. Evaluation to be completed in conjunction w/facility full power ascension program. TEDESCO, R. L. Assistant Director for Licensing. B0/11/21. 2pp. 07170:044.
- 8012090208 Summary of 801117 meeting w/util at site re OL application review.

 BIRKEL, R. A. Licensing Branch 1. 80/11/21. 5pp. 07202; 278.
- 8012010201 Forwards draft Tech Specs 3 4.7.2.4.4.7.2.2 & Table 3.4-1 re operational leakage for RCS & list of RCS pressure isolation valves, in response to NRC 801006 request. PARKER, N.O. Dute Power Co. 80/11/24. 4pp. 07098:001.
- --8012010225 Proposed Tech Specs 3.4.7.2.4.4.7.2.2 & Table 3.4-1 re RCS operational leakage.

 + Duke Power Co. 80/11/24. 3pp. 07098:005.
- 8012120229 Forwards summary of 801028-29 meeting w/util in Charlotte.NC re auxiliary feedwater sys reliability evaluation.
 YUUN091,000.8, J. Licensing Branch 1, 80/11/25, 2pp. 07236:197.

- --8012120238 Summary of 80:028-27 meeting w/util in Charlotte,NC reauxiliary feedwater sys reliability evaluation.
 PARR.O.D. Auxiliary Systems Branch. 80/11/20. 5pp. 07236:199.
- 8012050270 Enumerates events contributing to delay in facility fuel loading schedule.Deficiency repts entl. PARKER.W.O. Duke Power Co. 80/11/26. 3pp. 07175:043.
- --8012050392 Significant Deficiency Repts BD 369/80-20 & SD 370/80-15 re improper loads for design of pipe support/restraints initially reported 801028. Comprehensive program initiated to corract problems. PARKER.W.O Duke Power Co. BO/11/26. 4pp. 07175:046.
- --8012050314 Significant Deficiency Repts SD 369/80-21 & SD 370/80-16 re
 LBCA pressure effects not considered in analysis of piping
 W/cold penotrations initially reported 801031 Comprehensive
 program initiated to correct problems.
 PARKER.U.O Duke Power Co. 80/11/26. 3pp. 07175:050.
- BO12050371 Responds to NRC BO1105 ltr requesting addl info re effect of split breaks on peak clad temp. Forwards analysis of results of double-ended cold leg break. PARKER, N.O. Duke Power Co. BO/12/02. 3pp. 07175:072.
- 8012050446 Informs NRC that structural mods will be made to Category I masonry walls if results of spectrum reanalysis program identifies walls which do not comply w/specified design criteria.

 PARKER, W. D. Duke Power Co. 80/12/02. 1p. 07171:348.
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey DENION, H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & surmary of IE survey on low level waste at 81 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. Spp.
- B012150069 Informs that re-evaluation of schedule indicates Unit 1 could be ready for fuel loading by 810128 instead of 810216 as previously submitted Raduced number of pipe hangers requiring mods is primary reason for rescheduling. PARKER. H. U. Duke Power Co. B0/12/09. 1p. 07239: 360.
- B012220344 Notification of B01217 meeting u/util to discuss auxiliary faodwater sys reliability.
 BIRKEL.R.A. Licensing Branch 1. 80/12/09. 3pp. 07308:339.
- 8012230345 Suppls 801124 itr ro RCS pressure isolation valves, in response to NRC 801210 request. Valves listed in encl list will be defined as Category A.List includes add1 valves in cold leg accumulator discharge lines.
 PARKER, N. O. Dute Power Co. 80/12/18. 3pp. 07311:139.
- 8012300601 Forwards Charlotte-Mecklenburg Environ Coalition leaflet distributed to participants during 801205 & 06 emergency planning drill at facilities Document may have initiated recent itrs to ASLB requesting reopened hearings. PORTER. U. L. Duke Power Co. 80/12/22. 2pp. 07359:240.
- F. Security, medical, emergency & fire protection plans
- 8012240349 Releases public version of util draft emergency plan. Includes State of NC radiological response plan. FELTON J.M. Division of Rules and Records. 80/12/12. jp. 03748:001.
- ---8012240372 Forwards public version of util draft emergency plan & State of NC radiological response plan in support of fixed nuclear facilities. PARKER, N. O. Dube Power Co. GO/03/20. 1p. 03768:001.
- --8012240377 Public version of State of NC draft radiological emergency response plan in support of fixed nuclear facilities.

 * North Carolina: State of: 79/10/11. 125pp. 03768:001.
- --8012240381 Public version of util draft emergency plan.
- 8012230330 Outlines health physics program. Concludes that program is effective in reducing radiation exposure to levels ALARA.per util 800806 & 1010 meeting w/RRC.
 PARKER.N. D. Duke Power Co. 80/12/19. 6pp. 07314:095.

G Adjudicatory correspondence

- 8012120551 Order granting Carolina Environ Study Oroup 800815 revised notion to reopen hearing record to consider contentions rehydragen generation control. Natter has obvious safety implicational Revised Contentions 1-4 to be adjudicated. LAZOLRIM. Atomic Safety and Licensing Board Panel. 80/11/25. 5pp. 07237:123.
- E012120555 Order grenting in part applicant 800930 motion for summary disposition to allow Commission to issue license for fuel loading initial criticality & zero power physics test. AELB uill hear evidence re hydrogen generation issue. LAZO,R.O. Atomic Safety and Licensing Board Panel. 80/11/25. 6pp. 07237:128.
- 8012230014 Response in opposition to M Fennel 800926 request to reopen hearing if viewed as late petition to intervene. Certificate of Svc encl MCGARRY. J. M Debevoise & Liberman. 80/12/02. 4pp. 0/311:174.
- B012270207 Response to intervenor Carolina Environ Study Group B01107 addl contentions re hydrogen generation control. Contentions 5 & 6 should not be admitted in proceedings. Certificate of Svc encl.

 CURTISS, J. R. Regulations Division. 80/12/15. 11pp. 07344: 242.
- 8012300046 Response to Carolina Environ Study Group motion to add further contentions Carolina Environ Study Group add1 Cantentions 5 & 6 found factually & legally flawed & merit denial Certificate of Svc encl. MCGARRY.J.M. Duke Power Co. MCGARRY.J.M. Debevoise & Liberman, 80/12/15. Ppp. 07358:349.

H. General correspondence

- 8012040008 Ack receipt of 800911 ltr requesting hearing re low pressure containment & danger of hydrogen explosion. Forwards Commission matl addressing concerns. NRC reviewing evacuation plans to determine compliance w/1002FF50. W/o encl. KEICHEN.E.G. Hearing Branch 4. 80/11/14. 3pp. 06915:001.
- --B012040027 Att receipt of 800725 ltm requesting hearing me low pressure containent & danger of hydrogen explosion. Forwards Commission mati addressing concerns. RRC reviewing evacuation plans to determine compliance w/1007R50. Myo encl. KETCHEN.E.G. Hearing Branch 4. 80/11/14. 2pp. 06915:001.
- E012150198 Requests hearings be reopened no facility nef SECY 80-107 dtd 800626 ne containment thickness. MUNNEMARY, T. K. Affiliation Unknown. 80/12/09. 1p. 07187:001.
- B012190534 Act receipt of B01015 ltr requesting reopening of hearing to consider problems associated w/TM1-2-type accident.

 ASLB istued B01125 order reopening operating proceeding re hydrogen generation issue.

 KETCHEN.E. G. Hearing Branch 4 80/12/10. 2pp. 07286:177.
- E012220370 Expresses opinion that emergency evacuation procedures should be improved before QL is granted to facility. FRIMM-L.W. Affiliation Unknown. B0/12/10. 4pp. 0/304:142.
- 8012290293 Expresses concern re opening of facilities. SPARROW.K. Affiliation Unknown. BO/12/19. 1p. 07308:001.

M. Antitrust correspondence

- 2012300030 Order granting attached licensee commitments, agreed to by util, 25J & NRC.
 TUSRIBY, J. F. Atomic Safety and Licensing Board Panel. 74/05/24.
 21pp.
- --E012300040 Request for order directing licenses be amended per attacked conditions EOJ & util join in motion. Order would terminate NRC prosecutorial role, but NRC would remain as party. Certificate of Syc encl. VDG-ER
- a Inspection reports. If Bulletins & correspondence
- B012160342 Forwards IE Info Natice B0-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.

 1p.

- 8012170813 Forwards 1E Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30.

 1p.
- 8012170571 Forwards IE Info Notice 80-39, "Malfunction of Solenaid Valves Hig by Valcor Engineering Corp." No written response required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012230050 Forwards IE Circular 80-23, "Potential Defects in Detait Power Sys Emergency Generators." No written response required.

 O'REILIY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31, 1p. 07311:248.
- 8012110/49 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcola Foundry Co. Inc." Hritten response required.

 O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/11/06.
 10.
- BO12030873 Forwards IE Info Notice 80-40, "Excessive Nitragen Supply Pressure Actuates Safety Reliaf Valve Operation to Cause Reactor Depressuriation." No written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/07.
- 8012080603 Forwards IE Info Notice 80-41. "Failure of Bwing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10.

 1p.
- B012040172 Forwards IE Rulletin B0-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 D'RESLLY, J. P. Region 2. Atlanta, Office of the Director. B0/11/14.
- 8012020117 Ack receipt of 801024 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-369/80-25 & 50-370/80-15.

 MURPHYC.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/20. ip. 07142:110.
- --8012020127 Responds to NRC 800930 ltr re violations & deviations noted in IE insp Repts 50-369/80-25 & 50-370/80-15 Corrective actions: fire protection requirements during cutting & welding operations will be revised for clarification.

 PARXER.U.O. Duke Pawer Co. 80/10/24. 8pp. 07142:111.
- --8012020133 Forwards IE Insp. Repts 50-369/80-25 & 50-370/80-15 on B00932-05 & notices of violation & deviation.
 MURPHY.C.E. Region 2- Atlanta, Reactor Construction & Engineering Support Branch. 80/09/30. 2pp. 07142:119.
- --8012020141 Notice of violation from insp on 800702-05.

 † Region 2, Atlanta, Office of the Director. 80/07/25. 2pp
 07142:121.
- --8012920147 Notice of deviation from insp on 800902-05.

 # Region 2, Atlanta, Office of the Director. 80/09/25. 1p.
 07142:123.
- --B012020159 IE Insp Repts 50-369/80-25 & 50-370/80-15 on B00902-05. Noncompliance noted:welding operations conducted in cable spreading room of Unit 1 over combustible trash & fuel day tanks stored in same room as dissel generator. MILLER.N.H. Region 2. Atlanta, Office of the Director. CONLON.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/23. 13pp. 07142:124.
- 8012050055 Forwards IE Bulletin 80-24, "Prevention of Damago Due to Water Leakage Inside Containment," No written response required.

 O'REIL(Y, J. P. Region 2, Atlanta, Office of the Director, 80/11/21.
 1p. 07173:210.
- 8012170909 Forwards IE Info Natice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 60/11/28. 1p. 07268:096.
- 8012180341 Ack receipt of IE Insp Repts 80-369/80-28 & 50-370/80-10 on 800929-1002 No proprietary info. PARKER.H.O. Dute Power Co. 80/12/02. .ip. 03794: 205.

- -8012180365 Forwards IE Insp Repts 50-369/80-28 & 50-370/80-10 on 800929-1002. No noncompliance noted. STOHR: J. P. Region 2. Atlanta: Fuel Facility & Materials Safety Branch. 80/11/12. 2pp. 03794:205.
- --B012180375 IE Insp Repts 50-369/80-28 & 50-370/80-10 on 800929-1002. No noncompliance noted Major areas inspected: emergency planning drill exercise observation & environ protection.

 GI950%,0.**. Region 2. Atlanta. Office of the Director.

 JENKINS,0.R. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/11/04. 5pp. 03794:208.
- 8012180674 Forwards Revision 3 of response to 1E Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts," Results of statistical evaluation of anchor bolt safety features entl. PARKER,N O. Duke Power Co. 80/12/03. 59pp. 07271:265.
- 8012180397 Ack receipt of IE Insp Repts 50-369/80-31 % 50-370/80-17 on 801020-22 No propriectary info. PARKER, N. D. Duke Power Co. 80/12/04. 1p. 03794: 248.
- --8012180397 Forwards IE lnsp Repts 50-369/80-31 & 50-370/80-17 on 801020-22. No noncompliance noted. MURPHY,C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/14. 2pp. 03794:249.
- ~-8012180401 IE Insp Repts 50-369/80-31 & 50-370/80-17 on B01020-22.No noncompliance noted Major areas inspected: IE Bulletins 79-02 & 79-14 & GA training & qualifications.

 AN.W.P. Region 2, Atlanta, Office of the Director. HERDT.A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/12. 4pp. 03794:251.
- 8012230459 Informs of insp program developed to demonstrate lack of hole formation in guide thimble tubes of Westinghouse 17X17 fuel assembly array, insp results provided prior to startup after first Unit 1 refueling outage.

 PARKER.W.O. Duke Power Co. 89/12/19. 1p. 07314:121.
- 5. Reportable occurrences, LERs & related correspondence
- B012240093 Part 21 rept re improper operation of E-max isolator part Number 1750115. Single channel isolatars 1750141 & 1750115 will be changed out w/Part 1750146. PARKER. M.D. Duke Power Co. 80/11/18. 3pp. 07324: 288.
- 8012040408 Deficiency rept re improper loads used for support/restraint design (LOCA, valve discharge, mismatch). Comprehensive program initiated to identify support/restraints affected, revise design stetches & perform hardware changes.
 PARKER, U. D. Duke Power Co. 80/11/26. 4pp. 07161:359.
- 8012050290 Enumerates events contributing to delay in facility fuel loading schedule. Deficiency repts encl. PARKER, U.O. Duke Power Co. 60/11/26. 3pp.
- --8012050302 Significant Deficiency Repts 9D 349/80-20 & 5D 370/80-15 re improper loads for design of pipe support/restraints initially reported B01028. Comprehensive program initiated to correct problems. PARKER, N. D. Duke Power Co. 30/11/26. 4pp.
- ---8012050314 Significant Deficiency Repts SD 369/80-21 & SD 370/80-16 re LOCA pressure effects not considered in analysis of piping w/cold penetrations initially reported 801031. Comprehensive program initiated to correct problems. PARKER, N. O. Duke Power Co. 80/11/26. 3pp. 07175:050.
- 8012300606 Forwards supplemental response to Significant Deficiency Repts SD 369/80-18 & 370/80-13 re defective coils in Valcor solenoid valves.per NRC 801114 request Coils in valves of sys required for fuel loading will be replaced by 810107. PARKER, W. O. Duke Power Co. 80/12/17. 3pp. 07346:192.
- DOCKET 50-373 LASALLE COUNTY STATION, URIT 1 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 inplementation dates will be met. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.

- 8012220358 Ltr to all CP & OL holders for Blacks re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G Division of Licensing, 80/11/04, 4pp.
- 8012010011 Forward: Supplit to AUREG-0487. "Mark II Containment Lead Plant Program Load Evaluation 2 Acceptance Criteria..."

 Deviations: along webses for deviations, are to be documented in design assessment rept during FEAR review YOUNG31 600.8 J. Licensing Branch 1. 80/11/10. 2pp. 06916:001.
- 8012010051 Confirms 801030 plans for 801125 meeting in Chicago, R. to discuss PRC evaluation of regulatory porformance. KEPPLER, J. 9. Region 3. Chicago, Office of the Director. 80/t1/18. 1p. 07098:190.
- 8012010581 Confirms 801017 plans for 801120 meeting in Glem Ellyn, IL to discuss util evaluation of design/ongineering organizations & functions we significant const rework at Gradilities.

 REPPLEM, J. G. Region 3. Chirago, Office of the Director. BO/11/19.

 tp. 0/078:106.
- 8012040660 Forwards request for add1 info re certain deficiencies contained in Section 3 2 of FSAR for iturctures.sys & components subj to operational QA program 0-list. TECESOR.L. Assistant Director for Licensing. 80/11/20. App. 07170:070.
- 6012100714 Notification of 901202 meeting w/BUR licensing review group in Bethesda./MD to discuss status of group issues.
 WILEON.J.R. Licensing Branch 1. 80/11/20. 8pp.
- 80:2040584 Discusses tiRC review of schedular requirements for special low power test program & emergency procedures. Lists schedular requirements to be met. Evaluation to be completed in conjunction offscility full power ascension program. TEDESCO.R.L. Assistant Director for Licensing. 80/11/21. 2pp. 07170:054.
- 8012020301 Forwards tabulation of planned environ qualification testing programs, in response to NRC 801001 ltr.

 ABEL, J. S. Commonwealth Edison Co. 80/11/26. 4pp.
- 8012020465 Schmits response to NAC 801120 questions re-suppression pool column design. Encl info will be included in next revision of design analysis ropt.

 DELOGRACOL 0 Commonwealth Edison Co 80/11/26. 2pp. 07148:236.
- 8012040481 Responds to NRC RC1117 informal questions re suppression pool temp analyses ? forwards proposed revised procedure specifying min number of closure attempts & time to scram after SGRV.

 DELOGUROE, L. C. Commonwealth Edison Co. 80/11/26. 2pp. 07157:266.
- --8012040485 Draft 50RV procedure LOA-NP-02, "Failure of Relief Valve to Seat Properly or Inadvertent Actuation of Safety Relief Valve." « Cormonwealth Edison Co. 80/05/29 4pp. 07157:268.
- 8012160150 Notification of SOLETO meeting w/Mark II owners group in Bethesda,MD to discuss status of improved chugging load ANDERSUIL C Generic Issues Branch, 80/12/02, 1p
- BO12110111 Notification of 601016 meeting u/util in BethesdarMD to discuss util actions re-unique INI-BUE related actions. BBURNIA:A Licensing 2ranch 1 BO/12/04 3pp. 07223:196.
- 8012160008 Rotification of rescheduled 801222 meeting u/util in Bethesda-MD relactions taken by util w/regard to unique TMI-DDM related actions Meetings originally set for 801216. BGURNIA,A Licensing Branch 1 20/12/04. 3pp. 07262:327.
- 8012160032 Notification of 801212 meeting w/Mark II owners group in Bethesda,MD to discuss suppression pool temp limit. SU.T.M. Deneric Issues Branch. 80/12/05. 1p.
- 8012170283 Summary of B01202 meeting w/FNR licensing review group. Bechtel & S&D in Rothesoa: MD re current status of issues & fire protection concerns Rept on LaSalle specific issues WILSOM J. N. Licensing Branch 1. 00/12/05. 21pp.
- 8012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Committee. MIRAGLIA:F Licensing Branch 3. 80/12/05 Spp.

- 801222013: Survey of 6005:4-0828 meetings U/BWR Licensing Review Group in Bethesda, MD relidentification of generic issues, formation of consensus positions! resolutions that will apply to all six plants, Draft working paper enci NIUSON, J. N. Licensing Branch 1 80/12/05, 99pp. 07307:055.
- G012290398 Informs that meeting held to discuss util evaluation of design/engineering organization & functions proved effective in defining scope & orglaining results of util evaluation. FIORCULE Region 3. Obsesso, Reactor Construction & Engineering Support Branch 80/12/08 2pp 07345 348.
- B012310170 Forwards requist for addl info re mechanical engineering & instrumentation control for Ow application review. TEDESCOUR L. Assistant Director for Licensing. B0/12/09. 10pp. 07371-184
- 8012160555 Forwards inservice testing program for Unit 1.inservice insp program.Vols 1 & 2 & preservice insp rept.Vols 1-11.Info available in Central Files only BELGEORGE.L.O. Commonwealth Edison Co. 83/12/12. 2pp. 07321:342.
- E. NRC Safety Evaluation Peport (SER), suppls & correspondence
- 8012220350 Natification of 801217 meeting w/util to discuss all open items re facility SER.both TMI & non-TM1. 90URNIA.A. Licensing Branch (80/12/08. 33pp. 07308:002.
- F. Security, modical, emergency & fire protection plans
- B012120594 Rotification of B10113 meeting w/util in Bethesda.MD to discuss open items re industrial security. B0UKNIA.A. Licensing Branch 1. B0/12/04. 3pp. 07237:153.
- 8012310001 Hofffies that util 800811 revision to station guard training 2 qualification program is acceptable YOUN03LCOD, B.J. Licensing Branch 1, 80/12/15, 2pp. 07371:042.
- G. Adjudicatory correspondence
- 8012110540 Forwards Dlympic Associates thecklist documents re Leckenby audit per 801418 request Internal Nuclear Svcs Corp audit, requested 801503.re Laistle work as being located. Related correspondence M/o encil FIT201880NS.R. Isham, Lincoln & Beale. 80/12/05. 1p. 07222:359.
- N. Utility Final Safety Analysis Report (FSAR) & amends
- 8012190139 Forwards affidavit confirming distribution of FSAR Amends 51 & 52 on 801124-per 770526 ltm.
 DELGEGROE.L.O. Commonwealth Edison Co. 80/12/09. 2pp. 07240:084.
- E012230226 Forwards Amend 53 to facility FSAR Amend transmits response to 11 second round questions 8 voluntary text & response revisions, addressing some open issues previously discussed.

 ABEL, J. S. Commonwealth Edison Co. 60/12/18, 1p. 07317:087.
- ~-8012230229 Amend 53 to FEAR responding to if second round questions & voluntary test 3 response revisions addressing some open issues previously discussed 4 Conmonwealth Edison Co 80/12/18, 146pp. 07317:088.
- G. Inspection reports, 18 Bulletins k correspondence
- 8012170510 Forwards IE Info Natice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director. 80/10/24. ip.
- 8012020/61 Forwards IE Imap Rept 50-373/80-36, on 800825-29 & 0903-05, & notice of violation HETSHIMM R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/10/28 2pp 97144:011.
- ---8012020770 Notice of violation from insp on 800825-29 & 0903-05, 4 Region 3. Chicago, Office of the Director. 80/10/27. lp. 07144:013
- --8012020730 lE Insp Rept 50-373/80-36 & B00835-29 & 0903-05.
 Noncompliance noted mater operator valve torque switch setting lists not controlled & removal of two electrical jumpers not documented.

 MAURALF., MCOREGOR.L., CDINAUGHICN, K. Region 3, Chicago, Office of the Director. 80/10/27 6pp 07194.014.

- B012310464 Forwards IE Insp Pept 50-373/80-41 on B00908-11. No noncampliance noted. KEPPLCR.J.G. Region 3. Chicago, Office of the Director. 60/11/03 2pp. 07370:246.
- --8012310470 IE Insp Rept 50-373/80-41 on 800908-11. No noncompliance noted Major areas inspected onsite staff organization & mgt, safety engineering group & shift technical advisor. WALKER.R. D. JACKIW.I. N. SPESSARD, R. L. Region 3, Chicago, Office of the Director. 80/10/21 12pp. 07370:248.
- 8012230187 Forwards IE Insp Rept 50-373/80-45 on 801027-28 No noncompilance noted. DAVIS.A.B. Region 3: Chicago, Fuel Facility & Materials Safety Branch. 80/11/14. 2pp. 07317:016.
- --Bolt2230193 [E Insp Rept 50-373/80-45 on 801027-28, No noncompliance noted Kajor area inspected radiation protection program. MILLER, D.E. + MUETER, L. J. LOVENDALE, P.C. Region 3, Chicago, Office of the Director. 80/11/12. 4pp. 07317:018.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. Wo encl.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/18.
 4pp.
- 8012240052 Forwards IE Insp Repts 50-373/80-44 & 50-374/80-28 on 801021-23 & 29-30. No nencompliance noted. FIGRELLI.G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/11/19. 2pp. 07324:253.
- --B012240054 IE Insp Repts 50-373/80-44 & 50-374/90-28 on B01021-23 t 29-30.No noncompliance noted Major areas inspected:weld records electrical work activities & QA documentation.
 NeISLER.J.H. BARRETT.P.A. FULLIAMS.C. C. Region 3, Chicago.
 Office of the Director. 80/11/17. 8pp. 07324:285.
- 8012040637 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 60/11/21, 2pp. 07165:339.
- 8012080087 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid " No written response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/11/24
- 8012170552 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange," No written response required.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/26
- 8012190695 Ack receipt of 801125 ltr informing NRC of stags talen to correct violation noted in IE Insp Rept 50-373/80-36.
 HEISHKAN,R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/12/10. ip 07287:335.
- --8012190697 Responds to NRC 801028 ltm re violations noted in IE Interest 50-373/80-36 Corrective actions: cleared two removed electrical jumpers from master jumper log book. DELSCOROE.L. D. Commonwealth Edison Co. 80/11/25. 3pp. 07287:356.
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensess, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl i implementation dates will be met. EISERGRUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012270358 Ltr to all CP & OL holders for BURs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENMUT, D. O. Division of Licensing. 80/11/04. 4pp.

- BO12010011 Forwards Suppl 1 to NUREG-0487, "Mark II Containment Lead Flant Program Load Evaluation & Acceptance Criteria..."
 Deviations, along w/bases for deviations, are to be documented in design assessment rept during FSAR review.
 YOUNGSLOUD, B. J. Licensing Branch 1, 80/11/10. 2pp. 06916:001.
- B012010051 Confirms 801030 plans for 801125 meeting in Chicago. IL to discuss NAC evaluation of regulatory performance. KEPPLER. J. G. Ragion 3. Chicago. Office of the Director. 80/11/18. 1p. 07098:190.
- 8012010591 Confirms 801017 plans for 801120 meeting in Olen Ellyn, IL to discuss util evaluation of design/engineering organizations & functions to significant const resort at facilities.

 XEMPLER, J. 9. Region 3. Chicago. Office of the Director. 80/11/19.
 19. 07098:106.
- B012040650 Forwards request for add1 info re certain deficiencies contained in Section 3.2 of FSAR for sturctures.sys & components subj to operational QA program Q-list. TEDESCO.R. L. Assistant Director for Licensing. B0/11/20. App. 07170:07U.
- 8012040694 Discusses NRC review of schedular requirements for special low power test program & emergency procedures. Lists schedular requirements to be met. Evaluation to be completed in conjunction w/facility full power ascension program. TEDESCO.R L. Assistant Director for Licensing. 80/11/21. 2pp. 07170:094.
- 6012020301 Forwards tabulation of planned environ qualification testing programs, in response to NRC 861001 ltr.
 ABEL.J. S. Commonwealth Edison Co. 80/11/26. 4pp.
- 8012020465 Bubmits response to NRC 801120 questions re suppression pool calumn design. Encl info will be included in next revision of design analysis rept.

 DELOEGROE, L. O. Commonwealth Edison Co. 80/11/26. 2pp. 07148: 236.
- B012040481 Responds to NRC 801117 informal questions re suppression pool temp analyses & forwards proposed revised procedure specifying min number of closure attempts & time to scram after SDRV.

 DELOCOROE: L. O. Commonwealth Edison Co. 80/11/26. 2pp. 07157:266.
- --8012040485 Draft SORV procedure LOA-NB-02, "Failure of Relief Vaive to Seat Properly or Inadvertent Actuation of Safety Relief Valve."

 * Commonwealth Edison Co. 80/05/27, App. 07197:268.
- 8012140190 Notification of 801210 meeting w/Mark II owners group in Bethasda, MD to discuss status of improved chugging load program.
 ANDERSON, C. Oeneric Issues Branch. 80/12/02. 1p.
- BOU2110111 Notification of BO1216 meating w/util in Bethesda,MD to discuss util actions re unique TMI-BUR rolated actions. BDURNIA,A, Licensing Branch 1. 80/12/04. 3pp. 07223:156.
- 8012160008 Notification of rescheduled 801222 moeting w/util in Bethesda.MD re actions taken by util w/regard to unique TMI-BMX related actions. Meetings originally set for 801216. BOURNIA.A. Licensing Branch I. 80/12/04. 3pp. 07262:327.
- 8012160032 Notification of 801212 meeting w/Mark II owners group in Bethesda.MD to discuss suppression pool temp limit. BU.T.K. Oeneric Issues Branch. 80/12/05. ip.
- 8012170/80 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Conmittee. MIRAGLIA.F. Licensing Branch 3. 80/12/09. 3pp.
- 8012290398 Informs that meeting held to discuss util evaluation of design/engineering organization & functions proved effective in defining scope & explaining results of util evaluation. FIGRELLIG. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/08. 2pp. 07345:348.

- E MRC Safety Evaluation Report (SER), suppls & correspondence
- 8012220390 Notification of P01217 meeting w/util to discuss all open items re-facility SER both TMI binon-TMI BOURNIA.A. Licensing Spanch 1. 60/12/08. 33pp. 07308:002.
- F. Security, medical, emergency ℓ fire protection plans
- BO12120594 Notification of BIO113 meeting w/otil in Bethesda.MD to discuss open items re industrial security. BOURNIA.A. Licensing Branch L. 80/12/04. 3pp. 07237:193.
- 8012310001 Nofifies that util 800811 revision to station guard training & qualification program is acceptable YOUNGBLEOD. B. J. Licensing Branch 1. 80/12/15. 2pp. 07371:062.
- G. Adjudicatory correspondence
- 8012110540 Forwards Olympic Associates checklist documents on Leckenby audit per 801118 request Internal Nuclear Svcs Corp audit, requested 801203.re Lasalle work is bring located Related correspondence. W/o enci.
 FITZOIBSONS.R. Isham, Lincoln & Beale. 80/12/05. 1p.
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8012150139 Forwards affidavit confirming distribution of FSAR Amends 51 & 52 on 801134 per 770526 ltm.
 DELGEGROE, L. O. Commonwealth Edison Co. 89/12/08. 2pp. 07240:084.
- B012230226 Forwards Amend 53 to facility FSAR. Amend transmits response to 11 second round questions 5 voluntary test 5 response revisions, addressing some open issues previously discussed.

 ABFI. J. S. Commonwealth Edison Co. 80/12/18. 1p. 07317:087.
- --8012230229 Amend 53 to FBAR responding to 11 second round questions & voluntary text & response revisions addressing some open issues previously discussed.

 4 Commonwealth Edison Co 80/12/18. 146pp. 07317:089.
- G. Inspection reports, IE Bulletins ? correspondence
- 8012170510 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/24.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments W/o encl

 MEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/11/18.
- 8012240052 Forwards 16 Insp Repts 90-373/80-44 & 50-374/80-28 on 801021-23 & 29-30. No noncompliance noted. FIGRELLIG Region 3. Chicago: Reactor Construction 4 Engineering Support Branch. 80/11/19. App. 07324:253.
- --8012240054 IE Insp Repts 50-373/20-44 t t0-374/80-28 on 801021-23 & 29-30. No honcompliance nated Major areas inspected: weld records, electrical work activities \$ 3A documentation. NEISLER, J. H., BARRETI, P. A., BILLIAMS.C.C. Region 3, Chicago, Office of the Director. 80/11/17. Spp. 07324:255.
- 8012040637 Forwards 1E Bulletin 80-24. 'Prevention of Damage Due to Mater Leakage Inside Containment." No written response required.
 KEPPLER, J. G. Region 3. Chicago. Office of the Director. 80/11/21.
 Zpp. 07165:335.
- 8012080087 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid" No written response required. KEPPLER, J. G. Region 3. Chicago. Office of the Director. 80/11/24.
- 8012170552 Forwards IE Info Notice 80-29. Suppl 1. "Broken Studs on Tarry Turbine Steam Injet Flange" No written response required. KEPPLER. J. G. Region 3. Chicago, Office of the Director. 80/11/26. 200.

1

DOCKET 50-376 NORTH COAST NUC FLANT G. Adjudicatory correspondence

8012270528 Reply to applicant 3 NRC contention that withdrawn application should not be dismissed w/projudice. Urges that application be dismissed w/prejudice. Certificate of Svc encl. FERROB, 6. Citizens for the Conservation of Natural Resources, Inc. 80/12/93 9pg. 07332:279

8012240006 Order granting until 801231 for applicant & MRC to file responsive replies to intervenor 801203 argument that applicant motion to withdraw application should be granted u/gregudics.
MDLFE, S. J. Atomic Safaty and Licensing Board Panel 80/12/16. 2pp. 07324:194.

DOCKET 50-992 NATERFORD GENERATION STATION, UNIT 3

A. Application/construction stage documents & correspondence

8012140050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREC-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met EISEUMUT.D.O Division of Licensing. 80/10/31 7pp.

8012020572 Trip rept of 801024 site visit re initial test program & review of FBAR Chapter 14. CLAYTON S. Procedures & Test Review Branch. 80/11/18. 5pp. 07148:007.

8012100559 Forwards request for add1 info required to complete OL review. Response to Rouno 2 requests should be provided no later than 801219. #E02500.R.L. Assistant Director for Licensing. 80/11/19. 4pp.

8012020095 Surmary of 800930~1003 meeting woutil & consultants in New York,NY re Mechanical Engineering Branch review of open items in initial draft EER. KAME,NLF. Licensing Branch 2 E0/11/20, 24pp. 04916:001.

8012100473 Confirms 801202 telcon commitment to Oct 1982 Fuel load date. ASBELL-D.C. Louisiana Pover & Light Co. 80/12/05. 1p. 07218:305.

5012190322 Provides current schedule for QL application review as requested TEDESCORR L. Assistant Director for Cicensing 80/12/05. 2pp. 07286:062.

8012310180 Notification of 810103 meeting u/util in Bethesda.MD for applicant presentation on ultimate heat sink design. MANF.R.F. Licensing Branch 2. 80/12/11. 2pp. 07369:279.

8012180384 Forwards four oversize flow diagrams per NRC 801117 request. Info requested included in FSAR Amend 13 submitted 801121. Info is revised Subsoction 5.2.5.7. Table 5.2-11 & response to Question 211.67. Apeture cards in PSR MAURIN, L.V. Louisiana Fower & Light Co. 80/12/15. 1p. 07270:352.

8012240185 Forwards control room panel & general arrangement Drawings SK-1554-7, SK-1564-8, SK-1564-9, SK-1564-11, GK-1564-12, GK-1564-15, SK-1564-9, SK-1564-20, LDU-1564-9-134, HDFER, C. G. Ebasco Services, Inc. (subs. of Enserch Corp.), 80/12/19. 1p. 07322, 275

E. NRC Safety Evaluation Report (SER), supply & correspondence

8012020375 Summary of 800730-1003 meeting w/otil & consultants in New York-NY re Mechanical Engineering Branch review of open items in initial draft SER KANE-M.F. Licensing Branch 2 80/11/20, 24pp. 06916:001.

K Utility Final Safety Analysis Report (FSAR) & amonds

rids Amend 14 to FSAR. .ouisiana Power & Light Co 80/12/15, 4pp. 07276:248.

l to FSAR. In & Light Co. 80/12/31, 1000pp. 07274:252.

BD1230D408 Centifies svc of updated Amend 14 to FSAR on 801218. ** Neu York: State of 80/12/18. ** Ip. 0/357:319.

Q. Inspection reports. IE Sulletins & correspondence

8012170746 Forwards IE Circular 80-21, "Regulation of Refueling Creus." No written response required SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 80/09/10, ip. 07265:073.

B012020222 Forwards IE Insp Rept 50-382/80-24 on B00816-0915.No noncompliance noted.

MADSEN-9, L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. B0/10/06. 2pp 07133:127.

--8012020228 It Insp Rept 50-382/80-24 on 800816-0915. No noncompliance noted Major areas inspected: operational staffing overall preoperational test program & plant tours.

CONSTABLE G. L., WESTERMAN, T. F. Region 4, Dallas, Office of the Director. 80/10/06. 3pp 07133:129.

B012220694 Responds to IF. Bulletin B0-20. "Failures of Mestinghouse Type W-2 Spring Return to Neutral Control Switches." Specified switches are not used at facility. MAURIN.L.V. Louisians Power & Light Co. 80/10/15. 1p. 07299:270.

8012220699 Responds to IE Bulletin 80-16. "Potential Misapplication of Rosemont, Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes." Eight identified transmitters will remain within FSAR stds. MAURIN,C V. Louisiana Power & Light Co. 80/10/20, 1p. 07299:271.

B012170351 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. BEYFRIT. N. V. Region 4, Dallas, Office of the Director. 80/10/30. 1p. 07269:009.

8012170818 Forwards IE Into Notice 80-39, "Malfunction of Solemoid Valves Hig by Valcor Engineering Corp." No written response is required.

SEYFRIT.K. V. Region 4, Dallas, Office of the Director. BO/10/31.

B012240167 Forwards IE Insp Rept 50-382/26 on 800916-17 & 1007-10 & notice of violation.
SEIDLE,H.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/10/31. 2pp. 07325:017.

--8012240177 Notice of violation from insp on 800916-17 & 1007-10. * Region 4, Dallas, Office of the Director. 80/10/30. 1p. 07325:019.

--8012240(8) IE Insp Rept 50-382/80-26 on 800916-17 & 1007-10.
Noncompliance nuted: failure to follow procedures for protection of installed valves.
STEMART.R.C. Region 2. Atlanta, Office of the Director, ROBERDS.M.J., CROSSMAN.W.A. Region 4. Dallas, Office of the Director. 80/10/30. 6pp. 07325:020.

8012100619 Forwards IE Bullatin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.lnc." Written response required. SEYPRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/06. ip. 07220:090.

8012030878 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. SEYFRII.K.V. Region 4, Dallas, Office of the Director. 80/11/07. 1p. 07150:159.

80(2080575 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/10, tp. 07183:002.

8012040127 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/14. ip. 07158:051.

8012050404 Requests info resulting from review of application reinservice insp of pressure isolation valves. Requests list of pressure isolation valves included in testing program W/four sets of piping & instrumentation diagrams. TEDESCO.R.L. Assistant Director for Licensing. 80/11/17. 3pp. 07175:301.

- 8012050721 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/21.

 1p. 07173:049.
- BD12140D74 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No response required. BEYFRIT,K.V. Region 4, Dallas, Office of the Director. 80/11/24. 1p. 07262:132.
- B012140104 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
 SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/11/26.
 19. 07262:074.
- S. Reportable occurrences, LERs & related correspondence
- 8012190540 Interim Significant Deficiency Rept 19. Target Rock Motor Operated Valves-Bushing Not Staked." High pressure safety injection header shutoff valve found w/loose bushing. Bushings will be corrected & insp by 810630.
 ASWELL, D. L., PADALINO, J., HART, J. Lauisiana Power & Light Co. 80/12/15. 5pp. 07273:318.
- 8012300574 Interim Bignificant Const Deficiency Rept 21 re linear indications in electrical cable tray seismic support clips initially reported in 801124 telcon Performance of clips under actual loading conditions will be investigated.
 ASWELL.D.L., MILHISER.R.J., WILLS.J.L. Louisiana Power & Light Co. 80/12/23. 4pp. 07346:216.
- B0123005B1 Final deficiency rept re Class I vessel control element drive mechanism motor housings mfg L/O final surface penetrant nondestructive examination, initially reported in B01124 telcon. Deficiency determined not reportable. ASHELL, D. L. Louisiana Power & Light Co. 80/12/23. ip. 07346:215.

V. Operator Examinations

- 8012010058 Clarifies min TMI-related requirements for new operator licenses re training during low power testing Operators should experience initiation, maint & recovery from natural circulation mode, TEDESCO.R.L. Assistant Director for Licensing. 80/11/14. 3pp. 07098:197.
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

 A. Application/construction stage documents & correspondence
- 8012140050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISEKHUT.D.Q. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENRUT.D.Q. Division of Licensing. 80/11/04. 4pp.
- 8012010003 Forwards Suppl 1 to NUREO-0487, "Mark [I Cuntainment Lead Plant Pregram Load Evaluation & Acceptance Criteria..."

 Deviations, along w/bases for deviations, are to be documented in design assessment rept during FSAR review YOUNOS! GOD, B. J. Licensing Branch 1. 80/11/12, 2pp. 07098:012.
- 8012040617 Forwards list of specific add1 info required in order to complete review of OL application.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/20. 9pp. 07170: 081.
- B012070205 Summary of B01105-06 meeting w/util re projected fuel load date. BTARK,R.M. Licensing Granch 1. B0/11/20. 7pp. 07202:271.
- 8012100214 Notification of 801202 meeting w/BWR licensing review group in Bethesda.MD to discuss status of group issues. WILSON, J. N. Licensing Branch 1. 80/11/20. 8pp.
- 8012040562 Discusses NRC review of schedular requirements for special low power test program & emergency procedures. Lists schedular requirements to be met. Evaluation to be completed in conjunction wifacility full power ascension program. TEDESCO.R.L. Assistant Director for Licensing. 80/11/21. 2pp. 07170:104

- 80)21:0083 Notification of 801211 meeting w/util in Bethosda.MD for status review & discussion of open items by Containment Sys Branch. STARK.R.M Licensing Branch 1 80/11/24 3pp. 07223:326.
- 8012020448 Informs of plans to construct holding facility for low level radwaste at util.Facility util provide interim storage for 4-yr mar.Const util begin in Mar 1981.

 CURTIS.N.W. Pennsylvania Power & Light Co 80/11/25. ip.
- 8012230474 Forwards Amend 26 to OL containing Revision 18 to FSAR. CURTIS.N.B. Pennsylvania Poder & Light Co. B0/11/26. ip. 07314:301.
- ~~8012230477 Amend 26 to OL containing Revision 18 to FSAR. CUR118.N.W. Pennsylvania Power & Light Co. 80/11/26. 421pp. 07314:303
- 8012160190 Notification of 801210 meeting w/Mark II owners group in Bethesda.MD to discuss status of improved chugging load program. ANDERSON.C. Generic Issues Branch. 80/12/02. 1p.
- 8012070353 Documents current convercial operation dates in response to R Stark request. Unit 1 scheduled for operation during second quarter 1782 & Unit 2 during second quarter 1783. CURTIS.N.W. Pennsylvania Power & Light Co. 80/12/03. 1p. 07201-170
- 80(2110386 Summary of 80(1114 meeting u/util at site re results of NRC caseload forecast panel review & NRC licensing schedule.

 STARK, R.M. Licensing Branch 1. 80/12/04. 4pp. 07223:143.
- 8012160032 Notification of 801212 meeting w/Mark II owners group in Bethesda,MD to discuss suppression pool temp limit. SU.T.M. Generic Issues Branch, 80/12/05. ip.
- 8012170783 Summary of 801202 meeting o/BWR licensing review group. Bechtel & S&W in Bethesda.MD re current status of issues & fire protection concerns Rept on LaSaile specific issues encl.
 MILEON, J. N. Licensing Branch 1. 80/12/05. 21pp.
- 801222013: Summary of 800514-0828 meetings w/DNR Licensing Review Group in Bethesda. MD re identification of generic issues, formation of consensus positions b resolutions that will apply to all six plants. Draft working paper encl.
 WILSON, J. N. Licensing Branch 1. 80/12/05. 99pp.
- 8012110415 Documents util organizational & philosophical concepts re independent safety assessment function outlined at 801014 meating w/NRC Formation of nuclear safety assessment group proposed. CURTIS-N.W. Pennsylvania Power & Light Co. 80/12/08. 5pp. 07222: 348.
- 8012160039 Forwards reactor bldg drawings in response to FSAR Question 312.17 transmitted in MRC 800905 ltr. CURTIS, N. M. Pennsylvania Power & Light Co. 80/12/09, 10pp. 07354-149
- 8012160156 Notification of 801210 meeting w/util & BNL in Bethesdar MD to review util equipment seismic qualification program & current program status. STARK, R.M. Licensing Branch 1, 80/12/09, 3pp. 07263:030.
- 80121603-18 Forwards Drawings C-718, Revision 13 & C-011, Revision 3, in response to FSAR Question 312.18 transmitted in NRC 800905 ltr.
 CURTIS, N. M. Pennsylvania Power & Light Co. 80/12/09. 1p. 07256: 148.
- 8012310037 Forwards Hydrologic & Geotechnical Engineering Branch request for addition of Round 2 questions. Outstanding items: descriptions of heading requirements for seismic Category 1 pipelines & conduits.
 TEDEESCO.R.L. Assistant Director for Licensing. 80/12/09. 7pp. 07371:103.
- 8012220463 Forwards "Equipment Qualification Info Package," per FBAR Question 110.50. Hardcopy available in Central Files. CURTIS.N.W. Pennsylvania Power & Light Co. 80/12/16 lp. 07392-001
- 8012310255 Notification of 810127-27 meeting w/util in Allentown.PA to review util agt structure & technical resources using NUREO-0731 guidelines. STARK.R.M. Licensing Branch 1. 80/12/16. 3pp. 07370:003.

- 8012300306 Forwards proprietary slide presentations to LOCA load specy presented by MND 2. Creare Inc. during 801211 meeting w/util. Withholding requested (ref LOCFR2 790). Presentations available in Central Files only. CURTIS.N.D. Pennsylvania Power 2. Light Co. 80/12/23. 1p. 07356:068.
- F. Security, medical, emergency & fire protection plans
- E012310332 Forwards applicant emergency plan containing revisions required by ASLB 801112 memorandum & order.W/o encl. SNAPP.8.A. Pennsylvania Fower & Light Co. 80/12/19. 2pp. 07351:291.
- 8012310098 Forwards physical security plan for SNM protection. Plan withheld (ref 10CFR2.790) CURTIS.N.W. Pennsylvania Power & Light Co. 80/12/23. 3pp. 073342-275

G. Adjudicatory correspondence

- B012020814 Requests to make limited appearance statement at licensing hearing. Hearings should be staggered & held in Altentoun/Bethlahen so as to allow all to attend BAYLGR.C. J. Affiliation Uninown. B0/fi/17. 1p. 06586:003.
- 8011280038 Order granting extension until 801201 for Commission to consider ALA3-613.
 CHILK:S.J. Office of the Secretary of the Commission. 80/11/21.
- 8012180160 Request to deny applicants' motion for summary disposition of Contention 2 re chlorine jus to studies demonstrating relationship between cancer rates & chlorinated compounds in drinking water. W/Certificate of Svc. HALLIGAN. T. J. Citizens Against Nuclear Dangers. 80/11/24. App. 03791:267.
- RO12020658 Answer in support of applicants' motion for partial summary disposition of Contention 17 (ozone). No genuine issue as to matl fact re-portion of Contention 17 relating to ozone. LAVERTY, J. H. Hearing Branch 1. 80/11/25. 13pp. 07143:314.
- --8012020664 Affidavit evaluating potential environ effects of orone generated by facility 500-kV transmission lines. Prof qualifications & Certificate of Svc encl. GEARS, O. Environmental Engineering Branch. 80/11/25, 10pp. 07143:327.
- 8012120643 Order granting extension until 801222 for parties opposing applicant motion for summary disposition of Contention 17 (erone) to respond to new facts & arguments presented by NRC or applicants per 801104 order.

 BECHNOFER.C. Atomic Safety and Licensing Board Panel. 80/11/28.

 2pp. 07227:296.
- 8012240018 Order extending until 801205 time for Commission to consider ALAB-613.
 HGYLE, J. C. Office of the Secretary of the Commission. 80/12/01.
 1p. 07324:206.
- 112290171 Response to ASLS 801104 memorandum & order inviting further responses to summary disposition requests. Summary disposition of exone portion of Contention 17 should be granted. Certificate of Svc enci.
 SILBERG, J. E. Pennsylvania Power & Light Co. SILBERG, J. E. Allegheny Electric Cooperative, Inc. SILBERG, J. E. Shaw, Pittnan, Potts & Troubridge. 80/12/01. 12pp. 07444:154.
- B012170557 Answer in support of applicant motion for summary disposition of Contention 2 (chlorine). No issue as to any matl fact re Contention 2. Disposition in favor of applicants should be grained. Certificate of Syc encl. LAVERTY, J. H. Hearing Branch 1. B0/12/02. 14pp. 07264:302.
- --8012170663 Discusses potential health effects of chlorine used to control bifouling of heat exchange surfaces in main circulating water sys. Refs supplemental applicants statement of mail facts & prof qualifications encl. LEHR, J. C. Environmental Engineering Branch, 80/12/02 16pp.

ise to applicant's motion for summary disposition re 6 & 17 Metive is financial self-interest not rditing proceedings. ABLB should not be empromising safety. Certificate of Svc encl. itizens Against Nuclear Dangers. 80/12/04. 4pp.

- 8012290525 Order denying Environmental Coelition on Nuclear Power request to place commissioner on ASLB. In all other respects, Commission declines to review ALA8-613. CHILK. S. J. Office of the Secretary of the Commission. 80/12/04. 2pp. 07335:176.
- 8012300053 Response in support of applicants' 801027 motion for summary disposition of Contention 16 re cooling tower discharge. No genuine issue as to mati fact crists. CE Miller & HB Holz affidavits & Certificate of Svc enci. LAVERTY, J. H. Hearing Branch 1. 80/12/05. 8pp. 07356:148.
- --B012300055 Affidavit re Contention 16 Water evaporated in cooling towers will not provide radioactive pathway to environ. Prof qualifications encl. MILLER, C.E. Effluent Treatment Bystems Branch. 80/12/05. 5pp. 07356: 154.
- --8012300060 Affidavit on Contention 16 re cooling tower discharge.Prof qualifications & Certificate of Svc encl. ROLZFM, B. Auxiliary Systems Branch. 80/12/04. 7pp. 07356:161.
- B012300969 Request for partial summary disposition of Contention 17 ra whether 500 kV transmission lines will create electrostatic fields which would adversely affect living organisms along right of day.

 SILDERG, J.E. Pennsylvania Power & Light Co. SILDERG, J.E. Allegheny Electric Cooperative, Inc. SILBERG, J.E. Shaw, Pittman, Potts & Troubridge. 80/12/05. 2pp. 07392:043.
- --8012300075 Statement of matl facts as to which there is no genuine issue to be heard in support of motion for partial summary disposition of Contention 17 re effect of 800 kV transmission line. Certificate of Svc encl. LEIKAWAR.F. Pennsylvania Power & Light Co. LEHMAN, R.F. Allegheng Electric Cooperative, Inc. 80/12/05. 105pp. 07352:045.
- 8012310132 Staff requirements memo re open Commission B01203 Affirmation Session 80-52 & vote on SECY-80-481 & SECY-A-80-175. Requests proposed amends to proposed rules re unclassified safeguards info be published in FR. CHILK. 8. J. Office of the Secretary of the Commission. 80/12/08. 3pp. 07370:020.
- B012300044 Order allowing any party opposing applicants' motions for summary disposition of Contentions 2 % 16 to file responses to new facts & arguments presented in NRC B01202 & 05 answers. Responses to be filed by B10105.
 BECHHOEFER.C. Atomic Safety and Licensing Board Panel. B0/12/09. 1p. 07356:132.
- B012270330 Request for add1 60 days to respond to interrogatories re Contention 6 per ABLB 801112 order. SCHULTZ, O. R. Gusquehanna Environmental Advocates. 80/12/13. ip. 07343:102.
- 8012220428 Forwards corrected version of App F to RF Lehman affidavit in support of partial summary disposition of Contention 17. Error was in cost computation of compressed gas insulated transmission lines. TRAVIESO-DIAZ Shaw. Pittman, Potts & Trowbridge. 80/12/15. 2pp. 07301:183.
- --8012220432 Corrected version of App F to affidavit in support of partial summary disposition of Contention 17.Error was in cost computation for compressed gas insulated transmission line. Svc list encl.

 LEMMAN.R.F. Pennsylvania Pawer & Light Co. 80/12/15. 7pp. 02331-185
- B012290219 Requests denial of intervenor Citizens Against Nuclear Dangers B01124 petition for AELB order requiring applicant to energize transmission lines to conduct ozone tests. Certificate of Byc encl. LAVERTY, J. H. Hearing Brench 1, 80/12/15, 5pp. 07345:027.
- --8012270225 Affidavit re intervenor Citizens Against Nuclear Dangers 801124 request that applicant be required to energize transmission lines to conduct ozone tests. Certificate of Svc encl. 0EARS.G.E. Environmental Engineering Branch. 80/12/15. 7pp. 07345:032.
- B012290222 Forwards CW Elliott B01212 ltr to ASLB requesting background info in order to make limited appearance statement at licensing proceedings. Requests response. BECHDOFFER(C. Atomic Safety and Licensing Board Panel. B0/12/19. ip. 07345:039.
- --8012270227 Requests all relevant background mati in order to prepare limited appearance statement. ELLIGIT.C.W. Thomas & Hair. 80/12/12. 1p. 07345:040.

- 8012290288 Requests to make limited appearance statement at licensing hearings. WYNNELR, Affiliation Unknown 80/12/22. 1p. 07341:193
- 8012310292 Motion for extension until 810109 to answer applicant 801208 motion for partial summary disposition of Contention 17.
 Util & Citizens Against Nuclear Dangers do not oppose motion. Certificate of Svc encl.
 LAVERTY, J. H. Office of the Executive Legal Director. 80/12/24.
 4pp. 07370:155.

H. General correspondence

- 8012270720 Forwards Revision 1 to NUREG-0654. DES for facility. Rept discusses revised role of state & local emergency preparedness & omergency mpt. Facilities will provide desirable reserve margin in generated electricity, H/o encl. YOUNGSLOOD. B. J. Licensing Branch 1. 80/12/11. 1p. 07345:177.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- BO12230474 Forwards Amend 26 to OL, containing Revision 18 to FSAR. CURTIS-N.W. Pennsylvania Power & Light Co. 80/11/26. 1p. O7314:301.
- --B012230477 Amend 26 to OL containing Revision 18 to FSAR. CURTIS.N.W. Pennsylvania Power & Light Co. B0/11/26. 421pp. O7314:303.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012100388 Forwards IE Insp Rept 50-387/80-22 on 800825-28.No noncompliance noted. BRUNNEK.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/01. 2pp. 07217:352.
- --8012100372 IE Insp Rept 50-387/80-22 on 803825-28. No noncompliance noted Major areas inspected:preoperational containment leak test procedures & inservice test program for pumps & valves. REKITO.N.A. Region 1. Philadelphia. Office of the Director. CAFHTON, D.L. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 80/09/30. Bpp. 07217:354.
- 8012110603 Forwards IE Insp Repts 50-387/80-23 & 50-388/80-15 on 800912.15 & 16.No noncompliance noted. CARLSON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 80/10/07. 2pp. 07227:178.
- --8012110607 IE Insp Rept 30-387/80-23 & 50-388/80-15 on 800912.15 & 16. No noncompliance noted. Major areas inspected: facility inspector turnover activities & reactor control rod drive atub tube weld evaluation status.

 DURR.J.P., NARROW.L., MCBREARTY.R. Region 1, Philadelphia, Office of the Director. 80/10/06. 3pp. 07227:180.
- 8012080120 Forwards IE Insp Rept 50-387/80-20 on 800804-0905. No noncompliance noted. BRUNKER.E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 60/10/08. 2pp. 07189:202.
- --B012080125 IE insp Rept 50-387/80-20 on 800804-0905. No noncompliance noted. Major areas inspected: preoperational test program implementation & comparison of FBAR to as-built plant & preoperational test witnessing.

 QALLO,R. M. RHDADB,O. G. NICHDLAS. H. H. Region 1, Philadelphia, Office of the Director. 80/10/07, 14pp. 07189:204.
- B0120B010B Forwards IE Insp Rept 50-387/B0-26 on B0091B-22.No noncompliance noted.
 BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. B0/10/10 2pp. 07(B9:191.
- --8012080115 IE Insp Rept 50-387/80-26 on 800918-22 No noncompliance noted Major areas inspected; hydrostatic testing of reactor pressure vessel & associated piping & tours of containment & reactor bldgs.

 NICHOLASH. Region 1, Philadelphia, Office of the Director. CAPHTON, D.L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/07. 9pp. 07189:193.
- SO12190599 Forwards IE Insp Rept 50-397/80-27 on 800922-25. No noncompliance noted.

 CARLSON-R.T. Region i. Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/15. [2pp. 07288:198.

- --8032190560 IE insp Rept 50-387/80-27 on 80722-25.No noncompliance noted Major areas inspected previous insp findings & licensee audits of preservice insp contractor.

 MCBREARTY,R.A. Region 1. Philadelphia, Office of the Director.

 TRIPPLE Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. G0/10/14. 5pp. 07288:200.
- 8012080384 Ack receipt of 801013 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-387/80-19 & 50-388/80-13. CARLSON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/28. 1p. 07186:294.
- --8012080390 Responds to NRC 800321 ltr re violations noted in IE lnsp Repts 50-387/80-19 & 50-388/80-13 Corrective actions: softeners added to cable trays & memo emphasizing procedural requirements for softener installation issued. CURTIS.N.W Pennsylvania Power & Light Co. 80/10/13. 3pp. 07186:275.
- --8012080373 Forwards IE Insp Repts 50-387/80-19 & 50-389/80-13 on 800722-25 & notice of violation. CARLSDRAR.T. Region I. Philadelphia. Reactor Construction & Engineering Support Branch. 80/03/21. 2pp. 07186:298.
- --8012080396 Notice of violation from insp on 800722-25.

 * Region I, Philadelphia, Office of the Director, 80/08/19. ip.
 07184:300.
- --8012080405 IE Insp Repts 50-387/80-19 & 50-368/80-13 on 800722-25.
 Noncompliance noted failure to provide cable tray softeners.
 BURRLJ.P. Region i. Philadelphia. Office of the Director.
 HCGAUGHY,R.W. Region i. Philadelphia. Reactor Construction &
 Engineering Support Branch. GO/08/19. 5pp. 07186:301.
- B012080358 Ack receipt of 801022 ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-387/80-21 & 50-389/80-14. CARLSD'R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 83/10/32. 1p. 07186:269.
- --8012080363 Responds to NRC 800915 itr re violations noted in IE Insp. Repts 50-387/80-21 & 50-388/80-14. Corrective actions: audit of plant work areas performed & memo issued to foremen requiring gang boses to be checked. CURITS-N.W. Pennsylvania Power & Light Co. 80/10/22. 3pp. 07186: 270.
- --8012080368 Forwards 1E Insp Repts 50-387/80-21 & 50-389/80-14 on 800819-22 & notice of violation.
 CARLSON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/15. 2pp. 07186: 273.
- --8012080370 Notice of violation from insp on 800819-22.

 * Region 1. Philadelphia, Office of the Director. 80/09/12. ig. 07186: 279.
- --8012080378 IE Insp Repts 50-387/80-21 & 50-388/80-14 on 800819-22, Noncompliance noted: failure to control weld filler matl. DURR.J.P. Region I. Philadelphia. Office of the Director. MCGMVGHY,R.W. Region I. Philadelphia. Reactor Construction & Engineering Support Branch. 80/09/12, 7pp. 07186:276.
- 8012190713 Forwards IE Insp Repts 50-337/80-29 & 50-388/80-17 on 801014-17.Nu noncompliance noted. CARLSGUAR.T. Region 1, Philadelphia Reactor Construction & Engineering Support Brench. 80/10/31. 2pp 07288:030.
- --80[2190717 IE Insp Repts 50-397/60-27 & 50-388/80-17 on 801014-17.No noncompliance noted Major areas inspected: licensee work activities & documentation pertaining to installation of safaty-related cables PADLING.R.J. Region 1. Philádelphia. Office of the Director, EBNEIER.S.D. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/30. 6pp. 07288:032
- 8012120178 Forwards If Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07228:318.
- 8012030807 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director, 80/11/07, 1p. 07150:252.

- 6012080430 Forwards IE Info Notice 80-41. 'Failure of Swing Check Valve in Detay Heat Removal Eys at Davis Besse Unit I." No response required GRIEP.8 H Pegion I. Philadelphia, Office of the Director. 60/11/10 Ip 67:02 315
- 2012040031 Forwards IE Bulletin 80-23. "Fattures of Solenoid Valves may by Valcor Engineering Corp." Requires estimate of manquager associated uncorrective actions GRIEF. B.H. Region 1. Philadelphia. Office of the Director. 60/11/14 pp. 07169.316
- B012220555 Advises that written response is required to IE Bulletin 80-23. "Failures of Solehold Valves Hig by Valcor Engineering Corp." First paragraph erroneously stated no written response required GRIER.D H. Region 1, Fhiladelphia, Office of the Director. 80711/19. 1p. 07274-222
- EDIZBIOTBB Responds to IE Bulletin 80 03. "Loss of Charcoal from Std Type II-Tub-Inch Tray Adsorber Cells " One type of cell is used inps cet results showed no signs of screen casing separation. Rept encl CURTIS-N 11 Fernsylvania Fouer 1 Light Co. 80/11/19. 2pp. 07289 183
- 8012040620 Forwards IE Bulletin 80-24, "Prevention of Danage Due to Water Leabage Inside Containment." No unitten response required. GRIER 9 H Region 1. Philadelphia, Office of the Director. 80/11/21. 2pp. 07165.206
- 8012050597 Forwards Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER.B H. Region 1. Philadelphia, Office of the Director. 80/11/24. 1p 07174:CSD
- Reportable occurrences. LERs & related correspondence
- E012230937 Interin deficiency rept re application of non-Q pilot solenoid valvas in safety-related sys. Final rept delayed until Feb 1781 CURTIS.N.U Pennsylvania Power & Light Co. 80/11/16. 2pp. 07318.217.
- 8012010326 Final deficiency rept to 801112 notification of loose cap scrows on Linitorque turque suitches Caused by obsence of locking devices Loctife will be used on all Limitorque torque suitch 6 cap scrows on Units 1 & 2 motor operators. CURTIS.N.M. Pennsylvania Power & Light Co. 80/11/21. 6pp. 07097-206
- 8012020452 Interim deficiency rept.originally submitted 800430, re separation criteria for electrical equipment. Advises that portion of response will not be available until Jan 1981. Final rept will submitted in Feb 1981. CURTIS. ILL. Pennsylvania Fouer & Light Co. 80/11/21. 2pp. 07141:253
- 8012020755 Final deficiency rept re use of Hilti HOI shell anchors first reported on 800523 Project specs will be revised by 801101 to reflect Teledyne Engineering sycs test results. Insp. evaluation & repair to be done by May 1918. GURTIS.N.R. Pennsylvania Power & Light Co. 80/11/21. Spp. 07148 037
- 8012070588 Notifies that final deficiency rept re separation criteria for electrical equagment util be provided in Feb 1981.
 CURTIS:NW. Pennsylvania Power & Light Co. 80/11/21. 2pp.
- FIO12030363 Final deficiency rept.originally submitted on 800523 re use of too large recesses w/Hilti shell anchors. Caused by erromeous valve barses Hild placed on constitute to program developed for static Coyclic test under shear-tension.

 CUSTIS.REW. Pennsylvania Power & Light Co. 80/11/21. 5pp.
- BD12240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel survaces where termination modules are mounted. SHERUSDB. G General Electric Co. 80/12/08. 3pp. 07324:271.
- S012193973 Interio deficiency rept re unsupported anchors between concrete floors & equipment base plates initially reported 801107. Caused by unfilled annular space between pipe shim & CORTIS-IX II. Pennsylvania Pouer & Light Co. B0/12/09. 6pp.

- 8012309661 Interim deficiency rept re denating of Wortinghouse of the breakers, Number & location of all defective circuit breakers not yet determined Corrective action to be completed by 810430.
 CURTIS.N.W. Pennsylvania Power & Light Co. 80/12/19. (**pp. 07399.085.
- V. Operator Examinations
- 8012240190 Forwards facility operating shift personnel qualificated plan for attrition contingency allowance & projected staffing levels info per 801014 meeting request. Ropt withheld (ref 100FR2 790).

 CURTIS.N.W. Pennsylvania Power & Light Co. 80/12/181. *** 07322.272.
- DDCKET 50-088 SUSQUEHANNA STEAK ELECTRIC STATION, UNIT 22

 A. Application/construction stage documents & correspondents
- 8012160050 Ltr to operating plant licensees, DL applicants & CP Folds Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl i implementation dates will be net. EISE/MUT, D. 9. Division of Licensing. 80/10/31. 7pp.
- 8012220388 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISERMUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012040617 Forwards list of specific add1 info required in order to complete review of OL application.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/20 Yep 07170:081.
- 8012090705 Summary of 801105-06 meeting w/util re projected fuel food date. STARK,R.M. Licensing Branch 1. 80/11/20, 7pp. 07202: 271.
- 80120403562 Discusses NRC review of schedular requirements for spacial low power test program & emergency procedures. Lists schedular requirements to be met. Evaluation to be completed in conjunction w/facility full power ascension program. IEDESCO. R. L. Assistant Director for Licensing. 80/11/21. 2pp 07170.104.
- 8012110933 Notification of 801211 meeting w/util in Detherda. 附近 for status review & discussion of open items by Containment fly a Branch. STARK.R.B. Licensing Branch 1. 80/11/24. 马pp. 07223:324.
- 801202044B Informs of plans to construct holding facility for low lever advante at util. Facility will provide interim storage for A-yr mar. Const will begin in Mar 1981. CURTIS.N.W. Pennsylvania Power & Light Co. BO/11/25. lp. 07142:087
- 8012230474 Forwards Amend 26 to OL. containing Revision 1日 to が日本社. CURTIS-N.W. Pennsylvania Power & Light Co. 日の/11/26. まp.
- --8012230477 Amend 26 to OL containing Revision 18 to FBAR.

 CURTIS, N. M. Pennsylvania Power & Light Co. 80/11/26. 421pp.
- 8012160150 Notification of 801210 meeting w/Mark II owners group insection and the second status of improved chunging load program.

 ANDERSON, C. Generic Issues Branch. 80/12/02. ip.
- 8012090353 Documents current commercial operation dates in response R Stark request. Unit 1 scheduled for operation during second quarter 1982 & Unit 2 during second quarter 1983. CURTIS.N.B. Pennsylvania Power & Light Co. 80/12/03. 1p.
- 8012110396 Summary of BO1114 meeting w/util at mite re remults of 科教で caseload forecast panel review & NRC licensing mehedule, STARK,R.M. Licensing Branch I. 80/12/04, 中p. 07223:143.

- B012160032 Notification of 801212 meeting w/Mark II owners group in Bethasda MD to discuss suppression pool tamp limit. SU.T.K. Oeneric Issues Branch. B0/12/05. 1p.
- B012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Cormittee. MIRAGLIA,F. Licensing Branch 3. 80/12/05. 3pp.
- 8012110419 Documents util organizational & philosophical concepts re independent safety assessment function outlined at G01014 meeting w/NRC.Formation of nuclear safety assessment group proposed.
 CURTIS.N. W. Pennsylvania Power & Light Co. 80/12/08. 5pp. 07222:348.
- B012160039 Forwards reactor bldg drawings, in response to FSAR Question 312.17 transmitted in NRC 800705 ltr. CURTIS.N.N. Pennsylvania Power & Light Co. 80/12/09. 10pp. 07256:149.
- 9012160156 Notification of 801218 meeting w/util & BNL in Bethesda, MD to review util equipment seismic qualification program & current program status.

 STARK.R.M. Licensing Branch 1. 80/12/09. 3pp. 07263:030.
- 9012160348 Forwards Drawings C-718, Revision 13 & C-011, Revision 3, in response to FSAR Question 312.18 transmitted in NRC 800905 ltr CURTIS, N. W. Pennsylvania Power & Light Co. 80/12/09. lp.
- 8012310037 Forwards Hydrologic & Geotechnical Engineering Branch request for add1 info re Round 2 questions. Outstanding items: descriptions of heading requirements for seismic Category 1 pipelines & conduits. TEDESCO.R.L. Assistant Director for Licensing. 80/12/09. 7pp. 07371:103.
- 8012220463 Forwards "Equipment Qualification Info Package," per FSAR Ouestion 110.50. Hardcopy available in Central Files. CURTIS-N.W. Pennsylvania Power & Light Co. 60/12/16. 1p. 07322:001.
- BO12310255 Notification of 810127-29 meeting w/util in Allentown.PA to review util mgt structure & technical resources using NUREO-0731 guidelines.
 STARK.R.H. Licensing Branch 1. 80/12/16. 3pp. 07370:003.
- B012300306 Forwards proprietary slide presentations re LOCA load specpresented by KMU & Creare.Inc during B01211 meeting w/util. Withholding requested (ref 10CFR2.790). Presentations available in Central Files only. CURTIS.N.W. Pennsylvania Power & Light Co. 80/12/23. ip.
- F. Security, medical, emergency & fire protection plans
- 8012310302 Forwards applicant amorgancy plan containing revisions required by ASLB 801112 memorandum & order N/a encl. SNAPP.B.A. Pennsylvania Power & Light Co. 80/12/19, 2pp. 07361:291.
- 8012310098 Forwards physical security plan for 8NM protection Plan withheld (ref 102FR2.790). CURTIS.N.W. Pennsylvania Power & Light Co. 80/12/23. 3pp. 07348-275

G. Adjudicatory correspondence

- GO12020814 Requests to make limited appearance statement at licensing hearing Hearings should be staggered & held in Allentown/Bethlehem so as to allow all to attend.

 BAYLOR.C. J. Affiliation Unknown. 80/11/17. ip. 06586:003.
- BO12180160 Request to deny applicants' motion for summary disposition of Contention 2 re chlorine due to studies demonstrating relationship between cancer rates & chlorinated compounds in drinking water. H/Certificate of Svc.
 HALLIGAN: T.J. Citizens Against Nuclear Dangers. BO/11/24. App. 03791:287.
- BO12020658 Answer in support of applicants' motion for partial summary disposition of Contention 17 (ozone). No genuine issue as to math fact re portion of Contention 17 relating to erone.

 LAVERTY, J. H. Hearing Branch 1. BO/11/25. 13pp. 07143:314.

- --B012020464 Affidavit evaluating potential environ effects of ozone generated by facility 500-kV transmission lines.Prof qualifications & Certificate of Svc encl: QEARB.G. Environmental Engineering Branch. B0/11/25. 10pp. 07143:327
- 8012t20643 Order granting extension until 80t222 for parties opposing applicant motion for summary disposition of Contention 17 (ozone) to respond to new facts & arguments presented by NRC or applicants per 801104 order.

 BECHHOSTER, C. Atomic Safety and Licensing Board Panel. 80/11/28, 2pp. 07227: 296.
- 8012240018 Order extending until 801205 time for Commission to consider ALAS-613. HDYLE.J.C. Office of the Secretary of the Commission. 80/12/01. 1p. 07324:206.
- 8012290171 Response to ASLB 801104 memorandum & order inviting further responses to summary disposition requests. Summary disposition of contention 17 should be granted. Certificate of Svc encl.
 SILBERG, J.E. Pennsylvania Power & Light Co. BILBERG, J.E. Allegheny Electric Cooperative, Inc. SILBERG, J.E. Shaw, Pittman, Potts & Troubridge. 80/12/01. 12pp. 07344:154.
- 8012170657 Answer in support of applicant motion for summary disposition of Contention 2 (chlorine) No issue as to any math fact re Contention 2 Disposition in favor of applicants should be granted Certificate of Svc encl. LAVERTY, J. H. Hearing Branch 1. 80/12/02. 14pp. 07264:302
- ~~B012170663 Discusses potential health effects of chlorine used to control bifouling of heat exchange surfaces in main circulating water sys. Rofs supplemental applicants statement of math facts & prof qualifications encl.

 LEHR. J. C. Environmental Engineering Branch. B0/12/02. 16pp. 07264: 314.
- 8012130200 Response to applicant's notion for summary disposition re Contentions 2.16 & 17. Motive is financial self-interest not concern for expediting proceedings. ASLB should not be pressured into compromising safety. Certificate of Svc encl. HALLIOAIJ.T.J. Citizens Against Nuclear Dangers. 80/12/04. 4pp. 07241:078.
- 8012270525 Order denying Environmental Coalition on Nuclear Power request to place commissioner on ASLB. In all other respects, Cammission declines to review ALAS-613. CHILK, S. J. Office of the Secretary of the Commission. 80/12/04. 2pp. 07335:176.
- 8012300053 Response in support of applicants' 801027 motion for summary disposition of Contention 16 re cooling tower discharge-No genuine issue as to math fact exists CE Miller & HB Holz affidavits & Certificate of Svc encl.
 LAVERTY, J. H. Hearing Branch L. 80/12/05. 8pp. 07356:148.
- --8012309054 Affidavit re Contention 16. Water evaporated in cooling towers uill not provide radioactive pathway to environ. Prof qualifications encl. MILLER.C.E. Effluent Treatment Systems Branch. 80/12/05. Spp. 07356: 154.
- --8012300060 Affidavit on Contention 16 re cooling tower discharge Prof qualifications & Certificate of Svc encl. HDLZ, H.B. Auxiliary Systems Branch. 80/12/04. 7pp. 07356:161.
- 8012300059 Request for partial summary disposition of Contention 17 rewhether 500 kV transmission lines will create electrostatic fields which would adversely affect living organisms along right of uay
 SILBERG, J. E. Pennsylvania Power & Light Co. SILBERO, J. E. Allegheny Electric Cooperative, Inc. SILBERG, J. E. Shaw, Pittman, Potts & Trowbridge. 80/12/05. 2pp. 07352:043.
- --B012300075 Statement of matl facts as to which there is no genuine issue to be heard in support of motion for partial summary disposition of Contention 17 re effect of 500 kV transmission line.Cortificate of Svc encl.

 LEHMAND.R.F. Pennsylvania Power & Light Co. LEHMAN.R.F. Allegheny Electric Cooperative. Inc. B0/12/05 105pp. 07352:045.
- 8012310132 Staff requirements memo re upon Commission 801203 Affirmation Session 80-52 & vote on SECY-80-481 & SECY-A-80-175. Requests proposed amends to proposed rules re unclassified safeguards info be published in FR. CHILKIS. J. Office of the Secretary of the Commission. 80/12/08.

- 8012300044 Order allowin; any party opposing applicants' motions for summary disposition of Contentions 2 % to file responses to new facts & arguments presented in NRC 801202 & 05 answers. Responses to be filed by 810105 BECHHUEFER.C. Atomic Safety and Licensing Board Panel. 80/12/09. 1p. 07395:102.
- 8012270330 Request for addl 60 days to respond to interrogatories re Contention 6 per ASLB 801112 order. SCHULTZIG R. Susquehanna Environmental Advocates. 80/12/13. 1p. 07343:102.
- 8012220428 Forwards corrected version of App F to RF Lehman affidavit in support of partial summary disposition of Contention 17. Error was in cost computation of compressed gas insulated transmission lines.

 TRAVEESO-DIAZ Shaw, Pittman, Potts & Trombridge, 80/12/15, 2pp. 07301:183.
- --8012220432 Corrected version of App F to affidavit in support of partial summary disposition of Contention 17. Error was in cost computation for compressed gas insulated transmission line. Set list encl.

 LEHMAN R.F. Pennsylvania Power & Light Co. 80/12/15. 7pp. 07301:185.
- 8012290219 Requests denial of intervenor Citizens Against Nuclear Dangers 801124 petition for ASLB order requiring applicant to energize transmission lines to conduct ozone tests. Certificate of Svc encl. LAVERTY, J. H. Hearing Branch 1. 80/12/15. 5pp. 07345:027.
- --8012290225 Affidavit re intervenor Citizens Against Nuclear Dangers 801124 request that applicant be required to energize transmission lines to conduct ozone tests. Certificate of Svc encl. GEARS. C. E. Environmental Engineering Branch. 80/12/15, 7pp. 07345:032.
- 8012270792 Forwards CW Elliott 801212 ltr to ASLB requesting background info in order to make limited appearance statement at licensing procedings. Requests response.
 BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 80/12/19.
 1p. 07045:037
- --8012270227 Requests all relevant background matl in order to prepare limited appearance statement. ELLIOTX, C.H. Thomas & Hair. 80/12/12. 1p. 07345:040.
- B01227028B Requests to make limited appearance statement at licensing hearings. WYNNE,R. Affiliation Unknown. B0/12/22. 1p. 07341:193.
- 8012310272 Notion for extension until 810107 to answer applicant 801208 motion for partial summary disposition of Contention 17. Util & Citizens Against Nuclear Dangers do not appose motion. Certificate of Svc ancl. LAVERTY. J.H. Office of the Executive Legal Director. 80/12/24, 4pp. 07370:155.

H. Genaral correspondence

- B012290220 Forwards Revision 1 to NUREC-0654, DES for Pacility, Rept discusses revised role of state 2 local emergency preparedness & emergency mpt. Facilities will provide desirable reserve margin in generated electricity, N/o encl. YOUNGSLOOD, B. J. Licensing Branch 1. 89/12/11. 1p. 07345:177.
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8012230474 Forwards Amend 26 to OL, containing Revision 18 to FSAR. CURTIS.N. D. Pennsylvania Power & Light Co. 80/11/26. 1p. 07314:301.
- --8012230477 Amend 26 to OL containing Revision 18 to FSAR. CURITS N W. Pennsylvania Power & Light Co. 60/11/26. 421pp. 07314:303.
- Q. Inspection reports. [E Bulletins & correspondence
- 8012110603 Forwards IE Insp Repts 50-337/80-23 & 50-388/80-15 on 8007(2:15 & 14. No noncompliance noted. CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/07. 2pp. 07227:178.

- --8012110407 IE Insp Rept 50-387/80-23 & 50-388/80-15 on 800912.15 & 16.
 No noncompliance noted Major areas inspected facility
 inspector turnover activities & reactor control rod drive
 stub tube weld evaluation status.
 DURR.J.P., NARRON.L., MCGREARTY.R. Region 1, Philadelphia, Office
 of the Director. 80/10/06. 3pp. 07227:180.
- 8012080394 Ack receipt of 801013 itr informing NRC of steps taken to carrect violations noted in 16 Ensp Repts 50-387/80-19 & 50-388/80-13. CARLSDN/R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/28. 1p. 07186:294.
- --8012080370 Responds to NRC 800821 ltr re violations noted in IE Insp. Repts 50-397/80-19 & 50-388/80-13. Corrective actions: softeners added to cable trays & memo emphasizing procedural requirements for softener installation issued. CURTIS.N.W. Pennsylvanta Power & Light Co. 80/10/13. 3pp. 07186:295.
- --8012080393 Forwards IE Insp Repts 50-387/80-19 & 50-388/80-13 on 800722-25 & notice of violation CARLSGULR.T. Region I, Philadelphia. Reactor Construction & Engineering Support Branch. 80/03/21. 2pp. 07186:298.
- --80120B0394 Notice of violation from insp on 800722-25.

 * Region 1, Philadelphia, Office of the Director. 80/08/19. 1p.
 07184:300.
- --8012080406 IE Insp Repts 50-387/80-19 & 50-388/80-13 on 800722-25.
 Noncompliance moted: failure to provide cable tray softeners.
 DURM: J.P. Region 1. Philadelphia. Diffice of the Director.
 MCGAUGHY: R.W. Region 1. Philadelphia. Reactor Construction &
 Engineering Support Branch. 80/08/19. Spp. 07186:301.
- 8012080358 Ack receipt of 801022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-21 & 50-3887/80-14. CARLSO'-I.R. T. Region 1, Philedelphia, Reactor Construction & Engineering Support Branch. 80/10/30. ip. 07186:269.
- --8012080363 Responds to NRC 800915 ltr re violations noted, in IE Insp. Repts 50-387/80-21 & 50-388/80-14. Corrective actions: audit of plant work anreas performed & memo issued to foremen requiring gang bores to be checked.

 CURTIS.N. W. Pennsylvania Power & Light Co. 80/10/22. 3pp. 07186:270.
- --8012080368 Forwards IE Insp Repts 50-387/80-21 & 50-389/80-14 on 800919-22 & notice of violation CARLBON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/15. 2pp. 07186:273.
- --8012080370 Nutice of violation from insp on 800819-22.

 * Region 1, Philadelphia, Office of the Director. 80/09/12, ip. 07184:275.
- --8012080378 IE Insp Repts 50-087/80-21 & 50-388/80-14 on 800819-22. Noncompliance noted: failure to control weld filler matl. DURR.J.P. Region i. Philadelphia. Office of the Director. KGCAUCHY.R.W. Region i. Philadelphia. Reactor Construction & Engineering Support Branch. 80/09/12. 7pp. 07186:276.
- 8012190713 Forwards IE Insp Repts 50-387/80-29 & 50-388/80-17 on 801014-17.No noncompliance noted. CARLSO'R.F.T. Region i. Philadelphia. Reactor Construction & Engineering Support Branch. 80/10/31. 2pp. 07288:030.
- --8012170717 IE Insp Repts 50-387/80-27 & 50-388/80-17 on 801014-17. No noncompliance noted Major areas inspected: licensee work activities & documentation pertaining to installation of safety-related cables.

 PAOLING.R. J. Region 1, Philadelphia, Office of the Director, ERNETER, S. D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/30. App. 07288:032.
- B01212017B Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director, 80/11/06. 1p. 07228:318.
- 8012930807 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. GRIER, B. H. Region i. Philadelphia. Office of the Director, 80/11/07. lp. 07150:252.

- 8012080438 Forwards [E Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Bosse Unit 1." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. | p. 07182:315.
- 8012040031 Forwards IE Bulletin 80-23. "Fatiures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/14. 1p. 07169:316.
- 8012220655 Advises that written response is required to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.

 GRIER, B. H. Region I. Philadelphia, Office of the Director. 80/11/19. 1p. 07274:222
- B012310383 Responds to IE Bulletin 80-03. "Loss of Charcoal from Std Type II.Tuo-Inch Tray Adsorber Cells." One type of cell is used. Insp rept results showed no signs of screen casing separation. Rept encl. CURTIS.N. U. Pennsylvania Power & Light Co. B0/11/19. 2pp. 07349:184.
- B012040620 Forwards IE Bullotin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. GRIER, B. M. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07165:306.
- B012050589 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. GRIER, B. H. Region i. Philadelphia. Office of the Director. 80/11/24. 1p. 07174:080.
- S. Reportable occurrences, LERs k related correspondence
- 8012230337 Interim deficiency rept re application of non-Q pilot solenoid valves in safety-related sys. Final rept delayed until Feb 1981.
 CURTIS, N. U. Pennsylvania Pawer & Light Co. 80/11/16. 2pp. 07318:217.
- 8012010326 Final deficiency rept re 801112 notification of loose cap screus on Limitorque torque suitches. Caused by absence of locking devices. Loctite will be used on all Limitorque torque suitch 6 cap screus on Units 1 & 2 motor operators. CURTIS. N. W. Pennsylvania Pouer & Light Co. 80/11/21. 6pp.
- 8012020452 Interim deficiency rept, originally submitted 800430, re separation criteria for electrical equipment. Advisos that portion of response will not be available until Jan 1981. Final rept will submitted in Feb 1981. CURTIS-N.W. Pennsylvania Power & Light Co. 89/11/21. 2pp. 07141:253.
- 8012020885 Final deficiency rept re use of Hilti HOI shell anchors first reported on BOOS23. Project specs will be revised by BOI101 to reflect Teledyne Engineering svcs test results. Insp evaluation & repair to be done by May 1781. CURTIS-IA-II. Pennsylvania Power & Light Co. BO/11/21. Spp. 07148:047.
- B012020598 Notifies that final deficiency rept re separation criteria for electrical equipment will be provided in Feb 1981. CURTIS.M.W. Pennsylvania Power & Light Co. 80/11/21. 2pp. 07148:045.
- 8012030663 Final deficiency rept.originally submitted on 800523; re use of too large recesses w/Hilti shell anchors. Caused by erroneous valve bases. Hold placed on const & test program developed for static & cyclic test under shear-tension. CURIIS-N.W. Pennsylvania Pouer & Light Co. 80/11/21. 5pp. 07151; 266.
- 8012240089 Part 21 rept re roactor protection sys flexible conduit defect causing hot shorts if improperly grounded Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted.

 SHERNOOD, O. G. General Electric Co. 80/12/08 3pp.
- 8012190573 Interim deficiency rept re unsupported anchors between concrete floors & equipment base plates, initially reported 801107, Caused by unfilled annular space between pipe shim & anchor. Use of shims around anchors will be discontinued. CURTIS N. N. Pennsylvania Power & Light Co. BO/12/09. App. 07273:312.

- 8012300661 Interim deficiency rept re-densing of Mestinghouse circuit breakers. Number & location of all defective circuit breakers not yet determined. Corrective action to be completed by 810430.

 CURTIS-N.W. Pennsylvania Power & Light Co. 80/12/19. 3pp. 07399-089
- V. Operator Examinations
- 8012240190 Forwards facility operating shift personnel qualifications, plan for attrition contingency allowance & projected staffing levels info per 801014 meeting request. Rept withheld (ref 100FP2, 790).
 CURTIS.M. N. Pennsylvania Power & Light Co. 80/12/18, 1p. 07322:272.
- DOCKET 50-339 ST. LUCIE PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.GL applicants & CP holders. Forwards NUREG-0737 re YM1 action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl i implementation dates will be net. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012020722 Trip rept of 801023 site visit re initial test program & review of FSAR Chapter 14. CLAYTCM.B. Procedures & Test Review Branch. 80/11/05. 5pp. 07147:351.
- 8012160922 Forwards summary of 801023 neeting w/util at site re initial test program & Chapter 14 of plant FSAR.

 BIRKELIR, A. Licensing Branch 1. G0/11/20. 2pp. 07263:004.
- 8012090199 Forwards test schedules for environ qualification of safety-related equipment, in response to NRC 801001 request. Schedules are preliminary, Confirmation of test dates w/designated engineers is advisable.

 UHRIG.R.E. Florida Power & Light Co. 80/12/03. 6pp. 07200:166.
- 8012290495 Responds to 800911 riemo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IF survey.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 200.
- --8012220505 Forwards tabulation & surmary of IE survey on low level waste at 51 reactors Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity, BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. Spp.
- 8012170303 Forwards Nov 1980 const/startup progress rept for facility, URRIO.R.E. Florida Power & Light Co. 80/12/tl. 2pp. 07266:115.
- C. Utility Environmental Report (ER), amends & correspondence
- 8012230426 Discusses Ut. acceptance review Review will be completed if environ rept is supplemented by adequate responses to deficiency questions.

 JARGSLON,S.N. Argonne Mational Laboratory. 80/12/(2. 1p. 07312:262
- G. Adjudicatory correspondence
- 8012140639 Denies request under 100FR2 206, filed on behalf of intervenors in St Lucie Unit 2 CP proceedings, for consideration of environ consequences of Class 9 accidents. Forwards decision setting forth reasons for denial. DENIGN.H.R. Office of Nuclear Reactor Regulation, Director, 80/11/28, 2pp. 07261 289
- --8012160644 Notice of issuance of Director's decision under 100FR2.206, denying request for consideration of environ consequences of Class 9 accidents at facility CASE.E.O. Office of Nuclean Reactor Regulation, Director.
- --8012160717 Director's decision under 100FR2, 206, denying intervenors in St Lucis CP proceeding request for consideration of environ consequences of Class V accidents. Special circumstances do not exist to warrant such action.

 DENTON H.R. Office of Nuclear Reactor Regulation, Director. 80/11/28, 13pp. 07261-293

- 8012230021 Advise: that Kondria requested that Commission reconsider decision not to review ALAS-503. Deadline of 801213 set for determination Supporting menos and CHILKUS U. Office of the Sochetary of the Commission. 80/12/01. 1p. 07311:190
- --8012233027 Notes that station plackaut should be DBE for facility per ALA3-603 Requests commont status review of Task Action Plan A-44 by 800915 AHEARNS J. Commissioners 80708720 tp. 07311:191.
- --8012230037 Submits questions re 800926 status rept of Task Action Plan A-44 on station blackout Plants should be identified which are highly susceptible AHEARNES Commissioners 80/10/24 pp. 97311:195.
- --8012230040 Describes task action plan to resolve ASLAB concern restation blackout 8 responds to 801024 followup questions:

 Draft generic lin encl
 DENIOR, H.S. Office of Noclear Reactor Regulation, Director,
 80711710, 2pp 07311-176
- --8012230090 Disagrees w/ALA8-603 conclusion that station blackout should be considered design basis event for unit Flaws apparent in quantitative criterion, foreclosure of alternatives & assumption re susceptibility BERIZERO,R.M. Probabilistic Analysis Staff (Pre 801119). 80/08/22. Spp. , 07311-178
- --8012230046 Eplicits votes to reconsider no-review decision re ALAB-603.
 Decision must be reached by 801214.
 H-NORIE.J.M. Commissioners 80/11/26. ip. 07311:203.
- 2012240144 Memorandom & order deciding to reconsider generic aspects of ALAB-603 & affirming license amendments re operation during station blackout NAC brief due in 30 days & reply briefs in 50 days
 CHILLS. J. Office of the Secretary of the Commission. 80/12/12.
 4pp. 07324 184
- 8012270190 Natice of reconstitution of ASUAR RS Saliman, chairman & WR Johnson, member BIBHGP,C.J. Atomic Safety, and ticensing Appeal Panel. 80/12/19. 1p. 07344.177.
- 8012290777 Memorandum supporting APC 801212 order that station blackout should be considered as CBE based on threshold values in SRP. BRP. CMAPUNS, B.A. Atomic Safety and Licensing Appeal Panel. 80/12/22. Spp. 07341:133
- 8012300210 Order artending time for Commission to review Director's Decision DD-80-33 until 810107.
 CHI K.S. J. Office of the Secretary of the Commission. 80/12/23. 07355.361
- J. Insurance, b indemnity information
- 8012020478 Forwards Endomsement Go to NECIA Policy NF-227. FIELDER, J. Marsh & McLennan, Inc. , N & M Nuclear Consultants, Inc. Div 80/11/25 Epp. 07120 276.
- Y Utility Final Safety Analysis Report (FSAR) & amends
- B012170425 Forwards Amend 6 to FSAR UHWIG.R.E. Florida Power & Light Co. B0/12/11. 2pp. 07288:293.
- ~-8012190401 Amend O to FSAR.

 → Florida Power % Light Co = 80/12/31. 2000pp. 07288:295.
- M. Antitrust correspondence
- 8012120544 Response to FL Cities' answer to B00912 joint motion to make effective license conditions proposed by applicant, NRC & BDJ. Requests ASLE attach proposed license conditions effective immediately, Certificate of Svc encl.

 BEWEY, L. S Antitrust Division. B0/18/03 23pp. 07237:100.

- 8012270370 Response in apposition to FL Cities 801009 answer to util, MRC & DOJ 800912 joint motion re settlement Immediate implementation of licensee conditions would not prejudice or disadvantage FL Cities Centificate of Svc encl.

 DYM.H. BOUKRIOHT, J. A. Florida Pouer & Light Co. BOUKRIGHT, J. A. Lowenstein, Neuman, Reis, Applied & Toll. 80/12/03 26pp. 07336:150.
- --8012270373 Kinutes of Fort Pierce Utils Authority & Fort Pierce City Commission 760326 special joint meeting. Fort Pierce F1. 76/03/26 13pp. 07336:176.
- --80122Y0375 Summary of Tallahassee City Commissioner 800311 meeting recity involvement in nuclear power.

 * Tallahasse.FL 80/03/11. 12pp. 07336:188.
- --B012290397 Affidavit of RL Hester re City participation in util nuclear operations. City never given opportunity for access to FPL, nuclear units. Excerpts of Houston Lighting & Power & South TX Project 731201 agreement encl, HtST&R.R. U Gainesville.FL B0/07/10. 12pp. 07336:200,
- -8012290404 Order denying Cities of Gainesville & Tallahassee motion for declaratory order. Parties have right to settle or compromise dispute w/o knowledge of petitioner. Util 7/0916 1tr to HC Luff & RA Jablen encl. KING, J. L. U.S. District Court Southern District of Florida. 80/07/03. 10pp. 97336: 213.
- 801230023B Response to intervenor FL Cities 801009 answer to NRC, DOJ & util 80091R joint motion re CP application. Proposed license conditions should be effective immediately. Imposition uill not damage intervenor Certificate of Svc encl. URBAN, J. R. Justice, Dept. of 80/12/03. 15pp. 07358:071.
- P. Operating license stage documents k correspondence
- B012290321 Forwards Revision 3 to QA manual.
 UHRIO, R. E. Florida Power & Light Co. 80/12/17. 1p.
- ---801229032& Revision 3 to QA manual.

 Flarida Power & Light Co. 80/09/30. 89pp.
- Q. Inspection reports: IE Bulletins & correspondence
- 8012170310 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment." No written response required. O'REILLY, J. P. Region 2- Atlanta, Office of the Director. ILLY, J. P. Region 2- Atlanta, Office of the Director. 80/10/24.
- 8012180023 Forwards JE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. O'RELLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/30.
- 8012170422 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. B0/10/31.
- 8012230059 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. 0'REILLY.J.P. Region 2. Atlanta, Office of the Director, 80/10/31. 1p. 07313:232
- e012110736 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/11/06.
- 8012030868 Forwards IF Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/07.
- 2012080194 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Resso Unit 1." No response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/11/10.
- 2012090558 Submits final response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Suitches." Neutral position contact is not wired to any circuit Builtetin not applicable to facility.

 UHRID, R. E. Fiorida Power & Light Co. 80/11/13. 1p. 07189:203.

- 8012040183 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLYJ.P. Region 2, Atlanta, Office of the Director. 80/11/14... tp. 07158:091
- 6012150255 Forwards corrected 601028 transmittal ltr for IE Insp Rept 50-389/80-12. MURPHY.C.E. Region 2: Atlanta. Reactor Construction & Engineering Support Branch. 60/11/30. 1p. 07237:307.
- --8012150258 Corrected transmittal ltr for IE Insp Rept 50-389/80-12. MURPHY.C.E. Region 2: Atlanta: Reactor Construction & Engineering Support Branch. 89/10/28 2pp. 07237:308.
- --B012t30259 Forwards IE Insp Rept 50-389/80-12 on 800914-19 No noncompliance noted. KURPHY.C.E. Region 2- Atlanta, Reactor Construction & Engineering Support Branch. 80/10/28. 2pp. 07237:310.
- --8012150263 IE Insp Rept 50-389/80-12 on 800916-19. No noncompliance noted, Hajor areas inspected; Inspector follows items, licensee identified items & IE bulletins.

 MCFARLAND, C. R. Region 2, Atlanta, Office of the Director.

 BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/27, Spp. 07237:312.
- 8012030046 Forwards IE Bullotin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment:" No written response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 80/11/21. ip. 07173:106.
- B012080024 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid" No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. B0/11/24. ip.
- 8012170512 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange," No written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/26.
 1p. 07268:103.
- B012180199 Ack receipt of 801107 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-389/80-13. MMRPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. B0/11/26. 2pp 03791:355.
- --8012180207 Responds to NRC 801010 ltr re violations noted in IE Insp Rept 50-389/80-13. Corrective actions: valves covered until moved to permanent location & procedural requirement to control used welding filler mat has been incorporated. UHRIG.R.E. Florida Power & Light Co. 80/11/07. 3pp. 03791:356.
- --8012180209 Forwards IE Insp Rept 50-389/80-13 on 800917-19 & notice of violation. MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/10. 2pp. 03791:359.
- --8012180212 Notice of violation from insp on 800917-19. # Region 2. Atlanta. Office of the Director 80/10/09. 1p. 03791:341.
- ---B012180217 lE Insp Rept 50-307/80-13 on BC0917-t9.Noncompliance noted: improper valve storage & inadequate weiding filler control math. KLEIMSDRGE.W.P., VANDOURN.P.K. Region 2. Atlanta, Diffice of the Director. HERDT.A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/08. Spp. 03792:001.
- 8012220614 Forwards suppl to final response to IE Bulletin 80-08, "Examination of Containment Linear Penetration Welds," Previous info clarified w/figures 2: data re butt welds & results of nondestructive examinations.

 UHRIG.R.E. Florida Power & Light Co. 80/12/01, 25pp. 07299:234.
- S. Reportable occurrences, LERs & related correspondence
- B012110564 FQIA request for document entitled, "Summary of Meeting Held on 780605."
 BDRSUM.R.B. Babcock & Wilcox Co. B0/12/02. ip. 07227:154.
- 8012110591 Summary of 780605 meeting w/util to discuss 780514 loss of offsite power at facility draft NRC positions re electrical power grid & incorporation of Reg Quide 1 108 into facility Tech Specs.

 FITZPATRICK.R. Power Systems Branch. 78/06/23. 1p. 07227:155.

- 8012110556 Responds to FOIA request for document antiled, "Summary of Meeting Held on 780605" Forwards document. FELTOR-J. II Division of Pules and Records 80/12/05. 1p. 07227:153
- --B012110560 Summary of 780605 meeting w/util in Bethesda MD re 780514 loss of offsite power at facility & CRNL repts on 780411 & O511 transmission sys disturbances List of meeting attendees & MRC positions encl BIRKEL R. A Light Water Reactors Branch 2. 78/06/07. App.
- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8012160390 Ctr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net EISEKHUY.D. G. Division of Licensing. 80/10/31. 7pp.
- 8012160164 Notification of 801209-10 meeting w/util in Spring City, TN to perform caseload forecast to determine priorities for allocation of NRC manpower.

 KENYCH, T.J. Licensing Branch 2. 80/12/02. 5pp. 07263:033.
- 8012070186 Forwards interim status rept re NRC 800502 request to conduct electrical separation field audit.Final results will be submitted by 810213.

 MILLS.L.K. Tennessee Valley Authority. 80/12/04. 3pp. 07200:149.
- 8012100695 Notification of 801208 meeting u/util & ANL at site to discuss safety & relief valve piping computer model. KENYON.T.J. Licensing Branch 2. 80/12/04. 3pp. 07222:101.
- 8012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Committee. MIRAGLIA.F. Licensing Branch 3 80/12/05. 3pp.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201.
 MILLS.L.M. Tennessee Valley Authority. 80/12/09. 1p. 07243:359.
- F. Sacurity, medical, emergency & fire protection plans
- B012080835 Notification of B01121 meeting w/util in Bethesda,M0 to discuss will position on central emergency response ctr & plans for emergency mgt.

 STAMLE-C. Licensing Branch 2. 80/i1/19. App.
- G. Inspection reports, IE Bulletins & correspondence
- 8012150901 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.
 ip.
- 8012180274 Forwards IE Mgt Meeting Repts 50-438/80-24, 50-439/80-24, 50-390/80-31 & 50-391/80-24 to 800925. No reply required. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/27. 2pp. 03794:040.
- --8012180337 IE Mgt Meeting Repts 50-438/80-24.50-439/80-24.50-390/80-31 \$ 50-391/80-24 on 800925 Major areas discussed: issues identified in Insp. Repts 50-438/80-12, 50-439/80-12, 50-390/80-19 \$ 50-391/80-13 COLEY. J. L. Region 2. Atlanta, Office of the Director. MURPHY.C.E. Region 2. Atlanta, Pactor Construction & Engineering Support Branch. 80/10/24 29p. 03794.042.
- 8012180935 Forwards 1E Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. O'REILLY, J. P. Region 2: Atlanta: Office of the Director. 80/10/30. ip. 03790:098
- 8012170094 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Kig by Valcor Ergineering Corp." No specific action or response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.

 1p.

- 8012230030 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators " No written response required O'REILLY, J.P. Region 2: Atlanta, Office of the Director. 80/10/31.
- 8012110056 Requests assessment & corrective actions taken re-control room ceiling constructed u/apparently flammable titles within 20 days.
 TEOESCO.R.L. Assistant Director for Licensing. 80/11/04. 3pp.
- 8012110807 Forwards IE 3-lletin 80-21. "Valve Yokes Supplied by Malcolm Founday Co.Inc." Written response required. D'REILLY, J.P. Region 2 Atlanta, Office of the Director. 80/11/06. 10.
- 0012030037 Forwards IE Info Notice 80-40. "Erressive Nitrogen Supply Pressure Actuates Safety Relief Value Operation to Cause Reactor Depressuritation "No written response required. O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/11/07.
- 6012080276 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J. P. Region 2- Atlanta, Office of the Director. 80/11/10.

 1p.
- B012040143 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of mangouer associated u/corrective actions. O'REIU Y, J.P. Region 2. Atlanta, Office of the Director.
- 8012080616 Forwards updated response to IE Bulletin 80-07, "Hydramotor Actuator Deficiencies." Util will contact major valve suppliers to determine if add1 deficient actuators were supplied.
 MILLS.L.M. Tennessee Valley Authority. 80/11/17. 3pp. 07188:212.
- 8012110266 Forwards Nechanical Engineering Branch position re inservice insplot pressure isolation valves & requests addl info. List of valves included in program w/PAID diagrams are required. TEDESCO.R.L. Assistant Director for Licensing. 80/11/17. 3pp. 07224:145
- 801202040B Ack receipt of 801027 itr informing NRC of steps taken to correct violations noted in 16 insp Repts 30-390/80-26 & 50-391/80-20.
 LENIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/11/20. 1p 07143: 221.
- --8012020412 Responds to NRC 800930 ltr re violations noted in IE Insp. Repts 50-390/80-26 & 50-391/80-20. Corrective actions:upper head in jection sys test scoping document & test instruction will be revised & data collected will be evaluated. Hit.S.L. K. Tennessee Valley Authority. 80/10/27, 4pp. 07443:222.
- --8012020433 Forwards IE Insp Repts 50-370/80-26 & 50-391/80-20 on 800801-31 & notice of deviation.
 LEHS,R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/09/30. 2pp. 07143:226.
- --8012020435 Notice of deviation from insp on 800801-31.
 4 Region 2, Atlanta, Office of the Director. 80/09/30. ip.
 07143:228
- --8012020441 IE Insp Repts 50-390/80-26 & 50-391/80-20 on 800801-31.

 Noncompliance noted high pressure blowdown test performed U/o providing test acceptance criteria.

 MCCONALD. J. A. Region 2. Atlanta, Office of the Director.

 DANCE, N. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. E0/09/30. 4pp. 07143:227.
- 8012050023 Forwards IE Bulletin 80-24, 'Prevention of Damage Due to Nater Leakage Inside Containment." No written response required. C'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/21.
- 8012080004 Forwards 1E Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/24. 1a.
- S012170359 Forwards IE Info Notice 80-29. Suppl 1. "Broten Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/26.

- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah, Natts Bar & Bellefonte & TVA-TR75-1A. Changes supersede 801201 ltr. Changes will be included in application for OL for Hartsville-Phipps Bend & Yellow Creek plants.
 MICLS.L.M. Tennessee Valley Authority. 80/12/09. Spp. 07266:132.
- S. Reportable occurrences, LERs & related correspondence
- 8012050457 Final deficiency rept, initially reported 800818, re-emergency gas treatment sys fire protection sys supplied w/automatic open head water spray sys Spray nozzles will be replaced w/closed head water spray nozzles.

 MILLS,L.K. Tennessee Valley Authority. 80/09/17. 2pp. 07173:322.
- B012040428 Fourth interim deficiency rept re breakdown in Dravo DA program, initially reported on 800328. Dravo completed inhouse documentation search for Unit 1 piping 2: submitted corrected sletches. Unit 2 documentation search to be completed soon.

 MILLS, L. M. Tennessee Valley Authority. 80/11/24. 2pp. 07170: 122.
- 8012040422 Final deficiency rept re insufficient analysis of 3-inch fire protection line initially reported on 800606. Birteen addl supports per unit needed. Supports will be installed prior to fuel loading. MILLS.L.M. Tennessee Valley Authority. 80/11/25. 2pp. 07170:124.
- 8012040443 Interim deficiency rapt re automated fixed water spray sys in reactor bldg annulus, initially reported on 801027.
 Util in process of modifying fire protection sys in order to encompass addi interaction areas. Addi info due by 801009.
 MILLS, L. M. Tennessee Valley Authority. 80/11/26. 2pp. 07170:116.
- 8012090342 Interim deficiency rept.originally reported on 801031,re improper ueld attachment of shear lugs. Util determined that lugs will be acceptable if 1/4-inch fillet used. Mods completed by Aug 1981. Next rept will be submitted by 810125.
 MILLS.L.M. Tennessee Valley Authority. 80/12/01. 2pp. 07201:165.
- 8012100454 First interim deficiency rept re 3-inch gate valves which failed to clase completely under preoperational test flow conditions. Mods to be developed. Next rept will be submitted by 810323.

 MILLS.L.M. Tennessee Valley Authority. 80/12/01. 2pp. 07219:028.
- 8012100517 First interim deficiency rept re improper shear lug weld attachments in heating, ventilation & air conditionings sys, initially reported on 801030. One-quarter inch fillet weld will correct defects. Next rept by 810125.

 MILLS.L.M. Tennessee Valley Authority. 80/12/01. 2pp. 07219: 348.
- 8012090397 Final deficiency rept initially reported 801030 re failure to use latest revisions of break location summaries for design pipe rupture protective devices. Mods will be completed by Aug 1981 for Unit 1 & May 1982 for Unit 2, MILLS.L.M. Tennessee Valley Authority. 80/12/02. 2pp. 07207:148.
- 8012170425 Third interim deficiency rept re damage to UHI piping hanger. Hangor to be replaced. Insp of piping welds revealed no damage by lifting incident EDS Nuclear & Westinghouse analyzing & evaluating. Add1 info to be submitted by 810213.
 MILLS.L.M. Tennessee Valley Authority. 80/12/12. 1p. 07269: 350.
- 8012170460 Fourth interim deficiency rept re inadequate documentation for miscellaneous mechanical squipment Applicable QC procedures revised to specify proper insp & documentation requirements. Add info to be submitted by 810327.

 MILLS, L. M. Tennessee Valley Authority. 80/12/12. 1p. 07269:239.
- 8012300570 Final deficiency rept re Penn Ventilator Co OA program initially reported on 790618. Util has completed review of drawings & soismic & environ qualification documentation & found all documentation in compliance w/apers.

 MILLS, L. M. Tennessee Valley Authority. 80/12/18. 2pp. 07359: 236.
- 8012310378 First interim deficiency rept re possible error in safety injection sys preoperational test, initially reported 801124. Caused by failure to require that position of all check valves important to test results be checked. MILLS.L.K. Tennessee Valley Authority. 80/12/23. 2pp. 07369:084.

V. Operator Examinations

BO12010956 Clarifies min TMI-related requirements for new operator licenses re training during low power testing Operators should be able to control saturation marginaRCS pressure & heat removal rate w/o exceeding operating limits. TEDESCO.R.L. Assistant Director for Licensing. BO/11/14. 3pp. 07099: 194.

- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, QL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Enci 1 implementation dates will be met. EISEKHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012160164 Notification of 801208-10 meeting w/util in Spring City.TN to perform caselaad forecast to determine priorities for allocation of NRC manpower.
 KENYCH.T.J. Licensing Branch 2. 80/12/02. 5pp. 07263:039.
- 8012090184 Forwards interim status rept re NRC 800502 request to conduct electrical separation field audit. Final results will be submitted by 810213.

 MILLS, L. M. Tonnessee Valley Authority. 80/12/04. 3pp. 07200:149.
- 8012100695 Notification of 801203 meeting w/util & ANL at site to discuss safety & relief valve piping computer model.

 KENYON, T. J. Licensing Branch 2. 80/12/04. 3pp. 07222:101.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201.
 MILLS.L.M. Tennessee Valley Authority. 80/12/07. 19.
- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah. Watts Dar & Bellefonte & TVA-TR75-IA. Changes supersede 801201 ltr. Changes will be included in application for OL for Hartsville. Phipps Bend & Yellow Creek plants. MILLS.L. M. Tennessee Valley Authority. 80/12/09. 5pp.
- F. Security, medical, emergency & fire protection plans
- BO120B0B35 Notification of B01121 meeting w/util in Bethesda.MD to discuss util position on central emergency response ctr & plans for emergency mgt.

 STAKLE.C. Licensing Branch 2. B0/11/19. App.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012150201 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24. ib.
- 8012180274 Forwards IE Mgt Meeting Repts 50-428/80-24,50-437/80-24, 50-397/80-31 & 50-391/80-24 on 800923 Na reply required. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/27. 2pp.
- --8012180307 IE Myt Meeting Repts 50-438/80-24,50-439/80-24,50-390/80-31 & 50-391/60-24 on 800925 Major areas discussed issues identified in Insp Repts 30-438/80-12, 50-409/80-12, 50-390/80-12 & 50-391/80-13 GOLEY, J. L. Region 2, Atlanta, Office of the Director, 80/10/24.
- 8012180035 Forwards IF. Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. D'REILLY.J.P. Region 2. Atlanta. Diffice of the Director. 80/10/30. is.
- B012170004 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mig by Valcor Engineering Corp." No specific action or response required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31. ip.
- 8012230030 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No uritten response raquired. O'REIULY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31. 1p.
- 8012110366 Requests assessment & corrective actions taken re-control room celling constructed w/apparently flammable tiles within 20 days. TEDESCO.R.L. Assistant Director for Licensing. 80/11/04. 3pp.
- 8012110807 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc.," Uniten response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.

- R012030937 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/07. tp.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Suing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10.
- 8012040143 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'RELLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/14.
- 8012080516 Forwards updated response to IE Bulletin 80-07, "Hydramotor Actuator Deficiencies." Util will contact major valve suppliers to determine if addl deficient actuators were supplied.
 MILLS.L.M. Tennessee Valley Authority. 80/11/17. 3pp.
- 8012110366 Forwards Mechanical Engineering Branch position re inservice insplot pressure isolation valves & requests addl info.List of valves included in program w/P&ID diagrams are required. TEDESCO.R.L. Assistant Director for Licensing. 80/11/17. 3pp. 07224:145.
- 8012020408 Ack receipt of B01027 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-390/80-26 & 50-391/80-20.
 LEMIS.R.C. Region 2- Atlanta, Reactor Operations Nuclear Support Branch. 80/11/20. 1p. 07143:221.
- --8012020412 Responds to NRC 803730 ltr re violations noted in IE Insp. Repts 50-370/80-26 & 50-391/80-20. Corrective actions: upper head injection sys test scoping document & test instruction will be revised & data collected will be evaluated. MILLSL. M. Tennessee Valley Authority. 80/10/27, 4pp. 07143: 222.
- --8012020433 Forwards lE Insp Repts 50-390/80-26 & 50-391/80-20 on 800801-31 & notice of deviation. LEMIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/30. 2pp. 07143:226.
- --8012020435 Notice of deviation from insp on 800801-31.

 ≠ Region 2, Atlanta, Office of the Director. 80/09/30. ip.
 07143:228.
- --8012020441 IE Insp Repts 50-390/80-26 & 50-391/80-20 on 800801-31.
 Noncompliance noted:high pressure blowdown test performed u/o providing test acceptance criteria.
 HCDCMALD.J.A. Region 2: Atlanta, Office of the Director.
 DARCE, H. C. Region 2: Atlanta, Reactor Operations Nuclear Support Branch. 80/09/30. 4pp. 07143:229.
- BO12050023 Forwards IE Bulletin BO-24. "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. O'RELLLY.J.P. Region 2. Atlanta. Office of the Director. BO/11/21.
- 8012080204 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Shubber Fluid." No written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24.
- 8012170359 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/26,
- B0121B0331 Forwards IE insp Rept 50-371/80-29 on 800712.No noncompliance noted. KENNA.W.B. Region 2. Atlanta. Safeguards Branch. B0/12/10. 2pp. 03794:230.
- --8012190333 IE Insp Rept 50-391/80-29 on 800912. Ne noncompliance noted. Hajor area inspected: fuel storage.
 ILLIMAN.A., Hill.A., HALL.B. Region 2. Atlanta. Office of the Director. 80/12/10. 1p. 03794:232.

- 5. Reportable occurrences, LERs & related correspondence
- 8012050457 Final deficiency rept.initially reported 800818 re emergency gas treatment sys fire protection sys supplied u/automatic open head water spray sys. Spray notiles will be replaced w/closed head cater spray notile.

 MILLS.L.M. Tennessee Valley Authority. 80/09/17. 2pp. 07173:322.
- 8012040428 Fourth interim deficiency rept re breakdown in Dravo DA program, initially reported on 800326. Dravo completed inhouse documentation search for Unit 1 piping & submitted corrected sketches. Unit 2 documentation search to be completed soon.
 MILLS.L.M. Tennessee Valley Authority. 80/11/24. Zpp. 07170:122
- 8012040422 Final deficiency rept re insufficient analysis of 3-inch fire protection line initially reported on 800605. Sixteen add; supports per unit needed. Supports will be installed prior to fuel loading. BILLS:L.M. Tannessee Valley Authority. 80/11/25. 2pp. 07170:124.
- 8012040443 Interim deficiency rept re automated fixed water spray sys in reactor bldg annulus, initially reported on 801027. Util in process of modifying fire protection sys in order to encompass addl interaction areas. Addl info due by 801009. MILIS.L.II. Tennessee Valley Authority. 80/11/26. 2pp. 07170:116.
- 8012090342 Interim deficiency rept.originally reported on 801031,re improper ueld attachment of shear lugs. Util determined that lugs will be acceptable if 1/4-inch fillet used. Mods completed by Aug 1981. Nert rept will be submitted by 810125. MILLS, L.M. Tennessee Valley Authority. 80/12/01. 2pp. 07201:165.
- E012100454 First interim deficiency rept re 3-inch gate valves which failed to close completely under preoperational test flow conditions. Mods to be developed. Next rept will be submitted by 810323.

 MILLS.L.K. Tennessee Valley Authority. 89/12/01. 2pp. 07219:028.
- 80:12:1005:17 First interim deficiency rept re improper shear lug weld attachments in heating ventilation & air conditionings systematically reported on 80:10:30. One-quarter inch fillet weld will correct defects. Next rept by 81:0125.

 MILLS.L.M. Tennessee Valley Authority. 80:/12/01. 2pp. 07219:348.
- 8012090359 Final deficiency rept initially reported 801030 re failure to use latest revisions of break location summaries for design pipe rupture protective devices. Mods will be completed by Aug 1981 for Unit 1 & Hay 1982 for Unit 2. MILLS.L.M. Tennessee Valley Authority. 80/12/02. 2pp. 07207:148.
- 8012170425 Third interim deficiency rept re damage to UHI piping hanger. Hanger to be replaced. Insp of piping welds revealed no damage by lifting incident EDS Nuclear & Mestinghouse analyting & evaluating Addi info to be submitted by 810213.
 MILLS.L.N. Tennessee Valley Authority. 80/12/12. 1p. 07269: 350.
- 8012170460 Fourth interim deficiency rept re inadequate documentation for miscellaneous mechanical equipment Applicable GC procedures revised to specify proper insp & documentation requirements Add info to be submitted by 810327.

 MILLS, L. N. Tennessee Valley Authority. 80/12/12. ip. 07269:239.
- 8012300570 Final deficiency rept re Penn Ventilator Co QA program shitially reported on 790418 Util has completed review of drawings & seismic & environ qualification documentation & found all documentation in compliance w/specs.

 MILLS, L. K. Tennesses Valley Authority. B0/12/18. 2pp. 07359:236.
- 8012310378 First interim deficiency rept re possible error in safety injection sys preoperational test, initially reported 801124. Caused by failure to require that position of all check valves important to test results be checked. MILLS.L.M. Tennessee Valley Authority. 83/12/23, 2pp. 07369:084.

V. Operator Examinations

e012010056 Clarifies min TMI-related requirements for new operator licenses re training during low power testing. Operators should be able to control saturation margin. RCG pressure & heat removal rate u/o socceding operating limits. FEDESCO.R.L. Assistant Director for Licensing. BO/11/14. App. 07078:174.

- DOCKET 50-395 VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, DL applicants & CP holders. Farwards NUREC-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISEIRMUT.D. G. Division of Licensing. 80/10/31. 7pp.
- 8012920993 Forwards followup info re NRC Seismic Qualification Review Team 891014-17 audit of equipment qualification program. Notification to NRC will be provided upon completion of seismic rept review.

 NICHOLS, T.C. South Carolina Electric & Oas Co. 80/11/20. 122pp. 06916:001.
- --8012070278."Project Procedure for Design of Electrical & Instrumentation Equipment, Basis & Attachments." Related info encl.

 3 Oilbert/Communuealth Cos. 80/11/14, 1400.
- 8012040592 Advises of requirements that must be met re NRC review of special low power test program & emergency procedures for selected translants & accidents.

 TEOESCO.R.L. Assistant Director for Licensing. 80/11/20. 2pp. 07170:097.
- 8012080309 Informs of planned corporate & plant visit in Dec 1980 to permit timely SER preparation for inclusion in post-ACRB suppl. Requests schedule for completion of organizational changes & procedures required prior to visit.

 TEDESCO.R.L. Assistant Director for Licensing. 80/11/20. 2pp. 04594:003.
- 8012220014 Summary of 801106-07 meeting w/util at site re anticipated fuel load date & const status.

 KANE, W. F. Licensing Branch 2 80/11/20. 9pp. 07306:283.
- 8012110776 Summary of 801009 meeting w/util in Bethesda.MD re geology & seismology review. HOUSTON.D., KANE.W. Operating Reactors Branch 2, 80/11/21, 4pp.
- 8012010117 Forwards summary of impact test results on math used in main steam & feedwater sys.
 NICHOLS.T.C. South Carolina Electric & Gas Co. 80/11/25, 2pp. 07097:325.
- 8012010327 Advises that results of util review of control room habitability per SRP & Reg Guides 1.78 & 1.95 show no futher mods required. NICHOLS.T.C. South Carolina Electric & Gas Co. 80/11/25. 2pp. 07098:029.
- 8012020572 Forwards response to Reactor Sys Branch request for info re operator actions in mitigating consequences of transient. NICHOLS.T.C. South Carolina Electric & Gas Co. 80/t1/25, 2pp. 07130:320.
- 8012010108 Application for amend to CPPR-94 to further extend latest completion date to 820630 Environ impact appraisal supporting extension request & bar graph indicating interrelation of schedule factors encl.

 NICHOLS
- 8012160291 Summary of 801117 meeting u/util re open matters in NRC geotechnical review & resolution of future actions needed to resolve issues.

 KAPERER Licensing Branch 2. 80/11/26. 5pp. 07252:253.
- 8012160005 Summary of 801022 meeting u/util & consultant in Bethesda. MD re util proposal for resolving concerns arising from review of control room design. KANE.W.F. Licensing Branch 2. 80/11/28. 4pp, 07262:321.
- 8012140025 Summary of 801118 meeting w/util & LASL in Bethesda,MD re geology/seismology review.including reservoir induced seismicity.RB Russell project rept & Charleston earthquake. KANE,IL F. Licensing Branch 2. 80/12/01. Spp. 07243:010.
- 8012090218 Responds to Auviliary Sys Branch reviewer questions re emargancy feedwater sys reliability analysis & subsequent telcons w/L Huang Lists four commitment items to be incorporated in subsequent FSAR amend. Calculations encl. NICHOLS T. C. South Carolina Electric & Oas Co. 80/12/02. App. 07187:001.

- 8012090230 Responds to NRC request for info re Westinghouse topical repts presented in seismic qualification tests of safety-related electrical equipment Facility CP docketed prior to Oct 1972.
 NICHOLS.T.C. South Carolina Electric & Gas Co. 80/12/02. 4pp. 07207-154
- 3012090399 Provides progress rept on TMI concerns re NSSS review of procedures, short-term accident analysis & low power test program. Followup ltr documenting short-term accident analysis will be sent by 801205.

 NICHOLS, T. C. South Carolina Electric & Gas Co. 80/12/02. 2pp. 07207: 137.
- 8012090262 Forwards info re TMI Requirement II.F.2.Discussion of thermocouples & in-core instrumentation subcooling meter & reactor vessel water level instrumentation encl. NICHOLS.T.C. South Carolina Electric & Oas Co. 80/12/04. Spp. 07201:140.
- 8012090324 Forwards Moodward-Clyde Consultants soils investigation program for svc water pond west embankment & structures per NRC request. Field work will begin 801208. Final rept not available until Feb 1981 due to add1 testing.
 NICHOLS: T. C. South Carolina Electric & Gas Co. 80/12/05. App. 07201: 155
- 8012110659 Forwards "Joint Ownership Agreement," & Amend 1 to agreement between 8C Electric & Gas Co & SC Public Svc Authority per 801125 request. CPPH-94, notice of Issuance & availability, util 801126 ltr & EIA encl. KMOTTS, J. B. Debevoise & Liberman. 80/12/05. 77pp. 07223:007.
- --BD12110470 Amend 1 to CPPR-94 deteting Condition 2.E.5 & renumbering Condition 2.E.6 to 2.E.5. GIAMBUSSO.A. Atomic Energy Commission - Deputy Director for Reactor Projects. 73/05/27. 3pp. 07223:015.
- --8012110675 Notice of issuance & availability of Amend 1 to CPPR-94.

 GOLLER, K. R. Atomic Energy Commission Deputy Director for Reactor Projects. 73/05/29. 2pp. 07223:016.
- --8012110682 Requests extension of latest const completion date due to delays in NRC safety review process, increased OC activities, rework due to insp & delays in installation of pipe hangers & supports.

 NICHOLST.C. South Carolina Electric & Gas Co. 80/11/26. 4pp. 07292-018
- --8012110686 EIA supporting request for extension of dates for completion of const of facility.

 + South Carolina Electric & Gas Co. 80/11/R6. 2pp. 07223:022.
- 8012170780 Forwards info re nuclear power plants to be licensed Dec 1980-Dec 1981 in response to request from Nuclear Oversight Committee. MIRAGLIA:F. Licensing Branch 3. 80/12/05. 3pp.
- 8012170457 Submits add1 info re vibrational loads developed during operation of diesel generators per NRC request.Colt Pielstich Mcdel PC-2 units installed & tested to withstand vibration stresses. Testing will continue during startup. NICHOLS,T.C. South Carolina Electric & Gas Co. 80/12/10. 2pp. 07249:152.
- E012170431 Forwards revised response to FSAR Question 211.86 re residual heat removal sys requirements in response to NRC request. NICHOLB.Y. C. South Carolina Electric & Gas Co. 60/12/11. 31pp. 07270:193.
- 8012170495 Forwards response to NUREO-0694 Item 2.K.1 "IE Bulletin on Measures to Mitigate Small Break LOCA & Loss of Feedwater factidents." Util has developed overlapping & redundant series of procedures to assure engineered safuty feature. NICHOLS.T.C. South Carolina Electric & Cas Co. 80/12/11. Spp. 07269:154.
- 8012240152 Notification of 801217 maeting w/BNHL.8M1 & util to perform walk-through of operating procedures at facility to confirm acceptability.

 KANE.W. Licensing Branch 2. 80/12/11. 3pp. 07324:393.
- 8012160123 Forwards revised pages to 800705 & 1008 responses to Seismology Ovestion 361, comparing earthquake time histories spectra to facility design response spectra. Responses will be incorporated in FSAR by amend.

 NICHOLS, T. C. South Carolina Electric & Oas Co. 80/12/12. 44pp. 07262:196.

- 80:2160162 Forwards "Supplemental Seismologic Investigation" to support applicant position re seismic issues of interest for plant & to document positions & discussions presented 80:118 in Bethesda. ND. NICHOLST. C. South Carolina Electric & Oas Co. 80/12/12. 2pp. 07253:007.
- ~~8012160165 "Supplemental Seismologic Investigation."

 ◆ South Carolina Electric & Gas Co. 80/12/31. 375pp. 07253:009.
- 8012190192 Forwards add1 info re condensate polishers for facility, in response to Effluent Treatment Sys Branch request.Condensate polishers will be placed in svc during startup for chemical cleaning of condensate & feedwater cycles.

 NICHOLS.T.C. South Carolina Electric & Gas Co. 80/12/15. 3pp. 07284:218.
- 8012190372 Forwards add1 info re TMI Requirement II.F. 2.in response to NRC request. Includes description of in-core thermocouple monitoring & subcooling monitor backup capabilities. Info suppls stil 801204 ltr.
 NICHOLS.T.C. South Carolina Electric & Gas Co. 80/12/15. 3pp.
- 8012230230 Provides clarification re requested justification for deviations to Westinghouse topical rapt NCAP 8584, Apps B & C. No deviations from requirements noted per Feb 80 revision. NICHOLS, T. C. South Carolina Electric & Cas Co. 80/12/16. 2pp. 07314;070.
- 8012230460 Advises tht util has no plans to submit applications described in NRC 801205 ltr for review during 801205-631231. MICHOLS.T.C. South Carolina Electric & Gas Co. 80/12/16. 1p. 07314:122.
- 8012300637 Requests permission to use 1977 ASME code, in addition to 1971 ASME code, to analyze Class I chemical & vol control syspump seal injection line & Class I pressurizer pressure relief lines.
 NICHOLS, T. C. South Carolina Electric & Oas Co. 80/12/19. 2pp. 07346:165.
- 8012300417 Forwards response to TMI I tem II.F. i. Add1 justification will be provided for present arrangement of reactor bldg wide range monitor RMG-7 located in penetration 309. M/o encl. NICHOLS. I. C. South Carolina Electric & Oas Co. 80/12/22. tp. 07300-345
- 8012300495 Submits info re augmented low-power startup test program per RL Tedesco 801114 ltr 3 801219 telcon w/N Kane & N Long. NICHOLS.T.C. South Carolina Electric & Gas Co. 80/12/22. 2pp.
- 8012300550 Provides response to NRC questions re inadvertent releases of radioactivity at plant as applied to discharge of turbine blds sump pump & 790725 North Anna event. Summer station design provides adequate protection N/o encl. NICHOLS.T.C. South Carolina Electric & Gas Co. 80/12/22. 3pp. 07346:172.
- 8012300252 Forwards revised 801215 response re facility condensate politishers operation.FSAR will be updated to include encl info.
- nuro. NICHOLS:T.C. South Carolina Electric & Gas Co. 80/12/23. 3pp. 07357:228.
- 8012300261 Responds to NRC request for addl meteorological info re NUREO-0654, Revision I. Info given as revision to FSAR Section 2.3 & will be included in next FSAR amend. NICHOLS, T.C. South Carolina Electric & Gas Co. 80/12/23 10pp. 07357:233.
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 8011250165 Forwards Suppl 1 to NVREC-0534, facility DES Avatlability will be published in FR notice. Comments due by 801227. Constitutes first environ statement issued in response to interim policy published in 800613 FR notice. N/o encl. DENIONA N. R. Office of Nuclear Reactor Regulation, Director. 80/11/10. ip. 07056:147.
- 8012010316 Ack receipt of draft EIS which will be forwarded to responsible environ officer for review & comment. Provides procedures & addressees for subsequent EIS reviews.

 RCMUR.H. Housing & Urban Development. Dept. of. 80/12/01. 2pp. 07097:212.
- 8012230231 Forwards staff requirements memo to briefing on EIS, Requesting to the BES suppl.
 TEDE850,R L. Assistant Director for Licensing. 80/12/03. 1p.
 07318:034.

- --8012230283 Staff requirements name re 801117 briefing on E18.Requests into rept on 25 ltrs received re interim policy statement & clarification of final tert on probability assumptions. CHILK'S J. Office of the Sacretary of the Commission. 80/12/17. ip. 97318:935.
- 8012160402 Reviews facility DES per BO1110 request Draft appears acceptable in areas reviewed.

 MEINEMARAUM Federal Energy Regulatory Commission. 80/12/10. 1p. 07263:103.
- B012290517 Comments on NUREO-0534 suppl, draft EIS for facility. Takes issue w/RRC-EPA attempt to give statistical figure of effects of nuclear power since effects of exposure to low level radiation may not be known for 10-20 yrs.

 WASSERBACH. A Affiliation Unknown. B0/12/17. 1p. 07344:215.
- B012300473 Comments on NMREG-0534 suppl, "DES Re Operation of VC Summer Nuclear Station Unit i." Document should further address resultant reduction in effects anticipated w/mitigative actions required by basic emergency plan.
 NICHGLE, T. C. South Carolina Electric & Gas Co. B0/12/23. 2pp. 07347:064.
- 8012300538 Requests 15-day extension for review of suppl to facility DES.per 801223 telcon MOCRE.S.N. Environmental Protection Agency. 80/12/23. 1p. 07337:332
- E. NRC Bafety Evaluation Report (SER), supple & correspondence
- 8012070241 Informs that SER still scheduled for 801201 & that some official inputs for non-TMI items & TMI items not received. DES suppl & FR notice issued.Comments due by 801229. KARE.M. Licensing Branch 2 80/11/18 2pp. 07202:314.
- 8012080309 Informs of glanned corporate & plant visit in Dec 1980 to permit timely SER preparation for inclusion in post-ACRS suppl. Requests schedule for completion of organizational changes & procedures required prior to visit.

 TEDESCO.R.L. Assistant Director for Licensing. 80/11/20. 2pp. 04584-073

G. Adjudicatory correspondence

- B012030425 Forwards "Nuclear Power Plant Accident Considerations Under NEPA of 1969" 5 "Further Commission Guidance for Power Reactor CLs: Statement of Policy " W/o encl. COLDBENGIS.C. Hearing Branch 2. 80/11/28. 1p. 07150:076.
- 8012220273 Interrogatories to applicant requesting info re participation of local agencies in emergency planning, resident inspector authority & emergency offsite facility, a Affiliation Unknown. 80/12/02. 2pp. 0/306:232.
- 8012119559 Forwards "Joint Ownership Agreement," & Amend 1 to agreement between SC Electric & Gas Co & SC Public Svc Authority per 801125 request. CPPR-94, notice of issuance & availability, util 801126 the & ElA ancl.

 KNOTYS, J. 8. Debevoise & Liberman. 80/12/05. 77pp. 07223:007.
- 8012150161 Forwards Sept 1979 financial info package.not previously received.U/o encl. Related correspondence.

 MAMAN.R.R. Seuth Carolina Electric & Gas Co. 80/12/09. ip.
 07237:222.
- 8012110517 Forwards alternative responses confirming or denying decision to abandon Contention A3 re ATMS concerning NRC proceeding. Requests clarification of response.

 KKOTTS. J. B. Debevoise & Liberman. 80/12/10. 2pp. 07225:235.
- 8012160336 Requests confirmation of intention to pursue Bursey Contention A3 re ATMS in proceeding Countersigned w/positive confirmation from intervenor. KKOTTS, J. B. Debevoise & Liberman. 80/12/15. 2pp. 07255:035.
- 8012300217 Forwards Comptroller General 801203 opinion that procedural assistance in adjudicatory licensing proceedings was not permissible under law. GGLDERG.S.C. Hearing Branch 2. 80/12/23 1p. 07357:003.
- 8012310424 Answers to BA Bursey Interrogatories 1-24 re emergency planning Certificate of Svc encl. NICHGLS,T.C. South Carolina Electric & Gas Co. BO/12/24, 7pp. 07370: 193.

I Financial information

- 8012240140 Forwards request for updated info to complete application for evaluation of licensee financial qualifications to operate facility. Response should be received six wks prior to input for SER.

 KARLOHICZ.M L. Utility Finance Branch (formerly Antitrust & Indennity). 80/12/02. 7pp. 03808:324.
- 8012110559 Forwards "Joint Ownership Agreement," & Amend 1 to agreement between SC Electric & Gas Co & SC Public Svc Authority per BO1125 request. CPPR-991, notice of issuance & availability, viti 801126 tr & EIA encl.

 KROTTS, J. S. Debevoise & Liberman BO/12/05, 77pp. 07223:007.
- 8012310046 Forwards request for addl info for financial qualifications review. Update of estimated annual costs for first 5 yrs of commercial operation & revised estimated cost of permanent shutdown should be provided.

 TEDESCO.R. L. Assistant Director for Licensing. 80/12/08. 8pp. 07371:113
- B012150161 Forwards Sept 1979 financial info package, not previously received. N/o encl. Related correspondence.

 MAHADLR.R. South Carolina Electric & Gas Co. 80/12/09. 1p.
 07237:222.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012190140 Forwards revised FSAR Chapter 15.4 pages re control room doses following LOCA. Revision completes control room ventilation sys mods to provide positive pressure during normal & emergency conditions.

 NICHOLS.T.C. South Carolina Electric & Gas Co. 80/12/15. 5pp. 07284:221.

M. Antitrust correspondence

- 8012020765 Motion to defer ruling on pending petition for significant changes until Jan 1981 & to establish schedule for final settlement status repts for late Dec 1980.
 Certificate of Svc enci.
 ROSERTS, E., ROSERTS, E. South Carolina Electric & Qas Co.
 KNOTTS, J. B. Debevoise & Liberman. 80/11/21. 5pp. 07143:344.
- 8012230004 Request for denial of applicant motion to defer ruling on pending petition for significant change determination & to establish schedule for final settlement status repts. Certificate of Svc enci.
 BRAND.W.E., HALL.E.E., BEENY.S.T. Central Electric Power Cooperative, Inc. 80/12/09. 7pp. 07311:148.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012090191 Forwards IE Insp Rept 30-395/80-27 on 800915-19. No nancampliance noted. STORR.J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/23. 2pp. 07200:118.
- ---8012090197 IE Insp Rept 90-393/80-27 on 800915-19. No nencompliance noted. Major areas inspected: coordination w/outside support groups & emergency facilities, equipment & procedures.
 PERROTTI, D. J. Region 2, Atlanta, Office of the Director.
 JENKINS, G. R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/17. 9pp. 07200:120.
- 8012090216 Forwards IE Insp Rept 50-599/80-26 on 800827-29. No noncompliance noted. LEWISR.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/10/24. 2pp. 07202:284.
- --8012090219 IE Insp Rept 50-395/80-26 on 800827-29. No noncompliance noted. Major areas inspected: safety-related piping support & restraint sys, thermal expansion data & test measurements. INHITEMER.H.L. Region 2. Atlanta, Office of the Diractor. QUICK, D.R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/10/24. 4pp. 07202:285.
- 8012160329 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/24.

 ip. 07261:171.
- 8012170288 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
 0'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24, ip. 07268:299.

- 8012110633 Forwards IE Insp Rept 50-395/80-29 on 800901-1005.No noncoapliance noted. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/10/30. 2pp. 07226:195.
- --B017110637 IE Insp Rept 50-395/80-29 on B00901-1005. No noncompliance noted Major areas inspected: operating procedure review. 100ff85. 55 repts. Part 21 repts & IE bulletin & circular followup.

 EKOLDS, J. L. Region 2. Atlanta, Office of the Director.

 KELL093.P. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. E0/10/29. 6pp. 07226: 197.
- 8012180009 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/30. ip. 03790:102.
- 8012180011 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required, O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/31, 1p. 03790:128.
- 8012230072 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.

 1p. 07313:238.
- 8012230075 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31. 1p. 07313:247.
- 8012110725 Forwards IE Bulletin 80-21. "Valve Yores Supplied by Malcolm Foundry Co. Inc." Written response required. G'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/06. ip. 07225:223.
- 8012030835 Forwards IE Info Notice 80-40. "Excessive Nitrogon Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 90/11/07. 1p. 07:49:319.
- GO12080188 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10. 1p. 07182:258.
- 8012040212 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of mangower associated w/corrective actions. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/14. 1p. 07158:126.
- B012020207 Forwards revised praservice insp plan containing all known relief requests.

 NICHOLB.T.C. South Carolina Electric & Gas Co. B0/11/18. lp. 06916:001.
- --8012020289 Preservice insp plan, Revision 1.
 MDRROE, J. D., COLLIER, L. B. South Carolina Electric & Gas Co.
 80/11/30. 350pp. 06916;001.
- 8012030034 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. G'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/21. 1p. 07173:082.
- B0120B0002 Forwards IE Info Notice B0-42, "Effect of Radiation on Hydraulic Snobber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. B0/11/24. ip. 07182:117.
- 8012170348 Forwards IE Info Notice 80-29, Suppl 1, "Broken Stude on Terry Turbine Steam Inlet Flange." No written response required, G'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/26. ip. 07269:001.

- R. Periodic operating reports & related correspondence
- B012020241 Forwards Technical Rept B0-3. "Seismic Activity Near VC Summer Huclear Station for Jul-Sept.1980." NICHGLS.T.C. South Carolina Electric & Gas Co. B0/11/25. 1p. 07141:223.
- --8012020245 "Seismic Activity Near VC Summer Nuclear Station for Jul-Sept.1980." TALNANI.P. South Carolina, Univ. of. 80-3, 80/09/30, 20pp. 07141:224.
- S. Reportable occurrences. LERs & related correspondence
- 8012020367 Final deficiency rept re failure of instruments on main control board during hot functional testing initially reported on Bolo23 Causad by excessive heat inside control board Installation of ventilation sys is undervay.

 NICHOLS.T.C. South Carolina Electric & Oas Co. BO/11/20. 3pp. 07142:071
- 8012020377 Interim deficiency rapt re separation of Hestinghouse circuits, initially reported on 801023 Mismatches in color coding of cables exist due to difference in philosophy between supplier & AE Interface will be completed by 801215. NICHDLS, T.C. South Carolina Electric & Gas Co. 80/11/20. 2pp. 07142:080.
- 8012020493 Interim deficiency rept re potential for inadvertent boron dilution event, initially reported on 801024, Westinghouse is investigating event. Interim recommendation notes acceptable operation at three dilution flow rates.
 NICHOLS, T. C. South Carolina Electric & Gas Co. 80/11/20. 10pp. 07:10:284.
- 80(2020523 Interim deficiency rept of piping burn through, initially reported on 80(023 Pipe section has been replaced.

 Determination of reportability per 10CFR050 55e is under review.

 NICHOLS.T.C. South Carolina Electric & Gas Co. 80/11/20. 1p.
- 8012030613 Final Part 21 rept re substantial safety hazard. Cables supplying ac power to battery chargers not properly derated for random lay cable tray. Cables replaced.

 NICHBUS.T.C. South Carolina Electric & Gas Co. 80/11/20. 3pp.
- 8012030634 Interim deficiency rept re piping burn-thru identified by const company. Questionable pipe section replaced.
 Reportability determination has not been made.
 NICHOLST.C. South Carolina Electric & Gas Co. BO/11/20. ip. 07151:157.
- 8012030671 Interim deficiency rept.originally submitted on 801023, re separation of Westinghouse circults. Philosophy differences in separation methods caused mismatches in color coding of cables. Final rept will be sent after 801215 review. NICHOLS.T.C. Southern California Edison Co. 80/11/20, 2pp. 07151:275.
- 8012020494 Final deficiency rept re B01121 Part 21 rept of substantial safety hazard concerning omission of seal in contact of speed changing switch for svc water pumps. Caused by design error. Circuit revised to insure speed switch transfers. NICHOLS, T. C. South Carolina Electric & Gas Co. B0/11/21. 2pp. 07148: 247.
- 8012020437 Final deficiency rept.originally identified 800531, re omission of interlocking contact in swing component cooling pump that prevented starting on load sequencer signal, reported under 10CFR21. Interlock installed.
 NICHOLS.T.C. South Carolina Electric & Oas Co. 80/11/21. 2pp. 07148: 263.
- 8012020442 Final deficiency rept.originally identified 800717, refailure to insulate base instrument cable drain wire splices in penetrations as required by design guidelines.reported under 10cFR21. Penetrations removed & drain wires taped. NICHOLS.T.C. South Carolina Electric & Gas Co. 80/11/21. 2gp. 07148:261.
- 8012020445 Final deficiency rept, originally identified 800416, re-broken torque suitches on Limitorque valve operators, reported under 1006821. Design criteria revised concerning Limitorque operators on butterfly valves.

 NICHOLS, T. C. South Carolina Electric & Gas Co. 80/11/21, 2pp, 07148:256.

- 8012030636 Final deficiency rept re originally identified 800717 re failure to insulate base instrument cable drain wire splices in penetrations per design guidelines. Penetrations removed & drain wires taged.

 NICHOLS. T. C. South Carolina Electric & Gas Co. 80/11/2; 2pp. 07151:155.
- B012150035 Part 21 rept re Westinghouse gate valve failure to close under test conditiona less savere than design specs, initially reported on B01030 Cause is unknown. Final rept will be submitted upon determination of resolution. NICHGLS, T.C. South Carolina Electric & Gas Co. B0/11/24. 3pp.
- 8012140436 Final deficiency rept re piping "burn-thru" identified by Daniel Const Co.first reparted B01120 Condition determined not reportable as deficiency Pipe had sufficient design margin to preclude major failure.
 NICHOLS.T.C. South Carolina Electric & Gas Co. B0/12/09. 2pp. 07243:357.
- 8012240047 Part 21 rept re svc water pump speed control Only momentary contact made from load sequencer signal for svc water pump speed switch to go to high speed on loss of offsite power. Circuitry redesigned.

 BARKER.N.R. Ebasco Services Inc (subs. of Enserch Corp.).
 80/12/11. 3pp. 07324:242
- 8012240131 Part 21 rept re interlock contact not provided in control circuit of swing pump preventing startup on load sequencer signal Circuitry re-designed BARKER.N.R. Gilbert/Commonwealth Cos. 80/12/11. 3pp. 07324:180.
- 8012230350 Interim deficiency ropt re separation of Westinghouse circuits. Evaluation still incomplete. Final rept to be issued by 910115. DICHOLS T. C. Bouth Carolina Electric & Gas Co. 80/12/16. 1p. 07318:246.
- 8012300458 Follows up 800613 ltm re reportable substantial safety hazard involving centrifugal charging pump operation. Westinghouse is performing add1 plant-specific analysis to determine long-term solution.
 NICHOLS.T.C. South Carolina Electric & Gas Co. 80/12/19. 2pp. 07357: 204
- B012300534 Interim deficiency rept re failure to inspect conduit supports. Insp documentation lacking for C 14 conduit support. Reinsp will be completed by 810130. NICMOLST.C. South Carolina Electric & Gas Co. B0/12/23. 1p. 07397:337.
- 8012300628 Interim deficiency rapt re seismic installation not inspected Konsafety-related relay cabinets reinspected & minor discrepancies being evaluated by structural enginæering Evaluation to be completed by 810123. NICHOLS, T.C. South Carolina Electric & Oas Co. 80/12/23. 07397:324. B0/12/23. 1o.
- T. Hearing transcripts on non-antitrust matters
- 8012020151 Transcript of 801117 public meeting in Washington DC re EIS, Pp. 1-33. # Commissioners. 80/11/17. 33pp. 07143:006.
- 8012040535 Transcript of B01125 hearing in Columbia.SC re application for facility OL.Pp 278-336.

 * Atomic Safety and Licensing Board Panel. 80/11/25. 58pp. 07168.021.
- V. Operator Examinations
- 8012020031 Clarifies TM1-related requirements for new operator licenses re training during low power testing. Tests should demonstrate length of time required to stabilize natural circulation TEDESCO.R.L. Assistant Director for Licensing. 80/11/14. 2pp. 07148:347.
- DOCKET 50-377 WPPSS NUCLEAR PROJECT, UNIT 2
- A. Application/construction stage documents & correspondence
- 8012160350 Ltr to operating plant licensees.QL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISED#UT.D.G. Division of Licensing. 80/10/31. 7pp.

- B01222039B Ltr to all CP & DL holders for BNRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amands, including core reloads.
 EISENBUT, D. G. Division of Licensing, 80/11/04, 4pp.
- 8012010712 Discusses NRC evaluation of proposed corrective weld at 841 const joint of sacrificial shield wall. Metallurgical, 5 welding 8 structural aspects of proposed girth weld are acceptable Suggests instituting internal review procedure.
 TEOBECO.R. L. Assistant Director for Licensing. 80/t1/20. 4pp. 07170:048
- 8012100214 Notification of 801202 meeting w/BMR licensing review group in Bethesda-MD to discuss status of group issues.
 WILSON-J.M. Licensing Branch t. 80/11/20. Spp.
- 8012040595 Discusses NRC review of schedular requirements for special low power test program % emergency procedures. Lists schedular requirements to be met. Evaluation to be completed in conjunction w/facility full power ascension program. TEDESCO,R.t. Assistant Director for Licensing. 80/11/21. 2pp. 07170:052.
- 8012070275 Responds to NRC BD1170 & OB17 ltrs re sacrificial shield wall. Forwards info re fire hazard of shielding matl used in repair of wall gaps. Affidavit encl.
 BGUCHEY, O. D. Washington Public Power Supply System. 80/12/01. 8pp.
- ~~8012070302 "Fire Test on BISCO SF-20 Silicone Foam & Radiation Shielding Penetration Seals in Masonry Wall Design WP 374." PRICE, N.R., SHIELD, W.F. Factory Mutual Research, 75/08/05, 26pp. 07187:001.
- --B012090308 "Investigation of Surface Burning Characteristics of Solid Silicone Sheet Matl.NS-1." Summary of facility mock-up test re heat input to shield matl encl.
 HAFER.C. A Southwest Research Institute. 80/06/13. 7pp. 07187:001.
- 8012160032 Notification of 801212 meeting w/Mark II owners group in Bethesda, MD to discuss suppression pool temp limit, 8U, T. K. Generic Issues Branch, 80/12/05, 1p.
- B012140150 Notification of B01210 meeting w/Mark II owners group in Bethesda MD to discuss status of improved chugging load program. ANDERSON.C. Generic Issues Branch. 80/12/02. 1p.
- 8012170283 Summary of 801202 meeting w/BWR licensing review group, Bechtel & Stil in Bethesda,MD re current status of issues & fire protection concerns.Rapt on LaSalle specific issues WILSON, J. R. Licensing Branch 1, 80/12/05, 21pp. 07268: 264.
- 8012270131 Summary of 800514-0828 meetings w/BWR Licensing Review Group in Bethesda.MD re identification of generic issues, formation of commons positions & resolutions that will apply to all sir plants.Draft working paper enci.
 WILSON.J.R. Licensing Branch 1. 80/12/05. 99pp.
- 8012190162 Forwards primary containment vessel design diagrams, in response to NRC 801030 ltr. Drawings detail containment geometry, shell reinforcement, plate thickness & penetration sizes. Aperture cards available in Centri Files only.
 80UCHEY, G. D. Washington Public Power Supply System. 80/12/10, 9pp. 07256: 311.
- 8012300532 Requests meeting be scheduled for 810121 in Bethesda, Md to discuss Burns & Roe chugging & condensation oscillation load definition work. Util will respond to NRC questions on 800805 safety relief valve.
 BDUCHCY. (D. Washington Public Power Supply Bystem. 80/12/19, 2pp. 07346:175.
- C. Utility Environmental Report (ER), amends & correspondence
- 8012240273 Discusses review of Amend 4 to environ rept. Comments on discussion of endangered & threatened species on Page 6.1-20. Util should ensure that obligations of Endangered Species Act of 1973. as amended have been fulfilled. DUW.C.A. Interior. Dept. of, Fish & Hildlife Service. B0/12/16. ip. 0/324:349.

- F. Security, medical, emergency & fire protection plans
- 8012090295 Responds to NRC 801120 & 0819 ltrs re sacrificial shield wall. Forwards info re fire hazard of shielding matl used in repair of wall gaps. Affidavit encl.
 BOUCHEY, G. D. Washington Public Power Supply System. 80/12/01. Epp. 07187:001.
- --B012090302 "Fire Test on BISCO SF-20 Silicone Foam & Radiation Shielding Penetration Seals in Masonry Wall Design WP 374." PRICE.W.R. SHIELD.W.F. Pactory Mutual Research. 75/08/05. 26pp. 07187:001
- --B01207030B "Investigation of Surface Burning Characteristics of Solid Silicone Sheet Matl.NS-1." Summary of facility mock-up test re heat input to shield mati encl. HAFER.C.A. Southwest Research Institute, B0/06/13. 7pp. 07187:001.
- 8012230391 Requests NRC formalize & submit branch questions re physical security & safeguards contingency plans transmitted 770102 & 0423 respectively. Continued delays will adversely impact const schedules.

 80UCHEV, O. D. Washington Public Power Supply System. 80/12/18. 2pp. 07312:251.

1. Financial information

- 8012160128 Forwards Annual Financial Rept 1980. BOUCHEV. 6 D. Washington Public Power Supply System. 80/12/11. ip. 07187:001.
- --8012160134 Annual Financial Rept 1980.

 4 Washington Public Power Supply System. B0/12/11. 23pp. 07187:001.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012300255 Forwards Amend 12 to FSAR. Affidavit of distribution will be provided uithin 10 days. 80UCHEY.O.D. Mashington Public Power Supply System. 80/12/17. 3pp. 07350:039.
- --8012300257 Amend 11 to FSAR.

 * Washington Public Power Supply System. B0/11/30. B00pp.
 07350:042
- 8012300412 Forwards util 801219 transmittal ltr to & Certificate of Svc of FSAR Amend 12 on Chairman of Benton County Board of Commissioners, Chairman of Energy Facility Site Evaluation Council & EPA EIS coordinator.

 BOUCHEY, O. D. Washington Public Power Supply System. 80/12/19. 3pp. 07357:316.

Q. Inspection reports, IE Bulletins & correspondence

- 8012170/80 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 ENGELKHIR.H. Region 5, San Francisco, Office of the Director.
 80/10/24. 1p. 07266:069.
- 8012040305 Forwards IE Insp Rept 50-397/50-17 on 801007-10. No noncompliance noted. SPENCER, G. S. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 80/10/29. 2pp. 07163:286.
- --8012040310 IE Insp Rept 50-397/80-17 on 801007-10. No noncompliance noted, Major areas inspected: licensee actions on previous insp findings & allegations of concrete voids. HAIGT, D.P., WAONER, M.J., D'ANGELD, A.J., Region 5. San Francisco, Office of the Director. 80/10/29, Spp. 07163:288.
- 8012030763 Supplis 800909 response to IE Bulletin 79-03A. "Longitudinal Weld Detects in ASME BA-312 Type 304 Stainless Steel Pipe."
 No safety-related sys utilize specified pipes subj to greater than 85% of ASME code allocable stresses.
 RENUEROER D. L. Washington Public Power Supply System. 80/10/31.
 1P. 0/149:292.
- 8012170847 Forwards IE Info Notice 80-39, "Maifunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
 ENGELERI, R. H. Region 5, San Francisco, Office of the Director. 80/10/31. 1p. 07266:035.

- 8012120221 Forwards IE Bulletin 80-21, "Valve Yotes Supplied by Malcol Foundry Co. Inc." Written response required ENGELKFURM Region 5, San Francisco, Office of the Director, 80/11/06 ip. 07228:284
- 8012030914 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuatos Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. ENGELKEU,R H. Region 5. San Francisco, Office of the Director. 80/11/07. lp. 07150-133.
- 8012080658 Forwards IE Info Notice 80-41, "Failure of Swing Check Valy in Decay Heat Removal Sys at Davis Dasse Unit 1." No response required.
 ENSELECTION. Region 5, San Francisco, Office of the Director.
 80/11/10. 1p. 07183:041
- 8012040233 Forwards 16 Bulletin 80-23. "Failures of Sciencid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ENSELKFIJR.H. Region 5. San Francisco, Office of the Director. 80/11/14. lp. 07158:156
- 80(2040691 Forwards 16. Bulletin 80-24. "Frevention of Damage Due to Water Loakage Inside Containment." No written response required. EXSELVELLAR. Region 5. San Francisco, Office of the Director. 80/11/21. ip. 07169:272.
- B012160031 Forwards IE. Info Natice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No response required. ENSELKFH.R.H. Region 5. San Francisco. Office of the Director. 80/11/24. 1p. 07262:120.
- 8012030722 Forwards response to RRC 801104 ltm re violations noted in: IE Insp Rapt 50-397/80-16. Corrective actions:const deficiencies reviewed for reporting as potential 100FR. 50. 55e items.repts submitted & instruction drafted. MATLOCK.R. 9. Washington Public Power Supply System. 80/11/26. 4pp 07149:315.
- 8012160133 Forwards Suppl i to JE Inic Notice 80-29. "Broken Studs on Terry Turbing Steam Inlet Flange." No written response required. ENGELKFIAR H. Region 5. San Francisco. Office of the Director. 80/11/26. 1p. 07262.967
- 8012170357 Forwards full payment in response to NRC 801106 amended notices of violation & proposed imposition of civil penalties. Evaluation & corrective action program initiated as prerequisite to add safety-related work.
 MATLOSK.R.O. Washington Public Power Supply System. 80/11/26. 5pp. 07270-173
- 8012110174 Ack receipt of 801125 ltr 2 check of \$59.500 in full paymen of penalties imposed in 801105 notice of violation. THOMPSON.D. Office of Inspection 2 Enforcement, Office of the Director. 80/12/04 ip 07223.172
- S. Reportable occurrences, LERs & related correspondence
- 8012030728 Interim deficiency rept re inadequacy of sway brace bracket mig by Power Piping Co.initially reported on 800820. Caused by undersized welds & peor weld quality. In-plant insp of brackets performed. Next rept is scheduled for 810202. MATCOCK.R.O. Washington Public Power Supply System 80/11/26. 4pp 07149:303.
- 8012230592 Interim deficiency rept re diesel generator switchgear unit D0[-7 & D02-8 installation.Caused by insufficient clearance between cabinets to prevent impact during seismic event. Switchgear units connected to generator control cabinets. MATLOCK.R.O. Washington Public Power Supply System. 80/12/10. 2pp. 07316-242.
- U. Cong. essional/Executive Correspondence
- 8012100554 Responds to 803408 ltr to DDE requesting rept on Finley Quarry fault potential for earthquate & effect on facilities located at Hanford reservation. Seisnicity will be reesevationed as result of recent geologic discoveries. DIRCKS, N. J. Office of the Executive Director for Operations. 80/11/24. 11pp. 07187.001.

- DOCKET 50-400 BHEARDY HARRIS NUCLEAR POWER PLANT, UNIT 1 A. Application/construction stage documents & correspondence
- 8012160050 Ltm to operating plant licensees.OL applicants & CP holders. Forwards NUMEG-0737 me TMI action plan requirements, Requests operating reactor licensee confirmation in 45 days that Enci 1 implementation dates will be net. EISENHUT.D.G. Division of Licensing 80/10/31. 7pp.
- 6012020543 Forwards BMR cumers group design b operational criteria for scram discharge sys.Criteria viewed as being responsive to requirement of providing assurance of reliable b safe operation of sys MATERS.D.B Carolina Power b Light Co. 80/11/24. 4pp.
- G. Inspection reports. IE Bulletins & correspondence
- 8012150190 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No unitten response required.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/24, 1p. 07840:287.
- 8012170302 Forwards Suppl 3 to IE Sulletin 77-018, "Environ Qualification of Class IE Equipment." No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/24, 1p. 07268:319
- 8012180027 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. O'REILLY,J.P. Region 2. Atlanta, Office of the Director. 80/10/30. 1p. 03770:104.
- B012170/B5 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. B0/10/31.

 1p.
- 8012230045 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No unitten response required. 0'REICLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/31. 1p. 07311 244.
- 8012110/67 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. B0/11/06. 1p. 07225:191.
- 80120303A7 Forwards IE info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressorization." No written response required. O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/11/07. 1p.
- 8012080316 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Resse Unit 1." No response required. O'ABILLY, J. P. Region 2- Atlanta, Office of the Director. 80/11/10. 1p.
- 8012010157 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Kig by Valcor Engineering Corp." Requires estimate of manpower associated u/corrective actions. G'REILLY,J P. Region 2. Atlanta, Office of the Director. 80/11/14. lp. 07159:071.
- 8012050360 Forwards IF Bullistin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. 0'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/21. 1p. 0/173:215
- 8012050621 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Enubber Field." No written response required. O'REICLY, J.P. Region 2. Atlanta, Office of the Director, 80/11/24, ip.
- 8012170494 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REISLY, J. P. Region 2, Atlanta, Office of the Director. B0/11/26.

- B012190351 Ack receipt of 1E Insp Repts 50-400/80-25, 50-401/80-23, 50-402/80-23 & 50-403/80-23 on 800729-1031. No proprietary info! MCNE, P.W. Carolina Power & Light Co. 80/12/08. 1p. 07286:112.
- --8012190359 Forwards IE Insp. Repts 50-400/80-25,50-401/80-23, 30-402/80-23 & 90-402/80-23 on 803929-1031 & notice of violation. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/28. 2pp. 07286:113.
- --8012170368 Nutice of violation from insp on 800729-1031. • Region 2, Atlanta, Office of the Director, 80/11/26. 1p. 07286:115.
- --8012190385 iE insp Repts 50-400/80-25, 50-401/80-23, 50-402/80-23 & 50-403/80-23 on 800925-1031 Noncompliance noted: failure to control outdated drawings & to provide instructions for verification data collection.

 MAKKELL, O.F. Region B. Atlanta, Office of the Director.

 BRYANT, J.C. Region B. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/26. 7pp. 07286:116.
- 8012180395 Ack receipt of B01124 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-22, 50-401/80-20, 50-402/80-20 & 50-403/80-20. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/12/09. 1p. 03794:233.
- --8012180376 Responds to NRC 801103 itr re violations noted in IE Insp Repts 50-400/80-22,50-401/80-20,50-402/80-20 & 50-403/80-20. Corrective actions:reinsp of seismit or safety-related hanger installed prior to problem discovery. HDNE,P.W. Carolina Power & Light Co. 80/11/24. 3pp. 03794:234.
- ---8012180378 Ack receipt of IE Insp Repts 50-400/80-22, 50-401/80-20, 50-402/80-20 & 50-403/80-20. No proprietary info. HONE, P. W. Carolina Power & Light Co. 69/11/11. ip. 03774: 237.
- --8012180490 Forwards IE lnsp Repts 50-400/80-22.50-401/80-20, 50-402/80-20 & 50-403/80-20 on 800901-26 & notice of violation.

 KWRPNY.C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/(1/03. 2pp. 03794:238.
- --8012183402 Notice of violation from insp on 800701-24.

 Region 2, Atlanta, Office of the Director. 80/10/30. 1p. 03794:240.
- --8012180403 IE Insp Repts 30-400/80-22, 50-401/80-20, 50-402/80-20 & 50-403/80-20 an 800701-26. Noncompliance noted: failure to correctly translate & implement codes & stds for special processes.

 MAKINELL, 9. F. Region 2. Atlanta, Office of the Director.
 BRYANKI, J. C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/30 7pp. 03794:241.
- 8. Periodic operating reports & related correspondence
- 8012150073 Forwards const milestones & activities to 801130. MCDUFFIE.M.A. Carolina Power & Light Co. 80/12/04. 1p. 07237:263.
- --8012150074 Constr milestones & activities updated to 801130. 4 Carolina Power & Light Co. 80/11/30, 12pp. 07237; 264.
- S. Reportable occurrences, LERs & related correspondence
- 8012010339 Forwards interim deficiency rept re 801017 confirmation of nonsafety heating, ventilation & air conditioning for Class IE motor control ctrs. Due to extensive nature of problem, all corrective action expected to be completed by 810215. CHIANGLIE. J. Carolina Power & Light Co. 80/11/24. 4pp. 07097:039.
- OCCME1 50-401 BHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012160350 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licenses confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- SO12020643 Forwards BMR owners group design & operational criteria for scram discharge sys. Criteria viewed as being responsive to requirement of providing assurance of reliable & safe operation of sys.

 MATERS. D. B. Carolina Power & Light Co. 80/11/24. 4pp.

- Q. Inspection reports, IE Bulletins & correspondence
- 8012150190 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.
- 8012170302 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required, O'REILLY, J. P. . Region 2. Atlanta, Office of the Director. 80/10/24, 1p. 07268:319.
- 8012180027 Forwards IE Info Notice 80-39, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30, ip. 03790:104.
- 8012170785 Forwards IE info Notice 80-39, "Malfunction of Sciencid Valves Mfg by Valcor Engineering Corp." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012230045 Forwards 1E Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Conorators" No written response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012110/67 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.inc." Written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.
- 8012030887 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuriation "No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/07. ip.
- 8012080316 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/10.
- 8012040157 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/14. pp. 19.
- 8012050060 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. G'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/11/21. 1p. 07173:215.
- 8012050621 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid " No written response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24. ip.
- 8012170496 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/26. 1p.
- 8012190351 Ack receipt of IE Insp Repts 50-400/80-25,50-401/80-23, 50-402/80-23 & 50-403/80-23 an 800929-1031 No proprietary info.
 HOME, P. R. Carolina Power & Light Co. 80/12/08. 1p. 07286:112.
- --8012190359 Forwards IE Insp Repts 50-400/80-25,50-401/80-23, 50-402/80-23 & 50-403/80-23 on 800929-1031 & notice of violation. MXPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 60/11/28 2pp. 07286:113.
- --8012190368 Notice of violation from insp on 800729-1031. * Region 2, Atlanta, Office of the Director. 80/11/26. 1p. 07286:115

- --8012170G25 1E losp Rept. 50-402/80-25, 50-401/80-23.50-402/80-23 & 50-403/80-23 on 80092x-1031. Noncompliance noted: failure to control outdated drawings & to provide instructions for verification data collection MAMwell. O F Region 2. Atlanta. Office of the Director. BRYANT.J.C. Region 2. Atlanta. Reactor Construction & Engineeri Support Branch. 80/11/24 7pp 07286:116.
- 80121803y5 Ack receipt of 80(12)4 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-22, 50-401/80-20, 50-402/80-20 t 50-403/80-20. MURPHY.C.E. Region 2. Atlanta. Feator Construction & Engineering Support Branch 80/12/67. lp. 03794.233.
- --8012180396 Responds to LRC 801103 ltm re violations noted in IE In Repts 50-400780-22.50:401780-20.50-402780-20 & 50-403780-20. Connective actions reinsplor seismic on safety-related hanger installed prior to problem discovery. HONE.P.W. Canolina Fower & Light Co. 80/11/24. 3pp. 03794:23
- --8012180078 Ack receipt of 16 Insp Repts 50-400/80-22.50-401/80-20. 50-402/80-20 & 50-403/80-20 No proprietary info. HOME.P.W. Carolina Power & Light Co. 80/11/11. 1p. 03794:237.
- --8012180499 Forwards IE Insp. Repts 50-400/80-22,50-401/80-20, 50-402/80-20 & 50-403/80-20 on 800901-26 & notice of violation. RURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 2pp 03794:238
- --8012180402 Notice of violation from insp on 800901-26.
 * Region 2, Atlanta, Office of the Director. 80/10/30. 1p. 03794:240.
- --8012180403 IE Insp Repts 50-400/80-22,50-401/80-20,50-402/80-20 & 50-403/80-20 on 800901-26 (Concompliance noted: Pailure to correctly translate & implement codes & stds Por special processes.

 MAKIELLIGF. Region 2. Atlanta, Office of the Director.
 BRYANT, J. C. Region 2. Atlanta, Reactor Construction & Engineerin Support Branch. 80/10/30. 7pp. 03794:241.
- R. Periodic operating reports 3 related correspondence
- 8012150073 Forwards const milestones & activities to 801130. MCDUFFIE.M.A. Carolina Power & Light Co. 83/12/04, 1p. 07237:28
- --8012190074 Constr milestones % activities updated to 801130. ◆ Garolina Power & Light Co 80/11/30. 120p. 07237:264.
- 5. Repartable occurrences, LERs & related correspondence
- 8012010339 Forwards interim deficiency meptine 801017 confirmation of nensafety heating, ventilation & air conditioning for Class IE motor control ctys Duo to extensive nature of problem, all corrective action, especied to be completed by 810215. CHEARSIAN J. Carolina Power & Light Co. 80/11/24, 4pp. 07097:00
- DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

 A. Application/construction stage documents & correspondence
- 8012140050 Ltr to operating plant licensees. CL applicants & CP holder Forwards NUREC-0737 re TM1 action plan requirements. Requests operating reactor licenses confirmation in 45 days that Encl 1 implementation dates only be net.
 EISENHUT. D. C. Division of Licensing. 60/10/31. 7pp.
- 8012020643 Forwards BNR swhers group derigh & operational criteria for scram discharge sys Criteria viewed as being responsive to requirement of providing assurance of reliable & safe operation of sys

 WATERS, D. B. Caroline Power 1 Light Co. 60/11/24. 4pp.
- G. Inspection reports. IE Bulletins & correspondence
- 8012190190 Forwards IE Info Notice 80-37. "Containment Cooler Loaks Reactor Cavity Flooding At Indian Point Unit 2." No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director, 80/10/2/1p.
- 8012170302 Forwards Suppl 3 to 1E Bulletin 79-018. "Environ Qualification of Class IE Equipment." No written response required. URELLEY, J.P. Region 2 Atlanta, Office of the Director. BO/\$0/2/1p 0/268:319.

- 012180027 Forwards 1E Inio Notice 80-38. 'Cracking in Charging Pump Casing Cladding.' No written response required. O'RESELLYJJ.F. Region X. Artanta. Office of the Director. 80/10/30.
- 012170785 Farwards IE Info Notice 80-37, "Malfunction of Salenoid Valves Mfg by Valcor Engineering Corp." No written response required. O'REILLY, J.P. Pegion 2. Atlanta, Office of the Director. 80/10/31.
- 012230045 Forwards 16 Circular 86-23, 'Potential Defects in Belgit Power Sys Emergency Generators," No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 012110/67 Forwards IE Sulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Britton response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.
- 012030887 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Couse Reactor Depressuritation." No written response required. D'REIM Y.J.P. Region I. Atlanta, Office of the Director. B0/11/07.
- 012080316 Forwards 1E Info Lotice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/10.
- 012040157 Forwards IR Sulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. Q'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/14.
- 012050050 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21, 1p. 07173:215.
- 012050621 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY.J P. Region 2. Atlanta, Office of the Director. 80/11/24.
- Di2170496 Forwards IE Info Natice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.

 Q*REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26. dp.
- 012170351 Ack receipt of IE Insp Repts 50-400/80-25,50-401/80-23, 50-402/80-23 & 50-403/80-23 on 600727-1031.No proprietary info. HCME.P.W. Carolina Power & Light Co. 80/12/08, 1p. 07286:112.
- 8012190359 Forwards IE Insp Repts 50-400/80-25,50-401/80-23, 50-402/80-23 & 50-403/80-23 on 800929-1031 & motice of violation NURPHY.C.E. Region 2: Atlanta, Reactor Construction & Engineering Support Branch: 80/11/28 20p 07286:113.
- B012190269 Notice of violation from insp on 800529-1031.

 Region 2, Atlanta, Giffice of the Director. 80/11/26. 1p. 07285:115.
- B012190335 IE Insp Repts 50-400/EG-25, 50-401/B0-23, 50-402/B0-23 & 50-403/B0-23 on B00927-1031. Noncompliance noted: failure to control outdated shawings & to provide instructions for verification data collection.

 MANNELLO.F Region 2. Atlanta, Office of the Director.
 BRYANT.U.C. Region 2. Atlanta, Reactor Construction & Engineering Buoport Branch. B0/11/26 7pp 0/286:116.
- 012180375 Ack receipt of 201120 itr informing NRC of steps taken to correct violations noted in lE insp Repts 50-400/80-22, 50-401/80-20, 50-402/80-20 & 50-403/80-20. MURPHY.C.E. Region 2. Atlanta Reactor Construction & Engineering Support Branch. 80/12/04 ip 03/74-233.
- 8012180396 Responds to LRC 801103 ltm re violations noted in IE Inap Repts 50-400780-22:50-401780-20:50-402780-20:50-403780-20: Corrective actions: reimsp of sessnic or safety-related hanger installed prior to problem discovery. HONE, P. N. Carolina Power & Light Co. 80711724, 3pp. 03794:234.

- --8012180378 Ack receipt of IE Insp Repts 50-400/80-22,50-401/80-20, 50-402/80-20 & 50-403/80-20 No proprietary info. HOME P. M. Carolina-Power & Light Co. 80/t1/11. 1p. 03794:237.
- -8012180400 Forwards IE Insp Repts 50-400/80-22,50-401/80-20, 50-402/80-20 & 50-403/80-20 on 803901-26 & notice of Violation.

 KURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/03. 2pp. 03794:238.
- -8012180402 Natice of violation from insp on 800701-26.

 4 Region 2. Atlanta. Office of the Director. 80/10/30. 1p.
 03794:240.
- ---8012180403 IE Insp Repts 50-409/80-22,50-401/80-20,50-402/80-20 & 50-403/80-20 on B00901-26. Noncompliance noted: failure to correctly translate /: Implement codes // stds for special processes.

 MAXIELL.O.F. Region 2. Atlanta, Office of the Director.
 BRYNNI.J.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/30. 7pp. 03/74:241.
- R: Periodic operating reports & related correspondence
- 8012150073 Forwards const milostones & activities to 801130. MCDUFFIE.M.A. Carolina Power & Light Co. 80/12/04. lp. 07237:243.
- --8012150074 Constr milestones & activities updated to 801130. Carolina Powar & Light Co. 80/11/30. 12pp. 07237:264.
- S. Reportable occurrences, LERs & related correspondence
- 8012010339 Forwards interim deficiency rept re 801017 confirmation of nonsafety heating, ventilation & air conditioning for Class IE motor control ctrs. Due to extensive nature of problem, all carrective action expected to be completed by 810215, CHIAN31, N. J. Carolina Power & Light Co. 80/11/24, 4pp. 07097:039.
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4 A. Application/construction stage documents & correspondence
- B012160090 Ltr to operating plant licensees.DL applicants & CP holders. Forwards NUREG-0737 re TML action plan requirements.Requests appraising reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- BO12090643 Forwards BNR owners group design & operational criteria for scram discharge sys.Criteria viewed as being responsive to requirement of providing assurance of reliable & safe operation of sys.

 NATERS, D. 8. Carolina Power & Light Co. 80/11/24. 4pp.
- G. Inspection reports, IE Bulletins & correspondence
- 9012150190 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24.
- 8012170302 Forwards Suppl 2 to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/24.
- B012180927 Forwards IE Info Notice B0-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30.
- 8012170785 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mig by Valcor Engineering Corp." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012230045 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.

 U'REILLY, J.P. Region 2, Atlanta, Offica of the Director. 80/10/31.

- 8012110767 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/06, ip.
- BOI2030887 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. D'REILLY. J. P. Region 2. Atlanta. Office of the Director. BO/11/07. 10.
- 8012080316 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10. ip.
- 8012040157 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/14. 1p.
- 8012050060 Forwards IE Bulletin 80-24, "Provention of Damage Due to Water Leakage Inside Containment." No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21.
- 8012050621 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24.
- 8012170496 Forwards IE Info Notice 80-29, Suppl 1, "Broten Studs on Terry Turbine Steam Inlet Flange" No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.
- 8012190351 Ack receipt of 1E Insp Repts 50-400/80-25, 50-401/80-23, 50-402/80-23 & 50-403/80-23 on 800927-1031. No proprietary info. HDMs, P. N. Carolina Power & Light Co. 80/12/08. 1p.
- --8012190359 Forwards IE Insp Repts 50-400/80-25,50-401/80-23, 50-402/80-23 & 50-403/80-23 on 800929-1031 & notice of violation.
 MURPHY.C.E. Region 2- Atlanta, Reactor Construction & Engineering Support Branch. 80/11/28. 200.
- --8012170369 Notice of violation from insp on 800729-1031. Region 2. Atlanta, Office of the Director. 80/11/26. 1p
- --8012190385 IE Insp Repts 50-400/80-25.50-401/80-23.50-402/80-23 & 50-402/80-23 on 800729-1031. Noncompliance noted: failure to control outdated drawings & to provide instructions for verification data collection MAXWELL, O.F. Region 2. Atlanta, Office of the Director. 80/11/26.70a.
- 8012180395 Ack receipt of 801124 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-400/80-22, 50-401/80-20, 50-402/80-20 & 50-403/80-20. MRPHY.C.E. Region 2, 4tlanta, Reactor Construction & Engineering Support Branch. 80/12/09. 1p.
- --8012180396 Responds to NRC 801103 ltr re violations noted in IE Insp. Repts 50-400/80-22, 30-401/80-20, 30-402/80-20 & 50-403/80-20. Corrective actions: reinsp. of seismic or safety-related hanger installed prior to problem discovery.

 HOME, P. M. Carolina Power & Light Co. 80/11/24. 3pp.
- --8012180398 Ack receipt of IE Insp Repts 50-400/80-22,50-401/80-20, 50-402/80-20 & 50-403/80-20 No proprietary info, NOME, P. W. Carolina Power & Light Co. 80/11/11. 1p.
- --8017180490 Forwards IE Insp Repts 50-400/E0-22,50-401/B0-20, 50-402/B0-20, & 50-403/S0-20 on 800701-26 & notice of violation.

 HURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch, 80/11/03. 2pp.
- --B012180402 Notice of violation from insp on 800701-26.

 # Region 2, Atlanta, Office of the Director. B0/10/30. ip.

- --8012180403 lE lnsp Repts 50-440780-22.50-401780-20.50-402780-20 & 50-403780-20 on 800901-26 Noncompliance noted: failure to correctly translate & implement codes & stds for special processes MACKELL, G. F. Region 2. Atlanta, Office of the Director. 80/10/30.
- R. Periodic operating reports & related correspondence
- 8012150973 Forwards monthly operating repts for Nov 1980. MCDUFFIE: M.A. Carolina Power & Light Co. 80/12/04. 1p.
- --8012159074 Constr milestones & activities updated to 801130. 4 Carolina Power & Light Co. 80/11/30. 12pp.
- S. Reportable occurrences, LERs & related correspondence
- 8012010339 Forwards interim deficiency rept re 801017 confirmation of nonsafety heating, ventilation b air conditioning for Class IE motor control ctrs. Due to extensive nature of problem, all corrective action expected to be completed by 810215. CHIANSI, R. J. Carolina Power & Light Co. 80/11/24. 4pp.
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

 A. Application/construction stage documents & correspondence
- B012290485 Responds to 800911 week requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey. DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & surnary of 1E survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed ω/71% planning or considering increasing storage capacity.

 BARGART.R.L. Effluent Treatment Systems Branch. 80/11/06. Hpp.
- 8012300586 Notifies of completion of feasibility study & decision to cancel Unit 4 const. Evaluation of adequacy of Unit 3 design may warrant changes Licensee will address open items maintained in delay files as evaluation progresses.
 FEROUSURULLY Virginia Electric & Power Co 80/12/22. 2pp.
- Q. Inspection reports, IE Bulletins δ correspondence
- 8012160036 Forwards EE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No critten response required.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/24, 1p.
- 8012170774 Forwards Suppl 3 to 16 Bulletin 79-018, "Environ Qualification of Class 16 Equipment." No written response required.

 0'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/10/24, 1p. 07268:255.
- 8012170821 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/10/30.
- 8012180020 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required. G*REILJ Y.J.P. Region 2. Atlanta, Office of the Director. 80/10/31, 1p. 03790:120.
- 80122300/0 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergoncy Generators." No written response required. 0'REILLY.J.P. Region 2: Atlanta, Office of the Director. 80/10/31, 1p. 07313:236.
- B012110794 Forwards 1E Bullotin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. B0/11/06.
- 8012030819 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Pepressurization." No written response required. O'REIULY.J.P. Region 2. Atlanta, Office of the Director. 80/11/07.

- 8012080259 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Eys at Davis Basse Unit 1," No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 80/11/10. 1p.
- E012040135 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 60/11/14, 1p.
- 8012050303 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 G'REJULY.J.P. Region 2: Atlanta, Office of the Director. 80/11/21.
 1p. 07173:077.
- 8012080018 Forwards 16 Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid " No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24. p.
- 8012170387 Forwards IE Info Notice 80-29, Suppl 1. "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required. O'REILIV, J. P. Region 2. Atlanta. Office of the Director. 80/11/26. 15.
- DOCKET 50-405 NORTH ANNA FOWER STATION, UNIT 4
- A. Application/construction stage documents & correspondence
- 8012220485 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply u/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENTON.H.R. Diffice of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220505 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 3AMSART, R. L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- 8012300588 Notifies of completion of feasibility study & decision to cancel Unit 4 const Evaluation of adequacy of Unit 3 design may warrant changes. Licensee will address open items maintained in delay files as evaluation progresses. FEROUSOR.J.H. Virginia Electric & Power Co. 80/12/22. 2pp. 07339; 238.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012160936 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/10/24.
- 8012170274 Forwards Suppl 3 to 16 Sulletin 79-01B, "Environ Qualification of Class 16 Equipment," No written response required.
 0'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.
 1p. 07268:255.
- 80121709±1 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/30.
- 8012180320 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31, ip.
- 8012230070 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required., O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012110794 Forwards IE Bullatin 80-21, "Valve Yotes Supplied by Malcolm Founday Co. Inc." Written response required. O'REILLY. J. P. Region 2, Atlanta, Office of the Director. 80/11/06.

- 8012030849 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuriation "No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07. 16.
- B012090259 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Resse Unit 1," No response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/11/10.

 ip.
- 8012040135 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/14.
 1p.
- 8012090033 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response . required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21. ip. 07173:077.
- 8012080018 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director, 80/11/24. 1p.
- 8012170337 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY. J. P. Region 2. Atlanta. Office of the Director. 80/11/26. 1p.
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

 F. Security, medical, emergency & fire protection plans
- 8012190017 Informs of recently approved revised 10CFR50.48 containing schedules for completion of all fire protection mods.No present implementation required as necessary addl info has not yet been approved.

 EISENMUT.D.G. Division of Licensing. 80/11/06. 6pp. 07278:205.
- 8012020098 Discusses planned mods to emergency notification sys & health physics network NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys. W/o encl health physics network manual. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 80/11/19. 2pp. 07148:355.
- Q. Adjudicatory correspondence
- 8012080007 Order postponing scheduling of prehearing conference originally set for 801216 until conclusion of hearing originally scheduled to commence on that date. Also modifies limited appearance schedule.

 BECHHORRER.C. Atomic Safety and Licensing Board Panel. 80/11/25. 2pp. 07175:392.
- 8012110005 Order granting extension until 801212 for Commission to determine whether to review ALAB-617. CHILK, S. J. Office of the Secretary of the Commission. 80/11/26. ip. 07223:113.
- 8012120616 Petition for Commission review & reversal of ALAB-618. ASLB has transformed show cause proceeding re liquefaction potential into unnecessary inquiry into appropriate SSE. M/Certificate of Svc.
 GALLEN.K.P., HIESTAND.O.S. Dairyland Power Cooperative. GALLEN.K.P. Morgan, Lewis & Rockius. 89/12/01. 12pp. 07227:306.
- 8012300368 Licensee response in opposition to Coulee Region Energy Coalition (CREC) 801121 motion for extension of time & 801002 motion to compel discovery in liquefaction show cause proceeding Certificate of Svc encl.

 HIESTAND, O. S. Dairyland Power Cooperative. HIESTAND, D. S. Morgan, Lewis & Bockius. 80/12/03 5pp. 07957:174.
- 8012290590 Statement re risk issue identified in ASLB 801112 memorandum & order.Little.if any.risk to public health & safety exists if 810225 proposed operation date extended. Prof qualifications & Certificate of Svc encl. * Dairyland Power Cooperative. 80/12/05. 17pp. 07333:124.

- 8012290555 Lists questions to be answered prior to final determination. Parties should be prepared to discuss questions at 801216 evidentiary hearing. BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 80/12/05. 3pp. 07333:141.
- 8012270024 Response in opposition to consolidated parties' B01121 motion for extension of time & motion to compel discovery re show cause order. Motions moot due to ALAB-618, dtd B01117, declaring ASLB w/o authority. W/Certificate of Svc. BURNGS.S. C. Rulemaking & Enforcement Division. B0/12/08. 6pp. 07344:217.
- 8012220322 Response in support of util 801114 motion for summary disposition of liquefaction issue. Soil under pile-supported structures safe against liquefaction.
 BURNS: B. G., CYRIK. Rulemaking & Enforcement Division. 80/12/09.
 4pp. 07307:323.
- --8012220335 Affidavit in support of util contention that reasonable assurance exists that liquefaction will not occur beneath pile-supported structures in event of 5.5 earthquake.Prof qualifications & Certificate of Svc enct.

 ORECVES.J.T. Hydrologic & Geotechnical Engineering Branch.
 80/12/09. 5pp. 07307:327.
- E012270287 Requests denial of licenses B01201 petition for review of ALAB-618 MRC rules do not authorize petitions for review of ASLAP decisions on certified questions, except in matters of exceptional legal importance. Certificate of Svc enci. BURNIS, S. C., CYR. K. D. Rulemaking & Enforcement Division. 80/12/12, 13pp. 07341:174.
- 8012290180 Forwards NRC Exhibits 6 & 7 in show cause proceeding. W/o encls. BURNS, S. C. Rulemaking & Enforcement Division. 80/12/18. 1p. 07344:171.
- 8012290185 Order granting extension to 810109 for Commission to review ALAB-618.
 CHILK.S. J. Office of the Secretary of the Commission 80/12/22.
 ip. 07344:176

H. General correspondence

- 8012110232 FOIA request for documents concerning events re transportation & insp of eight raduaste shipments from util during Mar & Apr 1979 & all generic documentation re Hodel NFB-4. LITTLEJDIN, J. D. League Against Nuclear Dangers Minnesota Chapter. 80/10/25. ip. 07224:090.
- 8012110227 Responds to FQIA request for documents concerning events re transportation & insp of eight radiuste shipments from util during Mar & Apr 1979 & all generic documentation re Model NFS-4. Forwards App A documents. M/o encis. FELTON J. N. Division of Rules and Records. 80/12/04. 2pp. 07224:088.
- P. Operating license stage documents & correspondence
- B012160050 Ltr to operating plant licensees, QL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISE(HUT, D.O. Division of Licensing, 80/10/31, 7pp.
- 8012220358 Ltr to all CP % OL holders for BiRs re requirement for implementation of ODYN code for licensing basis calculations performed by QE. Applicable to all license applications & proposed amends, including core reloads.

 EISENORUT, D. G. Division of Licensing. 80/11/04. 4pp.
- B012220563 Ltr to all power reactor licensees forwarding NUREQ-0619, "BWR Feedwater Noizle % Control Rod Drive Return Line Noizle Cracking." Confirmation that implementation dates will be mat must be sent within 45 days (Wo encl. EISERHUT, D. C. Division of Licensing. 80/11/13. 1p.
- 8012020973 Forwards revised Page 6-3 of 800806 application to amend License DPR-45. LINDER, F. Dairyland Power Cooperative. 80/11/18. 3pp. 07148:174.
- 8012090393 Forwards corrected Tech Spec Page 32h & updated Page 6-3 from application for amend to License DPR-45 submitted 800912.

 LINDER, F. Dairgland Power Cooperative. 80/11/18. 2pp. 07207:139.

- ~~8012070377 Corrected Tech Spec Page 32h & updated Page 4-3 from application to amend License DPR-45 submitted 800912.

 * Dairyland Power Cooperative 80/10/29. 2pp. 07207:141.
- 8012010310 Concurs w/NRC 800820 evaluation of SEP Topic VIII-2 re onsite emergency power sys diesel generator Forwards responses to NRC questions re diesel generator testing. LINDER, F. Dairyland Fower Cooperative. 80/11/20. 4pp. 07098: 031
- 8012920100 Advises that injection of grout into voids underneath turbine bldg was completed on 801023. Encl table includes data for each hole in which grout was injected. One oversize drawing encl. PDR drawing on aperture card only.

 LINUER: F. Dairyland Poser Cooperative. 80/11/26. 6pp. 07148: 187
- 8012020315 Forwards "Design of Emergency Svc Water Supply Sys for LACBUR." Safe shutdown & conidown capability can be achieved & maintained in case of one or more adverse events. Installation of sys can be completed by 810225. LINGER.F. Dairyland Power Cooperative. 80/11/26. 2pp. 07142:001
- --8012020318 "Design of Emergency Svc Water Supply Sys for LACDWR," D & Moore statement of surface stability encl. FINNAW.C.F., MILDB.R., YOLLA. Nuclear Energy Service, Inc. 81A0039, 80/11/25, 26pp. 07142:003
- 8012080487 Forwards NES Document 81A0040, "Seismic & Structural Analysis of Genoa 3 Stack Using NRC Site-Specific Ground Response Spectra." LINUER.F. Dairyland Power Cooperative. 80/11/26. 1p. 07187:001.
- --8012080495 "Seismic & Sturctural Analysis of Genoa 3 Stack Using NR Site-Specific Ground Response Spectra." RUMPF, R.E. STRNAD, T. Nuclear Energy Service, Inc. 81A0040, 80/11/25. 33pp. 07187:001.
- B012180155 Confirms 801215 meeting in LaCrosse, HI to discuss evaluation of facility regulatory performance. KEPPLER, J. C. Region 3. Chicago, Office of the Director. 80/11/28. lp. 03771:286.
- 8012190061 "Safety Evaluation of Inservice Testing Program for Pumps Valves at LACBUR, Nov 1979-Jul 1981," SER. FEHRINGER, J.M., ROCKHOLD, H.C. Idaho National Engineering Laborator FIN A-6258. 8012190061 80/11/30. 33pp. 07279:042.
- BO12140350 Forwards "Liquefaction Potential Under Genoa-3 Stack Adjacent to LACBWR Near Genoa, Vernon County, MI." Rept concludes that adequate safety margin exists against liquefaction potential. LINDER, F. Dairyland Power Cooperative B0/12/04. 1p. 07248: 289.
- --8012160359 "Liquefaction Potential Under Genoa-3 Stack Adjacent to LACBUR Near Genoa-Vernon County, NT." * Dames & Moore, 80/12/10 54pp. 07248: 290.
- B0122204BS Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey. DENTOM. M.R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --8012220595 Forwards tabulation 5 summary of IE survey on low level waste at 51 reactors Low level waste storage facilities have been espanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANDARTER.L. Efficient Treatment Systems Branch. 80/11/06. 8pp.
- 8012120225 Forwards repts on reviews of plant transient & accident analyses, per NUREG-0578 requirements.
 LINDER, F. Dairyland Power Cooperative. 80/12/05, 9pp. 07228:249
- --8012120241 "LACBUR Review of Plant Transients." FIRMAN, C.F., YOLI, A.H., MILOS, R. Dairyland Power Cooperative, 81A0037, 80/07/09, 24pp. 07228; 260.
- 8012290475 Informs of completion of review of NES-BIACO33, "LACBUR Ro Drop Probability Study," submitted by 790329 its Backfitting of sys. to monitor rod patterns not necessary. CRUICHFIELD.D. Operating Reactors Branch 5, 80/12/05, 6pp.
- B012310157 Notifies of fee determination for util 800416 request for route approval to cover shipments of spent fuel.Ofc of Contralier has been notified to issue invoice.
 MILLER.R. O. License Fee Management Branch. 80/12/08. 1p.

- B0122404B9 Notification of B01213 meeting w/SEP owners group in Betheada.ND for discussions on SEP program schedule for license topic completion b assignment of lead topics to plants RUSSELL.N T Systematic Evaluation Program Branch. 80/12/16. 2pp.
- Q. Inspection reports: IE Bulletins & correspondence
- 8012160355 Forwards IE Info Motice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
 KEPPLER.J.G. Region 3. Chicago, Office of the Director. 80/10/24.
 1p. 07262-164.
- 8012180022 Forwards IE Investigation Rept 50-409/80-07 on 800826-27. No NEIDUCE 1 TO THE TOTAL OF THE PROPERTY OF THE DIRECTOR OF T
- --8012182026 IE Investigation Rept 50-409/80-07 on 800826-27. No noncompliance noted Major areas investigated whether contents of 800116 ltr re-status of modified amended security plan implementation were intentionally misleading. PHILLIP.G.A., NORELIUB.C.E., DONAHUE, J.R. Region 3, Chicago, Office of the Director 80/11/10, 6pp. 03790:112.
- 8012020743 Forwards three Performance Appraisal Branch inspirepts & mgt avaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments [No encl.].

 KEPPLER.J. G. Region 3/ Chicago: Office of the Director. 80/11/18.
- 8012040654 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Hater Leakage Inside Containment." No written response required.
 KEPPLER.J.G. Region 3, Chicago, Office of the Director. 80/11/21.
 2pp. 07166:321.
- 8012080055 Forwards 1E Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:198.
- 8012220688 Responds to IE Bulletin 80-23 re failure of solenoid valves mfg by Valcor Engineering Corp. No Valcor solenoid valves in use at site.

 LINGER.F. Dairyland Power Cooperative. 80/11/24. 1p. 07273:120.
- 8012230236 Forwards new security badge numbers & clearance levels for Region 3 personnel Changes should be entered on Sept 1980 access lists KEPPLER.J. G. Region 3. Chicago. Office of the Director. 80/11/25. 6pp. 07317:313
- 801217054; Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.

 KEPPLER J. G. Region 3, Chicago, Office of the Director. 80/11/2 ER.J. G. Region 3. Chicago. Office of the Director. 80/11/26. 07264:270
- B0121B022B Ack receipt of B01125 itr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-409/80-09. Time & date stated in rept is incorrect. HEIBMMAN.R.F. Region 3. Chicago. Reactor Operations Muclear Support Branch. B0/12/09. lp. 03792-027.
- R. Periodic operating reports & related correspondence
- S012160280 Forwards monthly operating rept for Nov 1980. LIMBER.F. Dairyland Power Cooperative. 80/12/09. Ip lp. 07252:241.
- --8012160284 Monthly operating rept for Nav 1980 ODBCMARL S. Dairyland Power Cooperative 80/12/04. 12pp. 0000MAN.L S. 07252:242.
- S Reportable occurrences, LERs & related correspondence
- B012020505 RO 80-12:on B0111B.abnormal wear degradation discovered in fuel cladding during reactor refueling. Further investigation determined fuel cladding on Assemblies 2-37 & 2-50 not abnormal. Notification of RO 83-12 is withdrawn.
 LINDER.F. Dairyland Power Cooperative. B0/11/20. 2pp. 07141:264.
- 8012020453 Forwards LER 8D-011/01T-0. LINDER.F. Dairyland Power Cacperative. 80/11/24. 4pp. 07143:233.

- --B012020455 LER 80-011/017-0: on B01110, cooldown rate exceeded Tech Spec limit of 190 F per/h at five points on reactor vessel. Caused by temp differential between coolant & upper portion of vessel. Water level lowered to slow cooldown rate. G000MAU.L. S. Dairyland Power Cooperative. 80/11/24. 4pp. 07143: 237.
- 8012050502 RO B0-14: degradation discovered in primary reactor containment during Type C leak rate testing. Leak flow rates exceeded Tech Specs. Heating steam condensate valve will be repaired or adjusted & retested.

 LINDER.F. Dairyland Power Cooperative. B0/11/28. 3pp. 07174:250.
- 8012100579 Forwards LER 80-010/03L-0. LINDER.F. Dairyland Power Cooperative. 80/11/28. 2pp. 07218:127.
- -8012100535 LER 80-010/03L-0: on 801028, shutdown condenser control valve quarterly test performed approx 4-h boyond deadline. Caused by personnel error. Test performed & supervisor will check schedule more closely in future.

 GOODMANS.L.S. Pairyland Power Cooperative. 80/10/28. ip.
- 8012100530 Forwards LER 80-009/03L-0 & updated LER 80-005/01T-1. LENDER: F. Dairyland Power Cooperative. 80/11/28. 3pp. 07218:133.
- --8012100540 LER 80-009/03L-0: on B01027, mechanical interlock preventing containment bldg personnel airlock doors from opening simultaneously found inoperable. Caused by stripped door link subassembly. Door guarded & padlocked & subassembly repaired. GODDMAN, L. S. Dairyland Power Cooperative. B0/11/25. ip. 07218: 136.
- --8012160547 Updated LER 80-005/017-1: on 800805, valve addition to shutdown condenser shell gage tap found w/o design change. Caused by personnel error. Valve removed, pipe cap installed & tested. vested. GOODMAN.L.S. Dairgland Power Cooperative. 80/11/28. 3pp. 07218:137.
- 8012090206 RO 80-15: on 801129, while performing periodic Type C leak tests on retention tank pump discharge valve, leak flow rates from condensate exceeded Tech Specs. Repairs & adjustments to valve will be accomplished & retest performed.

 LINDER, F. Dairyland Power Cooperative. 80/12/01. 2pp. 07207:186.
- 8012150744 RO 80-15: on 801129, degradation discovered in primary reactor containment during periodic Type C surveillance leakage rate testing while in shutdown condition. Repairs &/or adjustments to be performed on retention tank pump discharge valve.

 LINDER, F. Dairyland Power Cooperative. 80/12/01. 2pp. 07237:233.
- 8012090354 Forwards LER 80-016/01T-0. LIMBER, F. Dairyland Power Cooperative. 80/12/03. 2pp. 07203:001.
- --8012070369 LER 80-016/01T-0: on 801202, hourly fire watch patrol not established within 1-h of drilling holes through turbine bldg barriers for fire protection & sampling sys. Job coordinators reminded of fire barrier requirements. 00007464; L.S. Dairyland Power Cooperative. 80/12/03. 1p. 07203:003
- 8012160442 Forwards LERs 50-014/01T-0 & 80-015/01T-0. LINDER:F. Dairyland Power Comparative. 80/12/10. 2pp. 07254:172.
- --8012160449 LER 80-014/01T-0:on 801127, containment isolation did not meet test criteria. As-found leakage rate for condensate return isolation valve 73-25-021 was 14.3 SCFH. Cause not stated. Valve internals totally replaced. GODMAth.L.S. Dairyland Power Cooperative. 80/12/09. 1p. 07254:174.
- --8012160463 LER 80-015/01T-0:on B01127, containment isolation did not meet test criteria. As-found leakage rate for ratention tank pump discharge valve 54-25-006 was 0.56 4.0 BCFH Cause unstated. Gaskets replaced & new packing installed. G0DD/MAR, L. S. Dairyland Fower Cooperative. 80/12/07. lp. 07294:175.
- 8012230378 RD 80-17 on 801216, during periodic Type C surveillance leakage rate testing while shutdown, leak flow rates exceeded parmissable rates for reactor vent header valve & reactor cavity purge air line. Repairs will be accomplished.
 LINUER, F. Dairyland Power Cooperative. 80/12/17. 3pp. 07311:260.

- T. Hearing transcripts on non-antitrest matters
- B012270636 Forwards L Reiter & HA Levin B01205 prepared testimony in response to questions posed by 801112 & 25 show cause orders BURNS, S. G. Rulemaking & Enforcement Division. B0/12/05. 1p. 07332 312.
- --9012290640 Transcript of L. Reiter prepared testimony in response to questions posed by 801112 % 23 show cause orders Prof qualifications & Certificate of Svc encl. REITER.L. Gaosciences Branch. 80/12/05. 7pp. 07d32:313.
- --B012290645 Transcript of HA Levin testimony in response to Guestion 4 in ASLB 801212 order 3 Ovestion 6 in 801226 order Profqualifications & Certificate of Svc encl. LEVIN.M.A. Division of Engineering. 80/12/05. 7pp. 07332:320.
- 8012290388 Transcript of 801214 hearing in La Crosse.WI re show cause order. Pp 68-237. * Atomic Safety and Licensing Board Panel. 80/12/16. 169pp. 07330:028.
- 8012290454 Transcript of 801217 hearing in La Crosse,WI re show cause order,Pp 238-431.DE Nudd 801216 ltr encl. • Atomic Safety and Licensing Board Panel. 80/12/17. 193pp. 07337:191.
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- B012140050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be ret. EISENHUT.D.G. Division of Licensing. B0/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BURs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012160032 Notification of 801212 meeting w/Mark II owners group in Bothesda,MD to discuss suppression pool temp limit. SU.T.M. Generic Issues Branch. 80/12/05. 1p.
- 8012160190 Notification of 801210 meeting w/Mark II owners group in Bethesda,MD to discuss status of improved chugging load program, ANDERSON,C. Generic Issues Branch. 80/12/02 1p.
- 8012290485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENIGH, H. R. Office of Nuclear Reactor Regulation, Director. B0/12/04. 2pp.
- --8012220505 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been espanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART.R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- G. Inspection reports, IE Bulletins & correspondence
- BO1211039B Forwards LE Insp Rept 50-410/80-09 on B00909-11, No noncompliance noted.

 CARLSON, R. T. Region L. Philadelphia, Reactor Construction & Engineering Support Branch. 90/10/05. 2pp. 07227; 169.
- --8012110605 IE Insp Rept 50-410/60-07 on 800909-11. No noncompliance noted Major areas inspected: QC records, storage & unresolved items.
 FEIL.R. A. Region 1, Philadelphia, Office of the Director, NARRON, L. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/03 7pp. 07227:171.
- 8012230)73 Forwards IE Insp Rept 50-410/80-10 on 800723-26.No noncompliance noted. CARLBOX.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/16. 2pp. 07313: 240.

- --8012230080 IE Insp Rept 50-410/80-10 on 800923-26. No noncompliance noted Major areas inspected corporate QA program, organization, procedures & interface.
 CHADWHARY, EM. Region 1, Philadelphia. Office of the Director.
 EBNETER, S. D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/15 5pp.
- 8012160046 Forwards 18 Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 GRIER, B. H. Region 1, Philadelphia, Office of the Director.
 80/10/24.
- 8012010350 Responds to 1E Sulletin 80-20, "Failures of Hestinghouse Type H-2 Spring Return to Neutral Control Switches." Switches have not been used in safety-related sys at facility. RHDDE-C K. Niagara Mohawi Power Corp. 80/10/30. 1p. 07098:042.
- 8012030310 Advises that info requested in IE Bulletin 80-16, "Potential Misapplication of Rosemount, inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes," will be provided by 801231 RHODE, G. K. Niagara Mohawk Power Corp. 80/10/31. 1p. 07149:269.
- 8012120136 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER. B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230:205.
- 9012030780 Forwards IF. Info Natice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. GRIER.B. H. Region 1. Philadelphia, Office of the Director. 80/11/07. 1p. 07150:195.
- 8012080494 Forwards IF. Info Notice 80~41, "Failure of Bwing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 GRIER.B. H. Region 1. Philadelphia. Office of the Director.
 80/11/10. ip. 07:82:391.
- 8012040928 Forwards IF. Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpoder associated w/corrective actions. GRIER, B.H. Region 1. Philadelphia, Office of the Director. 80/11/14. ip. 07149;311.
- G012220695 Advises that written response is required to 1E Bulletin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.

 ORIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/19. 1p. 07293:123.
- B012040618 Forwards IE Bulletin B0-24. Prevention of Damage Due to Water Leskage Inside Containment. No written response required.

 ORIER, B.H. Region 1, Philadelphia, Office of the Director.

 B0/11/21. 2pp. 07165:296
- B012050575 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B. H. Region 1, Phi)adelphia, Office of the Director. 80/11/24. ip. 07174:065
- S. Reportable occurrences. LERs & related correspondence
- 8012080348 Ack receipt of B01008 interim deficiency rept no deviations in welding of rebar to shear bar-reactor pedestal Rept will be reviewed & evaluated CARLSON R. T. Division of Reactor Operations Inspections. 80/10/27.
- B012080414 Ack receipt of B01002 interim deficiency rept re spont fuel pool cooling water heat exchangers. Rept will be reviewed & evaluated.

 CARLSON R. T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. B0/10/27. 1p. 07196; 174.
- 8012070345 Interim deficiency rept.originally reported on 800702.re spent fuel pool cooling water heat exchangers. Addi info, furnished by vendor, being evaluted Affected heat exchangers rejected. Final rept will be submitted by 810430.

 DISE.D.P. Niagare Mohawk Power Corp. 80/12/01. 2pp. 07201:147.
- 8012240039 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded Caused by paint on panel surfaces or high resistance connection to panel surfaces where te mination modules are mounted.

 SHERMODD. O.G. General Electric Co. 80/12/08. 3pp.

2170448 Final deficiency rept.originally reported on 800708, re ASME procedures used to weld rebar 14 to shear bars on reactor adestal embedment PB-37 Procedures not code applicable for ork performed.
MDDE,G.K. Niagara Mohawa Power Corp. 80/12/12. 3pp. 07285:314.

2230462 Suppl to final deficiency rept transmitting corrected Pages i & 58 to biological shield wall rept & changing full mplementation date from Nav 1930 to Jan 1931. HODE-O.K. Niagara Mohaut Power Corp. 80/12/17. 3pp. 07319:287.

MET 50-412 BEAVER VALLEY POWER STATION. UNIT 2 Application/construction stage documents & correspondence

2160050 Ltr to operating plant licensees. OL applicants & CP holders. orwards NUREO-0737 re TM! action plan requirements. Requests perating reactor licensee confirmation in 45 days that incl 1 implementation dates will be not. [ISENHUT. D. G. Division of Licensing. 80/10/31. 7pp.

2030617 Forwards info to environ qualification of safety-related quipment, in response to NRC 801001 ltr. Util has not ownitted to qualification test program to upgrade lestinghouse (NSES) scope of supply (00LEVER-E J. Duquesne Light Co. 80/11/26. 4pp. 07151:158.

2220485 Responds to 800911 news requesting that Dfc of Nuclear leactor Regulation inform licensees of need to comply prevised Agreement State burial site conditions. Forwards results of IE survey. ENIONAR. Office of Nuclear Reactor Regulation, Director. 80/12/04. Spp.

012220506 Forwards tabulation & summary of LE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
BANSART, R. L. Effluent Treatment Systems Branch. 80/11/06. Bpp.

Security, medical, emergency & fire protection plans

2040118 Public version of "Independent Assessment of Evacuation imes for Beaver Valley Nuclear Power Plant," Vol 3, prepared or FEMA. GEBY.J.C., SHEPPARD, W.V., DAY, R.A., Wilbur Smith & Associates, 10/06/30. 56pp. 07188

2040055 Forwards public version of "Evacuation Time Assessment of line Nuclear Power Plants Emergency Planning Zones," secutive summary. [GLTDN.4] M. Division of Rules and Records. B0/12/03. ip. 04915:001.

012040088 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEMA Wilbur Smith & Associates. 80/06/30. 17pp. 04915:001.

012040153 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol Liprepared for FEMA. COSEY, J.C., SHEEPARD, R. V. Nitbur Smith & Associates. B0/06/30, 43pp. 07140:313

Inspection reports. IE Bulletins & correspondence

2(10074 Forwards IE Insp Rept 50-412/60-07 on 800722-24 No inccopilance noted ARLSCI.R.T. Region 1, Philadelphia, Reactor Construction & ingineering Support Branch SG/10/10. 2pp. 07223:302

3012110077 IE insp Rept 50~412/80~07 on 800722-24.No noncompliance noted Major areas inspected concrete placement, settlement monitoring program rept & review of outstanding items. NARNOULL, FEIL.R.A. VARREA.A.A. Region 1. Philadelphia, Office of the Director. 80/10/09. 7pp. 07223:304.

2170336 Forwards IE Info Notice 80-38, "Cracking in Charging Pumplessing Cladding " No written response required. RIER, B. H. Region 1, Philadelphia, Office of the Director. 10/10/30 1p. 07269:075.

2120157 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Coundry Co.luc." Hritten response required BRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06 1p. 07228:340

B012030525 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. GRIER, B.H. Region 1. Philadelphia. Office of the Director. 80/11/97. 1p. 07150:311.

8012080382 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

ORIERS H. Region 1, Philadelphia, Office of the Director.

80/11/10. 1p. 07182:360.

8012040042 Forwards IE Bulletin BO-23, "Failures of Solenoid Valves H#g by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions.

ORIER.B.H. Region 1, Philadelphia, Office of the Director.

BD/11/14. 1p. 07149.347.

8012220584 Advises that written response is required to IE Builetin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER B. H. Region i, Philadelphia, Office of the Director. 80/11/19. 1p. 07293:118.

8012040502 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp. 07165:207.

8012050551 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER,B.H. Region 1. Philadelphia, Office of the Director. 80/11/24. 1p. 07174:038.

DOCKET 50-413 CATAWBA NUCLFAR STATION, UNIT 1 A Application/construction stage documents & correspondence

8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREC-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be ret. EISSRMUT.D.G. Division of Licensing. 80/10/31. 7pp.

H. General correspondence

8012270021 Expresses concern re pending purchase by NC Electric Membership Corp of partial ownership in facilities, Questions financial advisability of purchase & requests hearings. AYERS.H. 9. Affiliation Unknown. 80/12/15. ip. 07308:001.

M. Antitrust correspondence

8012030752 Advises of receipt of 801027 add1 antitrust advice from Atty Oen re utils CP application. No antitrust hearing necessary re transfer of ownership interest. Forwards DDJ ltr. SALTIXARIJ. Utility Finance Branch (formerly Antitrust & Indemnity). 80/11/10. 2pp. 07149:276.

Q. Inspection reports, IE Bulletins & correspondence

8012140042 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/10/24.

8012170813 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30.

8012170571 Forwards IE Info Notice 80-37, "Kalfunction of Solenoid Vales Mfg by Valcor Engineering Corp." No written response required.

G'REILLY, J. P. Region 2: Atlanta, Gffice of the Director. 80/10/31.

8012230050 Forwards 1E Circular 80-23, "Fotential Defects in Beloit Power Sys Emergency Generators." No written response required.
O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/31.

- 8012110749 Forwards IE Bulletin 80-21, "Valve Yoles Supplied by Malcolm Foundry Co.Inc." Written response required. U'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/11/06.
- G012030873 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. G'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07.
- 8012080603 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10.
- 8012110613 Ack receipt of IE Insp Repts 50-413/80-27 & 50-414/80-27 on 800929-1003. No proprietary info. PARKER: U. G. Duke Power Co. 80/11/12. 1p. 07227:183.
- --8012110618 Forwards IE Insp Repts 50-413/80-27 & 50-414/80-27 on 800929-1003.No noncompliance noted. HURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/27. 2pp. 07227:184.
- --Bol2110623 IE Insp Repts 50-413/80-27 & 50-414/80-27, on 800929-1003. No noncompliance noted Major areas inspected: structural concrete, standby nuclear svc water pond dam foundations & site preparation.
 HARRISJ.R. Region 2, Atlanta, Office of the Director.
 CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/23. 4pp. 07227:186.
- 8012040172 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY, U.P. Region 2. Atlanta, Office of the Director. 80/11/14. is.
- B012050055 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21.

 Ip. 07173:210.
- 8012110666 Ack receipt of IE Insp Repts 50-413/80-31 & 50-414/80-31 on 801006-10. No proprietary info. PARKER-N C. Duke Power Co. 80/11/24. 1p. 07224:319.
- --80121(0474 Forwards IE Insp Repts 50-413/80-31 & 50-414/80-31 on 801006-10 No noncompliance noted. MURPHY.C.E Region 2- Atlanta. Reactor Construction & Engineering Support Branch. 80/11/05. 2pp. 07224:320.
- ---8012110694 IE Insp Repts 50-413/80-31 & 50-414/80-31 on 801006-10.No noncompliance noted Major areas inspected: installation of electrical penetrations, cobles, supports & equipment storage.

 MAXMcLLrG.F. Region 2, Atlanta, Office of the Director. BRYANT, J. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/04. 4pp. 07224:322.
- 8012170054 Ack receipt of 801121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-28 & 50-414/80-28. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/26. 1p. 07268:171.
- --9012170060 Responds to NRC 901028 ltr re violations noted in IE Insp. Repts 50-413/80-28 & 50-414/80-28, Corrective actions; supports removed & tray mounted correctly, Craftsmen trained to mount supports correctly.

 PARKER.N.O Duke Power Co. 80/11/21. 2pp. 07268:172.
- --8012170066 Forwards IE lnsp Repts 50-413/80-28 & 50-414/80-28 on 800922-26 & notice of violation KWRPHY.C.E. Region 2, Atlanta: Reactor Construction & Engineering Bupport Branch. 80/10/28. 2pp. 07268:174.
- --8012170070 Notice of violation from insp on 800922-26.

 * Region 2: Atlanta, Office of the Director. 80/10/22. 1p.
 07268:176.
- --8012170076 IE Insp Repts 50-419/80-28 % 50-414/80-28 on 800922-26.
 Noncompliance noted instrument tray & tray support installed on safety-related motors.
 GIBDNS.T.D. Region 2. Atlanta, Office of the Director.
 COXLON.T.E. Region 2. Atlanta Reactor Construction & Engineering Support Branch. 80/10/22. 3pp. 07268:177.

- 8012170507 Forward: IE Info Notice 80-27. Suppl 1. "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/26. 16.
- 8012180123 Act receipt of 801107 ltr informing NRC of steps taken to correct violations notes in IE lnsp Repts 50-413/80-24 & 50-414/80-24 & MURPHY, C.E. Region 2: Atlanta. Reactor Construction & Engineering Support Branch. 80/11/26. 1p. 03791:227.
- --8012180137 Responds to NRC 801008 ltr re violation noted in IE Insp. Repts 50-413/80-24 & 80-414/80-24. Corrective actions: measures established to ensure equipment removed from warehouse is maintained at designated storage levels.

 PARKER.N. O Duke Power Co. 80/11/07. 2pp. 03791:228.
- --8012180144 Forwards IE Insp Repts 50-413/80-24 & 50-414/80-24 on 800902-09 & notice of visitation MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/08. 2pp. 03791: 230.
- --8012180147 Notice of violation from insp on 800902-05.

 # Region 2, Atlanta, Office of the Director. 80/10/07. lp. 03791:332.
- --8012183150 IE Insp Repts 50-413/80-24 & 50-414/80-24 on B00702-05.
 Noncompliance moted: inadequate measures for storage & abandoned welding matl
 KLEINSDRGE.R.P. Region 2. Atlanta. Office of the Director.
 HERDT.A.B. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/07. 7pp. 03791:233.
- 8012190206 Act receipt of IE Insp Repts 50-413/80-32 & 50-414/80-32 on 801020-22 No proprietary this.

 PARKER, U. D. Dube Power Co 80/12/08 1p. 07282:094.
- --B012190213 Forwards IE Insp Repts 50-413/80-32 & 50-414/80-32 on B01020-22. No noncompliance noted. MVRPMY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. B0/11/20. 2pp. 07282:095.
- ---B012190222 IE Insp Repts 50-413/80-32 & 50-414/80-32 on B010R0-22.No noncompliance noted.Major areas inspected OA procedures & training records, response to 100FR50.55tel items & work recorrective actions.

 MCFARLAND.C.R. Region 2. Atlanta. Office of the Director.

 BRYANT.J C. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/11/17. 5pp. 07292:097.
- 8012310993 Ack receipt of IE Insp Repts 50-413/80-34 & 50-414/80-34 on 801105-07. No proprietary info PARKER, R. D. Buye Power Co. 80/12/18 Ip. 07370:159.
- --8012310295 Forwards IE Insp Repts 50-413/80-34 & 50-414/80-34 on B01105-07. No noncompliance noted. HARPHY.C. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/12/02. 2pp. 0/370:160.
- --8012310297 IE Insp Repts 50-413/80-34 & 50-414/80-34 on B01105-07. No noncompliance noted Major areas inspected previous insp findings. RCPB pipe welding & lafety-related pipe welding. GIRARD,E.H. Region F. Atlanta, Office of the Director. HERDT,A.R. Region R. Atlanta, Reactor Construction & Engineering Support Branch. 80/12/02. 3pp 0/370-162
- DOCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012160090 Ltr to operating plant licensees/DL applicants & CP holders. Forwards NUREC-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates unil be net.
 EISENNUT.D.G Division of Licensing. 80/10/31. 7pp.
- H. General correspondence
- B012290021 Expresses concern re pending purchase by NC Electric Membership Corp of partial ownership in facilities. Questions financial advisability of purchase & requests hearings. AYERS.H.O. Affiliation Uninc.m. 80/12/15. ip. 07308:001.

- O Inspection reports. IE Bulletins & correspondence
- 0012146032 Forwards IE Info Natice 80-37. "Containment Cooler Leats & Reactor Cavity Flooding 44 Indian Point Unit 2." No written response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/10/24.
- GO12170813 Forwards IE Info Rotice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 3. Atlanta, Office of the Director. B0/10/30.
- B012170571 Forwards IE Info Natice B0-39, "Malfunction of Solenoid Vales Hig by Valcor Engineering Corp." No written response required.

 O'REBLY, J. P. Region 2 Atlanta, Office of the Director. B0/10/31.
- 8012230050 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators," No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 6012110/49 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Kritten response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.
- 8012030973 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization "No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/07.
- BO12080A03 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10.
- 8012110613 Ack receipt of 1E Insp Repts 50-413/80-27 & 50-414/80-27 on 800929-1003 No proprietary info PARKER-N.O Duke Power Co. 80/11/12. 1p. 07227; 183.
- --8012110618 Forwards IE Insp Repts 50-413/80-27 & 50-414/80-27 on 800729-1003. No nuncorpliance roted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/27. 2pp. 07227:184.
- -8012110623 IE Insp Repts 50-413/80-27 & 50-414/80-27, on 800929-1003. No noncompliance noted Major areas inspected: structural concrete: standby nuclear svc unter pond dam foundations & site preparation HARRIS-J.R. Region 2. Atlanta, Office of the Director. COKCONITE. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/23. 4pp. 07227:186.
- 8012040172 Forwards IE Bulletin BO-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. D'REIU Y.J.P. Region 2, Atlanta, Office of the Director. 80/11/14.
- 8012050355 Forwards IE Bulletin 80-24, "Prevention of Danage Due to Water Leakage Inside Containment." No written response required. O'REILLY, J. P. Region 2 Atlanta, Office of the Director. 80/11/21.
- 8012110556 Act receipt of IE Insp Repts 50-413/80-31 & 50-414/80-31 on 801005-10 No proprietary info. PARKER-U.O. Dute Power Co. 60/11/24. 1p. 07224:319.
- --8012110676 Forwards IE losp Repts 50-413/80-31 & 50-414/80-31 on 831036-10. No honcompliance roted.
 MMRTMY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. GO/11/05. 2pp. 07224:320.
- --8012110484 IE Inso Repts 50-413/80-31 & 50-414/80-31 on 801006-10. No nencompliance rotad Major areas inspected installation of electrical genetrations, caples, supports & equipment storage MAKKELL.G F Region 2. Atlanta, Office of the Director. BRYAN Region 2. Atlanta. Reactor Construction & Engineering Support Branch. E0/11/04 4pp. 07224:322

- 6012176094 Ack receipt of 801121 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-413/80-28 & 50-414/80-28 MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Stanch.
- -8012170050 Responds to KRC 801028 ltr re violations noted in IE Insp Repts 59-413/80-28 ½ 50-414/80-28. Corrective actions; supports removed ½ tray mounted correctly. Craftsmen trained to mount supports correctly. PARKER, U. O. Dute Power Co. 80/11/21. 2pp. 07268: 172.
- --8012170066 Forwards IE Insp Repts 50-413/80-28 & 50-414/80-28 on 830922-26 & notice of violation. HWRPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/28. 2pp. 07268:174.
- --8012170070 Natice of violation from insp on 800722-24. → Region 2, Atlanta. Office of the Director. 80/16 07268:176. 80/10/22. 1p.
- -8012170076 IE Insp Repts 50-413/80-28 & 50-414/80-28 on 800922-26. Noncoapliance noted instrument tray & tray support installed on safety-related maters. GIBGUST.T.D. Region 2. Atlanta. Office of the Director. CONLON.T.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/22. 3pp. 07268:177.
- B012170509 Forwards IE Info Notice 80-29, Suppl 1. "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/26.
- B012180123 Act receipt of 801107 ltr informing NRC of steps taken to correct violations notes in IF Insp Repts 50-413/80-24 & 50-414/80-24. MRRPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Stanch. 80/11/26. 1p. 03791:227.
- --B01218G137 Responds to NRC B01008 ltr re violation noted in [E Insp Repts 50-413/B0-24 & 50-414/80-24. Corrective actions: measures established to ensure equipment removed from warehouse is maintained at designated storage levels. PARKER, U. O Duke Power Co. 80/11/07. 2pp. 03791:228.
- --8012180144 Forwards IE Insp Repts 50-413/80-24 & 50-414/80-24 on 800902-05 & notice of violation. HUPPHY.C.E. Region 2. Atlanks, Reactor Construction & Engineering Support Branch. 80/10/08. 2pp. 03791:230.
- --8012(80)47 Notice of violation from insp on 800702-05,

 Region 2, Atlanta, Office of the Director. 80/10/07. 1p.
 03791:332.
- --B012180150 IE Insp Repts 50-413/80-24 & 50-414/80-24 on B00902-05.

 Noncompliance noted inadequate measures for storage & abandoned welding math.

 RLEINSCRGE.N.P. Region 2, Atlanta, Office of the Director.

 HeRDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/07. 7pp. 03791:233.
- 8012190204 Ack receipt of 1E Insp Repts 50-413/80-32 & 50-414/80-32 on 801020-22 No proprietary info. PARKER, N. O. Duke Power Co. 80/12/09. 1p. 07282:074.
- -8012190213 Forwards IE Insp Repts 50-413/80-32 & 50-414/80-32 on 801020-22 No noncompliance noted. HURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/20. 2pp. 07282:095.
- --8012190222 IE insp Repts 50-413/80-32 & 50-414/80-32 on 801020-22.No noncompliance noted Major areas inspected: QA procedures & training records, response to 10CFR50, 55(e) items & work re corrective actions.

 NCFARLAND, C.R. Region 2. Atlanta, Office of the Director.

 BRYANT, J. C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 60/11/17. Spp. 07282:097.
- B012310293 Ack receipt of IE Insp Repts 50-413/80-34 & 50-414/80-34 on B01105-07. No proprietary info. PARKER.U.D. Duke Power Co. 80/12/18. 1p. 07370:159.

- --8012310299 IE Insp Repts 50-413/80-34 & 50-414/80-34 an 801105-07, No or 23/10277 It hisp Repts 30-413/80-34 & 50-414/80-34 an B01105-0; moncompliance noted Major areas inspected; previous insp findings.RCPR pipe welding & safety-related pipe welding. GIRAND.E.H. Region 2. Atlanta. Office of the Director. HERDT, Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 80/12/02. 3pp. 07370.162.
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- B012050554 Forwards application for Sk4 license to permit receipt, possession.insp & storage of SkK & associated radioactive matls incidental to operation of facility.

 DALE, L. F. Mississippi Power & Light Co. B0/10/01. 1p.
- 8012270012 Forwards Amends 6 to CPPR-118 & CPPR-119, safety evaluation, negative declaration.EIA & FR notice.
 EISER-UT, D. G. Division of Licensing. 80/10/29. 4pp. 07330:257.
- --8012270013 Amends 6 to CPPR-118 & CPPR-119, adding South KS Electric Power Association as co-cumer of facilities. EISENRUT, D. O. Division of Licensing. 60/10/27, 2pp. 07330:261.
- -B012270015 Safety evaluation supporting Amends 6 to CPPR-118 & CPPR-119.
 TEDESCO.R.L. Assistant Director for Licensing. 80/10/29. Bpp. 07330:263.
- --8012290018 EIA supporting Amends & to CPPR-118 & CPPR-119.

 * Division of Licensing. 20/10/29. 2pp. 07330:271.
- --B012270017 Negative declaration re Amend 6 to CPPR-118 & CPPR-119. HIRACLIA:F. J. Licensing Branch 3 80/10/29. 2pp. 07330:273.
- --8012270022 Notice of issuance of Amends & to CPPR-118 & CPPR-119. HIRAGLIA:F. J. Licensing Branch 3. 80/10/29. 2pp. 07330:275.
- DI2160350 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be ret. EISEIF-UT, D. C. Division of Licensing. 80/10/31. 7pp.
- 801222035B Ltr to all CP & OL holders for Bl&Rs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 ETSERGUT, D. O. Division of Licensing. 80/11/04. App.
- 8012080591 Forwards major casework milestones for DL review based on current Bevill schedules. Requests notification of inability to meet schedule & list of reviewers by 801129.
 TEDESCO.R. L. Assistant Director for Licensing. 80/11/18. App. 07196: 123.
- 8012300332 Confirms NRC 810105-09 visit to site re preliminary evaluation of control room.Preliminary human factors assessment to be forwarded & addl info supplied prior to Visit. KARTORE, J. A. Licensing Branch G. 80/12/04. App. 07359:001.
- 8012160777 Describes hydrogen control program, plans for implementation & preliminary conclusions resulting from evaluations, per NRC 801030 request.
 MCGAUGHY.J.P. Hississippi Power & Light Co. 80/12/07. 7pp. 07263: 148.
- 8012240250 Forwards draft Tech Specs for facility.Encl available in Central Files only. DALE:L F. Mississippi Power & Light Co. 80/12/15, 2pp. 07340:001.
- C. Utility Environmental Report (ER), amends & correspondence
- 8012080718 Requests add1 info in order to complete facility environ review & to satisfy NEPA requirements. Requests util amend environ rept to reflect responses to encl request.

 TEDESCO.R.L. Assistant Director for Licensing. 80/11/20. 3pp.
- 8012020449 Forwards clarified responses to environ rept Questions 350, 9-350, 12 re socioeconomic impact & initial response to Questions 451 l.Parts i & 2 re air quality. Encl responses will appear as Amend 5 to final environ rept.

 DALE, L. F. Mississippi Power & Light Co. 80/11/26, 9pp. 07148:247.

- 8012330489 Forwards preliminary responses to NRC Questions 371.07, 340.22 & 340.23 re plant sec unter-radial wells. Some changes may appear in final version to be included in Amend 5 to environ rept DATF.L.F. Mississippi Power & Light Co. 80/12/19, 114pp.
- F. Security, medical, emergency & fire protection plans
- 8012030592 Releases public versions of state & local emergency glans. FELTORY J. H. Division of Rules and Records. 80/11/26. 1p. 07188:055.
- --B012080606 Forwards public versions of State of MS emergency plan.State of MS.Port Gibson/Clairborne County emergency plan. State of LA preparedness plan for emergency operations Annex J.App 7 & State of LA Tensas County emergency plan. MSGAUGHY.J.P. Mississippi Power & Light Co. B0/11/20. 2pp. 07168:057.
- --8012030615 Public version of State of MS emergency operations plan.Vol 5. "Radiological Emergency Plan 4 4 Hississippi, State of 80/06/20, 100pp. 07183:131.
- ~-8012080620 Public version of State of MS.Port Gibson/Claiborne County energency operation plan.Anne> W. "Radiological Emergency Plan." * Claiborne County-MS * Affiliation Unknown. 80/11/20. 62ep. 07183:340.
- --8012080635 Public version of Revision 2 to State of LA,preparedness plan for emergency operations. Anney J. App 7, "Peacetime Radiological Response Plan."

 + Louisiana, State of. 80/04/30, 53pp. 07184:040.
- --8012083646 Public version of State of LA Tonsas Parish radiological emergency implementing plan.
 4 Affiliation Unknown. 80/04/30. 60pp. 07184:190.
- 8012080713 Releases public version of util revised energoncy plan. FELTON, J. M. Division of Rules and Records. 80/11/28, 1p. 07187:106.
- -8012090721 Forwards public version of revised emergency plan. Section 13.3 of FSAR will be revised.

 MCGAUGHY, J. P. Mississippi Power & Light Co. 80/11/20. 1p. 07187:100
- -8012093727 Public version of revised emergency plan to be incorporated in Section 13 3 of FSAR.

 * Mississippi Pawer & Light Co. 80/11/20. 250pp. 07187:109.
- M. Utility Final Safety Analysis Report (FSAR) & amends
- 8011280354 Forwards Amend 44 to application for Obs.consisting of responses to MRC questions.elscellaneous refinements of design info & revised hydrodynamic response spectra as required. Oversite drawings ent. MCGAUGHY.J.P. Mississippi Power & Light Co. 80/11/26. 2pp.
- --8011280067 Amend 44 to application for Ols, responding to NRC questions re FSAR & miscellaneous refinements of design info, MCGAUGHY, J. P. Mississippi Power & Light Co. 80/11/20. 2pp.
- 8012160497 Forwards affidavit of svc on distribution of Amend 44 to FSAR per 702627 ltr DALFal F. Mississippi Fower & Light Co. 80/12/08. 2pp. 07263:057.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012090505 Forwards IF Imap Rept 50-414/80-21 on 800901-30.No nonconfliance noted. LEWIG.R.C. Region 2, Atlanta, Deactor Operations Nuclear Support Branch, 80/10/22, Rep. 07206, 196.
- -8012070510 IE Insp Rept 50-416/80-21 on 800901-30. No nencompliance noted Major areas inspected preoperational test procedure & fuel storage license MaGKRF. A. C. Region 2. Atlanta. Office of the Director. KELLOGG. P. J. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/10/22. 5pp. 07206; 198.
- 8012166023 Forwards 1E Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No critten rasponse required. O'REILLY, J. P. Pec TULY, J.P. Region 2: Atlanta, Office of the Director. 80/10/24. 07261:175.

- 2012170370 Forwards Suppl 3 to 1E Sulletin 79-013, "Environ Gualification of Class IE Equipment " No written response required O'REIU'Y, J. P. Regian 2 Atlanta, Office of the Director. 80/10/24, 1p. 0/268, 306.
- 8012186306 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.

 O'REILULY.J.P. Region 2. Atlanta. Office of the Director. 80/10/31.
 19. 03791:163
- 8012230042 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Censisters" No written response required.

 O'REILLY J.F. Region 2. Atlanta. Office of the Director. 80/10/31. ip. 07311:233.
- 8012160027 Forwards IE Insp Repts 50-416/80-23 & 50-417/80-14 on 801007-10. No noncompliance noted. MURRHY, C.E. Regien 2. Atlanta, Feactor Construction & Engineering Support Branch. 80/11/03 2pp. 07263 014.
- --8012160035 IE Insp Repts 50-416/60-23 & 50-417/80-14 on 801007-10. No noncompliance noted Major areas inspected storage, housekeeping, followup of inspector identified items & Licensee identified items VALODORN. P K. Region 2. Atlanta, Office of the Director. BRYMITJ. C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/10/30. Spp. 07263:016
- 8012110727 Forwards IE Bulletin 80-21. "Valve Yotes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY.J.P. Region & Atlanta, Office of the Director. 80/11/06. 1p. 07225:219.
- 8012030929 Forwards [E Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/11/07. Ip. 07149:358.
- 8012080200 Forwards IF Info Notice 80-41, "Failure of Swing Check Valve in Decay Meat Pemoval Sys at Davis Besse Unit 1." No response required. O'PELLLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/10. 1p. 07182:264.
- B012040199 Forwards IE Bulletin B0-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. B0/11/14. lp. 07158.111.
- 8012050041 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'RELLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/21.
 19. 07:173:096.
- 8012050655 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluis." No written response required. O'REIL/Y.J.P. Region 2: Atlanta: Office of the Director. B0/11/24. 1p 07174:119.
- 8012170354 Forwards IE Irro Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. D'RELLIY.J.P. Region 2, Atlanta, Office of the Director. 80/11/26. tp. 07269:014.
- 8012110228 Act receipt of 801013 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/80-18. LEHIS.R.C. Region 2- Atlanta, Reactor Operations Nuclear Support Branch. 80/11/28. lp. 07283.168.
- --B012110237 Responds to NRC 806718 ltr re violations noted in 1E Insp Rept 50-416/80-18. Corrective actions electrodes discarded & unamounced tool box insp performed. RCGAUGHY J.P. Mississippi Power & Light Co. B0/10/13. 2pp. 07223:189
- --8012110246 Forwards IE Insp Rept 50-416/80-18 on 800804-29 & notice of violation LEUIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch, 80/09/18. 2sp. 07223:191.
- -8012110250 Notice of violation from imag on B00804-29.
 4 Region 2. Atlanta. Office of the Director. B0/09/18. 1p.
 07223:193

- --8012119257 IE Insp Rept 50-416/80-18 on B00804-29. Noncompliance noted: failure to control welding electrodes. MAGNER.A.S. Region 2. Atlanta. Office of the Director. KFLL00G.P.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/07/18 6pp 07223:194.
- 8012180072 Ack receipt of 801105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/80-20 & 50-417/80-13.

 MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/12/09. 1p. 03791:167.
- --8012180103 Responds to NRC 801009 ltr re violations noted in IE Insp Repts 50-416/80-20 & 50-417/80-13.Corrective actions:audit checklist corrected & training session held to review critoria for welds on componenta of different diameters. HCGAUGHY, J. P. Mississippi Power & Light Co. 80/11/06. Spp. 03791:190.
- --8012180106 Forwards IE Insp Repts 50-416/80-20 & 50-417/80-13 on 800818-22 & notice of violation. KURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/07. 2pp. 03791:195.
- ~-8012183110 Notice of violation from insp on 800818-22.

 * Region 2. Atlanta, Office of the Director. 80/10/08. 2pp. 03791:197.
- --B012180118 IE lnsp Repts 50-416/80-20 & 50-417/80-13 on 800818-22.

 Nuncompliance noted: Inadequate audit preparation & review, failure to establish adequate visual insp measures & matls issuance w/o authorization.

 BLAKE, J. J., ECONOMOS, N., KLEINSORGE, W. P., Region 2, Atlanta, Office of the Director. 80/10/08. 13pp. 03791:199.
- S. Reportable occurrences. LERs & related correspondence
- 8012070548 Part 21 final rept re defective control transformer used at circuit breaker in motor control ctr which supplies power to motor operated valve first reported on 800711. Failed transformer has been replaced. Incident was isolated case, MCGAUGHY, J. P. Mississippi Power & Light Co. 80/11/20, 2pp. 07204:130.
- 8012100541 Interim deficiency rept re reactor recirculation pump hanger component first reported on 801027. Investigation has not identified conditions reportable under 10CFR50. 55m or 10CFR51. Final rept due by 810304. MCGAUSHY, J. P. Mississippi Power & Light Co. 80/11/24. 2pp. 07220:117.
- 8012150011 Part 21 rept re defective ITT Grinnell recirculation pump hanger components, initially reported on 801027. Cause undetermined. Supplier info will be evaluated in final deficiency rept by 810304. MCGAUGHY, J. P. Mississippi Power & Light Co. 80/11/24. Spp. 07241:064.
- 8012090259 Interim deficiency rept advising that OAR F-227 has been upgraded to MCAR & deficiency being tracked by MCAR-100. MCGAUGHY, J. P. Mississippi Power & Light Co. 80/11/25. 1p. 07201:145.
- 8012150283 Part 21 rept re defective &PP-2 carbon filters supplied by Farr Co. Caused by faulty freon injection equipment.
 Corrective actions will be reported by 810510 pending receipt of addl info from supplier.
 MCGAUGHY. J. P. Mississippi Power & Light Co. 80/11/25. App. 07187:001.
- 8012090946 Fifth interim deficiency rapt re defective Topaz Inverter Model GZ. used on equipment supplied by GE. Cause associated w/transient signal failure. Supplier will make mode to product. Final rept to be submitted by 810325. MCOAUGHY. J. P. Mississippi Power & Light Co. 89/12/01. 4pp. 07187:001.
- B012100943 Sixth interim deficiency rept re inadequate circuit separation initially reported on B00323 Corrective actions include: wire redressing, conduit installation & wire relocation. Final rept to be submitted by B10610. MCGAU34V.J.P. Kississippi Power & Light Co. B0/12/01, 3pp. 07187:001.
- 8012309098 Part 21 rept re installation of fire dampers in ventilation sys w/o sufficient drawings or procedures, initially reported on 80103. Stop work notice issued on 801030. Safety evaluation underway.

 MC0AU04Y, J. P. Mississippi Power & Light Co. 80/12/03, 3pp. 07356:207.

- 8012170304 Part 21 rept re loose wire terminations on Potter & Brumfield AMF type relays used in MSIV loakage control syspanels, initially reported on 801104 Constructor evaluation of GE rept expected by 810206.
 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/12/04, 3pp. 07268: 324.
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by gaint on panel surfaces or high resistance connection to ganel surfaces where termination modules are mounted. SHERNOOD, G. G. General Electric Co. 80/12/08. 3pp.
- 8012170429 Final deficiency reptroriginally submitted 800441 re improper installation of high pressure core spray diesel generator panels. Concrete expansion anchors being added to strengthen mounting. Vendor drawings will be revised. MCGAUOHY, J. P. Mississippi Power & Light Co. 80/12/10. 2pp. 07269: 348.
- 8012160281 Final deficiency report to feedwater pipe bend below design min wall thickness, originally reported 800709. Pipe, supplied by TX Pipe Bending, appears to be isolated case. Defective pipe spaol removed & returned to vendor. MCGAU9HY, J. P. Mississippi Power & Light Co. 80/12/11. 2pp. 07248: 249.
- 8012190527 Interim Deficiency Rept 1 re electrical wiring problem in Size 3 starters supplied by Klockner-Mooller. Architect/ engineer is evaluating condition to determine extent of problem & preventative action.
 MCGAUGHY. J. P. Mississippi Power & Light Co. 80/12/11. 2pp. 07274:003.
- S012230427 Deficiency Rept 3 re unqualified insulation repairs in Rockbestos supplied 680 V cable. Qualification tests to be performed to demonstrate acceptability of repairs. Final rept to be provided by 810224.

 MCGAUDHY, J. P. Mississippi Power & Light Co. 80/12/16. 3pp. 07318: 268.
- DOCKET SO-417 GRAND GULF NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- B012290012 Forwards Amends 6 to CPPR-118 & CPPR-119, safety evaluation, negative declaration, EIA & FR notice.
 EIBENHUT, D. G. Division of Licensing. 80/10/29. 4pp. 07330:297.
- --8012270013 Amends & to CPPR-118 & CPPR-119, adding Bouth M3 Electric Power Association as co-owner of facilities. EISENHUT.D.G. Division of Licensing. 80/10/29. 2pp. 07330:241.
- --B012290015 Safety evaluation supporting Amends & to CPPR-118 & CPPR-117.
 TEDESCO.R.L. Assistant Director for Licensing. B0/10/29. Bpp. 07330:263.
- --8012290018 EIA supporting Amends 6 to CPPR-118 & CPPR-117.

 * Division of Licensing. 80/10/29. 2pp. 07330:271.
- --8012270019 Negative declaration re Amend 6 to CPPR-118 & CPPR-119. MIRAGLIA:F. J. Licensing Branch 3 80/10/29. 2pp. 07330:273.
- --8012290022 Natice of issuance of Amonds 6 to CPPR-118 & CPPR-119. MIRAGLIA, F. J. Licensing Branch 3, 80/10/29, 2pp. 07330:275.
- B012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements, Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be not. EISE(#UT.D.O. Division of Licensing. B0/10/31. 7pp.
- BO12220358 Ltr to all CP % Oi, holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. O. Division of Licensing. 80/11/04. 4pp.
- BO11280064 Forwards Amend 44 to application for OLs, consisting of responses to NRC questions, miscellaneous refinements of design info & revised hydrodynamic response spectra as required, Oversite drawings enci.

 MCGAUSHY, J. P. Mississippi Power & Light Co. BO/11/26. 2pp.
- --B011280067 Amend 44 to application for OLs, responding to NRC questions re FBAR & miscallaneous refinements of design info.

 MCGAUGHY, J. P. Mississippi Power & Light Co. 80/11/20. 2pp.

- B012300332 Confirms NRC 810105-09 visit to site re-preliminary evaluation of control room Preliminary human factors assessment to be forwarded & addl info supplied prior to visit.

 MARTORE J. A. Licensing Branch 3. B0/12/04. App. 07359:001.
- B012160277 Describes hydrogen control program, plans for implementation & preliminary tonclusions resulting from evaluations, per NRC 801030 request.

 KCGAU04FV, J. P. Mississippi Power & Light Co. 80/12/07. 7pp. 07263:148.
- C Utility Environmental Report (ER), amends & correspondence
- 8012080718 Requests add1 info in order to complete facility environ review & to satisfy NEPA requirements. Requests util amend environ rept to reflect responses to encl request. IECESCO.R.L. Assistant Director for Licensing. 80/11/20. 3pp. 07196:144.
- 8012020449 Forwards clarified responses to environ rept Questions 350.9-350.12 re-socioeconomic impact & initial response to Questions 451.1, Parts 1 & 2 re-air quality. Enci responses will appear as Amené 5 to final environ rept.

 DALF/L.F. Mississippi Power & Light Co. 80/11/26. 9pp. 07148:247.
- 8012300439 Forwards preliminary responses to NRC Questions 371.07, 340.22 & 340.23 re plant svc water radial wells. Some changes may appear in final version to be included in Amend 5 to environ rept.

 DALE/L F. Mississippi Power & Light Co. 60/12/19. 116pp.
- F. Security, medical, emergency & fire protection plans
- 8012980572 Reteases public versions of state & local emergency plans. FELTON, J. M. Division of Rules and Records. 80/11/26. 10. 07188:056.
- --8012080A05 Forwards public versions of State of MS emergency plan.State of M3.Port Gibson/Clairborne County emergency plan. State of LA preparedness plan for emergency operations Anner J.App 7 & State of LA.Tensas County emergency plan. MCOAUGHY, J.P. Mississippi Power & Light Co. 80/i1/20. 2pp. 07108:037.
- --8012080615 Public version of State of MS, emergency operations plan.Vol 5, "Radiological Emergency Plan" + Mississippi, State of. 80/06/20, 100pp. 07183:131.
- --8012080620 Public version of State of MS.Port Gibson/Claiborne County emergency operation plan.Annel N. "Radiological Emergency Plan."

 < Claiborne County.MS * Affiliation Unknown. 80/11/20. 62pp. 07183:340.
- --8012080639 Public version of Revision 2 to State of LA:preparedness plan for emergency operations. Annex J.App 7, "Peacetime Radiological Response Plan."

 4 Louisiana, Etate of. 80/04/30, 53pp. 07184:040.
- --6012080444 Public version of State of LA.Tensas Parish radiological amergency implementing plan.

 → Affiliation Unknown. 80/04/30. 40pp. 07(84:170.
- 8012080713 Releases public version of util revised emergency plan. FELTON J. II. Division of Rules and Records. 80/11/28. 1p. 07187:105.
- --8012080721 Forwards public version of revised emergency plan. Section 13.3 of FSAR will be revised.

 MCOAUOHY, J. P. Mississippi Power & Light Co. 80/11/20. 1p. 07187: 108
- ---8012080727 Public version of revised emergency plan, to be incorporated in Section 13.3 of FEAR.

 * Mississippi Power & Light Co. 80/11/20. 250pp. 07187:109.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B012160477 Forwards affidavit of svc on distribution of Amend 44 to FBAR per 780627 ltr.
 DALE:L.F. Mississippi Power & Light Co. 80/12/08. 2pp. 07263:057.

Q. Inspection reports. [E Bulletins & correspondence

- 8012160023 Forwards IE Info Notice 80-37, "Containment Cooler Leats & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/10/24.

 Ip. 07261:175.
- 6012170290 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.

 0'REILLY, J.P. Region 2. Atlanta. Office of the Director. 80/10/24.

 1p. 07268:306.
- 8012180936 Forwards IE Info Notice BO-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31.

 1p. 03791:163.
- 8012230042 Forwards IE Circular B0-23. "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. O'REILLY J.P. Region 2. Atlanta. Office of the Director. 80/10/31. ip. 07311:233.
- 801216G027 Forwards IE Insp Repts 50-416/80-23 & 50-417/80-14 on 801007-10. No noncompliance noted.
 MWRPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/03. 2pp. 07263.014.
- --G019160035 IE Insp Repts 50-416/80-23 & 50-417/80-14 on 801007-10. No noncompliance noted Hagor areas inspected:storage, howsekeeping, followup of inspector identified items & licensee identified items. VANDOORN.P.K. Region 2, Atlanta, Office of the Director. BRYANT.J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. G0/10/30. Spp. 07263:016.
- 8012110727 Forwards IE Bulletin 80-21, "Valve Yoles Supplied by Malcolm Foundry Co.Inc." Written response required. D'REILLY, J.P. Region 2: Atlanta, Office of the Director. BO/11/06. ip. 07225:219.
- 8012030329 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response requires, O'REILLY,J.P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p. 07149:358.
- 8012080200 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit I." No response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/10. 19. 07162:264.
- 8012040199 Forwards IE Bulletin 80-23. "Failures of Solemoid Valves Mg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY. J.P. Region 2. Atlanta, Office of the Director. 80/11/14. tp. 07158:111.
- 8012050041 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/21. Ip. 07173:096.
- 8012050655 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/24. 1p. 07174:119.
- 8012170354 Forwards IE info Natice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
 U'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/26.
 1p. 07267:014.
- B0121B0092 Ack receipt of B01106 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/80-20 & 50-417/80-13.

 MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. B0/12/04. ip. 03791:189.
- -B0121B0103 Responds to NRC 801009 ltr re violations noted in IE Insp Repts 50-416/80-20 & 50-417/80-13 Corrective actions: audit checklist corrected & training session held to review criteria for welds on companents of different diameters. KG9AUOHY.J.P. Hississippi Power & Light Co. 80/11/06, Spp. 03791:170.

- --8012180106 Forwards IE Insp Repts 50-416/80-20 & 50-417/80-13 on B00818-22 & notice of violation. KURPHY.C.E. Region 2. Atlanta: Reactor Construction & Engineering Support Branch. 80/10/09. 2pp. 03771:175.
- ~~B012180110 Notice of violation from insp on 800B18-22.

 4 Region 2. Atlanta, Office of the Director. B0/10/08, 2pp.
 03791:197.
- --8012180118 IE Ensp Repts 50-416/80-20 & 50-417/80-13 on 800818-22. Noncompliance noted: inadequate audit preparation & review, failure to establish adequate visual insp measures & matls issuance w/o authorization.

 BL6XE.J.J., ECONOMOS.N., KLEINSORGE.W.P. Region 2, Atlanta, Office of the Birector. 80/10/08. 13pp. 03791:197.
- S. Reportable occurrences, LERs & related correspondence
- 8012070568 Part 21 final rept re defective control transformer used at circuit breaker in motor control ctr which supplies power to motor operated valve, first reported on 800711. Failed transformer has been replaced. Incident was isolated case. KCGAUGHY, J. P. Mississippi Power & Light Co. 80/11/20. 2pp. 07204:130.
- BO12150011 Part 21 rept re defective ITT Grinnell recirculation pump hanger conponents.initially reported on B01027. Cause undetermined. Supplier info will be evaluated in final deficiency rept by B10304. MCGAU3HY, J. P. Mississippi Power & Light Co. B0/11/24. Spp. 07241:064.
- 8012090259 Interim deficiency rept advising that CAR F-227 has been upgraded to MCAR & deficiency being tracked by MCAR-100. MCGAUGHY.J.P. Mississippi Power & Light Co. 80/11/25. 1p. 07201:145.
- 8012150233 Part 21 rept re defective NPP-2 carbon filters supplied by Farr Co. Caused by faulty freen injection equipment. Corrective actions will be reported by BiO610, pending receipt of addl info from supplier. HCGAUGHY, J. P. Mississippi Power & Light Co. 89/11/25. 4pp. 07187:001.
- 8012090246 Fifth interim deficiency rept to defective Topaz Invertor Model GZ, used on equipment supplied by GE. Cause associated w/transient signal feilure. Supplier will make mods to product. Final rept to be submitted by 810325. HCGAUSHY, J. P. Mississippi Power & Light Co. 80/12/01. 4pp. 07187:001.
- 8012100543 Sixth interim deficiency rept re inadequate circuit separation initially reported on 800323. Corrective actions include: wire redressing, conduit installation & wire relocation. Final rept to be submitted by 810610. MCGAUCHY, J. P. Mississippi Pawer & Light Co. 80/12/01. 3pp. 07187:001.
- 8012300098 Part 21 rept re installation of fire dampers in ventilation sys w/o sufficient drawings or procedures, initially reported on 801103 Stop work notice issued on 801030, Safety evaluation underway. HCGAUGHY.J.P. Kississippi Power & Light Co. 80/12/03. 3pp. 07356:207.
- B012170304 Part 21 rept re loose wire terminations on Potter & Brucefield AMF type relays used in MSIV leakage control syspanels: initially reported on E01104. Constructor evaluation of EE rapt expected by 810206.
 MCGAWSHY.J.P. Mississippi Power & Light Co. 80/12/04. 3pp.
- 8012240039 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERWOOD, O. O. General Electric Co. HO/12/08. 3pp.
- B012170429 Final deficiency rept.originally submitted B00441, re improper installation of high pressure core spray diesel generator panels. Concrete expansion anchors being added to strengthen mounting. Vendor drawings will be revised. MCOAUSHY, J. P. Mississippi Power & Light Co. B0/12/10. 2pp.

•

B012160281 Final deficiency report re feedwater pips bend below design ain wall thickness; originally reported 800709. Pipe, supplied by TX Pipe Bending, appears to be isolated case, Defective pipe spool removed & returned to vendor.

MCGAUDHY, J. P. Mississippi Power & Light Co. 80/12/11. 2pp. 07248; 249.

- 8012190527 Interim Deficiency Rept 1 re electrical wiring problem in Size 3 starters supplied by Klockner-Moeller. Architect/ engineer is evaluating condition to determine extent of problem & preventative action.

 MCGAUGHY. J. P. Mississippi Power & Light Co. 80/12/11. 2pp. 07274:003.
- 8012230427 Deficiency Rept 3 re unqualified insulation repairs in Rockbestos supplied 680 V cable. Qualification tests to be performed to demonstrate acceptability of repairs. Final rept to be provided by B10224.
 MCGAUJ

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

- A. Application/construction stage documents & correspondence
- B012140050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISEXHUT.D.O. Division of Licensing. 80/10/31. 7pp.
- B0122204B5 Responds to 800911 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions.Forwards results of IE survey.

 DENTON, H. R. Office of Nuclear Reactor Regulation. Director. B0/12/04. 2pp.
- --8012220506 Forwards tabulation & surmary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BARGART.R.L. Effluent Treatment Systems Branch. 80/11/06, 8pp.
- F. Security, medical, emergency & fire protection plans
- B012040186 Public version of "Independent Assessment of Evacuation Times for Milistone Nuclear Power Plant," Vol B. prepared for FEMA. CDBBY.J.C., SHEPPARD.H.V., LAMAGNA,F. Hilbur Smith & Associates, B0/06/30. 72pp. 07161
- B012040065 Forwards public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary. FELTOW, J. M. Division of Rules and Records. 80/12/03. 1p.
- --B012040088 Public version of "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," executive summary, prepared for FEMA.

 4 Wilbur Smith & Associatos. B0/06/30. 17pp.
- --8012040155 Public version of program rept, "Evacuation Time Assessment of Nine Nuclear Power Plants Emergency Planning Zones," Vol 1. prepared for FEMA.
 COSBY, J. C. Wilbur Soith & Associates. 80/06/30. 43pp.
- G. Inspection reports, IE Bulletins & correspondence
- BO12190306 Forwards IE Insp Rept 50-423/50-07 on B01007-09 No noncampliance noted.
 CARLSON, R. T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. B0/10/24. 2pp. 07287:069.
- --8012170511 IE Insp Rept 50-423/80-0/ on 801007-09. No noncompliance noted. Major areas inspected: concrete placement activities for intake structure & activities for installation of rock anchors & shar wall mods in Auxiliary bidg. HATTIA.J.C. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. FEIL.R., VARELA.A. Region 1, Philadelphia, Office of the Director. 80/10/23. 7pp. 07287:071.
- 8012170402 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/30. ip. 07269:111.
- 8012120113 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230:221.

- 8012030/87 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 80/11/07. 1p. 07(50:207.
- 80120B0474 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Basse Unit 1." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/10. 1p. 07102:330.
- 8012040392 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/14. 1p. 07157:353.
- 8012270516 Advises that written response is required to IE Bulletin B0-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.
 GRIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/19. 1p. 07308:358.
- 8012040599 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. GRIER, B.H. Region i. Philadelphia. Office of the Director. 80/11/21. 2pp. 07165:201.
- BO12050573 Forwards Info Notice BO-42, "Effect of Radiation on Hydraulic Shubber Fluid," No written response required. GRIER, B. H. Region I. Philadelphia. Office of the Director. BO/11/24. 1p. 07174:062.
- DOCKET 50-424 ALVIN M. VOOTLE NUCLEAR PLANT, URIT 1
 A. Application/construction stage documents & correspondence
- GO12160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 inplementation dates will be ret. GIBERMUT.D.C. Division of Licensing. GO/10/31. 7pp.
- 8012020460 Forwards response to 801001 itr re environ qualification of safety-related equipment.
 EHMENSPERGER.W. Georgia Power Co. 80/11/24, 1p. 07148:238.
- --8012020462 Responds to 801001 ltr re environ qualification of safetyrelated equipment Qualification test schedules encl ANDERSON, T.M. Westinghouse Electric Corp. 80/10/31. Epp. 07148:239.
- 8012180119 Responds to 790821 Suppl 6 to CP application describing and to plant design. Deletion of containment encl bldg & safety grade exhaust & recirculation sys must be considered under amené to CP. Decision may be delayed until 810131.

 EISERHUT, D. G. Division of Licenstry. 80/12/01. 2pp. 07272:286.
- 8012230197 Application for amend to CPPR-108 & CPPR-109 to reflect mod in plent design Mod would substitute more restrictive primary leakage containment for encl bidg. Class I & III fees & cost/benefit assessment encl. EMMENSPERGER, W. Georgia Power Co 80/12/19. Spp. 07317:027.
- B. Utility Preliminary Safety Analysis Report, amends
- 8012310276 Forwards Suppl 8 to PSAR, submitted as suppl to application for CP & OL Suppl consists of revised analysis of radiological consequences of postulated LOCA.
 EHRENSPERGER, W. Georgia Power Co. 80/12/30. 1p. 07361:001.
- ---8012310298 Suppl 8 to PSAR.
 EHRENSFERGER. H. Georgia Power Co. 89/12/30. 45pp. 07361:002.
- G. Inspection reports, IE Bullatins & correspondence
- 8012070520 Forwards IE Insp Repts 50-424/80-14 & 50-425/80-14 on 800915-18 No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/23. 2pp. 07206:209.

- --8012090524 IE Insp Repts 50-424/80-14 & 50-425/80-14 on 800915-18.No noncompliance noted Major areas inspected structural conceste/backfill & previously identified items.

 HARRIS, J.R. Region 2. Atlanta, Office of the Director.

 CONCONTE Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 20/10/20. 2pp. 07206/211.
- 3012150199 Forwards IE Irfo Notice 60-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required. G-REILL(Y.J.P. Region 2. Atlanta, Office of the Director. 80/10/24, 1p. 07240.283.
- 5012170298 Forwards Suppl 3 to 16 Bulletin 79-018, "Environ Gualification of Class IE Equipment." No written response required.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/24.

 1p. 07268:311.
- 8012180R84 Forwards IE Insp Repts 50-424/80-15 & 50-425/80-15 on 80929-1001.40 noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/28 2pp. 03794:035.
- --B019183207 IE Insp Repts 50-424/E0-15 & 50-425/80-15 on 800929-1001. No noncompliance noted Major areas inspected; equipment storage, piping contractor facilities, noncomforming repts & surface water control.

 kUNIT, IS D. VANDOORN, P. K. Region 2, Atlanta, Office of the Director. SPYANTIJ C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/28. 3pp. 03794:037.
- 5012180012 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding" No unitten response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. BO/10/30. 1p. 03790-126.
- 3012170016 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31.

 1p. 07264:130.
- 8012830067 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No unition response required.
 O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/10/31.
 1p. 07313:234
- 2012110/32 Forwards IE Bulletin 80-21. "Valve Yotes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY.U.P. Region 2. Atlanta. Office of the Director. 80/11/06. ip. 07225.215.
- BOI2030357 Forwards IE Info Notice 80-40. "Ercessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'Reluiy.J.P. Region 2. Atlanta, Office of the Director. BO/11/07. 1p. 07150:109.
- 2012080303 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1," No response required.
 O'REILLY,U.P. Region 2. Atlanta, Office of the Director, GO/11/10.
 1p. 07182:288.
- S012040187 Forwards IE Sulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'RELLLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/14, 1p. 07158:100.
- 2012050043 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Lestage Inside Containment." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/21. ip. 07173:101.
- 8012080929 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/24, 1p. 07182:169.
- 6012170517 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlat Flange." No written response required.

 O'REILLY J.P. Region 2. Atlanta, Office of the Director. 80/11/26.
 10. 07268:109

- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012020460 Forwards response to 801001 ltr re environ qualification of safety-related equipment.

 EHRENSPERGER.W. Georgia Power Co. 80/11/24, ip. 07148:238.
- --8012020462 Responds to 801001 ltr re environ qualification of safetyrelated equipment. Qualification test schedules encl. ANDERSON.T.M. Westinghouse Electric Corp. 80/10/31. 8pp. 07148-239
- 8012180119 Responds to 770821 Suppl 6 to CP application describing mod to plant design Deletion of containment encl bidg & safety grade exhaust & recirculation sys must be considered under amend to CP.Decision may be delayed until 810131.
 EISENHUT.D.G. Division of Licensing. 80/12/01. 2pp. 07272:286.
- 8012230197 Application for amend to CPPR-108 & CPPR-109 to reflect modin plant design. Mod would substitute more restrictive primary laakage containment for encl bldg. Class I & III fees & cost/benefit assessment encl.

 EHRERSPERGER, N. Georgia Power Co. 80/12/19. 5pp. 07317: 027.
- S. Utility Preliminary Safety Analysis Report, amends
- 8012310296 Forwards Suppl B to PSAR, submitted as suppl to application for CP & OL. Suppl consists of revised analysis of radiological consequences of postulated LOCA.

 EHRENSPERGER, W. Georgia Power Co. 80/12/30. 1p. 07361:001.
- --8012310298 Suppl 8 to PSAR. EHRENSPERGER, W. Georgia Power Co. 80/12/30. 45pp. 07361:002.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012070520 Forwards IE Insp Repts 30-424/80-14 & 50-425/80-14 pn 800915-18 No noncompliance noted. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 60/10/23. 2pp. 07206:209.
- --8012090524 IE Insp Repts 50-424/80-14 & 50-425/80-14 on 800915-18. No nuncompliance noted Major areas inspected: structural concrete, backfill & previously identified items. HARRIS-J.R. Region 2. Atlanta, Office of the Director. COMLON.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/20. 3pp. 07204:211.
- 8012170286 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24.
- 8012170278 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
 O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24, 1p. 07268:311.
- 8012180284 Forwards 1E Insp Repts 50-424/80-15 & 90-425/80-15 on 800929-1001. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 60/10/28. 2pp. 03794:035.
- --8012180289 IE Insp Repts 50-424/80-15 & 50-425/80-15 on 800929-1001, No noncompliance noted. Hajor areas inspected: equipment storage, piping contractor facilities, nonconforming repts & surface water control.
 HUNT, M. D., VANDOORN, P. X. Region 2. Atlanta, Office of the Director, BRYANT, J. C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/28. 3pp. 03794:037.
- 8012180012 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required, 6'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/30. 1p. 03790:126.

- B012170016 Forwards IE Info Notice B0-39, "Malfunction of Solenoid Valves Kfg by Valcor Engineering Corp." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/10/31.
- 8012230047 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators," No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/3i.
- B012110732 Forwards (E Bulletin B0-21, "Valve Yokes Supplied by Malcolm Faundry Co.Inc.".Mritten response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/11/06.
- 8012030837 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valvo Operation to Cause Reactor Depressurization." No written response required. Q'REILLY, J. P. Rogion 2. Atlanta, Office of the Director. 80/11/03
- 8012080303 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10.
- 80120140189 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions. O'REILLY, J. P. Region 2. Atlanta, Orfice of the Director. 80/11/14.
- 8012050043 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.
 D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/21. ip. 07173:101.
- 8012080029 Forwards 1E Info Notice 80-42. "Effect of Radiation on Mydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24.
- B012170517 Forwards IE info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.
- DOCKET 50-436 ARGENTINA RESEARCH REACTOR A Application/construction stage documents & correspondence
- B012030701 Responds to B01023 itr re C-E applications to export components for Atucha II nuclear power plant in Argentina. Executive Branch review underway when applications were withdrawn. Chronology of NRC activity re applications encl. DIRCKS.M.J. Office of the Executive Director for Operations. B0/11/12. 2pp.
- --8012030708 Responds to 800527 ltr re C-E applications to export components to Atucha II power plant in Argentina. NRC following nuclear-related developments in Argentina & will act on applications upon receipt of Executive Branch views. SHEA.J.R. Office of International Programs. Director. 80/06/19.
- --8012030714 Discusses efforts to gain US govt approval of applications to export components to Argentina Contracts lost due to govt delays.

 BCHM17Z,H.K. Combustion Engineering, Inc. 80/07/16. 2pp.
- -8012030719 Forwards C-E 800527 ltr re applications to export components to Atucha II nuclear power plant in Argentina. Requests rept on stated problems. WARNER, J. W. Senate. 80/10/23. 5pp.
- DOCKET STN-50-437 FLOATING NUCLEAR PLANT H. General correspondence
- 8012040256 Forwards info in response to 801029 ltr requesting licensing categories & info re floating nuclear plants. PURPLE, R. A. Division of Licensing. 80/11/17. 4pp. 07170:059.

- -8012040258 Requests info re facilities w/active GPs pending license definitions & requirements for floating nuclear plants.

 DREY.L.A. Affiliation Uninown. 80/10/29. 1p. 07170:068.
- $\mathbf{0}.$ Inspection reports. IE Bulletins b correspondence
- 8012160069 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24.

 ip. 07262:340.
- 8012170249 Forwards Suppl 3 to 1E Bulletin 79-018, "Environ Qualification of Class 1E Equipment." No written response required. O'REILLY, J.P. Region 2: Atlanta, Office of the Director. 1p. 07268:216 Region 2. Atlanta, Office of the Director. 80/10/24.
- 8012180047 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 80/10/30. 1p. 03790:094
- 8012180008 Forwards IE Info Notice 80-39, "Malfunction of Bolenoid Valves Hifg by Valcor Engineering Corp." No written response is required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10, 1p. 03790:096. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012230079 Forwards IE Circular 80-23. "Potential Defects in Deloit Power Sys Emergency Cenerators." No written response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/10/31. 1p. 07313:251
- 8012110721 Forwards IE Bulletin 80-21, "Valve Yokes Bupplied by Malcoli Foundry Co.inc." Unitten response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/06. 1p. 07225:228.
- B012030832 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurfiation." No written response required. O'REILLY.J.P. Region 2: Atlanta. Office of the Director. B0/11/07. ip. 07150:081.
- 8012080218 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1," No response required. G'RELLLY, J.P. Ragion 2: Atlanta, Office of the Director. 80/11/10. LLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/10. 07182:273.
- 8012010195 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Hig by Valcor Engineering Corp." Requires estimate of management associated wicorrective actions.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 60/11/14. 07159-106
- 8012050039 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'REILLY,J.P. Region 2: Atlanta, Office of the Director, 80/11/21,"
 1p. 07173:091.
- 8012080001 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REIULY, J.P. Region 2. Atlanta, Office of the Director. 80/11/24, jp. 07182:113.
- 8012170347 Forwards IE Info Notice 80-29, Suppl 1, "Broten Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/26, 1p. 07268:361.
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1 A. Application/construction stage documents & correspondence
- 80:2140050 Ltr to operating plant licensess DL applicants & CP holders Forwards NUREC-0737 re TMI action plan requirements. Requests operating reactor licenses confirmation in 45 days that Encl I implementation dates will be ret. EISENHUT, D. C. Division of Licensing. 80/10/31, 7pp.
- 8012010470 Forwards request for add1 info re auxiliary sys in order to complete review of OL application.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/20. 1ipp. 06915:001.

- --8012010476 Ltr to all pending OL applicants of NSSS designed by B&H requesting info re auxiliary feedwater sys.
 ROSS,D.F. Division of Systems Integration. 80/04/24. 52pp.
- 8012010510 Forwards request for addl info re auxiliary sys.as result of OL application review Notification of availability of info requested is needed.

 IEDESCO.R.L. Assistant Director for Licensing. BO/11/20. 11pp. 07078:069.
- 8012020039 Forwards "Interim Confirmatory Piping Analysis" w/App A-E for decay heat removal sys & spent fuel cooling sys.per NRC 791228 request. Analysis will be updated when final as-built drawings are submitted.

 BATES.J.O. Roctwell International Corp., Energy Systems Div. B0/11/24. 2pp. 07123:159.
- --B012020073 "Interim Confirmatory Piping Analysis." W/App A-E.

 4 Energy Technology Engineering Center. 80/19/22. 2500pp.
 07123:161.
- 8012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept. TVA-TR75-1 re const & preliminary testing. MILLS.L.M. Tennessee Valley Authority. 80/12/01. 3pp. 07201:174.
- 8012090347 Informs that util will address NRC concerns re auxiliary faedwater sys when responding to FSAR Question 410.28.
 KILLS.L.H. Tennessee Valley Authority. 80/12/02. 1p. 07199:351.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment.Info will be available by 810201.
 MILLS.L. N. Tennessee Valley Authority. 80/12/09. ip.
- 8012170316 Forwards planned changes to Chapter 17 of FBAR for Sequoyah, Natts Bar & Bellefonts & TVA-TR75-1A. Changes supersede 801201 ltr. Changes will be included in application for OL for Hartsviller/Ripps Bend & Yellow Creek plants. MILLS.L.S. Tennessee Valley Authority. 80/12/09. 5pp.
- F. Security, medical, emergency & fire protection plans
- 8012080835 Notification of 801121 meeting w/util in Bethesda, MD to discuss util position on central emergency response ctr & plans for emergency agt.

 STAHLE.C. Licensing Branch 2. 80/11/19, 6pp.
- G. Inspection reports, IE Bulletins & correspondence
- 8012080372 Forwards IE Insp Repts 50-438/80-23 & 50-439/80-23, on 800829 -0926. No noncompliance noted. MWRPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering & Support Branch. 80/10/22. 2pp. 07186:336.
- --8012080082 IE Insp Repts 50-438/80-23 & 50-439/80-23, on 800829-0926. No noncompliance noted Major areas inspected: hardware in reactor bldgs & auxiliary bldg. WILCOX. J.D., CANTRELL, F.S. Region 2. Atlanta. Office of the Director. 80/10/22. 3pp. 07186:358.
- 80121502:11 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
 0'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/10/24.
 1p. 07240:279.
- 8012180274 Forwards IE Myt Meeting Repts 50-438/80-24, 50-439/80-21 & 50-390/80-31 & 50-391/80-24 on 800925. No reply required. MARPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/27. 2pp. 03794:040.
- --8012180337 IE Mgt Weeting Repts 50-438/80-24,50-439/80-24,50-390/80-31 & 50-391/80-24 on 800925. Major areas discussed: issues identified in Insp Repts 50-438/80-12,50-439/80-12,50-370/80-19 & 50-371/80-13. COLEY. J. L. Region 2, Atlanta, Office of the Director. MURPHY, C. E. Region 2, Atlanta, Paractor Construction & Engineering Support Branch. 80/10/24. 2pp 03794:042.
- 8012180035 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2- Atlanta, Office of the Director. 80/10/30, ip.
- 8012170004 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves M/g by Valcor Engineering Corp." No specific action or response required.

 O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/10/31, 1p. 07264:132.

- 8012230730 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. B0/10/31.

 Ip. 0/311:214.
- 8012110056 Requests assessment & corrective actions taken re-control room ceiling constructed w/apparently flammable tiles within 20 days.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/04. 3pp. 07223;139.
- 8012170471 Forwards IE Insp Repts 50-438/80-20 & 50-439/80-22 on B00729-1002 No noncompliance noted. MURPHY, C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/05. 2pp. 07264:218.
- --8012170473 IE Insp Repts 50-438/80-20 & 50-439/80-22 on 800929-1002. No noncompliance noted. Major areas inspected; welds on vendor supplied pipe spools & RCPB piping.
 GIRARD, E.H. Region 2. Atlanta. Office of the Director. HERDT, A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch, 80/11/03. 7pp. 07264:220.
- 8012180163 Forwards IE Insp Repts 50-438/80-21 & 50-439/80-20 on 860930-1003. No noncompliance noted.

 8TORR, J. P. Region 2: Atlanta, Fuel Facility & Materials Safety Branch. 80/11/05. 2pp. 03791:327.
- ---8012180167 IE Insp Repts 50-438/80-21 & 50-439/80-20 on 800930-1003, No noncompliance noted Majar areas inspected mgt controls, evosion & runoff controls, const effect monitoring & waste ngt.

 CHENINGHAM.A.L. Region 2, Atlanta, Office of the Director.

 JENNING, Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/11/04. 4pp. 03/91:329.
- 8012110507 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Halcolm Foundry Co. Inc." Written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/11/06. 1p. 07225:180.
- 8012030937 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. O'REILLY,J.P. Region 2. Atlanta. Office of the Director. 60/11/07. ip. 07150:085.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/10.
- 8012040143 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'RELLLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/14. 1p.
- 80:2080616 Forwards updated response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies." Util will contact major valve suppliers to determine if add1 deficient actuators were supplied.

 MILLS.L.K. Tennessee Valley Authority. 80/11/17. 3pp.
- 8012050023 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.
 O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/11/21.
 Ip.
- 8012310058 Forwards IE Insp Repts 50-438/80-25 & 50-439/80-25 on 800927-1031. No noncompliance noted. MURPHY.C.E. Region 2: Atlanta: Reactor Construction & Engineering Support Branch. 80/11/21. 2pp. 07369:072.
- --B012310063 IE Insp Repts 50-438/80-25 & S0-439/80-25 on B00927-1031.
 No noncompliance noted Major areas inspected:const surveillance training & audits.
 WHLCOX.J.D. Region 2. Atlanta. Office of the Director.
 CANTRELL.F.S Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/20. 6pp. 07369:074.
- 8012080604 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24. 1p.

- 8012090135 Ack receipt of 801105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-19 & 50-439/80-19. MRPHY.C.E. Region 2. Atlanta Reactor Construction & Engineering Support Branch. 80/11/25. ip. 07199:205.
- --8012090142 Responds to NRC 801014 ltr re violations noted in IE Insp Repts 50-438/80-19 & 50-439/80-19, Corrective actions: drawing changed to reflect as-built condition of truncions & personnel received retraining. HLLS.L.M. Tennessee Valley Authority. 80/11/05. 2pp. 07199:207.
- --8012070146 Forwards IE Insp Repts 50-438/80-19 & 50-437/80-19 on B00727-0829 & notice of violation. HXRPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. B0/10/14. 2pp. 07199:209.
- --8012090152 Notice of violation from insp on 800727-0829, * Regi n 2, Atlanta, Office of the Director. 80/10/07. ip. 07199:2.1.
- --8012070156 IE Insp Repts 50-438/80-19 & 50-439/80-19 on 800727-0829.

 Noncompliance noted: invalid QC signoffs for upper steam
 generator restraint installation.

 NILCOX.J.D. Region 2. Atlanta. Office of the Director.

 CARTRELL.F.S. Region 2. Atlanta. Reactor Construction &
 Engineering Support Branch. 80/10/07. 5pp. 07179:212.
- 8012170359 Forwards IE Info Notice 80-29. Suppl i, "Broten Stude on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/26. ip. 07269:022.
- 8012190716 Forwards IE Insp Rept 50-439/80-26 on B01113.No noncompliance noted. KENWA.W.B. Region 2, Atlanta, Safeguards Branch. B0/12/09, 2pp. 07288:038.
- --8012190719 IE Insp Rept 50-428/80-26 on 801113.No noncompliance noted. Major areas inspected: security practices at fuel storage areas. Details withheld (ref 100FR2.790).
 TILLMAN.A., HALL.V., HILL.A. Region 2, Atlanta. Office of the Director. 80/12/03. 1p. 07289:040.
- S. Reportable occurrences, LERs & related correspondence
- 8012150261 Part 21 rept re defective Transamerica Delaval diesel generators. Caused by shallow dowel counterbone in link rod assembly. Insp. procedures implemented & repairs scheduled.
 MILLS: L. M. Tennessee Valley Authority. 80/11/25. 3pp. 07237:357.
- 8012100486 Fourth interim deficiency rept re ITT controls of American Marming & Ventilating dampers, originally reported 800417.
 American Harming & Ventilating yet to receive & approve rept by ITT. Next util rept will be submitted 810508.
 MILLE, L. M. Tennessee Valley Authority. 80/11/26. 1p. 07220:040.
- 8012150266 Part 21 rept re ITT controls of American Warming & Ventilating dampers. Rept will be sent pending receipt & approval of ITT evaluation.
 MILLS.L.H. Tannessee Valley Authority. 80/11/26. 2pp. 07237:360.
- 80:2100447 Fourth interim deficiency rept re lack of internal purge on welds in chemical addition & boron recovery sys.initially reported on B00417. Util will identify stainless steel welds requiring purge. Next rept scheduled on B10624.
 MILLS,L.M. Tennessee Valley Authority. 80/12/01. 2pp. 07218:292.
- 8012160/03 Part 21 rept re excessive vibration in essential raw cooling water pump/motor while running initially reported on 800817. Util avaluating two solutions: add1 motor weight or addition of braces.
 MILLS.L.M. Tennessee Vailey Authority. 80/12/02, 3pp. 07261:315.
- 8012100447 First interim deficiency rept re fillet weld specification. American Insp of Steel Const stds & affected Welds are being evaluated. Nest rept will be submitted by 810119.

 KILLS.L.M. Tennessee Valley Authority. 80/12/03. 2pp. 07217:034.
- 8012100448 Forwards final deficiency rept.originally reported 801107, re undersized fillet wolds on high pressure fire protection sys supports. Util revised & reissued all questionable drawings detailing correct weld size.

 MILLS.L.M. Tennessee Valley Authority. 80/12/03. 2pp. 07217:032.

- 8012160675 Part 21 rept re B&W nonconservative analysis of neutron flus, initially reported on B01105. Util is awaiting vendor proposed resolution. Next rept will be submitted by 810331.

 MIULS.L.M. Tennessee Valley Authority. 80/12/03. 3pp. 07254:332.
- 8012170406 Second interim deficiency rept re 600-V & 8 & 15-kV power cables, types CPJ & CPSJ, installed in cable trays, not qualified for IEEE 383-1977 flame test. Next rept to be submitted by 810323.

 MILLS, L. H. Tennessee Valley Authority. 80/12/10. 2pg. 07270:003.
- 8012309496 Second interim deficiency rept re soctet weld misalignment on essential air sys welds. Inspectors were reinstructed re requirements of G-29M & applicable field const procedures. Std operating procedure SMP-HEV-SDP-711 revised. MILLS.L.M. Tennessee Valley Authority. 80/12/16. 2pp. 07359:212.
- 8012310382 First interia deficiency rept re seismic qualification of BAW equipment in frae standing open local instrument panels, initially reported 801124. Util is avaiuating sub; deficiency & is working w/BAW toward resolution MILLS.L.M. Tennessee Valley Authority. 80/12/23. 2pp. 07369:086.
- 8012310311 First interim deficiency mept me centified math test mepts on anchombeads. INRYCO, Inc has informed util that centified math test mepts have been obtained from Tech Steel & Alloy Garp. Util will review adequacy upon receipt.

 HILLS, L. 15. Tennessee Valley Authority. 60/12/24. 2pp. 07361:289.
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012160350 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be ret. EISENHUT. B. G. Division of Licensing. 80/10/31. 7pp.
- 8012010470 Forwards request for add1 info re auxiliary sys in order to complete review of OL application TEOESCO.R.L. Assistant Director for Licensing. 80/11/20. lipp. 05/15:001.
- 8012010510 Forwards request for additinfo re auxiliary sys.as result of DL application review. Notification of availability of inforequested is needed.

 TEDESCO.R.L. Assistant Director for Licensing. 80/11/20. 11pp.
- 8012070370 Forwards planned changes to FSAR Chapter 17 & TVA rept. TVA-TR75-1 re const & preliminary testing. MILLS-L.M. Tennessee Valley Authority. 80/12/01. 3pp.
- 80:2090347 Informs that util will address MRC concerns re auxiliary feedwater sys when responding to FBAR Question 410.28. MILLS,L.M. Tennessee Valley Authority. 80/12/02. 1p. 07199:351.
- 8012160327 Responds to NRC 801031 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201.
 MILLS.L.M. Tennessee Valley Authority. 80/12/09. 1p.
- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah. Watts Bar & Bellefonte & TVA-TR75-1A.Changes supersede B01201 ltr.Changes will be included in application for OL for Martsville.Phipps Bend & Yellou Creek plants. MIULS.L.M. Tennessee Valley Authority. 80/12/09, 5pp.
- F. Security, medical, emergency & fire protection plans
- 80:2080835 Motification of 80:121 meeting w/util in Hethesda.MD to discuss util position on central energency response ctr & plans for emergency mgt.

 8TAMLE.C. Licensing Branch 2. 80/11/19. dpp.
- Inspection reports. IE Bulletins & correspondence
- 8012080972 Forwards IE Insp Repts 50-438/80-23 & 50-439/80-23, on 800829 -0926 No honcompliance noted.

 MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/22. 2pg. 07186:356.
- --8012080062 IE Insp Repts 50-438/80-23 & 50-439/80-23.on 800829-0926.No noncompliance noted Kajor areas inspected: hardware in reactor bidgs & auxiliary bidg.
 #ILCOK.J.D. CANTRELL.F.S. Region 2. Atlanta, Office of the Director. 80/10/22 3pp. 07186:358.

- E012150201 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/10/24.

 1p.
- 2012180274 Forwards IE Mgt Meeting Repts 50-438/80-24, 50-439/80-24, 50-390/60-31 & 50-391/80-24 on 800725 No reply required. MURPHY:0 E Region 2- Atlanta: Reactor Construction & Engineering Support Branch: 80/10/27 2pp 03794.040.
- --B0121B3337 IE Myt Meeting Repts 50-43B/80-24,50-439/80-24,50-390/80-31 %,52-391/80-24 on 800725. Major areas discussed: issues identified in Insp Repts 50-43B/80-12, 50-439/80-12, 50-390/80-19 % 10-391/80-13.

 CDLET. J. L. Region 2. Atlanta, Office of the Director. MURPHY, C. E. Region 2. Atlanta, Construction & Engineering Support Branch. E0/10/24. Spp. 03794:042.
- 60121801935 Forwards IE Info Notice 80-33. "Cracking in Charging Pump Casing Cladding." No written response required.

 O'REILLYJ.P Region 2. Atlanta. Office of the Director. 80/10/30. ip.
- B012170304 Forwards IE Info Notice 80-37. "Malfunction of Solenoid Valves HTg by Valcor Engineering Corp." No specific action or response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 60/10/31.
- 8012230030 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No critten response required. O'REILIV.J.F. Region 2. Atlanta, Office of the Director. 80/10/31, 1p. 07311:214.
- 8012110066 Requests assessment & corrective actions taken re-control room celling constructed u/apparently flammable tiles within 20 days.
 TEDESCO.R.t. Assistant Director for Licensing. 80/11/04. 3pp. 07203-199
- 6012170471 Forwards IE Insp Repts 50-438/80-20 & 50-439/80-22 on 800929-1002 No noncompliance noted. MURPHYS.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 60/11/05 2pp. 07264:218.
- --B012170473 lE Insp Repts 50-439/80-20 & 50-439/80-22 on B00929-1002.No noncompliance noted Major areas inspected welds on vendor supplied pipe spools & RCPB piping.
 OIRARD.E.H. Region 2. Atlanta. Diffice of the Director. HERDT.A.R. Region 2. Atlanta. Percent & Engineering Support Branch. 50/11/03 7pp. 07264:229.
- 8012180163 Forwards IE Insp Repts 50-438/80-21 & 50-439/80-20 on 803930-1033. No noncompliance nated.

 STOMR.J. P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/11/05 2pp. 03771:327.
- --8012160147 IE Insp Repts 50-438/80-21 & 50-439/80-20 on 800930-1003. No noncompliance noted Major areas inspected; mpt controls, enosion & runoff controls, const effect manitoring & wastengt.

 GUNNINGHAM.A.L. Region 2. Atlanta, Office of the Director.

 JENNING.G. Region 2. Atlanta, Fuel Facility & Materials Safety
 Branch. 20/11/04 App. 03791:329.
- 8012110807 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/06.
- 8012030837 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuritation." No written response required. O'REICLY.J.P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p. 07150:085
- 8012030276 Forwards IE Info Notice 80~41. "Failure of Swing Chack Valve in Decay Reat Removal Sys at Davis Besse Unit 1." No response required.
 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/10.
- 8012040143 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mig by Valcor Engineering Corp." Requires estimate of Manpower associated w/corrective actions. O'REIU.Y. J.P. Region 2. Atlanta, Office of the Director. 80/11/14.

- 8012080516 Forwards updated response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies." Util will contact major valve suppliers to determine if addl deficient actuators were supplied.
 MILLS-L.M. Tennessee Valley Authority. 80/11/17. 3pp.
- 8012050023 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21, 1p. 07173-072.
- 8012310058 Forwards IE Insp Repts 50-438/80-25 & 50-439/80-25 on 800927-1031. No noncompliance noted. MURPHY.C.E. Region 2- Atlanta: Reactor Construction & Engineering Support Branch. 80/11/21. 2pp. 07369: 072.
- --B012310053 IE Insp Repts 50-438/80-25 & 50-439/80-25 on 800927-1031.

 No noncompliance noted Major areas inspected:const surveillence training & audits.

 WILCOX.J.D. Region 2. Atlanta, Office of the Director.

 CANTRELL.F.S. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. B0/11/20. App. 07369:074.
- 8012080204 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24, 1p.
- 8012070135 Ack receipt of 801105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-19 & 50-439/80-19.
 MCRPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/25. 1p. 07179:205.
- ~~8012050142 Responds to NRC 801014 ltr re violations noted in IE Insp. Repts 50-438/80-19 & 50-439/80-19. Corrective actions: drawing changed to reflect as-built condition of trunnions & personnel received retraining.

 MILLS.L.M. Tennessee Valley Authority. 80/11/Q5. 2pp 07199:207.
- --8012070146 Forwards IE Insp Repts 50-438/80-17 & 50-439/80-19 on 800727-0827 & notice of violation. MURPHY,C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/14. 2pp. 07199:209.
- --8012070152 Notice of violation from insp on 800727-0829.

 * Region 2. Atlanta: Office of the Director. 80/10/07. ip.
 07199:211.
- --8012070155 IE Insp Repts 50-438/80-19 % 50-439/80-19 on 800727-0829.

 Noncompliance noted: invalid OC signoffs for upper steam generator restraint installation.

 WILCOX,J.D. Region 2. Atlanta, Office of the Director.

 CANTRELL,F.S. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/07. 5pp. 07199:212.
- 8012170359 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/26. 1p. 07269:022.
- S. Reportable occurrences, LERs & related correspondence
- 8012150261 Part 21 rept re defective Transamerica Delaval diesel generators. Caused by shallow dowel counterbone in link rod assembly. Insp procedures implemented & repairs scheduled. MILLS.L. M Tennessee Valley Authority. 80/11/25. 3pp. 07237:357.
- 80:2100486 Fourth interim deficiency mept me ITT controls of American Warming & Ventilating dampers, originally reported 800417.
 American Warming & Ventilating yet to receive & approve mept by ITT. West util mept will be submitted 810508.
 MILLS, L.M. Tennessee Valley Authority. 80/11/26. ip. 07220:040.
- 8012150766 Part 21 rept re ITT controls of American Warming & Ventilating dampers. Rept will be sent pending receipt & approval of ITT evaluation.
 MILLS.L.M. Yennessee Valley Authority. 80/11/26. 2pp. 07237:360.
- 8012100467 Fourth interim deficiency rept re lack of internal purge on welds in chemical addition & boron recovery sys, initially reported on 800417 Util will identify stainless steel welds requiring purge Next rept scheduled on 810624.
 MILLS.L.M. Tennessee Valley Authority. 80/12/01. 2pp. 07218:272.

- 8G12100447 First interim deficiency rept re fillet weld specification. American Insp of Steel Const stds & affected welds are being evaluated. Next rept will be submitted by 810119.
 MILUS, L.M. Tennessee Valley Authority. 80/12/03. 2pp. 07219:034.
- 8012100448 Forwards final deficiency rept.originally reported 801107, re undersized fillet welds on high pressure fire protection sys supports. Util revised & reissued all questionable drawings detailing correct weld size.

 MILLS.L.M. Tennessee Valley Authority. 80/12/03. 2pp. 07219:032.
- 8012160575 Part 21 rept re 8%N nonconservative analysis of neutron flux.initially reported on 801105.Util is awaiting vendor proposed resolution. Neut rept will be submitted by 810331.
 MILLS,L.M. Tennessee Valley Authority. 80/12/03. 3pp. 07254:332.
- 8012179406 Second interim deficiency rept re 600-V & 8 & 15-kV power cables, types CPJ & CPSJ, installed in cable trays, not qualified for IEEE 383-1977 flame test. Next rept to be submitted by 810323.

 MILLS, L. M. Tennessee Valley Authority, 80/12/10. 2pp. 07270:003.
- 8012:300496 Second interim deficiency rept re socket weld misalignment on essential air sys welds. Inspectors were reinstructed re requirements of G-29M & applicable field const procedures. Std operating procedure RNP-NEU-SUP-711 revised, MILLS.L.M. Tennessee Valley Authority. B0/12/16. 2pp. 07359;212.
- 8012310311 First interim deficiency rept re certified matl test repts on anchorheads. INRYCO. Inc has informed util that certified matl test repts have been obtained from Tech Steel & Alloy Carp. Util will review adequacy upon receipt.

 MILLS, L. M. Tennessee Vailey Authority. 80/12/24. 2pp. 07361:289.
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- BO12146050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. E15ERHUT, D. C. Division of Licensing. B0/10/31. 7pp.
- 8012220358 Ltr to all CP & QL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing. 80/11/04. App.
- 8012220141 Summary of 801001 meeting u/util in Cleveland.OH resystematic assessment of licensee performance.Regulatory performance was adequate HDUSTON.M.D. Licensing Branch 2 80/12/01. 3pp. 07307:149.
- --8012220144 Advises that Systematic Assessment of Licensee Performance Board concluded licensee regulatory performance was adequate Evaluation results, action plan & meeting details encl.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/23. App. 07307:192.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012030841 Notifies that remaining portion of CL application consisting of FSAR, Vals 1-18, is being sent to Perry, OH Public Library under separate cover.

 SCUDER, J. L. Division of Rules and Records. 80/11/18. 1p. 07149: 258.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012110041 Forwards IE. Insp. Repts 50-440/80-20 & 50-441/80-18 on 800917-19 & notice of violation. FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/10/21. 2pp. 07223:279.
- --8012110044 Notice of violation from insp on 800917-19. ★ Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/21, 2pp. 07223:281.
- --B017110047 IE Insp Repts 50-440/80-20 % 50-441/80-18 on 800717-19.

 Noncompliance noted: inadequate insp program re const quality, failure to follow procedures for concrete placement & for certifying GA/GC personnel.

 LAHDSHAH.R.B. Region G. Chicago. Reactor Construction & Engineering Support Branch. HAYES, D. W. Region G. Chicago. Office of the Director. B0/10/21. Spp. 07223:283.

- 8012090138 Forwards IE Kgt Keeting Repts 50-440/80-24 & 50-441/80-22 on 801001. No noncompliance noted KEPPLER.J. G. Region 3. Chicago. Office of the Director. 80/10/24. Zpp 07199.269.
- --8012090145 IE Mgt Meeting Ropts 50--440/80-24 & 50-441/80-22 on 801001.
 No homocompliance note: Major areas discussed: regulatory performence as concluded in systematic assessment of licensee performance.

 MEPPLER, J. G., MILLIAMS, C. C. Region B. Chicago, Diffice of the Director. FIGRELLI, G. Region B., Chicago, Reactor Construction & Engineering Support Branch. 80/10/22 7pp 07199:271.
- 8012170549 Forwards IE Into Notice 80-27, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/10/24.

 1p. 07265.049.
- 8012050425 Requests info resulting from review of application reinservice insplict pressure isolation valves. Requests list of pressure isolation valves included in testing program w/foursets of piping to instrumentation diagrams. TEDESCO.R.L. Assistant Director for Licensing. 80/11/17. 4p. 07179:307.
- 8012020743 Forwards three Performance Appraisal Branch inspirepts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & mate appropriate adjustments. M/o encl.

 KEPPLER, J. C. Region 3. Chicago, Office of the Director. 80/11/18.
- 8012240169 Forwards IE Insp Repts 50-640/80-26 & 50-441/80-24 on 801103-05. No noncompliance noted FIGREPLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/20 | 2pp. 07325.026.
- --8012240172 IE Insp Repts 50-440/80-24 & 50-441/80-24 on 801103-05. No noncompliance noted. Major areas inspected: util/OAI/OE design control interfaces.

 KDN4LTR-J.E., ERB.C.M., NILLIAMB.C.C. Region 3, Chicago, Office of the Director. 80/11/18 7pp. 0/325-028.
- 8012040671 Forwards IE Sullatin 90-24, "Prevention of Damage Due to Mater Leakage Inside Centainment" No written response required.

 KEPPLER, J. O. Region 3. Chicago, Office of the Director. B0/11/21, 2pp. 07169:074.
- 8012080039 Forwards 1E Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid " No written response required. KEPPLER, J. C. Region 3. Coicago, Office of the Director. 80/11/24, 2pp. 07182:163.
- B012170557 Forwards 1E Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.

 KEPPLER, J. G. Region 2, Chicago, Office of the Director. 80/11/26. 2pp. 07264: 298.
- B0121603A2 Responds to NRC 601117 request for info re inservice insp program for pressure location values Program will be developed at future date in support of May 1983 licensing schedule. DAVIDSON D.R. Cleveland Electric Illuminating Co. 80/12/11. 1p.
- 8012300464 Responds to IE Sulletin 79-018 Suppl 2, "Environ Qualification of Class IE Equipment," Required info supporting electrical equipment qualification will be submitted 830161 supporting expected May 1983 CL issuance. DAVIDEON, D. R. Cleveland Electric Illuminating Co. 80/12/16. 1p. 07346:127.
- S. Reportable occurrences, LERs & related correspondence
- 8012099300 Interin deficiency rept on degradation of fuel pool penetration piping, initially reported on 80f103. Contractor was directed to identify? investigate problem. Final rept will be submitted by 810301.

 BAYIDSON.D.R. Cleveland Electric Illuminating Co. 80/12/03. 2pp. 07201:108
- 8012100421 Interim deficiency meptine degradation of fuel pool penetration piping 6-41 sys Nonconformance mept CQA-178 documenting deficiencies & status of 24 add1 assemblies being prepared final rept will be submitted by 810301. DAVIDSON, D.R. Cleveland Electric Hilvminating Co. B9/12/03. 2pp. 07219-038

- G012070337 Notifies of delay until 810201 for final deficiency rept resolubility of Mono-Sol 7-0015-3 CMS polyvinyl atcohol film. Additine is needed to determine extent of problem & resolution.
 DAVIDSON, D.R. Cleveland Electric Illuminating Co. 80/12/04. 1p. 07201:114
- 8012240039 Part 21 rept re reactor protection sys fierible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces on high resistance connection to panel surfaces where termination modules are mounted. SHERIGOD. C. G. Goneral Electric Co. 80/12/03 3pp.
- 8012390599 Second interim deficiency rept.originally reported on 801105-re site qualification teating of Hilti-Kuit Bolts which may not neet spec requirements for 1.5 times working load & ultimate capacity (mar pullant load). DAVIDEBILD R Cleveland Electric Illuminating Co. 80/12/19. 3pp. 07346:149
- DOCKET 50-441 PERRY NUCLEAR FOREN PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, DL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licenses confirmation in 45 days that Encl 1 implementation dates will be not. EISENHUT, D. C. Division of Licensing. 80/10/3i. 7pp.
- 8012220398 Ltr to all CP & CL. holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT.D.G. Division of Licensing, 80/11/04, 4pp.
- B012270141 Summary of B01001 nesting c/util in Cleveland.OH resystematic assessment of licensee performance Regulatory performance was adequate HOUSTEN.H.D. Licensing Branch 2 80/12/01 3pp. 07307:149.
- --8012220144 Advises that Systematic Assessment of Licensee Performance
 Board concluded licensee regulatory performance was
 adoquate. Evaluation results, action plan & meeting details
 encl.
 KEPPLER.J. G. Region 3. Chicago. Office of the Director. 80/10/23.
 App. 07307:152
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8012030941 Notifies that remaining portion of OL application consisting of FSAR, Vols 1-18, is being sent to Perry, OH Public Library under separate cover SOUVER, J.L. Division of Rules and Records. 80/11/18. 1p. 07149:259.
- Q. Inspection reports. IE Bulletins & correspondence
- B012110941 Forwards IE insp Repts 50-440/80-20 & 59-441/80-18 on 800917-19 & natice of violation. FIGRELLIG. Region 3. Obtrago. Reactor Construction & Engineering Support Branch 80/10/21 Spp. 07223: 279.
- --8012110045 Notice of violation from insp on 800717-19.

 * Region 3. Chicago. Reactor Construction & Engineering Support Branch. 80/10/21. 2pp. 07223:881.
- --8012110049 IE Into Repts 50-440/80-20 & 50-441/80-18 on 800917-19. Noncongliance noted:inadequate insp program re const quality, failure to follow procedures for concrete placement & for certifying OA/G1 personnel LANDSHAM, R B. Region 3. Chicago, Reactor Construction & Engineering Support Sranch MAYES.D & Region 3. Chicago, Office of the Director. 80/10/21 5pp. 07223.283.
- 8012070138 Forwards IE Mgt Meeting Repts 50-440/80-24 & 50-441/80-22 on 801001. No noncompliance noted KEPPLER. J. C. Region 3. Chicago, Office of the Director, 80/10/24. 2pp. 07197 289.
- ---B012C90145 IE Mgt Meeting Repts 50-440/80-24 & 50-441/80-22 on B01001. No noncompliance noted Major areas discussed regulatory performance as concluded in systematic assessment of licensee performance.

 KEPPLER, J. G. Williams, C. C. Region 3, Chicago, Office of the Director, FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support 3 anch. 80/10/22. 7pp. 07199:271.

- 8012170649 Forwards IE Info Notice 80-37, "Containment Cooler Leats & Reactor Cavity Flooding at Indian Point Unit 2." No written response required KEPPLER, J. C. Region 3, Chicago, Office of the Director, 80/10/24, ip. 07266:049.
- 8012050425 Requests info resulting from review of application re inservice insp of pressure isolation valves. Requests list of pressure isolation valves included in testing program w/four sets of piping & instrumentation diagrams. TEDESCO.R.L. Assistant Director for Licensing. 80/11/17. 4p. 07175:307.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. W/o encl.

 KEPPLER, J. C. Region 3. Chicago, Office of the Director. 80/11/18.
- 8012240169 Forwards IE Insp Repts 50-440/80-26 & 50-441/80-24 on 801103-05. No nuncompliance noted. FIGRELLI.O. Region 3. Chicago, Reactor Construction & Engineering Support Stanch. 80/11/20. 2pp. 07325:026.
- --B012240172 IE Insp Repts 50-440/80-26 & 50-441/80-24 on B01103-05. No noncompliance noted. Major areas inspected: util/QAI/OE design control interfaces.

 KONMLIN, J. E., ERB. C. M., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. B0/11/18. 7pp. 07325: 028.
- 8012040671 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Nater Leakage Inside Containment." No written response required. KEPPLER. J. G. Region 3. Chicago. Office of the Director. 80/11/21. 2pp. 07169:074.
- 8012080939 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/11/24. 2pp. 07182:183
- 8012170557 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.

 KEPPLER. J. G. Region 3, Chicago, Office of the Director. BO/11/26.
 2no. 07564-296
- 8012160362 Responds to NRC 801117 request for info re inservice insp program for pressure location valves. Program will be developed at future date in support of May 1983 licensing schedule. DAVIDEOU.D.R. Cleveland Electric Illuminating Co. 80/12/11. 1p. 07261:183.
- 8012300464 Responds to IE Sulletin 79-018. Suppl 2. "Environ Qualification of Class IE Equipment." Required info supporting electrical equipment qualification will be submitted 803001 supporting espected May 1983 GL issuance. DAVIDSOW.D.R. Cleveland Electric Illuminating Co. 80/12/16. 1p. 07386-127
- S. Reportable occurrences, LERs & related correspondence
- B012070330 Interim deficiency rept on degradation of fuel pool peretration piping, initially reported on 801103. Contractor was directed to identify & investigate problem. Final rept will be submitted by B10301. DAVIDEDM. D.R. Cleveland Electric Illuminating Co. 80/12/03. 2pp. 07201:108.
- 8012100421 Interim deficiency rept re degradation of fuel pool penetration piping G-41 sqs. Nonconformance rept COA-178 documenting deficiencies 2 status of 24 addl assemblies being prepared final rept will be submitted by 810301. DAVID6016 D.R. Cleveland Electric Illuminating Co. 80/12/03. 2pp. 07219:038.
- 8012090307 Notifies of delay until 810201 for final deficiency rept resolubility of Mono-Sol 7-0015-3 CNS polyvinyI alcohol film. Addl time is needed to determine extent of problem & resolution.

 DAVIDEDIAD R. Cleveland Electric Illuminating Co. 80/12/04. 1p. 07201:114.
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing bot whorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERIMODD. C. G. General Electric Ca. 80/12/08. 3pp.

- 8012300579 Second interim deficiency rept-originally reported on 801106.re site qualification testing of Hilki-Kuik Bolts which may not meet spec requirements for 1.5 times working load & ultimate capacity (max pullout load) DAVIDSDN.D.R. Cleveland Electric Illuminating Co. 80/12/19. 3pp. 07316: 149.
- DOCKET 50-443 SEARROOK NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 to TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be not. EISERMUT.D.C. Division of Licensing. 80/10/31. 7pp.
- 6011190371 Forwards Amend 41 to CL application. Amend relates to applicant request for reinstatement of prior authorization for transfer from CT Light & Power Co to Fitchburg Gas & Electric Light Co Ropes & Gray. 60/11/18. 1p. 07006;209. RITSHER, J. A.
- -8011190378 Amend 41 to application for OL requesting partial transfer of ownership from CT Light & Power Co to Fitchburg Gas & Electric Light Co.Certificate of Svc & applicant general info encl. HERRILL.D.N. Public Service Co. of New Hampshire. 80/11/10.
- --8011190983 Order approving Montaup Electric Co acquisition of 1% interest in project from PSC of lim Fitchburg Gas & Electric Light Co acquisition of percentages of interest in project. POTE.D.R. Massachusetts, State of
- --8011190396 Order directing consolidation of instant petitions for further hearing investigation & consideration w/petition docksted as DPH 20055. POTE.D.R. Massachusetts State of 79/06/28. 13pp. 07007:168.
- 8012110566 Requests authorization to use Code Case N-279 "Use of Torquing as Locking Device for Section 3.Div 1.Class 1.2 & 3 & MC Component Supports." Case N-279 not covered in Reg Guides 1.84 & 1.84.

 BEVINCENTIS.J. Public Service Co. of New Hampshire. 80/12/08. 1p.
- 8012240155 Forwards Amends 4 & 4 to Licenses CPPR-135 & CPPR-136, respectively & notice of issuance & availability. EISEID-UT, D. G. Division of Licensing. 80/12/12. 3pp. 07325:002.
- --B012240160 Amends 4 & 4 to Licenses CPPR-135 & CPPR-136, respectively, providing for transfer of partial ownership shares. EISENMUT.D.G. Division of Licensing. 80/12/12. 8pp. 07325:005.
- -B012240164 Notice of issuance & availability of Amends 4 & 4 to Licenses CPFR-135 & CPPR-136 YOURGBLOOD, 9. J. Licensing Branch 1. 80/12/09. 2pp. 07325:013.
- F. Security, medical, emergency & fire protection plans
- 8012080706 Releases public version of "Seabrook Station Evacuation Analysis: Final Rept.Estrmate of Evacuation Times" & "Seabrook Station Evacuation Analysis: Technical Memorandum L.Summary of Local Meetings." FELTON-U. II Division of Rules and Records. 80/12/01. 1p. 07190-077
- -8012060007 Public version of "Seabrook Station Evacuation Analysis, Final Rept, Estimate of Evacuation Times," prepared for FEKA. KAKEN, A., KULASH, H., HERALD, H. PRC Planning & Economics, Alan H. Voorhees & Associates Div. 80/08/31, 52pp. 07190:078.
- --B0170B0012 Public version of draft "Seabrook Station Evacuation Analysis, Final Rept. Estimate of Evacuation Times." prepared for FEMA. PRC Planning & Economics. Alan M. Voorhees & Associates Div. B0/07/31. 150pp. 07190:177.
- --8012030440 Public version of "Seabrook Station Evacuation Analysis: Technical Memorandum 1. Summary of Local Meetings." prepared for FEIFA.

 4 PRC Planning & Economics. Alan M. Voorhees & Associates Div. 80/08/31. 20pp. 07170: 265.

- G. Adjudicatory correspondence
- 8012290007 Transcript of IDRC 800925 Affirmation Session 80-42 repetition for review of Seatrool sessic issues.Pp 1-4. Exhibits each.
- 8012020573 Request for leave to reply to applicant & NRC answers to intervenor New England Coalition on Nuclear Pollution motion to suspend const due to newly acquired info.
 MEISS.E.R., JORDAN.M.S. New England Coalition on Nuclear Pollution.
 MEISS.E.R. Sheldon, Harmon & Meiss. 80/11/26 2pp. 07145:360.
- 8012230010 Interrogatories to be answered by MA Chinnery, requesting info re seismic zone definition, earthquates occurring in seismic zone & elsewhere & use of SSE of XII for all US nuclear plants. Certificate of Svc encl.

 DIGNAN.T.G. Public Service Co of New Hampshire. DIGNAN.T.G. Ropes & Gray. 80/11/26. Spp. 07311.167.
- 8012240021 Order granting New England Coalition on Nuclear Pollution leave to reply to NRC & applicant responses to RECNP motion to suspend effectiveness of CPs pending outcome of remand on seismic issues Reply due 801264.

 BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/12/01.

 1p. 07324:207.
- B012230C07 Confirms B01210 deposition in Los Angeles, CA re NRC 800925 order, NRC B01017 memorandum in response to ASLAB 800927 order & provious testimony LESSY, R. P. Antitrust Division. 80/12/03 2pp. 07311:163.
- 8012170675 Response to Licensee & applicant arguments against motion to suspend const. Requests immediate suspension of CPs.
 Gertificate of Svc oncl.
 JURDAN, M. S. New England Coalition on Nuclear Pollution. JURDAN, M.S.
 Sheldon, Harmon & Weiss. 80/12/04. 11pp. 07264:196.
- --8012170682 Affidavit evaluating plant const & impact on changes to safety-related structures & components Prof qualifications & list of publications enc3 MINOR.C.C. MMD Technical Associates. ED/12/02. 9pp. 07264:207.
- B012150P41 Denies 801015 request for Farrar participation in ASLAB proceeding or replacement of ASLAB cembers welsperts in appropriate fields. Request desired due to resignation of Farrar & failure to show need for recomposition of ASLAB. CHILK, S. U. Diffice of the Secretary of the Commission. 80/12/10. 1p. 07240:120
- --8012150248 Requests Farrar participation as ASLAB member in seismic proceeding or replacement of ASLAB members w/experts in fields of seismology, geology & earthquake engineering. HEIMHOLD, E. H. Affiliation Unknown. 80/10/15. 2pp. 07240:121.
- 8012230027 Discusses ASLAR 801207 memorandum & order (ALAB-623) ruling that effectiveness of CPs should not be suspended pending reconsideration of seismic issues.

 SMAPAR.H.K. Office of the Executive Legal Director. 80/12/12. 2pp. 07311:212.
- 8012270322 Request for extension to 810107 to respond to applicant interrogatories. Certificate of Svc encl.
 JGRDAN, U.S. New England Coalition on Nuclear Pollution. JORDAN, U.S. Harmon & Weiss. 80/12/16 3pp. 07343:075.
- H. General correspondence
- BO12050379 Requests immediate review of evacuation plan within 10-20 mile radius of plant Cites recent accident at Indian Point. Fears political pressure will be expedite license issuance. Demands immediate review DOUGHTY. J. Doherty. J. B0/11/24. 1p. 06915.001.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012080045 Forwards IE Insp Repts 50-443/80-06 & 50-444/80-06 on B00519-0627 & notice of violation.
 CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/08/01. 2pp. 07180:324.
- ~8012080049 Notice of violation from insp on 600519-0627 * Region 1, Philadelphia. Office of the Director, 8 07180:326. 80/07/25, ip.

- --8012080060 IE Insp Repts 50-443/80-06 & 50-444/80-06 on 800519-0627. Noncompliance noted failure to provide appropriate criteria for insp of equipment grouting. CERNE, 4 C., VARIELAA A. Rejion 1. Philadelphia. Office of the Director. MCGAUGHY, P. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 80/07/25. 15pp. 07180:327
- B012090224 Ack receipt of 801007 ltr informing NRC of steps taken to correct violations noted in IF lnsp Repts 50-443/80-07 & 50-444/80-07 CARLSCIE.T. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 80/10/30 1p. 07202:297.
- --8012090232 Responds to NRC 800704 ltr re violations noted in IE Insp Repts 50-443/80-07 & 50-444/80-07. Corrective actions: reinsp of stud welds & issuance of nonconformance repts performed. Increased surveillance & personnel reinstruction emphasized. DEVINCENTIS. Public Service Co. of New Hampshire. 80/10/09. 2pp. 07202:298.
- --8012070237 Forwards IE Insp Repts 50-4443/80-07 & 50-444/80-07 on 800430-0801 & notice of violation CARLSOLR.T. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 80/07/04: 2pp. 07202:309.
- --8012090240 Natice of violation from inse on 800630-0801.

 * Region 1, Philadelphia, Office of the Director. 80/09/03. ip. 07202:302.
- --8012070242 IE insp Repts 50-443/80-07 & 50-444/80-07 on 800630-0801.

 Noncompliance noted: failure to initiate nonconformance rept & to review & disposition stud weld nonconforming conditions u/procedural requirements.

 CERKE, A. C. Region I. Philadelphia, Diffice of the Director.

 MCGAUGHY, R. R. Region I. Philadelphia, Reactor Construction & Engineering Support Branch. 80/07/03 11pp. 07202:303.
- 8012170334 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. GRIER, B.H. Region i, Philadelphia, Office of the Director. 80/10/30. jp. 07269:070.
- 8012120121 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/06. 1p. 07230:210
- B012030777 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressorization " No written response required. GRIER. B.H. Region 1. Philadelphia. Office of the Director. B0/11/07. 1p 0/150:191
- 8012080375 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 GRIER, B.H. Region 1. "Philadelphia. Office of the Director.

 80/11/10. 1p. 0/182:297.
- 8012040507 Forwards EE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER. B.H. Region 1, Philadelphia, Office of the Director. BO/11/14. 1p. 07169:250.
- 8012220697 Advises that written response is required to IE Bulletin 80-23. "Failures of Solemoid Valves Rfg by Valcor Engineering Corp "First paragraph erroneously stated no written response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/19. 1p. 07293:124
- 8012040529 Forwards IE Bulletin GO-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No writton response required. GRIER.B.H. Region I. Philadelphia, Office of the Director. BO/11/21. 2pp 07165:324.
- 8012050598 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluis." No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/24, jp. 07174:092.

- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- BO12140050 Ltr to operating plant licensess.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISENMUT.D.G. Division of Licensing. B0/10/31. 7pp.
- 8012110566 Requests authorization to use Code Case N-279 "Use of Torquing as Locking Device for Section 3.Div 1.Class 1.2 & 3 & MC Component Supports." Case N-279 not covered in Reg Guides 1.84 & 1.84.

 DEVINCENTIS.J. Public Service Co. of New Hampshire, 80/12/08. 1p. 07223:106.
- 8012240155 Forwards Amends 4 & 4 to Licenses CPPR-135 & CPPR-136, respectively & notice of issuance & availability.
 EISERMUT, D. G. Division of Licensing. 80/12/12. 3pp. 07325:002.
- --8012240160 Amends 4 & 4 to Licenses CPPR-135 & CPPR-136, respectively, providing for transfer of partial ownership shares.
 EISERHUT, D. G. Division of Licensing. 60/12/12. 8pp. 07325:005.
- --B012240164 Notice of issuance & availability of Amends 4 & 4 to Licenses CPPR-135 & CPPR-135 Y0UM33L00D, B. J. Licensing Branch 1. B0/12/07. 2pp. 07325:013.
- F. Sacurity, medical, emergency & fire protection plans
- BD12080006 Releases public version of "Seabrook Station Evacuation Analysis.Final Rept.Estimate of Evacuation Times" & "Seabrook Station Evacuation Analysis:Technical Memorandum 1.Summary of Local Meetings." FELTON, J. M. Division of Rules and Records. 80/12/01. 1p. 07190:077.
- --8012080007 Public version of "Seabrook Station Evacuation Analysis, Final Rept.Estimate of Evacuation Times," prepared for FEMA. KANEN.A., KULASH, W. HERALD, W. PRC Planning & Economics, Alan M. Voorhees & Associates Div. 80/08/31. 92pp. 07190:078.
- --8012030012 Public version of draft "Seabrook Station Evacuation Analysis Final Rept Estimate of Evacuation Times," propared for FEMA. 4 PRC Planning & Economics, Alan M. Voorhees & Associates Div. 80/07/31. 150pp. 07190:177.
- --8012030440 Public version of "Seabrook Station Evacuation Analysis: Technical Memorandum I.Summary of Local Meetings." prepared for FEMA. → PRC Planning & Economics. Alan M. Voorhees & Associates Div. 80/08/31. 20pp. 07190: 265.
- G. Adjudicatory correspondence
- B012290007 Transcript of NRC 800925 Affirmation Session 80-42 repetition for review of Seabrook seismic issues.Pp 1-4. Exhibits encl. # Commissioners. 80/09/25. App.
- B012020673 Request for leave to reply to applicant & NRC answers to intervenar New England Coalition on Nuclear Pollution motion to suspend const due to newly acquired info.
 WEISS, E. R., JORDAN, H. S. New England Coalition on Nuclear Pollution.
 WEISS, E. R. Shelden, Harmon & Weiss. 80/11/26. 2pp. 07145:360.
- 8012230010 Interrogatories to be answered by MA Chinnery, requesting info re seismic zone definition, earthquakes occurring in smismic zone & elsewhere & use of SBE of XII for all US nuclear plants. Certificate of Svc encl.
 DIONAN, T. G. Public Service Co. of New Hampshire. DIONAN, T. G. Ropes & Oray, 80/f1/26 Spp. 07311:169.
- 8012240021 Order grenting New England Coalition on Nuclear Pollution leave to reply to NRC & applicant responses to NECNP motion to suspend effectiveness of CPs pending outcome of remand on saismic issues. Reply due 801204. BIEHOP.C. J. Atomic Safety and Licensing Appeal Panel. 80/12/01. 1p. 07324:207.
- 8012230007 Confirms 801210 deposition in Los Angeles, CA re NRC 800925 order, NRC 801017 memorandum in response to ASLAB 800929 order & previous testimony. LESSY.R.P. Antitrust Division. 80/12/03. 2pp. 07311:163.

- 8012170675 Response to Licensee & applicant arguments against motion to suspend const. Requests immediate suspension of CPs.
 Certificate of Svc encl.
 JGRDAN, M. S. New England Coalition on Nuclear Pollution. JGRDAN, M. S. Sheldon, Harmon & Weiss. 80/12/04. 11pp. 07264:196.
- --B0121706S2 Affidavit evaluating plant const & impact on changes to safety-related structures & components Prof qualifications & its of publications encl.
 MINGR.O.C. MHB Technical Associates. 80/12/02. 9pp. 07264:207.
- B012150241 Denies B01015 request for Farrar participation in ASLAB proceeding or replacement of ASLAB members w/experts in appropriate fields. Request denied due to resignation of Farrar & failure to show need for recomposition of ASLAB. CHILK, B. J. Office of the Secretary of the Commission. B0/12/10. ip. 07240:120.
- --801215024B Requests Farrar participation as ASLAB member in seismic proceeding or replacement of ASLAB members w/experts in fields of seismology.geology & earthquake engineering. KEINHOLD.E.H. Affillation Unknown. 80/10/15. 2pp. 07240:121.
- B012230029 Discusses ASLAS 801209 mamprandum & order (ALAB-623) ruling that effectiveness of CHs should not be suspended pending reconsideration of seismic issues.

 BHAPAR.H.K. Office of the Executive Legal Director. 80/12/12. 2pp. 07311:212.
- 8012290322 Request for extension to 810107 to respond to applicant interrogatories. Certificate of Svc encl. JORDAN. W. S. New England Coalition on Nuclear Pollution. JORDAN. W. S. Harmon & Weiss. 80/12/16. 3pp. 07343:095.

H. General correspondence

- E012050379 Requests immediate review of evacuation plan within 10-20 mile radius of plant. Cites recent accident at Indian Point. Fears political pressure will be exerted to expedite license issuance. Demands immediate review.

 DOUGHTY, J. Doherty, J. F. 80/11/24. 1p. 06915:001.
- I. Financial information
- 8011190371 Forwards Amend 41 to OL application. Amend relates to applicant request for reinstatement of prior authorization for transfer from CT Light & Power Co to Fitchburg Gas & Electric Light Co.
 RITSHER, J. A. Ropes & Oray. 80/11/18. 1p. 07006:209.
- --8011190378 Amend 41 to application for OL requesting partial transfer of ownership from CT Light & Power Co to Fitchburg Oas & Electric Light Co.Certificate of Svc & applicant general info encl.

 KERRILL, D.N. Public Service Co. of New Hampshire. 80/11/10. 15pp. 07006:220.
- --8011190383 Order approving Montaup Electric Co acquisition of 1% interest in project from PSC of NH Fitchburg Oas & Electric Light Co acquisition of percentages of interest in project. POTE. D. R. Massachusetts, State 67. 80/10/30. 303pp. 07006: 225.
- --8011170376 Order directing consolidation of instant petitions for further hearing investigation & consideration w/petition docketed as DPH 20055. POTE, D. R. Massathusetts, State of, 79/06/28. 13pp. 07007: 168.
- Q. Inspection reports, IE Bulletins & correspondence
- B0120B0045 Forwards IE Insp Repts 50-443/80-06 & 50-444/80-06 on B00519-0627 & notice of vigilation. CARLEON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. B0/08/01. 2pp, 07180:324.
- --8012080049 Natice of violation from insp on 800519-0627.

 * Region 1. Philadelphia. Office of the Director. 80/07/25. lp. 07180:326.
- --8012080060 IE Insp Repts 50-443/80-06 & 50-444/80-06 on 800519-0627. Noncompliance noted: failure to provide appropriate criteria for insp of equipment grouting. CERNE.A.C., VARELA,A.A. Region 1. Philadelphia, Office of the Director. MCGAUGHY.R.W. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 80/07/25, 15pp. 07180:327.

- 80120902/4 Ack receipt of 801007 ltr informing NRC of steps taken to correct violations noted in 16 lnsp Repts 50-443/80-07 & 50-444/80-07. CARLS0/JR T. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/30 1p. 07202:297.
- --8012070232 Responds to NRC 800704 ltr re violations noted in IE Insp. Repts 50-443/80-07 & 50-444/80-07. Corrective actions: reinsp. of stud welds & issuance of nonconformance repts performed. Increased surveillance & personnel reinstruction emphasized. DEVINCENTIS. J. Public Service Co. of New Hampshire. 80/10/09. 2pp. 07202: 278.
- --8012070237 Forwards 1E Insp Repts 50-443/80-07 & 50-444/80-07 on 800630-0801 & notice of violation. CARLSUN.R T. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/04. 2pp. 07202:300.
- --8012070242 IE Insp Repts 50-443/80-07 & 50-444/89-07 on 800630-0801.
 Noncompliance noted: Failure to initiate nonconformance rept & to review & disposition stud weld nonconforming conditions w/procedural requirements.

 CERNELA.C. Region 1. Philadelphia. Office of the Director.

 MCGAUGHY.R.W. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 80/07/03. 11pp. 07202:303.
- 8012170384 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/30. 1p. 07269:070.
- 8012120121 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Halcolm Foundry Co.Inc." Written response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 80/11/06. jp. 07230:210
- 8012030//7 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ORIER, 6.11. Region i, Philadelphia, Office of the Director. 80/11/07. 1p. 07150:171.
- B012080375 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besso Unit 1." No response required. GRIER, B.H. Region 1. Philadelphia, Effice of the Director. B0/11/10. 1p. 07182:297.
- B012040007 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/14. 1p. 07169: 260.
- 8012220697 Advises that written response is required to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/19. lp. 07293:124
- 8012040529 Forwards 16 Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment" No written response required.

 ORIER, B. H. Region 1, Philadelphia, Office of the Director, 80/11/21. 2pp. 07165.324.
- 8012050578 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. CRIER,B.H. Region 1, Philadelphia, Office of the Director. 80/11/24. 1p. 07174:072.
- DOCKET 50-449 COMANCHE PEAK STEAM ELECTRIC STA. UNIT 1

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licenspessOL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be ret. EISERMUT.D.G. Division of Licensing. 80/10/31, 7pp.
- 8012010351 Confirms 801030 plans for 831125 meeting in Chicago. IL to discuss NRC evaluation of regulatory performance.

 KEPPLER. J. O. Region 3. Chicago. Office of the Director. 80/11/18.

- 8012040017 Forwards request for add1 info required to complete NRC evaluation of application for operating licenses for facilities. Response should be submitted within 6 wks.
 TEDESCO.R. L. Assistant Director for Licensing. 80/11/20. 25pp. 07152:059
- 8012040197 Discusses NRC review schedular requirements for special low power test program b energency procedures. Provides list of lead times to be met in order to complete evaluations in conjunction wipower ascension program schedule. IEDESCOR L. Assistant Director for Licensing. 80/11/20. 2pp. 07170.217.
- 8012100663 Discusses NRC requirements for organizational structure & staff resources.FSAR amend reflecting recent organizational changes should be submitted by 810116 due to projected schedule for issuance of SER TEOESCO.R.L. Assistant Director for Licensing. 80/11/20. 3pp.
- 8012150230 Forwards Revision 1 of Table 1, providing scheduled documentation submittal dates to NRC for equipment qualification data packages included in vendor equipment qualification program. Table 2 re facility equipment encl. ANDERSON.T.M. Westinghouse Electric Corp. 80/11/26. 6pp. 07240:270.
- 8012300536 Respands to 801114 ltr requesting addl clarification re environ review Commercial firm will remove sludge to disposal area. Dead fish were removed from travelling screens as screens were rotated once every 8-h. GARY.R. J. Texas Utilities Generating Co. 80/12/22. Spp. 07316:271.
- C. Utility Environmental Report (ER), amends & correspondence
- 8012300338 Forwards Amend 2 to environ rept. GARY,R.J. Texas Utilities Co. 80/12/22. 2pp. 07350:005.
- --8012330344 Amend 2 to environ rept.
 # Teres Utilities Co. 80/17/22, 16pp. 07350:007.
- F. Security, medical, emergency & fire protection plans
- 8012160199 Notifies that util 800818 safeguards contingency plan is acceptable. Sample licensing condition encl. TEDSECO.R.L. Assistant Director for Licensing. 80/11/26. 3pp. 07262:310.
- 8012310988 Forwards response to NRC comments re interio physical security plan. Enci withheld (ref 100FR2. 790). GARY.R. J. Tevas Utilities Generating Co. 80/12/23. 3pp. 07359:272.
- G. Adjudicatory correspondence
- 8012290529 Informs of ASLAS 801124 memorandum & order dismissing appeal filed by Citizens for Fair Util Regulation, intervenor in facility GL proceeding Intervenor sought to appeal rejection of one contention.

 SHAPAR.H.K. Office of the Executive Legal Director. 80/11/25. ip. 07335:181.
- B01209034i Forwards original verification for B01201 suppl to answers to applicants' first set of interrogatories & requests to produce re util application for QLs.N/o encl. ELLIS.U. Citizens Association for Sound Energy. B0/12/01. 2pp. 07199:347.
- 8012270318 Suppl to Citizens Association for Sound Energy answer to applicants' first set of interrogatories & requests to produce. Details info relied upon for Contention 5 re IE insp repts. Certificate of Svc encl. Related correspondence. ELLIS. J. Citizens Association for Sound Energy. 80/12/01. 28pp. 07308:001
- BO12310780 Second set of interrogatories directed to applicants & requests to produce Concerns Contention 5 re failure to adhere to GA/GC provisions. W/Certificate of Svc. Related correspondence.
 ELLIS. J. Citirens Association for Sound Energy. BO/12/01. 28pp. 07308:001.
- 8012270537 Third set of interrogatories & requests to produce to applicant Addresses Contention 5 re failure to adhere to OA/OC provisions & Contention 24 about cost/denefit balance. H/Certificate of Svc. Related correspondence. ELLIS.J. Citizens Association for Sound Energy. 80/12/04. 21pp. 07335:197.

- 8012290311 Denial of Citizens for Fair Util Regulation 800918 motion for protection Grounds not stated w/particularity & good cause not shown.

 DEALE, V. B. Atomic Safety and Licensing Board Panel. 80/12/05. 4pp. 07341:225.
- 8012270647 Answer in opposition to Citizens Association for Sound Energy 801120 motions for separate intervenor status & alternatively for appointment as lead party on consolidated contentions. LVCentificate of Svc.
 REYNOLDS N. S. , HORIN, W. A. Texas Utilities Generating Co.
 REYNOLDS, N. S. Debevoise & Liberman. 80/12/05. 6pp. 07332:333.
- S012300077 Withdrawal of motion to compel Citizens Association for Sound Energy to respond to applicants' 800801 first interrogatories. Certificate of Svc encl. REYNOLDS.N.S. HORIN.M.A. Texas Utilities Generating Co. REYNOLDS.N.S. Debevoise & Liberman. 80/12/08. 5pp. 07:356:148.
- 8012150243 Response in opposition to Citizens Association for Bound Energy 801120 motion for separate intervenor status, CABE did not demonstrate that significant projudice will result from consolidation. Certificate of Svc encl.
 TURK, S.E. Hearing Branch 1. 80/12/09. 8pp. 07297: 395.
- 801229033B Response in opposition to Citizens Association for Sound Energy (CASE) 801201 motion for protective order.Certificate of Svc enc.1.
 REYNGLOS: N. S. HORIN, W. A. Texas Utilities Generating Co.
 REYNGLOS: N. S. Debevoise & Liberman. 80/12/14. App. 07343:129.
- 8012270436 Order overruling Association of Community Organizations for Reform Now 800711 objections to applicant 800813 interrogatories, denying ACORN motion for protective order & granting extension until 810105 for ACORN to respond. UEALE, V. B. Atomic Safety and Licensing Board Panel. 80/12/19, App. 07336: 278.
- 8012300238 Advises that NRC will not respond to Citizens for Safe Energy 801201 motion for protective order re applicant interrogatory. Motion set forth in 801201 suppl to answers to applicant first set of interrogatories.

 RDTHSCHILD. M U. Operations & Administrative Division. 80/12/22.

 1p. 07358: 151.
- 8012310240 Answers to Citizens Association for Sound Energy 801204 third set of interrogatories & objection to rewording of Contention 5.0nly ASLB can determine wording. Supportive tables: affidavit & Certificate of Svc encl.

 REYNOLDS: N. S. , HORIN, W. A. Texas Utilities Generating Co.
 REYNOLDS: N. S. Debevoise & Liberman. 80/12/23. 14pp. 07362:006.
- H. General correspondence
- 8012230012 Informs that 800501 prehearing conference transcript & missing pages from 800430 transcript were transmitted to mini PDR at Univ of TX.Arlington.

 ROTHSCHILD,M.U. Operations & Administrative Division. 80/12/02. 1p. 97311:167.
- --8012230015 Forwards transcript of 800501 hearing in Fort Worth.TX for placement in LPDR.

 * Records Services % Facilities Branch. 80/11/13. 1p.
 07311:168.
- 8012290424 Responds to request for NUREO publications & other repts. NUREOs available for sale from GPO, NRC unable to locate other requested repts. ROTHSCHILD, M. U. Operations & Administrative Division. G0/12/10. 2pp. 07337: 001.
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8012190497 Forwards Amend 13 to FSAR. GARY.R.J. Texas Utilities Generating Co. 80/12/15. 2pp. 07275;301.
- --8012190493 Amend 13 to FBAR.
 * Texas Utilities Generating Co. 80/12/15. 400pp. 07275:303.
- 8012300551 Ferwards affidavit of svc of copies of Amend 13 to conversion program sys environ statement FBAR. BCHMIDT, H. C. Teras Utilities Generating Co. 80/12/22. 5pp. 07346:256.

M. Antitrust correspondence

- 8012310258 Notification of contract ejecution. Mod 2 to "Economic Assistance Re Antitrust & Commanche Peak Antitrust Proceedings." Contractor Transcomm, Inc. HAIRSTUN.C. A., GLAGOLA: A.F. Technical Assistance Contracts Branch. FIN E-6573. 89/11/10. 1p. 07370:033.
- ~-8012310262 Mod 2: extending period of performance, to "Economic Assistance Re Antitrust & Commanche Peak Antitrust Proceedings." LERHER, N. C. Transcomm, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN 8-6573. 80/11/10. 1p. 07370:034.
- 8012030458 Request to withdraw 800731 petition to intervene due to agreement reached w/Central & South West Corp re proposed dc ties. Certificate of Svc encl.

 0°N8114, R. A. Texas Border Cooperatives. 80/11/24. 6pp. 07149:347.
- B01210G039 Notice of appearance on behalf of Central & South West Corp. Central Power & Light Co.PSC of CM. Southwestern Electric Power Co & West TX Utils Co. Certificate of Svc encl. THORNTON.P. Isham, Lincoln & Beale. THORNTON.P. Central & South West Corp. THORNTON.P. Carolina Power & Light Co. B0/11/26. 5pp. 07219:067.
- 8012300318 Hemorandum in support of 800915 proposed settlement license conditions & response to Public Utils Board of City of Brownsville 801112 opposing comments, Certificate of Svc enc. 80UKNIGHT. J. A. Houston Lighting & Power Co. SOUKNIGHT, J. A. Baker & Botts, 80/12/01, 22pp. 07357:097.
- 8012170672 Response to Public Utils Board of Brownsville 801112 comments on proposed license conditions & statement pursuant to ASLB 801024 requests at prehearing conference. Cartificate of Svc encl.
 KNOTTS.J.B., AMEARN.C.D. Texas Utilities Generating Co. KNOTTS.J.B., Debevoise & Liberman. 80/12/03. 59pp. 07264:063.
- 8012300013 Comments on & request for approval of encl settlement license conditions. CHANANIA-F.D., BLUME, M.B. Antitrust Division. LEWIS, S.H. Hearing Branch 2. 80/12/03. 65pp. 07351:301.
- --8012300024 Forwards executed stipulation re license conditions. BALGUGH.R C. Austin. TX 80/09/26. ip. 07352:004.
- --8012300030 Order granting attached licenses commitments, agreed to by util,000 & NRC.
 TUBNIDY,J.F., HALL,G.R., FARMAKIDES,J.B. Atomic Safety and Licensing Board Panel. 74/05/24. 21pp. 07352;015.
- --B012300040 Request for order directing licenses be amended per attached conditions.DOJ & util join in motion.Order would terminate NRC prosecutorial role but NRC would remain as party. Certificate of Sec encl.

 VDGLFR.B.H. Atomic Energy Commission. LECKIE.D.A., LEVIN.B.H. Justice, Dept. of. 74/05/13. 9pp. 07352:034.
- 801230025 Response to intervenor Public Utils Board of City of Brownsville.TX apposition to proposed settlement license conditions. Central antitrust issues are adequately addressed in license conditions.ASLB should approve conditions.

 STAHL, D. M. Central & South West Corp. STAHL, D. M. Isham, Lincoln & Beale. 80/12/03. 14pp. 07357:009.
- --8012300227 Supplemental response, submitted to FERC, on DOJ 800917 petition to intervene DOJ position is irrelevant to approval of supplemental offer of settlement & should be dented w/o prejudice, Supporting info & Certificate of Svc encl. STAML.D.K. Central & South Nest Corp. STAML.D.M. Isham, Lincoln & Reale. 80/11/25. 23pp. 07357:025.
- 8012300250 Response to intervenor Public Utils Board of City of Brownsville 801112 opposition to proposed settlement license conditions. Conditions are in public interest. Imposition will not damage intervenor. Certificate of Svc encl. FABRIKANT, R. MCMILLEN, N. M. DOPSOVIC, D. A. Justice, Dept. of. 80/12/03. 24pp. 07358:086.
- 8012230222 Order granting TX Border Cooperatives 801124 petition for leave to uithdraw 800731 petition to intervene. MILLER.K.E. Atomic Safety and Licensing Board Panel. 80/12/04. 2pp. 07317:079.
- 8012290163 Corrects typographical error in Certificate of Syc.encl to 801203 memorandum in support of proposed settlement license canditions. Date of syc should be 801203. N/Certificate of Syc. GREEN. D. G. Houston Lighting & Power Co. 80/12/04. Spp. 07344: 144.

- B012309251 Joint motion to make corrections to B00915 proposed settlement license conditions Also moves for leave to file encl conformed proposed license conditions Certificate of Svc encl.

 CHARANIA F D Antitrust Division + Justice Dept. of. * Texas Utilities Generating Co. 80/12/22. 20pp. 07359:110.
- 8012300469 Order granting leave to file 801222 conformed settlement license conditions & adopting corrections to 800915 proposed license conditions License conditions encl MILLER, M.E. Atomic Safety and Licensing Board Panel. 80/12/24. 17pp. 07397:210
- Q. Inspection reports, IE Bulletins & correspondence
- 8012170744 Forwards IE Circular 80-21, "Regulation of Refuciing Crews," No written response required SEYFRIF.K V. Region 4. Dallas, Office of the Director. 80/09/10. 1p. 07254:168.
- 8012030/98 Responds to 1E Bulletin 79-03A: "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe." Etching ends of all safety-related SA-312 Type 300 sories fusion welded pipe completed GARY.R.J. Texas Utilities Generating Co. 80/10/07. 1p. 07149:270.
- 8012020/39 Forwards 1E Insp Repts 50-445/80-24 & 50-446/80-24 on 801005-10. No noncompliance noted SEIDLE-M C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/10/24. 2pp 07143:168.
- --8012020749 1E Insp Repts 50-445/60-24 & 50-445/80-24 on 801006-10. No noncompliance noted fisjon areas inspected; safety-related const activities pertaining to installation of electrical cables.

 MARTIN-L.E. CROSSMALLE A. Region 4. Dallas. Office of the Director. JGRNSON, A.R. Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/10/22 3pp. 07143:170.
- 8012170360 Forwards 1E Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. SEYFRIT.A.V. Region 4. Dallas, Office of the Director. 80/10/30. 1p. 07259:025.
- 8012170822 Forwards 1E Info Notice 80-39, "Malfunction of Solenoid Valves Rfg by Valcor Engineering Corp." No written response is required.
 SEFFRITE V. Region 4. Dallas, Office of the Director. B0/10/31.
 1p. 07266:017.
- 8012100544 Act receipt of 801020 ltr informing NRC of steps taken to Eorrect violation nated in IE. Insp. Repts 50-445/80-20 & 50-445/80-20. SEIDLENG. Region 4. Pallat, Reactor Construction & Engineering Support Brench 80/11/05. ip 07218.140.
- --8012100550 Responds to NRC 803924 ltr re violations noted in IE Insp. Repts 50-445/80-20 & fo-446/80-20. Corrective actions, OA personnel will perform improcess & release insp. of future shipments from supplier.

 OARY, R. J. Texas Utilities Generating Co. 80/10/20, 3pp. 07218:141.
- B012100606 Forwards IE Bulletin 80-21, "Valve Yotes Supplied by Malcolo Foundry Co. Inc." Written response required. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 80/11/06. ip. 07220:109.
- 8012030377 Forwards IE Info Notice 60-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Causa Reactor Depressurization " No written response required. SEYFRIT.K.V. Region 4. Pallas, Office of the Director. 80/11/07. lp. 07150:155.
- 8012080584 Forwards IE Info Motice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Squ at Davis Besse Unit 1," No response required.
 SEVERITY.K.V. Region 4, Dallas, Office of the Director. 80/11/10.
 1p. 07183:008.
- 8012180349 Forwards IE Mgt Meeting Repts 50-445/80-25 & 50-446/80-25 on 801030 No concompliance noted. SEIDLEIM.C. Region 4, Pailar, Reactor Construction & Engineering Support Branch. 60/11/12 2pp 03794; 213.
- --8012180372 IE Myt Meeting Repts 50-445/60-25 & 50-446/80-25 on 801030. Major area discussed systematic assessment of licensee performance. SEYFRIT.K.V., CROSSMAN.W.A. Region 4. Dallas, Office of the Director. SEIDLE.W.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/11/12 (1pg. 03794:215.

- 0125 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves by Valcor Engineering Corp." Requires estimate of ouer associated uncorrective actions RITIK.V. Region 4. Dallas. Office of the Director. 80/11/14. 07158-045
- 0411 Requests info resulting from review of application rervice imap of pressure isolation valves. Requests list of sure isolation valves included in testing program U/four of piping (instrumentation diagrams, SCO.R.L. Assistant Director for Licensing, 80/11/17. 2pp.
- CO11 Forwards IE Bulletin 80-24, 'Prevention of Damage Due to a Leakage Inside Containment." No written response ired.
 RII.K V. Region 4. Dallas, Office of the Director. 80/11/21.
 G7173-055.
- 2071 Forwards IE Info Notice 80-42. "Effect of Radiation on sulic Shubber Fluid." No response required. PIL.K.V. Region 4. Dallas. Office of the Director. 80/11/24. 07262:135.
- DitS Forwards Suppl 1 to 1E info Notice 80-27, "Broken Studs on a Turbine Steam Inlet Flange," No unitten response ired.
 Region 4: Daliss: Office of the Director. 80/11/26.
- 1931 Informs that reactor coplant isolation valve inservice insportants will be addressed in facility inservice insportant Intervice insportant being developed & will be addressed in solution of the connection operation. R. J. Texas Utilivies Generating Co. 80/12/08. 1p. 07263:073.
- intable occurrences, LERs ψ related correspondence
- 1245 Deficiency rept.superseoing BCO421 submittal, re installation illed—in expension anchors, initially reported on 17. Installation procedure was revised to reflect min ng requirements between various anchor types.

 R. J. Tevas Utilities Generating Co. 80/12/10, 2pp. 1259
- ri69 Interim deficiency sept re-violation of piping min-wall ness.Engineering review & disposition of min-wall ritions at welds continuing.Next progress rept to be tited by 810615 R.J. Teras Utilities Generating Co. 80/12/16. ip 07343:341.
- 50-446 COMANCHE PEAK STEAM ELECTRIC STA .UNIT 2 ication/construction stage documents & correspondence
- 1017 Forwards request for add1 info required to complete RRC ration of application for operating licenses for ities. Response should be submitted within 6 wks. 100.R L. Assistant Director for Licensing. B0/11/20. 25pp. 2:058
- 1197 Discusses NRC review schedular requirements for special low-test program & energency procedures Provides list of times to be met in order to complete evaluations in motion w/power ascension program schedule.
 120.R.L. Assistant Director for Licensing. 80/11/20. 2pp. 1:217.
- MAG Discusses NRC requirements for organizational structure & resources FSAR arena reflecting recent organizational es should be submitted by 810116 due to projected but for issuance of SER (CO.R.C. Assistant Director for Licensing, 80/11/20, 3pp.
- ©30 Forwards Revision 1 of Table 1.providing scheduled entation submittal dates to NRC for equipment fitation data packages included in vendor equipment fitation program Table 2 is a facility equipment encl. 50% TM Westinghouse Electric Corp. 80/f1/26. 6pp. 270.

- 8012300536 Responds to 801114 ltr requesting add1 clarifications environ review. Commercial firm will remove sludge to disposal area. Dead fish were removed from travelling screens as screens were rotated once every 8-h. GARY.R. J. Texas Utilities Generating Co. 80/12/22. 3pp 07366:271.
- C Utility Environmental Report (ER), amends & correspondence
- B012300338 Forwards Amend 2 to environ rept.

 GARY, R. J. Texas Utilities Co. 80/12/22. 2pp. 07359: 009
- --8012300344 Amend 2 to environ rept.

 * Texas Utilities Co. 80/12/22 16pp. 07350:007
- F. Security, medical, emergency k fire protection plans
- 8012140199 Notifies that util 800818 safeguards contingency plan is acceptable. Sample licensing condition encl. TEDESCO.R. L. Assistant Director for Licensing. 80/11/26 $-3\sigma\sigma$ 07242:310.
- 8012310038 Forwards response to NRC comments re interin physical security plan. Encl withheld (ref 10CFR2 790). GARY.R.J. Fexas Utilities Generating Co. 80/12/23. 3pp 07369: 272.
- G. Adjudicatory correspondence
- 8012290529 Informs of ASLA3 801124 memorandum & order dismissing eases filed by Citizens for Fair Util Regulation intervenor in facility OL proceeding. Intervenor sought to appeal rejection of one contention.

 SHAPAR.M.K. Office of the Executive Legal Director. 80/11/25 607335:181.
- B01207034) Forwards original verification for B01201 suppl to answers to applicants' first set of interrogatories & requests to produce re util application for Obs.Wo encl. Et.LIS.J. Citizens Association for Sound Energy. B0/12/01 Ept. 07179: 347.
- 8012270318 Suppl to Citizens Association for Sound Energy answer to applicants' first set of interrogatories & requests to produce. Datails info nelled upon for Contention 5 re IE insp repts. Certificate of Svc encl. Related correspondence. ELLIS. J. Citizens Association for Sound Energy. 80/12/01 2Hgs 07308:001.
- 8012310P80 Second set of interrogatories directed to applicants & requests to produce. Concerns Contention 5 re failure to adhere to GA/QC provisions. W/Certificate of Svc. Related correspondence.

 ELLIS. J. Citizens Association for Sound Energy. 80/12/01 2000
- 8012270337 Third set of interrogatories & requests to produce to applicant. Addresses Contention 5 re failure to adhere to OA/GC provisions & Contention 24 about cost/benefit balance W/Certificate of Svc. Related correspondence. ELLIS. J. Citizens Association for Bound Energy. BO/12/04. 21st 07335:197.
- 8012290311 Denial of Citizens for Fair Util Regulation 800918 mutized for protection. Grounds not stated departicularity & good cause not shown.

 DEALERY, B. Atomic Safety and Licensing Board Panel. 80/12/68 ****

 07341:225.
- 8012290647 Answer in opposition to Citizens Association for Equad Energy 801120 motions for separate intervenor status & alternatively for appointment as lead party on consolidated contentions, M/Zertificate of Svc.
 REYNOLDS.R.S. HORIN.W.A. Teras Utilities Generating Co.
 REYNOLDS.R.S. BORINGER Liberman. 80/12/05. App. 07332 233
- 8012300057 Nithdrawal of mntion to compel Citizens Association for Bound Energy to respond to applicants' B00801 first interrogatories. Certificate of Svc encl.

 REYNCLOS.N.S., HORIN.W.A. Texas Utilities Generating Co.

 REYNCLOS.N.S. Debevoise & Liberman. 80/12/98. Spp. 07356 168
- 8012150243 Response in opposition to Citizens Association for Square Energy 801120 motion for separate intervanor status. CASE did not demonstrate that significant projudice will result from consolidation. Certificate of Syc encl.

 TURK-S.E. Hearing Branch 1. 80/12/09. 8pp. 07237:335.

- 8012290338 Response in opposition to Citizens Association for Sound Energy (CASE) 801201 motion for protective order Certificate of Svc encl.
 REYNOLDS: N.S. HORIN. N.A. Texas Utilities Generating Co.
 REYNOLDS: N.S. Debevoise & Liberman. 80/12/16. 6pp. 07343:129.
- 8012270436 Order overruling Association of Community Organizations for Reform Now 800911 objections to applicant 800813 interrogatories, denying ACDRN motion for protective order & granting extension until 810105 for ACDRN to respond. DEALE, V.B. Atomic Safety and Licensing Board Panel. 80/12/19. App. 07336:278.
- 8012300258 Advises that NRC will not respond to Citizens for Safe Energy 801201 motion for protective order re applicant interrogatory. Motion set forth in 801201 suppl to answers to applicant first set of interrogatories. ROTHSCHILD.H.U. Operations & Administrative Division. 80/12/22. 1p. 07358:151.
- 8012310290 Answers to Citizens Association for Sound Energy 801204 third set of interrogatories & objection to rewording of Contention 5.0nly ASLB can determine wording. Supportive tables affidavit & Certificate of Svc encl.
 REYNOLOG.N.S., HORIN.M.A. Teras Utilities Generating Co., REYNOLOG.N.S., Debevoise & Liberman. 80/12/23, 14pp. 07362:006.

H. General correspondence

- 8012230012 Informs that 800501 prehearing conference transcript & missing pages from 800430 transcript were transmitted to mini PDR at Univ of TX.Arlington.
 ROTHBCHILD,M.U. Operations & Administrative Division. 80/12/02.
- --8012230015 Forwards transcript of 800501 hearing in Fort Worth,TX for placement in LPDR. + Records Services & Facilities Branch. 80/11/13. 1p. 07311:168
- 8012270424 Responds to request for NUREG publications & other repts. NUREGs available for sale from GPO.NRC unable to locate other requested repts. ROTHSCHILD.M.U. Operations & Administrative Division. 80/12/10. 2pp. 07337:001.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- BO12190487 Forwards Amend 13 to FSAR. GARY.R.J. Texas Utilities Generating Co. 80/12/15. 2pp. 07275:301.
- --8012190493 Amend 13 to FSAR.
 * Texas Utilities Generating Co. 80/12/15. 400pp. 07275:303.
- 8012300551 Forwards affidavit of svc of copies of Amend 13 to conversion program sys environ statement FSAR. SCHMIOT.H.C. Texas Utilities Generating Co. 80/12/22, 5pp. 07346:235.

M. Antitrust correspondence

- 8012310258 Notification of contract execution.Mod 2 to "Economic Assistance Re Antitrust & Commanche Peak Antitrust Proceedings." Contractor: Transcomm. Inc. HAIRSTON.C.A., GLAGOLA.A.F. Technical Assistance Contracts Branch. FIN 8-6593. 80/11/10. 1p. 07370:033.
- --8012319262 Mod 2.extending period of performance to "Economic Assistance Re Antitrust & Commanche Peak Antitrust Proceedings." LERKER, U.C. Transcomm. Inc. BOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN 8-6573. 80/11/10, 1p. 07370:034.
- 8012030458 Request to withdraw 800731 petition to intervene due to agreement reached w/Central & South West Corp re proposed dc tites. Certificate of Svc encl.

 O'NEIL.R A. Texas Border Cooperatives. 80/11/24. 4pp. 07149:347.
- 8012100037 Notice of appearance on behalf of Central & South West Corp. Central Power & Light Co.PSC of CX.Southwestern Electric Power Co & West TX Utils Co.Certificate of Svc encl. THORNTON.P. Isham. Lincoln & Beale. THORNTON.P. Central & South West Corp. THORNTON.P. Carolina Power & Light Co. 60/11/26. Spp. 07219:067.

- 8012300318 Nomerandum in support of 800915 proposed settlement license conditions & response to Public Utils Board of City of Brownsville 801112 apposing comments Certificate of Syc enc. BOURNIGHT, J. A. Houston Lighting & Power Co. BOURNIGHT, J. A. Baker & Botts. 80/12/01. 22pp 07257:097
- 8012170572 Response to Public Utils Board of Brownsville 801112 comments on proposed liberal conditions b statement pursuant to ASL3 801024 requests at prehearing conference. Certificate of Skc encil RNDTTS-J.B., AHEARN-C D. Texas Vtilities Generating Co. KNDTTS-J.B. Debevoise & Liberman. 80/12/03. 59pp 07264:063.
- B012300013 Comments on & request for approval of encl settlement license conditions. CHANANIA.F.D., BLUKE.M 3 Antitrust Division. LEUIS.S.H. Hearing Branch 2. B0/12/03. 45pp. 07351:331.
- 8012300R25 Response to inhervenor Public Utils Board of City of Brownsville, TX opposition to proposed settlement license conditions. Central antitrost issues are adoquately addressed in license conditions. ASLB should approve conditions. STAHL, D.M. Central & Seuth Nest Corp. STAHL, D.M. Jsham, Lincoln & Beals. 80/12/03. 16pp. 07397:009.
- --8012300227 Supplemental response submitted to FERC, on BOJ 800917 petition to intervene DOJ position is irrelevant to approval of supplemental offer of settlement & should be denied w/o prejudice. Supporting info & Certificate of Svc encl. STAPL. D. M. Central & South West Corp. STAPL. D. M. Isham, Lincoln & Beale. 80/11/25. 23pp. 07397:025.
- 8012300250 Response to intervenor Public Utils Board of City of Brownsville 801112 apposition to proposed settlement license conditions. Conditions are in public interest Imposition will not Janage intervenor Certificate of Svc encl. FABRIMANT.R., MCMILLEN.M.M., DOPSOVIC.O.A. Justice, Dept. of. 80/12/03. 24pp. 07398:086
- 8012230222 Order granting TX Border Cooperatives 801124 potition for leave to withdraw 800731 potition to intervene. MILLER-M.E. Atomic Safety and Licensing Board Panel. 80/12/04. 2pp. 07317:079.
- 8012290163 Corrects typographical error in Cortificate of Svc, encl to 801203 memorandum in support of proposed settlement license conditions. Date of svc should be 801203. W/Certificate of Svc. GREEN D.G. Hauston Lighting & Power Co. 80/12/04 5pp. 07344:144.
- 8012300251 Joint motion to make corrections to 800915 proposed settlement license conditions Also moves for leave to file encl conformed proposed license conditions. Certificate of Svc ancl.
 CHANANIA.F.D. Antitrust Division. 4 Justice. Dept. of. * Texas Utilities Generating Co. 80/12/22. 20pp. 07358:110.
- 8012300469 Order granting leave to file 801222 conformed settlement license conditions & adopting corrections to 800715 proposed license conditions License conditions encl. MILLERIME. Atomic Safety and Licensing Board Panel. 80/12/24. 17pp. 07357.210.
- Q. Inspection reports, 18 Sulletins & correspondence
- 80)2170744 Forwards IR Circular 80-21, "Regulation of Refueling Crews." No written response required. SEYPRIT.X.V. Region 4: Dallas: Office of the Director. 80/09/10. 1p. 07264:168
- 8012030798 Responds to IF Bulletin 79-03A. "Longitudinal Weld Defects in ASMF SA-312. Type 304 Stainless Steel Pipe." Etching ends of all safety-related 64-312 Type 303 series fusion welded pipe campleted. GARY.R. J. Teras Utilities Generating Co. 80/10/07. 1p. 07149:270.
- 8012020739 Farwards IE Irsp Repts 50-445/80-24 % 50-446/80-24 on 801006-10. No noncompliance noted. SEIDLE.N.C. Region 4. Dallas. Reactor Construction & Engineering Support Branch. 80/10/24. 2pp. 07143:168.
- --8012020749 IE Insp Repts 50-445/80-24 & 50-446/80-24 on 801006-10.No noncoapliance noted. Major areas inspected; safety-related const activities pertaining to installation of electrical cables.

 MARTHULE, CROSSMARN N. A. Region 4, Dallas, Office of the Director. JOHNSON A. R. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/10/22 3pp. 07143:170.

- B012170250 Forwards IR Info Natice 80-28. *Gracking in Charging Pump Casing Cladding " No written response required. SEYPRITA V Region 4, Gallas. Office of the Director. B0/10/30. 1p 07269:025
- 8012170822 Forward: IE Info Natice 80-39, "Malfunction of Solenoid Valves Rfg by Valvor Engineering Cosp." No written response is required. SEYERIT.K V. Region 4. Dallas. Office of the Director. 80/10/31. ip. 07265-017
- B012100544 Act receipt of B01020 Itr informing NRC of steps taken to correct violation noted in 16 Insp Repts 50-445/B0-20 & 50-446/B0-20 Region 4. Dallas. Reactor Construction & Engineering Support Branch B0/11/05 ip 07218,140.
- --8012400550 Perponds to NRC 800924 lin re violations noted in IE Insp. Repts 50-445/80-20 / 50-446/80-20 Corrective actions: QA personnel will perform improcess & release insp. of future shipments from supplier GARY-R. J. Texas Utilities Generating Co. 80/10/20. 3pp. 07218:141
- 8012100506 Forwards IE Bulletin BO-21. "Valve Yokes Supplied by Malcale Foundry Co.Inc." Written response required. BEYFRIT,K V. Region 4. Dallss. Office of the Director. BO/11/06. 1p. 07220:105.
- B012030897 Forwards IE Info Motice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. SEYFRIT.K.V. Region 4. Dellas. Office of the Director. B0/11/07. to. 07150:155.
- B012080534 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal By: at Davis Besse Unit 1." No response required SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/10. 1p. 07183:008
- 8012180359 Forwards IE Mgt Meeting Repts 50-445/80-25 & 50-446/80-25 on 801030, No contempliance noted SEIDLE-M.C. Region 4, Pallas Reactor Construction & Engineering Support Branch. 80/11/12. 2pp 03794:213
- --B012160372 IE Mgt Meeting Repts 50-445/80-25 & 50-446/80-25 on B01030.
 Major area discussed systematic assessment of licensee performance.
 SEYFRIT.M.V. CROSSMANGRA. Region 4. Dallas. Office of the Director. SEIDLE.W C. Region 4. Dallas. Reactor Construction & Engineering Support Branch. B0/11/12. https://doi.org/10.03794:215.
- 8012040125 Forwards IE Sviletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 SEYFRIT.X. V. Region 4. Dallas, Office of the Director. 80/11/14, 1p. 07158:046.
- 8012050411 Requests info resulting from review of application reinservice insplot pressure isolation valves. Requests list of pressure isolation valves included in testing program uffoursets of piping & instrucentation diagrams. TEDESCO.R. L. Assistant Director for Licensing. 80/11/17. 2pp. 07125:304.
- 8012050011 Forwards IR Byllatin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 SEYFRILA V. Region, 4. Dallas. Office of the Director. 80/11/21.

 1p. 07173-055.
- B012160071 Forward: IE Info Notice 80-42. "Effect of Radiation on Mydraulic Snubber Fluis." No response required. SEffRIT.R.V. Region 4. Dallas. Office of the Directors B0/11/24. 1p. 07262:136.
- 80(2160115 Forwards Suppl 1 to 1E linfo Notice 80~27, "Broken Stude on Verry Turbine Steam Inlet Flange" No written response required. SEYPRITUS V. Region 4. Dailss. Office of the Director. 80/11/26. tp. 07262.035.
- 8012160531 Informs that reactor coolant isolation valve inservice inspecu(if the solution of t

- S. Reportable occurrences. LERs & related correspondence
- 8012180245 Deficiency rept, superseding 800421 submittal, re installation, of drilled-in expansion anchors, initially reported on 791107. Installation procedure was revised to reflect min spacing requirements between various anchor types. GARY, R. J. Tolas Utilities Generating Co. 80/12/10. 2pp. 07272:353.
- 8012290169 Interim deficiency rept re violation of piping min wall thickness. Engineering review & disposition of min wall violations at welds continuing. Next progress rept to be submitted by 810419.

 GARY.R.J. Texas Utilities Generating Co. 80/12/16. 1p. 07343:361.
- DOCKET STN-50-447 GESSAR-238 B. Utility Preliminary Safety Analysis Report, amends
- 8012150075 Forwards Amend 1 to GESSAR II. SHERWOOD, G. G. General Electric Co. 80/12/02. 3pp. 07241:305.
- --B012150094 Amend 1 to GESSAR-TI.
 * General Electric Co. 80/12/02. 625pp. 07241:308.
- B012170444 Forwards proprietary info for review of 23B Nuclear Island GESSAR-II. Info part of Amend 1, responding to NRC 800722 questions re safety reliaf valve actuation methodology. Affidavits encl. Rept withheld (ref 10CFR2, 790). SHER(100D, O. G. General Electric Co 80/12/02. 5pp. 07269;143.
- DOCKET 50-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1
 G. Adjudicatory correspondence
- B012310216 Motion for withdrawal of CP applications. Certificate of Svc encl.

 DLAKE-E.L. Potomac Electric Power Co. BLAKE-E.L. Shaw, Pittman, Potts & Troubridge. 80/12/24. 3pp. 07369:286.
- DOCKE: 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2-G. Adjudicatory correspondence
- 8012316216 Motion for withdrawal of CP applications. Certificate of Svc encl.
 BLAKE.E.L. Potomac Electric Power Co. BLAKE.E.L. Shaw, Pittman. Potts & Trowbridge. 80/12/24. 3pp. 07369:286.
- DECKET 90-450 SUMMIT NUCLEAR POWER STATION, UNIT 1
 G. Adjusticatory correspondence
- 80:2070263 Forwards motion withdrawing application for permit to construct twin HTGR units & terminating CP proceedings. IRWIN-D.P. Hunton & Hilliams. 80/12/05. 2pp. 07201:136.
- --8012090265 Motion to withdraw application for CP & to terminate permit proceedings.
 IRMIN.D.P. Delmarva Power & Light Co. IRWIN.D.P. Hunton & Williams. 80/12/05. 2pp. 07201:138.
- 6012230058 Motion to withdraw CP application & terminate proceedings. Certificate of Svc encl. IRWIN.D.P. Delmarva Power & Light Co. IRWIN.D.P. Hunton & Williams. 80/12/05. 4pp. 07313:228,
- 8012300134 URC staff response to motion to withdraw application & terminate proceeding. Determination on applicant motion should be held in abeyance until NRC has evaluated precise condition of site Centificate of Evc encl.

 KARMANAN. Hearing Branch 2. 80/12/17. 3pp. 07347:172.
- DOCKEI 50-451 SUMMIT NUCLEAR POWER STATION, UNIT 2

 O. Adjudicatory correspondence
- 8012070263 Forwards motion withdrawing application for permit to construct twin HTGR units & terminating CP proceedings. IRWIN.D.P. Hunton & Williams. 80/12/05. 2pp. 07201;136.

- -80:2070265 Motion to withdraw application for CP & to terminate permit Proceedings.

 ERMIN.D.P. Delmarva Power & Light Co. IRMIN.D.P. Hunton & Williams. 80/12/05. 2pp 07201:138.
- 8012230058 Motion to with draw CP application & terminate proceedings.
 Certificate of Svc encl.
 IRNIN.D.P. Delmarva Power & Light Co. IRNIN.D.P. Hunton &
 Williams. 80/12/05. 4pp 07313:228
- 8012300134 NRC staff response to motion to withdraw application & terminate proceeding. Determination on applicant motion should be held in abeyance until NRC has evaluated precise condition of site. Certificate of Svc encl KARHANIM. Hearing Branch 2. 80/12/17. 3pp. 07347:192.
- DOCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2
- A. Application/construction stage documents & correspondence
- 8012240778 Ack receipt of NPC 801110 itr & invoice for alleged cost in reviews of withdrawn applications. Util will not pay until rulemaking to amend 10CFR170 is complete & legality of collacting invoiced amount is resolved.

 JENS.W. H. Detroit Edison Co. 80/12/12. 2pp. 07324:342
- DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3
- A. Application/construction stage documents & correspondence
- 801224027B Ack receipt of NRC 801110 ltr & invoice for alleged cost in reviews of withdrawn applications. Util will not pay until rulemaking to amend 100FR170 is complete & legality of collecting invoiced amount is resolved.

 JENS.W.H. Detroit Edison Co. 80/12/12. 2pp. 07324:342.
- DOCKET 50-454 BYRON STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8012160950 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREG-0737 re TM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be not EISENHUT, D. G. Division of Licensing. 80/10/31. 7pp.
- 8012010051 Confirms 801020 plans for H01125 meeting in Chicago. IL to discuss MRC evaluation of regulatory performance. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/18. 1p. 97078: 190.
- 8012010084 Informs NRC of intentions to use ASME Code Case N-275, "Repair of Welds Section III, Div 1," to utilize alternate rules for examination of areas prepared for repair of uelds. Requests notice of acceptability of encl code case. TRAMM.T.R. Commonwealth Edison Co. 80/11/18. 2pp. 07098:206.
- 8012030448 Informs of intent to use ASME Code Case N-275, "Repair of Walds, Section III, Div 1." approved 800515, for utilization of alternate rules for examination prepared for repair of welds. Requests acknowledgement of acceptability.
 TRAMM, T. R. Commonwealth Edison Co. 80/11/18 2pp. 07183:053.
- 8012010381 Confirms 801017 plans for 801120 meeting in Olen Ellyn, IL to discuss util evaluation of design/engineering organizations & functions re significant const rework at facilities.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/19, 1p. 07098:104.
- 8012020301 Forwards tabulation of planned environ qualification testing programs, in response to NRC 801301 ltr.
 ABEL. J. S. Communuealth Edison Co 80/11/26, 4pp.
- 8012190304 Approves 801118 request for authorization to use ABME Code Case R-275, Use should be documented in FBAR. YOUNO91000 B. J. Licensing Branch 1. 80/12/09. 2pp. 03795:185.
- 8012290398 Informs that meeting held to discuss util evaluation of design/engineering organization & functions proved effective in defining scope & explaining results of util evaluation. FIGRELIT, 0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/08 2pp. 07345:348.

- O. Inspection reports. 15 Sulletins & correspondence
- B012170510 Forwards IE Info Notice 80-37, 'Containment Cooler Leaks & Reactor Covity Flooding at Indian Point Unit 2 * No written response required KEPPLER, J. C. Region 3, Chakago, Office of the Director. 80/10/24.
- 8012080027 Forwards IE Insp. Repts 50-454/80-19 & 50-455/80-18 on 800910-12 & 30. No noncompliance noted. FIBRELLI.G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80710/30 2pp. 67179: 396.
- -8012080035 IE Insh Repts 50-454/80-19 & 50-455/80-18 on 800910-12 & 30 No noncompliance noted that are as inspected status of previously noted unresolved items status of action & resolution & documentation of items reported per 10CFR50.55.
 JONES.C. E. MILLIAMS G. C. Region 3, Chicago, Office of the Director. 80/10/29. 5pp 07175:358. JONES, C. E. / NILLIAMA B3/10/29
- 8012080279 Forwards IE Insp Repts 50-454/80-20 & 50-455/80-19 on 801007-07. No honcompliance noted. FIORELLI.O. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/10/30 2pp. 07186-253.
- --B012080285 IE lnsp Repts 50-454/80-20 & 56-455/80-19, on B01007-09. No noncompliance noted Major areas inspected steam generator mods, hardware, safety-related components, fabrication & flux tote instrumentation.

 ERB.C.M. Region 3, Chicago, Office of the Director.

 DANTELSON, D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch, 60/10/28 4pp. 07186:235.
- B012190242 Forwards IE losp Repts 50-454/80-21 & 50-455/80-20 on B01022-24. No noncompliance noted. FIGREULI, 9. Region 3, Chicago, Reactor Construction & Engineering Support Branch. B0/11/13 | 2pp | 07282-125.
- ---8012190267 IE Insp Repts 50-454/80-21 & 50-459/80-20 on 801022-24. No noncompliance nuted, Major areas inspected: status of post-tensioning work & mfg of button heads.
 JUNES.C.E., WILLIAMS.C.C. Region 3, Chicago, Office of the Director. 80/11/13. 3pp 07282-127.
- 8012020/43 Forwards three Performance Appraisal Branch inspirepts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & mate appropriate adjustments. 11/0 encl.
 KEPPLER. J. G. Region 3. Chicago. Office of the Director. 80/11/18. 4pp.
- 8612040537 Forwards 16. 8.311atsn 86-24, "Prevention of Damage Due to Nater Leakage Inside Containment." No written response required. KEPPLER, J. G. Region 3: Chicago: Office of the Director. 80/11/21. 2pp. 07165: 335.
- 8012080987 Forwards IE Info Notice 80-42, "Effect of Radiation on Mydraulic Snubber Fluid." No written response required. KEPPLER. J. G. Region 3, Chicago. Office of the Director. 80/11/24.
- 8012170552 Forwards IE Info Notice 80-27.Suppl 1, "Broken Studs on Tarry Turbine Steam Inlet Flange," No written response required. KEPPLER.J. G. Region 3, Chicago, Office of the Director. 80/11/26.
- 8012160520 Ack receipt of 801113 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/80-18 & 50-455/80-17.
 DAVIG.A.B., Region 2, Chicago, Fuel Facility & Materials Safety Branch. B0/11/28.
- --8012160529 Forwards response to NRC 801016 ltm re violations noted in IE Insp Repts 50-454/80-18 ½ 50-455/80-17. Corrective actions: eroded area graded ½ proper use of daily const checklists reinstituted. ABEL.J. 6. Commonwealth Edison Co. 60/11/13. 3pp. 07261:188.
- S. Reportable occurrences, LERs & related correspondence
- 8012100482 Interim deficiency rept initially reported on 801104 re Westinghouse Electro-Mechanical Div mfg 3-inch gate valves. Model 30M88 failing to close under preoperational test conditions. Westinghouse developing generic solution. TRAMM-T.R. Commonwealth Edisan Co. 80/12/02 2pp. 07220:044.

- BOCKF: 50-495 STROM STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.QL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Enci 1 implementation dates will be ret. EISED9UT.D.C. Division of Licensing 80/10/31. 7pp.
- 8012010084 Informs NRC of intentions to use ASME Code Case N-275, "Repair of Welds, Section III. Div 1," to utilize alternate rules for examination of areas prepared for repair of welds. Requests notice of acceptability of enci code case. IRAMIN T. R. Commonwealth Editon Co. 60/11/18. 2pp. 07098; 206.
- 2012030448 Informs of intent to use ASSE Code Case N-275, "Repair of Nelds, Section III, Biv 1," approved 800515, for utilization of alternate rules for examination prepared for repair of welds. Requests acknowledgement of acceptability.

 IRAMMATER Commonwealth Edison Co. 80/11/18. 2pp. 07183:053.
- 8012010591 Confirms S01017 plans for B01120 meeting in Olen Ellyn, IL to discuss util evaluation of design/engineering organizations 2 functions re significant const rework at facilities KEPPLER. J. G. Region 3. Chicago, Office of the Director. B0/11/19. 10.
- 8012020301 Forwards tabulation of planned environ qualification testing programs, in response to NRC 601601 ltr.
 ABELLUS. Commonwealth Edison Co. 80/11/26. 4pp.
- 8012196>04 Approves 801118 request for authorization to use ASME Code Case N-275.Use should be documented in FSAR. YOUNG3LGOD, B. J. Licensing Branch 1. 80/12/09. 2pp. 03795:185.
- 8012290598 Informs that meeting held to discuss util evaluation of design/engineering organization & functions proved effective in defining scope & esplaining results of util evaluation. FIGRELLI.G. Region 3. Chizago. Reactor Construction & Engineering Support Branch. 60/12/08 Epp.
- Q. Inspection reports: IE Sulletins & correspondence
- 80:21700:0 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 %EMPLER.J.O. Region 3. Chicago. Office of the Director. 80/10/24.
- 8012080027 Forwards IE Insp Repts 50-454/80-19 & 50-455/80-18 on 800910-12 & 30.No noncompliance noted. FIGRELLI.G. Region 3. Chicago. Reactor Construction & Engineering Support Branch 60/10/30 2pp 07179:356.
- --B012083035 IE Insp Rept: 50-454/80-19 & 50-455/80-18 on 800910-12 & 30. No noncompliance noted Major areas inspected status of praviously noted unresolved items, status of action & resolution & documentation of items reported per 10CFR50.55. JONES, C. E., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 80/10/27, 5pp 0/175:358.
- 6012080279 Forwards if Insp Repts 90-454/80-20 & 50-455/80-19 on 801007-09. No noncompliance noted FIGRELIA. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/10/30. 2pp. 07186:233.
- --8012080205 IE Insp Repts 50-451/80-20 & 50-455/80-19, on 801007-09, No nonconpliance noted. Major areas inspected: steam generator mode, hardware, safety-related components, fabrication & flux tube instrumentation.

 ERB. C. M. Reylon 3. Chicago, Office of the Director.

 DANIELEON, D. H. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/10/28 4pp. 07186:205.
- E012190242 Forwards IE Irsp Repts 50-454/80-21 & 50-455/80-20 on 801022-24. No noncompliance noted. FIGRELLI, G. Region 3, Chicaga, Reactor Construction & Engineering Support Branch. 60/11/13. 2pp. 07282 125.
- --8012190267 JE Insp Repts 50-454/80-21 & 50-455/80-20 on 801022-24. No nencompliance noted Major areas inspected status of post-tensioning work & mfg of button heads.
 JOURGE C.E. WILLIAMS.C.C. Region 3. Chicago. Office of the Director. 80/11/13 3pp. 07282:127.

- 8032020743 Forwards three Performance Appraisal Branch insp repts & mpt evaluation tree w/user guide so that facility can compare program to program already reviewed & rake appropriate adjustments. W/o encl.
 KEPPLER. J. G. Region 3, Chicago, Office of the Director. 80/11/18.4pp.
- 8012040537 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment: "No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21, 2ab.
- 8012080387 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Shubber Fluid." No written response required. KEPPLER.J.G. Region 3. Chicago. Office of the Director. BO/11/24. 2pp.
- 8012170552 Forwards IE Info Notice 80-29, Suppl 1, "Broien Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/26. 2up.
- 8012140520 Ack receipt of 801113 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-454/80-18 & 50-455/80-17.
 DAVIS-A.B. Region 3. Chicago, Fuel Facility & Materials Bafety Branch. BD/11/28.
- ---8012160529 Forwards response to NRC 801016 ltr re violations noted in IE Insp Repts 50-454/80-18 & 50-455/80-17. Corrective actions: eroded area graded & proper use of daily const checklists reinstituted.
 ABEL.J.S. Commonwealth Edison Co. 80/11/13. 3pp. 07261:188.
- S. Reportable occurrences, LERs & related correspondence
- 8012100482 Intertm deficiency rept initially reported on 801106 re Hestinghouse Electro-Mechanical Div mfg 3-inch gate valves. Model 30M28 failing to close under preoperational test conditions. Hestinghouse developing generic solution. TRAMM. T.R. Commonwealth Edison Co. 80/12/02. 2pp. 07220:044.
- DOCKET 50-454 BRAIDWOOD STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensess OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements Requests operating reactor licenses confirmation in 45 days that Encl t implementation dates will be met. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012010051 Confirms 801030 plans for 801125 meeting in Chicago, IL to discuss NRC evaluation of regulatory performance. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/11/18, in.
- BO12010084 Informs NRC of intentions to use ABME Code Case N-275, "Repair of Welds. Section III, Div 1," to utilize alternate rules for examination of areas prepared for repair of welds. Requests notice of acceptability of encl code case. TRAMM.T.R Commonwealth Edison Co. 80/11/18. 2pp. 07098:206.
- 8012080448 Informs of intent to use ASME Code Case N-275, "Repair of Welds, Section III. Div 1," approved 800915, for utilization of alternate rules for examination prepared for repair of welds. Requests acknowledgement of acceptability.
 TRAMM.T.R. Commonwealth Edison Co. 80/11/18. 2pp. 07183:053.
- 8012010581 Confirms 801017 plans for 801120 meeting in Olan Ellyn, IL to discuss util evaluation of design/engineering organizations & functions re significant const rework at facilities.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/19.
- 8012020301 Forwards tabulation of planned environ qualification testing programs in response to MRC 801001 ltr.
 ABEL J. S. Commonwealth Edison Co. 80/11/26. 4pp.
- 8012190904 Approves 801118 request for authorization to use ABME Code Case N-275.Use should be documented in FSAR. YOUNOBLOOD, B. J. Licensing Branch 1. 80/12/08. 2pp. 03795; fB5.

- 8012290398 Informs that meeting held to discuss util evaluation of design/engineering organization & functions proved effective in defining scope & explaining results of util evaluation. FIGRELLI-G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/08 App.
- Q. Inspection reports, 18 Bulletins & correspondence
- 8012160535 Forwards IE Insp Repts 50-456/80-12 & 50-457/80-11 on 800922-25 & notice of violation. FIGRELLIO. Region 3. Chicagu. Reactor Construction & Engineering Support Branch. 80/10/23. 2pp. 07261:191.
- --8012140541 Notice of violation from insp on 800922-25.

 * Region 3, Chicago, Reactor Construction & Engineering Support Branch, 80/10/21. 2pp. 07261:193
- --8012160555 IE Insp Repts 50-456/80-12 & 50-457/80-11 on 800722-25.
 Noncompliance noted inadequate control of stored ductwork & defective shop welds.
 MAIDU.K. R. SCHAPKER.J. Region 3. Chicago. Office of the Director.
 HAYES.D.W. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 80/10/21. 10pp. 07261:195.
- BO12170510 Forwards IE Info Natice BO-37, "Containment Cooler Leaks & Reactar Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/24.
- B012190221 Forwards IE lnsp Repts 50-456/80-13 & 50-457/80-12 on 801022-23, No noncompliance noted. FIGRELLIG. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/11/13. 2pp. 07292:110.
- --8012170227 IE Insp Repts 50-454/80-13 & 50-457/80-12 on 801022-23. No noncompliance noted Major areas inspected preparation for reactor vessel move to containment & steam generator mod. ERB.C.M. Region 3, Chicago, Office of the Director. DANIFLEON, D.M. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/12. 4pp. 07282:112.
- 8012920743 Forwards three Performance Appraisal Branch insp repts & mgt avaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. N/o encl. KEPPLER. J. O. Region 3. Chicago, Office of the Director. 80/11/19.
- B012040537 Forwards IE Bullotin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/11/21.
- 8012980087 Forwards 1E Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/24. 2aa.
- B012150223 Ack receipt of B01106 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-456/80-11 & 50-457/80-10. FIORELLIG. Region 3. Chicago. Reactor Construction & Engineering Support Branch. B0/11/26. 1p. 07237:351.
- --8012150228 Forwards response to NRC 801003 ltr re violation noted in IE Insp Repts 50-496/80-11 & 50-457/80-10. Corrective actions: surveillance of storage is performed per BM-103, site storage instruction.

 ABEL, J. S. Commonwealth Edison Co. 80/11/06. 2pp. 07237:352.
- 8012170552 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.

 KEPPLER. J. C. Region 3. Chicago. Office of the Director. 60/11/26.
- S. Reportable occurrences. LERs & related correspondence
- B0121004B2 Interim deficiency rept initially reported on 801106 re Wastinghouse Electro-Mechanical Div mfg 3-inch gate valves, Model 39MBB failing to close under preoperational test conditions. Hestinghouse developing generic solution. TRAMM, T.R. Commonwealth Edison Co. 80/12/92. 2pp. 07220:044.

- BOCKET 50-457 BRAID-BOOD STATION. UNIT 2

 A Application/construction stage documents & correspondence
- 8012160090 Ltr to operating plant licensees.(U. applicants & CP holders. Forwards NUREG-0737 re TML action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation datas will be net. EISERHUT.D.G Division of Licensing. 80/10/31. 7pp.
- 8012010051 Confirms 801030 plans for 801125 meeting in Chicago, IL to discuss CRC evaluation of regulatory performance. KEPPLER, J. G. Region G. Chicago, Office of the Director 80/11/18. is.
- 8012010024 Informs NPC of Intentions to use ASME Gode Case N-275, "Repair of Welds, Section III. Div 1," to utilize alternate rules for eramination of areas prepared for repair of welds. Requests notice of acceptability of encl code case. TRAMM, T. R. Commonwealth Edison Co. 80/11/18. 2pp.
- 8012080448 Informs of intent to use ASME Code Case N-275, "Repair of Welds, Saction III. Div 1," approved 800015, for utilization of alternate rules for examination prepared for repair of welds. Requests acknowledgement of acceptability.

 TRAMM, T.R. Commonwealth Edison Co. 80/11/18. 2pp.
- 8012010581 Confirms 801017 plans for 801120 meeting in Olen Ellyn, fL to discuss util evaluation of design/engineering organizations & functions re significant const rework at facilities.

 KEPPLER, J. O. Region 3, Chicago, Diffice of the Director. 80/11/19. 1p.
- 8012020301 Forwards tabulation of planned environ qualification testing programs in response to NRC 801001 ltr.

 ABEL, J. S. Commonwealth Edison Co. 80/11/26. 4pp.
- 8012190004 Approves 801118 request for authorization to use ASKE Code Case N-275.Use should be documented in FSAR, YOUNGSLOOD.B. J. Licensing Branch 1. 80/12/08. 2pp.
- 8012290378 Informs that meeting held to discuss util evaluation of design/engineering organization & functions proved effective in defining scope & explaining results of util evaluation. FIORELLIG. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/08. 2pp.
- G. Inspection reports, IE Bulletins & correspondence
- B012160535 Forwards IE Insp Repts 50-496/80-12 & 30-457/80-11 on B00722-25 & notice of violation. FIORELLI,G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. B0/10/23. 2pp. 07261:191.
- --8012160541 Notice of violation from insp on 800922-25.
 4 Region 3, Chicago. Reactor Construction & Engineering Support Branch. 80/10/21. 2pp. 07261.193.
- --B012160555 lE Insp Repts 90-456/B0-12 & 50-457/B0-11 on 800922-25.
 Noncompliance noted: tradequate control of stored ductwork & dafactive shop welds.
 NAIDJ,K.R., SCHAPKER, J. Region 3. Chicago, Office of the Director.
 HAYES-D.W. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/10/21. 10pp. 07261:175.
- 8012170510 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No uritten response required.
 KEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/10/24.
- 8012190221 Forwards IE Insp Repts 50-456/80-13 & 50-457/80-12 on 801022-23. No honcompliance noted. FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/13 2pp. 07282:110.
- --8012190227 IE Insp Repts 50-456/80-13 & 50-457/80-12 on 801022-23. No noncompliance noted Major areas inspected preparation for reactor vessel move to containment & steam generator mod. ERB.C.M. Region 3. Chicago. Defice of the Director. DANIFLEON, D. H. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/11/12. 4pp. 07282:112.

- P012020743 Forwards three Porformance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments W/o encl. MEPPLER, J. C. Region 3, Chicago, Diffice of the Director. 80/11/18.40o.
- 012040637 Forwards IE Bulletin BO-24, "Prevention of Damage Due to Water Leakage Inside Containment" No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21.
- 012080087 Forwards IE Info Notice 80-42, "Effect of Radiation on Mydraulic Shubber Fluid." No written response required. KEPPLER. J. G. Rogion 3, Chicago, Office of the Director. 80/11/24.
- 012150223 Ac) receipt of 801106 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-456/80-11 & 50-457/80-10.
 FIGRELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/26. 1p. 07237:351.
- -8012150228 Forwards response to NRC 801003 ltr re violation noted in IE insp Repts 50-456/80-11 \$ 50-457/80-10. Corrective actions: surveillance of storage is performed per 8M-103, site storage instruction.

 AREL. J. S. Commonwealth Edison Co. 80/11/96. 2pp. 07237:352.
- 012170952 Farwards IE Info Notice 80-27, Suppl 1. "Broten Studs on Tarry Torbine Steam Inlet Flange." No written response required. KEPPLER, J. G. Region 3, Chicago, Diffice of the Director. 80/11/26. 2pp.
- Reportable occurrences, i.ERs & related correspondence
- i2100462 Interim deficiency rept initially reported on 801106 re Mastinghouse Electro-Mechanical Div mfg 3-inch gate valves, Model 30K88 failing to close under preoperational test conditions. Westinghouse developing generic solution. TRAMM, T.R Commonwealth Edison Co. 80/12/02, 2pp.
- CKET 50-456 RIVER DEND BEATION. UNIT 1 Application/construction stage documents & correspondence
- I2140090 Ltr to operating plant licensess,OL applicants & CP holders. Orwards NUREG--0737 re TM1 action plan requirements. Requests sperating reactor licenses confirmation in 45 days that incl i implementation dates will be net. ISERP-UT,D.G. Division of Licensing. 80/10/31. 7pp.
- 2220398 Ltr to all CP & CL holders for BuRs re requirement for mplementation of ODYN code for licensing basis calculations erformed by CE Applicable to all license applications & ropayed amends, including core reloads.

 ISERHUT, D. G. Division of Licensing. BO/11/04. App.
- 2160388 Forwards info re small dry transformer & 480-volt load trs, in response to NRC 801001 ltr re IEEE 323 environ ualification program.Review should be completed by 810115. RAPER, E. L. Gulf States Utilities Co. 80/12/05. 2pp. 07263:141.
- 2310332 Responds to NRC 801125 publication, "Subj:Commission engrandum 5 Order of 800523," referencing IE Bulletin 9 01B, Suppl 2. Info requested will be submitted during OL pplication review RAPER.E.L. Oulf States Utilities Co. 80/12/22. 1p. 07369:174.
- Security, medical, emergency & fire protection plans
- 2030536 Forwards public version of "Evacuation Time Estimates or 10-Mile Emergency Planning Zone." S.TON.J.M. Division of Rules and Records, 80/12/01, 1p. 2171:351
- 012050540 Forwards public version of "Evacuation Time Estimates for 10-Mila Emargency Planning Zone." DRAFER.E.L. Oulf States Utilities Co. BO/08/29. 1p. 07171:352.
- 012050542 Public version of "Evacuation Time Estimates for 10-Mile Emergency Planning Zone," + Oulf States Utilities Co. 80/03/29, 36pp. 07171:353.

- Inspection reports, IE Pulletins & correspondence
- 8012170737 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required. SEYFRIT, N. V. Region 4, Dallas, Office of the Director. 80/09/10. ip. 07264:158
- 8012030783 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type U-2 Spring Return to Neutral Control Switches."

 Specified control switches are not used in safety-related applications at facility.

 DRAPER,E.L. Gulf States Utilities Co. 80/09/19, 1p. 07149:291.
- BO12270649 Submits supplemental response to IE Bullatin 79-03A.
 "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless
 Steel Pipe." Fusion welds are not subj to greater than 85%
 of code allowable stresses.
 DRAPER.E.L. Gulf States Utilities Co. 80/09/19. tp. 07299:268.
- 80:12220685 Responds to IE Bulletin 80-16. "Potential Misapplication of Rosemount. Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes." Investigations are incomplete Final response scheduled by 801103.

 DRAPER.E. L. Gulf States Utilities Co. 80/10/06. ip. 07299:269.
- 8012170826 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Hig by Valcor Engineering Corp." No written response is required.

 SEFFRIT.R.V. Region 4, Dallas, Office of the Director. 80/10/31.
 1p. 07266:021
- 8012100602 Forwards IE Builetin 80-21, "Valve Yokes Bupplied by Malcolm Foundry Co.Inc." Written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/06.
- 8012030899 Forwards IE Info Notice 80-40, "Excessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. BEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/07. pp. 07150:129.
- 8012080591 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. BD/11/10. 1g. 07163:011
- 8012040106 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. SEYFRIT. K. V. Region 4, Dallas, Office of the Director. 80/11/14. 1p. 07158:035.
- 8012050015 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. SEYFRIT. K.V. Region 4, Dallas. Office of the Director. 80/11/21. 1p. 07173:063.
- BO12140077 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No response required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. BO/11/24. 1p. 07262:128.
- B012140102 Forwards Suppl 1 to IE Info Notice 80-27, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. SEYPRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/26. 1p. 07262:097.
- 8012190529 Ack receipt of 800729.0910 & 1003 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-453/80-05. SEIDLE, M. C. Region 4. Ballas, Reactor Construction & Engineering Support Branch. 80/12/02. 1p. 07288:285.
- --80i2190633 Responds to NRC 800815 ltr re violations noted in IE Insp Rept 50-458/80-05. Clarifies info submitted in 800710 ltr re usage of word qualified & supervision of technical parsonnel.
 DRAPER, E. L. Gulf States Utilities Co. 80/09/10. 5pp. 07288: 286.
- --8012190638 Responds to NRC request for clarification of Item B of B00910 itr re tests performed by technical personnel under supervision. Assistant technicians will work w/Level II or above parsonnel. DRAPER, E. L. Gu: Gulf States Utilities Co. 80/10/03. 2pp. 07298: 291.

- B012190529 Ack receipt of B00820 t. 1021 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-458/80-06 SEIDLE.U.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 50/12/03. 1p. 07887:214.
- --8012190534 Responds to NRC 800930 ltr re violations noted in IE Insp Rept 50-458/80-06.Addl info sutmitted as requested in 800728 ltr.Random sample of concrete samples tested for air content. DRAPER.E.L. Guif States Utilities Co. 80/10/21. 2pp. 07287:215.
- B012310332 Responds to NRC B01125 publication, "Subj; Commission Memorandum & Order of 800523," referencing IE Bulletin 79-018, Suppl 2. Info requested will be submitted during OL application review.

 DRAPER, E. L. Gulf States Utilities Co. B0/12/22. 1p. 07369:174.
- S. Reportable occurrences, LERs & related correspondence
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERWOOD, O. O. General Electric Co. 80/12/08. 3pp.
- DOCKET 50-459 RIVER BEND STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that a Enc1 1 implementation dates will be ret. EISERHUT, D. Q. Division of Licensing. B0/10/31. 7pp.
- 8012220358 Ltr to all CP & DL holders for BIJRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & progosed amends, including core reloads.

 EISELHUT, D. Q. Division of Licensing. 80/11/04. 4pp.
- 8012140088 Forwards info re small dry transformer & 480-volt load ctrs. in response to NRC 801001 ltr re IEEE 223 environ qualification program Review should be completed by 810115. DRAPER, E. L. Ouif States Utilities Co. 80/12/05. 2pp. 07263:141.
- Q. Inspection reports, IE Bulletins & correspondence
- B012170737 Forwards IE Circular 80-21, "Regulation of Refueling Crews."
 No written response required.
 EEYfRIT.K.V. Region 4, Dallas, Office of the Director. 80/09/10.
 1p. 07264:158.
- 8012030783 Responds to IE Sulletin HO-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches."

 Specified control switches are not used in safety-related applications at facility.

 DRAPER.E.L. Guif States Utilities Co. 80/09/19. 1p. 07149:291.
- 8012220649 Submits supplemental response to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe." Fusion welds are not subj to greater than 85% of code allowable stresses.

 DRAPER, E.L. Gulf States Utilities Co. 80/09/19. 1p. 07299: 268.
- 8012220/85 Responds to IF. Bulletin 80-16. "Potential Misapplication of Rosemount: Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes." Investigations are incomplete. Final response scheduled by 801103.

 DRAPER, E. L. Gulf States Utilities Co. 80/10/06. 1p. 07299: 269.
- 8012170826 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required. SEYFRIT, K. V. Region 4, Dallas. Office of the Director. 80/10/31. 1p. 07266:021.
- 8012100502 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. SEVFRIT-X.V. Region 4. Dallas. Office of the Director. 80/11/06. pp. 07220:110.
- B012030B99 Forwards IE Info Notice E0-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuritation " No written response required. SEYFRIT.K. V. Region 4. Dallas. Office of the Director. 80/11/07. ip. 07150:129.

- 8012080591 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Dacay Heat Removal Sys at Davis Desso Unit 1." No response required.

 SEYPRIT.K. V. Region 4, Dallas, Office of the Director. 80/11/10.

 10. 07183:011.
- 8012040106 Forwards IE Suiletin 80-23. "Failures of Sulencid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/14. 1p. 07158:035.
- 8012050015 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Nater Leskage Inside Containment." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director, 80/11/21, 1p. 07173:063.
- BO12160377 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid " No response required. SEYFRIT.K.V. Region 4, Dallas. Office of the Director. 80/11/24. ip. 07262:128.
- 8012160102 Forwards Suppl 1 to IE Info Notice 80-27, "Broken Studs on Terry Turbine Steam Injot Flange." No written response required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/26. 1p. 07262.097.
- S. Reportable occurrences, LERs & related correspondence
- 8012240039 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERNOOD, C. General Electric Co. 80/12/08. 3pp.
- DOCKET 50-450 NPPSS NUCLEAR PROJECT, UNIT 1

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be ret. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- I. Financial information
- BOI2160128 Forwards Annual Financial Rept 1980.
 BOUCHEY, O.D. Washington Public Power Supply System. BO/12/11. 1p. 07187-001.
- --B012160134 Annual Financial Rept 1980.

 ✓ Kashington Public Power Supply System. 80/12/11, 23pp. 07187:001.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012170680 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 ENGELERIA. H. Region 5. San Francisco. Office of the Director.

 80/10/24. 1p. 07266:069.
- 8012170418 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ENCELKEH.R.H. Region 5. San Francisco. Office of the Director. 80/10/30. 1p. 07266: 160.
- 8012170847 Forwards IE Info Notice 80-37, "Malfunction of Solenois Valves Mfg by Valcor Engineering Corp." No written response is required. ENGELEBIAR H. Region 5, San Francisco, Office of the Director. 80/10/31. 1p. 07266:035.
- 8012120221 Forwards IE Bulletin 80-21, "Valve Yotes Supplied by Malcolm Foundry Co.Inc." Written response required. ENCELKEN.8.H. Region 5, San Francisco, Office of the Director. 80/11/06. 1p. 07228:284.
- B012030714 Forwards IE Info Notice 80-40, "Ercessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. ENGELEFIJR.H. Region 5. San Francisco, Office of the Director. B0/11/07. 1p. 07150:133

- F312080n58 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Renoval Bys at Davis Bease Unit 1." No response required Exage Prescript Office of the Director. 80711719 | 1p. 07103-041
- £012040P33 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves MFg by Valcor Engineering Cotp " Requires estimate of manpower associated w/corrective actions ENGELVELUE H Region 5. Ban Francisco. Office of the Director. SO/11/14 1p 07158 195
- 6012040591 Forwards IF Bulletin 80-24. "Prevention of Damage Due to Mater Leatage Inside Containment." No written response required RNSELFERIR H Region 5, San Francisco. Office of the Director. 60/11/21. 1p 07169-272
- 3012160;31 Forward: IE Info Notice 80-32, "Effect of Radiation on Mydraulic Shubber Fluid " No response required. ENSELPHIR H Region 5. Ean Francisco. Office of the Director. 80/11/24 1p 07262 120
- 2012310503 Forwards IE Investigation Repts 50-460/80-14 & 50-513/80-14 on 800305-0717 No concempliance noted.

 SPENCER.G.S. Region 5. San Francisco. Reactor Construction & Engineering Support Branch 50/11/25. 2pp. 07365:237.
- ~ -8012310508 IE Investigation Repts 50-460/80-14 & 50-513/80-14 on 800335-0717. No noncompliance noted Major areas investigated: anonymous allegations re const & reinforcing steelwork/ activities.

 TOT⇒ A D . SHACKLETUM O C Region 5. San Francisco, Office of the Director HARDS.R.C Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 80/11/25. 16pp. 07045-239
- 2012(±0133 Forwards Suppl 1 to 1E Info Notice 80-29, "Broten Studs on Terry Turbine Steam Inlet Flange." No written response required. ENGELYEM.H. Region 5. San Francisco, Office of the Director. 20/11/26. 1p. 07262-067
- U Congressional/Elecutive Correspondence
- 8012100554 Responds to 800408 ltr to DOE requesting rept on finley dwarry fault potential for earthquake & effect on facilities totaked at Hanford reservation. Satsnicity will be re-evaluated as result of recent geologic discoveries.

 DIRCKS.U.J. Office of the Erecutive Director for Operations.
 80/41/24. 11pp. 07187:001.
- DOCKET 53-461 CLINTON POWER STATION, UNIT 1

 A. Application/construction stage documents & correspondence
- E012780340 Advises that Baldwin Associates has been authorized to repair disc/guide bar misalignments per mfg instructions (1990 1455) on Valves 186034 E127014A: IE: 2F014B: IE:12F04BA: IE:12F04BB & 1F0003A Repair plan will be available at site. SPENCER, J. Illinois Power Ca. 60/10/23. 1p. 07194:169.
- 201216C050 Ltr to operating plant licensees. GL applicants & CP holders. Forwards NOREO-0737 re TMI action plan requirements. Requests operating reactor licensee confination in 45 days that Encil 1 implementation dates will be not. EISEN-UT.D G. Division of Licensing. 80/10/31. 7pp. 07250:080.
- E012220359 Ltr to all CP & CL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends.including core reloads.

 EISEN-UT. D. G. Division of Licensing. 80/11/04. App.
- ECIZIA0577 Summary of E01112-14 meeting w/util in Clinton IL re const status Charts & graphs enclosed, GRIMES C I Licensing Branch 3 80/12/04 59pp. 07254:236.
- 8012160787 Notification of 810107-08 meeting w/AHL & util in Clinton, IL to obtain preliminary info concerning design & layout of instrument & control sys for facility.

 GRIMES.C. I. Licensing Branch 3. 89/12/10. 3pp. 07252:227.
- G. Adjudacatory correspondence
- 8012290165 Notice of apprarance in proceeding Certificate of Svc encl. FAZIO.P.V. Illinois Power Co. 60/11/26 5pp. 07344:149.

- 8012230227 Notice of appearance in proceeding. GODDARU,R.J. Hearing Branch 2. 80/12/04. 2μρ. 07317:263.
- 8012300114 Notice that encl notices of appearances were filed w/Secretary of NRC Certificate of Svc encl, MILLMAN, P. L. Illinois, State of. 80/12/09. 6pp. 07358: 324.
- 8012390112 Memorandum & order summarizing 801202 telephone conference & directing special prehearing conference to be held 810127 in Urbana IL.
 CLARK.H.K. Atomic Safety and Licensing Board Panel. 80/12/22, 2pp. 07358:330.
- X. Utility Final Safety Analysis Report (FSAR) & amends
- 8012310315 Forwards Amend 2 to FSAR, in response to NRC 800829 ltr. KOCH, L. J. Illinois Power Co. 80/12/30. 1p. 07361:054.
- --8012310317 Amend 2 to FSAR. KOCH.L.J. Illinois Power Co. 80/12/31. 260pp. 07361:035.
- Q. Inspection reports, IE Bulletins & correspondence
- 8011250274 Forwards IE Insp Rept 50-461/80-17 on 800801-31 & notice of violation.
 FIORELLI, O. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/09/11. 2pp. 07036:292.
- --B011250276 Notice of violation from insp on 800801-31.

 # Region 3, Chicago, Office of the Director. 80/09/11. 1p. 07055:294.
- --8011250278 IE Insp Rept 50-461/80-17 on 800801-31. Noncompliance noted:
 nonseismic Category i floor drain lines in reactor fuel bldg
 installed & routed over & close to electrical power & cable
 trays.
 LIVERKORE, H. H. , KNDP, R. C. Region 3, Chicago, Office of the
 Director. 80/09/11 14pp. 07056:295.
- 8012110006 Forwards IE Insp Rept 50-461/80-21 on 801006-08 & notice of violation.
 FIGRELLI, C. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/23. 2pp. 07223; 237.
- --8012110011 Notice of violation from insp on 801006-08.

 4 Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/23. [p. 07223:239.
- --8012110016 IE Insp Rept 50-461/80-21 on 801006-08. Noncompliance notes: failure to recalibr ultrascuic instrument for performance of nondestructure examinations.

 KEY, M. J., SCHAPKER, J., DANIFLEDIN, D. H. Region 3, Chicago, Office of the Director. 80/10/23. 7pp. 07223: 240.
- 8012170266 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Fluoding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/24.

 1p. 07266:061.
- 8012220154 Responds to NRC itr re violation noted in IE Insp Rept 50-461/80-20 Corrective action: constructor instructed to remove inadequately documented temporary attachmants from dryuall liner.

 KOCH.L.J. Illinois Power Co. 80/11/10. 2pp. 07303:234.
- B012180586 Forwards IE Mgt Meeting Rapt 50-461/80-22 on 801028 No noncorpliance noted. KEPPLER.J.G. Region 3. Chicago. Office of the Director. 80/11/12. 2pp. 03770:234.
- ~-8012180590 IE Mgt Meeting Rept 50-441/80-22 on 801028. No noncompliance noted Major areas discussed; regulatory performance of activities as concluded in systematic assessment of licensee performance program.

 FIGRELLI, C. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/11/12 9pp. 03790:236.
- S012290162 Responds to NRC S01007 ltr re violation noted in IE Insp Rept 50-461/80-19, Corrective action: BTS 402 revised to differentiate between various classes of work & to clarify filler metal & welder identification documentation. KOCH, L J. Illinois Power Co. S0/11/12, 2pp. 07303: 236.

- B012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility ran compare program to program already reviewed & make appropriate adjustments. W/o encl.

 KEPPLCR. J. G. Region 3. Chicago. Office of the Director. 80/11/18.
- 6012040236 Ack receipt of 801110 ltr informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-461/80-20. PIGRELLI.G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 60/11/21. 1p. 07158:161.
- --8012040247 Responds to NRC 801010 ltr re violations noted in IE Insp. Rept 50-461/80-20. Corrective actions stop work order issued 800724 for all permanent nonselsmic Category I structures & components in containment bldg.

 KOCH.L.J. Illinois Power Co. 80/11/10. 2pp. 07158:162.
- 8012040646 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21, 2pp. 07165:354.
- 8012080063 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. KEPPLER.J. C. Region 3, Chicago. Office of the Director. 80/11/24. 2pg. 07182:213.
- 8012170537 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange," No written response required.

 KEPPLER.J. O. Region 3, Chicago, Office of the Director. 80/11/26. 2pp. 07264:262.
- S. Reportable occurrences, LERs & related correspondence
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERWOOD, O. G. General Electric Co. 80/12/08. 3pp.
- DGCKE1 50-462 CLINTON POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8012080340 Advises that Baldwin Associates has been authorized to rapair disc/guide bar misalignments per m/g instructions (NRC 3455)on Valves 18F004.1E12F014A.1E.2F014B.1E12F08BA.1E12F06BB & 1FC003A.Repair plan will be available at site. SPENCER.J. Illinois Power Co. 80/10/23. ip. 07194:189.
- B012140050 Ltr to operating plant licensees.QL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISENHUT.D.G. Division of Licensing, B0/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by CE. Applicable to all license applications & proposed amends, including core reloads.

 EISENMUT, D. O. Division of Licensing. 80/11/04. 4pp.
- 8012160227 Notification of 810107-08 meeting w/ARL & util in Clinton, IL to obtain preliminary info concerning design & layout of instrument & control sys for facility,

 GRIMES, C. I. Licensing Branch 3. 80/12/10. 3pp. 07252-227.
- G. Adjudicatory correspondence
- 8012290165 Notice of appearance in proceeding Certificate of Svc encl. FAZIO, P. V. Illinois Power Co. 80/11/26. 5pp. 07344:147.
- 8012230227 Notice of appearance in proceeding. GODDARD, R. J. Hearing Branch 2. 80/12/04. 2pp. 07317:263.
- 8012300114 Notice that encl notices of appearances were filed w/Secretary of NRC Certificate of Svc encl. WILLMAN, P. L. Illinois, State of, 80/12/09, 6pp. 07358:324,

8012300112 Memorandum & order summarizing 801202 telephone conference & directing special prehearing conference to be held 810129 in Urbana, IL. CLARK-H.K. Atomic Safety and Licensing Board Panel. 80/12/22. 2pp. 07358:330.

- X. Utility Final Safety Analysis Report (FSAR) & amends
- 8012310315 Forwards Amend 2 to FSAR in response to NRC 800829 ltr. KOCH.L.J. Illinois Power Co. 90/12/30. ip. 97361:054.
- --8012310317 Amend 2 to FSAR. KGCH, L. J. Illinois Power Co. 80/12/31. 260pp. 07361:055.
- O. Inspection reports, IE Bulletins & correspondence
- 8012170555 Forwards IE Info Notice 80-37, "Containment Cooler Leaks Reactor Cavity Flooding at Indian Point Unit 2." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/6 tp. 07255:061.
- 8012020743 Forwards three Performance Appraisal Branch insp repts 8 mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. N/o encl.

 KEPPLER, J. O. Region 3. Chicago, Office of the Director. 80/11/1400.
- 8012040646 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Nater Leakage Inside Containment." No written response required. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 80/11/2 2pp. 07165:354.
- 8012080063 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydravlic Snubber Fluid." No written response required. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 80/11/2 2pp. 07182.213.
- 8012170939 Forwards IE Info Notice 80-29, Suppl 1, "Broten Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/2 2pp. 07264:262.
- S. Reportable occurrences, LERs & related correspondence
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERNOOD, 0.0. General Electric Co. 80/12/08. 3pp.
- DOCKET SO-443 FULTON GENERATING STATION, URIT 1
 G. Adjudicatory correspondence
- 8012140144 Forwards SEC Form 10-0. Quarterly Financial Rept & supporting the comments in response to NRC 790521.1109 & 800811 requests for info re significant financial developments affecting utils in restart proceeding.

 CONDON, V. H. General Public Utilities. 80/11/24. 3pp.
- --8012160154 Quarterly Financial Rept Sept 1980 & supporting mgt consents.
 * Denoral Public Utilities. 80/11/14. 44pp.
- 8012090297 Requests that util CP application be withdrawn w/o prejula CP proceedings be terminated Motion encl.
 IRWIN.D.P. Hunton & Williams. 80/12/05. 2pp. 07201:129.
- --8012090298 Motion to withdraw application for CP & terminate proceedings.
 IRWIN-D.P. Hunton & Williams, IRWIN-D.P. Philadelphia Electr Co. 80/12/05. 2pp. 07201:131.
- 8012100471 Motion to withdraw CP.application & terminate proceeding Certificate of Svc encl IRWIN.D.P. Hunton & Williams. IRWIN.D.P. Philadelphia Electric BO/12/05. 4pp. 07820:036.
- 8012290083 Response of intervenors York Committee for Safe Environ Central PA Committee on Nuclear Power, in opposition to applicant 801205 request to withdraw CP application w/o prejudice. Certificate of Svc encl.

 KEPFORU.C. Environmental Coalition on Nuclear Power. 80/12/17, 4pp. 07342:357.

- 8012300350 Response to applicant 801205 motion to withdraw application & terminate proceedings. Raises no objection to motion. No determination made to conditions of withdrawal. Certificate of Sve and of Svc encl. GRAV.J.R Hearing Branch 1. 80/12/24. 4pp. 07359:067.
- DECKET 50-464 FULTON GENERATING STATION, UNIT 2 G. Adjudicatory correspondence
- 8012160144 Forwards SEC Form 10-0. Quarterly Financial Rept & supporting mgt comments, in response to NRC 790921, 1109 & 800811 requests for info re significant financial developments affecting utils in restart proceeding.

 CONUON.V.H. General Public Utilities. 80/11/26. 3pp.
- --8012160154 Guarterly Financial Rept Sept 1980 & supporting mgt conments.

 * General Public Utilities. BO/11/14. 44pp.
- 8012090297 Requests that util CP application be withdrawn w/o prejudice & CP proceedings be terminated Motion encl.
 IRWIN.D.P. Hunton & Williams 80/12/05. 2pp. 07201:129.
- --8012090278 Motion to withdraw application for CP & terminate proceedings.
 IRWIN,D.P. Hunton & Williams. IRWIN,D.P. Philadelphia Electric
 Co. 80/12/05. 2pp. 07201:131.
- 8012100471 Motion to withdraw CP application & terminate proceedings. Certificate of Svc encl. IRWIN.D.P. Hunton & Williams. IRWIN.D.P. Philadelphia Electric Co. 83/12/03. 4pp. 07220:036.
- 8012290033 Response of intervenors York Committee for Safe Environ & Central PA Committee on Nuclear Pawer in apposition to applicant 801205 request to withdrau CP application w/o prejudice Certificate of Svc encl. KEPFORU C. Environmental Coalition on Nuclear Power. 80/12/17. 4pp. 07342:357.
- 8012300350 Response to applicant 801205 motion to withdraw application b terminate proceedings Raises no objection to motion. No determination made to conditions of uithdrawal. Certificate of Svc encl.

 GRAY. J. R. Hearing Branch 1. 80/12/24. 4pp. 07359:067.
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1 A. Application/construction stage documents & correspondence
- 8012220358 Ltr to all CP % CL holders for BWRs re requirement for implementation of DDYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENMUT, D. G. Division of Licensing. 80/11/04. 4pp.
- D. NAC Draft/Final Environmental Statements, suppls & correspondence
- 8012190214 Draft Suppl 2 to FES.

 * Office of Nuclear Reactor Regulation, Director. NUREO-0470 S2, 80/12/31. 104pp. 07282:153.
- G. Adjudicatory correspondence
- G012030B42 Advises that CP hearing re facility is scheduled to begin on B10117 in response to B01020 ltr re concerns expressed in util B00904 ltr.
 D1RGKS.W. J. Office of the Executive Director for Operations.
 B0/11/17. 1p. 07649:255.
- 8012050437 Notice of ASLAB reconstitution AS Rosenthal, chairman & JH Buck & CH Kohlpanel members. BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. B0/11/24. 1p. 07173:308.
- 8012020528 Forwards memorandum in support of applicant request to set date for commencement of health & safety hearings.
 Certificate of Svc encl.
 NEWARK.J.R. Lowenstein, Newman, Reis, Arelrad & Toll. 80/11/26. 10pp. 07148:017.

- -8012020634 Memorandum in support of applicant request to set date for commencement of health & safety hearings. Certificate of five
 - MEUMAN J.R , COPELAND, J.G. Houston Lighting & Power Co. MEUMAN, J.R. Lowenstein, Newman, Reis, Axelrad & Toll. 80/11/26. 1p. 07148:019.
- B012050400 Motion for summary disposition of consolidated contention (Cumings 9, Griffith 1, Johnston 1, & Lemmer 5) as reworded by ASLB & admitted pursuant to B00926 order. No genuine matl issue of fact remains to be litigated.

 BLACK.R.L. Hearing Branch 3. 80/11/26. 6pp. 07173:245.
- --8012050405 Statement of matl facts as to which no genuine issue is to be heard on consolidated contention re NEPA impacts of low level radiation. Hearing Branch 3 80/11/26. 4pp. 07173:251.
- --8012050406 Affidavit re NEPA impacts of low level radiation. Health risks associated w/LWRs are insignificant. Prof qualifications & Certificate of Svc encl. OPTCHV.R. L. Radiological Assessment Branch. 80/11/26. 21pp. 07173: 255.
- 8012290005 Motion for amend of 800627 protective order approving sattlement agreement on insp of GE Read Rept.Certificate of Evc enci.
 COPELAND.J.O., NEWMAN.J.R. Houston Lighting & Power Co. COPELAND.J.G. Baker & Botts. 80/12/02. 5pp. 07344:196.
- 8012300500 Requests to make limited appearance before Commission on 800114 or 15 in Houston.TX. MAGEE.A.A. Affiliation Unknown. 80/12/04. 1p. 07359:214.
- 8012190495 Order granting applicant 801202 motion for amend of 800627 protective order & amend to Attachment A reagreement regarding disclosure of confidential info. WOLFE, J. Atomic Safety and Licensing Board Panel. 80/12/05. 2pp. 07287:057.
- 8012300135 Response to first set of interrogatories & request for production of documents from util on health effects of low level radiation. Certificate of Svc encl. Related leves radiation of the correspondence.
 CUMMINGS.E. Affiliation Unknown. 80/12/09. 4pp. 07396:299.
- 8012150180 Responds to ASLBP 801202 request for clarification re exclusion of TX PIRQ Contention 30.1 from applicant 800804 motion for summary disposition Unfiltered leakage issue is relevant to McCarkle Contention 17 only. COPELAND, J. O. Baker & Botts. 80/12/06. 3pp. 07240:359.
- 8012190152 Requests to make limited appearance statement at CP hearings at Bates College of Law. Houston, TX.
 EIDMAN, V. Affiliation Unknown 80/12/08. 1p. 07237:223.
- 8012150199 Requests rewording of applicant & NRC joint response to ASLP B01121 order re intervenor failure to identify expert witnesses. Applicant has deposed many identified witnesses. HINDERBTEIN.C. Affiliation Unknown. 80/12/08. 2pp. 07241:082.
- 8012290641 Joint response of NRC & applicant to ASLB 801202 order to submit proposed schedule for commencement of hearings on health & safety issues. Lists 30 issues & requests 810501 hearing on 16 issues. Certificate of 8vc encl. NEMMAN, J. R., COPELAND, J. G. Houston Lighting & Power Co. NEWMAN, J. R., COPELAND, J. G. Houston Lighting & Power Co. NEWMAN, J. Copeland, Reis, Axelrad & Toli. 80/12/08. 6pp. 07332:32 NEWMAN, J. R. 07332: 327,
- 8012300035 Order rescinding all pravious orders & issuances which averted to &/or granted procedural assistance to any intervenors.

 MDLFERS.J. Atomic Safety and Licensing Board Panel. 80/12/09. 2pp. 07354:109.
- 8012160451 Requests opportunity to make limited oral statement on B00114 or 15 at Univ of Houston. MUELLER, E. E. Affiliation Unknown. B0/12/10, 1p. 07243:355.
- 8012290344 Notification of 801210 conference call re Comptroller Oeneral ruling terminating procedural assistance to intervenors for copying & serving direct testimony. Order issued 801209. W/Certificate of Svc. COPELAND, J. O. Houston Lighting & Power Co. 80/12/10, 1p. 07343:135.
- 8012290627 Notice that CD Stutzenbaker agreed to be witness. Certificate of Svc encl.
 MARRICK.D. Marrack.D. 80/12/10. 1p. 07308:001.

- 8012100500 Expresses desire to make limited appearance statement during ASLB 810114 meeting in Houston TX. POTTHOFF,F. Affiliation Unknown. 80/12/11. 1p. 07187:001.
- 8012300002 Clarifies redrafted Doherty Contention 26 re stud bolts. BLACK.R.L. Hearing Branch 1. 80/12/11. 2pp. 07356:082.
- 8012290271 Notifies that CD Stutzenbacker of TX Parks & Hildlife Dept will testify on Contention 76 re presence & movements of migratory wildfowl presented in 800730 job performance rept & 740521 special rept.

 MARRACK.D. Marrack.D. 80/12/16. 1p. 07341:181.
- 8012290327 Homorandum & order ruling that matters discussed or determined at ASLB 801202 second prehearing conference shall control subsequent course of proceeding unless modified for good cause.

 WOLFE,S.J. Atomic Safety and Licensing Board Panel. 80/12/16. 7pp. 07343:141.
- B012240384 Requests to make limited appearance statement at 8:0114 hearings in Houston TX. WHARIGN. A. Citizens Anti-Nuclear Information Team. 80/12/17. ip. 07:325:144.
- 8012300079 Request to make limited appearance statement at 810114 hearing in Houston, TX.
 HODKER, K. Affiliation Unknown. 80/12/17. 1p. 07308:001.
- 8012290071 Response in support of NRC motion for summary disposition of consolidated contention (Cummings 9, Oriffith 1, Johnston 1 & Lerner 5) re health effects of low level radiation.
 NEWHAN, J.R., CULP,R. H., RASKIN, D. B. Houston Lighting & Power Co. 80/12/18, 2pp. 07343:048.
- --B012270075 Affidavit re health effects of low level radiation. Supports NRC statement of matl facts re consolidated contention on NFFA impacts of low level radiation. Prof qualifications & Centificate of Svc enci.
 HAMILTON, L. D. Brookhaven National Leboratory. B0/12/17, 24pp. 07343:050.
- BOIZ300095 Requests to make limited appearance statement at evidentiary hearings in Houston TX.
 WATANABE, D. H. Affiliation Unknown, 80/12/18, 1p. 07356:206.
- 8012300266 Forwards testimony of RL Gatchy,WS Bivins,GE Gears & CH Moon. BLACK,R.L. Hearing Branch 1. 80/12/18, 2pp. 07358;241,
- --8012300268 Transcript of GE Gears supplemental testimony re transmission lines/health effects (Marrack Contention 2(b) & Rentfro Contention 2).Prof qualifications encl. GEARS.G.E. Environmental Engineering Branch. 80/12/18. 16pp. 07358:243.
- --8012300271 Transcript of RL Gotchy supplemental testimony re radioactivity in cooling lake (Bishop Contentions 12 & 21). Prof qualifications encl. GOTCHY.R.L. Radiological Assessment Branch. 80/12/18. 7pp. 07358: 260.
- --8012300277 Transcript of KS Bivins testimony re potential requirements for dredging San Bernard river to transport reactor pressure vessel. Prof qualifications encl. BIVING.W.S. Hydrologic & Seotechnical Engineering Branch. B0/12/18. 9pp. 07358:269.
- ~~8012300279 Transcript of CN Moon supplemental testimony in response to ASLB Question 2 on use of WASH-1400, Prof qualifications encl.
 MOON, C. N. Licensing Branch 1. 80/12/18. 3pp. 07398: 278.
- --8012300283 Transcript of CW Moon supplemental testimony in response to ASL8 Question 7 re onsite transportation accident.Prof qualifications encl. MQQW,C.W. Licensing Branch 1. 80/12/18 3pp. 07358:281.
- 8012290030 Confirms 801217 telcon re availability of campus parking spaces on 810114-16.NRC will not pay for parking during subsequent hearing sessions beginning 810202. MOLFE, S. J. Atomic Safety and Licensing Board Panel. 80/12/19. ip. 07336:325.
- 8012290207 Appeal of ASLB 801113 order ruling marine biomass farm is not viable alternative to facility (Contention 4), Author should be readmitted as intervenor & timely hearings on contention should be held, Certificate of Syc encl. POTTHOFF, F. H. Affiliation Unknown. 80/12/19, 5pp. 07308:001.

- 8012300476 Requests to make limited oral statement on 810114 or 15 . Univ of Houston, TX. PIMA, R. Affiliation Unknown. 80/12/19. 1p. 07359:144.
- 8012310277 Requests to appear for 10 minutes at NRC 810114 hearing a Bates College of Law in Houston TX. OLIVEROS, R. B. Affiliation Uninown, 80/12/19, 1p. 07308:001.
- 8012300685 Requests to make appearance before Commission on 810114 of 15 in Houston,TX re-util request for CP.
 CRUMP,D. Affiliation Uninoun. 80/12/20. 1p. 07359:244.
- 8012300550 Response to intervenor Doherty first set of special interrogatories on Contention 50. Includes data on metal composition in jet pump components. Affidavit & Certificate of Svc encl.

 MOON.C.W. Licensing Branch 1. 80/12/24. 8pp. 07361:344.
- 80123102년1 Requests to appear in afternoon at 810114 hearing in Houston,TX. BURNSTONE,G. Affiliation Uninown. 80/12/26. lp. 07308:001.
- 8012290295 Joint response to ASLB 801121 order requiring submittal centron contentions & ASLB questions & sequence in which is substituted by the heard. Proposed schedule is tentative. Certificate of Svc encl. Certificate of Svc encl. COPELAND. J. G., NEWMAN. J. R. Houston Lighting & Power Co. COPELAND. J. G. Bayer & Botts. 80/12/07. 7pp. 07341:206.
- 8012300587 Response in opposition to NRC motion for summary disposit of consolidated contention (Cummings 9.Griffith 1.Johnston 1 & Leamer 5) re NEPA impacts of low level radiation. Certificate of Svc encl.

 DOCOETT, S. A. Doggett, S. A. 80/12/29, 2pp. 07308;001.
- --8012300596 "1981 Reassessment of Health Hazards of Low Level Ioniz Radiation." Affidavit & curriculum vitae encl. 8RG38.I.D. Roswell Park Memorial Institute. 80/10/09. 40pp. 07398:001.
- H. General correspondence
- 8012290924 Requests hait to const of facility. STAVINOKA.J. Affiliation Unknown. 80/11/13. 2pp. 07308:001.
- B012040256 Forwards info in response to 801027 itr requesting licensing categories & info re floating nuclear plants, PURPLE,R. A. Division of Licensing, 80/11/17, 4pp.
- --8012040278 Requests info re facilities w/active CPs pending licens definitions & requirements for floating nuclear plants. DREY, L. A. Affiliation Unknown. 80/10/29, 1p. 07170:063.
- B012150167 Opposes facility const because engineering & technology nequal to task. & opposes owner company liability limits in event of major accident.
 HDWARO.H.J. Affiliation Unknown. B0/12/03. 1p. 07237:227.
- 8012170504 Requests Cessation of nuclear plant licensing. Nuclear pla believed to be unhealthy. SCHMIDT.T. Affiliation Unknown. 80/12/09. 1p. 07187:001.
- 5. Reportable occurrences. LERs & related correspondence
- B012246089 Part 21 rept re reactor protection sys flerible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERNOOD, G. G. General Electric Co. 80/12/08. 3pp.
- T. Hearing transcripts on non-antitrost matters
- 8012080204 Transcript of 801202 hearing in Houston.TX re environ imp of const.Pp 1,803-2,004. * Atomic Safety and Licensing Board Panel. 80/12/02. 201pp. 07181:268.
- 8012270156 Forwards L Hamilton 801218 testimony re Doggett Contentio 1(b) & ASLB Question 1 on health effects of coal & nuclear power & TX PIRO Contention 1(f) on comparative population rights.

 NEWYAR, J. R. Lowenstein, Newman, Reis, Arelrad & Toll, 80/12/18. 3p

- --8012270160 Testimony on Doggett Contention 1(b) (Bishop Contention 13) re health effects of coal 3 nuclear power Pp 1-69, Prof qualifications encl.
 HAMILTON, L. Brookhaven National Laboratory, 80/12/18, 74pp. 07344: 658.
- --8012290167 Testimony re TX PIRC Contention 1(f) re population risks. Pp 1-8. HAMILTON, L D. Brookhaven National Laboratory. 80/12/18. App. 07344:132.
- 8012300654 Forwards applicant direct testimony in environ phase of proceeding scheduled to begin 810112. Testimony addresses issues re-cooling lake-energy alternatives, transmission lines, alternative sites & barge slips.

 COPELAND, J. G. Baker & Notts. 80/12/18. 5pp. 97347: 195.
- --8012300658 Testimony on behalf of util re TX PIRG Contentions 2 & 4 & McCorkle Contention 2 concerning cooling lake recreational benefits & damertension SCHLICHT.F.G. Houston Lighting & Power Co. 80/12/18. 34gp. 07347:200.
- --80123C0664 Testimony on behalf of util re TX PIRG Contention 2, Griffith Contention 4 & McCorkle Contention 2 concerning cooling lake recreational benefits. Resume & calculations of total chlorine residuals encl.

 TISCHLER/L F. Engineering Science. 80/12/18. 88pp. 07347:234.
- --8012309469 Testimony on behalf of util re Bishop Contention 21, cooling lake radionativity & Bishop Contention 12, cooling lake seepage. Resume encl.
 ARMSTRONG, N. E. Texas, Univ. of. 80/12/18. 53pp. 07347: 322,
- --8012300675 Testimony on behalf of util re energy alternatives. Info re planned generation additions, sys capability, load purchase power & reserve for 1977-1990 encl.
 007.J.D. Houston Lighting & Power Co. 80/12/18. 20pp.
 07348:013
- --8012339677 Testimony on behalf of util re energy alternatives. Tables of actual & projected sales & peak loads for 1979, 1990 & 2000 encl.

 ANDERSON, K. P. National Economic Research Associates, Inc. 80/12/16. 27pp. 07348:938
- --8012330652 Testimony on behalf of util re energy alternatives. Charts re levelized electricity cost from facility & coal alternatives encl. FERL-L.J. National Economic Research Associates, Inc. 80/12/18. 56pp. 07348:060.
- --B012309688 Testimony on behalf of util re TX PIRO Contention 5 concerning solid waste combustion. NOODSGN.H.H. Texas, Univ. of. B0/(2/18. 13pp. 07348:116.
- --B012300692 Testimony on behalf of util re TX PIRG addl Contention 12 concerning interconnection/purchase of power. Matl Electric Reliability Council annual rept encl.
 SIMMONS.D.E. Houston Lighting & Power Co. B0/12/18. 92pp. 07348: 127.
- --B012300696 Testimony on behalf of util re Rentfro/Marrack contention concerning health effects of high voltage transmission lines.

 HICHAELSON, S. Rochester, Univ. of, Medical Center. 80/12/18.

 39pp. 07348: 221.
- --8012300702 Testimony on behalf of util re Marrack Contention 2(c) re transmission lines & waterfoul. SCH_ICHT.F. G. Houston Lighting & Power Co. 80/12/18. 28pp. 07349: 261
- --8012320706 Testimony on behalf of util re TX PIRQ add1 Contention 1 re barge slip. Dames 2 Moore rapt "Environ Assessment & Responses to NRC Questions:Transportation of Reactor Pressure Vessel," encl.
 HUSSEY, J. R. Galifornia, Univ. of. Berteley. 80/12/18, 87pp. 07348:289.
- --B012303711 Testimony on behalf of util re TX PIRO Contention 1 re South Teras Project 3 versus Allens Creek site Listing of cost savings enci. MCCUISTON R. M. Houston Lighting & Power Co. 80/12/18. 22pp. 07349:508
- --8012303719 Testimony on behalf of util re Hinderstein Contention 5 corcerning coastal sites. FINLAY.R.L. URS Co. 80/12/18 26pp. 07347:030.

- --8012300723 Testimony on behalf of util re Hinderstein Contention 5 concerning coastal sites.

 VARSICKLE, D. Turner Collie & Braden, Inc. 80/12/18, 10pp. 07349:056
- --8012307728 Testimony on behalf of util re TX PIRG Contention 1 concerning South Teras Project 3 versus Allens Creek 1. Analysis of prime farmland soils encl. HUSSEY, J. R. Dames & Moore. 80/12/18. 20pp. 07349:066.
- --801230731 Testimony on behalf of util re Bishop Contention 1 concerning population projections.
 UNITE, U. T. Dames & Moore. 80/12/18. 51pp. 07349:086.
- ~-8012300733 Testimony on behalf of util re Hinderstein Contention 5 concerning coastal site.TERA Corp "Coastal Site Comparison Rept," enci.
 SCHOEHBERG, E. TERA Corp. 60/12/18. 200pp. 07347:136.
- DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8012220358 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENMUT, D. G. Division of Licensing. 80/11/04. 4pp.
- O. Adjudicatory correspondence
- B012030842 Advises that CP hearing re facility is scheduled to begin on B10112 in response to B01020 ltr re concerns expressed in util B000204 ltr.

 DIRCKS W. J. Office of the Executive Director for Operations.

 B0/11/17. 1p. 07149:253.
- DOCKET STN-50-470 CESSAR SYSTEM 80
- A. Application/construction stage documents & correspondence
- 8012160197 Requests that CESBAR preliminary design approval (PDA-2) be extended until NRC issues final design approval or application is withdrawn. Lack of approved ref design adds to uncertainty facing util.

 SCHTRER.A.E. C-E Power Systems. 80/12/11. ip. 07262:309.
- DOCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012270485 Responds to 800711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/04, 2pp.
- --B012220506 Forwards tabulation & summary of IE survey on low level waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.
 BANDART.R.L. Effluent Treatment Systems Branch. 80/11/06, Bpp.
- Q. Adjudicatory correspondence
- 8012240027 Order receiving into record applicant Exhibits 23,24 & 25 & NRC Exhibit 67 subj to right of parties to file objections w/ASLB within 10 days.

 * Atomic Safety and Licensing Board Panel. 80/12/16. 2pp. 07324:218.
- H. General correspondence
- 8012040296 Forwards info in response to 801029 ltr requesting licensing categories & info re floating nuclear plants. PURPLE.R.A. Division of Licensing. 80/11/17. 4pp. 07170:059.
- --8012040298 Requests info re facilities w/active CPs pending, license definitions & requirements for floating nuclear plants.

 DREY.L.A. Affiliation Unknown. 80/10/29, 1p, 07170:063.

- DOCKET STH-50-482 MOLF CREEK GENERATING STATION

 A. Application/construction stage documents & correspondence
- 8012160950 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREC-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT.D.G. Division of Licensing. 80/10/31. 7pp.
- 8012220358 Ltr to all CP & OL holders for BNRs re requirement for implementation of DDYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing, 80/11/04, 4pp.
- 8012080320 Informs that NRC will attend 801209-10 meeting re util internal technical review of FSAR Chapter 8. Requests that panel members be chosen from both senior working levels & engineering mgt & members of public be allowed to attend. TEDESCO.R.L. Assistant Director for Licensing. 80/11/21. ip. 07104-1964.
- --B012080336 Extends invitation to attend 801209-10 meeting re internal technical review of FSAR Chapter 8 concerning electric power.
 PETRICK.N.A. Standardized Nuclear Unit Power Plant System.
 80/10/17. 1p. 07194:197.
- 8012110658 Notification of 801209-10 meeting w/util in Gaithersburg, MD to conduct independent design review of FSAR.Chapter 8.

 STARK.R.M. Licensing Branch 1. 80/11/25. 2pp. 07224:315.
- --8012110667 Confirms NRC attendance at util 801209-10 technical review of FSAR, Chapter 8.
 TEDESCO, R. L. Assistant Director for Licensing, 80/11/21. 2pp.
- C. Utility Environmental Report (ER), amends & correspondence
- B0120B0577 Advises that 600219 CL stage environ rept is sufficiently complete based on evaluation of all info filed.
 EISENMUT.D.Q. Division of Licensing. 80/11/21. 4pp. 0718B: 196.
- 8012020093 Forwards environ rept. Vols 1 & 2. for Wolf Creek 1. KOESTER. G. L. Kansas Gas & Electric Co. 80/11/25. 2pp. 07137: 037.
- --B012020089 Environ rept. Vol 1. for Noif Creek 1. + Kensas Gas & Electric Co. 80/11/25. 325pp. 07137:039.
- --8012020093 Environ rept, Vol 2, for Holf Creek 1. + Kansas Gas & Electric Co. 80/11/25. 400pp. 07139:064.
- E012070289 Advises that distribution of environ rept was made to parties on encl list, KGESTER.O.L. Kansas Oas & Electric Co. 80/12/03. 3pp. 07201:102.
- 8012300371 Informs of docketing of environ rept, GL stage, for facility. Notices of receipt of application for facility GL, availability of applicant environ rept & consideration of issuance of facility GL encl.
 YOUNGBLOOD, B. J. Licensing Branch 1. 80/12/08. 3pp. 07359: 339.
- --B012300375 Notice of receipt of application for facility DL.of availability of applicant environ rept, of consideration of issuance of facility DL.& of opportunity for hearing. YOUNDBLOOD, B. J. Licensing Branch 1. 80/12/08. App. 07359:342.
- Q. Inspection reports, IE Bulletins & correspondence
- B012170731 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required. BEYFRIT.K.V. Region 4. Dallas, Office of the Director. B0/09/10. ip. 07264:153.
- 8012020757 Forwards 1E insp Rept 50-482/80-20 on 801007-10.No noncompliance noted. SEIDLE-N.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/10/23. 2pp. 07143:338.
- --E012020762 IE Insp Rept 50-452/80-20 on 801007-10. No noncompliance noted Major areas inspected const activities including site tour & observation of work Records for RCPB pipe welding reviewed.

 OILBERTI.D., HALL, R.E. Region 4, Dallas, Reactor Construction & Engineering Support Branch, CROSSMAN, M.A. Region 4, Dallas, Office of the Director. 80/10/22. 4pp. 07143:340,

- 8012170349 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. SEYFRIT.K V. Region 4, Dallas, Office of the Director. 80/10/30. tp. 67269:004.
- 8012170832 Forwards 1E Info Notice 80-39, "Malfunction of Solenoid Valves Kfg by Valcor Engineering Corp." No written response is required.

 SEYFRIT.K. V. Region 4, Dallas, Office of the Director. 80/10/31, 1p. 07266:023.
- 8012100513 Forwards IE Bulletin 80-21, "Valve Yotes Supplied by Malcolm Foundry Co. Inc." Written response required. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. BO/11/06. ip 07220:100.
- 8012030901 Forwards IE Info Natice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. SEYFRIT.K. V. Region 4. Dallas, Office of the Director. 80/11/07. 1p. 97150:163.
- 8012080675 Forwards IE Info Notice 80-41, "Failure of Suing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1," No response required. BEYFRIT.K.V. Region 4, Dallas, Office of the Director. BO/11/10, 1p. 07163:044.
- 8012040127 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 80/11/14. 1p. 07169:267.
- 8012050013 Forwards IE Bulletin 60-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 60/11/21. 1p. 0/173:059.
- 8012160078 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Soubber Fluid." No response required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 60/11/24. ip. 07262:124.
- 8012160112 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam inlet Flange." No written response required. SEYRIT, X. V. Region 4. Dailás. Office of the Director. 80/11/26. io. 07262:088
- 8012190318 Confirms receipt of 801125 ltr re Work Hold Agreement 13, issued 808120 to Daniel Intl. Corrective actions to be taken prior to agreement release include shifting responsibility for pipe cleanliness to installing const craft. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 80/11/26. 2pp. 07286:080.
- 8012300717 Updates 800820 response to 1E Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe." Fusion-welded pipe supplied by manufacturers other than four listed not subj to greater than allowable stresses. SEIKEN S. J. Standardized Nuclear Unit Power Plant System. 80/11/26. 2pp. 07357:294.
- S. Reportable occurrences, LERs & related correspondence
- 8012040403 Final deficiency rept, originally submitted 801027, regeneric design interferences between Bergen-Patterson pipe clamp assemblies & Pacific Scientific Co mating snubber assemblies Clamps will be modified or replaced.

 BELKEN, S. J. Standardized Nuclear Unit Power Plant System. 80/11/26.

 Bpp. 07169:239.
- 8012100440 Interim deficiency rept re failure of Nestinghouse 3-inch gate valves to close first reported on 801030, Add1 info is still being obtained & corrective mods are being developed. Followup or final rept will be sent in first quarter 1981. PETRICK.N.A 3 Standardized Nuclear Unit Power Plant System. 80/11/26. 2pp. 07230:159
- 8012100174 PNO-1V-BO-39: by G01125 jtr.util notified Region 4 that work-hold agreement re safety-related piping issued to Daniel Inti for corrective action to pipe cleanliness conditions. Reactor coolant piping excluded.
 HU8ACFK.N.O. CRUSSMAN.K.A. Region 4. Dallas. Office of the Director. 89/12/01. ip 07218:302.

- DOCKET STR-50-483 CALLDUAY PLARE, WRIT I
- A. Application/construction stage documents & correspondence
- 80/12160050 Ltr to operating plant licenses.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licenses confirmation in 45 days that Encl I implementation cates will be net. EISEMHUT.D O. Division of Licensing. 80/10/31. 7pp.
- 80:12270358 Ltr to all CP & O. holders for BNRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISENMUT.D.G. Division of Licensing. 80/11/04. 4pp.
- 8012080320 Informs that NRC will attend 801209-10 meeting re util internal technical review of FSAR Chapter B. Requests that panel members be chosen from both senior working levels & engineering mgt & mombers of public be allowed to attend. TEDESCO.R.L. Assistant Director for Licensing. 80/11/21. 1p. 07194:196.
- --8012030335 Extends invitation to attend 801209-10 meeting ro internal technical review of FSAR Chapter 8 concerning electric power.
 PETRICK, N. A. Standardized Nuclear Unit Power Plant System.
 80/10/17. 1p 07194.197.
- 8012310134 Confirms agreement re E01218 meeting in St Louis,MO to discuss regional evaluation of licensee regulatory performance.

 KEPPLER,U.O. Region 3, Chicago, Office of the Director. 80/11/21. ip 07371:180.
- 8012110658 Notification of 801207-10 meeting w/otil in Caithersburg,MD to conduct independent design review of FSAR.Chapter 8. STARK,R.B. Licensing Branch 1. 80/11/25. 2pp. 07224:315.
- --80121(0/67 Confirms NRC attendance at util 801207-10 technical review of FSAR, Chapter 8.
 TEOESCO. R. L. Assistant Director for Licensing. 80/11/21. 2pp.
- C. Utility Environmental Report (ER), amends & correspondence
- BO12190565 Advises that environ rept is sufficiently complete for docketing w/realization that substantive deficiencies may exist that will need to be corrected during review. Distribution list enc! EISENHUT.D.O Division of Licensing. 80/11/26. 4pp. 07273:308.
- 8012190484 Forwards environ rept in response to ARC 801126 request.Rept suppls 791019 & 800822 submittals 475 encl.
 8RYAN, J. K. Union Electric Co. 80712715. 3pp. 07275:298.
- 8012190494 Forwards affidavit of eye re distribution of environ rept. in rasponse to NRC 801126 request. BRYAN.J.K. Union Electric Co. 80/12/15. 3pp. 07285:317.
- G. Adjudicatory correspondence
- 8012300505 Petition to interveno submitted by ANS MO-KS Section reissuance of facility OL Soc members are concerned as citizens & profs in energy matters & are aware of current natl crisis. Resumes of ICM Miller & D Mayer and L MILLER, M. H. American Muclear Society 69/12/19, 21pp. 07359:215.
- H. General correspondence
- 8012300443 Forwards M Hieronymus ltr apposing issuance of permit to dump radioactive meth into MD River Requests response. DAMFORTH J. C. Senate. 80/12/16, 5pp. 07308:001.
- 8012300610 Notifie: that environ rept sent to Dept of Army, Corps of Engineers, KS City, Md. per D Eisenbut 801126 request.
 BRYAN, J. K. Union Electric Co. 60/12/22, 1p. 07346; 154,
- Q. Inspection reports, IE Bulletine & correspondence
- 8012120287 Forwards IE Insp Rept 50-463/80-25 on 800730-1003 & natice of violation. FIDRELLIG. Region S. Chicago, Reactor Construction & Engineering Support Scanch. 80/10/20. 2pp. 97231.287.

- --8012120273 Notice of violation from insp on 800930-1003.

 # Region 3: Chicago: Office of the Director. 80/10/17. 1p. 07231:289.
- --8012120300 IE Insp Rept 50-483/80-25 on 800930-1003.Noncompliance noted:provision of 100FR21 not included in purchase order & welding procedure spec not at work location.
 #ESCOTT.H.M., NEISLER, J.H., XNOP,R.C. Region 3, Chicago, Office of the Director. 80/10/17, 7pp. 07231:290.
- 8012170553 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/10/24, 1p. 07264:290.
- 8012020/43 Forwards three Performance Appraisal Branch insp repts & mgt evaluation tree w/user guide so that facility can compare program to program already reviewed & make appropriate adjustments. W/o enci.

 KEPPLEN. J. O. Region 3. Chicago. Difice of the Director. 80/11/18.
- 8012040274 Ack receipt of 801030 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-485/80-22. FIGRELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/18. 2pp. 07163:279.
- --8012040303 Responds to NRC 860929 itr re violations noted in IE Insp Rept 50-483/80-22. Corrective actions: indoctrination film re concrete vibrating & onsite guidance of craft personnel to be shown. BRYAN, J. K. Union Electric Co. 80/10/30. 5pp. 07163:281.
- 8012240026 Forwards 1E Insp Rept 50-483/80-26 on 801001-31.No noncompliance noted. FIGRELLI,G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/11/19. 2pp. 07324:203.
- --8012240030 IE Insp Rept 50-483/80-26 on 801001-31 No noncompliance noted Major areas inspected protection of reactor vessel, mat1 lay down & storage areas.

 HANSER, W. A., XNDP, R. C. Region 3, Chicago, Office of the Director, 83/11/18. Gpp. 07324: 210.
- 8012040668 Ack receipt of 801105 ltr informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-483/80-07. FIGRELLI, 0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/11/20. 1p. 07169:067.
- --8012040672 Responds to NRC 800426 ltr re violations noted in IE Insp Rept 50-483/80-07. Corrective actions: Class IE cable tray sys has been designed & installed. Use of commercial grade tray sys incorporated. BRYAR. J. K. Union Ejectric Co. 80/11/05. 2pp. 07169: 068.
- 8012040664 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. KEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/11/21. 2pp. 07166:351.
- 80120800/6 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydravlic Snubber Fluid." No written response required. KEPPLER.J. G. Region 3. Chicago. Office of the Director. B0/11/24. 2pp. 07182: 238.
- 8012110630 Responds to NRC 801020 ltr re violations noted in IE Insp Rept 90-483/80-25. Corrective actions: change order to purchase number was initiated & controlled pamphlets are being issued to welders. BRYAN, J. K. Union Electric Co. 80/11/14. 3pp. 07227:191.
- 8012110521 Act receipt of 801114 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/80-25. FIGRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/11/25. ip. 07227:170.
- 8012170754 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER.J. G. Region 3, Chicago, Office of the Director. 80/11/26. lp. 07265:080.
- 8012300717 Updates 800820 response to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME GA-312. Type 304 Stainless Steel Pipe." Fusion-welded pipe supplied by manufacturers other than four listed not subj to greater than allowable stresses. SEIKEN, S. J. Standardized Nuclear Unit Power Plant System. 80/11/26. 2pp. 07359: 294.

- S. Reportable occurrences, LERs & related correspondence
- 8012040403 Final deficiency rept.originally submitted 801027, regeneric design interferences between Bergen-Patterson pipe clamp assemblies & Pacific Scientific Co making snubber assemblies. Clamps will be modified or replaced.

 SEIKEN.S.J. Standardized Nuclear Unit Power Plant System. 80/11/26.
 8pp. 07169:238.
- 8012100440 Interim deficiency rept re failure of Westinghouse 3-inch gate valves to close first reported on 801030. Addl info is still being obtained & corrective mods are being developed. Follouup or final rept will be sent in first quarter 1781. PETRICK, N. A. Standardized Nuclear Unit Power Plant System. 80/11/26. 2pp. 07220:159.
- 8012030726 Final deficiency rept re use of improper preheat of heavy structural members prior to wolding initially reported on 800418. Physical test program has been conducted Neids are acceptable as is.
 BRYAN, J. K. Union Electric Co. 80/11/28. Spp. 07149:307.
- DOCKET STN-50-484 TYRONE ENERGY PARK, UNIT 1
- G. Adjudicatory correspondence
- B012100047 Motion in apposition to Dakota Commission's petition for reconsideration of B01103 order denying Dakota request for hearing & refusing to defer revocation of CP.
 BAXTER.T.A. Shaw, Pittman, Potts & Troubridge. BAXTER.T.A.
 Northern States Power Co. B0/11/26 Spp. 07219:072.
- 8012100154 Answer in opposition to Dakota Commissions' 801113 petition for reconsideration. Requests denial of petition & affirmation of 801103 order declining to defer revocation of CP & denying hearing request. W/Certificate of Svc. 8VRNS, 8. Rulemaking & Enforcement Division. 80/12/01. 12pp. 07219: 286.
- 8012300399 Order denying Dakota Commissions' 801113 petition for reconsideration. CHILK, S. J. Office of the Secretary of the Commission. 80/12/24. 1p. 07357:181.
- DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT 1

 A. Application/construction stage documents & correspondence
- GO12140050 Ltr to operating plant licensees.DL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be set. EISENMUT.D.O. Division of Licensing. GO/10/31. 7pp.
- Q. Inspection reports, IE Bulletins & carrespondence
- 8012170391 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Gladding." No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/30, 1p. 07269:065.
- 8012120195 Forwards IR Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. CRIER.B.H. Region I. Philadelphia, Office of the Director. 80/11/06. ip. 07228:300.
- 80120308-39 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuritation " No written response required. ORIER. 8. H. Region 1. Philadelphia. Office of the Director. 80/11/07. 1p. 07150:256
- 8012080548 Forwards 16 In/o Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Resse Unit 1." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director, 80/11/10. 1p. 07182.303.
- 8012040073 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ORIER, B. M. Region in Philadelphia, Office of the Director. BO/11/14. ip. 07157:293.

- 8012220702 Advises that unitten response is required to IE Bulletin 80-23. "Failures of Sciencid Valves Mrg by Valcor Engineering Curp "First paragraph enconeously stated no written response required GRIER, B. M. Region 1. Philadelphia, Office of the Director. 80/11/19 ip 07293-124
- 8012040607 Forwards IE Belletin 80-24, Prevention of Damage Due to Mater Leakage Inside Containment 'No written response required.
 GRIER B. Region 1, Philadelphia. Office of the Director.
 80/11/21. 2pp 07165-278
- 8012050601 Forwards IE Info Notice 80-47. "Effect of Radiation on Hydraulic Souther Fluid | No written response required. GRIER, B.H. Region i, Philadelphia, Office of the Director. 80/11/24. ip. 07174:078
- DOCKET STN-50-486 CALLOWAY PLANT, URIT 2
- A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees. OL applicants & CP holder Forwards NUREG-0737 re TM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be not. EISERMUT. D. G. Division of Licensing 86/10/31 7pp.
- 8012220358 Ltr to all CP 1 (N. holders for bulks re requirement for implementation of QDVN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads EISERPUT, D. G. Division of Licensing 20/11/04, 4pp.
- 8012080320 Informs that NFC will attend 801209-10 meeting re util internal technical review of FSAF Chapter 8. Requests that panel members be chosen from both senior ucrking levels & engineering mgt & members of public be allowed to attend. TECESCO.R.L. Assistant Director for Licensing. 80/11/21. ip. 07194:1764
- --8012080336 Extends invitation to attend 801209-10 meeting re-internatechnical review of PSAR Chapter 8 concerning electric power.
 PETRICK, N. A. Standardized Nuclear Unit Power Plant System.
 80/10/17. ip. 07194, 197.
- 8012110558 Notification of 801234-10 meeting w/util in Gaithersburg, MI to conduct independent design review of FSAR, Chapter 8. STARK, R. M. Licensing Branch 1. 80/11/25 2pp. 07224:315.
- --8012119667 Confirms NRC attendance at util 801209-10 technical revis of FSAR, Chapter 8 TEDESCO, R.L. Assistant Director for Licensing. 80/11/21. 2pp.
- C. Utility Environmental Report (ER), amends & correspondence
- 8012190655 Advises that environ rept is sufficiently complete for docketing w/realization that substantive deficiencies may exist that will need to be corrected Juring review. Distribution list encl EISENGUT, D. 0. Division of Licensing 80/11/26 4pp. 07273:308.
- 8012190494 Forwards environ rept in response to MRC 801126 request.Res suppls 791019 & 800852 submittals M/o encl. BRYAN.J.K. Union Electric Co. 80/12/15. 3pp. 07875:298.
- 6012190494 Forwards affidants of averse distribution of environ mepto in response to NRC 801125 request BRYANJIX. Union Flecters Co. 80/12/15. 3pp. 07285:317.
- G. Adjudicatory correspondence
- 8012300505 Petition to Intervene submitted by ANS MO-KS Section, reissuance of facility OL Sections are concerned as citizens & profs in amongy matters & are awars of current nationals assumes of kM Miller & W Meyor encl.
 MILLER, W. H. American Suclear Society 80/12/19, 21pp. 07359:215.
- H. General correspondence
- 8012300443 Forwards K Hieronymus Itr opposing issuance of permit to dump radioactive matl into MO River Requests response. DAMPORTH.J.C. Senate. 80/12/16. Sup. 07308:001.

- 8012300610 Natifies that environ rept sent to Dept of Army, Corps of Engineers, KS City, MO, per D. Eisenhut 801126 request. BRYANA J. Union Electric Co. 80712/28 1p. 07346:154
- G. Inspection reports, IE Sulletins & correspondence
- 8012170593 Forwards IE Info Notice 89-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No unitten response required.

 KEPPLER.J.G. Region 3. Chicago, Office of the Director. 80/10/24.

 1p. 67264:270.
- 8012020743 Foruards three Performance Appraisal Smanch inspirets & mgt evaluation these wideer guide so that facility can compare program to program already reviewed & make appropriate adjustments W/o encl.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/18. App.
- 8012040564 Forwards IE Bullotin 80-24. "Prevention of Danage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER, J. G. Region 3. Chicago. Office of the Director. 80/11/21. 200. 07166: 351
- 8012080276 Forwards 16 Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid " No written response required. KEPPLER.J.G. Region 3. Chicago. Office of the Director. 80/11/24. 2pp. 07182:228
- 8012170754 Forwards IE Info Notice 80-29. Suppl 1. "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLCR.J. G. Region 3. Chicago. Office of the Director 80/11/26. 1p. 07265:080.
- 8012300717 Updates 800820 response to IE Bulletin 79-03A. "Longitudinal Held Defects in ASME 54-312 Type 304 Staintess Steel Pipe." Fusion-welded pipe supplied by Familiaturers other than four listed not subj to greater than allocable stresses. SEIKEN.S.J. Standardized Nuclear Weit Power Plant System. 80/11/26. 2pp. 07359:294
- S. Reportable occurrences: LERs & related correspondence
- 8012040403 Final deficiency reptroriginally submitted 801027, regeneric design interferences between Rergen-Patterson pipe clamp assemblies & Pacific Scientific Co mating snubber assembles Clamps will be modified or replaced.

 SEIKEM.S.J. Standardized Nuclear Unit Power Plant System. 80/11/26. 8pp 07167:234
- 8012100440 Interim deficiency rept re failure of Nestinghouse 3-inch gate valves to close first reported on 801030. Add1 info is still being obtained & corrective nods are being developed. Follows or final rept will be sent in first quarter 1981. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 80/11/26. 2pg. 07220:157
- DOCKET STN-50-488 PERMINS NUCLEAR STATION, UNIT 1
 G. Adjudicatory correspondence
- 8012230329 Order granting applicant motion for extension until 801231 to file brief. Time for NRC to file brief is extended until 810112.
 BISHOP.C.J. Administrative Branch. 60/11/25. 2pg. 07318:329,
- H General correspondence
- 8012040956 Forwards info in response to B01029 ltr requesting licensing categories & info re floating nuclear plants. PURPLE.R.A. Division of Licensing, 90/11/17, 4pp. 07170:059.
- --8012040278 Requests info me facilities w/active CPs pending,license definitions & requirements for Floating nuclear plants.

 DREY(L.A. Affiliation Unknown, 80/10/27, 1p.
- G. Inspection reports: If Bulletins & correspondence
- 8012150179 Forwards 16 Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Ficoding At Indian Point Unit 2." No Unitten response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 80/10/24. ip. 07240:291.

- 8012170823 Forwards IE Info Notice 80~38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY. J.P. Region 2, Atlanta, Office of the Director. 80/10/30. 1p. 07266:256
- 8012170595 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 80/10/31, 1p. 07264:126.
- 8012230057 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No unfitten responso required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. GO/10/31. 1p. 07313:226.
- 8012110760 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Matcolm Foundry Co. Inc." Written response required. D'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/06. 1p. 07225:195.
- 8012030862 Forwards IE Info Notice 80-40, "Excessive Nitrogen Bupply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07. 1p. 07150:113.
- B012080948 Forwards JE Info Notice 80-41, "Failure of Bwing Check Valve in Decay Heat Removal Sys at Davis Besse Unit i." No response required.

 O'REFLLY, J. P. Region 2. Atlanta, Office of the Director, 90/11/10.

 1p. 07182:279.
- 8012040164 Forwards IE Bullotin 80-23. "Failures of Solemoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. 0'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/14. 1p. 0/158:077.
- 8012050048 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/11/21.

 1p. 07173:111.
- 8012050626 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24, 1p. 07174:123.
- 8012170300 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Tarry Turbine Stoam Inlet Flange." No written response required.

 O'REIULY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.

 1p. 07268:085.
- DOCKET STN-90-489 PERKING NUCLEAR STATION, UNIT 2

 O. Adjudicatory correspondence
- 8012230329 Order granting applicant motion for extension until 801231 to file brief. Time for NRC to file brief is extended until 810112 BISHOP.C. J. Administrative Branch. 80/11/25. 2pp. 07318: 329,
- H. General correspondence
- 8012040256 Forwards info in response to 801029 ltr requesting licensing categories & info re floating nuclear plants. PURPLE,R. A. Division of Licensing. 80/11/17. 4pp.
- --8012040298 Requests info re facilities w/active CPs pending, license definitions & requirements for floating nuclear plants.

 DREY, L. A. Affiliation Unknown. 80/10/29, 1p.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012150179 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
 0'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24.
 1p. 07240: 291.
- B012170803 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. B0/10/30. ip. 07266:256

- 8012170595 Forwards [E Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required.

 O'REILLY, J.P. Region 2: Atlanta, Office of the Director. 80/10/31.

 1p. 07264:126.
- 8012230057 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators" No written response required. D'REILLY, J. P. Region 2, Atlanta, Diffice of the Director. 80/10/31. is.
- 8012110760 Forwards IE Sulletin 80-21, "Valve Yokes Supplied by Małcolm Foundry Co.Inc." Written response required. D'REILLY, P. Region 2. Atlanta, Office of the Director. 80/11/06. 1p. 07225:175.
- 8012030962 Forwards IE Info Notice 80~40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. D'REKLLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07. 16.
- 8012080948 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/ii/10.

 19. 07182:279.
- 8012040164 Forwards IE Bulletin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J. P. Region 2. Atlanta, Diffice of the Director. 80/11/14.
- 8012090048 Forwards IE Bulletin 80-24, 'Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21.

 1p.
- 8012050626 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/24. 1g. 07174:123.
- B012170500 Forwards IE Info Notice B0-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. D'REJLLY, J. P. Region 2. Atlanta. Office of the Director. B0/11/26.
- DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3
 G. Adjudicatory correspondence
- 8012230329 Order granting applicant motion for extension until 801231 to file brief. Time for NRC to file brief is extended until 810112.
 810112.
 BISHOP.C.J. Administrative Branch. 80/11/25. 2pp. 07318:329.
- H. General correspondence
- B012040256 Forwards info in response to B01029 ltr requesting licensing categories & info re floating nuclear plants. PURPLE,R.A. Division of Licensing. B0/11/17. 4pp.
- --8012040278 Requests info re facilities w/active CPs pending, license definitions & requirements for floating nuclear plants.

 DREY, L. A. Affiliation Unknown, 80/10/29, ip.
- Q. Inspection reports: IE Bulletins & correspondence
- 80:2150179 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/10/24, 1p. 07240:291.
- 8012170803 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30. lp. 07265:235.

- 8012170395 Forwards IE Info Notice 80-39. "Malfunction of Bolenoid Valves Big by Valcor Engineering Corp." No written response required.
 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/31.
 1p. 07264:126.
- 8012230057 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/36.
- 8012110760 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malco Foundry Co.inc." Written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/06. lp. 07225:192
- BO12030862 Forwards IE info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurisation " No written response required. D'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/07.
- 8012090248 Forwards 1E info Notice 80-41, "Failure of Swing Check , Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 O'REILLY, J.P. Region 2: Atlanta, Office of the Director. 80/11/10.

 ip. 07182:279.
- 8012040164 Forwards IE Bulletin 80-23. "Failures of Sciencid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REPLLY, J. P. Region 2. Atlanta, Diffice of the Director. 80/11/14.
- B012050048 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'REJLLY, J. P. Region 2, Atlanta. Office of the Director. 80/11/21
- 8012050626 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24 ip. 07174:123.
- 8012170500 Forwards IE Info Notice 80-29. Suppl 1. "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/26
- DOCKET STN-50-471 CHEROKEE NUCLEAR STATION, UNIT 1

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensess. BL applicants & CP holder Forwards NUREG-0737 re Thi action plan requirements. Requests operating reactor licenses confirmation in 45 days that Encl 1 implementation dates will be net.

 EISERHUT, D. O. Division of Licensing. B0/10/31. 7pp.
- Q. Inspection reports, IE Bulletins & correspondence
- B012150179 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/10/24
- B012170803 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/30 io.
- 80:2170595 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valvas Kég by Valcor Engineering Corp." No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31
- 8012230057 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. D'REILLY J.P. Region 2. Atlanta, Office of the Director. 80/10/3

- 8012:10/60 Forwards IE Bulletin 80-2:, "Valve Yoles Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY.J P. Region 2. Atlanta, Office of the Director. 80/11/06.
- 8012030952 forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLV.J P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p. 07150.113.
- B012030948 Forwards IE Info Notice B0-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Resse Unit 1." No response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. B0/11/10.
- 8012040164 Forwards JE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. 0'REIULY, J.P. Region 2, Atlanta, Office of the Director. 80/11/14. 1p. 07158:077.
- 8012050048 Forwards IE Bulletin 80-24. *Prevention of Damage Due to Mater Leakage Inside Containment. *No written response required.

 O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/21.
- 8012050626 Forwards IE Inio Notice BO-42. "Effect of Radiation Hydraulic Snubber Fluid " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24.
- 8012170500 Forwards IE Info Notice 80-29. Suppl i, "Broken Studs on Terry Turbine Steam inlet Flange" No written response required.

 O'REILLY, J.P. Region 2- Atlanta, Office of the Director. 80/11. CILLY, J.P. Region 2. Atlanta, Office of the Director, 80/11/26. 07269:085
- DOCKET STN-50-492 CHERCKEE NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8012160059 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISENHUT.D. C. Division of Licensing. 80/10/31. 7pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012150179 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Fisoding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta: Office of the Director. BO/10/24.
- 80:2170803 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/30.
- 8012170595 Forwards IE Info Notice 80-39. "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required.

 O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/10/31.
- 8012230057 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No unitten response required, d'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31, 1p. 07313:226.
- 8012110/60 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REBLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.
- 8012030862 Forwards IE Info Notice 80-40, "Ercessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurisation "No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/07.

- 8012030248 Forwards JE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Resse Unit 1." No response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/10.
- 8012040164 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/14.
- 8012050048 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response raquired.

 3'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21.
 1p. 07173:111.
- 8012050626 Forwards IE Info Notice 80-42, "Effect of Radiation Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24.
- 8012170500 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. ILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26. O'RETLLY, J. P.
- DOCKET STN-50-493 CHEROXEE NUCLEAR STATION, UNIT 3 A Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- G. Inspection reports, IE Bulletins & correspondence
- B012150177 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
 O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/10/24. Region 2. Atlanta. Office of the Director. 80/10/24.
- 8012170803 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30.
- 8012170595 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Higg by Valcor Engineering Corp." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012230057 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/3 ILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31. 07313:226.
- 8012110740 Forwards IE Builetin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required.
 D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.
- 8012030862 Forwards IE Info Notice 80-40, "Excessive Nitrogen Bupply Pressure Actuates Bafety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07.
- 8012090249 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Resse Unit 1." No response required. O'REUJY, J. P. Region 2, Atlanta, Office of the Director, 80/11/10.
- 8012040164 Forwards IE Bulletin 80-23, "Failures of Bolenoid Valves Mêg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. 0*REILLV.J.P. Region 2, Atlanta, Office of the Director. 80/11/14. 1p. 07158:077.

- 8012050048 Forwards IE Bulletin 80-24, 'Prevention of Damage Due to Water Leakage Inside Containment." No written response required. G'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/21. ip. 07173:111.
- ip. 07173:111.
- 8012050626 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24. 1p.
- 8012170500 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam [nlet Flange." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.
 10.
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees.GL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISE(BHUT, D. G. Division of Licensing, 80/10/31, 7pp.
- 8012080350 Discusses 800728 response to 800430 show cause order.Limited work restart in certain selected areas has been authorized. Bafety-related complex concrete const corrective actions are being reviewed.

 STELLO.V. Office of Inspection & Enforcement. Diffice of the Director. 80/11/21. 3pp. 07196:064.
- 8012100638 Ack receipt of 801002 & 1119 ltrs re actions taken concerning initiating ASME welding activities. Corrective actions have been verified & approved. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/21. 2pp. 07220:068.
- G. Adjudicatory correspondence
- 801224000B Notices of withdrawal from 5 appearance in proceeding. LOWERRE.R.W., BERWICK, B.E. Texas, State of BO/11/24, 2pp. 07324:196.
- BO12080005 Requests advice re Citizens Concerned About Nuclear Power. Inc discovery requests for names of inspectors & employees involved in harassment. Stello closed door statement & investigator identified items. Views needed by B01201. CHRISTENBURY.E. Hearings Division. 80/11/25. 4pp. 07187:001.
- SO12270112 Response to Citizens Concarned About Nuclear Power 801111 request for info.Request does not comply w/10CFR2.Documents should be available at LPBR.Certificate of Svc encl.
 BORDENICK.B.M. Hearing Branch 4. B0/12/01. 4pp. 07343:085.
- B012300477 Becond prehearing conference order setting forth issues accepted for consideration at expedited QA/QC hearing. Hearings will be held in Bay City, TX. List of QA/QC issues encl.

 BECHHOEFER. C. Atomic Safety and Licensing Board Panel. 80/12/02. 12pp. 07359:145.
- 8012270023 Ack receipt of 800910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-19 & 50-499/79-19 & in response to NRC 800430 order to show cause.

 SEIDLE-M.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/12/03. ip. 07336:315.
- --8012220030 Discusses violations noted in IE Insp Repts 50-498/79-19 & 50-479/79-19 & to 800430 order to show cause in preparation for 800913 meeting. W/o encl documentation re welding program.

 UPREA.Q.M. Houston Lighting & Power Co. 80/09/10. 2pp.
- 8012230053 Third set of interrogatories & requests for production of documents to Citizens Concerned About Nuclear Power Inc.
 Certificate of Svc encl.
 HUDSON.T.B. Houston Lighting & Power Co. 80/12/05. 3pp.
 07311:250.
- 8012310005 Add1 response to Citizens Concerned About Nuclear Power 801024 & 28 requests for info.Discusses & forwards requested insp repts & related info.Certificate of Svc encl. BORDENICK, B. M. Hearing Branch 4. 80/12/08. 200;p. 07362:020.

- B012300004 Responds to B01201 request for intervention.100FR2 encl.W/o encl.
 REIS.E.J. Hearing Branch 3. 80/12/11. tp. 07356:084.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012170329 Forwards Amend 14 to FSAR. OFREA: G. W. Houston Lighting & Power Co. 80/12/15 4pp. 07270:032.
- --8012170333 Amená 14 to FSAR. GPREA.G.N. Houston Lighting & Power Co. 80/12/15. 100pp. 07270:036.
- M. Antitrust correspondence
- 8012030458 Request to withdraw 830731 petition to intervene due to agreement reached w/Central & South West Corp re proposed dc ties. Certificate of Svc encl U'MFJL.R.A. Texas Border Cooperatives. 80/11/24. App. 07149:347.
- E012100039 Notice of appearance on behalf of Central & South West Corp. Central Power & Light Co.PSC of GX. Southwestern Electric Power Co & Rost TX Utils Co Certificate of Svc encl. THORNYON.P. Isham. Lincoln & Beale. THORNYON.P. Central & South West Corp. THORNYON.P. Carolina Power & Light Co. 80/11/26, 5pp. 07219:067.
- 8012300318 Memorandum in support of 800915 proposed settlement license conditions & response to Public Utils Board of City of Brownsville 801112 opposing comments Certificate of Svc enc. 80UMKNIGHT, J. A. Houston Lighting & Power Co. 80UKNIGHT, J. A. Baker & Botts, 80/12/01, 22pp. 07357:097.
- 8012170672 Response to Public Utils Board of Brownsville 801112 comments on proposed license conditions & statement pursuant to ASLB 801024 requests at prehearing conference. Certificate of Svc encl. KMOTTS, J. B., AMEARN, C. D. Teras Utilities Generating Co. KNOTTS, J. B., Debayoise & Liberman. 80/12/03, 59pp. 07264:063.
- 8012300013 Comments on & request for approval of encl settlement license conditions.

 CHANANIA:F.D., BLUME, M.B. Antitrust Division. LEWIS, S. H. Hearing Branch R. 80/12/03. 45pp. 07351:301.
- --8012300024 Forwards executed stipulation re license conditions. BALGUOH.R.C. Austin TX. 80/09/26. 1p. 07352:004.
- B012300225 Response to intervenor Public Utils Board of City of Brownsville, TX opposition to proposed settlement license conditions. Central antitrust issues are adequately addressed in license conditions. ASLB should approve conditions.

 STAHL. D. M. Central & South Nest Corp. STAHL. D. M. Isham. Lincoln & Beale. B0/12/03. 16pp. 07357,009.
- --8012030329 Supplemental response, submitted to FERC, on DOJ 800917 petition to intervene DDJ position is irrelevant to approval of supplemental offer of settlement & should be denied w/o prejudice. Supporting info & Certificate of Svc encl. STAHL, D. K. Central & South West Corp. STAHL, D. K. Isham, Lincoln & Beale. 80/11/25, 23pp. 07357:025.
- 8012300250 Response to intervenor Public Utils Board of City of Brownsville 801112 opposition to proposed settlement license conditions, Conditions are in public interest imposition will not danage intervenor. Certificate of Svc encl. FABRIKARF, R. MCMILLEN, N. H., DOPSOVIC, D. A. Justice, Dept. of. 80/12/03. 24pp. 07358:086.
- 8012230272 Order granting TX Border Cooperatives 801124 petition for leave to withdraw 800731 petition to intervene. MILLER-M.E. Atomic Safety and Licensing Board Panel. 80/12/04. 2pp. 07317:077.
- 8012270163 Corrects typographical error in Certificate of Svc.encl to 801203 memorandum in support of proposed settlement license conditions. Date of svc. should be 801203. M/Certificate of Svc. GREEN, D. G. Houston Lighting & Power Co. 80/12/04. Spp. 07344:144.
- 8012300251 Joint motion to make corrections to BC0915 proposed settlement license conditions. Also moves for leave to file encl conformed proposed license conditions. Certificate of Svc encl.
- CHANAMIA.F.D. Antitrust Division. ← Justice Dept. of. ★ Te Utilities Generating Co. BO/12/22, 20pp. 07358:110.



- E012030655 Third interim deficiency rept first reported on 800411, restop work order on safety-related welding. Discusses current status of safety-related welding. Forwards thronology of ASME/AWS Di. 1 welding restart correspondence.

 OPREA.O.N. Houston Lighting & Power Co. 80/11/25. 7pp. 07151: 259.
- 8012030666 Fifth interim deficiency rept.first reported on 800320,re broken tie-down studs in containment bldg polar crame rail sys. Repairs in progress & completion expected by late Dec 1530.Next rept to be submitted by 810401. CPREA.G.W. Houston Lighting & Power Co. 80/11/25. 4pp. 07151:271.
- 8012190418 Third interim deficiency rept.originally reported on 800321, re nonconforming backfill matl areas around power block. Provides status of structural backfill investigation & notes activities completed by independent review committee. OPREA.G. U. Houston Lighting & Power Co. 80/12/12. 6pp. 07285:308.
- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2
- A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be met. EISENHUT, D.O. Division of Licensing. B0/10/31. 7pp.
- 8012080350 Discusses 800722 response to 800430 show cause order.Limited work restart in certain selected areas has been authorized. Safety-related complex concrete const corrective actions are being reviewed. STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/11/21. 3pp. 07194:044.
- 8012100638 Ack receipt of 801002 & 1119 ltrs re actions taken concerning initiating ASME welding activities. Corrective actions have been verified & approved.

 SEYFRITK.K.V. Region 4. Dallas, Office of the Director. 80/11/21.
 2pp. 07220:068.
- G. Adjudicatory correspondence
- 8012240008 Notices of withdrawal from & appearance in proceeding. LOWERRE, R. W., BERWICK, B. E. Texas, State of. 80/11/24. 2pp. 07324:196.
- 8012080005 Requests advice re Citizens Concerned About Nuclear Power, Inc discovery requests for names of inspectors & employees involved in harassment Stello closed door statement & investigator identified items. Views needed by 801201.
 CKRISTENBURY, E. Hearings Division. 80/11/25. 4pp. 07187:001.
- 8012290112 Response to Citizens Concerned About Nuclear Power 801111 request for info.Request does not comply w/10CFR2.Documents should be available at LPDR.Certificate of Svc enci.
 BDRDENICK.8.M. Hearing Branch 4. 60/12/01. 4pp. 07343:085.
- B012300477 Second prehearing conference order setting forth issues accepted for consideration at expedited QA/QC hearing. Hearings will be held in Bay City, TX. List of QA/QC issues enci.

 BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 80/12/02. 12pp. 07359: 145.
- --8012220030 Discusses violations noted in IE lnsp Repts 30-498/79-19 & 50-499/79-19 & to 800430 order to show cause in preparation for BOD913 meeting. W/o encl documentation re welding program.

 OPREA: O. W. Houston Lighting & Power Co. 5FN-V-0110. 80/09/10.
- B012230053 Third set of interrogatories & requests far production of documents to Citizens Concerned About Nuclear Power, Inc. Certificate of Svc encl. HUDBON, T.B. Houston Lighting & Power Co. 80/12/05. 3pp. 07311:250.
- 8012310005 Add1 response to Citizens Concerned About Nuclear Power 801024 & 28 requests for info.Discusses & forwards requested insprepts & related info.Certificate of 8vc encl. BDRDEMICK, B. M. Hearing Branch 4. 80/12/08, 200pp. 07362:020.

- B012300004 Responds to 801201 request for intervention.10CFR2 encl. W/c encl. encl. REIS.E.J. Hearing Branch 3. 80/12/11. 1p. 07956:084.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012170329 Forwards Amend 14 to FSAR.

 OPREA.G.U. Houston Lighting & Power Co. 80/12/15, 4pp. 07270:032
- --8012170333 Amend 14 to FSAR. GREA.G.N. Houston Lighting & Paper Co. 80/12/15. 100pp. 07270:036.
- M. Antitrust correspondence
- 8012030458 Request to withdraw 800731 petition to intervene due to agreement reached w/Central & South West Corp re proposed do ties. Centificate of Svc encl.
 O'NEILLR.A. Texas Border Cooperatives. 80/11/24. 6pp.
- 8012100037 Notice of appearance on behalf of Central & South West Corp Central Power & Light CorpSC of OK. Southwestern Electric Power Co & Rest TX Utils Co. Certificate of Svc encl. THORNTON, P. Isham, Lincoln & Seale, THORNTON, P. Public Service Co of Oklahoma, THORNTON, P. West Texas Utilities Co. 80/11/26. Spp.
- 8012309318 Memorandum in support of 800915 proposed settlement license conditions & response to Public Utils Board of City of Brownsville 801112 apposing comments Certificate of Svc encl.

 BOURNIGHT, J.A. Houston Lighting & Power Co. 80/12/01. 22pp.
- 8012170572 Response to Public Utils Board of Brownsville B01112 comments on proposed license conditions & statement pursuant to ASLB 801024 requests at prehearing conference. Certificate of Svc encl. KNOTTS-J.S. Texas Utilities Generating Co. AHEARN.C.D. Debevoise Liberman. 80/12/03. 59pp.
- 8012300013 Comments on & request for approval of encl settlement license conditions.

 CHANANIA, F. D., HODGDOW, A. Antitrust Division. 80/12/03. 45pp.
- --8012300024 Forwards executed stipulation re license conditions. BALGUGH, R. C. Austin, TX. 80/09/26. ip. 07352:004.
- BO12300225 Response to intervenor Public Utils Board of City of Brownsville,TX opposition to proposed settlement license conditions, Central antitrust issues are adequately addressed in license conditions, AELB should approve conditions.

 STAHL, D. M. Central & South West Corp. 80/12/03. 16pg.
- --8012300227 Supplemental response, submitted to FERC, on DBJ 800917 petition to intervene, DBJ position is (relevant to approval of supplemental) offer of settlement & should be denied w/o prejudice. Supporting info & Centificate of Svc encl.

 STAHL, D. M. Central & South Nest Corp. 80/11/25, 23pp.
- 8012302250 Response to intervenor Public Utils Board of City of Brownsville 801112 opposition to proposed settlement license conditions. Conditions are in public interest. Imposition will not damage intervenor. Certificate of Svc encl. FABRIKAIRT, R., CALHOUN, M.L., UMITLER, J.D. Justice, Dept. of. 80/12/0 24pp.
- 8012230222 Order granting TX Border Cooperatives 801124 petition for leave to uithdraw 800731 petition to intervene. MILLER, M. E. Atomic Safety and Licensing Board Panel. 80/12/04,
- 8012290163 Corrects typographical error in Certificate of Svc.encl to 801203 memorandum in support of proposed settlement license conditions. Date of svc should be 801203. W/Certificate of Svc. Svc. REEN. D. C. Houston Lighting & Power Co. 80/12/04. 5pp.
- 8012300231 Joint motion to make corrections to 800915 proposed settlement license conditions Also moves for leave to file encl conformed groposed license conditions. Certificate of Svc apcl.
 CHANANIÁLF.D. Antitrust Division.

 ** Central Power & Light Co. 80/12/22, 20pp.
- 8012300469 Order granting leave to file 801222 conformed settlement license conditions & adopting corrections to 800915 proposed license conditions. License conditions enci. MILLER, R. E. Atomic Safety and Licensing Board Panel. 80/12/24,

- G. Inspection reports: IE Bulletins & correspondence
- 8012170740 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 80/09/10. 10. 07264-163
- 8012040032 Forwards IE Investigation Repts 50-498/80-26 & 50-499/80-26. No noncompliance neted SEIDLE.W.C. Region 4. Dailas, Reactor Construction & Engineering Support Branch. 80/10/24. 2pp. 07£69:321.
- --B012040037 IE Investigation Repts 50-478/80-26 & 50-499/80-26 on 800704-05 & 07 No noncompliance noted Major areas investigated allegations that audit followers were inappropriate, engineers unqualified & alleger intimidated. HERR.R.K. Region 4, Dallas, Office of the Director. TAPIA, J. I., CROSSMAN, M. A. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/10/03 7pp. 07169.323.
- 8012160299 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASKE SA-312, Type 304 Stainless Steel Pipe." Lists affected equipment. doly components affected are cylindrical portions of desineralizer shells.

 UPREA, G. U. Houston Lighting & Power Co. 80/10/27, 2pp. 07248: 245.
- 8012190539 Forwards IE lnsp Repts 50-498/80-25 & 50-499/80-25 on 800901-30 No noncompliance noted. SEIDLE-W C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/10/28. 2pp. 07288:103.
- --8012170544 IE Insp Repts 50-478/80-25 & 50-497/80-25 on 800701-30.No noncompliance noted. Major areas inspected: moncompliance followups.unresolved matters, const deficiencies & show cause order (tems. PHLLIPS.H.S.; CROSSKAN,W.A. Region 4, Dallas, Office of the Director, 80/10/29, 13pp. 07289:105.
- 8012170354 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. BEYFRIT.K.V. Region 4. Dallas. Office of the Director. BO/10/30. ip. 07269:017.
- 8012170825 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
 SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/10/31.
 1p. 07265:019.
- 8012100615 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcoln Foundry Co.lnc." Written response required SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 80/11/06. 1p. 07220:095.
- 8012190407 Forwards IE Insp Repts 50-498/80-24 & 50-499/80-24, on 800818-22,0902-05 & 16-19. No noncompliance hoted. SEIDLE, M.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/11/06 2pp. 07286: 225.
- -8012190416 IE Insp Repts 50-478/80-24 & 50-499/80-24 on 800818-22, 0902-05 & 16-19. No noncompliance noted Major areas inspected; const activities & records re responses to Insp Rept 50-498/79-19.

 TAPIA-J.I., TOMLINSON, D.P., HUBACEK, W.G. Region 4, Dallas, Office of the Director. 80/11/05, 19pp. 07286: 227.
- 8012030894 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization" No written response required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/07. 1p. 07150:125.
- 9012190618 Forwards [E Insp Repts 50-498/80-28 & 50-499/80-28 on 801036-10 & 14-17. No noncompliance notes, BEIOLE-H.C. Region 4, Datlas, Peactor Construction & Engineering Support Branch. E0/11/07. 2pp. 07288; 262.
- --8012190623 IE insp Repts 50-498/80-28 & 50-499/80-28 on 801006-10 & 14-17. No noncompliance noted Major areas inspected; const activities pertaining to resumption of AMS welding.
 TORLINSON.D.P., HALL.R E Region 4, Dallas, Reactor Construction & Engineering Support Branch. CROESHAN.M.A. Region 4, Dallas, Office of the Director. 80/11/06. 4pp. 07289:264.
- 80:2080580 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. SEY-RIT. 2.V. Region 4, Dallas. Office of the Director. 80/11/10. 1p. 07:83:005

- 8012190664 Forwards iE Insp Repts 50-498/80-32 & 50-499/80-32 on 801021-23. No noncompliance noted. BRCKW, G.D. Region 4/ Dallas, Eucl Facility & Materials Safety Branch. B0/11/13. 2pp. 07287:305.
- --8012190669 If Insp Repts 50-478/80-32 % 50-497/80-32 on 801021-23.No noncompliance noted Major areas inspected const phase environ protection programs.
 MILBORILL Region i, Philadelphia, Office of the Director.
 BROWN, C. D. Region i, Philadelphia, Fuel Facility & Materials
 Safety Branch. 80/11/12. 7pp. 07287:307.
- 8012040123 Forwards IE Builetin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Curp." Requires estimate of manpouer associated w/corrective actions. SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/11/14, 1p. 07158:041.
- B012110339 Forwards Mechanical Engineering Branch position & requests addl info re inservice insp of pressure isolation valves.

 List of valves & P&ID are required.

 TEDE3CO,R.L. Assistant Director for Licensing. 80/11/17. 3pp. 07224-128.
- 8012090018 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. BO/11/21, 1p. 07173:067.
- 8012080350 Discusses 800728 response to 800430 show cause order, Limited work restart in certain selected areas has been authorized. Safety-related complex concrete const corrective actions are being reviewed.

 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/11/21. 3pp. 07196:044.
- 8012160003 Forwards IE Info Notice 80-42, "Effect of Radiation on Mydraulic Snubber Fluid." No response required. SEYFRIT.K V. Region 4. Dallas, Office of the Director. 80/11/24. lp. 07255:031
- 8012140111 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 80/11/26. 10. 07262:091
- 8012190632 Ack receipt of 800918 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-19 & 50-497/79-19.

 8EIDLE-IR.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/12/03. 1p. 07287:293.
- --8012190647 Responds to NRC 800430 ltr re violations noted in IE Insp. Repts 50-498/79-19 & 50-499/79-19. Clarifies statements made in 800523 ltr re concrete placement activities & cadwelder recentification.

 DPREA.G.W. Houston Lighting & Pawer Co. 80/09/18. 3pp. 07287:294.
- B012220023 Ack receipt of 800910 ltr informing NRC of steps taken to corre:t vlolations noted in IE Insp Repts 50-498/79-19 & 50-499/79-19 & in response to NRC 800430 order to show cause.

 SEIDLE:H.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/12/03. 1p. 07306:315.
- --8012220030 Discusses violations noted in IE Insp Repts 50-498/79-19 & 50-499/79-19 & to 800430 order to show cause in preparation, for 800913 meeting. W/o encl documentation re welding program.

 EPREARG. M. Houston Lighting & Power Co. 80/09/10. 2pp. 02304-214
- 8012170420 Responds to NRC 801201 request for add1 info re inservice insp of pressure isolation valves. Not all details available. Request to be addressed in future submittal of inservice testing program on pumps & valves.

 OPREA, G. W. Houston Lighting & Power Co. 80/12/11, 2pp. 07268:148.
- S. Reportable occurrences, LERs & related correspondence
- 8012100200 PNO-IV-80-348: util G01119 ltr requested limited restart of ASME safety-related welding Request for new production welding is specific to site fabrication shop welding. Resumption permissible.

 HUBACEN, N. G. CROSSMAN, W. A. Region 4: Dellas, Office of the Director. 80/11/24. 1p. 07218:298.

- 8012030655 Third interim deficiency rept first reported on 800411.re stop work order on safety-related welding. Discusses current status of safety-related welding. Forwards chronology of ASKE/AWS D1.1 welding restart correspondence. CPREA.G.W. Houston Lighting & Power Co. 80/11/25. 7pp. 07151:259.
- 8012030866 Fifth interim deficiency rept.first reported on 800320, rebroten tie-down studs in containment bldg polar crane rail sys. Repairs in progress & completion expected by late Dec 1980. Next rept to be submitted by 810401.

 OPREA.G.N Houston Lighting & Power Co. 80/11/25. 4pp. 07151:271.
- 80:12190418 Third interim deficiency rept.originally reported on 800321, re nonconforming backfill matl areas around power block. Provides status of structural backfill investigation & notes activities completed by Independent review committee. OPREA.G.W. Houston Lighting & Power Co. 80/12/12. 6pp. 07285:308.
- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012090414 Forwards description of status of work authorized under LWA-1 & LWA-2 & plans to redress portions of site affected by facility const activities, in connection w/800123 decision to cancel facilities. Drawing encl. CROUSE, R. P. Toledo Edison Co. 80/11/26. 6pp. 07207: 126.
- 8012220485 Responds to 800911 memo requesting that Dfc of Nuclear Reactor Regulation inform licensees of need to comply w/revised Agreement State burial site conditions. Forwards results of IE survey.

 BENIOM: H. R. Diffice of Nuclear Reactor Regulation, Director. 80/12/04. 2pp.
- --8012220506 Forwards tabulation & summary of IE survey on low lavel waste at 51 reactors.Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANGART,R.L. Effluent Treatment Systems Branch. 80/11/06. 8pp.
- G. Adjudicatory correspondence
- 8012080013 Discusses util 801117 ltr to H Denton withdrawing joint applications for CPs. NRC will conduct site insp before presenting views to ASLB re whether termination requires imposition of special conditions.
 RDTHSCHILD.M.U. Hearing Branch 1. 80/11/26. 2pp. 07175; 334.
- BO12180162 Memorandum & order granting limited relief to applicants' re request to withdraw applications for CPs. Request for full termination of CP proceedings must be addressed to ABLB. BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 80/12/01. Spp. 03791:291.
- 8012290124 Confirms M Rothschild 801125 telcon w/G Fiorelli re request for insp of facilities to ascertain site conditions in view of withdrawal of CP applications Requests all insp repts re LNA activities.

 TREBY, S. A. Hearing Branch f. 80/12/03. 3pp. 07308:001.
- 8012300215 Forwards util 801126 ltr to BJ Youngblood describing status of all activities performed by applicant pursuant to LHAs & plans to redress portions of site affected by const activities.

 ROTHSCHILD.M.U. Operations & Administrative Division. 80/12/22. ip. 07357:001.
- 8012310276 Motion for termination of all further proceedings CP applications withdrawn Certificate of Svc encl. SILDERG, J. E. Toledo Edison Co. SILDERG, J. E. Shaw, Pittman, Potts & Trowbridge. 80/12/29. Spp. 07370: 083
- L. Limited work authorization & related correspondence
- 8012070414 Forwards description of status of work authorized under LNA-1 & LNA-2 & plans to redress portions of site affected by facility const activities, in connection w/800123 decision to cancel facilities. Drawing encl. CROUSE, R. P. Toledo Edison Co. 80/11/26. 6pp. 07207:126.
- O. Inspection reports, IE Bulletins & correspondence
- 8012190210 Forwards third bimonthly status rept on IE Bulletin 79-018 re environ qualification of Class IE equipment. HAYES, D. W. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp.

- DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

 A. Application/construction stage documents & correspondence
- 8012090414 Forwards description of status of work authorized under LWA-1 & LWA-2 & plans to redress partions of site affected by facility const activities in connection w/800123 decision to cancel facilities, Drawing encl CRGUSE.R.P. Toledo Edison Co. 80/11/26. 6pp. 07207:126.
- 8012220485 Responds to 8003711 memo requesting that Ofc of Nuclear Reactor Regulation inform licensess of need to comply whrevised Agreement State hursal site conditions. Forwards results of IE survey.

 DENTOR, H. R. Office of Muclear Reactor Regulation, Director, 80/12/04. 2pp.
- --8012220504 Forwards tabulation & summary of IE survey on low level waste at 51 reactors. Low level waste storage facilities have been expanded at 37% of reactors surveyed w/71% planning or considering increasing storage capacity.

 BANSART. R. L. Effluent Treatment Systems Branch, 80/11/06, 8pp.
- G. Adjudicatory correspondence
- 8012080013 Discusses util B01117 ltr to H Denton withdrawing joint applications for GPs.NRC will conduct site inspliefore presenting views to ASLE re-ubether termination requires imposition of special conditions.
 ROTHSCHILD.M.U. Hearing Branch L. B0/11/26. 2pp. 07175:354.
- 8012180162 Memorandum & order granting limited relief to applicants' re request to withdraw applications for CPs. Request for full termination of CP proceedings must be addressed to ASLB. BISHOP.C.J. Adomic Safety and Licensing Appeal Panel. 80/12/01. Spp. 03791:291.
- B012270124 Confirms M Rothschild B01125 telcon w/0 Fiorelli re request for insp of facilities to ascertain site conditions in view of withdrawal of CP applications Requests all insp repts re LHA activities.

 TREBY-S.A. Hearing Branch 1 80/12/03. 3pp. 07308:001.
- 8012300215 Forwards util 801126 ltr to BJ Youngblood describing status of all activitles performed by applicant pursuant to LHAs & plans to redress portions of site affected by const activities.

 ROTHSCHILD.R.U. Operations & Administrative Division. 80/12/22. ip. 07357:001.
- 9012310276 Motion for termination of all further proceedings CP applications withdrawn Cortificate of Svc encl. SILBERG J. E. Toledo Edison Co. SILBERG J. E. Shau, Pittman, Potts & Froubridge. 80/12/29. 5pp 07:370:053.
- L. Limited work authoritation & related correspondence
- 8012090414 Forwards description of status of work authorized under LWA-1 & LWA-2 & plans to redress portions of site affected by facility const activities in connection w/800123 decision to cancel facilities. Drawing encl CROUSE: R P. Toledo Edison Co 80/11/26. 6pp. 07207:126.
- O. Inspection reports: 1E Bullatins & correspondence
- 80:2170210 Forwards third bimonthly status rept on IE Bulletin 79-018 re environ qualification of Class IE equipment. HAYES, D. W. Region 3. Chizago, Reactor Construction & Engineering Support Branch. 80/12/09. 2pp
- DOCKET STN-50-508 NPPSS NUCLEAR PROJECT, UNIT 3

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees. DL applicants & CP holders. Forwards NUREO-0737 no TM1 action plan requirements. Requests operating yeactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISENHUT, D. O. Division of Licensing. B0/10/31, 7pp.
- I. Financial information
- 8012160128 Forwards Annual Financial Rept 1980. BOUCHEY, G. D. Washington Public Power Supply System. 80/12/11. 1p.

- ~-8012160134 Annual Financial Rept 1580.

 * Washington Public Fower Supply System. 80/12/11. 23pp.
- G. Inspection reports. IE Bulletins & correspondence
- 8012040677 Forward: IE Insy Repts 50-508/80-08 & 50-509/80-08 on 800304-28 No noncompliance nated.
 SPENCERG S Region 3. San Francisco. Reactor Construction & Engineering Support Branch. 80/09/26. 2pp. 07149:089.
- --8012040679 IE Insp Repts 50-508/80-08 & 50-509/80-08, on B00804-28. No noncompliance noted. Major areas inspected: const activities.

 BIS:OP.T. N. Region 5: San Francisco: Office of the Director.
 HAYMES: R.C. Region 5: San Francisco: Reactor Construction & Engineering Support Branch. 80/07/26 7pp. 07169:091.
- 8012170690 Forwards IE info Notice 80-37: "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 ENSELEKIAR H. Region 5: San Francisco: Office of the Director.
 80/10/24.
- 8012170418 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/10/30. 1p. 07266:160.
- 8012170347 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Rife by Valcor Engineering Corp." No written response is required.
 ENGELKERLR.H. Region 5, San Francisco, Office of the Director.
 80/10/31. 1p. 07265:035.
- 8012120221 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. ENSELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/06. pp. 07228-244
- 8012030914 Forwards IE Info Natice 80-40, "Ercessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ENGELVER.R.H. Region 5. San Francisco. Office of the Director. 80/11/07. 1p. 07150:133
- 8012080458 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. ENGELKEIN.R.H. Region 5. San Francisco, Office of the Director. 80/11/10. 1p. 07183:041.
- 8012020233 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Velcor Engineering Corp." Requires estimate of manpower associated u/corrective actions. EXCELERIA. H. Region 5, San Francisco, Office of the Director. 80/11/14. 1p.
- 8012040591 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leahage Inside Containment: "No written response required.

 EKGELKFN.R.H. Region 5, San Francisco, Office of the Director.

 80/11/21. 1p. 07159; 272.
- 8012160031 Forwards IE Info Notice 80~42, "Effect of Radiation on Hydraulic Snubber Fluid." No response required. ENGELMEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/24. 1p. 07262-120.
- 8012160133 Forwards Suppl 1 to 1E Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. ENSELKEN, R. N. Region 5, San Francisco, Office of the Director, 80/11/26, 1p. 07262:067.

NUCLEAR PROJECT, UNIT 5

lant licensees, OL applicants & CP holders, action plan requirements, Requests confirmation in 45 days that will be net.
Licensing. 80/10/31. 7pp.

mancial Rept 1780. blic Power Supply System. 80/12/11. 1p.

- --8012160134 Annual Financial Rept 1780.

 * Washington Public Power Supply System. 80/12/11. 23pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012040677 Forwards IE Insp Repts 50-508/80-08 & 50-509/80-08 on 800804-28.No noncompliance noted.

 SPENCER.O.S. Region 5, San Francisco. Reactor Construction & Engineering Support Branch. 80/09/26. 2pp. 07169:089.
- --8012040679 lE Insp Repts 50-598/80-03 & 50-509/80-08, on 800804-28. No noncompliance noted. Major areas inspected: const activities.
 BISHOP, T.W. Region 5. San Francisco, Office of the Director.
 HAYMES,R.C. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 80/09/26. 7pp. 07169:091.
- 6012170590 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
 ENCELERIAR H. Region 5. San Francisco. Office of the Director.
 80/10/24.
- 8012170418 Forwards 1E Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ENGELXEN.R.H. Region 5, San Francisco, Office of the Director. 80/10/30. 1p. 07266:160.
- 8012170847 Forwards IE Info Notice 80-37, "Malfunction of Bolenoid Valves Mfg by Valcor Engineering Corp." No written response is required. EMSELKEIJR. H. Region 5, Ban Francisco, Office of the Director. 80/10/31. ip.
- 8012120921 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. EKOELKEU.R.H. Region 5, San Francisco, Office of the Director. 80/11/06. ip.
- 8012030914 Forwards IE Info Notice 80-40, "Excessive Nitragen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/07. 1p.
- 801208065B Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1," No response required.
 EMSELEFIR.H Region 5, San Francisco, Office of the Director.
 80/11/10. 1p.
- 8012010233 Forwards IE Builetin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpouer associated w/corrective actions. EKGELKEBJR.H. Region 5, San Francisco, Office of the Director, 80/11/14. 1p. 07158:156.
- 8012040581 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 ENGELKEN.R. H. Region 5, San Francisco, Office of the Director. 80/11/21, 1p.
- 8012160031 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No response required. ENGELKEN.R.H Region 5, San Francisco, Office of the Director. 80/11/24. 1p.
- 8012160133 Forwards Suppl 1 to 16 Info Notice 80-29, "Broken Studs on Tarry Turbine Steam Inlet Flange." No written response required.
 ENGELKER R. H. Region 5, San Francisco. Office of the Director.
 80/11/26. 1a.

DOCKET 50-510 BLUE HILLS SYATION, UNIT 1

A. Application/construction stage documents & correspondence

8012160338 Forwards info re small dry transformer & 480-volt load ctrs. in response to NRC 801001 itr re IEEE 323 environ qualification program. Review should be completed by B10115.

DRAPER.E.L. Gulf States Utilities Co. 80/12/05. 2pp. 07263;141.

DOCKEL 50-511 BLUE HILLS STATION, UNIT 2

A. Application/construction stage documents & correspondence

B012160388 Forwards info re small dry transformer & 480-volt load ctrs.in response to NRC 801001 ltr re IEEE 323 environ qualification program. Review should be completed by B10115. DRAPER,E. L. Gulf States Utilities Co. 80/12/05, 2pp.

DOCKET 50-513 WPP8S NUCLEAR PROJECT, UNIT 4

A. Application/construction stage documents & correspondence

8012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be not. EISENHUT.D.O. Division of Licensing. 80/10/31. 7pp.

I. Financial information

- 8012160128 Forwards Annual Financial Rept 1980. BOUCHEY, C. D. Washington Public Power Supply System, 80/12/11. 1p. 07187:001.
- --8012160134 Annual Financial Rept 1980.

 * Washington Public Power Supply System. 89/12/11. 23pp.
 07187:001.
- G. Inspection reports, 1E Bulletins & correspondence
- 8012170680 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No uritten response required. ENGELERIA: R. Regton 5, San Francisco, Office of the Director. 80/10/24.
- 8012170418 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ENGELKFM.R.H. Region 5, San Francisco, Office of the Director. 80/10/30. ip.
- B012170847 Forwards IE Info Notice 80-37, "Malfunction of Sciencid Valves Mfg by Valcor Engineering Corp." No written response is required.
 ENOSLKEN.R.H. Region 5. San Francisco. Office of the Director.
 80/10/31. 1p.
- B012120221 Forwards IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ENGELKFN.R.H Region 5, San Francisco, Office of the Director. B0/11/04. jp.
- 8012030914 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ENGELKEN, R. H. Region 5. San Francisco. Office of the Director. 80/11/07. 1p.
- 8012080658 Forwards IE Info Notice 80-41, "Failure of Buing Check Valve in Decay Heat Removal Sys at Davis Desse Unit 1." No response required. ENDELKFILR. H. Region 9, San Francisco, Office of the Director, 80/11/10. 1p.
- 8012040233 Forwards IE Builetin BO-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. EMPELKEII.R.H Region 5. San Francisco. Office of the Director. BO/11/14. 1p.
- 8012040681 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. ENGELKPH,R.H. Region 5, San Francisco, Office of the Director, 80/11/21. 19.
- 8012160081 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No response required, ENGELKFN.R.H Region 5, San Francisco, Office of the Director. 80/11/24, ip.
- 8012310503 Forwards 1E Investigation Repts 50-460/80-14 & 50-513/80-14 on 800306-0717. No noncompliance noted. SPENCCR. 0. S. Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch. G0/11/25. 2pp. 07365:237.

- --8012310503 IE Investigation Repts 50-460/80-14 & 50-513/80-14 on 800306-0717. No noncompliance noted Major areas investigated: anoughous allegations re-const & reinforcing Steelwork activities.

 TOTH.A.D.: SMACKLETCH.O.C. Region 5, San Francisco, Office of the Director HAYNES.R.C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80/11/25, 16pp. 07365:237
- 8012160133 Forwards Suppl 1 to 18 Info Notice 80-29, "Broken Studs on Terry Turbline Steam Inlet Flange." No written response required.
 ENGSEMEN.R H. Region 5, San Francisco, Office of the Director.
 80/11/24 in
- U. Congressional/Executive Correspondence
- 8012100654 Responds to 800408 ltr to DBE requesting rept on Finley Quarry fault potential for earthquake & effect on facilities located at Hanford reservation. Seisminity will be reevaluated as result of recent geologic discoveries. DIRCKE.M.J. Office of the Executive Director for Operations. 80/11/24. 11pp. 07187:001.

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- B012290334 Responds to 800930 ltr re util desire to continue w/licensing effort of facility in limited fashion. Proposal to proceed w/limited effort accepted but may be problem w/time allocation.

 DENIGN-H.R. Office of Nuclear Reactor Regulation, Director. 80/12/11. 4pp. 07345:109.
- G. Adjudicatory correspondence
- 8012170689 Proposed findings of fact & conclusions of law in form of limited partial initial decision on environ & sita suitability matters.Certificate of Svc encl. BORDENICK.B.M. Hearing Branch 3. GO/12/02. 3Spp. 07264:012.
- H. General correspondence
- E012040756 Forwards info in response to 801027 ltr requesting licensing categories & info ie floating nuclear plants. PURPLE:R.A. Division of Licensing. 80/11/17. 4pp.
- --B012040278 Requests info re facilities w/active CPs pending, liconse definitions & requirements for floating nuclear plants.

 DREY.L.A. Affiliation Unknown. 80/10/29. 1p.
- DOCKEL 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012290384 Responds to 800730 ltr re util desire to continuo w/licensing effort of facility in limited fashion. Proposal to proceed w/limited effort accepted but may be problem w/time allocation.

 DENION.H.R. Office of Nuclear Reactor Regulation, Director. 80/12/11. 4pp. 07349:109.
- G. Adjudicatory correspondence
- BO12170689 Proposed findings of fact & conclusions of law in form of limited partial initial decision on environ & site suitability matters. Certificate of Svc encl.
 BORDENICK.B.M. Hearing Branch 3. BO/12/02. 38pp. 07264:012.
- H. General correspondence
- B012040296 Forwards info in response to B01027 ltr requesting licensing categories & info re floating nuclear plants. PURPLE.R.A. Division of Licensing. B0/11/17. 4pp.
- --B012040278 Requests info re facilities w/active CPs pending license definitions & requirements for floating nuclear plants. DREY.L.A. Affiliation Unknown. 80/10/29. 1p.

- DOCKET STR-50-516 JAMESPERT NUCLEAR STATION, UNIT 1 G. Adjudicatory correspondence
- 8012300572 Status Rept & 3 request that proceeding be terminated, Issues are most due to util decision to end nuclear project.

 Certificate of Svc encl

 REVELEY, R T Long Island Lighting Co. REVELEY, R. T. Hunton & Williams. 80/12/19 Spp. 07362-304.
- Q. Inspection reports. IE Bulletins & correspondence
- 8012170378 Forwards 1E Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. CRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/30. pp. 07264.040.
- 8012120173 Forwards IF Bulletin BO-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. GRIER B.H. Region 1, Philadelphia, Office of the Director. BO/11/06 1p. 07228.324.
- B012030782 Forwards IE Info Notice B0-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization "No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. B0/11/07. 1p. 07450:179.
- 6012080441 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Docay Heat Removal Sys at Davis Basse Unit 1." No response required.

 GRIER.B.H. Region 1, Philadelphia, Office of the Director, 80/11/10. 1p. 07182:318.
- 8012040077 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/14. pp. 07157: 298.
- B012220537 Advises that written response is required to IE Bulletin B0-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." First paragraph erroneously stated no written response required.
 GRIER.B.H. Region 1. Philadelphia. Office of the Director.
 80/11/19. 1p. 07293:133
- 8012040514 Forwards IE Bulletin 80-24, "Prevention of Danage Due to Mater Leakage Inside Containment." No written response required GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/11/21, 2pp. 07165-290.
- 8012050566 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulis Snubber Fluid." No written response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 80/11/24. 1p. 07174:053.
- DUCKET STH-50-817 JAMESPORT NUCLEAR STATION, UNIT 2
 G. Adjudicatory correspondence
- 8012300572 Status Rept 6 2 request that proceeding be terminated. Issues are most due to util decision to end nuclear project.
 Cartificate of Ske encl.
 REVELEY.H.T. Long Island Lighting Co. REVELEY.H.T. Hunton & Williams. 80/12/19. Spp. 07362.304.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012170378 Forwards IE Info Natice 80~38, "Cracking in Charging Pump Casing Cladding." No written response required. GRIER.8.13. Region 1. Philadelphia, Office of the Director. 80/10/30. 1p. 07269.060.
- 2012120173 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. CRIER.B.H. Region 1. Philadelphia, Office of the Director, 80/11/06. 1p. 07228:324.
- 8012030782 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization "No written response required. GRIER,B.H. Region 1. Philadelphia, Office of the Director, 80/11/07. 1p. 07150:199.

- 8012090441 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Basse Unit 1." No response required.

 ORIGE, B.H. Region 1, Philadelphia, Office of the Director.
 80/11/10. 1p. 07182:318.
- 8012040077 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. GRIER, B. H. Region 1. Philadelphia, Office of the Director. 80/11/14. 1p. 97157:258.
- 8013220637 Advises that written response is required to IE Bulletin 80-23, "Failures of Solenoid Valves life by Valcor Engineering Corp." First paragraph erroneously stated no written response required.
 GRIER, B. H. Region i. Philadelphia, Office of the Director. 80/11/19. 1p. 07293:133.
- B012040614 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.
 ORIER, B. H. Region i. Philadelphia, Office of the Director.
 B0/11/21. 2pp. 07165:270.
- 8012050556 Forwards Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. ORIER, B.H. Region 1. Philadelphia, Office of the Director. 80/11/24. 1p. 07174:053.
- DOCKET STR-90-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees, QL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISENHUT, D. Q. Division of Licensing. 80/10/31. 7pp.
- 8012220358 i.tr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core releads.

 EISEMHUT, D. G. Division of Licensing. 80/11/04. 4pp,
- 8012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept. TVA-TR75-1 re const & preliminary testing. MILLS.L.M. Tennessee Valley Authority. 80/12/01. 3pp.
- 8012160527 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment. Info will be aveilable by 810201.
 MILLS.L.M. Tennessee Valley Authority. 80/12/09. 1p.
- 8012170316 Forwards planned charges to Chapter 17 of FBAR for Bequovah, Watts Bar & Bellefonte & TVA-TR75-1A. Changes supersede 801201 ltr. Changes will be included in application for CL for Hortsville. Phipps Bend & Yellow Creek plants. MILLS. E. K. Tennessee Valley Authority. 80/12/09. 5pp.
- F. Security, medical, emergency & fire protection plans
- 8012080835 Notification of 801121 meeting w/util in Bethesda.MD to discuss util position on central emergency response ctr & plans for emergency mgt.

 STARLE.C. Licensing Branch 2. 80/11/19. App.
- O. Inspection reports, IE Bulletins & correspondence
- 8012150201 Forwards IE Info Notice 80-37, "Containment Cooler Leats & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/10/24.
- 8012110840 Forwards IE lnsp Repts 50-518/80-20,50-519/80-19, 90-320/80-20 % 50-521/80-18 on 800929-1001 No noncompliance noted. MURPHY, C.E. Region 2- Atlanta, Reactor Construction & Engineering Support Branch. 80/10/27. 2pp. 07825:135.
- ~-8012110847 IE insp Repts 50-518/80-20, 50-519/80-19, 50-520/80-20 & 50-521/80-18 on 800929-1001. No noncompliance noted. Major areas inspected; previous insp findings, licensee identified 102FR50, 55e items & welding.

 CROWLEY, B.R. Region 2. Atlanta, Office of the Director, HeRDT-A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/24. 7pp. 07225:137.

- 8012160730 Forwards IE Insp Repts 50-518/80-21,50-519/80-20, 50-520/80-21 & 50-521/80-19 on 800902-27. No noncompliance noted. MURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/28.
- --8012160750 IE Insp Repts 50-518/80-21,50-519/80-20,50-520/80-21 & 50-521/80-19 on 800902-27. No noncompliance noted Major areas inspected: earth compaction, rock fill & concrete for spray pends.

 SMANN N.B. Region 2, Atlanta, Office of the Director CANFRELL-F.S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/27. 5pg. 07261:320.
- 8012170004 Forwards JE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
 10.
- 9012230030 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. D'REILLY, J. P. Región 2. Atlanta, Office of the Director. 80/10/31.
- 8012110356 Requests assessment & corrective actions taken re control room celling constructed w/apparently flammable tiles within 20 days.
 TEDESCO: R. L. Assistant Director for Licensing. 80/11/04. 3pp.
- 8012110807 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.inc." Written response required.

 O'REIL! Y.J.P. Region 2, Atlanta, Office of the Director. 80/11/06.
 1p.
- 8012030837 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07. ip.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Ewing Check Valve in Decay Heat Removal Cys at Davis Besse Unit 1." No response required.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/10. is.
- B012040143 Forwards IE Bulletin B0-23, "Failures of Golenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director. B0/11/14.
 1p.
- 8012080601 Forwards third interim response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies." Actuators may have been used as part of valve actuators. Suppliers will be contacted. MILIS.L.M. Tennessee Valley Authority. 80/11/17. 3pp. 07188:208.
- 8012050023 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/21. ip. 07173:072
- 8012080304 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24, 1p.
- 8012080640 Ack receipt of 801110 ltr informing NRC of steps taken to correct violations noted in IF lnsp Repts 50-518/80-18, 50-519/80-17, 50-520/80-18 & 50-521/80-16. MVRPHY.C. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/25. 1p. 07(87:042.
- ~-8012080668 Responds to NRC 801016 ltr re violations noted in 1E Insp Repts 50-518/80-18.50-519/80-17.50-520/80-18 & 50-521/80-16. Corrective actions: drawing files updated & revised.List of current drawings & revisions issued. HILLS.L.M. Tennessee Valley Authority. 80/11/10. 3pp. 07187:043.
- --8012080678 Forwards IE Inap Repts 50-518/80-18, 50-519/80-17, 50-520/80-18 & 50-521/80-14 on 800801-27 & notice of violation MUPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/16. 2pp. 07187:046.

- --8012080684 Notice of violation from insp on 800801-29.

 4 Region 2, Atlanta, Office of the Director. 80/10/02. ip. 07187:048
- --8012083695 IE Insp Repts 50-518/80-18.50-519/80-17.50-520/80-18 & 50-521/80-16 on 800801-29. Noncompliance noted: failure to take timely corrective action on drawing control findings. SWALM B. Region 2. Atlanta, Office of the Director. CANTRELL,F. S. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/02 6pp. 07187:049.
- 8012170359 Forwards IE Info Notice 80-29. Suppl 1. "Broken Stude on Terry Turbine Steam Inlet Flange" No written response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/20
- R. Periodic operating reports & related correspondence
- 8012300652 Forwards Oct 1980 sociaeconomic monitoring & mitigation rept. MBLES-L.M. Tennessee Valley Authority. 80/12/23. ip. 07359:091.
- --B012300655 "Hartsville Nuclear Plants Socioeconomic Monitoring & Mitigation Rept." B01031.

 * Tennessee Valley Authority. INSP SMR-8. 80/10/31, 50pp. 07359:092.
- 8. Reportable occurrences, LERs & related correspondence
- 8012040657 Part 21 rept re reactor protection sys panel design deficiencies, initially reported on 800807. No addl info received from GE, therefore, no further progress to rept. Final rept to be transmitted by 810213.
 MILLS.L.M. Tennessee Valley Authority. 80/11/18, 2pp. 07166:337
- 8012050369 Deficiency rept re link rod assembly in Dolaval diesels. Dowel counterbore of link rod assembly may be too shallow. Transamerica Delaval described insp. method required. Onsite diesels will be placed on hold pending insp. MILLS. L.M. Tennessee Valloy Authority. N. 80/11/26. 2pp. 07173:340.
- 801209038[Third interim deficiency rept re standby gas treatment syscharcoal adsorber.CII nuclear submitted rept requiring review by util before final corrective actions can be prescribed.Final rept by 810303.

 MILLS,L.B. Tennessee Valley Authority 80/11/26. 1p. 07173:338.
- 8012100478 First interim deficiency rept re defective link rod assemb in Deleval diesel generators, initially reported on 801027. Unsite diesels will be placed on hold & inspected for defect. Final deficiency rept will be provided by 801125. MILLS, L. N. Tennessee Valloy Authority. 80/11/26. 2pp. 07218:306
- 8012230110 Part 21 rept.originally reported B01106, re inadequate wedg bolt expansion anchors by Rawtplug Caused by mfg deficiency. One-inch anchor design loads will be reduced. Final rept by 810325. MILLS.L.M. Tennessee Valley Authority. 80/12/04. 3pp.
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperty grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERMOOD, O. G. General Electric Co. 60/12/08. 3pp.
- 8012300484 Final deficiency rept re lack of steam tunnel embedment stiffner plate weld, initially reported on 800505. Caused by inadequacy of manufacturer GA program, Missing weld has been added 2 inspected. GA program a
- 8012310335 Fourth interim deficiency rept initially reported 800215 re reactor pressure vessel shield wall deficiencies. Addlunacceptable welds found & documented in IMP-A-115. Final rept by 810662.

 MILLS.L. K. Tennessee Valley Authority. 80/12/22. 1p. 07361:047.
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 2012160050 Ltr to operating plant licensees. Cl. applicants & CP holder Forwards NUREC-0737 re TM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EISENHUT, D. G. Division of Licensing. 20/10/31. 7pp.

- 8012220358 i.tr to all CP 2 OL halders for BWRs re requirement for implementation of OBYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.
 EISERHUT, D. G. Division of Licensing, 80/11/04, 4pp.
- 8012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept. TVA-TR75-1 re-const & preliminary testing.
 MILLS.L.B. Tennessee Valley Authority. 80/12/01. 3pp.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201 Mills, L. M. Tennessee Valley Authority. 80/12/09. 1p.
- 8012179316 Forwards planned changes to Chapter 17 of FSAR for Sequeyah. Natts Bar 3 Beliefonts 2 TVA-TR75-1A. Changes superseds 801201 ltr. Changes will be included in application for GL for Hactsville. Phipps Bend 2 Yellow Creek plants.
 MILLS-L.M. Tennesses Valley Authority. 80/12/09. 5pp.
- F. Security, medical, emergency b fire protection plans
- 8012080835 Notification of 801121 meeting wouth in DethesdarMD to discuss util position on central emergency response ctr & plans for emergency mgt.
 STAHLE.C. Licensing Branch 2. BO/11/19. 6pp.
- O. Inspection reports, IE Bulletins & correspondence
- 80:2180201 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24.
- G012110B40 Forwards IE Insp Repts 50-518/80-20, 50-919/80-19, 50-920/80-20 & 50-521/60-18 on B00929-1001. No noncompliance nated. MMRPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. B0/10/27, 2pp. 07225:135.
- --8012110847 IE insp Repts S0-518/80-20, 50-519/80-19, 50-520/80-20 & 50-521/80-18 on 800929-1001, No moncompliance noted Hajor areas inspected; previous insp findings, licensee identified 100FHS0, 550 items & wolding, CROMLEY.B.R. Region 2. Atlanta. Diffice of the Director. HERDI.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/24. 7pp. 07228:137.
- 8012160730 Forwards IE Insp Repts 50-518/80-21,50-519/80-20, 50-529/80-21 % 50-521/60-19 on 800902-27. No noncompliance noted. MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/28, 2pp. 07241:318.
- --8012150750 IE Insp Repts 50-518/80-21, 50-519/80-20, 50-520/80-21 & 50-521/80-19 on 800902-27. No noncompliance noted Major areas inspected: earth compaction, rock fill & concrete for spray ponds.

 EMARKUB B. Region 2. Atlanta. Office of the Director.

 CANTRELLES Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/27. Spp. 07261:320.
- 8012170304 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Hfg by Valcor Engineering Corp." No specific action or response required.

 G'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012230)30 Forwards IE Circular 80-23, "Potential Defects in Deloit Power Bys Emergency Generators." No written response required.

 O'REILLY J.P. Region 2, Atlanta, Office of the Director. 80/10/31.
 10.
- 8012110366 Requests assessment & corrective actions taken re control noom ceiling constructed w/apparently flammable tiles within 20 days.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/04. 3pp.
- 8012110807 Forwards IE Bulletin 80-21. "Valve Vokes Supplied by Malcolm Foundry Co.inc." Written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/04. 1p.

- B012030837 Forwards IF. Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Causa Reactor Depressuritation." No written response required. O'REILLY, J. P. Region 2., Atlanta, Office of the Director. B0/11/07.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/10.
- B012040143 Forwards IE Bulletin B0-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. B0/11/14.
- B012080501 Forwards third interim response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies." Actuators may have been used as part of valve actuators. Suppliers will be contacted. MILLS, L. M. Tennassee Valley Authority. 80/11/17. 3pp. 07188:208.
- 8012030023 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Mater Leakage Inside Containment." No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21. 10.
- B012080004 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid," No written response required. O'REILLY, J. P. Region 2- Atlanta, Office of the Director. B0/11/24, io.
- 8012080660 Ack receipt of 801110 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/80-18. 50-519/80-17.50-520/80-18 & 50-521/80-16. MURPHY.C.E. Region 2. Atlanta-Reactor Construction & Engineering Support Branch. 80/11/25. 1p. 07187:042.
- --8012080668 Responds to NRC 801016 ltr re violations noted in IE Insp Repts 50-518/80-18,50-519/80-17,50-520/80-18 & 50-521/80-18. Corrective actions: drawing files updated & revised. List of current drawings & revisions issued. HILLS.L M Tennessee Valley Authority, 80/11/10. 3pp. 07187:043.
- --B012080678 Forwards IE insp Repts 50-518/80-18,50-519/80-17, 50-520/80-18 & 50-521/80-16 on 800801-29 & notice of violation MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/16. 2pp. 07187:046.
- ---8012080684 Notice of violation from insp on 800801-29.

 # Region 2, Atlanta, Office of the Director. 80/10/02. 1p.
 07187:048.
- --8012080295 lE Insp Repts 50-518/80-18.50-519/80-17.50-520/80-18 & 50-521/80-16 on 800801-29.Noncompliance noted: failure to take timely corrective action on drawing control findings. SMAN.N.B. Region 2. Atlanta. Office of the Director. CANTRELL.F. S. Region 2. Atlanta. Reactor Construction & Engineering Support Granch. 80/10/02. App. 07187:049.
- 8012170359 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange," No written response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.
- R. Periodic operating reports & related correspondence
- 8012300652 Forwards Oct 1980 socioeconomic monitoring & mitigation rept.
 MILLS,L.M. Tennessee Valley Authority. 80/12/23. 1p. 07359:091.
- --8012300445 "Hartsville Nuclear Plants Bocioeconomic Monitoring & Mitigation Rept." B01031.

 * Tennessee Valley Authority. HNP SMR-8. 80/10/31. 50pp. 07359:092
- S. Reportable occurrences, LERs & related correspondence
- 8012050349 Deficiency rept re link rod assembly in Delaval diesels. Douel counterbore of link rod assembly may be too shallow. Transamerica Delaval described insp method required. Onsite diesels will be placed on hold pending insp. MILLS.L.M. Tennessee Valley Authority. N. 80/11/26. 2pp. 07173:340.

- 8012050381 Third interim deficiency rept re standby gas treatment sys charcoal adsorber.CII nuclear submitted rept requiring review by util before final corrective actions can be prescribed.Final rept by 810302. MILLS, L. N. Tennessee Valley Authority. 80/11/26. 1p. 07173:338.
- B012100478 First interim deficiency rept re defective link rod assembly in Delaval diesel generators, initially reported on B01027. Onsite diesels will be placed on hold & inspected for defect. Final deficiency rept will be provided by B01125. MILLS, L. M. Tennessee Valley Authority. B0/11/26. 2pp. 07218:306.
- 8012230110 Part 21 rept, originally reported 801105, re inadequate wedge bolt expansion anchors by Rawlplug Caused by mfg deficiency.

 One-inch anchor design loads will be reduced Final rept by 810325.

 MILLS, L. M. Tannessee Valley Authority. 80/12/04. 3pp.
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERNOOD, G. G. General Electric Co. 80/12/08. 3pp.
- 8012300484 Final deficiency rept re lack of steam tunnel embedment stiffner plate weld, initially reported on 800505. Caused by inadequacy of manufacturer GA program. Missing weld has been added & inspected. GA program a
- 8012310335 Fourth interim deficiency rept initially reported 800215 re reactor pressure vessel shield call deficiencies. Addl unacceptable welds found & documented in MNP-4-115. Final rept by 8102602.
 MILLS.L.M. Tennessee Valley Authority. 80/12/22. 1p. 07361:047.
- DOCKET BTH-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

 A. Application/construction stage documents & correspondence
- 8012140050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREQ-0737 re TM1 action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISENHUT,D.O. Division of Licensing. 80/10/31. 7pp.
- B01222035B Ltr to all CP % QL holders for BMRs re requirement for implementation of QDYN code for licensing basis calculations performed by QE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. O. Division of Licensing. B0/11/04. 4pp.
- 8012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept, TVA-TR75-1 re const & preliminary testing. MILLS,L.M. Tennessee Valley Authority, B0/12/01. 3pp.
- B012160327 Responds to NRC B01001 request for info re environ qualification testing of safety-related equipment. Info will be available by B10201.
 MILLS.L.H. Tennessee Valley Authority. B0/12/09. 1p.
- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequeyah, Matts Bar & Bellefonte & TVA-TR75-1A. Changes supersede 801201 ltr. Changes will be included in application for OL for Hartsville. Phipps Bend & Yellou Creek plants. MILLS,L.K. Tennessee Valley Authority. 80/12/07. 5pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012150201 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 80/10/24. ip.
- 8012110840 Forwards IE Insp Repts 50-518/80-20.50-519/80-19. 50-520/80-20 & 50-521/80-18 on 800929-1001 No noncompliance noted. MURPHY, C. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/27. 2pp. 07225:135.
- --8012110847 IE Insp Repts 50-518/80-20, 50-519/80-19, 50-520/80-20 & 50-521/80-18 on 800925-1001. No noncompliance noted Major areus inspected; provious insp findings, licensee identified 10CFR50, 55e items & welding.

 CRONLEY.B.R. Region 2, Atlanta, Office of the Director. HERDT.A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/24. 7pp. 07225:137.

- 8012160730 Forwards IE Insp Repts 50-518/80-21.50-519/80-20. 50-520/80-21 & 50-521/80-19 on 800902-27 No noncompliance noted. MUXPHY.C.E. Region 2- Atlanta- Reactor Construction & Engineering Support Stanch. 80/10/28. 2pp 07261:318.
- 801217G004 Forwards IE Info Notice 80-39, "Malfunction of Sciencid Valves Mfg by Valcor Engineering Corp." No specific action or response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31, 1p.
- 801223093D Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31.
- 8012110056 Requests assessment & corrective actions taken re control room celling constructed w/apparently flammable tiles within 20 days.
 TEDESCO.R. L. Assistant Director for Licensing. 80/11/04. 3pp.
- 8012110807 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.inc." Written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/06.
- 8012030837 Forwards 1E Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07.
- S012080276 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/10.
- 8012040143 Forwards IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/14.

 19.
- 8012080601 Forwards third interim response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Actuators may have been used as part of valve actuators. Suppliers will be contacted. MILLS.L.M. Tennessee Valley Authority. 80/11/17. 3pp. 07188:208.
- 8012050023 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21,
- 8012080504 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required.
 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/24.
- 8012080660 Ack receipt of 801110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/80-18, 90-919/80-17,50-520/80-18 & 50-521/80-16. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/25. 1p. 07187:042.
- ~-8012080468 Responds to NRC 801016 ltr re violations noted in IE Insp Repts 50-518/80-18,50-519/80-17,50-520/80-18 & 50-521/80-16. Corrective actions: drawing files updated & revised. List of current drawings & revisions issued. MILLS.L.M. Tennessee Vailoy Authority. 80/11/10. 3pp. 07187:043
- --8012090678 Forwards IE Insp Repts 50-518/80-18,50-519/80-17, 50-520/80-18 & 50-521/80-16 on 800301-29 & notice of violation. MURTHY.C.E. Region & Atlanta, Reactor Construction & Engineering Support Branch. 80/10/16. 2pp. 07187:046.

- --8012083684 Notice of violation from insp on 800801-29.

 * Region 2, Atlanta, Office of the Director. 80/10/02. 1p. 07187:048.
- --8012080695 IE Insp Repts 50-518/80-18,50-519/80-17,50-520/80-18 & 50-521/80-16 on 800801-25. Moncompliance noted: failure to take timely corrective action on drawing control findings. SWARLIE. Region 2. Atlanta. Defice of the Director. CARTHELL, F. S. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 60/10/02 6pp. 07187:049.
- B012170357 Forwards IE Info Notice B0-27. Suppl 1: "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. D'REILLY, J. P. Region 2: Atlanta: Office of the Director. B0/11/26.
- R. Periodic operating reports & related correspondence
- 8012300652 Forwards Oct 1980 socioeconomic monitoring & mitigation rept. MILLS.L.M. Tennessee Valley Authority. 80/12/23. 1p. 07359:091-
- --B012300665 "Hartsville Nuclear Plants Socioeconomic Monitoring & Mitigation Rept," B01031.

 4 Tennessee Valley Authority, 1822 SMR-B, B0/10/31, 50pp. 07359:072.
- S. Reportable occurrences, LERs & related correspondence
- 8012050359 Deficiency rept re lint rod assembly in Delaval dissels. Dowel counterbore of link rod assembly may be too shallow. Transamerica Delaval described insy method required. Onsite diesels will be placed on hold pending insp. MILLS.L. II Tennessee Valley Authority. N. BO/11/26. 2pp. 07173: 340.
- 8012050C8) Third interim deficiency rept re standby gas treatment sys charcoal adsorber CII nuclear submitted rept requiring review by util before final corrective actions can be prescribed Final rept by 810302 MILLS.L.M. Tonnessee Valley Authority. 80/11/26. ip. 07173:338.
- 8012100478 First interim deficiency rept re defective link rad assembly in Delaval diesel generators, initially reported on 801027. Onsite diesels will be placed on hold & inspected for defect. Final deficiency rept will be provided by 801125. MILLS, L. M. Tennessee Valley Authority. 80/11/26. 2pp. 07218:306.
- 8012230110 Part 21 rept, originally reported 801105, re inadequate wedge bolt expansion anchors by Rawlplug. Caused by mfg deficiency. One-inch anchor design loads will be reduced. Final rept by 810325. MILLS, L.M. Tennessee Valley Authority. 80/12/04. 3pp.
- B012240039 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERHOOD, C. C. General Electric Co. B0/12/08 3pp.
- 8012300484 Final deficiency rept rellack of steam tunnel embedment stiffner plate weld.initially reported on 800505. Caused by inade-twacy of manufacturer QA program. Missing weld has been added & inspected. QA program a
- B012310335 Fourth interim deficiency rept initially reported B00215 re reactor pressure vessel shield wall deficiencies. Add1 unacceptable welds found & documented in IMP-A-115. Final rept by B10602.

 MILLS,L.M. Tennessee Valley Authority. B0/12/22. 1p. 07361:047.
- DOCKET STM-50-521 HARTSVILLE MUCLEAR PLANT, UNIT 4

 A. Application/construction stage documents & correspondence
- BOIR160050 Ltr to operating plant licensees,OL applicants & CP holders. Forwards NUREC-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be ret. EISENWUT,D.C. Division of Licensing. BO/10/34. 7pp.
- 8012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept. TVA-TR75-1 re const & preliminary testing. MILLS.L.N. Tennessee Valley Authority. 80/12/01. 3pp.

- B012160327 Responds to NRC B01001 request for info re environ qualification testing of safety-related equipment. Info will be available by B10201.

 MILLS.L.K. Tennessee Valley Authority. B0/12/09. 1p.
- 8012170316 Forwards planned changes to Chapter 17 of FGAR for Sequoyah, Natts Bar & Bellefonte & TVA-TR75-1A. Changes supersede 801201 ltr. Changes will be included in application for OL for Hartsville, Phipps Bard & Yellow Creek plants, MILLS.L.M. Tennessee Valley Authority. 80/12/09. Spp.
- F. Security, medical, emergency & fire protection plans
- 8012080839 Notification of 801121 meeting w/util in Bathesda,MD to discuss util position on central emergency response ctr & plans for emergency mgt.

 STAHLE.C., Licensing Branch 2, 80/11/19, 4pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012150201 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2," No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24.
- B012110840 Forwards IE Insp Repts 50-518/80-20,50-519/80-19, 50-520/80-20 & 50-521/80-18 on 800927-1001. No noncompliance noted. MURPHY, C. E. Region 2: Atlanta Reactor Construction & Engineering Support Branch. 80/10/27. 2pp.
- --8012110847 IE Insp Repts 50-518/80-20, 50-519/80-19, 50-520/80-20 & 50-521/80-18 on 80092%-1001. No noncompliance noted. Major areas inspected: previous insp findings, licensee identified 10CFR50, 55e items & welding.

 CROMLEY, B. R. Region 2: Atlanta, Office of the Director. 80/10/24, 700.
- 8012160/30 Forwards IE Insp Repts 50-518/80-21,50-519/80-20, 50-529/80-21 & 50-521/80-19 on 800902-27. No noncompliance ' noted, MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/10/28, 2pp.
- --80(2160750 IE Insp Repts 50-518/80-21.50-519/80-20.50-520/80-21 & 50-521/80-19 on 800902-27. No noncompliance noted Major areas inspected; earth compaction, rock fill & concrete for spray ponds.

 SWAN, U. D. Region 2. Atlanta. Office of the Director. 80/10/27.500.
- 8012170004 Forwards IE Info Notice 80-37, "Halfunction of Solenoid Valves Hig by Valcor Engineering Corp." No specific action or response required.

 O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/10/31.
- B012230030 Forwards IE Circular 80-23, "Potential Defects in Belait Power Sys Emergency Generators," No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- 8012110066 Requests assessment & corrective actions taken re control room ceiling constructed w/apparently flammable tiles within 20 days.
 TEDESCO.R.L. Assistant Director for Licensing. 80/11/04. 3pp.
- 8012110807 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/06. 1p.
- BO120308:7 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/07. 1p.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/10.

- B012040143 Forwards IE Bulletin B0-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. O'REILLY, J. P. Region 2. Atlanta, Office of the Director, 80/11/14. is.
- 8012080601 Forwards third interim response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies." Actuators may have been used as part of valve actuators. Suppliers will be contacted. MILLS.L.M. Tennessee Valley Authority. 80/11/17. 3pp.
- 8012050023 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Lealage Inside Containment." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/21.
- 8012080094 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No written response required.

 O'REILLY, J. F. Region 2. Atlanta, Office of the Director. 80/11/24.
- 8012080640 Ack receipt of 801110 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-518/80-18, 50-519/80-17, 50-520/80-18 ½ 50-521/80-16. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/25. 1p.
- --801208066B Responds to NRC 801016 ltr re violations noted in IE Insp Ropts 30-518/80-18,50-519/80-17,50-520/80-18 & 50-521/80-16. Corrective actions: drawing files updated & revised. List of current drawings & revisions issued. HILLS.L.M. Tennessee Valley Authority. 80/11/10. 3pp.
- --8012030678 Forwards IE Insp Repts 50-518/80-18,50-519/80-17, 50-520/80-18 & 50-521/80-16 on 800301-29 & natice of violation. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/14. 2pp.
- --8012080684 Natice of violation from insp on 800801-29.

 * Region 2. Atlanta, Office of the Director. 80/10/02. ip.
- --8012080695 IE Insp Repts 50-518/B0-18.50-519/B0-17.50-520/B0-18 & 50-521/B0-16 on B00801-29. Noncompliance noted: failure to take timely corrective action on drawing control findings. SWAll. M. B. Region 2. Atlanta. Office of the Director. 80/10/02.6pp.
- B012170359 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26.
- R. Pariodic operating reports & related correspondence
- 8012300652 Forwards Oct 1980 socioeconomic monitoring & mitigation rept. MILLS.L.M. Tennessee Valley Authority. 80/12/23. 1p.
- --8012300665 "Hartsville Nuclear Plants Socioeconomic Monitoring & Mitigation Rept," 801031.

 4 Tennessee Valley Authority. HMP SMR-8. 80/10/31. 50pp.
- S. Reportable occurrences, LERs & related correspondence
- 8012050369 Deficiency rept re link rod assembly in Delaval diesels.

 Dowel counterbore of link rod assembly may be too shallow.

 Transamerica Delaval described insp method required. Onsite diesels will be placed on holf pending insp.

 MILLS.L.M. Tannessee Valley Authority. N. 80/11/26. 2pp.
- 8012090381 Third interim deficiency rept re standby gas treatment sys charcoal adsorber.CII nuclear submitted rept requiring review by util before final corrective actions can be prescribed.Final rept by \$10302. MILLS.L.M. Tennessee Valley Authority. \$07/11/26. 1p.
- 8012100478 First interim deficiency rept re defective link rod assembly in Delaval diesel generators, initially reported on 801027. Unsite diesels will be placed on hold & inspected for defect. Final deficiency rept will be provided by 801125. MILLS, L. M. Tennessee Valley Authority. 80/11/26. 2pp.

- 6012230110 Part 21 rept.originally reported 801105, re inadequate wedge bolt expansion anchors by Rawlplug Caused by mfg deficiency.
 One-inch anchor design loads will be reduced Final rept by 810325.
 MILLS.L.M. Tennessee Valley Authority. 80/12/04. 3pp.
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERKOOD, C. G. General Electric Co. 80/12/08. 3pp.
- 8012300484 Final deficiency rept re lack of steam tunnel embedment stiffner plate weld, initially reported on 800505. Caused by inadequacy of manufacturer 04 program. Missing weld has been added & inspected. 04 program audit conducted.

 MILLS, L. M. Tennessee Valley Authority. 80/12/18, 3pp.
- DOCKET STN-50-522 SKAGIT MUCLEAR POWER PROJECT, UNIT 1

 A. Application/construction stage documents & correspondence
- 8012220358 Ltr to all CP & DL holders for BHRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.
 EISENMUT, D. O. Division of Licensing. 80/11/04. App.
- 8012319386 Submits applicant second quarterly status rept per ASLB order of 800827 Geological & geophysical program involved substantial field work by consultants, including drilling, trenching & geological mapping Related correspondence. THOMSEN, F. T. Puget Sound Power & Light Co. THOMSEN, F. T. Perkins, Coie, Stane, Oisen & Williams. 80/12/24. 3pp. 07369:088.
- G. Adjudicatory correspondence
- 8012230001 Requests permission to withdraw from proceeding based on revised licensee application & ASLG 800827 order. MOSER.C.T. Scagit County, NA. 80/11/24. 1p. 07311:145.
- 8012240446 Requests return, per 10CFR2.790, of previously submitted proprietary geophysical data re facility licensing procedure. Info concerns proposed site in Skagit County, NA. Attachments withheld(ref 10CFR2.790).
 LITLE,D.S. Perkins, Coie, Stone, Olsen & Williams. 80/12/15. 2pp. 07327:334.
- 8012310388 Submits applicant second quarterly status rept per ASLB order of 800827. Geological & geophysical program involved substantial field work by consultants, including drilling, trenching & geological amapting. Related correspondence.
 THOMSEM, F. T. Puget Sound Power & Light Co. THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams. 80/12/24. 3pp. 07349:083.
- H. General correspondence
- B012040256 Forwards info in response to 801029 ltr requesting licensing categories & info re floating nuclear plants. PURPLE,R A. Division of Licensing. 60/11/17. 4pp.
- --8012040298 Requests info re facilities w/active CPs pending, license definitions & requirements for floating nuclear plants. DREY.L.A. Affiliation Unknown. 80/10/29. 1p.
- S. Reportable occurrences, LERs & related correspondence
- R012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERNODD, Q. Q. General Electric Co. 80/12/08 3pp.
- DOCKET STN-50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012220358 Ltr to all CP & OL holders for SURs re requirement for implementation of OBYN code for licensing basis calculations performed by GE.Applicable to all license applications & proposed amends, including core reloads.

 EISENMUT, D. O. Division of Licensing. 80/11/04. 4pp.



- 8012290232 Response in opposition to all PL Hourihan contentions, save Contention &B re postulated ATMS event Other contentions do not contain proper subj matter. Centificate of Svc encl. MCGURREN, H. J. Hearing Branch 1. 80/12/19. 15pp. 07345:043.
- 8012300487 Response in opposition to disputed Contention 6A reconsequences of Class 9 accidents.Contention 6B resafety measures to mitigate postulated ATUS event & Contention 14 reseffects of radiation.U/Certificate of Svc. OEHx.A.C., BISCHOFF.C.A. Arizona Public Service Co. GEHR.A.C. Snell & Wilmer. 80/12/19. 17pp. 07359:185.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012230302 Forwards Amend 3 to Palo Verde 1,2 & 3 FSAR, VAN BRUNT, E. E. Arizona Public Service Co. B0/12/18, 1p. 07308.001,
- --8012230307 Amend 3 to Palo Verde 1.2 & 3 FSAR. * Arizona Public Service Co. 80/12/18. 250pp. 07308:001.
- Q. Inspection reports, IE Bulletins & correspondence
- B012170725 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required. ENGELERN,R.H. Region 9, San Francisco: Office of the Director. 80/10/24, 1p. 07266:089.
- 8012170757 Forwards lE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No written response required. ENGELKEN,R.H. Region 5. San Francisco, Office of the Director. 80/10/20. ip. 07265:075.
- 8012010010 Forwards IE Insp Repts 50-528/80-15, 50-529/80-15 & 50-530/80-15 on 800909-12. No noncompliance noted. SPENCER. 0. 5 Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80/10/31. 2pp. 07092:097.
- --8012010014 IE Insp Repts 50-522/80-15.50-529/80-15 & 50-530/80-15 on 800909-12.No noncompliance noted Hajor areas inspected: licenses action on previous insp findings & Part 21 repts & installation of pipe supports & restraints.
 ECKHARDT.J.H., HERNANDEZ.G., D'ANGELD.A.J. Region 5, Ban Francisco, Office of the Director. 80/10/29. 8pp. 07092:099.
- 8012170844 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Hfg by Valcor Engineering Corp." No written response is required. ENGELMENT. Region 5, San Francisco, Office of the Director, 80/10/31. 1p. 07266:033.
- 8012120207 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 80/11/06. 1p. 07228:292.
- 8012030920 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. EMOELKFM.R.H. Region 5, San Francisco, Office of the Director. 80/11/07. ip. 071 0:179.
- 8012080638 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Sesse Unit 1." No response required. ENCELKEN,R.H. Region 5, San Francisco, Office of the Director. 80/11/10. 1p. 07183:035.
- 8012040215 Forwards 1E Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/14. 1p. 07158: 131.
- 801204053B Forwards IE Bulletin BO-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 80/11/21. 1p. 07169:156.
- 8012160075 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No response required. ENCELKPH.R.H Region 5, San Francisco, Office of the Director. 80/11/24. ip. 07262:104.

- E012160127 Forwards Suppl 1 to 1E Info Notice 80-27, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
 ENGELVEN.R.H. Region 5, San Francisco, Office of the Director.
 80/11/26. 1p. 07262:073.
- 8012310231 Forwards IE Insp Repts 50-528/80-18.50-527/80-18 & 50-530/80-18 on 801001-31.No noncompliance noted. SPENCFR.0.5 Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 80/12/03. 2pp. 07370:038.
- --8012310234 IE Insp Repts 50-528/80-18.50-529/80-18 & 50-530/80-18 on 801001-31 No noncompliance noted Major areas inspected: reactor vessel protection, anchor bolt tensioning & RCPB installation.
 VORDERBRUEGGEN Region 5. San Francisco, Office of the Director. MAYKS, R. C. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 80/12/01. Spp. 07370:040.
- 5. Reportable occurrences, LERs & related correspondence
- 8012100384 Interim deficiency rept updating 801120 telcon re sway struts, snubbers & shot) suppressors found to contain partially or totally disangaged self-aligning rod end bushings. Final rept to be submitted by 810301. VAN BRUNT, E. E. Arizona Public Service Co. 83/12/01, 3pp. 07219:046.
- 8012100414 Second interim deficiency rept re loose bushings on Corner & Lada sizey struts Investigation continuing Resolution & completion plan will be implemented by 810201 Final rept will be submitted by 810331 VAN BRUNF, E.E. Arifona Public Service Co. 80/12/01. 4pp. 07219:040.
- 6012230379 Interim deficiency rept re excessive shear stresses in concrete slabs supporting Safety Injection Tanks 1B.2A & 2B. Final rept completion date reforecasted to B10301. VAN BRUHI-E.E. Arizona Public Service Co. 80/12/12. 2pp. 07318:264.
- B012230496 Requests evaluation of deficiency repts within 30 days re weld overstress caused by pulled pipe spools, cable tray supports not meeting drawing requirements & class IE conductors too close to non-Class IE conductors. VAN BRUNT. E. E. Artiona Public Service Co. B0/12/12. 2pp. 07316:239.
- 8012230449 Interim deficiency rept re inadequate concrete strength acheived u/pneumatically placed mortar repairs.Final rept incomplete & will be sent by 601229. VAN BRUNTLE.E. Arizona Public Service Co. 80/12/16. 2pp. 07318:285.
- T. Hearing transcripts on non-antitrust matters
- 8012030197 Transcript of 801202 prehearing conference in Phoenix,AZ on facility OLs.Pp 1-50.

 * Atomic Safety and Licensing Board Panel. 80/12/02. 50pp.
 07181:217.
- 8012160499 Forwards Vols 1 b II of transcript, "Sys Review of Palo Verde Kuclear Generating Station Equipment Qualification, Before Equipment Qualification Review Board." Vol III uill be submitted w/resolutions to open items. VAN BRUNT, E.E. Arizona Public Service Co. B0/12/05, ip. 07249:039.
- --8012160505 Vol II of III of transcript of 800725 & 26 "Sys Review of Palo Verde Nuclear Cenerating Station Equipment Qualification Before Equipment Qualification Review Board." Pp 214-387. * Arizona Public Service Co. 80/09/25. 182pp. 07249:040.
- --B012170530 Vol I of [1] of transcript of 800725 & 26 "Sys Review of Palo Verde Nuclear Generating Station Equipment Qualification Before Equipment Qualification Review Board," Pp 1-213. * Artiona Public Service Co 80/07/25. 221pp. 07249:221.
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- B012160090 Ltr to operating plant licensees. DL applicants & CP holders. Forwards NUREG-0737 re YM1 action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates util be net. EISEKMUT.D. 0. Division of Licensing. B0/10/31. 7pp.

- 8012100246 Notification of S01118 meeting w/util in Bethesda.MD to discuss NRC position on location of technical support ctr. KERRIGAN.J. Licensing Branch 3. 80/11/18. 3pp. 07217; 322.
- 8012220319 Forwards util / Bechtel Power Corp 801113 & 05 responses to open items re Class IE at power tys review & as continuation of review record. Final resolution to be submitted upon resolution.

 VAN BRUNTE. E. Aritona Public Service Co. 80/12/09. 32pp. 07187-001
- C. Utility Environmental Report (ER), amends & correspondence
- 8012230456 Requests removal of DOA Soil Conservation Svc from OL stage environ mept distribution list, per encl DOA 801120 ltr to Bechtel.
 VAN BRUNT, E. E. Arizona Public Service Co. 80/12/16. 2pp. 07312:272.
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 8012140704 Discusses 801125 meeting re encl environ review schedule. Project manager should be contacted if Accident Evaluation Branch review of Class 9 accidents is delayed. MIRAGLIA.F. Licensing Branch 3. 80/12/04. 2pp. 07262:313.
- 8012160237 Sunmary of 801125 meeting @/ARL re environ review. KERRIGAN. J. Licensing Branch 3 80/12/04. 6pp. 07252:230.
- F. Security, medical, emergency & fire protection plans
- B012020693 Notification of B01119 meeting w/util in Bethesda.MD to discuss facility fire protection sys.

 KERRIGAN.J. Licensing Branch 3. 80/11/17. 3pp. 06916:001.
- BO12090044 Forwards info & drawings of fire detection & suppression sysumed in facility auditiony bldg.per agreement of B01119 meeting. Physical security drawings withheld from public disclosure (ref. IDCFR2. 750). Aperture cards in PDR. VAN BRUITE E. Arizona Public Service Co. 80/12/03. 9pp. 07187-001
- G. Adjudicatory correspondence
- B012290423 Forwards intervenor, joint applicants & NRC updated stigulations be language of intervenor remaining contentions.

 MCGURRERAH.J. Hearing Branch 3 00/12/12, 2pp. 07336:254.
- --B012270430 Updated stipulations re intervenors PL Hourihan, K Dahl & C Shuey contentions. Parties agreed to language in accepted Contentions 1,5.7 % & V disputed Contentions 6A, 6B, 14, 17, 18, 23A, 23S & 2B, GERR, A. C. Snell & Wilner HOURIHAN, P. L. Affiliation Unknown, MCGURREN, H. J. Hearing Branch 3 B0/12/12, 14pp. 07336:296.
- 8012290232 Response in opposition to all PL Hourihan contentions, save Contention 63 re postulated ATMS event Other contentions do not contain proper subj matter. Certificate of Syc encl. MCGURREN. H. J. Hearing Stanch 1. 80/12/19. 15pp. 07345:043.
- 8012300487 Response in opposition to disputed Contention 6A reconsequences of Class 9 accidents. Contention 6B re-safety measures to mitigate postulated ATMS event & Contention E4 re-effects of radiation W/Certificate of Svc. GEHR.A. C., BISCHOFF.C. A Artrona Public Service Co. GEHR.A. C. Snell & Wilmer. 60/12/19. 17pp 07359:185.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012230302 Forwards Amend 3 to Palo Verde 1,2 & 3 FSAR. VAN BRUNT, E. E. Arizona Public Service Co. 80/12/18. 1p. 07308:001.
- --8019230307 Amend 3 to Palo Verde 1.2 & 3 FSAR.

 + Arizona Public Service Co. 80/12/18. 250pp. 07308:001.
- O. Inspection reports: IE Bullatins & correspondence
- 8012170/25 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required. EIGELERIAR H. Region 5. San Francisco, Office of the Director, 80/10/24.

- 93:2170757 Forwards IE. Info Notice 80-38, "Cracking in Charging Pump Casing Cladding," No written response required. ENGELMFN, R. M. Region 5, San Francisco, Diffice of the Director. 80/10/30. ip. 07265:075.
- 8012010010 Forward: 1E Insp Repts 50-528/80-15,50-529/80-15 & 50-530/80-15 on 800709-12.Na honcompliance noted. SPENCER.G. S Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80/10/31. 2pp. 07092:097.
- --8012010014 16 Insp Repts 50-526/80-15, 50-529/80-15 & 50-530/80-15 on 800709-12.No noncompliance noted Major areas inspected: licensee action on previous insp findings & Part 21 repts & installation of pipe supports & restraints.

 ECKHARDT, J.H., HERKANDEZ, G., D'ANGELD, A. J. Region 5, San Francisco, Office of the Director. 80/10/29, 8pp. 07092:099.
- 8012170844 Forwards IE Info Nutice 80-39, "Malfunction of Sciencid Valves Mig by Valcor Engineering Corp." No written response is required.
 ENGELERIA: H. Region 5, San Francisco, Office of the Director. 80/10/31. 1p. 07266:033.
- 8012120209 Forwards IE Bulletin BO-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required. ENGELAFILR. H. Region 5, San Francisco, Office of the Director. 80/11/06. ip. 07228:292.
- 8012030920 Forwards 1E Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. ENSELKFN.R.K. Region 5. San Francisco
- 801208063B Forwards IE Info Notice 80-41, "Failure of Buing Check Valve in Decay Heat Removal Cys at Davis Besse Unit 1." No response required. EngELKERIA: H. Region 5, San Francisco, Office of the Director, 80/11/10. 1p. 07183:035.
- 8012040215 Forwards IE Bulletin 80~23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ENCELKER.R.H. Region 5, San Francisco, Office of the Director. 80/11/14. 1p. 07158:131.
- 8012040538 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." No written response required. ERGELKFU, R. K. Region 5, San Francisco, Office of the Director. 80/11/21. 1p. 07169:156.
- 8012160095 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Shubber Fluid." No response required. ENGELKFN.R.H. Region 5, San Francisco, Office of the Director, 80/11/24. 1p. 07262:104.
- 8012160127 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. EMSEKFIJR. H. Region 5, San Francisco, Office of the Director, 80/11/26. 1p. 07262:073.
- 8012310231 Forwards IE Insp Repts 50-528/80-18,50-529/80-18 & 50-533/80-18 on 901001-31.No noncompliance noted. SPENCER.G.S. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 80/12/03. 2pp. 07370:038.
- .--8012310234 IE Insp Repts 50-528/80-18,50-529/80-18 & 50-530/80-18 on 801001-31. No noncompliance noted, Major areas inspected: reactor vessel protection, anchor bolt tensioning & RCPB installation WORDERRRUEGSEN Region 5, San Francisco, Défice of the Director. HAYNES.R.C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80/12/01. Spp. 07370:040.
- S. Reportable occurrences, LERs & related correspondence
- 8012100384 Interim deficiency rept updating 801120 telcon re sway struts, snubbers & shock suppressors found to contain partially or totally disengaged self-aligning rod end bushings. Final rept to be submitted by 810301. VAN BRUNT, E.E. Arizona Public Service Co. 80/12/01, 3pp. 07217:046.
- 8012100414 Second interim deficiency rept ne loase bushings on Carner & Lada suay struts. Investigation continuing. Resolution & completion plan will be implemented by 810201. Final rept will be submitted by 810331. VAN BRUNT.E.E. Arizona Public Service Co. 80/12/01. 4pp. 07217:040.

- 8012230399 Interim deficiency rept re excessive shear stresses in concrete slabs supporting Safety Injection Tanks 18,2A & 2B. Final rept completion date reforecasted to 810301. VAN BRUNTLE.E. Arizona Public Service Co. 80/12/12. 2pp. 07318: 246.
- 8012230496 Requests evaluation of deficiency repts within 30 days re weld averstress caused by pulled pipe spools cable tray supports not meeting drawing requirements & class IE conductors too close to non-Class IE conductors.

 VAN BRUNTIE. E. Arizona Public Service Co. B0/12/12. 2pp. 07316: 237.
- 8012230449 Interim deficiency rept re inadequate concrete strength acheived u/pneumatically placed morter repairs. Final rept incomplete & will be sent by 801229.

 VAN BRUNT, E. E. Arizona Public Service Co. 80/12/tó. 2pp.
- T. Hearing transcripts on non-antitrust matters
- 8012080199 Transcript of B01202 prehearing conference in Phoenix.AZ on facility DLs.Pp (-50. * Atomic Safety and Licensing Board Panel. B0/12/02. 50pp. 07181:217.
- 8012160499 Forwards Vols I & Il of transcript, "Sys Review of Pale Verde Nuclear Generating Station Equipment Qualification, Before Equipment Qualification Review Board," Vol III will be submitted w/resolutions to open items. VAN SRUNT, E. E. Arizona Public Service Co. 80/12/05. 1p.
- --B012160505 Vol II of III of transcript of B00925 & 24 "Sys Review of Palo Verde Nuclear Generating Station Equipment Qualification Before Equipment Gualification Review Board." Pp 214-389. * Arizona Public Service Co. B0/09/25. 182pp. 07249:040.
- --8012170530 Vol 1 of III of transcript of 800725 & 26 "Sys Review of Palo Verde Nuclear Generating Station Equipment Qualification Before Equipment Qualification Review Board." Pp 1-213. # Arizona Public Service Co. 80/09/25. 22ipp. 07249:221.
- DDCKET 8TN-50-530 PALD VERDE NUCLEAR STATION, UNIT 3

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licenses, CL applicants & CP holders.
 Forwards NUREG-0737 re TML action plan requirements Requests operating reactor licenses confirmation in 45 days that Encl 1 implementation dates will be net.
 EISENHUT, D. G. Division of Licensing. B0/10/31. 7pp.
- 8012100246 Notification of 801118 meeting w/util in Bethesda.MD to discuss NRC position on location of technical support ctr. KERRIGAN.J. Licensing Branch 3. 80/11/18 3pp. 07217:322.
- 8012220319 Forwards util & Rechtel Power Corp 801113 & 05 responses to open items re Class IE ac power sys review & as continuation of review record. Final resolution to be submitted upon resolution.

 VAN BRUNTLE E. Arizona Public Service Co. 80/12/09. 32pp. 07183: 001.
- C. Utility Environmental Report (ER), amends & correspondence
- 8012230486 Requests removal of DDA Scil Conservation Svc from GL stage environ rept distribution list.per encl DDA 801120 ltr to Bechtel.
 VAN BRUNTLE E. Arizona Public Service Co. 80/12/16. 2pp. 07312: 272.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 8012160204 Discusses 801125 meeting re encl environ review schedule. Project manager should be contacted if Accident Evaluation Branch review of Class 9 accidents is delayed.
 MIRAOLIAF. Licensing Branch 3. 80/12/04. 2pp. 07262:313.
- 8012160237 Summary of 801125 meeting U/ANL re environ review. KERRIGAN, J. Licensing Branch 3. 80/12/04, App. 07252:230.

- F. Security, medical, emergency & fire protection plans
- B012020693 Notification of B01119 meeting u/util in Bethesda.MD to discuss facility fire protection sys. KERRIGAN.J. Licensing Branch 3 B0711717, 3pp 06914:001.
- 8012090024 Forwards info & Frauings of fine detection & suppression used in facility abbiliary bldg.per agreement of 801119 meeting Physical security drawings withheld from public disclosure (ref 100FRS) 790) Aperture cards in PDR. VAN BRUNT, E. E. Arizona Public Service Co. 80/12/03. 9pp. 07187:001.
- G. Adjudicatory correspondence
- 8012270:029 Forwards intervenor joint applicants & NRC updated stipulations to language of intervenor remaining contentions. MCOURREW.H.J. Hearing Branch 3 80/12/12. 2pp. 07336:254.
- --8012270430 Updated stipulations re intervenors PL Hourihan,K Dah Shueg contentions. Parties agreed to language in accepted Contentions 1,5,7 & 8 f disputed Contentions 6A,6B,14,17,18, 23A,23B & 28 GERR,A.C. Shell & Wilmer HOURIHAN,P.L. Affiliation Unknown HOGURREM.H J. Hearing Branch 3 80/12/12. 16pp. 07336:256.
- 8012270232 Response in apposition to all Pt. Hourihan contentions, a Contention 68 re-postulated ATMS event. Other contentions do not contain proper subj matter. Certificate of Svc encl. MCGURREN.H.J. Hearing Branch 1 80/17/19, 19pp. 07345:043.
- 8012300487 Response in apposition to disputed Contention 6A reconsequences of Class 7 accidents. Contention 6B resafety measures to mitigate postulated ATKS event & Contention 14 resifiects of radiation M/Certificate of Svc. GEHR.A. C. BISCHOFF.C.A Arizona Public Service Co. GEHR.A. C. Snatl & Wilmer. 80/12/17 17pp. 07359:185.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8012230392 Forwards Amend 3 to Palo Verde 1, 2 & 3 F9AR.

 VAN BRUNTLE E. Artiona Public Service Co. 80/12/18. 1p. 07398:001.
- --8012230307 Amend 3 to Pala Vende 1,2 8 3 FSAR.

 4 Arizona Public Service Co. 80/12/18. 250pp. 07308:001.
- Q. Inspection reports. IE 8:11etins & correspondence
- 8012170725 Forwards IE. In to Matice 80-37. "Containment Cooler Leak Reactor Cavity Floodsin; at Indian Point Unit 2." No written response required ENGELKFUR.H. Region 5. San Francisco. Effice of the Director. 80/10/24. ip. 67266.05%.
- 8012170797 Forwards IE Info Notice 80-38, "Gracking in Charging Pu Casing Cladding." No writhon response required. ENCELKERR.H. Region 5, San Francisco, Office of the Director. 80/10/30, ip. 07265.675
- 8012010010 Forwards 16 trip Repts 50-528/80-15,50-529/80-15 & 50-530/80-15 on 800909-12 No noncompliance noted. SPENCER, 0.3 Region 5. San Francisco, Reactor Construction & Engineering Support Branch. E0/10/31. 2pp. 07092:097.
- -8012010014 IE Insp Repts 50-528/80-15,50-529/80-15 & 50-530/80-1 800909-12 No honcompliance noted Major areas inspected: Accesse action on previous inspectatings & Part 21 repts & Installation of pipe separes & restraints. ECKHARDT,J.H., HERNANDEZ,G., D'ANGELO,A.J. Region 5, San Francisco, Office of the Director. 80/10/29. 8pp. 07092:099
- 8012170844 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mig by Valcor Engineering Corp." No written response is required.
 ENGELEFISR M. Region 5, San Francisco. Diffice of the Director.
 80/10/31. 1p. 07266.033
- 8012120209 Forwards IE Bulletin 80-21. "Valve Yoles Supplied by Ha Foundry Co.Inc." Written response required. ENSELKEN.R.H. Region 5. Sam Francisco. Office of the Director. 80/11/06. ip. 07228:292.

- 8012030920 Forwards IR Info Nonice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Deprosautization." No written response required. ENGELERIAR H. Region b. San Francisco, Office of the Director. 80/11/07. 1p. 07150:179
- 8012080638 Forwards IE Info Notice 80-41. 'Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.

 RMSELECTION Region 5, San Francisco, Office of the Director.

 80/11/10. 1p 07183-025.
- 8012040P15 Forwards IE Bulletin 80-23. 'Failures of Solenoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions. ENGELMFILE M. Region 5. San Francisco. Office of the Director. 80/11/14. 1p. 07158 t31
- 8012040538 Forwards IE Bulletin 60-24. 'Prevention of Damage Due to Mater Leakage Inside Containment " No written response required. ENSELFHIRRH Region 5. San Francisco. Office of the Director. 80/11/21. 1p. 07169:156
- 8012140095 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Flvid." No response required. ENGELMEN,R.H. Region 5, San Francisco, Office of the Director, 80/11/24, 1p. 07262:104.
- 8012160127 Forwards Suppl 1 to 1E Info Notice 80-29. "Broken Studs on Terry Turbine Steem Inlet Flange." No written response required. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 80/11/26. 1p. 07262:0/3
- 801231023) Forwards IE Insp Repts 50-528/80-18.50-529/80-18 & 50-530/80-18 on 801001-31.No nencompliance noted. SPENCERO, S. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 60/12/03 2pp. 07370:038.
- --8012310234 IE Insp Repts 50-526/80-18.50-529/80-18 & 50-530/80-18 on 801001-31.No noncompliance noted Major areas inspected: reactor vested protection, anchor bolt tensioning & RCPB installation.

 VORDERBRUGGEN Region 5. San Francisco, Office of the Director. HAYLESIR.C. Region 5. San Francisco, October Construction & Engineering Support Branch. 80/12/01. 5pp. 07370:040.
- S. Reportable occurrences, LERs & related correspondence
- 8012100394 Interim deficiency rept updating 801120 telcon re sway struts, snubbers to special suppressors found to contain partially or totally disengated self-aligning rod end bushings. Firsal rept to be submitted by 810301. VAN SRUNIZE E. Arsiona Fublic Service Co. 80/12/01. 3pp. 07219-084
- 8012100414 Second interim deficiency tept re-loose bushings on Corner & Lada suay struts. Investigation continuing, Resolution $\mathcal U$ completion plan will be implemented by 810201. Final rept will be submitted by 810233. VAN BRUNTLE $\mathcal E$. Arizona Public Service Co. 80/12/01. 4pp. 07219: 040.
- 8012230496 Requests evaluation of deficiency repts within 30 days reweld overstress caused by pulled pipe spools, cable tray supports not meeting disaming requirements & class IE confoctors too close to non-Class IE conductors. VAN BRUNTIE.E. Artiona Public Service Co. 80/12/12. 2pp. 07318-239
- 8012230449 Interim deficiency mept re inadequate concrete strength acheived u/gneumatically placed montan repairs. Final rept incomplete & will be sent by 801229. VAN BRUKILE E. Arizona Public Service Co. 80/12/16. 2pp. 07318:285.
- T. Hearing transcripts on non-antitrust matters
- 8012030199 Transcript of 801202 prehearing conference in Phoenix, AZ on facility OLs. Pp 1-50.

 * Atomic Safety and Licensing Board Panel: 80/12/02, 50pp. 07181:217.
- 8012160499 Foruards Vols ! & II of transcript, "Sys Review of Palo Verde Nuclear Generating Station Equipment Qualification, Before Equipment Qualification Review Board." Vol III will be submitted w/resolutions to open items. VAN BRUNFLE E. Artiona Public Service Co. 80/12/05. 19. 07249:039.

- --8012160595 Vol II of III of transcript of 800725 % 26 "Sys Review of Palo Verde Muclear Generating Station Equipment Qualification, Defore Equipment Qualification Review Board." Pp 214-389. Arizona Public Service Co. 80/09/25. 182pp. 07249:040.
- --8012170530 Vol I of III of transcript of B00725 & 26 "Bys Review of Palo Verde Nuclear Generating Station Equipment Qualification Before Equipment Gualification Review Board." Pp 1-213. Arizona Public Service Co. 80/09/25. 221pp. 07249:221.
- DOCKE: 50-537 CLINCH RIVER BREEDER REACTOR

 A. Application/construction stage documents & correspondence
- BO12190161 "Thermal Hydraulic LKFBR Safety Experiments:" monthly highlight ltr for Oct 1930. OINSBERO, T. Brookhaven National Laboratory. FIN A-3024. B012190161. 80/10/31. 4pp. 07282:044.
- B012020497 Forwards "Prediction of FFTF Natural Circulation Test
 Results Using Clinch River Breeder Reactor Plant Project
 Methodology," & "Domo Pretest Predictions for FFTF Natural
 Circulation Tests." Info available in Central Files only,
 CIPELAND.P.L. Energy, Dept. of, Clinch River Breeder Reactor Plant,
 B0/11/28. 2pp. 07131:012
- B. Utility Preliminary Safety Analysis Report, amends
- 8012050083 Forwards Certificate of Evc confirming distribution of Amend 58 to PSAR. CDPELAND, R.L. Energy, Dept. of, Clinch River Breader Reactor Plant. 80/12/02. 2pp. 07175:070.
- BO12310303 Forwards Amend 59 to PSAR Service list encl. COPELAND, R. L. Energy, Dept. of, Clinch River Breeder Reactor Plant. BO/12/30. 4pp. 07346: 040.
- --8012310305 Amend 59 to PSAR.

 4 Energy Dept.of. Clinch River Breeder Reactor Plant. 80/12/30. 1400pp. 07345:048.
- S. Reportable occurrences, LERs & related correspondence
- 6012100408 Part 21 rept re inoperable prototupe valve, reported on 801015 Procurement controls are in place to prevent fabrication of plant valves prior to design verification. Evaluation determined malfunction nonreportable. MCDERMOTT, R. J. Rockwell International Corp., Atomics International Div. 80/11/14. 3pp. 07218:005.
- DOCKET 81N-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees. CL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl I implementation dates will be met. EISERHUT. D. Q. Division of Licensing. 80/10/31. 7pp.
- 8012190427 Confirms 801207 meeting w/util at site to discuss NRC evaluation of regulatory performance. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 80/12/02. ip. 07886:261.
- 8012310165 Notification of 810109 meeting w/util in Bethesda.MD on insp & testing re cadweld deficiencies at facilities. MCNO, H.J. Assistant Director for Components & Structures Engineering. 80/12/18. 3pp. 0/369.277.
- H. General correspondence
- 8012300557 Supports operation of facility. Requests info on nuclear power plants. Congressional ltr encl. WALKER, C. K. Affiliation Unknown, 80/12/24, 2pp. 07308:001.
- Q. Inspection reports: IE Bulletins & correspondence
- 8012170498 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER.J.O. Region 3. Chicago, Office of the Director. 80/10/24.

 1p. 07268:081.

- 8012030376 Forwards IE Insp Repts 50-546/80-37 & 59-547/80-37 on 800701-30. No noncompliance nated. FIGRELLI,G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/10/28. 2pp. 07149:339.
- --B012030407 IE Insp Repts 50-546/80-37 & 50-547/80-37 on B00901-30. No noncompliance noted Major areas inspected auxiliary bldg, fuel handling bldg, storage of safety-related items & licensee program for receiving insp.

 HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the Diractor. 80/10/27, 4pp 07149, 340.
- B012220168 Requests extension until B1010t re corrective action implementation date for Item of Noncompliance 80-28-01. SHIELDS,S.W Public Service Co. of Indiana, Inc. 80/11/07. ip. 07303:238.
- 8012020743 Forwards three Performance Appraisal Branch insp repts & mgt evaluation treo w/user guide so that facility can compare program to program already reviewed & nake appropriate adjustments. W/o enci.

 KEPPLER.J. G. Region 3. Chicago, Office of the Director. 80/11/18.
- 8012040343 Ack receipt of 801107 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-546/80-28 & 50-547/80-28. FIORECLI.G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/20. 2pp. 07163:221.
- --8012040347 Responds to NRC 803724 itr re violations noted in IE Insp Repts 50-546/80-28 & 50-547/80-28 Requests extension of compliance date from 801031 to 810101. SHIELDS.5 W. Public Service Co. of Indiana, Inc. 80/11/07. ip. 07163:222
- 8012240066 Forwards JE Insp Repts 50-546/80-38 & 50-547/80-38 on 801008-10, 17 & 27. No noncompliance noted. FIORELLIG. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/20. 2pp. 07324:270.
- --8012240072 IE Insp Repts 50-546/80-68 & 50-547/80-38 on 801008-10,17 & 27. No noncompliance noted Major areas inspected revised document control sys.

 HARRISCN, J. J., SCHWEIBINZ, E. R., MILLIAMS, C. C. Region 3, Chicago, Office of the Director. 80/11/17, 4pp. 07324:272.
- 8012040541 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/21.

 2pp. 07165:340.
- 8012080071 Forwards IE Info Notice 80-42, "Effect of Radaition on Hydraulic Snubber Fluid." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/24, 2pp. 07182: 228.
- B012180154 Respands to IE 8v1letin 80-22 re Automation Industries Model 200-320-008 sealed source connectors. No connectors used. Radiographers informed of attwation JERGENG, C. Cherne Contracting Corp. 80/11/24. 1p. 03791:285.
- 8012170528 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/26. 2pp. 07268:128
- 8012230296 Authorizes Cherne Contracting Corp & Commonwealth-Lord to resume alectrical & piping work on site Conditions set for resumption of const work.

 BTELLD, V. Office of Inspection & Enforcement, Office of the Director. 80/12/05. 2pp. 07318:051.
- 8012300701 Notification of 810108 meeting w/util to discuss results of insps & addl testing performed.

 MONO.H.J. Office of Inspection & Enforcement. Office of the Director. 80/12/18, 3pp. 07363:029:
- 8012310165 Notification of 810108 meeting w/util in Bethesda.MD on insp & testing re cadweld deficiencies at facilities.
 MONC.H.J. Assistant Director for Components & Structures
 Engineering. 80/12/18. 3pp. 0/369.277.

•

- S. Reportable occurrences, LERs & related correspondence
- 8012040374 Final deficiency ment repatential deficiency reported B00923 involving SECY Y-21766 stainless steel liner work. Math substitution submitted by CB & 14 AE Sargent & Lundy, found not reportable per 100FR90.55e.
 SMIELDS.S.N. Public Service Co. of Indiana. Inc. 80/11/17. 2pp. 07163-359
- 8012040400 Final deficiency rept.originally submitted 790806, re-shot of stud placed in embedment plates Commonwealth-Lord instructed not to place studs in plates 4/o prior written authorization from util.
 SHIELDS, S.W. Public Service Co. of Indiana, Inc. 80/11/25. 8pp; .07189-244
- 8012220228 Interim deficiency rept re radiographs of steam generator upper lateral support embedments not meeting density requirements, initially reported on 800717. Re-examination has been performed Results will be available by 810115. SHIELDS, S.N. Public Service Co of Indiana. Inc. 80/12/10. 1p. 07307-248
- 8012220323 Final deficiency rept re potential failure of auxiliary steel at facility, initially reported on 800813. Corrective actions: all affected pieces will be reworked per approved procedures & receipt insp program strengthened.
 8HIELDS. S.W. Public Service Co. of Indiana. Inc. 80/12/15. 2pp. 07303. 189.
- 8012220337 Interim deficiency rept re discrepancies in math test repts for weld filler math.initially reported on 800328. Investigation of addlicecords will be performed w/results provided in final rept by 810201. SHIELDS.8 W. Public Service Co. of Indiana, Inc. 80/12/15. ip. 67201-201
- DOCKET STN-50-847 MARDLE HILL NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- BO12140050 Ltr to operating plant licensees, DL applicants & CP holders. Forwards NUREG-07:37 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be not. EISERHUT, D. G. Division of Licensing. BO/10/31. 7pp.
- B012190427 Confirms 801207 meeting w/util at site to discuss NRC avaluation of regulatory performance. KCPPLER, J. O. Region 3. Chicago, Office of the Director. B0/12/02. 1p. 07286:261.
- H. General correspondence
- 8012300657 Supports operation of facility.Requests info on nuclear power plants.Congressional ltr encl. WALKER, C. K. Affiliation Unknown. B0/12/24. 2pp. 07308:001.
- O. Inspection reports, IE Bulletins & carrespondence
- 8012170498 Forwards IE info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/24.

 1p. 07268:081,
- 8012030396 Forwards IE Insp Repts 50-546/80-37 & 50-547/80-37 on 800901-30. No noncompliance noted. FIORELLI.G. Region 3. Chicago, Reactor Construction & Engineering Support Stanch. 80/10/28. 2pp. 07149:338.
- --8012030409 IE Insp Repts 50-546/80-37 & 50-547/80-37 on 800901-30. No noncompliance noted. Major areas inspected: auxiliary blóg, fuel handling blóg, storage of safety-related items & licensee program for receiving insp.

 HAPRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 80/10/27, App. 07149:340.
- 8012220169 Requests extension until 810101 re corrective action implementation date for Item of Noncompliance 80-28-01. SHIELOS.S.W Public Service Co. of Indiana, Inc. 80/11/07, ip. 07303:236.
- 8012020/43 Forwards three Performance Appraisal Branch insp repts & most avaluation tree w/user guide so that facility can compale program to program already reviewed & make appropriate adjustments. W/o anci.

 XEPPLER, J. O. Region 3. Chicago, Office of the Director. 80/11/18.4pp.

- 8012040343 Ack receipt of 801107 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-546/80-28 & 50-547/80-28 FIGRELLI, 9. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/20. 2pp. 07163.221.
- --B012040347 Responds to NRC 800924 ltr re violations noted in IE Insp Repts 50-546/80-28 % 50-547/80-28 Requests extension of compliance date from 601031 to 810101. SMELDS:S M. Public Service Co. of Indiana, Inc. 80/11/07. 1p.
- 8012240C66 Forwards IE Insp Repts 50-546/80-38 & 50-547/80-38 on 801003-10,17 & 27. No encompliance noted. FIORELLI, G. Region G. Chicago, Reactor Construction & Engineering Support Branch. 60/11/20, 2pp. 07324:270.
- --8012240072 IE Insp Repts 50-544/80-32 & 50-547/80-38 on 801008-10.17 & 27. No noncompliance noted Major areas inspected: revised document control sys HARTISON J. J. SCHKETBINZ, E. R., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 80/11/17. App. 07324:272.
- 801204054! Forwards IE Bulietin 80-24, "Prevention of Danage Due to Water Leakage Inside Containment." No written response required.

 KEPPLER.J.C. Region 3. Chicago, Office of the Director. 80/11/21.

 2pp. 07165.340.
- 601208037: Forwards IE Info Notice 80-42, "Effect of Radaition on Hydraulic Snubber Fluid." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/24. 2pp. 07182:228.
- 8012180154 Responds to 18 Sulletin 80-22 re Automation Industries Model 200-520-008 sealed source connectors. No connecters used. Radiographers informed of situation. JERGENS.C. Cherne Contracting Corp. 80/11/24. ip. 03791:285.
- 8012170528 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." Ho written response required. KEPPLER.J.G. Region 3. Chicago, Office of the Director. 80/11/26. 2pp. 07268:128.
- 8012230276 Authorizes Cherne Contracting Corp & Commonwealth-Lord to resume electrical & piping work on site. Conditions set for resumption of const work.
 STELLO.V. Office of inspection & Enforcement, Office of the Director. 80/12/05. 2pp. 07318:051.
- 8012300701 Notification of 810103 meeting w/util to discuss results of insps & additesting performed. MONG-M.J. Office of Inspection & Enforcement, Office of the Director. 80/12/18. 3pp. 07363:029.
- 8012310165 Notification of 810103 meeting w/util in Bethesda, MD on insp & testing re cadueld deficiencies at facilities.
 MGR3, H.J. Assistant Director for Congonents & Structures
 Engineering. 80/12/18. 3pp. 0/369:277.
- S. Reportable occurrences. LERs & related correspondence
- 8012040374 Final deficiency rept re potential deficiency reported 800723 involving SECY Y-21746 stainless steel liner work. Matl substitution submitted by CB & 14 AE Sargent & Lundy, found not reportable per 10CFRSO.55e. SHIELDS.8. © Public Service Co. of Indiana, inc. 80/11/19. 2pp. 07144-359
- 8012040400 Final deficiency rept, originally submitted 790806, re shot on stud placed in embedment plates. Communumealth-Lord instructed not to place studs in plates w/o prior written authorization from util.

 SMIELDS.S.W. Public Service Co. of Indiana. Inc. 80/11/25. 8pp. 07149:244.
- 8012220008 Interim deficiency rept re radiographs of steam generator upper lateral support embedments not meeting density requirements initially reported on 800717. Re-examination has been performed. Results will be available by 810115. SHIELDS.S.W. Public Service Co. of Indiana. Inc. 80/12/10. ip. 07303:249.
- 8012270323 Final deficiency rept re potential failure of auxiliary steel at facility initially reported on 800813. Corrective actions: all affected pieces will be reworked per approved procedures & receipt insp program strengthened.
 SHIELDS.S.N. Public Service Co. of Indiana. Inc. 80/12/15. 2pp. 07303: 189

- B012220337 Interim deficiency rept re discrepancies in mati test repts for weld filler math, initially reported on 800328.

 Investigation of addl, records will be performed, w/results provided in final rept by 810201.

 SHIELDS, 8 W. Public Service Co. of Indiana, Inc. 80/12/19, ip. 07301:204.
- DOCKET 50-548 FORT CALHOUN STATION, UNIT 2
- B012080507 Response in support of applicant B01114 request for withdrawal of CP application. No LWA or CP issued & no site work done. Certificate of Svc encl.
 TURK, S. E. Hearing Branch 1. B0/12/03 4pp. 03767: 266.
- 8012300390 Order dismissing ASLB hearing on application for CP upon consideration of applicant 801113 request for withdrawai of application & NRC 801209 response. LAZO.R.M. Atomic Safety and Licensing Board Panel. 80/12/22, ip. 07357: 180.
- DOCKET STM-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Encl i implementation dates will be met. EISERHUT, D. O. Division of Licensing. 80/10/31, 7pp.
- 8012220358 Ltr to all CP & UL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE. Applicable to all license applications & proposed amends, including core reloads.

 EISENHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- 8012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept, TVA-TR75-1 re const & preliminary testing, MILLS, L. M. Tennessee Valley Authority, 80/12/01. 3pp.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201.
 MILLS.L.M. Tennessee Valley Authority. 80/12/09. 1p.
- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah, Matts Bar & Beliefonte & TVA-TR75-1A. Changes supersede 801201 ltr. Changes will be included in application for OL for Hartsville, Phipps Bend & Yellou Creek plants.
 MICLS, L. M. Tannessee Valley Authority. 80/12/07. 5pp.
- G. Inspection reports, IE Builetins & correspondence
- 8012150201 Forwards IE Info Notice 80-37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/24.
- 8012170094 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31.
 19.
- 8012230030 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No uritten response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/31. 1p.
- BO(2110056 Requests assessment & corrective actions taken re-control room ceiling constructed w/apparently flammable tiles within 20 days.
 TEDESCO.R.L. Assistant Director for Licensing. BO/11/04. 3pp.
- 8012110807 Forwards IE Bulietin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Written response required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/06.
- 8012030837 Forwards is Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/07. ip.

- 8012080276 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
 O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/11/10. 1p.
- 8012040143 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 60/11/14. in.
- 8012080&01 Forwards third interim response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies." Actuators may have been used as part of valve actuators. Suppliers will be contacted. MILLS.L.M. Tennessee Valley Authority. 80/11/17, 3pp.
- B012050023 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/21. p.
- 8012060004 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24. lp.
- 8012170359 Forwards IE Info Natice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. O'REILLY, J. P. Ragion 2. Atlanta, Office of the Director. 80/11/26. 1p.
- 8012180149 Ack receipt of 801112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/80-13 & 30-554/80-13. & 8004/80-13. & 8004/80-13. Branch. J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/12/01. 1p. 03791:343.
- --8012180175 Responds to NRC 801020 itr re violations noted in IE Insp Repts 50-553/80-13 % 50-554/80-13 Corrective actions: site holding pond discharge records placed in standardized format & spill prevent control & counter measure procedure revised. MILLS,L.M. Tennessee Valley Authority. 80/11/12. 3pp. 03791:344.
- --8012180178 Forwards IE Insp Repts 50-553/80-13 & 50-554/80-13 on BOO812-15 & notice of violation. SYOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/10/20. 2pp. 03791:347.
- --8012180180 Notice of violation from insp on 800812-15.

 * Region 2. Atlanta, Office of the Director. 80/10/20. 1p.
 03791:349.
- --8012180184 IE Inso Repts 50-553/80-13 & 50-554/80-13 on 800812-15. Noncompliance noted: failure to maintain records of site holding pond discharges & failure to provide required conditions for effective control of hazardous matl. GUNNINGHAM.A.L. Region 2. Atlanta, Office of the Director. JEINKINSIO.R. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/10/20. 5pp. 03791:350.
- R. Periodic operating reports & related correspondence
- 8012230395 Forwards "Phipps Rend Nuclear Plant, Const Effects Monitoring Rept. 791019-801018," per Part III, Section I. of N2DES Permit TK0029301.
 EL-ASKRY, M. T. Tennessee Valley Authority. 80/12/17, 1p.
- --8012230360 "Phipps Bend Nuclear Plant Const Effects Monitoring Rept 791019-801018," per Part III, Section I of NPDES Permit TNC029301. CARDER, D. M., GARRISON, J. M., TOOLE, T. W. Tennessee Valley Authority. 80/12/31. 4
- 8. Reportable occurrences, LERs & related correspondence
- B012040637 Part 21 rept re reactor protection sys panel design deficiencies, initially reported on 800807. No add1 info received from OE, therefore, no further progress to rept. Final rept to be transmitted by 810213.

 MILLS, L. M. Tennessee Valley Authority. 80/11/18. 2pp. 07166:337.
- 8012040432 Second interim deficiency rept re deficient welds on weir wall liner plates originally reported on 800820, Investigation & evaluation continuing. MILLB, L. M. Tennessee Valley Authority, 80/11/24, ip. 07170:121.

- 8012040435 Forwards first interim deficiency rept me inadequate welds on embedded pipe sleeves to plates. Initial notification made on 801024. Sleeves having end plates installed before 801024 placed on hold. Util reworking accessible sleeves. MILLS.L.M. Tennessee Valley Authority 80/11/24. 3pp: 07170:118.
- 8012050369 Deficiency meptine link rod assembly in Delaval diesels.
 Dodel counterbore of link rod assembly may be too shallow.
 Transamerica Delaval described inspirethod required. Onsite
 diesels will be placed on hold pending inspired.
 MILLS.L.M. Tennessee Valley Authority. N. 80/11/26. 2pp.
- 8012050381 Third interim deficiency rept re standby gas treatment sys charchal adsorber CII nuclear submitted rept requiring review by util before final corrective actions can be prescribed. Final rept by 810302. MINUS.L.M. Tennessee Valley Authority. 80/11/26. 1p.
- 8012100478 First interim deficiency rept re defective link rad assembly in Delaval diesel generators, initially reported on 801027. Onsite diesels will be placed on hold & inspected for defect. Final deficiency rept will be provided by 801125. MILLS.L. M. Tonnessee Valley Authority. 80/11/26. 2pp.
- 8012740089 Part 21 rept re reactor protection sys fierible conduit defect causing bot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHFRIVODD. 0. G. General Electric Co. 80/12/08 3pp.
- 8012300484 Final deficiency rept re lack of steam tunnel embedment stiffner plate weld, initially reported on 800505. Caused by inadequacy of manufacturer GA program Missing weld has been added & inspected. GA program audit conducted. MILLS-L.M. Tennessee Valley Authority. 80/12/18. 3pp.
- 8012310329 Forwards final deficiency rept initially reported on 800613, re reactor pressure vessel shroud head & moisture assembly fire. Corrective actions, including cleaning procedures & liquid penetrant examinations, to be completed by 810501.

 MILLS, L. M. Tennessee Valley Authority. 80/12/19. 1p. 07361:048.
- DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, OL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests operating reactor licensee confirmation in 45 days that Enci i implementation dates will be net. EISEMMUT, D. O. Division of Licensing, 80/10/31, 7pp.
- 8012220358 Ltr to all CP & DL holders for BURS re requirement for implementation of ODYN code for licensing basis calculations performed by GE Applicable to all license applications & proposed amends, including core reloads.

 EISERWIT.D.O. Division of Licensing. 80/11/04. 4pp.
- 8012090370 Forwards planned changes to FSAR Chapter 17 & TVA rept, TVA-TR75-1 re const & preliminary testing. MILLB/L.H. Tennessee Valley Authority. 60/12/01. 3pp.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201.

 MILLS.L.M. Tennessee Valley Authority. 80/12/09. 1p.
- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah, Matts Bar & Bellefonte & TVA-TR75-1A. Changes supersede 801201 ltr.Changes will be included in application for DL for Hartsville. Phipps Bend & Yellow Creek plants.
 MILLS.L.K. Tennessee Valley Authority. 80/12/09. Spp.
- G. Inspection reports. IE Bulletins & correspondence
- 8012150201 Forwards IE Info Notice 80~37. "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2. Atlanta. Diffice of the Director. B0/10/24.
- B012170004 Forwards IE Info Notice 80-37, "Molfunction of Bolenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31,

- 8012230030 Forwards IE Circular 80-23. "Potential Defects in Beloit Bower Sys Emergency Generators." No written response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31.
- BOI2110266 Requests assessment & corrective actions taken re-control room ceiling constructed w/apparently flammable tiles within 20 days. TEDESCO.R.L. Assistant Director for Licensing. B0/11/04, 3pp.
- 8012110807 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/04,
- 8012030307 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressuritation" No written response required. O'REJLLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/07.
- 8012080276 Forwards IE. Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Eys at Davis Besse Unit 1." No response required.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/10.
- 8012040143 Forwards 1E Bulletin 80-23, "Failures of Solenoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 O'REILLY, J.P. Region 2. Atlanta, Diffice of the Director. 80/11/14.
- 80(208060) Forwards third interim response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," Actuators may have been used as part of valve actuators. Suppliers will be contacted. MILLS, L. M. Tennessee Valley Authority. 80/11/17. Spp.
- 8012050623 Forwards IE Dulletin 80-24, "Provention of Damage Duo to Water Leakage Inside Containment." No written response required. G'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/21.
- B012080604 Forwards IE Info Notice B0-42. "Effect of Radiation on Hydraulic Snobber Fluid." No written response required. D'REILLY, J.P. Region 2. Atlanta, Office of the Director. B0/11/24.
- 8012170339 Forwards IE Info Notice 80-29. Suppl 1, "Broiem Studs on Terry Turbine Steam Inlet Flange." No written response reguired. required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/11/26.
- 8012180169 Act receipt of 801112 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-553/80-13 &
- --8012180175 Responds to NRC 801020 itr re violations noted in IE lasp Repts 50-553/80-13 & 50-554/80-13 Corrective actions: site holding pend discharge records placed in standardized format & spill prevent control & counter measure procedure revised. HHLLS-L.M. Tennessee Valley Authority. B0/11/12. 3pp. 03791:344
- --8012180178 Forwards IE Insp Rapts 50-533/80-13 & 50-554/80-13 on 809812-15 & notice of violation. STOHR.J.P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/10/20. 2pp. 03791:347.
- --8012180180 Natice of violation from inep on 800812-15. * Region 2. Atlanta, Office of the Director. 80/10 03791:349. 80/10/20. 1p.
- --B0121B0184 IE Insp Repts 90-553/80-13 & 50-554/80-13 on B00812-15.

 Nuncompliance noted: failure to maintain records of site holding pend discharges & failure to provide required conditions for effective control of hazardous math.

 CUNTRINOHAN. A. Region 2. Atlanta. Office of the Director.

 JENAINS, G.R. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 80/10/20. 5pp. 03791:350.

- R. Periodic operating reports & related correspondence
- 8012230355 Forwards "Phipps Bend Nuclear Plant.Const Effects Monitoring Rept. 791019-801018," per Part III. Section I. of NPDES Permit TN0029301. EL-ASHRY, H. T. Tennessee Valley Authority. 80/12/17, ip. 07183:001.
- -8012230350 "Phipps Bend Nuclear Plant, Const Effects Monitoring Rept 791019-801018," ger Part III, Section I of NPDES Permit FKNO279301. CARDEN, D. M., GARRISON, J. M., TODLE, T. W. Tonnessee Valley Authority, 80/12/31.
- S Reportable occurrences, LERs & related correspondence
- 8012040432 Second interim deficiency rept re deficient walds on weir wall liner plates originally reported on 800820.
 Investigation & avaluation continuing.
 MILLS,L.M. Tennossee Valley Authority. 80/11/24. 1p. 07170:126.
- 8012040435 Forwards first interim deficiency rept re inadequate uslds on embedded pipe sleeves to plates. Initial notification made on 801024. Sleeves having end plates installed before 801024 placed on hold. Util reworking accessible sleeves. MILIS, L. M. Tennessee Valley Authority. 80/11/24. 3pp. 07170:118.
- 8012050369 Deficiency rept re link rod assembly in Delaval diesels.
 Dowel counterbore of link rod assembly may be too shallow.
 Transamerica Delaval described insp method required, Onsite
 diesels will be placed on hold pending insp.
 MILLS.L.M. Tennessee Valley Authority. N. 80/11/26. 2pp.
- 801205033: Third interim deficiency rept re standby gas treatment system charcoal adsorber. Cll nuclear submitted rept requiring review by util before final corrective actions can be prescribed. Final rept by 810302.

 MILLS.L.K. Tennessee Valley Authority. 80/11/26. ip.
- 8012100478 First interim deficiency rept re defective link rod assembly in Delaval diesel generators, initially reported on 801027. Chasike diasels will be placed on hold & inspected for defect. Final deficiency rept will be provided by 80112b. MILLS-1.1. M. Tennessee Valley Authority. 80/11/26. 2pp.
- B0122400B9 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERWOUD, O. O. General Electric Co. 80/12/08, 3pp.
- 8012300484 Final deficiency rept re lack of steam tunnel embedment stiffner plate weld.initially reported on 800505. Caused by inadequacy of manufacturer GA program. Missing weld has been added & inspected. GA program audit conducted. MILLS.L.M. Tennessee Vailey Authority. 80/12/18. 3pp.
- DOCKET STN-50-556 BLACK FOX STATION, UNIT 1 A. Application/construction stage documents & correspondence
- 8012270398 Ltr to all CP & OL holders for BiRs re requirement for implementation of ODYN code for licensing basis calculations performed by OE. Applicable to all license applications & proposed amends, including core reloads.

 EISEKHUT, D. O. Division of Licensing. 80/11/04. 4pp.
- G. Adjudicatory correspondence
- B012120470 Responds to B01010 ltr requesting return of Reed rept to GE, per 16CFR2.790. Based on interpretation of F0IA. Commission has denied request. Separate views of Commissioners Hendris & Ahearne encl BICKUIT, L. Office of the General Counsel. BO/11/05. 9pp. 07230: 315.
- H. General correspondence
- 8012040296 Forwards info in response to 801029 ltr requesting licensing categories & info re floating nuclear plants. PURPLE.R.A. Division of Licensing. 80/11/17. 4pp.
- --B012040298 Requests info re facilities w/active CPs pending, license definitions & requirements for floating nuclear plants.

 DREY, L.A. Affiliation Unknown. 80/10/29. ip.

- 0. Inspection reports: IE Bulletins & correspondence
- 8012180035 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No written response required. O'REILLY, J. P. Region 2- Atlanta, Office of the Director. 80/10/30. to.
- S. Reportable occurrences. LERs & related correspondence
- 8012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modules are mounted. SHERNOOD. G. G. General Electric Co. 80/12/08 3pp.
- DOCKET BIN-50-557 BLACK FOX STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- 8012220358 Ltr to all CP & OL holders for BWRs re requirement for implementation of ODYN code for licensing basis calculations performed by GE.Applicable to all license applications & proposed amends, including core reloads. EISENHUT, D. G. Division of Licensing. 80/11/04. 4pp.
- H. General correspondence
- 8012040256 Forwards info in response to 801029 ltr requesting licensing categories & info re floating nuclear plants. PURPLE.R. A. Division of Licensing. 80/11/17. 4pp.
- --8012040298 Requests info re facilities w/active CPs pending,license definitions & requirements for floating nuclear plants.

 DREY, L. A. Affiliation Unknown. 89/10/29, 1p.
- S. Reportable occurrences. LERs & related correspondence
- B012240089 Part 21 rept re reactor protection sys flexible conduit defect causing hot shorts if improperly grounded. Caused by paint on panel surfaces or high resistance connection to panel surfaces where termination modulos are mounted. SHEKKOOD. 0. 0. General Electric Co. 80/12/08. 3pp.
- DOCKET SIN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

 A. Application/construction stage documents & correspondence
- 8012160050 Ltr to operating plant licensees, QL applicants & CP holders. Forwards NUREO-0737 re TMI action plan requirements. Requests aperating reactor licensee confirmation in 45 days that Encl I implementation dates will be net. EIGENHUT, D. O. Division of Licensing. 80/10/31. 7pp.
- 8012090370 Forwards planned changes to FSAR Chapter 17 & YVA rept. TVA-TR75-1 re const & preliminary testing. MILLS.L.H. Tennessee Valley Authority. 80/12/01. 3pp.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment. Info will be available by 810201.

 MILLS.L.M. Tannessee Valley Authority. 80/12/09. 1p.
- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah, Watts Bar & Bellefonte & TVA-TR75-1A. Changes supersede BO1201 ltr. Changes will be included in application for OL for Hartsville-Phipps Bend & Yellou Creet plants. MILLS.L.M. Tennessee Valley Authority. 80/12/09. 5pp.
- F. Security, medical, emergency & fire protection plans
- 8012080835 Notification of 801121 meeting w/util in Bethesda.KD to discuss util position on central emergency response ctr & plans for emergency mgt. STAHLE.C. Licensing Branch 2 80/11/19, App.
- Q. Inspection reports, IE Bulletins & correspondence
- 8012150201 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24.

- 8012170:004 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required U'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/31, 1p.
- 8012230030 Forwards IE Circular 80-23. "Potential Defects in Beloit Pauer Sys Emergency Congrators." No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 80/10/31. is.
- 8012110056 Requests assessment & corrective actions taken re-control room celling constructed w/apparently flammable tiles within 20 days. TEDESCO.R.L. Assistant Director for Licensing, 80/11/04. 3pp.
- 8012110807 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Halcolm Foundry Co.Inc." Written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/06.
- 80:2730837 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurfization." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/11/07. In.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Basse Unit 1." No response required.

 O'REILLY, J.F. Region 2. Atlanta. Office of the Director. 80/11/10.
- 8012040143 Forwards IE Bulletin 80-23, "Failures of Solemoid Valves Mig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.

 D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/14, 10
- 8012120354 Act receipt of 801021 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/80-14 & 50-567/80-14. MURPHY-C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/14. ip. 07236:305.
- . --8012120345 Forwards 1E Insp Repts 50-966/80-14 & 50-567/80-14, on 800902-05 & notice of violation. WURPHY, C. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/09/26 2pp. 07236:308.
 - --8012120369 Notice of violation from insp on 800702-05.

 4 Region 2, Atlanta, Office of the Director. 80/09/26. 1p.
 07236:310.
 - ~~8012120377 IE Insp Rept 50-556/50-14 % 50-567/80-14 on 800902-05.
 Noncompliance noted evaluation not made of concrete test
 cylinders that break below specified requirements.
 IMARIS.J.R. Region 2. Atlanta, Office of the Director.
 CDNLONLTE Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch. 80/09/26 App. 07236:311.
 - 8012080616 Forwards updated response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," Util will contact major valve suppliers to determine if add1 deficient actuators were supplied.
 MILLS, L. M. Tannessee Valley Authority. 80/11/17. 3pp.
 - 8012310050 Forwards LE lnsp Repts 50-556/80-16 & 50-567/80-16 on 801020-21. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/20. 2pp. 0/369.067.
 - --8012310053 IE Insp Repts 50-566/60-16 \$ 50-567/80-16 on 801020-21. No noncompliance noted Major areas inspected previous insp findings, licensee identified items & const status.

 BLAKF, J. J. Region 2. Atlanta. Office of the Director. HERDT, A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/19. 3pp. 07367:069.
 - 8012050023 Forwards 1E Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment," No written response required.

 D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/21.
 - BO12080004 Forwards IE Info Hobice BO-42, "Effect of Radiation on Mydraulic Snubber Fluid" No written response required. O'RELLLY, J.P. Region 2. Acianta, Office of the Director. BO/11/24.

- 8012170359 Forwards IE Info Notice 80-29. Suppl 1, "Broken Studs on Terry Purbine Steam Inlet Flange" No written response required. O'RENLLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/26. 1p.
- R. Periodic operating reports δ_{i} related correspondence
- 8012160149 Forwards "Socioeconomic Monitoring & Mitigation Rept." sectantival rept for Jul-Dac Rept prepared for FES.
 MILLS.L.M. Tennessee Valley Authority. 80/12/05. 1p. 07255:001.
- --B012169152 "Socioeconomic Monitoring & Mitigation Rept," semiannual rept for Jul-Dec 1979.

 → Tennessee Valley Authority, 85/10/31, 35pp. 07299:002.
- S. Reportable occurrences, LERs δ_{i} related correspondence
- 8012040357 Second interim deficiency rept re QA Audit M80-7 Deficiencies 2.3.5 & 14 initially reported on 800923. Some conditions adverse to quality are being reported on procedure revision request forms. MILLS.L.K. Tennessee Valley Authority. 80/11/25. 1p. 07170:152.
- 8012090369 Final significant deficiency rapt initially reported on 809421 re const QA audit.QC employees have been instructed to obtain math correctly.CCI C-204 revised & retest required.QC reminded of new requirements.

 MINLS.L.M. Tennassee Valley Authority. 80/12/01. 3pp. 07207:143.
- 8012170466 Final deficiency mept originally reported 801113 me nonconservative application for TPIPE computer program. Piping analyses to be submitted for re-analysis w/factors to be inserted to ensure conservative output.

 MILLS.L.M. Tennessee Valley Authority. 80/12/11. 2pp. 07269:234.
- 8012310374 Deficiency Repts 50-556/80-17-01 & 50-567/80-17-05, Div of Pauer Production operational OA manual found not clearly applicable for preservice insp in vendor shops. Manual rewritten by util Changes to be incorporated by 810228. MILLS.L.M. Tennessee Valley Authority. 80/12/23. 2pp. 07369:082.
- 8012310322 Revised final deficiency rept.initially reported 801113, re nonconservative application of TPIPE computer program. Piping analyses affected by incapability to meet design criteria to be resubmitted for reanalysis. MILUS, L.B. Teanessee Valley Authority. 80/12/24, 2pp. 07361:052.
- DOCKET STN-50-567 YELLON GREEK NUCLEAR PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- B012160050 Ltr to operating plant licensees.OL applicants & CP holders. Forwards NUREG-0737 re TMI action plan requirements.Requests operating reactor licensee confirmation in 45 days that Encl 1 implementation dates will be net. EISEKHUT.D.G. Division of Licensing. 80/19/31. 7pp.
- 8012090370 Forwards planned changes to FEAR Chapter 17 & TVA rept. TVA-TR75-1 re const & preliminary testing. MILLS.C.M. Tennessee Valley Authority. 80/12/01. 3pp.
- 8012160327 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment.Info will be available by 810201 MILLS.L.M. Teamesses Valley Authority. 80/12/09, ip.
- 8012170316 Forwards planned changes to Chapter 17 of FSAR for Sequoyah. Matts Bar & Bellefonte & TVA-TR75-1A Changes supersede 801201 ltr.Changes will be included in application for OL for Hartsville-Phipps Bend & Yellow Creek plants.
 MILLS.L.K. Tennessee Valley Authority. 80/12/09. 5pp.
- F. Sacurity, medical, emergency & fire protection plans
- 8012080335 Notification of 801121 meeting w/util in Bethesda.MD to discuss util position on central emergency response ctr & plans for emergency mgt STAHLE.C. Licensing Branch 2. 60/11/19. 6pp.
- O Inspection reports. IE Bulletins & correspondence

411 - -

BO12150201 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.

D'REILLY, J. P. Region 2, Atlanta, Office of the Director. BO/10/24.

1p.

- 8012180335 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/30. ip.
- 8012170004 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No specific action or response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31, ip.
- 8012230030 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No written response required. B'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/31.
- BO12110066 Requests assessment & corrective actions taken re-control room celling constructed w/apparently flammable tiles within 20 days. TEDESCO.R.L. Assistant Director for Licensing. BO/11/04, 3pp.
- 8012113307 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcola Foundry Co. Inc." Written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 80/11/06.
- 8012030837 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/07. lo.
- 8012080276 Forwards IE Info Notice 80-41, "Failure of Swing Check Valva in Decay Heat Removal Cys at Davis Besse Unit i." No response required.

 0'REIU Y. J. P. Region 2, Atlanta, Office of the Director. 80/11/10.
- 8012040143 Forwards IE Bulletin 80-23, "Failures of Splenoid Valves Hig by Valcor Engineering Corp." Requires estimate of manpower associated w/corrective actions.
 O'REILLY, J. P. Region 2: Atlanta, Office of the Director, H0/11/14.
 Ip.
- 8012120354 Ack receipt of 801021 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/B0-14 & 50-567/80-14. MORPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/14. 1p. 07236:305.
- --8012123356 Forwards IE Insp Repts 50-566/80-14 & 50-567/80-14, on 800702-05 & notice of violation (NURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/26, 2pp. 07236:308.
- --8012120377 IE insp Rept 90-566/80-14 & 50-567/80-14, on 800902-05.

 Noncompliance noted:evaluation not made of concrete test
 cylinders that break below specified requirements.

 HARRIS.J.R. Region 2. Atlanta. Office of the Director.
 COM.DN.T.E. Region 2. Atlanta. Reactor Construction & Engineering
 Support Branch. 80/09/26. 6pp. 07236:311.
- 8012080616 Forwards updated response to IE Bulletin 80-07, "Hydramotor Actuator Deficiencies." Util will contact major valve suppliers to determine if addl deficient actuators were supplied.

 MIUS.L.M. Tennessee Valley Authority. 80/11/17. 3pp.
- 8012310050 Forwards IE Insp Repts 50-556/80-16 & 50-567/80-16 on 801020-21. No noncompliance noted. HURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/11/20. 2pp. 07369:067.
- ---BD12310053 IE imsp Repts 50-566/80-16 to 50-567/80-16 on B01020-21.No noncompliance moted Major areas inspected previous inspefindings. Jicensee identified items & const status, BLAKE, J. J. Region 2, Atlanta, Office of the Director. HERDY, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. B0/11/19. 3pp. 07369:069.
- 8012050023 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment." No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/11/21.
- 8012080004 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No written response required, D'REINIY, J. P. Region 2, Atlanta, Office of the Director. 80/11/24, io.

- 8012170359 Forwards IE Info Notice 80-29, Suppl 1, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. U'REILLY, J.P. Ragion 2, Atlanta, Office of the Director, 80/11/26.
- R. Periodic operating reports & related correspondence
- 8012160149 Forwards "Socioeconomic Menitoring & Mitigation Rept." seniannual rept for Jul-Dec Rept prepared for FES. MILLS.L.M. Tennessee Valley Authority. 80/12/05. 1p. 07255:001.
- --8012160152 "Sociaeconomic Monitoring & Mitigation Repti" semiannual rapt for Jul-Dec 1979.

 * Tennessee Valley Authority. 80/10/31. 35pp. 07255:002.
- 5. Reportable occurrences. LERs & related correspondence
- 8012040337 Second interim deficiency rept re QA Audit M80-7 Deficiencies 2,3,5 %,14 initially reported on 800923. Same conditions adverse to quality are being reported on procedure revision request forms. MILLS, L. N. Tennessee Valley Authority. 80/11/25, 1p. 07170: 152.
- B012090349 Final significant deficiency rept initially reported on B00421 re const QA audit.QC employees have been instructed to obtain math correctly.QCL C-204 revised & retest required.QC reminded of new requirements.

 MILLS.L.M. Tennessee Valley Authority. B0/12/01. 3pp. 07207:145.
- 8012310374 Deficiency Repts 50-566/80-17-01 & 50-567/80-17-05 Div of Power Production operational OA manual found not clearly applicable for preservice insp in vendor shops Manual rewritten by util Changes to be incorporated by 810228.

 MILLS, L. M. Tennessee Valley Authority. 60/12/23. 2pp. 07369:082.
- DOCKET 81N-50-574 BAGNAC NUCLEAR POWER PROJECT
- A. Application/construction stage documents & correspondence
- 8012040162 Forwards staff requirements memos for closed Commission meetings. Transcripts for all meetings have been released in entirety to PDR. BROWN.J. Office of the Secretary of the Commission. 80/11/06. 1p. 07170: 035.
- --8012040173 Staff requirements memo from 800421 closed mouting re SECY-80-191 re proposed amend to US-Canada agreement for cooperation.ttr to President Carter signed on 800421. CHILK.S.J. Office of the Secretary of the Commission. 80/04/25. 1p. 07170:037.
- --8012040191 Staff requirements memo from 800505 closed meeting retwestimony to be given during wk of 800507. Requests draft statement be revised to reflect V Gilinsky comments & NRC & US responsibilities clarified.
 CHILK.S. J. Office of the Secretary of the Commission. 80/05/07.
- DOCKET 50-579 TRIGA MARK II POOL-TYPE REACTOR
- A. Application/construction stage documents & correspondence
- 8012080/36 Forwards Executive Branch position on pending license application from GA Co to export one TRIGA MARK 2 research reactor to Malaysia.License application encl. Executive Branch comments will be placed in LPDR SHEA.J.R. Office of International Programs, Director. SECY-80-495, 80/11/05. 1p. 07196:171.
- --B011250704 Application by GA Co to export TRIGA Mark II research reactor to Malaysia. Description encl MORRY.N.R. General Atomic Co. (subs. of Gulf Oil Co.). 77/01/19. 4pp. 03746:259.
- DOCKET 50-582 SUNDESERT, UNIT 1 G. Adjudicatory correspondence
- 8012300380 Order dismissing ASLB hearing on application for CPs upon consideration of applicant 800711 motion for termination of proceeding & NRC 801015 response.

 LATOR. M. Atomic Safety and Licensing Board Panel. 80/12/22. 1p. 07357:179.

- DOCKET SO-583 BUNDESERY, UNIT 2 G. Adjudicatory correspondence
- 8012300030 Order dismissing ASLB hearing on application for CPs upon consideration of applicant 800711 nation for termination of proceeding & MRC 801015 response.

 LAZO.R.M. Abomic Safety and Licensing Board Panel. 80/12/22. ip. 07337:179.
- DOCKET STN-50-596 NEW MAYON, UNIT 1
- A. Application/construction stage documents & correspondence
- BD12110376 Forwards FR notice re withdrawal of CP application. YOUNGSLOUD.B.J. Licensing Branch t. 60/11/26. 2pp. 07224:150.
- --8012110381 Notice of withdrawal of CP application. YOURG8LOOD, B. J. Licensing Branch 1 89/11/26. 1p. 07224:192.
- DUCKET STN-50-597 NEW HAVER, UNIT 2
- A. Application/construction stage documents & correspondence
- 8012110376 Forwards FR natice me withdrawal of CP application. YOUNGSLOOD, B. J. Licensing Branch 1. 80/11/26. 2pp. 07224:150.
- --8012110381 Notice of withdrawal of CP application. YOUNGBLOOD, B. J. Licensing Branch 1 80/11/26. 1p. 07224:152.
- DOCKET 90-599 CARROLL FACILITY 1
- M. Antitrust correspondence
- 8012090184 Responds to NRC 790402 & 801009 requests for info re-project status & plans for updating antitrust info.Units scheduled for svc in 1993 & 1994 Antitrust info will be updated at least 9 months prior to PSAR or environ rept filing.
 TRAMM.T.R. Commonwealth Edison Co. 80/12/01 1p. 07200:146.
- DOCKET 50-600 CARROLL FACILITY II

 M. Aptitrust correspondence
- 8012090184 Responds to NRC 290402 & 801009 requests for info re-projec status & plans for updating antitrust info.Units scheduled for svc in 1993 & 1994. Antitrust info will be updated at least 9 months prior to PSAR or environ rept filing. TRAMM.T.R. Commonwealth Edison Io. 80718701. 1p. 07200:146.

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

- DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES
- 8012030834 Discusses commitment to provide armed escort for shipment o radioactive spent fuel through Charleston, NV, Huntington, NV & Ashland, NY, Details of responsibilities encl. EMSNELER, T. R. Battelle Memorial Institute. Columbus Laboratories, 80/09/10. 3pp. 07149, 259
- 8012020715 Informs of specific terms & conditions for implementation of financial plan for eventual decommissioning for unrestricted use of facility in response to NRC 790629 ltr request Forwards draft trust agreement.

 TOY.H.L. Battelle Memorial Institute. Columbus Laboratories.
 80/10/01. Spp. 07147 356
- DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP.
- B012020399 Forwards application for anend to License SNM-21, in form of revised fixed site safoguards plan to provide protection against radiological sabutage, theft or diversion of SNM-Plan withheld (ref 10CFR2 790) Fee encl.

 REMIEY, M.E. Rockwell International Corp., Energy Systems Div. 80/09/19. 3pp. 07142.083

- DOCKET 70-0027 BATCOCK & WILCOX CO
- 8012040539 Provides info in response to N Ketilach 800Bl1 1tr to RA Cordani re results of enhaust monitoring of laundry beginning in Aug 1978. Discusses how info was obtained. Info shows no large fluctuations from will to will. GGRDANI.R.A. Babcock & Wilcox Co., Raval Nuclear Fuel Div. 80/09/19. 4pp 07170.108.
- 8012020297 Advises that revised physical security plan will be a forwarded by 801031 in response to HSC comments at 801002-03 meeting in Silver Spring, MD. CORDANIAR. A. Bebook & Milcor Co., Naval Nuclear Fuel Div. 80/10/15. ip. 07141: 359.
- 8012020480 Informs that 900924 itr is withheld (ref 10CFR2, 790).

 * Public Document Branch 80/10/15, 1p. 06916:001.
- B012120344 Forwards IE Insp Rept 70-0327/80-15 on 800923-24.No noncompliance noted.

 STCHR, J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/10/21. 1p. 07236:301
- --8012120349 IE Insp Pept 70-0027/80-15 on 800923-24. No noncompliance noted. Major areas inspected: employee training, groundwater sampling b site familianization toop. URAY, J.R., 01850N.A.F. Ragion 2, Atlanta, Office of the Director, 80/10/21. 3pp. 07236-302
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC.
- 8012110163 Forwards 1E Insp Rept 70-0033/B0-09 on 800908-12.No noncompliance noted Cover sheet only encl (ref 100FR2.790). MARTIN.N G. Region 1. Philadelphia. Safeguards Branch. 80/10/07. 2pp. 07224-057.
- --B012110171 IZ Insp Rept 70-0033/80-07 on B00708-12. No noncompliance noted. Kajor areas impeched measurements & statistical controls, shipping & neceiving, records & repts & storage. Betails withheld (ref 100FRZ, 790).
 ZIBULSKY, H., RATTA, A.D., Region 1, Philadelphia, Office of the Director. JOYNER, J. H., Region 1, Philadelphia, Safeguards Branch, 80/10/03 1p 07224:059
- 8012020259 Forwards purchase order providing submission fee for revised site safeguards physical protection plan.
 ELTIS.M. Teras Instruments. Inc. 89/10/03. 3pp. 07134:210.
- 8012080771 Forwards upposited Sections 10.5 10 1.1-1 & 10.5 10.1.1-2 of emergency plan. SCHWEMSFEIR.R Tewas Instruments. Inc. 80/10/15. 1p. 07188:043.
- --8012080793 Updated Sections 10 5.10, 1.1-1 & 10.5, 10.1, 1-2 of emergency plan.
 d Toras Instruments, Inc. 80/10/03. 2pp. 07188:044.
- 8012190043 Forwards updated acctions for HFIR project emergency plan. Changes do not decrease plan effectiveness & are submitted for info purposes only W/o encl SCHWERSFEIR.R. Toxas instruments, Inc. 80/11/24. Spp. 07278:229.
- DOCKET 70-9036 COMBUSTION ENGINEERING, INC.
- 8012180229 Forwards IE Insp Repts 70-0036/80-02.70-0036/80-03 & 70-0036/80-04 per 801114 telcon No noncompliance noted. KEPPLER, J. G. Region S. Chicago, Office of the Director. 80/12/08. 1p. 03792:028.
- --B012180234 [Ellisp Repts T0-0736/80-02,70-0036/80-03 & 70-0036/80-04 per 801114 beloom No mincompliance noted Major areas discussed systematic assessment of licensee performance program & results of facility appraisal. FISHER.U.L. DAVIS.A B., FECH.C.C. Region 3, Chicago, Fuel Facility & Materials Dafety & Manch. 80/11/28. Spp. 03792:029.
- DOCKET 70-0982 NUCLEAR METALS, INC.
- 8012100188 PNO-V-80-78: on 801120, shipment of low level radwaste neceived at Pichland, WA. burial site by Nuclear Engineering Co from Woclear Metals. Inc. determined to have one leaking drum. State of WA has cancelled licensee burial permit. THOMAG.R. B. Region 9. San Francisco, Office of the Director. 80/11/21. 1p. 07218: 279.

- DOCKET 70-0135 BABCOCK & WILCOX CO.
- 8012030789 Forwards revision to License SNM-145 fundamental nuclear control plan for organizational measurement sys stds & plant layout nods. Enci withheld (ref 100FR2, 790).
 AUSTIN.M.A. Babcock & Milcol Co. B0/09/12. 2pp. 07:90:145.
- 8012040549 Requests that License Conditions 9.1. B & 9.1. C of MPP-1 to SIM-145 be withdrawn. Request consistent w/safeguards release granted in 800921 ltr. AUSTIN.M.A. Babcock & Wilcox Co., Muclear Material Div. 80/09/12. lp. 07t70:106.
- 8012230054 Forwards IE Insp Rept 70-0135/80-28 on 800723-25. No noncompliance noted. MARTIN, M.O. Region 1. Philadelphia, Safeguards Branch. 80/10/14. 2pp. 0/311:253.
- --8012230061 IE Insp Rept 70-0135/80-28 on 800923-25. No noncompliance noted Major areas inspected residual U holdup in high anriched U facility. Datails withheld (ref 10CFR2.790). COHEN, 1., B158EIT, P. Region 1. Philadelphia. Office of the Director. JUYNER, J. H. Region 1. Philadelphia. Safeguards Branch. 80/10/10. ip. 07311:255
- B0122P0722 Forwards IE Insp Repts 70-0135/80-25 & 70-0364/80-22 on 803F02-30. No noncompliance noted. MARTIN.N.O. Region 1. Philadelphia, Safeguards Branch. 80/10/24. 2pp. 07306:305.
- --8012220025 IE lnsp Repts 70-0135/80-25 & 70-0344/80-22 on 800902-30. No concomptiance noted Major areas inspected matl control & accounting, physical security, health & safety. Portions withheld (ref 100FR2, 790). MUSINERIW.L. Region i. Philadelphia, Fuel Facility & Materials Safety Branch. JOYNER, J.H. Region i. Philadelphia, Safeguards Branch. B0/10/22. Spp. 07304:307.
- B012090047 Ack receipt of 801003 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/80-22 & 70-0364/80-18.
 MARTIN.N.O. Region 1, Philadelphia, Safeguards Branch. B0/10/29. ip. 07198:082.
- --8012093077 Responds to MRC 800712 ltr re violations noted in IE Insp.
 Rapts 70-0135/80-22 & 70-0364/80-18. Corrective actions:
 equipment snear survey log reviewed by health & safety
 supervision. Portions withheld (ref 100FR2.770).
 AUSTIN:K. A. Babcock & Wilcox Co. 80/10/03. 4pp. 07198:083.
- --8012090053 Forwards IE insp Repts 70--0135/80-22 & 70--0364/80-18 & on 800707-0801 & notice of violation. Notice of violation withheld (ref 100FR2 790).
 MARTIN.H.G. Region 1, Philadelphia, Safeguards Branch. 80/09/12.
 2pp. 07198:087.
- --8012090093 IE insp Repts 70-0135/80-22 & 70-0364/80-18 on 800707-0801. Noncompliance noted: access not controlled to power & dry scrap storage areas. Procedures not followed for equipment contamination surveys. Portions withheld (ref 10CFR2, 790). KUS::NER. W. L. Region 1, Philadelphia, Office of the Director. JUYISER. J. H. Region 1, Philadelphia, Bafeguards Branch. 80/09/12. 11pp. 07198:089.
- 8012120402 Ack receipt of 801104 application to amend License BVM-145 & fee payment. Request classified as minor Category 18 amend, requiring addl fee payment.
 WEISS, D. License Fee Itanagement Branch. 80/11/20. 1p. 07236:289.
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC.
- SOI2:80:339 Appeals denial of FOIA request for documents re NRC consideration of licensing facility & transcripts of two Commission meetings.

 COCHRAN, F. B. Natural Resources Defense Council. 80/07/10. ip.
- 8012010567 Forwards process monitoring charts in response to NRC 800626 ltr.Charts withheld (ref 100FR2.790). MANSER.U.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 80/99/10. 2pp. 07098:104.
- 8012310616 Forwards IE Insp Rept 70-0143/80-27 on 800819-21. No noncompliance noted. Corrective actions on previously identified item of noncompliance was determined to be unsatisfactory. Insp rept dotails withheld (ref 10CFR2, 790). O'REILLY, J. P. Region 2. Atlanta, Defice of the Director. 80/09/16. 2pp. 07370:010.

- --8012310619 IE Insp Rept 70-0143/80-27 on 80019-21. No noncompliance noted Hajor areas inspected; storage & internal facility organizantion. Details withheld (ref 100FR2.790). TODD: 0. A. / KAHLE: J. B. Region 2, Atlanta, Safeguards Branch. SMITH: C. N. Office of Nuclear Katerial Safety & Bafeguards. 80/09/14. 1p. 07370:012
- 8012040513 Forwards Revision P to 800730 physical protection plan, Revision 18. Drawing RMG-470D. Revision N. Plan withheld (ref 100FR2 770). MICHELR. J. Nuclear Fuel Services, Inc. (subs. of Oetty Dil Co.). 80/10/14. 2pp. 07170:112.
- 8012240130 FOIA request for all correspondence between NRC & licensee from June-Sept 1930 re incidents, violations &/or insps. 8ANDERS, L. A. Johnson City Press-Chronicle Johnson City, TN. 80/11/20. 1p. 07324:336.
- 80120907/2 Grants request for 10-day delay for completing requirements of 10CFR70,53(b)(1) & License Condition 5.6 of Amend MPP-1 in response to 801114 ltr. Encl to 801114 ltr withheld (ref 10CFR2.790). PARTLOW.J.O. Material Control Licensing Branch. 80/11/21. 1p. 07196:286.
- 8012040367 Registers strong opposition to NRC movement to transfer NFS from Erwin, TN. Strosses plant safety & positive economic impact on community.

 BANNER, J. E. Affiliation Unknown. 80/11/24. ip. 06915:001.
- 8012220175 FOIA request for documents re Pu or other radioactive substances unaccounted for at facility. VAIL.J. Legal Bervice of Upper East Tennesses. 80/11/25. Ip. 07303-240
- B012100670 Ack receipt of B01107 ltr informing NRC of steps taken to correct violations noted in IE Mgt Meeting Rept 70-0143/80-30.
 O'REILLY, J.P. Region 2. Atlanta. Difice of the Director. B0/11/28.
 1p. 07187:001.
- --8012100676 Responds to NRC 801009 ltr re violations noted in IE Mgt Hesting Rept 70-0143/80-30. Evaluation of stack sampling sys enci.

 MANSER. N. C. Nuclear Fuel Services, Inc. (subs. of Oetty Dil Co.). 80/10/31, ~9pp. 07187:001.
- --8012100690 Forwards IE Mgt Meeting Rept 70-0143/80-30 on 800918. Response requested re identified concerns within 20 days. D'REILLY,J.P. Region 2. Atlanta, Office of the Director. 80/10/09. 1p.
- --B012100685 IE Myt Meeting Rept 70-0143/80-30 on 800918. Major areas discussed: ID exceeding LEID, stack sampling, stack discharge concentrations, environ sampling, contamination control & emergency plans.
 KEN-VA: N. B. . STONR. J. P. Region 2, Atlanta, Safeguards Branch.
 80/10/07. 4pp.
- 8012150018 Confirms 801121 telcon re actions taken to correct violations noted in IE lnsp Rept 70 0143/80-36 on 801103-04. Stack sampling program deficiencies will be resolved to comply w/License Condition 26 0'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/11/28, ip. 07241:054.
- B012110524 Add1 response to FOIA request for decuments re NRC consideration of licensing facility & transcripts of closed Commission meetings.Forwards CN Smith 790927 memo, Info partially withheld (ref FOIA Exemption 3), FELTON, J.II Division of Rules and Records. B0/12/04, 2pp. 07227:146.
- --8012110528 Trip rept of 790918-21 visit to facility to investigate excessive inventory difference for June-Aug 1979, Provides chronology of events, Info partially withheld (ref FOIA Exemption 3).

 SMITH.C.N. Material Control Licensing Branch. 79/09/27. 4pp.
- 8012160216 Forwards 1E Insp Rept 70-0143/80-37 on 801107, No noncompliance noted. KENNA, H.B. Region 2, Atlanta, Safeguards Branch. 80/12/04, 1p. 07262:010.
- --8012160221 IE Insp Rept 70-0143/80-37 on 801107.No noncompliance noted. Major areas inspected; physical protection program. Details withheld (ref 100FR2, 790). HOUSELL.J.C., TILLMAN.A., MIGUIRE, D.R. Region 2, Atlanta, Office of the Director. 80/12/02. ip. 07262:011.

- 80(2270653 Transcript of 801204 public meeting in Erwin, TN re gaseous releases from NFS in Erwin, TN Pp 1-105. * Commissioners. 80/12/04. 107pp. 07274:116
- 8012160269 Forwards updated repts re Bidgs 233 & 302/303 daily monitoring results Data indicates corrective actions taken to lower concentrations released. NANSER, U. C. Nuclear Fuel Services, Inc. (subs. of Getty Dil 80/12/09. 4pp. 07253: GO3.
- B012180335 Responds to appeal of denial of F014 request for de re NRC consideration of licensing facility & transcripts of two Commission meetings Access to classified matls granted due to security clearance & participation in proceedings. FELTON, J. M. Division of Rules and Records. 80/12/11, 1p.
- 8012240126 Partial response to FOIA request for all correspond between MRC & licensee from June-Sept 1980 re incidents, violations &/or insps. Forwards documents listed in App A. FELTON.J.N. Division of Rules and Records. 80/12/15. 2pp. 07324: 334.
- --8012240133 Forwards IE Insp Rept 70-0143/80-24 on 800918-22, violation & notice of deviation. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/09/22. 2pp.
- --8012240135 Notice of violation from insp on 800818-22.

 * Ragion 2, Atlanta, Office of the Director. 80/07/12.
- --8012240139 Natice of deviation from insp on 800818-22.

 Region 2. Atlanta, Office of the Director. 80/07/12.
- --8012240141 IE Insp Rept 70-0143/80-24 on 800818-22. Noncomplifing hydrants were not located within 250 ft of Marchouse 310 & equipment in fire hydrant hose houses does not meet NPPA criteria.

 MILLER.W. H. Region 2. Atlanta. Office of the Director. CONLOPIST. E. Region 2. Atlanta. Reactor Construction & Eng Support Branch. 80/09/12 9pp.
- 8012220169 Partial response to FOIA request for documents re Pother radioactive substances unaccounted for at facility. SECY-80-519 is available in PDR. FELTON.J.M. Division of Rules and Records. 80/12/16. lp. 07303: 237.
- 8012230432 Forwards application for amend to License SNM-124.F Application withheld (ref 100FR2 790). HENBLEVY.N.D. Nuclear Fuel Services, Inc. (subs. of Getty Of 80/12/16 1p. 07312:264.
- 8012110467 Transcript of 811201 public meeting in Washington, Denviron releases at NFS-Erwin 3 other fuel cycle plants. Pp 1-45.

 # Commissioners. 80/12/01 45pp. 97227:039.
- --8012110478 Forwards correction notice to SECY 80-519 revisin & 8. • Office of the Secretary of the Commission. 80/11/28. 07227:105.
- --80171104Bl Forwards three replacement pages to SECY 80-519 r releases at NFS-Erwin Corrections recessary due to computational error. DIRCKS.N.J. Office of the Executive Director for Operatio 80/11/26. 1p. 07227:106.
- --B012110494 Revised Pages 1:7 & 8 to BECY-80-519 re environ r RFS-Erwin. DIRCKB-R.J. Office of the Executive Director for Operatio SECY-80-519 RI. G0/11/24. Gpp. 07227:107.
- ---8012110488 Discusses dose culculations re accidental release Provides info about emission control at NFS-Erwin & autlinisues re emission control at other fuel cycle & matl plants.

 DIRCKG.I.J. Office of the Executive Director for Operation SECY-80-519. BO/11/24. 24pp. 07227:110.
- DOCKET 70-0157 TEXAS, UNIV. OF
- B012020700 Provides info in response to questions re renewal o License SNM-180 Rediation safety officer is univ staff position supervised by safety engineer & responsible to univ radiation safety committee. BAUCR.T.L Texas, Univ of. B0/10/10, 3pp. 07148:001.

- 8012240097 Trip rept of 601203 visit to Univ of TX.Austin.TX resubcribital assembly & associated equipment & questions on application for reneval of License SIXF-180.
 KDSLA.B., STEVENSON.R.L. Uranium Fuel Licensing Branch. 80/12/08.
 200. 07325:129.
- DOCKET 70-0258 ILLINOIS URIV. OF URBANA-CHAMPAIGN
- 8012040198 Forwards physical security plan.Plan withheld (ref 190FRZ 790).

 BECK, O.P. Illinois, Univ. of, Urbana-Champaign. BO/11/26. 1p. 07170:064.
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BARCOCK & WILCOX CO.
- 8012080374 Forwards cross-ref index of License SNM-414 fundamental nuclear mat) control plan. Index withheld (ref 100FR2, 790).
 AUSTIN N.A. Batcock & Hilcor Co., Nuclear Material Div. 80/09/16.
 1p. 07196: 197.
- 8012270022 Forwards I£ Insp Repts 70-0135/80-25 & 70-0364/80-22 on 800902-30. No noncompliance noted. MARTIN.W.O. Region I. Philadelphia, Safeguards Branch. 80/10/24. 2pp. 07396: 305.
- --8012220025 IE Insp Repts 70-0135/80-25 & 70-0364/80-22 on 800902-30. No noncompliance moted Major areas inspected matl control & accounting physical accuratty, health & safety Portions withheld (ref 10CFR2 779).

 KUSHNER.N. L. Ragion i, Philadelphia, Fuel Facility & Materials Safety Branch. JOYNER.J. H. Region i, Philadelphia, Safeguards Branch. 80/10/22. Spp. 07306:307.
- 8012090067 Ack receipt of 801003 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 70-0135/80-22 & 70-0364/80-18. KARTIN, U.G. Region 1, Philadelphia, Safeguards Branch. 80/10/29. ip. 0/198:082.
- --8012090077 Responds to PRC 800912 ltr re violations noted in IE Insp Repts 70-0135/80-22 % 70-0354/80-18. Corrective actions: equipment smear survey log reviewed by health & safety supervision. Portions withheld fire? IOCFR2. 7901. AUSTIN:N A. Babcock & Wilcox Co. 80/10/03. 4pp. 07198:083.
- --8012090023 Forwards IE insp Repts 70-0135/80-22 & 70-0364/80-18 & on 800707-0801 & notice of violation. Notice of violation withheld (ref 100FR2.790).
 MARTIN.M.O. Region 1, Philadelphia, Bafeguards Branch. 80/09/12.
 2pp. 07178:087.
- --8012070073 IE Imsp Repts 70-0133/80-22 & 70-0364/80-18 on 800707-0801. Noncompliance noted acress not controlled to power & dry scrap storage areas. Procedures not followed for equipment contamination surveys Portions withheld (ref 10CFR2. 770). RUSHNER.N. L. Region 1, Philadelphia, Office of the Director. JOVER.J. M. Region 1. Philadelphia, Safeguards Branch. 60/09/12. 11pp. 07198-089.
- 8012290371 Responds to 801020 ltr re exemption from annual mgt review of matl control & accounting sys. Exemption granted. Encl to 801020 ltr will be withheld per 10CFR2. 790(d). PARTLCH, J. G. Material Control Licensing Branch. 80/12/10. ip. 07345: 352.
- 8012310R66 PNO-I-B0-177: on 801222.main valve of fire sprinkler systracked & released 4:000 gallons of water onto floor of plant Bmall quantity leaked outside protected area but was surveyed as not conteminated. Systurently inoperable. ROTH, J., CROCKER, N. M., SMITH, O. H. Region i. Philadelphia, Office of the Director. 80/12/22 2pp. 0/361:287.
- DOCKET 70-0371 UNITED NUCLEAR CORP.
- 8012020754 Forwards "Emergency Security Coverage Plan," to be implemented if guardforce contractor unable to supply necessary personnel. GIGLIOTTI,R.J. United Nuclear Corp., UNC Recovery Systems Div. B0/09/10. 1p. 06586:003.
- --8012029261 "Emergency Security Coverage Plan." → United Nuclear Corp., UNC Recovery Systems Div. 80/05/31, 7pp. 04586:003
- 8012010549 Forwards effluent menitoring rept for Jan-June 1980. KIRK-N.F. United Nuclear Core., Naval Products Div. 80/09/15. 2pp. 07098:082.

- 8012/20699 Forwards revision to 800919 application for amend to License 8(M-338 adding Page 8.3.3/Revision 2 re storage of limited quantity of fuel matl at site & withdrawing Pages 7.3-1 through 7.3-3.

 KIRK W.F. United Nuclear Corp./Naval Products Div. 80/10/16. ip. 07130:335.
- --8012070494 Application to amend License SNM-368, consisting of Revision 2 to Page B.3-3 re storage of fuel.

 4 United Nuclear Corp., Naval Products Div. 80/10/16. ip. 07130:336.
- 8012190694 Forwards IE Insp Rept 70-0371/80-15 on 800922-26. No noncopliance noted.

 MARTIN.N.O. Region 1, Philadelphia, Befeguards Branch. 80/10/28, 3pp. 07287:352.
- --8012190498 IE Insp Rept 70-0371/80-15 on 800922-26. No noncompliance noted Hajor areas inspected: measurement control program. Details withheld (ref 10CFR2.790).
 ZIBULSKY, M. Region 1. Philadelphia. Office of the Director. JOYNER, J. H. Region 1. Philadelphia. Safeguards Branch. 80/10/15. 1p. 07287: 354.
- 8012290374 PNS-I-80-026: on 801212. United Nuclear Corp reported bomb threat from unidentified male. Two searches revealed nothing. State local & Federal authorities will be notified. JONES, E., JOYNER, J. Region 1, Philadelphia, Office of the Director. 80/12/12. 2pp. 07339: 080.
- DDCKE1 70-0398 COMMERCE, DEPT. OF
- 8012240247 Ack receipt of 801105 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-0398/80-04.
 SMITH.O.M. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 80/11/13. 1p. 07323:098.
- --8012240251 Responds to NRC 801024 ltr re violations noted in IE Insp. Rept 70-0398/80-04. Corrective actions: staff will follow required procedures in shipping radioactive matls. PEVEYL. E. Commerce, Dept. of, National Bureau of Standards. 80/11/06. ip. 07325:099.
- --8012240253 Forwards IE Insp Rept 70-0378/80-04 on 800929-1001 & notice of violation.

 SMITH.O.H. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 80/10/24. 2pp. 07325;100.
- --8012240258 Notice of violation from insp on 800927-1001.

 4 Region I, Philadelphia, Office of the Director. 80/10/24, 1p. 07325:102.
- --8012240261 IE Insp Rept 70-0378/80-04 on 800929-1001. Noncompliance noted: failure to label package of radioactive matl prior to shipment.
 ROTH-J. Region 1, Philadelphia. Office of the Director. CROCKER.H.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/24. 10pp. 07325:103.
- 6012230145 Requests amend to License BNM-362, permitting use of up to 1 mg Pu & up to 1 g U-235 in mass spectrometer complex in Bldg 221.
 PEYEY, L. E. Commerce, Dept. of National Bureau of Standards.
 B0/11/24. 19. 07316: 357.
- 8012230483 Forwards add1 info in support of amend to License SNM-362, per 801124 request.

 * Commerce.Dept.of. 80/12/19. 7pp. 07314:132.
- DOCKET 70-0687 UNION CARBIDE CORP.
- 8012190548 Forwards IE Insp Rept 70-0597/80-06 on 800917-19 & notice of violation.

 8MITH.O.H. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 80/10/15. 2pp. 07288:180.
- --8012190550 Notice of violation from insp on 800917-19.

 # Region i, Philadelphia, Office of the Director. 80/10/14. 1p. 07288:182.
- --8032190533 IE Insp Rept 70-0687/80-05 on 800917-19, Noncompliance noted: failure to post cabinet containing U. CLEMDNS:P. Region i, Philadelphia, Défice of the Director, XNAPP.P.J. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/14. 6pp. 07288:183.

- 8012220624 Objects to NRC 801105 ltr advising of 1D facility classification.Licensee maintains that 10 status is correct category.Facility is specifically prohibited from full range of activities under 10.
 VOTH.M.H. Union Carbide Corp. 80/12/02. 2pp. 07299:259.
- 8012160422 Responds to FOIA request for documents re five categories of info re spent fuel shipments through Commonwealth of PA. Farwards documents listed in App A. Info partially withheld: local law enforcement capabilities (ref FOIA Exemption 3). FELTON.J.M. Division of Rules and Records. 80/12/03. 3pp. 07261:310.
- --B012160471 Bubmits request for route approval for spent reactor fuel transportation. Includes cask identification, quantity & type of fuel, loaded weight of unit, carrier, anticipated schedule & route info.

 HART, H. C. Union Carbide Corp. 79/11/29. 4pp.
- DOCKET 70-0698 WALTZ MILL BITE, WESTINGHOUSE ELECTRIC CORP.
- 8012100027 Summary of 801113 meeting w/Nestinghouse in Silver Bpring, MD re environ rept requirements for facility license renewal application.
 KEIZLACH, N. Uranium Recovery Licensing Branch. 80/11/17. 2pp. 07217:083.

DOCKET 70-0/34 GENERAL ATOMIC CO.

- 8012160601 Responds to 800527 ltr describing changes in fundamental nuclear matl control plan. Revised pages are acceptable, w/addition of encl qualifying words. Encl withheld (ref 100FR2, 790).
 PARTLON, J. 0. Material Control Licensing Branch. 80/12/03, 1p. 07261-232.
- B012240506 Informs that fee required for Commission review of 800506 request for fuel shipment route approval.

 MILLER.N.O. License Fee Management Branch. 80/12/08 ip. 07324:117.
- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO.
- 8002210087 Forwards request for route approval for shipment of irradiated reactor fuel. CARRIER, M. J. General Electric Co. 79/12/28. 1p. 04069:123.
- 8012080/67 Forwards "Seismic Evaluation of Vallecitos Site: Basis of Earthquake Oround Motion Design Criteria," final rept. HALL-W. J. N.M. Newmart Consulting Engineering Services. NRC-03-78-150. 80/09/29. ip. 07189:040.
- --8012090774 Forwards "Seismic Evaluation of Vallecitos Site:Basis of Earthquake Oround Motion Davign Criteria," final rept. Damage scenarios are realistic re effects of postulated seismic hazards.
 NEWMARK, N. M., HALL, H. J. N. M. Newmark Consulting Engineering Bervices, NRC-03-78-130. 80/09/29, 11pp. 07189:041.
- --8012080779 "Beismic Evaluation of Vallecitos Site:Basis of Earthquake Ground Motion Design Criteria." HALL.H.J., NEWMARK.N.M. N.M. Newmark Consulting Engineering Bervices. NRC-03-78-150. BD/09/29. 11pp. 07189:052.
- 8012020300 Application for amend to License SNM-960 replacing Sections i-8 of Amend MPP-2 w/condition limiting possession of BNM to 1 kg.
 MOSCHNER, R. A. General Electric Co. 80/10/15, 1p. 07141:360.
- 8012040483 Forwards RA Moschner 800911 ltr re re-issue of mati control t accounting plan for facility Plan withheld (ref 100FR2 790).

 * Public Document Branch. 80/10/20. 1p.
- --B012040492 Forwards mati control & accounting plan for Plants 3 & 4. Plant 2 has been completely deactivated & ref to plan removed Plan covers plant U which is to be reactivated. Plan withheld (ref 100FR2.740).

 MOBCHINER, R.A. General Electric Co. B0/09/11, ip. 07170:114.
- 8012020219 Notifies that review of 801031 revised request for approval of routes involving shipment of spent fuel is subj to NRC license fee schedule. Notification of fee will be made upon approval of request.

 WEISS: D. License Fee Management Branch. 80/11/18 1p. 07133: 126.

- 8012150037 Requests fee for proposed amend to License SNM-960, repl. Sections 1-8 of Amend MPP-2, submitted in util 801015 ltr. WEISS, D. License Fee Management Branch. 80/11/20. 1p. 07240: (
- 8012160422 Responds to FOIA request for documents re five categoric info re spent fuel shipments through Commonwealth of PA. Forwards documents listed in App A Info partially withheld: local law enforcement capabilities (ref FOIA Exemption 3). FELTON, J. H. D(vision of Rules and Records. 80/12/03. 3pp.
- --8012160424 Requests that approved spont fuel route be altered as indicated in enc).
 CARRIER, M.J. General Electric Co. 80/04/21, 2pp.
- 8012240501 Informs that review of licenses route approval requested 800414 & 0505 ltrs is subj to Commission license fee schedule. Fee invoice will be issued.
 MILLER. N. O. License Fee Management Branch. 80/12/08. ip. 07324:115.
- 8012290149 Notice of 810105 second prehearing conference in San Francisco.CA re discussion of all pending matters, including re-examination of status of discovery & further scheduling. No limited appearance statements will be heard. GROSSMAN.H. Atomic Sefety and Licensing Board Panel. 80/12/10.07344:051.
- 8012310256 Motion for issuance of order containing ABLD rulings granting joint petition to intervene Rotice of appearance & Certificate of 8vc encl.

 TREBY. 8. A. Hearing Branch 1. 80/12/24. 5pp. 07370.028.

DOCKET 70-0820 UNITED NUCLEAR CORP.

- B012020279 Advises that physical plant protection plan has been ame to permit storage of packaged lagoon waste awaiting shipment in open area & parking lot. Change does not decrease affectiveness of plan.
 SHULTZ. D. M. United Nuclear Corp., UNC Recovery Bystems Div. 80/09/17. 1p. 07133:125.
- 8012020374 Advises of attrition of contract security personnel due site decommissioning. Replacements uill be trained to perform individual rather than overall guard duties. Change will not decrease effectiveness of security plans. CDGAN, N. J. United Nuclear Corp., UNC Recovery Systems Div. 80/07/19. 1p. 07142:082.
- 8012290063 Documents events stated in 800916 telcon re incident on 800913 Containment basin surrounding tank held several inches of liquid-which came from tank via hose placed in tank. Flow stopped & liquid pumped back into tank. OREGO.R.J. United Nuclear Corg., UNC Recovery Systems Div. 80/09/23. 2pp. 07345:252
- 8012300034 Forwards IE Insp Rept 70-0820/80-17 on 800908-12 & 22-26, noncompliance noted.

 MARTIN, N. O. Region 1, Philadelphia, Safeguards Branch. 80/10/17, 2pp. 07356:106.
- --8012300037 IE Insp Rept 70-0820/80-17 on 800908-12 & 22-26. No noncompliance nuted Major areas inspected measurements of SNH in waste discards & licensee decommissioning activities. Details withheld (ref 10CFR2.790).
 SUMMERS.R., HOLODY.D., BISSETT.P. Region 1, Philadelphia, Offic of the Director. 80/10/15. ip. 07356:108.
- 8012100256 Ack receipt of 801010 & 16 ltrs informing NRC of steps to correct violation noted in IE Naste Packaging Insp Rept 15000039780-16.
 SHITH 0. H. Region 1. Philadelphia, Fuel Facility & Haterials Bafe Branch. 80/10/24. (p. 07217:328.
- --8012100264 Responds to NRC 800916 itr re violation noted in IE War Packaging Insp Rept 15000039/80-16 Corrective actions: modifying existing procedures to provide more detail re checkeff of individual requirements. BOWERB, C. E. United Nuclear Corp. 80/10/10. 2pp. 07217:329.
- ~-8012100273 Forwards response to 801010 ltr re violation noted in Raste Packaging Insp Rept 15000037/80-16. Corrective action: driver instructed not to remove placards until completion of unloading.
 BOWCRS.C.E. United Nuclear Corp. 80/10/16. 2pp. 07217:331.
- --8012100277 Forwards IE Waste Pactaging Insp Regt 15000039/80-16 or B00730 & notice of violation BNITH, G. H. Region i, Philadelphia, Fuel Facility & Materials Safaty Branch. 80/09/16. 2pp. 07217:333.

- -8012130280 Notice of violation from insp on 800730. * Region I. Philadelphia, Office of the Director. 80/08/20. 2pp. 07217:335.
- -80121002R5 IE Waste Packaging Insp Rept 18000039/80-16 on 800730.
 Noncompliance noted: no radioactive placard found on tractor or trailer.
 MACARTHUR, T. C., POTTER, J. P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/08/20. 3pp. 07217:337.
- 012226009 Forwards IE Insp Rept 70-0820/80-18 on 801006-09, No noncompliance, noted.

 MARTINI-W. G. Region 1, Philadelphia, Safeguards Branch, 80/10/24, 2pp. 07306:280.
- -8012220012 IE Insp Rept 70-0820/80-18 on 801006-09. No noncompliance noted. Major areas inspected: decommissioning activities & shipper/receiver differences. Details withheld (ref 10CFR2, 790).
 SUNKERB. R., ZIBULSKY, H. Region 1, Philadelphia, Office of the Director. JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch. 80/10/22, 1p. 07306:282.
- 012090247 Ack receipt of 801001 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/80-05. SMITH.O.H. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/28. 2pp. 07202:316.
- -8012090251 Responds to NRC 800708 ltm re violations noted in 16 Insp Rept 70-0820/80-05. Corrective actions: audit repts will include analysis of work station radiation exposure. Mower checked & found free of contamination. BOMERS-C.E. United Nuclear Corp., UNC Recovery Systems Div. 80/10/01. 4pp. 07202.318.
- -8012070253 Forwards IE insp Rept 70-0820/80-05 on 800514-16 & notice of violation. SMITH-0, H. Region i. Philadelphia. Fuel Facility & Materials Safety Branch. 80/09/08 2pp. 07202:322.
- 8012090254 Notice of violation form insp on 800514-16.

 * Region 1. Philadelphia. Office of the Director. 80/08/29. 2pp.
 07202:324.
- 8012070258 IE Insp Rept 70-0820/80-05 on 800514-16. Noncompliance noted: Dac 1979 audit did not include analysis of radiation exposure for each work station. Mower moved from contaminated area not surveyed.

 CLEKONS.P. Region i, Philadelphia, Office of the Director. KNAPP.P. J. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 80/08/29. 7pp. 07202:326.

CKET 70-0882 COLUMBIA UNIV.

- 12020913 Application for renewal of License SNH-870. Matl to be used for basic research & educational purposes.
 LORIO.P.M. Columbia Univ. 80/09/18. 18pp. 07148:094.
- 12240176 Act receipt of 801027 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 70-0882/80-01. 470-0882/80-01. 48871N.U.O. Region 1, Philadelphia, Safeguards Branch. 80/11/18.2pp. 07325:037.
- B012240178 Responds to NRC B03227 ltr re violation noted in IE Insp Repts 70-0882/78-01 & 70-0862/80-01. Corrective action: mat1 status repts submitted. LGRIG.P. H. Columbia Univ. 80/10/27. lp. 07325:038.
- CKET 70-0925 CIMARRON FACILITY, KERR-MCBEE CORP.
- 12180431 Forwards IE insp Repts 70-0925/80-03 & 70-1193/80-05 on 800930-1002 No moncompliance noted. DAVIS.A.B. Region G. Chicago, Fuel Facility & Materials Safety Branch. 80/11/12 2pp. 03794:283.
- .002.

- DOCKET 70-1062 TODD SHIPYARDS CORP.
- B012040524 Forwards 800415 ltr requesting termination of License. SKM-1015. HATHKAY, C. N. Todd Shipyards. 80/10/02, lp. 06915:001.
- ---B012040533 Requests that License 8MM-1015 be terminated, MINTERS, C.E. Todd Shipyards. 80/04/15, ip. 06915:00i,
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC.
- BG12180493 Requests amend to License SNM-1067, authorizing temporary possession of U & thorium-bearing waste matis for packaging & transfer to commercial disposal facility. Criteria, supportive info & license amend fee encl.

 LICHTENBERGER C-E Power Systems. 80/11/10. 26pp. 07183:001.
- 8012180395 Summary of 801110 meeting w/C-E to discuss proposed request for amend to License SN4-1067, changing organization for nuclear criticality & radiation safety. KETZLACHIN. Uranium Fuel Licensing Branch. 80/11/13, 2pp. 07272:337.

DOCKET 70-1113 GENERAL ELECTRIC CO.

- 8012040470 Submits latest revisions to fundamental nuclear mat1 control plan for fuel fabrication facility. Descriptive listing of page changes & revised pages encl. Revisions withheld (ref 10CFR2. 790).

 KAPLAN.A.L. General Electric Co. 80/09/11, 2pp. 07170:042.
- 8012010217 Informs that review of Amend MPP-2 to License SNM-1097 dtd 800703 is complete. No add1 fee required per 10CFR170. MILLER, N. O. License Fee Management Branch. 80/09/22, 1p. 07092: 137.
- 8012180472 Ack receipt of NRC 801126 ltr forwarding IE Insp Rept 70-1119/80-18 on 801105-07. KAPLANIA.L. General Electric Co. 80/12/01. 1p. 07272:007.
- --8012180478 Forwards nonproprietary version of IE Insp Rept 70-1118/80-18 on 801105-07. No items of noncompliance noted. KENNA.W.B. Region 2. Atlanta, Safeguards Branch, 80/11/26, 2pp. 07272:008
- --8012180482 Nonproprietary version of IE Insp Rept 70-1113/80-18 on 801105-07. No items of noncompliance noted. Major areas inspected: WMD measurement control program. BATES.J. N., MCALPINE.E.J. Region 2, Atlanta, Bafeguards Branch. 80/11/25. 1p. 07272:010.
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP.
- B012110152 Forwards IE Insp Rept 70-1143/80-13 on B00905.No noncompliance noted Insp details withheld (ref 10CFR2.790), MARTIN.N.O. Region i, Philadelphia, Safeguards Branch. 80/10/07. 2pp. 07224:052.
- --8012110138 IE insp Rept 70-1143/80-13 on 800905. No noncompilance notes. Major areas inspected:matl control & accounting physical security, health & safety. Details withheld (ref 100FR2, 790). KUSHNER. R. L. Region I. Philadelphia. Office of the Director. JOYNER. J. R. Region i. Philadelphia. Safeguards Branch. 80/10/02, 3pp. 07224:054.
- B012100227 Ack receipt of B00930 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-1143/80-11.
 MARTIN.N.G. Region I, Philadelphia, Safeguards Branch. B0/10/23.
 1p. 07217:316
- -8012100234 Responds to NRC 800708 ltr re violations noted in IE Insp Rept 70-1143/80-11. Corrective actions withheld (ref 10CFR2. 770). HODRE, J. B. Westinghouse Electric Corp. 80/09/30, ip. 07217: 317.
- --8012100241 Forwards IE Insp Rept 70-1143/80-11 on 800804-08 & nutice of violation Notice of violation withheld (ref 100FR2, 790). MARTIN,4.0. Region 1, Philadelphia, Safeguards Branch. 80/09/08. 2pp. 07217:318.

- --8012163247 IE Insp Rept 70-1143/80-11 on 800804-08.Noncompliance noted: failure to reconcile & adjust central control records & subsidiary accounts. Details withheld (ref 10CF82.790). RATIA.A.D., BISSETI.P. Region 1, Philadelphia, Office of the Director. JOYNER, J. H. Region 1, Philadelphia, Bafeguards Branch. 80/09/02. 1p. 07217:320.
- 8012220015 Forwards IE Insp Rept 70-1143/80-14 on 801007-08. No nencompliance noted.
 MARTIN, II G. Region 1. Philadelphia, Bafeguards Branch. 80/10/24, 2pp. 07306:302.
- --8012220017 IE Insp Rept 70-1143/80-14 on 801007-08.No noncompliance noted Major areas inspected decomplissioning activities.

 Details withheld (ref 100FR2.770).

 HOLDDY, D. J. Region 1, Philadelphia, Office of the Director.
 JOYNER, J. H. Region 1, Philadelphia, Eafeguards Branch. 80/10/21.

 1p. 07306:304.
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP.
- 8012090162 Ack receipt of 801002 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/80-21. KENNA.W.B. Region 2, Atlanta, Safeguards Branch. 80/11/25, ip. 07200:112.
- --8012070165 Responds to telcon re violations noted in IE Insp Rept 70-1151/80-21. Add1 info to 801002 ltr withheld (ref 10CFR2, 790).
 900DMIN.H.L., D'AMORE, M. Westinghouse Electric Corp. 80/11/07. ip. 07200:113.
- --8012070169 Responds to NRC 800829 itr re violations noted in IE Insp Rept 70-1151/80-21. Encl withheld (ref 100FR2. 790). GQQDMIN, M. L., D'AMGRE, M. Westinghouse Electric Corp. 80/10/02, 1p. 07200: 114.
- --8012090174 Forwards IE Insp Rept 70-1151/80-21 on 800721-25 & notice of violation. Notice of violation withheld (ref 100FR2.790). KERNA. N. B. Region 2. Atlanta. Safeguards Branch. 80/08/29. 2pp. 07200:115.
- --B0120901B5 IE Insp Rept 70-1151/80-21 on B00721-25, Noncompliance noted: failure to include provisions for review & approval of written procedures for analyzing control program data.

 Details withheld (ref 10CFR2.790).

 JOKES-D.W. Region 2, Atlanta, Office of the Director.

 GILLESPIE, E. P. Region 2, Atlanta, Bafeguards Branch. 80/08/28, ip. 07200:117.
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP.
- B012010191 Informs that Amend 4 to License SNM-1174 approved, allowing decontamination & dismantling of equipment & glove boxes & operation of Unnumbered comenting glove boxes, ROUBE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. B0/10/08. 3pp. 07072: 132.
- 8012080790 SER supporting Amend 4 to License SNM-1174 for decontamination & dismantlement of gloveboxes & plant equipment. HAU9RNEY.C. J., ROUSE.L.C. Advanced Fuel & Spant Fuel Licensing Branch. 80/10/18. Spp. 07196:275.
- 8012180431 Forwards IE Insp Repts 70-0925/80-03 & 70-1193/80-05 on 800930-1002 No noncompliance noted.

 DAVIS,A.B. Region 3. Chicago, Fuel Facility & Materials Bafety Branch. 80/11/12. 2pp. 03794:283.
- --8012180435 IE Insp Repts 70-0725/80-03 & 70-1193/80-05 on 800730-1002, No nuncompliance noted Major areas inspected facility changes & mods redwaste mpt & licensee actions on previous insp findings.

 HUETER, L. J. Region 3. Chicago, Office of the Director. FISHFR, W. L. Region 3. Chicago, Foel Facility & Materials Safety Branch. 80/11/10. 10pp. 03794:285.
- DOCKET 70-1201 UF 6 CONVERSION FACILITY, BABCOCK & WILCOX CO.
- 8012020269 Requests that target date for completion of investigation of inventory differences, per NRC 800520 request, be extended to 810228 to permit thorough review.

 ZEFF, D. H. Babcock & Wilcox Co. 80/10/07. 1p. 07134: 213.

DOCKET 70-1252 EDLON INTERNATIONAL CO.

- 8012010222 Approves "Edlow Intl Co Plan for Physical Protection per 10CFR73.67.Part I.SNM of Moderate Strategic Significance & Part II.SNM of Low Strategic Significance." MCCORKUE.O.W Physical Security Licensing Branch. 80/10/14. 1p 07092:139.
- DOCKET 70-1257 HIXED DXIDE FABRICATION PLANT, EXXON NUCLEAR CO., IN
- 8012020313 Advises that info contained in 800508 ltr specifying det of matts accounting procedures is proprietary & should be withheld (ref 100FR2.790).

 NILSON.R. Exton Nuclear Co., Inc. (subs. of Exxon Corp.), 80/09 lp. 07148:192.
- 8012090137 Forwards IE Insp Rept 70-1257/80-07 on 800812-15.No noncompliance noted.
 800K: H.E. Ragion 5. Ban Francisco, Fuel Facility & Materials Baf Branch. 80/10/15. 2pp. 07199:258.
- --8012070143 It Insp Rept 70-1257/80-07 on 800812-15. No noncompliant noted. Hajor areas inspected: licensee use of lagoons for storage & evaporation of liquid process wastes, lagoon monitoring & possible environ impact.

 COOLEY.N.J. THOMAS.R.D. Region 5, San Francisco, Office of the Director. BOOK.H.E. Region 5, San Francisco, Fuel Pacility & Materials Safety Branch. 80/10/14, 12pp. 07197:260.
- 8012160613 Ack receipt of 801028 & 1103 ltrs for emend to License SNM-1227 re laundry facility & reduction in Pu inventory. Request has been classified as requiring minor emend to license. Fee required, WEISS, D. License Fee Management Branch. 80/11/26. 1p. 07254:30
- 8012110100 Forwards IE Insp Rept 70-1257/80-08 on 800925-1003 & 27-30 & notice of violation. Insp rept withheld (ref 10CFR2.790).
 NORDERHAUG. L. Region 5, San Francisco, Safeguards Branch, 80/11/28. 2pp. 07223:150.
- --8012110106 Notice of violation from insp on 800925-1003 & 27-30. Noncompliance noted: failure to check tamper-indicating devices. NORDERHAUG.L.R. Region 5. San Francisco, Bafeguards Branch, 80/11/28. 1p. 07223:132.
- DOCKET 70-1308 MORRIS OPERATIONS. GENERAL ELECTRIC CO.
- B012010622 Forwards Revision 5 to NEDO-20776, "Spent Fuel Sycs Operation GA Plan." DAMSON, D. M. General Electric Co. B0/09/17. 2pp. 07091:232.
- --8012010626 Revision 5 to NEDD-20776. "Spent Fuel Syrs Operation QA Flan " VAN MODMISSEN General Elactric Co. NEDD-20776 R5. 80/07/15. 10pp. 07091:234.
- 8012020307 Advises that inventory of fuel stored at facility was increased by receipt of three PWR fuel bundles from Southern CA Edison during Aug & Sept. DANSON D. M. General Electric Co. 80/10/09. 2pp. 07141:361.
- 8012040166 Ack receipt of 800926 itr re use of evaporation of spray ponds. Partially installed spray field irrigation sys uses only treated water from sanitary waste sys.

 ROUSE.L.C. Advanced Fuel & Spent Fuel Licensing Branch. 80/10/14 ip. 07158:082.
- --8012040179 Requests info on climate restrictions for use of spray & use of spray ponds for fuel storage.

 DREY, L. A. Affiliation Unknown. 80/09/26, ip. 07158:083.
- 8012290527 Forwards DM Dawson 801121 ltr confirming QE intent to ren License 8NM-1265, ROUNEY,M.A. Mayer, Brown & Platt, 80/12/01, 1p. 07335:178,
- --8012270531 Confirms OE intent to pursue application for renewal of License SNM-1265. Appropriate documents to amend 790227 application will be filed on or about 810112.

 DANSON. D. M. General Electric Co. 80/11/21. 2pp. 07335: 177.
- 8012230017 Informs ASLB of 800825 FR notice of Director's decision under 100FR2. 205 that E18 on decontamination of Dresden Nuclear Power Station Unit 1, be prepared. FR notice encl. ROTHSCHILD, N. U. Hearing Branch 1. 80/12/03. 2pp. 07311:179,

- 8012290135 Informs that effective data of 10CFR72 corrected to read 801212 instead of 801128.

 BACHMANN, R. O. Rulemaking & Enforcement Division. 80/12/03. ip.
- 8012190460 Order granting State of IL stay of spent fuel pool proceeding until 30 days after effective date of new 10CFR72.0E ordered to submit revisions to consolidated SAR by 81012.Proposed amend to contentions due by 810226. GOODHOPE.A.C. Atomic Safety and Licensing Board Panel. 80/12/08. 2pp. 07286:324.

DOCKET 70-1349 HOSPITAL PAVIA

8012170220 Forwards IE Info Notice 80-35, "Leaking & Dislodged I-125 Implant Seeds," No written response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/10/10. lp. 07268:197.

DOCKET 70-1397 BT. MARY'S HOSP. RICHHOND. VA

8012170226 Forwards IE Info Notice 80-35, "Leaking & Dielodged I-125 Implant Seeds." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/10. ip. 07268:206.

DOCKET 70-1426 TRANSNUCLEAR, INC.

- B012030793 Approves 800915 request for extension until B01015 for submittal of safeguards transportation protection plan. MCCORKLE.O.H. Office of Nuclear Material Bafety & Safeguards. B0/09/29. ip. 07150:219.
- B01211062B Forwards IE Insp Rept 70-1426/79-01, on 790806-10. No noncompliance noted. Cover sheet only enclined tooffiz. 790). MARTIN. M. O. Region I, Philadelphia, Safeguards Branch. B0/10/08. ip. 07227:207.
- --8012110635 IE Insp Rept 70-1426/79-01 on 790806-10. No noncompliance noted Major areas inspected:domestic shipment of SSNK.

 Details withheld (ref 10CFR2. 790).

 DEVLIN, J.H., MARTIN, W.O. Region 1, Philadelphia, Safeguards Branch. SMITH, R.H. Region 1, Philadelphia, Office of the Director. 80/10/03. 1p. 07227:208

DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO.

- B012020647 Requests that due date for submission of revised safeguards transportation protection plan be extended to B01102 w/svc to continue under present plan in interim. Requests NRC position on 30-minute check call frequency. MAYER, C. H. Tri-State Motor Transit Co. (subs. of Georgia Pacific Corp.). B0/09/19. 1p. 07148:012.
- 8012040036 Ack receipt of 800919 itr requesting extension to 801101 for submittal of mafeguards transportation protection plan. Request approved NRC position on 30-minute check call frequency published on 800818. MCCORKLE,G.W Office of Nuclear Material Safety & Safeguards. 80/09/30. 19. 07170.011.
- 8012240304 Informs that fee required for Commission review of 800530 ltr requesting temporary amend to SNM Security Transportation Plan II. MILLER. H. O. License Fee Management Branch. 80/12/08. ip. 07324: 116.

DOCKET 70-1966 TENNESSEE VALLEY AUTHORITY

B012040545 Requests Item 8 of SNM-1526 be amended to allow max amount that licanses may possess at any one time be changed to up to 10,000 g U-235, enriched to less than 10%. Amend will relieve licenses of 10CFR73 requirement.

MILLS.L.K. Tennessee Valley Authority. 80/09/26. 1p. 07:70:107.

DOCKET 70-2156 ST. JOHN'S HOSP. LOWELL, MA

8012190594 Ack receipt of 800929 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-01952/80-01. KINNEPAN,J.D. Region 1, Philadelphia, Fuel Facility & Materials Safety Stanch. 80/11/06. 1p. 07288:228.

- ~-8012190597 Responds to NRC 800705 ltr re violations noted in IE Insp Rept 30-1952/80-01.Corrective actions:hot lab area locked at all times when unattended & dose calibrator checked daily. PEDIGREE, R B. St. John's Hosp. Louell, MA. 80/09/29. Zpp. 07289:229.
- --8012170601 Discusses IE Insp Rept 30-01952/80-01 on 800721 & forwards notice of violation. KINNEGRANI.J.D. Region 1. Philadelphia, Fuel Facility & Materiels Safety Branch. 80/09/05. 2pp. 07288:231.

- --8012170604 Notice of violation from insp on 800721. Noncompliance noted: licensed matl left unattended & unsecured in unlocked nuclear medicine leb & daily dose calibr checks not performed.

 * Region 1. Philadelphia. Office of the Director. BO/09/05. 2pp. 07288:233.

DOCKET 70-2286 MEDICAL CENTER OF VERBORT BURLINGTON, VT

- B012080720 Ack receipt of 800912 & 1003 itrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-00509780-01,30-03289780-01,70-2286780-01 & 40-8106780-01. KINNEMANJ.D. Region i, Philadelphila, Fuel Facility & Materials Bafety Branch. B0/10/30. ip. 07181:157.
- --8099190463 Responds to NRC 860819 itr re evaluations of I-i31 & I-i25 concentrations. Evaluations of restricted area concentrations of I-i31 & I-i25 & thyroid monitoring will be conducted within 30 days, using Reg Ouide 8, 20, Table 1 criteria.

 JANKEY, C. D. Medical Center of Vermont Burlington, VT. 80/09/12.

 ip. 07181:158,
- --8012080735 Responds to MRC 800819 ltr re violations noted in IE Insp Rept 30-03289/80-01 Corrective actions; evaluations of restricted area concentrations & thyroid monitoring to be conducted.

 JANNFY.C.D., BERRY.J.F. Medical Center of Vermont Burlington, VT.
 80/10/03. 19. 07181; 159.
- --8012080742 Discusses IE Insp Repts 30-00509/80-01,30-03289/80-01, 70-2205/80-01 & 40-8106/80-01 on 800729-30 & forwards notice of violation. KINNEMAN, J. D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch, 80/08/19, 2pp. 07181:160.

DOCKET 70-2322 EDLOW INTERNATIONAL CO.

- 8012040194 Ack receipt of 800703 ltr re approval of route used for transportation of spent reactor fuel Approves route change & proposed port security & forwards initial arrangements w/law agencies on route, W/o encl. MCCORKI E.O. W Office of Nuclear Material Bafety & Bafeguards, 80/09/23. 1p. 07158:105.
- 8012040380 Approves encl route to be used for transport of spent reactor fuel per 10CFR73.37.W/o encl. MCCORKLE.O.W. Physical Security Licensing Branch, 80/09/23. ip. 07163;257.
- 801204004B Ack receipt of 800924 ltr requesting change in route. Previously approved route remains in effect contingent upon meeting 100FR73.37 requirements for heavily populated areas. MCCORKLE.0. W. Office of Nuclear Material Bafety & Safeguerds. 80/09/29. 1p. 07169:362.

DOCKET 70-2392 EDLON INTERNATIONAL CO

- B012010545 Requests route approval for shipment of spent fuel around Fayetteville.NC. RAYENSCROFT, N. Edlow International Co. 80/09/24. 1p. 07098:081.
- DOCKET 70-2478 TRANSNUCLEAR, INC.
- 8012020289 Confirms telcon notifying that Pegase Cask 4 containing one irradiated fuel element is due to arrive in Portsmouth, VA on 801027. STONESURNER, W. Transnuclear, Inc. 80/10/09, ip. 06916:001.
- 8012020933 Confirms telcon notifying that one Pegase Cask 1, containing 36 irradiated fuel elements, is scheduled to arrive in Portsmouth, VA on 801027.
 STONEBURNER, M. Transnuclear, Inc. 80/10/14. ip. 07133:136.

- DOCKET 70-2479 TRANSNUCLEAR, INC.
- 8012020243 Confirms notification that TN-7 Cask containing 60 irradiated fuel elements is scheduled for arrival in Portsmouth.VA on 801029.
 STONEBURNER,W. Transnuclear, Inc. 80/10/15. 1p. 07133:143.
- DOCKET 70-2520 WEST VIRGINIA UNIV. HEDICAL CENTER MORGANIONN, WV
- 8012170258 Forwards IE Info Notice 80-35, "Leaking & Dislodged I-125 Implant Seeds." No written response required. O'REILLY,J.P." Region 2, Atlanta, Office of the Diractor. 80/10/10. ip. 07268:233.
- DOCKET 70-2609 COMMONWEALTH EDISON CO.
- 8012180340 Forwards IE Insp Repts 70-2409/80-02 & 70-2885/80-02 on B01117-20 & notice of violation. Notice of violation withheld (ref 10CFR2, 790), HIND, J.A. Region 3, Chicago, Safeguards Branch. 80/12/03. 2pp. 03794: 202.
- --B0121B0365 IE Insp Repts 70-2609/80-02 & 70-2885/80-02 on 801117-20. Noncompliance noted: degraded physical barrier. Details withheld (ref 10CFR2. 790). HADEDA.T.J., HIND, J.A. Region G. Chicago, Office of the Director. B0/12/03. ip. 03794:204.
- DOCKET 70-2623 MCQUIRE SPENT FUEL POOL, DUKE POWER CO.
- 8012030B4B Forwards Revision 1 to storage & in-transit security plan for SAM of low strategic significance. Revision withheld (ref 10CFR2.790). PARKER, W. O. Duke Power Co. 80/09/16. 1p. 07149:253.
- 8012020292 Requests NRC response to Buncombe County, NC, Civil Preparedness Agency 800711 telegram to President Certer & NRC requesting notification of high level radiation athipments through county.

 BOSTIAN, R. W. Duke Power Co. 80/10/02, ip. 07141:358.
- BO12080637 Amends License BNM-1773 to include encl condition for licensee to follow low strategic significance BNM storage & in transit security plan.

 MCCORKLE, O. W. Physical Security Licensing Branch. 80/10/15. 2pp. 07188: 225.
- 8012290299 Expresses approval of NRC decision not to permit shipment of raduaste through NC & SC.
 NGFF8UYER, P. G. Affiliation Unknown. 80/11/15. 1p. 07341:213.
- 8011200241 Suggests obtaining 8 Spitalny assistance in preparing appeal brief of initial decision re McGuire/Ocones spent fuel transportation.
 CHRISTENBURY, E. Hearings Division. 80/11/18. 1p.
- 8012030724 Supports NRC decision to ban shipment of spent fuel. Public hearing should be held & more planning should go into evacuation & decontamination plans.
 WILSOR, D. Affiliation Unknown. 80/11/18, 2pp. 06586:003.
- 8012110545 Applauds ASLB 801031 decision to deny Dute Power Co right to ship dangerous nuclear waste through Carolinas.Requests notification of date chosen for Duke Power Co appeal of vanguard decision.
 BEST, B., MOGRE, B., DAVIS, D. Carolina Action. 80/11/24. ip. 07223:105.
- B012290066 Request to file amicus curiae brief in support of NRC & util exceptions on B01222.
 TROSTEN.L.M. Electric Utility Companies Nuclear Transportation group. TROSTEN.L.M. LeRosuf, Lamb, Leiby & MacRae. 80/12/04. 2pp.
- 8012290061 Order granting Electric Util Companies' Nuclear Transportation Group motion for leave to file amicus curies brief on pending appeals of applicant & MAC from ASLB 801031 decision Brief to be filed & served before NRC brief. BISHOP.C.J. Administrative Branch. 80/12/05. 2pg. 07344:234.

- 8012290379 Brief support of 801110 exceptions to ASLB 801031 inition decision denying util application to store 300 spent fuel assemblies from Oconee at McGuire. Consideration of cask tipping incident was adequate. Certificate of 8vc encl. MCGARRY, J. M. PHILIPS. M. H. Duse Power Co. MCGARRY, J. M. Debevo Liberman. 80/12/10. 151pp. 07331:169
- 8012290052 Motion for extension to file reply to util 801215 brief enable consolidation. Granted for ASLAB 801219. DS Fleischaker notice of withdrawal & ER Weiss & LL Bishop notices of appearance encl. BISHOP.L.L. RILEY.J.L. Natural Resources Defense Council. BISHOP.L.L. Sheldon, Harmon & Weiss. 80/12/17. 4pp. 07344:17
- 8012270313 Notice of withdrawal of DS Fleischaker from proceeding, behalf of NRDC, & substitution of ER Heiss, LL Bishop & BJ Scherr.
 MEISB, E. R., BISHOP, L. L. Harmon & Weiss. SCHERR, S. J. Natural Resources Defense Council. 80/12/17. 2pp. 07343:089.
- --8012270317 Request for extension of time to file reply to applic B01215 brief to enable NRDC & Carolina Environ Study Group to file single brief supporting exceptions of applicant NRC & intervenor. Certificate of Svc encl.
 B15H0P.L.L. Harmon & Neiss. B1SiDP.L.L. Natural Resources DaFense Council. RILEY.J.L. Carolina Environmental Study Gro 80/12/17. 4pp. 07343:071.
- B012290971 Brief amicus curiae addressing ABLB 801031 decision & opposing denial of util request for authority to transport 300 Oconses spent fuel assemblies to HcGuire TRDSTEN.L.M., ANCARRON.M.R., MCGRIDE.M.F. Electric Utility Comp Nuclear Transportation Group. 80/12/22. 26pp. 07343:010.
- 8012300143 Brief on exceptions to ASLB 801031 initial decision den requested license amend to authorize storage & receipt of Oconee spent fuel assemblies at McOutre Denial should be reversed. Certificate of Svc encl.
 KETCHSN.E.G., HOEFLING.R.K. Hearing Branch 4. 80/12/22. 81pp. 07382
- DOCKET 70-2663 BT. MARY HOSP. GUINEY, IL
- 8012170225 Forwards IE Info Notice 80-35, "Leaking & Dislodged I-1 Implant Seeds." No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10 ip. 07268:203.
- DOCKET 70-2881 BETHESDA LUTHERN HOSP, ST. PAUL, MA
- 8012190100 IE Insp Findings & Licensee Ack dtd 801205 of License SNM-1837. Insp findings: no noncompliance noted. BUROIN.R.E. Region 3. Chicago. Office of the Director. 80/12/0 ip. 07281:339.
- DOCKET 70-2882 SOUTHERN CALIFORNIA EDISON CO.
- 8012190034 Forwards util application for revised new fuel storage.t encl. STEVENBOOLR.L. Uranium Fuel Licensing Branch. B0/12/08. ip.
- 8012190041 Forwards util application for revised new fuel storage. encl. STEVENSON.R.L. Uranium Fuel Licensing Branch. 80/12/08. 1p.
- DOCKET 70-2885 COMMONWEALTH EDISON
- 8012180360 Forwards IE Insp Repts 70-2609/80-02 & 70-2885/80-02 on B91117-20 & notice of violation Notice of violation withheld (raf 10CR2.790), HIND. J.A. Region 3. Chicago, Safeguards Branch. 80/12/03. 2pp. 03794:202.
- --8012180345 IE Insp Repts 70-2609/80 02 & 70-2885/80-02 on 801117
 Noncompliance noted degraded physical barrier Details
 withheld (ref 100FR2.790).
 MADEOAH.T.J., HIND.J.A. Region 3, Chicago, Office of the Direc
 80/12/03.

DOCKET 70-2892 AUXILIO MUTUO HOSP.

- 80/2170263 Forwards IE Info Notice 80-35, *Leaking & Dislodged I-125 Implant Seeds, " No written response required. Q'REILLYJ.P. Region 2. Atlanta, Office of the Director. 80/10/10. ip. 07268:236
- DOCKET 70-2909 NESTINGHOUSE ELECTRIC CORP. PONER SYSTEMS
- 8012230310 Order granting extension until 810130 for NRC & applicant to respond to Safe Energy Alliance of Central AL contentions. Thirty-day extension granted to file response to intervenor contentions after substitution motion ruling. HOLF. J.F. Atomic Safety and Licensing Board Panel. 80/12/11. 3pp. 07318:081.
- B01202075B Response in opposition to C Donelson 801110 intervention petition & substitution of Donelson for Allred as party to proceeding. Prior filings designated Safe Energy Alliance of Central AL.Inc. W/Certificate of Svc. CGMAN.B. Z. KENRICK.J.R. Eckert. Beamans, Cherin & Mellott. MARCUCCI.D.R. Westinghouse Electric Corp. B0/11/24. 23pp. 07143:349.
- 8012050374 Criticizes planned const & operation of nuclear fuel plant in Prattsville-Montgomery area of State of AL. WILLIAMS.L.O. Affiliation Unknown. 80/11/24. 2pp. 06915:001.
- 8012290706 Answer in opposition to DL Allred 801110 motion for substitution of named intervenor unless viewed as request for withdrawai. Certificate of Svc encl. CONAN, B. Z., MARCUCCI, D. R. Nestinghouse Electric Corp. KENRICK, J. R. Eclert, Seamans, Cherin & Hellott. 80/11/24. 4ps. 07344:238.
- 8012030512 Response in support of substitution of C Danelson for DL Allred subj to DL Allred withdrawal, identification of conto-stions to be preserved & identification of one admissible contention.

 TURK, S E. Hearing Branch 1, 80/12/01, 4pp. 07187:002.
- --8012080516 Response in support of C Donelson 801110 petition to intervene in substitution of DL Allred sub; to DL Allred withdraual & C Donelson submittal of one admissible contention
 TURK.S E. Hearing Branch 1. 80/12/01. 22pp. 07187:006.
- --8012080522 Request for extension of time in which to file response to DL Allred contentions until 30 days after ABLB rules on pending motion for substitution due to complexity of issues. Certificate of Bvc encl.
 BACHMANIR.O. Rulemaking & Enforcement Division. TURK.8.E. Hearing Branch 1. 80/12/01. 6pp. 07187:028.
- B01229004: Response in support of C Donelson 801110 petition for leave to intervene & simultaneous joint motion for substitution for D Allred as intervenor. Certificate of Byc encl.

 KCPHILI IPS, J. L. Safe Energy Alliance. B0/12/05. 2pp. 07344:230.
- 80:12270633 Suppl to petition for leave to intervene & substitution of maned intervenors. Certificate of Svc encl. DONELSOIN C., ALLRED. D. L. Affiliation Unknown, 80/12/06. Spp. 07332:307.
- 80i22900ii Request for extension to file response to DL Alired contentions until 30 days after ASLB rules on Alired 80iii0 motion to withdraw from proceeding. Certificate of 8vc encl. COMAN. B. Z., KERRICK. J. R., MARCUCCI. D. R. Westinghouse Electric Corp. 80/12/09. 5pp. 07344:203.
- 8012300076 Provides corrected list of names of administrative judges belonging to ASLB having jurisdiction over Westinghouse application for SMM license. Order issued 801211 contained two erroneous names. WDLF, J.F. Atomic Safety and Licensing Board Panel. 80/12/15. ip. 07358:344.
- 8012310448 Second suppl to potition to intervene. Requests withdrawal of listed proposed contentions which overlap w/Safe Energy Alliance of Central AL contentions. W/Certificate of Svc. DOWELSON, C. Affiliation Unknown. 80/12/20. 12pp. 07308:001.
- 8012090283 Outlines acceptance criteria for facility licensing process WILLIAMS, L. O. Affiliation Unknown. 80/11/24. 2pp. 07187:001.

- DOCKET 70-2936 MISSISSIPPI POWER & LIGHT CO.
- B012020491 Forwards interim security plan for fuel storage.Plan withheld (ref 10CFR2:790). MCGAUGHY.J.P.. Mississippi Power & Light Co. B0/10/01. 3pp. 07148:124.
- B012050564 Forwards application for SNM license to permit receipt, possession, imsp & storage of SNM & associated radioactive matls incidental to operation of facility.

 DALE, L.F. Mississippi Power & Light Co. B0/10/01. 1p. 07174; 273.
- --8012050584 Application for SNn License to permit receipt, possession, inspiratorage & packaging for delivery of SNn & associated radioactive matis incidental to operation of facility. NELIA declarations & endorsements encl. MGGAUGHY, J.P. Mississippi Power & Light Co. 80/10/01, 37pp. 07174: 274.

DOCKET 70-2937 PENNBYLVANIA POWER & LIGHT CO.

BO12190028 Submits application for authorization to receive, possess, store, inspect & package for transport, nuclear fuel bundle/assembliss. Radiation protection officer resume encl. CURTIS.N. N. Pennsylvania Power & Light Co. 80/10/ió. 13pp. 07278:212.

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP.

- 8012240173 Forwards GA program approval for radioactive matl pactage. MACDONALD, C. E. Transportation Branch. 80/12/09. 1p. 07325:035.
- --8012240175 GA program approval for radioactive matl package: 0024, Ravision 2. MACDONALD, C. E. Transportation Branch. 80/12/09. ip. 07325: 036.

DOCKET 71-0035 ROCKWELL INTERNATIONAL

- 8012030124 Forwards revised GA program plan for shipping packages of radioactive matl in response to GE MacDonald 800827 ltr. Proprietary & legal notice on cover page has been deleted. MCDERMOTT, R. J. Rockwell International Corp., Energy Systems Div. 80/11/12. ip. 07174:345.
- --8012050133 Revised QA program for shipping packages of radioactive math. OLASS, D. N., MCDERMOTT, R. J., REMLEY, M. E. Rockwell International Corp., Energy Systems Div. 80/11/12. 3ipp. 07174:346.
- 8012310215 Forwards GA program approval for radioactive mail package. MACDONALD, C. E. Transportation Branch. 80/12/01. ip. 07369:284.
- --8012310218 QA program approval for radioactive mat1 package: 0035, Revision 0. HACDONALD, C.E. Transportation Branch. 80/12/01, ip. 07369:285.
- DOCKET 71-0102 SOURCE PROD. & EQUIP. CO., INC.
- B012300260 Forwards GA program approval for radioactive matl package. MACDDMALD, C. E. Transportation Branch. 80/12/18. 1p. 07358:152.
- --8012300262 QA program approval for radioactive mat1 package: 0102, Revision O. MACDUNALD, C. E. Transportation Branch. 80/12/18, 1p. 07358: 153.

DOCKET 71-0345 CAROLINA PONER & LIGHT CO.

B012120421 Requests revision of approved "Bummary of Applicability iOCPR71:App E" to extend to all shipping packages for which util may become user Forwards summary listing criteria & extent to which util shall apply GA program.

UTLEY,E.E. Carolina Power & Light Co. B0/fi/iO. 4pp. 07236:290.

DOCKET 71-0350 PICKER CORP.

8012140403 Authorizes NRC to terminate Picker Corp as owner of Certificates of Compliance 5796 & 9011 upon issuance of certificates to Advanced Medical Sys. Inc. Requests registration as user of new certificates.
PENODY.C.A. Picker Corp. 80/11/24. 1p. 07241:234.

DOCKET 71-0354 ADVANCED NUCLEAR SYSTEMS

- B01219060B Forwards proposed new QA program & revised organization charts. Teletherapy units w/Co-60 in source head will be mfg. KELBLEY, N. D. Advanced Medical Bystems, Inc. 80/11/21, ip. 07273:295.
- --8012190611 GA policy for compliance ω/100FR71, App E.
 KELBLEY, N. D., ARNDT, R. W. Advanced Medical Bystems, Inc. 79/11/07,
 9pp. 07273:296.
- 8012240168 Forwards GA program approval for radioactive mat1 pactage. MACDONALD.C.E. Transportation Branch. 80/12/09. ip. 07324:362.
- --8012240170 0A program approval for radioactive matl package: 0354, Revision 1. MACDONALD.C.E. Transportation Branch. 80/12/09. 1p. 07325: 001.

DOCKET 71-0395 NAVY, DEPT. DF, NAVAL FACILITIES ENO. COMMAND

- B0120B0B17 Ack receipt of B00919 ltr.Describes changes in QA program for radioisotope thermoelectric generators, Jul 1980. Revised description encl. BMITH.R.H. Navy.Dept. of. B0/10/17. ip. 07175:344.
- --8012080819 Revised description of GA program for radioisotope thermoelectric generators. 4 (Kavy, Dept. of. 80/10/31. 7pp. 07175:345.

BOCKET 71-0399 NORTH CAROLINA, STATE OF

- 8012010278 Forwards revised NC Dept of Transportation 0A program. WAGNER, F. T. North Carolina, State of, 80/10/28. ipp. 07098:020.
- --8012010302 Revised NC Dept of Transporation GA program. WAGNER, F. T., KENT, T. T. RUDISILL, O. D. North Carolina, State of. 80/10/28. 5pp. 07098:021.
- 8012080008 Forwards GA program approval for radioactive matl package. MACDONALD.C.E. Transportation Branch. 80/11/20, 1p. 07194:187.
- --8012080034 GA program approval for radioactive matl package:0379. Revision O. MACDONALD.C.E. Transportation Branch. 80/11/20. ip. 07194:i88.

DOCKET 71-0400 NAVY, DEPT. OF

- 8012110504 Forwards OA program description for review & comments. BMITH:R.H. Navy,Dept. of. 80/10/08, 1p. 07226:144.
- --8012110505 Forwards OA program outline for packaging of radioactive matl for transport & transportation of radioactive matl.
 RIEDER.A.E. Navy.Dept. of. 80/09/10. 6pp. 07226:145.
- --8012110508 GA program for packaging of radioactive matt for transport & transportation of radioactive ratt.

 * Navy.Dept. of, 80/09/10. 5pp. 07226:146.

DOCKET 71-0401 RELIANCE TESTING LABORATORIES, INC.

- 8012240161 Forwards QA program approval for radioactive mati package. MACDQNALD.C.E. Transportation Branch. 80/12/09. 1p. 07325:015.
- --8012240165 QA program approval for radioactive matt package:0401, Revision O. HACDDHALD, C. E. Transportation Branch. 80/12/09. 1p. 07325:016.

- DOCKET 71-5988 RODEL: D34710-1, U.S. NUCLEAR, INC.
- 8012010328 Approves request for registration as user of Model D34710 HACDONALD, C. E. Transportation Branch. 80/11/14. ip. 07092:033,
- DOCKET 71-5362 MODEL: GE 700. AGRICULTURE, DEPT. GF
- 8012050213 Application for Certificate of Compliance 5362; for US Arm Natic) Lab Research Irradiator package for transporting Group 3 matls: special form by motor transport; exclusive use vehicle. Supporting documentation encl.

 JARRETT.R.D. Agriculture, Dept. of. 80/10/17, 1p.
- ---8012050217 Safety evaluation supporting amend to License 10-01425
 Atomic Energy Commission. 70/11/02. ip. 06915:001.
- --8012050225 Advises that US Army Natick Lab Research Irradiator package meets 100FR71 requirements provided that apace between inner surface of overpack & irradiaton is blocked w/plywsod to prevent internal impacts during transport. NUSSBAUNER. D. A. Atomic Energy Commission. 70/11/02. 69pp. 06715:001.
- DOCKET 71-5344 HODEL: NP1-67-0442 NEUTRON PRODUCTS, INC.
- 601217063B Requests registration as user of Model NPI-67-0442. MOFFMAN, D. P. Consumers Power Co. BO/11/17. ip. 07269: 194.
- DOCKET 71-5450 MODEL: RCC-1, -2, -3, RESTINGHOUSE ELECTRIC CORP.
- 8012080768 Request for extension of expiration date of Certificate o Compliance 5450 to 810131. Criticality evaluation for package currently being revises for submission by end of Nov 1980. DIPIAZZAR. P. Westinghouse Electric Corp. 80/10/10, 1p.
- DOCKET 71-5768 MODEL: 88-250-2, COMBUSTION ENGINEERING CO., INC.
- 8012030858 Forwards revised pages to consolidated application for renewal of Certificate of Compliance 5788.

 AUSTIN.M.A. Babcock & Nilcox Co. 80/10/30, 1p. 07149:247.
- --B012030963 Revised pages to consolidated application for renewal o Certificate of Compliance 576B. + Babcock & Wilcox Co. B0/10/28. Spp. 07149:24B.
- B012020234 Forwards request for add1 info re 800926 request for rene of Certificate of Compliance 5768. MACDONALD.C.E. Transportation Branch. 80/11/18. 1p. 07133:141.
- DOCKET 71-5796 MODEL: 181361. PICKER CORPORATION
- B012110336 Application for renewal. w/minor changes, of Certificate of Compliance 3796. Application referenced to Picker Corp. which has sold therapy products to applicant. KEUBLEY. M. D. Advanced Medical Systems. Inc. B0/11/19. 17pp. 07247:347.
- --8012110358 "Evaluation of Overpack Containers 181361, 181375, E-162H-00-00004 to Compliance W/IAEA, 1973 Safety 8tds." Oversize drawings encl. KGO, Nr. F. Affiliation Unknown. 80/01/21. 47pp. 07248:002.
- --8012110371 Submits data re cesium source capsule in connection u/request to amend Certificate of Compliance 37% changing Ce-137 to normal form Supporting documentation encl. PENGOV.C.A. Picker Corp. 80/01/04. 85pp. 07248:089.
- 8012160603 Authorizes KRC to terminate Picker Corp as owner of Cartificates of Compliance 5796 & 9011.upon issuance of certificates to Advanced Medical Sgs.lnc.Requests registration as user of new certificates.
 PENGUV.C.A. Picter Corp. B0/11/24, jp. 07261:234.

- DOCKET 71-5908 MODEL. DOT-GM TYPE B, BABCOCK & WILCOX CO.
- 8012120352 Requests registration as user of Model DOT-GM, Type 3. KEENEY, N. P. Arganne National Laboratory. 80/11/11. 1p. 07236: 256.
- DOCKET 71-5957 MODEL. BMT-1, ENERGY, DEPT. OF
- 8012080526 Forwards Revision 7 to Certificate of Compliance 3957 for Model BHI-1. MACDONALD.C.E. Transportation Branch. 89/11/18. 2pp. 07196:098.
- --8017089431 Certificate of Compliance 5957, Revision 7, for Model BHI-1. MACDONALD.C. E Transportation Branch. 80/11/18. 6pp. 07196:100.
- DOCKET 71-6058 MODEL: 83-1, MUCLEAR ENGINEERING CO
- 8012010032 Approves request for registration as user of Models 8-3 & ORM, UNIR CONT. MACDONALD, C. E. Transportation Branch. 80/11/14. 1p. 07092;040.
- DOCKET 71-6144 MODEL: 6144, NUCLEAR ENGINEERING CO.
- B012120379 Requests registration as user of Model 6144. CHEATHAM.A.C. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B0/11/13 1p. 97234:279.
- DOCKE 1 71-6375 MODEL: PB-1. CHEM-NUCLEAR SYSTEMS, INC.
- B012230274 Forwards Revision 9 to Cartificate of Compliance 6375 for Model CNS 4-45. MACDONALD, C.E. Transportation Branch. B0/12/01. 3pp. 07317: 352.
- --B012230276 Certificate of Compliance 6375, Revision 9, for Model CNS 4-45. HACDDNALD, C.E. Transportation Branch. B0/12/01. 2pp. 07317:355.
- DOCKET 71-6400 HODEL: SUPER TIGER, WESTINGHOUSE ELECTRIC CORP.
- BO120500/9 Updates status of Model Super Tiger. Two shipping packages were inspected per Certificate of Compliance &400. Revision B. Findings encl. Repair & refurblishing of units will address five basic areas.
 BAER. T. S. US Ecology, Inc. (Formerly Nuclear Engineering) BO/10/14. 27pp. 07171:319.
- B012160595 Authorizes delivery to carrier for transport of large equipment waste that has been decontaminated & fixed in accordance w/vendor B01120 ltr.
 MACDONALD.C.E. Transportation Branch. B0/12/03, 2pp. 07261:230.
- DOCKET 71-6458 MODEL: BU-5. GENERAL ELECTRIC CO
- B01201019B Requests fee for B01106 request for amend to Certificate of Compliance 6458.per 10CFR170. WEIBS, D. License Fee Management Branch. 80/11/18. 1p. 07092: 135.
- 8012230P17 Forwards Revision 1 to Certificate of Compliance 6458 for Model 80-5. MACDONALD.C.E. Transportation Branch. 80/11/24. 2pp. 07317:057.
- --8012230221 Certificate of Compliance 6458.Revision 1 for Model BU-5. MACDGRALD.C.E. Transportation Branch. 80/11/24. 4pp. 07317:059.
- DOCKET 71-6574 MODEL: HN-200, HITTMAN NUCLEAR & DEVELOPHENT CORP.
- 8012010004 Requests registration as user of Model HN-200.Series 2. MIDURA.H. J. Public Service Electric & Gas Co. of New Jersey. 80/10/30. 1p. 07091:247.

- DOCKET 71-6581 MODEL: 51032-1 & 1A. EXXUN NUCLEAR CO., INC.
- 8012050093 Requests withdrawal of BN-NF-439, Revision 2, to GA program for shipping container. Revision does not contain reorganization changes announced on 801107.
 NILBON.R. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/11/10.
 1p. 07174:338.
- DOCKET 71-6601 MODEL: LL-50-100, CHEM-NUCLEAR SYSTEMS, INC.
- 8012220350 Forwards Revision 9 to Certificate of Compliance 6601 for Model CNS 8-120.

 MACDONALD, C. E. Transportation Branch. 80/12/09. 3pp. 07307:339.
- --B012220365 Certificate of Compliance 6601, Ravision 7 for Model CNS B-120. MACDQNALD, C. E. Transportation Branch. B0/12/09. 2pp. 07307: 342.
- DOCKET 71-6579 MODEL: 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO.
- 8012040975 Forwards "SAR for Packaging Half Super Tiger, TEB-PPD-3" re ranewal of Certificate of Compliance 6679. BAER, T.S. US Ecology, Inc. (Formerly Nuclear Engineering) 80/11/17. 1p. 07176:001.
- --8012040590 "SAR for Packaging Half Super Tiger, TES-PPD-3." Eight oversize drawings encl.

 * Teledyne Energy Systems. 80/05/01. 41pp. 07176:002.
- DOCKET 71-6698 MODEL: NF8-4, NUCLEAR FUEL BERVICES, INC.
- 8012050143 Requests registration as user of model NAC-1, Certificate of Compliance 6698, Revision 9.
 CGUMSIL, U. G. Connecticut Yankee Atomic Power Co. 80/11/05. ip. 07175:014.
- 8012240307 Application to amend Certificate of Compliance 6698 to provide for empty shipping of casks to facilities for purpose of indefinite storage or for performance of maint, decontamination.cask cavity measurements or other sycs.

 JDPMSON, C. R. Nuclear Assurance Corp. 80/11/05. 2pp. 07328:185.
- 8012010212 Requests add1 fee for 801105 request for amend to Certificate of Compliance 6698 per 100FR170.31. WEISS.D. License Fee Management Branch. 80/11/18. 1p. 07092:136.
- 8012110432 Requests add1 info for 800521 application requesting mod to Model NFS-4 packaging. Add1 info should be submitted as revised pages.
 MACDDNALD, C. E. Transportation Branch. 80/11/24. 5pp. 07225:162.
- 8012170171 Forwards Revision 14 to Certificate of Compliance 6698 for Madel (FS-4. MACDONALD, C. E. Transportation Branch. 80/12/02. 3pp. 07268; 180.
- --8012170178 Certificate of Compliance 4678 Revision 14 for Model NF8-4. MCDC:(ALD, C.E. Transportation Branch. 80/12/02. 7pp. 07268:183.
- DOCKET 71-6717 HODEL: 6717 B
- 8012010015 Forwards revised GA program to Dapt of Transportation originally submitted on 801002. W/o encl. WAGNER, F. T. North Carolina, State of, 80/10/28. 1p. 07096:354.
- DOCKET 71-6722 MODEL: 88-33-180, TENNESSEE VALLEY AUTHORITY
- 8012310430 Forwards Revision 4 to Certificate of Compliance 4722 for Model 88-33-180.
 MACDONALD.C.E. Transportation Branch. 80/11/24. 1p. 07370:211.
- --B012310437 Certificate of Compliance 6722, Revision 4, for Model 85-33-180. MACDONALD, C.E. Transportation Branch. 90/11/24. 3pp. 07370:212.

- DOCKET 71-6744 MODEL: POLY TIGER, NUCLEAR ENGINEERING CO.
- 8012010034 Advises that response to NRC questions re renewal of cartification for Model Poly Tiger will be sent pending resolution of questions re drawing configuration welds.

 OBMEYER, W. E Teledyne Energy Systems. 80/11/03. Ip. 07092:041.
- 8012230272 Forwards Revision 3 to Certificate of Compliance 6744 for Model 6744. MACDONALD.C.E. Transportation Branch. 80/11/28. 2pp. 07317:347.
- --8012239273 Certificate of Compliance 6744. Revision 3, for Model 6744. MACDONALD.C.E. Transportation Branch. 80/11/28. 3pp. 07317:349.
- DOCKET 71-9010 MODEL: NLT-1/2 HL INDUSTRIES, INC.
- B012010490 Requests registration as user of Model NLI-1/2. MIDURA.H. J. Public Service Electric & Gas Co. of New Jersey. B0/11/06. 1p. 07093:149.
- 8012140278 Ack receipt of 800727 application requesting amend to Certificate of Compliance 7010 to authorize use of alternate personnel barrier arrangement. Requests info on max temp permitted on accessible pactage surface during transport. MACDQNALD, C. E. Transportation Branch. 80/11/26. 1p. 07252:258.
- DOCKET 71-9011 MODEL: E-MEH-00-00004, TRANSPORTATION, DEPT. OF
- 8012110343 Application to renew Certificate of Compliance 9011.
 Application referenced to Picker Corp 730925 application. Hod
 is mecastary in package label due to company name change.
 Oversize drawings enci.
 KELBLEY.N.D. Advanced Medical Systems, Inc. 60/11/19. 26pp.
 07247:310.
- 8012160603 Authorizes NRC to terminate Picker Corp as owner of Certificates of Compliance 3776 & 7011, upon issuance of certificates to Advanced Medical Sys, Inc. Requests registration as user of new certificates.
 PENGDV, C. A. Picker Corp 80/11/24, ip. 07261:234.
- DOCKET 71-9015 MODEL: TN-8, TRANSNUCLEAR, INC.
- B011210177 Forwards "TN-B & TN-9 SAR for TN-BL Packaging." Requests issuance of certificate of compliance for Model TN-BL packaging. Addendum supports proposed TN-BL package design & contents. One oversize frawing encl.

 G0LD!14NNJ, K. Transnuclear, Inc. B0/10/31. 2pp. 07044:220.
- --8011210181 Revision O to "TN-8 & TN-9 SAR, Addendum for TN-8L Packaging." * Transnuclear, Inc. 80/10/31, 8pp. 07044:222,
- DOCKET 71-7036 MODEL: C-1. SOURCE PRODUCTION EQUIPMENT CO.
- 8012010015 Forwards revised QA program to Dept of Transportation originally submitted on 801002 W/o encl.
 WAGNER, F. T. North Carolina, State of. 80/10/28. ip. 07076:354.
- DOCKET 71-9070 MODEL: N-55, ENERGY, DEPT. OF
- 8012020072 Requests registration as user of Model N-35. HANGEN, L. E. Exxon Corp. 80/10/22. 1p. 07147:267.
- 8012170186 Forwards Revision 4 to Certificate of Compliance 9070 for Model N-55. MACDONALD, C. E. Transportation Branch. 80/12/05. 2pp, 07268: 190.
- --8012170191 Certificate of Compliance 9070, Revision 4, for Model N-35. MACCONALD.C.E. Transportation Branch. 80/12/05, 3pp. 07268:192.
- BOCKET 71-9073 KODEL: OH-142, NUCLEAR PACKAGING, INC.
- 8004100928 Forwards Revision 2 to Certificate of Compliance 9073 for Model OH-142 MACDOMALD, C. E. Transportation Branch. 80/03/28, 2pp. 04549:153,

- --B004100230 Certificate of Compliance 9073, Revision 2, for Model OH-MACDDHALD, C. E. Transportation Branch. 80/03/28, 4pp. 04549:1
- 8012010126 Informs that NRC has reviewed 800717,24 & 31 memos re fracture toughness, recommendations for developing reg guides & certification of shipping package. Info provided will be used in developing reg guide in transportation area. DAVIS, J. 6. Office of Nuclear Material Safety & Safeguards. 80/11/10. 2pp. 06916:001.
- --B012010133 Discusses RC Shieh differing prof oginion. Requests documentation be provided re cases & itr written to Shieh succentring actions taken. Lists six items to be included in itr.

 DAVIS. J. G. Diffice of Nuclear Material Safety & Safeguards. B9/10/21. 1p. 06914.001.
- ~-80f1050013 Discusses request to form peer review group to clarify issues re differing professionnal opinion to RC Shigh on Fracture toughness & puncture resistance requirements for shipping containers. Review group util not be formed.
 MINOQUER B. Defice of Standards Development, Director. 80/10/13pp. 06/9107001.
- --8012010137 Responds to 800924 memo re possible differing prof opini of RC Shieh Needs specific issues 2 pertinent details to determine if differing opinion exists Requested comments cannot be provided.

 MACDONALD.C.E. Transportation Branch. 80/10/03. 1p. 06716:001
- --8010280584 Discusses differing professional opinions of RC Bhieh & mgt re GE radwaste shipping package Model 589 & NUPACC Model OH-142 shipping package design.
 RANDALL,P.N. Structures & Components Standards Branch. 80/09/24
 2pp. 01736:001.
- --8G09180046 Requests concurrence w/analysis of what constitutes "differing prof opinion" of issues described in SECY 80-164. Reply requested by 800915. RANDALL,P.N. Structures & Components Standards Branch. 80/08/261p. 03560:005.
- --8012010146 Discusses development of reg guides in impact, puncture & fracture safe design & analysis of Type B container structures. Marked-up related documents encl.

 SHIEH. R. C. Affiliation Unknown 80/09/17. 18pp. 06916:001.
- --B012010152 Provides summary of initial structural review of cask da & subsequent reviews of TN-12 fracture-safe design analyses & proposals Transnuclear, Inc proposed scale model testing technique was not acceptable. 5MIEH.R.C. Transportation Branch. 80/08/01. 4pp. 06916:001.
- --B012010196 Discusses 781130 meeting to discuss existing brittle fracture stds & appropriateness to fuel cash design. ASME Nuclear Class 1 & Mc components requirements & Navy submarine hull requirements were considered.

 GUZY, D. J. Transportation Branch. 78/12/13. 3pp. 06916:001.
- --B012010163 Discusses 790110 meeting re brittle fracture criteria of TN-12 spent fuel casi currently under licensing review.Lists major criteria items taken from discussion.Forthcoming unitten version may differ.

 GUZY.D.J. Transportation Branch. 79/01/30. 16pp. 06916:001.
- --8012010169 Forwards safety evaluation of QE Model 589 package desig Applicant 800711 submittals & drawings re latest version of package design is acceptable. BHIEH.R.C. Transportation Branch. 50/07/17. 1p. 06916:001.
- --B012010173 Bafety evaluation supporting GS Model 589 package design Bupporting nati encl. # Transportation Branch. 60/07/17. 7pp. 04916:001.
- --8012010178 Discusses brittle fracture Model CH-142.Provides background info re authorization of matl change for applicant to use A-516 carbon steel in addl packagings. Addresses RC Schiek concern re packaging safety.

 ODEGAARDEN.R.H. Transportation Branch. 80/07/31. tp. 06716:00
- ---8012010188 Responds to 600822 memo to RC Shieh differing prof opin Procedures provided in SECY-80-164 give well planned & reviewed framework for evaluating concerns. J Thomas should serve only as technical resource person. DAVIS. J. G. Office of Nuclear Material Safety & Safeguards. 80/08/28. ip. 06/16:001.

- --8012010196 Discusses request for peer review of RC Shieh differing prof opinion. Discusses request to have CR Chappell made member of any group to review differing opinion. Interofc review group would be more appropriate. THOMAS.J. National Treasury Employee Union. 80/08/18. 1p. 04914:001.
- --8039180039 Notifies that review group is being established per SECY 80-164 policy t procedures to review RC Shieh views readequacy of radwaste containers Clarifications needed rewhat issues constitute "differing opinion." MIRROUE, R. B. Office of Standards Development, Director. 80/08/22, ip. 03560:006.
- --8012010205 Forwards RC Shieh R00717 & 31 memos re fracture toughness of GE radwaste shipping package Hodel 559 & licensing matter of NUPAC Model CH-142 shipping package design. Revision 10. Requests review group for differing prof opinion. DIRCKS-H. J. Office of the Executive Director for Operations. 80/08/08. 1p. 06916:001.
- --8012010208 Ack receipt of 800717.24 & 31 memos re fracture toughness of radwaste shipping package recommendations for developing certain reg guides & certification of shipping package. Three 800801 amos will not be reviewed.

 MACDDNALD.C.E. Transportation Branch. 80/08/08. 1p. 06916:001.
- --8012010223 Forwards RC Shieh 800717.24 & 31 memos re fracture toughness for shipping package design. Nemos will be forwarded via chain-ar-command.per revised policy & procedures for differing prof opinions contained in SECY-80-164.

 MACDQNALD, C.E. Transportation Branch. 80/08/07. 1p. 06916:001.
- --8012010228 Discusses fracture toughness of GE radwaste shipping package Model 989. Forwards memos from branch personnel shouling conflict in assessing fracture toughness. Main problem involves trunnion areas.

 SHIEM. R. C. Transportation Branch. 80/07/17. 5pp. 06916:001.
- --8012010234 Informs that design problems re trunnion areas submitted in NPDG-24613 on 800319 still pose potential safety problem for GE radvaste shipping package (fodel 589 review. Comments encl.

 SHIEM, R. C. Transportation Branch. 80/04/18. 3pp. 06916:001.
- --8012010242 Forwards RC Shieh 800418 structural review of GE radwaste shipping package Model 589. Disagrees w/Shieh re nonductile fracture failure Reasonable degree of judgement must be used in evaluating package designs. ODEOAARDEN.R.H. Transportation Branch. 80/04/21. ip. 06916:001.
- --8012010247 Discusses structural review of GE radwaste shipping package Model 539 MRC methods for determining mat1 acceptability do not need to be made more stringent. MACDCNALD, C. E. Transportation Granch. 80/04/22. ip. 06916:001.
- --8012010252 Discusses splash-down type secondary impacts of GE radwaste shipping package Model 589. Splash-down secondary impact at trunnion/top impact limiter area is apparently much more critical than puncture viewpoints.

 SHICH.R. C. Transportation Branch 80/04/28. 3pp. 06916:001.
- --B012010257 Discusses recommendation for developing reg guides for impact puncture & fracture-safe analysis/design of Type B shipping containers. Cevelopment of guides is long overdue & should begin as early at possible.

 SHIEH, R. C. Transportation Branch. 80/07/24, 10pp. 06916:001.
- --R012010260 "Evaluation in Structural Besign Methods for Large Guantity Parkages." HAYMIRE.G.R. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). R0/11/10. 17pp. 06916.001.
- --8012010262 "Emperical Equations for Puncture Analysis of Lead-Shielded Spent Fuel Shipping Casks." SHIEH.R.C. Transportation Branch. 80/11/10. 10pp. 06916:001.
- --8012010265 "Analytical Puncture Study of Circular Metal Plates." SHIEH.R.C. Transportation Branch. 80/11/10. 29pp. 06716:001.
- --8012010265 Discusses litensing of KUPAC Model CH-142 shipping packaging design, Revision 10. Adequacy of shipping container design or design revision should be evaluated against regulations contained in 100FR71.

 SHIEM.R. C. Transportation Branch. 80/07/31. 2pp. 06916:001.

- --8012010269 Forwards former Transportation Certification Branch member, RC Shieh 800731 memo for info & appropriate action re differing prof opinion. Impartial peer requested to review group to address technical substance of issues raised.

 DIRCKS.N. J. Office of the Executive Director for Operations. 80/08/05. 1p. 06916:001
- --8012010274 Forwards 800724 menn, "Recommendation for Developing Reg Outdos for Impact.Puncture & Fracture-Safe Analysis/ Design of Type B Shipping Containers." SHIEH.R.C. Transportation Branch. 80/07/31. ip. 06916:001.
- --B012010279 Discusses RC Shieh differing prof opinion re technical bases for cask review & designer guidelines. Manner in which concerns are handled may be more complex, since Shieh terminated employment w/NRC. Branch will follow NRC policy. DAVIB.J. G. Office of Nuclear Material Safety & Safeguards. B0/08/31. 1p. 06916:001.
- DOCKET 71-9079 MODEL: HN-100 SERIES 2, HITTMAN NUCLEAR & DEVELOPMENT
- 8012010008 Requests registration as user of Model HN-100, Beries 2, KIDURA, H. J. Public Service Electric & Gas Co. of New Jersey, 80/10/30. 1p. 07091:249.
- DOCKET 71-9080 MODEL: HN-600, HITIMAN NUCLEAR & DEVELOPMENT CORP.
- 8012010902 Requests registration as user of Model 9080/A, Beries 2, MIDURA, H. J. Public Service Electric & Cas Co. of New Jersey, 80/10/30, ip. 07091:246.
- 8012190033 Requests registration as user of Model 9080. IULLA-S. B Power Authority of the State of New York. 80/11/21. ip. 07278:225.
- DOCKET 71-9086 MODEL: HN-100 SERIES 1. HITTMAN NUCLEAR & DEVELOPMENT
- 8012010003 Requests registration as user of Model HN-Series 1. MIDURA.H.J. Public Service Electric & Gas Co. of New Jersey. 80/10/30. 1p. 07091:248.
- 8012110442 Requests addl info for B01007 application requesting revision of drawings for Model HN-100. Series 1. Addl info should be submitted as revised pages.

 MACQONALD. C. E. Transportation Branch. 80/11/24. 2pp. 07225:171.
- DOCKET 71-9089 KODEL: NH-100 S. HITTMAN NUCLEAR & DEVELOPMENT CORP.
- 8012010001 Requests registration as user of Model RN-1005, Beries 2. MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey. 80/10/30. 1p. 07091:245.
- DOCKET 71-9111 MODEL: CN6-80A, CHEM-NUCLEAR, INC.
- 8012240927 Application to registration as user of Shipping Cask Model CN8-6-80-2 under Cortificate of Compliance 9111. TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/24. ip. 07328:219.
- DOCKET 71-9120 MODEL: TN-12, TRANSNUCLEAR CORP.
- 8012010126 Informs that NRC has reviewed 800717,24 & 31 memos re fracture toughness, recommendations for developing reg guides & certification of shipping package. Into provided will be used in developing reg guide in transportation area. DAVIS, J. O. Office of Nuclear Material Safety & Safeguards. 80/11/10. 2pp. 06916:001.
- --8012010146 Discusses development of reg guides in impact, puncture & fracture safe design & analysis of Type D container structures. Marked-up related documents encl.

 5H16H, R. C. Affiliation Unknown. 80/09/17, 18pp. 04916:001.
- --8012010156 Discusses 781130 meeting to discuss existing brittle fracture stds & appropriateness to fuel cask design. ABME Nuclear Class 1 & Mc components requirements & Navy submarine hull requirements were considered.

 GUZY.D.J. Transportation Branch. 78/12/13. 3pp. 06916:001.

- --8012010163 Discusses 790110 maeting re brittle fracture criteria of TN-12 spent fuel cast currently under licensing review.Lists major criteria items taken from discussion.Forthcoming uritten version may differ.

 GUZY,D.J. Transportation Branch. 79/01/30. 16pp. 06916:001.
- DOCKET 71-9136 MODEL: GE 9136, GENERAL ELECTRIC CO.
- 8012160576 Authorizes delivery to carrier for transport up to 30 hoods & glove boxes containing solid radioactive mat! In accordance w/terms set in vendor 80033! Itr.as amended. MACDDNALD.C.E. Transportation Branch. 80/12/03. ip. 07261:232.
- DOCKET 71-9139 MODEL: GE-589, GENERAL ELECTRIC CO.
- 8012010126 Informs that NRC has reviewed 800717.24 & 31 memos refracture toughness recommendations for developing regguides & certification of shipping package. Info provided will be used in developing regguide in transportation area DAVIS.J.O. Office of Nuclear Material Safety & Bareguards. 80/11/10. 2pp. 06916:001.
- --8012010146 Discusses development of reg guides in impact, puncture & fracture safe design & analysis of Type B container structures. Marked-up related documents ancl.

 SHIEH, R. C. Affiliation Unknown. 80/09/17, 18pp. 06916:001.
- --B012010169 Forwards safety evaluation of GE Model 589 package design. Applicant 800711 submittals & drawings re latest version of package design is acceptable. SHIEH.R.C. Transportation Branch. B0/07/17. 1p. 06916:001.
- --8012010173 Safety evaluation supporting GE Model 587 package design.
 Supporting mati encl.
 4 Transportation Branch. 80/07/17. 7pp. 05916:001.
- --8012010205 Forwards RC Shieh 800717 & 31 memps re fracture toughness of 95 radwaste shipping package Model 587 & licensing matter of NUPAC Model OH-142 shipping package dosign Revision 10. Requests review group for differing prof opinion.
 DIRCKS.N. J. Office of the Executive Director for Operations, B0/08/09. 1p. 06916:001.
- ---B012010228 Discusses fracture toughness of GE radwaste shipping package Model 589. Forwards memos from branch personnel showing conflict in assessing fracture toughness. Main problem involves trunion areas.

 SHIFH.R.C. Transportation Branch. 80/07/17. Spp. 06916:001.
- --8012010234 Informs that design problems re trunnion areas submitted in NtDD-24613 on 800319 still pose potential safety problem for GE radwaste shipping package Model 589 review, Comments entl.

 SHIEM.R.C. Transportation Branch. 80/04/18. 3pp. 06916:001.

- --8012010242 Forwards RC Shieh 6:00418 structural review of OE radwaste shipping package Model 589. Disagress w/Shieh re nonductile fracture failure. Realsonable degree of judgement must be used in evaluating package designs.

 ODEWAARDEN.R. H. Transportation Branch. 80/04/21. 1p. 06916:001
- --8012010247 Discusses structural review of GE radwaste shipping packs Model 589, NRC methods for determining mat1 acceptability do not need to be made where stringent.

 MACOONALDrC.E. Transportation Branch. 80/04/22. Ip. 06916:001.
- --B012010252 Discusses splash-down type secondary impacts of OE radwas shipping package Model 587 Splash-down secondary impact at trunsion/Sop impact limiter area is apparently much more critical than puncture vieupoints.

 SHIEH.R.C. Transportation Branch, 80/04/28, 3pp. 06916:001.
- DOCKET 71-9141 MODEL: 900 TYPE S. TECHNICAL OPERATIONS, INC.
- 8012010013 Requests registration as user of Model 900. RICHARDSON.C.A. Factory Mutual System 89/10/30. tp. 07091:250.
- DOCKET 71-9144 MODEL SOC-1, CHEM. -NUCLEAR SYSTEM, INC.
- B012300257 Forwards request for add1 info to complete review of Model SOC-1. MACDDNALD.C.E. Transportation Branch. 80/12/18. 3pp. 07358:001.
- DUCKET 71-9145 MEDEL: NUPAC 50 NUCLEAR PACKADING, INC.
- 8012180405 Ack receipt of 800919 ltr & forwards info required for review & approval of Model NUPAC 50.
 MACDONALD, C. E. Transportation Branch. 80/12/03. 2pp. 03794:255.
- DOCKET 71-9147 MODEL: 850 TYPE B PACKAGING, TECH GPS, INC.
- B012100269 Requests issuance of certificate of compliance for Tech/Ops Hodel 850 Type B package.Forwards "Safety Analysis Rept.Tech/Ops Model 850 Type 2 Package."
 MUNRO-J.J. Tech/Ops (Yechnical Operations, Inc.). 80/10/30. 2pp.
- --8012109672 "Bafety Analysis Rept.Tech/Ops Model 830 Type 8 Pactage." * Tech/Ops (Technical Operations, Inc.). 80/10/30. 65pp. 07187:001.
- DOCKET 71-9853 HODEL. ORK. BIR. NEB UR FUEL CONTAINER, ENERGY.
- 8012010032 Approves request for registration as user of Models B-3 & ORN UNIR CONT.

 MACDONALD, C. E. Transportation Branch. 80/11/14. 19. 07092:040.



10CFR COMMISSION MEETING RECORDS

- 8011200263 SECY-80-325A
 Forwards, to Commission, info re inclusion of steam generator transients as unresolved safety issue.
 PIRCKS, N. J. Diffice of the Executive Director for Operations. 80/11/07. 1p. 03743:345.
- B0112B0106 Transcript of B01121 Affirmation Bession 80-51 in Washington, DC re discussion & vote on SECY 80-457. Pp 1-31. # Commissioners. 80/11/21. 3ipp. 07082:043.
- --8011280117 SECY-80-457
 Requests NRC approval of revised Manual Chapter 0103 re EDD delegations of authority, Chapter will be published upon receipt of revisions & approval.
 DIRCKS.W.J. Office of the Executive Director for Operations. 80/10/07. 27pp. 07082:077.
- --B011280112 SECY-80-476
 Informs that NRC has concluded & recommended that revisions should be made to 100FR73 amend & to draft Reg Guide SC 701-4.Forwards revised amends & submits guide changes. MtMOQUE.R.B. Office of Standards Development, Director. 80/10/20. 6Bpp. 07082:091.
- B012020196 Transcript of B01117 meeting in Hashington, DC for discussion & vote on BECY-80-486 re resolution of pat-down search issue at power reactors & status of related safeguards activities. Pp 1-28.

 # Gommissioners. B0/11/17. ZBpp. 07143:067.
- --8011140484 BECY-80-486
 Recommends approval of encl amends to 100FR73 re search procedures at reactor protected area entry portals.Draft FR notices encl.
 DAVIS.J.O. Diffice of Nuclear Katerial Safety & Bafeguards. 80/10/28. 22pp. 03732:183.
- B012070351 "Role of Aerosol Behavior in LWR-Core-Malt Accidents," presented at ANS/ENS Intl Conference on B01116-21 in Washington, DC. BUNZ, M., SHKKARSKI, M., SCHOCK, W. Oermany, Federal Republic of B0/11/21, 12pp. 07144:190.
- --8012020353 SECY-80-504
 Summarizes potential impact of hypotheses re iodine release during reactor accidents & proposes agenda for 801118 meeting.
 DENTON, N.R. Office of Nuclear Reactor Regulation, Director, 80/11/13. App. 07144:202.
- --8012020359 Summary of 801022 meeting in Bethesda. HD w/HR Stratton. A Malinaustas & DO Campbell re content & bases of 800814 ltr to NHC on iodine release during nuclear accidents. PASEDAG. M. Accident Evaluation Branch. 80/10/30. 4pp. 07144:211.
- --8012020365 Summarizes current & planned research programs re iodine species behavior under accident conditions. SHERRY, R. R. Division of Reactor Bafety Research, 80/09/12. App. 07144:215.
- --8012020375 Questions NRC decisionmaking process re thyroid protection policy. Offers possible systematic approach for new policy. VON HIPPEL,F. Princeton Univ. 80/11/18. 9pp. 07144:233.

- 8012040162 Forwards staff requirements memos for closed Commission meetings. Transcripts for all meetings have been released in entirety to PDR.
 8RCWM.J. Office of the Secretary of the Commission. 80/11/06. 1p. 07170:035.
- --8010230021 Staff requirements memo re Commission 800313 Affirmation Bession 80-10 re SECY-A-80-20, SECY-B0-093, SECY-A-80-5A, SECY-A-80-9 & SECY-A-80-21. Commission approved notice of hearing re 791206 order, CHILK, S. J. Office of the Secretary of the Commission, 80/03/17, 3pp. 03653:301.
- 8012040324 Transcript of B01121 public meeting in Washington, DC ra radiation effects & radiation research, Pp 1-70. * Commissioners. 80/11/21, 70pp. 07163:001.
- --8012040330 Expresses appreciation for agreement to participate in 801121 meeting re radiation health effects & radiation research.
 HINOUE, R. B. Office of Standards Development, Director. 80/11/07. 2pp. 07163:112.
- --B012040337 Confirms telcon re participation in B01121 meeting on radiation health effects & radiation research. Expresses interest on views in Encl 1 re risks from low level ionizing radiation. W/o encl.

 MINDGUE, R. B. Office of Standards Davelopment, Director. 80/11/07. 2pp. 07162:114.
- --8012040342 "A-Bomb Radiation & Bone Marrow Damage," basis of talk give at 801121 NRC brisfing session. BTEKART, A.M. Environmental Policy Institute. 80/11/21, 48pp. 07162:116.
- ---8012040348 "Hetrogensity of Cancer Bensitivity & Implications for Problem of Estimating Risks of Low Doses of Radiation: Comment on Paper by CE Land," KNEALE, O. Environmental Policy Institute. 80/11/21. 36pp. 07163:175.
- S012090009 Transcript of S01125 public meeting in Washington, DC rediscussion of SECY-S0-409 PRN to amend 100FRS0 concerning ATMS events. Pp 1-58, Viewgraphs encl.

 * Commissioners. 80/11/25. 68pp. 07197; 223.
- 8012090276 Transcript of 801126 Affirmation Session 80-51 in Washington. DC re 8ECY 80-489 & reappointment of DW Moeller to ACR8.pp 1-3.

 **Gozmissioners. 80/11/26. 6pp. 07202:347.
- 8012100640 Transcript of Commission 801126 public meeting in Washington, DC Te SECY-80-474/474A & 10CFR60 concerning licensing procedures for disposal of high level waste in gaologic repositories.

 Commissioners, 80/11/26, 86pp. 07217:104.
- 8012110473 Staff requirements memo re 801110 briefing on inclusion of generator transients as unresolved safety issue. Directs Ofc of Executive Director to resolve differences w/Ofc of Nuclear Reactor Regulation. CHILK.8. J. Office of the Secretary of the Commission. H801110, 80/11/21, 1p. 07227:134.
- 8012120365 Transcript of 801126 public meeting in Washington,DC re instructions to ASLB on facility proceeding.Pp 1-39, * Commissioners. 80/11/26. 39pp.
- --8012120373 SECY-A-80-1790
 Forwards draft order reflecting divergent positions on certain questions re principal facus of adjudication, BICKWIT, L. Commissioners, 80/11/26, 14pp.

- B0121606B0 Transcript of B01203 Affirmation Bession 80-52 ra 8ECY 80-465, BECY-80-481, BECY-80-482 & SECY-80-472A in Washington, DC. Pp 1-22. * Commissioners. B0/12/03, 22pp. 07254: 335.
- 8012170464 Transcript of 801203 briefing in Washington.DC re ice condenser & Mark III containments.Pp 1-64. * Commissioners. 80/12/03. 64pp. 07264:341.
- --B012170467 Forwards tables summarizing design pressure, estimated static pressure capacity, assumptions used for matl strength & other criteria for design of 33 ice condenser & Mark III DIRCKS, W. J. 0441 80/11/26, 11pp.
- B012190701 Forwards notice of minor amends re revised costs for reproduction of agency records to be published in B01023 FR. CHILK.S.J. Office of the Becretary of the Commission. 80/10/16. pp. 07273:282.
- --8012190703 Notice of minor amends re revised costs for reproduction of agency records.

 DIRCKS.H.J. Office of the Executive Director for Operations.
 B0/10/08. 3pp. 07273:283.
- B012220641 Transcript of 801211 public meeting in Oakland.CA re revised enforcement policy.Pp 1-140.Remarks by NRC officials & vieugraphs encl. 80/12/11. 180pp. 07295:051.
- 8012220646 Transcript of 801201 public meeting in Atlanta. 9A re revised enforcement policy. Pp 1-172, Viewgraphs encl. * Commissioners. 80/12/01. 187pp. 07294: 225.
- 8012220709 Transcripts of 801209 afternoon & evening public meeting in Irving:TX re revised enforcement policy.Pp 1-118 & 1-18, respectively.Summary of comments on NRC proposed general palicy & procedure for enforcement action encl. e Commissioners. 80/12/09. 162pp. 07293:300.
- 8012220721 Transcript of 801204 public meeting in Philadelphia,PA re App C to 10CFR2, proposed general statement of policy & procedure for enforcement actions.Pg 1~193, Commissioners. 80/12/04. 197pp. 07298:212.
- 8012220725 Transcript of 801202 public meeting in Rosemont.IL re revised enforcement policy.Pp i-163. * Commissioners, 80/12/02, 165pp. 07293:137.
- B012240133 Staff requirements memo re 801126 Affirmation Session 80~51. Reappointment of DH Moeller to ACRS 4-yr term & change in titles for ASLS & ASLS members approved. CHILK.8.J. Office of the Secretary of the Commission. M8011268. B0/12/02. 1p. 07324:353.
- B012270009 SECY-80-384
 Recommends approval of FR natice to respond to DDE request for rulemaking to exempt from licensing requirements smelted alloys containing Tc-99 & low enriched U as residual contamination.

 MINOGUE, R.B. Office of Standards Development, Director. 80/08/15. MINOGUE, R. B. OF 8pp. 07330: 240.
- 8012290476 Transcript of 801211 meeting in Washington.DC re 8ECY-80-4740.Pg 1-32. + Commissioners. 80/12/11. 34pp. 07335:066.
- --8012290479 Discusses legal issues re proposal to approve publication of 1007R60 final rule re disposal of high level radwaste in geologic repositories. BICKNIT-L. Office of the General Counsel, 80/12/10, 3pp, 07335:101.
- --8012290483 SECY-80-474C
 Suppls SECY-80-474 & forwards clarifying changes to 10CFR60 final rule & conforming amends.
 DIRCKS M. J. Office of the Executive Director for Operations.
 80/12/09. 16pp. 07335:104.
- --8012290485 Forwards NRC recommended changes to final rule 10CFR60. DIRCK8.W.J. Office of the Executive Director for Operations. 80/12/11. 7pp. 07335:120.
- 8012290493 Transcript of 801215 public meeting in Washington.DC re ASLB instructions.Pp 1-54.

 * Commissioners. 80/12/15. 55pp. 07335:219.

- BO12300672 Staff requirements memo re Commission B01126 meeting on SECY-B0-474/474A. Requests staff actions re disposal of high level radwaste in geologic repositories. CHILR, B. J. Office of the Secretary of the Commission. MB01126A. B0/12/10. 1p. 07359: 269.
- BO12300693 Staff requirements memo re Commission B01125 meeting on BECY-B0-409 on petition for rulemaking re anticipated transients w/o scram.
 CHILN.8. J. Office of the Becratary of the Commission. MB01125. B0/12/09. 2pp. 07359: 290.
- 8012300698 Btaff requirements memo re Commission 801205 meeting on SECY-A-80-186. Approved mamp & order denying Duke Power Commution for reconsideration of emergency planning. CHILK, S. J. Office of the Secretary of the Commission. M801205, 80/12/11. 1p. 07359: 296.
- 8012300703 Staff requirements memo re Commission Affirmation Bession BD-53 on 801205. Approved memo & order denying Duke Power Comotion for reconsideration of emergency planning. CHILK, S. J. Office of the Secretary of the Commission. 80/12/08. 1p. 07359:297.
- ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
- 8010160576 Summarizes 246th ACRS meeting on 801009-11 re SECY-80-438A, proposed rule on fire protection. Extremely prescriptive requirement of Branch Technical Position 9.5-1 does not provide best means to assure safety.

 PLESSET.M.S. ACRS Advisory Committee on Reactor Safeguards.
 80/10/14. 2pp. 06727:132.
- 8011190374 Recommends add1 research before commitment to specific sys re nuclear data link. Bys interface w/reactor instrumentation may decrease reliability, as evidence that reactor sys is not adversely affected has not been clearly demonstrated. PLESSET, M.S. ACRS Advisory Committee on Reactor Safeguards, 80/11/12. 1p. 06979: 355.
- BO12010499 Apps to summary of 241st ACRB meeting on 800501-03.

 * ACRB Advisory Committee on Reactor Safeguards. B0/05/03.
 600pp. 07095:151.
- 8012010504 Apps to summary of 237th ACRS meeting on 800306-08. * ACRS Advisory Committee on Reactor Bafeguards. 80/03/6 575pp. 07090:001. BO/03/08.
- 8012010397 Summary of Advanced Reactor Subcommittee 800707 meeting in Washington, DC re NRC sponsored research on advanced reactors at AIL & BNL & aerosol release & transport work at DRNL & BINL. # ACRS Advisory Committee on Reactor Sefeguards. 80/09/22. 8pp. 07095:046.
- 8012020037 Bunmary of Subcommittee on Class 9 Accidents 800828 meeting in Washington, DC re role of Class 9 accidents in licensing process.

 ACRS Advisory Committee on Reactor Safeguards, 80/09/30, 4pp. Q7147:185.
- 8012020065 Summery of Subcommittee on Reliability & Probabilistic
 Assessment 800701 meeting in Inglewood.CA re-development of
 quantitative safety goals for nuclear plants.

 * ACRS Advisory Committee on Reactor Safeguards. 80/09/17, 7pp.
 07147:230.
- 8012020072 Summary of Reactor Fuel Subcommittee 800821 meeting w/EQ&O in Idaho Falls, ID re Fuel Behavior Research Branch in-pile test programs.

 **ACR8 Advisory Committee on Reactor Safeguerds. 80/10/10. 7pp.
- 8012020076 Summary of Bubcommittee on Reactor Fuel 800903 meeting w/ Hestinghouse in Washington.DC re NUREO-0630 review. # ACRB Advisory Committee on Reactor Safeguards. 80/10/08. 4pp. 07147: 252.
- 8012020982 Summary of Advanced Reactor Subcommittee 800630 meeting at Bandia & Los Alamos Labs re ANL experiments accident energetics & core debris behavior.

 # ACRB Advisory Cummittee on Reactor Safeguards. 80/09/30. 11pp. 07147:254.
- 8012020107 Transcript of 24ist general meeting on B00501 re extended operation of shipping port LHR core in Washington, DC. Pp i-256. Viewgraphs encl. * ACRS Advisory Committee on Reactor Bafeguards, B0/05/01, 256pp. 06916:001.

- B012020811 "Evaluation of Davis-Besse & Rancho Seco Feedwater Transients on 770924 & 760320 Using WASH-1400 Data." * Commissioners. 80/02/20. 16pp.
- 8012040650 Commends NRC for assembling Reg Quide 1,97 discussed at 800806 meeting in Washington, DC. Coverage of parameters to be monitored is too comprehensive. Requests specific attention to primary coolant inventory.

 ZUDANS, Z. Franklin Institute/Franklin Research Center. 80/09/23.

 Zac. 07165:359
- B012040655 Comments on matl assembled for Subcommittee on Class ?
 Accidents consideration at 800828 meeting Questions in
 Oilinsky 800807 ltr & opening remarks re hydrogen
 released in accident sequence are ill-perceived.
 SCHOTT.O.L. Los Alamos Scientific Laboratory, 0-7. 80/09/16. 6pp.
 07166:326,
- 8012040662 Informs that during 801009-11 meeting proposed rule on fire protection submitted to Committee w/SECY-80-438A was considered Does not recommend issuance of rule but requests examination of revisions.

 PLESSET, M.S. ACRS Advisory Committee on Reactor Safeguards.
 80/10/14, 2pp. 07166:349.
- 8012040665 Recommends that necessary manpower be committed to short-term review of seismic qualification of auxiliary feedwater sys. Affected licensees should perform independent review.

 PLEGRET, M. S. ACRS Advisory Committee on Reactor Gafeguards. 80/10/15, 2pp. 07166:356.
- 8012080191 Informs of review of MS Plesset 800730 memo. Hydraulically induced vibrations can be caused by pump operation at flow rates less than normal due to details of pump internal design & inlet plying.

 ACOSTA, A. J. ACRS Advisory Committee on Reactor Safeguards, 80/09/24. 1p. 07181:216.
- 8012080202 Informs that no technical reason should prevent disposal of spent fuels in geologic repositories. Spent fuel should be reprocessed for use in LMFBR. U reserve supplies not unlinited.

 CROMER. 8. ACRS Advisory Committee on Reactor Safeguards.
 80/10/02. 2pp. 07187:001.
- 8012080411 Comments on preliminary plans for addressing Section 1i0 of NRC FY80 authorization bili, as result of 244th meeting on 801009-11.
 FRALEY,R.F. ACR8 Advisory Committee on Reactor Safeguards. 90/10/14. ip. 07186:313.
- B012090091 Transcript of ACRS Subcommittee on Reactor Operations 801202 meeting in Washington.DC.Pp 1-59.

 * ACRS Advisory Committee on Reactor Safeguards. B0/12/02. 59pp. 07198:219.
- 8012090074 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment 801203 meeting in Washington, DC. Pp 1-42.

 **ACRS ~ Advisory Committee on Reactor Safeguards. 80/12/03. 42pp. 07198:285.
- 8012100193 Ack receipt of 801015 ltr providing observations & recommendations re-scismic qualification of auxiliary feedwater sys.Recommendations incorporated into scope of review program. Forwards 801021 ltr to licensees. M/o encl. DIRCKS, M. J. Office of the Executive Director for Operations. 80/11/21. 1p. 07218:249.
- 8012120284 Transcript of ACRS Bubcommittee on NRC Bafety Research Program 801203 meeting in Hashington, DC. Pp 1-206. Viewgraphs encl. * ACRS - Advisory Committee on Reactor Safeguards. 80/12/03. 280pp. 07231:005.
- 8012160365 Classifies systematically initiating events responsible for fluid vol changes in primary sys of PKRs.w/special applicability to NUREO-0467. "Transient Response of BAM-Designed Reactors."
 ETHERINOTON,H. ACRB Advisory Committee on Reactor Bafeguards. 80/05/01. 5pp. 07261:225.
- 8012140405 Forwards J Ebersole & I Catton comments re presentations at ACRS B&W Hater Reactors Subcommittee 800108 meeting on once-through steam generator sensitivity.

 MULLER: R. ACRS Advisory Committee on Reactor Safeguards.

 80/02/13 1p. 07261:235.

- --8012160608 Comments on ACRS meeting on once-through steam generator sensitivity. No criteria exist for upgrading secondary sys to reduce sensitivity to transients.
 EDERSOLE, J. ACRS Advisory Committee on Reactor Safeguards.
 80/07/13. 1p. 07261:236.
- --8012160616 Comments on ACRS meeting on once-through steam generator sensitivity. Handling of auxiliary feedwater is inadequate when inlet is above water level. CATTOMI.I. ACRS - Advisory Committee on Reactor Bafeguards. 80/02/13. 1p. 07261:237.
- 8012180235 Transcript of ACRS Subcommittee on Reactor Rediological Effects 801212 meeting in Washington, DC. Pp 1-212. Supporting documentation encl. ACRS Advisory Committee on Reactor Safeguards. 80/12/12. 375pp. 03792:034.
- 8012180238 Transcript of ACRS Subcommittee on Reactor Radiological Effects & Site Evaluation 801211 meeting in Washington, BC. Pp 1-203. Viewgraphs encl. * ACRS Advisory Committee on Reactor Safeguerds. 80/12/11. 240pp. 03793:040.
- 8012180239 Transcript of B01213 joint meeting of AGRS Subcommittee on Reactor Radiological Effects & Subcommittee on Bite Evaluation in Washington.DC.Pp 213-271.Viewgraphs encl. * AGRS Advisory Committee on Reactor Bafeguards. 80/12/13, 75pp. 03793.281.
- 8012190388 Suggests design concept oriented program w/DOE, in response to 800911 memo requesting advice re-potential safety improvements which could be incorporated into any new design for nuclear power plants.

 PLESSET, M. S. ACRS Advisory Committee on Reactor Bafeguards. 80/12/09. 2pp. 07282:140.
- 8012190533 Discusses 800109 request for ACRS participation in proposed rulemaking to reassess Commission confidence in safe disposal of radwastes is reasonably assured u/present state of knowledge.

 PLESSET.M.S. ACRS Advisory Committee on Reactor Safeguards.
 80/12/10. 6pp 07274:005.
- 8012240305 Transcript of Subcommittee on Combination of Dynamic Loads 801217 meeting in Washington, DC. Pp. 326-534, Viewpraphs encl. * ACRB Advisory Committee on Reactor Safeguards. 80/12/17, 290p. 07326; 318.
- 8012290372 Transcript of Subcommittee on Combination of Dynamic Loads 801216 meeting in Mashington.DC.Pp 1-328.Viewgraphs encl. * ACR8 Advisory Committee on Reactor Safeguards. 80/12/16. 435pp. 07341:229.
- B012300751 Submits comments on proposed waste confidence rulemaking. including institutional issues, societal issues & scientific/technical issues. PARKER, H. M. Affiliation Unknown. 80/11/20. 6pp. 07363:004.
- 8012300755 Forwards memo on disposal of high level waste in geologic repositories. CRDMER.S. ACRS — Advisory Committee on Reactor Safeguards. 80/11/20. 1p.
- --8012300758 Submits assurance that high level nuclear waste, including spent fuel.can be safely disposed of in geologic repositories.

 CROMER.S. ACRS -- Advisory Committee on Reactor Bafeguards.

 B0/11/20. 4pp. 03775:001.

COMMISSION NRC COMMISSIONERS

- 8012010527 Ack receipt of 800930 ltr describing NRC arrangement for naming Commissioner to serve as alternate representative on US delegation to each IAEA conference. Arrangement satisfactory & should avoid any future misunderstandings, AHEARNE, J. F. Commissioners. 80/11/04. 1p. 07098:228.
- --8012010531 Informs that NRC will be contacted by 810701, requesting nomination of Commissioner to serve, subj to requirements of IAEA Participation Act, as alternate on UB delegation to 25th Session of general conference.

 NEWLIN.M.H. State, Dept. of, 80/09/30, ip. 07098: 229.
- 8012020711 Weekly info rept for wk ending 801114, REMM.T.A. Office of the Executive Director for Operations, 80/11/20. 3ipp. 06916:001.

- B012030792 Forwards info re use of radioactive matl under AEC/NRC license in ocean. Three uses summarized in encl. RE Cunningham B01007 statement accurately reflects NRC understanding re disposal of high level waste in ocean. W/o encl. AHEARNE, J. F. Gommissioners. 80/11/04. 1p. 07149:271.
- --8012030797 Forwards info re use of radioactive matl under AEC/NRC license in ocean. Three uses summarized in encl. RE Cunningham 801007 statement accurately reflects NRC understanding re disposal of high level waste in ocean. W/o encl. AHEARNE, J.F. Commissioners. 80/11/04. 1p. 07149:272.
- --B012030801 Forwards info re use of radioactive math under AEC/NRC license in orean. Three uses summarized in encl. RE Cunningham 801007 statement accurately reflects NRC understanding redisposal of high level waste in ocean. N/v encl. AMEARNE, J.F. Commissioners. 80/11/04. ip. 07149:273.
- --8012030803 Forwards info re use of radioactive matt under AEC/NRC license in ocean. Three uses summarized in encl. RE Cunningham B01007 statement accurately reflects NRC understanding re disposal of high level waste in ocean. W/o encl. AHEARNE, J. F. Commissioners. 80/11/04. 1p. 07149:274.
- --8012030808 Forwards info re use of radioactive matt under AEC/NRC license in ocean. Three uses summarized in encl.RE Cunningham B01007 statement accurately reflects NRC understanding re disposal of high level waste in ocean. W/o ancl. AHEARNE, J. F. Commissioners. 80/11/04. 3pp. 07149: 275.
- 8012090264 Informs that nuclear power plant standardization rept appears to biased by placing blame for slow plant standardization on NRC Effects of safety not truly assessed in table of issues.

 HENDRIE: J. M. Commissioners. 60/11/21. 2pp. 07202:334.
- --B012090264 Forwards draft "Nucleor Power Plant Standardization." Final rept will incorporate NRC comments on draft & set of issues & findings.W/o encl. ABBOTT.E. House of Rep. B0/11/05. 3pp. 07202:336.
- 8012090270 Requests greater moderation in rapid development of nuclear power in Taiwan. Protests statements re obligations to nuclear safety.

 JUN-YI.L. Affiliation Uninown. 80/10/31. 4pp. 07187:001.
- 8012090406 Responds to 601010 itr re possible alternate technologies for interim storage of spent tyel. Dry storage would be subj to NRC licensing, Forwards NURC9-0575, Vols 1-3, NURC9/CR-1223 & final rule 10CFR72. W/O NURC9.

 AHEARNE, J. F. Commissioners. 80/11/18. 7pp. 07200:010.
- --8012090413 Requests info re NRC role in licensing of alternative commercial spent fuel storage facilities & status of NRC consideration given to dry spent fuel storage. CORCORAN.T. House of Rep. 80/10/10. 1p. 07200:016.
- --8012090422 Final rule 10CFR72. "Licensing Requirements for Storage of Spent Fuel in Independent Spent Fuel Storage Installation." Rule covers specific licensing requirements for independent spent fuel storage. CKILK:S.J. Office of the Secretary of the Commission. 80/11/03.84pp. 07200:017.
- 8012100196 Weekly info rept for Wk erding 801121. REHM:T.A. Office of the Executive Director for Operations. 80/11/26. 28pp. 07218:232.
- 8012110036 Responds to 801003 itr re NRC review of emergency procedures at operating reactors as part of consideration of ATMS problem. IE Bulletin 80-17 required BMR licensees to review emergency procedures re operator shutdown actions.

 AHEARKE, J. F. Commissioners. IEB-80-17. 80/11/24. 2pp. 03772:020.
- --8012110043 Requests info me review of emergency procedures for operator action during NRC consideration of ATMS problem.
 UDALL-M.K. House of Rep. 80/10/03. 1p. 03772:022,
- 8012110148 Notifies that members of transition team have been given ofc space to prepare biweekly rept on transition activities as requested in 801110 memo.

 AHEARNES.J.F. Commissioners. 80/11/20. 4pp. 07225:145.
- B012110150 Responds to 800730 suggestion that Commission reconsider or clarify 800619 "Statement of Policy:Further Commission Guidance for Power Reactor GLs." Forwards 801103 denial of UCS & Shoreham Opponents Coalition request for stay.

 AHEARNE, J. F. Commissioners. 80/11/19. 1p. 07223:349.

- --8012110161 Order denying UCS & Shoreham Opponents Coalition request for stay of Commission "Statement of Policy:Further Commission Outdance for Power OLs." Separate Commissioner views encl. CHILK.B J. Office of the Secretary of the Commission. 80/11/03. 15pp. 07223:350.
- --B012110167 Requests that policy statement re further Commission guidance for power reactor OLs be reconsidered based on Bubcommittee inquiry & facts elicited at 800702 hearing. MOFFETT. House of Rep., Government Operations. B0/07/30, 4pp, 02724:003
- 8012110318 Ack receipt of 801114 ltr re visit to Cumberland School of Law & univ. Staff guidance documents, including reg guides & SRPs, are more detailed than regulations & have strong influence on licensee actions, but do not have force of law. HENDRIE, J. M. Commissioners. 80/11/20. 1p. 07225:280.
- --B012110328 Requests NRC comments on remarks made at B01113 visit to Cumberland School of Law re staff guidance documents & CFR regulations. Also requests permission to observe administrative adjudicatory process in action at agency, MANNINO.R.K. Samford Univ., Cumberland School of Law. B0/11/14, 19. 07225:281.
- 8012190123 Weekly info rept for wk ending 801205. REFM.T.A. Office of the Executive Director for Operations. 80/12/11. 44pp. 07281:340.
- 8012220017 Forwards OAD 801203 ltr to Congress stating that use of funds appropriated by 1981 Energy & Water Development Appropriation Act to implement NRC procedural cost reduction program is unlawful. STAATS.E.B. General Accounting Office. B-200585. 80/12/03. 5pp. 07303:267.
- 8012230211 Responds to 801028 itr requesting help in development of info package & other matl for use by state & local emergency preparedness officers in event of incident at nuclear power plant, Info will be provided.

 A
- --B012230214 Informs of contract award to N Low & Associates, Inc to develop public education info programs re response to any possible incident at nuclear generating station. Requests NRC cooperation in course of project. MACY.J. H. Federal Emergency Management Agency. B0/10/28. ip-07317:054.
- B012240004 Forwards 1977 & 1978 briefing books for Commissioners. FITZGERALD.J.A. Office of the General Counsel. B0/12/10. Ip. 07107:001.
- --8012240012 "UB NRC Briefing Book.Vol 1:NRC General.Natl Energy Outlook. Reactor Licensing Process.Reactor Bafety.Pu Recycle." * Office of Policy Evaluations. 77/07/31. 43pp. 07187:001.
- ---8012240015 NEO-77
 Draft "1977 Natl Energy Outlook, Executive Summary."
 * Federal Energy Administration. 77/01/15. 31pp. 07187:001.
- --8012240020 "Natl Energy Plan." CARTER.J.E. President of US & Executive Offices. 77/04/29. 57pp. 07187:001.
- --8012240023 "NRC General Statement of Policy on Standardization of Nuclear Power Plants." CHILK, S.J. Office of the Secretary of the Commission. 77/06/29. 66pp. 07187:001.
- ---B012240025 NUREO-0002 EB
 "Final Generic Environ Statement on Use of Recycle Pu in
 Hirad Oxide Fuel in LWRs."
 * Office of Nuclear Material Safety & Safeguards. 76/08/31.
 43pp. 07187:001.
- --Bol2240028 "US NRC Briefing Book.Vol 2: Domestic Safeguards; Intl Waste Mgt.NRC/Btate Relations.Legislative/Congressional Current Issues."

 * Office of Policy Evaluations. 77/07/31. 86pp. 07187:001.
- --B012240031 NUREQ-0217

 "NRC Task Force Rept on Review of Federal/State Program for Regulation of Commercial Low Level Radwaste Burial Grounds."

 Office of Nuclear Material Safety & Bafaguards. # Office of State Programs, Director. 77/03/31. 26pp. 07187:001.

- --B012240034 Discusses ACRB meetings re long-term high level radwaste mgt. ACRB recognizes importance of improving mgt & procedural aspects:minimizing jurisdictional disputes & clarifying timetables for decisions, ropts & research & development. MDELLER, D. W. ACRB - Advisory Committee on Reactor Safeguards. 76/12/20, 87pp. 07187:001.
- --8012240037 Informs of NRC lagislative proposals re civil penalties, protection of licensee personnel, examption of safeguards info from FOIA: amending NRC quorum requirement & upgrading Director of Ofc of IE. STRAUSS, P.L. Office of the General Counsel, 77/06/01, 53pp. 07187:001.
- --B012240039 Submits status rept for Apr & May 1977 re pending litigation. EILPERIN.B.F. Office of the General Counsel. 77/05/31. 42pp. 071B7:001.
- --8012240036 "UB NRC Briefing Book. Vol 1 NRC General, Nuclear Economics/ Environ Effects, Licensing Process, Reactor Bafety, Domestic Bafeguards," * Office of Policy Evaluations, 78/05/26, 82pp. 07:87:001.
- --B012240068 "US NRC Brisfing Book, Vol 2: Intl Wasta Hgt, NRC/State Relations, Legislative/Congressional Current Issues, " # Office of Policy Evaluations. 78/05/26. 24pp. 07187:001.
- --8012240074 Forwards NRC legislative proposal in form of draft bill to amend Atomic Energy Act of 1934.as amended to provide for protection from unauthorized disclosurs of safeguards info & for other purposes.

 HENORIE, J. M. Commissioners. 78/05/23. 4pp. 07187:001.
- --8012240075 Recommends amending Atomic Energy Act of 1954, as amended, to increase panalty limits NRC may levy on violators.

 HENDRIE, J. M. Commissioners. 78/05/11. 21pp. 07187:001.
- --8019240078 Submits status rept for Apr 1978 rs pending litigation. ELLPERIN.S F. Office of the General Counsel. 78/04/03 68pp. 07187:001.
- --8019240081 Requests amplification of policy statement in BECY-78-163 to provide guidance on site consideration. CHILK:S.J. Defice of the Secretary of the Commission. 78/0B/15. 2pp. 07187:001.
- --8012240085 Requests groundrules to narrow listed gaps which pose difficult policy formulation problems. Recommends amplifying draft policy statement in SECY-78-163 which would then be considered for issuance as proposed rule.

 PEDERSEN.K. Commissioners. 78/07/11. 2pp. 07187:001.
- --8012240095 Expresses concern re implications in continuing const of nuclear power plants while challenges to CPs are under adjudication.
 CHILKIS.J. Office of the Secretary of the Commission. 78/04/05. 53pp. 07187:001.
- --8012240098 95-848
 "Rept of Committee on Environ & Public Works: US Benate to Accompany 8, 2584."
 RANDDLPH.J. MUSKIE, E. S., STAFFORD, R. T. Senate, Environment & Public Works, 78/05/15, 39pp. 07187: 001.
- 8012290030 Submits daily notes for 801210. Status of facilities in five IE regions encl. DIRCKS, M. J. Office of the Executive Director for Operations. 80/12/11. 3pp. 07308:001.
- 8012270034 Bubmits Status Rept 4 for Commission Papers from 1980. * Commissioners. 80/12/13. 35pp. 07330:277.
- 6012270037 Forwards fourth rept of ACRS membership data, including names of committees, memberships, terms of appointments & anticipated appointments through \$10121.

 HOYLE, J.C. Office of the Secretary of the Commission. 80/12/12.

 Bpp. 07338: 232.
- 8012290043 Submits daily notes for 801211. Status of facilities in five IE regions encl.
 DIRCKS, H.J. Office of the Executive Director for Operations,
 80/12/12. 4pp. 07308:001.

- B012290062 Forwards info re siting & licensing legislation in response to request.

 FITZOERALD, J. A. Office of the General Counsel. B0/12/12. ip. 07340:324.
- --8012270065 Submits comments & suggested revisions of DOE 771014 draft nuclear siting & licensing legislation in response to request. Revisions are also reflected on encl marked-up bill. HENDRIE, J. H. Commissioners. 77/10/26. 71pp. 07340:325.
- --8012270069 Forwards comparison of DOE 780317 nuclear licensing reform bill & 780104 draft. Bill presents many problems. State decision on soviron impact issue will be binding on NRC. SHAPAR, H.K. Office of the Executive Legal Director. 78/03/20. 31pp. 07340:326.
- --8012270073 Comments on DDE 780317 suclear licensing reform bill in response to request Ofc is in general agreement w/Ofc of Executive Legal Director analyses & adds add1 observations. KELEY, J. L. Office of the General Counsel. 78/03/22. 3pp. 07341:021.
- --8012270076 Forwards draft memorandum describing NRC approach for determining eligibility of intervenors for funding, in response to request. STOTUBERIC.R. Office of the General Counsel. 78/07/19. 4pp. 07341:024.
- --8012270081 Summary of 781218 meeting w/representatives of Congressman Dingell to discuss NRC efforts re siting & licensing legislation.
 STOIBER.C.R. Office of the General Counsel. 78/12/20. 3pp. 07341:028.
- --BOIR290085 Forwards preliminary discussion of major issues in siting & licensing legislation in response to 791006 request. BTOIBER.C.R. Office of the General Counsel. 79/01/05. 85pp. 07441:031.
- --8012290088 Provides industry's perspective on proposed legislation to reform licensing of nuclear power plants. Licensing reform is integral part of acceptance of nuclear power by public, BRAY.A.P. General Electric Co. 79/03/15. 3pp. 07341:137.
- 8012270403 Forwards list of documents provided transition team, list of personnel associated w/transition team & Commission instructions re info to be provided to team.
 AHEARNE, J. F. Commissioners. 80/12/04, 10pp. 07345:335.
- --B012290405 Informs that transition team should be provided w/info in same manner as Executive Branch.
 AHEARNE, J. F. Commissioners. 80/11/26, 2pp. 07345:345.
- --8012270408 Informs that EDO should provide President-elect designees w/info in same manner as info provided Executive Branch. CHILK, S. J. Office of the Secretary of the Commission. 80/11/26. 1p. 07345:347.
- 8012300798 Weekly info rept for wk ending 801212. RENGIT.A. Office of the Executive Director for Operations, 80/12/17, 32pp. 07360:034.
- 8012310391 Responds to request for summary rept covering status of NRC actions implementing Reorganization Plan 1 of 1980. Authority has been delegated to Executive Director for Operations.

 Emergency procedures & notification have been implemented.

 REMER.C.W. Office of the General Counsel. 80/12/02. 1p. 07369:213.
- --8012310393 Discusses areas of authority for Executive Director for Operations, effective 801001.
 AMEARNE, J. Commissioners. 80/09/26. 2pg. 07369:215.
- --8012310398 Advises that existing internal authorities, responsibilities & procedures re emergency will remain in effect until further notice. Draft NRC bulletin re delegation of authority encl.

 AMEARNE, J. Commissioners. 80/09/30, 2pp. 07369:217.
- --8012310403 Discusses review of delegations of authority & other documentation as result of reorganization Plan 1 of 1780, AHEARNE, J. Commissioners. 80/09/29. 2pp. 07369:220.

CONTRACT MRC CONTRACTS AND MODIFICATIONS

- B012020283 Forwards State of FL B01029 ltr transmitting fourth quarterly progress rept on transportation surveillance program. Rept covers period from Jul-Sept 1980. JANNINK, M. Office of State Programs, Director. B0/11/13. 2pp. 07133:111.
- --8012020294 Forwards fourth quarterly progress rept on transportation surveillance program covering period from Jul-Sept 1980. Objectives have been fulfilled in first yr of study. Contract renewal has not been requested. SHULER, P. E. Florida, State of. 80/10/29, 12pp. 07133:113.
- B012020771 Responds to FDIA request for info re Contract NRC-10-80-708. Document is available in PDR. FELTON.J.M. Division of Rules and Records. B0/11/25. 1p. 07130-344.
- B012020774 FDIA request for info submitted under Contract NRC-10-B0-709. MINKLER, W. B. Micrographic Systems Technology Consultants, Inc. (MSTC, Inc.). 80/11/11. ip. 07130:347.
- 8012040133 Notification of contract execution, Mod 4 to "Study of IN Fault Locations..., New Madrid, MO Region." Contractor: IN Univ.

 HAOEY, H. Research Contracts Branch. FIN 8-6262. NRC-04-77-164.

 80/11/14. 2pp. 07158:056.
- --8012040140 Mod 4.extending period of performance to 810831 & increasing funds to "Study of IN Fault Locations....New Hadrid.HD Region."
 MULHOLLAND, J. D. Indiana Univ. MCRTON, K. V. Research Contracts
 Branch. FIN 8-6262. NRC-04-77-164. 80/11/14. 3pp. 07158:057.
- 8012040147 Notification of contract execution, Mod 1 to "Btudy & Review of Issues Concerning Equal Employment Opportunity at NRC." Contractor:CRC Education & Human Development Inc. MEDROM,L.K. Administrative Contracts Branch. FIN B-1925. NRC-23-801-502. 80/11/10. 1p. 07162:348.
- 8012040374 Notification of contract execution: "Property Inventory Equipment." awarded to Control Module.Inc. LEBD.C. Administrative Contracts Branch. NRC-10-81-365. B0/11/12. ip. 07163:254.
- --8012040377 Contract: "Property Invantory Equipment," awarded to Control Module.Inc. BIANCO, J. 8. Control Module.Inc. (MATTIA.M. J. Administrative Contracts Branch. NRC-10-81-365. 80/11/12, 2pp. 07163:255.
- 8012040619 Notification of contract execution, Mod 20 to "Downcomer Effects Experimental Program." Contractor: CREARE, Inc. WOLLETT, S. Research Contracts Branch. FIN A-4070. NRC-04-75-162. B0/11/13. 1p. 07165:302.
- --8012040627 Mod 20, providing funding for FYB1 & workscope to "Downcomer Effects Experimental Program." HICKIN.R.A. Creare, Inc. KORTON.K.V. Research Contracts Branch. FIN A-4070. NRC-04-75-162. 80/11/13. 3pp. 07165:303.
- 8012080496 Notification of contract execution, Mod 4 to "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Bypass Lines & Pipes in BWR Piping Sys." Contractor: Daedalean Associates, Inc. BRDMBERO, B. Research Contracts Branch. FIN B-6212. NRC-04-78-242, 80/11/19. ip. 07186: 324.
- --8012080498 Mnd 4.authorizing workscape & funds for FY81.to "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Bypass Lines & Pipes in BHR Piping Bys."
 YEADER L. L. Daedalean Associates, Inc., MORTON, K. V. Research Contracts Branch. FIN 8-6212. NRC-04-78-242. B0/11/19, 3pp.

otification of contract execution, Mod 4 to "Study apply in New Hadrid Area of HS earch Foundation. FIN 8-3972. NRC-04-76-321.

lon, Mod 1 to "Symposium - tivity in Consumer

4 B-10147. NRC-01-77-038.

- --B012080503 Hod 1, deabligating funds to enable contract closeout, to
 "Symposium Entitled Public Health Aspects of Radioactivity
 in Consumer Products."
 CRONN, H. M. HEW. Dept. of, Food & Drug Administration. HORTON, K. V.
 Research Contracts Branch. FIN B-10147. NRC-01-77-038. B0/11/25.
 18. 07186:330.
- B0120B0504'Notification of contract execution.Mod 16 to "LOCA/ECCB Support Studies." Contractor:MPR Associates.Inc. BROMBERO.B. Research Contracts Branch. FIN B-5537. NRC-04-75-183. B0/11/26. 1p. 071B6:331.
- --B012080305 Mod 16.extending scope, adding funds & authorizing term extension, to "LOCA/ECCS Bupport Studies."

 HANDILI.H. HPR Associates Inc. HORTON, K. V. Research Contracts Branch. FIN B-5537. NRC-04-75-183. 80/11/26. 2pp. 07186:332.
- 8012080371 Notification of contract execution, Mod 5 to "Quantitative Classification of Two Phase Flow Regimes Using Olobal & Local Neutronic Perturbations II." Contractor: Univ of WA. JACOBS, A. Research Contracts Branch. FIN 8-6324. NRC-04-78-245, 80/11/13. 1p. 07196:338.
- --8012080602 Mod 9, unilaterally increasing funds, to "Quantitative Classification of Two-Phase Flow Regimes Using Qlobal & Local Neutronic Perturbations II."
 WOOLFA. Hashington, Univ. of. MORTON, K. V. Research Contracts
 Branch. FIN 8-6324. NRC-04-78-245. 80/11/07. ip. 07186:339,
- 8012080385 Notification of contract execution, Mod 2 to "Eastern TN/ Hestern NC Regional Seismic Network." Contractor: Memphis State Univ. HAGEY.H. Research Contracts Branch. FIN 8-6675. NRC-04-79-214. 80/11/25. 1p. 07186:
- --8012080623 Mod 2.extending period of performance & adding funds, to "Eastern TN/Hestern NC Regional Seismic Network."

 CARPENTER, T. O. Memphis State Univ. MORTON, K. V. Research Contracts Branch. FIN 8-6675. NRC-04-79-214. B0/11/25. 5pp. 07186: 182.
- 8012080636 Notification of contract execution, Mod 3 to "Shuttle Bus Svc." Contractor: Beltway Limousine Svc. Inc. MARTIN.L.C. Administrative Contracts Branch. NRC-10-80-372. 80/11/28. ip. 07186:391.
- --B012080641 Mad 3.deleting stop on Route B.to "Shuttle Bus Byc." ROBERTBON.J.C. Beltway Limousine Bervice: Inc. MATTIA.H.J. Administrative Contracts Brench. NRC-10-B0-372. B0/11/28. 3pp. 07186:352.
- 8012080807 Notification of contract execution, Mod 4 to "Study of Droplet Hydrodynamics Important in LOCA Reflood." Contractor: State Univ of NY.
 HAGEY, H. Research Contracts Branch. FIN 8-6211. NRC-04-78-194. 80/11/13. 1p. 07175: 340.
- --B012080812 Mod 4,providing no cost extension, to "Study of Droplet Hydrodynamics Important in LOCA Reflood," TENBEAU.P.N. New York: State Univ. of. (Albany). MORTON, K.V. Research Contracts Branch. FIN B-6211, NRC-04-78-174. 60/11/13, 2pp. 07175:341.
- 8012080813 Corrected copy of notification of contract execution, Mod 3 to "Confirmatory Research re Dating of Groundwater." Contractor: Univ of AZ B&R & FIN numbers corrected. HAGEY, M. Rassarch Contracts Branch, FIN B-
- B012090554 Notification of contract execution. Mod 2 to "Computer Output Microfilming & Production of 35mm Aperture Cards." Gontractor: Microtach Industries, Inc. MARTIN.L.C. Administrative Contracts Dranch. NRC-10-80-361. 80/12/01. 1p. 07206:216.
- --8012090567 Mod 2, revising pickup & delivery requirements to. "Computer Dutput Microfilming & Production of 35mm Aperture Cards."

 Hicrotech Industries, Inc. HATTIA.H.J. Administrative Contracts Branch. NRC-10-80-361. 80/12/01. 2pp. 07206:217.
- 8012090570 Notification of contract execution. Mod 1 to "Micrographic 8vcs." Contractor: Microtech Industries, Inc. MARTIN. L.C. Administrative Contracts Branch. FIN 8-6357. NRC-10-80-708. 80/12/01. 1p. 07206: 219.
- --8012070573 Mnd 1, changing pickup & delivery charge at no additional tone of the military of the state of t

- 8012100004 Notification of contract execution. Mod 17 to "Steam Water Mixing & Bys Hydrodynamics." Contractor: BHI. BROMBERG. 8. Office of Administration. FIN A-4048. NRC-04-76-293. 80/12/03. 1p. 07219: 059.
- --B012100007 Mod 17, adding workscope & funds for conclusion of task to "Steam Water Mixing & Bys Hydrodynamics."

 OMENS, D. H. Battelle Memorial Institute, Columbus Laboratories. HORTON, K. V. Research Contracts Branch. FIN A-4048, NRC-04-76-29304. B0/12/03. 3pp. 07217: 060.
- BO12100017 Notification of contract execution, Mod 3 to "Development of Official NRC Records Disposition Program." Contractor: JNK Intl. LEBO.C. D. Administrative Contracts Branch. NRC-10-80-383. B0/12/01. ip. 07219:043.
- --B012100022 Mod 3, changing key personnel & adjusting schedule to "Development of Official NRC Records Disposition Program." RUDDEN, M.A. JHK International Corp. TUN9TALL, J.E. Small Business Administration. MATTIA-M.J. Administrative Contracts Branch. NRC-10-80-383. 80/12/01. 4pp. 07219:064.
- 8012100183 Notification of contract execution: "Consultant to LOFT Bpecial Review Oroup," awarded to H Isbin. LITTLE, M. Administrative Contracts Branch. FIN B-7490. NRC-04-81-196. 80/12/03. ip. 07218:239.
- --8012100189 Contract: "Consultant to LGFT Brecial Review Group," awarded to H labin IBBIN.H.S. Isbin.H. PERLMAN, J. Administrative Contracts Branch, FIN 8-7490. NRC-04-81-196. B0/12/03. Spp. 07218:240.
- 8012100202 Notification of contract execution, Mod 2 to "Review of LERs." Contractor: TE Eaton. MILEG, E.B. Administrative Contracts Branch. FIN 8-1557. NRC-11-78-632. 80/11/14. 1p. 07218: 282.
- --8012100209 Mod 2, deobligating funds to "Review of LERs."

 EATON, T. E. Eaton, T. E. PERLMAN, J. Administrative Contracts

 Branch. FIN 8-1557. NRC-11-78-632. 80/11/14. ip. 07218:283
- 8012100412 Notification of contract execution: Mod 3 to "Memphis Area Regional Beismic Natwork." Contractor: Memphis State Univ. HAGEY.H. Rusearch Contracts Branch. FIN 8-6276. NRC-04-78-200. 80/11/25. 1p. 07218:008.
- --8012100417 Had 9, extending period of performance & adding funds, to "Memphis Area Regional Beismic Network."
 CARPENTER, 17. 0. Memphis State Univ. MORTON, K. V. Research Contracts Branch. FIN B-6276. NRC-04-78-200. 80/11/25. 5pp.
- B012100420 Notification of contract execution: "Disposal of Nedical & Research Haste Containing Low Level Radioactivity," awarded to Natl Academy of Sciences.
 LITTLE, M. Administrative Contracts Branch. FIN 8-7314.
 NRC-02-81-035. 80/11/20. ip. 07218:014.
- --8012100423 Contract: "Disposal of Medical & Research Haste Containing Low Level Redicactivity," awarded to Natl Academy of Sciences.

 BITTON-P-L. National Academy of Sciences. PERLMAN.J.
 Administrative Contracts Branch. FIN 8-7314, NRC-02-81-035.

 B0/11/20. 5pp. 07218:015.
- 8012110040 Natification of contract execution: "Procurement Byts Which NRG Will Provide to US Metric Board," awarded to US Metric Board. MARTIN.L.C. Administrative Contracts Branch. NRC-10-81-362, 80/11/12. ip. 07223:127.
- --8012110053 Contract: "Procurement Svcs Which NRC Will Provide to US Metric Board." swarded to US Metric Board. STELLMAN.H.J. Commerce.Dept. of. National Bureau of Standards. HALMAN.E.L. Administrative Contracts Branch. NRC-10-81-362, 80/11/12. 4pp. 07223:128.
- 8012110349 Notification of contract execution: "Liconsing Actions Status Monitoring Sys," awarded to Franklin Research Ctr. MAIRSTON.C., OLADDLA.A.F. Technical Assistance Contracts Branch. FIN 8-7504. NRC-03-81-076. 80/11/21. 1p. 07223:207.
- --8012110359 Contract: "Licensing Actions Status Monitoring Sys," awarded to Franklin Research Ctr.
 ASHTON.A.M. Franklin Institute/Franklin Research Center.
 BOUGHERTY, D. J. Tochnical Assistance Contracts Branch. FIN B-7504.
 NRC-03-81-096. 80/11/21. 7pp. 07223:208.

- 8012110373 Notification of contract execution.Mod 2 to "Evaluation of Efficiency & Effectiveness of 11 Mgt & Program Analysis Mgt Info Products." Contractor: TRW Inc. MIO02N8.E. Administrative Contracts Branch. NRC-25-80-312. 80/11/26. 1p. 07223:229.
- ---B0121103B2 Mod 2, changing form of contractor name, to "Evaluation of Efficiancy & Effectiveness of 11 Mgt & Program Analysis Mgt Info Products."

 * TRW, Inc., Energy Systems Planning Div. MATTIA.H.J. Administrative Contracts Branch. NRC-25-80-312. 80/11/26. 1p. 07223:230.
- B012110525 Notification of contract execution:Mod 6 to "Shuttle Bus Svc." Contractor:Edwards Trucking Co.Inc. MARTIN.L.C. Technical Assistance Contracts Branch. NRC-10-76-306. B0/11/26. 1p. 07226:151.
- --8012110527 Mod 6, correcting mathematical error in Mod 5 & deobligating funds, to "Shuttle Bus Bvc."

 EDMARDS, L. A. Edwards Trucking Co., Inc. MATTIA, M. J. Technical Assistance Contracts Branch. NRC-10-76-306, 80/11/26. 1p. 07226; 152.
- BO12110574 Notification of contract execution.Mod 10 to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions." Contractor: Franklin Inst. HAIRBTON.C., GLAODLA, A.F. Technical Assistance Contracts Branch. FIN E-6570. NRC-03-79-118. B0/10/28. 1p. 07226:173.
- --8012110609 Mod 10 definitizing Change Order 1.to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions." BTOVER, J. R. Franklin Institute/Franklin Research Center. DOUOHERTY, D. J. Technical Assistance Contracts Branch. FIN 8-6590. NRC-03-79-118. 80/10/28. 1p. 07226:174.
- B012110674 Notification of contract execution: "Purchase of Metal Alloy Analyzer," awarded to TX Nuclear. WIO0188.E. Administrative Contracts Branch. FIN B-1262. NRC-05-81-242. B0/11/21. 1p. 07224:326.
- --B0121106B1 Contract: "Purchase of Metal Alloy Analyser," awarded to TX Nuclear.

 ** Texas Nuclear Div. (subs. of Ramsay Eng. Co.), MATTIA,M. J. Administrative Contracts Branch. FIN B-1262. NRC-05-B1-242. 80/11/21. 64pp. 07224:329.
- BO12110688 Notification of contract execution: "Environ Assessment of Surface & Groundwater Impacts from U Recovery Operations," awarded to Batelle Facific Northwest Labs.

 HAIRSTON.C., SMITH.P.A. Technical Assistance Contracts Branch.

 NRC-02-80-028-03. 80/10/24. 1p. 07225:030.
- --8012110494 Contract: "Environ Assessment of Surface & Groundwater Impacts from U Recovery Operations," awarded to Battolle Pacific Northwest Labs.
 WILEY.H.R. Battalle Momorial Institute, Pacific Northwest Laboratory, DOUGHERTY, D. J. Technical Assistance Contracts Branch. NRC-02-80-028-03. 80/10/24. 22pp. 07225:031.
- B012120074 Natification of contract execution.Hod 1 to "Newspaper Clipping Bvc." Contractor:Press Intelligence, Inc. FLYNN, M. Administrative Contracts Branch. NRC-01-81-357, 80/11/19. 1p. 07237;264.
- --8012120082 Mod 1.correctiong error ra appropriation symbol to
 "Newspaper Clipping Evc."

 * Press Intelligence.Inc. MATTIA,M.J. Administrative Contracts
 Branch. NRC-01-81-357. 80/11/19. ip. 07231:349.
- B012120432 Mod 2, increasing cuiling amount of contract, to "ADS Gys Support."

 * Small Business Administration. * Technassociates, Inc. MATIA, M. J. Administrative Contracts Branch, NRC-10-80-673, 80/11/28. 2pp. 07236:020.
- B012140013 Notification of contract execution. Mod 9 to "Analytic Studies of Aerosol Behavior of Fast Reactors." Contractor: Battelle Columbus Labs.
 BROWBERO, B. Research Contracts Branch. FIN A-4063.
 NRC-04-76-293-0. B0/11/19. 1p. 07262:332.
- --8012160018 Mod 9. providing no cost extension, to "Analytic Studies of Asrosol Behavior of Fast Reactors,"
 LUKZ.F.J. Battelle Memorial Institute; Columbus Laboratories.
 MORTON.K.V. Research Contracts Branch. FIN A-4063,
 NRC-04-76-293-0. 80/11/19. 1p. 07262:333.

- 8012170701 Notification of contract execution Hod 12 to "Analysis of Hypothetical Accidents Resulting from Core Meltdowns." Contractor: Battelle Columbus Labs. BRQMBERO, B. Research Contracts Branch. FIN A-4067. NRC-04-76-293-0. 80/11/25. 1p. 07268: 195.
- --B012170219 Mod 12 adding funds & changing scope of work to "Analysis of Hypothetical Accidents Resulting from Core Meltdowns." LUKZ-F. J. Battelle Memorial Institute. Columbus Laboratories. HUBTONIK. V. Research Contracts Branch. FIN A-4067. NRC-04-76-293-0. B0/11/25. 1p. 0726B:196.
- 8012180520 Notification of contract execution Mod 4 to "Subsurface Radar Profiling Study of Marsy Flats.KY Waste Disposal Region." Contractor: Geo-Ctrs. Inc. MOLLETT.S.A Research Contracts Branch. FIN 8-6349. NRC-04-79-190. 80/12/01. 1p. 03790: 232.
- --B012180526 Mod 4.increasing funds.to "Subsurface Radar Profiling Study of Maxey Flats.KY Maste Disposal Region."

 Geo-Centers. Inc. MORTOU.K.V. Research Contracts Branch. FIN B-6349. NRC-04-79-190. B0/12/01. 1p. 03790:233.
- 8012220002 Notification of contract execution, Mod 1 to "Fuel Cycle Project Review." Contractor: Science Applications, Inc. WDLLETT.S. Research Contracts Branch. FIN 8-6494. NRC-04-80-178. 80/11/25. ip. 07306;269.
- --8012220603 Mod 1.increasing funds.to "Fuel Cycle Project Review."
 MARKL.R.L. Science Applications, Inc. MORTON, K. V. Research
 Contracts Branch. FIN 8-6694. NRC-04-89-178. 80/11/25, 1p.
 07306:270.
- --8012220005 Mod), deleting specific amount of money & correcting contract language to "Fuel Cycle Project Review." MARKL-R.L. Science Applications, Inc. MORTON, K.V. Research Contracts Branch. FIN 8-6694. MRC-04-80-178. 80/11/25. 1p. 07306: 278.
- 8012220240 Notification of contract execution, Mad 3 to "Code Selection Consulting." Contractor: AF Henry. PERLMAN. J. Purchasing Section. FIN 8-6682. NRC-04-78-273. 80/12/10. 1p. 07307:160.
- --B012220249 Mod 3.deobligating balance & closing out contract, to "Code Selection Consulting." HENRY.A.F. Henry.A.F. PERLMAN.J. Purchasing Section. FIN B-692. NRC-04-78-273 80/12/10. Ip. 07307:161.
- 8012230133 Notification of contract execution: "Methodology for Evaluating Objectivity & Improving Communications: " awarded to Health Hyt Sys.
 HCYLE,A. Administrative Contracts Branch. FIN B-1261.
 NRC-05-B1-241. 80/12/10. 1p. 07316:346.
- -8012230138 Contract: "Methodology for Evaluating Objectivity & Improving Communications," awarded to Health Mgt Sys.
 ABRAMSON,F. Health Management Systems. PERLMAN,J. Purchasing Section. FIN 8-1261. NRC-03-81-241. 80/12/10. 5pp. 07316:347.
- 8012230144 Notification of contract execution: "Commission Briefing on Radiation Health Effects & Radiation Research," awarded to HI Kohn. PERLIMAN.J. Purchasing Section. FIN 8-7111. NRC-81-01-005. BD/11/19. 1p. 07316:352.
- --8012230149 Contract: "Commission Briofing on Radiation Health Effects & Radiation Research:" awarded to HI Kohn.
 KOHN.H.I. Kohn, H.I. MATTIA:H.J. Administrative Contracts
 Branch. FIN B-7111. NRC-81-01-005. 80/11/19. 4pp. 07316:353.
- 8012230151 Notification of contract execution: "Commission Briefing on Radiation Health Effects & Radiation Research," awarded to M Ooldman. PERLMAN.J. Purchasing Section. FIN 8-7114. NRC-81-01-008, 80/11/19. 19. 07316:358.
- --B012230154 Contract: "Commission Briefing on Radiation Health Effects & Radiation Research," awarded to M Ooldman. GOLDMAN, M. Goldman, M. MATTIA, M. J. Administrative Contracts Branch. FIN B-7114. NRC-B1-01-009. 80/11/19. 4pp. 07316:359.
- 8012230168 Notification of contract execution: "Commission Briefing on Radiation Health Effects and Radiation Research:" awarded to H Rossi. PERLHAN.J. Purchasing Section. FIN 8-7112. NRC-81-01-006. 80/11/19. 1p. 07317:002.

- --8012230173 Contract: "Commission Briefing on Radiation Health Effects & Radiation Research," awarded to H Rossi.

 * Rossi, H. MATTIA,M.J. Administrative Contracts Branch. FIN 8-7112. NRC-81-01-006. 80/11/19. 4pp. 07317:003.
- B012230540 Notification of contract execution, Mod 3 to "ADP Bystems Support." Contractor: Technassociates Inc. FLYNN, M.J. Administrative Contracts Branch. NRC-10-80-679. B0/12/05. 1p. 07316:302.
- --8012230545 Had 3, correcting total dollar amount of contract reflected on Mad 3 to "ADP Systems Support."

 * Small Business Administration. * Technessociates, Inc. MATTIAM J. Administrative Contracts Branch. NRC-10-80-673, 80/12/05. 1p. 07316:303.
- 8012240032 Notification of contract execution. Mod 4 to "3-D Reflood Program Intl Communications & Liaison Support." Contractor: NUS Corp. BROMBERO, B. Research Contracts Branch. FIN 8-6272. NRC-04-78-202. 80/12/15. ip. 07324:219.
- --8012240035 Mod 4.extending period of performance to 810331.increasing cost & allowing provision for foreign taxes payable, to "3-D Program Intl Communications & Liaison Support." EDMONSDN.L.R. NUB Corp. MORTON,K.V. Research Contracts Dranch. FIN 8-6272. NRC-04-78-202. 80/12/15. 2pp. 07324:220.
- 8012240040 Notification of contract execution: Mod 1 to "Fission Product Transport Analysis." Contractor: Battelle Columbus Labs.
 HAGEY: H. Rosearch Contracts Branch. FIN B-6747. NRC-04-80-177. 80/12/15. 1p. 07324: 230.
- ~~8012240044 Mod 1, increasing amount of total contract obligation, to "Fission Product Transport Analysis."

 LUXZ, F.J. Battella Memorial Institute, Columbus Laboratories, HORION, K. V. Research Contracts Branch. FIN B-6747, NRC-04-80-177. 80/12/15. ip. 07324:231.
- 8012240042 Natification of contract execution Mod 5 to "Testing of Reinforced Concrete Containments Under Combined Membrane Tension & Tangential Shear." Contractor:Portland Coment Tension a languitte.
 Association.
 HOLLETTIS. Research Contracts Branch. FIN 9-6203. NRC-04-77-118.
 B0/12/08. 1p. 07324:232.
- -8012240051 Mod 5. providing funds for completion of final rept & extending period of performance to 810331.to "Testing of Reinforced Concrete Containments Under Combined Membrane Tension & Tangential Shear."

 KUMZE.N.E. Portland Cement Association. MORTON.K.V. Research Contracts Branch. FIN 8-6203. NRC-04-77-118. 80/12/08. 1p. 0/324:233.
- B012300139 Notification of contract execution.Nod 1 to "NRC Personnel Policies & Practices Seminar for Bupervisore & Managero."

 Contractor:Oraduate Bchool.USDA.

 COLEMAN.R. Administrative Contracts Branch. NRC-10-81-370.

 80/12/16. 1p. 07356:263.
- --8012300142 Med 1.extending period of performance.to "NRC Personnel Policies & Practices Seminar for Supervisors & Managers."

 VARNER.L.S. Graduato School, Agriculture, Dept. of.. LEBO.C.D. Administrative Contracts Branch. NRC-10-81-370. 80/12/16. ip. 07356: 264.
- 8012300149 Notification of contract execution: "Editorial Assistance NRC Safety Goal Project," awarded to Editorial Consultants: Inc. FLEENOR, C. M. Administrative Contracts Branch. FIN 8-1314. NRC-19-81-493. 80/12/18. 1p. 07356: 265.
- --8012300154 Contract: "Editorial Assistance -- NRC Bafety Ocal Project," awarded to Editorial Consultants.Inc.
 HAYS.M.L. Editorial Consultants.Inc. PERLMAN, J. Administrative Contracts Branch. FIN D-1314. NRC-17-81-493. 80/12/18. 4pp. 07356:266.
- 8012300158 Notification of contract execution Mod 2 to "Photographic Syts." Contractor: MD Color Photo. COLEMAN.R. Administrative Contracts Branch. NRC-10-80-668, 80/12/18. ip. 07356: 282.
- -8012390163 Mod 2. providing addl funds, to "Photographic Gvcs." * MO Color Photo. LEBU, C. D. Administrative Contracts Branch. NRC-10-80-668. B0/12/15. ip. 07356:283.

- 8012300208 Notification of contract execution Mod 1 to "Monitoring Equipment for Regional Ofc II Inspectors." Contractor: Eberline Instrument Corp. HIGOINS.E.J. Administrative Contracts Branch. NRC-05-78-340, 80/12/16 Ip. 07356:359.
- --B012300212 Mod i.deobligating unliquidated contract balance, to "Monitoring Equipment for Regional Ofc II Inspectors."
 TURNEY.J.M. Eberline Instrument Corp. MATTIA.M.J. Administrative Contracts Branch. NRC-05-78-340.
- 8012300218 Notification of contract execution, Mod 1 to "Conference Program for ASLB Fanel Members." Contractor:Capitol Communication Sys, Inc. HIGOINS, E. J. Administrative Contracts Branch. NRC-10-80-381. 80/09/30. 1p. 07357:005.
- --8012300221 Mod 1, revising delivery schedules due to govt delay, to "Conference Program for ASLB Panel Members."
 SUTTY.T.A. Capitol Communication Systems. MATTIA.H. J. Administrative Contracts Branch. NRC-10-80-381. 80/09/30. 1p. 07357:006.
- 8012300227 Notification of contract esecution, Mod 1 to "Assessment & Evaluation of Psychological Distress." Contractor: AU Murphy, FLEENOR, C.M. Administrative Contracts Branch. FIN 8-1360. NRC-17-80-452. 80/12/18. 1p. 07356:048.
- --8012300230 Mod 1. extending period of performance through 810102 at no add1 cost, to "Assessment & Evaluation of Psychological Distress."

 HURPHY, A. W. Columbia Univ. School of Law. PERLMAN, J. Administrative Contracts Branch. FIN 8-1560. NRC-17-80-452, 80/12/18. ip. 07357:049.
- 8012310575 Notification of contract execution, Mod 2 to "BNR Raffill-Raflood Program." Contractor: OE/EPR1. GUBTAVE:R.P. Research Contracto Branch. FIN 8-5877. NRG-04-79-184. 80/11/24. ip. 07366:029.
- --8012310579 Mpd 2, increasing funds for operating exponses, to "BHR Refill-Reflood Program." BOCK,R.G. General Eloctric Co. MURTON, K.V. Research Contracts Branch. FIN B-5877. NRC-04-79-184. 80/11/24. 1p. 07366:030.
- 8012310575 Notification of contract execution: "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," awarded to Parometer.Inc. SAISDEN,L. Research Contracts Branch. FIN 8-1013. NRC-05-80-251.
- --B012310602 Contract: "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," awarded to Perameter, Inc. LDFY, R. Parameter, Inc. MORTON, K.V. Research Contracts Branch. FIN B-1013. NRC-03-80-251. 80/11/26. 4pp. 07366:034.
- BO12310620 Notification of contract execution, Mod 4 to "Characterization & Classification of Geologic Faults & Fractures in Appalachian Foldbelt." Contractor:FL State Univ. GUSTAVE,R.P. Research Contracts Branch. FIN 8-10538. NRC-01-78-004. B0/09/30. ip. 07266:038.
- --8012310624 Mod 4,increasing funds,to "Characterization & Classification of Geologic Faults & Fractures in Appalachian Foldbalt." SLIGGER.B.F. Florida State Univ. MORTON.K.V. Research Contracts Branch. FIN B-10538. NRC-01-78-004. 80/09/30. 1p. 07366:039.
- DISCLOSURE FINANCIAL DISCLOSURE INFORMATION
- 8012270638 Grants exemption from 10CFR requirements to allow participation in matters before NRC affecting GE. Interest in GE ponsion plan not substantial enough to affect integrity of sycs to NRC.

 THOMPSON.D. Office of Inspection & Enforcement, Office of the Director, 80/12/03. 1p. 07335:218.
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- B0022B0167 Notifies that payment is due for NRC review of Topical Rept OLP-5640. "Use of Thorium Oxide Fertile Fuel Particles in Fort Baint Vrain Fuel Elements."
 MILLER, M. O. License Fee Management Branch. 80/02/07. ip. 04144:233.

- 8010160576 Summarizes 246th ACRS meeting on 801009-ii re SECY-80-438A, proposed rule on fire protection Extremely prescriptive requirement of Branch Technical Position 7.3-1 does not provide best means to assure safety.

 PLESET. M. S. ACRS Advisory Committee on Reactor Safeguards.
 80/10/14. 2pp. 06727: 132.
- 8012020604 Responds to FOIA request for info re spent fuel routes through & around Asheville, NC. Forwards NUREO-0725, NRC Announcement 80-191 & App A documents Documents partially withheld (ref FOIA Exemption 3), N/o NUREO-0725, FELTON, J. M. Division of Rules and Records. 80/11/21. 3pp. 07130-294
- --9012020617 "Spent Fuel Route Survey,Oconee,SC to Lynchburg,VA." Infa partially withheld (ref FDIA Exemption 3). 4 Commissioners. 80/04/30. 11pp.
- --8012020420 "Spent Fuel Route Survey, Lynchburg, VA to Oconee, SC. " Info partially withheld (ref FOIA Exemption 3). * Commissioners. 80/02/29. 11pp.
- --8012020624 "Spent Fuel Route Survey, Ogdensburg, NY to Savannah River ; Facility, SC." Info partially withheld (ref FOIA Exemption 3).

 4 Commissioners. 79/11/30. 23pp.
- * Commissioners, 79711730, 23pp.
- --8012020630 "Spent Fuel Route Survey, Tuxedo, NY to Savannah River, SC."
 Info partially withheld (ref FOIA Exemption 3).

 * Commissioners. 80/02/29. 20pp.
- --8012020637 "Bpent Fuel Route Survey. Ann Arbor, MI to Savannah River, 80 Info partially withheld (ref FDIA Exemption 3). 4 Commissioners. 79/12/31. 18pp.
- --8012020440 "Spant Fuel Route Survey, Columbia, MO to Savannah River Facility." Info part(ally withheld (ref FGIA Exemption 3). • Commissioners. 79/10/31. 20pp.
- 8012020611 FDIA request for info re spent fuel routes through & around Asheville, NC. PLEMXONS, R. L. Affiliation Unknown. 80/08/19, 1p. 07130:327.
- 8012020/05 Responds to FOIA request for NUREO/CR-1056, NUREO/CR-0628. NUREO/CR-0758 & NUREO/CR-1155. Waiver of fees has been granted Forwards documents. M/o encls. FELTON.J.N. Division of Rules and Records. 80/11/25. ip. 07130-377.
- 8012020/10 FOIA request for NUREO/CR-1056; NUREG/CR-0628; NUREO/CR-0758 & NUREO/CR-1155.

 JONES: L. Black Hills Alliance. 80/10/22. 2pp. 07130:338.
- 8012020720 Responds to FOIA request for winning technical proposal submitted under IFB R8-0RP-80-681, "State Legislative Reporting Svcs." Contract was awarded per bid price on bid form & not proposal. No proposal is evallable. FELTON, J. M. Division of Rules and Records. 80/11/25. 1p. 07130:340.
- B012020725 FDIA request for winning technical proposal submitted under IFB RS-OSP-B0-681, "State Legislative Reporting Bycs." STOVER, J. R. Franklin Institute/Franklin Research Center. 80/11/12. ip. 07130:341.
- 8012020731 Responds to FOIA request for documents specifying exact routes & number of spent fuel shipments made or scheduled. Forwards NURSO-0725, document entitled "Summary of Route Info" & NRC Announcement 80-171. W/o NURSO-0725. FELTON.J.M. Division of Rules and Records. 80/11/21. 1p. 07130:342.
- --8012020740 "Summary of Route Info." * Commissioners. 80/07/29. 2pp.
- 8012020736 FOIA request for documents specifying exact routes & number of spent fuel shipments taken or scheduled to be taken.

 REYNDLDS.W. Aperican Friends Service Committee. 80/07/11. ip.
 07130:343.
- 8012020751 Responds to FOIA request for study conducted in 1971-72 re radiation tovels in areas near active & inactive U mills in Mestern UB. Request has been withdrawn per 801113 telcon. FELTON J. H. Division of Rules and Records. 80/11/25. 1p. 07130:344.

- 8012020794 FOIA request for study conducted in 1971-72 re radiation levels in areas near active & inactive U mills in Western US. BEERS, R. Affiliation Unknown. 80/10/30. ip. 07130:345.
- 9012020771 Responds to FOIA request for info re Contract NRC-10-80-708. Document is available in PDR. FELTON J.M. Division of Rules and Records. 80/11/25. 1p. 07130:346.
- B012020774 F01A request for info submitted under Contract NRC-10-80-708. MINKLER, M. S. Micrographic Systems Technology Consultants, Inc. (MSTC, Inc.). B0/11/11. ip. 07130:347.
- B012070778 Responds to FOIA request for list of all info,including repts & studies within last 5 yrs.re radionuclides in milk, root & leafy vegetables, grains & meat. Forwards list. Names addl agancies which may be contacted for info. FELTON-J. II. Division of Rules and Records. B0/11/21. 2pp. 07130:356.
- 8012020781 FOIA request for listing of all info, including repts & studies within last 5 yrs, re radionuclides in milk, leafy & root vegetables, grains & meat, 8ADMITH.L. Center for Farm & Food Research, Inc. 80/10/30. ip. 07130: 358.
- G012030496 Forwards Ocean Transport Co radwaste disposal records. Includes disposal dates & sites & number of drums. HENITT.M.L. Parr-Richmond Terminal Co. 62/03/30. 4pp.
- 8012930001 Responds to FOIA request for documents re sites used for dumping radwasts in Pacific Ocean. Forwards documents listed in Apps A:B,C & D. Info partially withheld: home addresses & telephone numbers (ref FOIA Exemption 6).
 FELTON, J. M. Division of Rules and Records. 80/10/15. 34pp.
- --791015005B Requests amend to Mati/Byproduct License 53-00017-23 removing Po-210, changing radiation safety officer from RB Hall to N Rinaldi & allowing release of C-14 at sea, Certificate of disposition & resume for N Rinaldi encl. TOKKSLEY, S. J. Hawaii, Univ. of, at Monoa, Honolulu, HI. 79/09/07. 78p.
- --7911150300 Forwards Amend 9 to Matl/Byproduct License 53-00017-23.
 Indicates that authorization not granted for disposal of
 radwaste at sea. Addl info needed to support request.
 LAMASTRA, M. A. Licensing Management Branch. 79/10/11. Ip.
- ~-8012030006 "Ocean Disposal Licensees After 1959."

 * Commissioners. 80/10/15. 12pp.
- --8012030010 Submits info re disposal of radwasts under License 53-00017-04 since 590701 in response to AEC 590701 request. TORKSLEY, S. Hawaii, Univ. of, at Monoa, Honolulu, HI. 61/08/21. 1p.
- --8012030012 Recommends that Naval Radiological Defense Lab.License O4-00487-06 be amended to relocate radwaste dumping site to conform w/that of Nuclear Engineering Co. GRENDON, A. California, State of, 62/02/02. 2pp.
- ~~8012030013 Forwards to Coordinator of Atomic Energy Development & Radiation Protection.HRC ltr to Ocean Transport Co re 1.008 containers of raduatte prepared for disposal at sea by Atomics Intl. AEC approved 972 raduatte packages.H/o encl. PRICE.H.L. Atomic Energy Commission. 60/07/29. lp.
- --8012030015 Requests detailed info re raduaste disposals made at sea since 590701 under License 53-00017-04, including total activity in mci of hyproduct mathitsotopic contentidisposal location & depth of water & number of packages.

 MASON, J. R. Atomic Energy Commission 61/08/14, ip.
- --8012030017 Requests renewal of Matl/Byproduct License 46-03423-01. Also requests that restriction of disposal to single site be waived due to low radiation of products & jettisoning st min sea depth of 1.000 fathom.

 WALKER: H. V. American Mail Line. 60/07/28. 1p.
- --B012030020 Summary of licensing activities re ocean disposal of raduasts. Disposal records & fact sheets encl. * Cormissioners. 80/10/15. 68pp.
- --8012030021 Forwards to Coordinator of Atomic Energy Development & Radiation Protection. Amend 2 to License 04-03669-01 & notice of issuance. Licensee uill equip each waste container w/ prassure equalization pips if nocessary. W/o encl. PRICE, H. L. Atomic Energy Commission. 40/07/19. 1p.

- --8012030022 Matl/Buproduct License 04-09668-01 has been amended per 610117,0206,0407 & 14 & 0706 applications. Amend B reviess Conditions 1,3 & 7 to authorize possession of 1,000 Ci buproduct matl & 15,000 lb source matl.

 KIRK,R.L. Atomic Energy Commission. 61/08/01. 3pp.
- --8012030024 Advises that operation in accordance w/Amend 1 to License 04-03668-01 has been completed except for disposal at sea. Ocean Transport Co requires approval for dumping five radweste containers at sea.FR notice encl. BTEINAECKER, J. Parr-Richmond Terminal Co. 60/07/06. 2pp.
- --8012030027 Notifies of 600501 radwaste disposal at sea, Provides disposal location, waste content & amount, responsible disposal company & loading procedures. Excerpt from Nuclear Engineering Co, Inc 600307 ltr encl.

 BDSNELL, R. F. Coastwise Marine Disposal. 60/04/05, 4pp.
- --8012030030 Notifies that Matl/Byproduct License 53-00017-04 provides for disposal of package wasta at specified latitude & longitude. Provides chronology of waste disposals.

 BONYER, J. E. Atomic Energy Commission. 70/09/22, ip.
- --8012030031 Ack receipt of 641020 ltr supplementing 641020 telegram. Proposed licensing action confers limited authority. CONNER, T. B. Atomic Energy Commission. 64/10/26. 1p.
- ---8012030032 Requests that License 04-05668-01 be amended to include receipt of byproduct & SNM in stael drums filled w/waste & concrete. Drums will be of density not to sink readily in sea water.

 COX.J. P. Parr-Richmond Torminal Co. 60/06/17. 1p.
- --BD12030033 Notice of application by Military Bea Transportation Syr.for mat//byproduct license to dispose of radwaste.source & SNM in Pacific & Atlantic Oceans.
 PRICE.H. L. Atomic Energy Commission. 59/05/07. 2pp.
- --B012030034 Provides info re disposal of hot barrels containing Cs-137, Co-60 & Ra-226. Includes number of drums.origin of radwaste, distribution of surface readings, disposal procedures & precautions.

 VADEN.J.D. Nuclear Corp. of America Isotopes Specialities Co. Div. 60/12/22. 2pp.
- --B012030038 Informs AEC that Military Sea Transportation Svc does not generate radwasts. No revision of license application to dispose of radwasts at sea is requested.

 CLAUDIUS, H. O. Navy, Dept. of. 78M32. 60/06/07. ip.
- --B012030041 Discusses land burial of low level packaged radwasts. Application re sea burial of radwasts may be modified to provide for waste disposal svc utilizing land burial facilities now available. PRICE, H. L. Atomic Energy Commission. 60/05/19. ip.
- --8012030049 Requests that Condition 16 of License 04-00720-02, authorizing radwasts disposal at sea, be withdrawn. Radwasts disposal by sea has been discontinued.

 ETZLER: D. H. Chevron Research Co. 17329. 70/08/28. 1p.
- --8012030046 Notice of proposed issuance of matl/byproduct license to American Mail Line.Ltd to provide radwaste disposal svc. Proposed license encl. PRICE.H.L. Atomic Energy Commission. 98/07/25. 3pp.
- --B012030047 Notice of proposed amend of Mati/Byproduct License 04-03668-01, revising Conditions 1 & 3 to authorize receipt, storage & disposal of single unit of depleted U. weighing 6:700 lb per 6:10306 application.

 KIRW.R.L. Atomic Energy Commission. 6:1/06/23, 2pp.
- --B012030050 Requests AEC approval of 590403 application for license to dispose of radwasta generated by DDD. Proposed aquipment, facilities & procedures are adequate to protect health & minimize danger.

 ORANO, R. A. Navy, Dept. of. 60/02/08. 2pp.
- ---8012030051 Confirms telcon request for extension of license to package radwaste. US Navy requests supervision to seal off containers supplied by Gozan Transport Co.
 STEINAECKER. J. Parr-Richmond Terminal Co. 60/04/28. ip.
- --8012030053 Ack receipt of 641020 telegram suggesting that AEC delay issuance of license for waste storage & reprocessing facility. Commission authority is limited to questions of public health & safety & common defense & security.

 CONNER.T.B. Atomic Energy Commission. 64/10/21. ip.

- --8012030055 Informs of final byproduct math waste disposal by sea. Waste disposal svc companies will be used for future disposals. ETZLER, D.H. Chevron Research Co. 70/08/17. ip.
- --8012030087 Submits add1 data outlining radwaste disposal procedures in response to AEC 600112 ltr & 601230 & 0111 telcons. Includes waste processing radiation protection procedures, personnel monitoring & protective clothing & equipment.

 STEINAECKER, J. Parr-Richmond Terminal Co. 60/02/08. 4pp.
- --8012030059 Ack receipt of 641006 itr suggesting that AEC deny license for storage & disposal facility. Commission authority is limited to questions of public health & safety & common defense & security.

 CDNNER.T.B. Atomic Energy Commission. 64/10/21. ip.
- --8012030060 Dept of Fish & Qame ack receipt of AEC ltr re notice of application made by US Naval Radiological Defense Lab for license to dispose of radwaste in Pacific Ocean License should be amended to conform w/580512 Voluntary Agreement. WARNER, N. California, State of. 59/04/13. 2pp.
- --8012030061 Supports American Mail Line 571024 application for matl/ byproduct license to receive byproduct & source matl wastes packaged by Boeing Airplane. Co for disposal in Pacific Ocean. Provides info re experience of personnel & facilities. PRICE, H. L. Atomic Energy Commission. 58/07/25. App.
- --8012030042 Advises on behalf of Ocean Transport Co. of matts to be disposed of at sea 610619-23.
 STEINAECKER, J. Parr-Richmond Terminal Co. 61/06/09. 1p.
- --B012030063 Recommends that CA Research Corp licenses be amended specifying quantities, types & concentrations of radioisotopes authorized for distribution in commercial products & that disposal site be specified.
 ROGERB.L.R. Atomic Energy Commission. 60/02/01. 1p.
- --8017030064 Responds to 571124 & 1223 ltrs re amend of License 04-05658-01, authorizing packaging of low leval radwaste for sea disposal, Requests addl info re description of bldg or sheltered space within which processing will be conducted. MASON, J. R. Atomic Energy Commission. 60/01/12. 2pp.
- --8012030065 Forwards 641019 ltr to Atty General commencing legal action to restrain State of NA from entering into sublease of property to CA Nuclear Inc. License should not be issued to operate waste disposal site on leased premises.

 VANDEBERO, E. J. Conrad, Kane & Vandoberg, 64/10/20. 3pp.
- --B012030066 Application for matl/byproduct license authorizing disposal of radwaste at sea in min Septh of 1:000 fathoms. Includes 1:00 Ci any byproduct matl: 500 lb source matl & B g SNM. WILL.J.M. Navy.Dept.of. 17890. 59/04/08. Bpp.
- --8012030067 Application for renewal of Matl/Byproduct License 46-03623-01, authorizing WE Morgan to use 2/or supervise use & disposal of 10 Ci byproduct source waste & 200 Ci tritium in expended accelerator targets. License excerpt encl.
 WALKER, H. V. American Mail Line. 04502. 68/08/02. 4pp.
- --BOI2030068 Application for matl/byproduct license authorizing RF Boswell to use &/or supervise use of waste products in form of liquids.wiping rags & tissues for see disposal.
 BOSHELL,R.F. Coastwise Marine Disposal. 10522. 58/04/30. 2pp.
- --B012030069 Submits proposed temporary method for packaged matls having high Ci content.Ocean Transport Co possession limit will be temporarily relaxed to provide for storage during waste transit.

 BTEINAECKER, J. Parr-Richmond Terminal Co. 0434. 60/01/25. 1p.
- --8012030070 Matl/Byproduct License 04-05668-01 for Ocean Transport Co is amended in entirety per 610822 application. Amend 10 authorizes receipt & disposal at sea of 30-gallon drums filled w/solidified liquid & other noncompressible matl. KIRK/R. L. Atomic Energy Commission. 62/01/23. 2pp.
- --B012030071 Requests delay in granting AEC license to CA Nuclear, Inc. pending determination of validity of lease & proposed aublease between AEC & State of NA.

 # Conrad.Kane & Vandeberg. 64/10/20. ip.
- --8012030072 Forwards notice of application for metl/byproduct license by US Navel Radiological Defense Lab, to dispose of low level radwaste in Pacific Ocean.
 PRICE, H. L. Atomic Energy Commission. 59/04/02. 1p.

- --B012030073 Discusses proposed program for raduaste disposal. Provides detailed description of receipt.possession.packaging & disposal of raduaste.

 B05NELL.R.F. Coastwise Marine Disposal. 10522. 58/04/29. 4pp.
- --8012030075 Informs AEC that 659 tons of packaged radwaste will be shipped to Area E for sea disposal during whof 600125 if weather permits. BUSNELL.R. Coastwise Marine Disposal. 0082. 60/01/07, lp.
- --B012030076 Informs that notice of proposed amend to License 04-03668-01 was signed & submitted to FR on 610607. Bea disposal operation on 410619-24 is acceptable. MASON, J. R. Atomic Energy Commission. 61/06/08. Ip.
- --8012030078 Notice of application for math/byproduct license by US Naval Radiological Defense Lab, to dispose of low level radwaste in Pacific Ocean. Application specifies max possession limit of 150 Ci byproduct math. PRICE, H. L. Atomic Energy Commission. 39/04/02. 2pp.
- ---8012030079 Informs that Commission has issued natl/byproduct, source & SNM license to Ocean Transport Co. Forwards notice of issuance & license. W/o encls.
 PRICE, H. L. Atomic Energy Commission. 59/10/05. 1p.
- ---8012030080 Notifies AEC of 670817 disposal of 95-gallon concrete-filled drum of radwaste at sea. Describes contents of waste. Also informs that five drums of radwaste wore disposed of at sea on 670427.
 KROTZ.D.P. Chevron Research Co. 67/09/18, 2pp.
- --8012030081 Submits addl explanation re solidification of liquid waste for transportation & eventual sea disposal outlined in 591124 ltr. Steel tanks varying in capacity from 500 to 3,000 gallons will be used in waste transportation.

 8TEINAECKER, J. Parr-Richmond Terminal Co. 59/12/23. 3pp.
- --B0120300B2 Ack receipt of 580430 application for matl/byproduct license re disposal of radwaste in ocean. Forwards draft outline of info which can be used as guideline for supporting info needed to continue review. HITCH.J.W. Atomic Energy Commission. 10522. 58/05/89. Bpp.
- --8012030084 Natice of proposed amend of Matl/Byproduct License 04-05668-01, authorizing relocation of waste storage area within boundary of property owned by Parr-Richmond Terminal Co. Supporting AEC mend encl.

 KIRM.R.L. Atomic Energy Commission. 61/06/07. 6pp.
- --BD12030085 Informs that AEC issued Amond 10 to Mati/Byproduct License 04-05688-01 held by Ocean Transport Co.Amend authorized receipt & disposal of 35-gallon drums of concreted radwaste at sea.

 KIPK,R.L. Atomic Energy Commission. 62/01/23. 1p.
- --B0120300B7 Ack receipt of 590707 ltr re issuance of license for sea disposal of byproduct waste source & SNM to Ocean Transport Co. Excerpt from FR encl. BROWN.E.O. California. State of. 59/09/16. 2pp.
- --8012030088 Submits add1 info re policy of packaged radwaste. Vol of one cargo may be slightly exceeded when vessel. Garland (is employed on short-term oceanographic research work. COX. J.P. Parr-Richmond Terminal Co. 59/12/17. 1p.
- --E012030087 Ack receipt of Dept of Fish & Game 580414 ltr re Isotopes Specialities Co. Inc & disposal of radwaste in ocean areas adjacent to CA. Requests that meeting be hold u/all interested agencies re sea disposal.

 PRICE, H. L. Atomic Energy Commission. 58/05/09. 3pp.
- ---B012030072 Notifies that Ocean Transport Co intends to commence sea disposal operations during wk of 610619-24. Requests waiver of 20-day notice. STEINACKER, J. Parc-Richmond Terminal Co. 61/06/05. ip.
- --B012030093 Advises that cargo referred to in 661104 ltr was loaded to SS Canada Mail due to weekend loading of SS Japan Mail.
 Shipment of 40 drums radwaste & three blocks benyllium waste was jottisoned at sea on 661225. Masters rept encl.
 PELLY,B.B. American Mail Line. 67/01/10. 2pp.

- --8012030074 Application for renewal of Matl/Byproduct License 04-00487-03, authorizing collection, packaging & sea disposal of radwaste. Includes 150 Ct any radioactive matls per yr for sea disposal.

 BAIETTI.A L. Navy, Dept. of. 17096. 59/03/04. 10pp.
- --B012030095 Forwards motice re proposed issuance of mat1/byproduct source & SMM license to Dept of Navy to dispose of low level radwaste in Atlantic & Pacífic Deems H/o encl. PRICE, H. L. Atomic Energy Commission. 40M32. 59/08/04. 1p.
- --B012030096 Forwards Yankee Inc 580407 ltr.responding to AEC 580331 ltr. H/o encl. PRICE, H. L. Atomic Energy Commission. 58/04/14, 1p.
- --8012030079 Advises of proposed issuance of license for sea disposed of waste buproduct, source & SNM to Military Sea Transportation Svc.Mo FR notice.
 PRICE, H. L. Atomic Energy Commission. 59/08/04. ip.
- --8012030190 Requests add1 info re 610412 application to amend License 04-05668-01 to authorize receipt & ocean disposal of water insoluble chemical salts packaged in polyethylene lined 30 & 55-gallon steel drums.

 MASON.J.R. Atomic Energy Commission. 61/05/22, 1p.
- --8012030101 Ack recript of 590306 ltr re amend to License 46-03623-01 concerning receipt possession & disposal of prepackaged wastes from customers other than Boeing Airplane Co. Requests additisted info in order to complete application review. MASOM, J. R. Atomic Energy Commission. 59/04/02. 2pp.
- --8012030102 Forwards Amend 10 Licensa 04-05668-01, authorizing receipt & disposal of 55-gallon on drums at sea. W/o encis.

 KIRK, R. L. Atomic Energy Commission. 62/01/23. 1p.
- --B012030103 Notifies of receipt of Boeing Co waste matl for disposal at sea Description of contents encl.Instructions will be issued to jettison matl in accordance w/license terms.

 PELLY. D. B. American Mail Line. 45/11/04, 4pp.
- --8012030105 Ack receipt of AEC 580407 ltr re proposed issuance of matl byproduct license to Isotopes Specialities Co.Inc.Requests that addl requirements be implemented.Disposals should be made in waters no less than 2.000 fathoms.W/related ltr. GORDON, B. California, State of. 58/04/14. 6pp.
- ---B012030107 Notifies of radwaste disposal at sea during wk of 590706-10.

 Lists total number of containers, total hyproduct activity & number of concrete blocks. Radwaste will be disposed of in Pacific Ocean.

 MCGUILKIN, J. H. Navy, Dept. of. 730-67. 59/06/18. ip.
- ---8012030107 Submits additinform remewal of License 04-00437-06 & in response to AEC 610414 request. Estimated total that night accumulate prior to possible see disposal operation is 500 Ct. Disposal procedures encl.
 ROTH.E.B. Mavy, Dept. of. 61/05/11. 9pp.
- --8012030110 Application for matl/byproduct license.

 + American Electronics.Inc. Reed-Curtis Nuclear Div. 58/03/14.
 3pp.
- --8012030111 Provides policy re storage of packaged radwaste at ship site.Company will not accumulate more than one cargo load. General specs of vessel.Garland.encl. COX.J.P. Farr-Richmend Terminal Co. 59/12/17. App.
- --8012030114 Mati/Buproduct License 46-03623-01 for American Mail Line is amended in entirety per 660901 & 03 applications. Amend 3 authorizes receipt, possession & disposal of 10 Ci byproduct matl other than tritium, 200 Ci tritium & 200 lb source matl. + Atomic Energy Commission. 66/09/15, 3pp.
- --8012030115 Notice of issuance of Byproduct Source & SNM License Oq-04730-01.authorizing Coastwise Marine Disposal Co to receive.possess.package & dispose of byproduct.source & SNM in Pacific Ocean.
 PRICE.H. L. Atomic Energy Commission. 59/06/07. 1p.
- --8012030114 Application for renewal of Matl/Hyproduct License O4-00487-03.authorizing possession & use of 500 mC1 of any hyproduct matl between Atomic Numbers 3-94 for R&D, BAIETTI.A.L. Navy.Dept.of. L4993. 58/11/25. 13pp.
- ---8012030117 Confirms 580402 telcon to recent application for matl/ byproduct license to disposal of radwaste in ocean. Requests addl info before review of license application can continuo. HITCH. J. W. Atomic Energy Commission. 58/04/14. 3pp.

- --B012030119 Provides followup to 591124 request for two amends to license. Amends should be processed separately. Requests seek authorization for storage of 4,700 Ci byproduct matls, 4,000 lb source, matl & 400 g SMM.

 STEINAECKERJ, Parr-Richmond Terminal Co. 59/12/14. 1p.
- --B012030122 Informs City of Richmond that AEC has issued Amend 10 to Matl/Byproduct License 04-05688-01 held by Ocean Transport Co. Amend authorizes receipt & disposal of 55-gallon drums of concreted raduaste at sea.

 KIRK, R. L. Atomic Energy Commission. NRC. 62/01/23, 1p.
- --B012030123 Informs that Commission has issued matl/byproduct license to US Naval Radiological Defense Lab.authorizing disposal of low level radwaste in Pacific Ocean. H/o FR notice.
 PRICE, H. L. Atomic Energy Commission. 59/05/20, 1p.
- --B012030124 Application for renewal of Licenso 04-00037-02.authorizing possession & use of 500 Ci any byproduct matl w/Atomic Numbers 3-B4 in any form of waste matl. SIMPSON.R. Atomic Energy Waste Disposal Service. 17219. 59/03/11. ≳pp.
- --8012030125 Opposes granting matl/byproduct license to Isotopes Specialities Co for ocean disposal of radwaste, due to radwaste dumping in ocean areas less than 2,000 fathoms deep & proximity to shore. GORDON, S. California, State of, 58/03/20. 2pp.
- --8012030126 Notice of issuance & availability of Amend 3 to License 46-03623-01.

 * Atomic Energy Commission. 66/09/15. 2pp.
- --B012030128 Informs that Commission has issued matl/byproduct license to US Naval Radiological Defense Lab, authorizing disposal of low level raduaste in Pacific Ocean, H/o FR notice.

 PRICE, H. L. Atomic Energy Commission. 59/05/29, 1p.
- --8012030131 Application for renewal of License 04-00037-02 to provide for radwaste disposal svc. SIMPSON, R. Atomic Energy Waste Disposal Service. 17219. 59/03/11. 21pp.
- --8012030132 Discusses expansion of raduasto disposal svc. Lista procedures to be followed to minimize raduaste handling & radiation exposure. Requests authorization to collect & dispose of any raduaste contained by concrete. FRISOLI.A. American Electronics. Inc. Reed-Curtis Nuclear Div. 39/03/10. 3pp.
- --B012030135 Notifies of matl Boeing Co has transferred for disposal at sea. Matl will be loaded by 641010. Full description of contents encl. PELLY. B. D. American Mail Line. 64/09/20. 4pp.
- --B012030135 Forwards proposed FR notice re-receipt of Dept of Navy, Military Sea Transportation Svc application to dispose of low level radwasts in Pacific & Atlantic Oceans. M/o encl. PRICE, H. L. Atomic Energy Commission. 59/03/07, ip.
- --8012030138 Forwards responses to AEC 580113 questionnaire re ocean burial of radwaste.
 ELLIOT.L.P. California Research Corp. 58/02/18. 3pp.
- ~-B019030139 Informs Coordinator of Atomic Energy Development & Radiation Protection that AEC has issued Amend 10 to Matl/Byproduct License 04-03668-01 held by Ocean Transport Co. Amend authorizes recipt & disposal of raduaste at sea. KIRK, R. L. Atomic Energy Commission, 62/01/30. 1p.
- --8012030140 Application for amend of Matl/Byproduct License 46-03623-01 to allow shipment of radwaste to sea from organizations other than Boeing Airplane Co & to increase possession limit to 60 16 waste.

 WALKER-H.V. American Mail Line. 17019, 59/03/06. 3pp.
- --8012030141 Forwards notice of issuance & evailability of Amend 3 to License 46-03623-01 & license amend. Amend provides for receipt & storage of packaged radwaste matls by American Mail Line & authorizes disposal in Pacific Ocean. W/o encl. MCBRIDE: J. A. Atomic Energy Commission. 46/09/15. ip.
- --B012030142 Requests indication re max amount of math which will be possessed at any one timo per 610302 application for renawal of License 04-00487-06. Also requests revision of radwaste disposal procedures to include listed criteria.

 MASDN, J. R. Atomic Energy Commission. 61/04/14. 2pp.

- --8012030143 Ack receipt of info transmitted w/AEC 640902 ltr.Requests advisement of progress made.
 ROBFLLINI.A.D. Washington: State of. 64/09/11. ip.
- --8012030145 Matl/Byproduct License 04-05668-01 is amended per 601125 ltr.Amend & revised Condition 6.3(3) re packaging of motis containing radioisotopes of Pu.Am.polonium,curium or 8r-90 in quantities in excess of 100 mci. PRICE.E.R. Atomic Energy Commission. 60/12/30. 2pp.
- --8012030146 Forwards proposed FR notice re receipt of Dept of Navy, Military Sea Transportation Svc application to dispose of low level radwaste in Pacific & Atlantic Oceans. PRICE.H.L. Atomic Energy Commission. 59/05/07, 1p.
- --8012030147 Matl/Dyproduct License 04-04730-01 for Coastwise Marine Disposal Co.authorizing receipt passession, packaging & disposal of byproduct, source & SNM. Supporting memo encl. * Atomic Energy Commission. 59/02/19.
- --B01203014B Ack receipt of 640902 ltr.Dept of Health will be represented at 640915 meeting in Richland, WA re CA Nuclear, Inc & proposed amends to waste disposal license.
 STOCKMAN, R.L. Washington, State of. 64/09/09. ip.
- --8012030149 Requests info re waste matl packaged in concrete-filled steel drums for disposal into sea. Drums must meet criteria in encl FR notice of proposed rulemaking before authorization for receipt can be made. N/o FR notice. MASON, J. R. Atomic Energy Commission. 61/04/10. ip.
- --8012030150 Natics of issuance of Amend 10 to Hatl/Byproduct License 04-05668-01.FR notice excepts andl. KIRK,R.L. Atomic Energy Commission. 62/01/23. 3pp.
- --B0120301B4 Forwards proposed FR notice re receipt of Military Bea Transportation Buc application to dispose of low level radwaste in Pacific & Atlantic Oceans. W/o encl. PRICE, H. L. Atomic Energy Commission. 59/05/07. ip.
- --8012030195 Forwards notice of issuance & availability of Amend 3 to License 46-03623-01 & license amend. Amend provides for roceipt & storage of packaged radwaste matis by American Mail Line & authorizes disposal into Pacific Ocean. N/o encl. MCBRIDE, J. A. Atomic Energy Commission. 80/09/15. 1p.
- --8012030157 Submits response to AEC 581224 request for add1 info in support of application for matl/byproduct license.Includes info re treatment.use & ultimate disposal of radwasts.
 SIMPSON.R. Atomic Energy Waste Disposal Service. 59/01/27. 2pp.
- --B012030158 Forwards proposed FR notice to receipt of Dept of Navy, Military Bea Transportation Svc application to dispose of low level radwaste in Pacific & Atlantic Oceans, PRICE,H.L. Atomic Energy Commission. 59/05/07. 2pp.
- --8012030i60 Requests info re disposal of radwaste at sea, including number of radwaste packages, activity & isotopes per package & total quantities of matls dumped since 350930.

 BUCHANAN, C. R. Atomic Energy Commission. 58/01/13. 2pp.
- --8012030163 Requests clarification of listed items re treatment, use & ultimate disposal of radwasto. Review of application will continue upon receipt of info.

 BRINKMAN, R. E. Atomic Energy Commission. 58/12/24. 2pp.
- --B019030164 Ack roceipt of 590427 ltr re proposed issuance of matl/ byproduct license to US Naval Radiological Defense Lab to dispose of low lovel radwaste in Pacific Ocean.FR notice encl. BROWN.E.O. California, State of. 59/05/07. 2pp.
- --8012030166 Application for amend of Matl/Byproduct License 04-05668-01, authorizing storage of 4,700 Ci byproduct matls, 4,000 lb source matl 2,400 g SNM.
 STEINAECKER, J. Parr-Richmond Terminal Co. 22669, 59/11/24. 3pp.
- --8012030169 Submits add1 info re principle US ports from which radwaste would be lifted for disposal at sea.Ports include NY Harbor & Ban Francisco Harbor. ZWICKER,F. H. Navy, Dept. of, 50M32. 69/04/30. 1p.
- --8012030169 Responds to 581014 itr containing addit questions for AEC review of application for math/byproduct license re sea disposal of radioisotopes. Regulations re transportation of radwaste shout be included in application.

 BOBNELL, R. F. Coastwise Marine Disposal. 58/11/23. 9pp.

- --8012030170 Forwards notice of issuance & availability of Amend 3 to License 46-02623-01 & license amend. New criteria for preparation of packages for disposal at sea is under consideration. W/o encl.

 HGBRIDE, J. A. Atomic Energy Commission. 66/09/15. 1p.
- --8012030171 Matl/Byproduct License 46-03623-01 for American Mail Line, Ltd, authorizing receipt.possession & disposal of 10 Ci byproduct matl & 15 lb source matl from Boeing Airplane Co. MASON-J.R. Atomic Energy Commission. 58/12/31. 3pp.
- --8012030173 Forwards application for renewal of License 04-00487-06 re authorization to dispose of low level radwaste in Pacific Ocean. ROTH, E. B. Navy, Dept. of. 33112. 61/03/06. 1p.
- --B012030174 Forwards proposed FR notice re proposed issuence of matl/ byproduct license to US Naval Radiological Defense Lab. to dispose of low level radwaste in Pacific Ocean W/o encl. PRICE.H.L. Atomic Energy Commission. 59/04/27. ip.
- --8012030175 Hatl/Byproduct License 04-0566B-01 for Ocean Transport Coauthorizing receipt, possession & disposal of 750 Ci byproduct math.2.000 source math & 4 g SNM. KIRK.R.L. Atomic Energy Commission. 59/10/05. 5pp.
- --8012030177 Responds to 501126 ltr re disposition of byproduct & source mat1 wastes on 501030. Shipment was transferred by Doeing Airplane Co. A Jenson 501113 ltr & Atomic Energy Waste Disposal procedures encl.

 WALKER, H. V. American Mail Line. 50/12/29. 20pp.
- --8012030178 Notice of receipt of Isotopes Specialties Co application for license to provide radwaste disposal sycs. PITTMAN, F. K. Atomic Energy Commission. 57/11/26, 1p.
- --8012030179 Act receipt of 590402 itr re US Naval Radiological Defense Lab application to dispose of low level radwaste in Pacific Ocean.FR notice encl. BROWN.E.O. California, State of, 59/04/10. 2pp.
- --6012030180 Application for renewal of Matl/Byproduct License 04-00487-06, authorizing 500 Ci any radioactive matls per yr for sea disposal & receipt, possession, packaging & disposal of radwaste genorated by US Naval Radiological Defense. BAIETTI, A. L. Navy, Dept. of. 33112. 61/03/02. 10pp.
- ---9012030182 Application for amend of Matl/Byproduct License 46-03623-01.
 authorizing HV Walker, HA Greenwood, WH Clarke, J Jorgenson &
 E Headman to possess & dispose of 10 Ct byproduct source
 waste & 200 Ct tritum in expanded accelerator targets.
 WALKER, H. V. American Mail Line. 79214. 66/08/01. 2pp.
- --B012030185 Confirms 590106 telcon Coastwise Marine Disposal Co should be designated as logal licenses in Item 1 (a) of Application Form AEC-313 Cartified copy of ship log will be kept at all times. BOSWELL R. F. Coastwise Marine Disposal. AXX-1-4905. 59/01/08.
- --8012030187 Confirms 640831 telcon re application for license to receive passess & store radwaste at Richland, WA. Lists aspects of application requiring confirmation. clarification or amend.

 CUNNINGHAM, R. E. Atomic Energy Commission. 64/08/31. 2pp.
- ---8012030188 Advises Commission of 619215 & 0217 voyages to dispose of low level radwaste. Info is being provided in response to Amend 6. Condition 10 of 601230 license. STEINAECKER, J. Parr-Richmond Terminal Co. 61/03/06. ip.
- --8012030190 Notifies that shipment of 38 drums of radwaste was disposed of at sea on 501030 of depth of 2,000 fathoms, HALKER, H. V. American Mail Line. 58/11/24, 1p.
- ---8012030191 Ack receipt of 660623 ltr re disposal of three drums of radwaste in unauthorized disposal area Notes that stops have been taken to assure future disposals in area designated in license.
 PRICE.E. R. Atomic Energy Commission. 66/07/05. 1p.
- --8012030193 Ack receipt of 581024 ltr re Coastuise Marine Disposal Coapplication for license to provide radwaste disposal svc. KNIGHT.O. J. California. State of, 58/11/05. 1p.
- --8017030195 Submits revised schedule for sea disposal of radwaste authorized under License 04-04870-06. Provides info re load number date number of containers amount of activity & most hazardous radioisotoper. WFR notices & related ltr. CONNULLY, R. J. Navg. Dept. of. 730-93. 59/09/17. App.

- --8012030196 Notice of application for license to provide waste disposal svc filed by Coastuise Marine Disposal Co. PRICE, M. L. Atomic Energy Commission. 58/10/24, 19.
- --8012030198 Notice of proposed issuance of meth/byproduct license to Isotopes Specialties Co.Inc to provide radwaste disposal svc. PRICE,H.L. Atomic Energy Commission. 58/02/24. 4pp.
- --8012030199 Dept of Public Health requests clarification re AEC license condition that waste be disposed of in prescribed Pacific area, thus nullifyling voluntary agreement between CA agencies & Licensed AEC firms. News article encl.

 MERRILL.M.H. California, State of, 58/09/30. 2pp.
- ~-B012030200 Application for Mati/Byproduct License authorizing JS Corbett to use b/or supervise use of 50,000 GI any byproduct mati between Atomic Numbers 1-9 & 25,000 lb source mati. Info partially withheld (ref FOIA Elemption 6). CORDETI.J. S. US Ecology, Inc. (Formerly Nuclear Engineering) 64/07/08. 24pp.
- --8012030201 Clarifies points raised in 630924 ltr re renewal of Matl/
 Byproduct License 53-00017-04. Comments on radiation control
 programs personnel monitoring waste disposal & manual for
 radiation safety. Except from AEC 630924 ltr encl.
 TOWNSLEV.S. J. Hawaii, Univ. of, at Monoa, Honelulu, HI. 72626.
 65/11/08. 4pp.
- --8012030202 Notifies of 611207 sea disposal of packaged redwaste. Master log & sea disposal rept encl. CORBETT.J.S. US Ecology, Inc. (Formerly Nuclear Engineering) 61/12/13. 3pp.
- --B012030203 Supports application by Isotopes Specialties Co.Inc for mati/hyproduct license to collect.grepare for disposal & dispose of byproduct & source mati waste. Includes info re experience of personnel & equipment & facilities. PRICE.H.L. Abomic Energy Commission. 58/02/26. 3pp.
- --8012030204 Requests withdrawal of original application for license.
 Company will submit new application to proposal for license to collect.process & bury radwaste at sea.
 BOSNELL.R.F. Coastwise Harine Disposal. 58/09/05. 1p.
- --8012030205 Notifies that Boeing Airplane Co has transferred shipment of 3B drums of radwaste for disposal Provides specific location of disposal Detailed description of radwaste encl. HALKER.H.V. American Mail Line. 50/10/24. 2pp.
- --8012030207 Informs AEC of storage of radioactive matts at AEC approved storage site in Richmond, CA. Ocean Transport Co does not store industrial wastes. JE Steinaeckor &01110 ltr ta RL Kirk & Fulton Shipyard log encl.

 8TEINAECKER, J. Parr-Richmond Terminal Co. &0/11/10. 14pp.
- --8012030209 Forwards application for matl/byproduct license to possess raduaste in secured area. HCCLUNG.H.N. Boeing Co. 57/11/21. Ip.
- --8012030207 Forwards Byproduct & Source Matl License 46-03623-01.
 authorizing disposal of byproduct & source matl in Pacific
 Ocean. U/o encl.
 PRICE, E.R. Atomic Energy Commission. 58/08/28. 1p.
- --B012030211 Advises that radwaste shipment on SB Canada Mail has been jettisoned at sea.AD Smith 650829 ltr to MD Callahan encl. PELLY, B. B. American Mail Line. 65/09/14. 2pp.
- --B012030212 Responds to 590629 ltr re application for amend to Liconse 46-05623-01. Requests addl info re specific disposal area, customer radwaste packaging procedures & max amount of matl that will be possessed at one time.

 MASCN, J. R. Atomic Energy Commission. 59/09/14, 2pp.
- --8012030214 Application for matl/byproduct license, authorizing WH Poppe & HE Morgan to use &/or supervise use of 10 Ci byproduct & source matts for storage & disposal MCCLUNG,M. H. Boeing Co. 37/11/22. 11pp.
- --8012030216 Requests amend to 590714 application for matl/byproduct license to increase matl content to 500 Ci. Increase is based on recent request from customer.

 BIMPBONER. Atomic Energy Waste Disposel Service. 12119.

 58/07/25, 1p.
- ~-8012030217 Forwards notice of proposed issuance of amend to License 04-0358-01 held by Ocean Transport Co. M/o encl. KIRK.R L. Atomic Energy Commission. 61/12/08. ip.

- --8012030218 Notifies of radwaste disposal trips scheduled during wt of 410213-17.
 STEINAECKER, J. Parr-Richmond Terminal Co. 61/02/09. 1p.
- --8012030219 Notifies that radwaste was disposed of at sea on 590824.

 WALKER, H. V. American Mail Line. 59/09/23 1p.
- --B012030220 "Transportation Requirements for Radwaste Disposal Licensess." * Atomic Energy Commission. 58/10/21. 3pp.
- --B012030221 Requests status of 571025 application for matl/byproduct license & confirmation that Univ of HA is licensed to dispose of radwaste at sea. HALKER: H. V. American Mail Line. 57/12/11, ip.
- --B012030222 Notifies that 29 crums of radwaste were jettisoned at sea on 601017 at 2,000 fathors.
 HGODMAN, M. J. American Good Lines. 60713709. ip.
- ---8012030225 Responds to AEC 580826 request for add1 info & revised procedures re application for byproduct/matl license. Approx 56.000 lb source matl will be received during next 2 yrs. Revised procedures and.
 SIMPSON.R. Atomic Energy Waste Disposal Service, 58/10/17. 11pp.
- --8012030226 Informs AEC of amounts, types & locations of radwaste math disposed of in sea. All wastes were generated within army commands in Europe &/or Korea & encased in concrete in 55-gallon size drums.

 CLAUDIUS, H. O. Navy, Dept. of. 61/01/13. ip.
- ---B012030227 Application for amend of Matl/Byproduct License 04-00580-06, to incorporate Isotopes Specialties Co as div of Nuclear Corp of America Inc & to delete AM Goldstein & add J Vaden. Administrative procedures encl. HICHAUD.A.A. Nuclear Corp. of America Isotopes Specialities Co. Div. 57/07/10. 6pp.
- --8012030228 Forwards Amend 1 to License 46-03623-01, issued per 600728 application for license renewal. Condition 6 has been revised to require notification of listed officials re intent to conduct disposal operations.

 PRICE, H. L. Atomic Energy Commission. 60/12/02. 1p.
- --8012030229 Provides info re roducate packaging in response to AEC 571227 request. Heasures will be taken to ensure that primary container will not float if it becomes separated from waste disposal package.

 HCCLUNO, M. M. Bosing Co. 2-1880-9-264. 58/01/10. 2pp.
- --B012030230 Notifies that 33 drums of radwaste were jettisoned on 640327. Also provides latitude & longitude of drop. Hater dapth was in excess of 2,000 fathoms.

 MCOGNAN, H. J. American Mail Line. 64/04/17, ip.
- --B012030235 Forwards notice of proposed issuance of license & 590909 ltr to EO Brown, Governor of CA. PRICE, H. L. Atomic Energy Commission. 59/09/09. 1p.
- --B012030236 Requests clarification of number of drums & amount of radwaste disposed of on 640329.

 BASSIN.N. Atomic Energy Commission. 64/04/23. 1p.
- --8012030238 Advises of issuance of Amend 1 to License 46-03623-01 held by American Mail Line, extending license expiration date for 2-yr period. Condition 6 has been revised to require notification of listed officials re disposal operations. PRICE, H. L. Atomic Energy Commission. 60/12/02. 19.
- --B017030239 Ack receipt of 580714 application for matl/byproduct license re see disposal of 500 Ci byproduct matl. Requests more detailed info & revised procedures re proposed program due to increase in possession limit & ultimate disposel. BUCHANAN, C.R. Atomic Energy Commission. 58/08/26. 7pp.
- --8012030240 Suggests procedure for updating applications for byproduct meth license for disposal of radwaste. In current case new application should be submitted.

 BRINKMAN.R.E. Atomic Energy Commission. 58/07/01, ip.
- --B012030241 Ack receipt of 3B0113 ltr re packaging, handling & disposal of radwaste from Boeing Airplane Co. Lists procedures that will be followed in radwaste disposal sycs.

 WALKER, H. V. American Mail Line. 38/01/24. 2pp.

- --8012030242 Informs Coordinator of Atomic Energy Development & Radiation Protection, of issuance of Amend 7 to License 04-05668-01 held by Ocean Transport Co. Amend provides for receipt of metal scrap in plywood containers.

 KIRK, R. L. Atomic Energy Commission. 61/01/11. ip.
- --8012030243 Advises of proposed issuance of license to Ocean Transport Co for sea disposal of radwaste.Proposed license authorizes two waste disposal sites. PRICE.H.L. Atomic Energy Commission. 59/09/09. 2pp.
- --8012030244 Corrects error made in 640417 ltr re number of drums disposed of an 640329. Actual number jettisoned was 30 drums. MCQDMAN.W. J. American Mail Line. 64/04/24. ip.
- --8012030244 Responds to application for matl/byproduct license re sea disposal of radioisotopes. Requests clarification of listed items prior to continuing review. HITCH.J.M. Atomic Energy Commission. 58/10/14. 4pp.
- --8012030247 Notice of application by American Electronic, Inc for license to provide radwaste disposal svc. Application specifies max possession limit of 10 Ci & proposes to dispose of wastes at specific locations in Pacific Ocean. PRICE, H. L. Atomic Energy Commission. 58/06/13. ip.
- ---8012030249 Provides add1 info re application for license to dispose of radwaste, in response to AEC 580314 request. Includes info re radiation monitor to accompany waste shipment, instructions to driver of waste vehicle & exemption from surface limits. NCCLUNG, M. W. Boeing Co. 2, 4427, 1-106, 58/03/19, 2pp.
- --8012030250 Ack receipt of 590827 ltr re Ocean Transport Co application to dispose of raduaste in Pacific Ocean.
 BRONN, E. O. California, State of, 59/09/03. ip.
- --8012030252 Forwards to Coordinator of Atomic Energy Development & Radiation Protection, notice of proposed issuance of amend to License 04-05668-01 held by Ocean Transport Co.
 KIRK, R. L. Atomic Energy Commission. 61/12/06. ip.
- --B012030253 Mati/Byproduct License 04-05668-01 is amended per 610103 application. Amend 7 adds Condition 3. D, authorizing receipt of magnesium-thorium metal scrap having up to 4% Th-232 in steel-clipped, nafised & banded boxes.

 KIRK, R. L. Atomic Energy Commission. 61/01/11. ip.
- --8012030255 Notifies of 640209 sea burial of five 55-gallon.concretefilled drums of radwaste. No barrel weighed less than 780 lb. Lists approx contents of each barrel & longitude & latitude in which barrels were dropped. ETZLER, D. H. Galifornia Research Corp. 64/03/03. ip.
- --- 8012030256 Requests that Commission revalue application of 1,000 fathom rule appearing in NBS Handbook 5B re disposal off CA coast.

 Btd may not be advisable in this area.

 DAVIS.H.C. California Fish Canners Association, Inc. 58/04/29.
- --8012030260 Notice of proposed issuance of matl/byproduct license to Ocean Transport Co.authorizing disposal of waste in Pacific Ocean at depth of 1,000 fabboms. Draft license & supporting memo encl.

 KIRK.R.L. Atomic Energy Commission. 59/09/09. 10pp.
- --8012030262 Notifies that Boeing Co has transferred 33 drums of radwaste for disposal at sea Matl will be loaded by 640324.Full description of drum content encl.

 KCOCHAN.W. J. American Hail Line. 64/02/19. 2pp.
- --B012030263 Submits Ofc of Regional Water Pollution Control Board 4 response to AEC 580227 ltr te FR notice of proposed issuance of mati/byproduct license to Isotopes Specialties Co. Application is acceptable.

 LARBON, L. C. California, State of, 58/03/13. ip.
- --B012030244 Submits add1 info re method for preparing barrels for waste disposal in response to AEC 600928 request Provides detailed description of method. Procedure precludes presence of significant voids in barrels. 25 Corbett 601013 1ft encl. ELLIOT.L.P. Galifornia Research Corp. 60/10/14. 4pp.

- --8012030266 Notice of proposed amend of Matl/Bygroduct License O4-05668-O1 authorizing receipt & ocean disposal of waste in add1 types of confainers. KIRK.R.L. Atomic Energy Commission. 61/12/04. 3pp.
- --B012030267 Advises that number of drums to be disposed of is 30 & not 33.as stated in 640919 ltr.
 MC00NAN,W.J. American Mail Line. 64/02/25. ip.
- --8012030268 Discusses disposal operations & activities under license issued on 570331. No trips to see to dispose of radwaste have been made. Estimated 3,000 Ci matl will be disposed of in Pacific disposal ground & 5,000 Ci in Atlantic.

 LAN. J.E. US Ecology, Inc. (Formerly Nuclear Engineering) 58/01/22. 1p.
- --8012030269 Submits supplemental info re Matl/Buproduct License 04-00580-06. Includes sketches indicating types of waste containers that may be used as packaging for radwaste for sea disposal & types of high level waste containers.

 MICHAUD, A. A. Nuclear Corp. of America Isotopes Specialities Co. Div. 27416. 59/10/01. 14pp.
- --8012030270 Discusses application for matl/byproduct license re sea disposal of radwaste. Secondary containers & vehicles transporting radwaste will have appropriate warning labels. MCCLUNO.M.W. Bosing Co. 58/04/20, 1p.
- --8012030272 Advises Coordinator of Atomic Energy Development & Radiation Protection of issuance of Amend & to License 04-05668-01. held by Ocean Transport Co. License Condition 10 has been amended re notification of sea disposal operations. PRICE, E. R. Atomic Energy Commission 60/12/30. 1p.
- --B012030273 Act receipt of 600928 & 29 telegrams re 20-day notification for sea disposal operations. AEC has no objection to request to shorten 20-day waiting period. Requests notification of disposal site & completion date. L Fancey B01011 itr encl. PRICE, H. L. Atomic Energy Commission. 60/10/05. 4pp.
- --B012030275 Application for math/Suproduct license authorizing RF Boswell, LB Bilverman & Q Borg to use &/or supervise use of 100 Ci radwaste of any chemical &/or physical forms for collections storage & processing for see disposal.

 BOSWELL, R. F. Coastwise Marine Disposal. 58/07/05. 3pp.
- --B012030276 Requests info re possible disposal of radwaste by burial at sea. Info should be received prior to 58022B. Also requests names of users of radioactive waste disposal svc.
 BUCHANAN.C.R. Atomic Energy Commission. 58/01/13. 1p.
- --8012030277 Advises that 73 drums of radwaste will be jettisoned on 631115 at depth of 2.097 fathoms. Also provides longitude & latitude of drop. HCODHAN. W. J. American Mail Line. 63/12/04. 1p.
- --8017030278 Requests Commission approval to dispose of thoristed magnesium bundles in baking machines to reduce vol of scrap. Burning scrap prior to packing in 55-gallon drums created difficulties.

 HORGAN-N.E. Boeing Co. 2-1880-9-321, 59/05/26, 1p.
- --B012030279 Notice of Ocean Transport Co application for math/byproduct license to provide radwaste disposal svc.Application specifies max possession limit of 750 Ci byproduct math. 2.000 lb source math & 4 g BM.
 PRICE, E. R. Atomic Energy Commission. 59/08/27. ip.
- --8012030RB0 Responds to AEC 601227 ltr. Darge certified by US Coast Guard will be used in sea disposal operation. Loading will be done at Port of Long Beach. Druns having high radiation levels were discussed in 601222 ltr.
 HOBEG.A.J. Nuclear Corp. of America Isotopus Specialities Co. Div. 60/12/29. ip.
- --8012030282 Forwards notice of proposed issuence of amend to License 04-05668-01, M/a encl.
 KIRK, R. L. Atomic Energy Commission. 61/12/04. 1p.
- --8012030283 Notice of application by Atomic Energy Waste Disposal Svc. for license to provide radweste disposal svc. Application specifies max possession limit of 500 Ci & proposed disposal of waste at specific locations in Pacific Ocean.
 FRICE.H.L. Atomic Energy Commission. 58/10/23. 1p.
- --8012030284 Application for matl/byproduct license, authorizing R Simpson to use &/or supervise use of 200 Cl byproduct & source matl waste to be packaged & stored at NV County. CA site.

 BIMPSON.R. Atomic Energy Waste Disposal Service. 11865.

 58/07/14. 10pp.

- --8012030287 Forwards notice re receipt of Ocean Transport Co application to dispose of radwaste in Pacific Ocean. Further action will be communicated.

 PRICE. H. L. Atomic Energy Commission. 59/08/27. 1p.
- --801203028B Advises that Boeing Co has transferred 73 drums of radwaste for disposal at sea. Matl will be loaded by 631108 & jettisored in min sea depth of 1,000 fathoms. Full description of waste contents & draft license amends encl. MGODMAR, W. J. American Mail Line, 63/10/14. Bpp.
- -8012030290 Responds to 580526 ltr re sea disposal of thorium-magnesium scrap. Proposed method of baling thorium-magnesium scrap in tight packages & disposing at sea is satisfactory. Requests that specific proposal re method be submitted. RUGERS. L.R. Atomic Energy Commission. 2-1880-9-321. 58/06/23.
- --8012030272 Ack receipt of 600901 ltrs re employment of C Koivu & notice of proposed rulemaking which amends 10CFR20 to establish design & packaging criteria for containers used for sea disposal. Comments on rulemaking are voluntary. MASON, J. R. Atomic Energy Commission. 60/09/16. 2pp.
- --8012030273 "Proposal for Collection Processing & Sea Burial of Radwaste Matl." Info partially withheld (rof FOIA Exemption 6). # Coastwise Marine Disposal. 58/09/03, 36pp.
- -8017030274 Forwards data & info re application for mati/byproduct license, in response to AEC 590707 request. STEINAECKER, J. Parr-Richmond Terminal Co. 59/07/23, 9pp.
- -8012030295 Notice of issuance & availability of Amend 2 to Hatl/ Byproduct & Source Matl License 46-03623-01. PRICE: E. R. Atomic Energy Commission. 63/08/30. 2pp.
- -8012030296 Responds to \$20619 ltr re operational status of company. Licensee has no operational contracts wiradioisotope users on West Coast. Facilities for temporary radwaste storage are underway. SIMPSDN.R. Atomic Energy Waste Disposal Service. 11805. 32/07/18. 1p.
- -8012030297 Forwards to City of Richmond, notice of proposed issuance of amend to License 04-05668-01 held by Ocean Transport Co.W/o encl.

 KIRK, R. L. Atomic Energy Commission. 61/12/04. ip.
- -8012030298 Matl/Byproduct License 46-03623-01 for American Mail Line is amended in its entiroty per 620928 application. Amend 2 extends expiration date unitl 650831 & authorizes possession of no more than 200 lb source matl at one time. PRICE, E. R. Atomic Energy Commission. 63/08/30. 2pp.
- B012030299 Ack receipt of applications for extension of matl/byproduct licenses to increase possession limits & provide for use of matl at new facility. Requests addl info before review of application can be continued.

 HITCH. J. W Atomic Energy Commission. 57/11/14. 3pp.
- 8012030300 Ack receipt of 601202 request for add1 info re application for renewal of License 04-0580-06. Response will be provided by mid-Jan 1961.
 KDSE8.A.J. Nuclear Corp. of America Isotopes Specialities Co. Div. 60/12/20. ip.
- 8012030304 Advises that Boeing Airplane Co will be transferring 29 drums of radwaste for disposal at sea. Full description of drum content encl.

 RCODHAN, N. J. American Meil Line. 60/09/13. 4pp.
- 8012030305 Denies application for renewal of License 04-00037-02, due to past failure to determine quantities of hyproduct math received & to maintain records indicating that possession limits of license have not been exceeded. PRICE, H. L. Atomic Energy Commission. 59/08/10. 2pp.
- B012030307 Discusses 600624 application requesting renewal of License O4-00720-02. Requests detailed info re method in which waste will be gackaged to meet apposed criteria in Condition ID. Review of application will continue upon receipt of info. MASON J.R. Atomic Energy Commission, 27498, 60/07/28, 2pp.
- BOIROGOGO Application for matl/buproduct license authorizing receipt & disposal of radwaste transferred by Boeing Airplane Co.
 Request should be considered in conjunction w/Boeing 570617 application.
 WALKER, H. V. American Mail Line. 57/09/IO. 1p.

- ~~8012030309 Provides 20-day notice of intentions to dispose of radwaste at sea. Load will consist of 1,800 containers & total activity of 80,000 mCi byproduct matl, 1,400 lb source matl & 10 g 8kH.
 MOSES, A. J., Nuclear Corp. of America Isotopas Specialities Co. Div. 40/12/13. ip.
- --8012030312 Notifies that Booing Airplane Co has transferred 25 drums of radwaste for disposal at sea. Full description of drum contents enci.
 MCGDHAN, H. J. American Mail Line. 59/08/04. 2pp.
- --B012030314 Forwards Nuclear Engineering Co request for hearing on proposed amend to License i3-10042-01, authorizing burial of solid radwaste at Hanford W/o encl.
 PRICE: H. L. Atomic Energy Commission. 65/07/08, 1p.
- --8012030315 Notifies that Amend 2 has been issued to License 46-03623-01. Amend renews license for 2-yr period & ellows possession of 200 lb source matt. PRICE, E. R. Atomic Energy Commission. 63/09/30. ip.
- --B012090317 Application for matl/byproduct license authorizing HV Walker & HA Greenwood to use & for supervise use of 10 Ci packaged radwaste of any elements w/Atomic Numbers 1-84 for disposal at sea.

 LINTNER: A. R. American Mail Line. 57/10/24. 3pp.
- --B012030318 Notice of issuance of matl/byproduct license to American Mail Line, Ltd to provide radwaste disposal svc. PRICE, E. R. Atomic Energy Commission. 58/08/28. ip.
- --B012030920 Submits info re lab protedures concerning storage of hazardous & nonhazardous raduasts, in response to AEC 600B15 ltr. Contaminated & uncontaminated hazardous industrial & lab chemicals are separately packaged for sea disposal. CONNDLLY, R. J. Navy, Dept. of, 244, 60/09/29, lp.
- --B012030321 Notifies that Amend 2 has been issued to License 46-03623-01 Amend renews license for 2-yr period & ellows possession of 200 lb source metl. PRICE.E.R. Atomic Energy Commission, 63/09/30. ip.
- --B0120303R3 Butmits responses to AEC 570B12 request for add1 info re disposal of radwaste at sea Brawing of radioactive waste vault & storage area encl.
 WISDANL.O.M. Boeing Co. 2-1880-0-221. 57/08/30. 12pp.
- --8012030324 Matl/Byproduct License 46-03623-01 for American Mail Line, Ltd authorizing receipt possession & disposal of 10 Ci byproduct matl & 15 lb source matl. MASON, J. R. Atomic Energy Commission. 58/08/28. 3pp.
- --8012030325 Submits info re application renewal & amend to License 53-00017-04, in response to NRC 650730 request. Includes info re facilities used for radioisotope studies, receipt of radioisotopes & radiation control program.

 TOHNSLEY, B. J. Hawaii, Univ. of, at Monoa, Honolulu, HI. 68970. 65008730. Opp.
- ---8012030326 Amend to License 04-03668-01 adding requirement that each container received from Atomics Intl be weighed separately to assure min average density of 10 lb per gallon before disposal at sea.

 PRICE, H. L. Atomic Energy Commission. 60/11/17, 1p.
- ~~8012030327 Notice of proposed issuance of matl/byproduct license to Military Sea Transportation Svc to dispose of radwaste in Atlantic & Pacific Oceans at min depth of 1,000 fathoms. Proposed license & supporting memo encl. PRICE_H.L. Atomic Energy Commission. 59/07/31. Spp.
- --8012030328 Informs that AEC has issued matl/byproduct license to American Hail Line.Ltd to provide radwaste disposal svc. H/o FR notice & license. PRICE, E. R. Atomic Energy Commission. 58/08/28, 1p.
- --8012030329 Requests confirmation that application for renewal of License 46-03623-01 has been filed w/local officials & date filing was made. Ack receipt of 530427 ltr advising of proposed disposal of radwaste at sea by 530522. CURNINGHAM.R.E. Atomic Energy Commission. 63/03/03. 1p.
- ---8012030330 Requests waiver of requirements of 10CFR20 re transport of radwasts aboard motor vessel. Lists proposed procedures which will be followed to protect shipboard personnel.

 STEINAECKER. J. Parr-Richmond Terminal Co. 40/10/03. ip.

- --B012030331 Responds to telcon re 590616 application re license for disposal of radiaisotopes by ocean burial Requests addl info listed in encl. "Outline of Info to be Submitted in Application for License." W/o encl. MASON, J. R. Atomic Energy Commission. 59/07/22. 2pp.
- --8012030333 Forwards Mat1/Byproduct License 04-00580-06.authorizing disposal of byproduct & source mat1 in Pacific Ocean. PRICE, E. R. Atomic Energy Commission. 58/08/21. 1p.
- --B012030334 Advises that radwaste was jettisoned at sea on 630528. Provides longitude & latitude of drop. Company 630531 ltr to Mayor of Beattle enci. . MCODHAN.W J. American Mail Line. 63/06/13. 2pp.
- --B012030335 Submits proposed methods for collecting, packaging & disposal of radwaste. Includes advertisement tactics, disposal container design info & disposal locations. Application for radiotsotope procurement & magazine article encl. BANTANGELO, J. C. Crossroads Marine Disposal Corp. 15397. 52/07/02. 18pp.
- ---B012030336 Submits summary of radwaste disposal work conducted for off-Commission uses during 1954.completing rept of isotope uses during 1954.Related documentation encl. SANTANGELO.J.C. Crossroads Marine Disposal Corp. 54/12/29, 9pp.
- ---8012030337 Responds to 970617 & 24 ltrs & 570812 telcon re radwaste disposal at sea. Requests addi info to complete review of application, including description of transportation facilities which will be employed.

 HITCH, J. W. Atomic Energy Commission. 57/08/12. 2pp.
- --8012030338 Notice of issuance of mati/byproduct license to Isotopes Specialties Co to provide radwaste disposal svc. PRICE.H.L. Atomic Energy Commission. 38/08/21. 1p.
- --8012030337 Forwards renewal of Mat1/Byproduct License 04-00720-02. Longitudinal & latitudinal coordinates listed in 630402 ltr re radwasts disposal area are correct, Excerpt from Amend 14 encl.

 CUNNINGHAM, R. E. Atomic Energy Commission. 63/05/01. 2pp.
- --8012030340 Forwards new application for radioisotope procurement & 541116 ltr to Corps of Engineers re disposal of radwaste in Boston. MA. dumping area. Disposal methods will remain same. W/o encl engineer permits. BANTANDELO.J.C. Crossroads Marine Disposal Corp. 15397. 54/11/19. 11pp.
- --8012030341 Requests that listed amends be incorporated in 581107 application for amend to Matl/Byproduct License 04-00037-02. Includes info re GC procedures for radwaste disposal, concrete containers & radwaste loading procedures. BIMPSON.R. Atomic Energy Waste Disposal Service. 20225. 59/07/16. 3pp.
- --8012030342 Forwards corrected Page 2 to 570617 radwaste disposal proposal Corrects Section C re concrete. HISDAHL, O. M. Boeing Co. 2-1880-9-187. 57/06/24. 2pp.
- --B012030343 Mati/Byproduct License 04-00580-06 for Isotopes Specialties Co.authorizing receipt possession, packaging & disposal of 10 Ci byproduct matl & 2,000 lb source matl in Pacific Ocean. PRICE, H. L. Atomic Energy Commission. 5B/08/21. 3pp.
- --B012030345 Advises that Boeing Co has transferred 23 drums of radwaste for disposal at sea. Matl will be loaded by 630522 & jettisoned in min sea depth of 1.000 fathoms. Full description of waste contents encl.

 KCODWAN.W. J. American Mail Line. 63/04/29. App.
- ~-8012030346 Responds to 941025 ltr re procedures for renewal of license to dispose of radwaste. Renewal application must be submitted, including new type of instrumentation or changes in other physical equipment &/or waste disposal procedures. FOHLER, E. E. Atomic Energy Commission. 15397. 94/11/08. ip.
- --B012030347 Ack receipt of 650624 ltr giving notice that License 46-03623-01 will expire on 650B31. Forwards application for license renewalradding three names as authorized users &/or supervisors of source matl. W/o encl.
 PELLY/B.B. American Mail Line. 65/08/12. ip.
- --B012030349 Forwards radwaste disposal proposal for AEC approval.
 Radwaste other than wastes originating w/matis specifically
 licensed by AEC will be handled similarly & will not be
 differentiated from Commission controlled wastes.
 HIBDAHL, D. M. Boeing Co. 57/06/17, Zpp.

- --8012030350 Responds to NRC 590616 request for add1 info re mod of License 46-03623-01 re receipt, possession & disposal of prepackaged wastes. Specific disposal locations by latitude & longitude are not available.

 WALKER, H. V. American Mail Line. 59/06/29. 2pp.
- --B012030331 Supports Isotopes Specialists Co.Inc 580308 application for byproduct/matl license. State of CA.House of Representatives 580414 resolution encl. PRICE.E.R. Atomic Energy Commission. 58/08/21, 2pp.
- --B012030352 Forwards US Army Engineer Corps permit for disposal of radwaste in Boston Harbor & Marblehead area. Requests info re 540825 ltr re renewal of authorization to handle radwaste W/o enci. BANTANDELD, J. C. Crossroads Marine Disposal Corp. 54/10/25, 1p.
- --8012030353 "Radwaste Disposal Proposal." WISDAHL, O. M. Boeing Co. 97/06/17. App.
- ~-B012030354 Ack receipt of 630402 ltr re 630321 discussions w/BA Fries & DE Huil concerning License 04-00720-02.Provides longitude & latitude for future radwaste sea disposal.
 BATCHELDER, A. H. California Research Corp. 63/04/22. 1p.
- ~-8012030335 Submits add1 info which should be added to 60092B notification for sea disposal operations. Includes number of radwasts packages received, total Ci content & breakdown of package contents.
 STEIMAECKER, J. Parr-Richmond Terminal Co. 60/09/29. 1p.
- --B012030396 Discusses 600809 explosion at Cross Roads Marine Co which operates disposal svc for waste matls. Requests re-examination of precautionary measures taken to keep haiardous matls separate from low level wastes.

 KIRK.R.L. Atomic Energy Commission. 60/08/15. 2pp.
- --8012030357 Application for matl/byproduct license authorizing JP Carr. OT Linares & JE Steinaecker to use &/or supervise use of 750 Ci assorted byproduct matls, 2,000 lb source matl & 4 g SNM.
 COX.J.P. Parr-Richmond Terminal Co. 59/06/t6. 2pp.
- --801203039B Discusses 940326 ltr re past experience w/unfavorable publicity re disposal of radwaste at sea Subcommittee on Waste Disposal & Decontamination of NCRP has formulated recommendations on disposal at sea.

 MGRGAN.G.W. Atomic Energy Commission. 94/04/07. 1p.
- --8012030360 Notifies that mat! described in 610926 ltr was disposed of on 611011 & 12 Lists longitude & latitude of drop.

 KUEHL/E.C. Parr-Richmond Terminal Co. 61/10/17, 1p.
- --8012030362 Forwards application for renewal of License 04-00720-02 to pracess & use radioisotopes in R&D & to continue program of radioisotope tests in refineries in other states. H/o encl.

 BATCHELDER, A. H. California Research Corp. 48790. 63/01/11. 2pp.
- --8012030364 Mat1/Dyproduct License 20-00685-01 for Crossroads Marine Disposal Corp, authorizing collection, preparation & disposal of byproduct & source mat1 w/Atomic Numbers 3-83.

 4 Atomic Energy Commission. 56/06/22. tp.
- --8012030367 Forwards application for matl/byproduct license.asrial photographs & outline of supporting info.N/o application. STEINAECKER, J. Parr-Richmond Terminal Co. 19567. 39/06/16. 17pp.
- --B01203036B Provides 20-day notification for sea disposal operations.
 Trips will be consecutive except weekends & subj to wind & weather, until cargo is depleted from storage area.
 BTEINAECKER, J. Parr-Richmond Terminal Co. 60/09/28. ip.
- --B012030369 Application for matl/byproduct license to conduct waste disposal svc.authorizing CW Reed to use & /or supervise use of byproduct matl.
 REED.C.U. American Electronics.Inc., Reed-Curtis Nuclear Div. 56/12/12. 2pp.
- --8012030371 Application for mati/byproduct license, authorizing collection, preparation & disposal of 3 Ci byproduct & source mati w/Atonic Numbers 3-83.
 FERRY.O.C.: SANTANGELO.J.C. Crossroads Marine Disposal Corp. 36/06/14. 2pp.
- --8012030373 Matl/Byproduct License 04-04730-01 for Coastwise Marine Disposal Co.authorizing receipt possession, packaging & disposal of byproduct, source & RNM. PRICE, H. L. Atomic Energy Commission. 59/06/09. App.

- --B012030374 Ack receipt of 620927 ltr notifying AEC that disposal of radwaste was made on 620908. Requests notification of any changes in radwaste disposals.

 BASTIN M. Atomic Energy Commission. 62/10/03, 1p.
- --8012030376 Application for renewal of Hatl/Byproduct License 04-03766-01 authorizing possession &/or use of 2,000 Ci byproduct math 15,000 lb source math & 450 g BNN for disposal info partially withheld (ref FOIA Exemption 6). CORBETT. J. S. US Ecology, Inc. (Formerly Nuclear Engineering) 28396. &00/08/03. 27pp.
- --8012030377 Submits supplemental info re application for matl/byproduct license, including possession limits for individual isotopes, methods of disposal at sea-storage, remote handling equipment shielding & work areas.

 CHIPMAN. M. A. Interior, Dupt. of: Fish & Wildlife Service. 56/05/04.

 30p.
- --8012030380 Provides detailed description re packaging of raduaste for disposal at sea in response to AEC 560430 request. Liquid wastes will be put into B3-gallon drums filled w/cement. Application for radioisotope procurement enct. BOROLUGHS, H. Hawaii. Univ. of, at Monoa, Honolulu, HI. 56/05/28. Soc.
- --8012030382 Corrects typographical error made in 590315 ltr re proposed dump site.Lists correct longitudinal & latitudinal coordinates.Belected area conforms w/8tate of GA recommendations for safe disposal. BOSI/ELL, R. F. Coastwise Marine Disposal. 59/06/15. ip.
- --B012030394 Responds to 560110 request for renewal of Authorization 30224 for disposal of radwaste by burial at sea Proposal for disposing of waste at 1,000 fathoms is satisfactory. Requests info re storage facilities for accumulating waste. R00ERS, L. R. Atomic Energy Commission AU-30224. 56/01/25. 1p.
- --B0120303B5 Requests Commission approval to handle transport & dispose of packages of solid radwasts at sea. Inventory lists & results of external radiation & surface contamination surveys entl.

 STEINAECHER. J. Parr-Richmond Terminal Co. 61/08/22. 169pp.
- --B012030386 Application for renewal of Matl/Byproduct License 46-03623-01, authorizing HV Walker to use &/or supervise use of 10 Cl packaged radwaste of elements w/Atomic Numbers I-84. N/except from 620816 memo supporting amend to license. WALKER, H.V. American Mail Line. 62/09/28. 3pp.
- --B012020387 Discusses 1.008 containers prepared for disposal at man by Atomics Intl.Lists approved packages which can be disposed of including matl content & from weight. Fulton Shippard log encl.
 PRICE, H. L. Atomic Energy Commission. 60/07/29, 12pp.
- --8012030388 Forwards application for radioisotope procurement & ltr to Carbide & Carbon Chemicals Co.Lists two immediate aspects of proposed work including passage of fission metals in food chains. II/o encis.

 BDRQUONS.H. Hawaii. Univ. of at Monoa. Monolulu, HI. 34/08/23.

 1p.
- --8012030389 Notice of issuance of Matl/Byproduct License 04-00487-06, authorizing US Naval Radiological Defense tab to receive, possess, package & dispose of byproduct matl in Pacific Ocean, PRICE, M. L. Atomic Energy Commission, 59/05/25, 1p.
- --8012030390 Requests info re raduasta disposal activities by burial at sea. Info must be received prior to 371115. Related documentation enci. BUCHANAN, C.R. Atomic Energy Commission. 57/11/01. Spp.
- --B012030391 Ack receipt of 580728 application for mati/byproduct license for sea disposal of 200 Ci radwaste. Requests addl info to complete review of application, including amount of source mati that will be possessed.

 BUCHANAN, C.R. Atomic Energy Commission. 58/08/29. 9pp.
- --B012030392 Advises that Bosing Co has transferred 38 drums radwaste for disposal at sea. Mati will be loaded by 620903 to jettisoned in min sea depth of 1.000 fathoms. Full description of mati contained in drums encl.

 HGODMAN, W. J. American Mail Line. 62/08/06. 7pp.
- ---8012030393 Notifies of amounts, types & locations of radwarts disposed of in sea All wastes were generated within Army commands in Europe, encased in concrete in 53-gailon steel drums to meet ICG specs.

 CLAUDIUS, H. O. Navy, Dept. of. 153M32. 60/09/16. ip.

- ---B012030395 Application for matl/byproduct license to receive, possess & dispose of 1 Ci thorium & U wastes,
 PERRY.G.C. Crossroads Marine Disposal Corp. 57/09/23. 1p.
- --8012030397 Application for renewal of Matl/Byproduct License 04-00580-06, authorizing possession 2/or use of 500 Ci byproduct matl w/Atomic Numbers 3-83, 2,000 lb U or thorium & 100 g SNN, Related documentation ancl. NEHMAN, K. M. Nuclear Corp. of America Isotopes Specialities Co. Div. 60/07/23, 11pp.
- --8012030398 Forwards Amend 2 to License 53-00017-01 to provide for disposal of waste at soa in response to 570429 ltr. Amend sub; to listed conditions re packaging.
 HITCH, J. H. Atomic Energy Commission. 57/05/28. ip.
- --B012030399 Mat1/Byproduct License 04-00487-06 for US Naval Radiological Defense Lab.authorizing receipt.possession.packaging & disposal of byproduct mat1.

 # Atomic Energy Commission. 59/05/23. 7pp.
- --B012030400 Advises that Boeing Co radwaste was jettisoned on 620908 at depth of 1.957 fathoms.

 HCODWAR, H. J. American Mail Line. 62/09/27. ip.
- --8012030402 Discusses Licanse 20-00685-02, License is effective for 1 yr. Study will be made to evaluate feasibility of disposal on continental shelf. Relocation of dumping area to 1,000 fathoms might be required.
 MORGAN, O. W. Atomic Energy Commission. 57/09/04. 1p.
- --8012030403 Hatl/Byproduct License 04-05668-01 is amended per 600609 application. Amend 3 revises Condition 8 to authorize disposal of byproduct source & BRM by transfer to ORNL. KIRK.R.L. Atomic Energy Commission. 60/08/15. ip.
- --8012030404 Notice of issuance of amend to License 04-00580-06, authorizing possession of 20 g SNM in addition to 100 Ci buproduct matl & 2,000 lb source matl. PRICE,H.L. Atomic Energy Commission. 60/07/22, 1p.
- --B012030405 Provides detailed description re packaging of radwaste for disposal at sea, in response to AEC 570417 request. Two types of disposal containers are used including empty 5-gallon paint cans to 35-gallon of drums.

 BOROUOHS, H. Hawaii, Univ. of, at Monoa, Honolulu, HI. 57/04/29,
- --8012030406 Submits proposed plans for disposing of radwaste at sea.
 Plans will comply w/AEC new law.Requests renewal of
 authorization based on proposed plans.
 SANTANGELO.J.C. Crossroads Marine Disposal Corp. 56/01/10. 2pp.
- ---BD12030407 Forwards Ocean Transport Co radwaste disposal record.Records finalized marine disposal operations. HEWITT.M.L. Parr-Richmond Terminal Co. 62/06/14. 6pp.
- --BOI203040B Notice of proposed issuance of mati/byproduct license to New England Tank Cleaning Co to provide radwaste disposal svc.Proposed license enci. PRICE, E. R. Atomic Energy Commission. 58/08/20, 7pp.
- ~-8012030410 Informs NRC of proposed plans to bid on contract for collecting packaging & disposal of large amounts of radwasts from contractor labs when new sea disposal rule is implemented, New developments will be communicated to AEC. SANTANOELO, J. C. Crossroads Marine Disposal Corp. 55/09/06. 3pp.
- ~~80120304i1 Forwards Doean Transport Co radwaste disposal record.Ocean Transport Co disposed of 291 drums & three blocks on 620522. HEWITT.M.L. Parr-Richmond Terminal Co. 62/05/28. 2pp.
- --8012030412 Matl/Buproduct License 04-00580-06 is amended per 600505 application. Amend 2 revises Condition i, authorizing possession of 20 g SMM & Condition 10 authorizing use of add types of containers for packaging radwaste. PRICE, H. L. Atomic Energy Commission. 60/07/22. 2pp.
- --80120304i3 Responds to AEC 570603 request for info re application for matl/buproduct license. Isotope is any SNM in amount of 500 g & in any chemical form SNM will ultimately be buried at sea. Info partially withheld (ref FOIA Exemption 6). LAM. J. E. US Ecology, Inc. (Formerly Nuclear Engineering) 57/06/18. 2pp.

33

- --8012030416 Matl/Byproduct License 20-00685-01 for Crossroads Marine Disposal Corp. authorizing collection. packaging. storage & disposal of 20 Ci byproduct matl w/Atomic Numbers 3-84 in any form of radwaste.

 * Atomic Energy Commission. 57/08/23. 2pp.
- --8012030417 Supports New England Tank Cleaning Co 571219 application to receive, possess, package & dispose of byproduct math wastes in Atlantic Ocean. Provides info re personnel experience & equipment factilities & procedures. PRICE, E.R. Atomic Energy Commission. 58/08/20, 4pp.
- ---B012030418 Informs that 972 Atomics Intl waste packages were approved for transfer to Ocean Transport Co for sea disposal & 36 containers described as pipe sections were not approved. MABON, J. R. Atomic Energy Commission. SF 724. 60/07/29, ip.
- ---8012030419 Provides detailed responses to AEC 350408 questions re radwaste disposal. Includes info re first & second phase clarification units nuclear reactor filtration units & nuclear filtration engineering.

 SIMPSON, R. Atomic Energy Waste Disposal Service. 35/04/18. 9pp.
- --B012030421 Bubmits, on behalf of Ocean Transport Co.20-day notice of Intentions to dispose of three disposal cubes. Revision 2-60, containing low level wasts. Lists total contents & activity. HEWITY.M.L. Perr-Richmond Terminal Co. 62/04/24, p.
- --8012030422 Forwards responses to NRC 570628 questions re renewal of Mati/Byproduct License 20-00685-01. AEC request to dispose of mati in 1.000 fathom area will severally limit company operations. W/o enci.
 PERRY, O. C. Crossroads Marine Disposal Corp. 57/08/12. 2pp.
- --B012030423 "Container Specs for Intrastate Transportation of AEC Licensed Radioactive Matls."

 * Atomic Energy Commission. 58/08/31. 40pp.
- --8012030424 Notice of issuance of amend to License 04-03668-01, authorizing increase in possession limit of byproduct math source matl & BNM to 1,000 Ci.4,000 lb & 300 g, respectively.

 PRICE, H. L. Atomic Energy Commission, 60/07/15, ip.
- --B012030426 Act receipt of 350117 ltr re radwaste disposal Requests addlenter approach method of radwaste disposal at sea.

 Application for disposal of radwaste by burial in soil is inadequate. Radioisotope procurement application encl.

 MORGAN, G. W. Atomic Energy Commission. 35/02/01. 7pp.
- --8012030427 Submits on behalf of Ocean Transport Co.20-day notice of intention to dispose of 67 35-gallon drums containing solid low level waste.Lists total contents & activity. HEWITT.N.L. Parr-Richmond Terminal Co. 62/04/24, ip.
- --8012030429 Notice of proposed issuance of matl/byproduct license to Malker Trucking Co to provide radwaste disposal syc.Proposed license encl.
 PRICE, E. R. Atomic Energy Commission. 60/08/20. 7pp.
- --8012030430 Matl/Byproduct License 04-05668-01 is amended per applications. Amend 2 increases byproduct metl possession limit & authorizes Ocean Transport Co to package byproduct, source & BNM for sea disposal.

 PRICE, H. L. Atomic Energy Commission. 60/07/15. 7pp.
- --8012030431 Submits on behalf of Ocean Transport Co.20-day notice of intention to dispose of 10 cubes, Revision 2-60, containing solid low level waste. Lists total contents & activity.

 HEWITT, H. L. Parr-Richmond Terminal Co. 62/04/19. ip.
- --8012030434 Supports Walker Trucking Co 580304 application to receive, possessipackage & dispose of hyproduct & source matl wastes in Atlantic Ocean. Provides into re personnel experience & equipment facilities & procedures.

 PRICE, E. R. Atomic Energy Commission. 58/08/20. 3pp.
- --8012030435 Responds to AEC 570428 request for info re radwaste disposal sycs at sea Provides info re packaging of radwaste marking of containers; transportation & disposal of radwaste. Cleverdon: Varney & Pike 570723 ltr encl.
 PERRY, O. C. Crossroads Marine Disposal Corp. 57/08/12. 4pp.

- --8012030436 Forwards Ocean Transport Co radwaste disposal record. Includes disposal date & site & number of drums. HENITT,M.L. Parr-Richmond Terminal Co. 62/04/11. 4pp.
- ~-B012030438 Requests AEC concurrence in changing pressure relief pipe sys in concrete disposal container by increasing pipe diameter-eliminating pipe from present location-eliminating check valve & attaching protective screen.

 CDX.J.P. Parr-Richmond Terminal Co. 60/07/14, 2pp.
- --8012030440 Responds to 890825 telegram re proposed issuance of license to Military Bea Transportation Bvc for ocean disposal of low level radwasta. Conference has been scheduled for 800923 w/state & local officials to discuss sea disposal policies. PRICE. H. L. Atomic Energy Commission. 59/09/08. 2pp.
- --8012030442 Application for meth/byproduct license authorizing HL Andrews to use &/or supervise use of any elements, consistent w/procurement license, for disposal at sea. Disposal procedures & magazine article encl. ANDREMS:H.L. Health & Human Services: Dept. of, 16414. 59/02/12. Epp.
- --8012030443 Application for renewal of Matl/Byproduct License 20-00485-02 authorizing OC Perry & JJ Nuss to use &/or supervise use of 200 Ci byproduct natl.w/Atomic Numbers 3-84 in any form of radwaste for storage & disposal. PERRY. G. C. Grossroads Marine Disposal Corp. 58/07/28. 2pp.
- --8012030444 Act receipt of 570619 request for 90-fay extension on License 20-00685-01 Expiration data has been extended until 570831 Lists various phases of waste disposal program AEC will be re-evaluating & reviewing Requests response. HITCH, J. W. Atomic Energy Commission. 57/06/28. 3pp.
- --8012030445 Forwards Amend 2 to Litense 04-00487-06, changing location for disposal of packaged radwastes at sea. W/o encl. KIRK, R. L. Atomic Energy Commission. 62/04/09. 1p.
- --8012030446 Lists matls which Bosing Co has transferred for disposal at eas. Mati will be loaded by 650824. W/o full description of matl contents.
 PELLY. 8. 8. American Mail Line. 65/08/03. ip.
- --8012030447 Provides outline to Health Dept re AEC visit to Crossroad Marine Disposal Corp re rad⊘este disposal svc.AEC discovered that company records for disposal of radwaste were not in compliance w/AEC requrements. Action has been taken.
 HITCH:J.W. Atomic Energy Commission. 57/06/20. 2pp.
- --8012030448 Forwards add1 info in support of application for matl/ byproduct license & in response to AEC 580414 request. Related documentation delineating functions of disposal operations enci. HORTMAN.D. Nuclear Chem Disposal Corp. 59/02/11. 31pp.
- --8012030447 Requests that Licenses 04-03766-01 & 04-03766-03 be amended to add MD Johnson as authorized user of byproduct matl. License 04-03766-01 should be amended to provide for ocean disposel of 450 g waste.

 CURDETT.J. B. UG Ecology, Inc. (Formerly Nuclear Engineering) 59/09/04. 2pp.
- --8012030450 Forwards application for renewal of Matl/Byproduct License 20-00685-01. Applicant is expanding program to acquire new ships & related equipment & larger facility in preparation for sea disposal of radwaste. Requests AEC concurrence. PERRY, Q. C. Crossroads Marine Disposal Corp. 57/06/19. 2pp.
- ---B012030431 Discusses IE insp of License 20-00685-02 on 570916.
 Noncompliance noted:records of receipt & disposal of licensed matl were not maintained & steel drums containing radioactive matl were not labeled w/caution symbol & words.
 MASON, J. R. Atomic Energy Commission. 38/06/19. 2pp.
- --8012030452 Matl/Byproduct License 04-00580-06 is amended per 590514 application. Amend changes name of licenses to Isotopas Specialties Co & revises Conditions 3 & 5 authorizing J Vaden to supervise byroduct matl.

 MASON.J.R. Atomic Energy Commission. 60/06/24. 7pp.
- --8012030453 Confirms 610919 request for info, per meeting discussion. Info re weight & content of 29 drums & weste liners generated by QE is required before review of matl/byproduct application will be continued.

 MASON, J. R. Atomic Energy Commission. 61/09/27. 2pp.
- --8012030454 Informs that application for renewal of Matl/Byproduct License 20-00685-01 will be denied unless addl requested info is provided within 20 days. MASON: J. R. Atomic Energy Commission. 39/02/09. ip.

- --8012030455 Ack receipt of ltr re proposed issuance of license for sea disposal of radwaste off NJ coast More info is needed re sea disposal of radwaste before method is authorized for any appreciable amounts of radwaste. MEYNER, R. B. New Jørsey, State of, 59/09/02. 1p.
- ~~8012030497 Forwards Amend 2 to License 04-00487-06 issued to Dept of Navy.License authorizes charge in location for disposal of packaged radwastes at sea Wo encl.
 KIRK,R.L. Atomic Energy Commission. 62/04/09.
- --8012030459 Application for renswal of Matl/Byproduct License 20-00685-Ol, authorizing receipt, possession & disposal of 3 Ci byproduct matl w/Atomic Numbers 3-83 in all types of wastes, PERRY.G.C. Crossroads Marine Disposal Corp. 57/06/20, 2pp.
- --8012030460 Ack receipt of notification re-receipt of Walker Trucking Co-application to provide radwaste disposal svc.Lists questions for response. BCOTT.W.J. Connecticut: State of. 58/06/17. 2pp.
- ~-8012030461 Lists units that were not disposed of as scheduled on 601025 due to weight limitations. Total activity disposed of on 601026 was 7.013 Ci.

 BROWN.J.M. Health & Human Services, Dept. of.. 60/11/10. ip.
- --8012030462 Bubmits info re radwaste disposed of at sea for yr ending 570630, in response to AEC request.US Corps of Engineer 57038 ltr encl.
 PERRY.O.C. Grossroads Marine Disposal Corp. 57/06/19. 4pp.
- --8012030463 Notice of proposed amend to License 04-00580-06, authorizing receipt, packaging & disposal of 20 g SNM, 100 Ci byproduct met! & 2,000 lb source matl. Supporting draft mean encl. PRICE, H. L. Atomic Energy Commission. 60/06/24. 4pp.
- ~-8012030464 Forwards to Ofc of Atomic Energy Development & Radiation Protection, Amend 2 to License 04-00487-06, issued to Dept of Nevy, authorizing change in location for disposal of packaged radwasts at soa.

 KIRK.R. L. Atomic Energy Commission. 62/04/09. ip.
- --8012030465 Bubmits on behalf of Louer Cape Committee on Radwaste Disposal questions re proposed plans to establish disposal site off Cape Cod MA. including longitudinal & latitudinal coordinates radwaste origination & possession limits.

 LEHAC N . DELDED. J . Affiliation Unknown. 59/08/31. 1p.
- --8012030466 Lists contents of radwaste shipment schedulad for sea disposal on 591112 in accordance u/Condition B of License 19-00296-11. BROWN J. M. Hoalth & Human Services. Dopt. of.. 59/10/30. 2pp.
- --8012030467 Notice of issuance of Amend 3 to License 20-03541-01, authorizing New England Tant Cleaning Co to receive, possess, package & dispose of source & SMM in Atlantic Ocean. MADON J.R. Atomic Energy Commission. 98/12/31, 2pp.
- --8012030468 Application for renewal of Mati/Dyproduct License 4A-03623-01, authorizing HV Walker, HA Orsenwood, HH Clarke, U Jorgenson & E Hoadman to use &/or supervise use of 10 Ci slaments w/Atomic Numbers 1-34 & 200 1b source mati. HALKER, H. V. American Mail Line. 65/07/30. 2pp.
- --8012030469 Notifies of intentions to dispose of radwaste during wk of 611009 at designated marine site. Inventory consists of matl packaged in six Geen Trasport Co disposal blocks. Revision 2-60 & four 53-gallon concreted drums.

 KUEHL, E. L. Parr-Richmond Terminal Co. 61/09/26. Ip.
- --8012030470 Notice of proposed amend of License 04-05668-01, authorizing increase in possession limit of byproduct mat1, source mat1 & SNN & packaging of waste in precast concrete blacks. Supporting draft memo encl.
 PRICE, H. L. Atomic Energy Commission. 60/06/23. 4pp.
- --8012030471 Mati/Byproduct License 04-00487-06 for Dept of Navy,US Naval Radiological Defense Lab is amended in its entirety, Amend 2 authorizes radwaste burial at min depth of 1,000 fathoms in Facific Ocean within designated areas. KIRK,R.E. Atomic Energy Commission. 62/04/09. 1p.
- --B012030472 Forwards to Ofc of Radiation Control, proposed license for Military Sea Transportation Svc to dispose of radwaste in Atlantic & Pacific Oceans, License requires AEC notification 20 days prior to disposal operations, W/o enci. PRICE,H.L. Atomic Energy Commission. 59/08/28. 1p.

- --8012030473 Lists contents of radwasta shipment scheduled for sea disposal on 601020 in accordance w/Condition 8 of License 19-00296-11.
 BROWL J. M. Health & Human Services, Dept. of, 60/10/24. 2pp.
- --8012030474 Mat1/Byproduct License 20-03541-01 for New England Tank Co is amended. Amend 3 authorizes receipt possession, packaging & disposal of 50 1b source & 5 g SNM in Atlantic Ocean. MASDN: J. R. Atlanic Energy Commission. 38/12/31. 2pp.
- --8012030475 Application for renewal of Hatl/Byproduct License 32-00426-01, authorizing possession &/or use of 25 mC1 P-32 & Ca-45, 75 mC1 Sr-87, Cs-137, Ru-106, Ca-141 & Ce-144, 20 mC1 Co-60 & 125 mC1 mired fission products in any chemical form. CHIPMAN, M. A. Interior, Dept. of, Fish & Wildlife Service. 58/05/16.
- --8012030476 "Bummary of Radioactive Matls Packaged on 650310 for Disposal at Sea." * Atomic Energy Commission. 65/07/27. 1p.
- --8012030477 Matl/Byproduct License 04-00487-06 for Dept of Navy.UB Naval Radiological Defense Lab is amended in its entirety per 610302 & 0511 applications. Amend 1 authorizes receipt, possession, packaging & disposal of byproduct matl. KIRK.R.L. Atomic Energy Commission. 62/01/29. 8pp.
- --B012030477 Requests that AEC postpone granting of any permits or licenses for disposal of radwaste or atomic waste matls off coastal shores or territorial waters of Commonwealth of MA. Requests that gublic hearing be held in Boston, MA. TURKER, M. A. DOLAN, J. F. Hassachusetts, State of. 59/08/25. ip.
- --8012030480 Ack receipt of 581119 ltr re disposal of two Cs-137 sealed sources. AEC must complete processing of application for renewal of License 20-00685-02 before request can be considered. Requests add1 info to complete review.

 MASON, J. R. Atomic Energy Commission. 58/12/23. 2pp.
- --8012030481 instructs NRC to proceed w/requests for renewal of license & sea disposal of Livermore drums. Other requests should be held in abeyance until after visit to GE.
 HEWITT.H.L. Parr-Richmond Terminal Co. 61/09/25. ip.
- --8012030482 Responds to 600826 itr re 600809 explosion in Boston & restricting use of radwaste within city limits. Use of radioactive mat under AEC jurisdiction is subj to restrictions or controls to assure safe use.
 PRICE, E. R. Atomic Energy Commission. 60/09/16. 2pp.
- --B012030483 Requests amend to Page 26 of application for matl/byproduct license. Matl will be dumped 110 miles due southeast of Montauk Point,Long Island. HARRIG.R.E. Walker Trucking Co. 98/05/01. ip.
- --8012030484 Application for amond of Matl/Byproduct License 20-03541-01, authorizing possession & disposal of no more than 50 lb source act k 5 g SMM.

 DENALUT, E. W. New England Tank Cleaning Co. 58/12/10. 1p.
- --8012030485 Requests public hearing re issuance of license to Military Sea Transportation Svc for disposal of atomic wastes off coast of Cape Cod.MA. ATKINS.J.D., MOTHERWELL.B.L., WALKER.I.G. Provincetown, MA. 89/08/24.
- --B0120304B7 Forwards 641202 rapt that shipment of radwasts was juttisoned at sea on 641116. Also provides latitude & longitude of drop.
 PELLY.B. B. American Mail Line. 65/07/23. 2pp.
- --8012030489 Provides add1 info to Section F.Page 24 of supplemental manual to radwaste disposal application. All containers will be weighed & not released for final sea disposal until min average density has been attained.

 HARRIS.R.E. Nuclear Cham Disposal Corp. 58/04/18. 1p.
- --8012030490 Forwards Ocean Transport Co radwaste disposal records.
 Includes disposal date & site & number of drums.
 HENITT.M.L. Parr-Richmond Terminal Co. 62/04/06. Spp.
- --8012030491 Requests authorization to take possession of two Kel Ray projectors, Model CA, containing 40 & 80 Ci Cs-197, for disposal at sea. Projectors in locked & sealed condition will not be opened.

 PERRY, O. C. Crossroads Marine Disposal Corp. 58/11/19. 1p,

- -8012030492 Responds to 590810 ltr re license held by Crossroads Disposal Corp. Clarifies Conditions 6 & 11 of License 20-00685-02.
 - Atomic Energy Commission. 57/08/26. 2pp.
- --8012030493 Notifies of Ocean Transport Co disposal of radwaste at Commission, US Navy, US Coast Guard & State of CA disposal site. Radwaste consisted of 200 ib source matl. 4, 3705 Ci byproduct matl & 22 2 mCi radium. Details encl.
 STEINAECKER, J. Parr-Richmond Terminal Co. 61/08/31, 4pp.
- --B012030494 Responds to application for matl/byproduct license re sea disposal of radioisotopes & source matl. Requests addl info to complete application review M/o encl outline of info guideline. HITCH.J.W. Atomic Energy Commission. 58/04/14. 4pp.
- --8012030497 Informs of radwaste shipment to be disposed of at sea on 600620 under License 19-00296-11. Shipment will consist of 23 55-gallon drums from NBS. Max activity will be 25 mci. Most hazardous radioisotopes will be Co-60. 59-90 & U-233.
 BROWN.J.M. Health & Human Services, Dept. of. 60/06/08. 1p.
- --8012030498 Matl/Byproduct License 04-03766-01 for Nuclear Engineering Co.Inc is amended in its entirety per 650127 application.
 Amend 22 authorizes receipt possession, packaging, storage & disposal of byproduct, source & SIM,
 JOHNSON, L. Atomic Energy Commission. 62/05/20. 17pp.
- --B012030499 Submits on behalf of Ocean Transport Co.20-day notice of intention to dispose of two cubes.Rev 2-40.containing raduate.Lists disposal cube contants.

 HEWITT.M.L. Parr-Richmond Terminal Co. 42/03/09. ip.
- --8012030800 Discusses proposed amend to Mati/Byproduct License 20-03541-01 for disposal of radwaste at sea Requests AEC approval to store radioactive mati in newly acquired bidg. Bidg offers more security than previous storage area. DENAULT, E. M. New England Tank Cleaning Co. 58/11/04. ip.
- --B012030301 Submits Ofc of Radiation Control request info re identities & quantities of radwasts to be disposed of at sea per proposed license to Military Sea Transportation Svc. BLATZH, New York, NY. 57/08/18. [p.
- --B012030502 Submits amands & changes to application for byproduct matl & waste disposal license. Supplemental manuals of applications will be provided.

 HARRIS.R.E. Walker Trucking Co. 10134. 58/04/10. 2pp.
- --8012030504 Mati/Byproduct License 32-00426-01 for UB Fish & Wildlife Svc.authorizing possession &/or use of 25 mCi P-32.Ca-45 & Co-59.75 mCi Br-89.Cs-137.Ce-141.Pm-147 & Zn-65 & 124 mCi mised fission products in any form.
 MABON.J.R. Atomic Energy Commission, 58/10/29. 2pp.
- --B012030505 Advises of proposed issuance of matl/byproduct license to Military Sea Transportation Svc for sea disposal of waste byproduct, source & SNM in Atlantic & Pacific Oceans. Hestes would be packaged by AEC licenses & contractors.

 PRICE.E.R. Atomic Energy Commission. 59/08/14. 1p.
- --8012030596 Notice of receipt of Nuclear-Chem Disposal Byc application for license to provide raduasts disposal svc. Excerpt from AEC 580320 ltr to MIT encl. PRICE, H. L. Atomic Energy Commission. 58/04/04. 2pp.
- ---BO17030507 Notifies that four S5-gallon concrete-filled drums of radwaste were jettisoned at sea on 650424. Lists approx contents of drums, ETZLER, D. H. California Research Corp. 65/05/20. ip.
- --8017030507 Lists add1 units being prepared for shipment & sea disposal per 600511 ltr.
 BROWN, J. M. Health & Human Services: Dept. of.. 60/05/18. 1p.
- --8012030311 Requests to make appearance in proceeding rellicensing of Walker Trucking Co for mgt & disposal of radweste in State of CT. Lists major issues to be addressed. Also requests final order if indigent to provide the content of the conte
- --8012030512 Responds to AEC 610220 ltr re redesignation of radwastedisposal site. US Naval Radiological Defense Lab has no objection to suggested redesignation of ocean area defined as suitable for disposal of radwastes.

 BIRCH.T.L. Navy. Dept. of, 730-24. 62/03/01. 1p.

- --8012030513 Opposes proposed issuance of license to Military Sea Transportation Svc for disposal of low level radwaste off MA coast due to possible danger to public health & safety. Requests that formal hearing be held. WALL.N.X. Massachusetts, State of. 59/08/12. 1p.
- --B012030314 Ack receipt of 580213 ltr re storage of raduaste preparatory to disposal at sea. Bludy is being made to evaluate feasibility of disposal on continental shelf. Results should be helpful in providing position disposal guidelines. HITCH, J. W. Atomic Energy Commission. 58/03/04. 1p.
- ---8012030515 Ack receipt of 600511 ltr advising of intent to conduct waste disposal operation on 600324. Requests that provisions be made for AEC inspector on opean voyage.

 MASON J. R. Atomic Energy Commission. 60/05/17. 1p.
- --B012030516 Forwards AEC announcement re land burial facilities for radwaste. Suggests mod of application to provide for waste disposal svc utilizing land burial facilities.
 PRICE, H. L. Atomic Energy Commission. 60/05/19. ip.
- --8012030517 Natice of application for license to provide radwaste disposal svc to Crossroads Marine Disposal Corp. Application specifies mak possession limit of 200 CI any byproduct matl having Atomic Numbers 3-84.

 PRICE, H. L. Atomic Energy Commission. 58/10/23. ip.
- --B012030519 Advises of proposed issuance of matl/buproduct license to Military Bea Transportation Svc for disposel of waste buproduct source & SNN in Atlantic & Pacific Oceans Mastes would be packaged by AEC licensees & contractors. PRICE, H. L. Atomic Energy Commission. 59/08/12. 1p.
- --8012030520 Application for matl/byproduct license.authorizing H
 Olasser & M Lazarus to use &/or supervise use of 5 Ci
 byproduct matl & 1.000 lb source matl w/Atomic Numbers 1-83.
 |KORTMAN.D. Nuclear Chem Disposal Corp. 58/03/07. 2pp.
- -9012030521 Advises of proposed issuance of meth/byproduct license to Military Bea Transportation Svc for disposal of waste byproduct; source & BHM in Atlantic & Pacific Desans, Mastes would be packaged by AEC licensees & confractors.
 PRICE, H. L. Atomic Energy Commission. 59/08/12. 1p.
- ---8012030522 Ack receipt of 580922 application for matl/buproduct license re-sea disposal of radipisotopes. Requests add1 info to complete review of application including model number-make & sensitivity range of contamination survey instrument. HITCH, J. W. Atomic Energy Commission. 58/10/17, 3pp.
- ~-B012030523 Bubmits contents of radwaste shipment scheduled for sea disposel on 600524 in accordance U/conditions of License 19-00296-11. BRQNN.J.M. Health & Human Services, Dept. of.. 60/05/11. 2pp.
- --B012030524 Advises of proposed issuance of matl/byproduct license to Military Bee Transportation Bvc for dispusal of waste byproduct source & SNN in Atlantic & Pacific Deems. Mastes would be packaged by AEC licensees & contractors. PRICE.H.L. Atomic Energy Commission. 59/08/06, 1p.
- --8012030525 Informs that AEC proposes to amend License 04-00487-06, changing radwaste disposal area to coincide w/designated explosive disposal area.

 MASON, J. R. Atomic Energy Commission. 62/02/20. ip.
- ~-8012030526 Advises of proposed issuance of matl/Suproduct license to Military Bra Transportation Svc for disposal of wasta byproduct.source & ENM in Atlantic & Pacific Oceans. Hastes would be packaged by AEC licensees & contractors. PRICE.H.L. Atomic Energy Commission. 59/08/04. 1p.
- --8012030527 Matl/Byproduct License 20-03541-01 for New England Tank Clashing Co, authorizing receipt, possession, packaging & disposal of 1.000 Ci byproduct matl in Ablantic Ocean, MASON.J.R. Atomic Energy Commission. 58/10/09. App.
- --8012030528 Forwards application for hat1/byproduct license to dispose of radwaste at sea, Provides outline for disposal method & radiological safety procedures. N/o encl.

 MORTMAN. D. Nuclear Chem Disposal Corp. 58/03/05. 3pp.
- --8012030529 Order granting motion to reopen Industrial Haste Disposal Corp proceeding to admit RN Goodwin 620119 ltr. to deny license application & to terminate proceeding. Related documention encl.

 MCCODL.N.B. Atomic Energy Commission. 62/04/20, Opp.

- B012030530 Notice of issuance of amend to Matl/Bygroduct License 19-00269-11 held by NIH.authorizing 2-yr renewal of license. PRICE,E.R. Atomic Energy Commission. 63/09/24. 2pp.
- 8012030531 Bubmits dates, sites & estimated activity of waste disposed of from 1949 through 1939. BROWN, J. M. Health & Human Services, Dept. of, . 59/12/17. ip.
- 8017030532 Submits info re mati/byproduct license application, in response to AEC 580726 request Clarifies receipt, possession & disposal operations of current activities under Mati/Byproduct License 04-02314-01.

 LAN.J.E. US Ecology. Inc. (Formerly Nuclear Engineering) 58/10/09. App.
- 8012030533 Informs that AEC has issued amand to Matl/Byproduct License 20-00685-02 held by Crossroads Marine Disposal Corp. License has been amended effective 590815 to require use of ramote sites for disposal of low level radwaste.

 MASDN, J. R. Atomic Energy Commission, 59/08/04, 2pp.
- B012030534 Forwards to City of Richmond-Ocean Transport Co applications for renewal of License 04-05668-01 % disposal of concrete blocks. Application for concrete blocks deferred pending Commission studies re sae disposal containers. Wo encl. MABON. J. R. Atomic Energy Commission. 62/02/08. 1p.
- B012030535 Responds to AEC request for info re method to be used to offload & handle containers in raduatte disposal operations. Integrity tests were conducted on large drums. Adequate lifting devices will be used to load large drums. MICHAUD. A. A. Nuclear Corp. of America Isotopes Specialities Co. Div. 60/03/24, ip.
- 9012030536 Ack receipt of AEC 580928 ltr re proposal to dump radwaste off Montauk Point. Opposes sea disposal of radwaste. Requests that AEC withhold licensing of Walker Trucking Co until added safety precaution is incorporated in proposed license. LYNCH.C.A. Affiliation Unknown. 58/10/08. 2pp.
- 3012030537 Mati/Byproduct License 19-00296-11 for NIH is amended in entirety per 630430 & 0624 applications. Amend 2 authorizes receipt possession, packaging & disposal of 50 Ci byproduct mati.
 PRICE, E. R. Atomic Energy Commission. 63/09/24. 7pp.
- 1012030539 Hotions to deng Industrial Waste Disposal Corp application for mati/byproduct license to receive & store radwaste, & to terminate proceeding, Certificate of Svc ancl.
 HADLOCK, O. F. Atomic Energy Commission. 62/03/21. 10pp.
- 1012030539 Forwards to Coordinator of Atomic Energy Development & Radiation Protection.Ocean Transport Co applications for renewal of License 04-05668-01 & disposal of concrete blocks.U/a encl.

 MABON.J.R. Atomic Energy Commission. 62/02/08. 1p.
- 1012030540 Provides list of radwaste disposed of from 1946 to Aug 1939 In Atlantic Ocean. PERRY, Q. C. Crossroads Marine Disposal Corp. 60/02/15. 1p.
- 012030541 Informs Health Dept that AEC has issued amend to Matl/Byproduct License 20-00685-02 held by Crossroads Harine Disposal Corp. License has been amended effective 590815, to require use of remote disposal vites for low level radwaste. MABON, J. R. Atomic Energy Commission. 59/08/04. 1p.
- 012030542 Application for matl/buproduct license authorizing RE Harris to use &/or supervise use of 15 mCi enriched U as contamination on steel scrap & combustible matl.3 mCi Co-60 in 2.00 gallons of water & 3 mCi Fe-59 in water. HARRIS,R.E. Walker Trucking Co. 58/03/04. 3pp.
- 012030543 Ack receipt of 580915 ltr & telegram re AEC proposed issuance of license to Walker Trucking Co for disposal of radwasts in Atlantic Ocean Radwasts disposal will not pose threat to public & environ health & safety.
 PRICE, E. R. Atomic Energy Commission. 58/09/26, 2pp.
- 012030544 Informs that Mati/Buproduct License 46-03623-01 will expire on 600831. Requests that application for license renewal be submitted in order to continue program. Future disposal activities will be limited within 5-mile radius.

 MAEON. J. R. Atomic Energy Commission. 60/06/09. 1p.
- 012030545, Informs that AEC has issued Amend to Mati/Bygroduct License 20-00685-02 held by Crossroads Marine Disposal Corp. License has been amended effective 970815, to require use of remote disposal sites for low level radwaste. PRICE: H. L. Atomic Energy Commission. 59/07/27, 2pp.

- --8012030846 Application for renewal of Matl/Byproduct License 20-00685-02, authorizing receipt, possession & disposal at sea of 200 Ci isotopes w/Atomic Numbers 3-83 & 4,000 lb source matl.

 PERRY, O. C. Crossroads Marine Disposal Corp. 58/09/22, 7pp.
- --8012030547 Provides add1 info to be incorporated in application for mat1/byproduct license, including storage info, mat1 used for containers, radwaste transportation & disposal operations.

 DENAULT, E. H. New England Tank Cleaning Co. 58/02/27. 2pp.
- --B01203054B Opposes AEC proposed action to dispose of radwaste by land burial urges that competitive action be suspended due to disastrous economic results that would affect independent waste disposal firms.

 HUFFIT.D. US Ecology, Inc. (Formerly Nuclear Engineering)
 3176. 60/05/10. 2pp.
- --8012030549 Notifies of 610731 redwaste disposal operation. Includes infore max activity in containers, time of disposal & number of containers. No unexpected or abnormal events occurred, No leaking from container was observed.

 BANNER, R. H. Coast Quard, Transportation, Dept. of. HDMLEY, J. R. HHG, Dept. of, US Public Health Service. 61/07/31. 2pp.
- ---B012030330 Requests that AEC reconsider terms in proposed license to Walker Trucking Co to dipose of radwaste at sea. AEC should increase distance from Long Island at which disposal is to be made.

 LYNCH, W. A. Affiliation Unknown. 59/09/15. 2pp.
- --B012030551 Forwards safe handling methods for large radwaste containers.
 MGSES.A.J. Nuclear Corp. of America Isotopes Specialities Co. Div. 60/05/06. 3pp.
- ~-8012030352 Responds to 611278 ltr re application for license to dispose of package low level radwasts in Oulf of Mexico. Approval of radwasts disposal in Oulf would have serious harmful effects on US relations w/Mexico.

 GDODWIN, R. N. State, Dept. of. 62/01/19. 2pp.
- --8012030553 Matl/Byproduct License 32-00426-02 for DDI.Fish & Wildlife Svc is amended in entirety per 630716 application. Amend if authorizes possession & use of 25 mCf P-32 & 25 mCf Ca-45 in any chemical or physical form for research. BRINKMAN.R.E. Atomic Energy Commission. 63/08/12, 4pp.
- --8012030555 Notice of issuance of Matl/Byproduct License 20-03541-01 to New England Tank Cleaning Co to provide radwaste disposal svc. PRICE.H.L. Atomic Energy Commission. 58/10/20. 1p.
- --B012030557 Mati/Byproduct License 20-00584-02 for Crossroads Marine Disposal Corp is amended per 590619 application. Amend 3 authorizes increase of possession limit to 1.000 Ci byproduct mati & 16.000 lb source mati. Supporting memo encl. PRICE, H. L. Atomic Energy Commission. 59/07/23. 11pp.
- --B01203055B Matl/Byproduct License 19-00296-11 for NIH is amended per 610307 application. Amend 1 extends license expiration date to 630630 revised Condition B re notification of disposal & adds Condition 9 re recordkeeping.
 KIRK.R. L. Atomic Energy Commission. 61/06/19. 2pp.
- --B012030559 Order to show cause & denial of applications for amend to License 04-04730-01 authorizing increase in possession limits of byproduct mati & BNM transportation of radwaste under higher radiation levels.

 PRICE.M.L. Atomic Energy Commission, 59/04/13, 6pp.
- --0012030560 Matl/Byproduct License 42-04230-01 for Industrial Waste Disposal Corp. authorizing receipt possession & storage of byproduct matl & transfer of matl to ORNL.

 KIRK.R.L. Atomic Energy Commission. 60/08/10, 6pp.
- --8012030362 Submits contents of radwaste shipment schedule for sea disposal on 610731, in accordance w/Condition 8 of License 19-00294-11.

 ANDREWS.H.L. Health & Human Services, Dept. of, 61/07/17. 2pp.

- --B012030563 Notice of issuance of Matl/Byproduct License 20-00685-02 to increase possession limit to 1,000 Ci byproduct matl & 16,000 lb source matl. PRICE,H.L. Atomic Energy Commission. 59/07/23, 2pp.
- --8012030564 Informs that AEC has issued Amend 6 to Matl/Byproduct License 20-03541-01 held by New England Tank Cleaning Co. Amend renews license for 2 yrs. PRICE, E. R. Atomic Energy Commission. 63/07/11. ip.
- --8012030565 Requests to be informed of changes in waste disposal field which might apply to organization to minimize financial burden on customers.

 PERRY, O. C. Grossroads Marine Disposal Corp. 58/02/13. 1p.
- --B012030366 Notifies of 610731 radwaste disposal trip. Further details will be communicated,
 ANDREMS, H. L. Health & Human Services, Dept. of., 61/07/05. 1p.
- --B012030567 Informs that AEC has issued Amend 6 to Matl/Byproduct License 20-03941-01 held by New England Tank Cleaning Co. Amend renews license for 2.yrs. PRICE, E. R. Atomic Energy Commission. 63/07/11, 1p.
- --8012030569 Application for matl/byproduct license, authorizing receipt, possession & disposal of raduasts.

 4 Halker Trucking Co. 58/02/28, 50pp.
- --B012030570 Notice of issuance of Amend 6 to Matl/Byproduct License 20-03541-01, authorizing 2-yr license renewal. PRICE, E. R. Atomic Energy Commission. 63/07/11, 2pp.
- ---BOIRO30571 Submits info re radwaste disposal operations conducted under Matl/Byproduct License 32-00426-01, in response to AEC 580620 ltr. Includes location of disposal site, container info & matl content.

 CHIPMAN, W. A. Interior, Dept. of, Fish & Wildlife Service. 10763. 38/07/07. 2pp.
- --B012030572 Application for renewal of Matl/Byproduct License 20-00685-02, authorizing receipt, possession, use & disposal of 100 g BMM & 16,000 lb source matl in all forms except BMM. License except encl.
 PERRY, O. C. Crossroads Marine Disposal Corp. 61/06/29. 18pp.
- --B012030573 Notifies of proposed waste disposal trip to sea.utilizing UB Coast Guard facilities. Shipment will consist of 24 vaults & il steel drums centaining no more than 5 Ci of activity. Exact schedule & disposal date will be communicated. ANDREHB, H. L. HHB, Dept. of, UB Public Health Bervice. 69/04/23.
- ~-8012030374 Notice of receipt of New England Tank Cleaning Co application for license to provide redweste disposal sycs. Application specifies max possession limit of 1.000 Gi total byproduct matl. PRICE/H.L. Atomic Energy Commission. 58/01/20. ip.
- ~-8012030575 Forwards list of wastewater per 590629 telcon.Requests advisement as to whether metl could be dumped in ocean at dumping grounds under present license, using dilution method. PERRY.G.C. Crossroads Marine Disposal Corp. 38/07/01. 2pp.
- --8012030576 Matl/Byproduct License 20-03541-01 for New England Tank Cleaning Co is amended in its entirety per 630128 application, Amend 6 authorizes receipt possession, packaging & disposal of byproduct, source & SNM. PRICE, E. R. Atomic Energy Commission. 63/07/11. Spp.
- --B012030578 Opinion & final decision re Industrial Waste Disposal Corpapplication for math/byproduct license. Approves application for receipt & storage of packaged low level byproduct mathoniy. Except from order encl.

 MCCONE, J. A., GRAHAM, J. B., Atomic Energy Commission. 60/06/22.

 41nn.
- --8012030579 Forwards Amend 5 to Matl/Buproduct License 20-03541-01, renewing license for 2 urs & authorizing transfer of licensed waste to AEC dasignated land burial sites for disposal. W/o encl.
 LOWENSTEIN,R. Atomic Energy Commission. 61/03/16. 1p.
- --8012030580 Provides info in response to AEC request re application for renewal of License 20-03541-01. Original application for license remains same w/exception that Lovell Island will not be used as disposal site.

 DENAULT, E. W. New England Tank Cleaning Co. 63/04/16, 2pp.

- ~-8012030581 Forwards NiH application for renewal of License 19-00296-11 authorizing disposal of low level radwaste in Atlantic Ocean. H/o encl.
 PRICE. E. R. Atomic Energy Commission. 63/06/13. 1p.
- --8012030582 Submits responses to AEC 580103 questions re application for matl/byproduct license to dispose of radwaste. Yearly summaries of radwaste dumped in Pacific Ocean by UB encl. DENAULT, E. H. Walker Trucking Co. 58/01/17. 8pp.
- --8012030584 Requests addl info re 380516 application for renewal of Matl/Byproduct License 32-00426-01. Review of application will continue upon receipt of info.
 BOWYER, J. E. Atomic Energy Commission. 58/06/20. 1p.
- --B0120305B5 Forwards Amend 5 to Matl/Byproduct License 20-03541-01, renewing license for 2 yrs & authorizing transfer of licensed waste to AEC designated land burial sites for disposal. W/o encl.
 LOWENSTEIN.R. Atomic Energy Commission. 61/03/16. ip.
- --8012030586 Notice of issuance of Amend 2 to Matl/Byproduct License 20-03541-01: held by New England Tank Cleaning Co. to store & package byproduct matl for sea disposal. MASON, J. R. Atomic Energy Commission. 58/12/11. 2pp.
- --B0120303B7 Advises that Industrial Waste Disposal Corp has applied for license to dispose of radwaste in Oulf of Mexico. Commission will take no final action w/respect to pending applications for initial licensing for sea disposal. PRICE.H.L. Atomic Energy Commission. 60/01/15. 1p.
- --8012030589 Informs that License 20-03541-01 will not expire until renewal application has been determined by Commission. BUCHANAN.C.R. Atomic Energy Commission. 60/10/21. 1p.
- ~-8012030590 Application for renewal of Matl/Byproduct License 20~00685-02 authorizing possession, use & disposal of 3,000 cf tritium:100 g BNH & i6.000 lb source matl in all forms steept BNN.
 PERRY, G. C. Crossroads Marine Disposal Corp. 19388. 59/06/19. 1600.
- --8012030591 Matl/Buproduct License 20-03541-01 is amended per 581104 application.Amend 2 revises Condition 7 re storage & packaging of byproduct matl for sea disposal.

 MASON, J. R. Atomic Energy Commission. 37/12/11, ip.
- --8012030593 Notifies that Mayor of Poston MA has been issued listed documents. Company wishes to retain license for sea disposal. DENAULT, E.R. New England Tank Cleaning Co. 63/04/04. 28p.
- --8012030594 Responds to 621022 ltr.Revised radwaste disposal instruction is satisfactory.License requires that only individuals named in license can prepare radwaste for disposal.

 BABSIN.N. Atomic Energy Commission. 62/10/29. 1p.
- --8012030595 Discusses briefing paper for K Eisenhower in anticipation of 590812 trip to Mexico. Revises statement re radwaste disposal in Gulf of Hexico.
 DALTON: A. T. Atomic Energy Commission. 59/08/13. 2pp.
- --8012030596 Notice of application by Halker Trucking Co for license to provide radwaste disposal svc. Application specifies max possession limit of 50.216 Ci total any byproduct & source matl.

 PRICE.H. L. Atomic Energy Commission. 58/06/13. ip.
- ~-8012030397 Notifies AEC of waste disposal trip scheduled during first 2 wks in Nov 1959 from NIH Bethesda HD to Norfolk VA.
 Description of metl will be provided.
 BROUN. J. M. Health & Human Services. Dept. of.. 39/10/20. 1p.
- --B012030600 Responds to 590809 ltr re proposed issuance of license to NIH to dispose of low level radwaste in Atlantic Ocean. Forwards memo outlining principle factors considered in proposed license. W/o encl. ROCERS.L.R. Atomic Energy Commission. 59/03/28. 1p.
- --B012030602 Forwards updated info concerning disposal of radwaste in Oulf of Mexico, in response to DOB request & in anticipation of M Eisenhower trip to Mexico.

 VIOSEL.C. C. Atomic Energy Commission, 59/08/16, 2pp.

- --B012030603 Requests that radwaste disposal instructions be revised to conform w/terms & conditions of License 20-00695-02 Receipt of liquid waste is not permitted. Packaging of sea disposal must be done by 0C Perry or JJ Nuss.

 BASSIN N. Atomic Energy Commission. 62/09/27. 1p.
- ---8012030605 Requests to intervene in proceeding re proposed issuance of matl/byproduct license to authorize disposal of waste in Atlantic Ocean at depth of 1.000 fathoms.FR notice encl. TORSON.O.W. Affiliation Unknown. 59/05/09, 2pp.
- --8012030606 Application for renewal of Matl/Byproduct License 20-C0285-02, to provide radwaste disposal operation. Requests authorization to dispose of wastes at any authorized land burial site in US.
 MURPHY, J. D. Allied-Crossroads Nuclear Corp. 64/09/04. 7pp.
- ---8012030697 Forwards amend to Crossroads Marine Disposal Corp application for renewal of License 20-00685-02. GOLD.0.W. Gold.0.W. 42/01/08. lp.
- --8012030608 Informs that Commission has issued matl/byproduct license to NIH authorizing disposal of low level radwaste in Atlantic Dean. Forwards proposed FR notice.
 PRICE.H.L. Atonic Energy Commission. 59/05/28. 1p.
- --8012030609 Requests response to Congressman Ropers 890804 request for info re manner in which AEC supervises & polices licensees for lowing issuance of license for sea disposal of low level radwaste. Transmittial sheet enci.

 DOMOVAWAR X. Atomic Energy Commission. 59/08/05, 2pp.
- --8012030611 Amend to application for renewal of License 20-00685-02, changing address of facility & adding JP Cronin as user & radiation protection officer.

 4 Crossroads Marine Disposal Corp. 62/01/08. App.
- --B012030612 Nutice of issuance of Matl/Byproduct License 19--00276--11 to NIH to receive package.possess & dispose of byproduct matls in Atlantic Dean. PRICE,H.L. Atomic Energy Commission. 59/05/23. 1p.
- --8012030614 Submits contents of radwaste shipment schedule for 620820 sea disposab in accordance u/Condition 8 of License 19-00296-11.

 BROWN, M. Health & Human Services, Dent. of ... 62/08/10 2nn.
- --8012030615 Mat1/Byproduct License 19-00296-t1 for NIH authorizing receipt-possession packaging & disposal of byproduct mat1 in Atlantic Ocean.
 PRICE.H.L. Atomic Energy Commission. 59/05/25. 6pp.
- --8012030616 Notifies of radwaste disposal at sea on 640819 in accordance w/Condition B of License 19-00296-11. Shipment consisted of 24 concrete vaults containing 3.05 Ci byproduct matl, BRONN.J.M. HMS, Dept. of, US Public Health Service. 64/08/24.
- --801203061B Notifies of raduaste disposal trip by 620810. Coast Quard facilities will be utilized. Further details will be communicated. ANDRENS, H. L. Health & Human Services, Dept. of. 62/08/03. 1p.
- --8012033619 Submits addl & corrected info re application for matl/ byproduct license per NRC request Application should be amended to read 100 Ci byproduct matl & 1.000 lb source mat. Corrects typographical error re disposal site. HORIMAN, D. Nuclear Chem Disposal Corp. 18965. 39/09/14. 4pp.
- --B012030621 Submits contents of raduaste shipment scheduled for sea disposal on 620620 in accordance w/Condition 8 of License 19-00296-11. BROWN.J. M. Health & Human Services, Dept. of.. 62/06/29. 2pp.
- ---B012030622 Notifies of proposed waste disposal trip on 640B19 in accordance w/Condition 8 of License 19-0029611. Goast Guard Pacilities will be utilized.

 BROWN, J. M. HHS, Dept. of, US Public Health Bervice. 64/08/03.
- --8012030623 Notifies of waste disposal trip scheduled for 590518 from NIH. Arrangements can be made for NRC inspector to perticipate. FR notice encl.
 BROWN.J. M. Health & Human Sprvices. Dept. of.. 59/05/07. 4pp.
- --8012030625 Submits info re contents of radwaste shipment scheduled for 620619 sea disposal in accordance u/Condition B of License 19-00296-fit.
 BROWN,J.M. Health & Human Services, Dept. of, 62/06/08. 2pp.

- --B012030627 Notifies of proposed waste disposal trip to sea in May 1962. Coast Quard facilities will be utilized. Further details uill be communicated. ANDREWS.H.L. Health & Human Services: Dept. of.. 62/05/09. 1p.
- --8012030628 Matl/Byproduct License 20-00685-02 is amended per 640207 application. Amend 8 revises Condition 2 re disposel, packaging & receipt of byproduct matl. PRICE.E.R. Atomic Energy Commission. 64/03/25. ip.
- --8012030429 Notice of proposed issuance of matl/byproduct license to NIH to dispose of low level radwaste in Atlantic Ocean. Proposed license & supporting memo encl. PRICE, H. L. Atomic Energy Commission. 59/04/27. 12pp.
- --8012030631 Matl/Byproduct License 20-00685-02 to Crossroads Marine Dispusal Corp is amended in entirety per 610627 & 1217 & 620108 & 0127 applications, Amend 5 authorizes receipt, packaging & disposal of byproduct, source & SNM at sea, KIRK, R. L. Atomic Energy Commission. 62/04/19. 9pp.
- --8012030432 Notice of application by Nuclear Engineering Co. Inc for license to provide radwaste disposal svc. Application specifies max possession limit of 400 Ci total byproduct & source mati & 2 g SNM.

 PRICE.H.L. Atomic Energy Commission. 58/03/31, ip.
- --8012030433 Add1 amends to application for renewal of License 20-00485-02, adding mods to roof of proposed facility & mode to customer instructions, ravising pressure relief valve & eliminating name of JP Cronin.
 PERRY, G. C. Crossroads Marine Disposal Corp. 62/01/27, 4pp.
- --8012030635 Informs that AEC has issued Amend 10 to License 20-00685-02 held by Allied-Crossroads Nuclear Corp. Amend deletes authority for storage of radwaste matls in Dorchester MA & for disposal by buriel at sea.

 MCBRIDE, J. A. Atomic Energy Commission. 65/08/24, 1p.
- --B017030437 Discusser resolution contained in L Bmitzes 590716 ltr re AFC intentions to authorize raduaste disposal in Gulf of Hexico area. Transmittal sheet encl. LUEDECKE.A.R. Atomic Energy Commission, 59/07/31. 3pp.
- --8017030639 Informs that AEC has issued Amend 10 to License 20-00685-02 held by Allied-Crossroads Nuclear Corp. Amend deletes authority for storage of radwaste matls in Dorchester, MA & for disposal by burfal at sea.

 MCDRIDE, J. A. Atomic Energy Commission. 65/08/24. ip.
- ---B012030440 Forwards Tarpon Springs Sponge Exchange 590716 resolution protesting radwaste disposal into Gulf of Mexico. Requests review & comment.

 SHATHERS. G. Benate. 59/07/21. 2pp.
- --8012030644 Forwards Amend 10 to License 20-00685-02, Amend deletes authority for storage of radwaste matts in Dorchester, MA & for disposal by burial at sea, W/o encl. MCBRIDE, J. A. Atomic Energy Commission. 65/08/24. ip.
- --B012030645 Responds to 590803 ltr forwarding TX Qame & Fish Association 590729 ltr. Industrial Waste Disposal Corp application to dispose of radwaste is scheduled for oral argument before Commission on 591013.

 DQNAVAN
- ---8012030646 Statument before Joint Committee on Atomic Energy re H.R. 9187, restrictions on dumping of radwaste into Gulf of Hexico. YARBORGUOH, R. Senate. 59/07/29, 2pp.
- --8012030647 Notice of Amend 9 to Matl/Byproduct License 20-80685-02, deleting authority for storage of radwaste in Dorchester, MA & for disposal by burial at sea.

 * Abomic Energy Commission. 65/08/24. 2pp.
- --8012030648 Bubmits info re Commission instructions & regulations for licensing disposal of radwaste at sea, in response to 590618 request. Forwards NBS Handbook 58, "Disposal of Radwastes in Ocean." W/o enci.
 BUCHANAN, C. R. Atomic Energy Commission. 59/07/01, 2pp.
- --8012030649 Responds to 590615 ltr transmitting Corpus Christi, TX, Chamber of Commerce 590613 telegram re application of Industrial Waste Disposal Corp for license to dispose of low level raduaste in Gulf of Mexico.

 PRICE, H. L. Atomic Energy Commission. 59/07/15. ip.

- --8012030650 Mati/Byproduct License 20-00685-02 for Allied-Crossroads Nuclear Corp is amended in entirety per 650603 application. Amend 10 authorizes receipt & possession of waste byproduct packages for disposal at land burial sites, * Atomic Energy Commission. 65/08/24. 6pp.
- --B012030651 Notifies that radwaste shipment was disposed of at sea on 650714. Lists contents, serial number, weight & activity of shipment.

 BROWN, J. M. HHB. Dept. of US Public Health Service. 65/07/16.
- --8012030653 Discusses 590620 ltr transmitting W Negley 590619 ltr re Industrial Maste Disposal Corp application for license to dispose of low level radwaste in Oulf of Mexico. AEC is in process of final action. Related info encl. LUEDECKE.A.R. Atomic Energy Commission. 59/07/10. 9pp.
- --B012030454 Exceptions to Examiner immediate decision to grant license to Industrial Haste Disposal Corp to receive process, package & dispose of radwaste in Gulf of Mexico Certificate of Gvc encl.

 NEHMAN, E. W. Sportmen's Club of Texas, Inc. 39/06/17. 15pp.
- --8012030454 Application for amend to Matl/Byproduct Licanse 20-00485-02, deleting Amend 9, due to economic considerations, HURPHY, J. Allied-Grossroads Nuclear Corp. 65/07/08, 1p.
- --8012030487 Proposed findings of fact & conclusions re Industrial Waste Disposal Corp application for math/byproduct license.License should be denied due to threat posed to public health & safety. Certificate of 8vc encl.

 NEWMAN, E. W. Bportmen's Club of Texas, Inc. 59/04/10. 13pp.
- --B012030660 Response to applicant findings of fact & conclusions of law re Industrial Waste Disposal Corp application for math/ byproduct license. Applicant failed to produce sufficient evidence to guarantee safe operation of waste disposal. SMITH.F.L. Nucces County.TX. 59/04/10. 2pp.
- --B012030661 Bubmits resolution adopted by Galveston Chamber of Commerce Board of Directors re Industrial Waste Disposal Corp application for license to receive process & package radwaste for disposal in Gulf of Hexico. * Texas: State of, 59/06/17. 2pp.
- ---8012030462 Discusses Jersey City Real Estate Board, Inc 570716 resolution re disposal of radwaste in Atlantic Ocean, Sea disposal operations are being conducted in manner that is adequate to assure protection of man & matural resources. KIRK, R. L. Atomic Energy Commission. 59/10/12, 3pp.
- --B012030664 Intermediate decision re Industrial Waste Disposal Gorp application for matl/byproduct license to receive, store & dispose of radwaste. License is granted. Senate resolution & excerpt of testimony & pleading encl. JENSCH, S. W. Atomic Energy Commission. 59/08/29. 40pp.
- --B012030667 Responds to Commission on Atomic Energy 591001 telcon reproposed issuance of license to Military Sea Transportation Byc to dispose of radwaste in Ablantic & Pacific Oceans. Forwards notice of proposed issuance of license. W/o encl. MASON, J. R. Atomic Energy Commission. 59/10/01. 2pp.
- --8012030668 Notice of proposed issuance of matl/byproduct license to Industrial Maste Disposal Corp to provide radwaste disposal svc.Draft license & supporting memo encl.

 MABON, J. R. Atomic Energy Commission. 58/11/24. 9pp.
- ---8012030670 Responds to 590902 ltr re proposed issuance of license to Military Bea Transportation Svc to dispose of radwaste in Atlantic & Pacific Oceans. Radwaste is minimal. Forwards NRC statement re present sea disposal practices. Wo encl. PRICErH. L. Atomic Energy Commission. 59/09/21. 2pp.
- --8012030672 Notifies of proposed 650713 waste disposal at sea. Coast Ouard facilities will be utilized. Shipment will consist of six concrete vaults containing 4.310 CI activity. BROWN, J. M. HHB, Dept. of, US Public Health Service. 65/06/15. ip.
- --8012030673 Resolution by Jersey City Real Estate Board, Inc opposing disposal of radwaste in waters adjacent to shores of NY & NJ until further studies are made. Atomic waste should be stored to prevent future contamination.

 KOORSE, S. H. Affiliation Unknown, 59/09/16, 1p.

- ~-8012039676 Matl/Byproduct License 32-00426-02 for DDI, Fish & Wildlife Syc is amended in entirety per 650129 application. Amend 17 authorizes possession & use of no more than 100 mCi any radionuclide. except Au-198 & mired fission products.
 BRINKMAN, R. E. Atomic Energy Commission. 65/02/18. 3pp.
- --8012030677 Confirms 590911 telcon re sea disposal of radwaste.
 Conference has been scheduled for 590923 w/state & local
 officials to discuss AEC policies re sea disposal of
 radwaste.Determination of formal hearing will follow.
 PRICE, H. L. Atomic Energy Commission. 59/09/16. 2pp.
- --8012030678 Mati/Byproduct License 20-00685-02 for Allied-Crossroads Nuclear Corp is amended in entirety per 640904 application. Amend 9 authorizes receipt, transport & storage of waste byproduct. source & SNM for disposal at sea. JOH480N.L. Atomic Energy Commission. 65/01/08, 9pp.
- --8012030682 Notifies of proposed 670630 radwaste disposal trip.US Coast Guard facilities will be utilized.Shipment will consist of six concrete vaults containing 30, 5 cl activity. BROWN.J.M. HHS. Dept. of, US Public Health Service. 67/05/29, ip.
- --B012030683 Responds to 590812 itr re proposed issuance of license to Military Sea Transportation Svc to dispose of prepactaged low layel waste in Atlantic & Pacific Oceans Forwards notice of proposed issuance of license. W/o encl. PRICE, H. L. Atomic Energy Commission. 59/09/08. 3pp.
- --8012030685 Requests revision of application for renewal of License 20-03541-01, deleting continued authority to dispose of waste at sea. Waste disposal will be by transfer to authorized persons. Related info encl.

 DENAULT, E. H. New England Tank Cleaning Co. 67/05/12. 2pp.
- --8012030688 Forwards application for amend to Matl/Byproduct Licenses 04-02314-01 & 04-02314-02 to include AL Smith as authorized user of byproduct matl. Also submits addl info to be included in 580215 application for waste disposal license. LAN.J.E. US Ecology. Inc. (Formerly Nuclear Engineering) 58/04/02. 2pp.
- --8012030472 Application for amend of Hatl/Byproduct Licenses 04-02314-01 & 04-02314-02 to include AL Smith as authorized user of byproduct matl.

 * UB Ecology, Inc. (Formerly Nuclear Engineering) 59/04/02. ip.
- --8012030693 Forwards Hatl/Byproduct License 20-00683-01, authorizing disposal of byproduct & source matl. License is valid for 1 yr. Requests to be informed of radwaste quantity disposed of during valid period. Wirelated info. License not encl. RODERB. L.R. Atomic Energy Commission. 36/06/RR. 14pp.
- --B012030696 Supple info provided on 590211 re application for license to dispose of radwaste at sea, including type of waste containers, weight & possession limits.

 ANDREWS.H.L. Realth & Human Services: Dapt. of, 59/03/10. 1p.
- 8012030004 FOIA requestion behalf of N Lewis & J Conwellifor documents relates used for dumping radwaste in Pacific Ocean.

 SPAIN. 9. H. Affiliation Unknown. 80/08/23. 3pp. 07150:030.
- 8012030864 Responds to FOIA request for abstracts of NRC computer programs available to public. NRC has no documents subj to request. Info may be obtained from Technical Data Mgt Ctr, NTIS &/or Natl Computer Code Ctr. FELTON.J. H. Division of Rules and Records. 80/11/25, ip. 07149:245.
- BO12030869 FDIA request for abstracts of NRC computer programs available to public.

 MDDNEY.C.P. Engineering Design Concepts.Inc. 80/10/30. ip. 07149: 244.
- 8012030874 Responds to FDIA request for info re routes & quantities of 14 spent nuclear fuel shipments passing through Binghamton, NY. Forwards NUREG-0725 & NRC Announcement 80-191, W/o NUREG-0725. FELTON, J. M. Division of Rules and Records. 80/11/21, ip. 07149:238.
- --8012030882 Excerpts from "Spent Fuel Route Survey.Ogdensburg.NY to 8avannah River Facility, 8C."

 * Commissioners. 79/11/30. 3pp.
- 8012030878 FOIA request for info re routes & quantities of 14 spent nuclear fuel shipments passing through Binghamton, NY, 8WARTILANDER, D. Sun-Bulletin Singhamton, NY, 80/07/11. 1p. 07149; 239.

- 8012030918 Responds to FOIA request for all documents commenting on final rule 10CFR40. "Deletion of Source Matl Medicinals from Oeneral License of Small Quantities of Bource Matl." Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 80/11/21. 2pp. 07151:130.
- B012030722 FDIA request for all documents commenting on final rule iOCFR40. "Deletion of Source Matl Medicinals from General License of Smell Quantities of Source Matl."

 WATSON.T.M. FGI Service. 001386. 80/11/05. ip. 07151:132.
- B0120B0103 Responds to F01A request for records re NRC apposition to making fire protection rule applicable to future plants or licenses & future application of rule.Forwards documents listed in App A. FELTON. J. H. Division of Rules and Records. 80/12/02. 2pp. 07:00-107
- ---B0120B011B Comments on proposed App B re fire protection Disagrees ω/ waiver of requirement for automatic fire suppression & supports five member fire brigade for most plants. SCHROEDER, F. Division of Bystems Safety. 79/11/13. ip.
- 8012080107 FOIA request for records re NRC apposition to making fire protection rule applicable to future plants or licenses & future application of rule.
 WATKINS, ff. Debeyoise & Liberman. 80/11/18. 3pp. 07189: 189.
- 8012090161 Add1 response to FOIA request for nine categories of info re fees concerning withdrawn, suspended or postponed applications. App lists documents provided. FELTON.J.M. Division of Rules and Records, 80/11/26, 2pp. 07190;295.
- --8012080174 Responds to 770211 memo re development of proposed schedule of license fees. Functions which are attributable to issuance of specific domestic licenses have been reviewed. One function was identified. Related info encl. BTRAUSS.P.L. Office of the General Counsel. 77/02/23. 4pp.
- --8012080179 Bubmits changes to SECY-77-201 re proposed revised schedule of license fees. Pager should be approved for publication. STRAUSS-P.L. Office of the General Counsel. 77/04/20. 2pp.
- --8012080183 Forwards QAO rept. "Establishing Proper Fee Schedule Under Independent Ofcs Appropriation Act, 1952." Rept may be of interest in view of NRC efforts to establish revised fee schedule, Draft SECY paper encl.

 MCTIERNAN.T.J. Office of Inspector & Auditor. 77/06/13. 5pp.
- 8012110140 Responds to FOIA request for six categories of info rm fire protection requirements in App R to 10CFR50. Forwards draft rept. "Fire Protection for Colocated Elements of Redundant Divs." which will be placed in PDR.
 FELTON.J.M. Division of Rules and Records. 80/12/03. ip. 07223:346.
- --8012110157 Forwards preliminary draft rept. "Fire Protection for Colocated Elements of Redundant Divs." CAKPBELL, J. A. Gage-Babcock Associates, Inc. 7917-3. 79/08/07. 1p.
- --B012110164 Preliminary draft rept, "Fire Protection for Colocated Elements of Redundant Dive.

 ** Gage-Babcock Associates, Inc. 79/08/07. 29pp.
- BOL2110146 FOIA request for six categories of info re fire protection requirements in App R to 100FR50.

 WATKINS.M. Debevoice & Liberman. 80/11/18. 2pp. 07223:347.
- B012110184 Partial response to FOIA request for info re spent nuclear fuel transportation routes including those utilized by military packaging shipments & matts being transported. Forwards draft NUREQ-0725 & NUREQ-0383, M/o encl. FELION. J. M. Division of Rules and Records, 80/12/03, 1p. 07224:078.
- BOI2110193 FOIA request for info re spent nuclear fuel transportation routes, including those utilized by military nature of packaging, shipments & practise matis being transported. DAVIB.N.J. California, Univ. of Banta Cruz. 80/10/29, 2pp. 07224:079

- 8012110200 Responds to FOIA request for all documentation re Armadillo Coalition of TX or any affiliate organizations. Forwards documents listed in App A. FELTOR, J. M. Division of Rules and Records, 80/11/26. 3pp. 07224:081.
- ---B012110218 Forwards FOIA request for documents re Armadillo Coalition of TX. Requests documents subj to request number of documents which may be withheld from public disclosure & any problems anticipated in processing request & response, IV.d encl. CARR, J. C. Division of Rules and Records. 80/09/19. 1p.
- --B0121i0225 Requests that listed documents be provided in response to FOIA request re Armadillo Coalition of TX.

 CARR.J.C. Division of Rules and Records. B0/07/22. 2pp.
- --8012110231 Forwards documents subj to FOIA request re Armadillo Goalition of TX,8/o encis.
 BAILEY,I.X. Records Services & Facilities Branch. 80/09/26. 1p.
- --8012110238 Advises that Div of Security has no documents subj to FOIA request re Armadillo Coalition of TX.
 KIDD.D.G. Security Policy Branch. 80/07/29. 2pp.
- --8012110245 Forwards FOIA request for documents re Armadillo Coalition of TX. Requests documents subj to request number of documents which may be withheld from public disclosure & any problems anticipated in processing request & response. No encl. CAR, J. C. Division of Rules and Records. 80/11/12, 1p.
- --8012110232 Advises that IE has no documents subj to FDIA request re Armadillo Coalition of TX. HULLINIX,W. Office of Inspection & Enforcement. Office of the Director. 80/11/20. 1p.
- 8012110206 FOIA request for all documentation re Armadilio Coalition of TX or any affiliate organizations. Affidavit of identity encl.
 BELIN.A. Center for Law in the Public Interest. 80/11/06. 2pp. 07224:084.
- 80:12110/208 Responds to FOIA request for spent fuel transportation route from BNL through NY City & proposed route through Long Island. RRC has no documents subj to request. DOE may be contacted for info. FELTON: J. H. Division of Rules and Records. 80/12/03. 1p. 07224:086.
- 8012110216 FDIA request for spent fuel transportation route from BNL through NY City & proposed route through Long Island, GROSSMAN.K. Island Closeup News Bervice. 80/11/18. ip. 07224:087.
- 80:12:10438 Add1 response to FDIA request for documents re nuclear incident in USBR in 1955. Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 80/12/05. 2pp.
- --8012110445 BECY-79-416
 Provides Commission w/summary of reported events in UBBR resafety of peaceful nuclear activities. Forwards listing of reported UBBR nuclear events, news articles renuclear event & evaluation papers & repts.

 SHEALJ.R. Office of International Programs, Director. 79/06/26.
- --B012110452 OL8-79-124
 "Safety Problems of PWR Reactors." Related documentation encl.
 SIDDRENKO, V. A., VOZNESENSKII, B. Union of Boviet Socialist Republics. 77/06/26. 33pp.
- --8012110460 Forwards Nuclear Sefety article entitled: "Another Perspective of 1958 UBBR Accident, " First page only enci, OILINEKY, V. Commissioners. 79/06/07. 2pp.
- --BO12110465 Ack receipt of matls prepared by research depts on how TMI incident was handled in eastern Europe & USBR. Future related documentation should also be provided, OILINSKY. V. Commissioners. 79/06/07. 1p.
- --8012110471 Forwards mat! prepared by research depts on how TMI incident was handled in eastern Europe & USBR Includes rept on USBR nuclear power program & description of broadcast operations.

 BUELL.W.A. Radio Free Europe/Radio Liberty, 79/05/30. 1p.

- 8012110520 Responds to FOIA request for documents, submitted by Needles Desert Star, re-precautions taken on spent fuel shipments near Needles.CA & info concerning control of truck speeds. Forwards documents listed in App A. W/o antls. FELTON, J. N. Division of Rules and Records. 80/12/04. 2pp. 07227:143.
- B012110521 FOIA request for documents, submitted by Needles Desert Star, re precautions taken to provide security on spent fuel shipments near Needles.CA & info concerning control of truck speed.

 B0UIBB.J.F. Affiliation Unknown. B0/10/25. 1p. 07227:145.
- 8012110524 Addl response to FOIA request for documents to NRC consideration of licensing facility & transcripts of closed Commission meetings. Forwards CN Smith 790927 memo. Info partially withheld (ref FOIA Exemption 3). FELTON, J. M. Division of Rules and Records. 80/12/04. 2pp.
- --8012110528 Trip rept of 790918-21 visit to facility to investigate excessive inventory difference for June-Aug 1979, Provides chronology of events. Info partially withheld (ref FOIA Exemption 3).

 SMITH.C.N. Material Control Licensing Branch. 79/09/27. 4pp.
- 8012110535 Responds to FOIA request for memoranda of understanding between NRC & FEMA. Forwards two memoranda of understanding between NRC & FEMA for incident response & radiological emergency planning & preparedness.
 FELTON.J.H. Division of Rules and Records. 80/12/05. 1p. 07227:150.
- --8012110538 Hemorandum of understanding between NRC & FEMA re radiological emergency planning & preparadness. CAMM.F.A. Federal Emergency Management Agency. 80/11/04. 6pp.
- B012110542 FOIA request for memoranda of understanding between NRC & FEMA noted in encl press release.

 OROBEMAN, K. Island Closeup News Service. 80/11/28. 2pp. 07227:151.
- 8012i10643 Partial response to FOIA request for documents reimposition of civil penalties. NRC requests for congressional authorization for more severe ponalties & responsibilities & behavior of nuclear plant operators. Forwards documents. FELTON, J. M. Division of Rules and Records. 80/11/20. 2pp. 07227:209.
- --8012110656 Responds to 800312 inquiry concerning implementation of nuclear power plant staff work hours in TMI action plan. Overtims work does not have priority that would justify immediately effective rulemaking, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 80/05/07, 2pp.
- --8012110662 Discusses human factors study of nuclear power plant operator shift work. Forwards CF Ehret 800114 ltr proposing measurement of plant operators using ambulatory, visual & other body function measuring devices.

 FARKER, H. B. Research Support Branch (Pre 801119). 80/02/29. 1p.
- --8012110785 Provides review of current activities re circadian connection to shift work, including description of expertise in area & urgent need for initiating program of proposed activities, Summary enci.

 EHRET, C. F. Argonne National Laboratory, 80/01/14, 2pp.
- --B012110770 Forwards proposed Reg Ouids 1.xur. "Factors to be Considered Before Allowing Licensed Personnel to Manipulate or Direct Manipulation of Controls of Nuclear Power Plant." Requests comments on listed questions. FARMER.H.B. Research Support Branch (Pre 801119). 78/01/06. App.
- --B012110668 Forwards A Swain review of proposed Reg Guide 1,
 "Factors to be Considered Before Allowing Licensed Personnel
 to Manipulate or Direct Manipulation of Controls of Nuclear
 Power Plant" & related working paper.
 FARMER.N.B. Research Support Branch (Pre B01119). 78/01/31. 1p.
- --8012110764 Forwards comments on proposed Reg Guide 1. xyr, "Factors to be Considered Before Allowing Licensed Personnel to Manipulate or Direct Hanipulation of Controls of Nuclear Power Plant."

 BMAIN.A.D. Bandia Laboratories, 78/01/23, 6PP.
- --B012110777 "Effects of Hours on Job on Visual Detection & Decision Making H/Implications for Nuclear Power Plant Personnel." BWAIN.A.D. Sandia Laboratories. 78/01/20, 18pp.

- --8012110678 Provides background info on proposed Revision 1 to Reg Ouide 1.114, "Quidance on Being Operator at Controls of Nuclear Power Plant." Includes comment resolution & implementation schedule. ARLOTTO, O.A. Office of Standards Development, Director. 76/10/07, 200.
- ---8012110782 Draft of Revision 1 to Reg Guide 1.114, "Guidance on Being Operator at Controls of Nuclear Power Plant," * Office of Standards Development, Director, 76/09/15. 2pp.
- --8012110787 Comments on Reg Quide 1.114. "Quidance on Being Operator at Controls of Nuclear Power Plant." Section C. 1 should be modified to remove implication that changing conditions always requires corrective action on part of parator. CAMILL, U. J. Consolidated Edison Co. of New York. 76/04/16. ip.
- --B012110792 Comments on Reg Guide 1.114. "Quidance on Being Operator at Controls of Nuclear Power Plant." Strict interpretations of provisions in Section B.Paragraph 2 could preclude nuclear plant operator from performing data logging & review tasks. JQHNBON; W. P. Yankee Atomic Electric Co. 76/04/01. ip.
- --8012110800 Comments on Reg Quide 1.114. "Ouidance on Being Operator at Controls of Nuclear Power Plant." Quide can be improved by more strongly emphasizing importance of sound design for controls used during normal operating situations.

 8CHERER, A. E. C-E Power Bystems. LD-76-044. 76/04/20. 2pp.
- --B012110806 Comments on Reg Guide 1,114, "Quidance on Being Operator at Controls of Nuclear Power Plant." Paragraph C. 4 should differentiate between temporary relief & formal relief as conducted during shift change. UHRIQ.R.E. Florida Power & Light Co. L-76-154, 76/04/08. 1p.
- --8012110810 Comments, submitted by Nuclear Engineering Svc Co.on proposes Reg Ovide 1.114, "Guldance on Being Operator at Controls of Nuclear Power Plant." More stringent enforcement should be implemented. Resolution of public comments encl. YOUNGS, R. A. Affiliation Unknown. 021-6-41. 76/03/03. Spp.
- --8012110B18 Value/impact assessment of proposed Revision 1 to Reg Quide 1.114, "Quide to Being Operator of Controls of Nuclear Power Plant." Reg guide is consistent w/SRP.Bection 13.1.2. Uffice of Standards Development, Director. 76/10/07. 1p.
- ---8012110816 Forwards Reg Quide 1.114.Revision 1. "Quidance on Being Operator at Controls of Nuclear Power Plant." FR notice & draft NRC public announcement. Quide was revised as result of public comment & add1 staff review.

 MINDOUE.R.B. Office of Standards Development, Director. 76/11/23.
- ---B012110B22 Reg Ouide 1.114.Revision 1, "Quidance on Being Operator at Controls of Nuclear Power Plant." + Office of Btandards Development, Director. 76/11/30. 2pp.
- ---8012110B43 Notice of issuance & availability of Reg Ouids 1.114.
 Revision 1. "Guidance on Being Operator at Controls of
 Nuclear Power Plant." Draft NRC public announcement encl.
 HI(IDQUE.R.B., Office of Standards Development, Director. 76/11/23.
- --8012110846 Reg Guide 1.114. "Guidance on Being Operator at Controls of Nuclear Power Plant." Related FR notice encl. - Office of Standards Development, Director. 76/02/29, 4pp.
- --8012110849 Working Paper F on proposed Reg Oulds 1.XX, "Quidance on Being Operator at Controls of Nuclear Power Plant," a Office of Standards Davelopment, Director. 75/10/10. 5pp.
- -8012110B49 Horking Paper E on proposed Reg Guide L.XX, "Quidence on Heing Operator at Controls of Nuclear Power Plant." # Office of Standards Development, Director. 75/08/29. Spp.
- --B0121104B3 Forwards Working Paper D on proposed Reg Quide 1.XX.

 "Oudiance on Being Operator at Controls of Nuclear Power
 Plant." Regulatory position should be followed & applied by
 all current & future licensees.

 MIKDOUE, R. B. Office of Standards Development, Director. 75/08/12.

 2pp.
- --8012110851 Horking Paper D on proposed Reg Ouide 1.XX; "Quidance on Being Operator at Controls of Nuclear Power Plant." Three draft working papers encl. 4 Office of Standards Development; Director. 75/07/16, 18pp.

- -8012110687 Forwards Working Paper C on proposed Reg Quide 1.XX,
 "Qudiance on Being Operator at Controls of Nuclear Power
 Plant. "Revised working paper reflects suggestions made by
 Reg Quide Bubcommittee at 75507 meeting.
 HTMOGUE,R.B. Office of Standards Development, Director. 75/05/22.
- -8012110853 Working Paper C on proposed Rag Quide 1.XX, "Quidance on Being Operator at Controls of Nuclear Power Plant." Two draft working papers encl. * Office of Standards Dovelopment, Director. 75/05/19, 14pp.
- -801?110692 Forwards Working Paper B on proposed Reg Ouide 1 XX.
 "Quidance on Being Operator at Controls of Nuclear Power
 Plant."
 MINOGUE.R.B. Office of Standards Development, Director. 75/04/14.
- -8012110854 Working Paper B on proposed Reg Ouide 1.XX, "Quidance on Being Operator at Controls of Nuclear Power Plant." Three draft working papers sact. # Office of Standards Development, Director. 75/04/10. 20pp.
- -80121t0702 Requests comments on encl RO bulletin Comments should be provided by 741231. Recommends development & implementation of reg guide re maining controls at nuclear reactors. KNUTH. D.F. Atomic Energy Commission. Directorate of Regulatory Operations. 74/12/27. 3pp.
- -8012110707 Responds to 741227 request for comments & recommendations re issuance of proposed bulletin, "Failure to Proporly Man Controls at Licensed Reactor Facilities." Recommends that bulletin be issued. ROGERS.L. Atomic Energy Commission Directorate of Regulatory Standards. 74/12/31. 19.
- -8012110717 Comments on proposed reg guide & RO bulletin: "Manning of Controls at Reactor Facilities." Definition of "present at controls" should be publicized via reg guide Requests clarification re neccessity of RO.

 CASE
- -8012110723 Informs that guidance given RO inspectors is appropriate & should be used until reg guide re control room manning has been issued.
 OIAH8U580.A. Atomic Energy Commission. 74/10/11. 2pp.
- -8012110735 Requests comments & concurrence on encl proposed RO bulletin, "Failures to Properly Han Controls at Nuclear Power Stations," Comments should be provided by 740917. DAVIS.T.O. Atomic Energy Commission. Directorate of Regulatory Operations. 74/09/13. 2pp.
- 8012110739 Responds to 740927 request that rep guife be prepared for control room manning at nuclear power plant sites. Nork on guide is underway. Draft will be available for comment by 750106.
 ARLDITO.O.A. Atomic Energy Commission Directorate of Regulatory Standards. 74/10/17. ip.
- 8012110747 Recommends that applicants be required to document in FBAR plans for complying w/code re control room planning & recommends preparation of reg guide. Clarification of code requirements encl.

 ORIER, S. H. Atomic Energy Commission. 74/09/27. 11pp.
- 800804008B Forwards proposed revisions to 10CFRSO. "Domestic Licensing of Production & Utilization Facilities," to increase staffing & provide for control of working hours at nuclear power plants; for initial ACRS review. Draft FR notice encl. ARLUTTO.0.A. Division of Engineering Standards. 80/07/16. 19pp.
- 12110650 FOIA request for documents re imposition of civil penalties, NRC requests for congressional authorization for more severe civil penalties & responsibilities & behavior of nuclear plant operators.

 BLOOM, J. Isham, Lincoln & Beale. BO/10/24. 3pp. 07227:281.
- 12120337 FOIA request for documents re nuclear accident in USBR in 1955. GALLACHER, P. J. Affiliation Unknown. 80/11/16. 1p.
- 12150001 Responds to FOIA request for documents which reflect complaints against Univ of Northwestern Dental School in Chicago IL during 1967-1971.NRC has no documents subj to request.
 FELTON, J. H. Division of Rules and Records. BO/12/09. ip. 07241:076.

- 8012150002 FOIA request for documents which reflect complaints against Univ of Northwestern Dental School in Chicago, IL during 1967-1971. MUELLER, J. M. Dobbs & Neilsen, 80/11/12. ip. 07241:077.
- 8012150005 Responds to FOIA request for documents containing meanings of certain terms & other info re fire protection requirements in 10CFR50. App R. Forwards R Ferguson 791109 memo re supplemental fire protection staff positions. FELTON, J. H. Division of Rules and Records. 80/12/09. ip. 07241:067.
- 8012130006 Responds to FOIA request for listing of NRC contractors. Forwards document entitled "Contracts Executed in FY80." FELTON.J.M. Division of Rules and Records. 80/12/09. ip. 07241:070.
- --8012150010 "Contracts Executed in FY80,"
 * Commissioners. 80/10/01. 12pp.
- 8012190007 FOIA request for documents containing meanings of certain terms & other info re fire protection requirements in 10CFR90, App R. WATKINS, M. Debevoise & Liberman. 80/11/19. 2pp. 07241:068.
- 8012190008 FOIA request for listing of NRC contractors. HEISS-L. Paul Howard Associates. 80/11/20. ip. 07241:071.
- BO12190D12 Addi response to FOIA request for listing of firms responding to NRC Announcement 19 in Commerce Business Daily, Forwards listing of names & addresses of all businesses responding to announcement. FELTON.J.H. Division of Rules and Records, BO/12/03. 1p. 072041-050
- --B012130015 List of firms which responded to NRC Announcement 19 in Commerce Business Daily.

 # Commissioners. 80/12/03, 2pp. 07241:060.
- B012150014 FDIA request for listing of firms responding to NRC Announcement 19 in Commerce Business Daily, STERN, A. Al Stern Associates. 80/11/04. ip. 07241:059.
- 8012130016 Responds to FOIA request for four categories of info re NRC purchases of specified dictation equipment. NRC does not compile records containing requested info. FELTON.U.H. Division of Rules and Records. 80/12/03. ip. 07241:055.
- 8012150017 FOIA request for four categories of info re NRC purchases of specified dictation equipment. MUSICK.J. Sony Industries. 80/11/10, 2pp. 07241:056.
- 8012160004 Responds to FOIA request for documents re Windscale Nuclear Reactor accident in Cumberland, England in 1937. Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 80/12/09. 2pp. 07262:189.
- --8012160009 Excerpts from "Technology of Nuclear Reactor Safety," Vol 1,
 "Reactor Physics & Control."
 THOMPSON, T.J., SECKERLEY, J. O. Massachusetts Institute of
 Technology, 80/12/09, 10pp.
- --8012160012 Excerpts from "Technology of Nuclear Reactor Safety," Vol 2, "Reactor Matis & Engineering." THOMPAGN.T.J., BECKERLEY.J.O. Massachusetts Institute of Tachnology. B0/12/09. 7pp.
- B012160006 F0IA request for documents re Windscale Nuclear Reactor accident in Cumberland, England in 1957. MCCARTHY,M. Affiliation Unknown. 80/12/02, ip. 07262:190.
- 8012160015 Responds to FDIA request for listing of all individuals granted operator or senior operator licenses. NRC does not maintain listing of licenses. Each license is available in PDR. PR. Division of Rules and Records. 80/12/10, 1p. 07262:191.
- 8012160017 FOIA request for listing of all individuals granted operator or senior operator licenses.
 MCLELLAN, J. A. Pro-Tech Support Services, Inc. 80/12/02. 1p. 07262:192.
- 8012140021 FUIA request for info re nuclear power. STROUT.R. Affiliation Unknown, 80/12/09. 1p. 07187:001.

- B012160024 Responds to F01A request for info re nuclear power. Forwards NRC Annual Rept for 1979. W/o encl. FELTON, J. M. Division of Rules and Records. B0/12/11. 1p. 07262:193.
- BO12160431 Provides addl info re proposed spent fuel route from Forked River, NJ to West Jefferson, OH. Addl security will be provided when shipment crosses urbanized area. Travel will be on interstate & major highways & will be nonstop. FINFROCK, I.R. Jersey Central Power & Light Co. EAKQ-B0-47, B0/04/10. ip.
- 8012160423 FOIA request for documents re five categories of info concerning spent fuel shipments through Commonwealth of PA. ELLIOT.C.W. Affiliation Unknown. 80/11/04. 2pp. 07261;313.
- 8012180273 Responds to FOIA request for technical proposal submitted by Capital Communication Sys in response to RFP-RB-ADM-80-381. Forwards nonproprietary version of proposal & documents listed in encl app. FELTON, J.M. Division of Rules and Records. 80/12/10. 2pp. 07272:350.
- --8012180288 Nonproprietary version of response to RFP R8-ADM-80-381,
 "Development of Conference Program for ASLU Members."
 Describes technical approachs methodology & conference
 format Includes response to technical questions,
 * Capitol Communication Systems. R6-ADM-80-381, 80/06/16. 81pp.
- --8012180291 Original proposal clarification of response to RFP RE-ADM-80-381. "Development of Conference Program for ASLB Members." * Capitol Communication Systems. R8-ADM-80-381. 80/12/10. 4pp.
- --8012180295 Alternate proposal clarification of response to RFP RB-ADM-80-381. "Development of Conference Program for ASLD
- Humbers." * Capitol Communication Systems. RS-ADM-80-381. 80/12/10. 5pp.
- 8012180282 FDIA request for technical proposal submitted by Capital Communication Sys in response to RFP R8-ADM-80-381; "Development of Conference Program for ABLB Hembers." STOVER, J. R. Franklin Institute/Franklin Research Center, 80/11/17. ip. 07272:382.
- B012180326 Responds to FOIA request for NUREO/CR-1775.Forwards document.I/O encl. FELTON.J.M. Division of Rules and Records, B0/12/11. 1p. 07272:344.
- B01218032B F0IA request for NUREC/CR-1775, "Environ Assessment of Consumer Products Containing Radioactive Matl." OROBEMAN, K. Island Closeup News Bervice. B0/11/28. ip. 07272:345.
- E012(80305 Responds to appeal of denial of FOIA request for documents re NRC consideration of licensing facility & transcripts of two Commission meetings. Access to classified matis greated due to security clearance & participation in proceedings. FELTON.J.H. Division of Rules and Records. 80/12/11, 1p. 07272-741.
- B0121B0339 Appeals denial of FOIA request for documents re NRC consideration of licensing facility & transcripts of two Commission meetings.
 COCHRAN, T.B., Natural Resources Defense Council. FDIA/TBC/79-50.
 B0/07/10. 1p. 07272:342.
- B012190234 Responds to FUIA request for access to mailing list of NRC PDR daily accession list Company has been placed on NRC daily accession list distribution FELTUN.J.M. Division of Rules and Records. B0/12/12. ip. 07285:300.
- B012190241 FDIA request for access to mailing list of NRC PDR daily accession list.
 FORTI,E. KMQ International, Inc. (Ketchum MacLeod & Grove). DM-640.
 B0/12/09. 1p. 07285:301.
- BOI2190247 Responds to FOIA request for listing of spent fuel routes in State of NY. Forwards NUREO-0725 & NRC Announcement 80-191. W/o encl NUREO-0725. FELTON.J.H. Division of Rules and Records. 80/12/17. ip. 07285:302.
- 8012190252 FOIA request for listing of spent fuel routes in State of NY. BUETENB.E. Chronicle-Express Penn Yan,NY. 80/12/07, ip. 07288:303.

- 8012190366 Add1 response to F01A request for six categories of info refire protection requirements in App R of 10CFR50, Forwards G Harrison 790731 meno to V Benaroya re fire protection technical issue. FELTON, J. N. Division of Rules and Records. 80/12/15. 1p. 07284:045.
- --8012190374 Forwards draft memo describing technical fire protection issue between Div of Operating Reactors & Div of Sys Safety.

 Differences exist in fire protection measures accepted by divs. Suggests that meeting be held to resolve differences.

 HARRISON.O. Division of Systems Safety. 79/07/31. 7pp.
- 8012190383 Responds to FOIA request for 15 categories of documents re Memorandum & Order CLI-80-21 & IE Bulletin 77-018. Forwards documents listed in app. W/o encls. FELTON.J.W. Division of Rules and Records. 80/12/15. 4pp. 07284:055.
- 8012190391 FDIA request for 15 categories of documents re Memorandum & Order CLI-80-21 & 1E Dulletin 79-01B.
 REYNDLDS.N.B. Debevoise & Liberman. 80/11/07. 3pp. 07284:059.
- 8012190377 Responds to FOIA request for winning proposal submitted in response to RFP R8-RE6-80-214. "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impacts on Fish Populations." Proposal is available in PDR. FELTON. J. N. Division of Rules and Records. 80/12/16. 1p. 07284;065.
- 8012190404 FOIA request for winning proposal submitted in response to RFP RB-RES-80-214, "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impacts on Fish Populations."
 WRIGHT, J. Affiliation Unknown. 80/12/01. ip. 07183:001.
- 8012190406 Responds to FOIA request for 10 specifically identified documents to be used for educating general public. Forwards documents. W/o encls. FELTON, J. M. Division of Rules and Records. 80/12/15. ip. 07284:066.
- 8012190410 FOIA request for 10 specifically identified documents to bused for educating general public.

 JONES.L. Black Hills Alliance. 80/11/23. 2pp. 07284:047.
- 8012190415 Responds to FOIA request for damage claim filed against NR by General Public Utils on 801208 Forwards claim W/o encl. FELTON, J. M. Division of Rules and Records. 80/12/16. 1p. 07284:069.
- B012190420 F0IA request for damage claim filed against NRC by General Public Utils on B0120B Wall Street Journal article and. PESTLE.J.W. Varnum, Riddering, Wierengo & Christenson. 80/12/10. 3pp. 07284:070.
- 8012220183 Responds to FOIA request for info re storage of nuclear, radioactive or other hazardous waste in NM. App A documents may be obtained from NTIS Forwards App 8 documents & NUREO/CR-0374, H/o encl NUREO. FELTON, J. N. Division of Rules and Records. 80/12/05. 4pp. 07303:243.
- --8012220194 Excerpt from NM radiation control program from 751023-760827 re commercial low level raduasts burial.

 * New Mexico, State of, 76/08/27, lp.
- --B012220200 "NM Site Application Experience." Albuquerque Journal article entitled "NM Given Ruclear Waste Site Caution Note" encl. * New Hexico, Btate of. 80/12/05, 5pp. 07187:001.
 - w team linking beare of. dollarson. opp. officer.

- --B012220219 PNA-74-006: on 76120B, article appeared in Albuquerque Jore NRC comments on Btate of NM proposed licensing guide for commercial rodwaste burial grounds.NRC comments did not imply concurrence in licensing of commercial burial grounds. KERR, O.U. L. DAMUS, P. Office of State Programs, Director. 76/12/08. 1p.

- ~-8012220724 Discusses NRC ltr to State of NM re adoption of formalized policy on licensing of low level radwaste disposal facilities by agreement states. Requests meeting w/NRC to discuss current & future plans re radwaste disposal. ANDREMS, L. J. Chem-Nuclear Systems, Inc. 76/12/08. 2pp.
- --8012220233 Informs that recommendation in NRC 761119 ltr re-regulation of commercial low level waste buriel grounds was not adopted as Commission policy. Provides NRC current position. State of IM 771129 & 30 ltrs to Chem Nuclear Bys, Inc. encl. KERR, 0.14. Assistant Director for State Agreements Programs. 78/10/12. Bpp.
- --B012220243 Act receipt of 770607 request for info re schedule for consideration of Chem-Nuclear Bys low level radwaste disposal license application. Forwards listing of licensing activities & draft schedule of application processing. WOLFF, T. A. New Mexico, State of. 77/07/11. 4pp.
- --8012220245 "Gomments on Chem-Nuclear NM, Inc Application for Radioactive Matl License." W/related info. PIERCE.J., DUDLEY.J., GALLAHER.B. New Mexico, State of. 77/11/30.
- --8012220252 "Preliminary Review of Chem-Nuclear License Application Prepared for NM Environ Improvement Agency." W/related info. RODGERS, J. C. Affiliation Unknown. 77/11/30, 19pp.
- --8012220258 Statement to NK Environ Improvement Agency re Chem-Nuclear IXI, Inc. application for license to dispose of nuclear waste in Colfax County, NK. W/related info.

 DAVIOSON, J. P. Horatorium, Inc. 77/07/01, 6pp.
- --8012220264 "Comments on Application for Radioactive Matl License by Chem-Nuclear NM, Inc."
 MONIAOUE, P. Southwest Research and Information Center, 77/11/30.
- --B012220269 "Comments on Chem Huclear Radwaste Disposal License Application." HYDER.C. Southwest Research and Information Center. 77/11/30. 13pp.
- --8012220275 "Comments & Questions on Application for Radioactive Matl License by Chem-Nuclear NM, Inc." Related documentation encl, SCHVLTZ, K. B. Southwest Research and Information Center. 77/09/12. 37pp.
- ~-8012220284 "Comments on Application for Radioactive Hat1 License to Operate Commercial Radwaste Buriai Facility.Colfax County. RM."
 - # Environmental Protection Agency. 77/11/21. Opp.
- --8012220290 Act receipt of 770518 itr informing of receipt of application from Chem-Nuclear Sys. Inc to establish commercial low level radwaste burial ground. Offers assistance on environ rept.including economic analysis. KERN-0-M. Assistant Director for State Agreements Programs. 77/06/07.
- ---B012220298 Ack receipt of 761208 ltr re NRC ltr to State of NM re adoption of formalized policy on licensing of low level radwaste disposal facilities by agreement states. NRC comments & position were of generic nature. KERR.O.H. Assistant Director for State Agreements Programs. 76/12/17.
- 801222018B FOIA request for info re storage of nuclear, radioactive or other hazardous waste in NK.
 HUSBARD, B. Albuquerque Tribune Albuquerque NM. 80/11/17. 2pp. 07303:247.
- 8012240119 Responds to FOIA request for NUREO/CR-1138, NUREO/CR-1273 & Progress Rept 1 of NUREO/CR-1273, Forwards NUREO/CR-1138 & NUREO/CR-1273, NRC was unable to locate Item 3 of request. W/o encl, FELTOK J. N. Division of Rules and Records. 80/12/15. 1p.

ograss Rept

- 8012310560 Responds to FOIA request for documents re nuclear weapons testing in Australia in late 1950s & 1960s.NRG has no documents subj to request.

 FELTON.J.H. Division of Rules and Records. BO/12/24, 1p.
- 8012310563 FOIA request for documents re nuclear weapons testing in Australia in late 1750s & 1760s.
 FEINSTEIN.N. Bydney Morning Herald Ltd. 80/12/08. 1p.
- 8012310366 Responds to FOIA request for info re security guard contract procurements. Security guard svcs at NRC ofcs are provided through 08A Nuclear power plant security info is contained in NURGO-0632 which is available for purchase from NRC. FELTON.J. M. Division of Rules and Records. 80/12/22. 1p. 07370:016.
- 8012310370 FOIA request for info re security guard contract procurements. IRVING.B. J. Regard Security Service, Inc. 80/12/05. 1p. 07370:017.
- B012310594 Responds to F01A request for document entitled "Quidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source or SNM." Forwards document. FELTON.J. M. Division of Rules and Records. 80/12/24. 1p. 07370:00B.
- 8012310597 FOIA request for document entitled "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Dyproduct.Bource or SNN," VOLKER-S.C. Sierra Club. 80/11/24. 1p. 07370:009.
- GEN TEC IS GENERIC TECHNICAL ISSUES
- B01202025B Forwards errata to NEDD-24Bii. "AT Condensation Oscillation (4TCO) Test Program Final Test Rept." BUCHHOLZ,R.H. General Electric Co. MFN-193-80. 80/11/13. 1p. 07147;315.
- --8012020265 NEDD-24811 ERR 1 Errats 1 to NEDD-24811, "4T Condensation Oscillation (4TCD) Test Program Final Test Rept." * General Electric Co. 80/09/30. 6pp. 07147:316.
- 8012040496 Comments on NUREC-0377. Revision recommended re loading conditions & plant operating temps employed in fracture toughness evaluation of supports & bolting matl tests. 8HERER, A. E. C-E Power Systems. LD-80-067.
- 8012100123 NUREO-0619
 "BUR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking:" resolution of Generic Technical Activity A-10. SMAIDSR.R. Diffice of Nuclear Reactor Regulation, Director. B0/11/30. 104pp. Available at NTIS. 07219:166.
- --8012100131 Forwards revised & final edition of NUREG-0619 re BWR feedwater nozzle & control rod drive line nozzle cracking. Licenses commitment that NUREG requirements will be mot due in 45 days.
 EISENHUT.D.G. Division of Licensing. 80/11/13. 1p. 07219:260.
- 8012220250 Forwards affidavit describing proprietary nature of info contained in NEDE-24288-P. Affidavit provided on behalf of Mark II Ouners Group. Affidavit withheld (ref 10CFR2. 770). BUGHHOLZ, R. H. Oenoral Electric Co. MFN-214-80. 80/12/11. 1p.
- B012310024 NUREO-0588
 "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," resolution of Generic Technical Activity A-24, for comment, EZUNIFINICZ, A. Office of Nuclear Reactor Regulation, Director, 79/12/31, 70pp. Available at NTIS 07364:336.
- INSPECTION AND ENFORCEMENT
- 8006190946 IE Info Notice 80-XX, "Leaking & Dislodged I-25 Beeds." # Office of Inspection & Enforcement, Office of the Director. 80/08/12. 2. 07240:001.
- 8005190078 IE Info Notice 80-33, "Determination of Teletheraphy Timer Accuracy." # Office of Inspection & Enforcement, Office of the Director. 80/09/15. 2pp. 07374:023.

- 8008220180 IE Info Notice 80-38, "Cracking & Charging Pump Case Casing Cladding." * Office of Inspection & Enforcement, Office of the Director. 80/10/30. 2pp. 07259:171.
- 8008220243 IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." * Office of Inspection & Enforcement, Office of the Director, 80/10/31. 3pp. 07321:346.
- 8008220245 i5 Info Notice 80-39, "Malfunction of Bolenoid Valves Manufactured by Valcor Engineering Corp." * Office of Inspection & Enforcement, Office of the Director, 80/10/31. ip. 07256:323.
- 8008220246 IE Bulletin 80-21, Valve Yokes Supplied by Malcolm Foundry Co., Inc." ** Office of Inspection & Enforcement, Office of the Director. 80/11/06. Epp.
- 8008220249 IE Info Notice 80-37, "Containment Cooler Leaks and Reactor Cavity Flooding at Indian Point Unit 2." * Office of Inspection & Enforcement, Office of the Director, 80/10/24. 6pp. 07256:348.
- 8008220237 IE Sulletin 80-23, "Failures of Solenoid Valves Manufactured by Válcor Engineering Corp." * Office of Inspection & Enforcement, Office of the Director, 80/11/14. 3pp. 07175:327.
- 800B220260 IE Info Notice 80-41, "Failure of Swing Check Valve in the Decay Heat Removal Bys at Davis-Besse Unit 1." * Office of Inspection & Enforcement, Office of the Director. 80/11/10. 2pp. 07374:285.
- 8008220261 IE Info Notice 80-42, "Effect of Rediation on Hydraulic Boubber Fluid." * Office of Inspection & Enforcement, Office of the Director. 80/11/24, 2pp. 07374:273.
- BOOB220264 IE Circular 80-24, "AEGL Teletharapy Unit Malfunctions." * Office of Inspection & Enforcement, Office of the Director. 80/12/02. 3pp. 07256:342.
- 8008220269 IE Info Notice 80-40, "Excessive Nitrogen Bupply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization."

 ** Office of Inspection & Enforcement, Office of the Director. 80/11/07. 2pp. 07175:321,
- 8008220970 IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (October 17, 1980 Indian Point 2 event)."

 * Diffice of Inspection & Enforcement, Office of the Director, 80/11/21. 3pp. 07175:324.
- 8008220273 IE Circular 80-23, "Case Histories of Rediography Events."

 * Office of Inspection & Enforcement, Office of the Director.

 80/12/05. 1p. 07256:346.
- 8008220276 IE Info Notice 80-29 Si. "Broken Studs on Terry Turbine Steam Inlet Flange."

 * Office of Inspection & Enforcement, Office of the Director. 80/11/26. Ip.
- 8012010018 PNA-80-36B: status of State of FL & Intl Chemical Horkers Union actions relack of training & respiratory protection programs. Ofc of State Programs will review State of FL actions during Nov 1980 meeting w/Intl Minerals Corp. KERR, O. W. , DOLLINO, L. A. Office of State Programs, Director. 80/10/29. 1p. 06915:001,
- 8012110168 EN-80-41A: on 801204, order imposing civil penalties on Atomic Disposal Co. Inc. License 12-11284-01 issued. Action based on items of noncompliance re shipment of low specific radioactive matl from Tinley Park, IL, to Richland, HA. BROCKETT, T., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director. 80/12/04. jp. 07223:103.
- BO12110179 PNO-I-80-167A: investigation into source & extent of radioactive contamination near Route 17 in Rochelle Park, NJ, continues, Maywood Chemical & Stepan Chemical Gos may be source, but has not been definitely established.

 COSTELLO,F. Region 1, Philadylphia, Office of the Director, 80/12/01, 1p. 07223:102.

- 8012180255 EN-80-055: on 801215, notices of violation & of proposed imposition of civil penalties in amount of \$7.500 to be issued to licensee. Action based on alleged noncompliance re radiation protection program.

 BROCKETT, T. W. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director. 80/12/11. ip. 03794:005.
- 8012190110 PND-TMI-80-54: on 801209, fire started in reactor bldg containment sump apparently from sparks from air-arch cutting operations on grating above sump. Fire extinguished w/o damage.

 HAVERKAMP, D. TMI Program Office. 80/12/09. 2pp.
- 8012190562 PNA-80-040: an 801123, resident discovered radiation hot spots around Neutron Products. Inc facility in Dickerson, MD. State of MD will conduct isotope analysis of hot spot activity. LUBENAU.J. O., BOLLING.L. Office of State Programs, Director. 80/12/03. 2pp. 07296: 018.
- 8012220183 Responds to FOIA request for info re storage of nuclear, radioactive or other hazardous waste in NM App A documents may be obtained from NYIS. Forwards App B documents & NUREO/CR-0394. W/o encl NUREO. FELTON. J. H. Division of Rules and Records. 80/12/05. 4pp. 07303:243.
- --8012220219 PNA-74-006: on 761208, article appeared in Albuquerque Journal rs NRC comments on State of NR proposed licensing guide for commercial radwaste burial grounds. NRC comments did not imply concurrence in licensing of commercial burial grounds. KERR.O.N., LOHAUS.P. Office of State Programs, Director. 76/12/08. 1p.
- 8012290020 PNO-IV-80-40: on 801205, shaft coupling emergency feedwater pump to electric motor twisted in two when emergency feedwater pump bearings seized. Event followed manual scram when main feedwater value failed to open. Repair underway. JOHNSON, U. D. Region 4, Dallas, Office of the Director. 80/12/09. ia.
- 8012290025 PND-IV-80-40A: Unit 2 remains in cold shutdown following manual scram on 801205. Pump components replaced in emergency feedwater pump including rotating assembly. Test indicated pump curve dropped off at upper end. Evaluation continues. JOHNSDN, W. D. Region 4, Dallas, Office of the Director. B0/12/15.
- 8012290103 PNO-I-80-174: on 601215. Lebanon Valley General Hosp, License 37-15375-02, reported loss of 10 nCi Xe-133 gas. Matl signed for upon delivery earlier in day. Physical search & radiation survey revealed nothing. CAMPBELL, M., KINNEMAN, J. Region 1. Philadelphia, Office of the Director. 80/12/16, 1p. 07339:073.

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- BOD9140406 Responds to BCO523 memo re BHR jet pump integrity. Hold down beams must be replaced. Water hammer recommendation will be sent to special task group. Request for info re testing of areas whigh amplitude vibrations will be sent to licenses. DENTOW. H.R. Office of Nuclear Reactor Regulation. Director. 80/07/11. 3pp. 06586:001.
- B012010246 Responds to 900811 mamo re NEPA implementation.Review procedures for prime & unique agricultural lands described in "Environ Btd Review Plan for Environ Review of CP Applications for Nuclear Power Plants."

 DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 80/11/04. 3pp. 06916:001.
- B012010559 Forwards proposed manual chapter re operational data assessment program Requests comments by B01213.

 MICHELBON, C. Director's Office, 80/11/13. 20pp, 07098:084.
- 8012030711 Requests info re nuclear power. THURSTON J. Affiliation Unknown. 80/11/19. ip. 02319:196.
- 8012030850 Responds to 801021 ltr re util determination to refuse MJ Evans saployment NRC receives medical info on util employees only w/operator or senior operator license application. DIRGKB.N.J. Office of the Executive Director for Operations. 80/11/10. 2pp. 04586:003.
- --8012030859 Forwards BW Evans & MJ Evans ltrs re denial of employment for MJ Evans at nuclear plant due to physical impairment. Requests necessary info for reply. BMITH.V. House of Rep. 80/10/21, 3pp. 04586:003.

- 8012090023 Ack receipt of 801101 ltr re future licensing of nuclear plants that meet NRC stds.Four plants issued licenses to load fuel since TMI-2 accident. DENION.H.R. Office of Nuclear Reactor Regulation, Director. BO/11/25, Ip. 07187:001.
- --8012090024 Notifies that all energy sources must be exploited for energy needed in future.NRC should proceed w/nuclear plant licensing. BROWES.A. Affiliation Unknown. 80/11/01. 1p. 07187:001.
- 8012100650 "Some Selected Consensus Approaches," presented at 1980 IEEE Intl Conference on Cybernetics & Society, 801008-10. ABRAMSUN,L. R. Internal Information Systems Branch. 80/10/10. 11pp. 07220:044.
- 8012110155 Notification of 801208 meeting w/Inst of Nuclear Power Operations & DDE for technical exchange on human factors programs.
 IRELAND.R. Division of Human Factors Safety. 80/12/04. 3pp.
- 8012160322 Forwards Endorsement Form NE-46 dtd 770101; which was raplaced by Endorsement Form NE-48 attached to all facility form policies issued on or after 770101. Form NE-48 is amalyamation of several previous forms. GUATROCCI.J. American Nuclear Insurers. 80/12/12. 6pp. 07248-27
- 8012180430 IAEA-CN-39/100
 Speech entitled "Possible Hays to Improve Nuclear Power
 Plant Instrumentation." presented at IAEA 801020-24 Intl
 Conference on Current Nuclear Power Plant Safety Issues in
 Stoctholm: Sweden.
 HSU.Y. HGN.A.L. Division of Reactor Safety Research. 80/10/24.
 22pp. 07272:156.
- 8012190038 Notification of 801217 meeting w/Div of Human Factors Safety personnel & interested staff to review Human Factors research programs in Div of Sys & Reliability Research.

 * Division of Human Factors Safety. 80/12/17. 2pp. 07278:227.
- 8012190565 Forwards comments on draft NRC manual Chapter 0524, "Stds for Protection Against Radiation," in response to 801028 memo. HR Denton draft forwarding memo encl. MVRLEY, T.E. Division of Safety Technology, 80/12/02. 3pp. 07284:042.
- 8012240231 "NRC Nationwide Program for Direct Radiation Monitoring at Licensed Facilities." SLOGODIEM.M.J. Office of Inspection & Enforcement, Office of the Director. 80/12/22, 22pp. 07323:076.
- 8012240179 Forwards final list of mati to have approved for incorporation by ref under IOCFR51.13.Missing documents are on order & will be provided.

 ENGLHARDI.T.F. Deputy Executive Legal Director. 80/12/02. 7pp. 07324-315

NUREO NUREO REPORTS AND RELATED CORRESPONDENCE

- 8011210592 Expresses appreciation for NRC cooperation extended to Interorganizational Advisory Committee re NURCO-0654 & response to proposed changes, Requests revisions to NUREO-0676 to clarify NRC role in offsite emergency operations, MANCUSU,F. Connecticut, State of. 80/11/12. 2pp. 07034:004.
- B012010017 Forwards NUREO-0625 in response to 801020 request for NRC publications dealing w/nuclear power facility siting. H/o enci.
 VOLLMER, R. H. Division of Engineering. 80/11/14. ip. 07076:355.
- 8012010055 Comments on draft generic EIS on U milling Impractical to limit tailings disposal schemes to prime option of complete below grade disposal. LANG.E.A. Atomic Industrial Forum. 79/10/24, 74pp. 07098:116.
- 8012020074 Summary of Subcommittee on Reactor Fuel 800903 meeting w/ Westinghouse in Washington.DC re NUREG-0630 review, * ACRS Advisory Committee on Reactor Safeguards. 80/10/08. 4pp. 07147:252.
- B012020126 RUREO/CR-1749

 "Qualification Testing Evaluation Program, LWR Safety
 Research: "semiannual rept.Oct 1979-Har 1980.
 BONZON, L., STUETZER, O.M., SUCKALER, W.H. Sandia Laboratories. FIN
 A-1091-0. SANOBO-1907. 80/09/30. 57*pp. Available at NTIS.
 07142:137.

- 8012020139 NUREQ/CR-1469 V14
 "LUR Safety Research Program," quarterly rept.Oct-Dec 1979,
 Vol 14.
 BERMAN.M. Sandia Laboratories. FIN A-1019, 8AND80-0927, 80/09/30,
 181pp. 07142:190.
- 9012020363 Provides adddi comments on NURED-0731. "Guidelines for Util Mgt Structure & Tachnicai Resources." Recommends NRC review of proposed util organization on individual merits. HOWELL, S. H. Atomic Industrial Forum. 80/11/20. 2pp. 07142:069.
- 8012020.693 NUREG-0.654 R1
 "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparadness in Support of Nuclear Power Plants." Revision 1.

 * Commissioners. * Federal Emergency Management Agency, FEMA-REP-1. 80/11/30. 14Bpp. Available at NTIS. 07145:102.
- 8012020459 NUREG/CR-1746
 "Steam Expiosion Efficiency Studies:Part 2 Corium
 Expériments,"
 BUXTUN.L. D., BENDICK, M. B., CORRADINI, M. L. Bandia Laboratories, FIN
 A-1030. BANDB0-1324. 80/10/31. 35pp. Available at NTIB.
 07145:068.
- 8012020731 Responds to FOIA request for documents specifying exact routes & number of spent fuel shipments made or schedulad. Forwards NUREO-0725, document entitled "Summary of Route Info" & NRC Announcement 80-191. W/o NUREO-0725. FELTON. J. II. Division of Rules and Records. 80/11/21. ip. 07130:342.
- 8012020732 NVREG-0725
 "Public Info Circular for Shipments of Irradiated Reactor
 Fuei." Encl maps copyrighted.
 * Office of Nuclear Materiai Safety & Safeguards. 80/11/30. 4ipp.
 Available at NTIS. 04586:003
- 8012020738 NUREG/CR-1233 VI
 "Structured Assessment Approach, Version 1: Analysis Package
 (Executive Summary)," Voi 1.
 PARZIALE, A.A., SACKS, I.J. Lawrence Livermore Laboratory, FIN
 A-0115, UCRL-82735 VI. 80/11/30. 32pp. Available at NTIS,
 07145: 022.
- 8012020744 NUREO/CR-1233 V2
 "Btructured Assessment Approach, Version 1: License Submittal Document Content & Format for Hatl Control & Accounting Assessment," Vol 2.
 PARZIALE, A. A. ; SACKS, I. J. Laurence Livermore Laboratory, FIN A-0115, UCRL-52735 V2. 80/11/30. 504pp. Available at NTIS. 07146:001.
- BO12030B23 NUREO/CR-1662
 "Aeromagnetic Map of East-Central Midcontinent of UB."
 JOHNSBON.R.W. Indiana, State of, HAY000D.C. Tennessee Valley
 Authority, HILDENBRAND.T. Interior, Dept. of, Geological Survey. FIN
 B-5971. NRC-04-76-323. B0/10/31. 12pp. Available at NTIB.
 07149: 323.
- 8012040041 NUREO/CR-1736
 "Comparison of Physical Chemical Properties of Powders & Respirable Aerosols of Industrial Mixed U & Pu Oxide Fuels."
 EIDSON, A.F. Inhalation Toxicology Research Institute. * Lovelace Biomed & Environmental Research Institute. FIN A-1031. LMF-78.
 80/11/30. 22pp. Available at NTIB 07159:063.
- B012040070 NUREG/CR-1233 V3
 "Btructured Assessment Approach, Version 1: Applied
 Demonstration of Output Results," Vol 3.
 PATRIALE, A. A., BACKS, I. J. Lawrence Livermore Laboratory, FIN
 A-0115, UCRL-52735 V3. 80/11/30. 330pp. Available at NTIS.
 07159: 084.
- 8012040119 Bubmits corrected comments on proposed rule 10CFR50 & NUREO-0696, "Functional Criteria for Emergency Response Facilities."
 SCHUYLER, J. O. Pacific Gas & Electric Co. 45FR5470B 035. B0/11/03. ip. 07170:241.
- BO12040496 Comments on NUREG-0577. Revision recommended re loading conditions & plant operating temps employed in fracture toughness evaluation of supports & boiting mat1 tests. SHERER, A. E. C-E Power Systems. LD-80-067.
- BO12050053 SECY-B0-507
 Seeks Cormission approval of ancl draft FR notice endorsing deferment of mandatory acceptance of nuclear plant reliability data sys & development of integrated operational expensions reporting sys. Recommends approval. DIRCKS, N.J. Office of the Executive Director for Operations. BO/11/14. 60pp. 07173:116.

- BO12050440 Comments on DC Eisenbut 1tr to licensees re Section II.D.1, "Performance Testing of BWR & PWR Relief & Safety Valves." Present program does not provide for testing of PWR valves under ATMS conditions or include tests of block valves. LEVENSON.H. Electric Power Research Institute. BO/11/26. ip. 02741:346.
- 8012080010 RUREG/CR-1693
 "Experiment Data Rept for LOFT Nuclear Small Break
 Experiment L3-5/L3-5A."
 DAOL. T. CARPENTER.J. M. E0%0 Idahu, Inc. FIN A-6048. E00-2060.
 80/11/30. 277pp. Available at NTIS. 07195:137.
- 8012080014 NUREO/CR-1318
 "Analytical & Experimental Studies of Beam W/Geometric
 Nonlinearity."
 MIRIAMY,Y.A., MABRI,B.F., ANDERSON,J.C. California, Univ. of, Los
 Angeles, FIN 8-5976. 80/11/30. 134pp. Available at NTIS.
 07197:087,
- 8012080017 NUREO/CR-1694

 "Properties of Radwastes & Waste Containers," quarterly progress rept. Apr-June 1980.

 HORCOS, N., KEISS, A. J. Brookhaven National Laboratory. FIN A-3027.

 BNL-NUREO-51266. 80/08/31. 40pp. Available at NTIS. 07181:165.
- BO12080023 NURE9/CR-1672

 "Risk Assessment Methodology Development for Waste Isolation in Osologic Media," technical review of documents NURE9/CR-0394, NURE9/CR-0424 & NURE9/CR-0498.

 STEVENS, C. A., FULL MODD. R. R., BASIN, B. T. Science Applications, Inc. FIN B-6694. SAI-219-80-PA. 80/11/39. 106pp. Available at NTIS. 07196: 352.
- 8012080712 Comments on NUREG-0660 re action plan resulting from TMI-2 accident. All items in document are not related to TMI Lessons Learned.
 COUNSIL, N. O. Connecticut Yankee Atomic Power Co. COUNSIL, N. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
 GOUNSIL, N. O. Northeast Utilities Service Co. 45FR50613 001.
 BO/10/28. 3gp. 07196:139.
- 8012080794 NUREO/CR-146i
 "User Guide for MDDCUT & PL-MDDMC:Computer Codes for Fault Trea Analysis."
 MDDARRES, N. , RASMUSERN, N. C. , HDLF, L. Massachusetts Institute of Technology. FIN B-6256. 80/11/30. 49pp. Available at NTIS. 07196:276.
- B012090014 Comments on B00701 "Program Plan for Performance Testing of PMR Bafety & Relief Valves." Areas where program not completely responsive to NUREO-057B, Section 2. 1. 2 require addl info.
 VOLLMER, R. H. Division of Engineering. 80/11/26. 5pp. 07197: 293.
- B012090016 Forwards NUREO-0735, "Pian for Developing Safety Goal," & B01027 news release on subj. N/o enci.
 ZECH.O.O. Technical Bupport Branch. B0/11/22. 1p. 07197: 300.
- --Bol2090018 Requests NUREG-0735; "Plan for Developing Safety Goal", LEWIS, M. I. Affiliation Unknown. B0/12/05. ip. 07197:301.
- 8012070017 Comments on proposed rules 10CFR30, 32, 70 & 150 re licensing requirement exemption for contaminated smelted alloys.

 Opposes exemption.

 HRIGHT, N. Affiliation Unknown. 45FR70B74 0003. 80/11/20. 1p.
- B012090024 Comments on proposed rules 10FR30.32.70 & 150 re licensing requirement exemption for contaminated smelted alloys. Upposes exemption. FISHER, R. Affiliation Unknown. 45FR70874 0001. 80/11/14. ip.
- 8012090030 Comments on proposed rules 10FR30, 32,70 & 180 re licensing requirement exemption for contaminated smelted alloys. Opposes exemption, Requests to be kept informed about regulation.

 ATAMIAN, L. Affiliation Unknown. 45FR70874 0002. 80/11/15. 1p.
- BO12090248 Provides add1 guidance on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports." Option to use higher yield strength steels recommended.

 BRUND, I. Stone & Webster Engineering Corp. 80/12/03. 2pp. 07201:146.
- BO12100123 NUREO-0617
 "BUR Feedwater North & Control Rod Drive Return Line North Cracking," resolution of Generic Technical Activity A-10.
 BNAIDER,R. Office of Nuclear Reactor Regulation, Director, B0/11/30. 104pp. Available at NTIS. 07217:166.

- --8012100131 Forwards revised & final edition of NUREG-0619 re BWR feedwater nottle & control rod drive line nottle cracking.
 Licensee commitment that NUREO requirements will be met due in 45 days.
 EISENHUT.D.G. Division of Licensing. 80/11/13. 1p. 07219:260.
- 8012110453 NUREG/CR-1626
 "Eddy Current Insp of INCONEL-600 Steam Generator Tubes at
 Tube Sheet."
 MORRIS.C.J. LYON, O.H. DAVIS.T.J. Batteile Memorial Institute.
 Pacific Northwest Laboratory. FIN 8-2097. PNL-3472. 80/11/30.
 17pp. Available at NTIS. 07259:234.
- 8012110491 RUREO/CR-1752
 "Bimulating & Analyzing Artificial Non-Stationary Earthquake
 Ground Motions," seismic safety margins research program.
 NAU.R.F., CLIVER.R.M., PISTER.X.S. Lawrence Livermore Laboratory.
 FIN A-0139. UCRL-15277. BO/11/30. 46pp. Available at NTIS.
 07239:183.
- 8012110558 NUREG/CR-1715

 "Fuel Rad Dehavior During Tests PCK 8-1 RB, CHF Scoping & PCK 8-1 RF."

 JOHNSON, R.L., LASSAHN, P.L., KCCARDELL, R.K. Energy, Dept. of. FIN A-6041. E00-2061. BD/11/30. 46pp. Available at NTIB. 07226:065.
- B012120201 NUREO-0606 V2 NO4
 Aqua book: "Unresolved Bafety Issues," summary data as of
 B01107.Vol 2.Number 4.
 * Office of Management and Program Analysis. B0/11/07. 44pp.
 Available at NTIS.
- 8012120217 NUREG/CR-1468
 "Design Concepts for Independent Central Alarm Station & Secondary Alarm Station Intrusion Detection Sys."
 MAIT.H. J. MARNINO, M. W. Mason & Hanger Silas Mason Co., Inc. FIN A-9037. MHSM-SD 7919. BO/11/30. 64pp. Available at NTIS. 07261:045.
- 8012120270 NUREO/CR-1299
 "Investigation of Halogenated Components Formed From Chlorination of Natural Haters: Preliminary Studies,"
 BEAN.R.K., RILEY,R.G. Battelle Momorial Institute, Pacific Northwest Laboratory, FIN B-2098. PNL-2163, BO/11/30, 34pp. Available at NTIB. 07261: 112.
- BO12120307 NUREG/CR-1120 V4
 "Seismic Safety Margins Research Program (Phase I)." Vol 4.
 Progress Rept 8.800730.
 BALLEY.R.D., SMITH.P.D., DDNO.R.Q. Lawrence Livermore Laboratory.
 FIN A-0126. BO/11/30. 93pp. Available at NTIS. 07259:341.
- BO12120322 NUREG/CR-1558
 "BHR Refill-Reflood Program Task 4.2: Core Spray Distribution Experimental Task Plan."
 ECKERT, T. General Electric Co. FIN 8-5877. EPRI NP-1523. 80/11/30. 57pp. Available at NYIS. 07240:109.
- BOI2120324 HUREO/CR-0892
 "Chronic Effects of Chlorination & Byproduct on Rainbow
 Trout, Salco Qairdneri."
 ANDERSON, D. R. BEAN, R. M., SCHIRMER, R. C. Battelle Hemorial Institute,
 Pacific Northuest Laboratory. FIN B-2098 PNL-3045. B0/11/30.
 28pp. Available at NTIS. { 07260:073.
- 8012120331 NUREO-0693
 "Analysis of Ultimate Heat Bink Cooling Ponds."
 CODELL,R., NUTTLE-W.K. Division of Engineering. 80/11/30. 196pp.
 Available at NTIS. 07257:001.
- 8012120334 NUREO/CR-1605
 "Modeling of Plant Protection & Control Bys For BSC."
 KHATIB-RAHBAR Broothaven National Laboratory. FIN A-3041.
 BNL-NUREO-31241. B0/06/30. 90pp. Available at NYIS. 07258:183.
- 8012120342 NUREO/CR-1819
 "Development & Testing of Model for Fire Potential in Nuclear Power Plants."
 NUCLEAR Power Plants."
 HOCKENBURY, R. W., YEATER, M. L. Rensseleer Polytechnic Inst. FIN B-6302. 80/11/30. 123pp. Available at NTIS 07259:042.
- 8012120343 HUREO/CR-1454 V2
 "Reactor Safety Research Programs," quarterly rept.Apr-June
 1980, Vol 2.
 EDLER, S. K. Battelle Hemorial Institute, Pacific Northwest
 Laboratory, FIN B-2101. PNt.-3380-2. 80/11/30. 117pp. Available
 at NTIS. 07258:280.

GO12120350 NUREO/CR-1467

"CAB-BAS Operational Hork Station Design & Procedures."

WAIT.H.J., KANNINO,M.W. Kason & Hanger - Silas Mason Co., Inc. FIN
A-9028. KH8H-SD 7920. 80/11/30. 85pp. Available at NTIS.
07260:237.

8012120594 Responds to NUREG-0731. "Outdelines for Util Mgt Structure & Technical Resources." Draft found difficult to assimilate & perhaps more difficult to implement. Guide is overreaction to TMI.

URGENSEN, R. U. American Electric Power Co., Inc. 80/12/09, 4pp. 07230:308.

8012120590 NUREO/CR-1822
"Steam/Nater Mixing & Sys Hydrodynamics Program: Task 4."
quarterly progress rept.Jul-5ept 1980.
SEOEV.A., COLLIER.R.P. Battelle Memorial Institute, Columbus
Laboratories, FIN A-4048. BMI-2067. 80/11/30. 68pp. Available at
NTIS. 07260:328.

8012150149 Submits comments & suggestions pertinent to NUREO-0731, "Ouldelines for Util Mgt Structure & Technical Resources," NUREO-1280, "Power Plant Staffing," & NUREO/CR-1656, "Util Mgt & Technical Resources," before finalization.
CRANE,P.A. Pacific Gas & Electric Go. 80/12/08. 3pp. 07240:069.

8012160865 Classifies systematically initiating events responsible for fluid vol changes in primary sys of PHRs, w/special applicability to NUREO-0667, "Transient Response of BAY-Designed Reactors."

ETHERINOTON,H. ACRS - Advisory Committee on Reactor Safeguards. 80/05/01. Spp. 07261:225.

8012160589 NUREO/CR-1793 V1

"Study of Chemical Toxicity of Low Level Wastes: " main rept,
Vol 1.

" Ogneral Research Corp. FIN 8-6127. 80/11/30. 250pp. Available
at NTIS. 07250:343.

8012140598 NUREO/CR-1793 V2
"Btudy of Chemical Toxicity of Low Level Hastes,"
monographs, Vol 2.

* General Research Corp. FIN 8-6127. 80/11/30. 225pp. 07251;242.

8012170291 Comments on NUREC-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Bleam Generator & Reactor Coolant Pump Buggerts" & "General Operating Reactor Review Procedure & Acceptance Criteria." SYLVIA.B.R. Virginia Electric & Power Co. 943. 80/12/02. 2pp. 07187:001.

8012170519 Forwards NUREO/CR-1728, "Feasibility of Epidemiologic Investigations of Health Effects of Low Level Ionizing Radiation." Comments of Interagency Scientific Review Group encl. ODLOBMITH, R., PARSONT, M. A. Radiological Health Standards Branch. 80/12/04. 10pp. 07270:005.

--8012170524 NUREO/CR-1728

"Feasibility of Epidemiologic Investigations of Health
Effects of Low Level Ionizing Radiation," final rept.
DREYER,N.A., KAHN.H.I., CLAPP.R.W. Equifax Health Systems Div.
FIR B-1090-9. 80/11/30. 400pp. Available at NTIS. 07266;332.

8012180510 NUREO-0212 R2
"8td Tech Specs for C-E PWRs." Revision 2.superseding
NUREO 0212.Revision 1.
* Office of Nuclear Reactor Regulation, Director. 89/12/31. 400pp.
03787:026.

B012190040 NUREO/CR-1794 V2
"Summary of Activities & Accomplishments, May-Jul 1979:
Proposal to Develop Method for Detection of HE Employing
Chemiluminescence Reactions," progress rept, Vol 2.
NEARY, M. P. Low Alamos Scientific Laboratory. FIN A-7210. 80/11/30.
App. Available at NTIS. 07278:234.

BO12190424 NUREO/CR-1717 VI "Boil-Btructure Interaction Methods Bummary Rept," Vol 1. MILLER, C. A. Brookhaven National Laboratory. FIN A-3216-9. BNL-NUKEO-51263. BO/06/30 18pp. 07287:175.

8012190432 NUREO/CR-1847
"Std Containers for SNM Storage, Transfer & Measurement,"
final rept. Apr. 1978-Aug. 1980.
ALVAR, K. R., LUKENS, H. R., LURIE, N. A. IRT Corp. FIN 8-1051,
80/11/30. 74pp. Available at NTIS 07287:109.

8012190465 NUREO/CR-1157 V2
"Thermal/Hydraulic Analysis Research Program," quarterly research rept.Apr-June 1980.Vol 2.
THOMPSON, S. L. Sandia Laboratories. FIN A-1216. SANDBO-1091.
BO/OB/31. 76ps. Available at NTIS. 07286:326.

GO12190530 NUREO/CR-1493 "Review of In-Véssel Meltdown Models." RIVARD,J.B. Bandia Laboratories. FIN A-1181, BANDBO-0455. BO/07/31. 44pp. Available at NTIB 07287:217.

8012190537 NUREO/CR-1779
"Emergency Preparedness for Nuclear Generating Facilities in Foreign Countries: Brief Survey of Practices."
SCHULLER,C.R., MARCUS,A.A., HANHARDT,A.M. Battelle Hemorial Institute, Pacific Northwest Laboratory, FIN 8-2311,
BHARC-S11-80-02, 80/12/31, 89pp. Available at NT18, 07273:178,

8012220167 NUREO/CR-1526 V3
"Physics of Reactor Safety," quarterly rept for Jul-Sept 1980.

* Argonna National Laboratory. FIN A-2015. ANL-80-54 V3.
80/11/30. 37pp. 07309:182

8012220600 NUREO/CR-1595
Radiological Assessment of Steam Generator Removal & Replacement:Update & Revision."
HOENES.O.R.: MUELLER.M.A., MCCORMACK.W.D. Battelle Memorial Institute. Parific Northwest Laboratory. FIN 8-2322. PNL-3454. B0/12/31. 109pp. Available at NTIS. 07309:019.

8012220609 NUREO/CR-1808
"Countercurrent Air/Water & Steam/Water Flow Above
Perforates Plats."
HGIEH.C. BANKOFF, S. G. , TANKIN.R. B. Northeastern Univ. FIN 8-6188.
BO/11/30. 149pp. Available at NTIS. 07309:217.

8012220615 NUREO/CR-1651
"Constitutive Relations in TRAC-PIA.
ROMATOI,U.S , SAHA.P. Brookhaven National Laboratory.
BNL-NUREO-51258. 80/08/31. 49pp. Available at NTIS. 07309;121.

8012220623 NUREO/CR-1730
"Data Summaries of LERs of Frimary Containment Penetrations at US Commercial Nuclear Power Plants," Jan 1972-Dec 1978.
8AMS.D. M. 7 R1JDUSKY, M. E0&O Idaho. Inc. FIN A-6276. E00-EA-5188.
80/09/30. 337pp. Available at NTIS. 07187:001.

8012220634 NUREO/CR-1621 "Characteriration of Faults in Appalachian Foldbelt." DDOM.A.L., HATCHER.R.D. Florida State Univ. FIN B-1053-8. 80/09/30. 628pp. Available at NTIB. 07296:231.

8012270670 NUREQ/CR-1456
"Experiment Data Rept for Semiscale Mod-3 Small Break Test
8-07-10 (Baseline Test Beries)."
SACKETT, K. E. E020 Idaho, Inc. FIN A-6038. E00-2035, 80/05/31,
265pp. Available at NTIS. 07275:236.

8012220678 HUREO/CR-1407
"Field & Hodeling Brudy of Windblown Particles from U Mill
Tailings File."
801WENDIMAN, L.C. SCHMEL, Q. A., HURBT, T. W. Battelle Memorial
Institute, Pacific Northwest Laboratory, FIN B-2079-9, PNL-3345,
80/06/30, 242pp, Available at NII8, \$6,00, 07297:195.

8012220707 NUREQ/CR-1674
"Firston Product Release From LWR Fuel Failed During Power
Cooling Mismatch & Reactivity Initiated Accident
Transients."
CBETEK, D.J., KINO, J.J. EG&O Idaho, Inc. FIN A-6041, EGG-2058,
80/10/31, 38pp. Available at NTIB, 07294:081.

8012220716 NUREO/CR-1437
"Two-Phrase Flow Measurement Techniques in Gas-Liquid Sys."
JONES, O. C. Brookheven National Laboratory, FIN A-3045,
BLN-NUREO-51185, 80/04/30, 91pp, Available at NTIS, 07298:123.

8012220719 NUREO/CR-1364

"Uncertainty Analysis for PWR LOCA, Part II: Alternative Core
Damage Estimators."

BERMAN, HALL, I.J. Sandia Laboratories. FIN A-1205. SANDSO-0629,
80/05/31, 101pp. Available at NTIS. 07276; 135,

8012220728 NUREO/CR-1420
"Health Status & Body Radioactivity of Former Thorium
Norkers:" interim rept.
SJEHNEY, A. F., POLEDNAK, A. P., RUNDO, J. Argonne National Laboratory,
FIN A-2050. ANL-80-37, 80/01/31, 54pp. Available at NTIS,
07298:071.

B012230075 NUREO/CR-1474
"Interaction of U Mill Tailings Leachate W/Soils & Clay
Liners," lab analysis/progress rept.
OEE,O.W., CAMPBELL.A.C., SHERNDOD.D.R. Battelle Memorial Institute,
Pacific Northwest Laboratory, FIN B-2292, PNL-3391, B0/06/30,
BBpp. Available at NTIG. \$3.75. 07317:164.

8012230099 NUREO/CR-1511
"Containment Main Steam Line Break Analysis for Equipment Qualification."
LAKKIN.D.E., GIDD,R.G., KUESTEL.A. Los Alamos Scientific Laboratory. FIN A-7105, LA-8305-MS. 80/06/30, 68pp. Available at NTIS. \$3,50. 07319:101.

B012230104 NUREO/CR-1426
"Development of Mechanistic Model for ECC Penetration In
PHR Douncomer," topical rept.
SEGEV.A. COLLIER, R.P. Battelle Memorial Institute, Columbus
Laboratories. FIN A-404B. BMI-2051. B0/06/30, 88pp. Available at
NTIS. \$3.75. 07319:016

GO12230201 NUREO/CR-1643
"Bouguer Oravity Anomaly Map of East-Central Hidcontinent of US." Hap encl.
KELLER.O.R., RUSSELL.D.R. Texas, Univ. of. HINZE,H.J. Purdue Univ. FIN B-5971. NRC-04-76-323. GO/10/31. 15pp. Available at NTIS. 07318:331.

B012230315 NUREO/CR-1261

"Mathematical Model for Predicting Probability of Acuta Mortality in Human Population Exposed to Accidentally Released Airborne Radionucitides: Final Rept for Phase I of Early Effects of Inhaled Radionuclides."

FILIPY/R.E., BURBIF, J. Battelle Memorial Institute, Pacific Northwest Laboratory, FIN B-2268, PNL-3257, B0/03/31, 120pp. Available at NTIS. 07318:092.

B012230317 Comments on NUREG-0731, "Quidelines for Util Mgt Structure & Technical Resources." NUREG incorporates provisions of unfinalized & unapproved documents. Outstanding issues should be resolved before issuence of next draft.

HANGOCK, J. A. Florida Power Corp. B0/12/18. 4pp. 07311:104.

8012290319 NUREO/CR-1232
"Three-Dimensional Fluid Finite Element."
BATHE, K.J., HAHN, M.F. Massachusetts Institute of Technology.
NRC-03-78-142, 80/02/29, 33pp. Available at NTIS. 07318:346.

8012230323 RUREO/CR-1284
"Methods of Determining & Controlling Bias in Nuclear Matl
Accounting Measurements."
BROUNB.R.J., MERRILL.J.A., ROBERTS.F.P. Battelle Memorial Institute.
Pacific Northwest Laboratory. FIN B-20149. PRL-3264. BO/06/30.
SOpp. Available at NTIS. 07321:281.

8012230325 NUREG/CR-1291
"LWR Pressure Vessel Burveillance Dosimetry Improvement Program," 1979 annual rept.
MCELROY,N. N. Hanford Engineering Development Laboratory. FIN 8-5988-7. HEDL-BA 1949. 80/02/29. 64pp. Available at NTIS. 07321:218.

B012230331 NUREO/CR-1528
"Bafaguards User Manual for Nuclear Matls Mgt & Bafaguards
Sys." final rept.
Boeing Computer Services, Inc. (subs. of Boeing Co.). FIN
B-6902-9. 80/08/31. 178pp. Available at NTIS. \$5.50. 07321:044.

8012230340 NUREO/CR-1324
"Preliminary Analysis of Flashing Transiants."
CROMLEY.C.J., WEI.8. Creare, Inc. NRC-04-75-162. CREARE TN-313.
80/07/31. 95pp. 07320:283.

8012230368 NUREO/CR-1519
"General Deology, Geophysics & Seismicity of Northwest AL."
KID. J. T. Alabama, State of, FIN 8-6617, NRC-04-78-262, 80/04/30, 89pp. Available at NTIB. \$4.25. 07320:197.

8012230370 NUREO/CR-1660
"Compilation, Assessment & Expansion of Strong Earthquake
Oround Motion Data Base, Seismic Safety Margins Research
Program (SBMRP)."
CROUSE, G. B., HILEMAN, J. A., TURNER, B. E. Laurence Livermore
Laboratory, Fin A-0139. UCRL-13227. 80/09/30, 137pp, Available
at NTIS. 07320:053.

8012230372 Comments on NUREO-0731, "Quidolines for Util Hgt Structure & Technical Resources." Requirement re staffing near-tern onsite emergency organization within 2-h is in conflict w/NUREO-0654.
MCDQNALD,R.P. Alabama Power Co. NO-80-0029. 80/12/17. 3pp. 07312:239.

8012230374 NUREO/CR-1338
"Allocation of NRC Insp Effort to Risk-Related Activities in Nuclear Power Plants."
LYRCH.O.L., BRADLEY, O.H., BRISBIN, R.L., Bandia Laboratories, FIN A-0252, BAND80-0361, BD/04/30, 134pp, Available at NTIS, 07319:270.

8012230390 NUREO/CR-1568
"LWR Fuel Rod Post-Bubcaoled Blawdown Scoping Analysis."
GRUBB.R.L. EG&G, Inc. FIN A-6269. 80/08/31. 46pp. Available at NTIB. \$2.50. 07319:247.

8012230487 Forwards comments on NUREO-0731 re util mgt structure & technical resources. Independent safety engineering group should rept to technically qualified comporate official responsible for nuclear power production.
CLEMENTS.B.R. Texas Utilities Generating Co. 80/12/15. 3pp. 07313:256.

B012230599 NUREO/CR-1257

"Burmary of FY79 Progress on Refill Effects Program,"
quarterly progress rept, Jul-Espt 1979.
ROTHEP, H., CROMLEY, C. J. Creares, Inc. FIN A-4070. CREARE TN-312,
B0/03/31. 33pp. Available at NTIS. 07310:016.

8012230516 NUREO/CR-1503 "Earthquake Focal Mechanisms in Boutheastern US." 9UINN, B.A. Georgia Institute of Technology. FIN A-9028. NRC-04-77-210. B0/06/30. 163pg. Available at NTIS. \$5.00.

8012230522 NUREO/CR-1585
"Modeling Tornado Dynamics," final rept.Jan 1976-May 1980,
ARAP Rept 421.
LEWELLEN, N. S., SHENO, Y. P. Aeronautical Research Associates of
Princeton. FIN 8-5795, NRC-04-76-218, 80/09/30, 235pp. Available
at NTIS. 07310:048,

BO12240004 Forwards 1977 & 1978 briefing books for Commissioners. FITZQERALD, J. A. Office of the General Counsel. 80/12/10. 1p, 07187:001.

--B012240025 NUREO-ODO2 EB

"Final Generic Environ Statement on Use of Recycle Pu in
Mixed Dxide Fuel in LNRs."

* Office of Nuclear Material Safety & Safequards, 76/08/31,
43pp. 07187:001.

--8012240031 NUREO-0217

"NRC Task Force Rept on Review of Federal/State Program for Regulation of Commercial Low Level Radwaste Burial Grounds."

* Office of Nuclear Material Safety & Safeguards. * Office of State Programs, Director. 77/03/31. 26pp. 07187:001.

B012240399 NUREO/CR-1554
"On Motions of Particles in Turbulint Flows."
LEE, B.L. New York, State Univ. of Btony Brook. DURBT.F.
Universitat Karlsruhe. FIN B-6211. 80/07/31. 130pp. Available at
NTIS. 07327:254.

8012240312 NUREO-0123 R3 "BTB for OE SKR: (BLR/5)." Supersedes NUREO-0123.Rev 2. * Office of Nuclear Reactor Regulation, Director, 80/12/31, 380pp. 07325:276.

BO12240507 NUREO/CR-1454 V3

"Reactor Safety Research Programs," quarterly rept Jul-Sept
1980, Vol 3.

EDLFR.S. K. Battelle Memorial Institute, Pacific Northwest
Laboratory, FIN B-2101, PNL-3380-3, B0/12/31, 78pp, Available at
NTIS, 07323:133.

BO12270193 Comments on draft NUREG-0731. "Quidelines for Util Mgt Structure & Technical Resources." Qualification requirements for personnel are too restrictive Quidelines should permit consideration of equivalent experience & training. SYLVIA.B.R. Virginia Electric & Power Co. 1007. 80/12/19. App. 07338:254.

8012290611 NURE9/CR-1835

"Application of Lidar Techniques to Estimating Atmospheric Dispersion," final rept.
VIHE.E., JOHNSON, M. B. Stenford Research Institute. FIN 8-6222.
NRG-04-77-147. 80/12/31. 57pp. 07336:041.

- BO12290615 NUREO/CR-1739 V2
 "Conceptual Design of NRC Headquarters Operations Ctr.User
 Needs for Radiological & Meteorological Data." Vol 2.
 MANNAN.J., HIMES.J. Mitre Corp. FIN 8-3099, SANDBO-7145/2,
 B0/12/31. 58pp. Available at NTIS. 07336:097.
- BO12290619 NUREO/CR-1739 VI
 "Conceptual Design of NRC Headquaters Operations Ctr.User
 Needs for Nuclear Data Link Info," Vol 1.
 HANNANJ., HIMES.J., WOLFE,D. Mittee Corp. FIN B-3099. BANDBO-7145.
 B0/12/31. 94pp. Available at NTIS. 07335:315.
- 8012300482 Forwards NEDO-24823, "Analysis of Two-Loop Test Apparatus Small Break Test Results," on behalf of BWR owners group.

 Bubmitial satisfies part of NUREG-0578 Requirement 2.1.9.

 BUCHHOLZ.R.H. General Electric Co. MFN-218-80, 80/12/29. 1p.
 07392:352.
- 8012310024 NUREG-0588
 "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," resolution of Generic Technical Activity A-24.for comment.
 SZUKIFNICZ.A. Office of Nuclear Reactor Regulation, Director. 79/12/31. 70pp. Available at NTIS, 07364:356.
- 80123i0026 Forwards errata to NUREO/CR-1728, "Feasibility of Epidemiologic Investigations of Health Effects of Low Level Ionizing Radiation." * Division of Technical Information & Document Control. 80/11/28. 1p. 07371:099.
- --8012310031 NUREO/CR-1728 ERR
 Errata to NUREO/CR-1728, "Feasibility of Epidemiologic
 Investigations of Health Effects of Low Level Ionizing
 Radiation," consisting of revised Pages 89: 92 & 97.
 # Equifax Health Systems Div. 80/11/28, 3pp. 07371:100.
- BOIREJ10028 NUREG-0611
 "Generic Evaluation of Feedwater Transients & Small Break
 LOCAs in Nestinghouse-Designed Operating Plants."

 Office of Nuclear Reactor Regulation: Director. 80/01/31. 600pp.
 Available at NTR. 07363:032.
- B012310116 NUREG/CR-1485 V1 ERR
 Errate to NUREG/CR-1485,01 i.Number 1, "Bafeguards Mati Control & Accounting Program," quarterly rept.Oct - Dec 1979.Rept number changed to NUREG/CR-0849, Vol 5, Division of Technical Information & Document Control. 80/11/25. 1p. 07371:179.
- 8012310177 Forwards sactions of "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Override of Containment Purge Valve Isolation" in response to 801207 telcon re NOREC-0737.1ten II.E. 4.2.
 MARIORE, J. A. Licensing Branch 3. 80/12/11. 5pp. 07371:196.
- G012310187 Forwards proprietary & nonproprietary versions of "Mestinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (7300 Sys)." in response to NUREO-0737. Application & affidavit for withholding encl. ANDERSON, T. M. Westinghouse Electric Corp. N8-TMA-2358. B0/12/23. 9pp. 07374:025.
- --B012310193 Nonproprietary version of summary rept. "Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (7300 Sys)." * Westinghouse Electric Corp. B0/12/31. 78pp. 07374:034.
- --801231019B Nonproprietary version of summary rept. "Hestinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (Upper Head Injection Plant)." * Westinghouse Electric Corp. 80/12/31. 79pp. 07374:112.
- --B012310201 Nonproprietary version of summary rapt, "Mestinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (Microprocessor Sys)," * Nestinghouse Electric Corp. 80/12/31, 82gp. 07374:191.
- 8012310274 NUREO/CR-1717 V2
 "Boll Structure Interaction Methods BLAVE Code," Vol 2.
 COSTANINO, C. J., MILLER, C.A. Brookhaven National Laboratory. FIN
 A-3216-9. BNL-NUREO-51263. 79/09/30. BOpp.
- BO12310297 NUREQ/CR-0773
 "Training & Qualifying Personnel for Performing Measurements for Control & Accounting of SNM,"
 BROUNS.R.J., ROBERTEG.F. P. Battelle Memorial Institute, Pacific Northwest Laboratory. FRIS B-2014. PNL-3020. B0/11/30. 12pp. Available at NTIS. 07370:168.

- 8012310297 NUREC-0139 V4 NO1
 Buff book: "Status Bummary Rept.Water Reactor Safety
 Research." data as of 800131.Vol 4.Number 1.
 * Office of Nuclear Regulatory Research. Director. 80/04/14.
 300pp. Available at NTIS.
- 8012310300 NUREO-0327-79/9
 Gold book: "Regulatory Licensing, Data for Decisions," status
 surmany rept.
 Butter of Nuclear Material Bafety & Bafeguards, 79/09/28, 206pp.
- 8012310304 NURE0-0020 V4 NO5 Grey book: "Operating Units Status Rept," data as of 800430, Vol 4.Kumber 5. # Commissioners. 80/06/19. 230pp. Available at NTIB.
- 8012310308 NURE0-0580 V9 N03 Interim blue book: "Regulatory Licensing Data for Decisions, Nuclea: Power Plants," status summary rept.Vol 9, Number 3. " Commissioners. 80/08/01. 52pp. Available at NTIS.
- 8012310313 NUREO-0580 V9 NO1
 Blue book: "Regulatory Licensing, Data for Decisions, Nuclear Power Plants," status summary rept, Vol 9, Number 1,
 4 Commissioners, 80/02/29, 240pp, Available at NTIS.
- 8012310394 NUREO/CR-1805
 "Analysis of Earthquake Intensities H/Respect to
 Attenuation, Magnitude & Rate of Recurrence, Revised Edition,"
 final rept.
 8RAZEE,R.J. Commerce, Dept. of, National Oceanographic & Atmospheric
 Administration. FIN 8-5692. ED8 NOSDC-2. 80/12/31. 164pp.
 Available at NTIS. 07370:272.
- 8012310399 NUREO-0304 V3
 "Regulatory & Technical Repts," compilation for 1975-78,
 Vol 3.

 * Division of Technical Information & Document Control.
 MCKENZIE.L. ARAGON,R. Systematic Evaluation Program Branch.
 80/05/31, 550pp. Available at NTIS.
- 8012310445 MUREO/CR-1804
 "Re-evaluation of Modified Mercalli Intensity Scale for
 Earthquakes Using Distance as Determinant."
 BRAZEG.R.J. Commerce.Dept. of, National Oceanographic & Atmospheric
 Administration. FIN 8-3692. EDIS NOSDC-4. 80/12/31. 340pp.
 Available at NTIS. 07345:048
- GRO CORRESPONDENCE WITH OTHER ORGANIZATIONS
- B012010236 Forwards notification of B01124 meeting re LER sequence coding & search procedure workshop.
 MICHELBON.C. Director's Office. B0/10/23, 3pp. 07097:304.
- B012050001 Informs that NRC anticipates no difficulty in implementing FEMA guidelines for dam safety. Status of NRC progress reimplementation of guidelines & major recommendations will be provided by 811231. DIRCKB:H.J. Office of the Executive Director for Operations, 80/10/17. ip. 07211:001.
- --8012050002 Forwards "Federal Quidelines for Dam Bafety," & "Early Progress to Implement Federal Guidelines for Dam Bafety & Recommendations to Improve Federal Dam Safety Programs."

 Requests rept re progress of implementation guidelines.

 MACY, J. H. Federal Emergency Management Agency. 80/09/17. 2pp.
 07211:002.
- --8012050005 "Federal Ouidelines for Dam Safety."

 * Federal Coordinating Council for Science, Eng. & Technology.
 79/06/25, 32pp. 07211:006.
- --8012030009 "Early Progress to Implement Pederal Guidelines for Dam Bafety & Recommendations to Improve Federal Dam Safety Programs." * Federal Emergency Management Agency, 80/07/30, 100pp, 07211:056.
- 8012090028 Responds to 800925 ltr re future commercial availability of DUE atmospheric release advisory capability at nuclear gower stations. Pilot tests to be performed & evaluated. REHM.T.A. Office of the Executiva Director for Operations. 80/11/26. jp. 07197:309.
- --8012090032 Forwards DDE 800717 memo presenting legal opinion that DDE cannot assume commercial sector role for atmospheric release advisory capability sys. Program details need to be worked out w/MRC t. FEMA.
 BARBER, R.W. Energy, Dept. of. 80/09/25. 2pp. 07197:310.

- 8012110535 Responds to FOIA request for memoranda of understanding between NRC & FEMA.Forwards two memoranda of understanding between NRC & FEMA for incident response & radiological emergency planning & preparedness.

 FELTON, J. M. Division of Rules and Records, 80/12/05, 1p. 07227:150.
- --8012110338 Memorandum of understanding between NRC & FEMA re radiological emergency planning & preparadness. CAMM.F.A. Federal Emergency Management Agency, 80/11/04. App.
- 8012110542 FOIA request for memoranda of understanding between NRC & FEMA noted in encl press release.

 QROBEMAN.K. Island Closeup News Service. 80/11/28. 2pp. 07227: 151.
- B01211074B Concurs w/draft memo to Executive Director for Operations transmitting final rule on 40CFR190. DENION,H.R. Office of Nuclear Reactor Regulation, Director. B0/11/24. ip. 07227; 179.
- 8012230211 Responds to 801028 ltr requesting help in development of info package & other mat! for use by state & local emergency preparedness officers in event of incident at nuclear power plant. Info will be provided.

 AHEARNE, J. F. Commissioners. 80/11/13. 1p. 07317:033.
- --8012230216 Informs of contract award to N Low & Associates, Inc to develop public aducation info programs re response to any possible incident at nuclear generating station. Requests NRC cooperation in course of project.

 MACY.J. H. Federal Emergency Management Agency. 80/10/28. ip. 07317:054.
- 8012230474 Responds to 800908 request for info re Task Group membership & proposed schedule for completion of wastewater study. Meeting scheduled for 801218-17 at TMI.Recommendations retritium will be made in Feb 1981.

 81NCLAIR.W.K. National Council on Radiation Protection & Measurements. 80/12/16. 3pp. 07313:210.
- BO12240442 Responds to 801201 request for review & comment on "Draft Quidancs on Offsite Radiation Measurement Sys.Phase 2.Honitoring & Measurement of Radioiodine to Determine Dose Commitment in Milk Pathway." GRIMES.B. K. Emergency Preparedness Program Office (after 801119 see 1&E), 80/12/01. App. 07327:337.
- B012290245 Forwards TF Engelhardt 801208 ltr sent to FR requesting approval of matl to be incorporated by ref into various sections of 100FR.

 ENGELHARDT.T.F. Deputy Executive Legal Director. 80/12/12. ip.
- --8012270250 Notifies that review of listed matl to be incorporated by ref in various sections of 100FR is complete. EEQAL.O. Office of the Federal Register. 80/11/25. 4pp. 07337:088.
- 8012310387 "Use of Stds in Selecting Bites for Nuclear Power Plants." MINGOUE,R.B. Office of Standards Development, Director, ROBERTS.I.C. Assistant Director for Siting Standards. 80/12/16. 13pp. 07369:192.

PR PROPOSED RULE

- 8009100422 SECY-80-379 309100422 BECY-BO-379

 Bubmits proposed plan for development & articulation of NRC safety objectives, notably w/respect to reactors. Btatus of NRC work, description of Qfc of Research sponsored projects & draft staff requirement memo & FR notice ancl. HANRAHAN, E. J. Office of Policy Evaluations. BICKWIT, L. Of the General Counsel. 45FR71023. 80/08/12. 28pp. 03517:15 Office of 03517: 197.
- 8011280106 Transcript of 801121 Affirmation Session 80-51 in Washington DC re discussion & vote on SECY 80-457 Pp 1-31, * Commissioners. 80/11/21. 31pp, 07082:043.
- -8011280112 SECY-80-474
 Informs that NRC has concluded & recommended that revisions should be made to 100FR73 amend & to draft Reg Guide 80 901-4. Forwards revised amends & submits guide changes: MINOSUE,R.B. Office of Standards Development, Director. 86 48pp. 07082:091.

- 8012010099 Comments by Children's Orthopedic Hosp & Medical Ctr on proposed rule 10CFR20 re disposal of tritium & C-14 radwastes into sanitary sewer sys. Reduction in vol of waste in form of scintillation fluid & vials will reduce cost.

 SMITH.E. K. Affiliation Unknown. 48FR67018 093. 80/11/11. 1p. 07097:330.
- B012010103 Comments on proposed rule 10CFR20, "Btds for Protection Against Radiation." Supports rule. BONIE,F.J. Texas, Univ. of, Dallas. 45FR67018 077. 80/11/05. lp. 07097:327.
- B012010111 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Eliminates cost of shipment & burial, Bupperts rule. KALAKOWSKY, S.C. Carter Wallace, Inc. 45FR67018 078, 80/11/07. 2pp. 07097: 327.
- B012010209 Forwards notice of correction to final rule 10CFR73.1(b), physical protection of plants & matls.published in 790724 FR. Requests that correction be published at earliest possible date. CHILK, B. J. Office of the Secretary of the Commission. 60/10/08. ip. 07097:316.
- --8012010259 Notice of correction to final rule 10GFR73.1(b), physical protection of plants & matls, published in 790724 FR. Error made in amendatory language resulting in inadvertent deletion of 10GFR73.1(b)(2),(3),(4) & (5).

 DIRCKS,H. J. Office of the Executive Director for Operations. 80/09/30. 3pp. 07097:317.
- 8012010414 Forwards notices of Sys of Records proposed minor amends for publication in 801022 FR.
 CHILK.B.J. Office of the Secretary of the Commission. 80/10/16.
 1p. 07097:015.
- --8012010418 Notices of Sys on Records proposed minor amends to NRC-1, 4,7,8,9,11,15,16,18,20,22,27,31,33,34,36 & 38.Comments due on or before 80(121. DIRCKB.M.J. Office of the Executive Director for Operations, 80/10/09, 21pp. 07097:016.
- 8012010419 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule. HENDERSHOTTI. L. St. Louis Univ. Medical Center St. Louis, MQ. 45FR67018
- 8012010432 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 FERNANDEZ-PAL St. Louis Univ. Medical Center St. Louis, MD. 45FR67018 1CO. 80/11/10. 1p. 07097:013.
- 8012010444 Comments on proposed rule 10CFR20 re-disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.

 HERB19.F.K. St. Louis Univ. Medical Center St. Lauis.NG. 45FR67018 102.
- 8012010450 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 BOYD.R.M. Oborgia Institute of Technology. 45FR67018 109.
 BO/11/11. 1p. 07097:003.
- B012010461 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations," KEMPER, J. B. Philadelphia Electric Co. 45FR65466 003. B0/11/03. 2pp. 07096:359.
- 8012010468 Comments on proposed rule 10CFRSO, "Interim Requirements Re Hydrogen Control & Degraded Core Considerations." LEHIS,M. I. Affiliation Unknown. 45FR65466 005. 80/10/31. 7pp. 06916:001.
- 8012010301 Comments on proposed rule 10CFR20 re radwaste disposal. Changes should be applied to other isotopes as well. Supports rule.
 SUCARMAN.W. Chicago, Univ. of. 45FR67018 089, 80/11/11, 1p. 07098:233.
- 8012010508 Comments on proposed rule 10CFR20 re disposal of tritium & C-14 into sanitary sewer sys. Rule would reduce pressures on burtal sites. Supports rule. DALY.N.J. Arizona, Univ. of. 45FR67018 056, 80/11/04, 1p. 07098:232.

- 8012010516 Comments by Veterans Administration Medical Ctr.Northport.NY on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 HQDBON.W.L. Affiliation Unknown. NNFR67018 053. 80/10/30. 1p. 07098:231.
- 8012010322 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule will conserve resources, reduce medical costs & reduce chemical & pathogenic hazards associated w/wastes, DUELFER, T. Johns Hopkins Medical Institutions Baltimore, HD. 45FR67018 057. 80/11/05. 1p. 07098:230.
- 8012010530 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Heavy culture vial containing 1. 5 UCI C-14 culture media should also qualify under change. Bupports rule. GREGORY, W.D. Rochester, Univ. of, Medical Center. 45FR67018 054, 80/11/05. 1p. 07098; 227.
- 8012010624 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule would reduce quantity of low level radwaste sent to approved landfill & capacity for higher level waste.

 JUDD.C.I. Richardson-Kerrell.Inc. Herrell-National Laboratories Div. 45FR67018 091. 80/11/12. 1p. 07098:216.
- 8012020494 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C~14. Supports rule.

 CV14. Supports rule.

 CV150N.R.C. St. Louis Univ. Kedical Center St. Louis, MD. 45FR67018

 OPP. 80/11/10. 1p. 07148:136.
- 8012020459 Comments on proposed rute 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C~14.Supports rule.

 HG.J.E. Bt. Louis Univ. Medical Center St. Louis.MG. 45FR67018 098.
 80/11/10. ip. 07148:135.
- 8012020467 Comments on proposed rule 10CFR20 re disposal of liquid scintiliation media & animal carcasses containing tritium & C-14. Supports rule.

 GERROE. E. A. 8t. Louis Univ. Medical Center St. Louis.MO. 43FR67018 103. 80/11/10. 1p. 07148:134.
- 8012030816 Comments on proposed rule 10CFR50. "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Evaluation should be done re challenges be containment integrity due to fuel cladding & water hydrogen production. KGMALSKI, J. F. Affiliation Unknown. 45FR65466 CO9. 80/10/30. ip. 07149:142.
- B012030B24 Comments by Ethos Research Droup on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." BATES, A. Affiliation Unknown. 45FR65466 013. B0/10/29. 4pp. 07149:093.
- BO12030831 Comments on proposed rule IOCFR50, "Interim Requirements Re Hydrogen Control & Cortain Degraded Core Considerations," NRC should finalize policy & then ask for comment on technical details. YBARRONDO.L.J. Affiliation Unknown. 43FR65466 008, B0/10/28, 2pp. 07149:091.
- B012030836 Comments on proposed rule 10CFR50. "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Bite-specific evaluations of all subjs would be desirable in EIS to permit alternative solutions to problems. RATHLESBERGER Interior, Dept. of. 45FR65466 014. B0/11/03. 2pp. 07149:089.
- B012030718 Responds to FOIA request for all documents commenting on final rule 10CFR40. "Deletion of Bource Matl Medicinals from General License of Small Quantities of Source Matl." Forwards documents listed in App A. FELTON.J. N. Division of Rules and Records. B0/11/21, 2pp. 07/31:130
- 3012030922 FOIA request for all documents commenting on final rule 10CFR40. "Deletion of Source Matl Medicinals from General License of Small Quantities of Bource Matl." MATSON.T.M. FOI Service. 001386. 80/11/05. 1p. 07151:132.
- 3012040044 Comments on proposed rule 10CFR50 re advance notice of rulemaking on licensing requirements for pending CP & mfg license applications. Commitments required in areas subj to rulemaking have potential for delaying CP licensing process.

 CAMN.A.L. Bechtel Corp. 45FR65247 004. 80/11/14. 6pp. 07152:052.

- 8012040058 Advises recipients of comments on 10CFR50 under 45FR65466 & 45FR65474. Comment Numbers 14,28 & 29 under 45FR65464 should be Numbers 2.3 & 4 respectively under 45FR65474. Numbers 14,28 & 29 will not be used again.

 * Docksting & Services Branch. 45FR65466. 80/ii/14. lp. 07170:281.
- 8012040072 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedure for unforcement actions. Section on enforcement actions should devote same space to NRC responsibilities in inspecting plant, ALLEY, N. P. Federal Emergency Management Agency. 45FR66754 ODB, BO/11/97. 1p. 07170:280.
- B0120400B7 Comments on proposed rule 10CFR50 re whether broader range of accidents of both lesser & greater severity than DBA should be considered in plant design, operation & safety analysis.

 AGUILAR,F. E0&0, Inc. 45FR65474 004. 80/10/31. 2pp. 07170:261.
- 8012040097 Comments on proposed rule 10CFR50 re nuclear power plant degraded core & core melt accidents.

 DEARTEN.J. A. Affiliation Unknown. 45FR69474 003. 80/11/06. 2pp. 07170: 249.
- B012040108 Comments on proposed rule 10CFR50 re nuclear power plant degraded core & core melt accidents.
 RATHLESBERGER Interior, Dept. of. 45FR65474 002. B0/11/03. 2pp. 07170; 242.
- B012040119 Submits corrected comments on proposed rule 10CFR50 & NUREQ-0694, "Functional Criteria for Emergency Response Facilities."
 SCHUYLER.J.O. Pacific Gas & Electric Co. 45FR54708 035. 80/11/05. ip. 07170:241.
- 8012040327 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Dagraded Core Considerations," Rule should be integrated w/requirements of NUREO-0660. WATERS, D. B. Carolina Power & Light Co. 45FR65466 007. 80/10/29, 2pp. 07170.173.
- 8012040334 Comments on proposed rule 10CFR80. "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." EDNARDS.D.W. Yankee Atomic Electric Co. 45FR65466 016. 80/11/05. 3pp. 07170.153.
- --B012040347 IAEA-CA-39/212
 Probablistic assessment of containment inerting in BWRs.
 HEISIKO-GOODMAN Massachusetts Institute of Technology. 80/11/20.
 13pp. 07170:139.
- BO12040360 Comments on proposed rule iOCFR50. "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Rule is unrealistic & unnacessary & should be deleted or extensively revised. PARKER.N.O. Duke Power Co. 45FR65466 029. B0/11/07. 2pp. 07170.149.
- 8012040366 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Gare Consideration."
 Rule should assure that proceedings will not be rushed in effort to provide rule on degraded care matters.
 FEROUSON, J. H. Virginia Electric & Power Co. 45FR6546 026, 80/11/10. 2pp. 07170:143.
- 8012040372 Comments on progosed rule 10CFR30, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Implementation of rule may be useful in documenting actions to be taken to reduce reactor risk re hydrogen control. SHERHOOD, 0. O. General Electric Co. 45FR65466 017. 80/11/06. ipp. 07170:136.
- 8012040378 Forwards commments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations."

 JDNES, R.C. Gmeha Public Power District. 45FR65466 024. 80/10/30. 3pp. 07170:133.
- 8012040392 Comments on proposed rule 10CFR90, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Rule should pertain only to hot leg vents & pressurizer for raised loop Bill plants. BRIGHT,R.M. Florida Power Corp. 45FR65466 023. B0/11/07. 2pp. 07170:131.
- 8012040662 Informs that during 801009-11 meeting, proposed rule on fire protection submitted to Committee w/SECY-80-438A was considered. Does not recommend issuance of rule, but requests examination of revisions.

 PLESSET! M.S. ACRS Advisory Committee on Reactor Safeguards. 80/10/14. 2pp. 07166:349.

- 8012030012 Comments on proposed rules 10CFR30, 32,70 & 150 re exempting certain radioactive metals from use restrictions. Rule would increase risks of detrimental human health effects. Opposes rule. MAY, J. Affiliation Unknown. R70874 005. 80/11/21. 2pp.
- B012050053 SECY-80-507
 Seeks Commission approval of encl draft FR notice endorsing deferment of mandatory acceptance of nuclear plant reliability data sys & development of integrated operational experience reporting sys. Recommends approval. DIRCKB, M. J. Office of the Executive Director for Operations. 80/11/14. 60pp. 07173:116.
- 8012050065 Comments on proposed rule 10CFR50 on interim requirements re hydrogen control interim requirements should not be established which may be changed during long-term rulemaking process, unless necessary to protect public.

 80UCHEY. G. D. Washington Public Power Supply System. 45FR65466 031.

 80/11/13. 2pp. 07174:330.
- B012050075 Comments by QH EPA on proposed rule 10CFR20 re stds for protection against radiation. Assessment of scintillator solutions indicates that simplest & safest method of disposal is to add solutions to local heating oil. MCAVQY,J.F. Ohio, State of. 45FR45302 006. B0/11/13. 1p. 07174:332.
- B012000084 Comments on proposed rule 10CFR50 re advance notice of proposed rulemaking re Tech Specs. Rule should be postponed until specific criteria for categorizing Tech Bpec requirements generated.

 SHERNOD, 0.0. General Electric Co. 45FR45916 033. 80/11/14. 5pp. 07174: 333.
- B012030098 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations."
 Rule is premature & unnecessary.
 DEMPERS.P.A. Affiliation Unknown. 45FR65466 034. 80/10/30. 1p. 07174: 339.
- B012030103 Comments on proposed rule 10CFR50, "Interim Requirements Re Hudrogen Control & Certain Dagraded Core Considerations," Requirement to consider 75% of fuel cladding reacting u/ water to produce hudrogen appears excessive. BHIELDS.B.W. Public Bervice Co. of Indiana, Inc. 45FR65466 033. 80/11/17. 2pp.
- 8012050110 Bubmits supplemental comment on proposed rule 10CFR50, "Interim Requirement Re Hydrogen Control & Certain Degraded Core Considerations," Addition of second "block" valve could result in unsafe design or violation of ABRE code. KEMPER: J. B. Philadelphia Electric Co. 45FR65466 032A. 80/11/18. 2pp. 07174:343.
- 8012050115 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Commission should issue interim rule but concontrate on compilation bases for degraded or melt core rulemaking. CLAYTON.F.L. Alabama Power Co. 45FR45466 032. 80/11/04. 3pp. 06915:001.
- 8012050462 Forwards FES, "Mgt of Commercially Generated Radwaste," Yols 1,2 & 3, for use in proposed rulemaking on storage & disposal of nuclear waste.

 BROWN, D. F. Energy, Dept. of. 80/11/28. 7pp. 07176:044.
- --B012050474 D0E/E18-0046F V1
 FEB, "Mgt of Commercially Generated Radwaste," Vol 1.
 + Energy, Dept. of. UC-70, 80/10/31, 500pp. Available at NYIB, #27.50. 07176:051.
- --8012050485 DDE/EI8-0046F V2 FEB, "Mgt of Commercially Generated Radwaste," Vol 2, Apps. * Energy, Dept. of. UC-70. 80/10/31. 350pp. Available at NTIB. *19.00. 07177:309.
- --8012030493 DOE/EIB-0046F V3
 FEB "Mgt of Commercially Generated Redwaste," Vol 3, Public Comments Hearing Board Rept.
 * Energy, Dept. of, UC-70. HD/10/31, 500pp. Available at NTIB. \$29.00. 07179:288.
- B012030465 Forwards comments on proposed rule 10CFR30. "Interim Requirements Re Hydrogen Control & Cartain Degradad Core Considerations."

 ABEL J. B. Commonwealth Edison Co. 45FR4546 012. B0/11/03. App. 07175:313.

- 8012050508 Comments by State of UT. Dept of Health on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Approval recommended. ANDERSON. L. F. Utah, State of. 45FR67018 058. 80/11/04. 1p. 07174:245.
- B012050519 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14.Rule maintains safety of raduastes disposal resulting in reduction of vol of raduaste shipped to burial grounds.

 BDNATI.R M. St. Louis Univ. Medical School. 45FR67018 059.

 80/11/05. 1p. 07174:264.
- 8012050552 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media containing tritium & C-14. Burial procedures for subj metls are expensive & wasteful. Supports rule.

 BIERNAN.E.L. Washington, Univ. of. 45FR6701B 097. 80/11/10. 1p. 07123-270.
- 8012050570 Comments on proposed rule 10CFR20 re disposal of liquid scintillation waste containing tritium & C-14. Reducing val of waste shipped to disposal sites would allow longer usage time for those facilities. Supports rule. PERKINS.M.A. Washington, Univ. of. 45FR67018 096. 80/[1/10] ip. 07174:313.
- 8012050591 Comments on proposed rule 10CFR20 re disposal of liquid scintillation waste containing tritium & C-14. Reducing vol of redwaste shipped to disposal sites would allow longer usage time for those facilities. Supports rule.

 BENJANIN M. M. Washington, Univ. of. 45FR67018 095. 80/11/10. lp. 07174:314.
- 8012050592 Comments on proposed rule 10CFR20 re disposal of liquid scintillation waste containing tritium & C-14. Reducing vol of radwaste shipped to disposal sites would allow longer usage time for those facilities. Supports rule.
 WELCH, E. B. Washington, Univ. of. 45FR47018 094. 80/11/10. 1p. 07174-315.
- 8012050600 Comments on proposed rule iOCFR2O re disposal of liquid scintiliation media & animal carcasses containing tritium & C-14.Other listed radionuclides should be included in rule. Supports rule.

 80HADTIM, W. Oppr
- 8012030611 Comments by Atomic Disposal Co.Inc on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carasses containing tritium & C-14. Alternative would be to open regional waste sites for low level waste. BELL, J. P. Affiliation Unknown. 45FR47018 107. 80/11/11. 2pp. 07174:318.
- 8012050619 Comments by Chamical Industry Inst of Yoxicology on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 PARKER, Ø. D., WOLKOMSKI-TLY Affiliation Unknown. 45FR67018 106. 80/11/11. 20pp. 07174: 320.
- 8012050629 Comments by Natl Association of Countries Research, Inc on proposed rule 10GFR20 re disposal of liquid ecintillation media & animal carcasses containing tritium & C-14. Level of 0.05 mCl/g should be set lower in order to achieve ALARA. EPSTEIN.L.R. Affiliation Unknown. 45FR67018 105, 80/11/12. 3pp. 07174:322.
- 8012080103 Responds to FOIA request for records re NRC opposition to making fire protection rule applicable to future plants or licenses & future application of rule Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 80/12/02. 2pp. 07189:187.
- --8012080118 Comments on proposed App B re fire protection. Disagrees w/ waiver of requirement for automatic fire suppression & supports five member fire brigade for most plants.
 SCHROEDER.F. Division of Systems Bafety. 79/11/13. 1p.
- 8012080109 FOIA request for records to NRC opposition to making fire protection rule applicable to future plants or licenses & future application of rule.
 WATKING, M. Debavoice & Liberman. 80/11/18. 3pp. 07189:189.
- B012080110 Forwards comments on proposed rule 10CFR50, "Interia Requirements Re Hydrogen Control & Certain Degraded Core Considerations." BEELEY, 0.T., LEPPKE, D. M. Fluor Power Bervice, Inc. 45FR65466 010. B0/10/31. 3pp. 07194:184.

- 8012080128 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14.188C should examine ways to provide greater leeway in safe disposal of other radionuclides. Supports rule. FURTH.F.W. Mead Johnson & Co. 45FR47018 090. 80/11/12. ip. 07194:182.
- 8012080136 Comments on proposed rule 10CFR20 re disposal of radwaste containing tritium 2 C-14 Rule should be extended to include lab glassuare, plasticware 2 paperware. Supports rule. NEHTON, N. A. Childrens Hosp. Columbus. OH. 45FR67018 092. 80/11/07. ip. 07194:180.
- 8012080142 Comments on proposed rule 10CFRSO, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations."

 NRC should state intention to utilize interim rule as basis for licensing until final rule is developed. HAGALP. 8. Offshore Power Systems (subs. of Westinghouse Electric Corp.). 43FR63466 011. 80/11/03 3pp. 07174:177.
- B0120B0145 Comments on proposed rule 10CFR30, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." SULLIVAN.T.J. Consumers Power Co. 45FR65466 019. 80/11/03. 2pp.
- 8012080148 Comments on proposed rule 10CFRSO. "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Promulgation of Interim rule is premature & imprudent. HIDNER, M. A. Georgia Power Co. 45FR65464 020. B0/11/03. 3pp. 07194:327.
- 6012080152 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Supports rule. 01885, D. C. Atomic Industrial Forum. 45FR65466 015. 80/11/04. App. 07194:321
- 8012080154 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Imposing requirements w/o consideration of plant differences could lead to licensing difficulties resulting in shutdown. BRADBURY.R. B. Stone & Webster Engineering Corp. 45FR65466 018. 80/11/04. 3pp. 07194:318.
- 8012080160 Comments on proposed rule 10CFR3D, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Supports promotigation of interim criteria supplementing regulatory requirements.

 ANDERSON.T.M. Westinghouse Electric Corp. 45FR65966 021. 80/11/04. Spp. 07194:310.
- 8012080167 Comments on proposed rule IOCFR50. "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Rule should clearly state goals & if sufficient info is available.acceptable approaches to that goal. SCHERER.A.E. C-E Power Systems. 45FR65466 022. 80/11/06. 2pp. 07194:308.
- 8012080210 Comments on proposed rule 10CFR20 re disposal of 11quid scintillation media & animal carcasses containing tritium & C-14. Supports rule.

 LUCEY, J. (f. Notre Dame, Univ. of. 45FR67018 125. 80/11/13. ip. 07194:298.
- 8012080216 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Impact on human & animal health & environ will be negligible. Financial savings will be enormous. KRUECER, B. K. Haryland, Univ. of, Baltimore. 45FR67018 126. 80/11/13. 1p. 07194:297.
- 8012080221 Comments on proposed rule 10CFR20 re disposal of liquid scintiliation media & animal carcasses containing tritium & C-14. Rule should include other radionuclides if feasible. Supports rule. PERIKKAS, V. T. Connecticut, Univ. of. 45FR67018 127. 80/11/13. 1p. 07194: 296.
- 8012080226 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges adoption.

 SKIERAMINSKI,P. Hississippi, Univ. of., 45FR67018 123. 80/11/11.
- 8012080228 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & requests rapid implementation.
 GEARHART.J. Maryland. Univ. of, Saltimore. 45FR67018 124. BO/11/13.
 1p. 07194:270.

- 8012080231 Comments on proposed rule 10CFR20 re disposal of liquid scintiliation media & animal carcasses containing tritium & C-14. Similar approach should be taken w/P-32 & I-125. Bupports rule. WILCOX.F.W. Affiliation Unknown. 45FR67018 128. 80/11/13. 1p. 07194:236.
- 8012080239 Comments on proposed rule 10CFR20 re disposal of iiquid scintillation medja & animal carcasses containing tritium & C-14. Promotes increased safuty & better health associated w/use & disposal of low level waste. Bupports rule. SHAW.E. I. Kansas, Univ. of. 45FR6701B 129. B0/11/14. 1p. 07194:235.
- B0120B0242 Comments on proposed rule iOCFR20 re dispost of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 BROWN.R.F., MCKUZEN.J. W Arizona, Univ. of. 45FR67018 i30.
 B0/11/13. 1p. 07194:234.
- 8012080291 Comments on proposed rule 10CFR20 re disposal of liquid scintiliation media & animal carcasses containing tritium & C-14. Supports rule & encourages NRC to liberalize similar restrictions for other radionuclides.
 POLK. A. William H. Rorer, Inc. 45FR67018 134. 80/11/07. 1p. 07194:233.
- 8012080253 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Changes will extend buriai capacity, reduce high cost of waste disposal & reduce waste vol. Supports rule. UNTALAN, J. T. Affiliation Unknown. 45FR67018 139. 80/11/03. 3pp.
- 8012080255 Comments on proposed rula 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule but questions intent of rulemating & what must be done to comply.

 DUPRE, B. M., MILMICZ, R. R. Princeton Univ. 45FR67018 138. 80/11/06. 2pp. 07194: 231.
- 8012080262 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animai carcasses containing tritium & C-14. Supports rule.

 LAMBERT. J. P. Kansas State Univ. 45FR67018 137. 80/11/12. 2pp. 07194: 228
- B012080766 Comments on proposed rule iOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Opposes rule.
 TILDERG.K.R. Friends of the Earth. 45FR67018 132. 80/11/06. 1p. 07194:227.
- B0120B027I Comments on proposed rule 10CFR20 re disposal of liquid scintiliation modia & animal carcasses containing tritium & C-14. Supports liberalization of regulations.
 MEYER, J. H. Vet. Admin. Hosp. Sepulveda, CA. 45FR67018 133. B0/11/13. lp. 07194:223.
- 8012080277 Comments by East Carolina Univ on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule. DEFRIFS9.F.P. Affiliation Unknown. 45FR67018 136. 80/11/07. 2pp. 07174: 217.
- 8012080281 Comments on proposed rule iOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & recommends that same criteria be applied to I-125.

 ANDERSON. H.: BROWN. J. L., HANSON. P. Mallinckrodt, Inc. 45FR67018 135. 80/11/07. 1p. 07174:209.
- 8012080285 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.

 FOLANI, J. H. Missouri, Univ. of, Columbia. 45FR67018 041. 80/10/29.

 10. 07194: 208.
- 80:20B0992 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcassas containing tritium & C-14. Rule would decrease handling & burial costs. Supports rule.

 FEREZ. C. A. Hashington Univ. 45FR67018 110. B0/11/04, 1p.
- 8012080299 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.

 GUTH, F. H. Vet. Admin. Hosp. Los Angales, CA. 45FR67018 111, 80/11/06.

- 8012080304 Comments on proposed rule 10CFR20 re dispusal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule should include other radwaste based on isotope radiotoxicity. half-life & behavior in environ. COPE.R. M. Affillation Unknown. 45FR67018 112. 80/11/12. 1p. 07194:201.
- B01298030B Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & encourages liberalization of similar restrictions for other radionuclides.
 LINDENBLAD.O.E. Mallinckroot, Inc. 45FR67018 113. 80/11/14. 1p. 07194:200.
- BO120B0312 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Bupports rule.
 LAMB007.J.P. Maryland. Univ.of. Baltimore. 45FR67018 115.
 B0/11/14. 1p. 07194:199.
- 8012080317 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule would conserve burial capacity & produce little radiological health hazard. Supports rule.
 OBTER-GRANITE Maryland, Univ. of, Baltimore. 45FR67018 117. 80/11/13. ip. 07194:178.
- 8012080325 Comments on proposed rule 102FR20 re disposal of liquid scintillation media & animal carcassas containing tritium & C-14. Supports rule.
 FLETCHER, J.W. St. Louis Univ. Medical Center St. Louis, HD. 43FR67018 104. 80/11/10. ip. 07194:195.
- B0120B0330 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 RODKEY.L.B. Kansas State Univ. 45FR67018 122. B0/11/13. 1p. 07194:194.
- B0120B0333 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule. PICKARD.R.C. Indiana. State of. 45FR67018 120. B0/11/07. 1p. 07194:191.
- B0120B0337 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Bupports rule.
 HYMER.H.W. Affiliation Unknown. 45FR67018 119. B0/11/11. lp. 07194:190.
- 8012080343 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. NRC must resolve controversial matter of risk involved in public exposure. Opposes rule.

 MEISBLAT, D. 1. Upjohn Co. 45FR67018 (18. 80/11/14. 1p. 07196; 210.
- 8012080345 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & enimal carcasses containing tritium & C-14. Rule should be extended to include disposal of other radionuclides such as 1-125, I-131 & F-32. Supports rule. WETTERAU, L. W. Vet. Admin. Hosp. Los Angeles, CA. 45FR67018 08B. 80/11/06. 1p. 07196:209.
- B0120B0349 Comments on proposed rule iOCFR2O re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Facility does not possess nor use liquid scintillation media, tritium or C-14. MONROE.M. Bt. Hargaret's Hosp. Epring Valley, IL. 45FR67018 085, 80/11/10. ip. 07196:063.
- 8012080352 Comments on proposed rule iOCFR20 re disposal of liquid scinbillation media & animal carcasses containing tritium & C~14. Rule would reduce strain on disposal sites & medical research facilities w/o affecting public sefety.
 DMDRKIN, H. J., HORNITZ, N. William Beaumont Hosp. Royal Oak, MI. 45FR67018 086. 80/11/10. ip. 07176; 208.
- 8012080385 Comments on proposed rule 10CFR20 re disposal of radwaste. Change would be economically advantageous, reduce likelihood of toxic contamination by nonradioactive matis & present smaller health heart. BCHMIDT, F. H., WEITMANP, W. G. Washington, Univ. of. 45FR67018 109A. 80/11/07. 1p. 07196:207.
- 8012080336 Comments on proposed rule iOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule would alleviate onerous restrictions applied to matts & reduce disposal costs. Supports rule. BLAHD, W. H. Vet. Admin. Hosp. Los Angeles, CA. 45FR67018 087. BO/11/06. 1p. 07196: 206.

- 8012080361 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Reduction of vol added to radioactive disposal sites would allow longer usage for facilities. Supports rule. ODEBEL-L. Washington, Univ. of. 49FR67018 121. 80/11/10. lp. 07196:205.
- 8012080465 Comments by IN State Board of Health on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcavses containing tritium & C-14. Supports rule. KATTERUDHN.J.C. Indiana, State of, 45FR67018 042. 80/11/03. 1p. 07194:361.
- 8012080476 Comments by State Board of Health on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 BLANKENBAKER.R. Indiana, State of. 45FR67018 114. B0/11/07. 19.07194-1360
- 8012080488 Comments by Dept of Environ Resources on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing trituim & C-14 Rule should be astablished for various other isotopes, Supports rule. OERUSKY.T.M. Pennsylvania, State of. 45FR67018 116. 80/11/12. In 07194: 344.
- 8012080531 Forwards comments on proposed rule 10CFR30 re CP licensing requirements & mfg license applications. Proposed rule imposes requirements which are excessively & needlessly burdensome & are inconsistent & confusing.

 LDMENSTEIG.R. Lowenstein.Newman.Reis.Arelrad & Toll. 45FR65247 00 80/11/18. 12pp. 07194:330.
- 8012080654 Forwards comments by constituent on proposed rule 10CFR2 repensed policy statement & procedure for enforcement actions. Opposes penalising licensees for identification & correction of errors.

 HUDHES M. J. House of Rep., Judiciary Committee. 45FR66754 011.

 B0/11/14. 3pp. 07176:108.
- 8012080662 Comments on proposed rule 10CFR2 re general policy statems & procedure for enforcement actions. Regulations now in force are wholly adequate.
 CREMB.J.R. LADYMAN, G.H., HERBST.M. Doctors Hosp. Poplar Bluff, HO;
 45FR66754 017. 80/11/19. 2pp. 07196:112.
- 8012080&67 Comment by Plum Creek Lumber Co on proposed rule 10CFR2 regeneral policy statement & procedure for enforcement actions, Program generates revenue from stiff fines which finance fiRC growth.

 MCCORMICK.D. Affiliation Unknown. 45FR66754 009. 80/11/10. 2pp. 07196:114.
- 8012080667 Comments by IN State Board of Health on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcases containing tritium & C-14. Supports rule. YOHO.R.O. Indiana. State of: 45FR67018 131. 80/11/07. 1p. 07196: 116.
- 8012080671 Comments on proposed rule 10CFR2 re general policy statems by procedure for enforcement actions. Proposal should be withdrawn until assessment of new regulations.

 JANSEEN, T. K. Washington County Hosp. Nashville, IL. 49FR66784 019. 80/11/20. ip. 07196: 117.
- 8012080676 Comments on proposed rule 10CFR2 regeneral policy statem & procedure for enforcement actions, Buggests revoking operator license instead of levying fine.
 TERRELL.B.E. Affiliation Unknown. 45FR66754 012. 80/11/11. 2pp
- 8012080682 Comments on proposed rule 10CFR2 re general policy statem & procedure for enforcement actions. Scheduled meetings should be postponed for at least 6 months & should include provisions for Regulatory Flexibility Act of 1980. BORKON.E.L. Hemorial Hosp. of Carbondale Carbondale, IL. 45FR667 010. 80/11/14. 2pp. 07196:118
- 8012080688 Comments on proposed rule 10CFR50 re CP licensing requirements & mfg license applications CP licensing requirements should follow current guidelines for OL applicants. De facto moratorium on CPs should be listed.
 SHERRIDDD, 0. 0. Oeneral Electric Co. 45FR65247 009. 80/11/17. 20 02196:121.
- BOI2080693 Comments on proposed rule 10CFR2 re general policy states & procedure for enforcement actions. Considers policy ambiguous. Severe penalties should be reserved for wilful violations only. STOCKLAND. L. Family Hosp. Milwaukee.WI. 45FR66794 016. BO/11/2 2pp. 07196:127.

- 8012080499 Comments on proposed rule 10CFR2 re general policy statement & procedure for enforcement actions. Opposes proposed rule.
 AMBLER.C.D. Affiliation Unknown. 45FR36754 015. 80/11/18. 1p.
- 8012080702 Comments on proposed rule 10CFR2 re general policy statement & procedure for enforcement actions. Opposes proposed rule. PICKUS-M. Orant Hosp. of Chicago Chicago.ii. 45FR66754 014. 80/11/18. 2pp. 07196:133.
- 8012080707 Comments on proposed rule 10CFR2 re general pulicy statement & procedure for enforcement actions. Concerned w/escalation of civil penalties which appears to be liberally regulated against medical use licensees. Requests public meeting delay. SAMMELSON, D.R., RETTERMATER, ZIMMÉRMAN, O.R. Affiliation Unknown, 45FR66754 013. 69/11/18 2pp. 07176:137.
- B0120B0744 Advises of corrections for recipients of comments re 10CFR50 (45FR65466) & 10CFR2 (45FR66754). Comment Number 27 in 10CFR50 was misnumbered & now is Number 8 in 10CFR2. Number 27 will not be used again in 19CFR50.

 **Docketing & Services Branch. 45FR65466. B0/11/14. lp. 06586:003.
- 8012090758 Comments on proposed rule 10CFR20 re disposal of radwaste. Opposes rule & urges NRC not to lower stds on disposal of nuclear radwastes. LANE.M. Affiliation Unknown. 49FR67018 095. 80/11/02. 1p. 07196: 295.
- 8012080762 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations."
 Rule should permit approval of previously agreed upon solutions for operating plants.
 CAHN,A.L. Bochtel Corp. 45FR65466 006. 80/10/31. 4pp. 07196:291.
- 8012080766 Comments on proposed rule 10CFR50. "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." NRC attention should be prompt completion of long-term rulemaking. Rule should not be adopted. WETTERHAMN, M.J. Conner, Moore & Corber. 45FR65466 OD4. 80/11/03. 2pp. 07196:289.
- B012080769 Comments on proposed rule 10CFR50, "Interim Requirements Re Hydrogen Control & Certain Degraded Core Considerations." Rule will provide sufficient assurance that health & safety of public will be protected re degraded core accidents. KEARNEY, J. J. Edison Electric Institute. 43FR65466 001. 80/11/03. 2pp. 07196:287.
- 8012080776 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from ERP. Plan is too broad & would place complex burden on NRC licensees & applicants.

 CAHNIA. L. Bechtel Power Corp. (subs. of Bechtel Corp.). 45FR67079 004. BO/11/21. Epp. 07196:266.
- 8012080781 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from SRP. Revised SRP should be issued for public comment in Apr 1981 as only viable basis for proposal. GRADIN.L.P. Affillation Unknown. 45FR67099 001. 80/11/12. 2pp. 07196:226.
- B012080789 Comments on proposed rule 10CFRSD re plan to require licensees & applicants to document deviations from SRP. Plan exceeds Congressional mandate & requires resources in excess of any expected benefit.

 FERGUSCRI, J. H. Virginla Electric & Power Co. 45FR67099 005. B0/11/24. 2pp. 07196:224.
- 8012080/95 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from SRP. Proposed plan is poorly timed & counterproductive. PLYNIU. D. Cincinnati Gas & Electric Co. 43FR67097 003, 80/11/18, 2pp. 07196:222.
- 8012080/99 Comments on proposed rule to iOCFR30 re plan to require licensees & applicants to document deviations from SRP. Plan is neither cost-effective or safety-affective. REED.C. Commonwealth Edison Co. 45FR47099 003. 80/11/20. 3pp. 07194:219.
- 8012080801 Comments by Veterans Administration, Hadsworth Medical Ctr on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14, No danger to environ from proposed routes of disposal Supports rule.
 80L0MON, T. E. Affiliation Unknown. 45FR47018 052. 80/11/03. ip.

- 8012080833 Comments on proposed rule 10CFR50 re CP licensing requirements & mfg license applications. Site evaluation, dagraded core rulemaking & SRP conformance requirements should be delated & Option i utilized. HOWARD, J. E. Boston Edison Co. 45FR68247 008. 80/11/17. 5pp. 07196:211.
- BO12090002 Comments on proposed rule lOCFR2 re general policy statement to procedure for enforcement actions. Proposel violates 1980 Regulatory Flexibility Act.
 SELIGINAL, B. J. Dunn Hamorial Hosp. Bedford, IN. 45FR66754 018, BO/11/17. 2pp. 07199:344.
- 8012090008 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from etd review plan.
 FURBUSH.H. H. Pacific Oas & Electric Co. 45FR67099-007. 80/11/24.
 4pp. 07199:334.
- B012090017 Comments on proposed rules lOCFR30, 32, 70 & 150 re licensing requirement exemption for contaminated smelted alloys.

 Opposes exemption.

 HRIGHT, N. Affiliation Unknown. 45FR70874 0003. B0/11/20. ip.
- 8012090024 Comments on proposed rules 10FR30,32,70 & 150 re licensing requirement exemption for contaminated smelted alloys.

 Opposes exemption.

 FISHER,B. Affiliation Unknown. 45FR70B74 0001. 80/11/14. lp.
- B012090030 Comments on proposed rules 10FR30, 32,70 & 150 re licensing requirement exemption for contaminated smolted alloys. Opposes exemption. Requests to be kept informed about regulation.

 ATAMIAN.L. Affiliation Unknown. 45FR70B74 0002. B0/11/15. 1p.
- B012090037 Comments on proposed rule 10CFR50 re CP licensing requirements & mfg license applications. NRC should issue rule in conformity w/Option 1 terms.
 CDNRAD.V. L. Public Service Co. of Oklahoma. 45FR65247 007 B0/11/17. 15pp. 07197:301.
- 8012090042 Comments on proposed rule 10CFR90 re CP licensing requirments & mfg license applications. Supports efforts to lift gost-TKI moratorium from CP applicants. HAGA, P. B. Offshore Power Systems (subs. of Westinghouse Electric Corp.). 49FR65247 006. 80/11/17. 4pp. 07199:297
- GO12090035 Comments on proposed rule 10CFR50 re CP licensing requirements & mfg license applications.NRC should respond to Congress by outlining comprehensive safety review conducted during DL & SEP reviews.

 SHERNOOD, O. G. General Electric Co. 45FR65247 010. B0/11/18. 2pp. 07199:290.
- 8012090036 Forwards comments on proposed rule 10CFR50 re plan to require licensess & applicants to document deviations from SRP. Plan is unacceptable as RRC gives implicit status of rule of regulation to SRP.

 LEPPKE, D.M., SEELEY, O.T. Fluor Power Service, Inc. 45FR67099 016. 80/11/21. Opp. 07199:287.
- 8012090058 Forwards comments on proposed rule 10CFR90 re plan to require licensees & applicants to document deviations from SRP. Plan goes beyond Congressional intent of NRC FY80 authorization bill.
 UTLEY.E.E. Carolina Power & Light Co. 45FR67099 025. B0/11/24. 4pp. 07199: 283.
- 8012070066 Comments on proposed rule 10CFR50 re plan to require licensess & applicants to document deviations from SRP. Plan should be postponed so that provisions re small user may be reuritten. CERNY.R. J. Hemorial Hosp. of Mason County Ludington,MI. 45FR67079 026. 80/11/20. 2pp. 07179:281.
- BO12090071 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from SRP. Substantial concern about need for plan. Plan should be narroully focused.

 ABEL.J.B. Commonwealth Edison Co. 45FR67099 023. B0/11/25, 2pp. 07199:279.
- 8012090075 Comments on proposed rule 10CFR50 re plan to require licenseos & applicants to document deviations from BRP. Program exceeds Congressional intent of FYBO authorization bill. Program should be withdrawn. MCDDMALD, R.P. Alabama Power Co. 45FR67099 022. 80/11/26. 5pp. 07207:233.

- 8012090078 Comments on proposed rule 10CFR30 re pian to require licensees & applicants to document deviations from SRP. Plan constitutes inappropriate use of limited manpower resources in NRC & industry. MITHERS B. D. Portland General Electric Co. 45FR67099 021. 80/11/24. 2pp. 07207:231.
- B0120700B5 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from BRP. Plan is unnecessary & could cause severe disruption of regulatory process.

 BCHERER: A. E. C-E Power Systems. 45FR67079 020. B0/11/24. 3pp. 07207: 228.
- 8012070089 Comments on proposed rule 10CFR50 re plan to require licensess & applicants to document deviations from SRP. Plan extends considerably beyond Congressional intent of Section 110 of FY80 authorization biil.

 SALDARINI, J. C. Envirosphere Co., 45FR67079 019. 80/11/24. 4pp. 07207:224.
- BO12090092 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from 5RP. Plan should remain guidance document for NRC use. JDNES, M. C. Omaha Public Power District. 45FR67099 015. 80/11/24. 2pp. 07207:222.
- BO12090074 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from SRP. Proposal should be withdrawn until assessment can be made as to necessity of rule.

 WEBER, J. A. Nashington County Hosp. Nashvills, IL. 45FR67099 014. BO/11/25. 1p. 07207:221.
- 8012090100 Comments on proposed rule 10CFR50 re plan to require licensess & applicants to document deviations from SRP. Proposed plan is unwarranted & would serve to sidetrack NRC & industry capabilities in questionable exercise. WEARREY, J. J. Edison Electric Institute. 45FR67099 011. 80/11/24. 2pp. 07207:219.
- B012090102 Comments on proposed rule 10CFR50 re plan to require likensees & applicants to document deviations from SRR. Program will result in actions which are cumbersome & overreactive. BRADBURY.R.D. Stone & Webster Engineering Corp. 45FR67099 008. B0/11/24. 3pp. 07207:216.
- 8012090105 Comments on proposed rule iOCFR30 ra plan to require licenses & applicants to document deviations from BRP. Revised BRP should not be baseline document. LEGOEUF.R.J. LAMBI.H.R., LEIBY.A.C. LeBOeuf. Lamb, Leiby & MacRas. 45FR67099 004. 80/11/24. 5pp. 07207:211.
- B01209010B Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from SRP. Proposal would not be productive. BOUCHEY, 6.D. Nashington Public Power Bupply Bystem. 45FR67099 009. B0/11/20. 5pp. 07207:206.
- BO12090111 Comments on proposed rule 10GFR50 re plan to require licenses & applicants to document deviations from SRP. Proposal is unnecessary & burdensome to nuclear power plant industry w/o substantive contribution to plant safety. ANDERGON.T.M. Westinghouse Electric Corp. 45FR67099 013. B0/11/24. 2pp. 07207; 204.
- 8012090117 Comments on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from SRP. Proposals are inequitable & burdensone. UHRIG.R.E. Florida Power & Light Co. 45FR67099 012, 80/11/24, 4pp. 07207:200.
- 8012090120 Comments on proposed rule ICCFR50 re plan to require licensess & applicants to document deviations from SRP. Documentation & justification of deviations from SRP will drain industry manpower. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 45FR67099 017. 80/11/24. 2pp. 07207:198.
- BO12090126 Forwards comments on behalf of Shoreham Opponents Committee on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from BRP. Plan should require documentation of deviations for plants in OL stage. LATHAM, B B. Tuomey, Latham & Schmitt. 45FR67099 018, 80/11/24. 3pp. 07207;195.
- BOI2090132 Forwards, on behalf of Public Svc Co of DK, comments on proposed rule 10CFR50 re plan to require licensess & applicants to document deviations from SRP. Plan should be changed to include post-licensing considerations. OALLO, J. Isham, Lincoln & Beale. 45FR67099 026. 80/11/24. 4pp. 07207:191.

Antaly to the

- 8012090406 Responds to 801010 ltr re possible alternate technologies for interim storage of spent fuel. Dry storage would be subj to NRC licensing. Forwards NUREO-0575, Vols 1-3, NUREO/CR-1223 & final rule 10CFR72. WO NUREOS.

 AHEARNE, J. F. Commissioners. 80/11/18. 7pp. 07200:010.
- --8012090422 Final rule 10CFR72, "Licensing Requirements for Storage of Spent Fuel in Independent Spent Fuel Storage Installation." Rule covers specific licensing requirements for independent spent fuel storage. CHILK.S.J. Office of the Secretary of the Commission. 80/11/03.84pp. 07200:017.
- 8012100006 Comments on proposed rules 10CFR30.32.70 & 150 re licensing requirement exemption for contaminated smelted alloys.Rule does not address problem of contact U/radioactive products from mining to reprocessing to recycling.

 LAMUERT.B. Potomac Alliance. 45FR70874 0004. 80/11/18. 1p.
- 8012100010 Conments on proposed rule 10CFR50 re licensing requirements for pending CP & mfg license applications. Hajor effect of rule will be to increase paperwork burden on both applicant & NRC.
 SCHERER. A. E. Combustion Engineering, Inc. 45FR65474 005. B0/11/14. 3pp. 07217:034.
- 8012100014 Comments on proposed rules 10CFR50.51 & 100 re remote siting criteria for nuclear power plants.Requirement & substance of proposed mod of policy & regulation re siting criteria appear to be arbitrarily established. BRANDURY,R. B. Stone & Webster Engineering Corp. 45FR50350 068. 80/11/17. 7pp. 07217:027.
- 8012100020 Comments on proposed rules 10CFR30,32,70 % 190 re licensing requirement exemption for contaminated smelted alloys. Opposed to exemption Radioactive contamination should not be released to industry.

 MOROAN, K. Z. Affiliation Unknown, 45FR70B74 0006. 80/11/17. 2pp.
- B012100024 Comments on proposed rules 10CFR50,51 & 100 re remote siting criteria for nuclear power plants. Expresses concern refuture growth & development of remote area. Bite cannot be mandated to remain remote.

 ARNDT.E.O. Btructures & Components Standards Branch. 45FR50350 067. B0/11/18. 1p. 07217:022.
- B012100042 Comments by NY Hosp-Cornell Medical Ctr on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule will greatly decrease cost of burial procedures. Supports rule. BECKER, D. V. Affiliation Unknown. 45FR67018 174. B0/11/17. lp. 07217:021.
- 8012100945 Forwards comment on proposed rule 10GFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges swift snactment of proposal.
 ALIGNRAVITCH, 0. ICI Americas, Inc. 45FR67018 141. 80/11/14. ip. 07217:019.
- --8012100083 Comments on proposed rule 10CFR20 ra disposal of liquid scintillation media & animal carcasses containing tritium & C-14.Levels under consideration reasonable & safe.
 ZULESKI-F. BALAMA.A.I. 101 Americas. Inc. 80/11/04. 1p. 07217:020.
- B012100054 Motion for denial of NY Atty General B01103 motion to strike portion of Bcientists & Engineers for Secure Energy B01006 suggestions & NRDC & New England Coalition on Nuclear Pollution B01107 motion to strike all of same. MCORANERY, J.P. Scientists & Engineers for Secure Energy. MCORANERY, J.P. LeBoeuf, Lamb, Leiby & MacRae. B0/11/18. 9pp. 07219:008
- ---8012100060 Notice of address change for MM Todorovich, Executive Secretary for Scientists & Engineers for Secure Energy. MCORANERY, J. P. Scientists & Engineers for Secure Energy. MCORANERY, J. P. LeBoeuf, Lamb, Leiby & MacRae. 80/11/18. ip. 0721018082
- E012100082 Forwards comments on behalf of Boston Edison Co.C-E. FL Power & Light Co & Houston Lighting & Power Co on proposed rule 10CFR50 re plan to require licensees & applicants to document deviations from ERP. NEHMAN.J.R. Lowenstein.Newman.Reis.Axelrad & Toll. 45FR67099 010. 80/11/24. 4pp. 07217:093.
- BO12100088 Forwards comments on behalf of TX Utils Generating Co on proposed rule 100FR80 re plan to require licenses & applicants to document deviations from SRP. Plan cannot be justified as efficient method of achieving improvements. REYNOLDS.N.S. HORIN.W.A. Debevoise & Liberman, 45FR67099 027. 80/11/24. 6pp. 07217:097.

- 8012100075 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule should be modified to include de minimus level for solid radioactive mails.

 GREELEY, O. M. Affiliation Unknown. 45FR67018 176. 80/11/17. 1p. 07217:015.
- B0i2100097 Comments on proposed rule 10CFR20 re disposel of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to continue to study other ways of reducing low level waste requiring special disposal. WGETHER: M. 8t. Louis Univ. Medical School. 45FR67018 169. GO/11/10. 1p. 07217:014.
- 8012100300 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to continue to study other ways of reducing low level waste requiring special disposal. ELLIOTT.IK.H. St. Louis Univ. Medical School. 45FR67018 167. 80/11/10. 1p. 07217:013.
- 8012100103 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carrasses containing tritium & C-14. Supports rule & urges NRC to continue to study other ways of reducing low level waste requiring special disposal. HILL.W. B. St. Louis Univ. Medical School. 45FR67018 166. 80/11/10. 1p. 07217:012.
- B012100115 Commants on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to continue to study other ways of reducing low level wasts requiring special disposal. MUNDAY.S. R. St. Louis Univ. Medical School. 45FR67018 165. B0/11/10. 1p. 07217:011.
- BO12100127 Comments on proposed rule 10CFR20 re dieposal of liquid scintillation media & animal carcases containing tritium & C-i4. Supports rule & urges NRC to continue to study other ways of reducing low level waste requiring special disposal. ELIGETRIPOL. Bt. Louis Univ. Medical School. 45FR67018 164. 80/11/10. ip. 07217:010.
- B012100130 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to continue to study other ways of reducing low level waste requiring special disposal. BRACKMANN, K. St. Louis Univ. Hedical School. 45FR67018 163, 80/11/10. 1p. 07217:007.
- 8012100132 Comments on proposed rule 10CFR50 re hydrogen mgt.Rulemaking proposals should be withdraun until policies on hydrogen control degraded core cooling plant accident instrumentation & other items are established.

 LEACH.L.P. Affiliation Unknown. 45FR65466 002. 80/10/30. 3pp.
- 8012100137 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rules support procedures which will reduce overall risks as they are encountered Supports rule. FRIEEEAN S. S. Kansas, Univ. of. 45FR67018 160. 80/11/14. ip. 07217:005.
- BO12100142 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Disposal in sewage is simple solution & should be safe, w/asequate treatment.
 PICKUB.M. Orant Mosp. of Chicago Chicago, IL. 45FR6701B 175.
 BO/11/1B. 1p. 07217:004.
- SO12100145 Comments on proposed rule 10CFR20 re disposel of liquid scintillation media & animal carcasses containing tritium & G-14. Chemical & pathogenic hazards of shipment & burial exceed radiation hazards of low isotope levels.

 EXOEL,R. H. Affiliation Unknown. 45FR67018 173. 80/11/18. 1p. 07217:003.
- S012100152 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule. \(\). Widnessta Mining & Mfg. Co. 45FR67018 172. 80/11/18. Ip. 07217:002.
- 8012100156 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to encourage Agreement States to follow lead in matter.

 COOKE.W.D. Cornell Univ. 45FR67018 171. 80/11/13. 1p. 07217:001.

- S012100159 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Situation could arise where neither radwaste disposal sites nor chemical disposal sites will accept scintillation. MILEONAB. M. Louisville, Univ. of. 45FR67018 170. 80/11/19. ip 07217:103.
- 601210016B Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcassas containing tritium & C-14. Supports rule & urges NRC to continue to study other ways of reducing low level waste requiring special disposal, MELLEIN.M. 8t. Louis Univ. Medical Echool. 45FR67018 169. 89/11/10. ip. 07217:092.
- 8012100173 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcases containing tritium & C-14. Bupports rule & urges NRC to liberalize similar restrictions for other radionuclides.

 CASTELLION.A.W. Morton Norwich Products, Inc., Morton Salt Div. 45FR67018 157. 80/11/17. 2pp. 07217:090.
- B0i2i00178 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Increasing acceptable radioactive dose to environ will eliminate necessity of processing waste from isotope users. OLOVER: H. Bigelow Laboratory for Ocean Sciences. 45FR67018 156. B0/11/14. 2pp. 07217:088.
- 8012300184 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to continue study on disposal of other low level wastes.

 PATEL. B. Vet. Admin. Hosp. St. Louis, MQ. 45FR67018 155, 80/11/10.
- BO12:00:085 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to continue study on disposal of other low level wastes.

 RIAZ, A. Vet. Admin. Hosp. St. Louis, MO. 45FR670:18 154. B0/11/10. ip. 07217:087.
- BO12100191 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule will facilitate safe disposal of waste. Supports rule.
 BORER, K. T. Michigan, Univ. of. 45FR67018 153. 80/11/17, 1p. 07217:086.
- 8012100195 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Investigation should be performed to assure complete combustion of fluors. Supports rule.
 PAGUETTE, T. Hashington, Univ. of. 45FR67018 140. 60/11/04. ip. 07217:085.
- 8012100203 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports change for disposal of liquid scintillation. Opposes increased release into sanitary sewer sys. MACKCNZIE.R. D. Richardson-Merrell. Inc. Merrell-National Laboratories Div. 45FR67018 146. 80/11/16. 1p. 07217:084.
- B012100206 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcassas containing tritium & C-14.Rule would eliminate costs of waste disposal. Supports rule.

 ODRDON.R.F. Notre Dame, Univ. of. 45FR67018 147. 80/11/17. 1p. 07217:053.
- 8012100211 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Recognizes necessity of differentiating certain wastes resulting from medical & nuclear power applications. THALER.M E.; LONERGAN.G. T. lowe, Univ. of, 45FR67018 152, 80/11/14, ip. 07217:052.
- 80i21002i8 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Appears that NRC is making decision on economical basis rather than environ basis. Opposes rule, CHARLEBOIS, D. L. Affiliation Unknown. 45FR670i8 i5i, 80/11/17. ip. 07197:00i.
- 8012100223 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 BASSINOTHRAIDHT Washington. Univ. of. 45FR67018 150. 80/11/14. ip. 07217:051.

- B012100296 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule would reduce vol of radwaste to be shipped to burial ground. Supports rule.
 BMILEY.D.C. Virginia Tech. 45FR67018 149. BD/11/18. 1p. 07217:030.
- 8012100233 Comments on proposed rule IOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 BURT, D. R. Mayuland, Univ. of, Baltimors. 45FR67018 148. 80/11/18.
 ip. 07217:049.
- 8012100240 Comments on proposed rule 100FR20 re disposed of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.

 ORIFFIN.E.E. Texas, Univ. of, Dallas. 45FR67018 143. 80/11/13. ip. 07217:047.
- 8012100243 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. In absence of universal acceptance, such wastes may not be accepted by radwaste disposal contractors. Supports rule. MARBHALL.C.H. New York Univ. Medical Center New York NY. 45FR67016 145. 80/11/11. ip. 07217:046.
- 8012100251 Comments by Veterans Administration Medical Ctr.Chicago. IL on proposed rule 10CFR20 re disposal of liquid scintiliation media & animal carcasses containing tritium & C-14. Supports rule.
 HILLIAMS, O.A. Affiliation Unknown. 45FR67018 159, 80/11/06. 2pp. 07217:044.
- BOIZIO0257 Comments by Goleta Sanitary District on proposed rule iOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Opposes rule. HIGNOT.R.E., DAVIS.S.J., URIBE.J.B. California, State of. 45FR67018 15B. 80/11/12. 2pp. 07217:042.
- 8012100263 Comments by Rockefeller Univ on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule will relieve undue physical & financial burden. Supports rule. LEDERBERRO, J. Affiliation Unknown. 45FR6701B 161, 80/11/14. 1p. 07217:040.
- BO12100270 Comments by Santa Clara Valley Medical Ctr on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Bupports rule & urges NRC to continue to look for ways to dispose of wastes. MCLAUSHLIN.W.T. Affiliation Unknown. 43FR67018 162. B0/11/14. Ip. 07217:040.
- 8012100278 Comments by American Council on Ed on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Hods re clarification of animal carcasses & disposable items should be included.

 BTEINBACH. 8, E. Affiliation Unknown. 40FR67018 142. 80/11/17. 2pp. 07217:038.
- 8012100640 Transcript of Commission 801126 public meeting in Washington,DC re 8ECY-80-474/474A & 10CFR60 concerning licensing procedures for disposal of high level waste in geologic repositories.

 * Commissioners. 80/11/26. 86pp. 07217:104.
- BO12110021 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions. Opposes heavy fines. BCHUMACHER, J. L. Calumet Memorial Hosp. Chilton, WI. 45FR66754 026. BO711728, 1p. 07226:054.
- B012110027 Comments by Dept of Health on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. ANDERSON.L.F. Utah, State of, 45FR67018 196, 60/11/20, 1p. 07226:053.
- 8012110044 Comments by Dept of Natural Resources on proposed rule 10CFR20 Te disposal of liquid scintillation media & animal carcasses containing tritium & C-1A. Any storage or burial of radwasts at 9A must comply existate rules & regulations. MODAN.B.A. Osorgia, State of, 45FR67018 183. 80/11/18, lp. 07226:002.

- 8012110051 Comments by North Shore Univ Hosp on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.

 SJILAOYI.A. Affiliation Unknown. 45FR67018 238. 80/11/20. ip. 07226:051.
- 8012110062 Comments by Pharm Mfgs Association on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule would alleviate regulatory & financial burdens re disposal. Supports rule. ADAMS, J. O. Affiliation Unknown. 45FR67018 243, 80/11/24. 2pp. 07226:049.
- B012110067 Comments by City of NY Dept of Health on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Approves overall objective & intent of rule w/listed qualifications. FERRER, R. A. New York, NY. 45FR67018 246. 80/11/17. 3pp. 07226:046.
- B012110075 Comments by Univ of MD Hosp on proposed rule 10CFR20 redisposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule will save public costs. Radioactive disposal vol outweighs radioactive releases. HOUK, J. L. Affiliation Unknown. 45FR67018 247. B0/11/19. ip. 07226: 045.
- 8012110081 Comments by Natl Cancer Inst, Baltimore Research Program, on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses continuing tritium & C-14. Conturs W/RRC rule changes.

 BACHUR, N. R. Health & Human Bervices, Dept. of. 45FR67018 252.

 B0/11/21. 1p. 07226:044.
- 8012110094 Comments by Dept of Human Resources on proposed rule 10CFR2 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Favors changes, however raises questions re chamical problems.

 GBBORNE, R. P. Kentucky, State of, 45FR67018 260, 80/11/26, 2pp.
- 8012110105 Comments by Sterling Drug Inc on proposed rule 10CFR20 redisposal of liquid ecintillation media & animal carcasses containing tritium & C-14. Recommends rule be finalized & restrictions liberalized for other radionuclides.

 ANYALONE, A.E. Affiliation Unknown. 45FR67018 253, 80/11/21. 1p. 07295-041
- 8012110f16 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Opposes rule.
 ILLHARDT. J. Affiliation Unknown. 45FR67018 250. 80/11/20. 1p. 07187:001.
- 8012110133 Advises recipients of corrections to comments on proposed rule 10CFR20 45FR67018. Comment Number 181 miscategorized. Comment should be Number 25 under 10CFR2(45FR6734). Number 181 will not be used again under 10CFR20(45FR67018).

 8 Docketing & Bervices Branch. 45FR67018. 80/12/02. 1p. 07187:001.
- B012110139 Comments on proposed rule iOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Proposal should be rejected due to hazards presented to public health.

 DDUCHTY. J. Affiliation Unknown. 45FR67018 245. 80/11/10. 3pp. 07187:001.
- 8012110140 Responds to FOIA request for six categories of info re fire protection requirements in App R to 10CFR50. Forwards draft rept. "Fire Protection for Colocated Elements of Redundant Divs." which will be placed in PDR. FELTON.J. N. Division of Rules and Records. 80/12/03. 1p. 07223:346.
- --B012110157 Forwards preliminary draft rept, "Fire Protection for Colocated Elements of Redundant Divs."

 CAMPBELL, J. A. Gage-Babcock Associates, Inc. 7917-3, 79/00/07.
 16.
- ---B012110164 Preliminary draft ropt, "Fire Protection for Colocated Elements of Redundant Divs.

 * Gage-Babcock Associates, Inc. 79/08/07. 29pp.
- 8012110146 FOIA request for six categories of info re fire protection requirements in App R to 10CFR50.

 WATKING, M. Debevoise & Liberman. 80/11/18. 2pp. 07223:347.

- 8012J10147 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. More appropriate disposal method would be above-ground storage in metal drums or bins after waste is mixed w/lime. VAUDHANAR.C. Affiliation Unknown. 45FR67018 244. 80/11/22. 2pp. 07187:001.
- BOI2110149 Comments by Medical Univ of SC on proposed rule tOCFR20 re disposal of liquid scintillation media & animal carcasses cantaining tritium & C-14, Supports proposals. MISE J. D. Affiliation Unknown. 45FR67018 213. BO/11/21. 3pp. 07226:038.
- B012110150 Responds to B00730 suggestion that Commission reconsider or clarify 800619 "Statement of Policy:Further Commission Guidance for Power Reactor DLs." Forwards B01103 denial of VCB & Shoreham Opponents Coalition request for stay.
 AMEARNE, J. F. Commissioners. 80/11/19. ip. 07223:349.
- --B012110161 Order denying UCS & Shoreham Deponents Coalition request for stay of Commission "Statement of Policy: Further Commission Guidance for Power OLs." Separate Commissioner views enci. CHILK.S. J. Office of the Secretary of the Commission. 80/11/03. 15pp. 07223:350.
- 80i2110154 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule should include 0.05 uCi/g Bactec blood culturemedia containing C-14. Supports rule, GRBSS.M. Vet. Admin. Medical Center Ann Arbor.HI, 45FR67018 242. 80/11/21. 1p. 07826:037
- 8012110160 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Safety of low level radiation has not been established. Opposes rule.

 MINTZ.S.L. Affiliation Unknown. 45FR67018 241. 80/11/20. ip. 07187:001.
- BOI2E10166 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule should include other radionuclides. C-14 blood media & Cr-51. Supports rule.
 ECKHAUSER.F. Vet. Admin. Medical Center Ann Arbor. HI. 49FR67018 240. BO/11/21. 1p. 07226:036.
- 8012110170 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Environ impact should not pose any undur concern.

 8Upports rule.
 CAZER.F.D. Ohio State Univ. 45FR67018 239. 80/11/21. ip. 07226:035.
- 8012110173 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Disposing of radwaste in sanitary sewer sys should not be permitted.

 HICKS.B. G. Affiliation Unknown. 45FR67018 251. 80/11/20. ip. 07226:034.
- 8012110176 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcassas containing tritium & C-14. Supports rule.

 HILLER, K. L. Hilton S. Hershey Medical Center Hershey, PA. 45FR67018 249. 80/11/21. 1p. 07226:033.
- 8012110180 Comments on proposed rulm 10CFR20 re disposed of liquid scintillation media & animal carcasses containing tritism & C-14. Urges speedy adoption of proposed rulm & expansion to include other isotopos.

 HOLEMAN, O. R. American Association of Physicists in Medicine, 45FR67018 248. 80/11/21, 1p. 07226:032.
- 8012110186 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.

 COOLEY.L.R. Maryland, Univ. of, Baltimore. 45FR67018 283. 80/11/21.

 1p. 07226:031.
- 2012110188 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. People would violate guidelines under more lenient controls. Opposes rule. ABRAHAMG, A. Affiliation Unknown. 45FR67018 282. 80/11/30. 1p. 07187:001.
- 8012110192 Comments by AZ Hosp Association on proposed rule 10CFR20 redisposed of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Basic problem is having no uniform definition of radwaste math. SAVACLIO,F. J. Affiliation Uninown. 45FR67018 224. 80/11/19. 2pp. 07226:029.

- 8012110195 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Endorses proposed rule. Urges that rule be made offsetive as soon as possible.
 HORGAN, J. T. National Naval Medical Center Bothesda, MD. 45FR67018 261. 80/11/25. 2pp. 07226:027.
- 8012110178 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule will help generats program that will result in significant savings for univ. Supports rule.

 BASS.M. B. Alabama, Univ. of. 45FR67018 259. B0/11/21, 2pp. 07226:025.
- 8012110201 Comments on proposed rule 10CFR20 re disposal of liquid acintiliation media & animal carcasses containing tritium & C-14. Changes will achieve better cost effectiveness for waste processing. Urges adoption of proposed changes.

 ZIEMER, P. L. Purdue Univ. 45FR67018 259. 80/11/21. Ip. 07826:024.
- 8012110204 Comments on p.cgoscá rule 10cFR20 re disposal of liquid scintillation media & animal carcastes containing tritium & C-14. Suggests expansion of program to pormit similar disposals of numerous other isotopes used. OERTH. 0. E. Mallinckrodt, Inc. 45FR67018 257. 80/11/21. ip. 07226:023.
- 8012110212 Comments by American Hosp Supply Corp on proposed rule iOCFR20 re disposal liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Favors expansion to cover dry.solid contaminated w/C-14 br H-9. DYBAS. J. A. Affiliation Unknown. 45FR67018 226. 80/11/19. 2pp. 07225:325.
- 6012110R14 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to continue study to reduce other low level waste requiring special disposal. NALEGNIK.W. J. 8t. Louis Univ. Hedical School. 45FR67018 256. SO/11/10. ip. 07225:324.
- B012110219 Comments on proposed rule iOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule should include de minimus level for solid radioactive metis based on isotopes radiotoxicity.

 CORELEY, T.F. St. Joseph's Hosp. Tucson, AZ. 45FR67018 255.

 B0/11/25. 1p. 07223:323.
- 8012110223 Comments by Syntex Research on proposed rule 10CFR20 redisposal of liquid scintillation media & animal carcasses containing tritium & C-14.Supports proposal.

 81MS-J.M. Affiliation Unknown, 45FR67018 222, 80/11/14, 2pp. 07225:321.
- B012110237 Comments on proposed rule 10CFR20 re disposal of liquid scintiliation media & animal carcasses containing tritium & C-14. Rule should be modified to include de minimus level for solld radioactive matls based on radiotoxicity.

 MORTON. 0. Affiliation Unknown. 45FR67018 285. 80/11/24. 2pp. 07225:319.
- B012110241 Comments by Association of American Medical Colleges on proposed rule 10CFR2O re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Suggests minor mads to solve total problem. COQPER.J. A., BARTLETT, T. A. Affiliation Unknown. 45FR67018 229. B0/11/19. 2pp. 07225:317.
- BOI2110248 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Proposal does not consider cumulative effect on public health. NRC shows no scientific bases for new cutoff level. YUAN. 0., OOLDBTEIN.D. Natural Resources Defense Council. 45FR67018 220. 80/11/21. 2pp. 07225:315.
- 80:2110262 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.
 LINTON.O.W. American College of Radiology. 45FR67018 225.
 80/11/21. 2pp. 07225:307.
- BOIR110270 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Suggests extension to cover other organic raduaste.

 COMPTON. A. T. Smith: Kline & French Laboratories. 45FR47018 227. 80/11/20, 2pp. 07225:308.

- 8012110273 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Favors extension to cover other isotopes.

 CORRIDAN. W. Foster G. McGraw Hosp. Chicago. IL. 45FR67018 228. 80/11/21. 2pp. 07225:303.
- 8012110284 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule. Urges NRC to continue to study ways of raducing low level waste requiring special disposal. WARNECKBE, M.A. St. Louis Univ. Medical Center St. Louis, MD. 45FR67018 179. 80/11/10. 1p. 07225:301.
- 8012110288 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14.0ther means of elimination, such as incineration, would cause no environ or public health consequence. Supports rule. LAMBREMONT.E.N. Louisiana State Univ. 45FR67018 177. 80/11/18. ip. 07223:300.
- 8012110993 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Proposal should also cover other raduaste.

 O'BRIEN, M. J. Washington, Univ. of. 45FR67018 214. 80/11/18. Gpp. 07225:290.
- 8012110296 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Urges consideration of fragile nature of groundwater sys & land-use/land-discharge relationship.

 MEYLAND: 8. New York, State of. 45FR67018 218. 80/11/21. 2pp. 07225:288.
- B012110310 Comments on proposed rule 10CFR20 re disposal of liquid exintilation media & animal carcasses containing tritium & C~14. Supports proposal.

 KATSINIS.E. Burroughs Wellcome Co. 45FR67018 217. 80/11/19. 2pp. 07225: 286.
- 8012110312 Comments on proposed rule 100FR20 re disposel of liquid scintillation media & animal carcasses containing tritium & C-14. Eupports proposal. Favors extension to cover other commonly used radiotracers.
 PATTON.D.D. Arizona, Univ. of. 45FR67018 219. 80/11/21, 2pp. 07293-284
- B012110317 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal, Expresses concern re companies without access to EPA-approved incinerator.
 LUTZ,H.J. KcNeil Laboratories. 45FR67018 223, 80/11/21. 2pp. 07225:282.
- 8012110319 Comments on proposed rule 10CFR20 re disposed of liquid scintillation media & animal carcasses containing tritium & C-14. Bupports proposal. Favors extension to cover other radionuclides.

 BROSEUSS R. W. HHB, Dept. of, US Public Health Service. 45FR6701B 221. B0/11/21. 3pp. 07225:277.
- B012110323 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. PETTIMOA.C.W. Eli Lilly & Co., Lilly Research Laboratories Div. 45FR67018 231. 80/11/20. 3pp. 07225:274.
- B012110326 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.
 DIBALVO,R. Johnston Labs. 45FR67018 216. B0/11/17. 2pp. 07225:272.
- 80:2110331 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Problems associated w/liquid scintillation counting are not eliminated. MURPHY. Q. L. Georgia: Univ. of., 45FR67018 230, 80/11/20, 2pp. 07225: 270.
- 80(2110334 Comments on proposed rule 10CFR20 re disposel of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal Favors extension to cover other isotopes:
 DURKOSH, E. D. Pittsburgh, Univ. of. 43FR67018 215. 80/11/17. 2pp. 0723:268.

- 8012110337 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Present burial policy for radwaste will continue. Requests further info re proposal. JACKSUM O.L. Harrisburg Hosp. Harrisburg, PA. 45FR47018 232. 80/11/19. 2pp. 07225:266.
- B012:10344 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcesses containing tritium & C-14. Bupports approval of all radioactive limits & looks forward to add1 revisions re other radioisotopes.
 FLINT.S. N. New England Nuclear Corp. 45FR6701B 234. B0/11/21. ig. 07225: 265.
- 8012110365 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule will reduce risks by eliminating environ impact of transporting waste matls & exposure. Supports rule.

 SHAPIRO, J. Harvard Univ. 45FR67018 235. 80/11/21. ip. 07225: 244.
- 8012110575 Comments on proposed rules 10CFR30:32.70 & 150 re use of low enriched U as contaminant in metals. Opposes rule.

 SPILKA: E. Affiliation Unknown. 45FR70874 0022. 80/11/24. 1p.
- 80:21:10583 Comments on proposed rules 10CFR30:32:70 & 150 re licensing requirement exemption for contaminated smalled alloys. Byproducts of enrichment process are all emiters of alphabeta & gamma rays. Opposes rule.

 DOSIK.S. Affiliation Unknown. 45FR70874 0021. 80/11/21. 1p.
- 8012110648 Comments on proposed rules 10CFR30, 32, 70 & 150 re returning radioactive scrap metal to market as uncontrolled metal. Opposes rule.

 DBBCRNE, J. Affiliation Unknown. 45FR70B74 0020. 80/11/28. 1p.
- BOI2110564 Comments on proposed rules 100FR30,32,70 & 150 re releasing contaminated matls for unrestricted use in consumer goods.

 Opposes rule.

 DASS,R. Affiliation Unknown. 45FR70874 0019. 80/11/25. 1p.
- 8012110670 Comments on proposed rules 10CFR30,32,70 & 150 which would be exempt from licensing & regulatory requirements persons who receive possess, use of transfer Tc-77 or low enriched U as residual contamination in smalted alloy, Opposes rule. HEDMAN, B. Affiliation Unknown. 45FR70874 0019. 80/11/24. ip.
- 8012110706 Comments on proposed rules 10CFR30:32:70 & 150 which would allow possession; use & transfer of low enriched U as contaminant in metals. Opposes rule.
 FOOELSONA. Affiliation Unknown. 45FR70874 0017. 80/11/26. 1p.
- 8012110724 Comments on proposed rules 10CFR30,32,70 & 150 re licensing requirement exemption for contaminated smelted alloys.

 Opposes rule, ERLICH, J. Affiliation Unknown. 45FR70874 0016. 80/11/28. lp.
- 8012110744 Comments on proposed rules 10CFR30.32.70 & 130 re exemption of licensing requirement for contaminated smelted alloys. Opposes rule.
 MINDLIN.M. Affiliation Unknown, 43FR70874 0015. 80/11/26. 1p.
- 8012110783 Comments on proposed rules 10CFR30, 32,70 & 150 re licensing requirement examption for contaminated smelted alloys.

 Contaminated scrap should be buried in one place. Hfg scrap should be marked w/red & yellow warning labels.

 JACOBSON,N. Affiliation Unknown, 43FR70874 0014.
- 8012110798 Comments on proposed rules 1GCFR30:32:70 & 150 processing contaminated metals for mfg of consumer &/or capital equipment products. Hazards from low level exposure have not been determined. Opposes rule.

 ORADY: J. Rhode Island Public Interest Research Group. 45FR70874 0013. 80/11/24. 2pp.
- B012110B15 Comments on proposed rules 10CFR30,32,70 & 150 re licensing requirement exemption for contaminated smalted alloy. Opposes rule. UDFPA,U. Affiliation Unknown. 45FR70B74 0012, 80/11/25, ig.
- B012110825 Comments on proposed rules 100FR30,32,70 & 150 exempting from licensing or regulatory requirements any person who receives uses or transfers low enriched U as residual contamination smelted alloy Opposes rule.

 KENNEDY.B.E. Affiliation Unknown. ASFR70B74 0011. 80/11/24. 1p.
- 8012110833 Comments on proposed rules 100FR30.32.70 & 150 exampting licensing & regulatory requirement for any person who receives possesses or uses 16W anniched U as residual contamination in smelted alloy, Opposes rule, LEPKONBKI.0. Affiliation Unknown. 45FR70874 0010. 80/11/24. 1p.

- 8012110844 Comments on proposed rules 10CFR30.32..70 & 150 exempting from licensing & regulation Tc-99.No safe level of radiation.Radiation has cumulative effect.Opposes rule.

 LEFKOWSKI.M. Affiliation Unknown. 45FR70874 0009. 80/11/24. ip.
- B012110852 Comments on proposed rules 100FR30,32,70 & 150 re exemption from licensing or regulatory requirements for persons receiving, possessing, using or transferring Tc-99 contaminated products. Protects rule, SCHUMACHER, J. Affiliation Unknown, 45FR70874 000B. B0/11/23, 1p.
- 8012120003 Comments on proposed rules 100FR30.32,70 & 150 re exemption of licensing for smelted alloys. Rule is irresponsible & reckless. Protests rule.
 FREED-THALL. P. Affiliation Unknown. 45FR70874 0007. 80/11/23. 1p.
- B012120005 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule is excellent step in better allocation of money & burial space. Supports rule.
 FLUKE.D. J. Duke Univ. 45FR6701B 235. 80/11/19. ip. 07227:345.
- 8012120007 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule would alleviate shortage of wasta burial capacity risks involved in transportation of wastas. Supports rule. TREINISH: N. J. Abbott Laboratories. 45FR67018 237. 80/11/18. 1p. 07227:344.
- 8012120713 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 SAHMONS J. H. American Medical Association. 43FR67018 184. 80/11/18. 8pp. 07187:001.
- 8012120918 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Preamble to final rule should state that federal, state & local requirements would be applicable.
 FIDELMAN.S. J. Merck Sharp & Dohme. 43FR67018 185. 80/11/19. 2pp.
- 8012120036 Forwards comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animat cercasses containing tritium & C-14.

 0'8RIEN.M.J. Washington, Univ. of. 45FR67018 284. 80/11/25. 3pp. 07230: 295.
- 8012120039 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule fails to address impact on incineration as waste disposal method & total scope of practices. Supports rule. RAMPY-L.M., Dow Chemical Co., Dow Chemical U.S.A. Div. 45FR47018 233. 80/11/21. 3pp. 07230:292.
- 8012120044 Commants on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.

 LUEDKE, D. Veterans Administration. ASFR67018 209. 80/11/10. 1p. 07230:291.
- 8012120771 Comments on proposed rule IOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Proposed concentration limits for tritium & C-14 should be increased to 0.1 or 0.2 uCl/g.

 DETORIE, N. A. Southern Illinois Univ., School of Medicine. 49FR47018 182. 80/11/13. ip. 07230:278.
- 8012120076 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Supports proposal.
 OARTLER.S.M. Washington, Univ. of. 45FR67018 203. 80/11/20, ip. 07230:267.
- 8012120085 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.
 FLUKE. D. J., KAMIN. H. Duke University Medical Center. 45FR67018 204. 80/11/20. ip. 07230:256.
- 8012120092 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Suggests rule be extended to include chemical & biological matis.
 MILLER.D. R. . LEASIA: L. T. Northwestern Univ. 45FR67018 205. 80/11/18. ip. 07230:250.
- 8012120076 Comments on proposed rule IOCFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.

 BRANTLEY.J.C. New England Nuclear Corp. 45FR67018 206. 80/11/21.

 1p. 07230:239.

- 8012120101 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Suggests proposal be extended to include addl isotopes.

 HOLEMAN.O.R. Yale Univ. 45FR67018 207. 80/11/21. 1p. 07230; 233.
- 8012120104 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. FEIR.D. St. Louis Univ. Medical School. 45FR67018 208. 80/11/10. ip. 07230:232.
- 8012120107 Comments on proposed rule 10CFR20 re disposel of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal Action should apply to other dry & liquid wastes. Stanford Univ. 45FR67018 199. 80/11/17. ip. FINSTON, R. A.
- SDI2120115 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Bupports proposal. Other commonly used radionuclides should be included. included.

 D. Warner-Lambert Research Institute. 45FR47018 201.

 1p. 07230:215. HARTHAN, J. D. 80/11/17.
- 8012120142 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Suports proposal. Regulation should be first step in dealing w/low level medical radioactive waste disposal. LAUGHLIN, J. 8. Hemorial Bloan-Kettering Cancer Center New York, NY, 45FR67018 202. 80/11/20. 1p. 07228:357.
- 8012:120147 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Other C-14 & tritium media should be included in rule.
 CODPER.R.F. Veterans Administration. 45FR67018 191. 80/11/21.07228:351. Veterans Administration. 45FR67018 191. 80/11/21. 1p.
- 8012120151 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.
 L16K.R.D. Princeton Univ. 45FR67018 192. 80/11/19. ip. 07228:345.
- EDI2120157 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Questions several points of proposal. Concerned about radioactive ash & distillation & recycling of liquid.

 SUTHERB.H.B. Princeton Univ. 45FR67018 193. 80/11/20. 1p. 07228:339.
- 8012120169 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal & suggests application of similar logic to other low specific activity waste.
 LOVANB.A. Colorado State Univ. 45FR67018 194. 80/11/20. 1p. 07228:323,
- B012120180 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Bupports proposal Suggests other media besides liquid scintillation be included at C-14 level.

 MEINHOLD, P. Veterans Administration. 45FR67018 195. 80/11/21, ip. 07228.317.
- 8012120185 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.

 DAIN. J. O. Sandoz. Inc. 45FR67018 197. 80/11/20. ip. 07228:311.
- B012120187 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.
 CHR ISTIAN. J. E. Purdue Univ. 45FR67018 198, 80/11/24, 1p.
- 8012120193 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.

 SIBLEY.C. H. Washington, Univ. of. 45FR67018 190. 80/11/20, ip.
- 8012120196 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. VOMACHKA.A.J. Princeton Univ. 45FR67018 189. 80/11/18. 1p. 07228: 299.

- 8012120199 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.
 JENKINS, C. L., North Carolina State Univ. 45FR67018 188. 80/11/18.
- 8012120204 Comments on proposed rule 10CFR20 re disposal of liquid scintiliation media & animal carcasses containing tritium & C-14. Supports proposal w/suggestion of including strongar admonitions for licensees to comply w/non-NRC statutes.
 BRINER,N.H. Duke University Medical Center, 45FR67018 187, 80/11/21. 2pp. 07228:276,
- 8012120261 Comments on proposed rule 10CFR20 re disposel of liquid scintillation media & animal carcasses containing tritium & C-14. Changes do not protect health & safety of public & should be reversed.

 LOCHSTET. M. A. Affiliation Unknown. 43FR67018 288. 80/11/24. 3pp. 07227:319.
- 8012120268 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14.0vidance should recognize problems & should not promote sewage disposal.

 MARD, J. O. California, State of: 45FR67018 287. 80/11/24. 2pp. 07231:337.
- B012120273 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.

 MEIR. J. . American College of Nuclear Physicians. 45FR67018 275. 80/11/28. 1p. 07231:306.
- B012120288 Comments on proposed rule 10CFR20 re disposat of liquid scintillation media & animal carcasses containing tritium & C-14. Bupports proposal.
 MACINTYRE, W. J. Cleveland Clinic Cleveland, OM. 45FR47018 274.
 B0/11/14. 1p. 07231:324.
- 80:2120275 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Favors broadening proposal. Definition of what constitutes radioactive mati needs clarification. NIMMO.E. Wisconsin, Univ. of Hadison. 45FR67018 277. BO/11/24. ip. 07231:323.
- 8012120297 Comments by Jawish Memorial Hosp on proposed rule 10CFR20 redisposed of liquid scintillation media & animal carcasses containing tritium & C-14. Opposes rule.

 LUTMAN. M. Affiliation Unknown. 45FR67018 266. 80/11/18. [p. 07231: 322.
- 8012120302 Comments on proposed rule 10CFR20 re disposal of liquid scintilletion media & animal carcasses containing tritium & C-14. Opposes rule.

 # Affiliation Unknown. 43FR67018 278. B0/11/24. ip. 07187:001.
- 8012120310 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.

 SEEKER-WALKER St. Louis Univ. Medical School. 45FR47018 281.

 BD/11/10. ip. 07231:321.
- 8012120312 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.
 ORIFO, A.P. Dhio Agriculture Research & Development Center.
 45FR67018 280. 80/11/26 1p. 07231:320.
- B012120316 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Bupports proposal.
 BPECTOR: A. Columbia Univ. 45FR67018 271. 80/11/26. ip. 07231:319.
- 8012120318 Comments by Rivanne Mater & Sewer Authority on proposed rule 10CFR20 re disposel of liquid scintillation media & animal carcasses containing tritium & C-14. Questions basis for proposed limits. Requests further info. WILLIAMS. O. W. Cheriottesville, Va. 45FR67018 267. 80/11/21. 1p. 07231:318.
- 8012120319 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.

 JESSE.K.E. Illinois State Univ. 45FR47019 270. 80/11/19. 1p. 07231:317.

- 8012120333 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposel. KEENE. 4. E. Catholic Univ. 45FR67018 264. 80/11/21. 2pp. 07187:001.
- 8012120335 Commants by TX Momans Univ on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14, Supports proposal, ERDMAN, M.E., HARDCASTLE, J.E., MECAY, M.L. Affiliation Unknown, 45FR67018 268, 80/11/19, 1p. 07231:316
- 8012120348 Comments by TX Homans Univ on proposed rule iOCFR20 re disposed of liquid scintiliation media & animal carcasses containing tritium & C-14. Supports proposal. HUEY, M.E. Affiliation Unknown. 45FR67018 269. 80/11/20. 1p. 07231:315.
- 8012120355 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media % animal carcasses containing tritium & C-14. Supports proposal. TALLEY, N. Affiliation Unknown. 45FR47018 293. 80/12/01. 1p. 07231: 314.
- B012120357 Comments by Beth Israel Redical Ctr on proposed rula 10CFR20 re disposal of liquid scintillation media & animal carcastes containing tritium & C-14, Supports proposal. LORCH, L.B. Affiliation Unknown. 45FR67018 273. B0/i1/25, 1p. 07231: 313.
- 8012120359 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.

 STEWARD,P. Vet. Admin. Hosp. St. Lauis, MO. 45FR67018 292.
 80/11/28. ip. 07231:312.
- 8012120369 Comments on proposed rule 10CFR20 re disposed of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & encourages changes to improve low lavel raduaste disposal practices.

 BROBEUS.R.H. Health & Human Services, Dept. of., 45FR67018 290. 80/11/21, 2pp. 07231:310.
- 8012120370 Comments by Desert Samaritan Rosp & Health Ctr on proposed rule 10CFR20 re disposed of liquid scintillation media & animal carcasess containing thitim & C-14. Supports proposed. Favors extension to cover other isotopes.

 JOHNSON: 8 Affiliation Unknown. 45FR67018 272. 80/11/26. Ip. 07231:309.
- 8012120374 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Stés re biological by-products not developed.

 81LVA. J. Michigan: Univ. of, Medical School. 45FR67018 262. 80/11/22. 2pp. 07231:307.
- 8012120380 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-i4. Bupports proposal Favors extension to cover other radionuclides.
 MURPHY:R.T. Travenol Laboratories. 45FR67018 263. 80/11/25. 1p.
- 8012120383 Comments by Cutter Labs on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal.

 NAKANURA. C.M. Affiliation Unknown. 45FR67018 276. 80/11/20. 1p. 07234-385
- 8012120384 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports proposal. Favors extension to cover radio-immuno assay generated waste.

 MANGEMANN.R.T. Army.Dept. of. Office of Surgeon General. 45FR67018 265. 80/11/24. 1p. 07231:304.
- 8012120608 Comments by Hunter College on proposed rule 100FR20 redisposed of liquid scintillation media & animal carcasses containing tritium & Co-i4. Opposes rule. PICCIONI.R.O. PISELLO.B.M. Affiliation Unknown. 49FR67018 289. 80/11/30. 4pp. 07228:240.
- 8012120613 Comments by St Lukes Hosp Medical Ctr on proposed rule 10CFR20 re disposal of liquid scintillation media & enimal carcasses containing tritium & C-14. Supports rule. Other isotopes should be included.
 RINDE, A. Affiliation Unknown. 49FR47018 295. 80/11/26. 2pp. 07227:358.

- B012120617 Comments by Humana on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & (c-14. Supports proposal. Problem exists re lack of uniform definition of what constitutes radwaste.
 HDLSCOTT.M.D. Affiliation Unknown. 45FR67018 212. 80/11/20. 2pp. 07227: 356.
- BO12120620 Comments by Montefiore Hosp & Hedical Ctr.Bronz.NY on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14.
 Supports rule
 FRERICHS-U. Affiliation Unitrown. 45FR67018 291. 80/11/26, 107227.355. . Affiliation Univolun. 45FR67018 291, 80/11/26, ip.
- 8012120624 Comments by Good Samaritan Hosp on proposed rule 10CFR20 redisposal of liquid scintilitation media & animal carcasses containing tritium & C-14. Supports proposal Other isotopes in common use should be included.
 HILGER, H. T. Affiliation Unknown. 45FR67018 200. 80/11/18. 1p. 07207-1944
- 3012120626 Comments by HA Univ (n St Louis on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcaises containing tritium & C-14. Supports proposal. MELDON.V.V. Affiliation Unknown. 45FR67018 279. 80/11/25. 1p. 07227:353.
- 012120627 Comments by Joint Commission on Accreditation of Hosps on proposed rule 10CFR20 re disposed of liquid scintillation media & animal carcasses containing tritium & C-14.
 Supports rule.
 MULLEN.P. & Affiliation Unknown. 45FR67018 286. 60/11/24. 2pp. 07227:351.
- 012120631 Comments by Resources Agency of CA on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. No comment, BURNS, U.W. California, State of. 45FR67018 294. B0/12/01. 1p. 07227:350.
- 01216023B Responds to 801115 comments on proposed rules 30,32,70 & 150 re elemption of smelted alloys from licensing requirements.
 Prospect that recycled enrichment plant scrap would cause cancer unlikely.
 HE/RY, J. J. Transportation & Product Standards Branch. 80/12/02.
- 012160550 Comments on proposed rules 10CFR30,32,70 & 150 re possession.use & transfer of low enriched U as contaminant in metals.Opposes rule. MARTINEZ.G. Affiliation Unknown. 45FR70874 0070, 80/12/03. ip.
- D12160562 Comments on proposed rules 10CFR30,32,70 & 150 repossession,use & transfer of low enriched V as contaminant in metals. Opposes rule.

 PAMESEEFF, D. Affiliation Unknown. 45FR70874 0066. 80/12/03. 1p.
- 012160969 Comments on proposed rules 10CFR30, 32,70 & 150 re possassion, use & transfer of low enriched U as contaminant in metals. Opposes rule. CAPELLAN.R. Affiliation Unknown. 45FR70874 0051. 60/12/03.
- pt2160574 Comments on proposed rules 10CFR30,32,70 & 150 reposession.use & transfer of low enriched U as contaminant in metals.Opposes rule.

 STROMBERO.M. Affiliation Unknown. 45FR70874 0090. 80/12/03. 1p.
- 12160578 Comments on proposed rules 10CFR30:32:70 & 150 reposession.use & transfer of low enriched U as contaminant in metals.Opposes rule.

 HONIEZ.Y. Affiliation Unindwa. 45FR70874 0049. 80/12/03. 1p.
- 12160581 Comments on proposed rules 10CFR30,32,70 & 180 re passession.use & transfer of low enriched U as contaminant in metals.Opposes rule. JACOBOMITZ,P. Affiliation Unknown. 45FR70874 0048. 80/12/03. 1p.
- 12160583 Comments on proposed rules 10CFR30,32,70 & 150 reposession.use & transfer of low enriched U as contaminant in metals. Opposes rule.
 RICK, S. Affiliation Unknown, 45FR70874 0047, 80/12/03, 1p.
- 12160588 Comments on proposed rules 10CFR30,32,70 & 150 re possession,use & transfer of low enriched U as conteminant in metals.Opposes rule. CGRHHELL,H. Affiliation Unknown: 43FR70874 0046. 80/12/03. lp.
- i2160593 Comments on proposed rules 100FR30,32,70 % 150 re postession.use & transfer of low enriched U as contaminant in metals.Opposes rule HENTZER, M. Affiliation Unknown, 45FR70874 0044, 80/12/03, 1p.

- 8012160600 Comments on proposed rules 10CFR30, 32, 70 & 150 repossession.use & transfer of low enriched U as contaminant in metals. Opposes rule.

 BILLEGI, G. D. Affiliation Unknown. 45FR70874 0043. 80/12/03. 1p.
- 8012160606 Comments on proposed rules 100FR30, 32,70 & 130 re possession. wse & transfer of law enriched U as contaminant in metals. Opposes rule.

 LECNARD, C. Affiliation Unknown. 45FR70874 0042. 80/12/03. 1p.
- B012160609 Comments on proposed rules 100FR30, 32,70 & 150 re possession, use & transfer of low enriched U as contaminant in metals. Opposes rule.

 MURPHY, T. A. Affiliation Unknown. 45FR70874 0041. B0/12/03. ip.
- 8012160517 Comments on proposed rules 10CFR30, 32, 70 t 150 re possession, use & transfer of low enriched U as contaminant in metals. Opposes rule.

 COMER.M. Affiliation Unknown. 45FR70874 0031, 80/12/03, 1p.
- 8012160631 Comments on proposed rules 10CFR30, 32,70 & 150 re possession.use & transfer of low enriched U as contaminant in metals.Opposes rule. HULLER, J. C. Affiliation Unknown. 45FR70874 0026, 80/12/03. 1p.
- 8012160642 Comments on proposed rules 10CFR30.32.70 & 150 re using contaminated scrap metal & mixing w/other metals. Protests ruce. RICHARDS, R. L. Affiliation Unknown. 45FR70874 0025. 80/11/29. 1p.
- 9012160649 Comments on proposed rules 10CFR30, 32,70 & 150 re reusing scrap metal from U enrichment plants for consumer or other items. Opposes rule.
 PILUGIN, N. W. Affiliation Unknown. 45FR70874 0024. 80/11/25. 1p.
- BO121606A3 Comments on proposed rules 10CFR30,32,70 & 150 re possession,use & transfer of low enriched U as contaminant in metals.Opposes rule. JONES.B. Affiliation Unknown. 45FR70874 0035. 80/12/03. 1p.
- 8012160668 Comments on proposed rules 10CFR30,32,70 & 150 repossession, use & transfer of law enriched U as contaminant in metals. Opposes rule.

 SHEM-TRANZ, E. Affiliation Unknown. 45FR70874 0038, 80/12/03, 1p.
- 8012160482 Comments on proposed rules 100FR30,32,70 & 150 repossession.use & transfer of low enriched U as contaminant in metals. Opposes rules.
 IAROBSE.D. Affiliation Unknown. 45FR70874 0037. 80/12/03. ip.
- 8012160089 Comments on proposed rules 100FR30,32,70 & 150 repossession, use & transfer of low enriched U as contaminants in metals. Opposes rule.

 # Affiliation Unknown. 45FR70874 0036. 80/12/03. 1p.
- 8012160707 Comments on proposed rules 10CFR30.32.70 & 150 rm using contaminated metals for consumer products Opposes rule. HUNEZ.M. Affiliation Unknown. 45FR70874 0040. 80/12/03. 1p.
- 8012160718 Comments on proposed rules 100FR30,32,70 & 150 repossession, use & transfer of low enriched U as contaminant in metals. Opposes rule.

 KRAUS, G. Affiliation Unknown. 45FR70874 0030. 80/12/03. ip.
- 8012160737 Comments on proposed rules 10CFR30,32,70 & 130 repossession,use & transfer of low enriched U as contaminant in metals. Opposes rule.

 CARDELI,A. Affiliation Unknown. 45FR70874 0037. 80/11/26. 1p
- 8012170030 Schments on proposed rules 10CFR30:32,70 & 150 re releasing radwaste water, Opposes rule.

 CORNNELL, N. Affiliation Uninown. 45FR70874 0045. 80/11/26. ip.
- 8012170046 Comments on proposed rule 10CFR50 re "Proposed Licensing Requirements for Pending CP & Mfg License Applications." Urges NRC to terminate proposed rulemaking, but in swent of rulemaking, util requests to participate.

 DAIL.L.C. Duke Power Co. 45FR65247 014, 80/11/25, 2pp. 07286:155,
- 8012170053 Comments on proposed rule 10CFR50 re proposed licensing requirements for pending CP & mfg license applications.NRC should pursue licensing policy that ensures only necessary safety improvements will be made based on TMI experience. WITHERS.B.D. Portland General Electric Co. 45FR65247 013. 80/11/24. 2pp. 07266:153.

- B01217065B Comments on proposed rule 10CFR50 re plan to require documentation from BRP, Urges NRC to restructure plan in accordance w/util recommendations. COUNBIL. M. O. CONNECTICUT Yankee Atomic Power Co. COUNBIL. M. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 45FR67099 031, B0/11/24. 3pp. 07266: 150.
- 80:12170065 Comments on proposed rule iOCFR50 re proposed licensing requirements for pending CP & mfg license applications. Option 1 is only logical approach to resuming licensing pending completion of generic rulemaking proceedings. ANDERESON. T. M. Westinghouse Electric Corp. 45FR65247 012. 80/11/24. 2pp. 07266:148.
- 8012170089 Comments on proposed rules 10CFR30,32,70 & 150 re possession.use & transfer of low enriched U as contaminant in metals.Opposes rule.

 LEVINE.H.R. Affiliation Unknown. 45FR70874 0082. 80/11/27. 1p.
- 8012170092 Communts on proposed rules 100FR30,32,70 & 150 re possession.use & transfer of low enriched U as contaminant in metals.Opposes rule. BECKER.P. Affiliation Unknown. 45FR70874 0081. 80/12/04. ip.
- BO12170095 Comments on proposed rules 10CFR30,32,70 & 130 re exempting certain radioactive metals from restrictive use. Opposes rule.

 BADGER,D. Affiliation Unknown. 45FR70874 0023. B0/12/03, 1p.
- BO12170100 Comments on proposed rules 10CFR30,32,70 & 150 re possession, use & transfer of low enriched U as contaminent in metals. Opposes rule.

 KELLOOP,M. Affiliation Unknown. 45FR70874 0080. 80/12/02. 1p.
- BO12170101 Comments on proposed rules 10CFR30,32.70 & 150 re possession.use & transfer of low enriched U as contaminant in matals.Opposes rule.

 DUFFY.D. Affiliation Unknown. 45FR70B74 0028. 80/12/03. 1p.
- 8012170117 Comments on proposed rules 10CFR30,32,70 & 150 repossestion, use & transfer of low enriched U as contaminant in metals. Opposes rule.
 HILLER: 0. Affiliation Unknown. 45FR70874 0032, 80/12/03. 1p.
- 8012170120 Comments on proposed rules 10CFR30,32,70 & 150 repossession.use & transfer of low enriched U as contaminant in metals.Opposes rule.
 FDPAKIAN.K. Affiliation Unknown. 45FR70874 0079, 80/12/01. ip.
- 80:2170:27 Comments on proposed rules 10CFR30, 32, 70 & 130 repossession, use & transfer of low enriched U as contaminant in metals. Opposes rule.

 ZEBLR.K. Affiliation Unknown. 45FR70874 0078. 80/12/04. ip.
- 8012170129 Comments on proposed rules iGCFR30.32.70 & i50 repossession.use & transfer of low enriched U as contaminant in metals.Opposes rule.
 RDSENFELD.8. Affiliation Unknown. 45FR70874 0034. 80/12/03. ip.
- 8D12170134 Comments on proposed rules 10CFR30.32.70 & 180 repossession.use & transfer of low enriched U as contaminant in metals.Opposes rule.
 HTLLS.M. Affiliation Unknown. 45FR70874 0077. 80/12/01. ip.
- B012170137 Comments on proposed rules 10CFR30.32.70 & 150 reposeession, use & transfer of low enriched U as contaminant in metals. Opposes rule.

 CHOPRA, D. Affiliation Unknown. 45FR70B74 0029. B0/12/03. ip.
- B012170143 Comments on proposed rules 10CFR30,32.70 & 150 re postession.use & transfer of low enriched U as contaminant in metals.Opposes rule. * Affiliation Unknown. 45FR70874 0076. B0/I1/24. 1p.
- 8012170146 Comments on proposed rules iOCFR30:32.70 & 150 re possession.use & transfer of low enriched U as contaminant in metals.Opposes rule. BOANOA.F.S. Affiliation Unknown. 45FR70874 0033. 80/11/26. ip.
- 8012170150 Comments on proposed rules (OCFR30, 32, 70 & 150 repossession.use & transfer of low enriched U as contaminant in metals.Opposes rule.

 DMORETZKY, B. A. Affiliation Unknown, 45FR70874 0075. 80/11/30. ip.
- B012170157 Comments on proposed rules 100FR30:32:70 & 150 re user possession & transfer of low enriched U as contaminant in metals. Opposes rule.

 KABMANR. Affiliation Unknown. 45FR70874 0027. 80/12/03. 1p.

- B012170159 Comments on proposed rules 100FR30, 32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals. Opposes rule.

 LAMBERT. 0. Affiliation Unknown. 45FR70874 0074. 80/12/03. 1p.
- B012170173 Comments on proposed rules 10CFR30,32,70 % 180 repossession, use % transfer of low enriched U as contaminant in metals. Opposes rule.

 DE LIONIBUS. 0. Affiliation Uninown. 45FR70874 0073. 80/12/03.
- B012170184 Comments on proposed rules 100FR30,32,70 & 150 repossession.use & transfer of low enriched U as contaminant in metals. Opposes rule.
 OALANO,N. Affiliation Unknown. 45FR70874 0072, B0/11/25. ip.
- B012170190 Comments on graposed rules 10CFR30,32,70 & 150 repossession.use & transfer of low enriched U as contaminant in metals. Opposes rule.

 LAZARO.J. Affiliation Unknown. 45FR70874 0971, 80/11/25, 1p.
- 8012170193 Comments on proposed rule 10CFR20 re proposed general statement of policy & procedure for enforcement actions.

 Opposes rule. NRC should not become both judge & jury because of license violations.

 MEGREMIG.T.L. Morgan County Memorial Hosp. Martinsville. IN. 43FR67018 181. 80/11/18. 1p. 07266:139.
- 8012170231 Comments on proposed rule 10CFR20 re disposal of liquid scintilistion media & animal carcasses containing tritium & C-14. Rule would alleviate chronic & costly radwaste disposal problems. Other isotopes should be added. Supports rule.
 BRONN: R.C. Washington State Univ. 45FR67018 180. BO/11/19. 1p 07266: 198.
- 8012170294 Comments on proposed rule 10CFR2 re policy & procedure f enforcement actions. Opposes policy. MEGREMIS.T.L. Morgan County Memorial Hosp. Martinsville.IN. 45FR66754 025. 80/11/18. ip. 07266:180.
- 8012170243 Comments on proposed rule 10CFR2 repolicy & procedure f anforcement actions. Policy is inappropriate for nonprofit organizations, especially hosps. CULVER.C. Veterans Administration. 45FR66754 024. 80/11/24. 1
- 8012170250 Comments on proposed rule 10CFR2 repolicy & procedure fundorement actions. Requests extension of comment period.
 COUNSIL. M. Q. Affiliation Unknown. 45FR66754 023. BO/11/25. Op 07266: 169.
- 8012170267 Comments on proposed rule 10CFR2 repolicy & procedure f enforcement actions. Opposes proposed policy. MCKAY, C.E. Cabel Huntington Hosp. Huntington, NV. 45FR66754 021, 80/11/28. 1p. 07266:276.
- 8012170285 Comments on proposed rules 100FRSD.51 & 100, "Mod of Policy & Regulatory Practice Governing Siting of Nuclear Power Plants."

 ORASSO,E. Connecticut, State of. 45FR50350 069. 80/11/25. 6pp 07266:001.
- 80(2170297 Comments on proposed rule 10CFR2 repolicy & procedure fendorcement actions. Civil penalties for violation of health physics, transportation & matts operation should be equal for all categories of licensees.

 9ROWNEY,E. J. Affiliation Unknown. 45FR66754 020. B0/11/18. 1p07266: 117.
- 8012170307 Comments on proposed rule 10CFR2 repolicy & procedure enforcement actions. Limited consideration has been given to small entities comprised of diagnostic & therapeutic nuclear medicine depts.
 RIEIVELD.P. A Dickinson County Memorial Hosp. Iron Hountain, HI. 45FR66754 022. 80/11/17. 2pp. 07266:113.
- BD12170320 Comments on proposed rule 10CFR34 re disposal of records pocket dosimeter readings. Maintaining pocket dosimeter reading for 2 yr period is reasonable.
 MALEK.F.A. Oulf Nuclear, Inc. 45FR37836 046. 80/06/30. 1p. 07266: 131.
- 8012170330 Comments on proposed rule 10CFR50 re hydrogen control & certain degraded core considerations.
 COUNBIL, M. G. Connecticut Yankee Atomic Power Co. COUNBIL, M. G. Northeast Nuclear Energy Co. (2005. of Northeast Utilities).
 45FR63466 035. 80/11/17. 5pp. 07266:126.

- 801217034D Comments on proposed rule 10CFR50 re plan to require documentation of deviations from BRP. Urges NRC to withdraw current proposal & begin congressionally mandated effort w/identification of regulations significant to public health. WHITE.L.D. Rochester Gas & Electric Corp. 45FR67099 028. BO/11/24. 3pp. 07266:123.
- 8012180196 Forwards MG Laurence 801106 comments on proposed rule 10CFR20 re disposal of low level radwaste. Opposes rule. CRANSTON. A. Senate. 45FR67018 306 80/12/03. 2pp. 07272:244.
- B012180159 Comments on proposed rule 10CFRSO re plan requiring licensees & applicants to document deviations from SRP. Mods should be made to take greater advantage of existing programs.
 TAYLOR, J. H. Babcock & Nilcox Co. 45FR67099 032. 80/11/26. 29p. 07272-242
- B012180161 Comments on proposed ruje 10CFRSD to plan requiring licensees & applicants to document deviations from BRF. Opposes rule in present form.
 WIDNER.N.A. Georgia Power Co. 43FR67099 029. 80/11/26, 4pp. 07237:224.
- 8012180166 Comments on proposed rule 10CFR50 re plan requiring licensees & applicants to document deviations from ERF.NAC should respond to Congress by outlining comprehensive safety review conducted by NRC during OL.EEP & Thi reviews.

 SHERRODD, 0. 9. General Electric Co. 45FR67099 030. 80/11/18. 2pp. 07272-236.
- B012180171 Forwards comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcassas containing tritiun & C=14. FUSON, B. Affiliation Unknown. 45FR67018 305, 80/12/04. 1p. 07272:232.
- 8012180173 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Opposes rule. GOORIES.P.R. Affiliation Unknown. 45FR67018 303. 80/12/10. 3pp. 07272, 229.
- BO12180177 Comments on progosed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Opposes rule.

 WEISBLAT, D. I. Upjohn Co. 45FR67018 307. 80/12/04. 1p. 07272:228.
- 8012180182 Comments by Dept of Environ Protection on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule. HEUBNER, A. T. Connecticut, State of. 45FR6701B 304. 80/11/23. 1p. 07272:227.
- B012180187 Comments on proposed twie 10CFR20 re disposal of liquid scintillation media & enimal carcasses containing tritium & C-14.
 HGRRIE.V. Affiliation Unknown. 45FR67018 302. B0/11/18. ip. 07272:226.
- 8012180191 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
 HIGH.M. Affiliation Unknown. 45FR47018 301. 80/11/24. 1p. 07272: 225.
- B012180197 Comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Supports rule.
 KELSEY, C.A. New Mexica, Univ. of, 45FR67018 297. 80/11/26. 1p. 07272:224
- 8012180200 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule. NADEL-E. M. St. Louis Univ. Hedical Center St. Louis, MO. 45FR67018 296. 80/11/25. 1p. 07272: 223.
- B012180203 Comments on proposed rule 10CFR20 re disposal of liquid scintiliation media & enimal carcasses containing tritium & C-14. Supports rule.
 SHAPIRO.E. J. Air Force Dept. of. 45FR67018 300. B0/12/02. 1p. 07183:001.
- 8012180P06 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule & urges NRC to proceed w/adoption as soon as possible.

 VAN PELTATER. Hoffman-La Roche, Inc. (subs. of F. Hoffman-Le Roche & Co., Ltd.). 45FR67018 278. B0/11/25, ip. 07272: 222.

- 8012180211 Advises recipiensts of comments on proposed rule 100FR50 that comment Numbers 14 & 24 were miscategorized. Comments 14 & 24 will be Numbers 27 & 23 under proposed rule 100FR2.

 * Docketing & Services Branch. 80/12/03. 1p. 07183:001.
- 8012180218 Forwards 1976 & 1977 NRC documents from Ofc of Nuclear Reactor Regulation re documentation of deviation, as noted in 801124 camments on proposed rule 100FR50 on behalf of Shoreham Opponents Coalition. LATHAM, S. Twomey, Latham & Schmitt. 45FR67097 018A, 80/11/25, 3pp. 07183:001.
- 8012180221 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Supports rule. REZNOR.U.S. MCCUTCHEON.J.D.: BELL.H.E. Mercer.PA. 49FR46754 032. 80/11/06. ip. 07272:221.
- 8012180224 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for unforcement action. Suppls IV & V address specific exposure to personnel as violation but do not include time frame. WILLARD.T. Affiliation Unknown. 45FR66754 031. 80/11/04. 1p. 07272:220.
- 8012180225 Comments on proposed rules 10CFR30,32,70 & 150 re possession.use & transfer of low enriched U as contaminant in metals.Opposes rules. ERDOS.K. Affiliation Unknown. 45FR70874 0084. 80/12/03. ip.
- 8012180227 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Requests extension to 810227 to comment. EDGAR, 0.L. Margan, Lewis & Bockius. 45FR66754 030. 80/12/01, 1p. 07272; 218.
- 8012180230 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Proposal should be withdrawn until assessment can be made as to necessity of new regulations.

 JANSSEN.T.K. Washington County Hosp. Nashville, IL. 45FR66754 029. 80/11/20. ip. 07272:217.
- 8012180233 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Requests that NRC postpone planned meetings on proposed policies & rewrite regulations pertaining to small user. CERNY.R.J. Memorial Hosp. of Mason County Ludington.MI. 45FR66754 028. 80/11/20. 2pp. 07272:215.
- 8012180237 Comments on proposed rules 10CFR30,32,70 & 150 re licensing requirement exemption for contaminated smelted alloys.

 Opposes rule.

 PETERS.A. Affiliation Unknown. 45FR70874 0083. 80/12/02. ip.
- B012180242 Comments on proposed rules 100FR30,32,70 & 130 re licensing requirement exemption for contaminated scrap metal.Opposes rule.
 MULLER.M.B. Affiliation Unknown. 45FR70874 0085. 80/11/30, 1p.
- 8012180246 Comments on proposed rules 10CFR3D,32,70 & 150 re licensing requirement exemption for contaminated scrap metal. Opposes rule.
 MUELLER,B.P. Affiliation Unknown. 45FR70874 0086. 80/11/30. ip.
- 8012180236 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Proposal should be withdrawn until assessment can be made as to necessity of new regulations.

 WEBER, J. A. Washington County Hosp. Nashville, IL. 43FR66754 027, 80/11/25. 1p. 07272:213.
- 8012180259 Comments on proposed rule 10CFR50 re plan requiring licensees & applicants to document deviations from BRP. Imappropriate to use Section 110 of RRC FY80 Authorization as basis for documenting deviation from BRP. EDWARDS.D.W. Yankee Atomic Electric Co. 45FR67099 041. 80/12/03. 3pp. 07272:210.
- 8012180260 Comments on proposed rule iOCFR50 re plan requiring licensees & applicants to document deviations from SRP. OIDBS,D.C. Atomic industrial Forum. 45FR67099 038. 80/12/04, 8pp. 07272:202.
- 8012180266 Comments on proposed rule 10CFR50 re plan requiring licensees & applicants to document deviations from SRP. Opposes rule. BOCKELR.T. Palos Community Hosp. Palos Park.IL. 45FR67099 040. 80/12/04. 5pp. 07272:197.

- 8012180271 Forwards comments on proposed rule 10CFR50 re plan requiring licensees & applicants to document deviations from BRP.Plan offers NRC opportunity to demonstrate that programs aimed at plant safety can be carried out in efficient manner.

 BAYNE, J. P. Power Authority of the State of New York. 45FR67097 037. 80/12/04. 6pp. 07272:191.
- B012180274 Comments on proposed rule 100FR50 re plan requiring licensess & applicants to document deviations from SRP. FURBUSH,M.H. Pacific Gas & Electric Co. 45FR67099 039. 80/11/24. 4pp. 07272:187.
- 8012180277 Comments on proposed rule 10CFR50 re plan requiring licensees & applicants to document deviations from SRP. Program is overreaction to Section 110 of Public Law 96-295. FAY.C.W. Kisconsin Electric Power Co. 45FR67099 036, 80/11/25 30p. 07272:184.
- 8012180283 Comments on proposed rule 10CFR50 re plan requiring licensees & applicants to document deviations from SRP. Proposed rule should be rescinded & advance notice of proposed rulemaking issued.

 BAIL.L.C. Duke Power Co. 45FR67099 035. 80/12/01. 2pp. 07271:360.
- 8012180286 Comments on proposed rule 10CFR90 re plan requiring licensees & applicants to document deviations from BRP. NRC should consider plan whereby regulations are significant in terms of public health & safety. PARKER, N. D. Duke Power Co. 45FR67099 033, 80/11/24, 2pp. 07272:178.
- 8012190457 Comments on revision of 10CFR51 & related conforming amends in response to 801103 memo, Orandfather clause should be incorporated in 50.36b to cover facilities licensed prior to 700101. Environ repts will be required for 10CFR50 amends. EISELHUT, D. O. Division of Licensing. 80/12/04. 5pp. 07284:073.
- --8012170463 Forwards Commission paper requesting approval of FR notice promulgating revised 10CFR51 & related conforming amends as final rule. Comments should be submitted by 801114. W/o enci. SHAPAR;H.K. Dffice of the Executive Legal Director. 80/11/03. 3pp. 07284:077.
- 8012190533 Discusses 800109 request for ACRS participation in proposed rulemaking to reassess Commission confidence in safe disposal of radwastes. Safe disposal of radwastes is reasonably assured w/present state of knowledge. PLESEST.M.S. ACRS - Advisory Committee on Reactor Safeguards. 80/12/10. 6pp. 07274:005.
- B012220027 Comments on proposed rule 10CFR2 re-proposed general statement of policy & procedures for enforcement action. Disproportionate significance attached to matters of little potential or actual consequence. RAKE, A.V. Wright State Univ. 45FR66794 41. 80/11/18. 1p. 07304:140.
- 8012220039 Comments on proposed rules 10CFR50 re plan to require licensees & applicants to document deviations from SRP & proposed general statement of policy, respectively. Opposes rules, FEULKER, R. C. Waukesha Memorial Hosp, Waukesha, WI. 45FR67099 034. 80/11/25, 3pp. 07304:136.
- 8012220067 Comments on proposed rule 10CFR2 re-proposed general statement of policy & procedures for enforcement action. Requests that NRC postpone scheduled hearings for 6 months & reconsider proposed policies.

 ABRAMSON, C. L. Edward A. Utlaut Foundation: Inc. E. A. Utlaut Hemorial Hosp. Greenville, IL. 45FR66754 040. 80/11/25. 1p. 95104:265.
- 8012220076 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. More flexibility & judgment is required. PRICE, D. J. St. Michael Hosp. Milwaulee. NI. 45FR66754 039. B0/12/01. 1p. 07304:139.
- BD12240002 Motion for withdrawl of requests for quotation re waste confidence rulemaking.
 BCHAEFER, N. W. Bafe Haven, Ltd. B0/11/26. 19. 07324:179.
- 8012290032 Draft *Compliance Determination Procedures for Environ: Radiation Protection Stds for U Recovery Facilities: 40CFR190. **

 **Uranium Recovery Licensing Branch. 40CFR190. 80/11/30. 23pp. 07308; 001.

- 8012290121 Forwards comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Proposed statement of enforcement actions should not be applied to research & test reactors.

 8HRIVER.B.L. Affiliation Unknown. 43FR66754 054. 80/12/09. 44pp. 07345: 207.
- 8012290123 Comments on proposed rule IQCFR2 re-proposed general statement of policy & procedures for enforcement action. PATII, F. J. Burns & Roe Co. 45FR66754-049. 80/12/03. 7pp. 07345-200
- 8012270126 Comments on proposed rule IOCFR2 re proposed general statement of policy & procedures for enforcement action. Opposes rule. BMALL J.H. Henry County Health Center, Mt. Pleasant, IA. 45FR66754 046. BD/11/28. 2pp. 07345:118.
- 8012290128 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Proposed fines not necessary Statement indicating how matter of noncompliance will be corrected is sufficient. LOZADD.8.E. Calumet Memorial Hosp. Chilton.(II. 45FR66754 045. EO/11/25. ip. 07345:199.
- 8012270132 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Advises that A Nassman & NP Dyek will attend 801204 public meeting & will submit listed questions. ONOHUNDRD, F.P. Public Service Electric & Gas Co. of New Jersey. 45FR66754 044. 80/11/26. 2pp. 07187:001.
- 8012270133 Comments on proposed rule (OCFR2 re proposed general statement of policy & procedures for enforcement action. Protests imposition of monetary fines for noncompliance w/NRC regulations.

 ORAKA.E.S. Frances A. Bell Memorial Hosp. Ishpemins/MI. 45FR64754
 043. 80/12/02. 1p. 07345:198.
- B012290137 Comments on proposed rule LOCFR2 re proposed general statement of policy & procedures for enforcement action. Requests that NRC postpone scheduled hearing for 6 months & reconsider proposed policies.

 ABRAMSON.C.L. St. Joseph's Hosp Highland.IL. 45FR66754 038. B0/11/25. 2pp. 07345:196.
- 8012290139 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Public meetings should be deferred for 6 months in order to make schedule changes & formulate proper response. CLAYDAUOH.W M. Hartford demorial Hosp. Hartford, WI. 45FR66784 036. BO/11/23. ip. 07345:195.
- 8012290141 Comments on proposed rule 100FR2 re proposed general statement of policy & procedures for enforcement action. Opposes rule. LAVER.J.D. St. Joseph Hosp, Kirkwood,MO. 45FR66754 035. 80/11/28. 1p. 07345:194.
- BO12290144 Comments on groposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Proposed policy is corruption of professionalism & works to defeat high purpose of NRC-safe nuclear industry. RUSELL.J.L. Georgia Institute of Technology. 45FR66754 034. BO/11/06. ip. 07345:116.
- B012270147 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Preamble should be included re dedication to continued implementation & expansion of safe nuclear energy industry. HAUSMAN.A.L. Affiliation Unknown. 45FR66754 033. B0/11/01. 1p. 07345:117.
- BO12290131 Forwards comments on proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement action. Comments will be presented by BR Clements at NRC B01209 regional meeting in Irving.TX, KAHLER.R.E. Teras Utilities Generating Co. 45FR66754 042. B0/12/03. 7pp. 07345:187
- 8012270457 Response joining NY Atty General 801103 motion that NRC withdraw request for bids to unidentified consultants. NRC must provide all participants w/all correspondence. Certificate of Svc enci. JOINSRUD. J. H. Environmental Coalition on Nuclear Power. 80/11/28. 2pp. 07335-042.
- 8012290476 Transcript of 801211 meeting in Washington.DC re 8ECY-80-474C.Pp 1-32.

 * Commissioners. 80/12/11. 34pp. 07335:066.

- --8012270477 Discusses legal issues re proposal to approve publication of 100FR60 final rule re disposal of high level radwaste in geologic repositories.
 BICKURITL. Office of the General Counsel. 80/12/10. 3pp. 07335:101.
- --8012270483 SECY-80-474C
 Suppls SECY-80-474 & forwards clarifying changes to 100FR60 final rule & conforming amends.
 DIRCKS,N.J. Office of the Executive Director for Operations.
 80/12/07. 16pp. 07335:104.
- ---8012270485 Forwards NRC recommended changes to final rule 100FR60. DIRCKB.N.J. Office of the Executive Director for Operations. 80/12/11. 9pp. 07335:120.
- 8012300672 Staff requirements memo re Commission 801126 meeting on SECY-80-474/474A. Requests staff actions re disposal of high level radwaste in geologic repositories. CHILKS.J. Office of the Secretary of the Commission. M801126A. B0/12/10. 1p. 07359:209.
- 8012300703 Staff requirements memo re Commission Affirmation Session 80-53 on 801205. Approved memo & order denying Duke Power Committee for reconsideration of emergency planning. CHILK: S. J. Office of the Secretary of the Commission. 80/12/08. 1p. 07359: 297.
- PROJ PROJECTS PREDOCKET LICENSING
- 8012010055 Comments on draft generic EIS on U milling. Impractical to limit tailings disposal schemes to prime option of complete below grade disposal. LANG.E.A. Atomic Industrial Forum, 79/10/24. 74pp. 07098:116.
- B012050482 Forwards project prediction for FFTF reactor systemsient natural circulation test from 35% power. CARLISLE, C. B. Energy, Dept. of. FTF: DJF: 234. 80/11/28. ip. 07174: 127.
- --8012030488 Submits info re pretest predictions for 35% natural circulations test & up-to-date revision of Tech Specs.
 MCSHANG, N. J. Hanford Engineering Development Laboratory. 8054023, 80711748. pp. 07174:128.
- ---8012030492 T8-51-5A008

 "Pratest Predictions for FFTF Reactor Sys Transient
 Natural Circulation Test From 35% Power," Part 2.
 NUTT.U.T., HECK.F.M., ELIA.G. D. Hanford Engineering Development
 Laboratory. 80/11/10. 29pp. 07174:129.
- --8012057496 TC-1799
 "Pretest Predictions of Thermal & Hydraulic Responses of Fueled Open Yest Assemblied to 35% Power Natural Circulation FFFF Plant Startup Test."
 JOHNSON, H.O., Hanford Engineering Davelopment Laboratory.
 80/10/31. 68pp. 07174:161.
- 8012080243 Informs that 30-day review of final EIS began on 801019. * Gregon, State of. 17722. 80/10/19. ip. 07187:065.
- 8012090743 Verifies official filing of FES re generic V milling. Scheduled FR publication of notice of availability is 801010. Public review period terminates 801110. WILBON.K.L. Environmental Protection Agency. 80/10/08.
- SOIR180436 Forwards agenda & list of attendees re SO1106 meeting on hot experimental facility. Next meeting scheduled on 9:0114. Matl accountability instrumentation & physical protection will be addressed.

 CLARK.A.T. Advanced Fuel & Spent Fuel Licensing Branch. 80/11/25.
 3pp. 07272:130.
- B01222008B Forwards draft West Valley Demonstration Project Act requiring NRC to enter interspency agreement w/DDE to define role in reviewing DDE activities for project. CUNNINOHAM.R.E. Division of Fuel Cycle & Material Bafety. 80/11/25. 8pp. 07307:047.
- B012240435 Ack receipt of FES for final generic environ impact statement on U milling No addi comments received.
 BANKS, L. E. North Dakota, State of. 17960. B0/11/13. ip. 07327:336.

- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8012100406 Part 21 rept re N521-SR actuators, reported on 801113. Parts causing problem have been changed by 801118 engineering change notice.

 LOCASCIO, A. T. GH Bettis Corp. 80/11/17. 4pp. 07218:001.

QA999 QUALITY ASSURANCE INSPECTIONS

- B012020667 Ack receipt of B01106 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900030/B0-02. POTAPDVS, U. Region 4, Dallas, Vendor Inspection Branch. B0/11/19.
- --8012020675 Responds to NRC 801017 ltr re deviation noted in QA Program Insp Rept 99900030780-02. Corrective actions: signed Revision i rept will be sent to architect. Relding procedures will be documented & drawings redesigned.

 KOROAN, J. F. Colt Industries, Inc., Fairbanks Morse Engine Div. 80/11/06. 15pp. 07145:330.
- --8012020683 Forwards GA Program Insp Rept 99900300/80-02 on 800915-18 & notice of deviation. POTAPDVS.U. Region 4. Dallas. Vendor Inspection Branch. B0/10/17. 2pp. 07145:345.
- --B012020692 Notice of deviation from insp on 800915-18. * Region 4. Dallas. Office of the Director. 80/10/14. 2pp. 07145:347.
- --8012020702 QA Program Insp Rept 99900300/80-02 on 800915-18.
 Noncompliance noted: followups on Part 21 repts & inspector identified problems not consistent w/regulations.
 FOSTER.W.E., BARNES.I. Region 4, Dallas, Vendor Inspection Branch.
 BO/10/14. ilpp. 07145:339.
- 8012020709 Ack receipt of 801027 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99700510/80-02.
 POTAPOVS.U. Region 4, Dellas, Vendor Inspection Branch. 80/11/14.
 ip. 07147:275.
- --8012020716 Responds to NRC 800922 ltr re deviation noted in GA Program Insp Rept 99700510/80-02 Corrective actions:revisions to specs will be identified & recorded w/monthly reviews by planning engineer.

 CURNANC.R.A. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 80/10/27. 2pp. 07147:276.
- --B012020721 Forwards GA Program Insp Rept 99700510/80-02 on 800825-29 & notice of deviation. POTAPOVS.U. Region 4, Delias, Vendor Inspection Branch. 80/09/22. 2pp. 07147:278.
- --8012020726 Notice of deviation from insp on 800825-29.

 + Region 4. Dallas, Office of the Director. 80/09/19. 1p. 07147:300.
- --B012020733 QA Program Insp Rept 99900510/80-02 on 800825-29.
 Noncompliance noted:design document control contrary to procedural requirements.
 COSTELLO, J. R., SREAUX, D. O., HALE, C. J. Region 4, Dallas, Vendor Inspection Branch. 80/09/19, 14pp. 07147:301.
- 8012/120792 Ack receipt of 801014 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900209/80-02. Addi info required re welding operator performance qualifications.
 FDTAPDVS.U. Region 4. Dallas, Vendor Inspection Branch. 80/11/12. ip. 07145:291.
- ~-B012020776 Responds to NRC 800910 ltr re deviation noted in GA Program Insp Rept 9990209/80-02. No proprietary info. Corrective actions: training program to be held in Oct 1980 re documentation requirements for welding matls.

 BECKBTED. M. F. Bergen-Patterson Pipe Support Corp. 80/10/14. 6pp. 07145:292.
- --8012020800 Forwards QA Program Insp Rept 99900209/80-02 on 800804-08 & natice of deviation.
 PGTAPDV8.U. Region 4. Dallas, Vendor Inspection Branch. 80/09/10.
 2pp. 07148:298
- --B012020B02 Notice of deviation from insp on B00804-0B. * Ragion 4. Dallas, Office of the Director. 80/09/03. 2pp. 07445:300.

- --8012020898 GA Program Insp Rept 99900209/80-02 on 800804-08.

 Noncompliance noted math not checked against purchase order requirements prior to release & drawing requirements not included in purchase documents.

 ELLERSHAW.L.E., BARNES, I. Region 4, Dallas, Vendor Inspection Branch. 80/09/05, 10pp. 07145:302.
- B012040013 Forwards GA Program Insp Rept 99900401/80-02 on 800826-28. No noncompliance noted. PDTAPOVB.U. Region 4. Dallas, Vendor Inspection Branch. 80/10/20. 2pp. 07169: 235.
- --B012040023 OA Program Insp Rept 95900410/80-02 on B00826-28 No noncompliance noted. Major areas inspected: implementation of 100FH21 & 100FH30, App B re OA records & action on previous insp findings.
 BRICKLEY.R.H., AGEE, J.R., ANORROWN, D.G. Region 4, Dallas, Vendor Inspection Branch. 80/10/17. 10pp. 07149: 257.
- B012080238 Ack receipt of 801002, iii0 & i9 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 79700325/80-02. POTAPDVS.U. Region 4, Dallas, Vendor Inspection Branch. 80/11/25. ip. 07186:187.
- --8012080244 Responds to NRC 801002 ltr re deviation noted in GA Program Insp Rept 99700525/80-02. Corrective actions: design verification procedures will be followed & design review general checklist will be completed.

 BARKER, N. R. Gilbert/Commonwealth Cos. 80/11/19, 2pp. 07186: 188.
- ~-8012080250 Responds to NRC 801021 ltr re deviations noted in GA Program Insp Rept 99900525/80-02. Clarifies that vendor drawings revised by GAI 800501-0908 will be handled according to comprehensive identification sys manual.

 BARKER, N. R. Gilbert/Commonwealth Cos. 80/11/10, 2pp. 07186: 190.
- --B0120B0287 Ack receipt of B01002 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900528/80-02. Requests addl info on handling of revisions to TMI-rsvised vendor drawings issued B00501-0908. P0TAPOVB, U. Region 4. Dallas, Vendor Inspection Branch. B0/10/21. ip. 07186:192.
- --8012080254 Responds to NRC 806903 ltr re deviation noted in GA Program Insp Rept 9990525/80-02. Corrective actions: change to project mgt manual incorporating commitment of 800427 ltr & electrical discipline drawings design verified.

 BARKER, N. R. 01lbert/Commonwealth Cos. 80/10/02. 8pp. 07186:193.
- --8017080260 Forwards QA Program Insp Rept 97700525/80-02 on 800721-25 & notice of deviation. POTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. 80/09/03. 2pp. 07186:201.
- --8012080265 Notice of deviation from insp on B00721-25.

 * Region 4. Dallas. Office of the Director. 80/08/27. 5pp.
 07186:203.
- --8010080268 QA Program Insp Rept 97900325/80-02 on 800821-25.

 Noncompliance noted:corrective actions to previous deviations not completed. Vendor drawings not identified w/ID numbers & issued w/o design verifications.

 FOX.D.F.: BREAUX.D.O., GAGE.L.W. Region 4, Dallas, Vendor Inspection Branch. 80/08/29. 24pp. 07186; 208.
- 8012080252 Forwards GA Program Insp Rept 99900396/80-01 on 800922-26. No noncompliance noted. POTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. B0/10/17. 2pp. 07187:066.
- --8012080256 CA Program Insp Rept 99900396/80-01 on 800922-26. No noncompliance noted Major areas inspected: initial mgt meeting & implementation of 100FR30, App B including afg process controls & audits.
 BROWN.R.L., WHITEBELL.D.E. Region 4, Dailas, Vendor Inspection Branch. 80/10/08. App. 07187:068.
- B012080263 Ack receipt of B01106 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900081/80-02. PDTAPGV8.U. Region 4. Dallas. Vendor Inspection Branch. 80/11/17. ip. 07189:279.
- --8017080267 Responds to NRC 801024 ltr re deviation noted in QA Program Insp Rept 90900081/80-02. Corrective actions caller of electron beam welders checked & log sys set Up to insure all aquipment will be entered on computer sys updating maint. VOLMER.C.J. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/11/06. 2pp. 07189:280.

- --8012080272 Forwards GA Program Insp Rept 59900081/80-02 on 801014-16 & notice of deviation. POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch. 80/10/24. 2pp. 07189:282.
- --8012080275 Notice of deviation from insp on 801014-16.

 * Region 4: Dallas: Office of the Director. 80/10/24. 1p. 07189:284.
- --8012080282 GA Program Insp Rept 99900081/80-02 on 801014-16.
 Noncompliance noted:two electron beam welders still in use
 were past calibr cycle.
 MCNETILLW M. WHITESELL.D.E. Region 4. Dallas. Vendor Inspection
 Branch. 80/10/24. 6pp. 07189:285.
- 8012080287 Ack receipt of 801028 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900710/80-02.
 POTAPOVS,U. Region 4, Dallas, Vendor Inspection Branch. 80/11/19. 1p. 07186: 239.
- --B012080291 Responds to NRC B01010 ltr re deviation noted in GA Program Insp Rept 99900710/B0-02. Corrective actions: sessions given to educate workers in use of ID tags & in review of drawings to assure inclusion of welder call-outs.

 JACKBON.R.W. National Valve & Mfg. Co. 80/10/28. 3pp. 07186:240.
- --8012080297 Forwards GA Program Insp Rept 99900710/80-02 on 800825-28 & notice of deviation. POTAPOVS.U. Region 4, Dallas, Vandor Inspection Branch. 80/10/10. 2pp. 07186:243.
- --8012080300 Natice of deviation from insp on 800825-28.

 * Region 4, Dallas: Office of the Director. 80/10/08. ip. 07186:245.
- --8012080307 QA Program Insp Rept 99700710/80-02 on 800823-28.
 Noncompliance noted:pallet lacked blue ID tag. Assembly drawing % QC data sheet did not include tack welding documentation provisions. NCM number not on QC sheet. ROBERDS.H.W., BARNES.I. Region 4, Dallas. Vendor Inspection Branch. 80/10/08. App. 07186:246.
- 8D12090048 Ack receipt of 800917 & 1024 ltrs informing NRC of steps taken to correct deviation noted in OA Program Insp Rept 99900086/80-01. POTAPOVS,U. Region 4, Dallas, Vendor Inspection Branch. B0/11/12. lp. 07199:217.
- --8012090051 Responds to NRC 801006 ltr re deviation noted in GA Program Insp Rept 99700086/80-01. Corrective actions: all gauges routed to dept to insure calibr accuracy & reinsp of castings made. HOLT.P.E. Hopkinsons, Ltd. 80/10/24. 3pp. 07199: 218.
- --8012070050 Ack receipt of 800917 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 97900085/80-01. Requests add1 info. PDTAPDVS.U. Region 4. Dallas. Vendor Inspection Branch. 80/10/04.
- --8012090054 Responds to NRC 800731 itr re deviation noted in QA Program Insp Rept 99900086/80-01. Corrective actions: cleaning operation added to operational chart & induction hardening procedure prepared.
 HDLT.P.E. Hopkinsons, Ltd. 80/09/17. App. 07199: 222.
- --8012090057 Procedure TDL O31: "Calibr of Hand Operated Torque Brenchee." 4 Hopkinsons Ltd. 80/06/26. Spp. 07199:228.
- --B012090059 Forwards QA Program insp Rept 99900086/80-01 & notice of deviation.
 POTAPOVS.U. Region 4. Dallas. Vendor Inspection Branch. 80/07/31.
 2pp. 07199:237.
- --8012090062 Nutice of deviation from insp on B00623-27.

 * Region 4: Dallas: Office of the Director. B0/07/29. 3pp. 07199:239.
- --B012070065 GA Program Insp Rept 9990086/80-01 on B00623-27.
 Noncompliance noted: mfg orders did not provide complete
 instructions: torque wrench not checked for accuracy &
 flange had inadequate radius.
 BARNEB, I., ELLERSHAW, L. E. Region 4: Dallas, Vendor Inspection
 Branch. B0/07/29, idpp. 07199:242.

10 H 44 C

- B012180594 Forwards QA Program Insp Rept 99900219/80-01 on B00929-1003. No noncompliance noted. POTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. 80/10/21. 2pp. 03790:245.
- --8012180599 QA Program Insp Rept 99900219/80-01 on 800929-1003.No noncompliance noted Major areas inspected: implementation of 100FR59, App B & applicable codes & stds. FOSTER.U.E., BARNES.I. Region 4, Dallas, Vendor Inspection Branch. 80/10/16. 9pp. 03790:247.
- 8012180602 Ack receipt of 801201 ltr informing NRC of steps taken to correct deviations noted in OA Program Insp Rept 99900100/80-02.
 POTAPOVS.U. Region 4. Dailas, Vendor Inspection Branch. 80/12/11. tp. 03790:256.
- --B012180607 Responds to NRC B01106 ltr re deviations noted in GA Program Insp Rept 99700100/80-02 Corrective actions:all variation repts will be reviewed by GC supervisor.

 GROCME.K. Limitorque Corp. B0/12/01. 2pp. 03770:257.
- --8012180612 Forwards GA Program Insp Rept 99900100/80-02 on 800930-1003 & notice of deviations, POTAPOVS, U. Region 4, Dallas, Vandor Inspection Branch. 80/11/06. 2pp. 03790:259.
- --8012180615 Notice of deviations from insp on 800930-1003. * Region 4. Dallas, Vendor Inspection Branch. 80/11/05. 2pp. 03790:261.
- --B012180621 QA Program insp Rept 99900100/B0-02 on B00930-1003.

 Noncompliance noted: failed to include mfg supervisor signature on variation repts originated in machine shop. OLLER.R.E. DARNES.I. Region 4. Dallas, Vendor Inspection Branch. B0/11/05. 9pp. 03790.263.
- 8012180623 Forwards QA Program Insp Rept 99900404/80-04 on 800708-12. No noncompliance noted. POTAPOVS-U. Region 4. Dalias, Vendor Inspection Branch. 80/09/26. 2pp. 03790: 272.
- --B012180629 GA Program Insp Rept 99700404/80-04 on 800708-12.No noncompliance noted Major areas inspected:10CFR21 & iDCFR30, App 8 in areas of design insp.
 BRICKLEY.R.H., BENNETT.A.B., AGEE.J.R. Region 4, Dallas. Vendor Inspection Branch. B0/09/25. (ipp. 03790:274.
- 8012180637 Forwards GA Program Insp Rept 99700054/80-02 on 800724. No noncompliance noted. POTAPOVS.V. Region 4. Dallas. Vendor Inspection Branch. 80/09/23. 2pp. 03790: 285.
- --8012180644 GA Program Insp Rept 97900054/80-02 on 800724.No noncompliance nuted.Kajor areas inspected:implementation of 100FR30.App B & 100FR21 & applicable codes & stds. KELLEY.N.D., WHITESELL.D.E. Region 4, Dallas, Vendor Inspection Branch, 80/09/23. Spp. 03790:287.
- 8012190008 Ack receipt of 801121 Itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900293/80-01. PDTAPOVS-U. Region 4. Dallas. Vendor Inspection Branch. 80/12/03. ip. 97278:183.
- --B012190012 Responds to NRC B01030 ltr re deviation noted in GA Program
 Insp Rept 99900293/B0-01. Corrective action::IOCFR21
 compliance revised on div level.Previous procedure replaced
 in entiraty.
 ALLIN.R.V. Oulf & Western Industries. Inc. B0/11/21. 3pp.
 07278: 184.
- --B012170016 Forwards OA Program Insp Rept 99900293/80-01 on 800930-1003. No noncompliance noted. POTAPOVS,U. Region 4, Dallas, Vendor Inspection Branch. 80/10/30. 22p. 07278:187.
- --8012170021 GA Program Insp Rept 97900293/80-01 on 800930-1003.No noncompliance noted Clarification of audit schedule requirements needed to clarify discrepancy between Sections 1.1.2 & 13.4.a of QA menual, SUTTON J.W. (WHITESELL, D. E. Region 4, Dallas, Vendor Inspection Branch, 80/10/28, 6pp. 07278:189.
- 8012190050 Ack receipt of 801126 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99900521/80-03.
 POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch. 80/12/09, ip. 07279:010.

- ~-8012190060 Responds to NRC 801020 ltr re deviations noted in QA Program Insp Rept 99900521/80-03. Corrective actions: matis & quality svc dept & project engineering reviewed Form 84 & made necessary corrections per Drawing Change Notice 52. MORDMSWI.J. V. Bechtel Power Corp. (subs. of Bechtel Corp.). 80/11/26. 6pp. 07279:011.
- ---B012190068 Forwards GA Program Insp Rept 99900521/80-03 on 800922-25 & motice of deviation.
 POTAPORS, U. Region 4, Dallas, Vendor Inspection Branch. 80/10/20, 28p. 07279.017.
- --8012190074 Notice of deviation from insp on 800922-25.

 * Region 4, Dallas, Vendor Inspection Branch. 80/10/17. 2pp. 07279:019.
- --B012190080 QA Program Insp Rept 97900321/80-03 on 800922-25.

 Noncompliance noted: failure to check drawing for compliance usapplicable codes & stds required by procedures.

 GRICKLEY, R. H., ADEE, J. R., HALE, C. J. Region 4. Dallas, Vendor Inspection Branch. 80/10/17. 11pp. 07279:021.
- 8012190085 Ack receipt of 801121 ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99900047/80-02.
 PUTAPOVB.U. Region 4. Dallas, Vendor Inspection Branch. 80/12/03. 1p. 07279:096.
- --8012190093 Responds to NRC 801010 ltr re deviations noted in QA Program Insp Rept 99900047/80-02. Corrective actions: complete evaluation of all records re automatic submerged arc welding process performed.

 MILLER.T. D. Westinghouse Electric Corp. 80/11/21. 6pp. 07279:097.
- --8012170078 Forwards QA Program Insp Rept 97900047/80-02 on 800708-12 & notice of deviation.
 SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/10/10. 2pp. 07279:103.
- --8012170101 Notice of deviation from insp on 800708-12.

 ** Region 4. Dallas, Vendor Inspection Branch. 80/10/07. 2pp. 07279; 105.
- --B012170104 QA Program Insp Rept 99700047/80-02 on 800708-12.

 Noncompliance noted: failure to maintain sagregation & identity of welding math in holding ovens.

 ELLERGHAW-L. E., RODERDS,H. W., BARNES, I., Region 4, Dallas, Vendor Inspection Branch. 80/10/07. 11pp. 07277:107.
- 8012190095 Notes decision not to submit application for withholding of info from public disclosure. POTAPOVB.U. Region 4: Dalias, Vendor Inspection Branch. 80/12/11. ip. 07279:120.
- --8012170154 Informs that QA Program Insp Rept 79700271/80-01 affidavit will not be prepared because of current priorities & effort required. Rept errors should be corrected prior to placement in PDR.
 KUCH-W.H. Rosemount, Inc. 80/11/24. 1p. 07279:121.
- --8012190160 Informs that application must be submitted for withholding of info in GA Program Insp Rept 99900271/80-01. POTAPOVS, U. Region 4. Dellas, Vendor Inspection Branch. 80/10/24. 1p. 07279:122.
- --8012190186 Requests QA Program Insp Rept 99900271/80-01 on 800721-25 be withheld from public disclosure due to proprietary nature of info.
 KUCH-N-H. Rosemount, Inc. 80/10/10. 1p. 07279:123.
- --8012190194 Forwards QA Program Insp Rept 99900271/80-01 on 800721-25. No noncompliance noted. POTAPDV8.U. Region 4. Dallas, Vendor Inspection Branch. 80/09/10. 2pp. 07279:124.
- --8012170200 CA Program Insp Rept 99700271/80-01 on 800721-25. No noncompliance noted. Major areas inspected: environ & seismic qualifications of Model 1153A pressure transmitters & procurement documents.

 ELLERGHAW, L. E., BARNES, I. Region 4: Dallas, Vendor Inspection Branch. 80/09/05. 18pp. 07279:126
- B012190289 Ack receipt of B01111 ltr clarifying comments re QA Program Insp Rept 9990018280-01. PDTAPDVB.U. Region 4, Dallas, Vendor Inspection Branch. B0/11/26. lp. 07286:041.

- -- 8012190296 Responds to NRC 801030 itr re GA Program Insp Rept 99900118/80-01. Clarifies rept items re intent to cease mfg operations at plant facility & decision not to subcontract mfg of N stamp valves. SHIELDS.S. Walworth Co. (subs. of IU International Corp.), 80/11/11. 1p. 07286:042.
- --8012190302 Forwards GA Program Insp Rept 99900118/80-01 on 801008-09. No noncompliance noted. POTAPDV8,U. Region 4, Dallas, Vendor Inspection Branch. 80/10/30. 1p. 07886:043.
- --B012i9O3i2 OA Program insp Rept 99900118/80-01 on B01008-09. No noncompliance noted, Major area inspected: implementation of 10CFRSD. App B & applicable codes & stds & verification GA records will be protected after plant closure.

 KELLEY, W. D. , WHYTESELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 80/10/28. 7pp. 07286:045.
- B012190433 Forwards GA Program Insp Rept 99900262/80-01 on B00803-06 & notice of deviation.
 PDTAPBUS-U. Region 4. Dallas, Vendor Inspection Branch. 80/09/04.
 Zpp. 07286;262.
- --B012170437 Natice of deviation from insp on B00805-06.

 * Region 4, Dallas, Vendor Inspection Branch. B0/09/02. ip.
 07286:264.
- --B012170446 CA Program Insp Rept 99900262/80-01 on B00805-06.
 Noncompliance noted:revised procedures not being processed as required by App B to 10CFR50 prior to release & implementation.
 KELLEY, W. D., WHITESELL, D. E. Region 4, Dailas, Vendor Inspection Branch, 80/09/02, 9pp. 07284:265.
- 8012190438 Ack receipt of 801121 ltr informing NRC of steps taken to correct deviations noted in QA Program lnsp Rept 99900507/80-02. POTAPOVS.U. Region 4: Dallas: Vendor Inspection Branch. 80/12/09. 1p. 07286:274.
- --8012190442 Responds to NRC 801017 ltr re deviations noted in QA Program Insp Rept 99700507/80-02. Corrective action: revised project drawling list to show current Revision F of Btructural Drawing 830-1418.
 KGFARLAND.J.E. Bargent & Lundy, Inc. 80/11/21. 2pp. 07286:275.
- --B012170445 Forwards GA Program Insp Rept 99900507/80-02 on B00915-19 k notice of deviation.
 PCTAPQVB.U. Region 4. Dallas. Vendor Inspection Branch. 80/10/17.
 2pp. 07286:277.
- --B012190449 Notice of deviation from insp on 800915-19.

 * Region 4. Dallas, Vendor Inspection Branch. 80/10/08. ip. 07286:279.
- --8012190434 GATProgram Insp Rept 97900507/80-02 on 800915-19.

 Noncompliance noted:project drawing list not updated to show current revision of structural drawing.

 COSTELLOJ.R. N. JUNNEON, J. M., HALE. C. J. Region 4, Dailas, Vendor Inspection Branch, 80/10/08, 10pp. 07286:280,
- B012190453 Ack receipt of 800912 & 1105 ltrs informing NRC of steps taken to correct deviations noted in OA Program Insp Rept 94900400/80-02.
 PDTAPGVS,U. Region 4, Dalles, Vendor Inspection Branch. 80/11/26.
 1p. 07286:290.
- --8012190470 Responds to 801021 ltr requesting addl info re responses to QA Program Insp Rept 99900400/80-02. Discusses measures to assure that variations from equipment design requirements receive equivalent level of review as original design.

 GUILBERTID. E. Babcock & Wilcox Co. 80/11/06. 3pp. 07286:291.
- --8012190476 Ack receipt of 800912 ltr & requests addl info re measures to assure that variations from equipment design requirements receive equivalent level of review as original. POTAPOVS.U. Region 4. Dallas. Vendor Inspection Branch. 80/10/21. 1p. 07286:294.
- --B0121904B9 Responds to NRC B00B1B ltr re deviations noted in QA Program Insp Rept 99900400/B0-02. Corrective actions: initiated tracking & followup sys to assure most commitments for resolution of notices of deviations performed.

 GUILRERT, D. E. Babcock & Wilcox Co. 80/09/12. Bpp. 07286:295.
- --8012190496 Forwards GA Program Insp Rept 99900400/80-02 on 800707-11 & notice of deviation. POTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. 80/08/15. 2pp. 07286:303.

- --8012190515 Notice of deviation from Insp on 800707-11.

 * Region 4. Dallas, Vendor Inspection Branch. 80/08/13. 4pp. 07286:305.
- --B012190522 GA Program Insp Rept 99900400/B0-02 on B00707-ii.
 Noncompliance noted:contract variation approval requests not categorized reviewed or approved in accordance M/procedures.
 FOX.D.F., BREAUX.D G., HALE.C.J. Region 4, Dallas, Vendor Inspection Branch. 80/08/13. 15pp. 07286:309.
- 8012190551 Forwards QA Program Insp Rept 99700345/80-02 on 801014-16. No noncompliance noted. POTAPOVS.U. Region 4. Dallas. Vendor Inspection Branch. 60/10/30. 2pp. 07288:189.
- --8012190552 GA Program Insp Rept 99900345/80-02 on 801014-16. No noncompliance noted Major areas inspected: implementation of 10CFR50, including procurement control & training. BROWN, R. L., WHITESELL, D. E. Region 4. Dallas, Vendor Inspection Branch. 80/10/29. 7pp. 07289:191.
- 8012220081 Ack receipt of B01117 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900509780-03.
 POTAPOYS,U. Region 4, Dallas, Vendor Inspection Branch. 80/12/11. ip. 07307:029.
- --8012220086 Responds to NRC 801030 ltr re deviation noted in GA Program
 Insp rept 99700309/80-03.No problems exist w/flued head
 penetrations at North Anna 3 & 4.Requests deletion of
 facility name from rept.
 KELLY.R.B. Stone & Nebster Engineering Corp. 801534/JMK/BAR.
 80/11/17. 1p. 07307:030.
- --B012220090 Forwards QA Program Insp Rept 99700509/80-05 on 800923-1003 & notice of deviation.
 POTAPOVS.U. Region 4. Delias. Vendor Inspection Branch. 80/10/30. 2pp. 07307:031.
- --8012220074 Notice of deviation from insp on 800727-1003. * Region 4, Dallas, Office of the Director. 80/10/30. | Zpp. 07307: 023
- --8012220078 QA Program Insp Rept 99900509/80-05 on 800929-1003.
 Noncompliance noted:specs for nonengineered items not approved by constr or QA & pipe stress analysis summary did not have independent revisuer signature block.
 CDSTELLO,J.R., JOHNSON,J.H., HALE,C.J. Region 4, Dallas, Vandor Inspection Branch. 80/10/30. 12pp. 07307:035.
- 8012230169 Ack receipt of 801029 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99700404/80-03.
 PDTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. 80/12/03. bp. 07317:007.
- --B012230174 Responds to NRC B00925 ltr re deviation noted in GA Program Insp Rept 99900404/B0-03 Corrective actions:revised MRD-OPR-19. O to reflect current practices & changes resulting from insp. ANDERSON T. M. Westinghouse Electric Corp. NB-TMA-2390. 80/10/29. 2pp. 07317:008.
- --B012230178 Forwards QA Program Insp Rept 99900404/80-03 on B00812-15. POTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. B0/09/25, 2pp. 07317:010.
- --8012230183 GA Program Insp Rept 99900404/80-03 on 800812-15.
 Noncompliance noted:implementation of 10CFR21 requirements,
 particularly data varification.
 AMDERSON, D. O., HALE, C. J. Region 4, Dallas, Vendor Inspection
 Branch. 60/09/22, 4pp. 07317:012.
- 8012230234 Ack receipt of 800705 % 1004 ltrs informing NRC of steps taken to correct deviation noted in OA Program Insp Rept 97900037/80-01.
 POTAPOVB.U. Region 4. Dallas, Vendor Inspection Branch. 80/11/14.
 1p. 07317:272.
- --8012230239 Responds to NRC 800922 ltr re deviation noted in GA Program Insp Rept 99900039/80-01. Lists findings on survey of Thyssen Drackt 79-0-06. SLUIS, B.J.A. Rhins-Schelds-Veroime Zware Apparatenbouw. DIR/021. 80/10/06. 2pp. 07317:273.
- --8012230242 Act receipt of 800905 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900039/80-01.Requests add1 info. PDTAPDUBLU. Region 4. Dallas. Vendor Inspection Branch. 80/09/22. 2pg. 07317:275.

- --8012230246 Responds to NRC 800729 ltr re deviation noted in QA Program Inap Rept 99900039/80-01. Corrective actions: internal audits conducted & welding wire matl tested. Nonconformance repts & QA procedure encl.
 SLUIS.B.J.A., LODDER.M. Rhine-Schelde-Verolme Zware Apparatenbouw. DIR/019. 80/09/05. 18pp. 07317:276.
- --8012230248 Forwards GA Program Insp Rept 99900039/80-01 on 800616-20 & notice of deviation. SEYFRITI.K.V. Region 4. Dallas, Vendor Inspection Branch. 80/07/29. 2pp. 07317:294.
- --8012230249 Notice of deviation from insp on 800616-20. * Region 4. Dallas, Vendor Inspection Branch. 80/07/28. 3pp. 0/317:296.
- --B012230295 GA Program Insp Rept 99900039/80-01 on 800516-20.

 Noncompliance noted approval of vendor w/o followup actions required & failure to issue heat treatment nonconformity repts.

 BARNES, I., ELLERSHAW, L. E. Region 4, Dallas, Vendor Inspection Branch. 80/07/28. 13pp. 07317:279.
- 8012290486 Ack receipt of 801120 ltr informing NRC of steps taken to correct deviation noted in QA Program Into Rept 97900400/80-02. POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch. 80/12/09. ip. 07335:134.
- --8012270492 Responds to NRC 800912 ltr re deviation noted in GA Program Insp Rept 99900400/80-02 Corrective actions: Phase 1 of NPGD historical document hist review will be completed by 810303. GUILBERT, D. E. Babcock & Wilcox Co. 80/11/20. ip. 07335:135.
- 8012300005 Ack receipt of 801113 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9900036/80-02.
 PGTAPOVS.U. Region 4. Dallas. Vendor Inspection Branch. 80/12/02. ip. 07356:085.
- --8012300009 Responds to NRC 801017 ltr re deviations noted in GA Program Insp Rept 9990036/80-02. Corrective actions: reinstructed personnel that crange quality status tags should be attached & retained on shop traveler.

 BATES. B. J., MILLER. L. C. STONE, W. A. Combustion Engineering, Inc. 80/11/13. 3pp. 07356:086.
- --B0123C0016 Forwards GA Program Insp Rept 99900036/80-02 on 800922-26 & notice of deviation POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. B0/10/17, 2pp. 07356:089.
- --8012330018 Natice of deviation from insp on 800972-26.

 # Region 4, Dallas, Vendor Inspection Branch. 80/10/14. ip. 07356:091.
- --B012300026 OA Frogram insp Rept 99900036/80-02 on 800922-26.
 Noncompliance noted: status quality tags not attached to appropriate traveler as required by 10CFR30.
 ROBEROS,M.W., BARNEST. Region 4, Dallas, Vendor Inspection Branch. 80/10/14. 6pp. 07356:092.

REGOD REGULATORY GUIDES

- 8011210740 Forwards notice of withdrawal of Reg Guide 1.101:Revision 1. "Emergency Planning for Nuclear Power Plants." CHILK-8. J. Office of the Secretary of the Commission. 80/10/16. ip. 07029:131.
- --8011060238 Notice of withdrawel of Reg Guide 1, 101, Revision 1,
 "Emergency Planning for Nuclear Power Plants."
 MINOOUE, R. B. Office of Standards Development, Director. 80/10/06.
 3pp. 03708;193.
- --8011060236 Forwards FR notice for publication.
 MINOCUE, R. B. Office of Standards Development, Director. 80/10/08.
 1p. 03708:192.
- 8011280106 Transcript of 801121 Affirmation Session 80-51 in Washington, DC to discussion & vote on SECY 80-457, Pp 1-31, a Commissioners, 80/11/21; Sipp. 07082:043.
- --Boli280i12 BECY-80-476
 Informs that NRC has concluded & recommended that revisions should be made to 10CFR73 amend & to draft Reg Quide BC 901-AiForwards revised amends & submits guide changes. MIWOGUE.R.B. Office of Btandards Development, Director. BO/10/20. 68pp. 07082:091.

- 8012020264 Forwards Revision 2 to BAN-10082. "Environ Qualification of Class IE Control & Instrumentation Equipment." TAYLOR, J. H. Babcock & Wilcox Co. 80/11/20, 2pp. 07132: 342.
- --8012020268 Revision 2 to "Environ Qualification of Class IE Control & Instrumentation Equipment."
 BURBITIN, N. N., LESNIKA, L. M., LLOYD, A. B. Babcock & Wilcox Co.
 BAU-10082 R2. 80/10/31. 130pp. 07132:344.
- 8012030840 Forwards comments on proposed Revision 3 to Reg Quide 1.35, "Inservice Insps of Ung.outed Tendons in Prestressed Concrete Containments," & Reg Quide 1.35.1. FULTON, J. F. Oilbert/Commenwealth Cos. 80/10/31. 13pp. 07149:076.
- BO12040650 Commends NRC for assembling Reg Quide 1.97 discussed at BO0806 meeting in Washington.DC. Coverage of parameters to be monitored is too comprehensive. Requests specific attention to primary coolant inventory.

 ZUDANS, Z Franklin Institute/Franklin Research Center. 80/09/23.

 Zpp. 07165:359.
- 8012050053 BECY-80-507
 Seeks Commission approval of encl draft FR notice endorsing deferment of mandatory acceptance of nuclear plant reliability data sys & development of integrated operational experience reporting sys.Recommends approval.
 DIRCKS.M.J. Office of the Executive Director for Operations. 80/11/14. 60pp. 07173:116.
- --B011130046 Forwards input re IE needs for upgraded NPRDB & LER sys.Rsg Ouide I, 16 does not provide requirements for reporting model & serial numbers & mods for failed components.Quidelines need to address AO repts as LER subsets, JORDAN, E. L. Division of Reactor Operations Inspections. 80/08/28, 2pp. 03731:117.
- 8012080170 Comments on proposed Revision 1 to Reg Ouide 1, 23.
 Differences between primary & other towers should be addressed, tower instrumentation requirements should also be addressed.
 BAYNE, J.P. Power Authority of the Btate of New York. 80/11/17. ip. 07194:307.
- 80i2080177 Comments on proposed Revision 1 to Reg Guide 1.23. FAY.C.W. Wisconsin Electric Power Co. 80/11/14. 2pp. 07194:305.
- B0120B0184 Comments on proposed Revision 1 to Reg Guide 1.23. Requirement for add1 mechanism for transmitting same meteorological info unwarranted. DALE-L.F. Mississippi Power & Light Co. AECM-80/2B8. 80/11/20. 2pp. 07194:303.
- 8012080190 Comments on proposed Revision 1 to Reg Quide 1.23. KEMPER, J. S. Philadelphia Electric Co. 80/11/18, 1p. 07194:301.
- 8012080208 Comments on proposed Revision 1 to Reg Guide 1.23. Ouide should define coastal sites. Definition of adequate display is not given LAWHN. R. W. Bay Point Power & Light Co. 8T-HL~AE~578. 80/11/20. 2pp. 07194:299.
- 8012080223 Comments on proposed Revision 1 to Reg Ouide 1.23.Monitoring schemes other than those in guide would be more appropriate. SALDARINI.J.C. Ebasco Services, Inc. (subs. of Enserch Corp.), 80/11/20. App. 07194:272.
- 8012080245 Comments on proposed Revision 1 to Reg Ouide 1.23. Comments directed at Section 7 requirements re meteorological monitoring sys. Other means to collect meteorologic info available.

 YENDALL:R.F. Affiliation Unknown. 80/11/18. 2pp. 07194:192.
- 8012080261 Comments on proposed Revision 1 to Reg Ouide 1.23. Allowance should be made for digital wind speed & direction on both channels if sample rate is high enough to give effectively continuous chart recording.
 PUC
- 9012080269 Forwards comments on proposed Revision 1 to Reg Guide 1.23. Ravision lacks guidance re availability of offsite meteorological data.
 TIPTOM.T.E. General Public Utilities QPU Service Corp. E&L-2958, 80/11/19. 3pp. 07194:224.
- 8012080280 Comments on proposed Revision 1 to Reg Quide 1,23 remeterological programs in support nuclear plants, Quide needs to be modfied & elaborated on in certain areas.

 BRENNAN,P,T., BHITH,M.E. Meteorological Evaluation Bervices, Inc. 80/09/30. 10pp. 07194:210.

- BO12080276 Comments on proposed Revision 1 to Reg Guide 1.23 Appears to be no apparent application for ambient moisture into at plants which do not use closed cycle cooling sys. MODDY, J. H. Yankee Atomic Electric Co. WYC-80-35. BO/11/13. 2pp. 07194:203.
- 8012080380 Comments on proposed Revision 1 to Reg Guide 1.23.Many positions are not justifiable for either routine operations or accident conditions. Revision should be re-evaluated w/consideration given to other safety requirements. HIGGINBOTHAM.L. Office of Inspection & Enforcement, Office of the Director. 80/11/14. 2pp. 07196:195.
- B0120B0401 Comments by RI Dept of Health on revision to Reg Quide 10.8. Info in Item D. 4 re plotting data obtained during linearity checks of dose calibrators is incorrect.Correct procedure is to use semi-log paper.

 DNNOULIS.H.P. Rhode Island, State of. B0/10/31. 1p. 07176:189.
- 8012080502 Comments on proposed Revision 1 to Reg Guide 5.7. Concerns exist re correct sequence for protected area entry searches.

 BRADBURY R. B. Stone & Webster Engineering Corp. 80/11/18. 2pp. 07194:342.
- BO120B0697 Comments on second proposed Revision 2 to Reg Guide 1.8, "Personnel Gualification & Training."
 MODDY, J. H. Yankee Atomic Electric Co. NYC 80-36, 80/11/17, 2pp. 07176:127.
- B0120B0704 Comments on draft reg guide fp 716-4 re value/impart statement format. Suggests addl guidance documents worthy of ref in Bection 34.2.2 on ventilation requirements. FIGH. J. E. American Air Filter Co. 80/11/17.
- 8012080724 Comments on draft reg guide FP 818-4 re std format & content of license applications. No consideration given, in info required, for environ rept. to federal land which may be used or located near in situ extraction solution site.

 * Interior. Dept. of, Bureau of Land Management. 3500(530). 80/11/19. 5pp. 07196:147.
- 8012080731 Comments on proposed Revision 3 to Reg Guide 1.33 re QA program requirements. Some wording in Paragraph C.13 should be delated.

 BRADBRY.R.B. Btone & Webster Engineering Corp. 80/11/14. ip. Q7196:156.
- 8012110643 Partial response to FOIA request for documents re imposition of civil penalties, NRC requests for congressional authorization for more severe penalties & responsibilities & behavior of nuclear plant operators. Forwards documents. FELTON, J. H. Division of Rules and Records, 80/11/20. 2pp. 07227:209.
- --B012110770 Forwards proposed Reg Ouide 1, xyz, "Factors to be Considered Before Allowing Licensed Personnel to Manipulate or Direct Manipulation of Controls of Nuclear Power Plant." Requests comments on listed questions. FARMER.W.B. Research Support Branch (Pre 801119). 78/01/06. 4pp.
- --B012110678 Provides background info on proposed Revision 1 to Reg Guide 1.114: "Guidance on Being Operator at Controls of Nuclear Power Plant." Includes comment resolution & implementation schedule. ARLOTTO.O.A. Office of Standards Development, Director. 76/10/07. 2pp.
- --B012110782 Draft of Revision 1 to Reg Ouide 1.114, "Ouidance on Being Operator at Controls of Nuclear Power Plant."

 # Office of Standards Development, Director, 76/09/15, 2pp.
- --B012110787 Comments on Reg Guide 1, 114. "Guidance on Being Operator at Controls of Nuclear Power Plant." Section C. 1 should be modified to remove implication that changing conditions always requires corrective action on part of operator. CAHILL, H. J. Consolidated Edison Co. of New York. 76/04/16. 1p.
- --B012110772 Comments on Reg Guide 1.114. "Guidance on Being Operator at Controls of Nuclear Power Plant." Strict interpretations of provisions in Section BrParagraph 2 could practice nuclear plant operator from purforming data logging & review tasks. JOHNSON N. P. Yankee Atomic Electric Co. 76/04/01. ip.
- --8012110800 Comments on Reg Quide 1,114, "Quidance on Being Operator at Controls of Nuclear Power Plant," Quide can be improved by more strongly emphasizing importance of sound design for controls used during normal operating stuations.

 BCHERER, A. E. C-E Power Systems. LD-76-044, 76/04/20, 2pp.

- --80(21)0806 Comments on Reg Guide 1.114, "Guidance on Deing Operator at Controls of Nuclear Power Plant." Paragraph C. 4 should differentiate between temporary relief & formal relief as conducted during shift change.

 UHRIO.R.E Florida Power & Light Co. L-76-154. 76/04/08. 1p.
- --B012110B10 Comments, submitted by Nuclear Engineering Bvc Co, on proposed Reg Guide 1.114, "Guidance on Being Operator at Controls of Nuclear Power Plant." More stringent enforcement should be implemented. Resolution of public comments encl. YOUNOS, R. A. Affiliation Unknown. 021-6-41. 76/03/03. 5pp.
- --8012110B18 Value/impact assessment of proposed Revision 1 to Reg Guide 1.114. "Guide to Being Operator of Controls of Nuclear Power Plant: Reg guide is consistent w/SRP.Bection i3.1.2. 4 Office of Standards Development, Director. 76/10/07. 1g.
- --8012110Bl6 Forwards Reg Guide 1.114, Revision 1, "Guidance on Being Operator at Controls of Nuclear Power Plant," FR notice & draft NRC public announcement, Guide was revised as result of public comment & addl staff review.
 MINOGUE, R. B. Office of Standards Development, Director. 76/11/23.
- --B012110B22 Reg Quide 1.114,Revision 1, "Quidance on Being Operator at Controls of Nuclear Power Plant." # Office of Standards Development, Director. 76/11/30. 2pp.
- --B012110B43 Notice of issuance & availability of Reg Guide 1.114, Revision 1, "Ouidance on Being Operator at Controls of Nuclear Power Plant." Draft NRC public announcement encl. MINGOUE,R.B. Office of Standards Development, Director. 76/11/23.
- --B012110B46 Reg Ouide 1.114. "Ouidance on Being Operator at Controls of Nuclear Power Plant." Related FR notice encl.

 # Office of Standards Development, Director. 76/02/29. App.
- --8012110848 Working Paper F on proposed Reg Guide 1.XX, "Guidance on Being Operator at Controls of Nuclear Power Plant." # Office of Standards Development, Director. 75/10/10. 5pp.
- ~-8012110849 Working Paper E on proposed Reg Guide 1.XX, "Guidance on Being Operator at Controls of Nuclear Power Plant." ← Office of Standards Development, Director. 75/08/29, 5pp.
- --8012110683 Forwards Horking Paper D on proposed Reg Quide 1.XX.

 "Oudiance on Being Operator at Controls of Nuclear Power
 Plant." Regulatory position should be followed & applied by
 all current & future licensees.

 MINDOUS.R.B. Office of Standards Development, Director. 75/08/12.
- --8012110851 Working Paper D on proposed Reg Quide 1.XX, "Quidance on Baing Operator at Controls of Nuclear Power Plant." Three draft working papers encl.

 * Office of Standards Development, Director. 75/07/16. 18pp.
- --8012110853 Working Paper C on proposed Reg Ouise 1.XX, "Ouisence on Being Operator at Controls of Nuclear Power Plant." Two draft working papers encl. * Office of Standards Development, Director. 75/05/19. 14pp.
- --Boizi10692 Forwards Working Paper B on proposed Reg Ouide 1.XX,
 "Ouidance on Being Operator at Controls of Nuclear Power
 Plant."
 MINDOUE, R. B. Office of Standards Development, Director, 75/04/14.
- --B012110854 Working Paper B on proposed Reg Quide 1, XX, "Quidence on Heing Operator at Controls of Nuclear Power Plant." Three draft working papers encl. # Office of Standards Development, Director. 75/04/10. 20pp.
- --H012110717 Comments on proposed reg guide & RG bulletin, "Hanning of Controls at Reactor Facilities." Definition of "present at controls" should be publicized via reg guide Requests clarification re necessity of RO. CASE.E.G. Atomic Energy Commission. 75/01/06. 1p.

- B012120280 Comments on proposed Revision 1 to Reg Guide 1.23 re meteorological programs in support of nuclear power plants. Comments in German. TAMER Germany, Federal Republic of. B0/11/20. 11pp. 07231:325.
- 8012160561 Forwards review of draft Reg Owide B. 14. Revision 2, "Personnel Neutron Dosimeters," in response to 801007 memo. Calculational methods for dosimetry are unacceptable alternatives.

 SCHROEDER: Assistant Director for Generic Projects. 80/12/0i.
 13pp. 07261:212.
- 8012170040 Comments on draft Reg Guide OH 710-4, "Health Physics Survays in U Hills." HAZLE.A. J. Colorado. State of. 80/11/07. 3pp. 07266:157.
- 8012170240 Forwards comments summary on proposed revision of Reg Quide 1.23. Section C. 4 instrument criteria is improved. Licensee clearinghouses for meteorological info should be considered carefully.

 RAMSDELL, J. V. Battelle Memorial Institute, Pacific Northwest Laboratory. 80/11/19. 5pp. 07266; 175.
- 8012170244 Forwards comments on Draft 3 of Revision 2 to Reg Ouide 1.97 to LNR instrumentation to assess plant & environ conditions before & after accident bocument is confusing, RENRERGER, D. L. Washington Public Power Supply System, ELE-KAH-80-055. 80/11/07. 2pp. 07266:173.
- 9012170252 Comments on second proposed Revision 2 to Reg Ouide 1.8 reparsonnel qualification & proposed training Supports revision. Minor change should be required for items that conflict b/revision. Affiliation Unknown. 80/11/26. 3pp. 07266:166.
- 8012170259 Comments by Empresas Nucleares Brasileiras on proposed Revision i to Reg Guide 1.23 re meteorological programs in support of nuclear power plants Requests additinfo re wind speed criteria.

 DE ALMEIDA, G. L. Affiliation Unknown. DEER. RP. E. 045/B. 80/11/17. 2pp. 07266:164.
- 80f2180075 Comments on Draft 3 of Revision 2 to Reg Ouide 1.97 re LUR instrumentation to assess plant & environ conditions before & after accident. Supports revision.
 OET[LER.F. M. Oibbs & Hill, Inc. (subs. of Dravo Corp.). 80/10/31.
 3pp. 07272: 288.
- 9012240284 Forwards comments on proposed Revision 1 to Reg Quide 1.23 re meteorological programs in support of nuclear power plants.
 LODMIB. J. S. Sargent & Lundy. Inc. 80/11/24. 2pp. 07328:208.
- 8012290755 Forwards draft Reg Quide RB 110-5, "Nuclear Power Plant Simulators for Use in Operator Training," draft value/impact statement & draft ANS 3.5. "Nuclear Power Plant Simulators for Use in Operator Training."

 ARLOTTO, O.A. Division of Engineering Standards. 80/12/12. ip.
- ---8012270259 Draft Reg Ouife RB 110-5. "Nuclear Power Plant Simulators for Use in Operator Training." MERBCHOFF, E. W. Reactor Systems Standards Branch. 80/10/01. 6pp.
- --8012290265 Value/impact statement re draft Reg Oulde R8 110-5, "Nuclear Power Plant Simulators for Use in Operator Training." Reg guide has been prepared endorsing ANB 3.5, * Reactor Systems Standards Branch. 80/10/31. App. 07337:015.
- --8012270269 Revised "Nuclear Power Plant Simulators for Use in Operator Training." Apps A & B & discussion of public comments on draft reg guide encl.

 4 American Nuclear Society. 80/03/24. 38pp. Available at Standards-Setting Organizations. 07397:021.
- --8012270276 Forwards comments on draft Reg Quide RB 110-5, "Nuclear Power Plant Bimulators for Use in Operator Training." Quide is wall written & will enhance training of nuclear gower plant operators.

 CRAWFORD, Q. D. Binger, Aerospace & Marine Bystems, Kearfott Div., 80/09/11. 3pp. 07337:046.
- --8012270282 Commants, submitted by Power Technologies, Inc. on draft Reg Ouide RS [10-5]. "Nuclear Power Plant Simulators for Use in Operator Training." Any reg guide must recognize limitations Affiliation Unknown. 80/09/12. 12pp. 07337:049.

- 8012300155 Draft summary of public comments & resolution re draft Reg Quide SC 705-4. "Ultrasonic Testing of Reactor Vessel Helds During Preservice & Inservice Examination." Marked-up draft reg guide-unofficial comments & public comments encl. # Commissioners. 80/11/14. 282pp. 07347:068.
- RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS
- 8012010043 "Trip Rept for Univ of MI Meeting on 800822-25;NRC-04-77-145;" Itr rept. HAMLIN.D.R. Southwest Research Institute. NRC-04-77-145, 80/09/09. 6pp. 07092:106.
- 8012010045 "Review of Ltr from DN Keefer, EG&O, to DP Manley, US DDE, NRC-04-77-145;" ltr rept. JACKSON, J. L. Southwest Research Institute. NRC-04-77-145. 80/09/11. 5pp. 07092:112
- 8012010046 "Southwest Research Inst Project Organization for NRC-04-77-145." Itr rept.
 HAMLIN D.R. Sauthwest Research Institute. NRC-04-77-145. 80/10/07. 4pp. 07092.117.
- 8012010090 "Status Rept on NRC-04-77-145, Activities for Aug 1980." JACK80N.J.L. Southwest Research Institute, NRC-04-77-145. 80/09/09. 6pp. 07092:121.
- 8012020224 Submits Progress Rept 33 to NRC-01-77-180 for Oct 1980. PLATO,P. Michigan, Univ. of. 80/11/10. 4pp. 07133:132.
- 8012040383 "Monthly Status Rept 2 on NRC-04-77-145 Activities for Sept 1980." HAMLIN, D.R. Southwest Research Institute. NRC-04-77-145. 80/10/08. 7pp. 07163:294.
- 8012040396 "Monthly Status Rept 3 on NRC-04-77-145 Activities for Oct 1980."
 HAMLIN D.R. Southwest Research Institute. NRC-04-77-145. 80/ Southwest Research Institute. NRC-04-77-145, 80/11/07. 07163:301
- 8012040583 "Bummary of PWR Loss of Offsite Power Calculations." preliminary assessment rept. FLETCH:R.C.D. EQ&O Idaho Inc. FIN A-604BC EQQ-CAAP-52B3. BQ/11/30. 107pp. 07167:142.
- B012040591 "Review of LOFT Cladding Temp Response for L2-2 & L2-3: Recommendations for improved LOFT Fuel Rod Measurements (Bys 14 & B7), "informal rept. TOLPHANE.L., CORVELL, E. ECO Idaho, Inc. FIN A-6053. EGO-LOFT-5244. 80/10/17. 117pp. 07167:254.
- 8012040605 "Program for Field Validation of Synthetic Aperture Focusing Technique for Ultrasonic Testing (SAFT UT)," quarterly rept on NRC-04-77-145. JACKSDN-J.L., HAMILIN, D.R. Southwest Research Institute. NRC-04-77-145, 80/11/19. 36pp. 07145:213.
- B012040606 "Documentation of Bidding Cames Used in Measuring Social Value." excerpt from NUREO/CR-0989, PNL-2952, Vol 2, App C. CURRIE, J.N., KIDD. J. Battelle Memorial Institute. Pacific Northwest Laboratory. PNL-2798. B0/09/30. 2ipp. 07165:252.
- 8012050682 Forwards status rept for Sept 1980 for core melt & separate effects programs. BERMAN.M. Bandia Laboratories. 4441/ML-16. BO/11/13, 4pp. 07171:199.
- 801210D146 "Program for Standardized Analysis of Fuel Shipping Containers: " technical programs rept. WHITEGIDES, O.E., PARKS, C.V. Union Carbide Corp. FIN B-1072. GRNL/CBD/INF-80. 80/10/29. 9pp. 07219:277.
- 8012100170 "Nondestructive Examination Evaluation Support," monthly progress rept.Oct 1980.
 SMITH.J.H. Clak Ridge National Laboratory. FIN B-0233.
 URAL/HCD/NEEB-B. 80/11/11. 4pp. 07218:245.
- 8012100643 "Experiment Safety Analysis (ESA) for LOFT Small Break Test, EBA L3-5/5A." COOPER.C.H. E0&0 Idaho, Inc. EBA L3-5, 80/09/23, 30pp.
- 8012110003 "Technology & Costs of Termination Surveys Associated W/Decommissioning of Nuclear Facilities," monthly progress rept for Aug 1980. HOLOWAY, C.F., MITHERSPOON, J. Oak Ridge National Laboratory. FIN A-9042. ORNL/HASRD-93. BO/OB/31. 3pp. 07223:110.

- 8012110057 "Analysis of Hypothetical Accidents Resulting in Core Meltdown," monthly progress rept for Oct 1980. DENNING.R.S., CYBUL8KI8,P., BAYBUTT,P. Battelle Memorial Institute. Columbus Laboratories. FIN A-4067. 80/11/14. 7pp. 07223:132.
- BO12110548 "Decontamination as Pracursor to Decommissioning," informal monthly progress rept for Oct 1980.
 PERRIGO, L. D. Battelle Memorial Institute, Pacific Northwest Laboratory, FIN B-2303. 80/11/17. 2pp. 07226:167.
- 8012110951 "LWR In-Plant Measurement Program," informal monthly progress rept for Oct 1980.
 MANDLER, J. W. EG&O Idaho, Inc. FIN A~6075. 80/11/12. 4pp.
- 8012120609 "Acoustic Emission Characterization of Flaw Growth in A533B Pressure Vessel Steel: "monthly ltr rept for Oct 1980. HUTTON:P.H. Battelle Hemorial Institute, Pacific Northwest Laboratory, FIN B-2088, 80/11/21. 10pp. 07228:230.
- 8012170781 "Communications & Control to Support Incident Mgt:Initial Design Considerations." GASPAROTII.J. HIMES,J., JANICIK,E. Mitre Corp. 46~6996. 79/12/31. 62pp. 07265:084.
- --B012170784 "NRC Incident Response Exercise 10." HANNAN,J., HIMEB,J., WOLFE,D. Mitre Corp. MTR-BOW00121. E0/04/30, 13pp. 07265:145.
- --8012170788 "Operational Implications of Alternative NRC Roles in Incidents." JANICIK,E., OTTENBERO,M. Mitre Corp. NRC-05-80-252. MIR-80N00120, 80/05/31. 200pp. 07265:163.
- B012180058 "Div of Reactor Bafety Research-ORNL Programs," monthly highlights for Oct. 1980. MYNATT.F.R. Oak Ridge National Laboratory. B0/11/10. 37pp. 07272:291.
- 8012190044 "Operational Transient Test Series, Tests QPT 1-1 & QPT 1-3 Experiment Predictions."

 GARNER, R. H., MARTINSON, Z. R., SMITH, R. H. Idaho National Engineering Laboratory, FIN A-6041. EGG-TF8P-5259. B0/11/30. 71pp. 07278: 241.
- 8012190049 "Preliminary Model of Steam Sector Test Facility Using TRAG-BDI Computer Program," technical rept. BOLANDER, M.A., LARSON, J.R. Idaho National Engineering Laboratory, FIN A-6039. E00-CAAP-5292. 80/11/30. 49pp. 07278:324.
- B01219013B "Relating Pressure Vessel Surveillance Capsule Measurements to Pressure Vessel Damage."

 CAREN, J. F., MIN, K. D., ARUNBUN, A. L.
 BNL-HUREO-28511. 80/07/30. 25pp. 07282:014.
- 8012190146 "RAMONA-3B Code Mod & Evaluation." monthly highlight ltr for Oct 1980. DIAMONO, D. J. Brookhaven National Laboratory. FIN A-3014. 80/10/31. 4pp. 07282:010.
- 8012190151 "88C Code Development, Verification & Application," monthly highlights for Oct 1980. OUPPY, J. O. Brookhaven National Laboratory. FIN A-3015. 80/10/31. 7pp. 07282:037.
- BO12190166 "HTOR Bafety Program," monthly highlights ltr for Oct 1980. BABTRE, C. Brookhaven National Laboratory. FIN A-3016. 80/11/04. 6pp. 07282:048.
- B0(2190179 "Bimulator Improvement Program," monthly highlight ltr for Oct 1980. WULFF,W. Brookhaven National Laboratory. FIN A-3014. 80/10/31. 4pp. 07282:066.
- B012190185 "Technology & Costs of Termination Surveys Associated W/Decommissioning of Nuclear Facilities," monthly progress rept for Oct 1980. HITHERBROON, J. HOLOWAY, C.F. Oak Ridge National Laboratory. FIN A-9042. QRNL/HABRD-103. B0/10/31. Spp. 07282:076.
- BO12190199 "Advanced Instrumentation for Reflood Studies (AIRS)," foreign trip rept. HERBKOVITZ:M.B., PAYNE,H.R., THORNTON,R.H. Cak Ridge National Laboratory, FIN B-0413 ORNL/FTR-782. 80/11/17. 9pp. 07282:085.
- 8012190208 "Bafeguards Analysis for Byproduct Matls & Small Guantities of BHM," monthly progress rept for Oct 1980.
 CHESTER, R. O., RANDOLPH, M. L. Oak Ridge National Laboratory. FIN B-6108. ORNL/MASRD-102. 80/11/17. 6pp. 07282:102.

- 8012220164 "Bouthwest Research Inst Activities in Support of NRC for Field Validation of Synthotic Aperture Focusing Technique for Ultrasonic Testing." Monthly Status Rept 40. HAMLIN.D.R. Southwest Research Institute. NRC-04-77-145. 17-5023(26). 80/12/04. 7pp. 0/305:261.
- 8012220174 "LOFT Monthly fragress Rept," Oct 1980. KAVFHAN,N.C. EG&G Idaho, Inc. FIN A-6048. EGG-LOFT-5290. 80/11/30. 86pp. 07305:268.
- 8012220186 Monthly rept for Oct 1980 for Semiscale, Thermal Fuels Dehavior Program, 2D/3D Program, Code Development & Analysis Program, Code Assessment & Applications Programs & OPP & Line Items.
 BOSTNICK, W. E., LEACH, L. P. Idaho National Engineering Laboratory. FIN A-6009. 80/11/3D. 150pp. 07306:069.
- 8012240156 "LWR Code Assessment & Application," monthly highlight ltr for Oct 1980.
 SAHA,P. Brookhaven National Laboratory. FIN A-3215. 80/10/31.
 6pp. 07324:336.

REVIEW GRP NRC RESEARCH REVIEW GROUPS

- 8009100422 SECY-B0-379
 Submits proposed plan for development & articulation of NRC safety objectives notably w/respect to reactors. Status of NRC work description of Dfc of Research sponsored projects & draft staff requirement means & FR notice encl. HANRAHAN.E.J. Office of Policy Evaluations. BICKMIT.L. Office of the General Counsel. 45FR71023. 80/08/12. 28pp. 03517:177.
- 8012020246 Forwards summary of 801028 meeting in Oaithersburg.MD redevelopment of in-place test for early warning fire detection sys acceptance & verification procedures at nuclear power plants.List of attenders enci.
 FEIT.R. Fire Protection Review Group. 80/11/17. 6pp. 07133:148.
- B012030B61 Advises that docket for safety goal project has been established in PDR in Mashington DC. All project-related matts should be sent to PDR except for items withheld under FOIA or determined to be withheld by responsible member. HANRAHAM, E. J. Office of Policy Evaluations. 45FR71023. B0/11/24. 1p. 07149:060.
- 8012030866 Discusses 801029 interview w/T Cochran of NRDC re NRC safety goal NRDC is not actively engaged in any work related directly to safety-goal formulation.
 8E0E, O. Office of Policy Evaluations. 45FR71023. 80/11/24. 3pp. d7149:057.
- 8012030870 Discusses 801029 interview u/R Wiesmann & D Goeser of Westinghouse re NRC mafety goal, BEGE, G. Diffice of Policy Evaluations, 45FR71023, 80/11/18, 2pp. 07149: 055.
- 8D12030875 Forwards working paper on criteria for safety goal formulation, for comment. 8E0E.Q. Office of Policy Evaluations. 45FR71023, 80/11/17. ip. 07149; 03B.
- --8012030877 Working paper criteria for safety goal formulation. SEGE, 0. Office of Policy Evaluations. 45FR71023. 80/11/14. 12pp. 07149:039.
- --B012030879 Forwards NUREQ-0735, "Plan for Developing Safety Qual," for comment. H/o enci.
 SEGE.O. Office of Policy Evaluations. 45FR71023. 80/11/12. ip. 07149.051.
- --B0120308B3 Agenda for B01120 inter-ofc steering group meeting in Bethesda, MD re-criteria for development of safety goal. HANRAHAN, E. J. Office of Policy Evaluations. 45FR71023, B0/11/12. 1p. 07149:052.
- --B0120308B5 Agenda for 801103 inter-ofc steering group in Bethesda.MD re-action plans.assignments & basis for resource estimates for development of safety goal.

 HANRAHAN.E.J. Office of Policy Evaluations. 45FR71023. 80/10/30.
 1p. 07149:053
- --B012030890 Forwards NUREG-0735, "Plan for Developing Bafety Coal," for comment. W/o encl. SEGE.0. Office of Policy Evaluations. 45FR71023. B0/10/31. 1p. 07149:054.

- 8012030895 Summary of 801120 meeting w/inter-ofc steering group redevelopment of safety goal.
 SEGE, 9. Office of Policy Evaluations. 45FR71023. 80/11/24. ip.
- 8012030902 Requests comments on encl tentative outline for preliminary policy paper by 801107. SEGE.G. Office of Policy Evaluations. 45FR71023. 60/10/28. 4pp. 07147.031.
- --8012030905 Submits tentative general outline re safety goal for preliminary policy paper. SEGE: 0. Office of Policy Evaluations. 45FR71023. 80/10/27. 3pp. 07149:032.
- --B012030910 Confirms 801029 meeting w/inter-ofc steering group re safety goal project.Agenda encl. HANRAHA/L.E.J. Office of Policy Evaluations. 45FR71023. 80/10/27, 2pp. 07149:035.
- 8012030717 Forwards 801027 press release to NRC issues plan for developing safety goal & T Rehm 601027.0 Sege 801028 & EJ Hanrahan 801014 memos. SEGE. 6. Office of Policy Evaluations. 45FR71023, 80/10/30, ip. 07149.009.
- --B012030925 Responds to 801014 info request re-safety goal project.
 Steering group will identify areas likely to require
 addl resources, including work simed toward policy paper
 due Aug 1981.
 HANRAHAN, E. J. Office of Policy Evaluations. 45FR71023. 80/10/27.
 1p. 07149:013.
- --8012030927 Forwards safety goal interview questions for industry & public interest groups. SECE, 0. Office of Policy Evaluations. 45FR71023. 80/10/28. 5pp. 07149:014.
- ---8012030930 Forwards questions re development of safety goal. Plans include interviewing each Commissioner early in program to gain benefit of preliminary thoughts & advice.

 HAKRAHAN, E. J. Office of Policy Evaluations. 45FR71023: 80/10/14.

 3pp. 07149:015.
- 8012030924 Forwards update on status of Chapter V of THI Action Plan. HANRAHANNE.J. Office of Policy Evaluations. 45FR71023. 80/09/23. 4pp. 07149:022,
- --B012030928 Staff requirements memo re Commission 800707 meeting to discuss SECY-80-0248.Lists actions agreed upon as result of actions identified in Chapter V of TMI Action Plan. HD\LE, J. C. Office of the Secretary of the Commission. 45FR71023.
- 8012030931 Staff requirements mamo re BECY-80-379. Advises that Commission has approved proposed plan for development of safety goal subj to listed mods. HOYLE, U. C. Office of the Sucretary of the Commission. 45FR71023. 80/10/14. 2pp. 07149:029.
- 8012090016 Forwards NUREG-0733, "Plan for Developing Safety Goal," & 801027 news release on subj. N/a enci. ZECH, G. O. Technical Support Branch. 90/11/22. 1p. 07197: 300.
- --8012090018 Requests NUREC-0735, "Plan for Developing Bafety Go LEWIS, M. I. Affiliation Unknown. 80/12/05, ip. 07197:301.
- SEÇY POSITION PAPERS BEFORE THE COMMISSION
- 8009100422 SECY-80-379 JO9100422 SECY-B0-379

 Bubmits proposed plan for development & articulation of NRC safety objectives notably w/respect to reactors. Status of NRC work description of Ofc of Research sponsored projects & draft staff requirement memo & FR notice enci. HANRAHAH, E. J. Office of Policy Evaluations. BICKMIT, L. Of the General Counsel. 45FR71023. B0/08/12. 28pp. 03517:19 IT, L. Office of 03517: 197.
- 8011200233 BECY-80-489 011200233 BECY-BO-4B9 Recommends reappointment of DN Moeller to ACRB for 4-yr term beginning Bioloi Recommendation supported by fellow members. Draft reappointment itr encl. FRALEY.R.F. ACRB - Advisory Committee on Reactor Bafeguards. BO/10/30. 4pp. 03743:341.
- 8011200263 SECY-B0-325A
 Forwards to Commission, info re inclusion of steam generator transients as unresolved safety issue.
 DIRCKS: H.J. Office of the Erecutive Director for Operations. 80/11/07. 1p. 03743:345.

- 8011200286 SECY-80-500 Place Sect -80-500 Recommends Commission approval of anci draft final rule reamend to code requirements providing title change for NRC adjudicatory panel members. Solicitation of public comments not required, since rule concerns agency organization. FITZOERALD, J. A. Office of the General Coursel. 80/11/10. BO/11/10. 5pp.
- 8011280106 Transcript of 801121 Affirmation Session 80-51 in Hashington, DC re discussion & vote on SECY 80-457.Pp 1-31. # Commissioners. 80/11/21. 31pp. 07082:043.
- --8011280117 SECY-80-457
 Requests NRC approval of revised Manual Chapter 0103 re EDO delegations of authority. Chapter will be published upon receipt of revisions & approval.
 DIRCKS.W.J. Office of the Executive Director for Operations. 80/10/07. 27pp. 07082:077.
- --B011280112 SECY-80-476
 Informs that NRC has concluded & recommended that revisions should be made to 10CFR73 amend & to draft Reg Ouide 50 901-4. Forwards revised amends & submits guide changes. MINDOUE, R. B. Office of Standards Development, Director. 80/10/20, 68pp. 07082:091.
- 8012020196 Transcript of 801117 meeting in Washington, DC for discussion to vote on SECY-80-486 re resolution of pat-down search issue at power reactors & status of related safeguards activities.

 Pp i-28.

 * Commissioners. 80/11/17. 28pp. 07143:067.
- --801ii40484 SECY-80-486
 Recommends approval of enci amands to 10CFR73 re search procedures at reactor protected area entry portals.Draft FR notices encl.
 DAVIS.J. 0. Office of Nuclear Material Safety & Safeguards, 80/10/28. 22pp. 03732:183
- B012020353 BECY-80-504
 Summarizes potential impact of hypotheses re iodine release during reactor accidents & proposes agenda for 80i118 meeting.
 DEN10N.H.R. Office of Nuclear Reactor Regulation, Director. 80/11/13. App. 07144: 202.
- 8012030773 SECY-80-512
 Informs Commission of favorable Executive Branch position on two pending export license applications, XSNM-1425 & XSNM-1429. DIRCKS, M.J. Office of the Executive Director for Operations. BO/11/19. ip. 03758: 174.
- 8012040162 Forwards staff requirements memos for closed Commission meetings. Transcripts for all meetings have been released in entirety to PDR.

 BROWN.J. Office of the Secretary of the Commission. 80/11/06. 1p. 07170:035.
- --B010230021 Staff requirements memo re Commission 800313 Affirmation Session 80-10 re SECY-A-80-20.SECY-80-098.SECY-A-80-3A. SECY-A-80-9 & SECY-A-80-21. Commission approved notice of hearing re 791206 order. CHILK.S.J. Office of the Secretary of the Commission. 80/03/17.
- B012050033 BECY-80-507

 Beets Commission approval of encl draft FR notice endorsing deferment of mandatury acceptance of nuclear plant reliability data sys & development of integrated operational experience reporting sys. Recommends approval.

 DIRCKS.(f. J. Office of the Executive Director for Operations. 80/11/14. 60pp. 07173:116.
- --8012050061 Informs of 800528 memo requesting various Ofc of Nuclear Reactor Regulation branches to identify areas of needed improvement in LERs. Submits improvements & needs for both LER & nuclear plant reliability sys. DENTOW.H.R. Office of Nuclear Reactor Regulation, Director. 80/10/29, 4pp. 07173:106.
- --8012050066 Forwards seven paragraphs describing nuclear plant reliability data sys needs as requested in 800716 meeting. VESELY, W. E. Probabilistic Analysis Staff (Pre 801119). 80/08/15.
- --8012050073 Submits reasons for mandatory nuclear plant reliability data sys & changes that include features not installed. HARTFIELD.R.A. Office of Management and Progrem Analysis. BO/08/14. 17pp. 07173:173.

- --8008270155 Forwards branch statement re need for NPROS-type info.as input to Commission paper. Input should be placed in apps to paper.as supporting documents. Description of combined NPROS & LER reporting sys available late Aug.
 MICHELSON.C. Director's Office. 80/08/15. 15pp. 03431:032.
- ~-B011130046 Forwards input re IE needs for upgraded NPRDS & LER sys.Reg Quide 1.16 does not provide requirements for reporting model & serial numbers & mods for failed components. Quidelines need to address AO repts as LER subsets. JORDAN,E.L. Division of Reactor Operations Inspections. B0/08/28. 2pp. 03731:117.
- B0120B0765 SECY-B0-513
 Forwards Executive Branch position recommending approval of application by OA Co to export 1,372 g U.enriched to 70% U-235.to Yugoslavia.
 DIRCKS,N.J. Office of the Executive Director for Operations.
- --8012980770 Forwards application for export license.
 MOWRY.W.R. General Atomic Co. (subs. of Oulf Oil Co.). IEL-858.
 77/11/16. 2pp. 03767:065.
- --8012080778 Application for license to export 1.372 g U.enriched to 70% U-235, to Yugoslavia. End use statement encl. MOMRY. H. R. Oeneral Atomic Co. (subs. of Gulf Oil Co.). IEL-858. 79/11/16. 2pp. 03767:067.
- 8012110438 Add1 response to FOIA request for documents re nuclear incident in USBR in 1955. Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 80/12/05, 2pp. 07227:140.
- --8012110445 BECY-79-416
 Provides Commission w/summary of reported events in USBR researety of peaceful nuclear activities. Forwards listing of reported USBR nuclear events, news articles resources event & evaluation papers & repts.

 SHEA.J.R. Office of International Programs, Director. 79/06/26.
- 8012120220 BECY-80-514
 Forwards rept on possible changes in statistical treatment of inventory differences in nuclear math accounting.NMSS will evaluate costs & benefits of possible changes listed in rept.
 DIRCKS,K.J. Office of the Executive Director for Operations. 80/11/20, 43pp. 03773:208.
- 8012120365 Transcript of 801126 public meeting in Washington. DC reinstructions to ABLB on facility proceeding. Pp 1-39.

 * Commissioners. 80/11/26. 39pp.
- --8012120373 SECY-A-80-179C
 Forwards draft order reflecting divergent positions on certain questions re principal focus of adjudication. BICKHIT, L. Commissioners. 80/11/26. 14pp.
- B012180327 BECY-B0-520
 Forwards Executive Branch response to pending export applications XBNM-1725.XBNM-1726 & XBNM-1727.original applications & related correspondence. DIRGKS,M.J. Office of the Executive Director for Operations. 80/11/21. ip. 03794:064.
- 8012180416 BECY-80-523
 Requests authorization for issuance of proposed export
 License XCOM-0315 & authorization for staff to process
 future similar licenses for exports destined for Cernavoda
 Nuclear Power Station w/o Commission referral.
 BIRCKB. M. J. Office of the Executive Director for Operations.
 BO/11/28. 4pp. 03794:267.
- --B0121B0420 Discusses encl Canadian Embassy 781205 ltr of assurance re US exports of nuclear components. Assurances meet requirements. NOSENZO,L.V. State, Dept. of, Bureau of Oceans & Internatl, Environ. & Scientific Affairs. 80/06/23. 4pp. 03794:276.
- --B012190427 Concurs w/revised procedure allowing Commission to take action on license applications for export to Canada u/o Executive Branch review, Applications for export to other countries still need review. Ltr of assurance encl. NOSENZOIL. V. State. Dept. of, Bureau of Oceans & Internatl, Environ. & Bcientific Affairs, 78/09/06 3pp. 03774:280.

- 8012270009 SECY-80-384
 Recommends approval of FR notice to respond to DGE request for rulewaking to exempt from licensing requirements smelted alloys containing Tc-99 & low enriched U as residual contamination.

 MINUOUE,R.B. Office of Standards Development, Director. 80/08/15, 8pp. 07330;240.
- 8012290476 Transcript of 801211 meeting in Washington.DG re SECY-80-474C.Pp 1-32

 * Commissioners. 80/12/11. 34pp. 07335:066.
- --8012290483 SECY-80-4740
 Suppls SECY-80-474 & forwards clarifying changes to 10CFR60 final rule & conforming amends.
 DIRCKS-W.J. Office of the Executive Director for Operations.
 80/12/09. 16pp. 07335:104.
- 8012290493 Transcript of 801215 public meeting in Washington, DC re ASLB instructions. Pp. 1-54.

 * Commissioners. 80/12/15. 56pp. 07335: 219.
- 8012290385 SECY-80-534
 Summarizes status of application by CA Co to export research reactor to Malaysia. Recommends license be issued.
 DIRCKS-W.J. Office of the Executive Director for Operations, 80/12/10. App. 07335:301.
- --8012290589 Responds to 800211 memo re plans to provide one TRIGA MARK II research reactor & SNM to Malaysia. DDE should modify proposal to show physical protection into being given on bilateral basis.

 6HEA, J. R. Office of International Programs, Director. 80/07/15.

 2pp. 07335:312.
- --8012270593 Responds to NRC 800719 memo re US/IAEA/Malaysia project & supply agreement. Exchange of physical security info. safeguards info & fallback safeguards meets all statutory requirements.

 BENG-L8008Fr.H. Energy, Dept. of. 80/09/02. 6pp. 07335:314.

STATE PROO STATE PROGRAMS

- 8011180303 Forwards statement of NRC/FEMA interfacing responsibilities re assessment of states' emergency plans, in response to 801007 request for input to GAO evaluation. BENION.H.R. Office of Nuclear Reactor Regulation, Director. BO/10/15. 2pp. 06986:030.
- ---BO11180319 Requests statement of NRC/FEMA interfacing responsibilities re assessment of states' emergency plans for QAD evaluation of faderal programs.

 BARRY, L. W. Diffice of the Controller. BQ/10/07, 1p. 06986:032.
- 8012010018 PNA-80-36B: status of State of FL & Intl Chemical Workers Union actions relack of training & respiratory protection programs. Ofc of State Programs will review State of FL actions during Nov 1780 meeting w/Intl Minerals Corp. KERR.O. U. 7 BQLLINO, L. A. Office of State Programs. Director. 80/10/29. 1p. 06915:001.
- 8012010019 Comments on 801003 FR notice re evaluation of agreement state radiation control programs. Std requirements re program budgetting & staffing should be developed. WARD. J. O. California. State of. 80/11/05. 1p. 07096; 356.
- 8012010037 Comments on 801105 FR notice re evaluation of agreement state radiation control programs, proposed general policy.

 Commission licensing program should be reviewed by outside entity.

 WOLFF.T.A. New Mexico, State of. 80/11/05. ip. 07092:081.
- 8012010048 Submits comments on NRC notice of proposed general statement of policy, "Evaluation of Agreement State Radiation Control Programs," Technical qualification of agreement state staff should be improved, SHEALY, H. G. South Carolina, State of. 80/10/29. 3pp. 07092:094.
- 80(201045) Informs Div of Radiological Health. Dept of Public Health that state control of agreement matts program is satisfactory. Requests review of & comment on NRC recommendations & comments re-program.

 LUBEKAU.J. 0 Assistant Director for State Agreements Programs. 80/11/07. 2pp. 07097:001.

- B012010457 Informs TN Dept of Public Health that state program for regulation of agreement matl is adequate to protect public health & safety & is compatible w/NRC program for regulation of similar matls.

 KERR.O.W. Diffice of State Programs, Director. SA/RJD. 80/11/07.
 2pp. 07076:361.
- 8012020283 Forwards State of FL 801027 ltr transmitting fourth quarterly progress rept on transportation surveillance program. Rept covers period from Jul-Sept 1980. JANINEM M. Office of State Programs, Director. 80/11/13, 2pp. 07133:141.
- ---9012020294 Forwards fourth quarterly progress rept on transportation surveillance program, covering period from Jul-Sept 1780.

 Objectives have been fulfilled in first yr of study. Contract remewal has not been requested.

 SHULER, P. E. Florida, State of, 80/10/29, 12pp. 07133:113.
- 8012020691 Discusses regional (lation of emergency preparedness technical review functions for development of safety evaluations. Regions 1 & 2 ready for emergency preparedness team leaders.

 GRIMES. B. K. Emergency Preparedness Program Office (after 80fil9 see 1&E). B9/11/21. 1p. 06916:001.
- 8012050038 Confirms intention to provide adequate resources for radiation control program in NY Dept of Environ Conservation. Reorganization will place increased emphasis on control of toric substances including radioactive matl. FLACKE.R.F. New York, State of. E0/11/07. ip. 07174:327.
- --B012050056 Ack receipt of 800926 ltr to NY Dept of Environ Conservation re NRC program review Comments on findings summarized in ltr. Radioactive matl permits issued will be forwarded to NRC quarterly.

 CASIMAN.T.J. New York, State of, 80/10/30, 2pp. 07174:328.
- 8012100549 Forwards rept to Governor re NRC & DDT agreement to shift emphasis from surveillance to enforcement. Restructured program will have state focus on enforcement action against violators of RAM transportation regulations. W/o enci. DIRCKS, W. J. Office of the Executive Director for Operations, 80/11/24. 3pp. 07220:057.
- 8012110474 Forwards rept to Governor re NRC & DDT agreement to shift emphasis from surveillance to enforcement. Restructured program will have state focus on enforcement action against violators of RAM transportation regulations. W/o encl. DIRCKS.W. J. Office of the Executive Director for Operations. B0/11/24. 3pp. 07225:254.
- 801211'476 Forwards rept to Opvernor to NRC & DOT agreement to shift emphasis from surveillance to enforcement Rostructured program will have state focus on enforcement action against violators of RAM transportation regulations. W/o enci. DIRGKS, N. J. Office of the Executive Director for Operations, 80/11/24. 3pg. 07225: 249.
- BO12120235 Notifies that NY City Dept of Health radiation control program is adequate to protect public health & compatible w/NRC program.Ltr to L Solon conveying technical comments encl.

 KERR.O. W. Office of State Programs, Director. 80/11/20. 1p. 07234:205.
- --8012120243 Confirms discussion re review of NY City radiation control program. Recommends procedures be modified to include grovision for follows a recording of results of all previous violations.

 LUBENAU, J. O. Assistant Director for State Agreements Programs. 80/11/20. 1p. 07236:206.
- 8012160620 Confirms comments made at conclusion of radiation control program review.RI program for control of agreement matls is adequate to protect public health & safety. LUSEKAN,J.O. Assistant Director for State Agreements Programs. 80/12/02. 1p. 07261:252.
- --8012160625 Confirms comments made re regulatory program review. RI program for regulation of agreement matts is adequate to protect public health & safety. KERR, O. W. Office of State Programs, Director. 80/12/02. 2pp. 07261: 253.
- B012170040 Comments on draft Reg Guide DH 710-4, "Health Physics Surveys in U Mills." HAZLE.A.J. Colorado, State of. B0/11/07. 3pp. 07266:197.

- BO12190562 PNA-BO-040: on B01123, resident discovered radiation hot spots around Neutron Products, Inc facility in Dickerson, MD. State of MD uill conduct isotope analysis of hot spot activity. LUBENAN, J. O., BDLLING. L. Office of State Programs, Director. B0/12/03. 2pp. 07286: 018.
- SO12220183 Responds to FOIA request for info re storage of nuclear, radioactive or other hazardous waste in NM App A documents may be obtained from NTIS Forwards App B documents & NUREO/GR-0394.W/o encl NUREO, FELTON, J. K. Division of Rules and Records. 80/12/05, 4pp. 07303:243.
- --8012220194 Excerpt from NM radiation control program from 751023-760827 re commercial low level radwaste burial.

 * New Mexico, State of. 76/08/27. 1p.
- --B012220200 "NM Site Application Experience." Albuquerque Journal article entitled "NM Given Nuclear Waste Site Caution Note" encl. 4 New Mexico, State of. 80/12/05, 5pp. 07187:001.
- --9012220207 Requests NRC comments on encl draft guide for applications for license to operate low level radwasta disposal facility, including overall scope of guide, compatibility of state & NRC technical requiraments & acceptance criteria. NOLFF.T.A. New Mexico, State of. 76/09/29, 10pp.
- --B012220212 Forwards NRC comments on draft licensing guide for radwasta disposal facilities, in response to 760928 request Licensing of New Burial grounds is not prudent grior to development of comprehensive natl low level waste mpt program.

 KERR, O. W. Assistant Director for State Agreements Programs, 76/11/19. 6pp.
- --B012220219 PNA-76-006: on 76120B, article appeared in Albuquerque Journal re NRC comments on Btata of NM proposed licensing guide for commercial raduaste burial grounds. NRC comments did not imply concurrence in licensing of commercial burial grounds. KERR, G. N., LOHAUS, P. Office of State Programs, Director, 76/12/08. (p.
- --8012220224 Discusses NRC ltr to State of NM re adoption of formalized policy on licensing of low level radwaste disposal facilities by agreement states. Requests masting w/NRC to discuss current & future plans re radwaste disposal.

 ANDREWS.L.J. Chem-Nuclear Systems, Inc. 76/12/08. 2pp.
- --8012220233 Informs that recommendation in NRC 761117 ltr re regulation of commercial low level waste burial grounds was not adopted as Commission policy. Provides NRC current position, Btate of NM 771129 & 30 ltrs to Chem-Nuclear Sys, Inc encl. KERR, O. W. Assistant Director for State Agreements Programs, 78/10/12. Bpp.
- --8012220243 Ack receipt of 770507 request for info re schedule for consideration of Chem-Nuclear Sys low level radwasts disposal license application. Forwards listing of licensing activities & draft schedule of application processing. WOLFF.T.A. New Mexico. State of. 77/07/11. 4pp.
- --B012220246 "Comments on Chem-Nuclear NM, Inc Application for Radioactive Matl License." M/related info.
 PIERCE, J., DUDLEY, J., QALLAHER, B. New Mexico, State of. 77/11/30. 36pp.
- --8012220232 "Preliminary Review of Chem-Nuclear License Application Prepared for NM Environ Improvement Agency." W/related info. RODDERS.J.C. Affiliation Unknown. 77/11/30, 19pp.
- --B01222025B Statement to NM Environ Improvement Agency re Chem-Nuclear NM Inc application for license to dispose of nuclear waste in Colfax County,NM, W/related info. DAVIDSON, J. P. Maratorium, Inc. 77/09/01. 6pp.
- --8012220264 "Comments on Application for Radioactive Matl License by Chem-Nuclear NM.Inc." MONTAQUE.P. Southwest Research and Information Center. 77/11/30. Spp.
- --B012220269 "Comments on Chem-Nuclear Radwaste Disposal License Application." HYDER.C. Bouthwest Research and Information Center. 77/11/30, 13pp.
- --B012220275 "Comments & Questions on Application for Radioactive Matl Liceuse by Chem Nuclear NM. Inc. " Related documentation encl. BCHULTZ.K.B. Bouthwest Research and Information Center. 77/09/12. 37pp.

- --8012220284 "Comments on Application for Radioactive Matl License to Operate Commercial Radwaste Burial Facility, Colfax County, NM."
 - Environmental Protection Agency. 77/11/21. App.
- --8012220270 Ack receipt of 770518 ltr informing of receipt of application from Chem-Nuclear Sys, Inc to establish commercial low level radwaste burial ground Offers assistance on environ rept including economic analysis. KERR.G.W. Assistant Director for State Agreements Programs. 77/06/07. 2pp.
- --9012220298 Ack receipt of 761208 ltr re NRC ltr to State of NM re adoption of formalized policy on licensing of low level radwaste disposal facilities by agreement states. NRC comments & position were of generic nature. KERR, O, U. Assistant Director for State Agreements Programs. 76/12/17. 1p.
- B0122P0402 Notifies that NY State Dept of Environ Conservation program for control of agreement matl is acceptable.
 KERR, G. W. Office of State Programs, Director. 80/12/05. 1p. 03797:072.
- 8012220410 Confirms 801107 discussion re NRC review of State of CA radiation control program. Earliest possible adoption of State revised radiation control regulations recommended. Burmary statement encl. XERR.9.W. Office of State Programs, Director. 80/12/09. 7pp. 07301:169.
- 8012220417 Confirms NRC comments re RRC review of radiation control program. Regulations recommended to provide for insp of licensees to DOT requirements re package preparation & shipping procedures. Summary statement encl.

 LUBENAU, J. O. Office of State Programs: Director. 80/12/09. 7pp.
- 8012230290 Responds to 800908 ltr re overview of radiation control program. Addi staff resources necessary to complete program requirements.
 ARNOTTIR.A. Colorado, State of. 80/11/12, 3pp. 07318:039.
- 8012240365 Forwards comments, on behalf of NL Industries, Inc. re proposed policy statement re evaluation of Agreement State radiation control programs published in 801003 FR. FRIEDLANDER, J. LeBoeuf, Lamb, Leiby & MacRae. 45FR65726 010. 80/11/17. 7pp. 07324:055.
- --B012240370 Forwards NRDC comments on NRC proposed general statement of policy for evaluation of Agreement State programs. Supports evaluation process & utilization of administrative criteria. YUAN, G. Natural Resources Defense Council. 45FR65726 004. 80/11/14. 12pp. 07324:062.
- --8012240374 Comments on evaluation of Agreement State radiation control programs proposed general statement of policy Questions adequacy of program structure. Problems are not unflaterally fault of agreement states.

 BERICK.D. Environmental Policy Instituts. 45FR65726 006.

 80/11/17. 3pp. 07324:074.
- --8012240379 Comments on criteria for evaluation of Agreement States program. Statements in supplemental info of Commission policy require discussion. PARROTT, M.W. Oregon, State of, 45FR63726 005, 80/11/14. Spp. 07924:077.
- --8012240383 Comments on proposed general statement of policy reevaluation of Agreement State radiation control programs. Qualification of staff members should be strengthened through training programs.

 BROWN.C.B. North Carolina, State of. 450F65726 002. 80/11/07. 2pp. 07324:082.
- --8012240390 Comments on FR notice of NRC proposed general statement of policy re evaluation of Agreement State radiation control programs. Program evaluation criteria should be well thought out & consistently applied.

 BEARE.J.A. Washington, State of. 45FR65726 009. B0/11/17. 6pp. 07324:084.
- --8012240395 Comments on proposed general policy statement for evaluation of Agreement State radiation control programs. Program guidelines adequate but stds may be costly & time consuming for operators.

 THOMAS. E. L. Air Transport Association. ASFR65726 007. 80/11/17. 18. 07324:070.

- -- A012240399 Informs of review of proposed general statement of policy p evaluation of Agraement State radiation control programs No RATHLESBERGER Interior, Dept. of. 45FR65726 003. 80/11/12, 1p.
- -8012240404 Comments on Category I indicator of personnel qualification in guide for evaluation of Agreement State radiation control programs. Questions if x-ray technician w/two yrs training would be acceptable personnel for state program. QSBURNE, R P. Kentucky, State of. BO/11/17. ip. 07324:092.
- --8012240407 Comments on proposed general statement of policy for evaluation of Agreement State radiation control programs.

 Larger data set should be gathered by licensee to provide better program.

 HECTOR,A. O. ROBINSON,P. Southwest Research and Information Center. 80/11/17. 9pp. 07324:073.
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8002280187 Notifies that payment is due for NRC review of Topical Rept OLP-5640. "Use of Thorium Oxide Fertile Fuel Particles in Furt Saint Vrain Fuel Elements."

 MILLER, N.O. License Fee Management Branch. 80/02/07. ip.
- 8012010463 Informs that proposed changes described in Revision 14 to QA rept CE-1A: "Comm Ed QA Program for Nuclear Generating Stations;" have been evaluated. Rept acceptable \(\omega \)/exception of certain potential changes.

 HAASS, W. P. Quality Assurance Branch. 80/11/10. 2pp. 07096; 359.
- 8012020041 Notification of 800908 meeting w/Westinghouse in Bethesda, MD to discuss manual actuation of engineered safety features. OLSHAN, L.N. Operating Reactors Branch 1. 80/09/02, 2pp. 07147:191.
- 8012020046 Notification of B00911 meeting w/OE in Bethesda.HD to discuss application of core spray heat transfer coefficient using OE nethodology.
 PHILLIPS.L.E. Core Performance Branch. 80/08/29. 2pp. 07147:193.
- 8012020094 Notification of 801015-16 meeting w/B&W owners group to finalize criteria that will form basis for future plant-specific mods.

 HANNON, J. N. Operating Reactors Branch 2, 80/10/08. 1p. 07147:196.
- 8012020182 Forwards GA program for nuclear generating stations. TRAMM.T.R. Commonwealth Edison Co. 60/11/24. 1p. 07141:079.
- --8012020217 CE-1-A R14

 GA program.Revision 14.for nuclear generating stations.

 * Gommonwealth Edison Co. 80/09/09. 142pp. 07141:080.
- 8012020298 Forwards errata to NEDD-24811, "4T Condensation Oscillation (4TCD) Tast Program Final Test Rept." BUCHHOLZ.R.H. Oeneral Electric Co. MFN-193-80, 80/11/13, 1p. 07147:315
- -8012020265 NEDD-24811 ERR 1 Errata I to NEDD-24811, "4T Condensation Oscillation (4TCD) Test Program Final Test Rept." # General Electric Co. 80/09/30. 6pg. 07147:316.
- 8012020264 Forwards Revision 2 to BAN-10082, "Environ Qualification of Class IE Control & Instrumentation Equipment," TAYLOR, J. H. Babcock & Wilcox Co. 80/11/20, 2pp. 07132:342.
- --801202026B Revision 2 to "Environ Qualification of Class IE Control & Instrumentation Equipment." EURSTEIN.N.M., LEBNIAK.L.M., LLOYD.A.B. Babcoct & Hilcox Co. BAU-10082 R2. 80/10/31. 130pp. 07132:344.
- 8012020481 Advises that details of plan for developing & submitting revisions to Westinghouse small break ECCB evaluation model will also be applicable to Westinghouse fuel reloads of C-E plants. NOTRUMP code will be submitted by 820401.
 ANDERSON.T.M. Westinghouse Electric Corp. NB-TMA-2344. 80/(1/25, ip. 07130):280.
- 8012020/68 Forwards 791206:800222 & 0606 itrs for entry into QA program topical rept Changes mentioned in ltrs will be incorporated into next topical rept revision. DIEDRICK, D. O. Northeast Utilities. QA-4065. BO/11/06. ip. 07147:322.

- 8012030285 Forwards Errata 1 to NEDE-24811-P "4T Condensation Oscillation (4TCO) Test Program Final Test Rept." Errata available in Central Files only (ref 10CFR2.790). BUCHHOLIR.M. General Electric Co. MFR-194-80. 80/11/13. Ip. 07151:251.
- 8012030316 Forwards proprietary & nonproprietary documentation re model & input for analysis of LOFT Test L3-6. Description of model for LOFT L3-6 analysis withheld (ref 10CFR2, 790). Affidavit for u(thholding enci. BAEKIN, K. P. C-E Operating Plants Cuners Group. B0/12/01. 7pp. 07151:252.
- 8012030697 Forwards NEDE-24288-P, "Generic Condensation Oscillation Load Definition Rept." Document defines load for Mark II pressure suppression containments Rept withheld (ref 10CFR2.790).
 BUCHHOLZ,R.H. General Electric Co. MFN 80-205. 80/11/26. 1p. 07151-298
- B012040228 Forwards proprietary & nonproprietary versions of "Inadequate Core Cooling Studies of Scenarios W/Feedwater Available for Upper Head Injection Plants Using NOTRUMP Computer Code." Application for withholding enci. ANDERSON, T. K. Westinghouse Electric Corp. NS-YMA-2326. B0/11/17. 11pp. 07160:072.
- --B012040237 WCAP-9763

 Nonproprietary version of "Inadequate Core Cooling Studies of Scenarios W/Feeduater Available for Upper Head Injection Plants Using MORRWIP Computer Code."

 MARK. R. H., THOMPSON, C. M., ANDERSON, T. M. Westinghouse Electric Corp. B0/06/30. 200pp. 07160:083.
- 8012050126 Forwards proprietary version of "GE BUR Feeduater Noirle Surveillance Instrumentation Sys." Encl withheld (ref 10CFR2, 790). MATANABE, H. T. General Electric Co. HTM-80-68. 80/11/24. 5pp. 03760:053.
- B012030428 Forwards description of analytical model intended for use for prediction of LOFT L3-6 test. Submittal of L3-6 prediction results is planned for approx 5 wks after receipt of actual initial conditions & results verification. TAYLOR, J. H. Babcock & Wilcor Co. 83/12/04. 15pp. 07:95:010.
- 8012080467 Forwards input & model for prediction of LOFT Small Break Test 13-6. WFLASH computer code evaluation model version will be used w/listed mods. Noding diagram, input & printout of initialized problem encl.
 ANDERSON. T.M. Westinghouse Electric Corp. NS-TMA-234B. 80/12/01. 12pp. 04586:003.
- 8012090014 Comments on 800701 Program Plan for Performance Testing of PWR Safety & Relief Valves." Areas where program not completely responsive to NUREG-0578, Section 2. 1.2 require add i info.
 VOLLKER, R. H. Division of Engineering. 80/11/26, Spp. 07197:293.
- B012090021 Informs that organizational changes in Westinghouse Nater Reactor Divs requested in B01028 ltr acceptable. HAABS.W.P. Quality Assurance Branch. B0/11/21. 1p. 07197:302.
- 8012090194 Notification of 801118 meeting w/ORNL.Dartmouth Coilege & Westinghouse in Bethesda, MD to discuss info requirements of DP measurement sys for inadequate core cooling indication. PHILLIPS.L.E. Core Performance Branch. 80/11/14. 2pp. 07199:361.
- 8012090198 Summary of 801028-29 meetings w/ARMP users in Dallas, TX re util. EPRI & contractor progress & experience in ARMP sys of codes. Abstracts of particular interest encl. LOIS, L. Core Performance Branch. 80/11/12, 6pp. 07202:258.
- 8012070227 Forwards organizational changes WE Orser became manager technical operations & RL Steele became manager nuclear projects engineering effective 801117.

 WITHERS. B. D. Portland General Electric Co. 80/12/03. 2pp. 07201: 153.
- 8012070768 Forwards guide tube wear input for Fuel Performance Annual Rept. PGMERS.D.A. Core Parformance Branch. 80/11/17. 6pp. 07202:339.
- 8012100379 Forwards RELAX computer code description for LOFT small break Test L3-6; in response to NRC 800626 ltr. W/o encl nodalization & listing of code input data, JENSEN.S E. Exxon Nuclear Co.; Inc. (subs. of Exxon Corp.), SEU: 057:80. 80/12/01. 3pp. 07219: 049.

- 8012100385 Forwards input model description & transient time steps for prediction of LOFT small break Test L3-6 using NOTRUMP computer code.
 ANDERSON, T. M. Westinghouse Electric Corp. . PWR Bystems Div. NS-TMA-2351. 80/12/08. 34pp. 07187:001.
- 8012120492 Responds to NRC 801016 ltr re Bechtel 9A Topical Rept BQ-TDP-1, Revision 3A. Vice president for corporate staff functions added & manager of OA, thermal power organization, reinstated. Organization chart encl.
 AMARAL. J. H. Bechtel Power Corp. (subs. of Bechtel Corp.), 9A9-80-385, 80/12/02, 2pp. 07230: 312.
- 8012150084 Informs that changes to QA Topical Rept TVA-TR79-1 provided in 801201 ltr are not specifically referenced in FBAR & ltr should be disregarded.
 MIU.S.L.M. Tennéssee Valley Authority. 80/12/08. 1p. 07239:355.
- 8012150202 Forwards proprietary & nonproprietary versions of slides presented at 801125 meeting w/NRC & BNL. SCHERER, A. E. C-E Power Systems. LD-80-071. 80/12/08. 6pp. 07241:189.
- B012160011 Notification of 801202 meeting w/vendor in Lunchburg, VA to review human factors program.
 IRELANO, R. Division of Human Factors Safety, B0/12/04, 2pp. 07262:330.
- 8012160408 Submits comments in response to W Belke questions re 801022 revisions of ETR-1001.GA program manual. TENZER, B.E. Ebasco Services, Inc. (subs. of Enserch Corp.), 80/12/08. 2pp. 07263:047.
- B012160410 Forwards proprietary & nonproprietary versions of BAH-L0143, "Statistical Core Design Applied to Babcock-205 Core." Rept supersedes BAH-10139, "Statistical Core Design." Affidevit encl. Proprietary version withheld (ref 10CFR2.790). TAYLOR, J. H. Babcock & Wilcox Co. B0/12/10. 10pp. 07252:104.
- --8012160413 BAW-10145
 Nonproprietary version of "Statistical Core Design Applied to Babcock-205 Core."
 HELLER:A. B., JONES: J. H.: FARNBHORTH, D. A. Babcock & Wilcox Co. 80/10/31. 113pp. 07252:114.
- 8012160503 Informs of recently established policy re communications between C-E Owners Group & NRC.per group request. Owners group submittals will not be applicable to individual licenses until referenced by licenses for use on docket. BASKIN.K.P. C-E Operating Plants Guners Group. 80/12/02. 2pp. 07253:001.
- 8012180510 NUREO-0212 R2
 "Std Tech Specs for C-E PWRs." Revision 2, superseding
 NUREO-0212, Revision 1.
 * Office of Nuclear Reactor Regulation. Director. 80/12/31, 400pp.
 03789: 026.
- BO12190090 Notification of 810128 meating w/util in Bethesda:MD to discuss topical rept in support of core reload licensing. BEROGREN, J. B. Standardization & Special Projects Branch. B0/12/09. 2pp. 07279:118.
- 8012190471 Requests approval of Topical Rept EI/NNI-77-7-P, "RHR-1TM Radwaste Vol Reduction Sys." Affidavit requesting that rept be withheld (ref 10CFR2.770) encl.

 KANNARD, J. R. Newport News Industrial Corp. (subs. of Newport News Shipbuilding & DryDock Co.). 080/MRC/80-202. 80/11/25. 5pp.
- 8012270250 Forwards affidavit describing proprietary nature of info contained in NEDE-24288-P. Affidavit provided on behalf of Mark II Owners Group. Affidavit withheld (ref 10CFR2.770). BUCHHOLZ, R. H. General Electric Co. MFN-214-80, 80/12/11. 1p.
- B012230109 Summary of B00418 meeting w/GE re review of DDYN code. JENSEN.W.L. Reactor Systems Branch. B0/11/20. 4pp. 07316:320.
- 8012230199 Forwards summary re changes made in projects engineering & const organization re CPC-1A GA Program.
 HOFFHAN, D. P. Consumers Power Co. 80/12/19. 2pp. 07314:013.
- 8012230265 Comments on methods & lines of communication re L3-1 test results. Requests meeting w/NRC & E0&O. Inc to discuss Hestinghouse owners group L3-1 results & post-test analyses. JUROENSEN. R.W. Westinghouse Operating Plants Guners Oroup. G9-46. 80/12/03. 3pp. 07312:242.

- 8012230308 Summarizes proposal re utilization of Westinghouse NDTRUMP code as potential means of resulving reactor coolant pump trip issue. Will submit final L3-6 transient using NDTRUMP by B10215.

 JURGENSEN.R W. Westinghouse Operating Plants Guners Group. 00-45. B0/12/03. 2pp. 07311:108.
- B012230467 Objects to issuance of Suppl 2 to IE Bulletin 79-018.
 "Environ Qualification of Class IE Equipment." Recommends withdrawal of new scope items installed due to TMI Lessons Learned. Addl comments encl.
 ANDERSON.T.M. Westinghouse Electric Corp. IEB-79-018. B0/12/10. 3pp. 07313:223.
- 8012230473 Confirms 801127 telcon re proposed method to calculate leak rate from best estimate cracks in RCS. Details & resulting sample calculations will be included in final rept on fracture mechanics work.

 HOCHREITER.L. E. Westinghouse Electric Corp. SE-LEH-385. 80/12/22, 3pp. 07312:284.
- 8012230507 Forwards XN-NF-75-27(A), Suppl 2, "Exxon Nuclear Neutronics Design Methods for PMRs," Dec 1980. GMSLEY, O.F. Exxon Nuclear Co., Inc. (tubs., of Exxon Corp.). OFO:161:80. 80/12/12, 1p. 07314:163
- --8012230511 XN-NF-75-27(A) S2
 "Exxon Nuclear Neutronics Design Methods for PHRs," Dec 1980.
 5K0GEN,F.B., STOUT,R.B., MORGAN,J.N. Exxon Nuclear Go., Inc. (subs. of Exxon Corp.). 80/12/31, 120pp. 07314:164.
- 8012230550 Forwards add1 info requested by NRC 801125 itr re NEDE-23785-P. "QESTR - Model for Prediction of OE HWR Fuel Red Thermal/Mechanical Performance." Affidavit for withholding (ref IOCFR2.790) and 1. HUCHHOLJR.H. General Electric Co. MFN 215-80. 80/12/05. 5pp. 07316:221.
- 8012240312 NUREO-0123 R3
 "STB for OE BHRs (BHR/5)." Supersedes NUREO-0123, Rev 2.
 * Office of Nuclear Reactor Regulation, Director. B0/12/31. 380pp. 07325:276.
- 8012240480 Notification of 801217 meeting w/LLL in Bethesda.MD to kick off contract for review of RCB high point vents.
 ALBERTHAL.O. Reactor Systems Branch. 80/12/12. 2pp. 07324:177.
- 8012240484 Notification of 800114-15 meeting w/vendor to discuss small break LOCA methodology & BHR jet pump LOCA models. OUTTMANN.J. Reactor Systems Branch. 80/12/12. 2pp. 07324:102.
- 8012240509 Notification of 801218 meeting w/vendor & ANL re review of Section 15 in WGAP-9500.

 GUTTMANN.J. Reactor Systems Branch, 80/12/12, 2pp. Q7324:172.
- B012290094 Requests billing of CF Braum & Co for Ofc of Nuclear Reactor Regulation review of B00707 organizational change for TR-21A-0A program. MILLER:M.O. License Fee Management Branch, 80/11/26. 1p. 07346:251.
- B012270261 Forwards add1 info re Bection 4.4 of WCAP-9500, in response to Request 4 transmitted in NRC B01203 ltr.
 ANDERBON.T.M. Mestinghouse Electric Corp., PHR Bystems Div.
 NB-TMA-2335. B0/12/10. 9pp. 07342:329.
- 8012300231 Forwards proprietary & nonproprietary versions of topical rept on TN-220 Radwaste Vol Reduction Sys & application & affidavit for withholding.

 TEER, B. R. Transnuclear, Inc. RW-0037. 80/12/24. ip. 07352:256.
- --8012300239 Requests portion of TN-220 topical rept be withheld (ref 100FR2.790).
 TEER.B.R. Transnucleer, Inc. RN-0036. 80/12/24. 2pp. 07352:288
- --B012300237 TN-RW-101/00-NP Monproprietary version of "TN-220 Radwaste Vol Reduction Sys Topical Rept." | TRANSPORT | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | 1
- B012300482 Forwards NEDU-24823, "Analysis of Two-Loop Test Apperatus Small Break Test Results," on behalf of BHR owners group.:

 8ubmittal satisfies part of NUREG-0578 Requirement 2.1.9.

 8uCHROLZ,R.H. General Electric Co. MFN-218-80, 80/12/27. ip.
 07352:352.

- --B012300486 NEDD-24823

 "Analysis of Two-Loop Test Apparatus Bmall Break Test
 Results."

 HMANG H. S., MARRIOTT, HOOD, J. E. General Electric Co. BONEDD42,
 80/08/31. 62pp. 07352:353
- B012300569 Forwards SCP-01. "Radical Gamma Thermometers as Local Power Measuring Devices for Use in Cores of All PWRs." W/o encl. MORRIS.P.A. Scanpower. Inc. 80/12/23. 2pp. 07346: 220.
- B012300726 Summary of B01202 meeting w/Westinghouse re planned responses to NRC requests for add1 info re WCAP-9500. "Ref Core Rept 17x17 Optimized Fuel Assembly." List of attendoes encl.
 BERGOREN, J. S. Standardization & Special Projects Branch. B0/12/11. 3pp. 07359:291.
- 8012310028 NUREC-0611
 "Ogneric Evaluation of Feedwater Transients & Smoll Break
 LOCAs in Hestinghouse-Designed Operating Plants."

 ** Office of Nuclear Reactor Regulation, Director, 80/01/31, 600pp.
 Available at NTIS. 07363:032.
- 8012310187 Forwards proprietary & nonproprietary versions of "Westinghouse Reactor Vessel Level Instrumentation 8ys for Monitoring Inadequate Core Cooling (7300 Sys)." In response to NOREO-0737. Application & affidavit for withholding encl. ANDERSON.T.M. Westinghouse Electric Corp. NB-TMA-2358. 80/12/23, 9pp. 07374:025
- --BD12310193 Nonproprietary version of summary rept, "Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (73CD Sys)." # Westinghouse Electric Corp. 89/12/31, 78pp. 07374:034.
- --8012310198 Nonproprietary version of summary rept. "Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (Upper Head Injection Plant)." 4 Westinghouse Electric Corp. 80/12/31. 79pp. 07374:112.
- --8012310201 Nonproprietary version of summary rept. "Westinghouse Reactor Vessel Lavel Instrumentation Sys for Monitoring Inadequate Core Cooling (Microprocessor Sys)." # Westinghouse Electric Corp. 80/12/31. 82pp. 07374:191.
- B012310247 Notification of B01222 meeting w/Westinghouse in Bethesda.MD to discuss plans for reviewing & improving small break LOCA methodology.

 GUTTMANN.J. Reactor Systems Branch. 80/12/12. 2pp. 07369:360.
- BO12310252 Notification of B10172 meeting w/C-E in Bethesda, MD to discuss plans for reviewing & improving small break LGCA liceneing codes.

 GUTHARR, J. Reactor Systems Branch. B0/12/12. 2pp. 07370:001.
- B012310496 Forwards request for add1 info on BAH-10120, "LYNX 1.Reactor Fuel Assembly Thermal Hydraulic Analysis Code" & BAN-10130, "LYNX 2.Bubchannel Thermal Hydraulic Analysis Program." TEDESCO.R.L. Assistant Director for Licensing. B0/12/04. 4pp. 07365:224.

WASTE NOT NUCLEAR WASTE MANAGEMENT

- 8012030893 Proposes high density polyethelyne for use as alternative lining mati for new tailings disposal facility. THOMPSON.J.E. Dawn Mining Co. 17834. 80/10/31. 3pp. 07149:242.
- 8012080643 Forwards notice of public hearing on Dawn Mining Co mill talling expansion project. SCR0008.A.C. Washington State of, 80/10/20. 2pp. 07186:361.
- B012080775 Informs of intention of making licensing determination for continued operation of Uravan by B01231 Buggests B01119-21 meating u/NRC to resolve remaining relicensing issues. MAZLE, A. J. Colorado: State of. 17716. B0/10/15. 2pp. 07187:059.
- 8012090053 Responds to NRC request re ownership & easements at mill site. Three deeds & oversize map of site encl.
 THOMPSON, J. E. Dawn Hining Co. 17967. 80/10/20. (4pp. 07246:182.

- 8012120352 Forwards Water Quality Monitoring Rept 8-80. CAIN.J. Cotter Corp. 80/11/05, 5pp. 07236:251.
- B012120074 Responds to final question re tailings area settlement. Tailings distribution sys & planned procedures for reclawation of 3-cell scheme will commence in initial cell while nill operations are underway.

 THOMPSON, M. A. Cyprus Mines Corp. 17879. B0/t1/06. 6pp. 07236:283.
- 8012180443 Application to amend State of CD Radioactive Matl License 150-015, authorizing production of U-238 & associated isotopes & daughter products.

 RANSONE, J. W. Homestate Mining Co. 17997. B0/08/11. 100pp. D7272:
- 8012220405 Responds to 801028 itr requesting description of info obtained by NRC contractors at mill.Data will be forwarded panding ANL info retrieval from computer storage.

 8CARAND.R.A. Uranium Recovery Licensing Branch. 80/12/03. ip. 07301:167.
- --8012220409 Requests description of info obtained by NRC contractors at mill in 1977-78.
 HAZLE, A. J. Colorado, State of. 80/10/28. ip. 07301:168.
- 8012220477 Forwards "Preliminary Executive Licensing Review Summary," evaluating application & environ repts for radioactive matls license. Draft notice of hearing encl.
 HAZLErA. J. Colorado, State of. 17997. 80/11/07. Spp. 07299:047.
- --8012220479 "Preliminary Executive Licensing Review Bummary." * Colorado, State of. 17997, 80/11/06, 79pp. 07299:052.
- 8012230220 Forwards summary of NRC technical assistance to State of NM on Church Rock dam failure contamination. Ofc recommended clean-up criteria, arranged mobile lab onsite to process soil samples & provided svcs of health physicists. DAVIS. J. G. Office of Nuclear Material Safety & Bafeguards. 80/12/92. Spp. 07311:092.
- --8012230224 Confirms B01119 telcon re revision to criteria for cleanup of contamination from Church Rock dam fallure. Revised criteria do not appear to pose unacceptable risk to public health & safety.

 HATTIN J.B. Division of Waste Management. 80/12/02. 2pp. 07311:097.
- 8012240076 Trip rept of 801030-i104 visit to Edgement.8D to observe Edgement cleanup action program. EADIE.0.0. Uranium Recovery Licensing Branch. 80/11/17. ip. 07324:280.
- G012240286 Comments on "Revised Draft EIB for Dawn Mining Co Mill Tailings Expansion Project," Table & maps encl. THOMPSON, J. E. Dawn Mining Co. 80/11/21. 10pp. 07328:198.
- B012240289 Discusses "Revised Draft EIS-Proposed Dewn Mining Co Mill Tailings Expansion Project." Beveral items questionable or contradictory Draft w/ARC input is much improved in content. MENORICKS.D.W. Environmental Protection Agency. 17946. B0/11/13. 5pp. 07328:193.
- 8012240303 Evaluates environ impact on ground water by seepage from existing tailings pond at Dawn mill. Detailed resistivity survey should be conducted over area prior to implementation of withdrawal sys if such withdrawal sys deemad desirable. WILLIAMS,R.E. Affiliation Unknown. 17964. 80/10/15. 6pc. 07328:187.
- 8012240437 Forwards rept from Golder Associates re differential settlement question at new tailings disposal facility. W/o encl.
 THCHPSON, J. E. Dawn Mining Co. 17947. 80/11/11. 1p. 07328:060.
- 8012290224 Responds to NRC request to provide background on decision to recommend use of high density polyethylene as alternative mati for liner. Polyethylene resistant to leaks, saturated w/carbor black & less expansive to use.

 WILLIAMS, R. E. R. E. Williams & Associates, Inc. 17966, 80/11/20, 2pp. 07345:175.
- 801230028B Responds to 801031 ltr re use of alternative synthetic lining meth for planned below-grade tailings disposal area. Lining meth change recommended. SCARAMOR R.A. Uranium Recovery Licensing Branch. 80/12/03, ip. 07346:177.

- XPORTLIC EXPORT AND IMPORT LICENSES
- 8012020150 Forwards Executive Branch response on pending application for license to export highly enriched U to Yugoslavia. Requests prompt review of response to facilitate early reply to Commission action paper. W/o enci.
 SHEA. J. R. Defice of International Programs, Director. 80/11/14.
 1p. 07142:089.
- 8012020184 Informs that Cf-252 cermet wire will be repacked in sealed source & used in France for electrical board reactors.

 * Transnuclear, Inc. 80/11/12. 1p. 06916:001.
- BO12020214 Requests Amend I to export license, adding two utilization facilities.
 HERSCH.M.M. Westinghouse Electric Corp. IL8-015. 80/11/11. 2pp. 07142:099.
- 8012020233 Confirms telcon notifying that one Pegasa Cask 1, containing 36 irradiated fuel elements, is scheduled to arrive in Portsmouth. VA on 801027.
 STONEBURNER, W. Transnuclear, Inc. 17667. 80/10/14. ip.
- 8012020243 Confirms notification that TN-7 Cask containing 60 irradiated fuel elements is scheduled for arrival in Portsmouth, VA on 801029.

 8TONEBURNER, W. Transnuciear, Inc. 17668, 80/10/15, 1p.
- B012020280 Confirms telcon notifying that Pegase Cask 4 containing one irradiated fuel element is due to arrive in Portsmouth, VA on 801027.

 STONEBURNER, W. Transnucteur, Inc. 17661. 80/10/09. 1p.
- 8012020317 Application by Transnuclear Inc for license to export 34.900 kg U.containing 1.159 kg U-235 to West Germany.

 * Transnuclear Inc. R8U 354-80-230. 80/10/24. 3pp. 07143:110.
- 8012020322 Application by Transnuclear, Inc for license to export 131.600 kg U.containing 4.473 kg U-235 to West Germany. MATSON.V. Transnuclear, Inc. RBU 351 80-231/. 80/10/24. 4pp. 07143:116.
- BO12020327 Forwards application for license to export 19,412 kg U. containing 650 kg U-235, to Wast Germany. BUTERMO,T. Transnuclear, Inc. 80/11/04. ip. 07143:121.
- --8012020331 Submits addl info for records re delivery of product. MARSON, V. Transnuclear, Inc. 80/11/06, ip. 07143:122.
- --B012020335 Application by Transnuclear Inc for license to export 19,412 kg U.containing 650 kg U-235, to West Germany. End use statement encl.

 * Transnuclear, Inc. RBU 355 80-236/. 80/11/04. 3pp. 07143:123.
- 8012020472 Forwards SNM security routing received from Tri-State Motor Transit Co for review as addendum to 800904 ltr. Info withheld (ref 10CFR2.790).

 MATSUN.V. Transnuclear, Inc. 17501. 80/09/24. 2pp. 07148:132.
- 8012020477 Provides initial notification of moderate strategic significance shipment of 4.66 kg U-235 contained in 5.0 kg U metal to Japan Info withheld (ref 10CFR2,770).

 * Transnuciear, Inc. 17502. 80/09/24. 2pp. 06916:001.
- 8012030701 Responds to 801023 ltr re C-E applications to export components for Atucha II nuclear power plant in Argentina. Executive Branch review underway when applications were withdrawn. Chronology of NRC activity re applications encl. DIRCKS-M. J. Office of the Executive Director for Operations. 80/11/12. 2pp. 07131:221.
- --8012030708 Responds to 800527 ltr re C-E applications to export components to Atucha II power plant in Argentina NRC following nuclear-related developments in Argentina & will act on applications upon receipt of Executive Branch views. SHEA. J. R. Office of International Programs, Director. 80/06/19. ip. 07191;223.
- --8012030714 Discusses efforts to gain US govt approval of applications to export components to Argentina Contracts lost due to govt dalays.

 SCH4172.H.K. Combustion Engineering, Inc. 80/07/16. 2pp. 07/51:224.

- --8012030717 Forwards C-E 800527 ltr re applications to export components to Atucha II nuclear power plant in Argentina. Requests rept on stated problems. WARNER. J. W. Benate, 80/10/23 5pp. 07131: 226.
- B0120307/3 SECY-80-512
 Informs Commission of fevorable Executive Branch position on two pending export license applications, XSNM-1425 & XSNM-1427.
 DIRCKS/N.J. Office of the Executive Director for Operations. 80/11/19. 1p. 03788:174.
- 8012050627 Submits findings re GE 801107 application for license to import 2,000 kg U, enriched to 3.8% U-235, from Italy. License should be granted.

 MCDRE, R.N. Assistant Director for Export/Import & International Safeguards. 80/(1/19. 1p. 07172:027.
- --80(205063) License for GE to import 2,000 ig U,enriched to 3.8% U-235, from Italy.
 DEVINE, J.B. Office of International Programs, Director. 80/11/19.
 1p. 07172:028.
- 8012080040 Responds to 801118 telcon Discusses reasons for increase in number of absorber tubes required for export. Requests liteness be revised to permit 874 tubes. PARSONS, W. B. Par Systems Corp. 80/11/19. 1p. 06586:003.
- 8012080054 License for Edlow Intl Co to export .127 g U 235, enriched to 1.5223% U-235, to Japan.
 DEVINE: J.B. Assistant Director for Export/Import & International Safeguards. SHIB 8 8-97-80. 80/11/25. 2pp. 04588:003.
- 8012080067 License for Mitsubishi Intl Corp to export .81 g U-235, contained in eight hoke tubes & 41.59 g depleted U, in four hoke tubes to Japan.
 DEVING.J.B. Assistant Director for Export/Import & International Safeguards. HSA-6702-01. 80/11/25. Epp.
- 8012080086 License for Aldrich Chemical Co to export 5 kg deuterium oxide to Venezuela. DEVINE.J.B. Assistant Director for Export/Import & International Befeguards. 23/80. 80/11/25. 2pp. 06586:003.
- 8012080097 Informs that export application for Kearsarge Metallurgical Corp meets requirements of Atomic Energy Act. Normal 13-day waiting period waived. DEVINE. J. S. Assistant Director for Export/Import & International Bafeguards. 80/11/25. 1p. 06384:003.
- --8012080104 License for Kearsarge Metallurgical Corp to export 750 sets of tie plate castings to West Germany.
 DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/11/24. 1p. 06586:003.
- 8012080112 Requests Executive Branch position re Westinghouse amend request extending expiration date of License SR-003 to Dec 31, 2021.

 DEVING.J.B. Assistant Director for Export/Import & International Safeguards. 80/11/21. 1p. 07194:183
- B0120B0132 Executive Branch position re Dept of Navy application for license to export 375,000 rounds of 20 millimeter penetrator ammunition; containing 2%,000 kg deplated U, to Saudi Arabia. License should be issued.

 NOSENZO,L.V. State, Dept of, Bureau of Oceans & Internati, Environ. & Scientific Affairs. B0/11/21 1p. 07174:181.
- 8012080138 Amend 2 to license for GE, extending expiration date from 810101 to 840101.
 DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. TK22R1. 80/11/25. 1p. 06586:003.
- 8012080144 Amend 2 to license for GE, extending expiration date from 810101 to 940101.

 DEVINE, J.B. Assistant Director for Export/Import & International Safeguards. T-R7. 80/11/25. ip. 06586:003.
- 8012080150 Amend I to license for GE extending expiration date from 801201 to 810701.
 DEVINE.J.B. Assistant Director for Export/Import & International Safeguards. BDV 77225. 80/11/25. 1p. 06986:003.
- 8012080157 License for Dept of Navy to export 25,725 kg depleted U in 375,000 rounds of 20 millimeter amounition to Saudi Arabia. DEVINE, U.S. Assistant Director for Export/Import & International Safeguerds. 63/374519. 80/11/2(, 2pp. 06586:003.

- B0120B0166 License for Edlow Intl Co to export 3,790 kg depleted U.in form of U tetrafluoride, to United Kingdom DEVINE, J.B. Assistant Director for Export/Import & International Safeguards. B0/11/20. 2pp. 07194:221.
- 8012080639 Application by Reuter-Stokes.Inc for license to export Model RS-C3-2510-114 fission chamber to Hest Germany. EECKHOUT, A. Reuter-Stokes, Inc. N-8785. B0/11/05. 1p. 07176:106.
- 8012080647 Application by Sigma Chemical Co for license to export aquivalent of 10 tg deuterium oxide liquid to Indía.

 STERI, W.C. Sigma Chemical Co. (subs. of Sigma-Aldrich Corp.). D-60.

 80/11/21. ip. 07196:107.
- 8012080769 SECY-80-519
 Forwards Executive Branch position recommending approval of application by OA Co to export 1.372 g U.enriched to 70% U-235 to Yugoslavia.
 DIRCKB.R. J. Office of the Executive Director for Operations. 80/11/19. 1p. 03767:063.
- --B012080770 Furwards application for export license. HOURY, U. R. General Atomic Co. (subs. of Gulf Dil Co.), IEL-858. 77/11/16. 2pp. 93767:065.
- --8012080778 Application for license to export 1,372 g U.enriched to 70% U-235 to Yugoslavia, End use statement encl. MDNRY.W.R. General Atomic Co. (subs. of Gulf Qil Co.). IEL-858. 79/11/16. 2pp. 03767:067.
- GO120B0B00 Approves application by Graham Mfg Co. Inc for license to export pump by-pass cooler & return cooler & supply heaters to Korea. License issued a/o customary 15-day waiting period due to urgency of export.

 DEVINE. J. B. Assistant Director for Export/Import & International Safeguards. GO/11/37, 1p. 07196:217.
- --B0120B0807 License for Graham Hfg Co.Inc to export pump by-pass cooler & return cooler & supply heaters to Korea.

 DEVING.J.B. Assistant Director for Export/Import & International Safeguards. B0/11/17. 2pp. 07176: 218.
- 8012070257 Informs that due to anticipated licensing delays, different intermediate storage facility in Germany will be utilized. Review & approval of change requested. HAYSEN, L. E. Exxon Nuclear Co.: Inc. (subs. of Exxon Corp.). B0/11/24. ip. 07202:345.
- B012090534 Amend i to license for Fransnuciear, Inc.extending expiration date to 820101.
 DEVINE,J.B. Assistant Director for Export/Import & International Safeguards. Ft라 300 79~116. 80/12/01. ip. 07206: 224.
- 8012090537 License for Bandvik Special Metals Corp to export Zircalov-4 Caterpillar thimble tube to Japan. DEVINE.J.B. Assistant Director for Export/Import & International Bafeguards. D3-6-78. 80/12/01. 1p. 07187:001.
- 8012090542 License for Bandvik Special Metals Corp to export zirconiumniobium seamless tubing to Canada DEVIKE.J.B. Assistant Director for Export/Import & International Safeguards. 80/12/01. jp. 07187:001.
- 8012070546 Amend 1 to license for Timex Corp. extending expiration date to 811101.

 DEVIRE-J.B. Assistant Director for Export/Import & International Safeguerds. 80/12/01. 2pp. 07187:001.
- 8012090549 Amend I to license for Transnuclear, Inc. extending expiration date to 820801.

 DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. NUK-277 7911970. 80/12/01. 1p. 07187:001.
- 8012100012 Forwards ltr from Transnuclear, Int requesting cancellation of 801001 amend to License XSNM-1345.
 DEVINE.U.S. Assistant Director for Expart/Import & International Safeguards. 80/12/01. 1p. 07217:062.
- 8012100962 Application by Mitsubishi Inti Corp for license to export six reactor vessel irradiation surveillance test capsules containing 120 mg Np-237.86 mg U-398 & 72 mg U-238 KW3E.T. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). 64-7370-80. 80/11/25. ip. 07219:087.
- 8012100182 Application by Sydkraft for license to import 138,991 kg U-308 from Canada. WINGREN.H. SydKraft Aktiebolag Sweden. 80/11/11. 3pp. 07218:236.

- 8012100197 Requests Executive Branch position re Transmuclear, Inc application for license to export SM to West Germany. DEVINE, J.B. Assistant Director for Export/Import & International Safeguards. 80/11/21. 1p. 07218:280.
- 8012100201 Requests Executive Branch position of Ediow Intl.Co application for license to export SNM to France, DEVINEY.J.B. Assistant Director for Export/Import & International Safeguards. 80/11/21. ip. 07218:281.
- B012100204 Requests Executive Branch position re Transnuclear, Inc application for license amend decreasing quantity of exported mati from 5.72 kg U to 2.353 kg U. DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. B0/II/21. ip. 07218:284.
- B012100210 Requests Executive Branch position re Transnuclear, Inc application for license to export SMM to Switzerland. DEVINE, J. R. - Assistant Director for Export/Import & International Safeguards. B0/11/21. 1p. 07217:303.
- 8012100216 Erecutive Branch position re Mitsubishi Intl Corpapplication for license to export 0.81 g U-235, contained in 83.18 g U-to Japan. Etr of essurance encl. License should be granted.

 NOSENZO, L. V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 80/11/18. 3pp. 07217:312.
- S012100222 License for Radiation Mgt Corp to export two power range detector assemblios. Model WL-23686 & addl miscellaneous parts for use in nuclear reactors to South Korea. BEVINE.J. B. Assistant Director for Export/Import & International Safeguards. B0/11/21. (p. 07217:315.
- 8012100230 Forwards Executive Branch responses on three pending export license applications, original applications & related correspondence. Requests response as soon as possible. Wo encl.
 SHEA. J. R. Office of International Programs, Director. 80/11/21, ip. 07217: 321.
- 8012100235 Forwards self-explanatory Executive Branch views on three pending export applications. Commission action paper is being prepared. W/s enci. SH2A.J.R. Office of International Programs, Director. BO/11/21.ip. 07218:132.
- 6012100427 License for Sigma Chamical Corp to export 10 kg deuterium oxide to Italy.

 DEVINE.J.B. Assistant Director for Export/Import & International Safeguards D-6.2. 80/12/03. 2pp. 07187:001.
- 8012100428 Notifies of delay in completing licensing actions on applications due to need for addl info re matl fabrication. SKEA.J.R. Office of International Programs. Director. 80/11/28. ip. 07218:020.
- 8012100436 Application by Eberline Instrument Corp for license to export certified Fu-237 alpha calibr std Model DNS-218 to Canada.

 JCHNS70L.N.R. Eberline Instrument Corp. 50 874041. 80/10/07. 1p. 07218:027.
- 8012100437 Requests Executive Branch position re PAR Gys Corp application for amend to license to increase quantity of neutron absorber tubes exported W/o encl 801117 teles. DEVINELUS. Assistant Director for Export/Import & International Safeguards. 80/(1/26, 1p. 07218:028
- 8012110320 Forwards application by Transnuclear, Inc for license to export 20,894.34 kg U.enriched to max 3 53% U-235, to Suitzerland.
 BUTENMO, T. A. Transnuclear, Inc. 80/11/12. 1p. 07223:124.
- --8012110024 Application by Transnuclear, Inc. for license to export 20,893.34 kg U.enriched to max 3.55% U-235, to Switzerland. BUTERKO, T. A. Transnuclear, Inc. B0-241/01 RBU-3, B0/11/12, 2pp. 07223:126.
- 8012110031 Application by Sigma Chemical Co for license to export equivalent of 10 kg deuterium oxide liquid over 2-yr period to Australia STERM.W.C. Sigma Chemical Co. (subs. of Sigma-Aldrich Corp.). D 58. 80/11/12. ip. 07224:311.
- 80(2(10035 Requests Eracutive Branch position re Univ of CA application for license to export small amounts of tritium to countries involved in joint research projects u/univ & for use by univ personnel working abroad.

 DEVINE. J. B. Assistant Director for Export/Import & International Safeguards. 80/11/18. 1p. 07224:310.

- 8012110072 Requests Executive Branch position re Transnuclear, Inc application to amend license, increasing quantity of natural U from 129.224 to 146,100 kg. W/o ercl 801105 ltr. DEVINE.J. B Assistant Director for Export/Import & International Safeguards. 80/12/01. 1p. 07223:147.
- 8012i10074 Executive Branch position re Timex Corp application for extension of license to export 400.000 Ci tritium to Philippines & Singapore. License should be extended. NGSENZOLL.V. State-Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 80/11/25. 2pp. 07223:148.
- 8012(10103 Executive Branch position re Nissho-Iwai American Corpapplication for license to export 650 kg heavy water to Japan for use as moderator & coolant.License should be granted.

 NOSENZO, L. V. State, Dept. of, Bureau of Oceans & Internati. Environ. & Scientific Affairs. 80/11/26. 2pp. 07223:153.
- B012110115 Ltr of assurance re Marubeni America Corp application for license to export 485 kg U-235, contained in 18,491 kg U, to Japan, MIYABAYASHI, M. Japan. 80/10/07. ip. 07223:159.
- 8012110165 Requests extension of expiration date on license to 820101. BUTENKO, T. A. Transnuclear, Inc. 80/11/03. 1p. 07223:170.
- 80:2110169 Requests amend to license extending expiration date from June 1981 to June 1982. MATSON, V. Transnuclear, Inc. 80/11/19. 1p. 07223:171.
- B012110367 Requests Executive Branch position re Westinghouse application for amend to license to extend expiration date.

 H/G encl B01031 ltr.

 DEVINE, J, B. Assistant Director for Export/Import & International Safeguards. B0/11/26. ip. 07223:227.
- 3012120546 Forwards FR notice of license application to export/import nuclear facilities or matis.

 CHILK.S. J. Office of the Secretary of the Commission. 80/10/16.

 1p. 07228; 244.
- --8012120540 Forwards FR notice of applications for licenses to export/import nuclear facilities or matls.

 5HEA: J.R. Office of International Programs, Director. 80/10/07.

 19. 07228:245.
- --B012120693 Notice of license applications to export/import nuclear facilities or matis, SHEA, J. R. Office of International Programs, Director. 80/10/07, 1p. 07228:246.
- 8012160640 License for Chase Brass & Copper to export 250 lb sirconium 2.5% niobium ailou extruded tubes to United Kingdom. DEVINE. J. B. Assistant Director for Export/Import & International Safeguards. 80-4083. 80/12/05. ip. 07254:330.
- B012160647 Executive Branch position re Edlow Intl Co application on behalf of Redio Chemical Ctr to re-export 3.7 mg Cf-252 to India License should be amended.

 NDSENZO,L.V. State, Dept. of, Eureau of Oceans & Internati, Environ. & Scientific Affairs. B0/12/04. ip. 07254:331.
- 8012160746 Licenso for Transnuclear, Inc to export 2,002 mCi Cf-252 to France. DEVINE.J.B. Assistant Director for Export/Import & International Safeguards. TNP 356 80-238. 80/11/28. 2pp. 07261:325.
- GO12160/95 Requests Executive Branch position re Westinghouse application for license to export two addl power reactors to Gouth Korea, W/o entl BO11[1 application.

 DEVINE. J. B. Assistant Director for Export/Import & International Gafeguards. BO/12/04. ip. 07261; 327.
- BO12170242 Requests Executive Branch position re Harubeni American Corp application for license to export SNM to Japan. DEVING.J. II. Assistant Director for Export/Import & International Safeguards, 80/12/09. ip. 07268:211.
- B012170245 Forwards application for export license for minor nuclear export.Ltr of assurance required.W/o encl. DEVING.J.B. Assistant Director for Export/Import & International Safeguerds. B0/12/09. 1p. 07268:212.
- 8012170248 Requests Executive Branch position re Overseas Bechtel, Inc application for license to export CP-252 to Taiwan, DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/09. 1p. 07248:215.

- 8012170254 Executive Branch position re Commonwealth of Australia application for license to export 650 kg heavy water to Australia. Ltr of assurance sncl. License should be granted. HOSENZO, L.V. Btate, Dept. of, Bureau of Oceans & Internati. Environ. & Scientific Affairs. 80/12/03 2pp. 07187:001.
- 80:2170255 Executive Branch position re PaR Metal Bellows Corp application for amend to license increasing number of neutron absorber tubes to be exported to Spain. Amend should be granted.
 NDSENYOLV, State. Dept. of. Bureau of Oceans & Internatl Environ. & Scientific Affairs. 80/12/05. 1p. 07268:220.
- 8012170297 Executive Branch position re Transnuclear, Inc application for license to export 2.009 kg of U-235, contained in 4.416 kg U-to Bultzerland.
 NGSENTO, L.V. State, Dept. of, Bureau of Oceans & Internati, Environ. & Scientific Affairs. 80/11/19. 2pp. 07268: 224.
- BO12170261 Requests Executive Branch position to C-E application for license to export components to India.W/o encl BD1114 application. DEVINE.J.B. Office of International Programs, Director. BO/(1/24.ip. 0/268:232.
- 8012170264 Executive Branch position re Boeing Co application for amend to license to export max of 1,000 lb per consignee or 10,000 lb per country, of depleted U. Amend should be granted. NOSERNIO, L. V. States Dept. of
- 8012170265 License for Reuter-Stokes, Inc to export fiesion chamber. Reuter-Stokes Model RS-C3-2310-114, to West Germany. DEVINE, J. 8. Assistant Director for Export/Import & International Safeguards. W-8765. 80/12/09. 1p. 07187:001.
- 8012170269 License for Matheson Gas Products to export 180 g deuterium, contained in Number 2 cylinder, to Australia. DEVINE, J.B. Assistant Director for Export/Import & International Safeguards. 101-17399. 80/12/09. 2pp. 07268:242.
- 8012170270 Forwards application for license to export nuclear matl & equipment to West Oermany.

 HANSEN,L.E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

 80/12/03. 1p. 07268:249.
- --8012170273 Application by Exxon Nuclear Co.Inc for license to export nuclear fuel element hardware including fuel rod hardware & cage assemblies to West Cormany.

 HANGENILE. Exxon Nuclear Co., Inc. (subs., of Exxon Corp.).

 80/12/01. 1p. 07268:250.
- 8012170272 Informs that since no mati changed circumstances exist since issuance of License X8NM-1495.License X8NM-1705 may be issued.

 MODRE, R. N. Assistant Director for Export/Import & International Bafeguards. 80/12/04. 1p. 07187:001.
- --8012170277 License for Marubani American Corp to export 3.486 kg U-235, contained in 156.333 kg U, to Japan.

 DEVINE.J.B. Assistant Director for Export/Import & International Bafeguards. SK-1169/ZK0170. 80/12/09. 2pp. 07187:001.
- 8012170280 Forwards application for license to export nuclear matl & equipment to West Germany.

 HANSEN.L.E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

 BO/12/02. ip. 07268:263.
- --8012170287 Application by Exxon Nuclear Co. Inc. for license to export spacer assemblies, fuel rod hardware, tie plates & miscellaneous assembly hardware to West Germany, HAMSEN.L.E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 80/12/01. 1p. 07268:264.
- 8012170292 Application by Teledyne Wah Chang Albany for license to export 4.409 ib Zircaloy-2 trex to Uest Germany. AERNI.B.L. Teledyne Wah Chang Albany. 80/12/01. ip. 07268:332.
- 8012170296 Application by Sigma Chemical Co for license to export 10 kg deuterium oxide over 2-ur period to Switzerland.

 BTERNIH.C. Sigma Chemical Co. (subs. of Sigma-Aldrich Corp.). D 64.

 B0/12/01. 1p. 07268:310.
- 8012170305 Application by Sigma Chemical Co for license to export 10 kg dauterium oxide over 2-yr period France.
 STERN, N.C. Sigma Chemical Co. (subs. of Sigma-Aldrich Corp.). D-63.
 GO/12/01. ip. 072681323.

- 8012170311 Application by Teledyne Nah Chang Albany for license to export 22,046 lb Zircaloy-2 tube shell to West Germany.

 ARRNI, B. L. Teledyne Wah Chang Albany. 3481 (JFM). 80/12/01. ip. 07268:331.
- 8012170317 Submits application to amend license changing intermediate consignee.
 VANANA, K. Nissko-lwai American Corp. 80/12/02. ip. 07268:343.
- 8012170325 Submits application to amend license extending expiration data from B01231 to 811231.

 HANSEN.L E. Exzon Nuclear Co. (Inc. (subs. of Exxon Corp.), B0/12/01 1p. 07268:352.
- 8012170331 Bubmits application to import 530 kg U-235.contained in 21.600 kg U-from West Germany. HANSEN.L.E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/12/02. 3pp. 07268:358.
- 8012170388 Ltr of assurance re Transnuclear. Inc application for license to export 2.005 kg U-235, contained in 4.416 kg U to Switzerland. Delegation of Commission of European Communities 80105 ltr of assurance enct.
 MULLER.R.E. Switzerland. 80/10/08. 2pp. 07270:187.
- 8012170393 Approves issuance of License X5NM-1713. MODRE, R. M. Assistant Director for Export/Import & International Bafeguards. 80/11/26, 1p. 07270:189.
- B012170459 Litense for QE to export 265 kg U-235.contained in 9.675 kg U as U-dioxide power.to Japan DEVINE.J.B. Assistant Director for Export/Import & International Bafaguards. BDW 80104. B0/12/09. 2pp. 07187:001.
- 8012180269 License for Eberline Instrument Corp to export 0, 10 microgram Pu-239, certified Pu-239 alpha calibr std. Model DNS-215, electroplated on 3/4-inch diameter stainless steel disc. to Canada.

 DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. S. 0, 874041. 80/12/10. 2pp. 03768, 001.
- 8012180275 License for Sigma Chemical Co to export 10 kg deuterium oxide to France.

 DEVINE.J.B. Assistant Director for Export/Import & International Bafaguards. D-63. 80/12/11. 2pp. 03768:001.
- 8012180280 License for Westinghouse to export two self-powered neutron assemblies. Model HX 32964. to Nest Germany.
 DEVINE, J. B. Assistant Director for Export/import & International Safeguards. ZE-10347. 80/12/09. ip. 03768.001.
- 8012180327 SECY-80-520
 Forwards Executive Branch response to pending export applications XSNM-1725 XSNM-1726 & KBNM-1727, original applications & related correspondence.

 DIRCKB.N.J. Office of the Executive Director for Operations. 80/11/21. pp. 03794:064.
- 8012180382 Requests license to export 400 sets of machined tie plate castings to West Germany. POKPIAN.S. Kearsarge Metallurgical Corp. 80/11/06. 2pp. 03768:001.
- 8012180416 SECY-80-523
 Requests authorization for issuance of proposed export
 License XCQM-0915 & authorization for staff to process
 future similar licenses for exports destined for Cernavoda
 Nuclear Power Btation w/o Commission referral.
 DIRCKS, W.J. Office of the Executive Director for Operations.
 80/11/28. 4pp. 03794:267.
- 8012190026 Application by OE for license to export 690 g U dioxide.of various entichments.to Italy. WILBON, B.D. General Electric Co. BDN 80130. 80/11/25. ip. 07278: 210.
- B012190029 Application by GE for license to export 650 g U dioxide as U powder to Japan.
 WILBON B. D. General Electric Co. BDW 80131. B0/11/25. ip. 67279:211.
- 8012190605 Forwards IE Ensp Rept 110-542/80-01 on 801020-22.No noncompliance noted. KENNA, M. B. Region 2, Atlanta, Safeguards Branch. 80/12/03. ip. 07288: 243.

- --B012190609 [E Insp Rept 110-542/80-01 on B01020-22, No noncompliance noted. Hajor areas (inspected: Intransit physical security measures. Details withheld (ref 10CFR2, 790).

 TOBIN, M. J., HILL, A. O., HONELL, J. Region 2, Atlanta, Office of the Director, 80/12/02. 1p. 97288: 244.
- 80(2220(35 Application by Nuclear Transport & Storage, Inc. to amend license to include import of depleted U metal castings from Canada. JODY, B. Huclear Transport & Storage, Inc. 80/11/17. 2pp. 07303:232.
- 8012220471 Ltr of assurance for export of 265 kg U-235.contained in 9.675 kg U.to Japan Atomic Power Co.inc as fuel for reactor. MIYABAYASHI.M. Japan. 80/11/21, lp. 07301:192.
- 8012220473 Requests that Transnuclear, Inc be listed as agent for EURATUM for shipment of matl under License XBNM-1425. MATSUN.V. Transnuclear, Inc. 79-046/01. 80/12/09. 1p. 07299:046.
- 8012220900 Forwards Intl Customs Svc.Inc 801119 ltr & CERN 801202 ltr requesting amond to export license. Requests input re increasing amount of U exported & extending expiration until 811231. W/o encls.

 DEVIKE. J. B. Assistant Director for Export/Import & International Safeguards. 80/12/11. ip. 07279:221.
- 8012230083 Requests Executive Branch position re Belfab Bailey Controls to application for license to export bellow control rod seals to India BEVINE.J.B. Assistant Director for Export/Import & International Safeguards. 80/12/09. 1p. 07313:253.
- B012230086 Requests Executive Branch position re Nissho-Iwaí Corpapplication to amend license to change name of intermediate consignee.

 DEVINE. J. B. Assistant Director for Export/Import & International Bafeguards. B0/12/16. 1p. 07313:254.
- 8012230091 Amend 1 to import license for Exxon Nuclear Co.Inc.extending expiration date from 801231 to 811231.

 DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/16. 1pp. 07313:255.
- 8012230074 Requests Executive Branch position re Exxon Muclear Co. Inc application for license to export SMA to Hest Germany. DEVINE.J.B. Assistant Director for Export/Import & International Safeguards. 80/12/16. ip. 07316:308.
- B012230197 Forwards application for license to export ENH & related fuel hardware to West Germany for two ennual reloads of Biblis A reactor, HANSEN, L. E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). B0/12/03. ip. 07317:032,
- --8012230204 Application by Exron Nuclear Co.Inc for license to export 1.670 kg U-235 contained in 49.200 kg U to West Garmany. HANSEN, L. E. Exron Nuclear Co., Inc. (aubs. of Exxon Corp.). 80/12/03. 1p. 07317:032.
- B012230202 Forwards application by Mitsubishi Intl Corp for license to export 8, 116 kg U-containing 256 kg U-235, to Japan. SHIMA.8. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5480-11. B0/11/10. 3pp. 07317:034.
- --8012230206 Application by Mitsubishi Intt Corp for license to export 8:116 kg U-containing 256 kg U-235; to Japan End use statement enci.
 SHIMA: S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5480-11. 80/11/10. 2pp. 07317:037.
- 8012230208 Submits application to amend export license, changing intermediate consignee to NUKEM GmbH.
 DEVINE, J. 8. Assistant Director for Export/Import & International Safeguards. S0/12/01. ip. 07317:050.
- 8012230210 Submits application to extend expired License XCOM-0314 to 800228 Classified as new license request. SHEAMLLIS. Chase Brass & Copper Co., Inc., Chase Nuclear Div. 80/f1/14. 2pp. 07317:051.
- B012230212 Application by Sigma Chemical Co for license to export compounds containing 10 kg deuterium exide to India. STERM.U.C. Sigma Chemical Co. (subs. of Sigma-Aldrich Corp.). D-61. B9/11/24. 1p. 07317:039.
- B012230235 Application by Nissho-Iwai American Corp for license to export 1.87 Ct Cf-252 contained in sealed neutron radiation source to Japan.

 * Nissho-Iwai American Corp. GBH-1252. 80/11/21. 1p. 07317:312.

- 8012230237 Forwards application for export license for minor nuclear export. Ltr of assurance required W/o encl. DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/01. lp. 07317:319.
- BO12240149 Requests license to import small quantities of nonirradated archive pellets for examination in high burnup effects program.

 HENRY, H. L. Bettelle Momorial Institute, Pacific Northwest Laboratory, 80/11/25, 5pp. 07187:001.
- B012240218 Executive Branch position re Seamodal Transport Corpapplication for license to export 440 NBS U stds & 172 NBS PU stds camprising 3.166g U-235.in 5B0g U.ta Belgium. License should be issued. Ltr of assurance encl. NDSEMZO.L.V. State.Dept.of. Bureau of Oceans & Internatl. Environ & Scientific Affairs. B0/12/04. 3pp. 07325:068.
- 8012240315 Amend 3 to license for OE.extending expiration date from 810101 to 840101.

 BEVING. J. B. Assistant Director for Export/Import & International Bafeguards. BDW 80/22. 80/12/03. 2pp. 07183:001.
- 8012240317 Informs of Reuter-Stokes. Inc request for expeditious processing of proposed license to export components to France. License issued w/o normal 15 day waiting period. DEVING. J. B. Assistant Director for Export/Import & International Safeguards. 80/12/04. ip. 07325;136.
- --8012240319 License for Reuter-Stokes, Inc to export three miniature fission chambers, Model R8-C4-0201-231, to France.

 DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. GE-8132. 80/12/04. 1p. 07325:137.
- 8012240326 Application by Reuter-Stokes, Inc for license to export three Model RS-C6-0201-231 miniature fission chamber units to France. EECKHOUT.A. Reuter-Stokes, Inc. QE-8132, 80/11/25, 1p. 07183:001.
- B012240329 License for Sigma Chemical Co to export 10 kg deuterium oride to Canada.

 DEVING. J. B. Assistant Director for Export/Import & International Gafeguards. D-57. B0/11/28. ip. 07183:001.
- B012240340 Application by Overseas Bechtel, Inc for license to export 25 microgram Cf-252, Type A. to Talwan, DICK, M. E. Bachtel Corp. 9713-N-10B. 80/12/01. ip. 07187:001.
- 8012240332 Forwards application to export 20 bellows control rod seals to India.

 MERINGER, J.H. J. Ray McDermott & Co. 80/11/24, 1p. 07187:00L
- --B012240356 Application by Belfab Bailey Controls Co for license to export 20 bellows control rod seals to India.

 * Bailey Controls Co. (subs. of Babcock & Wilcox Co.). 001-026A.
 B0/11/25. 3pp. 07107:001.
- B012240361 Application by Sigma Chemical Co for license to export equivalent of 10 kg deuterium oxide over 2-yr period to India.

 STERN.H.C. Bigma Chemical Co. (subs. of Sigma-Aldrich Corp.). D-59. B0/11/14. ip. 07325:141.
- B012240364 License for Nissho-Iwai American Corp to export 660 kg heavy water to Japan.
 DEVINE, J. B. Assistant Director for Export/Import & International Bafeguards. HIM-0210. 80/12/04. 2pp. 07325:142.
- BO12240367 License for Bigma Chamical Co to export 10 kg deuterium oxide to Australia.

 DEVING.J.B. Assistant Director for Export/Import & International Safeguards. D-58. B0/12/02. 2pp. 07187:001.
- 8012240375 Forwards application for license to export SNM, Pu sulfate tetrahydrate & Pu to Japan. End use statement encl.

 OKUDA: H. Marubeni America Corp. (subs. of Marubeni Corp.).

 MA1-HO-6239. 80/11/21. ip. 07187:001.
- --8012240380 Application by Marubeni America Corp for license to export 59.75 g Pu & Pu sulfate tetrahydrate to Japan.

 **Marubeni America Corp. (subs. of Marubeni Corp.), ZHO158-OW.

 **G9/11/21. 3pp. 07187:001.
- 8012240392 Application by Westinghouse for license to export 2 Units WK32964 to West Germany. POCHAL-M.F. Westinghouse Electric Corp. 2E-10347. 80/11/18. ip. 07325:145.

- 8012240398 Application by Matheson Gas Products for license to export 1,000 liters chemically pure deuterium, contained in Bize 2 cylinder, to Australia.

 Matheson Gas Products. 101-17359. 80/11/14. 1p. 07323:131.
- 8012290534 Petition for leave to intervene & request for hearing. Requests USOS volcanic & seismic assessment & study of global impact. Supportive documentation encl. MATTISON, O. L. Center for Development Policy, 80/12/09, 25pp. 07335:182.
- 8012290585 SECY-80-534
 Summarizes status of application by GA Co to export research reactor to Malaysia. Recommends license be issued. DIRCKS, H. J. Office of the Executive Director for Operations. 80/12/10. App. 07335:301.
- --B012270587 Responds to B00211 memo re plans to provide one TRIGA MARK II research reactor & SNM to Malaysia DDE should modify proposal to show physical protection info being given on bilateral basis. BHEA.J.R. Office of International Programs. Director. B0/07/15. 2pp. 07335:312.
- B012270634 Submits application to amend license, increasing quantity to be exported by 5,794 kg U. Amend urgently needed.

 MATSON, V. Transnuclear, Inc. 80/12/10. 1p. 07335: 217.
- 8012300224 Amend 2 to License XU-8422 to remove Transnuclear, Inc as licensee & add Intl Customs 8vc.Inc. DEVINE.J.B. Assistant Director for Export/Import & International Bafeguards. 80/12/17. lp. 07357:009.
- B012300313 Forwards C-E request for extension of License XR-0137 until Dec 2030 & confirmation that matl under License XBNM-1754 will be imited to three reloads. W/o encl. DEVINE, J.B. Assistant Director for Export/Import & International Safaguards. 80/12/02. ip. 07308:001.
- 8012300323 Requests amend to license increasing quantity by 16,786 kg natural U for export to West Germany.
 BUTENKO, T. A. Transnuclear, Inc. 80/11/05. 1p. 07358: 359.
- 8012300328 Requests cancellation of 801001 request to amend License X8NM-1345. MATSON, V. Transmuclear: Inc. 80/11/03. ip. 07358: 360.
- B012300712 License for Marubeni America Corp to export 485 kg U-235, contained in 18,491 kg U. to Japan. DEVINE: U.S. Assistant Director for Export/Import & International Safeguards. ZH-0180-0W. 80/11/26. 2pp. 07308:001.
- 8012300742 Application by Reuter-Stokes, Inc for license to expert RB-C4-0201-231 incore fission chamber for flux mapping to West Germany.

 * Reuter-Stokes, Inc. N-8849. 80/12/10. 1p. 07363;010.
- B012300745 Application by Westinghouse for license to export HLB105 compensated ionization chamber to Host Germany. SCHNAUTZ.C.E. Westinghouse Electric Corp. 2E-10227. B0/12/12. 1p. 07343:011.
- 8012300769 Application by Westinghouse for license to export WL23745 compensated ionization chamber to France. SCINAUTZ.C.E. Westinghouse Electric Corp. ZE-20394. 80/12/11. 1p. 07365:012.

- 8012300773 Application by Pacific Pumps.Inc for license to export specially designed pump parts needed for repairs to India. * Pacific Pumps Div. Q7L01038-R-R 80/12/12. 1p. 07363:013.
- 8012300777 Amend 2 to license for GA Co.extending expiration date from 810101 to 840101.

 DEVINE.J.B. Assistant Director for Export/Import & International Safeguards. IEL-2030. 80/12/22 1p. 09307:021.
- 8012300782 Amend 1 to license for Transnuclear, Inc. increasing quantity from 900 to 905.849 kg U to be exported to France.

 DEVINE-J.B. Assistant Director for Export/Import & International Safeguards. TKP-288 79-203. 80/12/19. ip. 07363:015.
- 8012310056 Submits application to amend export license.extending expiration date to 840101.

 HARMON, D. Edlaw International Co. 80/12/15, 1p. 07369:080.
- 8012310069 Bubmits application to amend license, extending expiration date to 820301.
 MATSOM V. Transnuclear, Inc. 79-258/01 (RBU. 80/12/19. 1p. 07369:081.
- B012310073 Requests Executive Branch position re Ediou, Intl application to amend export license, increasing quantity, extending expiration date & adding EIR storage facility in Buitzerland to store mati before enrichment. W/o encl B01203 ltr. DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. B0/12/19. 1p. 07362:001.
- 8012310077 Executive Branch position re Nissho-Iuai American Corpapplication for license to export 1.000 kg heavy water to Japan. License should be granted.
 NOSENZO.L.V. State, Dept. of, Bureau of Oceans & Internati. Environ. & Scientific Affairs. 80/12/15. 1p. 07362:002.
- 8012310079 Executive Branch position re Exxon Nuclear Co application to amend license changing intermediate consigner for storage to NUMEN GmbH. Hanau. West Germany. Litr of assurance encl. License amend should be granted. NOSENZO, L. V. State. Dept. of. Bureau of Oceans & Internati, Environ. & Scientific Affairs. 80/12/15. 3pp. 07362:003.
- 8012310034 Forwards application for export license for minor nuclear export. Ltr of assurance required, N/o oncl.
 DEVINE. J. B. Assistant Director for Export/Import & International Safeguards. 80/12/19. 1p. 07369:271.
- 8012310100 Forwards application for export license for minor nuclear export.Ltr of assurance required.W/o encl. DEVINE,J.S. Assistant Director for Export/Import & International Safeguards. 80/12/19. 1p. 07369:276.
- B012310230 Requests amend to license for export of two NSSS to Taiwan to extend proposed expiration date to Dec 2030.
 WEST, J. K. C-E Power Systems. 80/11/11. ip. 07367:358
- 8012310836 Requests amend to license for export of reload nuclear fuel to Taiwan to cover only first three reload fuel batches.

 WEST, J.M. C-E Power Systems. 90/11/11. 1p. 07369:359.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

| AUTHOR | ACCEBSION NUMBER | SUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY | | ACCEBSION | BUBJECT |
|----------------------------------|----------------------------|----------------------|-------------------------------------|---------------------------|----------------------|------------------------------------|----------------------------|----------------------|
| | | | | | CATEOURY | AUTHOR | NUMBER | CATEODRY |
| AAMODT, M. | 6012310405 | 50-269 Q | AHEARNE, J. F. | 8012010527 | COMMISSION | ANDERBON, T. H. | 8012150230 | |
| ABBOTT, E. ABBOTT, E. E. | B012020797* | 50-312 0 | AHEARNE, J. F. | 8012030748 | 50-320 U | ANDERBON, J. C. | 8012080014 | 50-445 A |
| ADBOTT, E. E. | 8012020804* | 50-312 0 | AHEARNE, J. F. | 8012030772 | COMMISSION | ANDERBON, D. R. | 8012120324 | NUREC |
| ABEL, J. B. | 8012090266* | COMMISSION | AHEARNE, J. F. | B012030797* | COMMISSION | ANDERSON, T. M. | B0120B0467 | NUREO TOPREP |
| AUELI O. a. | 8009260776 | 50-10 H | AHEARNE, J. F. | 8012030801* | COMMISSION | ANDERSON, R. W. | B012240294* | 50-282 Q |
| ABEL, J. B. | 8012040284* | 50-295 G | AHEARNE, J. F. | 001.0000 | | | | OU KOE G |
| ABEL, J. S. | 8012040064# | 50-295 g | AHEARNE, J. F. | 8012030808* | CORMIBBION | ANDERBON, C. | 8012160150 | 50-322 A |
| ABEL: J. S. | 8012020312* | 50-10 Q | AHEARNE, J. F. | 8012030501 | COMMISSION | ANDERSON, T. H. | 8012100385 | TOPREP |
| ABEL, J. S. | 8012020110* | 50-254 Q | AHEARNE, J. F. | 8012040136 | 50-320 P 50-320 P | ANDERBON, E. | 8012170686* | 50-209 H |
| ABEL, J. B. | 8012050465 | PR | AHEARNE, J. F. | 8012230211 | COMMISSION | ANDERSON, T. K. ANDERSON, T. K. | 8012230467 | TOPREP |
| ABEL, J. B. | | | | | | PHOENODIN 1. II. | 8012290261 | TOPREP |
| ABEL, J. S. | 8012120425* 8012150228* | 50-254 Q 50-456 Q | AHEARNE, J. F. | 8012030762 | 50-320 U | ANDERBON, K. P. | 8012300677# | 50-466 T |
| ABEL, J. S. | B01211060B* | 50-456 Q 50-10 Q | AHEARNE, J. F. AHEARNE, J. F. | 8012090404 | CONKIESION | ANDERBON, T. &. | 8012310187 | TOPREP |
| ABEL, J. B. | 8012290459 | 50-237 Q | AHEARNE, J. F. | 8012110150 | COMMISSION | ANDREWS, H. L. | 8012030442* | FOIA |
| ABEL, J. B. | 8012160329* | 50-454 Q | AHEARNE, J. F. | 8012110148 8012110036 | COMMISSION | ANDREWS, H. L. | 8012030696* | FOIA |
| | | | | 0014110036 | COMMISSION | ANDREWS, H. U. | 8012030566# | FOIA |
| ABEL, J. S. ABEL, J. S. | 8012310590# | 50-275 0 | AHEARNE, J. F. | 8012270405* | COMMISSION | ANDREWS, H. L. | 8012030562* | FOIA |
| ABEL, J. B. | 8012100582* | 50-295 G | AHEARN, C. D. | 8012170672 | 50-445 M | ANDREWS. H. L. | 8012030627* | FOIA |
| ABEL, J. B. | 8012090071 8012310630* | PR | AHEARN, C. D. | 8012170672 | 50-445 M | ANDREWS, H. L. | 8012030618* | FOIA |
| ABEL, J. B. | 8012020301 | 50-10 Q | AHEARNE, J. F. | 8012270403 | COMMISSION | ANDREWS, H. L. | 8012030573* | FOIA |
| | DOIROROSOI | 50-10 P | AHEARNE, J. F. | 8012270031* | 50-289 Q | ANDREWS, L. J. | 8012220224# | FOIA |
| AREL, J. S. | 8012120576 | 50-10 F | AKER, R. E. | 8012090473* | 50-275 8 | ANDRUS, N. J. | | |
| ABEL, J. B. | 8012170488 | 50~10 P | AKER, R. E. | 8012150218# | 50-275 8 | ANESHANGLEY, IL | 6012220134 | 40-4472 |
| ABEL, J. S. | 8012240158 | 50-10 P | ALDERTHAL, Q. | 8012240480 | TOPREP | ANO, W. P. | 8012080834* 8012080656* | 50-313 0 |
| ABEL, J. 8, ABERCROMB (E, H. | B012230226 | 50-373 K | ALDEN, H. I1. | 8012040393 | 50-277 P | ANO, W. P. | 8012110709* | 50-369 G 50-364 G |
| ABERORUMB IEI M. | 8012160317 | 50-259 R | ALDEN, W. H. | 8012160475* | 50-277 R | ANCOLOBE, O. | 8012030715 | 50-364 0 50-247 H |
| ABRAHAMB, A. | 8012110188 | ₽R | ALICKNAVITCH, O. | 8012100045 | PR | AMOON II n | | |
| ABRAMSON, L. R. | 8012100650 | MIBC | ALIVIANKIB, N. | 8012160479 | 50~254 P | ANSON, W. B. ANSTINE, L. D. | 8012120212* | 50-275 H |
| ABRAMSON, C. L. | 8012220067 | PR | ALLAN, J. M. | 8012180353* | 50-247 Q | ANZALONE, A. E. | 8012030854* | 50-10 P |
| ABRAMSON, C. L. | 8012270137 | PR | ALILAN, J. M. | 8012180357* | 50-247 Q | ANZELONE, 8. | 8012110105 8012150115 | PR |
| ABRAMSON, F. | 8012230138* | CONTRACT | allenspach, f. r. | 8012310249* | 50-287 T | ARAGON, R. | 8012310399 | 50-287 H NVREG |
| ABT, B. R. | 8012080798* | 40-8084 | ALLEY, N. P. | 8012040072 | PR | 100111 | | |
| ABT, B. R. | 8012080825* | 40-8084 | ALLIN, R. V. | 8012170012* | QA999 | ARENAL, A. | 8012310065 | 50-361 B |
| ACOBTA, A. J. | 8012080191 | ACRE | ALLRED, D. L. | 8012270633 | 70-2909 | ARKINS, R. J. | 8012010210 | 40-8743 |
| ACOSTA, A. P. | 8012010036 | 40-8584 | ALTER, H. H. | 6012120382* | 40-6622 | ARLOTTO, Q. A. ARLOTTO, Q. A. | 8012110739* 8012110678* | FOIA |
| ACOSTA, A. P. | 8012020576 | 40-8584 | ALVAR, K. R. | 8012190432 | NUREO | ARLOTTO, Q. A. | #B008060088 | FOIA |
| ACCETA, A. P. | 8012050332 | 40-9584 | AMARAL A M | | | | avouoovada* | PUIM |
| ADAMB, J. G. | 8012110062 | PR | AMARAL, J. M. AMBLER, C. D. | 8012120492 | TOPREP | ARLOTTI, M. O. | B012120434* | 50-206 P |
| ADITYA, I. | 8012070287# | 50-275 Q | AN, U. P. | 8012080699 8012180401* | PR TO THE | ARLOTTO, G. A. | 8012270255 | RECOD |
| ADLER, R. W | 8012290198 | 50-289 0 | ANCARROW, M. R. | E012290071 | 50-369 Q 70-2623 | ARMSTRONG, N. E. | 801530099B# | 50-466 T |
| ADLER, R. W. | 8012290003 | 50-289 0 | ANCARROW, M. R. | 8012290071 | 70-2623 | ARNDT, R. W. ARNDT, E. G. | 8012170611* | 71-354 |
| ABI CO D II | | | | | 10 2023 | HANDITE, O. | 8012100024 | PR |
| ADLER, R. W. AERNI, B. L. | 8012310307 | 50-289 Q | ANDERBON, T. IS. | 8012040237* | TOPREP | ARNOTT, R. A. | 8012230290 | State Prog |
| AERNI, B. L. | 8012170292 8012170311 | XPORTLIC | ANDERBON, D. O. | 8012230183* | QA999 | ARDNEON, A. L. | 8012170138 | RES |
| AGEE, J. R. | 8012170311 | XPORTLIC QA999 | ANDERSON, D. O. | E012040023# | QA999 | ABH, R. F. | 8012030248 | 50-317 P |
| AGEE, J. R. | B012040023# | QA999 | ANDERSON, L. F. ANDERSON, T. II. | B012160766* | 40-3453 | ASH, R. F. | B012170450 | 50-318 P |
| | | MITTE. | machaniti I. (). | 8012230174* | QA999 | ABH, R. F. | 8012270285 | 50-317 P |
| AGEE, J. R. AGUILAR, F. | 8012170080* | QA999 | ANDERSON, T. H. | 8012020462* | 50-424 A | ASHTON, A. M. | 8012110359# | CONTRACT |
| AHEARNE, J. | 8012040087 | PR | ANDERSON, T. H. | 8012080160 | PR | ASWELL, D. L. | 8012100473 | 50-382 A |
| AHEARNE, J. | 8012230027* 8012020443* | 50-389 Q | ANDERSON, L. F. | B01205050B | PR | ABHELL, D. L. | 8012190473 | 50-382 K |
| AHEARNE, J. | 8012020443# | 50-364 E | ANDERBON, H. | 9012080281 | PR | ABHELL, D. L | 8012190540 | 50-382 8 |
| | - GAIRGING TOR | COMMIGBION | ANDERSON, C. R. | 8012090280* | 50-244 Q | ABWELL, D. L. | 8012300574 | 50-362 8 |
| AHEARNE, J. | B012310403* | COMMISSION | ANDERSON, T. H. | 8012040228 | TOPREP | ABHELL, D. L. | 8012300581 | 50-382 B |
| AHEARNE, J. | 8012310398* | COMMISSION | ANDERBON, L. F. | 8012110029 | PR | ATAMIAN, L. | 8012070030 | PR B |
| AHEARNE, J. F. AHEARNE, J. F. | 8010300535 | 50-320 U | ANDERBUN, T. M. | 8012090111 | PR | ATKINS, J. D. | 8012030485* | FOIA |
| AHEARNE, J. | 8010300539* | 50-320 U | ANDERSON, T. M. | 8012170045 | PR | AUGE, L. J. | 8012080808 | 50-329 A |
| | 8012230037* | 50-389 0 | ANDERSON, T. M. | B0120204B1 | TOPREP | AULTHOUSE, D. L. | 8012030854* | 20-350 H |
| | | | | | | | | |

| AUTHOR | NO IBBEDDA RECKUN | SUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | ROHTUA | ACCEBBION NUMBER | BUBJECT CATEOORY |
|---|---|--|--|--|--|--|--|--|
| AUSTIN, M. A. | 8012030789 | 70-135 | BARTLETT, J. | 6012270446* | 50-220 Q | BECKERLEY, J. G. | 8012170092 | PR |
| AUSTIN, M. A. | 8012040549 | 70-135 | BARTLETT, T. A. | 6012110241 | PR | BECKERLEY, J. G. | 8012160009* | FOIA |
| AUSTIN, M. A. | 8012080374 | 70-364 | BASIN, S. T. | 6012080023 | NUREG | BECKERLEY, J. G. | 8012160012* | FOIA |
| AUSTIN, M. A. | 8012090077* | 70-135 | BASKIN, K. P. | 6011250547 | 50-361 A | BECKMAN, D. A. | 8012100102* | 50-334 Q |
| AUSTIN, M. A. | 8012030858 | 71-5768 | BASKIN, K. P. | 6012020521 | 50-206 P | BECKSTED, W. F. | 8012020796* | QA999 |
| AUTIO. H. A. | 7910190174 8012020470 8012050390 8012090292 8012090301 | 50-29 8 50-29 8 50-29 8 50-29 8 | Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P. | 8012020247 8012020282 8012020405 8012030316 8012030377 | 50-361 A 50-361 A 50-206 P TOPREP 50-206 P | BEENY, B. T. BEERS, R. BEERB, R. BEILMAN, T, P. BEINHOWER, L. E. | 8012230004 8012010026* 8012020754 8012160496* 8012030368 | 50-395 M 40-8743 FOIA 50-315 B 50-289 H |
| AUTIO, H. A. AUTIO, H. A. AVANT, D. AXELRAD, M. AXELRAD, M. | B012160509 | 50-29 8 | Babkin, K. P. | 8012160503 | TOPREP | BELIN, A. | 8012110204 | FOIA |
| | B012300595 | 50-29 8 | Babkin, K. P. | 8012100527 | 50-206 P | BELIBLE, Q. A. | 8012070228* | 50-261 Q |
| | B012170324* | 50-187 R | Babkin, K. P. | 8012070202 | 50-361 A | BELL, H. E. | 8012180221 | PR |
| | B012020446 | 50-344 0 | Babkin, K. P. | 8012100536 | 50-361 A | BELL, J. P. | 8012050411 | PR |
| | B012020450* | 50-344 0 | Baskin, K. P. | 8012300385 | 50-361 E | BELOTTI, M. | 8012030718 | 50-247 H |
| AXELRAD, M. AXELRAD, M. AXELRAD, M. AXELRAD, M. AXELRAD, M. | *012020450* 8012070325 80022108 *7240022108 | 50-344 0 50-344 0 50-344 0 50-344 0 50-344 0 | Baskin, K. P. Bass, H. B. Bass, D. R. Bassin, N. Bassin, N. | 8012300544 8012110178 8012220181 8012030603* 8012030374* | 50-206 P PR Nureq Foia Poia | BENDICK, W. B. BENEDETTI, F. P. BENGELBDORF, H. BENJAHIN, M. M. BENNETT, A. B. | 8012020659 8012170736* 8012270593* 8012050581 8012180629* | NUREO 50-289 H BECY PR QA999 |
| AYERB, H. G. | 8012270021 | 50-413 H | Bassin, N. | 8012030574* | FOIA | BEOLETTO: J. A. | 8012120413* | 50-206 P |
| BACHMANN, R. G. | 8012080522* | 70-2909 | Bassin, N. | 8012030236* | FOIA | BEOLETTO: J. A. | 8012240427* | 50-361 C |
| BACHMANN, R. G. | 8012270155 | 70-1308 | Bassinothnaight | 8012100223 | PR | BERGAN: O. | 8012020591* | 50-249 8 |
| BACHMANN, R. G. | 8012310460 | 50-170 Q | Bast, B. A. | 8012270306 | 50-266 G | BERGOREN: J. B. | 8011200397 | 50-280 P |
| BACHWR, N. R. | 8012110081 | PR | Batchelder, A. H. | 8012030342* | FOIA | BERGOREN: J. B. | 8012190090 | TOPREP |
| BADGER, D. BAER, T. S. BAER, T. S. BAGAGLID, H. BAIETTI, A. L. | 8012170075 8012050079 8012040575 8012090036* 8012030116* | PR 71-6400 71-6679 50-275 | BATCHELDER, A. H. BATES, A. BATES, B. J. BATES, J. O. BATES, J. N. | 8012030354* 8012030824 801230007* 8012020067 8012180482* | FOIA PR QA999 50-439 A 70-1113 | Bergoren, J. S. Berick, D. Berman, M. Berman, M. Berman, M. | 8012300724 8012240374* 8012220719 8012020139 8012050682 | TOPREP State Prog NUREO NUREO RES |
| BAIETTI,A.L. BAIETTI,A.L. BAILEY,I.K. BAILEY,R.J. BAILEY,R.J. | 8012030094* 8012030180* 8012110231* 8012220049* 8012120307 | FDIA FDIA FDIA 50-220 G NUREO | BATES, A. BATHE, K. J. BAUER, T. L. BAUM, A. BAUM, P. W. | 8012220314 8012230319 8012020700 8012230335 8012130047* | 50-327 0 NUREO 70-157 50-320 P 50-133 R | BERNARD, D. M. BERNARD, D. M. BERNERD, R. M. BERNREUTER, D. L. BERRY, J. F. | 8012160432* 8012180276* 8012230090* 8012030379 8012080795* | 50-271 R 50-29 R 50-387 G 50-206 P 40-8106 |
| BAILEY, K. D. | 8012160353 | 50-329 8 | BAUM, E. A. BAUM, S. A. BAXLEY, B. X. BAXLEY, S. X. BAXTER, T. A. | 8012220363 | 50-280 f | BERWICK, B. E. | 8012240008 | 50-498 0 |
| Bair, C. O. | 8012150057* | 50-344 R | | 8012220373 | 50-280 f | BESHORE, M. | 8012170655# | 50-289 H |
| Bair, C. Q. | 8012230455* | 50-344 8 | | 8012240268* | 50-321 8 | BEST, B. | 8012110545 | 70-2623 |
| Bair, C. Q. | 8012300573* | 50-344 8 | | 8012270335* | 50-321 8 | BETTENHAUSEN, L. | 8012160309# | 50-289 G |
| Baisden, L. | 8012310595 | GONTRACT | | 8012100047 | 50-484 0 | BIANCO, J. S | 8012040377# | CONTRACT |
| Baker, C. E. | 8012080780 | 40-8691 | BAXTER, T. A. BAXTER, T. A. BAYBUTT, P. BAYLOR, C. J. BAYLOR, J. S. | 8012100047 | 50-484 0 | BICKEL, J. | 8012020797* | 50-312 D |
| Baker, K. R. | 8012150268* | 50-331 0 | | 8012300449 | 50-289 0 | BICKEL, J. | 8012020804* | 50-312 D |
| Baker, K. R. | 8012310459* | 50-346 0 | | 8012110057 | RE8 | BICKWIT, L. | 8012300273* | 50-287 O |
| Daker, E. H. | 8012290023 | 50-247 H | | 8012020814 | 50-387 0 | BICKWIT, L. | 8009100422 | 8ECY |
| Ball, L. H, | 8012030703 | 50-247 H | | 8012110405 | 50-289 H | BICKWIT, L. | 8012120470 | 50-554 O |
| BALL, H. L. BALLARD, R. L. BALLARD, R. L. BALLARD, R. L. BALLARD, R. L. | 8012030254 8012020718* 8012020728* 8012020750* 8012140633 | * 50-247 H 50-367 G 50-367 G 50-367 G 50-259 P | BAYNARD, P. Y. BAYNARD, P. Y. BAYNARD, P. Y. BAYNARD, P. Y. BAYNARD, P. Y. | 8012010511 8012080738 8012240232 8012010097 8012010098* | 50-302 G 50-302 G 50-302 G 50-302 P 50-302 P | BICKWIT, L. BICKWIT, L. BICKWIT, L. BICKWIT, L. BIELAWSKI, A. P. | 8012120373* 8012270477* 8012270507* 8012270501* 8012270333 | 50-247 T 10CFR 50-3 T 50-255 0 |
| BALLENTIKE, J. M. | 8012160330 | 50-327 R | BAYNARD; P. Y. | 8012070211 | 50-302 P | BIERMAN, E. L. | 8012050552 | PR |
| BALLINDER, P. L. | 8012150081* | 50-298 R | BAYNARD; P. Y. | 8012070220 | 50-302 P | BILLECI, O. D. | 8012160600 | PR |
| BALDUOH, R. C. | 8012300024* | 50-445 M | BAYNARD; P. Y. | 8012300740 | 50-302 Q | BINOGELI, B. L. | 8012150094* | 50-304 8 |
| BALTZO, R. M. | 8012220056* | 50-266 G | BAYNARD; P. Y. | 8012150238 | 50-302 F | DIRCH, T. L. | 8012030512* | FOIA |
| BANCROFT, J. R. | 8012040114 | 50-329 F | BAYNARD; P. Y. | 8012160483 | 50-302 R | BIRKEL, R. A. | 8012110560* | 50-389 8 |
| BANCROFT, J. R. | 8012040238 | 50-367 F | BAYNARD, P. Y. | 8012170505 | 50-302 P | BIRKEL, R. A. | 8012020717 | 50-349 A |
| BANGART, R. L. | 8012220506* | 50-10 P | BAYNARD, P. Y. | 8012240274 | 50-302 P | BIRKEL, R. A. | 8012070127 | 50-369 A |
| BANKOFF, B. G. | 8012220609 | NUREO | BAYNARD, P. Y. | 8012240328 | 50-302 P | BIRKEL, R. A. | 8012070208 | 50-369 A |
| BANKG, L. E. | 8012240435 | PROJ | BAYNARD, P. Y. | 8012300481 | 50-302 P | BIRKEL, R. A. | 8012160022 | 50-389 A |
| BANNER, R. H. | 8012030549* | FOIA | BAYNE, J. P. | 8012080824 | 50-206 Q | BIRKEL, R. A. | 8012220344 | 50-389 A |
| BANNER, J.E. BARBER, R.W. BARBOUR, Q.H. BARCLAY, A.G. BARKER, N.R. | 8012040367 8012070032* 8012020687* 8012170730* 8012080254* | 70-143 GRQ 50-289 G 50-289 H GA999 | BAYNE, J. P. | 8012080170 8012030592 8012100457 8012180271 8012100224 | REGOD 50-206 P 50-333 V PR 50-333 Q | BISCHOFF, C. A. BISCHOFF, C. A. BISHOP, T. W. BISHOP, C. J. BISHOP, C. J. | 8012300487 8012300487 8012040679* 8012050432 8012050437 | 50-528 0 50-528 0 50-508 0 50-327 0 50-466 0 |
| BARKER, N.R. | 8012080250* | GA999 | DAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. DAYNE, J. P. DAYNE, J. P. | 8012140340 | 50-286 P | 818HOP, C. J. | 8012050453 | 50-275 G |
| BARKER, N.R. | 8012080244* | GA999 | | 8012170352 | 50-286 P | 818HOP, C. J. | 8012230329 | 50-488 G |
| BARKER, N.R. | 8012240047 | 50-395 B | | 8012230361 | 50-333 P | 818HOP, D. J. | 8012120308 | 50-206 P |
| BARKER, N.R. | 8012240131 | 50-395 B | | 8012300584 | 50-333 P | 818HOP, C. J. | 8012180162 | 50-500 G |
| BARNEG, I. | 8012230255* | GA999 | | 8012300552 | 50-286 P | 818HOP, C. J. | 8012240021 | 50-443 G |
| BARNES, I. | 8012070065* | 0A999 | BEAN, R. M. | 8012120270 | NUREO | 818HOP, C. J. | 8012270170 | 50-327 Q |
| DARNES, I. | 8012020808* | 0A999 | BEAN, R. M. | 8012120324 | NUREO | 818HOP, C. J. | 8012070286 | 50-275 Q |
| BARNES, I. | 8012170200* | 0A999 | BEARE, J. A. | 8012240370* | State Prog | 818HOP, C. J. | 8012170488 | 50-277 Q |
| BARNES, I. | 8012170104* | 0A999 | BECHHOEFER, C. | 8012080009 | 50-409 O | 818HOP, C. J. | 8012170545 | 50-354 Q |
| BARNES, I. | 8012080307* | 0A999 | BECHHOEFER, C. | 8012120643 | 50-387 O | 818HOP, C. J. | 8012270061 | 70-2623 |
| BARNES, I. BARNES, I. BARNES, I. BARNES, I. BARRETT, P. A. | 8012020702* 8012300026* 8012180597* 8012180621* 8012240054* | 0A999 0A999 0A999 0A999 50~373 Q | BECHHOEFER, C. DECHHOEFER, C. BECHHOEFER, C. BECHHOEFER, C. BECHHOEFER, C. | 8012300477 8012230233 8012290555 8012300044 8012300068 | 50-498 0 50-329 9 50-409 0 50-387 9 50-329 0 | BISHOP, C. J. | 8012270038* 8012300128 8012230268 8012230270 8012300072 | 50-155 H 50-344 Q 50-272 Q 50-155 Q 50-155 Q |
| BARRY, L. W. | 8011180319* | 8tate Prog | BECHHOEFER.C. | 8012290222 | 50-387 0 | BISHOP, L. L. | 8012270052 | 70-2623 |
| BARTH, C. A. | 8012110346 | 50-338 0 | BECHHOEFER.C. | 8012300494 | 50-358 0 | BISHOP, L. L. | 8012270317* | 70-2623 |
| BARTH, C. A. | 8012190586 | 50-358 0 | BECK.O.P. | 8012040198 | 50-151 F | BISHOP, L. L. | 8012270313 | 70-2623 |
| BARTH, C. A. | 8012190649 | 50-358 0 | BECK.O.P. | 8012090303 | 50-151 8 | BISHOP, L. L. | 8012270317* | 70-2623 |
| BARTH, C. A. | 8012290457 | 50-358 0 | BECKER.D.V. | 8012100042 | PR | BISHOP, L. L. | 8012270052 | 70-2623 |

| | CCEBBION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCEBSION NUMBER | SUBJECT CATEGORY |
|--|--|--|--|---|--|--|---|--|
| BIBHOP, C. J. BO BIBHOP, C. J. BO BIBHOP, C. J. BO BIBHOP, C. J. BO | 12270365 12270176 12270056 12270170 12270275 | 50-329 0 50-354 0 50-195 0 50-389 0 50-344 0 | BOSWELL, R. F. BOSWELL, R. F. BOSWELL, R. F. BOSWELL, R. F. BOSWELL, R. F. | 8012030068* 8012030204* 8012030275* 8012030167* 8012030185* | FOIA FOIA FOIA FOIA FOIA | BROMBERG, B. BROMBERG, B. BROMBERG, B. BROMBERG, B. BROMBERG, B. | 8012080501 8012170201 80121080504 8012100004 8012240032 | CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT |
| BISSETT. P. BO: BISSETT. P. BO: BITNER, E. L. BO: BIVING, W. S. BO: | 12100247* 12230061* 12300039* 12300125 12300277* | 70-1149 70-135 70-820 50-289 H 50-466 G | BOBWELL, R. F. BOSWELL, R. BOSWELL, R. F. BOUCHEY, O. D. BOUCHEY, O. D. | 8012030382* 8012030075* 8012030027* 8012050065 8012070108 | FOIA FOIA FOIA PR PR | BRONES, A. BROOKS, E. L. BROSEUS, R. W. DROSEUS, R. W. BROSS, I. D. | 8012090026* 8012300448 8012120369 8012110319 8012300596* | MISC 50-287 H PR PR 50-466 Q |
| BLACK, R. L. 801 BLACK, R. L. 801 BLACK, R. L. 801 BLACK, R. L. 801 | 1230357* 12050400 12050405* 1230002 12300266 | 50-361 A 50-466 Q 50-466 Q 50-466 Q 50-466 Q | BOUCHEY, O. D. BOUCHEY, O. D. BOUCHEY, O. D. BOUCHEY, O. D. | 8012070295 8012150162 8012160128 8012300255 8012230391 | 50-397 F 50-397 A 50-397 I 50-397 K 50-397 F | BROUNS, R. J. BROUNS, R. J. BROWN, E. Q. BROWN, E. Q. BROWN, E. Q. | 8012230323 8012310287 8012290407 8012030179* 8012030164* | NUREO NUREO 50-275 Q FOIA FOIA |
| BLAKE, J. J. 801 BLAKE, J. J. 801 BLAKE, E. L. 801 BLAKE, E. L. 901 | 12080338 12180138* 12310053* 12110410 12150182 | PR 30-414 Q 30-364 Q 50-289 Q 50-524 Q 50-289 Q | BOUCHEY, O. D. BOUCHEY, O. D. BOUKNIOHT, J. A. BOUKNIOHT, J. A. BOUKNIOHT, J. A. | 8012300412 8012300432 8012300318 8012300318 8012290390 | 50-397 K 50-397 A 50-445 M 50-445 M 50-389 M | Brown, J. M. Drown, E. O. Brown, E. Q. Brown, J. M. Brown, J. M. | 8012030623* 8012030250* 8012030087* 8012030597* 8012030466* | FDIA FDIA FOIA FOIA FOIA |
| BLAKE, E. L. 801 BLAKE, E. L. 801 BLAKE, E. L. 901 BLANCHETTI, V. 801 | 12290582 12310216 12310216 12170733* | 50-287 Q 50-448 Q 50-448 G 50-287 H | BOUKNIOHT, J. A. BOURNIA, A. BOURNIA, A. BOURNIA, A. BOURNIA, A. | 8012270370 8012310470* 8012110111 8012120574 8012160008 | 50-387 H 50-373 G 50-373 A 50-373 F 50-373 A | Brohn, J. M. Brohn, J. H. Brohn, J. H. Brohn, J. M. Brohn, J. M. | 8012030531* 8012030523* 8012030507* 8012030497* 8012030473* | FOIA FOIA FOIA FOIA |
| BLATZ, H. 901 BLOOK, J. 801 BLOUGH, A. P. 801 BLUME, M. B. 801 | 12030501* 12110650 12300080* 12300013 | FOIA FOIA 50-277 Q 50-445 M | BOURNIA: A. BOWERS: C. E. BOWERS: C. E. BOWERS: C. E. BOWERS: J. R. | 8012220350 8012070251* 8012100264* 8012100273* 8012050368 | 50-373 E 70-820 70-820 70-820 50-287 H | BROWN, J. M. BROWN, J. M. BROWN, J. M. BROWN, J. M. BROWN, J. M. | 8012030461* 8012030625* 8012030621* 8012030614* 8012030622* | FOIA FOIA FOIA FOIA |
| BOCKEL, R. T. 801 BODDY, J. R. 801 BODDY, J. R. 801 BODTKE, P. J. 801 | 12180246 12010031 12010037 12140426# | PR 40-8084 40-8084 50-255 R | Domers, E. S. Bomers, E. S. Bomers, E. S. Bomers, E. S. Bomers, E. S. | 8012300049 8012230047 8012290244 8012300029 8012290284 | 50-322 0 50-250 0 50-322 0 50-275 0 50-142 0 | BROWN, J. M. BROWN, J. M. BROWN, J. M. BROWN, J. M. BROWN, O. D. | 8012030616* 8012030672* 8012030651* 8012030682* 8012020361* | FOIA FOIA FOIA FOIA 40~8084 |
| BOODEN, Q. 801 BOODEN, Q. 801 BOODEN, Q. 801 BOODEN, Q. 801 | 2010199 2010534 2080785 2310528 | 40-1162 40-1162 40-1162 40-1162 50-289 T | BOHYER, J. E. BOHYER, J. E. BOYD, D. BOYD, D. C. BOYD, D. C. | 8012030584* 8012030030* 8012100174* 8012110753* 8012310433* | F01A F01A 50-155 Q 50-186 Q 50-255 Q | BRDWNER, H. D. BROWN, Q. D. BROWN, R. L. BROWN, Q. D. BROWN, Q. D. | 8012040141 8012020347* 8012080256* 8012020257 8012020340 | 50-322 F 40-8084 9A979 40-8709 40-8084 |
| BOGER, B. A. 801 NOHN, R. J. 801 BOHN, R. J. 801 BOHN, R. J. 801 | 2310244# 2020703# 2030583 2090182 | 50-289 T 50-367 0 50-367 R 50-367 R | BOYD, D. C. HOYD, R. M. BRACKHANN, K. BRADBURY, R. D. BRADBURY, R. B. | 8012100432* 8012010450 8012100130 8012080154 8012080731 | 50-155 Q PR PR PR REGOD | BROWNENG; R. E. BROWN, O. D. BROWN, C. H. BROWN, R. L. | 8012160070* 8012020383* 8012020376 80120207793* 8012170552* | 50-10 Q 40-2259 40-2259 50-263 Q |
| BDHN, R. J. 801 BDLANDER, M. A. 801 BDLLING, L. A. 801 BOLLING, L. 801 | 2240431 2170047 2010018 2170562 | 50-367 R RES 14E 14E | BRADBURY, R. B. BRADBURY, R. B. BRADBURY, R. B. BRADFORD, W. H. BRADFORD, Q. | 8012100014 8012080502 8012090102 8012110420* 8012300264 | PR REGOD PR 50-348 Q 50-289 Q | BROWN, J. L. BROWN, J. L. BROWN, C. B. BROWN, Q. D. BROWN, R. F. | 8012040162 8012080281 8012240383* 8012170668* 8012080242 | 50-219 Q PR State Prog 50-498 Q PR |
| BONZON, L. L. 801 BOOK, H. E. 801 BOOK, H. E. 801 BOOK, H. E. 801 | 2020124 2070143# 2070137 2070075# | NUREQ 70-1257 70-1257 50-344 Q | BRADLEY, O. H. BRADLEY, E. J. BRADLEY, E. J. BRAMLETT, L. S. BRAMLETT, L. S. | 8012230374 8012010249 8012150141 8012090445# 8012160411# | NUREO 50-277 F 50-277 P 50-313 8 50-313 R | BROWN, G. D. BROWN, G. D. BROWN, R. C. BROWN, G. J. BROWN, G. F. | 8012170664 8012020238 8012170231 8012240262* 8012050462 | 50-448 Q 40-8709 PR 50-29 P PR |
| BOOK, H. E. 801 BOONE, J. M. 801 BORDENICK, B. M. 801 BORDENICK, B. M. 801 | 2310546# 2110645# 2290112 2170689 | 50-940 Q 50-340 Q 50-242 Q 50-493 Q 50-514 Q | Brand, H. E. Brant, H. E. Brantley, J. C. Brashe, J. H. Braun, L. | 8012230004 8012230004 8012120096 8012220388* 8012150164 | 50-395 H 50-395 H PR 50-320 P 50-287 H | BROWN, R. H. BROWN, H. H. BROWN, H. H. BROWN, H. H. BROWN, H. H. | 8012010316 8012270002 8012270161 801227002 8012270161 | 50-395 D 50-275 Q 50-275 Q 50-275 Q 50-275 Q |
| BORDENICK, B. M. 801: BORDENICK, B. M. 801: BORER, K. T. 901: BORGMANN, E. A. 801: | 2300138 2300354 2100171 2020247 | 50-322 0 50-322 0 PR 50-358 A | BRAY.A.P. BRAZEE,R.J. DRAZEE,R.J. BREAUX,D.O. BREAUX,D.O. | 8012290088* 8012310394 8012310445 8012190522* 8012080268* | Comiesion Nureo Nureo Oa777 Ga777 | BROWN, J. A. BROWN, H. H. BROWN, H. H. BROWN, H. H. BROWN, H. H. | 8012160489* 8012270662 8012270662 8012270662 8012300117 8012310588 | 50-302 R 50-275 0 50-275 0 50-275 0 50-275 H |
| BOROMANN, E. A. BO11 BOROMANN, E. A. BO11 BOROMANN, E. A. BO11 BOROMANN, E. A. BO11 | 2050389 2080320 2100303 2170260 | 50-358 A 50-358 A 50-358 K 50-358 K | DREAUX, D. C. BRENNAN, P. T. BRICKLEY, R. H. BRICKLEY, R. H. BRICKLEY, R. H. | 8012020733* 8012080280 8012180529* 8012040023* 8012170080* | 0A979 REGOD GA979 GA979 GA999 | BROWN, H. H. BROWN, H. H. BROWN, H. H. BRUWNER, E. J. BRUWNER, E. J. | 8012300117 8012270407 8012290407 8012160108* 8012070545* | 50-275 0 50-275 0 50-275 0 50-277 0 50-277 0 |
| BOROMANN, E. A. 801: BOROMANN, E. A. 801: BOROMANN, E. A. 801: BOROMANN, E. A. 801: | 2300607 2230291 2270286 2310367 | 50-358 8 50-358 8 50-358 K 50-358 K | Brigos, L. E, Bright, R. M. Briner, W. H. Brinkman, R. E. Brinkman, R. E. | 8012110090* 8012040382 8012120204 8012030240* 8012030163* | 50-219 G PR PR FOIA FOIA | DRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. | 8012100094* 8012300058* 8012070076* 8012100388 8012110082 | 50-334 Q 50-277 Q 50-29 Q 50-387 Q 50-219 Q |
| BORKON, E. L. 8012 BORDUGHB, H. 8012 BORDUGHB, H. 8012 BORDUGHB, H. 8013 | 2080682 F 2030388* F 2030380* F 2030405* F | 50-358 B PR FOIA FOIA NUREO | BRINKHAN, R. E. BRINKHAN, R. E. BRINK, T. BRINKLER, J. E. BRISBIN, N. L. | 8012030553# 8012030676# 8012300141 8012300483# 8012230374 | FOIA FOIA 50-287 H 50-309 B NUREG | BRUNNER: E. J. | 8012080120 8012110389 8012080092 8012140304 8012080108 | 50-387 Q 50-322 Q 50-244 Q 50-289 Q 50-387 Q |
| BORSUM, R. B. 801 BOBTIAN, R. W. 801 BOBTWICK, W. E. 801 | 2110964 5 2020292 7 2220186 F | 50-389 8 70-2623 REB FOIA | BRITTIOAN, R. L. BROCKETT, T. U. BROCKETT, T. U. BROMBERG, B. BROMBERG, B. | 8012310474 8012110168 8012180255 8012080496 8012160013 | SO-17Q O 1&E 1&E CONTRACT CONTRACT | DRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. | 8012100077 8012240266 8012200001 8012090070 8012220028 | 50-334 Q 50-29 Q 50-247 Q 50-29 Q 50-317 Q |

| AUTHOR | ACCESSION NUMBER | SUBJECT Cateoory | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|--|---|---|--|---|--|--|
| BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. | 8012220004 8012220071 8012190703 8012240048 8012190710 | 50-29 | CALLAN. V. CAKHI, F. A. CAMHI, F. A. CAMPBELLI, J. A. CAMPBELLI, A. C. | 8012100461 8012080550* 8012110538* 8012110157* 8012230095 | 50-271 H 50-327 F FOIA FOIA NUREO | CARTWRIGHT, W. R. | 8012010370* 8012020423 8012020426* 8012020581 8012020570* | 50-338 8 50-339 8 50-339 8 50-339 8 50-339 8 |
| BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. | 8012306045 8012100087* 8012100205 8012270420* 8012270407* | 50-277 | CAMPBELL, R. H. CAMPBELL, M. CANNON, T. M. CANNON, J. M. CANNON, T. M. | 8012030704 8012270103 8012220300 8012230006 8012220300 | 50-289 H 1&E 27-39 27-39 27-39 | CARTWRIGHT, N. R. CARTWRIGHT, N. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. | 8012020574 8012020402* 8012020423 8012020431* 8012100543 | 50-337 8 50-337 8 50-338 8 50-338 8 50-337 8 |
| BRYANT, J. C. BRYANT, J. C. BRYANT, J. K. BRYANT, J. C. BRYANT, J. C. | 8012150263* 8012180289* 8012040303* 8012160035* 8012180403* | 50-387 0 50-424 0 50-483 0 50-416 0 50-400 9 | CANTER, H. L. CANTER, H. L. CANTRELL, F. S. CANTRELL, F. S. CANTRELL, F. S. | 8012120253* 8012100056* 8012080495* 8012090156* 8012080082* | 50-312 Q 50-312 Q 50-518 Q 50-439 Q 50-438 Q | GARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, N. R. CARTWRIGHT, N. R. CARTWRIGHT, W. R. | 8012100570# 8012020482 8012020712# 8012090401 8012090408* | 50-339 8 50-338 8 50-338 8 50-338 8 50-338 8 |
| BRYANT, J. BRYAN, J. K. BRYAN, J. K. BRYANT, J. C. BRYANT, J. C. | 8012110684* 8012040672* 8012110630* 8012190222* 8012190399* | 50-413 Q 50-483 Q 50-483 Q 50-413 Q 50-400 Q | CANTRELL, F. B. CANTRELL, F. B. CAPELLAN, R. CAPHTON, D. L. CAPHTON, D. L. | 8012160750* 8012310063* 8012160569 8012100392* 8012080099* | 50-518 Q 50-439 Q PR 50-387 Q 50-244 Q | GARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. | 8012070315 8012070317* 8012070350 8012070351* 8012070362 | 50-338 8 50-339 8 50-338 8 50-338 8 50-338 8 |
| BRYAN, J. K. BRYAN, J. K. BRYAN, J. K. BRYAN, J. K. BUCHANAN, C. R. | 8012030724 8012170484 8012170494 8012300610 8012030370* | 50-483 S 50-483 C 50-483 C 50-483 H FOIA | CAPHTON, D. L. CAPHTON, D. L. CAPHTON, D. L. CAPHTON, D. L. CAPRA, R. A. CAR, J. C. | 8012080119# 8012220006* 8012240049# 8012270542* 8012110245* | 50-387 Q 50-29 Q 50-334 Q 50-289 T FOIA | CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, M. CARTWRIGHT, W. R. | 8012070345* 8012150173 8012150174* 8012170443 8012140459 | 50-338 8 50-339 8 50-339 8 50-289 H 50-339 8 |
| Buchanan, C. R. Buchanan, C. R. Buchanan, C. R. Buchanan, C. R. Buchanan, C. R. | 8012030160* 8012030276* 8012030239* 8012030391* 8012030648* | FOIA FOIA FOIA FOIA | CARDELI, A. CARDEN, D. M. CAREW, J. F. CAREY, K. S. GAREY, K. S. | 8012160737 8012230360* 8012190138 8012030134* 8012030134* | PR 50-553 R REB 27-10 27-10 | CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. | 8012160467* 8012160514 8012230371 8012230376* 8012230412 | 50-337 8 50-337 8 50-337 8 50-337 8 50-337 8 |
| BUCHANAN, C. R. BUCHHOLZ, R. H. BUCHHOLZ, R. H. BUCHHOLZ, R. H. BUCHHOLZ, R. H. | 8012030589* 8012020258 8012030285 8012030697 8012230530 | FOIA TOPREP TOPREP TOPREP TOPREP | GAREY, K. S. CAREY, K. S. GAREY, K. S. CAREY, K. S. CARLISLE, C. S. | 8012030104* 8012030112* 8012030112* 8012030083* 8012050482 | 27-10 27-10 27-10 27-10 27-39 PROJ | CARTHRIGHT, W. R. CARTHRIGHT, W. R. CARTHRIGHT, W. R. CARTHRIGHT, W. R. CARTHRIGHT, W. R. | 8012230416* 8012230419 8012230423 8012230424* 8012230428* | 50-339 8 50-339 8 50-338 8 50-339 8 50-338 8 |
| BUCHHOLZ, R. H. BUCHHOLZ, R. H. BUCKALEH, W. H. BUDZIK, D. K. BUDZIK, D. K. | 8012220250 8012300482 8012020126 8012050322 8012080480 | TOPREP TOPREP NUREO 50-329 A 50-329 A | CARLOS, P. C. CARLOS, P. C. CARLOS, P. C. CARLSON, R. T. CARLSON, R. T. | 8012120390 8012010350 8012120395* 8012080045 8012080393* | 40-9348 40-9348 40-9348 50-443 Q 50-387 Q | CARTWRIOHT, W. R. CARTWRIOHT, W. R. CARTWRIOHT, W. R. CARTWRIOHT, W. R. CARUSO, R. | 8012310316 8012310325 8012310330* 8012310333* 8012040188 | 50-338 8 50-338 8 50-338 8 50-338 8 50-29 P |
| Budzik, D. K. Buell, W. A. Bueteng, E. Bukeg, P. E. Bukoarner, D. H. | 8012300557 8012110471* 8012170252 8012160368* 8012310379 | 50-329 K FOIA FOIA 50-286 Q 40-2061 | CARLBON, R. T. | 8012070237# 8012080368* 8012240226* 8012020210 8012110598 | 50-443 | CARUBO, R. CABE, E. O. CABE, E. G. CABE, E. G. CABE, E. O. | 8012170084 8012110717* 8012080537* 8012170673* 8012160644* | 50-29 P FOIA 50-10 Q 50-237 Q 50-389 Q |
| BUNZ, H. BURGER, F. J. BURGIN, R. E. BURNETT, P. T. BURNETT, P. T. | 8012020351* 8012140432* 8012170100 8012160041* 8012310242* | 10CFR 50-271 R 70-2881 50-302 G 50-261 Q | CARLBON: R. T. | 8012110603 8012110074 8012190652 8012300165 8012190559 | 50-387 Q 50-412 Q 50-336 Q 50-287 Q 50-387 Q | CABEY, B. B. CABHMAN, T. J. CABTELLION, A. V. CATCHPOLE, G. J. CATCHPOLE, G. J. | 8012300509 8012050056* 8012100173 8011170005 8012100483 | 50-361 |
| Burns, J. W. Burns, S. Burns, B. O. Burns, B. G. Burns, B. G. | 8012120631 8012100154 8012220278 8012220287 8012290636 | PR 50-484 0 50-255 0 50-255 0 50-407 T | CARLEON, R. T. | 8012230034 8012230073 8012230044 8012170506 8012080348 | 50-352 0 50-410 0 50-336 0 50-423 0 50-410 8 | CATTON: I. CAVANAUGH, U. CAVANAUGH: W. CAVANAUGH: W. CAVANAUGH: W. | 8012160616* 8012220587 8012120191 8012020144 8012150021 | AGR8 50-313 G 50-313 G 50-313 G 50-313 G |
| BURNS, S. O. SURNS, S. O. URNS, S. O. RNS, S. O. RNS, S. O. | 8012270076 8012270322 8012270287 8012270180 8012270226 | 50-409 0 50-409 0 50-409 0 50-409 0 50-255 0 | CARLBON, R. T. | 8012080414 8012080384 8012080358 8012090224 8012190713 | 50-410 8 50-387 0 50-387 0 50-443 0 50-387 0 | CAVANAUGH, W. CAVANAUGH, W. CAVANAUGH, H. CAZER, F. D. CERNE, A. C. | 8012080399 8012230482 8012290188 8012110170 8012080060# | 50-313 P 50-313 P 50-313 P PR 50-443 Q |
| RNSTONE.C. RSTEIN.N.K. JRSTEIN.S. JRT.D.R. JRWELL,S B. | 8012310281 8012020268* 8012290131 8012100233 8012180372* | 50-466 | CARLBON, J. D. CARLBON, R. T. CARLBON, R. T. CARLBON, M. E. CARPENTER, T. O. | 8012100134* 8012240217 8012300173 8012170722* 8012080623* | 50-344 0 50-322 0 50-272 0 50-287 H CONTRACT | CERNE: A, C. CERNY: R. J. CERNY: R. J. CHAFFEE: A. E. CHAFFEE: A. E. | 8012090242* 8012090066 8012180233 8012100147* 8012310415* | 50-443 0 PR PR 50-361 0 50-228 0 |
| BUBHEMI J. BUTCHER, R. BUTENKO, T. A. BUTENKO, T. BUTENKO, T. BUTENKO, T. A. | 8012040401 8012170585# 8012110165 8012020327 8012300323 | 50-247 H 50-281 G XPORYLIC XPORYLIC XPORYLIC | CARPENTER, T. Q. CARPENTER, J. M. CARR, J. C. CARR, J. C. CARRIER, M. J. | 8012100417* 8012080010 8012110218* 8012110225* 8002210087 | CONTRACT NUREO FOIA FOIA 70-754 | CHANANIA: F. D. CHANANIA: F. D. CHANDLER: L. J. CHAPLIN: 8. D. CHAPLIN: 8. D. | 8012300013 8012300251 8012270389 8012070374* 8012150188* | 50-445 M 50-445 M 50-361 G 50-320 B 50-320 B |
| BUTENKO, T. A. BUTENKO, T. A. BUXTON, L. D. BYRON, P. M. BYRON, P. M. | 8012110020 8012110024* 8012020659 8012110646* 8012310511* | XPORTLIC XPORTLIC NUREO 50-341 G 50-341 G | CARRIER, M. J. CARROLLI J. T. CARTER, J. E. CARTER, R. S. CARTER, R. S. | 8012160424* 8003170023 8012240020* 8012280485 8012150143 | 70-754 50-219 P Commission 50-184 P 50-184 P | CHAPLIN, 8. D. CHAPLIN, 8. D. CHAPLIN, 8. D. CHARLEBOIB, D. L. CHARLEBOIB, A. | 8012160500* 8012230480* 8012300493* 8012100218 8012170688* | 50-320 8 50-320 8 50-320 8 PR 50-289 H |
| CAHILLI W. J. CAHNI A. L. CAHNI A. L. CAHNI A. L. GAINI C. L. | | FOTA PR PR PR 40-8084 | CARTER, D. CARTHRIGHT, N. R. CARTHRIGHT, N. R. CARTHRIGHT, N. R. CARTHRIGHT, N. R. | 8012300085 8012010277 8012010280* 8012010353 8012010342* | 50-247 H 50-339 8 50-339 8 50-339 8 50-339 8 | Chase, J. W. Chase, J. W Chaudhary, S. K. Cheatham, A. C. Chen, W. | 8012190512* 8012020364* 8012230080* 8012120379 8012160107 | 50-259 Q 50-259 Q 50-410 Q 71-4144 50-83 I |
| CAIN, C. L. CAIN, J. CALDHELL, R. A. CALHOUN, U. CALLAN, L. J. | 8012040315 | 40-8642 MASTE HOT 50-267 0 50-320 H 50-313 0 | CARTHRIOHT, N. R. CARTHRIOHT, N. R. CARTHRIOHT, N. R. CARTHRIOHT, N. R. CARTHRIOHT, N. R. | 8012010363 8012010373* 8012010352 8012010359* 8012010378 | 50-338 8 50-339 8 50-339 8 50-339 8 | CHESTER, R. O. CHIANOI, N. J. CHILDS, H. V. CHILDS, W. V. CHILDS, W. V. | 8012170208 8012010337 8012050444* 8012080457* 8012150130* | RE8 50-400 8 50-333 8 50-333 8 |
| | | | | | | | | |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEOORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY |
|---|---|--|---|---|--|---|--|--|
| CHILDS, W. V. CHILDS, W. V. CHILDS, W. V. CHILDS, W. V. CHILDS, W. V. | 8012160556# 8012290437# 8012290447# 8012290451# 8012290474# | 50-333 8 50-333 8 50-333 8 50-333 8 50-333 8 | GLARK, R. A. | 8012310051 8012310011 8012310045 8012310043 80123100340 | 50-344 F 50-266 P 50-266 P 50-307 P 50-313 P | COLITZ, J. J. COLL, N. A. COLL, N. A. COLL, N. A. COLLINS, P. F. COLLIER, R. P. | 8012100177 8012300516 8012300516 7909200110 8012230104 | 50-287 T. 50-250 G 50-250 O. 50-29 G NUREO |
| CHILDS, W. V. | 8012300546* | B CCE-05 | Clark, H. K. | 8012300112 | 50-461 Q | COLLINS, J. T. COLLINS, J. T. COLLINS, J. T. COLLINS, P. F. COLLIER, L. B. | 8012020022 | 50-320 R |
| CHILK, B. J. | 8012240023* | NOISSIMMOD | Claudius, H. Q. | 8012030038* | FOIA | | 8012110425 | 50-320 R |
| CHILK, B. J. | 8012240075* | NOISSIMMOD | Claudius, H. Q. | 8012030393* | FOIA | | 8012100179 | 50-320 B |
| CHILK, B. J. | 8012240092* | NOISSIMMOD | Claudius, H. Q. | 8012030226* | FOIA | | 8012170577 | 50-302 V |
| CHILK, B. J. | 8012240081* | NOISSIMMOD | Claubun, K. K. | 8012010618 | 50-201 H | | 8012020289* | 50-395 0 |
| CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J. | 8010230021* 8012040173* 8012040191* 8012040205* 8012010209 | 10CFR 50-574 A 50-574 A 50-219 Q PR | CLAYBAUGH, N. H. CLAYTON, F. L. | 8012290139 8001030448 8012100514 6012020397* 8012090113* | PR 50-348 F 50-348 8 50-344 0 50-348 F | COLLIER R. P. COLLING P. F. COLLING P. F. COLLING J. COLLING J. | 8012120570 8012270382 8012310075 8012170092 8012170110 | NUREQ 50-287 V 50-287 B 50-287 B |
| CHILK, B. J. | 8011210740 | RECOD | CLAYTON, F. L. | 8012050115 | PR | COLLING, M. P. | 8012170717# | 50-289 H |
| CHILK, B. J. | 8012010414 | PR | CLAYTON, B. | 8012020722 | 50-387 A | COLLINS, J. T. | 8012270411 | 50-320 P |
| CHILK, B. J. | 8012120546 | XPORTLIC | CLAYTON, F. L, | 8012150194 | 50-344 P | COLOMBO, R. | 8012120484* | 50-312 R |
| CHILK, B. J. | 8012170701 | 10CFR | CLAYTON, B. | 8012020672 | 50-382 A | COLOMBO, R. W. | 8012070376# | 50-312 S |
| CHILK, B. J. | 8012070422* | COMMISBION | CLAYTON, F. L. | 8012180016 | 50-364 Q | COLOMBO, R. W. | 8012160487 | 50-312 P |
| CHILK, B, J, | 8012110161* | COMMIBBION | CLAYTON, F. L. CLAYTON, B. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. | 8012130146 | 50-364 P | COLOMBO, R. W. | 6012270228 | 50-312 P |
| CHILK, B, J, | 8011280008 | 50-387 Q | | 8012180501 | 50-369 A | COLOMBO, R. W. | 6012300467 | 50-312 S |
| CHILK, B, J, | 8012110473 | 100FR | | 8012010348 | 50-348 8 | COLON, T. E. | 6012180223* | 50-259 Q |
| CHILK, B, J, | 8012110480 | 50-247 Q | | 8012020512 | 50-364 8 | COLON, T. E | 8012160222* | 50-338 Q |
| CHILK, B, J, | 8012110005 | 50-409 Q | | 8012020345 | 50-348 8 | COMER, M. | 8012160617 | PR |
| CHILK, B. J. | 8012270408* | COMMISSION | CLAYTON, F. L. | 8012030426 | 50-364 P | COMPTON, A. T. | 8012110270 | PR |
| CHILK, B. J. | 8012230021 | 50-389 0 | | 8012170409 | 50-364 P | CONDON, V. H. | 8012020468* | 50-287 Q |
| CHILK, B. J. | 8012240153 | 10CFR | | 8012180585 | 50-348 Q | CONDON, V. H. | 8012020460 | 50-289 Q |
| CHILK, B. J. | 8012050376 | 50-327 0 | | 9012180611 | 50-348 Q | CONDON, V. H. | 8012160144 | 50-219 Q |
| CHILK, B. J. | 8012270525 | 50-387 0 | | 8012100424 | 50-348 P | CONLON, T. E | 8012240141* | 70-143 |
| CHILK, B. J. | 8012300278 | 50-247 Q | CLAYTON, F, L, | 8012100519 | 50-348 8 | CONLON. T. E. | 8012020159* | 50-367 Q |
| CHILK, B. J. | 8012300703 | 10CFR | CLAYTON, F, L, | 8012100556 | 50-364 8 | | 8012120377* | 50-566 Q |
| CHILK, B. J. | 8012310132 | 50-387 Q | CLAYTON, F, L, | 8012230309 | 50-364 P | | 8012090524* | 50-424 Q |
| CHILK, B. J. | 8012300673 | 10CFR | CLAYTON, F, L, | 8012230461 | 50-348 P | | 8012110539* | 50-321 Q |
| CHILK, B. J. | 8012150241 | 50-443 G | CLAYTON, F, L, | 8012150235 | 50-364 8 | | 8012170076* | 50-413 Q |
| CHILK, B. J. | 8012300281 | 50-143 C | CLAYTON, F. L. | 8012230463 | 50-364 P | CONLON, T, E. CONLON, T. E. CONLON, T. E CONNAUGHTON, K. CONNAUGHTON, K. A | B012110623* | 50-413 0 |
| CHILK, B. J. | 8012300672 | 10CFR | CLAYTON, F. L. | 8012230504 | 50-348 F | | B012110144* | 50-261 0 |
| CHILK, B. J. | 8012300678 | 10CFR | CLAYTON, F. L. | 8012160345 | 50-348 B | | B012110629* | 50-250 0 |
| CHILK, B. J. | 8012240144 | 50-387 G | CLAYTON, F. L. | 8012170484 | 50-348 P | | B012020780* | 50-373 0 |
| CHILK, B. J. | 8012230288* | 50-375 D | CLAYTON, F. L. | 8012160398 | 50-364 R | | B012110753* | 50-186 0 |
| CHILK, B. J. | 8012270185 | 50-409 Q | CLAYTON, F. L. | 8012160403 | 50-348 R | CONNER, T. B. | 8012030053* | FOIA |
| CHILK, B. J. | 8012300210 | 50-389 Q | CLAYTON, F. L. | 8012270274 | 50-364 P | | 8012030059* | FOIA |
| CHILK, B. J. | 8012300379 | 50-484 Q | GLAYTON, F. L. | 8012230422 | 50-364 P | | 8012030031* | FOIA |
| CHILBON, V. T. | 8012160468* | 50-250 R | CLAYTON, F. L. | 8012300627 | 50-349 B | | 8012120542 | 27-39 |
| CHILBON, V. T. | 8012180265* | 50-250 R | GLAYTON, F. L. | 8012310340 | 50-348 P | | 8012120542 | 27-39 |
| CHIPMAN, W. A. CHIPMAN, W. A. CHIPMAN, W. A. CHONIN, N. CHONIN, N. | 8012030377* 8012030475* 8012030571* 8012290400 8012290400 | FOIA FOIA FOIA 50-250 0 50-250 0 | CLAYTON, F. L. | 8012230476 8012270314 8012300533 8012300523 8012300543 | 50-348 F 50-364 P 50-348 9 50-348 8 | CONNELL, C. CONNER, E. L. CONNELLY, E. B. CONNER, T. B. CONNER, T. B. | 8012220321* 8012170224 8012310268 8012310271 8012310271 | 50-286 R 50-336 Q 50-271 H 50-358 Q 50-358 Q |
| CHOPRA, D. | 8012170137 | PR | CLEMENT; C. | 8012020535* | 50-336 S | CONFOLLY, R. J. CONNOLLY, R. J. CONOVER, W. K. CONRAD, V. L. CONRAD, C. | 8012030195* | FOIA |
| CHOULES, N. C. | 8012040678* | 50-316 Q | CLEMENTS; B. R. | 8012230487 | NUREO | | 8012030320* | FOIA |
| CHRISTIANSON, U. | 8012110703* | 50-331 Q | GLEMONS; P. | 8012090258* | 70-920 | | 8012030705 | 50-289 H |
| CHRISSOTIMOS, N. | 8012180157* | 50-254 Q | CLEMONS; P. | 8012190553* | 70-687 | | 8012090037 | PR |
| CHRISTENBURY, E. | 8011200241 | 50-267 Q | CLEMONS; P. | 8012190728* | 50-47 G | | 8012110578 | 50-275 O |
| CHRISTOPHER, R. CHRISTIANSON, W. CHRISTIAN, J. E. CHRISTENBURY, E. CHRISTMAN, J. N. | 8012290420* 8012310447* 8012120189 8012080005 8012170819 | 50-220 | CLUCAB, J. COCHRAN, T. B. COCHRAN, T. B. CODELL, R. CODEY, L. R. | 8012170316* 8012180337 8012110562 8012120331 8012010304 | 50-275 H FOIA 50-320 P NUREO 50-272 Q | CONSTABLE, D. L. CONSTUM, L. CONTE, S. O. CONTE, R. CONVERSE, W. E. | 8012020228* 8012030680 8012100072 8012170072 8012030713* | 50-382 0 50-247 H 50-29 H 50-289 S 50-298 S |
| CHRISTMAN, J.N. CHUNG, J.W. CIESZKIEWICZ, S. CLAPP, R.W. CLARDY, L.S. | 8012170817 8012190712* 8012160420* 8012170524* 8012110703* | 50-280 0 50-333 0 50-10 R NUREO 50-331 0 | COFFMAN, W. A. COBAN, N. J. COBOIN, C. L. COBOIN, C. L. COBOIN, C. L. | 8012020389 8012020394 8012010314* 8012020507* 8012020516* | 50-201 P 70-820 50-346 8 50-366 8 50-366 8 | CONMAY, W. F. CONMAY, H. F. CONMAY, W. F. COOK, J. W. COOK, J. W. | 8012100705 8012160430 8012230172 8012020323 8012020577 | 50-271 Q 50-271 R 50-271 P 50-329 A 50-329 S |
| CLARDY, L. S. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. | 8012310447* 8012040353 8012040358* 8012040367* 8012110826 | 50-331 0 50-282 P 50-282 P 50-282 P 50-285 P | COOOIN, C. L. COOOIN, C. L. COOOIN, C. L. COOOIN, C. L. COOOIN, C. L. | 8012090377* 8012090384* 8012150167* 8012150195* 8012170637* | 50-346 B 50-321 B 50-346 B 50-346 B 50-366 B | COOK, J. H. COOK, J. W. COOK, J. W. COOK, J. W. COOK, J. W. | 8012110363# 8012100302 8012160353 8012160443 8012230338 | 50-295 R 50-329 B 50-329 B 50-329 A |
| CLARK, R. A. CLARK, R. A. CLARK, R. J. CLARK, R. A. CLARK, R. A. | 8012110828* 8012110832* 8012040007 8012110429 8012120533* | 50-285 P 50-285 P 50-259 F 50-285 P 50-336 P | COOOIN, C. L. COOOIN, C. L. COOOIN, C. L. COOOIN, C. L. COHEN, I. | 8012230549* 8012240285* 8012240304* 8012270253* 8012230061* | 50-366 8 50-366 8 50-366 8 50-366 8 | COOK, J. W. COOK, J. W. COOKE, W. D. COOKE, W. D. | 8012230277 8012300460 8012310223 8012100136 8012070143# | 50-329 B 50-329 B 50-329 R PR 70-1257 |
| CLARK, R. A. | 8012230121 | 50-338 P | COHN, D. B. | 8012270535 | 50-367 0 | CDOLEY, L, R. CDONEY, M. J. GOONEY, M. J. GOONEY, M. J. GOONEY, M. J. | 8012110186 | PR |
| CLARK, R. A. | 8012230127* | 50-338 P | COHN, D. B. | 8012270538* | 50-367 0 | | 8012010440 | 30-277 B |
| CLARK, R. A. | 8012230139* | 50-338 P | COHN, D. B. | 8012270535 | 50-367 0 | | 8012010455* | 50-277 B |
| CLARK, R. A. | 8012140515 | 50-285 P | COHN, D. B. | 8012270538* | 50-367 0 | | 8012010472 | 50-277 B |
| CLARK, R. A. | 8012170472 | 50-338 P | COLBURN, T. G. | 8012010140 | 50-367 0 | | 8012090464 | 50-277 S |
| CLARK, R. A. | 8012170494 | 50-338 P | COLEMAN, A. C. | 8012300250 | 50-272 | COONEY, M. J. | 8012090470* | 50-277 8 |
| CLARK, R. A. | 8012160607 | 50-348 P | COLEMAN, R. | 8012300158 | | COONEY, M. J. | 8012100499 | 50-278 8 |
| CLARK, R. A. | 8012300267 | 50-344 F | COLEMAN, R. | 8012300139 | | COONEY, M. J. | 8012100499* | 50-278 8 |
| CLARK, A. T. | 8012180436 | PROJ | COLEY, J. L. | 8012180307* | | COONEY, M. J. | 8012090441 | 50-279 8 |
| CLARK, L. | 8012030686 | 50-20 8 | COLHOUN, M. L. | 8012180307* | | COONEY, M. J. | 8012090455 | 50-277 8 |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATECORY | AUTHOR | ACCESSION NUMBER | EUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|--|---|---|--|---|--|--|
| CDONEY, M. J. CDONEY, M. J. CDONEY, M. J. CDONEY, M. J. CDONEY, M. J. | B012170633 B012170641* B012180247 B012180250* B012160472 | 50-278 S 50-278 S 50-278 S 50-277 S 50-277 S 50-277 R | COSTELLO, J. R. COSTELLO, F. COTTER, B. P. COTTLE, W. T. COTTLE, W. T. | 8012220098* 8012110179 8012290402 8012020633* 8012020621* | GA779 I&E 50-170 0 50-327 8 90-327 8 | CRANE, P. A. CRANSTON, A. | 8012160382 8012270086 8012300466 8012310274 8012180156 | 50-275 8 50-275 A 50-275 G 50-275 G PR |
| COONEY, M. J. | 6012230352 | 50-277 8 | COTTLE. W. T. | 8012030674* | 50-327 8 | CRANSTON, A. | 8012290242 | 50-206 H |
| COONEY, M. J. | 8012230358* | 50-277 8 | | 8012080430* | 50-327 8 | CRAWFORD, O. D. | 8012290276* | REGOD |
| COONEY, M. J. | 6012230359 | 50-277 8 | | 8012040376* | 50-327 8 | CREED, J. R. | 8012150261* | 50-266 Q |
| COONEY, M. J. | 8012310320 | 50-278 8 | | 8012070358* | 50-327 6 | CREED, J. R. | 8012240061* | 50-305 Q |
| COONEY, M. J. | 8012310323* | 50-278 8 | | 8012150170* | 50-327 8 | CREWS, J. L. | 8012120248 | 50-312 Q |
| CODPER. C. H. COOPER. J. A. COOPER. R. F. COPE, R. H. COPELAND, J. O. | B012100643 B012110241 B012120147 B012080304 B012020634* | REB PR PR PR 50-466 G | COTTLE, W. T. COTTLE, H. T. COTTLE, W. T. COTTLE, W. T. COTTLE, W. T. | 8012160454* 8012170605* 8012230365* 8012230373* 8012300424 | 50-327 8 50-327 8 50-327 8 50-327 8 50-327 8 | CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L. | 8012040336 8012040313 8012040323 8012090022 8012100128 | 50-312 G 50-206 G 50-361 G 50-206 G 50-344 G |
| COPELAND, J. O. COPELAND, P. L. COPELAND, J. O. COPELAND, J. O. COPELAND, R. L. | B012020634* B012020497 B012270005 B012270295 B012270295 | 50-466 | COTTLE, H. T. COTTLE, H. T. COTTLE, H. T. COTTLE, W. T. COTTLE, W. T. COTTON, Q. D. | 8012300548* 8012300444* 8012300535* 8012300544* 8012240427* | 50-327 8 50-327 8 50-327 8 50-327 8 50-327 6 | CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. R. | 8012100140 8012090034 8012310549 8012100031 8012080662 | 50-361 Q 50-275 Q 50-133 Q 50-312 Q PR |
| COPELAND, J. O. | B012270005 | 50-466 Q | COTTON, O. D. | 8012300374* | 50-361 K | CREWS, J. L. | 8012310411 | 50-228 0 |
| COPELAND, J. O. | B012270275 | 50-466 G | COULTER, O. S. | 8012040145 | 50-352 F | CREWS, J. L. | 8012310535 | 50-344 0 |
| COPELAND, J. O. | B012150180 | 50-466 Q | COUNSIL, N. O. | 8012040139 | 50-213 Q | CROCKER, H. W. | 8012240261* | 70-398 |
| COPELAND, J. O. | B012270641 | 50-466 Q | COUNSIL, H. O. | 8012030884* | 50-213 F | CROCKER, H. W. | 8012170687* | 50-201 0 |
| COPELAND, J. O. | B012270641 | 50-466 Q | COUNSIL, H. O. | 8012040151 | 50-336 Q | CROCKER, H. W. | 8012270378 | 40-672 |
| COPELAND, J. O. COPELAND, J. O. COPELAND, R. L. CORBETT, J. S. CORBETT, J. S. | B012270344 B012300654 B012310303 B012030108* B012030052* | 50-466 G 50-466 T 50-537 B 27-10 27-10 | COUNSIL, H. O. COUNSIL, H. O. COUNSIL, H. O. COUNSIL, H. O. | B012080712 B012080712 B012080712 B012090012 B012080230 | NUREO NUREO NUREO 30-245 P 50-336 Q | CROCKER, H. W. CROCKER, L. P. CROMER, B. CROMER, B. CROMER, B. | 8012310266 8012310249* 8012080202 8012300755 8012300758* | 70-364 50-289 T ACR8 ACR8 ACR8 |
| CORDETT, J. 8. CORBETT, J. S. | B012030447* | 27-10 | COUNBIL, H. O. | B012050143 | 71-6698 | CROBBY, P. J. | 8012020554* | 50-219 8 |
| | B012030187* | 27-10 | COUNBIL, H. O. | B012010090 | 50-213 P | CROBBMAN, W. A. | 8012040039* | 50-498 0 |
| | B012030183* | 27-10 | COUNBIL, H. O. | B012010101 | 50-245 P | CROBBMAN, W. A. | 8012020749* | 50-445 0 |
| | B012030042* | 27-10 | COUNBIL, H. O. | B012020334 | 50-336 P | CROBBMAN, W. A. | 8012020762* | 50-482 0 |
| | B012030035* | 27-10 | COUNBIL, H. O. | B012020573 | 50-245 P | CROBBMAN, W. A. | 8012190544* | 50-498 0 |
| CORBETT, J. S. | 8012030058* 8012030510* 8012030468* 8012030374* 8012030375* | 27-10 27-10 27-10 27-10 27-10 | COUNSIL, H. Q. COUNSIL, H. Q. COUNSIL, H. Q. COUNSIL, H. Q. | 8012170330 8012170330 8012310389 8012020253 8012050272 | PR PR 50-245 Q 50-336 P 50-213 P | CROSSHAN, W. A. CROSSHAN, W. A. CROSSHAN, W. A. GROSSHAN, W. A. CROSSHAN, W. A. | 8012240181* 8012170416* 8012170623* 8012180372* 8012100200 | 50-382 Q 50-498 Q 50-498 Q 50-445 Q 50-498 8 |
| CORBETT, J. S. | 8012030281* | 27-10 | COUNBIL, H. O. | 8012170058 | PR | CROSSHAN, H. A. | 8012100174 | 50-482 B |
| | 8012030245* | 27-10 | COUNBIL, H. O. | 8012050202 | 50-245 P | CROSS, J. L. | 8012150107 | 50-327 P |
| | 8012030215* | 27-10 | COUNBIL, H. O. | 8012170058 | PR | CROSS, J. L. | 8012230158 | 50-327 P |
| | 8012030271* | 27-10 | COUNBIL, H. O. | 8012170250 | PR | CROSS, J. L. | 8012230163 | 50-327 F |
| | 8012030165* | 27-10 | COUNBIL, H. O. | 8012070172 | 50-213 Q | CROSS, J. L. | 8012230451 | 50-327 P |
| CORDETT, J. S. CORBETT, J. S. CORDETT, J. S. CORDETT, J. S. CORDETT, J. S. | 8012030159* 8012030121* 8012030054* 8012030039* 8012030508* | 27-10 27-10 27-10 27-10 27-10 | COUNBIL, H. O. COUNBIL, H. O. COUNBIL, H. O. COUNBIL, H. O. | 8012180451 8012160117 8012160117 8012160371 8012230262 | 50-245 P 50-213 P 50-213 P 50-245 P 50-213 P | CROUSE, C. S. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. | 8012230370 8012020559# 8012020594# 8012020270 8012020430 | NUREO 50-346 G 50-346 G 50-346 F 50-346 P |
| CORBETT, J. S. CORBETT, J. S. CORBETT, J. S. CORBETT, J. S. ORBETT, J. S. | 8012030372* | 27-10 | COUNBIL, M. O. | 8012220123 | 50-245 0 | CROUSE, R. P. | 8012310569 | 50-346 Q |
| | 8012030420* | 27-10 | COUNBIL, M. O. | 8012230262 | 50-213 P | CROUSE, R. P. | 8012090414 | 50-500 A |
| | 8012030348* | 27-10 | COUNBIL, M. O. | 8012220123 | 50-245 Q | CROUSE, R. P. | 8012310422 | 50-346 Q |
| | 8012030310* | 27-10 | COUNBIL, M. O. | 8012270270 | 50-245 P | CROWLEY, C. J. | 8012230509 | NUREQ |
| | 8012030322* | 27-10 | COHAN, B. Z. | 8012020758 | 70-2909 | CROWLEY, C. J. | 8012230340 | NUREQ |
| RBETT, J. B. | 8012030202* | 27-10 | COHAN, B. Z. | 8012020758 | 70-2909 | CROWLEY, B. R. CROWLEY, B. R. CROWN, H. M. CRUMP, D. CRUTCHFIELD, D. | 8012020404* | 50-364 G |
| RBETT, J. B. | 8012030186* | 27-10 | COHAN, B. Z. | 8012270204 | 70-2909 | | 8012110847* | 50-518 G |
| RBETT, J. S. | 8012030200* | FOIA | COHAN, B. Z. | 8012270011 | 70-2909 | | 8012080503* | CONTRACT |
| RCORAN, T. | 8012090413* | COMMISSION | COHOILL, C. J. | 8012300080* | 50-277 @ | | 8012300685 | 50-466 G |
| RD, E. | 8012080822* | 50-320 H | COX, J. P. | 8012030357* | FOIA | | 8012110060 | 50-217 P |
| RDANI, R. A. | 8012040539 | 70-27 | COX, J. P. | 8012030088* | FOIA | CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012080574 | 50-219 P |
| RDANI, R. A. | 8012020297 | 70-27 | COX, J. P. | 8012030111* | FOIA | | 8012080672 | 50-213 P |
| GRELEY, T. F. | 8012110219 | PR | COX, J. P. | 8012030032* | FOIA | | 8012110009 | 50-135 P |
| GRHIER, W. H. | 8012300351 | 50-142 0 | COX, J. P. | 8012030438* | FOIA | | 8012110377 | 50-27 P |
| DRHIER, W. | 8012100171* | 50-142 0 | COZENS, Q. | 8012170324* | 50-187 R | | 8012080533 | 50-10 0 |
| RMELL, H. | 8012170030 | PR | CRANDALL, H. E. | 8012170314 | 50-187 R | CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012110027 | 50-185 P |
| RMELL, U. | 8012160588 | PR | CRANE, F. A. | 8012240129* | 50-275 F | | 8012110018 | 50-217 P |
| RRADINI, M. L. | 8012020657 | NUREO | CRANE, F. A. | 8011260125 | 50-275 A | | 8012110054 | 50-217 0 |
| "RREA, H. A. | 8012020562 | 50-89 J | CRANE, P. A. | 8012050430 | 50-275 A | | 8012110270 | 50-245 F |
| JRREA, H. A. | 8012010360 | 50-272 J | CRANE, P. A. | 8012080335 | 50-275 A | | 8012010503 | 50-10 P |
| ORRIGAN, K. W. | 8012110273 | PR | CRANE: P. A. | 8012040520 | 50-275 A | CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012040128 | 50-255 P |
| JORYELL, E. W. | 8012040591 | REB | CRANE: P. A. | 8012070329 | 50-275 A | | 8012170476 | 50-213 P |
| GOBBY, J. C. | 8012040114 | 50-329 F | CRANE: P. A. | 8012270008 | 50-275 G | | 8012110414 | 50-255 P |
| GOBBY, J. C. | 8012040118 | 50-334 F | CRANE: P. A. | 8012270469* | 50-275 F | | 8012080748 | 50-255 P |
| GOBBY, J. C. | 8012040141 | 50-322 F | CRANE: P. A. | 8012070338 | 50-133 P | | 8012110039 | 50-213 F |
| COSBY, J. C. | 8012040145 | 50-352 F | Crane, P. A. | 8012070360 | 50-275 A | CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012120356 | 50-155 P |
| COSBY, J. C. | 8012040149 | 50-309 F | Crane, P. A. | 8012050273 | 50-275 A | | 8012080527 | 50-213 Q |
| COSBY, J. C. | 8012040155* | 50-245 F | Crane, P. A. | 8012070235 | 50-275 A | | 8012040211 | 50-245 P |
| COSBY, J. C. | 8012040171 | 50-341 F | Crane, P. A. | 8012110386 | 50-275 F | | 8012090038 | 50-244 P |
| COSBY, J. C. | 8012040180 | 50-289 F | Grane, P. A. | 8012110526 | 50-275 A | | 8012090580 | 50-237 P |
| COBBY. J. C. | 8012040186 | 30-245 F | CRANE, P. A. | 8012270542 | 50-275 Q | CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012080521 | 50-27 F |
| COSBY. J. C. | 8012040238 | 30-367 F | GRANE, P. A. | 8012100470 | 50-275 A | | 8012180620 | 50-10 P |
| COSTANINO, C. J. | 8012310224 | NUREQ | GRANE, P. A. | 8012270136 | 50-275 A | | 8012180633* | 50-10 P |
| COSTELLO, J. R. | 8012020733* | QA999 | GRANE, P. A. | 8012150149 | NUREO | | 8012180671* | 50-10 P |
| COSTELLO, J. R. | 8012190454* | QA999 | CRANE, P. A. | 8012160158 | 50-275 A | | 8012110076 | 50-213 P |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|--|--|---|--|---|---|--|
| CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012110426 8012110435 8012120417 8012150117 8012150123* | 50-10 P 50-206 P 50-255 P 50-245 Q 50-245 Q | DAHLMAN, L. D. DAIL, L. C. DAIL, L. C. DAIN, J. Q. DALE, L. F. | 8012240294# 8012170044 8012180283 8012120185 8012050564 | 50-282 G PR PR PR PR 70-2934 | DELGEORGE, L. O. DELGEORGE, L. O. DELGEORGE, L. O. DEMPSEY, P. A. DENALUT, E. W. | 8012040481 8012150139 8012160655 8012050098 8012030484* | 50-373 A 50-373 K 50-373 A PR FOIA |
| CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012110808 8012110812* 8012110819* 8012080135 8012190329 | 50-245 P 50-245 P 50-245 P 50-219 P 50-244 P | DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F. | 8012080184 8012020449 8012160497 8012240250 8012300489 | REOGD 30-416 C 30-416 K 50-416 A 50-416 C | DENAULT, E. W. | 8012030582* 8012030547* 8012030500* 8012030593* 8012030580* | FOIA FOIA FOIA FOIA FOIA |
| GRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012070041 8012070531 8012170660 8012110440 8012170274 | 50-213 P 50-213 P 50-213 P 50-255 P 50-27 P | DALTON, A. T. DALTROFF, B. L. DALTROFF, B. L. DALTROFF, D. O. DALTROFF, B. L. | 8012030595* 8012300051* 8012020358 8012230493 8012310310 | FOIA 50-277 Q 50-277 P 50-277 P 90-277 P | DENAULT, E. W. DENESS, S. J. DENESS, S. J. DENHAM, D. H. DENNINO, R. S. | 8012030685# 8012020537 8012270302 8012070095# 8012230066 | FDIA 50-142 J 50-142 J 50-344 Q 50-320 P |
| CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. | 8012170314 8012170321* 8012170330* 8012240477 8012240476 | 50-219 F 50-213 P 50-213 P 50-155 P 50-255 P | DALTROFF, B. L. DALY, M. J. DALZELL, M. G. DANGE, H. C. DANGE, H. G. | 8012310327 8012010508 8012150113* 8012170512* 8012020441* | 50-277 P PR 50-327 P 50-259 Q 50-390 Q | DENNINO, R. 8. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. | 8012110057 7907030173> 8012290426* 8012290431* 8012290434* | RE6 50-367 0 50-220 0 50-220 0 50-220 0 |
| CRUTCHFIELD, D. CRUTCHFIELD, D. CULP, R. H. CULP, R. H. CULVER, C. | 8012270475 8012270479 8012270071 8012270071 8012170243 | 50-409 P 50-244 P 50-466 O 50-466 O PR | DANCE, H. C. DANFORTH, J. C. DANIELSON, D. H. DANIELSON, D. H. DANIELSON, T. H. DANIELS, F. T. | 8012020364* 8012300443 8012310518* 8012180135* 8012110110* | 50-257 Q 50-483 H 50-341 Q 50-358 Q | DENTON, H. R. | 8012110656# 8007160606 8012230033# 8011180303 8012120075 | FOIA MISC 50-387 Q State Prog 50-170 H |
| CULVER, M. W. CUMMINOB, J. J. CUMMINOB, E. CUNNINOHAM, R. E. CUNNINOHAM, R. E. | 8012160487* 8012240432* 8012300135 8012030339* 8012030329* | 50~302 R 50~10 Q 50~466 G FOIA FOIA | DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H. | 8012040488* 8012110016* 8012080236* 8012190227* 8012190279* | 50-341 Q 50-461 Q 50-454 Q 50-456 Q 50-331 Q | DENTON, H. R. | 8012020642 8012050061* 8012310504 8011200546 8012010246 | 50-295 H 8ECY 50-320 H 50-320 P MISC |
| CUNNINGHAM, R. E. | 8012030187* 8012030136* 8012030167* 8012030176* 8012030113* | FOIA 27-39 27-39 27-39 27-39 | DANIEL, J. A. DAD, L. T. DASS. R. DAVIDSON, J. P. DAVIDSON, D. R. | 8012220388* 8012080010 8012110644 8012220258* 8012070300 | 50-320 P NUREG PR FOIA 50-440 S | DENTON, H. R. | 8012010411 8011250165 8012230040* 8012020353* 8012020020 | 50-289 H 50-395 D 50-389 Q 10GFR 50-275 O |
| CUNNINGHAM, R. E. CUNNINGHAM, R. E. CUNNINGHAM, R. E. CUNNINGHAM, R. E. CUNNINGHAM, R. E. | 8012030048* 8012030037 8012030007* 8012030003* | 27-39 27-39 27-39 27-39 27-39 | DAVIDSON, D. R. DAVIDSON, D. R. DAVIDSON, D. R. DAVIDSON, D. R. DAVIDSON, D. R. | 8012100421 8012070307 8012160362 8012300464 8012300579 | 50-440 8 50-440 8 50-440 0 50-440 0 50-440 8 | DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. | 8012020023* 8012020440 8012110748 8012180433 8012180534 | 50-275 Q 50-364 E DRQ 50-213 H 50-213 H |
| Cunninoham, A. L. Cunninoham, A. L. Cunninoham, A. L. Cunninoham, R. E. Cunninoham, J. | 8012180184* 8012180167* 8012180308* 8012220088 8012300264 | 50-553 Q 50-438 Q 50-302 Q PROJ 50-207 Q | DAVIS, H. C. DAVIS, J. E. DAVIS, T. G. DAVIS, J. G. DAVIS, J. G. | 8012030254* 8012270506* 8012110735* 8012010188* 8012010279* | FOIA 30-320 F FOIA 71-9073 71-9073 | DENTON, H. R. | 8012170260 8012240441 8012310635 8012070023 8012120227 | 50-213 H 50-213 P 50-213 P MISC 50-320 H |
| CURNANE, R. A. CURRAN, J. M. CURRAN, J. M. CURRIE, J. W. CURTIS, N. W. | 8012020716* 8012160335 8012170628* 8012040606 8012080370* | QA999 50-204 R 50-204 B RES 50-387 Q | DAVIS, J. Q. DAVIS, A. B. DAVIS, J. Q. DAVIS, J. Q. DAVIS, J. Q. | 8012220534* 8012070039 8012010133* 8011140484* 8012110193 | 50-10 P 50-254 0 71-9073 10CFR FOIA | DENTON, H. R. | 8012120653 8012170669 8012170678* 8012160639 8012160717* | 50-320 H 50-237 0 50-237 0 50-389 0 50-389 0 |
| CURTIB, N. W. CURTIB, C. B. CURTIB, C. B. CURTIB, J. R. CURTIB, N. W. | 8012190028 8012080363* 8012290513 8012310546* 8012230337 | 70-2937 30-387 Q 50-320 I 50-340 Q 50-387 8 | DAVIS, A. B. DAVIS, A. B. DAVIS, A. B. DAVIS, A. B. DAVIS, J. O. | 8012040255 8012160573 8012180406 8012310550+ 8012010126 | 30-331 0 50-182 0 50-2 0 40-7402 71-9073 | DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DETMOLD, D. | 8012220485 8012290384 8012290075 8012290077 8012150192 | 50-10 P 50-514 A 50-275 A 50-323 A 50-271 H |
| CURTIS, N. W. | 8012310383 8012010324 8012020452 8012020585 8012020588 | 50-387 G 50-387 S 50-387 B 50-387 S 50-387 S | DAVIB, B. J. DAVIB, A. B. DAVIB, A. B. DAVIB, A. B. DAVIB, A. B. | 9012100257 8012180431 8012020099 8012230187 8012220093 | PR 70-925 50-254 Q 50-373 Q 40-3392 | DETORIE, N. A. DEVINCENTIB, J. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012120071 8012070232* 8012080800 8012080807* 8012110035 | PR 50-443 Q XPORTLIC XPORTLIC XPORTLIC |
| CURTIS, N. W. | 8012030663 8012020448 8012230474 8012230477* 8012090353 | 50-397 8 50-387 A 50-387 K 50-387 K 50-387 A | DAVIE, A. B. DAVIE, D. DAVIE, E. K. DAVIE, A. B. DAVIE, A. B. | 8012020071 8012110545 8012010336* 8012110788 8012160520 | 50-10 P 70-2623 50-318 \$ 50-150 0 50-454 Q | DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012030631* 8012080146 8012080112 8012080137 8012100197 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC |
| CURTIS, N. U. CURTISS, J. R. | 8012110415 8012160037 8012160348 8012170573 8012270207 | 50-387 A 50-387 A 50-387 A 50-387 B 50-369 0 | DAVIS, A. B. DAVIS, T. J. DAVIS, J. G. DAVIS, B. B. DAVIS, S. M. | 8012180234* 8012110453 8012230220 8012170742* 8012160394* | 70-36 NUREO WASTE HOT 50-289 H 50-317 S | DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012100201 8012100204 8012100210 8012100222 8012170241 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC |
| CURTIS, N. W. | 8012220463 8012240190 8012300661 8012300306 8012310098 | 50-387 A 50-387 V 50-387 B 50-387 A 50-387 F | DAHBON, D. M. DAHBON, D. M. DAHBON, D. M. DAY, R. A. DE ALMEIDA, O. L. | 8012010622 8012020307 8012290531* 8012040118 8012170259 | 70-1308 70-1308 70-1308 50-334 F REGOD | DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012080104* 8012080054 8012080067 8012080086 8012080097 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC |
| CURTNER, A. P. CUTCHIN, J. M. CYBULSKIS, P. CYBULSKIS, P. CYR, K. | 8012030690 8012270558 8012230066 8012110057 8012220322 | 50-124 P 50-287 T 50-320 P RES 50-409 0 | DE LIONIBUB.O. DEALE, V.B. DEALE, V.B. DEAN.B. DEAN.B.R. | 8012170173 8012290311 8012290436 8012120326* 8012080834* | PR 50-445 G 50-445 Q 50-313 Q 50-313 Q | DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012080138 8012080144 8012080150 8012100439 8012110367 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC |
| CYR, K. D. D'AHORE, M. D'AHORE, M. D'ANOELD, A. J. D'ANOELG, A. J. | 8012290289 8012090169# 8012090165# 8012010014# 8012040310# | 50-409 | DEARIEN, J. A. DEFRIESS, F. P. DELDEC, J. DELGEGROE, L. O. DELGEGROE, L. O. | 8012040097 8012080277 8012030465* 8012170697* 8012020465 | PR PR FDIA 50-373 Q 50-373 A | DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. | 8012090534 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCEBBION NUMBER | SUBJECT CATEOURY | AUTHOR | ACCESSION NUMBER | BUBJECT CATEGORY |
|---|---|--|--|---|--|--|---|---|
| DEVINE, J. B. | 8012070542 8012070546 8012070547 8012100012 8012110072 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. | 8012010205* 8012020824 80120210259* 8011280117* 8012190705* | 71-9073 50-170 H PR 10CFR 10CFR | DUCKWORTH, J. P. DUCKWORTH, J. P. DUDLEY, J. DUELFER, T. DUFFEE, R. | B012040362 B012040410* B012220246* B012010522 B012160441 | 50-201 R 50-201 R FOIA PR 50-247 H |
| DEVINE, J. B. | 8012230208 8012230237 8012240367 8012300313 8012100427 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. | 8012010418* 8012050001 8012020815 8011200243 8012010584 | FR ORO 50-293 H 10CFR 50-324 U | DUFFY, D. DUMAS, Q. T. BUNDUL IS, W. P. BUNN, G. N. BUNN, C. N. | 8012170101 8012270518 8012080401 8008210481 8012100083* | PR 50-133 Q REGOD 50-334 Q 50-334 Q |
| DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012240315 8012160755 8012240317 8012240319* 8012240364 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | Dircks, W. J. Dircks, W. J. Dircks, W. J. Dircks, W. J. | 8012030850 8012030701 8012030053 8012030842 8012030774 | MISC XPORTLIC SECY 50-466 Q 50-269 H | DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, G. N. DUNN, B. D. | 8012090001 8012090010 8012020355 8012080456 8012190535* | 50-334 G 50-334 G 50-334 P 50-334 F 50-280 R |
| DEVINE, J. B. DEVINCENTIS, J. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012140640 8012110564 8012170242 8012170245 8012170248 | XPORTLIC 50-443 A XPORTLIC XPORTLIC XPORTLIC | Dircke, W. J. Dircke, W. J. Dircke, W. J. Dircke, W. J. | 8012030786 8012030773 8012039814 8012080765 8012120220 | 50-320 H 8ECY 50-320 U 8ECY 8ECY | DUNN, G. N. DUNN, C. N. DUNN, C. N. DUNN, G. A. DUNN, C. N. | 8012150273 8012170463 8012170567 8012240293 8012230299 | 50-334 R 50-334 F 50-334 R 50-397 C 50-334 P |
| DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012170265 8012170269 8012170277* 8012170459 8012180280 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. | 8012100193 8012180327 8012100649 8012100654 8012110474 | ACRS SECY State Prog 30-397 U State Prog | DUNN, G. N. DUPONT, S. Q. DUPRE, B. M. DUPREE, D. DURKOSH, E. D. | 8012300409 8012180157* 8012080255 8012160333* 8012110334 | 50-334 P 50-254 G PR 50-327 R PR |
| DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012230083 8012180269 8012180275 8012220500 8012230086 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | DIRCKB, W. J. DIRCKB, W. J. DIRCKB, W. J. DIRCKB, W. J. DIRCKB, W. J. | 8012110476 8012110484* 8012110488* 8012110481* 8012170467* | State Prog 70-143 70-143 70-143 100FR | DURR, J. P. DURR, J. P. DURR, J. P. DURBT, F. DWORETZKY, B. A. | 8012080406* 8012080378* 8012110607* 8012240309 8012170150 | 50-387 G 50-387 G 50-387 G NUREG PR |
| DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. | 8012230091 8012230094 8012300224 8012300782 8012310073 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | DIRCKS.W.J. DIRCKS.W.J. DIRCKS.W.J. DIRCKS.W.J. DIRCKS.W.J. | 8012180416 8012270483* 8012270585 8012270030 8012270485* | SECY 10CFR SECY COMMISSION 10CFR | DHORKIN, H. J. DYBAS, J. A. DYM, H. DYMEK, E. J. EADIE, G. O. | 8012080352 8012110212 8012270370 8012050418 8012240076 | PR PR 50-389 M 50-97 J Waste Mot |
| DEVINE: J. B. DEVINE: J. B. DEVINE: J. B. DEVLIN: J. W. DEVLIN: J. W. | 8012310084 8012310100 8012300777 8012090545* 8012220062* | XPORTLIC XPORTLIC XPORTLIC 30-272 Q 50-317 Q | DIRCKS.W.J. DISALVO.R. DISE.D.P. DISE.D.P. DISE.D.P. | 8012270043 8012110326 8012040424 8012040438 8012070343 | COMMISSION PR 50-220 P 50-220 P 50-410 S | EARL, E. EATON, T. E. EBERBOLE, J. EBNETER, B. D. EBNETER, B. D. | 8012030511* 8012100209* 8012160608* 8012020216* 8012230041* | FOIA CONTRACT ACRB 50-289 Q 50-352 Q |
| DEVLIN, J. W. DEVLIN, J. W. DEVLIN, J. W. DEVLIN, J. W. DEVLIN, J. | 8012020205* 8012110635* 8012220085* 8012220069* 8012100239 | 50-29 Q 70-1425 50-289 Q 50-220 Q 50-247 8 | DISE, D. P. DISE, D. P. DISE, D. P. DISE, D. P. DDDDS, R. T. | 8012230321 8012170377 8012300503 8012230472 8012310227* | 50-220 P 50-220 P 50-220 P 50-220 P 50-344 Q | EBNETER, S. D. | 8012190655* 8012300169* 8012230080* 8012190717* 8012300185* | 50-334 0 50-289 0 50-410 0 50-387 0 50-272 0 |
| DEVLIN, J. DEWEY, L. G. DEWITT, R. B. DEWITT, R. B. DEWITT, R. B. | 8012100164 8012120544 8012010189 8012010160* 8012010287* | 50-336 8 50-387 M 50-155 P 50-255 P 50-255 P | DDOGETT, S, A. DDLAN, J. F, DDNAHUE, J. R. DDNALDSDN, D. E. DDNALDSDN, D. E. | 8012300587 8012030479* 8012180026* 8012080195* 6012220348* | 5D-466 | ECKERT, T. ECKHARDT, J. H. ECKHAUSER, F. ECONOMOS, N. ECONOMOS, N. | 8012120322 8012010014* 8012110166 8012180118* 8012170048* | NUREQ 50-528 G PR 50-414 G 50-338 G |
| DEWITTER, 8. DEWITTER, 8. DEWITTER, 8. DIAHONDED, J. DIAZEN, J. | 8012090426* 8012230209* 8012300502 8012190146 8012230348* | 50-155 P 50-255 P 50-155 P REB 50-83 R | DONATI.R.M. DONAVAN.R.X. DONELBON.G. DONELBON.C. DONO.R.O. | 6012050519 6012030645# 6012270633 6012310446 8012120307 | PR F01A 70-2909 70-2909 NUREG | ECONOMOB, N. EDGAR, G. L. EDLER, B. K. EDLER, B. X. EDMONSON, L. R. | 8012170039* 8012180227 8012120343 8012240507 8012240036* | SO-280 Q PR Nureo Nureo Contract |
| DIAZ, N. J. DIAZ, N. J. DIAZ, N. J. DICK, W. E. DICKENSON, R. E. | 8012160107 8012230344 8012300506 8012240340 80120 7 0310 | 50-83 I 50-83 R 50-83 P XPORTLIC 50-367 A | DONLON. W. J. DONGVAN. R. X. DOPSOVIC. D. A. DOSIN. S. DOUGHERTY. D. J. | 8012290491 8012030607* 8012300250 8012110583 8012110696* | SQ-220 G FOIA SQ-445 M PR CONTRACT | EDWARDS, D. W. EDWARDS, L. A. EDWARDS, D. W. EECKHOUT, A. EECKHOUT, A. | 8012040334 8012110527* 8012180259 8012080639 8012240326 | PR CONTRACT PR XPORTLIC XPORTLIC |
| DIECKAMP, H. DIECKAMP, H. DIECKAMP, H. DIECKAMP, H. DIECKAMP, H. | 8012110417* 8012050384 8012150178* 8012300269* 8012170610 | 50-287 0 50-287 0 50-287 0 50-287 0 50-289 0 | DOUGHERTY, D. J. DOUGHERTY, J. DOUGHERTY, D. J. DOUGHERTY, D. J. DOUGHERTY, D. J. | 8012110139 8012110139 8012310262* 80123102309 8012110357* | CONTRACT PR 50-445 M 27-39 CONTRACT | EHRENSPEROER, W. EHRENSPEROER, W. EHRENSPEROER, W. EHRENSPEROER, W. EHRET, C. F. | 8012020460 8012230197 8012310296 8012310298* 8012110755* | 50-424 A 50-424 A 50-424 B 50-424 B FOIA |
| DIEDRICK, D. G. DIETCH. R. DIETCH. R. DIETCH. R. DIETCH. R. | 8012020768 8012030716 8012120413 * 8012120399 8012310092 | TOPREP 50-206 P 50-206 P 50-206 P 50-206 F | DOUGHTY, J. DOUGLAS, . M. H. BOWLING, L. J. DRAKE, J. B. DRAPER, E. L. | 9012050379 8012150186 8012150153 8012220181 8012050540* | 50-443 H 50-289 H 50-271 H NUREO 50-458 F | EHRMANN, E. EIGH, E. EIGHHORN, W. H. EIGHHORN, W. H. EIGHHORN, W. H. | 8012150172 8012230304* 8012270181 8012270181 8012310437 | 50-289 0 50-247 R 50-367 0 50-367 0 50-367 0 |
| DIETCH R. DIETCH R. DIETCH R. DIETCH R. DIGOB.R.M, | 8012240427* 8012300369 8012300374* 8012240425 9012090213 | 50-361 C 50-361 K 50-361 K 50-361 C 50-289 P | DRAPER, E. L. | 8012170433* 8012030783 8012220447 8012170438* 801222085 | 50-458 Q 50-458 Q 50-458 Q 50-458 Q 50-458 Q | EICHHORN, W. H. EIDMAN, V. EIDBON, A. F. EILPERIN, B. F. EILPERIN, B. F. | 8012310437 8012150152 8012040061 8012240039* 8012240078* | 50-367 0 50-466 0 NUREQ COMMISSION COMMISSION |
| Digge, R. M. Digge, R. Dignan, T. O. Dignan, T. O. Dignan, T. O. | 8012170627 8012270272* 8012230010 8012230010 8012170588 | 50-259 P 50-267 P 50-443 Q 50-443 Q 50-273 Q | DRAPER, E. L. DRAPER, E. L. DRAPER, E. L. DREY, L. A. DREY, L. A. | 8012170534* 8012160388 8012310332 8012040179* 8012160073* | 50-458 G 50-458 A 50-458 A 70-1308 50-10 G | EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. | 8008150060 8012020753 8012080530* 8012290012 8012290013* | 50-275 A 50-3 P 50-213 0 50-416 A 50-416 A |
| DIGNAN T. O. DILLON, J. U. DILBAVER, D. DIPIAZZA, R. P. DIRCKS, W. U. | 8012190598 8012150150 8012110400 8012080748 8012080748 | 50-293 G 50-287 H 50-287 H 71-5450 71-9073 | DREY, L. A. DREYER, N. A. DROMERICK, A. W. OUBGSE, D. B. DUBRY, N. E. | 8012040298* 8012170524* 8012170096 8012170668 8012110124* | 50-437 H NUREO 50-339 P 50-289 H 50-315 Q | EISENHUT, D. O. EISENHUT, D. O. EISENHUT, D. O. EISENHUT, D. O. EISENHUT, D. O. | 8012140050 | 50-217 F 50-255 F 50-29 F 50-3 P 50-10 P |
| | | | | 4837% | | | | • |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION | SUBJECT |
|--|---|--|---|--|--|--|---|--|
| EIBENHUT, D. G. EIBENHUT, D. G. EIBENHUT, D. G. EIBENHUT, D. G. EIBENHUT, D. G. | 8012170011 8012170015 8012170017 8012170335 8012170338 | 50-244 F 50-213 F 50-409 F 50-206 F 50-155 F | ENOELKEN, R. H. ENOELKEN, R. H. ENOELKEN, R. H. ENOELKEN, R. H. ENOELKEN, R. H. | 8012170841 8012170844 8012170847 8012170852 8012170857 | 50~344 Q 50~528 Q 50~397 Q 50~204 Q 50~133 Q | FARMER, W. S. FARMER, W. S. FARMER, W. S. FARNELL, A. S. FARNEWORTH, D. A. | NUMBER | FOIA FOIA FOIA FOIA 50-329 Q TOPREP |
| EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. | 8012190342 8012040010 8012040079 8012040096 8012040099 | 50-10 F 50-249 F 50-271 F 50-333 F 50-298 F | ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. | 8012120236 8012120231 8012120231 8012120236 | 50-528 q 50-312 q 50-397 q 50-344 q 50-275 q | FAGANO, A. N. FAULKENBERRY, B. FAULKENBERRY, B. FAULKENBERRY, B. FAULKENBERRY, B. | 8012100179 8012120253* 8012040339* 8012040319* 8012040329* | 50-320 8 50-312 0 50-312 0 50-206 0 50-341 0 |
| EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. | 8012205034 8012220543 8012220543 8012010534 8012070007 | 50-331 F NUREO 50-3 P 50-369 A 50-338 F | ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. | 8012120240 8012120244 8012120247 8012030914 8012030916 | 50-206 | FAULKENBERRY, B. FAULKENBERRY, B. FAULKENBERRY, B. FAULKENBERRY, B. FAULKENBERRY, R. | 8012070029* 8012100147* 8012100054* 8012310415* 8012270200* | 50-206 G 50-361 G 50-312 G 50-228 G 50-287 H |
| EIBENHUT, D. O. EIBENHUT, D. G. EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. | 8012070511 8012100594 8012110004 8012110012 8012040248 | 50-309 F 50-348 F 50-335 F 50-336 F 50-295 F | ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. | 8012030920 8012030934 8012030935 8012030936 8012080621 | 50-528 Q 50-133 Q 50-344 Q 50-312 Q 50-312 Q | FAY, C. H. FAY, C. W. FAY, C. W. FAY, C. W. FAY, C. W. | 8012050642* 8012080177 8012010364 8012010372* 8012070306 | 50-266 F REGGD 50-266 B 50-266 B 50-301 S |
| EISENHUT, D. O. | 8012050172 8012050180 8012050190 8012050197 8012050205 | 50-247 F 50-280 F 50-250 F 50-334 F 50-286 F | ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. | 6012080638 6012080632 6012080636 6012080658 | 50-344 Q 50-133 Q 50-528 Q 50-206 Q 50-397 Q | FAY, C. W. FAY, C. W. FAY, C. W. FAY, C. W. FAY, C. W. | 8012090314* 8012180277 8012090378 8012230069 8012240473 | 50-301 S PR 50-246 F 50-266 O 50-264 Q |
| EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. | 8012080750 8012080753 8012070516 8012170645 8012230105 | 50-261 F 50-348 F 50-266 F 50-289 F 50-313 F | engelken, R. H. Engelken, R. H. Engelken, R. H. Engelken, R. H. Engelken, R. H. | 8012040215 8012040220 8012040221 8012040225 8012040230 | 50-528 | FAY, C. W. FAY, C. W. FAY, C. W. FAY, C. W. FAY, C. W. | 8012240409 8012150077 8012160428* 8012160427 8012170549 | 50-266 Q 50-266 P 50-266 R 50-266 R 50-301 B |
| EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. | 8012030819 8012020701 8012080577 8012290415 8012290418 | 50-10 P 50-327 P 50-482 C 50-336 F 50-295 F | ENGELKEN, R. H. ENGELKEN, R. H. ENGEL, R. H. ENGEL, R. H. ENGELKEN, R. H. | 8012040233 8012040241 8012040244 8012100145 8012110422 | 50-397 0 50-361 0 50-206 0 PR 50-206 P | FAY, C. W. FAY, C. W. FAY, C. W. FAY, G. W. FAY, G. U. | 8012170598 8012170604# 8012170606# 8012300593 8012300404 | 50-301 8 50-301 8 50-301 8 50-266 P |
| EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. | 8012270419 8012310006 8012170699 8012310008* 8012190665 | 50-338 F 50-331 F 50-289 P 50-331 F 50-483 C | ENOELKEN, R. H. ENOELKEN, R. H. ENOELKEN, R. H. ENOELKEN, R. H. ENOELKEN, R. H. | 8012040457 8012040461 8012040463 8012040465 8012040538 | 50-206 0 50-312 0 50-344 0 50-133 0 50-526 0 | FAY.C.W. FAZIO.P.V. FEE.W.I. FEE.W.F. FEE.W.F. | 8012300584 8012270165 8012030884* 8012010101 8012270270 | 50-266 P 50-461 Q 50-213 F 50-245 P 50-245 P |
| EIBENHUT, D. Q. EIBENHUT, D. Q. EIBENHUT, D. Q. EIBENHUT, D. Q. EIBNEHUT, D. Q. | 8012180119 8012190457 . G012240155 8012240160# 8012090506 | 50-424 A PR 50-443 A 50-443 A 50-265 F | ENGELKEN, R, H, ENGELKEN, R, H, ENGELKEN, R, H, ENGELKEN, R, H, ENGELKEN, R, H, | 8012040481 8012040485 8012040487 8012140081 8012140087 | 50-397 0 50-361 0 50-275 0 50-397 0 50-206 0 | FEHRINGER, J. H. FEHRINGER, J. H. FEIL, R. A. FEIL, R. A. FEIL, R. | 8012170061 8012170547 8012110605* 8012110079* 8012170511* | 50-407 P 50-312 P 50-410 G 50-412 G 50-423 Q |
| EL-ASHRY, M. T. EL-ASHRY, M. T. ELIA, O. O. ELICEIRI, O. L. ELIN, J. O. | 8012020254 8012230355 8012050492* 8012100127 8012310229* | 50-327 R 50-553 R PROJ PR 50-344 Q | ENCELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. | 8012140088 8012160092 8012160095 8012160097 8012160118 | 50-312 | FEINSTEIN, N. FEIR, D. J. FEIT, R. FELLOWS, M. E. FELTON, J. M. | 8012310543 8012120104 8012020246 8012170513* 8005130126 | FOIA PR REVIEW GRP 50-338 R 40-4940 |
| ELLERSHAW, L. E. ELLERSHAW, L. E. ELLERSHAW, L. E. ELLERSHAW, L. E. ELLERSHAW, L. E. | 8012230255# 8012070065# 8012020808# 8012170200# 8012170104# | GA999 GA999 GA999 GA999 GA999 | Enoelken, R. H. Enoelken, R. H. Enoelken, R. H. Enoelken, R. H. Enoelken, R. H. | 8012160121 8012160124 8012160127 8012160130 8012160133 | 50-344 Q 50-133 Q 50-528 Q 50-206 Q 50-397 Q | FELTOX: J. M. FELTON: J. M. FELTON: J. K. FELTON: J. M. FELTON: J. M. FELTON: J. M. | 9012030001 8012010602 8012030872 8012110643 8012020604 | 27-10 50-33B F 50-213 F FOIA FOIA |
| ELLIOT, L. P. ELLIOT, C. P. ELLIOT, C. H. ELLIOTT, W. H. ELLIOTT, C. W. | 8012030138# 8012030264# 8012160423 8012100100 8012270227# | FOIA FOIA FOIA PR 30-387 0 | ENOELHARDT, T. F. ENGELKEN, R. H. ENGELHARDT, T. F. ENGLE, L. ENGLE, L. | 8012240479 8012180313 8012290245 8012020050 8012050034 | MISC 30-344 0 ORO 50-338 P 50-336 P | FELTOH: J. M. FELTON: J. K. | 8012020731 8012020778 8012030874 8012030918 8012020705 | FOIA FOIA FOIA FOIA FOIA |
| ELLIB, J. ELLIB, J. ELLIB, J. ELLIB, J. ELMORE, W. E. | 8012070341 8012270318 8012310280 8012270337 8012160110* | 50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-83 I | ENGLE, L. B. ENTHIBLE, E. ENTHIBLE, E. B. EPSTEIN, L. R. ERB, C. M. | 8012310633 8012120081* 8012290588 8012050629 8012080286* | 50-33B P 50-170 H 50-170 Q PR 50-454 Q | FELTON, J. M. | 8012020720 8012020751 8012020771 8012020864 8012080161 | FOIA FOIA FOIA FOIA |
| ELTIS, M. EMENS, F. M. EMERSON, R. R. EMERY, D. F. EMSWILER, T. R. | 8012020259 8012300119 8012120308 8012290045 8012030834 | 70-33 50-287 H 50-206 P 50-247 H 70-8 | ERB, C. M. ERB, C. M. ERDMAN, H. E. ERDOS, K. ERLICK, J. | 8012140172* 8012240172* 8012120335 8012180225 8012110724 | 50-436 Q 50-440 Q PR PR PR | FELTON, J. M. | 8012080592 8012110200 8012160082 8012080713 8012040701 | 50-416 F F01A 50-10 Q 50-416 F 50-3 F |
| ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. | 8012170680 8012170695 8012170700 8012170708 8012170715 | 50-397 Q 50-206 Q 50-312 Q 50-344 Q 50-133 Q | ERTEL, A. E. ESTES, C. ETHER INOTOK, H. ETZLER, D. H. ETZLER, D. H. | 8012030769# 8012050368 8012160565 8012030255# 8012030507# | 50-320 U 50-289 H ACR8 FOIA FOIA | FELTON, J. M. | 8012050534 8012050433 8012080006 8012080353 8012080345 | 50-458 F 50-266 F 50-443 F 50-263 F 50-327 F |
| ENGELKEN, R. H. ENGELMANN, R. ENGELKEN, R. H. ENGELKEN, R. H. | 8012170725 8012010063 8012170411 8012170414 8012170415 | 50-528 0 40-8348 50-206 0 50-312 0 50-344 0 | ETZLER, D. H. ETZLER, D. H. EVANG, V. R. EVANG, C. A. FABRIKANT, R. | 8012030055* 8012030045* 8012220037* 8012120562* 8012300250 | FOIA FOIA 50-317 0 50-112 0 50-445 M | FELTON, J. M. | 8012080103 8012100632 8012170155 8012040043 8012040371 | FOIA 50-331 F 50-84 F 50-245 F 50-327 F |
| ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. | 8012170416 8012170418 8012170757 8012070087 8012170836 | 50-275 Q 50-460 Q 50-528 Q 50-312 Q | FAHNER, T. C. FAHNER, T. C. FALCONER, D. P. FARLEY, E. R. FARMAKIDEB, J. B. | 8012300070 8012300084* 8012160041* 8012080217 8012300030* | 50-237 0 50-237 0 50-302 0 40-3453 50-445 M | FELTON, J. M. | 8012150012 | FOIA FOIA FOIA 50-219 H |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | BUBJECT CATEGORY | AUTHOR | ACCEBSION NUMBER | SUBJECT CATEGORY |
|--|---|--|---|--|--|---|--|---|
| FELTON, J. H. FELTON, J. K. | 8012110227 8012110520 8012110524 8012080213 8012110208 | 50-407 H FOIA 70-143 50-250 F FOIA | FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R. | 8012070177 8012160482 8012160461 8012220404 8012230188 | 50-217 P 50-217 8 50-217 V 50-217 R 50-217 P | FOPAKIAN, K. FORD, W. H. FORD, R. C. FORD, E. J. FORT, J. E. | 8012170120 8012020027 8012080664* 8012160041* 8012100434 | PR 40-8502 40-1341 50-302 Q 50-287 H |
| FELTON, J. M. | 8012110438 | FOIA | FINFROCK, I.R. | 8012230468 | 50-219 8 | FORTI, E. | 8012190241 | FOIA |
| | 8012110535 | FOIA | FINK, B. | 8012050388 | 50-247 U | FOSTER, J. E. | 8012310518* | 50-341 Q |
| | 8012110556 | 50-369 8 | FINLAY, R.L. | 8012300719* | 50-466 T | FOSTER, W. E. | 8012020702* | QA979 |
| | 8012180322 | 50-142 P | FINLEY, A.G. | 8012160192* | 50-315 Q | FOSTER, W. E. | 8012180599* | QA979 |
| | 8012180323* | 50-142 P | FINNAN, G.F. | 8012120241* | 50-409 P | FOSTER, L. E. | 8012190711* | 50-348 Q |
| FELTON, J. H. FELTON, J. H. FELTON, J. H. FELTON, J. H. FELTON, J. H. | 8012220183 8012070107 8012150001 8012150005 8012150006 | FOIA 50-348 F FOIA FOIA | FINNAN, G. F. FINSTON, R. A. FIORELLI, O. FIORELLI, O. FIORELLI, O. | 8012020318* 8012120109 8011250274 8012120287 8012110041 | 50-409 P PR 50-461 Q 50-463 Q 50-440 Q | FOWLER, E. E. FOX, D. F. FOX, D. F. FRALEY, R. F. FRALEY, R. F. | 8012030346* 8012170522* 8012080268* 8012080411 8011200233 | FOIA GA999 GA999 ACRS BECY |
| FELTON, J. M. | 8012160004 | FOIA | FIORELLI, O. | 8012070145* | 50-440 0 | FREDERICKB.K.H. | 8012100458* | 50-320 P |
| | 8012160015 | FOIA | FIORELLI, O. | 8012110004 | 50-461 G | FREE, B. | 8012170235 | 40-8783 |
| | 8012180273 | FOIA | FIORELLI, O. | 8012140535 | 50-456 G | FREED-THALL.P. | 8012120003 | PR |
| | 8012190086 | 50-269 F | FIORELLI, O. | 8012040482 | 50-341 G | FREEDMAN.P.F. | 8012300161 | 50-289 Q |
| | 8012160024 | FOIA | FIORELLI, O. | 8012030394 | 50-546 Q | FREEMAN.J.D. | 8012010631 | 40-299 |
| FELTON, J. M. | 8012180326 | FOIA | FIGRELLI.G. | 8012080027 | 50-454 Q | FRENGH, L. D. | 8012020475* | 50-29 6 |
| | 8012180335 | FOIA | FIGRELLI.G. | 8012080279 | 50-454 Q | FRENCH, L. D. | 8012160511* | 50-29 8 |
| | 8012230521 | 50-146 F | FIGRELLI.G. | 8012180590* | 50-461 Q | FRERICHB, J. | 8012120620 | PR |
| | 8012170234 | FOIA | FIGRELLI.G. | 8012190221 | 50-456 Q | FRIEDLANDER, J. | 8012240365 | Etate Frog |
| | 8012230512 | 50-124 F | FIGRELLI.G. | 8012190242 | 50-454 Q | FRIESEMA, H. P. | 8012040176* | 50-320 H |
| FELTON, J. M. | 8012230530 6012240118 6012240367 6012240429 6012190366 | 50-369 A 50-275 F 50-369 F 50-10 Q FOIA | FIGRELLI.O. FIDRELLI.O. FIDRELLI.O. FIDRELLI.O. FIDRELLI.O. | 8012170271 8012040276 8012240026 8012240052 8012040343 | 50-331 Q 50-483 Q 50-483 Q 50-373 Q 50-546 Q | frieben, B. B. Frieben, B. B. Friboli, A. Frobt, B. R. Frobt, B. R. | 8012100137 8012100531 8012030132* 8011250067 8012270243 | PR 50-148 F FOIA 50-255 Q 50-255 Q |
| FELTON, J. M. | 8012170383 | FOIA | FIORELLI, O. | 8012040648 | 50-463 Q | FROBT, 8. R | 8012300404 | 50-255 8 |
| | 8012170406 | FOIA | FIORELLI, G. | 8012240046 | 50-546 Q | FULLWOOD, R. R. | 8012080023 | NUREO |
| | 8012240117 | FOIA | FIORELLI, G. | 8012240169 | 50-440 Q | FULTON, J. F. | 8012030840 | REGOD |
| | 8012240126 | 70-143 | FIORELLI, G. | 8012040236 | 50-461 Q | FULTON, J. F. | 8012180344* | 50-244 P |
| | 8012240400 | 50-295 H | FIORELLI, G. | 8012110621 | 50-463 Q | FURBUSH, M. H. | 8012090008 | PR |
| FELTON, J. M. | 8012190053 | 50-317 F | FIDRELLI, O. | 8012150223 | 50-454 G | FURBUSH, M. H. | 8012180274 | PR |
| FELTON, J. M. | 8012190397 | F01A | FIDRELLI, O. | 8012290398 | 50-373 A | FURBUSH, M. H. | 8012300352 | 50-275 0 |
| FELTON, J. M. | 8012190415 | F01A | FIDRELLI, O. | 8012100679 | 50-329 A | FURR, B. J. | 8012040551 | 50-324 0 |
| FELTON, J. M. | 8012220169 | 70-143 | FIDRELLI, O. | 8012290394 | 50-295 G | FURR, B. J. | 8012230018 | 50-324 0 |
| FELTON, J. M. | 8012220433 | 50-313 F | FIBCHER, D. L. | 8012110390 | 50-289 H | FURR, B. J. | 8012310174 | 50-261 0 |
| FELTON, J. H. | 8012270464 | 50-275 F | FISHER, W. L. | 8012080704 | REGQD | FURR, B. J. | 8012310376 | 50-261 0 |
| | 8012170247 | F01A | FISHER, W. L. | 8012180408* | 50-2 0 | FURR, B. J. | 8012310404 | 50-261 0 |
| | 8012270440 | 50-320 F | FISHER, W. L. | 8012180435* | 70-925 | FURR, B. J. | 8012310470 | 50-324 0 |
| | 8012270447 | 50-320 F | FISHER, W. L. | 8012220056* | 50-266 0 | FURR, B. J. | 8012310474 | 50-324 0 |
| | 8012270456 | 50-289 F | FISHER, W. L. | 8012230193* | 50-973 0 | FURTH, F. W. | 8012080128 | PR |
| FELTON: J. M. | 8012270477 8012270470 8012270477 8012270504 8012240406 | 50-320 F 50-320 F 50-320 F 50-320 F FOIA | FIBHER, B. FIBHER, W. L. FIBHER, W. L. FITZOERALD, J. A. FITZOIBBONS, R. | 8012070024 8012220076* 8012180234* 8011200286 8012300324 | PR 40-3392 70-36 BECY 50-237 0 | Fubon. B. Gage, L. W. Gage, L. Gagliardo, J. E. Gagliardo, J. E. | 8012180171 8012080268* 8012230041* 8012120326* 8012080834* | PR GA999 50-352 |
| FELTON, J. H. | 8012310566 | FOIA | FITZGERALD, M. J. | 8012070471* | 50-217 6 | OAHM, J. W. | 8011250501* | 50-267 8 |
| FELTON, J. K. | 8012310584 | 50-278 H | FITZGIBBONB.R. | 8012110540 | 50-237 0 | OAHM, J. W. | 8012020563* | 50-247 8 |
| FELTON, J. K. | 8012310560 | FOIA | FITZGERALD.M. J. | 8012160471* | 50-217 8 | GAHM, J. W. | 8012020575* | 50-267 8 |
| FELTON, J. K. | 8012310574 | FOIA | FITZGERALD.J.A. | 801224004 | COMMISSION | OAHM, J. W. | G012050419* | 50-267 8 |
| FENWICK, A. J. | 8012170481* | 50-269 H | FITZGERALD.J.A. | 8012270062 | COMMISSION | OAHM, J. W. | 8012100337* | 50-267 R |
| FEROUSON: J. H. | 8012040366 | PR | FITZPATRICK, R. | 8012110591* | 50-387 8 | оанм, J. Н. | 8012100491* | 50-247 8 |
| FEROUSON: J. H. | 8012080789 | PR | FLACKE, R. F. | 8012050038 | State Prog | Оанм, J. Н. | 8012100509* | 50-247 8 |
| FEROUSON: J. H. | 8012230439 | 50-337 P | FLANDERB, W. L. | 8012020597* | 50-309 R | Оанм, J. Н. | 8012100521* | 50-247 8 |
| FEROUSON: J. H. | 8012300588 | 50-404 A | FLANDERB, W. | 8012300529* | 50-309 R | Оанм, J. Н. | 8012100537* | 50-247 8 |
| FEROUSON: J. H. | 8012290154 | 50-280 P | FLEENOR, C. K. | 8012300149 | CONTRACT | Оанм, J. Н. | 8012290442* | 50-247 8 |
| FERGUSON, J. H. FERGUSON, J. H. FERNANDEZ-PÅL FERNOS: 0. | 8012270264 8012270272 8012270316 8012010432 8012270628 | 50-338 P 50-338 P 50-339 P PR 50-374 0 | FLEENOR, C. M. FLEIBCHER, R. L. FLEIBCHAKER, D. FLEIBCHAKER, D. FLEIBCHAKER, D. | 8012300227 8012120382* 8011250108* 8012270120 8012080513 | CONTRACT 40-6622 50-275 Q 50-275 Q 50-275 Q | Oahm, J. W. Oalang, M. Oallaher, B. Oallaoher, P. J. Oallen, K. P. | 8012300567* 8012170184 8012220246* 8012120337 8012120646 | 50-267 6 PR FOIA FOIA 50-409 0 |
| FERRER, R. A. FEULNER, R. C. FIDELMAN, S. J. FIELDER, J. FIELDER, J. | 8012110067 8012220037 8012120018 8012010355 8012020473 | PR PR PR 50-302 J 50-327 J | FLEIBCHAKER, D. FLEIBCHAKER, D. FLEIBCHAKER, D. FLEIBCHAKER, D. FLEIBCHAKER, D. | 8012270120 8012170440 8012170442* 8012300364 8012300364 | 50-275 | OALLEN, K. P. GALLO, J. GALLO, J. GALLO, J. GALLO, J. | 8012120646 8012080125* 8012090132 8012300360 8012300360 | 50-409 0 50-387 0 PR 50-155 0 50-155 0 |
| FIELDER, J. FIELDER, J. FIELDER, J. FILIPY, R. E. FINFROCK, I. R. | 8012020478 8012100511 8012160307 8012230315 8012160431* | 50-335 J 50-327 J 50-327 J NUREO 50-219 H | FLE ISCHAKER, D. FLETCHER, J. H. FLETCHER, C. D. FLICK, R. FLICK, R. | 8012310283 8012080325 8012040583 8012310510* 8012110344 | 50~275 | GARNER, D. J. GARNER, R. W. GARRITY, J. H. GARRITY, J. H. GARRITY, J. H. | 8012180318* 8012170044 8012020288 8012020587 8012300526 | 50-346 P RE8 50-307 P 50-307 R 50-307 R |
| FINFROCK, I.R. | 9012310418 | 50-217 Q | Florreich. G. | 8012120005 | 50-289 H | GARRIBON, J. M. | 8012230360* | 50-553 R |
| FINFROCK, I.R. | 8012010319 | 50-217 B | Fluke, D. J. | 8012120005 | PR | GARTLER, B. M. | 8012120076 | PR |
| FINFROCK, I.R. | 8012040445 | 50-217 B | Fluke, D. J. | 8012120085 | PR | GARY, R. J. | 80121300798 | 50-445 Q |
| FINFROCK, I.R. | 8012010318 | 50-217 B | Flynn, J. D. | 8012080795 | PR | GARY, R. J. | 8012100550* | 50-445 Q |
| FINFROCK, I.R. | 8012020552 | 50-217 B | Flynn, M. J. | 8012120074 | Contract | GARY, R. J. | 8012160531 | 50-445 Q |
| FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R. | 8012090204 8012080420 8012090464 8012090363 8012160546 | 50-219 F 50-219 8 50-219 8 50-219 P 50-219 8 | FLYNN M. J. FLYNN, J. D. FOGELBON, A. FOLEY, T. FOLEY, T. | 8012230540 8012170502 8012110706 8012090084* 8012240277* | CONTRACT 50-358 G PR 50-29 G 50-29 G | QARY, R. J. Gary, R. J. Gary, R. J. Gary, R. J. Gary, R. J. | 8012180245 8012190487 8012290169 8012300338 8012300536 | 50-445 8 50-445 K 50-445 B 50-445 C |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | BUBJECT CATEOORY |
|--|---|--|---|---|--|---|---|--|
| GARY, R. J. GABPAROTTI, J. GATCHEL, R. GATES, W. GEARHART, J. | 8012310088 8012170781 8012230335 8012020616* 8012080228 | 50-445 F RE8 50-320 P 50-285 8 PR | GOLDSTEIN, D. GOLDSMITH, R. GOLLER, K. R. GOLLER, K. R. GOGDHOPE, A. C. | 8012110248 8012170519 8012110675* 8012110276 8012190460 | PR NUREO 50-395 A 50-10 P 70-1308 | OREEN, H. J. OREEN, H. J. OREEN, H. J. OREEN, H. J. GREEN, H. J. | 8012230362 8012230386 8012300417 8012300514 8012300541 | 50-327 8 50-327 8 50-327 8 50-260 8 50-327 6 |
| GEARS, G. E. GEARS, G. E. GEARS, G. E. GEE, G. H. GEHR, A. C. | 8012020664* 8012270225* 8012300268* 8012230075 8012270430* | 50-387 Q 50-387 Q 50-466 G Nureg 50-828 Q | Goddling, B. Goddling, B. Goddman, L. B. Goddman, L. B. Goddman, L. B. | 8012100668# 8012030781# 8012100535# 8012020436# 8012100540# | 50-320 U 50-287 H 50-409 S 50-409 S | OREEN: H. J. OREEN: H. J. OREEN: H. J. OREEN: H. J. OREEN: H. J. | 8012300577 8012300634 8012300428 8012300438 8012300518 | 50-259 8 50-259 8 50-259 8 50-327 8 50-327 9 |
| GEHR, A. C. GEHR, A. C. GEIS, J. W. GELSTON, A. H. GELBTON, A. H. | 8012300487 8012300487 8012300636 8012300424 8012300444* | 50-528 G 50-528 G 50-347 A 50-327 8 50-327 8 | GOODHAN, L. B. GOODHAN, L. B. GOODHAN, L. B. GOODHAN, L. B. GOODHAN, L. B. | 8012100547* 8012070348* 8012160286* 8012160447* 8012160463* | 50-407 8 50-409 8 50-409 8 50-409 6 50-409 8 | GREEN, H. J. GREEN, H. J. GREEN, H. J. GREEVER, J. GREEVER, J. T. | 8012300531 8012300555 8012300615 8012140576* 8012220335* | 50-276 8 50-327 8 50-259 9 50-182 0 50-409 0 |
| QELSTON, A. H. QEORGE, E. A. QEORGIGU, D. S. QEORGIGU, B. S. QEORGIGU, B. S. | 8012300535* 8012020467 8012290002 8012290161 8012290462 | 50-327 8 PR 50-275 0 50-275 0 50-275 0 | OGODWIN, R. N. OGODWIN, W. L. GOODWIN, W. L. ODORIS, P. R. ODRDON, S. | 8012030552* 8012070167* 8012070165* 8012180173 8012030125* | FOIA 70-1151 70-1151 PR FOIA | OREGER, R. L. OREGO, R. J. OREGORY, W. D. ORENDON, A. ORENDON, A. | 8012080175# 8012270043 8012010530 8012030344# 8012030012# | 50-272 Q 70-820 PR 27-10 FOIA |
| GEOROIGU, B. S. OERLT, D. H. OERTH, D. E. OERUSKY, T. M. OETTLER, F. W. | 8012300117 8012070217* 8012110204 8012080488 8012180075 | 50-275 Q 50~344 P PR REGOD | OORDON, B. OORDON, R. F. OORE, A. OORMLEY, J. F. OOTCHY, R. L | 8012030105# 8012100204 8012020651 8012170635 8012050406# | F01A PR 50-201 H 50-287 H 50-466 Q | ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012110747* 8012080186* 8012090540 8012010109 8012010389 | FOIA 50-272 Q 50-272 Q 50-201 Q 50-213 Q |
| OIAMBUSED, A. OIAMBUSED, A. OIBBONS, T. D. OIBBONS, T. D. | 8012100458* 8012110670* 8012110723* 8012170076* 8012110629* | 50-320 P 50-395 A FDIA 50-413 Q 50-250 Q | GDTCHY, R. L. GBULD, W. GRABB, H. H. GRADIN, L. P. GRADY, J. | 8012300271* 8012110394 8012270357* 8012080781 8012110778 | 50-466 0 50-287 H 50-320 H PR PR | GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. | 8012020316 8012020320 8012020321 8012020325 6012020329 | 50-273 |
| 01888, D. C. 01888, D. C. 01880N, A. F. 01880N, A. F. 01860N, A. F. | 8012180222* 8012080152 8012180240 8012170440* 8012070210* | 50~338 | GRAESSER, K. L. GRAESSER, K. L. GRAESSER, K. L. GRAESSER, K. L. GRAESSAR, K. L. | 8012090433 8012090461 8012150093 8012150211 8012110358 | 50-304 S 50-295 S 50-304 B 50-295 B 50-295 R | ORIER, B. H. | 8012050019 8012160046 8012160049 8012080116 6012170367 | 50-217 Q 50-410 Q 50-284 Q 50-272 Q 50-3 Q |
| GIBSON, H. S. GIBSON, Q. T. GIBSON, A. F. GIBSON, A. F. GIDO, R. Q. | 8012120347* 8012100566* 8012180215* 8012180215* 8012190202* | 70-27 50-317 S 50-369 0 50-364 0 | Graebber, K. L. Graebber, K. L. Oraebber, K. L. Graham, J. S. Grand, R. A. | 8012170607 8012230316 8012230322 8012030378* 8012030050* | 50-304 8 50-304 8 50-275 8 FOIA FOIA | ORIER, B. H. | 8012170370 8012170375 8012170374 8012170378 8012170381 | 50-213 G 50-317 Q 50-309 Q 50-316 G 50-485 G |
| GILBERT, L. D. GILBERTS, D. E. GILBERTS, D. E. GILBERTS, D. E. GILBERTS, D. E. | 8012020762* 8012070006 8012180010 8012220177 | NUREO 50-482 Q 50-282 Q 50-263 Q 50-282 Q | GRANT, N. B. GRASBO, E. GRAVEB, R. H. GRAVEB, R. H. GRAY, J. R. | 8012040263* 8012170285 8012070361 8012170524 8012150231 | 50-331 Q PR 50-213 B 50-213 R 50-344 Q | ORIER.B.H. ORIER.B.H. GRIER.B.H. GRIER.B.H. ORIER.B.H. | 8012170384 8012170384 8012170387 8012170392 8012170394 | 50-443 Q 50-412 Q 50-363 Q 50-29 Q 50-244 Q |
| OILBERTS, D. E. OILCHREST, G. V. OILDNER, M. L. OILINSKY, V. | 8012220182 8012220734 8012270270 8012310459* 8012110460* | 50-263 Q 50-282 Q 50-170 H 50-344 Q FOIA | GRAY, J. R. GRAY, J. R. GRAY, J. R. GRAY, J. R. GRAY, J. R. | 8012170748 8012290416 8012290385 8012300110 8012300457* | 50-289 | ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H. | 8012170397 8012170398 8012170402 8012170404 8012170405 | 50-272 Q 50-284 Q 50-336 Q 50-289 Q 50-334 Q |
| OILINGKY, V. OILLEBPIE, E., P. OILLEN, D. M. OILLETT, W. T. | 8012110465* 8012070185* 8012020003 8012020007 8012190505* | FOIA 70~1151 40~259 40~254 50~316 R | ORAY, J. R. GRAY, J. R. OREELEY, O. H. OREENMAN, E. O. OREENMAN, E. O. | 8012300350 8012300356 8012100075 8012160113* 801230000* | 50-463 Q 50-524 Q PR 50-277 Q 50-277 Q | GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. | 8012090486 8012090536 8012100057 8012190465 8012300153 | 50-334 P 50-293 8 50-334 Q 50-334 Q 50-320 Q |
| GILLIB, J. P. GILLILAND, D. L. GILMAN, D. GILMAN, D. N. GILMARTIN, D. H. GILMAN, D. W. | 8012150113* 8012050149 8012110352* 8012040420 8012020706 | 50-327 P 50-70 P 50-358 0 50-361 A 50-322 A | GREENMAN, E. O. GREENMAN, E. O. GREEN, H. J. GREEN, H. J. GREEN, H. J. | 8012220031* 8012170712* 8012020623 8012020610 8012030667 | 50-317 Q 50-333 Q 50-327 B 50-327 B 50-327 S | ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012120024 8012120048 8012120060 8012120072 8012120077 | 50-286 Q 50-333 Q 50-272 Q 50-273 Q 50-213 Q |
| OINSBERO, T. OIRARD, E. H. OIRARD, E. H. OIRARD, E. H. | 8012120413* 8012190161 8012180112* 8012170473* 8012310279* | 50-206 P 50-537 A 50-260 Q 50-438 Q 50-413 Q | OREEN, H. J. GREEN, H. J. GREEN, H. J. GREENHALD, R. GREEN, H. J. | 8012020418 8012020514 8012080423 8012150192 8012020444 | 50-240 8 50-294 8 50-327 8 50-271 H 50-296 8 | GRIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012120080 8012120084 8012120089 8012120093 8012120097 | 50-3 Q 50-334 Q 50-219 Q 50-277 Q 50-244 Q |
| OLAGOLA: A. F. GLAGOLA: A. F. OLAGOLA: A. F. OLAGS: D. N. GLENN: J. | 8012110574 8012310258 8012110349 8012050133* 8012270378 | CONTRACT 50-445 M GONTRACT 71-35 40-672 | GREEN, H. J. GREEN, H. J. GREEN, H. J. GREEN, H. J. GREEN, H. J. | 8012020499 8012020629 8012040392 8012090355 8012100523 | 50-294 8 50-327 8 50-327 8 50-327 8 50-240 8 | ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012120100 8012120105 8012120113 8012120117 8012120121 | 50-307 G 50-317 G 50-245 O 50-220 G 50-443 G |
| GLOVER, H. GODDARD, R. J. GODDARD, R. J. GODDARD, R. J. GODDARD, R. J. | 8012100178 8012230227 8012290406 8012230019 8012270213 | PR 50-461 D 50-237 T 50-237 Q 50-237 Q | OREEN, H. J. OREEN, H. J. OREEN, H. J. OREEN, H. J. OREEN, H. J. | 8012270163 8012120466 8012120502 8012120507 8012150165 | 50-445 M 50-259 8 50-259 8 50-276 8 50-327 8 | GRIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012120136 6012120141 8012120145 8012120150 8012120157 | 50-410 q 50-287 0 50-271 0 50-27 0 50-412 0 |
| ODEREC, L. ODLD, C. W. ODLDBERG, S. C. ODLDBERG, S. C. ODLDBERG, S. J. | 8012080361 8012030607* 8012020695 8012030425 8012190543 | PR FOIA 50-367 0 50-367 0 | OREEN, H. J. OREEN, H. J. OREEN, H. J. OREEN, H. J. OREEN, H. J. | 8012120510 8012140447 8012140542 8012170545 8012170558 | 50-259 8 50-327 8 50-274 8 50-274 8 50-260 8 | GRIER, B. H. ORIER, B. H. | 8012120161 8012120167 8012120173 8012120178 8012120184 | 50-363 Q 50-322 Q 50-516 Q 50-387 Q 50-352 Q |
| OOLDBERO, B. C. OOLDBERO, B. C. OOLDBERO, B. C. OOLDHANN, K. OOLDMAN, M. | 8012270651 8012300011 8012300217 8011210177 8012230154* | 50-250 P 50-367 0 50-395 G 71~9018 CONTRACT | OREEN, H. J. OREEN, H. J. OREEN, H. J. OREEN, H. J. OREEN, H. J. | 8012170642 8012220455 8012160553 8012170602 8012170603 | 50-260 8 50-260 8 50-276 8 50-327 8 50-276 8 | ORIER, B. H. | 8012120170 8012120175 8012030759 8012030764 8012030767 | 50-354 Q 50-485 Q 50-271 Q 50-289 Q 50-217 Q |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | BUBJECT CATEGORY |
|--|--|--|---|--|--|--|--|--|
| GRIER, B. H. | 8012030768 | 50-317 Q | ORIER, B. H. | 8012050487 | 50-277 F | GRIER, B. H. | 8012050593 | 50-354 Q |
| ORIER, B. H. | 8012030770 | 50-293 Q | | 8012050526 | 50-271 F | GRIER, B. H. | 8012050595 | 50-272 Q |
| ORIER, B. H. | 8012030771 | 50-213 Q | | 8012050538 | 50-293 F | GRIER, B. H. | 8012050598 | 50-443 Q |
| ORIER, B. H. | 8012030772 | 50-3 Q | | 8012050550 | 50-393 F | ORIER, B. H. | 8012050579 | 50-244 Q |
| ORIER, B. H. | 8012030776 | 50-334 Q | | 8012080716 | 50-245 F | ORIER, B. H. | 8012050601 | 50-485 Q |
| ORIER, B. H. | 8012030777 | 50-443 Q | ORIER. B. H. | 8012080726 | 50-286 F | ORIER, B. H. | 8012050408 | 50-271 Q |
| ORIER, B. H. | 8012030780 | 50-410 Q | GRIER. B. H. | 8012080730 | 50-309 F | ORIER, B. H. | 8012050410 | 50-29 Q |
| ORIER, B. H. | 8012030782 | 50-516 Q | ORIER. D. H. | 8012080734 | 50-272 F | ORIER, B. H. | 8012220338 | 50-289 Q |
| ORIER, B. H. | 8012030785 | 50-220 Q | GRIER. B. H. | 8012080740 | 50-213 F | ORIER, B. H. | 8012270401 | 50-220 Q |
| ORIER, B. H. | 8012030787 | 50-245 Q | GRIER, B. H. | 8012290006 | 50-334 F | GRIER, B. H. | 8012180351 | 50-247 Q |
| ORIER, B. H. | 8012030790 | 50-277 G | GRIER, B. H. | 8012220616 | 50-245 0 | ORIER, B. H. | 8012180357# | 50-247 Q |
| ORIER, B. H. | 8012030791 | 50-286 G | GRIER, B. H. | 8012220618 | 50-3 0 | ORIFFIN, E. E. | 8012100240 | PR |
| ORIER, B. H. | 8012030794 | 50-333 G | GRIER, B. H. | 8012220621 | 50-317 0 | ORIFO, A. P. | 8012120312 | PR |
| ORIER, B. H. | 8012030796 | 50-272 G | GRIER, B. H. | 8012220626 | 50-277 0 | ORIMES, B. K. | 8012170382# | 50-133 F |
| ORIER, B. H. | 8012030799 | 50-244 G | GRIER, B. H. | 8012220627 | 50-299 0 | ORIMES, B. K. | 8012300272* | 50-344 F |
| GRIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. GRIER, B. H. | 8012030804 8012030805 8012030807 8012030809 8012030813 | 50-354 Q 50-352 Q 50-387 Q 50-485 Q 50-309 Q | ORIER, B. H. | 8012220633 8012220637 8012220645 8012220647 8012220651 | 50-213 G 50-516 G 50-220 G 50-334 G 50-289 G | ORIMES, B. K. ORIMES, B. K. ORIMES, C. I. ORIMES, C. I. OROCE, R. H. | 8012020671 8012240442 8012160377 8012160227 7812010146 | 8tate Prog ORG 50-461 A 50-461 A 50-27 Q |
| GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. | 8012030815 8012030821 8012030825 8012080158 8012080837 | 50-322 | ORIER, B. H. | 8012220655 8012220660 8012220661 8012220665 8012220667 | 50-387 G 50-352 G 50-354 G 50-217 G 50-309 G | ORDCE, R. H. ORDCE, R. H. GROCE, R. H. ORDCE, R. H. ORDCE, R. H. | 7811280221 7906130106 7907090076 7908070673 7908270511 | 50-29 P 50-29 Q 50-29 Q 50-29 Q |
| ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012080310 8012080375 8012080382 8012080419 8012080426 | 50-286 G 50-443 G 50-412 G 50-271 G 50-272 G | GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. | 8012220671 8012220675 8012220674 8012220679 | 50-244 0 50-333 0 50-286 0 50-272 0 50-27 0 | GROCE, R. H. GROCE, R. H. GROCE, R. H. GROCE, R. H. GROCE, R. H. | 7910030679 7910040432 7909210287 7910180149 7910310256 | 50-27 Q 50-29 Q 50-29 P 50-29 Q |
| GRIER, B. H. | 8012080433 | 50-333 Q | ORIER, B. H. | 8012220684 | 50-412 | ORDCE, R. H. | 7911230340 | 50-27 Q |
| GRIER, B. H. | 8012080438 | 50-387 Q | ORIER, B. H. | 8012220686 | | ORDCE, R. H. | 7912140252 | 50-27 Q |
| GRIER, B. H. | 8012080441 | 50-316 Q | ORIER, B. H. | 8012220689 | | ORDCE, R. H. | 8012070170 | 50-271 P |
| GRIER, B. H. | 8012080444 | 50-322 Q | ORIER, B. H. | 8012220691 | | ORDCE, R. H. | 8012150082 | 50-309 F |
| GRIER, B. H. | 8012080449 | 50-220 Q | ORIER, B. H. | 8012220675 | | OROOME, K. | 8012180607* | QA999 |
| ORIER, B. H. | 8012080454 | 50-277 Q | ORIER, B. H. GRIER, B. H. | 8012220697 | 50-443 0 | Groseman, K. | 8012110214 | FOIA |
| ORIER, B. H. | 8012080474 | 50-245 Q | | 8012220702 | 50-465 0 | Orobe, H. | 8012110154 | PR |
| ORIER, B. H. | 8012080477 | 50-293 Q | | 8012040454 | 50-271 0 | Orobeman, K. | 8012110542 | FOIA |
| ORIER, B. H. | 8012080481 | 50-317 Q | | 8012040488 | 50-277 0 | Orobeman, K. | 8012180328 | FOIA |
| ORIER, B. H. | 8012080483 | 50-29 Q | | 8012040495 | 50-245 0 | Orobeman, H. | 8012290145 | 50-70 0 |
| ORIER, B. H. | 8012080486 | 50~244 Q | GRIER, B. H. | 8012040497 | 50-272 0 | OROSSMAN, H. OROTENHUIS, M. OROWNEY, E. J. ORUBB, R. L. QUILBERT, D. E. | 8012270089 | 50-367 0 |
| ORIER, B. H. | 8012080470 | 50~363 Q | GRIER, B. H. | 8012040499 | 50-244 0 | | 8012190067 | 50-250 0 |
| ORIER, B. H. | 8012080473 | 50~352 Q | ORIER, B. H. | 8012040300 | 50-213 0 | | 8012170297 | PR |
| ORIER, B. H. | 8012080474 | 50~410 Q | ORIER, B. H. | 8012040502 | 50-286 0 | | 8012230380 | NUREG |
| ORIER, B. H. | 8012080336 | 50~309 Q | ORIER, B. H. | 8012040504 | 50-293 0 | | 8012170489* | GA999 |
| ORIER, B. H. | 8012080539 | 50-334 Q | ORIER, B. H. | 8012040508 | 50-287 0 | OUILBERT, D. E. | 8012190470* | GA999 |
| ORIER, B. H. | 8012080542 | 50-219 G | | 8012040509 | 50-27 0 | GUILBERT, D. E. | 8012290492* | GA999 |
| ORIER, B. H. | 8012080547 | 50-3 Q | | 8012040514 | 50-333 0 | GUINN, B. A. | 8012230316 | NUREO |
| ORIER, B. H. | 8012080549 | 50-289 Q | | 8012040519 | 50-220 0 | GULDEMOND, W. G. | 8012310300* | 50-266 G |
| ORIER, B. H. | 8012080568 | 50-485 Q | | 8012040522 | 50-317 0 | GUMBLE, F. W. | 8012010415* | 50-286 B |
| ORIER, B. H. | 8012020488 | 50-317 F | ORIER: B. H. | 8012040529 | 50-219 0 | QUMBLE, F. W. | 8012130135# | 50-285 B |
| ORIER, B. H. | 8012020735 | 50-201 F | ORIER: B. H. | 8012040531 | 50-334 0 | QUMBLE, F. W. | 8012270427* | 50-286 B |
| ORIER, B. H. | 8012040007 | 50-443 G | ORIER: B. H. | 8012040532 | 50-3 0 | QUPPY, J. Q. | 8012170131 | RES |
| ORIER, B. H. | 8012040012 | 50-363 G | ORIER: B. H. | 8012040536 | 50-309 0 | QUBTAVE, R. P. | 8012310620 | CONTRACT |
| ORIER, B. H. | 8012040028 | 50-410 G | ORIER: B. H. | 8012040595 | 50-322 0 | QUBTAVE, R. P. | 8012310575 | CONTRACT |
| ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012040031 8012040033 8012040037 8012040040 8012040042 | 50-387 Q 50-352 Q 50-317 Q 50-309 Q 50-412 Q | ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012040599 8012040602 8012040607 8012040612 8012040614 | 50-423 | QUTH, P. H. QUTBON, R. C. QUTTMANN, J. QUTTMANN, J. QUTTMANN, J. | 8012080299 8012020454 8012240484 8012240509 8012310247 | PR PR TOPREP TOPREP TOPREP |
| ORTER, B. H. ORTER, B. H. ORTER, B. H. ORTER, B. H. ORTER, B. H. | 8012040045 8012040047 8012040050 8012040053 8012040060 | 50-29 | ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012040610 8012040620 8012040625 8012040628 8012040629 | 50-410 | OUTTMANN, J. OUY, J. D. OUZY, D. J. OUZY, D. J. OWYNN, T. P. | 8012310252 8012300675# 8012010156# 8012010163# 8012110110# | TOPREP 50-466 T 71-9073 71-9073 50-350 Q |
| ORIER, B. H. | 8012040062 | 50-333 | ORIER, B. H. | 8012050528 | 50-273 0 | Haabb, W. P. | 8012010463 | TOPREP |
| ORIER, B. H. | 8012040066 | | ORIER, B. H. | 8012050543 | 50-317 0 | Haabb, H. P. | 8012070021 | TOPREP |
| ORIER, B. H. | 8012040067 | | ORIER, B. H. | 8012050546 | 50-3 0 | Hackney, R. | 8012040407* | 50-267 P |
| ORIER, B. H. | 8012040073 | | ORIER, B. H. | 8012050547 | 50-213 0 | Hadlock, Q. F. | 8012030538* | FOIA |
| ORIER, B. H. | 8012040077 | | ORIER, B. H. | 8012050551 | 50-412 0 | Hafer, C. A. | 8012090308* | 50-397 F |
| ORIER, B. H. | 8012040078 | 50-271 | ORIER, D. H. | 8012030554 | 50-334 0 | HAQA: P. B. | 8012080142 | PR |
| ORIER, B. H. | 8012040082 | | ORIER, B. H. | 8012030557 | 50-363 0 | HAQA: P. B. | 8012090042 | PR |
| ORIER, J. H. | 8012040086 | | ORIER, B. H. | 8012030561 | 50-219 0 | HAQEY: H. | 8012080813 | CONTRACT |
| ORIER, B. H. | 8012040090 | | ORIER, B. H. | 8012030563 | 50-322 0 | HAQEY: H. | 8012080807 | CONTRACT |
| ORIER, B. H. | 8012040092 | | ORIER, B. H. | 8012030564 | 50-516 0 | HAGEY: H. | 8012040133 | CONTRACT |
| ORIER. B. H. | 8012040075 | 50-289 Q | ORIER, B. H. | 8012050569 | 50-287 0 | HAGEY, H. | 8012080497 | CONTRACT |
| ORIER. B. H. | 8012040078 | 50-220 Q | ORIER, B. H. | 8012050572 | 50-309 0 | HAGEY, H. | 8012080585 | CONTRACT |
| ORIER. B. H. | 8012040102 | 50-219 Q | ORIER, B. H. | 8012050573 | 50-245 0 | HAGEY, H. | 8012100412 | CONTRACT |
| ORIER. B. H. | 8012040104 | 50-234 Q | ORIER, B. H. | 8012050575 | 50-410 0 | HAGEY, H. | 8012240040 | CONTRACT |
| ORIER. B. H. | 8012040104 | 50-244 F | ORIER, B. H. | 8012050578 | 50-220 0 | HAGUE, R. L. | 8012310500* | 50-266 G |
| ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. | 8012040177 8012040632 8012040651 8012050456 8012050477 | 50-27 F 50-3 F 50-220 F 50-219 F 50-289 F | GRIER, B. H. ORIER, B. H. ORIER, B. H. GRIER, B. H. | 8012050580 8012050585 8012050585 8012050588 8012050589 | 50-333 0 50-296 0 50-352 0 50-277 0 50-387 0 | HAHN, W. F. HAILE; L. HAIRBTON; C. HAIRBTON; C. HAIRBTON; C. | 8012230319 8012110523 8012110588 8012110574 8012040159 | NUREG 50-289 H CONTRACT CONTRACT 27-39 |
| → . | | | W. C. J. | | | | | |

| AUTHOR | ACCEBSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION | SUB JECT CATEGORY | AUTHOR | ACCEBBION NUMBER | EUB JECT CATEOUR |
|---|---|---|--|---|--|--|---|--|
| HAIRSTON, C. A. HAIRSTON, C. HAIRSTON, H. Q. HAIRSTON, H. Q. HAIRSTON, W. Q. HAIRSTON, W. Q. | 8012310258 8012110347 8012010347* 8012020519* 8012020558* | 50-445 M CONTRACT 50-348 B 50-364 S 50-348 B | HANSEN, L. E. HANBEN. L. E. HANSEN, L. E. HANSEN, L. E. HANBEN, L. E. | 8012170287* 8012170325 8012170280 8012170331 8012170270 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | HEIBHMAN, R. F. HEIBHMAN, R. F. HEIBHMAN, R. F. HEIBHMAN, R. F. HEIBHMAN, R. F. | 8012110636 8012110645* 8012100589 8012310426 8012100430 | 50-341 50-282 50-10 50-255 50-155 |
| HAIRBTON, W. O. HAIRBTON, W. O. HAIRBTON, W. C. HAIRBTON, W. O. HAIRBTON, W. O. | 8012020346# 8012020574# 8012020566# 8012020575# 8012020601# | 50-348 8 50-348 8 50-348 8 50-348 8 50-348 8 | HANSEN, L. E. HANSEN, L. E. HANSLER, O. M. KANSON, P. KARBISON, U. | 8012230199 8012230204* 8012220395 8012080281 8012130252 | XPORTLIC XPORTLIC 50-352 D PR 50-329 B | HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F. | 8012110641 8012110673 8012150245 8012180151 8012020309 | 50-262 50-331 50-331 50-254 50-10 |
| HAIRSTON, W. O. HAIRSTON, W. G. HAIRSTON, W. G. HAIRSTON, W. O. HAIRSTON, W. O. HAIRSTON, W. Q. | 8012160400* 8012140406* 8012100526* 8012100562* 8012300539* | 50-364 R 50-348 R 50-348 8 50-364 8 50-368 8 | HARDCABTLE: J. E. HARDIN, A. K. HARLAN, R. L. HARMON, D. KARRAN, Q. | 8012120335 8012180037* 8012010031 8012310066 8012230343* | PR 50-261 | HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F. | 8012310478 8012020587 8012310453 8012340259 8012310498 | 50-344 50-344 50-344 50-305 50-264 |
| HAIRSTON, W. G. HAIRSTON, W. G. HAIST, D. P. HALE, C. J. HALE, C. J. | 8012300530* 8012300547* 8012040310* 8012170522* 8012080268* | 50-348 8 50-344 B 50-397 Q GATTY GATTY | HARRIB, R. E. HARRIB, R. E. HARRIB, R. E. HARRIB, R. E. HARRIB, A. W. | 8012030542* 8012030502* 8012030487* 8012030483* 8012030074* | FOIA FOIA FOIA FOIA 27-10 | Heishman, R. F. Heishman, R. F. Heishman, R. F. Heishman, R. F. Heishman, R. F. | 8012310506 8012310442 8012110763 8012120415 8012180228 | 50-341 50-331 50-331 50-254 50-409 |
| HALE, C. J. HALE, C. J. HALE, C. J. HALE, C. J. | 8012020733* 8012230183* 8012180629* 8012190454* 8012040023* | QA999 QA999 QA999 QA999 QA999 | Harris, A. H. Harris, A. H. Harris, A. W. Harris, A. M. Harrison, O. | 8012030118* 8012030127* 8012030091* 8012030097* 8012190374* | 27-10 27-10 27-10 27-10 FOJA | Heighman, R. F. Heighman, R. F. Heiging-Goodman Helfrecht, D. J. Helgebon, O. L. | 8012310629 8012190695 8012040349# 8012300180 8012030077# | 50-10 50-373 PR 50-287 27-39 |
| HALE, C. J. HALE, C. J. HALL, O. R. HALL, I. J. HALL, W. J. | 8012190080* 8012220098* 8012300030* 8012220719 8012080767 | QA999 QA999 50-445 H NUREO 70-754 | HARRIS, J. R. HARRIS, J. R. HARRIS, J. R. HARRISON, J. J. HARRISON, J. J. | 8012120377* 8012090524* 8012110623* 8012030409* 8012240072* | 50-566 Q 50-424 Q 50-413 Q 50-546 Q 50-546 Q | HELDESON, O. L. HELLER, A. S. HELLER, J. K. HELTON, A. H. HELWICK, C. | 8012030002* 8012160413* 8012310433* 8012270370* 8012300105 | 27-39 TOPREP 50-255 50-320 50-142 |
| HALL: H. J. HALL: H. J. HALL: R. E. HALL: R. E. HALL: R. E. | 8012080774* 8012080779* 8012040039* 8012020749* 8012020762* | 70-754 70-754 50-49B G 50-445 G 50-482 G | Harrigan, K. C. Harrison, P. Harrison, F. L. Harrison, P. Harbtead, O. A. | 8012110852 8012100481* 8012120308 8012100475* 8012040325* | PR · 50-220 8 50-226 P 50-220 8 50-315 P | HENDERBHOTT, L. HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M. HENDRICKB, D. U. | 8012010419 8012270065# 8012240075# 8012240074# 8012240287 | PR COMMISSIC COMMISSIC COMMISSIC WASTE MOT |
| HALL: R. E. HALL: R. E. HALL: V. HALL: E. E. | 8012020383* 8012170416* 8012170623* 8012170717* 8012230004 | 40-2259 50-498 Q 50-498 Q 50-438 Q 50-395 M | HART, H. C. HART, Q. HART, J. HARTFIELD, R. A. HARTMAN, J. D. | 8012160471* 8010300544* 8012190540 8012050073* 8012120115 | 70-487 50-320 U 50-382 8 8ECY PR | HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M. HENDRIX, E. J. HENDRIE, J. M. | 8012110318 8012070264 8012230046* 8012270035 8012270413 | COMMISSIO COMMISSIO 50-389 50-155 50-327 |
| HALL, E, E, HALL, B, HALLIDAY HALLIDAN, T. J. HALLIDAN, T. J. | 8012230004 8012180383* 8012300354* 8012180160 8012150200 | 50-395 M 50-391 Q 50-361 K 50-387 Q 50-387 Q | HARTHAN, C. J. HARTNETT, H. HARVEY, R. C. HATCHER, R. D. HATHHAY, C. H. | 8012170452 8012300264 8012240262* 8012220634 8012040524 | 50-155 R 50-287 0 50-27 P NUREO 70-1062 | HENGOELER, J. T. HENRY, H. L. HENRY, J. J. HENRY, A. F. HENSLEY, K. D. | 8012270191# 8012240149 8012160238 8012220249# 8012230432 | 50-287 XPORTLIC FR CONTRACT 70-143 |
| HALMAN, E. L. HAMILL, K. J. HAMILL, K. J. HAMILTON, L. D. HAMILTON, L. | 8012110053* 8012010025 8012160764 8012270075* 8012270160* | CONTRACT 40-8743 40-8743 50-466 C | HAUGHNEY, C. J. HAUGHNEY, C. J. HAUGHNEY, C. J. HAUBHAN, A. L. HAVERKAMP, D. | 8012080790 8012300346 8012220722 8012270147 8012170110 | 70-1173 50-201 P 50-201 P PR 50-267 8 | HERALD, W. HERBIO, F. K. HERBET, M. HERDT, A. R. HERDT, A. R. | 8012080007# 8012010444 8012080662 8012020404# 8012180150# | 50-443 PR PR 50-364 50-413 |
| HAMILTON, L. D. HAMLIN, D. R. HAMLIN, D. R. HAMLIN, D. R. HAMLIN, D. R. | 8012270167* 8012010043 8012010046 8012040383 8012040386 | 50-466 T. RES RES RES RES | HANKINS, E. F. HAYES, D. H. HAYES, D. H. HAYES, D. N. HAYGOOD, C. | 8012110762 8012110049* 8012140555* 8012190210 8012030823 | 27-47 50-440 0 50-496 0 50-249 0 NUREO | HERDT, A. R. | 8012180116* 8012180217* 8012170048* 8012180174* 8012180112* | 50-416 50-389 50-338 50-261 50-260 |
| Hamlin, D. R. Hamlin, D. R. Hangock, J. A. Hangock, J. A. Hangock, J. A. | 8012040605 8012220164 8012020524 8012020635 8012020304 | RES 30-302 8 30-302 8 50-308 8 | HAYNES, R. C. HAYNES, R. C. HAYNES, R. C. HAYNES, R. C. HAYNES, R. C. | 8012040679* 8012010014* 8012040310* 8012310508* 8012310234* | 50-508 q 50-528 q 50-397 q 50-460 q 50-528 q | HERDT, A, R. HERDT, A. R. HERDT, A. R. HERDT, A. R. KERDT, A. R. | 8012170039* 8012070317* 8012080656* 8012110847* 8012110709* | 50-280 50-321 50-349 50-518 50-364 |
| HANGOCK, J. A. HANGOCK, J. A. HANGOCK, J. A. HANGOCK, J. A. HANGOCK, J. A. | 9012230448 8012230513 9012230317 8012230433 8012230440 | 50-302 8 50-302 8 NUREO 50-302 8 50-302 8 | HAYNEB, J. Q. HAYB, M. L. HAZLE, A. J. HAZLE, A. J. HAZLE, A. J. | 8012170619 8012300154* 8012080775 8012220409* 8012170040 | 50-206 8 CONTRACT WASTE HOT MASTE HOT REGOD | HERDT, A. R. HERDT, A. R. HERDT, A. R. HERDT, A. R. HERNANDEZ, Q. | 8012170473# 8012180401* 8012310053# 8012310297# 8012010014# | 50-438 50-369 50-566 50-413 50-528 |
| HANCOCK, J. A. HAND, A. HANHARDT, A. M. HANNAN, J. HANNAN, J. | 8012300501 8012050348 8012170537 8012170784* 8012270615 | 50-302 8 50-289 H NUREQ REB NUREO | HAZLE, A. J. HECK, F. M. HECTOR, A. O. HEDMAN, S. HEGNER, J. D. | 8012220477 8012050492* 8012240407* 8012110490 8012100102* | WABIE MOT PROJ Blate Prog PR 50-334 0 | HERNANDEZ, V. A. HERNANDEZ, V. HERNANDEZ, V. A. HERNANDEZ, V. A. HERNANDEZ, V. A. | 8012020646# 8012220312# 8012230454# 8012230524# 8012230437# | 50-302 50-302 50-302 50-302 50-302 |
| HANNAN, J., HANNON, J., N., HANNUN, D., HANRAHAN, E. J., HANRAHAN, E. J., | 8012270617 8012020054 8012010382* 8007100422 8012030724 | NUREO TOPREP 50-254 B BECY REVIEW GRP | HEIBEL, R. P. HEIDER, L. H. HEIDER, L. H. HEIDER, L. H. HEINEMAN, J. M. | 8012230409* 8012090595 8012230219 8012240174 8012160402 | 50-317 8 50-271 G 50-271 P 50-27 P 50-375 D | HERNANDEZ, V. A. HERR, R. K. HERSCHLER, E. HERSCH, M. H. HERSKOVITZ, M, B. | 8012300512# *E000039* 801204003108 1012020214 8012170199 | 50-302 50-498 40-8743 XPDRTLIC REB |
| HANRAHAN, E. J. HANRAHAN, E. J. HANRAHAN, E. J. HANRAHAN, E. J. HANRAHAN, E. J. | 8012030730* 8012030710* 8012030725* 8012030883* 8012030883* | REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP | HEISHMAN, R. F. | 8012030827* 8012100167 8012040093 8012040691 8011190515 | 50-320 U 50-155 Q 50-346 Q 50-316 Q 50-10 Q | HESTER, R. L. HEUSNER, A, T. HEWITT, M. L. HEWITT, M. L. HEWITT, M. L. | 8012270377# 8012180182 8012030481# 8012030437# 8012030479# | 50-389 PR FOIA 27-10 PUIA |
| HANRAHAN, E. J. HANSEN, L., E. HANSEN, H. A. HANSEN, L. E. HANSEN, L. E. | 8012030861 8012020092 8012240030 * 8012090237 8012170273 * | REVIEW GRP 71-9070 50-483 G XPORTLIC XPORTLIC | HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F. | 8012110104 8012110117 8012080761 8012110737 8012020787 | 50-358 Q 50-315 Q 50-373 Q 50-186 Q 50-263 Q | HEWITT, M. L. | 8012030496 8012030490# 9012030436# 8012030431# 8012030421# | FOIA FOIA FOIA FOIA |
| | | | | | | | | |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | EUBJECT CATEGORY |
|--|---|--|--|--|--|---|---|--|
| HEWITT M. L. HEWITT M. L. HEWITT M. L. HEYER, R. B. HEYER, R. B. | B012030427* B012030411* B012030407* B012160171 B012160167 | FOIA FOIA 40-8727 40-8434 | HOFFMAN, D. P. | 8012220701 8012180005 8012080354 8012080362 8012080460 | 50-155 Q 50-155 Q 50-255 P 50-155 P 50-255 P | HDVEY, G. K. HOWARD, J. E. HOWARD, J. E. HOWARD, H. J. HOWE, P. W. | 8012300645 8012080833 8012010233 8012150167 8012180378* | 50-320 P PR 50-293 P 50-466 H 50-400 G |
| HEYER, R. S. HEYER, R. S. HICKEY, C. R. HICKIN, R. A. HICKIN, R. A. | 8012160179 8012240114 801230008 8012310406 8012040627# | 40-6622 40-8502 40-8584 50-346 P CONTRACY | HOPFKAN, D. P. HOPFMAN, D. P. HOPFMAN, D. P. HOPFMAN, D. P. HOPFMAN, D. P. | 8012150058 8012160182 8012160474 8012230205 8012230341 | 50-155 F 50-155 P 50-155 S 50-255 P 50-155 S | HOWE, P. W. HOWE, P. W. HOWELL, B. H. HOWELL, J. C. HOWELL, J. C. | 8012180396* 8012190381 8012020369 8012160221* 8012160256* | 50-400 Q 50-400 Q NUREO 70-143 50-261 Q |
| HICKS, B. O. HIESTAND, D. S. HIESTAND, D. S. HIESTAND, D. S HIGOINS, J. C. | 8012110173 8012120646 8012300348 8012300348 8012110577* | PR 50-409 Q 50-409 Q 50-409 Q 50-322 Q | HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. | 8012230527 8012230159 8012230275 8012300499 8012300502 | 50-133 S TOPREP 50-133 P 50-235 P 50-155 P | HOWELL, J. HOWLEY, J. R. HOWLETT, O. H. HOYLE, J. C. HOYLE, J. C. | 8012170609* 8012030549* 8012230347* 8012030728* 8012030731 | XPORTLIC FOIA 50-336 R REVIEW GRP REVIEW GRP |
| HIGOINBOTHAN, L. HIGOINS, J. C. HIGOINS, J. C. HIGH, H. HILDENBRAND, T. | 8012080380 8012180353* 8012180357* 8012180191 8012030823 | REGGD 50-247 Q 50-247 Q PR NUREO | Hoffman, D. P. Hogan, B. A. Hohmston, L. A. Holeman, O. R. Holeman, O. R. | 8012300422 8012110044 8012110852 8012120101 8012110180 | 50-155 8 PR PR PR PR | HDYLE, J. C. HDYLE, A. HDYLE, J. C. HDZA, H. HBIEH, C. | 8012240018 8012230133 8012270037 8012240443* 8012220609 | SO-387 O CONTRACT COMMISSION ORG NUREO |
| HILEHAN, J. A. HILGER, M. T. HILL, N. M. HILL, A. O. HILL, A. O. | 8012230370 8012120624 8012190707* 8012190609* 8012190719* | NUREG PR 50-272 G XPGRTLIC 50-438 G | HOLODY, D. HOLODY, D. J. HOLOWAY, C. F. HOLOWAY, C. F. HOLOWAY, C. F. | 8012300039* 8012220019* 8012110003 8012190185 8012120617 | 70-820 70-1143 REB REB PR | HBU, Y. Hubacek, W. O. Hubacek, W. O. Hubacek, W. O. Hubbard, B. | 8012180430 8012170416* 8012100200 8012100174 8012220188 | MISC 50-498 Q 50-498 B 50-482 B FQIA |
| HILL, A. HIELB, M. HIMEBAUCH, N. HIMEB, J. HIMEB, J. | 8012180383* 8012170134 8012170456* 8012170781 8012170784* | 50-391 Q PR 50-155 R RES RES | HOLT, P. E. HOLT, J. HOLT, P. E. HOLT, J. HOLZ, H. B. | 8012070054* 8012150140* 8012070051* 8012150138 8012300040* | 9A777 50-247 G 9A779 50-247 G 50-387 G | HUDBON, B. D. HUDBON, T. B. HUETER, L. J. HUETER, L. J. HUEY, M. E. | 8012270407* 8012230053 8012180435* 8012230173* 8012120348 | 50-220 Q 50-498 Q 70-925 50-373 Q PR |
| HIMES, J. HIMES, J. HIND, J. A. HIND, J. A. HIND, J. A. | 9012270615 9012270617 9012010586* 9012010566 8012020547 | NUREO NUREO 50-282 Q 50-282 Q 50-346 Q | HON, A. L. HOOD, D. HOOKER, K. HOOKER, K. HOPKINS, J. B. | 8012180430 8012070133 8012270107 8012300077 8012040698# | MIBC 50-329 A 50-329 G 50-466 G 50-316 G | HUFF, T. D. HUQHEB, H. J. HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. | 8012030548* 8012080654 8012020797* 8012020791 8012220080* | FOIA PR 50-289 Q 50-289 Q 50-289 Q |
| HIND, J. A. HIND, J. A. HIND, J. A. HIND, J. A. HIND, J. A. | 8012040274 8012110602 8012240254 8012180365* 8012150281* | 50-275 Q 50-10 Q 50-331 Q 70-2609 50-266 Q | HORGAN, J. T. HORIN, W. A. HORIN, W. A. HORIN, W. A. HORIN, W. A. | 8012110195 8012100088 8012270647 8012300057 8012300057 | PR PR 50-445 G 50-445 G 50-445 G | HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. | 9012020464 8012090348 8012170481 8012160421 8012290461* | 50-289 P 50-289 P 50-289 P 50-289 F 50-289 F |
| HIND, J. A. HIND, J. A. HIND, J. A. HIND, J. A. HIND, J. A. | 8012160192* 8012180360 8012160174 8012180600 8012310583 | 50-315 G 70-2609 50-315 G 50-155 G 50-295 G | HORIN, W. A. HORIN, W. A. HORIN, W. A. HORIN, W. A. HORN, A. J. | 8012270338 8012270338 8012310270 8012310270 8012070027* | 50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-206 Q | HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. HUKILL, R. O. HUKILL, H. D. | 9012160446 8012160521 8012190517 8012220235 8012290187 | 50-289 Q 50-289 P 50-289 R 50-289 P 50-289 F |
| HIND, J. A. HIND: J. A. HINDERSTEIN: C. HINES: E. HINZE: W. J. | 8012240061* 8012240058 8012150199 8012120459 8012230201 | 50-305 G 50-305 G 50-466 G 50-341 B NUREO | HORN, A. J. HORST, T. W. HORKITZ, K. HOSSY, C. K. HOSSLER, D. | 8012310415* 8012220678 8012080352 8012080195* 8012100498 | 50-228 Q NUREO PR 50-272 Q 50-289 H | HUKILL, H, D. HUKILL, H. D. HULMAN, L. O. HUNEZ, M. HUNNICUTT, D. M. | 8012300388 8012300408 8002220053* 8012140707 8012120326* | 50-287 P 50-289 P 50-347 Q PR 80-313 Q |
| HERBCH, D. HERBCH, D. HETCH, J. H. HETCH, J. H. HETCH, J. K. | 8012120648 8012120655* 8012030378* 8012030447* 8012030444* | 50-142 Q 50-142 Q FOIA FOIA | HOSSLER, D. HOUK, J. L. HOURIHAN, P. L. HOUSTON, D. HOUSTON, K. D. | 8012300264 8012110075 8012270430* 8012110776 8012220141 | 50-287 | HUNNICUTT, D. H. | 8012020194* 8012080834* 8012120570* 8012120237* 8012240045* | 50-285 Q 50-313 Q 50-285 Q 50-313 Q 50-285 Q |
| HITCH, J. W. HITCH, J. W. HITCH, J. W. HITCH, J. W. HITCH, J. W. | 8012030337* 8012030299* 8012030514* 8012030117* 8012030494* | FOIA FOIA FOIA FOIA | HOVEY, O, K. HOVEY, O. HOVEY, O. K. HOVEY, O. K. HOVEY, O. K. | 8012300160* 8012040613 8012040441 8012050376 8012010105 | 50~320 Q 50~320 Q 50~320 8 50~320 P 50~320 P | HUNNICUTT, D. 11. HUNNICUTT, D. H. HUNSTAD, A. A. HUNSTAD, A. A. HUNSTAD, A. A. | 8012270020 8012270025 8012010473* 8012160458* 8012070381* | 50-348 8 50-348 8 50-282 8 50-282 R 50-282 8 |
| HITCH, J. W. HITCH, J. W. HITCH, J. W. HITCH, J. W. | 8012030259* 8012030082* 8012030246* 8012030522* 8012020459 | FOIA FOIA FOIA PR | HOVEY, O. K. HOVEY, O. K. HOVEY, O. K. HOVEY, O. K. HOVEY, O. K. | 8012020532 8012020515 8012050345 8012070383 8012050412 | 50-320 P 50-320 P 50-320 P 50-320 8 50-320 P | HUNSTAD, A. A. HUNSTAD, A. A. HUNT, M. D. HUNTER, R. S. HUNTER, R. H. | 8012070402# 8012150177* 8012180289# 8012040578# 8012170839 | 50-304 8 50-282 8 50-424 0 50-315 F 50-280 0 |
| HOCHREITER. L. E. HOCKENBURY, R. W. HODODON, A. HODSON, W. L. | 8012230473 8012120342 8012300013 8012010516 | TOPREP NUREO 50-445 M PR 70-2623 | HOVEY, O. K. | 801210D451 8012110407 8012110507 8012150185 8012150240 | 50-320 P 50-320 P 50-320 P 50-320 S 50-320 0 | HUNTER, R. S. HUNTER, R. S. HUNTER, R. S. HUNTLEY, H. W. HUSEBY, D. E. | 8012100599 8012180312 8012180315 8012040476 8012010369* | 50-315 F 50-315 P 50-315 P 50-287 H 50-317 B |
| | | 50-10 P 50-10 P 50-10 P NUREO 50-382 A | HOVEY, O. K. | 8012160273 8012160367 8012160452 8012160495 8012170518 | 50-320 P 50-320 P 50-320 P 50-320 B 50-320 P | HUSSEY, J. R. HUSSEY, J. R. HUSSEY, J. R. HUTTON, P. H. HWANG, W. S. | 8012160767* 8012300728* 8012300706* 8012120609 8012300486* | 50-466 T 50-466 T RES |
| | | GRQ 50-155 G 71-5364 50-155 G 50-255 P | HOVEY, O. K. | 8012170571 8012220237 8012220383 8012230475 8012300470 | 50-320 8 50-320 P 50-320 P 50-320 8 50-320 S | HYDERIC. IAROBBEID. ILLHARDTIJ. IPPOLITOIT.A. IPPOLITOIT.A. | 8012220269* 8012160682 8012110116 8012290450* 8012010460 | PR PR |
| | | 50-255 P 50-255 8 50-255 8 50-255 Q 50-255 P | HOVEY: Q. K. HOVEY: Q. K. HOVEY: Q. K. HOVEY: Q. K. | 8012300621 8012300629 8012300641 8012310318 8012310324 | 50-320 P 50-320 P 50-320 P 50-320 P | IPPOLITO, T. A. | 8012080313 8012080321 8012080331 8012080089 8012080095 | 90-271 P |
| | | | | Audwes. | | | | |

| AUTHOR | ACCESSION NUMBER | SUBJECT SATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEOORY |
|---|--|--|---|---|---|--|---|--|
| IPPOLITO, T. A. | 8012080106* 8012080290 8012080295* 8012080306* 8012010481 | 50-237 P 50-240 P 50-240 P 50-240 P 50-240 F | JANECEK, R. F. JANIC IK, E. JANIC IK, E. JANINEK, M. JANINEY, C. D. | 8012160172 8012170781 8012170788* 8012020283 8009190463* | SO-10 P RES RES State Prog 40-8106 | JONES, B. H. JONES, B. | 8012050670 8012270109* 8012160663 8012300233 8012300469* | 50-329 (50-329 (PR 50-329 (50-270 E |
| IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A. | 8012080048 8012080053* 8012080059* 8012080387 8012080395* | 50-278 P 50-278 P 50-278 P 50-278 P 50-278 P | JANNEY, C. D. JANSEN, C. JANSSEN, T. K. JANUSKA, A. Q. | 8012080735* 8012240434* 8012080671 8012180230 8012040263* | 40-8106 40-8743 PR PR 50-331 G | JDNE8; W. C. JDNE5; W. C. JDNE6; B. W. JDNE6; B. W. JONE8; J. L. | 8012170538 8012220377 8012270374 8012270148 8012230520* | 50-285 F 50-285 F 70-371 50-329 G 50-287 8 |
| IPPOLITO, T. A. | 8012080403* 8012010465 8012080377 8012080573* 8012080582* | 50-278 P 50-273 F 50-273 P 50-273 P 50-273 P | JAROSŁOW, B. N. JARRETT, R. D. JAUDON, J. P. JENKINS, G. R. JENKINS, G. R. | 8012230426 8012050213 8012080834* 8012090197* 8012180184* | 50-387 C 71-5362 50-313 Q 50-395 Q 50-553 Q | JONES, J. L. JONES, B. W. JONES, B. W. | 8012300475* 8012300498* 8012270547 8012270575 8012300007 | 50-287 8 50-269 8 50-329 0 50-275 0 50-275 0 |
| IPPOLITO, T. A. | 8012180633* 8012180640* 8012120437 8012130126 8012170372 | 50-10 P 50-10 P 50-269 F 50-249 F 50-139 F | JENKING, Q. R. JENKING, G. JENKING, Q. R. JENKING, Q. R. JENKING, C. L. | 8012110222* 8012180167* 8012180375* 8012180308* 8012120199 | 50-348 Q 50-438 Q 50-369 Q 50-302 Q PR | JONES, J. L. JOPPA, J. | 8012300183 8012300488* 8012110815 8011130046* 8012100597* | 50-275 G 50-287 E PR BECY 50-10 0 |
| IPPOLITO, T. A. | 8012300614 8012300622* 8012300633* 8012300704 8012300707* | 50-278 P 50-278 P 50-278 P 50-271 P 50-271 P | Jenkins, R. V. Jenkins, R. V. Jens, H. H. Jensch, S. H. Jensch, S. W. | 9012070444* 9012170618* 9012240278 9012030664* 9012030317* | 50-304 S 50-304 S 50-452 A FOIA 27-10 | JORDAN, W. S. | 6012100065 8012020673 8012020673 6012170675 8012170675 | 50-313 P 50-443 G 50-443 G 50-443 G |
| IPPOLITO, T. A. | 8012300710* 8012230515* 8012230523* 8012230510 8012300786 | 50-271 P 50-257 P 50-259 P 50-259 P 50-254 P | Jensen, W. L Jensen, B. E. Jergenb, C. Jesse, K. E. Jody, B. | 8012230109 8012100379 8012180154 8012120319 8012220135 | TOPREP TOPREP 50-546 G PR XPORTLIC | JORDAN, H. B. JORDAN, H. B. JORDENSON, B. L. JOY, J. M. JOYNER, J. H. | 8012270322 8012270322 8012310433* 8012140338* 8012100247* | 50-443 0 50-443 0 50-255 0 50-206 R 70-1143 |
| IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. | 8012300790* 8012300795* 8012220251* 8012220256 | 50-254 P 50-254 P 50-324 P 50-324 P 50-324 P | JOHNSON, L. JOHNSON, L. JOHNSON, L. JOHNSON, L. JOHNSON, L. JOHNSON, L. | 8012030478* 8012030070* 8012030078* 8012030007* | FOIA 27-39 27-39 27-39 27-39 | JOYNER, J. H. | 8012070073* 8012110158* 8012110171* 8012230061* 8012300037* | 70-135 70-1143 70-33 70-135 70-820 |
| IPPOLITO, T. A. | 8012300691 8012300697* 8012300700* 8012300713 8012300716* | 50~293 P 50~293 P 50~293 P 50~259 P 50~259 P | JOHNSON, L. JOHNSON, L. JOHNSON, L. JOHNSON, L. JOHNSON, L. | 8012030014* 8012030016* 8012030017* 8012030024* 8012030028* | 27-39 27-39 27-39 27-39 27-39 | JOYNER, J. H. | 8012170478* 8012220019* 8012220012* 8012220025* 8012270374 | 70-371 70-1143 70-820 70-135 70-371 |
| IPPOLITO, T. A. | 8012300724* 8012310004 8012300640 8012300647* 8012300653* | 50-259 P 50-271 P 50-220 P 50-220 P 50-220 P | JOHNSON, L. JOHNSON, W. P. JOHNSON, W. P. JOHNSON, M. R. JOHNSON, J. M. | 8012030678* 8012110792* 7810240085 8012100436 8012190454* | FOIA FOIA 50-29 P XPDRTLIC GA999 | JUDD. C. T. JUN-YT. L. JURASTN. R. P. JURGENSEK, R. N. JURGENSEK, R. N. | 8012010624 8012090270 8012040149 8012230365 8012230308 | PR COMMISSION SO-309 F TOPREP TOPREP |
| IREDALE, J. R. IRELAND, R. IRELAND, R. IRVING, B. J. IRWIN, D. P. | 8012170704* 8012110155 8012160011 8012310570 8012070263 | 50-289 H MISC TOPREP FOIA 50-450 Q | JOHNSON, A. R. JOHNSON, J. M. JOHNSON, R. H. JOHNSON, W. D. JOHNSON, W. D. | 8012020749* 8012220098* 8012030823 8012030496* 8012120237* | 90-445 Q QA979 NUREO PROJ 50-313 Q | KAHLE, J. D. KAHLER, R. S. KAHN, H. I. | 8012120504 8012310619* 8012270151 8012170524* 8012010111 | NUREO 70-143 PR NUREO PR |
| IRHIN, D. P. | 8012070265* 8012070277 8012070278* 8012100471* 8012230058 | 50-450 Q 50-463 Q 50-463 Q 50-463 Q 50-450 Q | JOHNSON, N. P. JOHNSON, C. R. JOHNSON, A. D. JOHNSON, A. D. JOHNSTON, O. N. | 8012100319 8012240307 8012100147* 8012310554* 8012310538* | 50-309 0 71-6698 50-361 0 50-133 0 50-344 0 | KALIVIANAKIS, N. | 8012010374 8012090407 8012090446 8012090451 8012150200 | 50-254 8 50-245 8 50-245 8 50-245 8 50-245 8 |
| IRGIN, D. P. ISBIN, H. B. | 8012070265* 8012230058 8012070278* 8012100471* 8012100187* | 50-450 0 50-450 0 50-463 0 50-463 0 CONTRACT | JOHNSON, R. E. JOHNSON, J. W. JOHNSON, B. JOHNSON, R. W. JOHNSRUD, J. H. | 8012300384* 8012150286* 8012120370 8012120480* 8012290459 | 50-341 K 50-158 P PR 50-344 O PR | KALIVIANAKISIN. KALIVIANAKISIN. KALOWSKYJYIH KANINIH. KANEIH. | 8012170446 8012300414 8012240082* 8012120085 8012070241 | 50-254 R 50-265 S 40-7924 PR 50-395 E |
| ISLEY, T. ISLEY, T. ISLEY, T. JABBOUR, K. N. JACKIW, I. N. | 8012120474* 8012120512* 8012310328* 8012310389 8012310470* | 50-346 S 50-346 S 50-346 S 50-327 V 50-373 Q | JOHNSON, R. L. JOHNSON, R. P. JOHNSON, R. H. JOHNSON, M. D. JOHNSRUD, J. H. | 8012110558 8012110516 8012290184* 8012290020 8012290514 | NUREO 50~309 0 50~289 H 50~348 8 50~289 0 | | 8012020095 8012220014 8012110774 8012140291 8012160005 | 50-382 A 50-395 A 50-395 A 50-395 A 50-395 A |
| Jackių, I. N. Jackson, J. L. Jackson, J. L. Jackson, R. W. Jackson, O. L. | 8012150268* 8012010050 8012010045 8012080271* 8012110337 | 50-331 Q RE8 RE9 QA999 PR | JOHNSON, W. D. JOHNSON, W. P. JOHNSON, W. B. JONES, O. C. JONES, W. C. | 8012290025 8012319278 8012290611 8012220716 8012220607 | 50-368 8 50-309 P NUREQ NUREQ 50-285 Q | KANE, W. F. KANE, W. KANE, W. F. KANEN, A. KANNARD, J. R. | 6012160025 8012240152 8012310180 8012380007* 8012190471 | 50-395 A 50-395 A 50-382 A 50-443 F TOPREP |
| JACKSON, J. L. JACOBSI, A. JACOBSI, K. JACOBSON, N. JACOBSONITZ, P. | 8012040605 8012080871 8012160368* 8012110783 8012160581 | RES CONTRACT 50-286 G PR PR | JONES, H. C. JONES, D. W. JONES, P. N. JONES, E. JONES, C. E. | 8012120210 8012070185# 8012310605* 8012020710 8012080035# | 50-285 Q 70-1151 40-7402 FOIA 50-454 Q | KAPLAN, A. L. Kaplan, A. L. Karluntoz, 11. L. Karman, M. Karp, F. B. | 8012040470 8012180472 8012240140 8012360134 8012080450* | 70-1113 70-1113 50-395 I 50-450 9 50-247 8 |
| JACOBB. A. K. JAKOBCIN, K. D. JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. | 8012160107 8012030441 8012090400 8012160510 8012170408 | 50-83 I 50-289 H 50-237 P 50-237 P 50-237 Q | JONES, H. C. JONES, J. H. JONES, H. C. JONES, E. JONES, E. | 8012040378 8012160413* 8012150024 8012170267* 8012100239 | PR TOPREP 50-285 Q 50-454 Q 50-247 8 | Kasman, R. Kastenberg, W. Kastenberg, W. E. Katsikis, E. Katterjohn, J. C. | 8012170187 8012020797* 8012020804* 8012110310 8012080465 | PR 50-312 0 50-312 0 PR PR |
| JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. | 8012010343 8012110274 8012150052 8012120301 8012160136 | 50-254 P 50-237 P 50-237 P 50-237 P 50-237 P | JONES, L. JONES, L. JONES, N. C. JONES, J. L. JONES, B. N. | 8012190410 8012240122 8012090092 8012020543* 8012050662 | FOIA FOIA PR 50-270 8 50-329 0 | Kaufman, n. c. Kayi J. A. Kayi J. A. Kayi J. A. Kayi J. A. | 8012220174 8012020111 8012020242 8012240259 8012240259 | RES F 50-29 F 50-29 P 50-29 P 50-29 H |

| | ACCE85ION | TOSLBUR | | ACCESSION | SUBJECT | AUTHOR | ACCESSION NUMBER | SUBJECT CATEOORY |
|--|---|--|--|--|--|--|---|--|
| AUTHOR | NUMBER 8012080769 | CATEGORY PR | AUTHOR KEPPLER, J. Q. | NUKBER | CATEOURY 50-309 Q | KEPPLER, J. G. | 8012230236 | 50-409 Q |
| KEARNEY, J. J. KEARNEY, J. J. KEATEN, R. W. KEENEY, H. P. KEENE, W. E. | 8012070100 8012100177 8012120362 8012120333 | PR 50-284 T 71-5909 PR | KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. | 8012170506 8012170510 8012170527 8012170537 | 50-315 0 50-10 0 50-155 0 50-329 0 | KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. | 8012100261 8012170520 8012170522 8012170525 | 50-237 Q 50-305 Q 50-266 Q 50-346 Q |
| KEIMIO, R. R. | 8012110090* | 50-219 Q | KEPPLER, J. Q. | 8012170542 | 50-346 Q | KEPPLER, J. O. | 8012170528 | 50-546 Q |
| KEIMIO, R. R | 8012160309* | 50-289 Q | KEPPLER, J. Q. | 8012170546 | 50-237 Q | KEPPLER, J. O. | 8012170531 | 50-263 Q |
| KEIMIO, R. R. | 8012220077* | 50-245 Q | KEPPLER, J. Q. | 8012170553 | 50-483 Q | KEPPLER, J. O. | 8012170533 | 50-367 Q |
| KEIMIO, R. R. | 8012190707* | 50-272 Q | KEPPLER, J. Q. | 8012170624 | 50-266 Q | KEPPLER, J. O. | 8012170535 | 50-331 Q |
| KEIMIO, R. R. | 8012100205 | 50-219 S | KEPPLER, J. Q. | 8012170634 | 50-331 Q | KEPPLER, J. O. | 8012170537 | 50-461 Q |
| KEIMIG, R. R. KELBLEY, N. D. KELBLEY, N. D. KELBLEY, N. D. | 8012310238* 8012190611* 8012110343 8012110354 8012190608 | 50-269 T 71-354 71-9011 71-5794 71-354 | KEPPLER, J. O. KEPPLER, J. G. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. | 8012170644 8012170649 8012170656 8012170661 8012170666 | 50-263 0 50-440 0 50-367 0 50-358 0 50-461 0 | KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. G. KEPPLER, J. O. KEPPLER, J. O. | 8012170540 8012170541 8012170545 8012170549 8012170552 | 50-341 Q 50-409 Q 50-329 Q 50-315 Q 50-10 Q |
| KELLEY, J. L. KELLEY, W. D. KELLEY, W. D. KELLEY, D. L. | 8012290073* 8012240443* 8012190446* 8012180644* 8012080194* | COMMISBION ORG GATTT GATTT 50-285 Q | KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. | 8012170671 8012180130 8012310464 8012310534 8012020112 | 50-341 0 50-358 0 50-373 0 40-7402 50-305 P | KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. | 8012170555 8012170557 8012170561 8012170754 8012170709 | 50-358 Q 50-440 Q 50-155 Q 50-483 Q 50-346 P |
| KELLEY, W. D. | 8012190312* | 0A979 | KEPPLER, J. O. | 8012180022 | 50-409 Q | KEPPLER, J. O. | 8012180185 | 50-407 P |
| KELLER, G. R. | 8012230201 | NUREO | KEPPLER, J. Q. | 8012180596 | 50-461 Q | KEPPLER, J. O. | 8012180414 | 50-315 Q |
| KELLOGG, P. J. | 8012180208* | 50-338 G | KEPPLER, J. Q. | 8012040270 | 50-10 S | KEPPLER, J. O. | 8012100579 | 50-275 Q |
| KELLOGG, P. J. | 8012110257* | 50-416 Q | KEPPLER, J. Q. | 8012040589 | 50-315 F | KEPPLER, J. O. | 8012190427 | 50-546 A |
| KELLOGG, P. J. | 8012180149* | 50-338 G | KEPPLER, J. Q. | 8012220042 | 50-266 Q | KEPPLER, J. G. | 8012150278 | 50-266 Q |
| KELLDOG, P. J. | 8012070310# | 50-414 Q | KEPPLER, J. O, | 8012010051 | 50-373 A | KEPPLER, J. O. | 8012180002 | 50-237 P |
| KELLDOG, P. J. | 8012110637# | 50-375 Q | KEPPLER, J. O, | 8012020743 | 50-10 Q | KEPPLER, J. O. | 8012240472 | 50-151 Q |
| KELLDOG, P. J. | 8012180039# | 50-261 Q | KEPPLER, J. O, | 8012010581 | 50-373 A | KEPPLER, J. G. | 8012290396 | 50-265 H |
| KELLDOG, M. | 8012170100 | PR | KEPPLER, J. O, | 801202052 | 50-331 F | KEPPLER, J. G. | 8012310002 | 50-315 P |
| KELLY, R. B. | 8012220086# | QATTY | KEPPLER, J. O, | 801202053 | 50-263 F | KEPPLER, J. Q. | 8012180229 | 70-36 |
| KELLY, J. A. KELLY, J. A. F. KELLY, J. A. KELLY, J. A. F. KELLY, R. J. | 8012120562* 8012110784* 8012120559 8012110780 8012090385 | 50-112 Q 50-267 Q 50-112 Q 50-267 Q 50-321 P | KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. | 8012020077 8012020098 8012020102 8012020106 8012020118 | 50-315 F 50-409 F 50-305 F 80-155 P 50-346 F | Kerr, G. W. Kerr, G. W. Kerr, O. W. Kerr, G. W. Kerr, G. W. | 8012220212* 8012220219* 8012220278* 8012220270* 8012220233* | FOIA FOIA FOIA FOIA |
| KELLY,R.J. | 8012230064 | 50-321 Q | Keppler, J. O. | 8012020122 | 50-246 F | KERT, O. W. | 8012010018 | I&E |
| KELSEY.C.A. | 8012180197 | PR | Keppler, J. G. | 8012020155 | 50-155 F | KERT, G. W. | 8012010457 | State Prog |
| KEMPER,J.S. | 8012010461 | PR | Keppler, J. G. | 8012020167 | 50-10 F | KERT, O. W. | 8012120235 | State Prog |
| KEMPER,J.S. | 8012050110 | PR | Keppler, J. G. | 8012040057 | 50-295 0 | KERT, W. | 8012040288 | 50-2 F |
| KEMPER,J.S. | 8012080190 | REGOD | Keppler, J. G. | 8012020457 | 50-331 Q | KERT, J. E. | 8012270518 | 50-133 Q |
| KEMPER. J. S. | 8012080424 | 50-352 A | KEPPLER, J. Q. | B012020666 | 50-315 0 | KERR, O. W. | 8012160625* | State Prop |
| KEMPER. J. S. | 8012100493 | 50-352 A | KEPPLER, J. Q. | B012040633 | 50-263 0 | KERR, Q. W. | 8012220402 | State Prop |
| KEMPER. J. S | 8012300527 | 50-352 8 | KEPPLER, J. Q. | B012040637 | 50-373 0 | KERR, Q. W. | 8012220410 | State Prop |
| KENDALL. M. L. | 8012170648 | 50-287 H | KEPPLER, J. Q. | B012040641 | 50-546 0 | KERRIGAN, J. | 8012030708 | 50-311 P |
| KENI TZER. H. L. | 8012030854* | 50-10 P | KEPPLER, J. Q. | B012040644 | 50-367 0 | KERRIGAN, J. | 8012020693 | 50-528 F |
| Kenna, H. B. | 8012070176* | 70-1131 | Keppler, J. G. | 8012040646 | 50-461 | Kerr Igan, J. | 8012080784 | 50-311 P |
| Kenna, H. B. | 8012120580* | 50-335 0 | Keppler, J. G. | 8012040647 | | Kerr Igan, J. | 8012100246 | 50-528 A |
| Kenna, W. B. | 8012120575* | 50-302 0 | Keppler, J. G. | 8012040649 | | Kerr Igan, J. | 8012100250 | 50-272 P |
| Kenna, W. B. | 8012100686* | 70-143 | Keppler, J. G. | 8012040653 | | Kerr Igan, J. D. | 8012070437 | 50-528 A |
| Kenna, W. B. | 8012180055 | 50-259 0 | Keppler, J. G. | 8012040654 | | Kerr Igan, J. | 8012150004 | 50-311 P |
| Kenna, W. B. | 8012120573 | 50-302 0 | KEPPLER, J. Q. | B012040656 | 50-346 Q | KERR I GAN, J. KEBTENBAUM, L. KEBTENBAUM, L. KETCHEN, E. G. KETCHEN, E. G. | 8012160237 | 50-528 D |
| Kenna, W. B. | 8012120579 | 50-335 0 | KEPPLER, J. Q. | B012040659 | 50-266 Q | | 8012030153* | 27-10 |
| Kenna, W. B. | 8012090162 | 70-1151 | KEPPLER, J. Q. | B012040661 | 50-305 Q | | 8012030043* | 27-10 |
| Kenna, W. B. | 8012180476* | 70-1113 | KEPPLER, J. Q. | B012040664 | 50-483 Q | | 8012040008 | 50-369 H |
| Kenna, W. B. | 8012160242 | 50-261 0 | KEPPLER, J. Q. | B012040667 | 50-10 Q | | 8012040022* | 50-367 H |
| KENNA, W. B. KENNA, W. B. KENNA, W. B. KENNA, W. B. KENNEDY, B. E. | 8012190605 8012160216 8012190716 8012180391 8012110825 | XPORTLIC 70-143 50-438 Q 50-391 Q PR | Keppler. J. O. Keppler. J. O. Keppler. J. O. Keppler. J. O. Keppler. J. O. | 8012040671 8012040674 8012040676 8012040678 8012310136 | 50-440 | METCHEN, E. Q. KETCHEN, E. Q. KETCHEN, E. Q. KETCHEN, E. Q. KETZLACH, N. | 8012190584 8012290427 8012300143 8012300403 8012180385 | 50-369 H 50-275 G 70-2623 50-275 G 70-1100 |
| KENNEDY, D. M. | 8012160425 | 50-255 R | KEPPLER, J. O. | 8012080031 | 50-315 Q | KETZLACH, N. KEY, W. J. KEY, W. J. KHATIB-RAHBAR KID, J. T. | 8012100027 | 70-698 |
| KENNY, T. | 8012300003* | 50-247 Q | KEPPLER, J. O. | 8012080036 | 50-358 Q | | 8012110016* | 50-461 Q |
| KENNY, T. J. | 8012180353* | 50-247 Q | KEPPLER, J. O. | 8012080039 | 50-440 Q | | 8012170279* | 50-331 Q |
| KENR ICK, J. R. | 8012020758 | 70-2909 | KEPPLER, J. O. | 8012080041 | 50-327 Q | | 8012120334 | NUREQ |
| KENR ICK, J. R. | 8012270206 | 70-2909 | KEPPLER, J. O. | 8012080044 | 50-155 Q | | 8012230368 | NUREQ |
| KENRICK, J. R. | 8012020758 | 70-2909 | KEPPLER, J. Q. | 8012080055 | 50-409 | KIDD, M. S. | 8012180208* | 50-338 0 |
| KENRICK, J. R. | 8012290011 | 70-2909 | KEPPLER, J. Q. | 8012080056 | | KIDD, D. G. | 8012110238* | FOIA |
| KENRICK, J. R. | 8012290011 | 70-2909 | KEPPLER, J. Q. | 8012080057 | | KIDD, J. | 8012040404 | RE8 |
| KENT, T. T | 8012010302* | 71-399 | KEPPLER, J. Q. | 8012080063 | | KING, J. L. | 8012270404* | 50-387 M |
| KENYON, T. J. | 8012120597 | 50-328 A | KEPPLER, J. Q. | 8012080066 | | KING, J. J. | 8012220707 | NURE0 |
| KENYON, T. J. | 8012160164 | 50-390 A | Keppler, J. O. | 8012080070 | 50-263 | Kinneman, J. D. | 8012080742* | 40-8106 |
| KENYON, T. J. | 8012100695 | 50-390 A | Keppler, J. O. | 8012080071 | | Kinneman, J. D. | 8012190601* | 70-2156 |
| KENYON, T. J. | 8012190065 | 50-327 P | Keppler, J. O. | 8012080074 | | Kinneman, J. D. | 8012240087* | 40-7924 |
| KEPFORD, C. | 8012290083 | 50-463 Q | Keppler, J. O. | 8012080074 | | Kinneman, J. D. | 8012240086* | 40-7102 |
| KEPPLER, J. G. | 8012310573* | 40-7402 | Keppler, J. Q. | 8012080080 | | Kinneman, J. D. | 8012080720 | 40-8106 |
| KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. Q. | 8012310543* 8012190672* 8012310514 8012390145* 8012190667 | 40-7402 50-305 | KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. | 8012080083 8012080087 8012120387 8012070468 8012170262 | 50-305 Q 50-10 Q 50-305 Q 50-155 F 50-155 Q | KINNEMAN, J. D. KINNEMAN, J. D. KINNEMAN, J. D. KINNEMAN, J. KINNEMAN, J. | 8012190594 8012240077 8012190678 8012110179 8012290103 | 70-2156 40-7924 40-7102 18E 18E |
| KEPPLER, J. G. | 8012220144* | 50-440 A | KEPPLER, J. O. | 8012170270 | 50-263 0 | Kintner, L. L. | 8012120615 | 50-364 P |
| KEPPLER, J. G. | 8012070138 | 50-440 Q | KEPPLER, J. Q. | 8012220571 | 50-346 0 | Kintner, L. L. | 8012190723 | 50-364 P |
| KEPPLER, J. G. | 8012160055 | 50-409 Q | KEPPLER, J. Q. | 8012220574 | 50-331 0 | Kintner, L. L. | 8012160007 | 50-364 P |
| KEPPLER, J. G. | 8012170271 | 50-329 Q | KEPPLER, J. Q. | 8012220606 | 50-315 0 | Kintner, L. L. | 8012160014 | 50-341 F |
| KEPPLER, J. G. | 8012170478 | 50-546 Q | KEPPLER, J. Q. | 8012230223 | 50-10 0 | Kintner, L. L. | 8012240151 | 50-364 P |
| | | | V 1981 1 4 | | | | | |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEQURY |
|--|---|--|---|---|--|--|--|--|
| KINTNER, L. L. | 8012170071 | 50-341 A | KOSLA, B. | 8012240097 | 70-157 | LANÇ, G. | 8012110402 | 50-289 H |
| KIRK, R. L. | 8012030260* | FOIA | KOTH, R. M. | 8012080664* | 40-1341 | LANPHER, L. C. | 8012290002 | 50-275 Q |
| KIRK, R. L. | 8012030175* | FOIA | KOTSCH, J. L. | 8012010606 | 40-6659 | LANPHER, C. | 8012290161 | 50-275 Q |
| KIRK, R. L. | 8012030462* | FOIA | KOTSCH, J. L. | 8012160184 | 40-8084 | LANPHER, L. C. | 8012290002 | 50-275 O |
| KIRK, R. L. | 8012030360* | FOIA | KOTSCH, J. L. | 8012240073 | 40-299 | LANPHER, C. | 8012290161 | 50-275 O |
| KIRK, R. L. KIRK, R. L. KIRK, R. L. KIRK, R. L. KIRK, R. L. | 8012030356* 8012030403* 8012030242* 8012030253* 8012030084* | FOIA FOIA FOIA FOIA | KOTBCH.J.L. KOTTAN.J.J. KOWALSKI.J.F. KRAUS.G. KRAVOTIL.E.J. | 8012140171 8012220348* 8012030814 8012160718 8012300108 | 40-8084 50-287 G PR PR 50-287 H | LARSON, L. C. LARSON, J. R. LASSAHN, P. L. LATHAM, B. B. LATHAM, B. | B012030243* B012170049 B012110558 B012070126 B012180218 | FOIA RES HUREO PR PR |
| KIRK, R. L. KIRK, R. L. KIRK, R. L. KIRK, R. L. KIRK, R. L. | 8012030558* 8012030047* 8012030022* 8012030266* 8012030282* | FOIA FOIA FOIA FOIA | KREGER, W. E. KRIZAN, P. KROTZ, D. P. KRUEGER, B. K. KRU!/POB, P. J. | 8012070260 8012170660* 8012030080* 8012080216 8012240274* | 50-10 P 50-287 H FOIA PR 50-282 Q | LATHAM, 8, B, LAU, L, W, LAUER, J, D, LAUGHLIN, J, B LAVERTY, J, H. | 8012270001 8012150112* 8012270141 8012120142 8012020658 | 50-322 0 50-327 P PR PR 50-387 0 |
| KIRK, R. L. | 8012030297* | FOIA | KUEHL, E. L, | 8012030469* | FOIA | LAVERTY, J. H. | 8012020699 | 50-142 0 |
| KIRK, R. L. | 8012030252* | FOIA | KUEHL, E. L. | 8012030360* | FOIA | LAVERTY, J. H. | 8012100171* | 50-142 0 |
| KIRK, R. L. | 8012030217* | FOIA | KUEMIN, J. L. | 8012080525 | 50-255 P | LAVERTY, J. H. | 8012170657 | 50-387 0 |
| KIRK, R. L. | 8012030070* | FOIA | KUEMIN, J. L. | 8012170453 | 50-255 P | LAVERTY, J. H. | 8012300053 | 50-387 0 |
| KIRK, R. L. | 8012030085* | FOIA | KUGE, T. | 8012100062 | XPORTLIC | LAVERTY, J. H. | 8012270219 | 50-387 0 |
| KIRK, R. L. KIRK, R. L. KIRK, R. L. KIRK, R. L. KIRK, R. L. | 8012030102* 8012030122* 8012030150* 8012030477* 8012030137* | FOIA FOIA FOIA FOIA | KULASH. W. KUND. M. J. KUNZE, W. E. KUSHNER, W. L. KUSHNER, W. L. | 8012080007# 8012040375 8012240051# 8012070073# 8012110158# | 50-443 F 50-247 H CONTRACT 70-135 70-1143 | LAVERTY, J. H. LAW, J. E. LAW, J. E. LAW, J. E. LAW, J. E. | B012310272 B012030413* B012030268* B012030556* B012030561* | 50-387 0 FOIA FOIA FOIA 27-10 |
| KIRK, R. L. | 8012030025* | 27-10 | KUSHNER, W. L. | 8012220025# | 70-135 | Law, J. E. | 8012030488* | FOIA |
| KIRK, R. L. | 8012030445* | F01A | KUZMYCZ, G. | 8012110122 | 50-267 F | Law, J. E. | 8012030231* | 27-10 |
| KIRK, R. L. | 8012030457* | F01A | LACEY, W. S. | 8012030659# | 50-334 8 | Law, J. E. | 8012030532* | FOIA |
| KIRK, R. L. | 8012030464* | F01A | LACEY, W. S. | 8012090392# | 50-334 8 | Lawin, R. N. | 8012080208 | REOOD |
| KIRK, R. L. | 8012030471* | F01A | LACEY, W. S. | 8012100463# | 50-334 8 | Lawrence, R. M. | 8012270187* | 50-287 H |
| KIRK, R. L. | 8012030631* | FOIA | LAGEY: W. B. | 8012050407* | 50-334 8 | LAYFIELD, R. L. | 8005190347# | 40-4940 |
| KIRK, N. F. | 8012010547 | 70-371 | LAGEY: W. B. | 8012080437* | 50-334 8 | LAZARO, J. | 8012170190 | PR |
| KIRK, W. F. | 8012020687 | 70-371 | LAGEY: W. B. | 8012120530* | 50-334 8 | LAZO, R. M. | 8012120551 | 50-349 0 |
| KIRK, Q. B. | 8012020633* | 50-327 8 | LAGEY: W. B | 8012120535* | 50-334 8 | LAZO, R. M. | 8012120555 | 50-349 0 |
| KIRK, Q. B. | 8012070358* | 50-327 8 | LAGEY: W. B. | 8012120545* | 50-334 8 | LAZO, R. M. | 8012300380 | 50-562 0 |
| KIRK, Q. B. KIRK, Q. B. KIRK, Q. B. KISTER, H. B. KISTER, H. | 8012230365* 8012230373* 8012300564* 8012110597* 8012300003* | 50-327 8 50-327 8 50-327 8 50-322 0 50-247 0 | LACEY, W. B LACEY, W. B LACEY, W. B LACEY, W. B LACEY, W. B | 8012160488* 8012170509* 8012170590* 8012170592* 8012170576* | 50-334 S 50-334 S 50-334 B 50-334 B 50-334 B | LAZO, R. M. LEACH, L. P. LEACH, L. P. LEASIA, L. T. LEBERGTEIN, J. H. | 8012300370 8012100132 8012220186 8012120092 | 50-548 G PR REB PR 50-280 P |
| KISTERN, H. B. KISTER, H. B. KISTER, H. B. KLEINSDROE, H. P. KLEINSDROE, H. P. | 8012270420* 8012270407* 8012180357* 8012180130* 8012180118* | 50-220 | LACEY, W. B. LACEY, W. B. LACEY, W. B. LACEY, W. B. LACEY, W. B. | 8012170400* 8012170402* 8012230533* 8012230538* 8012230445* | 50-334 8 50-334 8 50-334 8 50-334 8 50-334 8 | LEBO.G. LEBO.G.D, LEBO.G.D, LEBOEUF.R.J. | 8012040374 8012100017 8012300163* 8012300142* 8011180561 | CONTRACT CONTRACT CONTRACT CONTRACT 50-283 P |
| KLEINEOROE, W.P. | 8012180217* | 50-389 G | LACEY, W. B. | 8012300467* | 50-334 | LENDEUF, R. J. | 8012010297 | 50-244 P |
| KLINGSBERG, D. | 8012160604 | 50-320 0 | LACEY, W. B. | 8012300470* | | LEBDEUF, R. J. | 8012090105 | PR |
| KLINGSBERG, D. | 8012160604 | 50-320 0 | LACEY, W. B. | 8012300474* | | LECKIE, D. A. | 8012300040* | 50-445 M |
| KNAPP, P.J. | 8012070258* | 70-820 | LACEY, W. B. | 8012300481* | | LEDERBERO, J. | 8012100263 | PR |
| KNAPP, P.J. | 8012170553* | 70-687 | LACEY, W. B. | 8012300484* | | LEE, E. W. K. | 8012040688* | 50-341 Q |
| KNAPP, P. J. | 8012170680* | 50-336 0 | Ladun, R. H. | 8012020205* | 90-29 0 | LEE, J. Y. | 8012070447 | 50-10 P |
| KNAPP, P. J. | 8012170728* | 50-47 0 | Ladyman, G. H. | 8012080462 | PR | LEE, O. R. | 8012010436# | 50-247 Q |
| KNEALE, Q. | 8012040348* | 10CFR | Lagiewski, J. 8. | 8012230366* | 50-317 8 | LEE, S. L. | 8012240307 | NUREO |
| KNICELEY, J. R. | 8012150281* | 50-266 0 | Lagiewski, J. 8. | 8012020619* | 50-317 8 | LEHAG, N. | 8012230465# | FOIA |
| KNICELEY, J. R | 8012240061* | 50-305 0 | Lagiewski, J. 8. | 8012100565* | 50-317 8 | LEHMAN, R. F. | 8012300075# | 50-387 Q |
| KNIGHT, Q. J. | 8012030193* | FOIA | Lagienski, J. 8. | 8012010369* | 50-317 8 | LEHMAN, R. F. | 8012300075# | 50-387 0 |
| KNIGHTON, Q. U. | 8012230256 | 50-10 P | Lagienski, J. 8. | 8012100557* | 50-318 8 | LEHMAN, R. F. | 8012220432# | 50-387 0 |
| KNIGHT, C. F. | 8012290336 | 50-155 0 | Lagienski, J. 8. | 8012220414* | 50-318 8 | LEHR, J. C. | 8012170443# | 50-387 0 |
| KNGP, R. C. | 8011250278* | 50-461 G | Lainab, G. C. | 8012110023 | 50-237 P | LEIBY, A. C. | 8011180561 | 50-285 P |
| KNGP, R. C. | 8012120300* | 50-483 G | Lainab, G. C. | 8012110387 | 50-245 P | LEIBY, A. C. | 8012010277 | 50-244 P |
| KNOP, R. C. | 8012240030* | 50-483 G | Lainab. Q. C. | 8011210443 | 50-250 P | LEIBY, A. C. | 8012070105 | PR |
| KNOTTB, J. B, | 8012020765 | 50-395 H | Lainab. Q. C. | 8012080627 | 50-155 F | LEITHAUSER, J. | 8012110001 | 50-155 Q |
| KNOTTB, J. B. | 8012170672 | 50-445 M | Lainab. Q. C. | 8012120521 | 50-336 P | LEITHAUSER, J. A. | 8012300247 | 50-156 Q |
| KNOTTB, J. B. | 8012170672 | 50-445 M | Lainab. Q. C. | 8012240067 | 50-245 P | LEITHAUSER, J. | 8012300417 | 50-155 Q |
| KNOTTB, J. B. | 8012110659 | 50-395 Q | Lainab. Q. C. | 8012190657 | 50-237 P | LEMPOES, T. E. | 80123040592* | 50-220 Q |
| KNOTTB, J. B. KNOTTB, J. B. KNUTH, D. F. KOGEN, B KOGH, W. H. | 8012110617 8012160336 8012110702* 8012160258* E012170186* | 50-395 | Laird, 8. u. Lamagna, F. Laman, J. T. Lamastra, M. A. Lamb, H. R. | 8012040388 8012040184 8011200186 7711150300* 8011180561 | 50-287 H 50-245 F 40-8714 F01A 50-285 P | Lempoes, T. E. Lempoes, T. E. Lempoes, T. E. Lempoes, T. E. Lempoes, T. E. | 8012040577 8012120497 8012090015 8012100477 8012100472 | 50-220 Q 50-220 Q 50-220 Q 50-220 B |
| КОСН; L. J. | 8012040247* | 50-461 G | LAMB, H. R. | 80120102Y7 | 50-244 P | LEMPQEB, T. E. | 8012160474 | 50-220 R |
| КОСН; L. J. | 8012220134 | 50-461 G | LAMB, H. R. | 8012070105 | PR | LEMPQEB, T. E. | 8012190514 | 50-220 P |
| КОСН; L. J. | 8012220162 | 50-461 G | LAMBERT, J. P. | 8012080262 | PR | LEMPQEB, T. E. | 8012190475 | 50-220 P |
| КОСН; И. Н. | 8012170134* | GAT99 | LAMBERT, B. | 8012100006 | PR | LENAHAN, J. J. | 8012180223* | 50-259 Q |
| КОСН; L. J. | 8012310315 | 50-461 K | LAMBERT, Q. | 8012170159 | PR | LENAHAN, E. | 8012290023 | 50-247 H |
| KOCH, L. J. | 8012310317* | 50-461 K | LAMBERT, J. B. LAMBOOY, J. P. LAMBREMONT, E. N. LAMKIN, D. E. LAMONT, L. | 8012170626 | 50-289 H | LEONARD, C. | 8012160606 | PR |
| KOESTEL, A. | 8012230099 | NUREO | | 8012080312 | PR | LEPERVANCHE-VAL | 8012040349* | PR |
| KOESTER, O. L. | 8012020083 | 50-482 C | | 8012110288 | PR | LEPKONEKI, G. | 8012110833 | PR |
| KOESTER, O. L. | 8012090289 | 50-482 C | | 8012230099 | NUREO | LEPKONEKI, M. | 8012110844 | PR |
| KOHN, H. I. | 8012230149* | CONTRACT | | 8012150192 | 30-271 H | LEPPKE, D. 14. | 8012080110 | PR |
| KOLTAY, P. KOLTAY, P. B. KONKLIN, J. E. KODRBE, B. H. KOPPELL, O. | 8012300169* 8012300185* 8012240172* 8012030673* 8012050388 | 50-287 Q 50-272 Q 50-440 Q FOIA U | LANDRMAN, R. B. LANDRMAN, R. B. LANE, J. R. LANE, M. LANG, E. A. | 8012110049# 8012020383# 8011070245 8012080758 8012010055 | 50-440 & 40-2257 40-4492 PR PROJ | LEPPKE, D. M. LERNER, W. G. LEBNIAN, L. M. LEBBOR, L. G. LEBBOR, L. G. | 8012070054 8012310242* 8012020248* 8012030704 8012150079 | PR 50-445 H TOPREP 50-298 B 50-298 R |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEOURY | AUTHOR | ACCESSION NUMBER | BUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY |
|---|---|--|--|---|---|--|---|---|
| LEBSY, R. P. | 8012230007 | 50-443 G | LINEHAN, J. J. | 8012160171 | 40-8084 | MACARTHUR, T. C. | 8012310047# | 50-338 0 |
| LEVENSON, M. | 8012020379# | 10CFR | LINEHAN, J. J. | 8012160126 | 40-1162 | MACARTHUR, T. C. | 8012190582# | 50-327 0 |
| LEVENSON, M. | 8012050440 | NUREG | LINTMER, A. R. | 8012030317* | FOIA | MACARTHUR, T. C. | 8012190192# | 27-47 |
| LEVENODUD, M. | 8012150157 | 50-271 H | LINTMN, O. W. | 8012110262 | PR | MACARTHUR, T. C. | 8012190409# | XPORTLIC |
| LEVEN, P. | 8012310260 | 50-271 H | LISK, R. D. | 8012120151 | PR | MACDONALD, C. E. | 8004100228 | 71-9073 |
| LEVIN, K. M, | 8012300040* | 50-445 M | LITTLE, H. S. | 8012110703* | 50-331 Q | MAGDONALD, C. E. | 8004100230* | 71-9073 |
| LEVINE, H. R. | 8012170085 | PR | LITTLEJDHN, J. D. | 8012110232 | 50-409 H | MAGDONALD, C. E. | 8012010247* | 71-9073 |
| LEVINE, J. M. | 8012090364* | 50-213 E | LITTLE, B. H. | 8012110444* | 50-341 Q | MAGDONALD, C. E. | 8012010223* | 71-9073 |
| LEVIN, H. A. | 8012290645* | 50-407 T | LITTLE, H. S. | 8012020793* | 50-263 Q | MAGDONALD, C. E. | 8012010208* | 71-9073 |
| LEWELLEN, W. S. | 8012230522 | NUREO | LITTLE, B. H. | 8012310511* | 50-341 Q | MAGDONALD, C. E. | 8012010137* | 71-9073 |
| LEWIS, R. C. | 8012180201* | 50-338 G | LITTLE: M. | 8012100420 | CONTRACT | MACDONALD, C. E. | 8012010028 | 71-5088 |
| LEWIS, R. C. | 8012190499* | 50-259 G | LITTLE: W. S. | 8012310447* | 50-331 G | MACDONALD, C. E. | 8012010032 | 71-6058 |
| LEWIS, R. C. | 8012180195* | 50-338 G | LITTLE: M. | 8012100183 | CONTRACT | MACDONALD, C. E. | 8012020234 | 71-5768 |
| LEWIS, R. C. | 8012110246* | 50-416 G | LITTLE: D. S. | 8012240444 | 50-522 O | MACDONALD, C. E. | 8012080626 | 71-5957 |
| LEWIS, R. C. | 8012020433* | 50-390 G | LIVERMORE: H. H. | 8011250278* | 50-461 G | MACDONALD, C. E. | 8012080631* | 71-5957 |
| Lewes, R. C. | 8012180145* | 50-338 Q | LLOYD, A. B. | 8012020268* | TOPREP | MACDONALD, C. E. | 8012080028 | 71-399 |
| Lewes, R. C. | 8012020346* | 50-259 Q | LOCASCIO, A. T. | 8012100406 | PT21 | MACDONALD, C. E. | 8012080034* | 71-399 |
| Lewes, R. C. | 8012090222 | 50-261 Q | LOCHSTET, H. A. | 8012120261 | PR | MACDONALD, C. E. | 8012110432 | 71-6698 |
| Lewes, R. C. | 8012090505 | 50-416 Q | LODDER, H. | 8012230246* | OA999 | MACDONALD, C. E. | 8012110442 | 71-9086 |
| Lewes, R. C. | 8012090216 | 50-395 Q | LOFY, R. | 8012310602* | CONTRACT | MACDONALD, C. E. | 8012230217 | 71-6459 |
| Lewis, R. C. | 8012110633 | 50-395 Q | LOOAN, A. | 8012150023* | 50-320 H | MACDONALD, C. E. | 8012230221* | 71~6459 |
| Lewis, R. C. | 8012160039 | 50-302 Q | LOOUE, R. H. | 8012300549 | 50-352 A | MACDONALD, C. E. | 8012310430 | 71~6722 |
| Lewis, R. I. | 8012010469 | PR | LOHAUB, P. | 8012220219* | FOIA | MACDONALD, C. E. | 8012310437* | 71~6722 |
| Lewis, R. C. | 8012110614 | 50-340 Q | LOIS, L. | 8012090198 | TOPREP | MACDONALD, C. E. | 8012160278 | 71~9010 |
| Lewis, W. H. | 8012090004 | 50-201 Q | LONERGAN, G. T. | 8012100211 | PR | MACDONALD, C. E. | 8012230272 | 71~6744 |
| LEWIS, R. C. | 801219032 | 50-261 Q | LONGAKER, J. B. | 8012170683* | 40-7102 | MACDONALD, C. E. | 8012230273* | 71-6744 |
| LEWIB, R. C. | 8012190383 | 50-281 Q | LODMIS, J. S. | 8012240284 | REGOD | MACDONALD, C. E. | 8012230274 | 71-6979 |
| LEWIB, R. C. | 8012190708 | 50-348 Q | LORCH, L. B. | 8012120357 | PR | MACDONALD, C. E. | 8012230276* | 71-6975 |
| LEWIB, R. C. | 8012020339 | 50-257 Q | LORID, P. H. | 8012020513 | 70-882 | MACDONALD, C. E. | 8012310215 | 71-95 |
| LEWIB, R. C. | 8012020408 | 50-390 Q | LORID, P. K. | 8012240178* | 70-882 | MACDONALD, G. E. | 8012310218* | 71-95 |
| LEWIS.R. C. LEWIS.R. C. LEWIS.R. C. LEWIS.R. C. LEWIS.B. H. | 6012310239 6012110228 6012160140 6012160168 6012300013 | 30-261 Q 50-416 Q 50-338 Q 50-338 Q 50-445 M | LOTOCKI.D. LOUDERBACK,T.E. LOVAAG,A. LOVENDALE,P.C. LOVENDALE,P.C. | 8012270023 8012180388 8012120147 8012170480* 8012230173* | 50-247 H 40-8714 PR 50-336 Q 50-373 Q | MACDONALD, C. E. | 8012170171 8012160575 8012160576 8012180405 8012170186 | 71-6698 71-6400 71-9136 71-9145 71-9070 |
| LEWIS, R. C. LEWIS, M. I. LEWIS, S. H. LEWIS, R. K. LEWIS, R. C. | 8012100497 8012090018* 8012240009 8012290175 8012190466 | 50-259 B NUREO 50-320 O 50-320 O 50-259 Q | LOWENSTEIN, R. LOWENSTEIN, R. LOWENSTEIN, R. LOWENSTEIN, R. LOWENSTEIN, R. | 8012030153* 8012030043* 8012030377* 8012030385* 8012030040* | 27-10 27-10 FOIA FOIA 27-10 | MACDONALD, C. E. | 0012170191* 8012220360 8012220366* 8012240161 8012240165* | 71-9070 71-6601 71-6601 71-401 71-401 |
| LEWIS, B. H. LEWIS, B. H. LEWIS, B. H. LEWIS, S. H. LIBERMAN, J. B. | 8012230036 8012300189 8012290444 8012290519 8012160604 | 50-320 0 50-320 0 50-320 0 50-320 0 | LOHENBTEIN, R. LOHENBTEIN, R. LOHENBTEIN, R. LOHENBTEIN, R. LOHENBTEIN, R. | 8012030332* 8012030554 8012030518* 8012030578* 8012080531 | 27-10 27-10 27-10 FOIA PR | MAGDONALD, C. E. | 8012240148 8012240170* 8012240173 8012240175* 80122300257 | 71-354 71-354 71-24 71-24 71-9144 |
| LIBERMAN, J. B. | B012160604 | 50-320 Q | LOVERRE, R. W. | 8012240008 | 50-498 | MACDONALD, C. E. | 8012300260 | 71-102 |
| LIBRIZZI, F. P. | B012020645 | 50-272 8 | LOZADO, B. E. | 8012290128 | | MACDONALD, C. E. | 8012300262* | 71-102 |
| LIBRIZZI, F. P. | B012020485 | 50-272 8 | LUBENAU, J. O. | 8012010451 | | MACHON, R. D. | 8012020599 | 50-293 8 |
| LIBRIZZI, F. P. | B012020655 | 50-272 8 | LUBENAU, J. O. | 8012120243* | | MACHON, R. D. | 8012010341 | 50-293 8 |
| LIBRIZZI, F. P. | B012020540 | 50-272 8 | LUBENAU, J. O, | 8012160620 | | MACHON, R. D. | 8012020615 | 50-293 8 |
| LIBRIZZI.F. P. | 8012050082 | 50-272 8 | LUBENAU, J. B. | 0012170562 | I&E | MACHON, R. D. | 8012080407 | 50-293 8 |
| LIBRIZZI.F. P. | 8012110403 | 50-272 8 | LUGENAU, J. D. | 8012220417 | State Prog | MACHON, R. D. | 8012100373 | 50-293 8 |
| LIBRIZZI.F. P. | 8012150121 | 50-272 8 | LUCEY, J. H. | 8012020210 | PR | MACHON, R. D. | 8012160416 | 50-293 R |
| LICCIARDD, R. B. | 8012080398 | 50-305 0 | LUEDECKE, A. R. | 8012030653* | FOIA | MACHON, R. D. | 8012150091 | 50-293 B |
| LICHTENBERGER | 8012180493 | 70-1100 | LUEDECKE, A. R. | 8012030637* | FOIA | MACHON, R. D. | 8012220442 | 50-293 B |
| Liederman, J. Lieurange, M. T Lioiehbki, J. B. Lindenblad, O. E. Linder, F. | 8012270104 8012010272 8012020400* 8012080308 8012020273 | 30-255 G 40-8743 50-318 8 PR 50-409 P | LUEDKE, D. LUKENBJ H. R. LUKZ, F. J. LUKZ, F. J. LUKZ, F. J. | 8012120044 8012170432 8012160018* 8012170217* 8012240044* | PR NUREO CONTRACT CONTRACT CONTRACT | MACHON, R. D. MACHON, R. D. MACHON, R. D. MACHON, R. D. MACINTYRE, W. J. | 8012290951 8012290172 8012300401 8012270331 8012120288 | 50-293 B 50-293 R 50-293 B 50-293 B |
| LINDER, F. | 8012070373 | 50-409 P | LUNDVALL, A. E. | 8012010348 | 50-317 G | MACKENZIE, R. D, | 8012100203 | PR |
| LINDER, F. | 8012010310 | 50-409 P | LUNDVALL, A. E. | 8012030458 | 50-317 G | MACNULTY, J. J. | 8012040371 | 50-247 H |
| LINDER, F. | 8012020305 | 50-409 B | LUNDVALL, A. E. | 8012020425 | 50-317 P | MACY, J. H. | 8012050002* | ORG |
| LINDER, F. | 8012020453 | 50-409 S | LUNDVALL, A. E. | 8012020429 | 50-317 P | MACY, J. H. | 8012230216* | COMMISSION |
| LINDER, F. | 8012220688 | 50-409 Q | LUNDVALL, A. E. | 8012020432 | 50-317 P | MADDEN, W. | 8012220062* | 50-317 Q |
| LINDER, F. | 8012020100 | 50-409 P | LUNDVALL, A. E. | 8012020438 | 50-317 P | MADDOX, B. Q. | 8012150170# | 50-327 8 |
| LINDER, F. | 8012020315 | 50-409 P | LUNDVALL, A. E. | 8012050454 | 50-317 P | MADDOX, B. Q. | 8012160454# | 50-327 8 |
| LINDER, F. | 8012080489 | 50-409 P | LUNDVALL, A. E. | 8012050277 | 50-318 P | MADDOX, B. Q. | 8012170605# | 50-327 8 |
| LINDER, F. | 8012050502 | 50-409 8 | LUNDVALL, A. E. | 8012120479 | 50-318 Q | MADEDA, T. J. | 8012010586# | 50-282 0 |
| LINDER, F. | 8012100529 | 50-409 8 | LUNDVALL, A. E. | 8012170295 | 50-317 P | MADEDA, T. J. | 8012180365# | 70-2609 |
| LINDER, F. | 8012100530 | 50-409 8 | LUNDVALL, A. E. | 8012190117 | 50-317 P | MADEIRA, R. L. MADISON, A. L. MADSEN, Q. L. MADSEN, Q. L. MADSEN, Q. L. | 8012170620 | 50-289 H |
| LINDER, F. | 8012070204 | 50-409 8 | LUNDVALL, A. E. | 8012220375 | 50-317 P | | 8012020793# | 50-263 Q |
| LINDER, F. | 8012150244 | 50-409 8 | LUNDVALL, A. E. | 8012230481 | 50-317 P | | 8012020222 | 50-382 Q |
| LINDER, F. | 8012070344 | 50-409 9 | LURIE, M. A. | 8012190432 | NUREO | | 8012120305 | 50-313 Q |
| LINDER, F. | 8012140350 | 50-409 P | LUTMAN, M. | 8012120299 | PR | | 8012020190 | 50-285 Q |
| Linder, F. | 8012120225 | 50-409 P | LUTZ, H. J. | 8012110317 | PR | MADSEN, O. L. MADSEN, O. L. MADSEN, Q. L. MADSEN, Q. L. MADSEN, Q. L. | 8012080829 | 50-313 Q |
| Linder, F. | 8012160280 | 50-409 R | LYNCH, W. A. | 8012030550# | FOIA | | 8012120567 | 50-285 Q |
| Linder, F. | 8012160442 | 50-409 S | LYNCH, C. A. | 8012030536# | FOIA | | 8012120224 | 50-313 Q |
| Linder, F. | 8012230378 | 50-409 B | LYNCH, O. L. | 8012230374 | HUREO | | 8012010417 | 50-247 Q |
| Linehan, J. V. | 8012230003 | 40-2259 | LYNG, T. | 8012300172 | 50-289 H | | 8012240043 | 50-285 Q |
| Linehan, J. J. | 8012020007 | 40-8584 | LYON, O. H. MACARTHUR, T. C. | 8012110453 | NUREO | MADSEN, O. L. | 8012240323 | 50-313 Q |
| Linehan, J. J. | 8012140184 | 40-8084 | | 8012190595* | 27-47 | MADSEN, O. L. | 8012240033 | 50-313 Q |
| Linehan, J. J. | 8012140171 | 40-8727 | | 8012190235* | 27-47 | MADSEN, Q. L. | 8012290020 | 50-368 B |
| Linehan, J. J. | 8012140167 | 40-8434 | | 8012090147* | 50-339 G | MADSEN, Q. L. | 8012290028 | 50-368 B |
| Linehan, J. J. | 8012140179 | 40-6622 | | 8012100286* | 70-820 | MAGEE, A. A. | 80123900500 | 50-466 Q |

| AUTHOR | ACCESBION NUMBER | SUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|--|--|---|---|--|---|---|--|
| MAHAN, R. R. MAIER, J. E. MAIER, J. E. MAIER, J. E. MAIER, J. E. | 8012150161 8012090043 8012010299* 8012160429 8012160240 | 50-395 G 50-244 Q 50-244 P 50-244 P 50-244 P | MARTIN, W. C. MARTIN, R. D. MARTIN, W. J. MARTIN, W. J. MARTIN, W. J. | B012220035 B012110620# B012170340 B012170344 B012170346 | 50-317 Q 50-348 Q 50-293 Q 50-317 Q 50-286 Q | MASON, J. R. MASON, J. R. MASON, J. R. MASON, J. R. MASON, J. R. MASON, B. F. | 8012030534* 8012030539* 8012030525* 8012030415* 8012080014 | FOIA FOIA FOIA FOIA NUREG |
| MAIER, J. E. MAIER, J. E. MAIER, J. E. MAIER, J. E. MAIER, J. E. | 8012160540 8012180391 8012220227 8012220329 8012220341 | 50-244 P 50-244 P 50-244 P 50-244 P 50-244 P | MARTIN, W. J. MARTIN, W. J. MARTIN, W. J. MARTIN, W. J. MARTIN, W. J. | 8012170350 8012170353 8012170359 8012170360 8012170362 | 50-277 Q 50-29 Q 50-272 Q 50-213 Q 50-333 Q | MASSE, R. E. MATHEWS, E. H. MATHEWS, E. R. MATHEWS, E. R. MATHEWS, E. R. | 8012110124* 8012040302* 8012120407* 9012020372 8012020428 | 50-315 0 50-305 0 50-305 0 90-305 P 50-305 8 |
| MAIER, J. E. MAIER, J. E. MALEK, F. A. MALMROS, M. H. MANGUEO, F. | 8012300393 8012300522 8012170320 8012310538* 8011210592 | 50-244 P 50-244 S PR 50-344 Q NUREO | MARTIN, W. J. MARTIN, W. J. MARTIN, H. J. MARTIN, W. J. MARTIN, W. J. | 6012170365 8012170367 6012170372 6012170373 8012170377 | 50-3 0 50-219 0 50-309 0 50-220 0 50-245 0 | MATHENS, E. R. MATHENS, E. R. MATHENS, E. R. MATHENS, E. R. MATHENS, E. R. | 80121000AB 8012100324 8012310421 8012150264 8012160316 | 50~305 F 50~305 R 50~305 Q 50~305 P |
| MANDIL, I. H. MANDLER, J. H. MANNING, R. K. MANNING, M. H. MANNING, M. H. | 8012080505* 8012110551 8012110328* 8012120217 8012120350 | CONTRACT RES COMMISSION NUREO NUREO | MARTIN, W. J. MARTIN, W. J. MARTIN, W. J. MARTIN, M. J. MARTINI, D. | 8012190379 8012190362 8012190384 8012190386 8011210432 | 50-334 0 50-244 0 50-271 0 50-287 0 50-361 8 | MATHENS, E. R. MATHENS E. R. MATHENS, E. R. MATHENS, E. R. MATHENS, E. R. | 8012170576 8012230385 8012300254 8012300416 8012300413 | 50-305 8 50-305 8 50-305 F 50-305 P 50-305 P |
| MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M. | 8012010307 8012010325 8012010371 8012010384 8012010349 | 50-346 8 50-321 8 50-346 8 50-344 8 50-366 8 | MARTIN, L. C. MARTIN, J. B. MARTIN, D. E. MARTIN, T. J. MARTIN, T. J. | 8012110040 8012170246 8012240146 8012310634 8012310636 | CONTRACT 40-8745 40-8745 50-354 G 50-354 G | MATHEUB, E. R. MATHEUB, E. R. MATLOCK, R. G. MATLOCK, R. G. MATLOCK, R. G. | 8012300474 8012300559 8012030722 8012030728 8012170357 | 50-305 P 50-305 P 50-397 Q 50-397 B 50-397 0 |
| MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M. | 8012010377 8012020500 8012020511 8012070371 8012070379 | 50-321 8 50-366 8 50-366 8 50-366 8 50-321 8 | MARTIN, W. O. MARTIN, W. O. MARTIN, L. C. MARTIN, L. C. MARTIN, L. T. | 8012220079 8012240176 8012110525 8012080636 8012180353* | 50-289 Q 70-882 CONTRACT CONTRACT 50-247 Q | MATLOCK, R. O. MATSON, V. MATSON, V. MATSON, V. MATSON, V. | 0012230502 8012020472 8012020322 8012300328 8012020331* | 50-397 8 XPORTLIC XPORTLIC XPORTLIC XPORTLIC |
| MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M. | 8012270240 8012130184 8012130189 8012170629 8012230292 | 50-321 B 50-366 B 50-366 B 50-366 B 50-321 R | MARTINGON, Z.R. MARTIN, L.C. MARTIN, L.C, MARTIN, L.C, MARTIN, W. MARTIN, J.B. | 8012170044 8012070554 8012070570 8012100164 8012230224* | REB CONTRACT CONTRACT 50-336 B WABTE HOT | MATEON, V. MATEON, V. MATEON, V. MATEON, V. MATTIA, M. J. | 8012110169 8012220473 8012270634 8012310069 8012300221* | XPORTLIC XPORTLIC XPORTLIC XPORTLIC CONTRACT |
| MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M. | 8012230298 8012230342 8012240244 8012240280 8012240297 | 50-366 R 50-366 B 50-321 B 50-366 B | MARTIN, R.E. MARTINEZ, G. MARTIN, T. T. MARTIN, R. E. MARTIN, T. J. | 8012100074 8012160350 8012180357* 8012240101 8012230492 | 50~368 P PR 50-247 Q 50-368 F 50-354 8 | MATTIA, J. C. MATTIA, J. C. MATTIA, M. J. MATTIA, M. J. MATTIA, M. J. | 6012110079* 6012190511* 6012040377* 6012120082* 6012230149* | 50-412 0 50-423 0 CONTRACT CONTRACT |
| MANRY, M. MANRY, M. MANRY, M. MANBER, H. C. MANBER, W. C. | 8012270248 8012270258 8012270325 8012010547 8012100676* | 50-344 8 50-344 8 50-321 8 70-143 70-143 | MARTORE, J. A. MARTORE, J. A. MASON, J. R. MASON, J. R. MASON, J. R. | 8012300332 8012310177 8012030451* 8012030223* 8012030324* | 50-416 A NUREO FOIA 27-10 FOIA | MATTIA: M. J. MATTIA: M. J. MATTIA: M. J. MATTIA: M. J. MATTIA: M. J. | 8012230154* 8012230173* 8012110681* 8012110382* 8012110527* | CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT |
| MANSER, W. C. MAPLES, A. MARCH, R. N. MARCUCCI, D. R. MARCUCCI, D. R. | 8012160269 8012310263 8012090285 8012020758 8012290206 | 70-143 50-271 H 50-289 H 70-2909 70-2909 | MABON, J. R. MABON, J. R. MABON, J. R. MABON, J. R. MASON, J. R. | 8012030527* 8012030197* 8012030213* 8012030504* 8012030104* | FOIA 27-10 27-10 FOIA 27-10 | MATTIA, M. J. MATTIA, M. J. MATTIA, M. J. MATTIA, M. J. MATTIA, M. J. | 8012030641* 8012120432 8012070567* 8012070573* 8012100022* | CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT |
| MARCUGGI.D.R. MARGUS.A.A. MARK.R.H. MARKET.J.A. MARKL.R.L. | 8012270011 8012170537 8012040237* 8012270175* 8012220003* | 70-2909 NUREO TOPREP 50-289 H CONTRACT | MASON, J. R. MASON, J. R. MASON, J. R. MASON, J. R. MASON, J. R. | 8012030468* 8012030586* 8012030480* 8012030171* 8012030467* | FOIA FOIA FOIA FOIA | MATTINDE, J. J. MATTIA: M. J. MATTISON: O. L. MATTINDE: J. J. MATTINDE: J. J. MATTINDE: J. J. | 8012070370 8012230545* 8012270534 6012160507 8012170458 | 50-312 S CONTRACT XPORTLIC 50-312 P 50-312 P |
| MARKL, R. L. MAROTTA, G. R. MARRACK, D. MARRIOTT MARRICK, D. | 8012220005* 8012100646 8012270271 8012300486* 8012270627 | CONTRACT 50-320 P 50-466 Q TOPREP 50-466 O | MABON; J. A. MABON; J. R. MABON; J. R. MABON; J. R. MABON; J. R. | 8012030474* 8012030454* 8012030101* 8012030331* 8012030533* | FOIA FOIA FOIA FOIA | MATTIKOE, J. MATTIKOE, J. J. MATTIKOE, J. J. MATTIKOE, J. J. MATTIKOE, J. J. | 8012230375 8012170309 8012170339 8012180304 8012220309 | 50-312 P 50-312 F 50-312 P 50-312 P 50-312 P |
| MARSHALL, C. H. MARSHALL, W. H. MARTIN, R. E. MARTIN, W. G. MARTIN, W. G. | 8012100243 8012020449 8012010593 8012070545* 8012220040* | PR 50-329 | MABON, J. R. MABON, J. R. MABON, J. R. MABON, J. R. MABON, J. R. | 8012030541* 8012030492* 8012030212* 8012030667* 8012030591* | FOIA FOIA FOIA FOIA | MATTIA:M.J. MATTIMDE,J.J, MATTIMGE:J.J. MAURA:F. MAURIN:L.V. | 8012300212* 8012270301 8012300617 8012020780* 8012220674 | CONTRACT 50-312 P 50-312 P 50-373 C 50-382 C |
| MARTIN, H. G. MARTIN, W. Q. MARTIN, T. T. MARTIN, T. T. MARTIN, H. G. | 8012100241* 8012070083* 8012070084* 8012240277* 8012020197 | 70-1143 70-135 50-27 Q 50-27 Q 50-29 Q | MAGON, J. R. MAGON, J. R. MAGON, J. R. MAGON, J. R. MAGON, J. R. | 8012030064* 8012030049* 8012030515* 8012030478* 8012030503* | FOIA 27-10 FOIA 27-10 27-10 | MAUR IN, L. V. MAUR IN, L. V. MAXHELL, G. F. MAXHELL, G. F. MAXHELL, G. F. | 8012320649 8012180386 8012180409* 8012110684* 8012170395* | 50-382 0 50-382 / 50-400 0 50-413 0 50-400 0 |
| MARTIN, U. O. MARTIN, W. Q. MARTIN, W. O. MARTIN, W. O. MARTIN, W. Q. MARTIN, W. Q. | 8012110635# 8012110152 8012110163 8012110428 8012220082# | 70-1424 70-1143 70-33 70-1424 50-287 Q | MASON; J. R. MASON; J. R. MASON; J. R. MASON; J. R. MASON; J. R. | 8012030544* 8012030452* 801203041B* 8012030292* 8012030307* | FOIA FOIA FOIA FOIA | MAY, E. MAY, E. L. MAY, E. L. MAY, J. MAYER, L. O. | 8012050012 80120503784 8012300600# 8012050012 80120803604 | PR 50-27 E 50-27 E PR 50-263 F |
| MARTIN, W. O. MARTIN, W. G. MARTIN, L. E. MARTIN, H. O. MARTIN, W. G. | 8012230054 8012300034 8012020749* 8012100227 8012220009 | 70-135 70-820 50-445 Q 70-1143 70-820 | Magon, J. R. Magon, J. R. Magon, J. R. Magon, J. R. Magon, J. R. | 8012030210* 8012030147* 8012030142* 8012030133* 8012030100* | 27-10 FOIA FOIA 27-10 FOIA | MAYER, C. H. MAYER, L. O. MAYER, L. O. MAYER, L. O. MAYER, L. O. | 8012020647 8012010070 8012010351 8012010477 8012020332 | 70-1739 50-282 F 50-263 F 50-202 E 50-282 F |
| HARTIN, W. G. MARTIN, H. G. MARTIN, W. G. MARTIN, W. G. MARTIN, H. G. | 8012220013 8012220022 8012190694 8012220065 8012090067 | 70-1149 70-135 70-371 50-220 70-135 | Mason, J. R. Mason, J. R. Mason, J. R. Mason, J. R. Mason, J. R. | 8012030076* 8012030015* 8012030453* 8012030234* 8012030172* | FOIA FOIA FOIA 27-10 27-10 | MAYER, L. O. MAYER, L. O. MAYER, L. O. MAYER, L. O. MAYER, L. O. | 8012080319 8012080323* 8012090374 8012090394 8012150183 | 20-565 20-565 20-565 20-565 20-565 20-565 |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEOORY | AUTHOR | ACCEBBION NUMBER | SUBJECT CATEGORY |
|---|---|--|---|---|--|---|--|---|
| MAYER, L. O. | 8012170640 | 50-282 8 | MCGARRY, J. H. | 8012230014 | 50-347 0 | MCPHILLIPB, J, L, | 8012290041 | 70-2909 |
| MAYER, L. O. | 8012150048 | 50-243 R | MCGARRY, J. H. | 8012230014 | 50-347 0 | MCQUILKIN, J, H, | 8012030086* | FDIA |
| MAYER, L. O. | 8012150191 | 50-282 8 | MCGARRY, J. H. | 8012270379 | 70-2423 | MCQUILKIN, J, H, | 8012030107* | FDIA |
| MAYER, L. O. | 8012160453 | 50-282 R | MCGARRY, J. M. | 8012270379 | 70-2423 | MCBHANE, H, J, | 8012030488* | PROJ |
| MAYER, L. O. | 8012230285 | 50-263 P | MCGARRY, J. M. | 8012300066 | 50-349 0 | MCTIERNAN, T, J, | 8012080183* | FDIA |
| MAYER, L. D. | 8012230287* | 50-263 P | McGarry, J. M. | 8012300066 | 50-349 0 | MECAY, W. L. MEDROW, L. K. MEEHAN, R. MEGNEMIB, T. L. MEGREMIB, T. L. | 8012120335 | PR |
| MAYER, L. D. | 8012300265 | 50-282 P | McGaughy, R. H. | 8012080060* | 50-443 0 | | 8012040147 | CONTRACT |
| MAYER, L. D. | 8012240270 | 50-282 Q | McGaughy, R. H. | 8012080406* | 50-397 0 | | 8012050151* | 50-70 P |
| MAYER, L. D. | 8012300302 | 50-282 P | McGaughy, R. H. | 8012090242* | 50-443 0 | | 8012170193 | PR |
| MAYER, L. D. | 8012300305* | 50-282 P | McGaughy, R. H. | 8012080378* | 50-387 0 | | 8012170234 | PR |
| MAYER, L. O | 8012300578 | 50-263 P | MCGAUGHY, J. P. | 8012240233* | 50-322 Q | Mellein, M. | 8012100168 | PR |
| MAYER, L. O. | 8012300605# | 50-263 P | | 8012020491 | 70-2936 | Mellon, K. | 8012310314 | 50-361 A |
| MCALPINE, E. J. | 8012180482# | 70-1113 | | 8012030384* | 70-2936 | Menard, H. H. | 8012010276 | 50-361 A |
| MCAVOY, J. F. | 8012050075 | PR | | 8012110237* | 50-416 Q | Mendenhall, E. E. | 8012090452* | 50-265 B |
| MCBREARTY, R. A. | 8012100102# | 50-334 Q | | 8012180103* | 50-416 Q | Mendez, J. A. | 8012270254 | 50-361 Q |
| HCBREARTY, R. A. | 8012240233* | 50-322 0 | MCGAUGHY, J. P. | 8011280067* | 50-416 K | Mendez, J. A. | 8012270254 | 50-361 0 |
| MCBREARTY, R. | 6012110607* | 50-387 0 | | 8012080606* | 50-416 F | Mentzer, M. | 8012160593 | PR |
| MCBREARTY, R. A. | 6012190560* | 50-387 0 | | 8012080721* | 50-416 F | Meringer, J. H. | 8012240352 | XPORTLIC |
| MCBREARTY, R. A. | 6012180353* | 50-247 0 | | 8012090568 | 50-416 B | Merrill, M. H. | 8012030199* | FOIA |
| MCBRIDE, J. A. | 6012030361* | 27-39 | | 8012100541 | 50-416 8 | Merrill, M. H. | 8012030833* | 27-10 |
| MCBRIDE, J. A. | 8012030381* | 27-39 | MCGAUGHY, J. P. | 8012150011 | 50-416 B | MERRILL, J. A. | 8012230323 | NUREO |
| | 8012030374* | 27-39 | MCGAUGHY, J. P. | 8012090259 | 50-416 B | MERRILL, D. N. | 8011170378# | 50-443 A |
| | 8012030414* | 27-39 | MCGAUGHY, J. P. | 8012150253 | 50-416 B | MERSCHOFF, E. N. | 8012270259# | REGOD |
| | 8012030428* | 27-39 | MCGAUGHY, J. P. | 8011280064 | 50-416 K | MERSON, B. D. | 8012170626 | 50-317 R |
| | 8012030439* | 27-39 | MCGAUGHY, J. P. | 8012090246 | 50-416 B | MERSON, B. D. | 8012170630# | 50-317 R |
| MCBRIDE, J. A. | 8012030635* | FOIA | MCGAUGHY, J. P. | 8012100543 | 50-416 B | METGALF, M. K. | 8012040418 | 50-209 Q |
| | 8012030639* | FOIA | MCGAUGHY, J. P. | 8012300098 | 50-416 B | MEYER, J. H. | 8012080271 | PR |
| | 8012030644* | FOIA | MCGAUGHY, J. P. | 8012170304 | 50-416 B | MEYLAND, S. | 8012110296 | PR |
| | 8012030224* | 27-39 | MCGAUGHY, J. P. | 8012160277 | 50-416 A | MEYNER, R. B. | 8012030455* | FOIA |
| | 8012030237* | 27-39 | MCGAUGHY, J. P. | 8012170429 | 50-416 B | MIGHAUD, A. A. | 8012030227* | FOIA |
| MCBRIDE, J. A. | 8012030251* | 27-39 | MCGAUGHY, J. P. | 8012160281 | 50-416 8 | MICHAUD, A. A. | 8012030249* | FOIA |
| | 8012030265* | 27-39 | MCGAUGHY, J. P. | 8012190527 | 50-416 8 | MICHAUD, A. A. | 8012030535* | FOIA |
| | 8012030274* | 27-39 | MCGAUGHY, J. P. | 8012230429 | 50-416 8 | MICHAELBON, B. | 8012300696* | 50-466 T |
| | 8012030286* | 27-39 | MCGHRAN, H. J. | 8012030312* | FOIA | MICHELSON, C. | 8008270155* | SECY |
| | 8012030301* | 27-39 | MCGHRAN, H. J. | 8012030304* | FOIA | MICHEL, R. J. | 8012040513 | 70-143 |
| MCBRIDE, J. A. MCBRIDE, J. A. MCBRIDE, J. A. MCBRIDE, H. F. HCCABE, E. C. | 8012030141* | FOIA | MCODHAN, H. J. | 8012030222* | FOIA | MICHELBON, G. | 8012010236 | ORO |
| | 8012030170* | FOIA | MCODHAN, H. J. | 8012030392* | FOIA | MIGHELBON, C. | 8012010359 | MIBC |
| | 8012030155* | FOIA | MCODHAN, H. J. | 8012030400* | FOIA | MIDURA, H. J. | 8012010378 | 50-272 B |
| | 8012290071 | 70-2623 | MCODHAN, H. J. | 801203045* | FOIA | MIDURA, H. J. | 8012010001 | 71-9089 |
| | 8012160113* | 50-277 G | MCODHAN, H. J. | 801203034* | FOIA | MIDURA, H. J. | 8012010002 | 71-9080 |
| MCCABE, E. C. | 8012160105* | 50-277 G | MGGBHAN, H. J. | 8012030288* | FOIA | Midura, H. J. | 8012010004 | 71-6574 |
| MCCABE, E. C. | 8012100102* | 50-334 G | MGGBHAN, H. J. | 801203027* | FOIA | Midura, H. J. | 8012010005 | 71-9086 |
| MCCADE, E. C. | 8012300080* | 50-277 G | MGGBHAN, H. J. | 8012030262* | FOIA | Midura, H. J. | 8012010008 | 71-9079 |
| MCCANN, J. | 8012170712* | 50-333 G | MGGBHAN, H. J. | 8012030267* | FOIA | Midura, H. J. | 8012010470 | 71-9010 |
| MCCARTHY, L. H. | 8012030700 | 50-289 H | MGGBHAN, H. J. | 8012030230* | FOIA | Midura, H. J. | 8012040447 | 50-272 8 |
| MCCARDELL, R, K. | 8012110558 | NUREO | MCGDMAN. H. J. MCGRANERY, J. P. | 8012030244* | FOIA | MIDURA, H, J. | 8012010401 | 50-272 8 |
| MCCARTHY, M. | 8012160006 | FOIA | | 8012100054 | PR | MIDURA, H, J. | 8012160340 | 50-311 R |
| MCCARTER, J. T. | 8012110357 | 50-289 H | | 8012100060* | PR | MIDURA, H, J. | 8012160445 | 50-272 R |
| MCCLUNO, M. W. | 8012030208* | FOIA | | 8012100054 | PR | MIELE, A. | 8012110625 | 50-247 H |
| MCCLUNO, M. W. | 8012030214* | FOIA | | 8012100060* | PR | MIERNICKI, M, J. | 8012020530* | 50-317 8 |
| MCGLUNG, M. H. MCGLUNG, M. H. MCGUNE, J. A. MCGUOL, W. B. | 8012030229* 8012030249* 8012030270* 8012030578* 8012030529* | FOIA FOIA FOIA FOIA | MCGREGOR, L. MCGVIRE, D. R. MCGVIRE, D. R. MCGVIRE, D. R. MCGVIRE, D. R. | 8012020780* 8012120384* 8012120377* 8012180069* 8012160256* | 50-373 0 50-335 0 50-302 0 50-257 0 50-261 0 | MIGEDN.C.J. MIGUIRE,D.R. MILAVICKAB.L.R. MILES.E.B. MILHISER,R.J. | 8012100237 8012160221* 8012070303 8012100202 8012300574 | PR 70-149 50-151 8 CONTRACT 50-382 8 |
| MCCORKLE, O. W. | 8012140439* | 50-219 H | MCGUIRE, D. R. | 8012190409# | XPORTLIC | MILL, H. B. | 8012100103 | PR |
| MCCORKLE, O. W. | 8012140457* | 50-219 H | MCGUIRE, D. | 8012190719# | 50-438 Q | MILLER, G. A. | 8012310224 | NUREO |
| MCCORKLE, O. W. | 8012140462* | 50-219 H | MCGUIRE, D. R. | 8012180383# | 50-391 Q | MILLER, W. O | 8002280187 | TOPREP |
| MCCORKLE, O. W. | 8012040194 | 70-2322 | MCGURREN, H. J. | 8012300044 | 27-39 | MILLER, G. A. | 8012170424 | NUREO |
| MCCORKLE, O. W. | 8012040380 | 70-2322 | MCGURREN, H. J. | 8012290423 | 50-528 Q | MILLER, W. H. | 8012240141* | 70-143 |
| MCCORKLE, O. W. MCCORKLE, O. W. MCCORKLE, O. W. MCCORKLE, O. W. MCCORKLE, O. W. | 8012030793 8012040046 8012040056 8012010222 8012020489 | 70-1426 70-2322 70-1739 70-1252 50-324 P | McGurren, H. J. McGurren, H. J. McIntosh, J. McKay, C. E. | 8012290430* 8012290232 8012300256 8012110413 8012170267 | 50-528 0 50-528 0 27-39 50-289 H PR | MILLER, W. O. MILLER, W. H. MILLER, E. H. MILLER, L. H. MILLER, W. H. | 8012010217 8012020159* 8012110539* 8012040319* 8012110144* | 70-1113 50-367 Q 50-321 Q 50-206 Q 50-261 Q |
| MCCORKLE, O. W. | 8012300293 | 40-8000 | MCKENZIE, L. | 8012310399 | NUREG | MILLER, L. K. MILLER, W. Q. MILLER, W. Q. HILLER, D. E. MILLER, H. J. | 8012040329* | 50-361 G |
| MCCORKLE, O. W. | 8012080637 | 70-2623 | MCKEUMN, L. | 8012100164 | 50-336 8 | | 8012030847 | 50-269 P |
| MCCORMICK, D. | 8012080667 | PR | MCKLVEEN, J. U. | 8012080242 | PR | | 8012120066 | 50-366 P |
| MCCORMACK, U. D. | 8012220600 | NUREQ | MCLAIN, B. | 8012030194# | 27-39 | | 8012220056* | 50-266 G |
| MCCOISTON, R. M. | 8012300711* | 50-466 T | MCLAIN, B. | 8012030120# | 27-39 | | 8012010616 | 40-8697 |
| MCGULLOUGH, E.R. | 8012160085 | 50-10 Q | MCLAIN, 8, | 8012030489# | 27-39 | MILLER, D. E. | 8012230193* | 50-373 G |
| MCGUTCHEGN, J.D. | 8012180221 | PR | MCLAUGHLIN, K, T, | 8012100270 | PR | MILLER, L. C. | 8012300009* | GA999 |
| MCDERMOTT, R.J. | 8012050124 | 71-35 | MCLELLAN, J, A, | 8012140017 | FOIA | HILLER, D. R. | 8012120092 | PR |
| MCDERKOTT, R.J. | 8012050133* | 71-35 | MCLOUGHLIN, M, T, | 8012020404# | 50-293 8 | HILLER, J. R. | 8012010533 | 50-170 P |
| HCDERMOTT, R.J. | 8012100408 | 50-537 B | MCLOUGHLIN, M, T, | 8012010347# | 50-293 8 | MILLER, J. R. | 8012010535* | 50-170 P |
| HCDONALD, J. A. MCDONALD, R. P. MCDONALD, R. P. MCDONALD, C. E. MCDONALD, R. P. | 0012020441* | 50-390 Q | MCLOUGHLIN, M. T. | 8012100576# | 50-293 8 | HILLER, J. R. | 8012010575 | 50-157 P |
| | 8012070075 | PR | MCLOUGHLIN, M. T. | 8012080417# | 50-293 8 | HILLER, J. R. | 8012010579* | 50-157 P |
| | 8012180384* | 50-364 Q | MCLOUGHLIN, M. T. | 8012150072# | 50-293 8 | HILLER, H. J. | 8012170256 | 40-8745 |
| | 8012170178* | 71-6698 | MCLOUGHLIN, M. T. | 8012220457# | 50-293 8 | HILLER, J. R. | 8012010561 | 50-224 P |
| | 8012230372 | NUREG | MCLOUGHLIN, M. T. | 8012230356# | 50-293 8 | HILLER, J. R. | 8012010564* | 50-224 P |
| MCDUFFIE, M. A. MCELROY, W. N. MCFARLAND, G. R. MCFARLAND, C. R. MCFARLAND, J. E. | 8012150073 6012230325 8012150263* 8012150222* 8012150442* | 50-400 R NUREO 50-389 Q 50-413 Q GAPP9 | MCLOUGHLIN, M. T. MCLOUGHLIN, M. T. MCMILLEN, N. H. MCNAHARA, A. E. MGNEILL, H. M. | 8012300407* 8012270345* 8012300250 8012320443* 8012080282* | 50-293 8 50-293 8 50-445 M 50-244 R GA999 | MILLER, J. R. MILLER, K. L. MILLER, T. D. MILLER, H. J. MILLER, J. R. | 8012140629 | 50-73 P PR GA999 40-8771 50-124 P |
| | | | | | | | | |

| AUTHOR | ACCEBBION NUMBER | GUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEOGRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|--|--|--|--|---|--|--|---|--|
| MILLER, J. R. | 8012090031* | 50-124 P | MILLS.L.M. | 8012160149 | 50-7566 R | MIRAGLIA, F. MIRAGLIA, F. J. MIRAGLIA, F. J. MIRAGLIA, F. J. MIRAGLIA, F. J. MIRAGLIA, F. | 8012170780 | 50-275 A |
| MILLER, J. R. | 8012110718 | 50-20 P | MILLS.L.M. | 8012310111 | 50-257 0 | | 8012170394 | 50-311 P |
| MILLER, J. R. | 8012110726* | 50-20 P | MILLS.L.M. | 8012150084 | TOPREP | | 8012170400# | 50-311 P |
| MILLER, H. J. | 8012160175 | 40-8304 | MILLS.L.M. | 8012150290 | 50-327 P | | 8012170409# | 50-311 P |
| MILLER, W. O. | 8012080079 | 50-320 P | MILLS.L.M. | 8012160327 | 50-327 P | | 8012310178 | 50-275 H |
| MILLER, W. D. | 8012080407 | 50-321 P | MILLS, E. M. | 8012170316 | 50-327 P | MIRIAMY, Y.A. | 8012080014 | NUREQ |
| MILLER, W. D. | 8012240137 | 50-267 P | HILLS, E. M. | 8012310104 | 50-327 0 | MITCHELL, R.C. | 8012170654 | 50-289 H |
| MILLER, W. D. | 8012270074 | TOPREP | HILLS, E. M. | 8012160301 | 50-327 A | MITCHELL, D.O. | 8012170519* | 50-289 R |
| MILLER, W. D. | 8012270077 | 50-206 P | HILLS, E. K. | 8012170306 | 50-327 P | MITTL, R.L. | 8012020137 | 50-272 Q |
| MILLER, O. | 8012170117 | PR | HILLS, E. K. | 8012170406 | 50-438 8 | MITTL, R.L. | 8012030620 | 50-311 F |
| MILLER, M. E. MILLER, C. E. MILLER, W. O. MILLER, W. O. MILLER, W. O. | 8012230222 8012300054* 8012240501 8012240504 8012240506 | 50-445 M 50-387 G 70-754 70-1739 70-734 | MILLB, L. K. MILLB, L. K. MILLB, L. K. MILLB, L. K. MILLB, L. K. | B012170515 B012170464 B012170425 B012170460 B012170125 | 50-328 | MITTL: R. L. MITTL: R. L. MITTL: R. L. MITTL: R. L. MITTL: R. L. MITTL: R. L. | 8012030624 8012030630 8012170413 8012240282 8012230259 | 50-311 F 50-311 P 50-272 P 50-354 A 50-311 P |
| MILLER, W. D. MILLER, L. X. MILLER, L. X. MILLER, L. X. MILLER, H. H. | 8012310059 8012310157 8012160343* 8012160450* 8012300505 | 50-213 P 50-407 P 50-311 R 50-272 R 50-483 G | MILLB, L. M. MILLB, L. M. MILLB, L. M. MILLB, L. M. MILLB, L. M. | 8012170503 8012230257 8012230370 8012300496 8012240265 | 50-328 A 50-259 P 50-328 V 50-438 8 50-259 P | MITTL, R. L. MIYABAYASHI, H. MIYABAYASHI, M. MOCZKA, E. J. MODARREB, H. | 8012310284 8012110115 9012220471 8012230489 8012080794 | 50-272 P XPORTLIC XPORTLIC 50-245 9 NUREO |
| MILLER, M. E. | 8012300469 | 50~445 K | MILLS, L. M. | 8012300484 | 50-518 8 | MODENDB: L. | 8012180174* | 50-261 G |
| MILLB, L. M. | 8012190492* | 50~259 G | MILLS, L. M. | 8012300570 | 50-370 8 | MOELLER, D. W. | 8012240034* | COMMISSION |
| MILLB, R. J. | 8012290282* | REGOD | MILLS, L. M. | 8012270238 | 50-327 P | MOFFETT: T. | 8012110167* | COMMISSION |
| MILLB, L. M. | 8012030437 | 50~390 S | MILLS, L. M. | 8012310327 | 50-553 8 | MOG: W. F. | 8012110368* | 71-5796 |
| MILLB, L. M. | 8012040545 | 70~1966 | MILLS, L. M. | 8012300287 | 50-257 P | MOLLOY, K. J. | 8012270452* | 50-320 F |
| MILLS, L. M. | 8012190575* | 50-327 | MILLS, L. H. | 8012310335 | 50-518 8 | MONGERBON, G. | 8012020484 | 50-201 F |
| MILLS, L. M. | 8012080725 | | MILLS, L., K. | 8012270237 | 50-257 P | MONROE, M. | 8012080349 | PR |
| MILLS, L. M. | 8012020412* | | MILLS, L. H. | 8012300652 | 50-518 R | MONROE, J. D. | 8012020289* | 50-395 G |
| MILLS, L. M. | 8012010021 | | MILLS, L. K. | 8012310374 | 50-346 8 | MONTAGUE, P. | 8012220264* | FDIA |
| MILLS, L. M. | 8012020345* | | MILLS, L. M. | 8012310378 | 50-390 8 | MONTEZ, Y. | 8012160378 | PR |
| MILLS, L. M. | 8012070142* | 50-438 Q | MILLS, L. M. | 8012310382 | 50-438 8 | MONTI, W. A. MOODY, D. E. MOODY, D. E. MOODY, D. E. MOODY, D. E. | 8012160476 | 50-3 R |
| MILLS, L. M. | 8012100339 | 40-1341 | MILLS, L. M. | 8012300294 | 50-259 P | | 7704170132 | 50-29 Q |
| MILLS, L. M. | 8012080661 | 40-1341 | MILLS, L. M. | 8012300566 | 50-327 P | | 7705070673 | 50-271 Q |
| MILLS, L. M. | 8012080668* | 50-518 Q | MILLS, L. M. | 8012300648 | 50-259 F | | 7707050153 | 50-29 Q |
| MILLS, L. M. | 8012080773 | 50-259 Q | MILLS, L. M. | 8012310311 | 50-438 8 | | 7707170684 | 50-29 Q |
| MILLS, L. M. | 8012180097* | 50-240 | MILLS, L. H. | 8012310322 | 50-566 8 | MOODY, D. E. | 7908030172 | 50-29 0 |
| MILLS, L. M. | 8012180175* | | MILOB, R. | 8012120241* | 50-409 P | MOODY, D. E. | 7908160563 | 50-29 0 |
| MILLS, L. M. | 8012190472* | | MILOB, R. | 8012020318* | 50-409 P | MOODY, D. E. | 7908070712 | 50-29 0 |
| MILLS, L. M. | 8012080401 | | MILWICZ, R. R. | 8012080255 | PR | MOODY, D. E. | 7908200004 | 50-29 0 |
| MILLS, L. M. | 8012080410 | | MIN, K. D. | 8012190138 | RES | MOODY, D. E. | 7909200465 | 50-29 0 |
| MILLE, L. M. | 8012080616 | 50-327 Q | Mindlin, H. | 8012110744 | PR | MODDY, D. E. | 7909100441 | 50-29 0 |
| MILLE, L. M. | 8012040657 | 50-518 S | Mineck, D. L. | 8012010408 | 50-331 8 | MODDY, D. E. | 8012090074* | 50-29 0 |
| MILLE, L. M. | 8011250423 | 50-259 P | Mineck, D. L. | 8012020492 | 50-331 8 | MODDY, J. H. | 8012080294 | REGOD |
| MILLE, L. M. | 8012040359 | 50-327 S | Mineck, D. L. | 8012020541 | 50-331 8 | MODBY, J. H. | 8012080497 | REGOD |
| MILLE, L. M. | 8012040428 | 50-390 B | Mineck, D. L. | 8012020603 | 50-331 8 | MODDY, D. E. | 8012180270 | 50-29 R |
| MILLB, L. M. | 8012040492 | 50-553 8 | Mineck, D. L. | 8012170573 | 50-331 8 | HOODY, W. C. | 8012170434 | 50-205 T |
| MILLB, L. M. | 8012040495 | 50-553 S | Mineck, D. L. | 8012170643 | 50-331 8 | HOON, G. W. | 8012300279* | 50-465 O |
| MILLB, L. M. | 8012010394 | 50-327 P | Mineck, D. L. | 8012230311 | 50-331 R | HOON, G. W. | 8012300283* | 50-466 O |
| MILLB, L. M. | 8012040957 | 50-566 8 | Mineck, D. L. | 8012240241 | 50-331 8 | HOON, C. W. | 8012300550 | 50-466 O |
| MILLB, L. M. | 8012040416 | 50-328 8 | Mineck, D. L. | 8012300465 | 50-331 8 | HOONEY, C. F | 8012030869 | FOIA |
| MILLE, L. M. | 8012040422 | 50-370 8 | Mineck, D. L. | 8012270410 | 50-331 8 | HOORE, J. B. | 8012100234* | 70-1149 |
| MILLE, L. M. | 8012150261 | 50-438 8 | Hineck, D. L. | 8012270422 | 50-331 8 | HOORE, D. E. | 8012120577* | 50-902 Q |
| MILLE, L. M. | 8012030599 | 50-240 8 | Miner, B. | 8012310257 | 50-315 P | HOORE, R. N. | 8012050627 | XPORTLIC |
| MILLE, L. M. | 8012030694 | 50-328 8 | Minkler, W. B. | 8012020774 | FOIA | HOORE, B. | 8012110545 | 70-2623 |
| MILLE, L. M. | 8012040443 | 50-370 8 | Minkowski, H. O. | 8012080529* | 50-255 P | HOORE, R. N. | 8012170393 | XPORTLIC |
| MILLB, L. M. MILLB, L. M. MILLB, L. M. MILLB, L. M. MILLB, L. M. | 8012050367 8012050381 8012100478 8012100486 8012100548 | 50-518 8 50-518 8 50-518 8 50-438 8 50-328 8 | Minnich, J. F. Minooue, R. B. Minooue, R. B. Minooue, R. B. Minooue, R. B. | 8012020598 8012110692* 8012110689* 8012110683* 8012110816* | 50-320 P FOIA FOIA FOIA | MOORE, O. H. MOORE, D. MOORE, R. N. MOORE, J. E. MOORE, J. E. | 8012030588 8012190609* 8012170272 8012220310 8012290381 | 10-334 R XPDRTLIC XPDRTLIC 50-272 0 50-272 0 |
| MILLE, L. M. MILLE, L. K. MILLE, L. K. MILLE, L. K. MILLE, L. K. | 8012150257 8012150266 8012050397 8012080314 8012090231 | 50-328 8 50-439 8 50-327 P 50-327 P 50-259 P | Mindoue, R. B. Mindoue, R. B. Mindoue, R. B. Mindoue, R. B. Mindoue, R. B. Mindoue, R. B. | 8012110843* 8012270007* 8007180037* 8011060238* 8011060236* | FOIA 10CFR 71-9073 RECOD RECOD | MODRE, R. C. MODRE, J. E. MODRE, J. E. MODRE, B. N. MORCOB, N. | 8012270204 8012270236 8012270241 8012300338 8012080017 | 50-312 F 50-247 0 50-155 0 50-395 D NUREG |
| MILLE, L. M. | 8012090342 | 50-370 8 | Mindoue, R. B. | 8011060013* | 71-9073 | MOREADETH, F. L. | 8012180394* | SO-244 P |
| MILLE, L. M. | 8012090369 | 50-566 8 | Mindoue, R. B. | 8011280112* | 100FR | MOROAN, O. W. | 8012030358* | FOIA |
| MILLE, L. M. | 8012090370 | 50-327 P | Mindoue, R. B. | 8012040330* | 100FR | MOROAN, O. W. | 8012030426* | FOIA |
| MILLE, L. M. | 8012100464 | 50-370 8 | Mindoue, R. B. | 8012040337* | 100FR | MOROAN, O. W. | 8012030402* | FOIA |
| MILLE, L. M. | 8012100467 | 50-438 8 | Mindoue, R. B. | 8012160253 | 50-320 H | MOROAN, W. E. | 8012030278* | FOIA |
| MILLB, L. M. | 8012100517 | 50-370 8 | Mindoue, R. B. | 8012310387 | GRQ | MORGAN, J. F. | 8012020675# | QA999 |
| MILLB, L. M. | 8012070347 | 50-438 A | Mindr, G. C. | 8012170682* | 50-449 G | MORGAN, K. Z. | 8012100020 | PR |
| MILLB, L. M. | 8012070359 | 50-370 6 | Mintz, B. L. | 8012110160 | PR | MORGAN, J. N. | 8012230511# | TOPREP |
| MILLB, L. M. | 8012100460 | 50-328 8 | Miraolia, F. J. | 8012270010 | 50-275 H | MORIARTY, J. M. | 8012310454 | 50-352 8 |
| MILLB, L. M. | 8012160703 | 50-438 8 | Miraolia, F. J. | 8012270017* | 50-416 A | MORISI, A. V. | 8012010096 | 50-293 P |
| MILLB, L. M. | 8012070207 | 50-257 F | MIRAGLIA:F.J. | 8012270022* | 50-416 A | MORISI, A. V. HORISI, A. V. MORISI, A. V. MORISI, A. V. MORISI, A. V. MORISI, A. V. | 8012240242 | 50-293 Q |
| HILLB, L. M. | 8012070410 | 50-257 S | MIRAGLIA:F.J. | 8012040354 | 50-275 H | | 8012240256* | 50-293 Q |
| MILLB, L. M. | 8012100447 | 50-438 S | MIRAGLIA:F.J. | 8012110835 | 50-275 A | | 8012240270* | 50-293 Q |
| MILLB, L. M. | 8012100448 | 50-438 S | MIRAGLIA:F.J. | 8012080414 | 50-275 H | | 8012170483 | 50-293 P |
| MILLB, L. M. | 8012160675 | 50-438 S | MIRAGLIA:F.J. | 8012070005 | 50-275 H | | 8012230354 | 50-293 P |
| MILLS, L. M. | 8012220575 | 50-257 Q | HIRACLIA.F. J. | 8012120203 | 50-275 H | HORTSI, A.V. | 8012240272 | 50-293 P |
| MILLS, L. M. | 8012070184 | 50-390 A | HIRACLIA.F. | 8012020684 | 50-361 D | HOROWSKI, J.V. | 8012170060* | GA999 |
| MILLS, L. H. | 8012070344 | 50-259 P | HIRACLIA.F. | 8012160204 | 50-588 D | HORRIG, V. | 8012180187 | PR |
| MILLS, L. H. | 8012230110 | 50-518 8 | HIRACLIA.F. | 8012180132 | 50-275 A | HORRIG, C. J. | 8012110453 | NUREG |
| MILLS, L. H, | 8012070311 | 50-327 P | HIRACLIA.F. | 801219030D | 50-275 H | HORRIG, P. A. | 8012300569 | TOPREP |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEORY |
|--|---|--|---|--|--|---|---|--|
| MORROW, D. MORTENBEN, W. MORTMAN, D. MORTMAN, D. MORTMAN, D. | 8012080698 8012270016 8012030528; 8012030520; 8012030448; | FOIA FOIA | MURPHY, C. E. | 8012170028* 8012180099* 8012080072 8012090513 8012090520 | 50-280 0 50-260 0 50-438 Q 50-321 0 50-424 Q | NALEPKA, D. S. NALEPKA, D. S. NALEPKA, D. B. NALESNIK, U. J. NAPUDA, G. | 8012170588* 8012170592* 8012170600* 8012110214 8012220031* | 50-305 8 50-305 8 50-305 8 PR 50-317 Q |
| MORTMAN, D. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. | 6012030619# 8012310624# 8012080602# 8012040627# 8012080812# | CONTRACT CONTRACT CONTRACT | MURPHY, C. E. HURPHY, C. E. HURPHY, C. E. MURPHY, C. E. MURPHY, C. E. | 8012180307* 8012080649* 8012110137* 8012110618* 8012110840 | 50-390 Q 50-369 Q 50-261 Q 50-413 Q 50-518 Q | NAPUDA, G. NAPUDA, G. NARDACCI, G. A. NARROW, L. NARROW, L. | 8012180353* 8012180357* 8012160486* 8012240233* 8012110405* | 50-247 Q 50-247 Q 50-289 R 50-322 Q 50-410 Q |
| MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, O. MORTON, K. V. | 8012040140± 8012080498± 8012164018± 8012110237 8012310579± | CONTRACT | MURPHY, C. E. | 8012180294 8012110701 8012150258* 8012150259* 8012160730 | 50-390 Q 50-364 Q 50-389 Q 50-389 Q 50-518 Q | NARROW, L. NARROW, L. NAU, R. F. NEARY, M. P. NEELY, D. R. | 8012110607* 8012110479* 8012110491 8012190040 8012220348* | 50-387 Q 50-412 Q NUREQ NUREQ 50-289 Q |
| MORTON, K. V. | 8012080503* 8012080623* 8012100417* 8012170219* 8012220003* | CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT | MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. HURPHY, C. E. | 8012170064* 8012180284 8012110626 8012160027 8012180400* | 50-413 Q 50-424 Q 50-250 Q 50-416 Q 50-400 Q | Nehemiab, J. Neighborb, J. D. Neilbon, C. O. Neibler, J. H. Neibler, J. H. | 9012220348* 8012110652 8012310591* 8012120300* 9012240054* | 50-289 Q 50-280 F 40-7402 50-483 Q 50-373 Q |
| MORTON, K. V. | 8012220005* 8012080505* 8012310602* 8012180526* 8012100007* | CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT | MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, D. W. | 8012110676* 8012170471 8012180220 8012180219 8012220056* | 50-413 Q 50-438 Q 50-259 Q 50-338 Q 50-266 Q | NELBON, J. D. NELBON, J. D. NELBON, J. D. NELBON, J. D. NEUMANN, M. R. | 8012080788 8012080796* 8012080823* 8012080823 8012080784 | 40-8084 40-8084 40-8084 40-8084 40-8084 |
| MORTON, K. V. MORTON, K. V. MORTON, K. V. MOSCHNER, R. A. MOSCHNER, R. A. | 6012240051* 8012240036* 8012240044* 6012040492* 8012020300 | CONTRACT CONTRACT CONTRACT 70-754 70-754 | MURPHY, C. E. MURPHY, C. E. MURPHY, O. L. MURPHY, C. E. MURPHY, C. E. | 8012120354 8012180379* 8012110331 8012020117 8012020375 | 50-544 Q 50-349 Q PR 50-349 Q 50-344 Q | NEWLIN, M. H. NEWMAN, E. W. NEWMAN, E. W. NEWMAN, K. W. NEWMARK, N. M. | 8012010531* 8012030457* 8012030454* 8012030397* 8012080774* | COMMISSION FOIA FOIA FOIA 70-754 |
| MOSES, A. J. MOSES, A. J. MOSES, A. J. MOSES, A. J. MOSES, A. J. | 8012230001 80120303551* 8012030309* 8012030280* | 50-522 | MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. | 8012170213* 8012310050 8012080227 8012150027 8012310058 | 50-413 Q 50-564 Q 50-250 Q 50-261 Q 50-43B Q | NEHMARK, N. M. NEHMAN, J. R. NEHMAN, J. R. NEHMAN, J. R. NEHMAN, J. R. | 8012080779* 8012100082 8012020628 8012020634* 8012020634* | 70-754 PR 50-466 Q 50-466 Q |
| MOSK, S. MOSK, S. MOSK, S. MOTHERWELL, B. L. MOUNT, R. E. | 8012030074* 8012030127* 8012030091* 8012030485* 8012290522 | 27-10 27-10 27-10 FOIA 50-255 G | MURPHY, W. P. MURPHY, W. P. MURPHY, R. T. MURPHY, G. E. MURPHY, G. E. | 8012010379 8012010403* 8012120380 8012080660 8012090135 | 50-271 8 50-271 8 PR 50-518 G 50-438 G | NEHMAN, J. R. NEHMAN, J. R. NEHMAN, J. R. NEHMAN, J. R. NEHMAN, J. R. | 8012270005 8012270275 8012270005 6012270275 8012270241 | 50-466 Q 50-466 Q 50-466 Q 50-466 Q |
| MOUNT, R. E. MOURY, W. R. MOURY, W. R. MOURY, W. R. MOURY, W. R. MROCIXA, E. J. | 8012270214 8011250704* 8012080770* 8012080778* 8012020529 | 50-255 0 50-579 A SECY BEGY 50-336 S | MURPHY, G. E. MURPHY, W. P. MURPHY, W. P. MURPHY, G. E. MURPHY, G. E. | 8012110127 8012020435 8012020439* 8012110529 8012170054 | 50-261 Q 50-271 B 50-271 B 50-321 Q 50-413 Q | NEHMAN, J. R NEHMAN, J. R. NEHMAN, J. R. NEHMAN, J. R. NEHTON, F. | 8012270641 8012270071 8012270156 8012270071 | 50-466 Q 50-466 Q 50-466 T 50-466 Q |
| MROCZKA, E. J. MROCZKA, E. J. MROCZKA, E. J. MROCZKA, E. J. MROCZKA, E. J. | 8012230346 8012230342 8012230384 8012230487 8012300635 | 50-336 R 50-245 R 50-336 B 50-245 B 50-245 S | MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. | 8012180123 8012180165 8012180169 8012180089 8012190359* | 50-413 G 50-261 G 50-387 G 50-260 G 50-400 G | NEHTON, W. A. NICHOLAG, L. H. NICHOLAG, H. NICHOLAG, H. H. NICHOLAGN, N. A. | 8012080563* 8012080136 8012180541* 8012080115* 8012080125* 8012160574* | 90-327 F PR 50-213 H 50-387 Q 50-387 Q |
| MROCZKA, E. J. MUDGE, E. MUELLER, R. MUELLER, J. M. MUELLER, R. | 8012230465 8012270520 8012100484* 8012150002 8012020677* | 50-336 8 50-289 H 50-285 S FOIA 50-285 S | HURPHY, C. E. HURPHY, C. E. HURPHY, T. A. HURPHY, C. E. MURPHY, C. E. | 8012150255 8012310295* 8012160609 8012170023 8012180092 | 50-389 G 50-413 G PR 50-338 G 50-414 G | NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. | 8012020287 8012030671 8012030293 8012020369 8012020377 | 50-182 G 50-395 G 50-395 A 50-395 A |
| MUELLER, R. MUELLER, M. B. MUELLER, B. P. MUELLER, E. E. MUELLER, M. A. | 8012020616* 8012180242 8012180246 8012160451 8012220600 | 50-285 8 PR PR 50-466 0 Nureo | MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, A. W. MURRAY, R. | 8012170013 8012180375 8012180379 8012300230* 8012090416* | 50-280 Q 50-400 Q 50-364 Q CONTRACT 50-265 B | NICHOLB.T.C. NICHOLB.T.C. NICHOLS.T.C. NICHOLS.T.C. NICHOLS.T.C. | 8012020493 8012020523 8012030613 8012030634 8012030434 | 50-375 8 50-375 8 50-375 8 50-375 8 50-375 8 |
| MULHOLLAND, J. D. MULKEY, J. P. MULLER, R. MULLER, R. E. MULLEN, P. E. | 8012040140* 8012110620* 8012160605 8012170388 8012120629 | CONTRACT 50-348 G ACRS XPORTLIC PR | MURRAY, H. J. MURRAY, T. D. | 8012020681 8012020525 8012040385 8012120490 8012120501 | 50-237 | NICHOLB: T. C. NICHOLS: T. C. NICHOLS: T. C. NICHOLB: T. C. NICHOLB: T. C. | 8012020437 8012020442 8012020445 8012030636 | 50-375 S 50-375 S 50-375 S 50-375 S |
| MULLER, M. S. MULLER, J. C. MULLINIX, II. MUNDAY, S. R. MUNRO, J. J. | 8012180242 8012160631 8012110252* 8012100115 8012100669 | PR PR FOIA PR 71-9147 | MURRAY, T. D. MURRAY, M. J. | 8012120614 8012170536 8012070380 8012150053 8012300070 | 50-346 8 50-346 8 50-346 B 50-346 R 50-237 0 | NICHOLB, T. C. NICHOLB, T. C. NICHOLB, T. C. NICHOLB, T. C. NICHOLB, T. C. | 8012150035 8012010117 8012010327 8012020241 8012020372 | 50-395 A 50-395 A 50-395 A 50-395 R 50-395 A |
| MURDOCK, B. MURDOCK, L. T. HURCEY, T. E. HURPHY, J. D. MURPHY, J. | 8012120378 8012220137# 8012170545 8012030404# 8012030454# | 40-4622 40-4492 MISC Foia Foia | MURRAY, T. D. MURRAY, M. J. MURRAY, M. J. MURRAY, T. D. MURRAY, T. D. | 8012150116 8012300081 8012300084* 8012150168 8012220446 | 50-346 B 50-237 0 50-237 0 50-346 B 50-346 S | NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. | 8012010108 8012110682* 8012070218 8012070230 8012070377 8012070262 | 50-395 A 50-395 A 50-395 A 50-395 A 50-395 A |
| MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. | 8012020400* 8012120366* 8012020133* 8012180144* 8012180106* | 50-364 Q 50-566 Q 50-369 Q 50-413 Q 50-416 Q | MURRAY, T. D. MURRAY, T. D. MUSICK, J. MUSKIE, E. S. MYERS, R. V. | 8012310319 8012310321 8012150017 8012240098* 8012300132 | 50-346 8 50-346 S FD1A COMMISSION 50-287 H | NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. | 8012070324 8012160436 8012170437 9012170431 8012170431 | 50-375 A 50-375 B 50-375 A 50-375 A |
| MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. | 6012180209* 8012090146* 8012170036* 8012180185* 8012080678* | 50-389 Q 50-438 Q 50-338 Q 50-318 Q 50-518 Q | MYNATT, F. R. MYRABO, A. L. NADEL, E. M. NAIDU, K. R. NAKAMURA, Q. M. | 8012140555* | RES 50-263 R PR 50-456 Q PR | NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C. | 8012160123 8012160162 8012190132 8012190140 | 50-375 A 50-375 A 50-375 A 50-375 A 50-375 K 50-375 A |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCEBSION NUMBER | SUBJECT CATEGORY |
|--|---|--|---|--|--|---|--|--|
| NICHOLS, T. C. | 8012230280 | 50-395 A | O'REILIR.A. | 8012030458 | 50-445 M | O'REILLY, J. P. | 8012030829 | 50-416 Q |
| NICHOLS, T. C. | 8012230350 | 50-395 B | O'NEILLIJ. | 8012300059* | 50-155 0 | | 8012030830 | 50-348 Q |
| NICHOLS, T. C. | 8012230460 | 50-395 A | O'NEILLIJ. | 8012300055 | 50-155 0 | | 8012030832 | 50-437 Q |
| NICHOLS, T. C. | 8012300458 | 50-395 B | O'NEILLIJ. | 8012150171* | 50-346 8 | | 8012030835 | 50-395 Q |
| NICHOLS, T. C. | 8012300637 | 50-395 A | O'REILLIJ. | 8012310616 | 70-143 | | 8012030837 | 50-259 Q |
| NICHOLS, T. C. | 8012300417 | 50-395 A | O'REILLY, J. P. | 8012240133* | 70-143 | O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. | 8012030849 | 50-280 Q |
| NICHOLS, T. C. | 8012300455 | 50-395 A | O'REILLY, J. P. | 8012100680* | 70-143 | | 8012030857 | 50-321 Q |
| NICHOLS, T. C. | 8012300450 | 50-395 A | O'REILLY, J. P. | 8012170220 | 70-1349 | | 8012039862 | 50-480 Q |
| NICHOLS, T. C. | 8012300252 | 50-395 A | O'REILLY, J. P. | 8012170225 | 70-2663 | | 8012030868 | 50-250 Q |
| NICHOLS, T. C. | 8012300261 | 50-395 A | O'REILLY, J. P. | 8012170226 | 70-1397 | | 8012030873 | 50-267 Q |
| NICHOLB, T. C. | 8012300473 | 50-395 D | O'REILLY, J. P. | 8012170258 | 70-2520 | O'REILLY, J. P. | 8012030887 | 50-261 0 |
| NICHOLB, T. C. | 8012300534 | 50-395 8 | O'REILLY, J. P. | 8012170263 | 70-2892 | | 8012030892 | 50-302 0 |
| NICHOLB, T. C. | 8012300628 | 50-395 8 | O'REILLY, J. P. | 8012150179 | 50-488 Q | | 8012080188 | 50-395 0 |
| NICHOLB, T. C. | 8012310424 | 50-395 Q | O'REILLY, J. P. | 8012150190 | 50-261 Q | | 8012080194 | 50-250 0 |
| NILSON, R. | 8012020313 | 70-1257 | O'REILLY, J. P. | 8012150198 | 50-321 Q | | 8012080200 | 50-416 0 |
| NILSON, R. | 8012050093 | 71-4591 | O'REILLY, J. P. | 8012150201 | 50-257 Q | O'REILLY, J. P. | 8012080204 | 50-302 Q |
| NIMITZ, R. L. | 8012220348* | 50-287 Q | O'REILLY, J. P. | 8012160023 | 50-416 Q | O'REILLY, J. P. | 8012080212 | 50-348 Q |
| NIMMO, E. | 8012120295 | PR | O'REILLY, J. P. | 8012160026 | 50-302 Q | O'REILLY, J. P. | 8012080218 | 50-437 Q |
| NIX, R. T. | 8012010346* | 50-321 6 | O'REILLY, J. P. | 8012160029 | 50-395 Q | O'REILLY, J. P. | 8012080248 | 50-488 Q |
| NIX, R, T. | 8012010383* | 50-364 B | O'REILLY, J. P. | 8012160031 | 50-340 Q | O'REILLY, J. P. | 8012080239 | 50-280 Q |
| NIX, R. T. NIX, R. T. NIX, R. T. NIX, R. T. NODA, L. | 8012010393# 8012010357# 8012010394# 8012290266# 8012310272 | 50-366 B 50-366 S 50-321 B 50-366 B 50-271 H | O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. | 8012160036 8012160042 8012160069 8012170249 8012170274 | 00-280 G 50-269 G 50-437 G 50-437 G 90-404 G | O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. | 801208027& 8012080303 8012080316 8012080403 8012040135 | 50-259 0 50-321 0 50-261 0 50-269 0 |
| NOFFBUYER, P. O. NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. NORDERHAUG, L. NORELIUB; C. E. | 8012270277 8012110100 8012110106* 8012270016 8012310518* | 70-2623 70-1257 70-1257 50-312 8 50-341 Q | O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. | 6012170279 6012170281 6012170284 6012170286 6012170288 | 50-348 0 50-269 0 50-302 0 50-321 0 50-395 0 | O'REILLY, J. P. | 8012040143 8012040157 8012040164 8012040172 8012040183 | 50-259 G 50-261 Q 50-48B Q 50-269 Q 50-250 G |
| NORELIUS, C. E. NORELIUS, C. E. NORELIUS, C. E. NORRHOLM, L. J. NORTH, H. B. | 8012170554* 8012310550* 8012180024* 8012190707* 8012090075* | 50-237 | O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. | 8012170270 8012170298 8012170300 8012170302 8012170310 | 50-416 G 50-424 G 50-364 G 50-400 G 50-367 G | O'REILLY, J. P. | 8012040199 8012040193 8012040199 8012040202 8012040206 | 50-321 0 50-437 0 50-416 0 50-302 0 50-348 0 |
| NORTON, B. | 8012300352 | 50-275 0 | O'REILLY, J. P. | 8012110534# | 50-321 0 | D'REILLY, J.P. D'REILLY, J.P. D'REILLY, J.P. D'REILLY, J.P. D'REILLY, J.P. | 8012040212 | 50-348 Q |
| NORTON, B. | 8012300352 | 50-275 0 | O'REILLY, J. P. | 8012170491# | 50-259 0 | | 8012110371 | 50-348 P |
| NOSENZO, L. V. | 8012180427* | BEGY | O'REILLY, J. P. | 8012170803 | 50-488 0 | | 8012150020 | 50-328 P |
| NOSENZO, L. V. | 8012180420* | SECY | O'REILLY, J. P. | 8012170813 | 50-269 0 | | 8012040468 | 50-241 Q |
| NOSENZO, L. V. | 6012100216 | XPORTLIC | O'REILLY, J. P. | 8012170821 | 50-280 0 | | 8012040472 | 50-348 Q |
| NOSENZO, L. V. NOSENZO, L. V. NOSENZO, L. V. NOSENZO, L. V. NOSENZO, L. V. | 8012170257 8012080132 8012110096 8012110103 8012170254 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. | 8012170833 8012180007 8012180012 8012180017 8012180023 | 50-34B | O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. | 8012040474 8012040477 8012040479 8012040482 8012050023 | 50-321 0 50-250 0 50-302 0 50-269 0 50-328 0 |
| NOSENZO, L. V. | 8012160647 | XPORTLIC | O'REILLY, J. P. | 8012180027 | 50-261 '0 | O'REILLY, J. P. | 8012050033 | 50-404 0 |
| NOSENZO, L. V. | 8012170264 | XPORTLIC | O'REILLY, J. P. | 8012180035 | 50-327 0 | O'REILLY, J. P. | 8012050034 | 50-375 0 |
| NOSENZO, L. V. | 8012240218 | XPORTLIC | O'REILLY, J. P. | 8012180047 | 50-437 0 | O'REILLY, J. P. | 8012050039 | 50-437 0 |
| NOSENZO, L. V. | 8012170255 | XPORTLIC | O'REILLY, J. P. | 8012170004 | 50-259 0 | O'REILLY, J. P. | 8012050041 | 50-416 0 |
| NOSENZO, L. V. | 8012310077 | XPORTLIC | O'REILLY, J. P. | 8012170014 | 50-321 0 | O'REILLY, J. P. | 8012050043 | 50-424 0 |
| NOSENZO, L. V. | 8012310079 | XFORTLIC | O'REILLY, J. P. | 8012170422 | 50-250 Q | O'REILLY, J.P. | 8012050046 | 50-369 0 |
| NOVAK, T. M. | 8012010453 | 50-293 P | O'REILLY, J. P. | 8012170571 | 50-267 Q | O'REILLY, J.P. | 8012050048 | 50-468 0 |
| NOVAK, T. M. | 8012120521 | 50-336 P | O'REILLY, J. P. | 8012170595 | 50-488 Q | O'REILLY, J.P. | 8012050055 | 50-369 0 |
| NOVAK, T. M. | 8012180314 | 50-346 P | O'REILLY, J. P. | 8012170785 | 50-261 Q | O'REILLY, J.P. | 8012050060 | 50-400 0 |
| NOVAK, T. M. | 8012090430 | 50-317 Q | O'REILLY, J. P. | 8012180006 | 50-416 Q | O'REILLY, J.P. | 8012050064 | 50-344 0 |
| NOVAK, T. M. | 8012300188 | 50-344 Q | O'REILLY, J.P. | 8012180008 | 50-497 Q | O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. | 8012050067 | 50-259 0 |
| NOVAK, T. M. | 8012160194 | 50-305 P | O'REILLY, J.P. | 8012180011 | 50-395 Q | | 8012050070 | 50-280 0 |
| NOVAK, T. M. | 8012180082 | 50-344 Q | O'REILLY, J.P. | 8012180014 | 50-902 Q | | 8012050614 | 50-348 0 |
| NOVAK, T. M. | 8012300738 | 50-348 P | O'REILLY, J.P. | 8012180017 | 50-948 Q | | 8012050621 | 50-261 0 |
| NOVAK, T. M. | 8012310015 | 50-338 P | O'REILLY, J.P. | 8012180020 | 50-280 Q | | 8012050626 | 50-469 0 |
| NOVARRO, J. P. | 8012310414 | 50-322 | O'REILLY, J. P. | 8012230030 | 50-257 Q | O'REILLY, J. P. | 8012050454 | 50-302 0 |
| NOVARRO, J. P. | 8012010080 | | O'REILLY, J. P. | 8012230042 | 50-416 Q | O'REILLY, J. P. | 8012050455 | 50-414 0 |
| NOVARRO, J. P. | 8012020723* | | O'REILLY, J. P. | 8012230043 | 50-302 Q | O'REILLY, J. P. | 8012080901 | 50-437 0 |
| NOVARRO, J. P. | 8012100276 | | O'REILLY, J. P. | 8012230045 | 50-261 Q | O'REILLY, J. P. | 8012080902 | 50-395 0 |
| NOVARRO, J. P. | 8012150216 | | O'REILLY, J. P. | 8012230050 | 50-267 Q | O'REILLY, J. P. | 8012080904 | 50-259 0 |
| NOVARRO, J. P. NOVARRO, J. P. NOWICKI, S. NOWICKI, S. J. NOWICKI, S. J. | 8012150220* 8012180301 8012090041 8012100048 8012180298 | 50-322 K 50-322 G 50-206 P 50-206 P 50-206 P | O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. | 8012230057 8012230063 8012230067 8012230070 8012230072 | 30~48B Q 50~250 Q 50~321 Q 50~280 Q 50~395 Q | O'REILLY, J. P. | 8012080018 8012080024 8012080029 8012170347 8012170348 | 50-280 0 50-250 0 50-321 0 50-437 0 50-375 0 |
| NUGENT, E. L. NUNN, D. E. NUNNENKAMP, T. U. NUBBBAUMER, D. NUBBBAUMER, D. A. | 8012160305 | 40-2259 | O'REILLY, J. P. | 8012230075 | 50-395 Q | O'REILLY, J. P. | 8012170354 | 50-416 0 |
| | 8011250285 | 30-361 A | O'REILLY, J. P. | 8012230077 | 50-348 Q | O'REILLY, J. P. | 8012170357 | 50-259 0 |
| | 8012150158 | 50-369 H | O'REILLY, J. P. | 8012230079 | 50-437 G | O'REILLY, J. P. | 8012170387 | 50-280 0 |
| | 8012030181 * | 27-39 | O'REILLY, J. P. | 8012110721 | 50-437 Q | O'REILLY, J. P. | 8012170400 | 50-348 0 |
| | 8012030162* | 27-39 | O'REILLY, J. P. | 8012110725 | 50-395 Q | O'REILLY, J. P. | 8012170496 | 50-261 0 |
| NUBSBAUMER, D. A. NUTT, H. T. NUTTLE, W. K. NUZZO, D. G. D'BRIEN, J. | 8012050225* 8012050492* 8012120371 8012100229* 8012120253* | 71-3362 PRDJ NUREG 50-333 G 50-312 G | O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. | 8012110727 8012110732 8012110734 8012110743 8012110743 | 50-416 | D'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. | 6012170500 6012170509 6012170512 6012170516 6012170517 | 50-488 0 50-269 0 50-250 0 50-302 0 50-321 0 |
| O'BRIEN, M. J. O'BRIEN, M. J. O'BRIEN, M. J. O'CONNOR, P. W. O'NEILL, J. | 8012100036* 8012110279 8012120036 8012110341 8012030271 | 50-312 Q PR PR 50-10 P 50-155 Q | O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. | 8012110749 8012110740 8012110747 8012110794 8012110807 | 50-269 | O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'TOOLE, J. D. O'TOOLE, J. D. | 8012100470 8012150018 8012310033 8012040507 8012020564 | 70-143 70-143 50-335 0 50-247 8 50-247 |

| AUTHOR | WIMBER VCCERRION | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT | |
|--|---|--|--|---|--|--|---|--|---------------|
|)'TOOLE, J. D.)'TOOLE, J. D.)'TOOLE, J. D.)'TOOLE, J. D.)'TOOLE, J. D. | 8012030695 8012160296 8012080444 8012100489 8012090281 | 50-3 H 50-247 P 50-247 B 50-247 P 50-247 P | PAGUETTE, T. PARIS, W. C. PARKER, W. O. PARKER, W. O. PARKER, M. J. | 8012100175 8011180742 8012240372* 8012230848 8012100176* | PR 40-299 50-369 F 70-2623 50-155 Q | PATE, R. J. PATE, R. J. PATEL, B. PATON, W. D. PATON, W. | 8012040329* 8012100147* 8012100184 8012050443 8012050420 | 50-341 50-341 PR 50-329 50-329 | ģ c c c |
| D'TOOLE, J. D. D'TOOLE, J. D. DCHITELL, H. DDEOAARDEN, R. H. DDEOAARDEN, R. H. | 8012220397 8012230303 8012150104 8012010242* 8012010178* | 50-3 R 50-247 R 50-289 H 71-9073 71-9073 | PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, O. D. | 8012020127* 8012100311 8012040340 8012180137* 8012050619 | 50-369 @ 50-269 P PR 50-413 @ PR | PATON, W. D. | 8012020694 8012270305 8012240001 8012270104 8012230304 | 50-327 50-327 50-327 50-327 50-327 | 0 T T |
| DDOM, A. L. DESTHANN, M. J. DIGLIGTTI, R. J. DKUDA: H. DLIVER: R. H. | 8012220634 8012220056* 8012020254 8012240373 8012110491 | NUREO 50-266 G 70-371 XPORTLIC NUREO | PARKER, M. O. PARKER, M. O. PARKER, M. O. PARKER, M. O. PARKER, H. M. | 8012080596 8012110613 8012080645 8012240083 8012300751 | 50-269 Q 50-413 Q 50-369 Q 50-369 S ACRB | PATON, W. B. PATRIALE, A. A. PATTERSON, J. P. PATTERSON, T. L. PATTI, F. J. | 8012230282 8012040070 8012160192* 8012170542* 8012270123 | 50-289 NUREO 50-315 90-285 PR | O R |
| DLIVEROB, R. B. DLLER, R. E. DLMSTEAD, W. J. DLMSTEAD, W. J. DLMSTEAD, W. J. | 8012310277 8012180621* 8012230009 8012270417 8012300065 | 50-466 | PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. | B012170060* B012010201 B012110666 B012180286 B012180571 | 50-413 Q 50-369 A 50-413 Q PR 50-269 Q | PATTON, D. D. PAUL, R. A. PAULBON, W. A. PAULBON, W. A. PAYNE, H. R. | 8012110312 8012180408* 8012040081 8012140634 8012170177 | PR 50-2 50-219 50-219 REB | Q P P |
| DLSEN, A. F. RLSHAM, L. N. DLSHINSKI, J. A. DLSON, J. DLSON, R. C. | 8012020286 8012020041 8012160255 8012300636 8012270223 | 50-13 F TOPREP 50-206 P 50-367 A 50-317 F | PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. | 8012020592 8012020502 8012040408 8012050250 8012050302* | 50-269 P 50-270 S 50-369 S 50-369 A 50-369 A | PECK, C. G. PECK, G. G. PEDERBEN, K. PEDIGREE, R. B. PEERY, W. W. | 8012220074* 8012180234* 8012240085* 8012170577* 8012170606* | 40-3372 70-34 COMMISSI 70-2154 27-47 | טאי |
| DMOHUNDRO, F. P. DPREA, Q. M. DPREA, Q. M. DPREA, Q. M. DPREA, Q. M. DPREA, Q. M. | 8012270132 801222030* 8012170647* 8012160277 8012030655 | PR 50-498 O 50-498 O 50-498 G 50-498 S | PARKER, W. O. | 8012050314# 8012050448 8012050391 8012050444 8012180361 | 50-369 A 50-269 P 50-369 A 50-369 A 50-369 G | PELLY, B. B. | 8012030135* 8012030487* 8012030444* 8012030347* 8012030211* | FOIA FOIA FOIA FOIA | |
| DPREA: Q. M. DPREA: Q. M. DPREA: Q. M. DPREA: Q. M. DPREA: Q. M. | 8012030666 8012170420 8012170418 8012170329 8012170333* | 50-498 8 50-498 9 50-498 8 50-498 K 50-498 K | PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. | B012180674 B012230535* B012100374 - 2180397 | 50-369 0 50-369 A 50-269 P 50-369 0 50-270 S | PELLY, B. B. PELLY, B. B. PENDERGRAFT, R. PENDERGRAFT, R. PENDERGRAFT, R. | B012030103* B012030093* B012020461* B012030641* B012030643* | FOIA FOIA 50-348 50-348 50-348 | 8 8 8 |
| DRAKA, E. 8. DRTLOFF, O. D. DSBORNE, R. P. DSBORNE, R. P. DSBORNE, J. | 8012270133 8012080776 8012240404* 8012110074 8012110648 | PR 40-8102 State Prog PR PR | PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. | 8012310167 8012190206 8012150069 8012160435 8012160325 | 50-269 Q 50-413 Q 50-369 A 50-269 Q 50-269 P | PENDERORAFT, R. PENDERORAFT, R. PENDERORAFT, R. PENODV, C. A. PENODV, C. A. | 8012100560* 8012170630* 8012160415* 8012110391* 8012160603 | 50-368 50-368 50-368 71-5796 71-350 | 8 8 R |
| DSETEK.D.J. DSHERENKO.O. DSHERENKO.O. DSHERENKO.O. DSHEYER.W.E. | 8012220707 8012270516 8012270142 8012270336 8012010034 | NUREO 50-155 G 50-155 G 50-155 G 71-6744 | PARKER, W. D. PARKER, W. D. PARKER, W. O. PARKER, W. O. PARKER, W. O. | 8012170482 8012230488 8012170615 8012230450 8012230458 | 50-269 P 50-269 P 50-269 R 50-269 P 50-369 Q | PENIKAS, V. T. PEOPLES, D. L. PEREZ, C. A. PERKINS, M. A. PERL, L. J. | 8012080221 8012070045* 8012080272 8012050570 8012300682* | PR 50-254 PR PR 50-466 | a T |
| DSTER-ORANITE DSTRANDER, F. W. DSUCH, J. C. DSUCH, J. C. DSUCH, J. C. | 8012080317 80123004574 8012020652* 8012020488* 8012020663* | PR 50-344 | PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. | 8012230479 8012230435 8012230514 8012300606 8012230345 | 50-267 8 50-269 P 50-287 8 50-369 8 50-369 A | PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J. | B012100207* B012230144 B012230151 B012230168 B012100423* | CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT | |
| 180CH, J. C. 180CH, J. C. 180CH, J. C. 180CH, J. C. 180CH, J. C. | 8012050385* 8012110409* 8012150124* 8012170640* 8012230382* | 50-272 B 50-272 B 50-272 B 50-272 B 50-272 B | PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. | 8012310273 8012230330 8012230457 8012300471 8012300478 | 50-413 Q 50-369 F 50-369 Q 50-287 B 50-269 B | PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J. | 8012100189* 8012220240 8012220249* 8012230138* 8012300154* | CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT | |
| DTT, L. J. DTT, W. Q. DTTENBERQ, K. DWENB, D. H. DWBLEY, Q, F. | 8012220181 8012300136 8012170788* 8012100007* 9012230507 | NUREO 50-287 H REB CONTRACT TOPREP | PARKER, H. O. PARKINSON, T. F. PARKS, C. V. PARR, O. D. PARROTT, H. W. | 8012300485 8012230517# 8012100146 8012120238* 8012240379* | 50-287 8 50-124 F RES 50-369 A State Prog | PERLMAN, J. PERNY, C. D. PERNY, C. PEROTTI, D. J. PERRIGO, L. D. | 8012300230# 8012120584# 8012190609# 8012110222# 8012110548 | XPORTLIC | a a |
| D'CONNOR, P. W. PACE, P. L. PACE, P. L. PACE, P. L. PACE, P. L. | 8012090459 8012100528* 8012100538* 8012100479* 8012100407* | 50-10 P 50-335 8 50-335 8 50-335 B 50-335 B | PAREONS W. B. PAREONT M. A. PARTLOW J. Q. PARTLOW J. Q. PARTLOW J. Q. PARTLOW J. Q. | 8012080040 8012170517 8012080772 8012160601 8012290391 | XPORTLIC NUREQ 70-143 70-734 70-364 | PERROTTI, D. J. PERRY, Q. C. | 8012070177* 8012030371* 8012030450* 8012030462* 8012030459* | 50-395 FOIA FOIA FOIA FOIA | G |
| PACE, P. L. PACE, P. L. PACE, P. L. PACE, P. L. PACE, P. L. | 8012020557* 8012020474* 8012020544* 8012020567* 8012020542* | 50-335 8 50-251 8 50-250 8 50-335 8 50-335 8 | PARZIALE, A. A. PARZIALE, A. A. PASEDAO, N. PASTERNAX, R. J. PASTERNAX, R. J. | 801202073B 8012020744 8012020359* 8012070153* 8012030933 | NUREO NUREO 10CFR 50-333 Q 50-333 Q | PERRY, Q. C. | 8012030422* 8012030435* 8012030375* 8012030565* 8012030575* | FOIA FOIA FOIA FOIA | |
| PAGE: P. L. PAGE: P. L. PAGE: P. L. PADALINO: J. PAGES: R. E. | 8012020507# 8012020555+ 8012050470# 8012170540 8012180374* | 50-335 8 50-335 9 50-335 8 50-382 8 50-244 P | PABTERNAKI R. J. PABTERNAKI R. J. PABTERNAKI R. J. PABTERNAKI R. J. PABTERNAKI R. J. | 8012090003 8012010409 8012050431 8012080455 8012150127 | 50-333 0 50-333 8 50-333 8 50-333 8 | PERRY, Q. C. PERRY, Q. C. PERRY, Q. C. PERRY, Q. C. PERRY, Q. C. | 8012030443* 8012030546* 8012030491* 8012030590* 8012030540* | FOIA FOIA FOIA FOIA | |
| PALMETER, B. B. PANAGUS, A. PANEGEEFF, D. PANGBURN, G. C. PAGUINO, R. J. | 8012300145 8012230327* 8012160862 8012110762 8012020216* | 50-269 H 50-295 B PR 27-47 50-269 Q | Pasternak, R. J. Pasternak, R. J. Pasternak, R. J. Pasternak, R. J. Pasternak, R. J. | 8012160302 8012160530 8012270432 8012270439 8012270441 | 50-333 R 50-333 8 50-333 8 50-333 8 50-333 8 | PERRY, O. C. PERRY, O. C. PERRY, J. C. PERRY, J. C. PESCHEL, J. M. | 8012030872* 8012030633* 8012300558* 8012300565* 8012310433* | 50-344 | 8 B Q |
| PAOLINO, R. J. PAOLINO, R. J. PAPERIELLO, C. PAPERIELLO, C. PAPERIELLO, C. J. | 8012190655* 8012190717* 8012300521 8012040263* 8012160576* | 50-394 Q 50-387 Q 50-361 8 50-331 Q 50-182 Q | PABTERNAK, R. J. PABTERNAK, R. J. PABTERNAK, R. J. PABTERNAK, R. J. PABTERNAK, R. J. | 8012270443 8012270468 8012300655 8012300542 8012300630 | 50-933 | PESTCOE, S. PESTLE, J. H. PETERSON, LR. PETERS, A. PETERSON, R, W. | 8012300085 8012170420 8012010572 8012180237 8012300263 | FOIA 40-8502 PR | Н Н |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCEBBION NUMBER | SUBJECT CATEODRY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|--|--|--|---|---|---|---|---|---|
| PETRICK, N. A. PETRICK, N. A. PETRICK, N. A. PETRICK, N. A. PETTINOA, G. W. PEVEY, L. E. | 8012080336* 8012070120 8012100440 8012110323 8012240251* | 50-482 A PR 50-482 B PR 70-398 | POTAPOVE, U. POTAPOVE, U. POTAPOVE, U. POTAPOVE, U. POTAPOVE, U. POTAPOVE, U. | 8012180574 8012190476* 8012080272* 8012190160* 8012190016* | 0A979 QA999 QA999 QA999 QA999 QA999 | PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. | 8012030146* 8012030154* 8012030158* 8012030123* 8012030128* | FOIA FOIA FOIA FOIA FOIA |
| PEVEY, L. E. PHILIPB, M. H. PHILIPB, H. H. PHILLIPB, L. E. PHILLIP, O. A. | 8012230145 8012290379 8012290379 8012020046 B012170554* | 70-398 70-2623 70-2623 TOPREP 50-237 Q | POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. | 8012170302* 8012170551 8012220070* 8012180612* 8012020772 | QA999 QA999 QA999 QA999 QA999 | PRICE, H. L. | 8012030389* 8012030608* 8012030612* 8012030615* 8012030115* | FOIA FOIA FOIA FOIA |
| Phillips, H. S. Phillip, G. A. Phillips, L. E. Phillips, J. R. Phillips, J. R. | 8012190544* 8012180026* 8012090194 8012080513 8012290120 | 50-498 Q 50-409 G TOPREP 50-275 O 50-275 O | POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. | 801207004B 8012020709 8012230234 8012080263 8012020667 | 04777 04777 04777 04777 04777 | PRICE: H. L. | 8012030373* 8012030547* 8012030557* 8012030563* 8012030545* | FOIA FOIA FOIA FOIA |
| PHILLIPS, J. R. PICCIONI, R. O. PICKARD, R. C. PICKERINO, K. PICKUS, H. | 8012170442* 8012120408 8012080333 8012170444 8012080702 | 50-275 Q PR PR 50-287 H PR | POTAPOVE, U, POTAPOVE, U, POTAPOVE, U, POTAPOVE, U, POTAPOVE, U, | 8012080287 8012080238 8012190289 8012190453 8012300005 | QA999 QA999 QA999 QA999 QA999 | PRICE, H. L. | 8012030327* 8012030095* 8012030099* 8012030526* 8012030524* | FOIA FOIA FOIA FOIA |
| PICKUS, M. PIERCE, J. PICOTT, D. R. PICOTT, D. R. PICOTT, D. R. | 8012100142 8012220246* 8012030306 8012030306 8012120413* | PR FOIA 50-361 0 50-361 0 50-206 P | POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. | 8012170008 8012170085 8012230167 8012170050 8012170438 | QA999 QA999 QA999 QA999 QA999 | Price, H. L. Price, H. L. Price, H. L. Price, H. L. Price, E. R. Price, E. R. | 8012030305* 8012030519* 8012030521* 8012030505* 8012030279* | FOIA FOIA FOIA FOIA |
| PILANT, J. M. | 8012180128* 8012010405* 8012180232* 8012090335 8012240287 | 50-248 Q 50-248 Q 50-248 Q 50-248 P 50-248 P | POTAPOVS. U. POTAPOVS. U. POTAPOVS. U. POTAPOVS. U. POTE. D. R. | 8012270486 8012180602 8012170075 8012220081 8011170376* | QAYYY QAYYY QAYYY QAYYY 50-443 A | PRICE: H. L. PRICE: H. L. PRICE: H. L. PRICE: H. L. PRICE: H. L. | 8012030287# 8012030472# 8012030432# 8012030440# 8012030683# | FOIA FOIA FOIA FOIA |
| PILANT, J. M. PILANT, J. M. PILUGIR, N. W. PINA, R. PIRTLE, Q. L. | 8012230334 8012300623 8012160649 8012300476 8012010586* | 50-278 | POTER D. R. POTTER J. P. POTTER J. P. POTTER J. P. POTTER J. P. | 8011190383* 8012190606* 8012190177* 8012190235* 8012090167* | 50-443 A 27-47 27-47 27-47 50-393 Q | PRICE, H. L. | 8012030235* 8012030243* 8012030677* 8012030670* 8012030079* | FOIA FOIA FOIA FOIA |
| Pisello, D. M. Pister, K. S. Pittman, F. K. Plato, P. Plemmons, R. L. | 8012120608 8012110491 8012030178# 8012020224 8012020611 | PR Nureo Foia Reb Foia | POTTER, J. P. POTTER, J. P. POTTER, J. P. POTTER, J. F. POTTHOFF, F. | 8012100286* 8012310047* 8012170582* 8012170172* 8012100500 | 70-920 50-338 Q 50-327 Q 27-47 50-466 Q | PRICE, H. L. | 8012030127# 8012030137# 8012030144# 8012030152# 8012030161# | 27-10 27-10 27-10 27-10 27-10 |
| PLESBET, M. G. PLESBET, M. S. PLESBET, M. B. PLESBET, M. G. PLESBET, M. G. | 8012020784 8010140574 8012040642 8012040665 8011190374 | 50-312 0 ACR8 ACR8 ACR8 ACR8 | POTTHOFF.F.H. POWERS,D.A. PRATT.D. PRICE.H.L. PRICE,H.L. | 8012270207 8012070268 8012170686* 8012030374* 8012030178* | 50-466 Q TOPREP 50-289 H FOIA FOIA | PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. | 8012030387* 8012030041* 8012030516* 8012030486* 8012030495* | FDIA FOIA FOIA 27-10 27-10 |
| PLESSET, M. S. PLESSET, M. S. PLESSET, M. S. PLESSET, M. S. POCHAL, W. F. | 8012170388 8012170533 8012150066 8012310384 8012240372 | ACR8 ACR8 50-287 0 50-287 0 XPORTLIC | PRICE, H. L. | 8012030203* 8012030632* 8012030506* 8012030076* 8012030087* | FOIA FOIA FOIA FOIA FOIA | PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. FRICE, H. L. | 8012030470* 8012030463* 8012030424* 8012030430* 8012030021* | FOIA FOIA FOIA FOIA |
| POLEDNAK, A. P. POLK, A. POLLARD, R. D. POLLOCK, H. B. POLLOCK, K. B. | 8012220728 8012080251 8012290547 8012240221* 8012050373 | NUREO PR 50-289 T 50-322 Q 50-322 H | PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. | 8012030247* 8012030596* 8012030289* 8012030046* 8012030046* | FOIA FOIA 27-10 FOIA FOIA | PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, E. R. | 8012030404* 8012030412* 8012030013* 8012030387* 8012030429* | FOIA FOIA FOIA FOIA |
| POLLOCK, M. 8. | 8012300196 8012300203* 8012300196 8012300203* 8012100171* | 50-142 0 50-142 0 50-142 0 50-142 0 50-142 0 | PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, H. L. | 8012030408* 8012030417* 8012030434* 8012030333* 8012030338* | FOIA FOIA FOIA FOIA FOIA | PRICE: H. L. PRICE: E. R. PRICE: H. L. PRICE: H. L. PRICE: H. L. | 8012030313* 8012030482* 8012030273* 8012030237* 8012030325* | 27-10 FOIA FOIA 27-10 FOIA |
| POLLOCK, M. 8. POMPIAN, 6. POND, O. D. PORTER, W. L. PORTER, W. L. | 8012300479 8012180382 8012310638* 8012090367 8012300601 | 50-322 E XPORTLIC 50-213 P 50-247 0 50-349 A | Price, H. L. Price, E. R. Price, E. R. Price, E. R. Price, E. R. | 8012030343* 8012030351* 8012030207* 8012030318* 8012030328* | FOIA FOIA FOIA FOIA | PRICE, H. L. PRICE, H. L. PRICE, E. R. PRICE, E. R. PRICE, E. R. | 8012030228* 8012030238* 8012030145* 8012030272* 8012030581* | FOIA FOIA FOIA FOIA |
| PDTAPOVS.U. POTAPOVS.U. POTAPOVS.U. POTAPOVS.U. POTAPOVS.U. POTAPOVS.U. | 8012070057* 8012170476* 8012080260* 8012170433 8012020800* | QA999 QA999 QA999 QA999 QA999 | PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, E. R. | 8012030303# 8012030311# 8012030383# 8012030370# 8012030378# | 27-10 27-10 27-10 27-10 27-10 | PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, E. R. | 8012030564* 8012030567* 8012030570* 8012030576* 8012030295* | FOIA FOIA FOIA FOIA |
| POTAPOVB.U. POTAPOVB.U. POTAPOVB.U. POTAPOVB.U. POTAPOVB.U. | 8012170174* 8012020721* 8012230242* 8012180637 8012230178* | GA999 GA999 GA999 GA999 GA999 | PRICE, E. R. PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. | 8012030343* 8012030258* 8012030601* 8012030555* 8012030283* | FOIA 27-10 27-10 FOIA FOIA | PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, E. R. | 8012030278# 8012030315# 8012030321# 8012030530# 8012030537# | FOIA FOIA FOIA FOIA |
| POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. | 8012180623 8012090050* 8012080297* 8012080252 8012080252 | 0A797 0A797 0A797 0A797 0A777 | PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. | 8012030517* 8012030196* 8012030192* 8012030072* 8012030078* | FOIA FOIA 27-10 FOIA FOIA | PRICE, E. R. PRICE, H. L. PRICE, E. R. PRICE, M. R. PRICE, D. J. | 8012030628* 8012030314* 8012030191* 8012090302* 8012220070 | FOIA FOIA FOIA 50-397 F |
| POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. | B012170445* B012300016* B012040013 B01217006B* B012080257* | QA999 QA999 GA999 QA999 QA999 | PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. PRICE, H. L. | 8012030559* 8012030174* 8012030629* 8012030033* 8012030136* | FOIA FOIA FOIA FOIA | PRIMM, L. W. PROFT, T. L. PROFT, T. L. PRUS, L. B. PUCKETT, J. M. | 8012220390 8012100073* 8012100073* 8012020252* 8012190440* | 50-369 H 50-313 P 50-313 P 40-8709 50-324 Q |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEOURY | ROHTUA | ACCESSION NUMBER | SUBJECT CATEGORY. |
|--|---|--|--|--|---|--|--|--|
| PUGH, L. C. | 8012080261 | REGGD | REID, R. W. | 8012070106 | 50-313 P | RIVARD, J. B. RIVENBARK, G. W. RIZZO, P. O. RIZZO, P. G. RIZZO, P. G. | B012170530 | NUREQ |
| PURCELL, J. F. | 8012170130 | 50-367 R | REID, R. W. | 8012070110* | 50-313 P | | B012310470* | 50-373 Q |
| PURPLE, R. A. | 8012040256 | 50-437 H | REID, R. W. | 8012070115* | 50-313 P | | B012100565* | 50-317 8 |
| PUSHECK, B. N. | 8012080529# | 50-255 P | REID, R. W. | 8012170497 | 50-287 F | | B012010336* | 50-318 8 |
| GUATTROCCI, J. | 8012160322 | HISC | REID, R. W. | 8012040242 | 50-287 Q | | B012020600* | 50-318 8 |
| GUICK, D. R. | 8012070219* | 50-395 Q | REID, R. W. | 8012080704 | 50-267 P | RIZZO, P. O. | 8012030733* | 50-318 8 |
| GUICK, D. R. | 8012160041* | 50-302 G | REID, R. W. | 8012120240 | 50-312 P | RIZZO, P. O. | 8012100557* | 50-318 8 |
| GUICK, D. R. | 8012170585* | 50-281 Q | REID, R. W. | 8012120246* | 50-312 P | RIZZO, P. O. | 8012160387* | 50-318 8 |
| GUICK, D. R. | 8012310242* | 50-261 G | REID, R. W. | 8012120278* | 50-312 P | RIZZO, P. O. | 8012160394* | 50-317 8 |
| GUIGLEY, T. H. | 8012010221 | 40-8743 | REID, R. W. | 8012170479 | 50-277 F | ROBERTB, H. | 8012020835* | 50-320 H |
| QUIOLEY, T. W. | 8012180374 | 40-8743 | REID, R. W. | 9012300274 | 50-312 F | ROBERTS, F. P. ROBERDS, H. W. ROBERDS, H. W. ROBERDS, H. W. ROBERDS, M. J. | 8012230323 | NUKEQ |
| QUIOLEY, T. W. | 8012240508 | 40-8743 | REID, R. H. | 8012270377 | 50-287 P | | 8012170104* | GA777 |
| QUIOLEY, T. W. | 8012240439 | 40-8743 | REID, R. H. | 8012270390# | 50-289 P | | 8012080307* | GA777 |
| QUIOLEY, T. W. | 8012240433 | 40-8743 | REID, R. W. | 8012180134 | 50-346 B | | 8012300026* | GA777 |
| RADER, R. M. | 8012120542 | 27-39 | REID, R. W. | 8012270480 | 50-269 P | | 8012240181* | 50-382 G |
| RADER, R. H. | 8012120542 | 27-39 | REID, R. W. | 8012270488 | 50-277 F | ROBERTS, E, | 8012020765 | 50-395 M |
| RADER, M. B. | 8012020546* | 50-331 8 | REID, R. W. | 8012270476 | 50-319 P | ROBERTSON, J. C. | 8012080641* | CONTRACT |
| RADER, M. B. | 8012170579* | 50-331 8 | REID, R. W. | 8012310085 | 50-269 Q | ROBERTS, F. P. | 8012310287 | NUREO |
| RADER, M. S. | 8012170650* | 50-331 8 | REID, R. W. | 8012240176 | 50-277 P | ROBERTS, I. C. | 8012310387 | ORO |
| RADER, M. S. | 8012300468* | 50-331 8 | REID, R. W. | 80122402024 | 50-277 P | ROBINGON, D. L. | 8012040698* | 50-316 G |
| RAGER: M. B. | 8012270414* | 50-331 8 | REID, R, W. | 8012240210# | 50-277 P | ROBINSON, P. ROCKHOLD, H. G. ROCKHOLD, H. C. RODGERS, J. C. RODKEY, L. S. | 8012240407* | State Prog |
| RAGER: M. B. | 8012270428* | 50-331 B | REID, R. W. | 8012300340 | 50-313 P | | 8012170061 | 50-409 P |
| RAKE: A. V. | 8012220027 | PR | REIDHAAR, D. L. | 8012300105 | 50-142 0 | | 8012170547 | 50-312 IP |
| RAMPY: L. W. | 8012120037 | PR | REIMER, E. T. | 8012190057# | 50-317 F | | 8012220252* | FOIA |
| RAMSDELL: J, V. | 8012170240 | REGGD | REIS, E. J. | 8012300004 | 50-498 Q | | 8012080330 | PR |
| RANDALL, F. N. RANDALL, F. N. RANDAZZA, J. B. RANDAZZA, J. B. RANDOLPH, J. | 8007180046* 8010280584* 8012170467 8012230430 8012240078* | 71-9073 71-9079 9 906-05 9 906-05 701831MMO | REITER, L. REKITO, W. A. REKITO, W. A. REMLEY, M. E. REMLEY, M. E. | 8012270640* 8012100372* 8012220006* 8012020377 8012050133* | 50-409 T 50-387 Q 50-29 Q 70-25 71-35 | RODRIQUEZ, R. J. ROGERS, L. R. ROGERS, L. R. ROGERS, L. R. ROGERS, L. R. | 8012120480 8012030384* 8012030493* 8012030270* 8012030600* | 50-312 R FOIA FOIA FOIA |
| RANDOLPHIK.L. | 8012170208 | RES | RENBEROER, D. L. | 8012030763 | 50-397 Q | ROGERS, L. R. | 8012030063* | FOIA |
| RANDOLPHIJ.K. | 8012020550* | 50-272 8 | RENBEROER, D. L. | 8012170244 | REGOD | ROGERS, L. | 8012110707* | FOIA |
| RANSONEJJ.K. | 8012180443 | WABTE MOT | REGUA, O. | 8012110153 | 50-309 P | ROGERS, W. G. | 8012310482* | 50-346 G |
| RAPKINIA. | 8012020695 | 50-367 0 | REGNIKOFF, M. | 8012020727 | 50-201 P | ROGERS, J. G. | 8012170658 | 50-289 H |
| RAPKINIA. | 8012020690 | 50-367 0 | RETTENMAIER, R. | 8012080707 | PR | ROHATGI, U. S. | 8012220615 | NUREG |
| RASKIN, D. B. | 8012270091 | 50-466 G | REVELEY, W. T. | 8012300572 | 50-516 0 | RDMAN, T. W. | 8012140480* | 50-220 R |
| RASHUSSEN, N. C. | 8012080794 | NUREO | REVELEY, H. T. | 6012300572 | 50-516 0 | ROOD, H. | 8012100044 | 50-361 F |
| RATHLESBERGER | 8012030836 | FR | REYES, L. A. | 8012040115* | 50-346 0 | ROOD, H. | 8012100079 | 50-361 A |
| RATHLESBERGER | 8012040108 | PR | REYES, L. A. | 8012310482* | 50-346 0 | ROONEY, M. A. | 8012270327 | 70-1308 |
| RATHLESBERGER | 8012240399* | State Prog | REYNOLDS, W. | 8012020736 | FOIA | ROOT, L. D. | 8012110769* | 50-331 G |
| RATTA, A. D. RATTA, A. D. RAUSCH, T. J. RAUSCH, T. J. RAVENSCROFT, N. | 8012100247* 8012110171* 8012310212 8012230065 8012010545 | 70-1143 70-33 50-295 Q 50-10 Q 70-2372 | REYNOLDS; J. REYNOLDS; N. S. REYNOLDS; N. S. REYNOLDS; N. S. REYNOLDS; J. R. | 8011250100 8012170371 8012100088 8012180353* 8012080513 | 50-275 | ROOT, L. D. ROOT, L. D. ROOT, L. D. ROOT, L. D. ROOT, L. D. | 8011170078 8012070318 8012240263* 8012050397 8012070274 | 50-331 Q 50-331 P 50-331 G 50-331 P 50-331 Q |
| REAMER, C. W. | 8012310391 | CG/MISBION | REYNOLDS, J. R. REYNOLDS, N. S. REYNOLDS, N. S. REYNOLDS, N. S. REYNOLDS, J. R. | 8012270120 | 50-275 0 | ROOT, L. D. | 8012230297 | 50-331 P |
| REAVIS, J. A. | 8012190619* | 50-269 R | | 8012080472 | 50-313 0 | ROOT, L. D. | 8012230457 | 50-331 P |
| REBELOWSKI, T. | 8012300003* | 50-247 Q | | 8012270647 | 50-445 0 | ROBA, F. | 8012110439* | 50-205 P |
| REBELOWSKI, T. A. | 8012180393* | 50-247 Q | | 8012270647 | 50-445 0 | ROBE, R. E. | 8012030130* | 27-39 |
| REOMOND, R. F. | 8012110796* | 50-150 Q | | 8012270372 | 50-275 0 | ROBE, C. | 8012010589* | 50-324 U |
| REED, C. W. | 8012030349* | FOIA | REYNOLDS, N. S. | 8012300057 | 50-445 Q | ROSELLINI, A. D. | 8012030143* | FOIA |
| REED, C. | 8012040333* | 50-10 8 | | 8012300057 | 50-445 Q | ROSENFELD, S. | 8012170129 | PR |
| REED, C. | 8012080779 | PR | | 8012170442* | 50-275 Q | ROSS, D. F. | 8012010476* | 50-438 A |
| REED, C. | 8012270466 | 50-237 0 | | 8012270338 | 50-445 Q | ROSS, W. J. | 8012120343 | 50-334 P |
| REED, C. | 8012270470 | 50-237 0 | | 8012290338 | 50-445 Q | ROSS, M. J. | 8012100177 | 50-289 T |
| REED, O. H. REED, E. C. REED, H. R. REED, C. REHM, T. A. | 8012170252 8012040293 8012170453# 8012310282 8012020711 | REGOD 50-289 P 50-289 H 50-237 P COMMISSION | REYNOLDS: J. R. REYNOLDS: N. S. REYNOLDS: N. S. REZNOR: W. M. RHOADS: O. O. | 8012300364 8012310270 8012310270 8012310221 8012080125# | 50-275 | ROSB, W. J. ROSB, T. K. ROSB, W. J. ROSS IN, F. ROSS IN, A. D. | 8012110037 8012010275* 8012170239 8012270562* 8012300151 | 50-334 Q 50-280 P 50-272 P 50-289 T 50-289 H |
| REHM, T. A. | 8012070028 | ORO | RHODE, C. K. RHODE, C. K. RHODE, G. K. RHODE, G. K. RHODE, G. K. RIAZ, A. | 8012010350 | 50-410 G | ROTH, E. B. | 8012030173* | F01A |
| REHM, T. A. | 8012100174 | COMMISSION | | 8012030810 | 50-410 G | ROTH, E. B. | 8012030107* | F01A |
| REHM, T. A. | 8012170123 | COMMISSION | | 8012170448 | 50-410 B | ROTH, J. | 8012240261* | 70-398 |
| REHM, T. A. | 8012300778 | COMMISSION | | 8012230462 | 50-410 B | ROTH, J. | 8012170687* | 50-201 G |
| REHNSTROH, J. B. | 801230078 | 50-331 I | | 8012100185 | PR | ROTH, J. | 8012310266 | 70-364 |
| REID, R. W. | 8012150037 | 50-313 F | RIGE, K. M. | 8012080657 | 40-8743 | ROTHE, P. H. | 8012230509 | NUREG |
| REID, R. W. | 8012010446 | 50-289 F | RIGE, K. M. | 8012240222 | 40-8743 | ROTHSCHILD, M. U. | 8012080013 | 50-500 9 |
| REID, R. W. | 8012020036 | 50-269 P | RIGHARDBON, C. A. | 8012010013 | 71-9141 | ROTHSCHILD, M. U. | 8012230012 | 50-445 H |
| REID, R. W. | 8012020042* | 50-269 P | RIGHARDBON, C. | 8012100461 | 50-271 H | ROTHSCHILD, M. U. | 8012230017 | 70-1308 |
| REID, R. W. | 8012020057* | 50-269 P | RIGHARDB, R. L. | 8012160642 | PR | ROTHSCHILD, M. U. | 8012270424 | 50-445 H |
| REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W. | 8012010421 8012010431* 8012010441* 8012020807 8012030845 | 50-366 P 50-366 P 50-366 P 50-267 P 50-269 P | Richardbon, D. Rick, S. Ridoway, K. R. Ridoway, D. A. Ridoway, D. A. | 8012150164 8012160583 8012110753* 8012290663 8012290663 | 50-287 H PR 50-186 Q 50-320 Q | ROTHBCHILD, M. U. ROTHBCHILD, M. U. ROUBE, L. C. ROUBE, L. C. ROUBE, L. C. | 8012300215 8012300258 8012010191 8012080685 8012040166 | 50-500 Q 50-445 Q 70-1173 50-201 P 70-1308 |
| REID, R. W. | 8012090047 | 50-346 P | RIEDER, A. E. | 8012110306* | 71-400 | ROUSE, L. C. | 8012080790 | 70-1193 |
| REID, R. W. | 8012080535 | 50-302 P | RIEBLANDJ J. | 8012180261 | 50-284 8 | ROWDEN, M. A. | 8012020834 | 50-367 U |
| REID, R. W. | 8012080538* | 50-302 P | RIETHLE, W. E. | 8012020482 | 50-287 R | ROWLEY, E. | 8012160543+ | 50-237 B |
| REID, R. W. | 8012080555* | 50-302 P | RIETVELD, P. A. | 8012170307 | PR | RUDDEN, M. A. | 8012100022+ | CONTRACT |
| REID, R. W. | 8012240093 | 50-346 P | RILEY, R. G. | 8012120270 | NUREQ | RUDISILL, O. D | 8012010302+ | 71-399 |
| REID, R. W. | 8012240096* | 50-346 P | RILEY, J. L. | 8012270319* | 70-2623 | RUDOLPH, J. RUITER, O. H. RUMPF, R. E. RUNDO, J. RUPPE, P. E. | 8012070387* | 50-346 8 |
| REID, R. W. | 8012240100* | 50-346 P | RILEY, J. L. | 8012270052 | 70-2623 | | 8012100328* | 50-305 R |
| REID, R. W. | 8012010074 | 50-277 P | RINDE, A, | 8012120613 | PR | | 8012080475* | 50-407 P |
| REID, R. W. | 8012010078* | 50-277 P | RING, M. | 8012020780* | 50-373 Q | | 8012220728 | NUREO |
| REID, R. W. | 8012010085* | 50-277 P | RITSHER, J. A. | 8011170371 | 50-443 A | | 8012020838* | 50-367 U |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | Accession Number | SUBJECT CATEODRY |
|--|--|---|---|--|--|--|---|--|
| RUSSELL, D. R. | 8012230201 | NUREO | BCHMITZ, H. K. | 8012030714* | XPORTLIC | SEIG, M. | 8012300085 | 50-247 H |
| RUSSELL, J. L. | 8012270144 | PR | BCHMIDT, A. D. | 8012100522 | 50-335 8 | SEIKEN, B. J. | 8012040403 | 50-482 S |
| RUSSELL, L. B. | 8012010322 | 50-318 8 | BCHMIDT, A. D. | 8012100532 | 50-335 8 | SEIKEN, B. J. | 8012300717 | 50-482 Q |
| RUSSELL, L. B. | 8012010356 | 50-317 8 | BCHMIDT, A. D. | 8012100474 | 50-335 8 | SELIGMAN, B. J. | 801230002 | PR |
| RUSSELL, L. B. | 8012020612 | 50-317 8 | BCHMIDT, A. D. | 8012100404 | 50-335 8 | SELLG, D. | 8012020165 | 50-352 A |
| RUSSELL, L. B. | 8012020593 | 50-318 8 | SCHMIDT, A. D. SCHMIDT, F. H. SCHMIDT, A. D. SCHMIDT, A. D. SCHMIDT, A. D. | 8012020551 | 50-33\$ 8 | BEYFRIT, K. V. | 8012230248* | GA779 |
| RUSSELL, L. B. | 8012020506 | 50-317 8 | | 8012080355 | PR | BEYFRIT, K. V. | 8012170731 | 50-482 Q |
| RUSSELL, L. B. | 8012030731 | 50-318 8 | | 8012020469 | 50-251 8 | BEYFRIT, K. V. | 8012170737 | 50-458 Q |
| RUSSELL, L. B. | 8012100553 | 50-318 8 | | 8012020538 | 50-250 8 | BEYFRIT, K. V. | 8012170740 | 50-498 Q |
| RUSSELL, L. B. | 8012100561 | 50-317 8 | | 8012020561 | 50-335 6 | BEYFRIT, K. V. | 8012170744 | 50-445 Q |
| RUSSELL, L. B. | 8012100539 | 50-317 8 | SCHMIDT, A.D. SCHMIDT, A.D. SCHMIDT, A.D. SCHMIDT, A.D. SCHMIDT, A.D. SCHMIDT, A.D. | B012020534 | 50-335 8 | SEYFRIT, K. V. | 8012170746 | 50-382 Q |
| RUSSELL, L. B. | 8012150072 | 50-317 F | | B012020501 | 50-335 8 | SEYFRIT, K. V. | 8012190098* | QA999 |
| RUSSELL, L. B. | 8012160381 | 50-318 B | | B012020548 | 50-335 8 | SEYFRIT, K. V. | 8012170312 | 50-247 Q |
| RUSSELL, L. B. | 8012160390 | 50-317 8 | | B012030452 | 50-335 8 | SEYFRIT, K. V. | 8012170315 | 50-298 Q |
| RUSSELL, L. B. | 8012220401 | 50-318 S | | B012160466 | 50-250 R | SEYFRIT, K. V. | 8012170318 | 50-285 Q |
| RUBBELL, W, T. | 8012240489 | 50-10 P | SCHMIDT, A.D. | 8012180258 | 50-250 R | SEYFRIT, K. V. | 8012170322 | 50-313 Q |
| RUBBELL, L. B. | 8012230361 | 50-317 S | SCHMIDT, T. | 8012170504 | 50-466 H | SEYFRIT, K. V. | 8012160058 | 50-267 Q |
| RUBBELL, L. B. | 8012230405 | 50-317 S | SCHMIDT, H. C. | 8012300551 | 50-445 K | SEYFRIT, K. V. | 8012160059 | 50-298 Q |
| BACKETT, K. E. | 8012220670 | NUREO | SCHNAUTZ, C. E, | 8012300769 | XPORTLIC | SEYFRIT, K. V. | 8012160062 | 50-285 Q |
| BACKB, I, J. | 8012020738 | NUREO | SCHNAUTZ, C. E. | 8012300765 | XPORTLIC | SEYFRIT, K. V. | 8012160065 | 50-313 Q |
| SACKS: I. J. | 8012020744 | NUREO | SCHNEIDER, F. W. | 8012080122* | 50-272 Q | SEYFRIT, K. V. | 8012180122 | 50-298 Q |
| BACKS: I. J. | 8012040070 | NUREO | SCHNEIDER, F. W. | 8012080131* | 50-272 Q | SEYFRIT, K. V. | 8012170349 | 50-482 Q |
| BADWITH: L. | 8012020781 | FOIA | SCHNEIDER, F. W. | 8012040621 | 50-272 Q | SEYFRIT, K. V. | 8012170351 | 50-382 Q |
| BAEGER: J. | 8012040407* | 50-267 P | SCHWEIDER, F. W. | 8012020370 | 50-272 Q | SEYFRIT, K. V. | 8012170356 | 50-498 Q |
| BAHA: P. | 8012220615 | KUREO | SCHWEIDER, F. W. | 8012190225* | 50-272 P | BEYFRIT, K. V. | 8012170360 | 50-449 Q |
| Baha, P. | 8012240156 | RES | ECHOCK, W. ECHOENDERO, E. ECHOTT, Q. L. ECHROEDER, F. ECHROEDER, F. | 8012020351* | 100FR | BEYFRIT, K. V. | 8012170362 | 50-313 0 |
| Baha, P. | 8012180310 | 50-312 P | | 8012300733* | 30-466 T | BEYFRIT, K. V. | 8012170345 | 50-285 0 |
| Balama, A. I. | 8012100033* | PR | | 8012040555 | ACRS | BEYFRIT, K. V. | 8012170806 | 50-267 0 |
| Baldarini, J. C. | 8012080223 | REGOD | | 8012080118* | FOIA | BEYFRIT, K. V. | 8012170809 | 50-285 0 |
| Baldarini, J. C. | 8012070089 | PR | | 8012160561 | REGOD | BEYFRIT, K. V. | 8012170812 | 50-298 0 |
| BALTZMAN, J. | 8012030752 | 50~413 M | BCHULTZ, K. B. | 8012220275* | FOIA | SEYFRIT, K, V. | 8012170816 | 50-313 Q |
| BALTZMAN, J. | 8012010582 | 50~358 M | BCHULZ, R. D. | 8012150268* | 50-331 Q | SEYFRIT, K, V. | 8012170818 | 50-382 Q |
| BALTZMAN, J. | 8012050418 | 50~97 J | BCHULTZ, H. B. | 8012290538* | 50-367 Q | SEYFRIT, K, V. | 8012170822 | 50-445 Q |
| BAMMONB, J. H. | 8012120013 | PR | BCHULZE, R. | 8012170650 | 90-289 H | SEYFRIT, K, V. | 8012170825 | 50-498 Q |
| BAMB, D. W. | 8012220623 | NUREQ | BCHULZE, R. | 8012290330 | 50-387 Q | SEYFRIT, K, V. | 8012170826 | 50-458 Q |
| BAMUELSON, D. R. | 8012080707 | PR | SCHULLER, C. R. | 8012190537 | NUREO | SEYFRIT, K. V. | 8012170832 | 50-482 0 |
| BANDERB, L. A. | 8012240130 | 70-143 | SCHUMACHER, J. | 8012110852 | PR | SEYFRIT, K. V. | 8012230022 | 50-298 0 |
| BANTANGELO, J. C. | 8012030335* | Foia | SCHUMACHER, J. L. | 8012110021 | PR | SEYFRIT, K. V. | 8012230024 | 50-285 0 |
| BANTANGELO, J. C. | 8012030352* | Foia | SCHUSTER, M. D. | 8012290016 | 50-312 B | SEYFRIT, K. V. | 8012230025 | 50-267 0 |
| BANTANGELO, J. C. | 8012030340* | Foia | SCHUYLER, J. O | 8012040119 | PR | SEYFRIT, K. V. | 8012230028 | 50-313 0 |
| BANTANOELO, J. C. | 8012030336* | FQIA | SCHUYLER, J. D. | 8012300545 | 50-275 F | SEYFRIT, K. V. | 8012010376 | 50-258 Q |
| BANTANOELO, J. C. | 8012030410* | FQIA | SCHWARTZ, H. H. | 8012170613* | 50-287 0 | SEYFRIT, K. V. | 8012100602 | 50-458 Q |
| BANTANOELO, J. C. | 8012030406* | FQIA | SCHNENCER, A. | 7907240626 | 50-29 G | SEYFRIT, K. V. | 8012100606 | 50-445 Q |
| BANTANOELO, J. C. | 8012030371* | FQIA | SCHHENDIMAN, L. C | 8012220678 | NUREO | SEYFRIT, K. V. | 8012100613 | 90-492 Q |
| BARBANEG, P. B. | 8012020828* | 50-170 H | SCHWENSFEIR, R. | 8012080791 | 70-33 | SEYFRIT, K. V. | 8012100615 | 50-498 Q |
| BARBOUR, B. | 8012150055* | 50-346 R | BCHWEIBINZ, E. R. BCHWENCER, A. BCHWENBFEIR, R. BCOTT, W. J. BCOTT, D. J. | 8012240072* | 50-546 Q | SEYFRIT, K. V. | 8012100617 | 50-362 Q |
| BASTRE, C. | 8012170166 | REG | | 8012040187 | 50-327 A | SEYFRIT, K. V. | 8012100623 | 50-267 Q |
| BAUNDERB, G. A. | 8012100483 | 40-8693 | | 8012190043 | 70-33 | SEYFRIT, K. V. | 8012100625 | 50-313 Q |
| BAUNDERB, G. A. | 8012300508 | 40-8745 | | 8012030440* | FOTA | BEYFRIT, K. V. | 8012100628 | 50-285 Q |
| BAVAOLIG, F. J. | 8012110172 | PR | | 8012020583 | 50-249 S | BEYFRIT, K. V. | 8012100627 | 50-278 Q |
| Samicky, W. | 8012100229# | 50-333 | BCOTT, D. J. | 8012160538 | 50-237 S | SEYFRIT, K. V. | 8012030894 | 50-498 Q . |
| Sayers, E. D. | 8012290174 | | BCOTT, D. J. | 8012160417 | 50-10 R | BEYFRIT, K. V. | 8012030897 | 50-445 Q |
| Scarand, R. A. | 8012020125 | | BCOTT, D. J. | 8012230500 | 50-237 S | BEYFRIT, K. V. | 8012030898 | 50-382 Q |
| Scarand, R. A. | 8012160556 | | BCROGOB: A. C. | 8012080643 | WASTE HOT | BEYFRIT, K. V. | 8012030899 | 50-458 Q |
| Scarand, R. A. | 8012010616 | | BEEKER-WALKER | 8012120310 | PR | BEYFRIT, K. V. | 8012030901 | 50-482 Q |
| SCARAND, R. A. | 8012240112 | 40-1162 | SEELEY, Q. T. | 8012080110 | PR | SEYFRIT, K. V. | 8012030904 | 50-295 0 |
| SCARAND, R. A. | 8012160763 | 40-3453 | SEELEY, Q. T. | 8012070034 | PR | SEYFRIT, K. V. | 8012030906 | 50-295 0 |
| SCARAND, R. A. | 8012170251 | 40-299 | SEQAL, Q. | 8012270230* | GRO | SEYFRIT, K. V. | 8012030909 | 50-313 0 |
| SCARAND, R. A. | 8012160287 | 40-8084 | SEQE, Q. | 8012030703* | REVIEW GRP | SEYFRIT, K. V. | 8012170802 | 50-267 0 |
| SCARAND, R. A. | 8012160548 | 40-6622 | SEQE, Q. | 8012030702 | REVIEW GRP | SEYFRIT, K. V. | 8012030743 | 50-298 0 |
| SCARAND, R. A. SCARAND, R. A. SCARAND, R. A. SCARAND, R. A. SCARAND, R. A. | 8012160175 8012170262 8012270216 8012220405 8012300288 | 40-8304 40-8602 40-3453 WABTE MOT WABTE MOT | SEOE. Q. SEOE. Q. SEOE. Q. SEOE. Q. SEOE. Q. | 8012030927* 8012030917 8012030870* 8012030877* 8012030877* | REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP | SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. | 8012080575 8012080580 8012080584 8012080591 8012080595 | 50-382 Q 50-498 Q 50-445 Q 50-458 Q 50-313 Q |
| SCHADT, W. W. SCHAEFER, W. W. SCHAPKER, J. SCHAPKER, J. SCHENDEL, K. R. | 8012050600 8012240002 8012160555* 8012110016* 8012050075 | PR PR 50-456 Q 50-461 Q 40-8385 | SEGE, G. SEGE, G. SEGE, G. SEGE, G. BEGEV, A. | 8012030875 8012030870 8012030866 8012030895 8012230104 | REVIEW ORP REVIEW ORP REVIEW ORP NUREO | SEYFRIT, K. V. BEYFRIT, K. V. SEYFRIT, K. V. BEYFRIT, K. V. SEYFRIT, K. V. | 8012080611 8012080618 8012080675 8012180372* 8012080677 | 50-267 Q 50-285 Q 50-482 Q 80-445 Q 50-267 F |
| SCHENDEL: K. R. | 8012040722 | 40-8502 | SEQEV, A. SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C. | 8012120570 | NUREO | SEYFRIT, K. V. | 8012030820 | 50-298 P |
| SCHENDEL: K. R. | 8012170542 | 40-8502 | | 8012020757 | 50-462 G | SEYFRIT, K. V. | 8012030826 | 50-267 P |
| SCHERER: A. E. | 8012110800* | FOIA | | 8012020737 | 50-448 G | SEYFRIT, K. V. | 8012030837 | 50-313 P |
| SCHERER: A. E. | 8012080147 | PR | | 8012040032 | 50-498 G | SEYFRIT, K. V. | 8012030844 | 50-285 P |
| SCHERER: A. E. | 8012150098* | 50-368 P | | 8012190537 | 50-498 G | SEYFRIT, K. V. | 8012040014 | 50-285 Q |
| BCHERER, A. E. | 8012100010 | PR | BEIDLE, W. C. | 8012240167 | 50-382 | BEYFRIT, K. V. | 8012040018 | 50-298 0 |
| BCHERER, A. E. | 8012070085 | PR | BEIDLE, W. C. | 8012100544 | | BEYFRIT, K. V. | 8012040024 | 50-313 0 |
| BCHERER, A. E. | 8012150202 | TOPREP | BEIDLE, W. C. | 8012190407 | | BEYFRIT, K. V. | 8012040027 | 50-267 0 |
| BCHERER, A. E. | 8012160197 | 50-470 A | BEIDLE, W. C. | 8012190618 | | BEYFRIT, K. V. | 8012040106 | 50-458 0 |
| BCHERR, B. J. | 8012270313 | 70-2623 | BEIDLE, W. C. | 8012180369 | | BEYFRIT, K. V. | 8012040123 | 50-498 0 |
| SCHIRMER, R. E. | 8012120324 | NUREQ | SEIDLE, W. C. | 8012180372# | 50-445 O | SEYFRIT, K. V. | 8012040125 | 50-445 Q |
| SCHLIGHT, F. O. | 8012300638* | 30-466 T | SEIDLE, W. C. | 8012190629 | 50-459 Q | SEYFRIT, K. V. | 8012040127 | 50-382 Q |
| SCHLIGHT, F. O. | 8012300702* | 50-466 T | SEIDLE, W. C. | 8012190529 | 50-458 Q | SEYFRIT, K. V. | 8012040129 | 50-482 Q |
| SCHLOMER, E. A. | 8012220388* | 50-320 P | SEIDLE, W. C. | 8012190642 | 50-478 Q | SEYFRIT, K. V. | 8012050011 | 50-445 Q |
| SCHNEL, O. A. | 8012220478 | NUREO | SEIDLE, W. C. | 8012220023 | 50-478 Q | SEYFRIT, K. V. | 8012050013 | 50-482 Q |

| AUTHOR | ACCESSION NUMBER | SUBJECT | AUTHOR | ACCESSION NUMBER | GUBJECT CATEOURY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|--|--|--|--|---|--|---|--|--|
| SEYFRIT, K. V. | 8012050015 | 50-458 G | SHIEH, R. C. | 8012010152* | 71-9073 | BMATHERB. J. B. | 8012070075* | 50-344 G |
| SEYFRIT, K. V. | 8012050018 | 50-498 G | SHIEH, R. C. | 8012010146* | 71-9073 | BMILEY, D. C. | 8012100226 | PR , |
| SEYFRIT, K. V. | 8012050021 | 50-382 G | SHIEH, R. C. | 8012010262* | 71-9073 | BMITH, F. L. | 8012030660* | FOIA |
| SEYFRIT, K. V. | 8012100638 | 50-498 A | SHIEH, R. C. | 8012010265* | 71-9073 | BMITH, C. N. | 8012110528* | 70-143 |
| SEYFRIT, K. V. | 8012160003 | 50-498 G | SHIELD, W. F. | 8012090302* | 50-397 F | SMITH, G. H. | 8012080175* | 50-272 G |
| SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. | 8012140071 8012140074 8012140077 8012140078 8012140102 | 50-445 0 50-362 0 50-458 Q 50-482 Q 50-48B Q | SHIELDS, S. W. SHIELDS, S. W. SHIELDS, S. W. SHIELDS, S. W. | 8012040347* 8012220168 8012190296* 8012050103 8012040394 | 50-546 G 50-546 G GA999 PR 50-546 B | Smith, O. H. Smith, Q. H. Smith, Q. H. Smith, C. N. Smith, M. E. | 8012090158* 8012090259* 8012100277* 8012310619* 8012080280 | 50-333 Q 70-820 70-820 70-143 REGOD |
| SEYFRIT, K. V. | 8012160104 | 50-382 0 | Shields, S. W. | 8012040400 | 50-546 B | Smith, R. H. | 8012110435* | 70-1426 |
| SEYFRIT, K. V. | 8012160111 | 50-478 0 | Shields, S. W. | 8012220228 | 50-546 B | Smith, R. H. | 8012110504 | 71-400 |
| SEYFRIT, K. V. | 8012160112 | 50-482 0 | Shields, S. W. | 8012220323 | 50-546 B | Smith, O. H. | 8012190548 | 70-487 |
| SEYFRIT, K. V. | 8012160115 | 50-445 0 | Shields, S. W. | 8012220337 | 50-546 B | Smith, R. H. | 8012080817 | 71-395 |
| SEYFRIT, K. V. | 8012170318 | 50-482 0 | Shikarski, W. | 8012020351* | 10CFR | Smith, G. H. | 8012190673 | 50-336 Q |
| SEYFRIT, K. V. | 8012180226 | 50-298 G | Shima, 8 | 8012230206* | XPORTL.IC | Smith, V. | 8012030859* | MISC |
| SOANOA, F. S. | 8012170146 | PR | Shima, 8. | 8012230206* | XPORTL.IC | Smith, M. | 8012220049* | 50-220 Q |
| SHACKLETON, D. C. | 8012319508* | 50-460 G | Shinefluo, M. | 8012240403 | 50-295 H | Smith, P. A. | 8012110688 | CONTRACT |
| SHAFER, N. D. | 8012170711* | 50-348 G | Shively, C. N. | 8012010381* | 50-368 8 | Smith, O. H. | 8012100256 | 70-820 |
| SHAFFNER, J. A. | 8012180393 | 27-39 | Shively, C. N. | 8012010324* | 50-368 5 | Smith, O. H. | 8012240253* | 70-398 |
| EHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHAMLA, W. A. SHAMBAKY, M. | 8012160493 8012190500 8012180281 8012020476 8012190092 | 50-315 8 50-316 R 50-315 8 50-263 8 50-287 8 | SHIVELY, C. N. SHIVELY, C. N. SHIVELY, C. N. | 8012010340* 8012010361* 8012010404* 8012010406* 8012020466* | 50-368 8 50-313 8 50-313 8 50-368 6 50-313 8 | BMITH, F. J. SMITH, O. H. BMITH, O. H. BMITH, O. H. BMITH, O. H. | 8012020674* 8012090149 8012090247 8012190724 8012190685 | 50-289 0 50-333 0 70-820 50-47 0 50-201 0 |
| SHANBAKY, M. | 8012170110 | 50-287 S | SHIVELY, C. N. SHIVELY, C. N. SHIVELY, C. N. | 8012070375* | 50-348 B | Smith, P. A. | 8012040159 | 27-39 |
| SHAPAR, H. K. | 8012270067* | COMMISSION | | 8012070428* | 50-348 B | Bmith, E. K. | 8012010095 | PR |
| SHAPAR, H. K. | 8012170463* | FR | | 8012070463* | 50-348 B | Smith, J. H, | 8012100190 | RES |
| SHAPAR, H. K. | 8012270527 | 50-445 G | | 8012150088* | 50-348 B | Smith, G. H. | 8012240247 | 70-398 |
| SHAPAR, H. K. | 8012270127 | 50-263 G | | 8012150070* | 50-348 B | Smith, R. D. | 8012030900 | 27-48 |
| SHAPARIH, K. SHAPIROIJ. SHAPIROIE. J. SHARPIH. SHAWIE. I. | 8012230027 8012110365 8012180203 8012300156 8012080237 | 50-443 G PR PR 50-287 H PR | SHIVELY, C. N. SHIVELY, C. N. SHOEMAKER, C. L. SHOLLY, B. C. SHOLLY, B. C. | 8012180243* 8012220466* 8012160313 8012120657* 8012300264 | 50-368 8 50-368 9 50-317 J 50-320 H 50-287 0 | SMITH, O. H. BMITH, R. L. BMITH, R. L. BMITH, R. L. BMITH, I. W. BMITH, P. A. | 8012220348* 8012020420 8012010089 8012240014 8012050368 | 50-289 0 50-271 8 50-271 P 50-289 0 50-209 H |
| SHAW, R. | H012160554* | 50-219 8 | SHORB, E. M. | 8012300708 | 50-367 | SMITH, R. H. | 8012180353* | 50-247 Q |
| SHEA, J. R. | H012110445* | FOIA | SHORB, E. M. | 8012020427 | | SMITH, R. H. | 8012190044 | RES |
| SHEA, J. R. | B012030708* | XPORTLIC | SHORB, E. M. | 8012240150 | | SMITH, P. D. | 8012120307 | NUREO |
| SHEA, J. R. | B012290587* | SECY | SHRIVER, B. L. | 8012290121 | | SMITH, E. R. | 8012100492 | 50-289 H |
| SHEA, J. R. | H012120560* | XPORTLIC | SHULER, P. E | 8012020294* | | SMITH, R. L. | 8012050112 | 50-271 P |
| SHEA: J. R. | 8012120603* | XPORTLIC | SHULTZ, D. M. | 8012020299 | 70-820 | SMITH, B. C. | 8012100431 | 50-289 H |
| SHEA: J. R. | 8012080756 | 50-579 A | SHUTE, S. | 8012290543 | 30-271 8 | SMITH, I. W. | 8012290014 | 50-289 Q |
| SHEA: J. R. | 8012020150 | XPORTLIC | SIBLEY, C. H. | 8012120193 | PR | SMITH, J. | 8012230300 | 50-289 Q |
| SHEA: J. R. | 8012100230 | XPORTLIC | SIDDRENKO, V. A. | 8012110452* | FOIA | SMITH, O. H. | 8012310266 | 70-364 |
| SHEA: J. R. | 8012100235 | XPORTLIC | SIEFKEN, D. L. | 8012180393 | 27-39 | SMOKER, C. S. | 8012020431* | 50-305 B |
| SKEA, K. H. | 8012110014 | 50-367 Q | Bilbero, J. E. | 8012290171 | 50-387 0 | SMOKER, C. S. | 8012170581# | 50-305 B |
| BKEA, K. H. | 8012110014 | 50-367 G | Bilbero, J. E. | 8012290171 | 50-387 0 | SMOKER, C. S. | 8012230389# | 50-305 B |
| SKEA, J. R. | 8012100428 | KPORTLIC | Bilbero, J. E. | 8012290171 | 50-387 0 | SMOKER, C. S | 8012230397* | 50-305 B |
| SKEA, K. H. | 8012270235 | 50-367 Q | Bilbero, J. E. | 8012110351 | 50-312 0 | SNAIDER, R. | 8012100123 | NUREQ |
| SKEA, K. H. | 8012270235 | 50-367 Q | Bilbero, J. E. | 8012110354 | 50-346 0 | SNAPP, B. A. | 8012310302 | 50-387 F |
| SHEALY, H, G. SHEAN, L, M. SHEDLOGKY, J. T. SHENO, Y. P. SHEPHERD, R. E. | 8012210048 8012230210 8012220077* 8012230522 8012220085* | State Prog XPORTLIC 50-245 G NUREQ 50-287 G | eilbero, J. E. Bilbero, J. E. Bilbero, J. E. Bilbero, J. E. Bilbero, J. E. | 8012110379 8012300069 8012300069 8012300069 8012310276 | 50-266 0 50-387 0 50-387 0 50-387 0 50-500 0 | SNOW, B. A. BNYDER, B. J. | 8012220440 8012050530* 8012020729 8012030853 8012080803 | 50-244 R 50-320 P 50-320 H 50-320 H 50-320 H |
| SHEPHERD, R. E. | 8012180353* | 90-247 Q | Bilberg, J. E. | 8012310276 | 50-300 | BNYDER, B. J. | 8012020817 | 50-320 H |
| SHEPPARD, W. V. | 8012040114 | 50-329 F | Bilva, J. | 8012120374 | | BNYDER, B. J. | 8012040168 | 50-320 H |
| SHEPPARD, W. V. | 8012040118 | 50-334 F | Bilver, R. D. | 8012020381 | | BNYDER, B. J. | 8012120122 | 50-320 P |
| SHEPPARD, W. V. | 8012040141 | 50-322 F | Bimmons, D. E. | 8012300492* | | BNYDER, B. J. | 8012040561 | 50-320 T |
| SHEPPARD, W. V. | 8012040145 | 50-352 F | Bimpbon, R. | 8012030296* | | BNYDER, B. J. | 8012110454 | 50-320 T |
| BHEPPARD, W. V. | 8012040149 | 50-309 F | SIMPBON, R. SIMPBON, R. SIMPBON, R. SIMPBON, R. SIMPBON, R. | 8012030417* | FOIA | BNYDER, B. J. | 8012120011 | 50-320 P |
| BHEPPARD, W. V. | 8012040155* | 50-245 F | | 8012030284* | FOIA | BNYDER, B. J. | 8012120027 | 50-320 P |
| BHEPPARD, W. V. | 8012040171 | 50-341 F | | 8012030216* | FOIA | BNYDER, B. J. | 8012080113 | 50-320 P |
| BHEPPARD, W. V. | 9012040180 | 50-289 F | | 8012030225* | FOIA | BNYDER, B. J. | 8012100664 | 50-320 U |
| SHEPPARD, W. V. | 8012040186 | 50-245 F | | 8012030157* | FOIA | BNYDER, B. J. | 8012150022 | 50-320 H |
| SHEPPARD, W. V. | 801204023B | 50-367 F | Bimpeon. R. | 8012030124* | FOIA | SNYDER, B. J. | 8012240495 | 50-320 P |
| SHERER, A. E. | 801204047A | NUREO | Bimpeon. R. | 8012030131* | FOIA | | 8012080816 | 50-320 H |
| SHERRY, R. R. | B012020365* | 10CFR | Bimpeon. R. | 8012030341* | FOIA | | 8012310081 | 50-320 P |
| SHERWOOD, D. R. | 8012230095 | NUREO | Bimpeon. A. K. | 8010300544* | 50-320 U | | 8012110500 | 50-320 T |
| SHERWOOD, O. G. | 8012040372 | PR | Bimpeon. J. C. | 8012290518 | 50-133 O | | 8012220239 | 50-320 H |
| SHERWOOD, O. O. | 8012050084 | PR | SIMS, J. N | 8012110223 | PR | SNYDER, B. J. | 8012270356 | 50-320 H |
| SHERWOOD, O. O. | 8012080688 | PR | SINCLAIR, N. K. | 8012230474 | ORO | SNYDER, B. J. | 8012270368 | 50-320 H |
| SHERWOOD, O. O. | 8012090055 | PR | SITTON, P. L. | 8012100423* | CONTRACT | BOLOMON, T. E. | 8012080801 | PR |
| SHERWOOD, O. O. | 8012180166 | PR | SKARITKA, J. | 8012120434* | 50-204 P | BORRENTINO, A. V. | 8012160368* | 50-286 Q |
| SHERWOOD, O. O. | 8012150095 | SO-447 B | SKIERKOWSKI, P. | 8012080226 | PR | BOUDER, J. L. | 8012030841 | 50-440 K |
| SHERWOOD, O. O. SHERWOOD, Q. O. SHEW-TRANZ, E. SHIEH, R. C. SHIEH, R. C. | 8012170444 8012240089 8012160668 8012010234* 8012010252* | 50-447 B 50-352 G PR 71-9073 | SKLAR, J. B. SKLEDAR, F. SKOLDS, J. L. SLIGER, B. F. | 8012220408* 8012300101 8012230511* 8012110637* 8012310624* | 50-219 R 50-289 H TOPHEP 50-395 Q CONTRACT | Souder, J. L. Souder, J. L. Bouder, J. L. BPAIN, Q. H. SPARROW, K. | 8012040639 8012040643 8012110518 8012030004 8012270293 | 50-245 F 50-213 F 50-348 F FDIA 50-367 H |
| SHIEH, R. C. | 8012010169* | 71-9073 | SLOBODIEN, M. J. | 8012240231 | MIEC | BPECIOR, A. BPECTOR, R. BPECTOR, B. M. BPENCER, O. B. BPENCER, J. | 8012120316 | PR |
| SHIEH, R. C. | 9012010228* | 71-9073 | BLUIS, B. J. A. | 8012230246* | GA999 | | 8012270270 | 50-170 H |
| SHIEH, R. C. | 8012010257* | 71-9073 | BLUIS, B. J. A. | 8012230239* | GA999 | | 8012300525# | 50-244 B |
| SHIEH, R. C. | 8012010266* | 71-9073 | SMALL, J. H. | 8012270126 | PR | | 8012040677 | 50-50B Q |
| TFH: R. C. | 8012010274* | 71-9073 | BMATHERS, O. | 8012030640* | FOIA | | 8012080340 | 50-441 A |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY |
|---|--|---|---|--|--|---|---|--|
| SPENCER, O. B. | 8012040305 | 50-397 Q | 8TEPTOE, P. | 8012110345 | 50-10 G | STUDDS, C. E | 8012070255 | 50-293 |
| | 8012010010 | 50-528 Q | 8TEPTOE, P. P. | 8012300333* | 50-237 G | STUETZER, D. M. | 8012020126 | NUREO |
| | 8012310227 | 50-344 Q | 8TEPTOE, P. P. | 8012300341* | 50-237 G | SU, T. M. | 8012160032 | 50-322 |
| | 8012310503 | 50-460 Q | 8TEPTOE, P. P. | 8012300333* | 50-237 G | SUFLESKI, C. | 8012170651# | 50-289 |
| | 8012310231 | 50-528 Q | 8TEPTOE, P. P. | 8012300341* | 50-237 G | SUGARMAN, N. | 8012010501 | PR |
| SPEROFF, R. D. SPESBARD, R. L. SPESBARD, R. L. SPESBARD, R. L. SPESBARD, R. L. | 8012230506* | 50-237 8 | STEPTOE, P. P. | 8012270657 | 50-237 0 | SULLIVAN, R. F. | 8012190512* | 50-257 |
| | 8012310470* | 50-373 0 | STEPTOE, P. P. | 8012270659 | 50-237 0 | SULLIVAN, R. F. | 8012020364* | 50-257 |
| | 8012170554* | 50-237 0 | STEPTOE, P. | 8012160332 | 50-237 0 | SULLIVAN, T. J. | 8012080145 | PR |
| | 8012100597* | 50-10 0 | STEPTOE, P. P. | 8012300122 | 50-237 0 | SUMMERB, R. | 8012300039* | 70-920 |
| | 8012180157* | 50-254 0 | STEPTOE, P. P. | 8012310288 | 50-237 0 | SUMMERB, R. | 8012320012* | 70-820 |
| SPETH, O. | 8012050535* | 50-320 P | BTERNBERG, D. H. | 8012100134* | 50-344 O | SUTHERS, H. B. | 8012120159 | PR |
| SPILKA, E. | 8012110575 | PR | BTERN, A. | 8012150014 | FOIA | SUTTON, J. K. | 8012170021* | GA999 |
| BPRUNG, I. | 8012090248 | NUREG | BTERN, W. C. | 8012110031 | XPORTLIC | SUTTY, T. A. | 8012300221* | GGNTRACT |
| BQUIBB, J. F. | 8012110521 | FOIA | BTERNBERG, D. H. | 8012090036* | 50-275 Q | SWAIN, A. D. | 8012110777* | FOIA |
| SRENIAWSKI, D. J. | 8012310550* | 40-7402 | BTERN, W. C. | 8012240361 | XPORTLIC | SWAIN, A. D. | 8012110764* | FOIA |
| STAATB, E. D. | 8012220017 | COMMISSION | BTERNBERO, D. | 8012310554* | 50-133 Q | SWAN, W. B. | 8012080695* | 50-518 |
| STAFFORD.R.T. | 8012240098* | COMMISSION | STERNBERO, D. H. | 8012310538* | 50-344 Q | SWAN, W. B. | 8012160790* | 50-518 |
| STAHLE, C. | 8012080835 | 50-259 F | STERN, W. C. | 8012380647 | XPORTLIC | SWANBY, Q. T. | 8012010024 | 40-3453 |
| STAHL, D. M. | 8012300229* | 30-445 M | STERN, W. C. | 8012230212 | XPORTLIC | SWANBY, Q. T. | 8012080385 | 40-3453 |
| STAHL, D. M. | 8012300229* | 50-445 M | STERN, W. C. | 8012170296 | XPORTLIC | SWANBY, Q. T. | 8012080710 | 40-3453 |
| STAHL, D. M. | 8012300225 | 50-445 M | BTERN, M. C. | 8012170305 | XPORTLIC | SWANBY, C. T. SWANBY, C. T. SWANBY, Q. T. SWANBON, E. R. SWANBON, E. R. | 8012190055 | 40-3453 |
| STAHL, D. M. | 8012300225 | 50-445 M | STEUCKE, M. | 8012310523 | 40-8745 | | 8012240310 | 40-3453 |
| STAHMER, F. | 8012230318* | 50-304 B | BTEVENB, B. C. | 8012020670 | 50-285 B | | 8012190046 | 40-3453 |
| STAMIRIS, B. | 8012270140 | 50-327 0 | BTEVENB, B. C. | 8012100480 | 50-285 B | | 8012110124* | 50-315 |
| STAMIRIS, B. | 8012300205 | 90-327 0 | BTEVENB, B. C. | 8012020607 | 50-285 B | | 8012310459* | 50-344 |
| STARKEY, R. B. STARKEY, R. B. STARK, R. H. STARK, R. H. STARK, R. H. | 8012180183* 8012110133* 8012070205 8012110083 8012110658 | 50-261 Q 50-261 Q 50-387 A 50-387 A 50-482 A | STEVENS, C. A. STEVENSON, R. L. STEVENSON, R. L. STEVENSON, R. L. STEVENSON, R. L. STEWART, R. C. | 8012080023 8012170034 8012170041 8012240097 8012240181* | NURE0 70-2882 70-2882 70-157 50-382 Q | SWANSON, D. T. SWANSON, D. T. SWANSON, D. T. SWANSON, D. T. SWARTILANDER, D. SWART, F. E. | 8012120644 8012310222 8012310228* 8012030878 8012120130 | 50-287 50-287 50-287 FOIA 50-267 |
| STARKEY, P. B. | 8012050422 | 50-241 8 | STEWART, A. M. | 8012040342* | 10CFR | SWART, F. E. | 9012170417 | 50-267 |
| STARKEY, R. B. | 8012050429* | 50-261 8 | STEWARD, P. | 8012120359 | PR | SWART, F. E. | 8012120152 | 50-267 |
| STARK, R. M. | 8012110084 | 50-387 A | STEWART, R. B. | 8012170714* | 50-289 H | SWART, F. E. | 8012040404 | 50-267 |
| STARKEY, R. B. | 8012090457 | 50-261 8 | STOCKMAN, R. L. | 8012030148* | FOIA | SWART, F. E. | 8012160146 | 50-267 |
| STARKEY, R. B. | 8012090442* | 50-261 8 | STOCKLAND, L. | 8012080693 | PR | SWART, F. E. | 8012240237 | 50-267 |
| STARKEY, R. B. | 8012140434 | 50-261 R | STOHR, J. P. | 8012170578 | 27-47 | SWARTZ, L. L. | 9012290387 | 50-275 |
| STARK, R. M. | 8012160156 | 50-387 A | STOHR, J. P. | 8012170170 | 27-47 | SWART, F. E. | 8012300591 | 50-267 |
| STARKEY, R. B. | 8012150222 | 50-261 8 | STOHR, J. P. | 8012170587 | 27-47 | SWATKOWSKI, S, | 8012240434* | 40-8743 |
| STARKEY, R. B. | 8012150227* | 50-261 8 | STOHR, J. P. | 8012170228 | 27-47 | SYLVIA, B. R. | 8012180172* | 50-338 |
| STARK, R. M. | 8012310255 | 50-387 A | STOHR, J. P. | 8012310042* | 30-338 G | SYLVIA, B. R. | 8012316038* | 50-338 |
| STARKEY, R. B. | 8012300411 | 50-261 8 | STOHR: J. P. | 8012190574* | 50-327 Q | 8YLVIA: B. R. | 8012180142* | 50-338 |
| STARKEY, R. B. | 8012300415* | 50-261 8 | STOHR: J. P. | 8012100686* | 70-143 | 8YLVIA: B. R. | 8012010607* | 50-338 |
| STARR, C. | 8012020379* | 100FR | STOHR: J. P. | 8012190430* | 50-324 Q | 8YLVIA: B. R. | 8012170031* | 50-338 |
| STAUB, J. L. | 8012090293* | 50-29 8 | STOHR: J. P. | 9012180178* | 50-553 Q | 8YLVIA: B. R. | 8012080652 | 50-338 |
| STAUB, J. L. | 8012090304* | 50-29 8 | STOHR: J. P. | 8012090201 | 50-261 Q | 8YLVIA: B. R. | 8012170021* | 90-280 |
| BTAVINOKA, J. | 8012290524 | 30-466 H | BTOHR, J. P. | 8012120344 | 70-27 | SYLVIA: B. R. | 8012040669 | 50-280 |
| Biehney, A. F. | 8012220728 | NUREO | BTOHR, J. P. | 8012070191 | 50-395 Q | SYLVIA: B. R. | 8012020276 | 50-280 |
| Bieinaecker, J. | 8012030367* | FOIA | BTOHR, J. P. | 8012110213* | 50-348 Q | SYLVIA: B. R. | 8012040414 | 50-237 |
| Bieinaecker, J. | 8012030294* | FOIA | BTOHR, J. P. | 8012180163 | 50-438 Q | SYLVIA: B. R. | 8012040306 | 50-280 |
| Bieinaecker, J. | 8012030166* | FOIA | BTOHR, J. P. | 8012180214 | 50-364 Q | SYLVIA: B. R. | 8012080541 | 50-232 |
| STEINAEGKER, J. | 8012030119* | FOIA | STOHR: J. P. | 8012180302 | 50-302 Q | SYLVIA: B. R. | 8012170432 | 50-337 |
| STEINAEGKER, J. | 8012030081* | FOIA | STOHR: J. P. | 8012180366* | 50-369 Q | SYLVIA: B. R. | 8012050328 | 50-280 |
| STEINAEGKER, J. | 8012030069* | FOIA | STOHR: J. P. | 8012190183 | 27-47 | SYLVIA: B. R. | 8012050421 | 80-338 |
| STEINAEGKER, J. | 8012030057* | FOIA | STOHR: J. P. | 8012190196 | 50-364 Q | SYLVIA: B. R. | 8012170271 | NUREO |
| STEINAEGKER, J. | 8012030051* | FOIA | STOHR: J. P. | 8012110207 | 50-348 Q | SYLVIA: B. R. | 8012080413 | 50-280 |
| STEINAECKER, J. STEINAECKER, J. STEINAECKER, J. STEINAECKER, J. STEINAECKER, J. | 8012030026* 8012030355* 8012030330* 8012030207* | FOIA FOIA FOIA FOIA | STOHR, J. P. STOHR, J. P. STOHR, J. P. STOIBEK, C. R. STOIBER, C. R. | 8012180169 8012190574 8012190414 8012290076* 8012290081* | 50-553 G 50-327 G 50-324 G COMMISSION COMMISSION | SYLVIA, B. R. SYLVIA, B. R. SYLVIA, B. R. SYLVIA, B. R. SYLVIA, B. R. | 8012090179 8012110543 8012230081 8012240503 8012120467 | 50-280 50-280 50-280 50-280 50-280 |
| BTEINAECKER, J. | 8012030218* | FOIA | STOIBER, C. R. | 8012290085* | COMMISSION | BYLVIA, B. R. | 8012150083 | 50-338 |
| BTEINAECKER, J. | 8012030188* | FOIA | STONEBURNER, U. | 8012020280 | 70-2478 | BYLVIA, B. R. | 8012160142 | 50-280 |
| BTEINAECKER, J. | 8012030072* | FOIA | STONEBURNER, U. | 8012020233 | 70-2478 | BYLVIA, B. R. | 8012170454 | 50-280 |
| BTEINAECKER, J. | 8012030062* | FOIA | STONEBURNER, U. | 8012020243 | 70-2479 | BYLVIA, B. R. | 8012170659 | 50-281 |
| BTEINAECKER, J. | 8012030385* | FOIA | STONE, W. A. | 8012300009* | QA779 | BYLVIA, B. R. | 8012170354 | 50-280 |
| STEINAECKER, J. | 8012030493* | FOIA | BYOTZ, J. | 8012150171* | 50-346 B | BYLVIA. B. R. | 8012170378 | 50-339 |
| STEINBACH, S. E. | 8012100278 | PR | STOUT, R. B. | 8012230511* | TOPREP | BYLVIA. B. R. | 8012170308 | 50-338 |
| STEINER, O. R. | 8012020256 | 50-927 R | STOVER, J. R. | 8012110609* | CONTRACT | BYLVIA. B. R. | 8012170532 | 50-280 |
| STELLMAN, H. J. | 8012110053* | CONTRACT | STOVER, J. R. | 8012020725 | FOIA | BYLVIA. B. R. | 8012230214 | 50-338 |
| STELLO, V. | 8012020803 | 50-321 G | STOVER, J. R. | 8012180282 | FOIA | BYLVIA. B. R. | 8012230286 | 50-280 |
| STELLO, V. STELLO, V. STELLO, V. STELLO, V. | 8012120398 8012080350 8012150025 8012030008 8012100108 | 50-320 G 50-498 A 50-320 G 50-220 G 50-220 G | STRAIT, R. A. STRAIT, R. A. STRAUSS, P. L. STRAUSS, P. L. STRAUSS, P. L. | 8012080679* 8012080653 8012080165* 8012080174* 8012080179* | 40-1341 40-1341 FOIA FOIA FOIA | BYEVIA: B. R. BYEVIA: B. R. BYEVIA: B. P. BYEVIA: B. R. SYEVIA: B. R. | 8012270173 8012270268 8012270274 8012270280 8012300585 | NUREO 50-280 50-280 50-338 50-280 |
| STELLO, V. STELLO, V. STELLO, V. STELLO, V. | 8012100125* 8012240458 8012230274 8012130282 8012130284* | 50-220 0 50-171 F 50-546 0 50-286 0 50-286 0 | STRAUSS, P. L. STREETER, J. F. STREETER, J. STREETER, J. F. STREUFERT, S. | 8012240037* 8012040678* 8012020780* 8012110645* 8012230335 | COMMISSION 50-316 G 50-373 G 50-282 G 50-320 P | Sylvia B. R. Bzilagyi, A. Bzukiewicz A. Talley, W. Talwani, P. | 8012310286 8012110031 8012310024 8012120355 8012020245* | 50-280 PR NUREO PR 50-375 |
| STELLO, V. STELLO, V. STELLO, V. STELLO, V. STELLO, V. | 8012300087 8012310094 8012310102* 8012300104 8012300118 | 50-247 G 50-247 G 50-247 G 50-247 G 50-247 G 50-10 G | STRICKLER, L, J. STROMBERO, N. STROUP, S, R. STROUT, R. | 8012240432* 8012080495* 8012140574 8012150163 8012160021 | 50-10 G 50-409 P FR: 50-289 H FDIA | TAMER TANKIN, R. S. TAPIA; J. I. TAPIA; J. I. TATERSALL; A. P. | 8012120280 8012220409 8012040039* 8012190414* 8012180149* | REGOD NUREO 50-478 50-478 |
| | | | | | | | | |

| ROHTUA | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEOURY | AUTHOR | ACCESSION NUMBER | BUBJECT CATEGORY, |
|---|---|--|---|--|---|---|---|--|
| TATTERBALL, A. P. TAYLOR, R. G. TAYLOR, J. H. TAYLOR, J. H. TAYLOR, J. H. TAYLOR, J. H, | 8012180208* 8012180372* 8012020264 8012180159 8012080428 | 50-33B G 50-445 G TOPREP PR TOPREP | THOMAS, R. D. THOMAS, E. L. THOMAS, W. N. THOMAS, R. D. THOMAS, J. A. | 8012070143* 8012240375* 8012010271 8012010016 8012100205 | 70-1257 State Prog 50-260 P 27-48 50-219 S | TOLLISON, A. C. | 8012160469 8012160477* 8012190525 8012190536* 8012220349 | 50-324 8 50-324 8 50-324 8 50-324 8 50-324 8 |
| TAYLOR, J. H. TEDESCO, R. L. | 8012160410 8012270015* 8012030800 8012110966 8011210010 | TOPREP 50-416 A 50-327 P 50-259 Q 50-361 A | THOMAS, R. D. THOMAS, E. B. THOMAS, E. B. THOMAS, E. B. THOMAS, E. B. | 8012100189 8012150076 8012150155 8012310294 8012310294 | 40-472 50-220 P 50-220 P 50-220 G 50-220 G | TOLLISON, A. C. | 8012220425 8012220436* 8012220483 8012220490 8012220324 | 50-324 B 50-324 8 50-324 8 50-324 B 50-324 B |
| TEDESCO, R. L. | 8012310130 8012010483 8012010056 8012010058 8012020081 | 50-311 P 50-245 P 50-390 V 50-382 V 50-395 V | THOMPEON, W. E. THOMPEON, C. M. THOMPEON, B. L. THOMPEON, J. E. THOMPEON, J. E. | 8012040180 8012040237* 8012170465 8012070053 8012030873 | 50-269 F TOPREP NUREO WASTE MOT WASTE MOT | TOLLIGON, A. C. | 8012220330* 8012230401 8012230406* 8012230434 8012230443* | 50-324 8 50-325 8 50-325 8 50-324 8 50-324 8 |
| TEDESCO, R. L. | 8012120447 8012040156 8012040161 8012050404 8012050411 | 50-361 V 50-311 P 50-311 F 50-382 0 50-445 Ω | THOMPSON: M. A. THOMPSON: J. E. THOMPSON: J. E. THOMPSON: D. THOMPSON: D. | 8012120374 8012240437 8012240284 8012230008 8012270638 | WASTE MOT WASTE MOT WASTE MOT 50-220 G DISCLOSURE | TOLLISON, A. C. | 8012230367 8012230373* 8012230501 8012230505* 8012300078 | 50-324 8 50-324 8 50-324 8 50-324 8 |
| TEDESCO, R. L. | 8012050425 8012080581 8012080442 8012080804 8012110339 | 50-440 0 50-352 0 50-364 0 50-358 0 50-478 0 | THOMPSON: D. THOMPSON: D. THOMPSON: D. THOMPSON: D. THOMPSON: D. THOMPSON: D. | 801211010B 801211014B 8012110174 8012110384 8012180261 | 40-672 I&E 50-397 Q 50-313 Q 50-286 8 | TOLLIBON, A. C. | 8012300402* 8012300425 8012300433* 8012300571 8012300570* | 50-324 8 50-325 8 50-325 8 50-325 6 50-325 8 |
| TEDESCO, R. L. | 8012110344 8012010053 8012040182 8012080491 8012080729 | 50-390 Q 50-358 E 50-267 Q 50-416 A 50-364 P | THOMPSON, T. J. THOMPSON, T. J. THOMPSON, D. THOMSEN, A. L. THOMSEN, F. T. | 8012160007* 8012160012* 8012180255 8012180262 8012310388 | FOIA FOIA I&E 40-8743 50-522 Q | TOLLISON; A. C. | 8012300472 8012300575 8012300579* 8012300583 8012300589* | 50-324 8 50-324 8 50-324 8 50-324 8 50-324 8 |
| TEDESCO, R. L. | 8012100659 8012010470 8012010510 8012040017 8012040197 | 50-382 A 50-438 A 50-438 A 50-445 A 50-445 A | THOMSEN, F. T. THONUS, L. H. THORNTON, R. H. THORNTON, P. THORNTON, P. | 8012310388 8012100179 8012170199 8012100039 8012100039 | 50-522 Q 50-320 B REB 50-445 M 50-445 M | TOLMAN, E. L. TOMLINGON, D. P. TOMLINGON, D. P. TOMPKING, B. A. TONGUE, T. M. | 8012040591 8012190416# 8012190623# 8012290277 8012100597# | REB 50-498 Q 50-498 Q 50-389 Q 50-10 Q |
| TEDESCO.R.L. TEDESCO.R.L. TEDESCO.R.L. TEDESCO.R.L. TEDESCO.R.L. TEDESCO.R.L. | 8012040582 B012040617 B012040660 B012040712 B012080309 | 50-395 A 50-387 A 50-373 A 50-397 A 50-395 A | THORNTON, P. THORNTON, P. THORNTON, P. THORNTON, P. THORNTON, P. THORNTON, P. | 8012100039 8012100039 8012100039 80123003A0 80123003A0 | 50-445 M 50-445 M 50-445 M 50-155 Q 50-155 Q | TOOKER, D. W. TOOKER, D. W. TOOLE, T. W. TORSDN, O. W. TOTH, A. D. | 8012020495* 8012020613* 8012230360* 8012030605* 8012310508* | 50-331 B 50-331 B 50-553 R FOIA 50-460 G |
| TEDESCO, R. L. | 8012080366 8012080442 8012080462 8012080689 8012080718 | 50-327 A 50-358 A 50-358 A 50-361 E 50-416 C | THROM, E. D. THROM, E. D. THURSTON: J. TILBERO, K. R. TILLHAN, A. | 8012220230 8012240474 8012030711 8012080264 8012160221* | 50-267 P 50-267 P MISC PR 70-143 | TOWNSLEY, B. TOWNSLEY, S. J. TOWNSLEY, S. J. TOWNSLEY, S. J. TOY, H. L. | 8012030010# 8012030325# 8012030201# 7910130058# 8012020715 | FOIA FOIA FOIA 70-8 |
| TEDESCO, R. L. | 8012100655 8012100663 8012230032 8012040075 8012040562 | 50-358 A 50-445 A 50-367 A 50-322 A 50-387 A | TILLHAN, A. TILLHAN, A. TILLHAN, A. TIMKO, D. R. TINO, W. W. | 8012190609* 8012190719* 8012180383* 8012170572* 8012220726 | XPORTLIC 50-438 Q 50-391 Q 50-334 R 50-201 P | TRAMM, T. R. | 8012010084 8012080448 8012020105 8012020182 8012070184 | 50-454 A 50-454 A 50-295 P TOPREP 50-599 H |
| TEDESCO, R. L. | 8012040684 8012040695 8012040717 8012040721 8012080320 | 50-373 A 50-397 A 50-322 A 50-349 A 50-482 A | TIPTON, T. E TISCHLER, L. F. TOBIN, W. J. TODD, Q. A. | 8012080267 8012300664* 8012180069* 8012190609* 8012310619* | REGOD 50-466 T 50-259 G XPGRTLIC 70-143 | TRAMM, T. R. | 8012100482 8012110254 8012170447 8012290247 8012300639 | 50-454 8 50-275 P 50-275 P 50-275 P 50-275 P |
| TEDESCO, R. L. | 8012090811 8012110247* 8012110178 8012140199 8012170289 | 50-367 A 50-482 A 50-339 F 50-445 F 50-358 A | TODOROVICH, M. II. TOLAN, J. H. TGLLISON, A. C. TOLLISON, A. C. TOLLISON, A. C. | 8012150026 8012080285 8012170426* 8011180672 8011180703* | 50-247 T PR 50-324 G 50-325 B 50-325 B | TRAUBENIK, M. TRAUTMAN, D. TRAUTMAN, D. TRAVERS, W. TRAVIEGO-DIAZ | 8012030131* 801215011B* 8012310337* 8012160615 8012220428 | 50-70 P 50-346 8 50-346 9 50-320 P 50-387 0 |
| TEDESCO, R. L. | 8012180143 8012180148 8012230281 8012170775 8012180126 | 50-364 F 50-327 P 50-395 D 50-329 A 50-311 F | TOLLIBON, A. C. | 8012080047 8012100449 8012100452* 8012020571 8012020578* | 50-324 G 50-325 B 50-325 B 50-324 B 50-324 B | TREBY, B, A, TREBY, B, A, TREINISH, N, J, TRIBBLE, J, E, TRIBBLE, M, | 8012290124 8012310254 8012120007 8012090423 8012170726* | 50-500 9 50-70 0 PR 50-29 P 50-287 H |
| TEDEBCO, R. L. TEDESCO. R. L. | 8012170324 8012310476 8012170322 8012310046 8012310037 | 50-311 F TOPREF 50-382 A 50-395 I 50-387 A | TOLLIBON, A. C. | 8012020474 8012020520* 8012020565 8012020569* 8012030721 | 50-324 8 50-324 8 50-325 8 50-325 8 50-324 P | TRIJOVSKY, M. TRIMBLE, D. C. | 8012220623 8012120174 8012120156 8012120079 8012120106 | NUREO 50-313 Q 50-313 Q 50-313 Q 50-313 Q |
| TEDESCO, R. L. TEDESCO, R. L. TEDESCO, R. L. TEER, B. R. TEER, B. R. | 8012310162 8012310170 8012240108 8012300231 8012300235* | 50-337 P 50-373 A 50-361 A TOPREP TOPREP | TOLLISON, A. C. | 8012070332 8012100453 8012100453* 8012100454 8012100459* | 50-324 8 50-324 8 50-324 8 50-324 8 50-324 8 | TRIMBLE, D. C. | 8012240331* 8012030687 8012010370 8012010315 8012010331 | 50-313 0 50-368 8 50-368 8 50-368 8 50-368 8 |
| TEITT, T.R. TENBEAU, P.N. TENZER, B.E. TERRELL, B.E. TERRELL, O.D. | 8012160473 8012080812* 8012160408 8012080676 8012030698 | 50-289 R CONTRACT TOPREP PR 50-289 H | TOLLISON, A. C. | 8012100547 8012100572* 8012150085 8012150251 8012150256* | 50-324 8 50-324 8 50-324 R 50-324 8 50-324 8 | TRIMBLE, D. C. | 8012010394 8012010399 8012010402 8012240038# 8012030638 | 50-313 8 50-313 8 50-368 8 50-313 9 50-368 8 |
| THIERER.I. THIES.A.C. THOM.T. THOMAS.J. THOMAS.J.A | 8012230490 8011210440 8012160321* 8012010196* 8012110090* | 50-341 A 50-269 Q 50-259 R 71-9073 50-219 Q | TOLLISON, A. C. TOLLISON, A. C. TOLLISON, A. C. TOLLISON, A. C. TOLLISON, A. C. | 8012170614 8012170625* 8012220351 8012160433 8012160440* | 50-324 8 50-324 8 50-324 8 50-324 8 50-324 8 | TRIMBLE, D. C. | 8012240227 8012020458 8012070431 8012020463 8012050517 | 71-9111 50-365 8 50-313 8 50-313 8 50-313 R |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEOURY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|--|--|--|---|--|---|---|--|
| TRIMBLE, D. C. | 8012080342 8012080515 8012150097 8012090174 8012090180 | 50-313 | ULLRICH, W. T. ULLRICH, W. T. ULLRICH, W. T. ULLRICH, W. T. ULLRICH, W. T. | 8012040411 8012040439 8012010289 8012040429 8012040419 | 50-278 8 50-277 8 50-277 8 50-277 5 50-277 8 | VARGA, B. A. VARGA, B. A. VARGA, B. A. VARGA, B. A. VARGA, B. A. | 8012270342 8012270363 8012270364 8012270375 8012270210 | 50-275 P 50-272 P 50-250 P 50-250 P 50-275 P |
| TRIMBLE, D. C. | 8012070388 8012070420 8012070453 8012150174 8012100555 | 50-368 8 50-368 8 50-368 8 50-313 P 50-368 8 | UMSTED, J. M. UMSTED, J. M. UNDERWOOD, P. R. UNDERWOOD, P. R. UNTALAN, J. T. | 8012230366* 8012020619* 8012230295* 8012230301* 8012080293 | 50-317 8 50-317 \$ 50-321 R 50-346 R PR | VAROA, B. A. VAROA, B. A. VAROA, B. A. VAROA, B. A. VAROA, B. A. | 8012270315 8012270346 8012270353 8012270354 8012170402 | 50-247 P 50-295 F 50-286 F 50-305 P 50-261 P |
| TRIMBLE, D. C. | 8012150049 8012150087 8012150089 8012170623 8012160409 | 50-313 P 50-348 B 50-348 S 50-348 B 50-313 R | upright, C. M. Urban, J. R. Uribe, J. D. Uthe, E. Utley, E. E. | 8012070228* 8012300238 8012100257 8012270611 8012120421 | 50-261 Q 50-389 M PR NUREO 71-345 | VAROA, S. A. VAROA, S. A. VARNER, L. S VAUGHN, C. VAUGHAN, R. C. | 8012170408* 8012170412* 8012300142* 8012080435* 8012110147 | 50-261 P 50-261 P CONTRACT 50-275 H PR |
| TRIMBLE, D. C. TRIPP, L. E. | 8012160414 8012180240 8012220452 8012230200 8012170560* | 50-368 R 50-368 8 50-368 8 50-368 P 50-387 Q | UTLEY, E. E. | 8012070058 8012030677 8012050275 8012050338 8012050436 | PR 50-261 P 50-261 P 50-261 0 50-324 P | VEGA, D. H. VEKLOTZ, R. J. VELAN, P. O. VEBELY, H. E. VINCENT, R. A. | 8012170696* 8012100438 8012240127 8012050066* 8012020479 | 50-289 H 50-289 H 50-322 8 8ECY 50-155 P |
| TRIPP, L. E. TROSKOSKI, W. TROSTEN, L. M. TROSTEN, L. M. TROSTEN, L. M. | 8012230049* 8012240049* 8012270066 8012270066 8012270071 | 50-394 | UTLEY, E. E. | 8012080479 8012090405 8012100450 8012100495 8012090189 | 50-261 P 50-261 P 50-261 P 50-261 P 50-261 F | VINCENT, R. A. VOGEL, C. C. VOOLER, B. H. VOLKER, B. C. VOLLEN, R. J. | 8012310307 8012030402* 8012300040* 8012310577 8012109044 | 50-155 8 FOIA 50-445 M FOIA 50-367 0 |
| TROSTEN, L. M. TROUP, G. L. TROUP, G. L. TROUP, G. L. TROUP, G. L. TROUTMAN, H. A. | 8012270071 8012190595* 8012180215* 8012190202* | 70-2623 27-47 50-364 Q 50-364 Q 50-289 H | UTLEY, E, E, UTLEY, E, E, UTLEY, E, E, UTLEY, E, E, UTLEY, E, E | 8012110552 8012160319 8012160460 8012160464 8012220332 | 50-324 P 50-324 P 50-324 P 50-261 P 50-325 P | VOLLEN, R. J. VOLLEN, R. J. VOLLMER, R. H. VOLLMER, H. W. VOLLMER, R. H. | 8012100064 8012300644* 8012010017 8012020471 8012070014 | 50-367 Q 50-367 A NUREQ 50-352 A TOPREP |
| TRUSSELL, H. H. TRUSSELL, H. H. TRUSSELL, H. H. TSCHAECHE, A. N. TSCNGAS, P. E. | 8012100116* 8012010227 8012100106 8012040375 8012300176 | 40-8064 40-8064 40-8064 50-289 H 50-293 U | UTLEY, E. E. | 8012220472 8012230470 8012220295 8012230328 8012300471 | 50-261 P 50-324 P 50-324 P 50-324 H 50-261 P | VOLMER, C. J. VOMACHKA, A. J. VON HIPPEL, F. VORDERBRUEGGEN VOTH, M. H. | 8012080267* 8012120196 8012020375* 8012310234* 8012220624 | QA799 PR 10CFR 50-528 Q 70-687 |
| TUBBB, R. C. TUBBB, R. C. TUBBB, R. C. TUBBIDY, J. F. TUCKER, J. J. | 8012070458* 8012170447* 8012300420* 8012300030* 8012230003 | 50-265 8 50-254 R 50-265 8 50-445 M 50-287 H | VADEN, J. D. VALL, J. VALORE, C. J. VAN BRUNT, E. E. VAN BRUNT, E. E. | B012030034* B012220175 B012270377 B012100344 B012100414 | FOIA 70-149 50-272 0 50-528 8 50-528 8 | VOZNEGENSKII, B. WACKER, H. WAGNER, A. G. WAGNER, A. G. WAGNER, F. T. | 8012110452* 8012170709* 8012110257* 8012090510* 8012010015 | FOIA 50-287 H 50-416 G 50-416 G 71-6717 |
| TUNSTALL, J. E. TUPPER, S. R. TURK, S. E. TURK, S. E. TURK, S. E. TURK, S. E. | 8012100022* 8012150070 8012080516* 8012080522* 8012080612 | CONTRACT 50-309 G 70-2909 70-2909 70-2909 | VAN BRUNT, E. E. | 8012090064 8012160477 8012220319 8012230379 8012230496 | 50-528 F 50-528 T 50-528 A 50-528 8 50-528 8 | HAGNER, F. T. WAGNER, F. T. WAGNER, W. J. WAGNER, P. C. WAIT, H. J. | 8012010278 8012010302* 8012040310* 8012010524 8012120217 | 71-377 71-377 50-397 0 50-285 P NUREG |
| TURK, 8, E. TURK, 8, E. TURNAQE, J. C. TURNBULL, K. R. TURNER, W. A. | 8012080507 8012150243 8012240262* 8012150112* 8012030479* | 50-548 Q 50-445 Q 50-29 P 50-327 P FOIA | VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E. E. VAN DYKE, C. VAN HOOMISSEN | 8012230449 8012230456 8012230302 8012020248* 8012010626* | 50-528 8 50-528 C 50-528 K 40-8707 70-1308 | Wait, H. J. Waite, D. A. Walbridge, W. C. Walbridge, W. C. Walbridge, W. C. | B012120350 B012110065 B012090415 B012090331 B012090411 | NUREO 50-10 P 50-312 P 50-312 F 50-312 F |
| TURNER, B. E. TURNEY, J. M. THALER, W. E. TYLER, P. E. TYLER, P. E. | 8012230370 8012300212* 8012100211 8012080451 8012080508 | NUREQ CONTRACT PR 50-170 P 50-170 R | VAN PELT, II. R. VAN BICKEL, J. VANDEBERO, E. J. VANDOORN, P. K. VANDOORN, P. K. | 8012180205 8012230314* 8012030065* 8012180217* 8012180289* | PR 50-331 R F01A 50-387 G 50-424 G | WALKER, H. V. WALKER, H. V. WALKER, H. V. WALKER, H. V. WALKER, H. V. | B012030308* B012030221* B012030241* B012030205* B012030190* | FOIA FOIA FOIA FOIA |
| UDALL, M. K. UDERITZ, R. A. UDERITZ, R. A. UDERITZ, R. A. UDERITZ, R. A. UHRIG, R. E. | 8012110043* 8012170214 8012170634 8012230377 8012110806* | COMMISSION 50-272 P 50-272 S 50-272 S FOIA | VANDOORN: F. K. VANBICKLE: D. VARELA: A. A. VARELA: A. A. VARELA: A. | 8012160035* 8012300723* 8012080060* 80121100793 8012170511* | 50-416 Q 50-466 T 50-443 Q 50-412 Q 50-423 Q | HALKER, H. V. HALKER, H. V. HALKER, H. V. HALKER, I. G. HALKER, H. V. | 8012030177* 8012030140* 8012030350* 8012030485* 8012030219* | FOIA FOIA FOIA FOIA |
| UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. | 8012080234* 8012080220* 8012180207* 8012080588 8012010106 | 50-250 Q 50-250 F 50-387 Q 50-387 Q 50-335 P | VAROA, 8. A. VAROA, 8. A. VAROA, 8. A. VAROA, 8. A. VAROA, 8. A. | 8011170738 8012040673 8012040320 8012030812 8012120012 | 50-286 0 50-247 F 50-315 P 50-280 F 50-334 P | WALKER, H. V. WALKER, H. V. WALKER, H. V. WALKER, H. V. WALKER, H. V. | B012030017* B012030386* B012030468* B012030182* B012030067* | FOIA FOIA FOIA FOIA |
| UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E | 8012010131 8012010091 8012090117 8012020071 8012020079 | 50-250 P 50-250 P PR 50-335 F 50-250 P | VAROA, 8. A. VAROA, 8. A. VAROA, 8. A. VAROA, 8. A. VAROA, 8. A. | 8012120020# 8012120028# 8012180668# 8012080587 8012080593# | 50-334 P 50-334 P 50-10 P 50-3 P 50-3 P | WALKER, R. D. WALKER, R. B WALKER, F. T. WALKER, C. K. WALL, W. X. | 8012310470* 8012040406 8012170617 8012300657 8012030513* | 50-373 Q 50-289 U 50-289 H 50-346 H FOIA |
| UHRIO, R. E. | 8012020121 8012040085 8012220614 8012070177 8012150233 | 50-250 P 50-250 F 50-387 Q 50-387 A 50-335 P | VARGA, 8. A. VARGA, 8. A. VARGA, 8. A. VARGA, 8. A. VARGA, 8. A. | 8012080598* 8012100682 8012170497 8012170493 8012170694 | 50-3 P 50-286 Q 80-295 P 50-280 P 50-261 P | HALL, L. B. WALL, I. B. HALLACE, J. J. WALTON, Q. A. WANG, B. Y. | 8012020309 8012020379* 8012030712 8012230049* 8012100542* | 40-8743 10CFR 50-287 H 50-336 G 50-361 A |
| UHRIGIR. E. UHRIGIR. E. UHRIGIR. E. UHRIGIR. E. UHRIGIR. E. UHRIGIR. E. | 8012160145 8012310410 8012170303 8012170425 8012240177 | 50-230 P 50-335 Q 50-387 A 50-387 K 50-335 P | VARGA, 8. A. VARGA, 8. A. VARGA, 8. A. VARGA, 8. A. VARGA, 8. A. | 8012170067 8012170075* 8012170077* 8012240135 8012240142* | 50-250 P 50-250 P 50-250 P 50-334 P 50-334 P | WANQ. C. H. WANQEMANN, R. T. WANNER, D, J. WARD, K. D, WARD, J. C. | 8012300453 8012120384 8012170724* 8012310518* 8012010017 | 50-243 B PR 50-289 H 50-341 G State Prog |
| UHRIG, R. E. | 9012270321 8012220301 8012240430 8012300216 8012300320 | 50-250 P 50-251 Q 50-250 P 50-335 P 50-250 P | VARGA, 8, A. VARGA, 8, A. VARGA, 8, A. VARGA, 8, A. VARGA, 8, A. | 8012240148* 8012240182 8012240184* 8012240191* 8012270312 | 50-334 P 50-272 P 50-272 P 50-272 P 50-334 F | WARD, J. C. WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D. | 8012120268 8011250201 8011250498 8012290267 8012020554 | PR 50-267 R 50-267 B 50-267 P 50-267 B |

| MARTINGUILD, 10 10 10 10 10 10 10 10 | AUTHOR | ACCESS I ON NUMBER | SUB JEC CATEOD | RY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | _ | AUTHOR | ACCESSION NUMBER | SUBJECT CATEODRY, |
|--|--|---|--------------------------------|--------------|---|---|-----------------------------------|--------------|---|---|--|
| AMARCHERUS B. 191919 50-37 8 WELLING J. A. 19120020 50-34 8 WILLER I. B. 1912002 1 | WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D. | 8012050408 8012100444 8012100332 | 50-267 50-267 50-267 | 83 P R | WERLING, J. A. WERLING, J. A. WERLING, J. A. | 8012100462 8012080436 8012080469 | 50-334 6 50-334 6 50-334 6 | 8 8 8 | WILKEY, A. M. WILKEY, A. M. WILKEY, A. M. | 8012020621* 8012030674* 8012080430* | 50-327 S 50-327 S 50-327 S |
| MARRIEL S. I. 1912/200525 20-247 5 | WAREMBOURO, D. WAREMBOURO, D. WAREMBOURO, D. | 8012100515 8012100524 9012170417 | 50-247 50-247 50-247 | S S P | WERLING, J. A. WERLING, J. A. WERLING, J. A. | 8012050416* 8012090369 8012120522 | 50-334 5 50-334 5 50-334 6 | 8 \$ 8 | WILL, J. M. WILLARD, T. WILLARD, D. | 8012030066* 8012180224 8012300636 | FOIA PR 50-367 A |
| MARTHER, E. 091240011 09-346 0 | WAREMBOURG, D. WAREMBOURG, D. U. WARNER, W. | 8012300562 8012290231 8012030060* | 50-247 50-267 FOIA | g P | WERLING, J. A. WERLING, J. A. WERLING, J. A. | 8012190501 8012190587 8012230528 | 50-334 8 50-334 8 | 8 8 6 | WILLIAMS, C. C. WILLIAMS, C. C. WILLIAMS, Q. C. | 8012030409* 8012030409* 8012080035* | 50-446 Q 50-546 Q 50-454 Q |
| MARTERI, R. | Harnick, R. F. Harnick, R. F. Harnick, R. F. | 8012040115* 8012110110* 8012310482* | 50-346 50-358 50-346 | 0 0 | WERNER, J. WERNER, J. WESCOTT, H. M. | 8012020533* 8012040369* 8012120300* | 50-346 8 50-346 8 50-483 (| 8 8 | WILLIAMS, C. C. WILLIAMS, C. C. WILLIAMS, C. C. | 9012190267* 8012240054* 8012240072* | 50-454 Q 50-373 Q 50-546 Q |
| MATERS E. L. | Warren, S. K. Wasserbach, A. Watanabe, H. T. | 8012230016 8012290017 8012050126 | 50-327 50-395 Toprep | D D | WESTERHAN, T. F. WETTERHAHN, M. J. WETTERAV, L. W. | 8012020228* 8012080744 8012080345 | 50-382 (PR PR | | WILLIAMS, O. W. WILLIAMS, L. Q. WILLIAMS, L. Q. | 8012120318 8012050394 8012070283 | PR 70-2909 I 70-2909 |
| MATKINB.H. 001210047 FOLA HILLEY.H. D. 801200079 S0-281 0 WILLEY.H. D. 8012002077 S0-277 R MATKINB.H. 001210007 FOLA HILLEY.H. D. 801200079 S0-277 R MATKINB.H. 001210020 71 P MATKINB.H. 0. E. 801210020 71 P MATKINB.H. 001210020 71 P MATKINB.H. 0. E. 801210020 71 P MATKINB.H. 001210020 71 P MAT | WATERS, D. B. WATERS, D. B. WATFORD, H. L. | 8012040327 8012020643 8012160438* | FR 50-261 50-261 | Р | WETTERHAMM, M. J. WETTERHAMM, M. J. WETTERHAMM, M. J. | 8012300071 8012310271 8012310271 | 50-272 0 50-358 0 50-358 0 | 9 | WILLIAMS, M. H. WILLIAMS, J. WILLMAN, P. L. | 8012150140 8012120592 8012290179* 8012300114 | 50-289 H 50-293 F 50-289 H 50-461 0 |
| HEERIN S | Watkins.M. Watson.T.M. Waymire.Q.R. | 8012030922 8012030922 8012010260* | FDIA FDIA 71-9073 | н | WHARTON, R. J. WHITE, J. R. WHITESELL, D. E. | 8012300507 8012080175* 8012170446* | 50-361 0 50-272 0 0A999 | 3 | WILLS, J. L. WILLS, J. L. WILNER, S. M. | 8012160267 8012300618 8012300574 8012310577* | 50-277 R 50-277 R 50-382 B 40-7402 |
| HERSE, E. D. B01210046 S0-133 R HITEKER, H. L. B012200389 S0-281 Q HILESON B. B01200389 S0-282 Q HILESON B. B012100189 S0-282 Q HILESON B. B012100200 KPORTLIC B. B012100189 S0-282 Q HILESON B. B012100200 S0-282 B HILESON B. B0122000177 S0-280 B HILESON B. B0122000777 S0-280 B HILESON B. B0122000779 S0-280 B HILESO | WEBER, J. A. WEBER, J. A. WEBBTER, E. H. | 8012090096 8012180256 8012180149* | PR PR 50-338 | G. | WHITENER, H. L. WHITESELL, D. E. WHITESELL, D. E. | 8012090219* 8012080282* 8012190021* | 50-395 G 98999 98999 | 9 | WILSON, J. L. WILSON, B. D. WILSON, B. D. | 8012030723* 8012230254 8012110008 | 50-281 S 40-8231 50-226 P |
| HEISHOLD.E.H. B0121002ABP B0121002ABP B0121002ABP HITTEL.D. B012100307 B0121001B B0120001B B0121001B B0121 | HEEKS, E. D. HEGST, H. HE1, 8 | 8012150046 8012170438 8012230340 | 50-133 50-142 NUREO | R | WHITEKER, H. L. WHITE, J. R. WHITE, L. D. | 8012190585* 8012290420* 8012010282 | 50-281 0 50-220 0 50-244 F | 3 | WILSON, D. WILSON, B. H. WILSON, J. N. | 8012030724 8012100159 8012100214 | 70-2623 PR 50-322 A |
| HEIBS, D. BO1210409* 40-8948 HHITLER, J. D. BO12300250 50-445 M HILBON, J. N. BO1210768 50-222 A BO12100110* 40-8064 HHITMEY, O. O. BO12160418* 50-293 R HILBON, J. L. BO1210768 50-222 A BO1210110* 40-8064 HHITMEY, O. O. BO1220017* 50-293 R HILBON, J. L. BO1205054 50-200 B HEIBS, D. BO1201019* 71-649B HHITMEY, O. O. BO12290176* 50-293 R HILBON, J. L. BO1205054 50-200 B HILBON, J. L. BO12050578* 50-200 B HILBON, J. L. BO12050578* 50-200 B HILBON, J. L. BO12050578* 50-200 B HILBON, J. L. BO1210373* 50-201 B HILBON, J. L. BO1210370* 50-201 B HILBON, J. L. BO1210370* 50-201 B HILBON, J. L. BO1210370* 50-201 B HILBON, J. L. BO1210327* 50-201 B HILBON, J. L. BO1210320* 50-201 B HILBON, J. L. BO1210320* 50-201 B HILBON, J. L. BO1210320* 50-201 B HILBON, J. L. BO12103049* 50-201 B HILBON, J. L. BO12203097* 50-200 | WEINHOLD,P. WEIR.Q.J. WEISBLAT.D.I. | 8012120180 8012120273 8012080343 | PR PR PR | a | WHITE, L. D. WHITE, J. R. WHITE, L. D. | 8012170340 8012270409# 8012090278 | PR 50-220 0 50-244 0 | 3 | WILSON, B. D. WILSON, B. D. WILSON, J. L. | 8012170026 8012170027 8012030707 | XPORTLIC XPORTLIC 50-280 8 |
| MEISS, D. 801200065 40-3453 HICHERS, D. L. 801210327 40-8502 WILSON, J. L. 801210379 50-281 8 HICHERS, D. B. 801210008 FOLA HICHERS, D. L. 801210397 40-8502 WILSON, J. L. 8012103793 50-281 8 HICHERS, D. B. 801210008 FOLA HICHERS, D. L. 8012103987 50-321 Q WILSON, J. L. 8012103989 50-281 8 HICHERS, D. B. 801210008 FOLA HICKER, W. A. 8012030817 50-321 Q WILSON, J. N. 801220131 50-322 A WILSON, J. N. 801210037 50-281 8 WILSON, J. N. 8012170611 50-281 8 WILSON, J. N. 8012170627* 50-321 Q WILSON, J. L. 8012170627* 50-281 8 WILSON, J. L. 8012170627* 50-281 8 WILSON, J. L. 8012170634* 50-281 8 WILSON, J. L. 8012170634* 50-281 8 WILSON, J. L. 8012170644* 50-281 8 WIDNER, W. A. 8012230344 50-321 P WILSON, J. L. 8012170644* 50-281 8 WIDNER, W. A. 8012230344 50-321 P WILSON, J. L. 8012300395 50-280 8 WIDNER, W. A. 80122300218 CONTRACT WILSON, J. L. 8012300497* 50-280 8 WISSE, E. 801213018 50-287 H WIGOINS, E. J. 8012230497* 50-280 8 WISSE, E. R. 801270674 50-289 H WIGOINS, E. J. 8012230497* 50-281 8 WISSE, E. R. 801270674 50-289 H WIGOINS, E. J. 8012230497* 50-281 8 WISSE, E. R. 8012300313 70-2623 WIGOINTON, J. E. 8012230497* 50-281 8 WISSE, E. R. 8012300313 70-2623 WIGOINTON, J. E. 8012230497* 50-281 8 WISSE, E. R. 8012300313 70-2623 WIGOINTON, J. E. 8012200448 50-281 8 WISSE, E. R. 8012300313 70-2623 WIGOINTON, J. E. 8012200474 50-281 8 WISSEN, J. L. 8012200474 50-281 8 WISSEN, W. WISSEN, J. L. 8012200474 50-281 8 WISSEN, J. R. R. 8012200474 50-281 8 WISSEN, J. R. R. 8012200474 50-281 8 WISSEN, | Weiss.d. Weiss.d. Weiss.d. | 8012120405* 8012100110* 8012010178 | 40-8348 40-8064 71-6458 | | WHITLER, J. D. WHITNEY, O. O. WHITNEY, O. O. | 8012300250 8012160418* 8012270176* | 50-445 is 50-273 R 50-273 R | 1 | WILSON, J. N. WILSON, J. L. WILSON, J. L. | 8012110768 8012050364 8012050370* | 50-322 A 50-280 8 50-280 B |
| MEIBB.E.R. 8012290217 50-3 0 MIDNER.W.A. 801210392W 90-321 0 MILSON.J.L. 8012170627# 50-281 8 MEIBB.E.R. 801220673 50-443 0 MIDNER.W.A. 8012240235 50-321 0 MILSON.J.L. 8012170627# 50-281 8 MEIBB.E.R. 801220673 70-1257 MIDNER.W.A. 8012240235 50-321 P MILSON.J.L. 8012170627# 50-281 8 MIDNER.W.A. 8012230364 50-321 P MILSON.J.L. 8012170627# 50-280 8 MIDNER.W.A. 8012230364 50-321 P MILSON.J.L. 8012230395 50-280 8 MIDNER.W.A. 8012230364 50-321 P MILSON.J.L. 8012230395 50-280 8 MIDNER.W.A. 8012230364 50-321 P MILSON.J.L. 8012230395 50-280 8 MIDNER.W.A. 8012230491 S0-280 8 MIDNER.W.A. 8012300218 CONTRACT MILSON.J.L. 8012230403* 50-281 8 MIDNER.W.A. 8012230499* 50-281 8 MIDNER.W.A. 8012230399 | Weiss.d. Weiss.d. Weiss.L. | 8012040122 8012100665 8012150008 | 50-206 40-3453 Foia | Р | WICHERS, D. L. WICHERS, D. L. WIDNER, W. A. | 8012310527 8012110419 8012030817 | 40-8502 40-8502 50-321 G | | WILSON, J. L. WILSON, J. L. WILSON, J. N. | 8012110393* 8012110398* 8012170283 | 50-281 8 50-281 8 50-322 A |
| MEISS.E. 8012190181 30-247 H WIGOINS.E.J. 8012300218 CONTRACT WILSON, J. L. 80122304999 50-280 B WIGOINTON, J. E. 80122003498 50-281 B WIGOINTON, J. E. 80122003498 50-281 B WIGOINTON, J. E. 80122003498 50-289 Q WILSON, J. L. 8012270448 50-281 B WIGOINTON, J. E. 80122700349 S0-281 B WIGOINTON, J. BOLIZEPOURS, E. R. 8012270313 70-2623 WIGOINTON, J. 801227003498 50-281 B WIGOINTON, J. BOLIZEPOURS, E. R. 8012030370 CONTRACT WILSON, J. L. 80122704598 50-281 B WIGOINTON, J. BOLIZEPOURS, E. R. 8012030370 CONTRACT WILSON, J. BOLIZEPOURS, E. R. 8012030370 CONTRACT WILSON, W. BOLIZEPOURS, G. M. 8012030707 SO-286 P WILSON, V. BOLIZEPOURS, E. R. 8012030370 PR WILSON, W. BOLIZEPOURS, G. M. 8012030370 | WEISS, E. R. WEISS, E. R. WEISS, E. R. | 8012270217 8012020673 8012020673 | 50-3 50-443 50-443 | 0 | WIDNER, W. A. WIDNER, W. A. WIDNER, W. A. | 8012110532* 8012240235 8012180161 | 50-321 0 50-321 0 PR |) | WILSON, J. L. WILSON, J. L. WILSON, J. L. | 8012170627* 8012170636* 8012170646* | 50-281 8 50-281 8 50-281 8 |
| HELCH, E. B. 9012030592 PR HIGOING, E. J. 8012300208 CONTRACT HILVERDING, G. M. 8012303074 50-286 P HELDON, V. V. 8012130626 PR HIGNOT, R. E. 8012100257 PR HILVERDING, G. M. 8012090375 50-286 P HELLER, R. 8012090274 50-320 H HILBORN, L. 80122020349 40-8084 HILVERDING, G. M. 8012090375 50-286 P HENDER, ICH B. 1 8012103644 50-317 F. HILBORN, L. 80122020349 40-8084 HINGREN, H. 8012100182 XPORTLIC | Weiss, E. Weiss, E. R. Weiss, E. R. | 8012150181 8012170674 8012270134 | 50-247 50-269 50-269 | H | Wigoins, E. J. Wigoins, J. T. Wigointon, J. E. | 8012300218 8012080099* 8012220348* | CONTRACT 50-244 0 50-289 0 |) | WILSON, J. L. WILSON, J. L. WILSON, J. L. | 8012230499* 8012270448 8012290435* | 50-280 8 50-281 8 50-281 8 |
| | WELCH, E. B. WELDON, V. V. WELLER, R. | 9012030592 8012120626 8012090274 | PR P R 50-320 | | WIGOINS, E. J. WIGNOT, R. E. WILBORN, L. | 8012300208 8012100257 8012020349* | CONTRACT PR 40-8084 | ì | WILVERDING, G. M. WILVERDING, G. M. WINGREN, H. | 8012030707 8012090375 8012100182 | 50-265 P 50-266 P XPORTLIC |
| HENDERLICH, R. B012020530* 50-317 8 WILCOX, J. D. B012090156* 50-438 Q WIBDAHL, D. M. B012030349* FDIA WENDERLICH, R. L. B012030733* 50-318 8 WILCOX, J. D. B012030028* 50-438 Q WIBDAHL, D. M. B012030333* FDIA WENDERLICH, R. L. B01203034* FDIA WILCOX, J. D. B012030231 PR WIBDAHL, D. M. B012030342* FDIA WIBDAHL, D. M. | WENDERLICH R.L. WENDERLICH R.L. WENSLAWSKIF.A. | 8012030733* 8012160397* 8012090095* | 50-318 50-318 50-344 | 8 8 0 | WILCOX, J. D. WILCOX, F. W. WILCOX, J. D. | 80120800831 8012080231 | 50-438 G PR 50-438 G | 1 | WISDAHL, O. M. WISDAHL, O. M. WISDAHL, O. M. | 8012030353* 8012030342* 8012030323* | FOIA FOIA FOIA |
| MERLING, J. A. 8012020527 50-334 8 WILD, P. A. 8012120618 50-322 8 WISKUS, A. T. 8012190105 50-289 H WERLING, J. A. 8012070269 50-334 8 WILD, P. A. 8012120638 50-322 8 WISSINK, R. Q. 8012100132 PR WERLING, J. A. 8012010303 50-334 8 WILD, A. A. 8012170698* 50-289 H WITHERSPOON, P. 8012100032 50-361 A WERLING, J. A. 8012020526 50-334 8 WILDER, J. J. 8012190112* 50-327 P WITHERSPOON, J. 8012190185 REB | WERLING, J. A. WERLING, J. A. WERLING, J. A. | 8012070269 8012010300 8012010303 | 50-334 50-334 50-334 | 5 8 8 | WILD, P. A. WILD, P. A. WILD, A. A. | 8012120638 8012150033 8012170698* | 50-322 8 50-338 8 50-287 H | } } ! | WIBSINK, R. Q. WITHERBPOON, P. WITHERBPOON, J. | 8012100152 8012100542* 8012110003 | PR 50-361 A RES |

| | ACCESSION NUMBER | SUBJECT | | AUTHÜR | ACCESSION NUMBER | SUBJECT | | AUTHOR | ACCESSION NUMBER | SUBJECT |
|------------------------------------|---------------------|----------|-----|----------------------------------|----------------------------|----------|---------|---------------------------|--------------------------|------------------|
| AUTHOR | | | | | | 27-47 | | YOUNGBLOOD, 9. J. | 8012240164* | 50-443 |
| WITHERS, B. D. | 8012090078 | PR | | HOODRUFF.R.L. | 8012190177* | | R | YOUNGBLOOD, B. J. | 8012290220 | 50~387 |
| WITHERS, B. D. | 6012170093 | PR | | WDODS, J. | 8012170324* | | n O | YOUNGBLOOD, B. J. | 8012310001 | 50-373 |
| WITHERS, B. D. | 8012020560 | 50-344 P | | HOODS, O. R. | 8012300105 | | T | YUANI O. | B012240370* | State Pr |
| WITHERS, B. D. | 8012080461 | 50-344 P | | WOODSON, H. H. | 8012300688* | | ά | YUAN, G. | 6012110248 | PR |
| WITHERS, B. D. | 8012180325* | 50-344 0 | | WOOLEVER, E. J. | 8012100090* | 50-334 | u | | | |
| WI INCROID. D. | | | | | | 50-412 | A | YUHAB, O, P. | 8012090095* | 50-344 |
| WITHERS, B. D. | 8012090227 | TOPREP | | HODLEVER, E. J. | 8012030617 | CONTRACT | n | YUNDT, C. P. | 8012150056 | 50-344 |
| WITHERS, B. D. | 8012090215 | 50-344 P | | WOOLF, A. | 8012080402* | | Н | YUNDT, C. P. | 8012150061 | 50-344 |
| WITHERS, B. D. | 8012160437 | 50-344 F | | WOOLMAN, J. | 8012090011* | | 5 11 | YUNDT, C. P. | 8012230466 | 50-344 |
| WITHERS, B. D. | 8012230313 | 50-344 P | | HODTON, R. C. | 8012230046 | | á | YUNDT, C. P. | 8012230305 | 50-344 |
| WITHERS, B. D. | 8012300299 | 50-344 F | 7 | WRAY, J. R. | 8012090210# | 30-261 | u | | | |
| WE INChas b. D. | | | | | 20101500404 | 70-27 | | YUNDT, C. P. | 8012230452 | 50-344 |
| WITHERS, B. D. | 8012300561 | 50-344 F | | WRAY, J. R. | B012120349* | 71-5796 | | YUNDT, C. P. | 8012230469 | 50-344 |
| WITHROW, O. C. | 8012020341 | | 3 | WRICHT, E. O. | B012110379* | | Q. | YUNDT, C. P. | 8012300405 | 50-344 |
| WITHROW, G. C. | 8012090419 | | | HRIGHT, C. C. | 8012100176* 8012100432* | | ä | YUNDT, C. P. | B012300616 | 50-344 |
| WITHROW, O. C. | 8012150285 | 44 .0- | 2 | WRIGHT, Q. C. | 8012090017 | PR | • | YUNDT, C. P. | 6012300553 | 50-344 |
| WIZNER, D. G. | 8012180292* | 50-315 | 8 | WRIGHT, N. | 8015040011 | rn | | | | |
| Me Pillerin at | | | | UP COURT | 8012190404 | FOIA | | YUNDT, C. P. | 6015300240 | 50-344 50-344 |
| WOETHER, M. | 8012100097 | PR | | HRIGHT, J. | 8012190179 | RES | | YUNDT, C. P. | 8012300568 | 50-344 |
| WOLF, L. | 8012080794 | NUREG | | HULFF. H. | 8012150254* | 50-265 | 8 | ZAAYENGA, R. | 8012170691* | |
| WOLF, J. | B012230284 | | Q | WUNDERLICH, J. R. | 80121802347 | PR | - | ZAJAG, L. D. | 8012090517+ | 50-321 50-329 |
| WOLF, J. F. | 8012230310 | 70-2909 | | WYMER, H. H. | 8012290288 | 50-387 | O. | ZAMARIN, R. | 8012270242 | 20-354 |
| HOLF, J. F. | 8012300076 | 70-2909 | | WYNNE, R. | 8012279266 | 20 307 | • | | 40440000040 | 50-329 |
| HOEL I WILL | | | _ | | 8012170317 | XPORTLIC | | ZAMARIN, R. | 6012270242 | NUREO |
| HOLF, J. F. | 8012270147 | | Q | YAMANA, K. | 8012120570* | 50-285 | 0 | ZECH, Q. Q. | 8012070016 8012020267 | 70-1201 |
| WOLF, J. F. | 8012310419 | | • | YANDELL, L. A. | B012240045* | 50-285 | ā | ZEFF. D. H. | 8012020269 | 40-7402 |
| WOLFE, D. | 8012170784* | KEB | | YANDELL, L. A. YARBDROUGH, R. | 8012030646* | FOIA | - | ZEMAN, D. | 8012310592* | 40-7402 |
| WOLFE, B. J. | 8012170495 | | G | | 8012030831 | PR | | ZEMAN, D. | 9015910039 | 40-7404 |
| WOLFE, S. J. | 6012300035 | 50-466 | G | YBARRONDO, L. J. | B012033331 | | | 7501 D. W | 8012170127 | PR |
| | | | | YEAGER, L. L. | 8012080498* | CONTRACT | | ZESLR, K. Zibulsky, H. | 8012110171* | 70-33 |
| WOLFE, B. J. | 8012240006 | | G. | YEATER, M. L. | 8012120342 | NUREO | | ZIBULSKY, H. | 8012190698* | 70-371 |
| HOLFE, S. J. | 8012290327 | 50-466 | 0 | YENDALL, R. F. | B012080245 | REGOD | | ZIBULBKY, H. | 8012300039* | 70-020 |
| WOLFE, B. J. | 8012340080 | 50-466 | v | YIN, I. T. | 00121801354 | 50-350 | G . | ZIBULEKY, H. | 8012220012* | 70-820 |
| WOLFE, D. | 0012290619 | NUREO | | YOHO, R. O. | 8012080449 | PR | | EIBVLGNIII. | GOTEE COOLE | ,,, |
| HOLFF. T. A. | 8012220207# | FOIA | | tondi k. v. | | | | ZIEKER, P. L. | 8012110201 | PR |
| | | FOIA | | YOLI, A. H. | 6012120241* | 50-407 | P | ZIMBERMAN, R. P. | 8012220077* | 50-245 |
| HOLFF, T. A. | 8012220243* | State Pr | | YOLL, A. | 8012020318* | 90-409 | Ъ | ZIMMERMAN, O. R. | 8012080707 | PR |
| WOLFF, T. A. | 8012010037 | PR | 28 | YOUNGE, R. A. | 8012110810* | FOIA | | ZINDROSKI, J. O. | B012310587* | 40-7402 |
| HOLKOHSKI-TLY | 8012050619 | CONTRACT | | YOUNGBLOOD, D. J. | 8012010011 | 50-373 | A | ZUDANB, Z. | B012040650 | ACRS |
| WOLLETT, S. | 8012040619 | CONTRACT | | YOUNGBLOOD, B. J. | 8012010484 | 50-322 | A | EGDINGS E. | | |
| WOLLETT, B. | 6012220002 | CUITIANG | | YDUNG, T. | B012070034* | 50-275 | Gr. | ZUFELT, E. | 8012140505# | 50-333 |
| | ********** | CONTRACT | | YOUNGBLOOD, B. J. | 6012010003 | 50-307 | Ä | ZULESKI, F. | 80121Q0053* | PR |
| WOLLETT, B. A. | 8012180520 | CONTRACT | | YOUNGELOOD, B. J. | 8012010422 | 50-349 | A | ZULLA, S. S. | 8012190033 | 71-9080 |
| WOLLETT, 8 | 8012240042 | | | YOUNGBLOOD, B. J. | 8012010007 | 50~358 | A | ZULLA, B. B. | 8012010410 | 50-286 |
| HONDERLY, J. | 8012180001 | 40-279 | | YOUNGBLOOD, B. J. | 6012010006 | 50-352 | Α | ZULLA, S. S. | 8012170341 | 50-284 |
| WONO, T. | | 50-237 | G . | Collabration at a | | | | | | |
| WONG, H. J. | 8012070044 | 20 ==. | ~ | YOUNGBLOOD, B. J. | 8012120229 | PAE~08 | A | ZULLA: S S | 8012150107 | 50-206 |
| | 8012300701 | 50-546 | a | YOUNGBLOOD, B. J. | 8012110376 | 50-596 | Α | ZULLA: B. S. | 8012150132 | 50-286 |
| MONO! H' J' | 8012300701 | 50-544 | ä | YOUNGBLOOD, B. J. | *10E0112108 | 50-596 | Α | ZULLA. B. S | 8012170464 | 50-286 |
| MDMG' H' T' | 8012300486* | | | YOUNGELOOD, B. J. | 8012150067* | 50-322 | tt | ZULLA, 8. S. | 8012220316 | 50-286 |
| WOOD, J. E. | 8012300478 | 50-309 | 8 | YOUNGBLOOD, B. J. | 8012180348 | 50-322 | Ħ | ZULLA, S. S. | 8012270425 | 50-286 |
| WOOD, E.C. | 8012020699 | 50-142 | 0 | , | | | | | | |
| WOODHEAD, C. P. | COLEGERAL | | | YOUNOBLOOD, B. J. | 8012190265 | 50-322 | 11 | ZWETZ TO, Q. B. | 8012040339# | 50-312 |
| HODIELD C C | 8012030433 | 50-142 | Q | YOUNGBLOOD, B. J. | 8012240224 | 50-322 | 41 | ZHTCKER, F. W. | 801203014B* | FOTA |
| WOODHEAD, C. P. | 8012100161 | 50-142 | Q | YOUNGBLOOD, B. J. | 8012190004 | 50-454 | Ą | ZWICK, E. E. | B012180464* | 50-245 |
| WOODHEAD, C. | 8012230011 | 50-142 | 0 | YOUNGBLOOD, B. J. | 6012300371 | 50-462 | Ç | | | |
| HOODHEAD, C. P. | 8012300022 | 50-142 | н | YOUNGBLOOD, B. J. | 8012300375* | 50-492 | C | | | |
| WOODHEAD, C. P. WOODRUFF, R. W. | 8012160119 | | Q: | | | | | | | |
| MUMPHOLE ! U. M. | HH-M | | | | | | | | | |
| | | | | | | | | | | |



The subject category column in this index gives the docket number and the symbol for the category of Information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

| AUTHÖR AFFILTATION | ACCESSION NUMBER | SUBJECT | Y. | AUTHOR AFFILIATION | ACCESBION NUMBER | EUBJECT CATEODRY |
|--|---|--|------------------|--|---|---|
| 3M Co., Minnesota Mining & Mfg. Co. Abbott Laboratories Advanced Medical Systems, Inc. | 8012100152 8012120007 8012110343 8012110396 8012170408 | PR PR 71-9011 71-5794 71-354 | | | 8012180585 8012180585 8012180611 8012180611 8012230309 | 50-348 (50-348 (50-348 (50-348 (50-364 f |
| Advisory Council on Historic Preservation Aeronautical Research Associates of | B012190611* | 71-354 40-8743 NUREO | | | 8012230372 8012230422 8012230461 8012230463 | NUREQ 50-364 F 50-368 F 50-364 F |
| Princeton Agriculture, Dept. of Air Force, Dept. of | 8012050213 8012180203 | 71-5362 PR | | | 8012230476 | 50-348 F |
| Air Transport Association Al Stern Associates Alabama Power Co | 8012240395* 8012150014 8001030448 8001030454* 8012010348 | State Pr FOIA 50-348 50-348 50-348 | F F B | | 8012230504 8012230504 8012270274 8012270314 8012300523 | 50-348 50-348 50-364 50-364 50-348 |
| • | 8012010367* 8012020397* 8012020512 8012020519* | 50-348 50-364 50-364 50-364 50-348 | 80888 | | 8012300530* 8012300533 8012300539* 8012300543 8012300547* | 50-348 50-348 50-348 50-364 50-364 |
| | 8012020558* 8012020558* 8012020564* 8012020574* 80120205864* 8012020595* | 50-348 50-348 50-348 50-348 50-348 | 9 9 8 6 8 9 | Alabama, State of | 8012300627 8012300627 8012310390 8012310395* 8012230368 | 50-348 1 50-348 1 50-348 1 50-348 1 NUREO |
| | 8012020401* 8012050115 8012050424 8012090075 | 50-349 PR 50-364 PR | 8 P | Alabara: Univ. of. Albuquerque Tribune Albuquerque, RM Allegheny Electric Cooperative, Inc. | 8012110178 8012220189 8012270171 8012300067 8012300067 | PR FOIA 50-387 50-387 50-387 |
| | 8012090113* 8012090113* 8012090118* 8012090118* 8012100424 | 50-348 50-348 50-349 50-348 50-348 | F F F P | Allegheng Ludium Industries, Inc. Allied-Crossroads Nuclear Corp. | B012300075* B012300075* B012310577* B012030606* B012030656* | 50-387 50-387 40-7402 FOIA FOIA |
| | 8012100424 8012100516 | 50-348 50-348 | P G | American Air Filber Co. American Association of Meat Processors | B012080704 B012170620 B012110180 | REGOD 50-289 PR |
| | 8012100517 8012100520* 8012100526* 8012100555 | 50-348 50-348 50-348 50-364 | 9 8 8 | American Association of Physicists in Medicine American College of Nuclear Physicians American College of Radiology | 8012120273 8012110262 | PR PR |
| • | 8015120147 8015100295* | 50-364 50-364 | S P | American Electric Power Co., Inc. American Electronics, Inc. Raed-Curtis | B012120904 B012030110* | NUREQ FOIA |
| | 8012150194 8012150235 8012160345 | 50-364 50-364 50-348 | P S | Nuclear Div. American Friends Service Committee | 8012030192* 8012030369* 8012020736 | FOIA FOIA |
| | 80121403514 8012160398 8012160400* 8012160403 8012160406* | 50-348 50-364 50-364 50-348 50-348 | B R R | American Hail Line | 8012030017# 8012030067# 8012030093# 8012030103# | FOIA FOIA FOIA |
| | 8012170409 8012170412# 8012180016 8012180384* | 50-364 50-364 50-364 50-364 | P G G | | 8012030135* 8012030140* 8012030177* 8012030182* | FOIA FOIA FOIA FOIA |

| AUTHOR AFFILIATION | ACCESSION NUMBER | CATE | ORY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJE CATEQ | |
|--|---|--|------------------|---|---|--|-----------------------|
| | 8012030221+ 8012030211+ 8012030211+ 8012030211+ | FOIA FOIA FOIA FOIA | | | B0120104044 B0120104064 B012020144 B012020144 | 50-313 | 8 9 |
| | 6012030222* 8012030230* 8012030241* 8012030244* 80120302624 | FOIA FOIA FOIA | | | 80120204614 8012020463 80120204664 8012030638 8012030641* | 50-368 50-313 50-313 50-368 50-368 | \$ \$ |
| | 8012030247* 8012030269* 8012030304* 8012030308* | FOIA FOIA FOIA | | | 80120306434 8012030687 8012050517 80120505234 8012080342 | 50~369 50~369 50~313 50~313 50~313 | 8 9 8 |
| | 8012030312+ 8012030317+ 8012030334+ 8012030345+ 8012030347+ | FOIA | | | 8012080347* 8012080397 8012080515 8012090174 8012090180 | 50-313 50-313 50-368 50-368 50-313 | Q P |
| | 8012030350 * 8012030384 * 8012030372 * 8012030400 * 8012030446 * | FOIA FOIA FOIA FOIA | | | 8012090180 8012090388 8012090395* 8012090420 6012090428* | 50-313 50-368 50-368 50-368 50-368 | P 8 8 8 8 |
| American Medical Association American Nuclear Insurers | 8012030468* 8012030487* 8012030354* 8012120013 8012160307 | FOIA FOIA FOIA PR 50~327 | Ų | | 8012070431 80120704454 8012070453 80120704634 8012100555 | 50-313 50-313 50-360 50-368 50-368 | |
| American Nuclear Society Anti-Nuclear Oroup Representing York | 8012160322 8012220300 80122702694 8012300505 8012300264 | MIEC 27-39 RECOD 50-483 50-269 | G O | | 80121005604 8012120097 8012120106 8012120106 8012120156 | 50-348 50-313 50-313 50-313 | 6 0 0 |
| Argonne National Laboratory | 8012110755* 8012120362 8012220167 8012220728 8012230426 | FOIA 71-5908 NUREO NUREO 50-389 | c | | 8012120174 8012120191 8012120021 8012150021 8012150049 | 50-313 50-313 50-313 50-313 | Q Q Q |
| Arizona Public Service Co. | 8012090064 8012100384 8012100384 8012100384 8012100414 | 50-528 50-528 50-528 50-528 50-528 | F 88 88 88 | | 8012150087 80121500884 8012150089 8012150090* 8012150097 | 50-313 50-348 50-348 50-348 50-348 50-348 | P 55 65 P |
| | G012100414 G012100414 G012160477 G012160506* G012160506* | 50-528 50-528 50-528 50-528 50-528 | 8 T T | | B012180174 B012160407 B0121604114 B012160414 | 50-313 50-313 50-313 50-368 50-368 | P R R R |
| | 8012140506* 8012170530* 8012170530* 8012170530* 8012220317 | 50-528 50-528 50-528 50-528 50-528 | T T T | | 8012170484 8012170623 8012170630* 8012170654 8012180240 | 50-348 50-368 50-368 50-289 50-368 | P 8 8 H 8 |
| | 8012230302 8012230302 8012230307* 8012230307* | 50-528 50-528 50-528 50-528 50-528 | K K K K | | 8012180243* 8012220452 8012220466* 8012220587 8012230200 | 50-368 50-368 50-368 50-313 50-368 | 88 89 69 |
| | 8012230307+ 8012230399 8012230399 8012230449 8012230449 | 50~528 50~528 50~528 50~528 50~528 | K 8 8 | | 8012230312* 8012230482 8012230482 8012240038* 8012240038* | 50-364 50-313 50-313 50-313 50-313 | P P Q |
| | 8012230447 8012230456 8012230456 8012230456 8012230476 | 50-528 50-528 50-528 50-528 50-528 | 6 C C B | | 8012240227 8012240331* 8012240331* 8012290188 8012290438* | 71-9111 50-313 50-313 50-313 50-313 | Q Q P F |
| Aritona, Univ. of | 8012230496 8012300487 8012010508 8012080242 8012110312 | 50-528 50-528 PR PR PR | 9 | Army, Dept. of Army, Dept. of, Office of Surgeon General Atlas Minerals | 8012120262 8012120384 8012010024 8012080217 8012080385 | 40-8743 PR 40-3453 40-3453 40-3453 | |
| Arkansas Power & Light Co. | 8012010315 8012010324 8012010331 80120103404 8012010354 | 50-368 50-368 50-368 50-368 50-313 | 6 5 5 6 | Atomic Energy Weste Disposal Service | B0120B0710 B012190046 B012190055 B012240310 B012030124* | 40-3453 40-3453 40-3453 40-3453 FOTA | |
| | 80120103614 8012010370 80120103814 8012010399 8012010402 | 50-313 50-368 50-368 50-313 50-368 | 8 8 8 8 | | 8012030131* 8012030157* 8012030216* 8012030225* 8012030284* | AIDR AIDR AIDR AIDR AIDR | |
| | | | | | | | |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJE(CATEG | BRY | | AUTHOR AFFILIATION | ACCESSION NUMBER | BUBJECT CATEGOR' | |
|---|--|--|-----------------------|---|---|---|--|-----------------------|
| Atomic Industrial Forum | 80120302964 80120303414 80120304194 8012010055 8012020363 | FOIA FOIA FOIA PROJ NUREG | | | | 8012190117 8012190117 8012190626 8012190626 8012190630= | 50-317 | P P R R |
| Austin, TX Badcock & Hilcox Co. | 8012080152 8012180240 6012300024 + 6012020264 8012020268 + | PR PR 50-445 TOPREP TOPREP | н | | | 8012190630* 8012220037* 8012220375 8012220401 8012220414* | 50-317 | R Q P S S |
| | 8012020269 8012020286 8012030789 8012030859 | 70-120) 50-13 70-135 71-5766 71-5766 | F | | | 8012230361 8012230366* 8012230405 8012230409* 8012230478 | 50-317 50-317 50-317 50-317 50-317 | 8888 |
| | 6012080428 80120900774 80120902254 8012110564 8012160410 | TOPREP 70-135 50-302 50-389 TOPREP | P G | | Sattelle Memorial Institute, Columbus Laboratories | 8012230481 8012290223 8012290285 8012020715 | 50-317 | P F |
| | 8012160413* 8012180159 8012190470* 8012190489* 8012290492* | TOPREP PR GA999 GA999 GA999 | | | | 8012100007* 8012110057 8012110057 8012120570 8012150110* | 70-8 CONTRACT RES NUREO 50-327 | Р |
| Babcock & Wilcox Co., Naval Nuclear Fuel Div. | 6012020297 | 70-27 | | | | 8012160018+ | CONTRACT | 1 |
| Babcock & Hilcox Co., Nuclear Material Div. Bailey Controls Co. (subs. of Babcock & | 8012040537 8012040549 8012080374 | 70-27 70-135 70-364 | | | Battelle Memorial Institute, Pacífic | 8012170219* 8012230066 8012230104 8012240044* 8012040606 | CONTRACT 90-320 NUREO CONTRACT RES | P |
| Hilco Co.) | 60122403544 | XPORTL1 | С | | Northwest Laboratory | 8012090095+ | 50-344 | a |
| Rayer & Botts | 8012020634* 8012150180 8012270005 8012270275 8012270441 | 50-466 50-466 50-466 50-466 50-466 | 0000 | | | 8012110063 8012110065 8012110258 8012110453 | 50-10 50-10 | P P |
| Baltimore Gas & Electric Co. | 8012300318 8012300654 8012010322 8012010326+ 8012010356 | 90-445 50-466 50-319 50-318 50-317 | M T S S | | | 8012110548 8012110676* -8012120270 8012120324 8012120343 | RES CONTRACT KUREO NUREO NUREO | |
| | 8012010368 8012010369+ 8012020425 8012020427 8012020429 | 50-317 50-317 50-317 50-317 50-317 | 98 8 8 8 | | | 8012120609 8012170240 8012170537 8012220600 8012220678 | RES RECOD NUREO NUREO NUREO | |
| | 8012020432 8012020438 8012020304 8012020530# 8012020593 | 50-317 50-317 50-317 50-317 50-318 | P 6 5 5 | | | 8012230075 8012230315 8012230323 8012240147 8012240507 | NUREO NUREO NUREO XPORTLIC NUREO | |
| | 8012020600# 8012020612 8012020619# 8012030248 8012030248 | 50-318 50-317 50-317 50-317 50-317 | 8886 | | Bay Point Power & Light Co. Bechtel Associates Professional Corp. Bechtel Corp. | 8012310287 8012080208 80120805294 80120105294 8012040044 | | P Q |
| | 8012030458 8012030731 8012030733# 8012050454 | 50-317 50-318 50-318 50-317 | 0 8 8 | | Bechtel Power Corp. (subs. of Bechtel Corp.) | 6012080762 8012240340 8012020129* | PR XPORTLIC 50-250 | Ρ |
| | 8012090277 | 50-319 | þ | | | 8012120492 | TOPREP | |
| | 8012100553 80121005574 8012100559 8012100561 8012100565* | 50-318 50-318 50-317 50-317 | 8888 | | Beltway Limpusine Bervice, Inc. Bergen-Patterson Pipe Bupport Corp. Berlack, israels & Liberman | 8012160353 8012190060* 8012080641* 8012020796* 8012160604 | QA999 Contract Qa999 | ₿ |
| | 8012100566# 8012120479 8012150072 8012150072 8012160313 | 50-317 50-318 50-317 50-317 | 8 F F J | | Biggiow Laboratory for Ocean Sciences Black Hills Alliance Bowing Co. | 8012100178 8012020710 8012170410 8012240122 8012030208* | PR FOIA FOIA FOIA | |
| | 8012160381 8012160387* 8012160390 8012160394* 8012170295 | 50-318 50-319 50-317 50-317 | 8 8 8 9 | * | | 8012030214# 8012030227# 8012030247# 8012030270# 8012030278# | FDIA FOIA FOIA FOIA | |
| | 8012170295 8012170297* 8012170299* 8012170450 8012190057* | 50-317 50-317 50-317 50-318 50-317 | ₽ ₽ ₽ ₽ ₽ | | Boeing Computer Bervices, Inc. (subs. of Boeing Co.) | 8012030323* 8012030342* 8012030347* 8012030353* 8012230331 | FOIA FOIA FOIA NUREO | |
| | 8012190057* 8012190064* | | F | | Boston Edison Co. | 8012010094 | 50-293 (| P |

| AVTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC. | RY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT |
|---|--|---|-----------------------|---|---|--|
| | 8012010233 8012010241# 8012010341 8012010347* 8012020599 | 50-293 50-293 50-293 50-293 50-293 | P P S S S | Californía Research Corp. | 8012030194+ 8012030689+ 8012030138+ 8012030255+ 8012030264+ | 27-39 27-39 FOIA FOIA |
| | 8012020606# 8012020615 80120206224 80120208214 8012080407 | 50-293 50-293 50-293 50-293 50-293 | S S S H S | California, State of | 8012030354* 8012030362* 8012030507* 8012010019 8012030012* | FOIA FOIA FOIA State Prog FOIA |
| | 8012080417+ 8012080833 8012090291+ 8012090443+ 8012100873 | 50-293 PR 50-318 50-29 50-293 | 5 թ 8 | | 80120300604 80120300744 80120300874 80120300914 80120300974 | FOIA 27-10 FOIA 27-10 27-10 |
| | 80121005764 8012150091 80121500924 8012160416 80121604184 | 50-293 50-293 50-293 50-293 50-293 | 5 5 9 R R | | 8012030105* 80120301184 8012030125* 80120301274 8012030164* | FOIA 27-10 FOIA 27-10 FOIA |
| | 8012170483 8012170588 8012220442 80122204574 8012230391 | 50-293 50-293 50-293 50-293 50-293 | P 0 5 5 6 | | 8012030179* 8012030193* 8012030199* 8012030250* | FOIA FOIA FOIA FOIA |
| | 8012230354 8012230356* 8012240242 8012240256* 8012240270* | 50-273 50-273 50-273 50-273 50-273 | P S Q Q | | 8012030365* 8012030833* 8012100257 8012120268 8012120631 | 27-10 27-10 PR PR PR |
| | 8012240272 8012270172 8012270176* 8012270331 8012270345* | 50-293 50-293 50-293 50-293 50-293 | P R R S S | | 8012270002 8012270002 8012270161 8012270161 8012270407 | 50-275 G 50-275 G 50-275 G 50-275 G 50-275 G |
| Brand & Hall Brookhaveπ National Laboratory | 1 8012300401 8012300407* 8012230004 8012080017 8012120334 | 50-293 50-293 50-395 NUREO NUREG | S S II | California, Univ. of: Berkeley | 8012290518 8012290662 8012300117 8012310314 8012020537 | 50-133 6 50-275 6 50-275 6 50-361 A 50-142 J |
| | 8012160232 8012160245 8012180310 8012190138 8012190146 | 50-10 50-10 50-312 RES RES | P P P | California, Univ. of, Los Angeles | 8012270302 8012300105 8012300704* 8012080014 8012070095+ | 50-142 J 50-142 0 50-466 T NUREO 50-344 0 |
| | 8012170151 8012170161 8012170166 8012170177 8012170424 | RES 50-537 RES RES NUREO | A | California, Univ. of, Santa Cruz Calumet Menorial Hosp Chilton.WI | 8012100171* 8012170438 8012300351 8012110193 8012110021 | 50-142 G 50-142 S 50-142 G FOIA PR |
| | 8012220&15 8012220714 8012240154 8012270075* 8012270160* | NUREO NUREO RES 50-466 50-466 | G T | Capitol Communication Systems | 8012270128 8012180288* 8012180271* 8012180295* 8012300221* | PR FGIA FGIA FGIA CONTRACT |
| Bruce Norton Burns & Roe Co Burnaughs Hallcome Co. | 8012290147* 6012310224 6012300352 6012290123 6012110310 | 50-466 NUREG 50-275 PR PR | τ 0 | Carolina Action Carolina Environmental Study Group Carolina Power & Light Co. | B012110545 B0122703194 B011180692 B0111807034 B012010337 | 70-2623 70-2623 50-325 S 50-325 S 50-400 S |
| Businessman for the Public Interest C-E Operating Plants Owners Group C-E Power Systems | 80123006444 8012030316 8012160503 8012040496 8012080167 | 50-367 TOPREP TOPREP NUREO PR | A | | 8012010339 8012010339 8012010339 8012020496 80120205204 | 50-400 S 50-400 S 50-400 S 50-324 S 50-324 S |
| | 8012090085 8012110800* 8012150202 8012150197 8012180493 | PR FOIA TOPREP 50-470 70-1100 | A | | 8012020565 8012020569* 8012020571 8012020578* 8012020643 | 50-325 8 50-325 8 50-324 8 50-324 8 50-261 P |
| CONOCO, Inc. (Continental Gil Co.) | 8012310230 8012310236 8012010221 8012080657 8012240222 | XPORTLIC XPORTLIC 40-8743 40-8743 40-8743 | | | 8012020643 8012020643 8012020643 8012020643 8012030679 | 50-261 P 50-261 P 50-261 P 50-261 P 50-261 P |
| CONSAD RESEARCH CURP. | 8012240433 8012240439 8012240509 80120407044 80120407104 | 40-8743 40-8743 40-8743 50-3 50-3 | F F | | 8012030721 8012030721 8012040327 8012040351 8012040551 | 50-324 P 50-324 P PR 50-324 Q 50-324 Q |
| Cabel Huntington Hosp: Huntington WV California Fish Canners Association Inc. California Nuclear Inc. | 8012170267 80120302564 80120300024 80120300774 80120301204 | PR FOIA 27-39 27-39 27-39 | | | 8012050275 8012050278* 8012050333 8012050422 8012050427* | 50-261 P 50-261 P 50-261 Q 50-261 S 50-261 S |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | Y | AUTHOR AFFILIATION | ACCESS FON NUMBER | SUBJECT CATEGORY | 4 |
|-----------------------|---|--|-----------------------|---|--|--|------------------|
| | 8012050435 8012050435 8012080047 8012080479 80120804824 | 50-324 50-324 50-324 50-261 50-261 | P P Q P | | 8012230401 8012230406* 8012230434 8012230443* 8012230470 | 50-325 50-325 50-324 50-324 50-324 | 8 8 8 8 |
| | 8012070058 8012070167 8012070352 8012070354 8012070405 | PR 50-261 50-324 50-324 50-261 | F S S P | | 8012230470 8012230501 8012230505* 8012300398 8012300402* | 50-324 50-324 50-324 50-324 50-324 | 8 8 8 |
| | 8012090409* 8012090457 8012090462* 8012100039 8012100449 | 50-261 50-261 50-261 50-445 50-325 | 8 8 8 M 8 | | 8012300411 8012300415* 8012300425 8012300433* 8012300472 | 50-261 50-261 50-325 50-325 50-324 | 8 8 8 8 |
| | 8012100450 6012100452* 8012100453 8012100455* 8012100456 | 50-261 50-325 50-324 50-324 50-324 | P S S G | | 8012300571 8012300575 80123005794 8012300583 8012300587* | 50-329 50-324 50-324 50-324 50-324 | 6 6 6 6 |
| | 8012100459* 8012100495 8012100495 8012100495 8012100513* | 50-324 50-261 50-261 50-261 50-259 | S P P P | | 8012300590* 8012300471 8012310194 8012310394 8012310404 | 50-251 50-261 50-261 50-261 50-261 | 6 P Q Q |
| | G012100547 G012100572* G012110133* G012110532 G012110552 | 50-324 50-324 50-261 50-324 50-324 | S G P P | Carter-Hallace, Inc. | 8012310490 8012310490 8012310494 8012310494 8012310111 | 50-324 50-324 50-324 50-324 PR | a a a |
| | 801212042) 8012150073 8012150074+ 8012150085 8012150085 | 71-345 50-400 50-400 50-324 50-324 | R R R | Catholic Univ. Center for Development Policy Center for Farm & Food Research, Inc. Center for Law in the Public Interest | 8012120333 8012270534 8012020781 8011250100 8012080513 | PR XPORTLIC FOIA 50-275 50-275 | 0 |
| | 80121500864 80121500864 8012150222 8012150229# 8012150251 | 50-324 50-324 50-261 50-261 50-324 | R R S S | | 8012080513 8012110204 8012170442* 8012270120 8012270120 | 50-275 FD1A 50-275 50-275 50-275 | 0 |
| | 8012150254+ 8012140317 8012140317 8012140433 8012140434 | 50-324 50-324 50-324 50-324 50-261 | 5 P S R | Center for Planning Research, Inc. Central & South West Corp. | 8012270392 8012300364 8012040704* 8012040710* 8012100037 | 50-275 50-275 80-3 50-3 50-445 | G G F F M |
| | 8012140458# 8012140440# 8012140460 8012140460 8012140464 | 50-261 50-324 50-324 50-324 50-261 | R G P P | Contral Electric Power Cooperative, Inc. Central Iowa Power Cooperative Central Power & Light Co. | 6012300225 8012300227* 8012230004 8012010376* 8012300251 | 50-445 50-445 50-375 50-331 50-445 | M M I |
| | 8012160467 8012160477* 8012170614 8012170625* 8012180183* | 50-324 | 5 5 8 8 0 | Charlottesville.Va Chase Brass & Copper Co., Inc., Chase Muclear Div. Chem-Ruclear Bystems, Inc. Chemtrol Corp. Chemtron Corp. | 801212031B 8012230210 8012220224* 8012270543 80123105814 | PR XPORTLIC FOIA 50-271 40-7402 | 8 |
| | 8012180376+ 8012180376+ 8012180376+ 8012180376+ 80121803784 | 50-400 50-400 50-400 50-400 50-400 | Q Q Q Q | Cherne Contracting Corp. Chevron Research Co. | 6012310587* 6012160154 6012030045* 6012030055* 8012030080* | 40-7402 50-546 FOIA FOIA FOIA | ٥ |
| | 8012190351 80121904264 80121904264 8012190825 80121905364 | 50-400 50-324 50-324 50-324 50-324 | Q Q Q S S | Chicago, Univ. of Chickering & Gregory Childrens Mosp. Gotumbus, OH Chonton N. | 8012010501 8012030306 8012270254 8012080136 8012270400 | PR 50-361 50-361 PR 50-250 | 0 |
| | 8012220275 8012220275 8012220324 8012220330# 8012220332 | 50-324 50-324 50-324 50-324 50-325 | ր Ե Տ Բ | Chronicle-Express Penn Yan, NY Cincinnati Gas & Electric Co. | 8012190252 8012020249 8012030232 8012030389 8012080520 | FOIA 50-358 50-358 50-358 50-358 | A K |
| | 6012220349 8012220349 6012220351 8012220425 8012220436+ | 50-324 50-324 50-324 50-324 50-324 | S S S S S | | 8012080523* 8012080795 8012100305 8012170240 | | |
| | 8012220472 8012220483 8012220483 8012220490 8012220490 | 50-261 50-324 50-324 50-324 50-324 | 8 8 8 | | | | |
| | 8012230318 8012230328 8012230328 60122303734 | 50-324 50-324 50-324 | 0 H H S S | Citizens Against Nuclear Dangers | | | |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT | Y | | AUTHOR FILIATION | ACCESSION NUMBER | SUNJEC | |
|---|---|---|------------------|-----------|---------------------|---|--|-----------------------|
| Citizens Anti-Nuclear Information Team Citizens Association for Sound Energy | 8012180140 8012240384 8012070341 8012070341 8012270318 | 50-387 50-466 50-445 50-445 50-445 | 0000 | | | 8012010343 8012010374 8012010382* 8012020105 8012020110# | 50-254 50-254 50-254 50-255 50-254 | P S S P Q |
| Citizens for Bafe Energy | 8012270318 8012270337 8012310280 8012310280 8012170410 | 50-445 50-445 50-445 50-445 50-10 | 0 0 0 0 | | | 8012020182 80120202174 8012020301 8012020301 8012020301 | TOPREP TOPREP 50-10 50-10 50-10 | 9 9 |
| Citizens for the Conservation of Natural Resources, Inc. | 6012290628 | 50-376 50-416 | G F | | | 8015050301 8015050301 | 50-10 50-10 | P |
| Claiborne County-MS Cleveland Clinic Cleveland.EH Cleveland Electric Illuminating Co. | B012120288 B012090300 B012090300 | PR 50-440 50-440 | 6 | | | 80150503154 80150503154 80150503154 | 50-10 50-10 50-10 | 0 0 0 |
| | 8012070307 8012100421 8012100421 8012160362 8012300464 | 50-440 50-440 50-440 50-440 50-440 | 5 6 0 0 | | | 8012020465 8012020465 8012020583 80120205914 50120400644 | 50-373 50-373 50-249 50-249 50-295 | A 8 8 |
| Cleveland-Cliffs Iron Co. Coast Quard, Transportation, Dept. of | 8012300597 8011200184 8011200191* 8012180388 8012030549* | 50-440 40-8714 40-8714 40-8714 FOIA | s | | | 8012040064+ 8012040068+ 8012040068+ 8012040284+ 8012040323+ | 50-295 50-295 50-295 50-295 50-10 | 0 0 0 8 |
| Coastwise Marine Disposal | 6012030027+ 6012030068+ 6012030073+ 6012030075+ 6012030169+ | FOIA FOIA FOIA FOIA | | | | 80120403334 8012040333# 6012040481 8012040486# | 50-10 50-10 50-373 50-373 50-373 | 8 8 A A |
| | 6012030185* 6012030204+ 6012030275+ 6012030273* 6012030362+ | FOIA FOIA FOIA FOIA | | | | 8012040507 8012050445 8012080448 8012080449 8012080448 | 50-247 PR 50-454 50-454 50-454 | S A A |
| Colorado State Univ. | 6012080768 6012080798* 6012080823 8012080825* 8012120149 | 40-8084 40-8084 40-8084 40-8084 PR | | | | 9012080448 8012080797 80120900454 8012090071 8012090184 | 90-454 PR 50-254 PR 50-599 | A G H |
| Colorado, State of | 8012080775 8012170040 8012220407* 8012220477 8012220479* | WASTE MG REGGD WASTE MG WASTE MG WASTE MG | T T | | | 8012070400 8012070407 80120704164 8012070433 80120704444 | 50-237 50-265 50-265 50-304 50-304 | P 5 5 5 |
| Colt Industries, Inc. Colt Industries, Inc., Fairbants Morse Engine Div. | 8012230290 8012310454 8012020475* | State Pr 50-352 0A979 | °00 8 | | | 8012070444 8012070451 80120704524 80120704584 | 50-265 50-265 50-265 | 9. 98 98 98 |
| Columbia Univ. | 8012020513 8012120316 | 70~882 PR | | | | 8012070461 80120704734 | 50-295 50-275 | S S |
| Columbia Univ.School of Law Combustion Engineering, Inc. | 6012240178# 60123002304 6012030714# 6012070214# 8012070214# | 70-882 CONTRACT XPORTLIC 50-361 50-361 | | | | 8012100462 8012100582* 8012110254 8012110254 | 50-454 50-275 50-275 50-275 | \$ G P P |
| | 8012100010 8012150098* 8012150101* 80123000094 | PR 50-368 50-369 0A999 | þ | | | 80121102674 B0121102674 B012110274 6012110358 6012110358 | 50-275 50-295 50-237 50-295 50-295 | P P R |
| Coomerce, Dept. of, National Oceanographic | 6012300384* 6012300384* 8012310394 | 50-361 50-361 NUREO | K | | | 8012110363* 8012110363* 8012110608* 8012110608* | 50-275 50-275 50-10 50-10 | R R Q Q |
| & Atmospheric Administration Commerce Dept. of | 8012310445 8012230483 | NUREO 70-398 | | | | 8012120301 8012120301 | 50-237 50-237 | P F |
| Commerce, Dept. of, National Bureau of Standards | 8012080485 60120804874 | 50-184 50-184 | P P | | | 8012120301 8012120301 8012120341* 8012120341* | 50-237 50-237 50-237 50-237 | P P P |
| | B0120B04914 | 50-184 CONTRACT | p | | | 8012120341* 8012120341* 8012120425* 8012120576 8012120576 | 50-237 50-237 50-254 50-16 50-16 | P Q F |
| Commonussith Edison Co. | #012300203* #009240774 | 50-142 50-10 | , , , , o H |) | | 8012120576 8012120576 8012150052 8012150052 8012150054* | 50-10 50-10 50-237 50-237 50-237 | F P P |
| | 8012010084 8012010084 8012010084 | 50-454 50-454 50-454 50-454 | AAAA | | | 8012150054* 8012150093 8012150094* 8012150139 8012150211 | 50-237 50-304 50-304 50-373 50-295 | р \$ % |
| | | | | | | | | |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC CATEGO | | AUTHOR AFF 11. I AT I ON | ACCESSION NUMBER | SUBJECT CATEGOR |
|-----------------------|---|--|---|---|--|--|
| | 8012150218* 8012150228* 8012150250 8012150254* 8012160136 | 50-295 50-456 50-265 50-265 50-237 | 50 S S P | | 8012300637 8012310212 8012310282 80123102874 80123105904 | 50-295 50-295 50-237 50-237 50-295 |
| | 8012160172 8012160419 8012160419 8012160419 8012160420* | 50-10 50-10 50-10 50-10 50-10 | P R R R | Connecticut Yankee Atomic Power Co. | 8012310630* 8012310630* 8012010090 8012030884* 8012030889* | 50-10 50-10 50-213 50-213 |
| | 8012160420* 8012160479 8012160479 8012160510 8012160517* | 50-10 50-254 50-254 50-237 50-237 | R P P P | | 8012040139 8012050143 8012050272 8012080712 8012090172 | 50-213 71-6698 50-213 NUREO 50-213 |
| | 8012160319# 8012160522# 8012160528# 8012160528# 8012160527# | 50-237 50-237 50-237 50-237 50-454 | e e e e e e e e | | 8012090361 8012090364* 8012160117 8012170058 8012170330 | 50-213 50-213 50-213 PR PR |
| | 8012160532* 8012160537* 8012160538 8012160539* 8012160943* | 50-237 50-237 50-237 50-237 50-237 | ម្នា | Connecticut, State of | 8012170524 8012170526* 8012230262 8011210572 8012030460* | 50-213 50-213 50-213 NUREO FOIA |
| | 8012160655 8012170408 8012170408 8012170408 8012170408 | 50-373 50-237 50-237 50-237 50-237 | A G G G | Connecticut, Univ. of Conner, Moore & Corber | 8012170285 8012180182 8012310438* 8012380221 8012040412 | PR PR 50-213 PR 50-358 |
| | 8012170446 8012170446 8012170447 8012170449* 8012170449* | 50-254 50-254 50-255 50-254 50-254 | R R P R R | Conoco Goal Davelopment Co. | 8012080766 8012120542 8012300071 8012310291 8012180374 | PR 27-39 50-272 50-358 40-0743 |
| | 8012170469 8012170468 8012170468 8012170469 8012170469 | 50-10 50-10 50-10 50-10 50-10 | P P P | Consolidated Edison Co. of New York | 8012030045* 8012030071* 8012020564 8012030495 8012080444 | FOIA FOIA 50-247 50-3 50-247 |
| | 8012170468 8012170489 8012170607 8012170618* 8012170697* | 50-10 50-10 50-304 50-304 50-373 | P P S S O | | B012080450* B012090281 B012090282* B012100489 B012110787* | 50-247 50-247 50-247 50-247 FOIA |
| | 8012230045 8012230049 8012230045 8012230045 8012230045 | 50-10 50-10 50-10 50-10 50-10 | 0 0 0 0 0 | | 8012140294 8012140474 8012220399 8012220399 8012230303 | 50-247 50-3 50-3 50-3 50-247 |
| | 8012230224 8012230224 8012230229* 8012230227* 8012230316 | 50-373 50-373 50-373 50-373 50-304 | K K K K K K K K K K K K K K K K K K K | Consumers Power Co. | 8012230306# 8011250069 8012010138 8012010160# 8012010189 | 50-247 50-255 50-255 50-255 50-155 |
| | 80122303184 8012230322 80122303274 6012230500 60122305064 | 50-304 50-295 50-295 50-237 50-237 | 5 5 6 6 | | 8012010284 8012010287# 8012010384 8012010392# 8012010496 | 50-255 50-255 50-265 50-255 50-155 |
| | 8012240158 8012240159 8012240159 8012240158 8012240159 | 50-10 50-10 50-10 50-10 50-10 | P P P P | | 8012020323 8012020341 8012020479 8012020577 8012020580 | 50-329 50-155 50-155 50-329 50-255 |
| | 8012240159 8012240158 8012290247 8012290459 8012290458 | 50-10 50-10 50-275 50-237 50-237 | P P Q Q | | 8012030702 8012050322 8012050322 8012050345 8012080354 | 50-255 50-329 50-329 PR 50-255 |
| | 8012270465 8012270466 8012270470 8012270470 8012270657 | 50-237 50-237 50-237 50-237 50-237 | 0 0 0 0 | | 8012080357# 8012080362 8012080365# 8012080460 8012080464# | 50-255 50-155 50-155 50-255 50-255 |
| | 8012300151 8012300151 80123003334 80123003414 | 50-237 50-289 50-237 50-237 50-237 | G G O O | | 8012080480 8012080480 8012080525 8012090419 80120904264 | 50-329 50-329 50-255 50-153 50-155 |
| | 8012300341* 8012300345* 8012300345* 8012300414 8012300420* | 50-237 50-237 50-237 50-265 50-265 | 0 0 9 8 | | 80120904294 8012100502 8012150058 8012150058 8012150285 | 50-155 50-324 50-158 50-155 |

| AUTIUA NDITAIJAA | ACCESSION NUMBER | SUBJECT CATEGOR | | | AUTHÜR AFFILIATIOR | ACCESSION NUMBER | SUBJEC | RY |
|---|---|---|------------------|---------------------------------|---|---|---|-----------------------|
| | 8012160182 8012160353 8012160353 8012160425 8012160426+ | 50~155 50~329 50~329 50~255 50~255 | P. 55 F. F. | | | 8012020273 8012020273 8012020315 8012020453 80120204564 | 50-409 50-409 50-409 50-409 50-409 | P P S S |
| | 6012160443 6012160443 6012160494 80121604584 80121605044 | 50-329 50-329 50-155 50-155 50-155 | A S S | | | 8012020505 8012050502 8012080489 8012090206 8012090366 | 50-409 50-409 50-409 50-409 50-409 | ទ ទ ទ |
| | 8012160503* 8012170452 8012170453 8012170456* 8012170538 | 50-155 50-155 50-255 50-155 71-5364 | S R P R | | | 8012090368* 6012090393* 8012090397* 8012100529 8012100530 | 50-409 50-409 50-409 50-409 50-409 | 5 P P S S |
| | 8012180005 8012180403* 8012220701 8012220701 8012230159 | 50-155 50-155 50-155 50-155 TOPREP | 0 0 0 | | | 80121005354 80121005404 80121005474 8012120225 80121202414 | 50-409 50-409 50-409 50-409 50-409 | 5 5 5 6 |
| | 8012230205 8012230209* 8012230275 8012230277 8012230277 | 50-255 50-255 50-155 50-329 50-329 | P P S S | | | 8012120646 5012150244 6012160280 6012160286* 6012160350 | 50-409 50-409 50-409 50-409 50-409 | 0 8 8 8 |
| | 8012230339 8012230341 8012230349* 8012230527 8012230534* | 50-327 50-155 50-155 50-155 50-155 | 9 8 8 8 | | | 8012160442 80121604494 80121604634 8012220688 8012230378 | 50-409 50-409 50-409 50-409 | 5 5 G G S |
| | 6012240016 6012240242 6012240242 6012240243 6012240333 | 50-329 50-329 50-329 50-255 50-255 | G G G | Dames | s & Hoore | 8012290550 8012300368 8012010031 6012010038* 8012010037 | 50-409 50-409 40-8084 49-8584 40-8084 | 0 |
| | 8012300360 8012300405 80123004104 8012300422 80123004274 | 50-155 50-255 50-255 50-155 50-155 | 6 8 8 8 | | | 8012080512+ 8012160359+ 8012220137+ 8012300728+ 8012300731+ | 50-170 50-409 40-4492 50-466 | R P T |
| | 8012300460 8012300499 8012300502 8012300557 8012310202 | 50-329 50-255 50-155 50-329 50-255 | 8 P K O | | hin County, PA Mining Co. | 80122904524 8012030893 8012090053 8012240286 8012240437 | 50-320 MATE MO WASTE MO WASTE MO | gt gt |
| Control Hodule, Inc. Cornell Univ. | 8012310225 8012310307 8012310312* 80120403774 8012050418 | 50-329 50-155 50-155 CONTRACT 50-97 | 8 8 8 | Debev | voise & Liberman | 8012020765 8012080107 8012080472 8012100088 6012110146 | 50-395 FOIA 50-313 PR FOIA | II G |
| Cotter Corp. Council on Environmental Quality | 8012100155 8012120352 80120505354 8012270142 8012270335 | PR WASTE NG 50-320 50-155 50-155 | T P Q | | | 8012110617 8012110659 8012150007 8012160336 8012170672 | 50-395 50-395 FOIA 50-395 50-445 | 0 0 0 |
| Creare, Inc. Crossroads Marine Disposal Corp. | 8012290516 80120405274 8012230340 8012230509 80120303354 | 50-155 CONTRACT NUREO NUREO FOIA | G | | | 8012170391 8012230014 8012270339 8012270379 6012270647 | FOIA 50-369 50-445 70-2623 50-445 | G G |
| | 8012030335* 8012030340* 8012030352* 8012030371* 8012030395* | FOIA FOIA FOIA FOIA | | Defen | nse Civil Preparedness Agency | 8012300057 8012300066 8012310290 80122905054 80122905104 | 50-445 50-369 50-445 50-320 50-320 | 6 6 7 7 |
| | 8012030405+ 6012030410+ 8012030422+ 8012030435+ 8012030443+ | FOIA FOIA FOIA FOIA | | | nse Dept.of, Defense Nuclear Agency arva Power & Light Co | 8012080451 6012080503 80120805104 8012310474 8012090265* | 50-170 50-170 50-170 50-170 50-450 | P R R G |
| | 80120304504 8012030459* 80120304624 8012030491* 8012030540* | FOIA FOIA FOIA FOIA | | Detro | ait Edison Co. | 80120702654 8012230059 8012230059 8012120459 8012240278 | 50-450 50-450 50-450 50-341 50-452 | 0 0 8 A |
| | E012030546+ B012030565+ B012030572+ B012030575+ B012030590+ | FOIA FOIA FOIA FOIA | | Moun Dobbs Docto Dogge | inson County Memorial Hosp Iron htain.HI s & Nailsen ors Hosp. Poplar Bluff.HO ott. S.A. ttyr.J.F. | 8012170307 8012150002 8012080662 8012300587 8012050379 | PR FOIA PR 50-466 50-443 | G H |
| Cyprus Mines Corp. Daedalean Associates, Inc. Dairyland Power Cooperative | 8012030411# 8012030633# 8012120394 80120804784 8012010310 | FOIA FOIA HABTE MG CONTRACT 50-409 | | Dow C Div. | Chemical Co. , Dow Chemical U.S.A. | 8012120037 8012120037 8011210440 8011210440 | PR 50-269 50-269 | 0 |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | | AUTHGR AFFILIATION | ACCESSION NUMBER | SUBJECT | |
|-----------------------|--|---|-----------------------|---|---|---|-----------------------|
| | 8011210440 8012010201 8012010201 80120102254 80120102254 | 50-269 50-369 50-369 50-369 50-369 | Q A A A A | | 8012230543+ 8012230546+ 8012230548+ 8012240083 8012240372+ | 50-369 50-369 50-369 50-369 50-369 | A A B F |
| | 80120201274 8012020272 8012020502 8012020543+ 8012020552 | 50-369 70-2623 50-270 50-270 50-269 | G S S P | | 8012240372* 8012240381* 8012240381* 8012290379 8012300066 | 50-369 50-369 50-369 70-2623 50-369 | F F C |
| | 9012030848 9012040340 8012040408 8012040408 9012040408 | 70-2623 PR 50-369 50-369 50-369 | S S A | | 8012300471 8012300475* 8012300485 8012300488* 8012300495 | 50-287 50-287 50-287 50-287 50-269 | 99999 |
| | 8012050270 80120503024 80120503024 80120503144 80120503144 | 50-369 50-369 50-369 50-369 50-369 | A A A A | | 8012300498+ 8012300601 8012300606 8012310167 8012310167 | 50-269 50-369 50-369 50-269 50-269 | S A S Q |
| | 8012050391 8012050391 8012050446 8012050446 8012030448 | 50-369 50-369 50-369 50-369 50-269 | ለ A A A P | Duke Univ. Duke University Medical Center Dunn Memorial Hosp. Bedford, IN | 8012310273 8012120005 8012120085 8012120204 8012070002 | 50-413 PR PR PR PR | Q |
| | 8012080594 8012080645 8012090367 8012090367 8012100311 | 50-269 50-369 50-269 50-269 50-269 | a a o o p | Duquesne Light Co. | 8008210481 8012010300 8012010303 8012020355 8012020526 | 50-334 50-334 50-334 50-334 50-334 | 0 8 8 9 8 |
| | 8012100311 8012100311 8012100374 8012100465 8012100467+ | 50-269 50-269 50-269 50-270 50-270 | P P 9 8 | | 8012020527 8012030588 8012030617 8012030652 8012030659* | 50-334 50-334 50-412 50-334 50-334 | B R A B B |
| | 80121005014 80121005064 80121005104 8012110613 8012110665 | 50-259 50-259 50-259 50-413 50-413 | 6 5 8 Q Q | | 8012050402 8012050407+ 8012050413 8012050414+ 8012080436 | 50-334 50-334 50-334 50-334 50-334 | 98898 |
| | 80121206104 8012150069 8012160325 8012160435 8012170046 | 50-269 50-369 50-269 50-269 PR | Q A P O | | 8012080437* 8012080456 8012080467 8012070001 8012070010 | 50-334 50-334 50-334 50-334 50-334 | 8 5 8 9 9 |
| | 8012170060* 8012170669 8012180137* 6012180283 8012180285 | 50-413 50-289 50-413 PR PR | 0 16 0 | | 8012090269 8012090389 8012090392* 8012100083* 8012100090* | 50-334 50-334 50-334 50-334 50-334 | 6 6 9 0 |
| | 8012180361 8012180361 8012180397 8012180591 8012180674 | 50-349 50-349 50-349 50-249 50-349 | 0 0 0 0 | | 8012100462 8012100463+ 8012120522 8012120530+ 8012120535+ | 50-334 50-334 50-334 50-334 50-334 | 8 8 8 |
| | 8012180674 8012190205 8012190462 8012190615 8012190615 | 50-369 50-413 50-269 50-269 50-269 | 0 0 P R R | | 8012120539 8012120545* 8012150273 8012150277* 8012160481 | 50-334 50-334 50-334 50-334 50-334 | 8 8 R 8 |
| | 6012190615 8012190619+ 8012190619+ 8012190619+ 8012230014 | 50-269 50-269 50-269 50-269 50-369 | R R R R | | 8012160488* 8012170463 8012170567 8012170572* 8012170501 | 50-334 50-334 50-334 50-334 50-334 | S F R R |
| | 801 223001 4 801 2230330 801 2230330 801 2230345 801 2230435 | 50-369 50-369 50-369 50-369 50-269 | 0 f f A P | | 8012190509* 8012190587 8012190590* 6012190592* 8012190596* | 50-334 50-334 50-334 50-334 50-334 | 8 8 8 8 |
| | 8012230450 8012230450 8012230450 8012230458 8012230458 | 50-269 50-269 50-269 50-369 50-369 | P P Q Q | | 8012170600* 8012170602* 8012230277 8012230441 8012230445* | 50-334 50-334 50-334 50-334 50-334 | S 8 8 8 8 |
| | 8012230459 8012230479 8012230479 8012230479 8012230489 | 50-369 50-269 50-269 50-269 50-269 | 0 5 5 P | | 8012230528 80122305334 80122305384 8012300409 8012300659 | 50-334 50-334 50-334 50-334 50-334 | 8 8 8 P 8 |
| | 8012230514 80122305204 80122305354 80122305374 80122305414 | 50-369 | 8 8 A A A | | 8012300667* 8012300670* 8012300676* 8012300681* 8012300686* | 50-334 50-334 50-334 50-334 50-334 | 6 8 9 9 6 |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|--|---|--|--|---|--|
| EQ%9 Idaho, Inc. | 8012040593 8012040591 8012080010 8012100643 8012110551 | RES RES NUREG RES RES | | 8012170280 8012170287* 8012170325 8012170331 8012230159 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC |
| EQ&G. Inc. | 8012220174 8012220623 8012220670 8012220707 8012240087 | REG NURED NURED NUREG PR | Ezzon Nuclear Idaho Co. FOI Service | 8012230204* 8012230507 8012230511* 8012240443* 8012030722 | XPORTLIC TOPREP TOPREP ORO FOIA |
| Earth Sciences Associates Eaton T. E. Ebasco Bervices, Inc. (subs of Enserch Gorp.) | | NUREG SO-70 P CONTRACT REGGD | Factory Mutual Research Factory Mutual System Family Hosp. Milwaukee,WI Federal American Partners | 80120903024 8012010013 8012080693 8011070245 8012220134 | 50-397 F 71-9141 PR 40-4492 40-4492 |
| | 80121002274 | 50-333 0 | Federal Coordinating Council for | 80120500054 | GRG |
| Eberline Instrument Corp. | 8012160408 8012240047 8012240189 8012100436 8012300212* | TOPREP 50-395 S 50-392 A XPORTLIC CONTRACT | Science, Eng. & Technology Federal Energency Management Agency | 8012020653 8012040072 80120500024 8012050007* | NUREO PR ORO ORO |
| Eckert, Seamans, Cherin & Keilott | 801202075B 8012270011 | 70-2909 70-2 7 09 | | 8012080550+ 8012080563+ | 50-327 F 50-327 F |
| Edison Electric Institute | 8012270206 8012080769 8012090100 | 70-2709 PR PR | Federal Energy Administration | 8012110538* 8012230216* 8012240015* | FOIA COMMISSION COMMISSION |
| Editorial Consultants, Inc. | 8012300154* | CONTRACT | Federal Energy Regulatory Commission | 8012160402 | 50-395 D |
| Edlow International Co. Edward A. Utlaut Foundation, Inc | 8012010545 8012310066 8012220067 | 70-2392 XPORTLIC PR | Fleischaker, D. S. | 8012270513 8011250108* 8012080513 | 50-320 1 50-275 0 50-275 0 |
| E.A. Utlaut Hemorial Hosp. Greenville, IL. Edwards Trucking Co., Inc. | E012110527* | CONTRACT | | 8012080513 8012170440 | 50-275 0 50-275 0 |
| Eichharn, Eichhorn & Link | 8012270181 8012310437 | 50-367 Q 50-367 Q | | 8012170440 8012170442* | 50-275 0 50-275 0 |
| Electric Power Research Institute | 8012020377* 8012050440 8012290066 | 100FR NUREQ 70-2623 | | 8012170442 4 8012270120 | 50-275 0 50-275 0 |
| Electric Utility Companies Nuclear Transportation Group | 8012290071 | 70~2623 | | 8012270120 8012300364 8012310283 | 50-275 0 50-275 0 50-275 0 |
| Eli Lilly & Co., Lilly Research Laboratories Div. | 8012110323 | PR | Florida Pouer & Light Co. | 8012010091 8012010106 | 50-250 P 50-335 P |
| Energy Fuels Nuclear, Inc. Energy Technology Engineering Center | 8012080780 8012020073* 6012080805 | 40-8681 50-438 A 50-329 A | | 8012010131 8012020071 8012020079 | 50-250 P 50-335 F 50-250 P |
| Energy, Dept. of | 8012050462 8012050474+ 8012050482 8012050485* | PR PR PROJ PR | | 8012020079 8012020121 8012020121 | 50-250 P 50-250 P 50-250 P |
| | B012050493* | PR | | 8012020467 8012020474* | 50-251 S 50-251 S 50-335 B |
| Energy, Dept. of, Clinch River Breeder | 8012070032* 8012110358 8012270593* 8012020497 | ORO NUREG SECY 50-537 A | | 8012020501 80120205074 8012020534 | 50-335 8 50-335 8 |
| Reactor Plant | 8012050383 | 50-537 B | | 8012020538 80120205424 | 50-250 S 50-335 S |
| | 8012310303 8012310305# | 50-537 B 50-537 B | | 80120205444 8012020548 | 50-250 S 50-335 S |
| Engineering Design Concepts, Inc. Engineering Science Environmental Coalition on Nuclear Power | 8012030869 8012300664* 8012290083 8012290459 | FOIA 50-466 T 50-463 G PR | | 8012020551 8012020555* 8012020557* 8012020561 8012020567* | 50-335 8 50-335 8 50-335 8 50-335 8 |
| Environmental Policy Institute | 80122707514 80120403424 8012040348* 80122403744 | 50-289 0 100FR 100FR State Prog | | 9012040085 8012040085 8012050452 | 50-250 F 50-250 F 50-335 S |
| Environmental Protection Agency | 8012080743 8012220284* | PROJ FOIA | | 80120802204 80120802204 | 50-335 S 50-250 F |
| | 8012240267 8012300539 | NASTE MGT 50-375 D | | 8012080225+ 8012080234+ | 50-250 F 50-250 0 50-387 0 |
| Envirosphere Co. Equifax Health Systems Div. | E012090089 E012170524⊀ | PR NUREO | | 8012080558 8012070117 8012070177 | FR 50-389 A |
| Exxon Corp. | 80123100314 8012020092 | NUREG 71-9070 | | 8012100404 | 50-335 B |
| Exxon Hinerals Co., USA | 6012010227 6012100106 | 40-8064 40-8064 | | 8012100407* 8012100476 | 50-335 S 50-335 S |
| | 8012100114× | 40-8064 | | 8012100479# 8012100522 | 50-335 S 50-335 S |
| Erron Nuclear Co., Inc. (subs. of Erron Corp.) | 8015010590* | 71-9073 | | 8012100528* | 60-335 B |
| | 6012020313 6012050093 60120802674 | 70-1257 71-6581 GA777 | | 8012100532 8012100538* 8012110805* 8012150233 | 50-335 8 50-335 5 FOIA 50-335 P |
| | 8012080796 8012090257 8012100379 6012170270 8012170273* | 40-B102 XPORTLIC TOPREP XPORTLIC XPORTLIC | | 8012160145 8012160466 8012160466 8012160465 | 50-250 P 50-250 R 50-250 R 50-250 P |
| | | | | | |

| AUTHOR AFFILIATION | ACCESS ION NUMBER | SUBJECT CATEGOR | ŧ٧ | AUTHOR Affiliation | ACCESSION NUMBER | SUBJEC CATEGO! | |
|--|--|--|------------------|---|---|--|---------------------|
| | 8012160468* 8012160468* 8012160468* 8012170303 8012180207* | 50-250 50-250 50-250 50-250 50-387 | R R R A | Friends of the Earth OH Bettis Corp. Gage-Babcock Associates, Inc. | 8012160262 8012080266 8012300509 8012100406 8012110157= | FOIA FR 50-941 PT21 FOIA | , |
| | 8012180258 8012180258 8012180258 801218025# 8012180245* | 50-250 50-250 50-250 50-250 50-250 | R R R R | Gainesville.FL Gary.IN General Accounting Office | 8012110164* 8012290399* 8012290535 8012290536* 8012220017 | FOIA 50-389 50-367 50-367 COMMISS | 101 0 0 10 |
| | 8012180265* 8012190422* 8012190425 | 50~250 50~267 50~389 | R P K | General Atomic Co. (subs. of Gulf Gil Co.) | 8011250704* 8012040407* | 50-579 50-267 | A |
| | 8012270431 * 8012220301 | 50-387 50-251 | a | General Electric Co. | 8012080770# 8012080778# 8002210087 | 8ECY 8ECY 70-754 | , |
| | 8012220307* 8012220614 8012240179 8012240430 8012240430 | 50-251 50-389 50-335 50-250 50-250 | О Р Р | | 8012010622 8012010626* 8012020258 8012020265* 8012020300 | 70-1308 70-1308 TOPREP TOPREP 70-754 | |
| | 8012270321 8012270326* 8012270370 8012300216 8012300320 | 50-250 50-250 50-387 50-335 50-250 | P H P P | | 8012020307 8012030285 8012030697 8012030854* 8012040372 | 70-1308 TOPREP TOPREP 50-10 PR | P |
| | 8012300320 8012300334# 8012300334# 8012300516 8012310410 | 50-250 50-250 50-250 50-250 50-335 | 6 6 6 | | 8012040470 8012040492* 8012050084 8012050126 8012050149 | 70-1113 70-754 PR TOPREP 50-70 | P |
| Florida Power Corp. | 8012010097 8012010098* 8012010511 8012020524 8012020531* | 50-302 50-302 50-302 50-302 50-302 | P Q \$ | | 8012080261 8012080688 8012090055 8012110008 8012110015* | REGOD PR PR 50-226 50-226 | e e |
| | 8012020635 8012020644* 8012040382 8012080738 8012090211 | 50-302 50-302 PR 50-302 50-302 | 8 9 Q P | | 8012120322 8012120382* 8012150095 8012150094* 8012140424* | NUREO 40-6622 50-447 50-447 70-754 | 8 |
| | 8012090212* 8012090220 8012150238 8012160483 8012160487* | 50-302 50-302 50-302 50-302 50-302 | P F R R | | 8012160512* 8012170444 8012180166 8012180464* 8012180472 | 50-237 50-447 PR 50-245 70-1113 | P B |
| | 8012170505 8012220304 80122203124 8012230317 8012230433 | 50-302 50-302 50-302 NUREG 50-302 | P 8 8 | | 8012190026 8012190029 8012220250 8012230254 8012230550 | XPORTL I XPORTL I TOPREP 40-823 I TOPREP | |
| | 8012230437* 8012230440 8012230446* 8012230448 8012230454* | 50-302 50-302 50-302 50-302 50-302 | 8888 | | 8012240089 8012290088* 8012290531* 8012300482 8012300486* | 50-352 COMMISS 70-1308 TOPREP TOPREP | |
| | 8012230513 8012230524* 8012240232 8012240274 | 50-302 50-302 50-302 50-302 | 8 0 P | General Electric Co., Nuclear Energy | 6012300613* 6012310579* 8012030441 | 50-263 CONTRAC 50-289 | т <mark>Р</mark> . |
| | 8012240328 8012240332 4 | 50~302 50~302 | P | Products Div. General Public Utilities | 8012110417# 8012130178# | 50-287 50-289 | 00 |
| | 8012300481 8012300501 8012300512+ 8012300740 | 50-302 50-302 50-302 50-302 | 8 8 0 | | 8012160144 8012160154* 8012170074* 8012300269* | 50-219 50-219 50-289 50-289 | 00101 |
| Florida Btate Univ. Florida, State of | 8012220634 8012310624 4 8012020294* | NUREG CONTRAC Blate P | rog | General Public Utilities - OPU Service Corp. | 8003170023 | 50-219 | Ρ. |
| Florida, Univ. of, Gainesville | 8012090130* 8012160107 | 50-34B 50-83 | ŗ | | | | |
| Fluor Power Service, Inc. | 8012160110* 8012230344 8012230348* 8012300506 8012080110 | 50-83 50-83 50-83 50-83 PR | R R P | | | | |
| Fort Pierce,Fl Foster O. McOraw Hosp. Chicago, Ii. Frances A. Ball Memorial Hosp. Ishpemins, | 8012090054 8012290393+ 8012110273 8012290133 | PR 50~387 PR PR | н | General Research Corp. | | | |
| MI Franklin Institute/Franklin Research Center | 8012020725 | FOIA | | General Services Administration Geo-Centers, Inc. Georgetown Univ. Medical Center | | | |
| | 8012040450 8012110359* | ACRS CONTRAC | | Mashington, DC Georgia Institute of Tachnology | | | |

8012040450 ACRS 8012110359* CONTRACT 8012110409* CONTRACT

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC | JRY | ADHTUA AGITAL⊥IFA | ACCESION NUMBER | SUBJECT CATEGORY |
|---|---|--|-----------------------|--|---|--|
| Georgia Power Co. | 8012290144 8012010307 80120103144 8012010325 80120103464 | PR 50-366 50-366 50-321 50-321 | S S S | | 80120505404 80120505424 80121603E3 80121707264 80121707344 | 50-458 F 50-458 F 50-458 A 50-287 H 50-458 Q |
| | 8012010349 8012010357+ 8012010371 8012010377 8012010363+ | 50-366 50-366 50-366 50-321 50-366 | ទទទទ | | 8012170633* 8012170638* 8012220667 6012220667 | 50-458 0 50-458 0 50-458 0 50-458 0 |
| | 8012010384 80120103934 80120103944 8012020440 8012020500 | 50-366 50-366 50-321 50-424 50-366 | 5 5 4 5 | HEW, Dept. of, Food & Drug Administration HHS, Dept. of, US Public Health Service | 8012310332 8012080503* 8012030549* 8012030573* 8012030516* | SO-458 A CONTRACT FOIA FOIA FOIA |
| | 8012020507* 8012020511 8012020514* 8012020752 8012030817 | 50-366 50-366 50-366 50-366 50-321 | S S Q | | 8012030622* 8012030651* 8012030472* 80120304824 8012110319 | FOIA FOIA FOIA PR |
| | 8012080148 8012090371 80120903774 8012090379 8012090384* | PR 50-346 50-346 50-321 | 5 5 5 | Hanford Engineering Development Laboratory | 8012050488* 8012050492* 8012050496* 8012230325 | PROJ PROJ PROJ NUREG |
| | 8012090385 8012090385 8012110532* 8012150184 8012150187* | 50-321 50-321 50-321 50-366 50-366 | P 0 8 | Harmon & Weiss Harrisburg Hosp. Harrisburg,PA Harrisburg, PA | 8012270313 8012270317+ 6012270322 8012110337 8012020578 | 70-2623 70-2623 50-443 0 PR 50-320 P |
| | 8012150169 8012150195* 8012170629 8012170637* 8012180161 | 50-366 50-366 50-366 50-366 Pr | 5 5 5 5 | Harstead Éngineering Associates, Inc. Hartford Memoriai Hosp. Hartford, WI Harvand Univ. Hawaii, Univ. of, at Monoa, Honolulu, Hi | 8012040325+ 8012290139 8012110345 7910150058+ 8012030010+ | 50-315 P PR PR FOIA FOIA |
| | 8012230064 8012230064 8012230197 8012230252 8012230295* | 50~321 50~321 50~424 50~321 50~321 | Q Q A R R | | 80120302014 8012030325# 80120303804 8012030388# 8012030405* | FOIA FOIA FOIA FOIA |
| | 8012230298 8012230301+ 8012230364 8012230542 8012230549* | 50-366 50-366 50-321 50-366 50-366 | R P S S | Health & Human Services, Dept. of, | 8012030442+ 80120304614 80120304644 80120304734 8012030497* | FOIA FOIA FOIA FOIA |
| | 8012240235 8012240264 8012240268≠ 8012240280 8012240285≠ | 50-321 50-321 50-321 50-366 50-366 | 9 9 9 9 | | 8012030509* 8012030523* 8012030531* 8012030562* | FOIA FOIA FOIA FOIA |
| | 8012240297 80122403044 8012270240 8012270248 80122702534 | 50-366 50-366 50-366 50-366 | 8 8 8 | | 8012030597* 80120306144 8012030618* 8012030621* 8012030623* | FOIA FOIA FOIA FOIA |
| | 8012270259 8012270266* 8012270325 8012270335* 8012310276 | 50-366 50-366 50-321 50-321 50-424 | 8 8 8 | | 8012030625* 8012030627* 8012030676* 8012110081 8012120369 | FOIA FOIA PR PR |
| | 8012310276 8012310278* | 50-424 50-424 | B | Health Management Systems Henry County Health Center, Mt. | 80122301384 | CONTRACT |
| Georgia, State of Georgia, Univ. of, Germany, Federal Republic of | 8012310278* 8012070117* 8012110044 8012110331 8012020351* | 50-424 50-348 PR PR 10CFR | F | Pleasant.IÀ Hanry.A.F Hill Christopher & Phillips | 80122202494 8012290002 8012290161 8012290407 | CONTRACT 50-275 Q 50-275 G 50-275 G |
| | 241220001 | REGOD REGOD 50-375 REGOD | A | Hassanania Bacha, Inc. Janha at 5 | 8012290462 8012300117 8012310588 6012310588 | 50-275 0 50-275 0 50-275 H 50-275 H |
| | | QA999 QA999 QA999 | | Hoffman-La Roche, Inc. (subs. of F. Hoffman-La Roche & Co., Ltd.) | 8012180205 | PR |
| | | | 8 P | Homestake Mining Co. Hopkinsons, Ltd. House of Rap. | 8012180443 8012070051+ 8012070054+ 80120700574 8012010587* | WASTE MGT GA999 GA999 GA999 50-324 U |
| | | | | | 80120307694 80120307614 80120308594 8012090255 80120902664 | 50-320 U 50-289 H M18C 50-273 H COMMISSION |
| | | | 3 | | 8012090413+ 8012100072 | COMMISSION 50-29 H |

| AUTHOR AFFILIATION | ACCESS I ON MUMBER | SUBJECT CATEODS | RY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEODRY |
|---|---|--|-----------------------|--|--|--|
| House of Rep., Armed Services House of Rep., Government Operations | B012100469+ B012110043+ B012290045 E012040406 B012110167+ | 50-320 COMMISS 50-247 50-289 COMMISS | U ION H U | | 8012180292* 8012180312 8012180312 8012180315 8012180315 | 50-315 P 50-315 P 50-315 P 50-315 P 50-315 P |
| House of Rep., Interior & Insular Affairs House of Rep., Judiciary Committee Housing & Urban Development,Dept. of Houston Lighting & Power Co. | 8012020838* 8012080654 8012010316 8012020634* 8012030655 | 50-367 PR 50-375 50-466 50-498 | U D G Si | | 8012180317* 8012180321* 8012180321* 8012190500 8012190505* | 50-315 P 50-315 P 50-315 P 50-316 R 50-316 R |
| | 8012030555 8012030565 8012030566 8012160297 8012170327 | 50-498 50-498 50-498 50-498 50-498 | S S G K | Indiana Univ. Indiana, State of | 8012040140* 8012300636 8012030823 8012040401 8012080333 | CONTRACT 50-367 A NUREQ 50-247 H PR |
| | 8012170327 8012170333* 8012170333* 8012170420 8012170418 | 50-498 50-498 50-498 50-498 50-498 | К К С С | Inhalation Toxicology Research Institute Institute for Nuclear Serology | 8012080465 8012080476 8012080667 8012040061 80120305114 | PR PR PR NUREO FDIA |
| | 8012190447* 8012220030* 8012230053 8012290005 8012290091 | 50-498 50-498 50-498 50-466 50-466 | Q O O O O | Interior, Dept. of | 8012010210 8012030836 8012040108 8012240399* 8012310379 | 40-8743 PR PR State Prog: 40-2041 |
| | 8012290143 8012290295 | 50-445 50-466 | и 0 | Interior.Dept.of, Bureau of Land Management | 8012010272 | 40-8743 |
| | 8012290344 8012270641 8012300251 8012300318 | 50-466 50-465 50-445 | 0 G H | Interior, Dept. of. Fish & Wildlife Service | 8012080724 80120303774 8012030475* 8012030571* | FOIA FOIA FOIA |
| | 8012300458* 8012300475* 8012300492* 8012300702* | 50-445 50-466 50-466 50-466 50-466 | (6 T T T | Interior,Dept.of, Geological Survey Interior,Dept.of, National Park Service | 8012240293 8012310523 8012010276 8012030823 8012080653 | 50-397 C 40-8745 50-361 A NUREQ 40-1341 |
| Human Design Group Hunton & Williams | 80123007114 8012230335 8012090263 8012090263 80120902654 | 50-466 50-320 50-450 50-450 50-450 | T P G G G | Jowa Electric Light & Power Co. | 8012080677* 8012090310 8011190098 8012010366 8012010409 | 40-1341 50-367 A 50-331 0 50-331 I 50-331 8 |
| | 80120902454 8012090297 8012090297 8012090298* 8012090298* | 50~450 50~463 50~463 50~463 50~463 | 0 0 0 0 | | 8012020492 8012020495* 8012020541 8012020546* 8012020603 | 50-331 8 50-331 8 50-331 8 50-331 8 |
| | 8012100471* 8012100471* 8012170819 8012230058 8012230058 | 50-463 50-463 50-280 50-450 50-450 | G G G G | | 8012020613* 8012050399 8012070294 8012090296* 8012090318 | 50-331 S 50-331 P 50-331 0 50-331 0 50-331 P |
| IGI Americas, Inc. IRT Corp. Ichthyological Associates, Inc. | 8012300572 8012100045 8012100053* 8012170432 8012160486* | 50-516 PR PR NUREG 50-209 | e R | | 8012070321* 8012110769* 8012170717* 8012170593 8012170597* | 50-331 F 50-331 Q 50-289 H 50-331 S 50-331 S |
| Idaho National Engineering Laboratory | 8012190044 8012190049 8012190061 8012190547 8012220186 | RES RES 50-409 50-312 RES | P P | | 8012170643 8012170650* 8012230297 8012230311 8012230314* | 50-331 8 50-331 8 50-331 P 50-331 R |
| lilinois Pawer Co. | 80120402474 8012060340 8012220154 8012220162 8012270165 | 50-461 50-461 50-461 50-461 50-461 | Q A Q Q G | | 6012230457 6012240241 60122402634 8012270410 6012270414 | 50-331 P 50-331 S 50-331 0 50-331 S 50-331 8 |
| Illinois Safe Energy Alliance Illinois State Univ. Illinois, State of | 8012310315 80123103174 8012240403 8012120319 8012020681 | 50-461 50-461 50-295 PR 50-237 | к к н | torre librire and | 8012270422 8012270428* 8012300465 8012300468* 8012100211 | 50-331 8 50-331 9 50-331 8 50-331 8 PR |
| | 8012020685 8012020670 8012300081 8012300081 8012300084* | 50-367 50-367 50-237 50-237 50-237 | 0 0 0 0 | Iowa, Univ. of Isbin,H. Isham, Lincoln & Boale | 8012100189* 8012090132 8012100039 8012110345 8012110540 | CONTRACT PR 50-445 M 50-10 0 50-237 0 |
| Illinois, Univ. of, Urbana-Champaign | 80123000844 8012300070 8012300114 8012040178 8012070303 | 50-237 50-237 50-461 50-151 50-151 | 0 0 F 8 | | 8012110606 8012110650 8012160332 8012160332 8012160332 | 50-10 0 FOIA 50-237 0 50-237 0 50-329 0 |
| Indiana & Michigan Electric Co. | 80120405784 8012100553 8012160473 80121604764 8012180281 | 50-315 50-315 50-315 50-315 50-315 | F G 8 S | | 8012300122 8012300122 8012300122 | 50-237 0 50-237 0 50-237 0 50-445 H |
| | | | | | | : |

| AUTHOR AFFILIATION | ACCESSION NUMBER | EUBJEC CATEGO | RY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC | |
|--|---|---|------------------------|---|--|--|------------------|
| | 80123002274 6012300324 8012300324 6012300333* 8012300333* | 50-445 50-237 50-237 50-237 50-237 | 14 0 0 0 0 | | 8012010297 8012090105 8012100054 80121000604 8012150076 | CATEGO: 50-244 PR PR PR PR 50-220 | ~ |
| | 80123003414 80123003414 8012300360 8012310289 8012310289 | 50-237 50-237 50-155 50-237 50-237 | G G G | | 8012150155 8012240365 8012290066 8012290071 8012310294 | 50-220 State P ₁ 70-2623 70-2623 50-220 | rog |
| Island Closeup News Service | 80123102674 8012310267* 8012110216 8012110542 8012180328 | 50-237 50-237 FOIA FOIA FOIA | 0 | League Against Nuclear Dangers Minnesota Chapter Legal Service of Upper East Tennessee Limitorque Corp. Linn County, IA | 8012220175 8012180607* 8012100635* | 50-409 70-143 QA999 50-331 | H |
| J. Ray McDermott & Co. JHK International Corp. Japan Jersey Central Power & Light Co. | 8012240352 8012100022+ 8012110115 8012220471 8003120301 | XPORTLIC CONTRAC XPORTLIC XPORTLIC 50-219 | T C C | Long Island Committee for Jobs & Energy Independence Long Island Lighting Co. | 8012150164 8012010080 8012020723* 8012050373 | 50-289 50-322 50-322 | H A H |
| | 8003173023 8012010318 8012010319 8012020552 8012020555 | 50-219 50-219 50-219 50-219 50-219 | P 8 8 8 | | 8012100294 8012150216 8012150220* 8012150225* 8012180301 | 50-322 50-322 50-322 50-322 | A K K Q |
| | 8012040445 8012040489 8012080420 8012090177 8012090204 | 50-219 50-219 50-219 50-219 50-219 | 6 8 P F | Los Alamos Scientific Laboratory | 8012240221# 8012300479 8012300572 8012310414 8012040655 | 50-322 50-322 50-514 50-322 ACRB | e e o |
| | 8012070363 8012070466 80120704714 80121604314 8012160461 | 50-219 50-219 50-219 50-219 | 8 8 H V | Louisiana Power & Light Co. | 8012170040 8012230077 8012100473 8012180386 8012170473 | NUREG NUREG 50-382 50-382 50-382 | A A K |
| | 8012160462 8012160491# 8012160546 8012160554# 8012220404 | 50-219 50-219 50-219 50-219 50-219 | 8 8 8 | | 8012190479* 8012190540 8012220694 8012220697 8012300874 | 50-382 50-382 50-382 50-382 50-382 | 8 0 0 6 |
| Johns Hopkins Medical Institutions Baltimore MO | 80122204084 8012230198 8012230468 8012310418 8012010522 | 50-219 50-219 50-219 50-219 PR | R P 9 0 | Louisiana State Univ. Louisiana, State of Louisvilla, Univ. of Lovelace Biomed & Environmental Research | 8012300581 8012110289 80120806354 8012100159 8012040061 | 50-392 PR 50-416 PR NUREG | s F |
| Johnson City Press-Chronicle Johnson City, TN | 8012100237 8012240130 | PR 70-143 | | Institute Lowenstein,Newman,Reis,Axeirad & Toll | 8012020446 80120204504 | 50-344 50-344 | e e |
| Johnston Labs Justice, Dept. of | 8012110324 8012300040+ 8012300239 8012300250 | PR 50-445 50-389 50-445 | M M | | 8015100085 8015040352 8015040352 8015040931 8015050658 | 50-466 50-466 Pr 50-344 Pr | G G |
| KMO International, Inc. (Ketchum MacLeod & Grove) Kansas Gaw & Electric Co. | 80120200251 8012170241 8012020083 80120200874 | 50-445 FOIA 50-482 50-482 | C C | | 8012110014 6012290005 8012290048 8012290091 8012290156 | 50-367 50-466 50-344 50-466 50-466 | G 0 0 T |
| Kansas State Univ. Kansas, Univ. of | 80120200734 8012070289 8012080262 8012080330 8012080237 | 50-482 50-482 PR PR PR | c c | | 8012270235 8012270275 8012270370 8012270441 8012300451 | 50-367 50-466 50-389 50-466 50-344 | 0 0 0 |
| Kays, Scholer, Fierman, Hays & Handler Kearsarge Hetallurgical Corp. Kentucky, State of | 8012100137 8012100531 8012160404 8012180382 8012110094 | PR 50-148 50-320 XPORTLIC PR | F 0 | Lower Alloways Creek, NJ MD Color Photo MHB Technical Associates | 8012300457* 8012290397 8012300163* 8012170682* 8012300093* | | G G G |
| Kohm, H.I. Lakeshore Citizens for Safe Energy Lawrence Livermore Laboratory | 80122404044 8012230149* 8012290306 8012020738 8012020744 | State Pro CONTRACT 50-266 NUREO NUREO | o O | MPR Associates, Inc. Haine Yankee Atomic Power Co. | 8012080505+ 8012150286+ 8012020268 8012020569 8012020597+ | 50-309 50-309 | P P R R |
| | 8012030379 8012040070 8012100542* 8012110491 8012120307 | NUREO | P A | | 8012100319 8012110516 8012150082 8012190469 8012230430 | 50-309 50-309 50-309 | 0 6 F P |
| Leyman, E. S. | 8012120308 8012230370 80120300834 8012030104* 8012030112* | 50-204 NVREQ 27-39 27-10 27-10 | P | | | 50-309 50-309 50-309 | S S R R |
| LaBoeuf, Lamb, Leiby & MacRae | 8012030134* 8011180561 | 27-10 50-285 | P | | | PR PR | |

| Market M | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | Y | | AUTHOR AFFIL 1AT ION | ACCESSION NUMBER | SUBJECT CATEGORY |
|--|---|--|--------------------------------------|------------------|---|---|--|--|
| ### STATE OF THE PROPERTY OF T | Mapleton Intervenors Marrach D. Marsh & McLeunan, Inc., M & M Nuclear | 8012110204 8012020649 8012290271 8012290627 | PR 50-329 50-466 50-466 | 0 | | | 8012160500 + 8012160521 8012170481 | 50-320 \$ 50-289 8 50-289 8 |
| ## 1901-000-1909 190-200 | Consultants, Inc. Div. | 8012010360 8012010360 8012020473 | 50-272 50-272 50-327 | .; .; .; | | | 8012170518 8012170517* 8012170591 8012220080* | 50-320 P 50-289 R 50-320 S 50-289 0 |
| Maryland, Unity of Ballium Section Secti | | 8012020562 8012100511 | 50-89 50-327 | J. | | | 8012220237 8012220383 8012220388+ | 50-320 P 50-320 P 50-320 P |
| ### Company Co | Maryland, State of | 80122903704 | 50-320 | н | | | 8012230480* | 50-320 \$ |
| Massachusetts Institute of Technology 101200077 MREG 101200077 MREG 101200077 | Maryland, Univ. of, Baltimore | 6012080216 8012080228 6012080312 6012080317 | PR PR PR PR | • | | | 8012290461* 8012290663 8012300160* 801230038B | 50-289 F 50-320 Q 50-320 Q 50-289 P |
| Solid Control Solid Contro | Mason & Hanger - Siles Mason Co., Inc. Massachusetts Institute of Technology | 8012110186 8012120217 8012120350 8012030686 | PR NUREG NUREG 50-20 | ន | | | 8012300473* 8012300608 8012300621 8012300627 | 50-320 S 50-289 P 50-320 P 50-320 P |
| ### ### ### ### ### ### ### ### ### ## | | 8012080794 8012140009* 8012140012* | NUREO FOIA FOIA | | | Michigan, Univ. of | 8012300645 8012310318 8012310324 | 50-320 P 50-320 P 50-320 P |
| Mathesian Oas Products | Massachusetts Voice of Energy Massachusetts, State of | 60111903634 | 50-443 | A | | | 8012100191 8012120374 | PR PR |
| Nathern Oas Products No. Products No. Products No. Products No. No. Products No. No. Products No. No. No. Products No. | | 8012030479* | FOIA | A | | Consultants, Inc. (MBTC, Inc.) | | |
| Mad Johnson & Co. | Mayer, Brown & Platt McCutlough, E. R. | 8012270527 8012160085 | 70-1308 50-10 | | | Mid-America Legal Foundation | 8012070573+ 8012220300 8012230006 | CONTRACT 27-37 27-39 |
| ### ### ### ### ### ### ### ### ### ## | Head Johnson & Co. Medical Center of Vermont Burlington, VT | | | | | Hershey, PA Minerals Exploration Co. (subs. of Union | 8012010036 | 40-8584 |
| Renerial forp of Hason County Ludington Boll2090066 FR | | | | | • | | | |
| Manual Sican-Kettering Cancer Center Mouvorthing Sican-Kettering Cancer Center Sican | Memorial Hosp of Mason County Ludington, | | | | | | 6012020449 6012020491 | 50-416 C 70-2936 |
| Mamphils State Univ. | Memorial Sican-Kettering Cancer Center New York, NY | | | | | | 8012050564 | 50-416 A |
| ### ### ### ### ### ### ### ### ### ## | | 80121004174 8012180221 8012120018 | CONTRACT PR PR | | | | 8012080184 8012080606* 8012080606* | RECOD 50-416 F 50-416 F |
| 8012020532 50-320 P 8012020574 50-289 0 8012070289 50-416 80120207791 50-289 0 8012070368 50-416 8012020797 50-289 0 8012070368 50-416 8012020797 50-289 P 8012040441 50-320 S 8012040441 50-320 S 8012050345 50-320 P 8012050345 50-320 P 8012050345 50-320 P 8012050345 50-320 P 8012050346 8012050343 50-416 8012050345 50-320 P 8012070348 50-320 P 8012100451 50-320 P | · · | 8012010105 8012020464 8012020469* | 50-320 50-289 50-289 | P P | | | 8012080721* 8012080727* 8012080727* | 50-416 F 50-416 F 50-416 F |
| B012040441 50-320 B012103941 50-416 B012103943 50-416 B012103943 50-416 B012103943 50-416 B012050345 50-320 B01210239* 50-416 B012050345 50-320 B012150311 50-416 B012050345 50-320 B012150313 50-416 B012050345 50-320 B012150233 50-416 B012090344 50-320 B012150253 50-416 B012090344* 50-320 B01216027 50-416 B012100177 50-429 T | | 8012020532 80120206744 8012020791 8012020799* | 50-320 50-289 50-289 50-289 | P 0 0 0 | | | 8012090259 8012090259 8012090568 | 50-416 8 50-416 8 |
| 80120903412 | | 8012040441 8012040613 8012050365 | 50-320 50-320 | S Q P | | | 8012100543 8012100543 8012110237* | 50-416 8 50-416 8 50-416 0 |
| SOI2100177 SO-289 T | | 8012070348 8012070348 | 50-320 50-289 50-320 | P P 8 | | | 8012150253 8012150253 8012160277 | 50-416 8 50-416 8 50-416 A |
| 8012110507 50-320 P 8012180103* 50-416 8012130189 50-320 B 8012190527 50-416 8012150189 50-320 B 8012190527 50-416 8012150260 50-320 P 8012230429 50-416 8012160421 50-287 F 8012300489 50-416 8012160442 50-320 P 8012300489 50-416 8012160452 50-320 P 8112151ppi, State of 8012080615* 50-416 | | 8012100177 8012100451 8012100458* | 50-289 50-320 50-320 | P P | | | B012160281 B012160497 B012170304 | 50-416 8 50-416 8 |
| 801220427 50-416 801220427 50-416 8012160367 50-320 P 801220099 50-416 8012160421 50-287 F 8012300489 50-416 8012160465 50-287 G 8012300489 50-416 8012160465 50-320 P Mississippi, State of 8012080615* 50-416 | | 8012110507 8012150185 8012150188* | 50-320 50-320 50-320 | B B | | · × | 8012190103* 8012190527 8012190527 | 50-416 9 50-416 9 |
| 8012160452 90-320 P Mississippi, State of 8012080615* 50-416 | | 8012160273 8012160367 8012160421 | 50-320 50-320 50-287 | <u>የ</u> የ | | | 8012240250 8012300098 | 50-416 5 50-416 5 |
| | | | | | | | | |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | ₹Y | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|--|---|---|-------------|---|---|--|
| Missauri, Univ. of, Columbia Mitre Carp. | 6012080285 8012170781 8012170784± 8012170769± 8012290615 | PR RES RES RES NUREG | | | 8012030560+ 8012030547* 8012030580+ 8012030593+ 8012030685+ | FOIA FOIA FOIA FOIA |
| Mitsubishi International Corp. (subs. of Mitsubishi Carp.) | 8012270617 8012100062 8012230202 | NUREG XPORTLIC | | New Hampshire Clamshell New Jorsey, State of | 8012040418 80120206874 80120304554 8012220395 | 50-289 0 50-289 0 FOIA |
| Montgonery County, MD | 80122302054 8012290270 | XPORTL 1C | | New Mexico, State of | 8012010037 | 50-352 p State Prog |
| Moratorium Inc. Morgan County Memorial Hosp. Martinsvill e.IN | 80122202584 8012170193 8012170234 | FDIA PR PR | | | 8012220194* 8012220200* 8012220207* 8012220243* 8012220244* | FOIA FOIA FOIA |
| Morgan, Lewis & Bockius | 8012120646 8012180227 | 59-409 PR | G | New Mexico, Univ. of New Orleans Edison League | 8012160197 | PR ' 50-287 H |
| Morton Norwich Products, Inc., Morton Sait Div. Muddy Run Ecological Laboratory, RMC | 8012300348 8012100173 8012300275# | 50~409 PR 50~171 | G | New York Univ. Medical Center New York, NY New York, State Univ. of, Stony Brook New York, State of | 8012100243 8012240309 8012050038 | PR NUREG State Prog |
| Ecological Div. N. M. Newmark Consulting Engineering | 6015300565* | 50-171 | R | | 6012050056+ 6012050368 | State Prog 50-247 U |
| Services | 8012080767 | 70-754 | | New York, HY | 8012110296 8012300408 80120305014 | PR 50-302 K FOIA |
| NPS Industries, inc. NUS Carp. | 80120807744 80120807794 8012150252 8012030903 80122400354 | 70-754 70-754 50-329 27-39 CONTRACT | 8 | New York, State Univ. of. (Albany) New York, State Univ. of. College of Environ Sci & Forestry | 8012110067 80120808124 8012300636 | PR CONTRACT 50-367 A |
| National Academy of Sciences National Audubon Society National Council on Radiation Protection & Measurements | 8012100423# 6012300263 | CONTRACT | н | Newberry Tourship TMI Steering Committee Newport News Industrial Corp. (subs. of Newport News Shipbuilding & DryDock Co.) | 8012300264 8012190471 | 50-287 G TOPREP |
| National Economic Research Associates, Inc. | 80123006774 | 50-466 | T | Niagara Mohauk Power Corp. | 8012010350 8012030810 8012040424 | 50-410 0 50-410 0 50-220 P |
| National Naval Medical Center Bethesda, Mc | 80123006824 | 50-466 PR | T | | 8012040438 8012040577 | 50-220 P |
| National Treasury Employee Union National Valve & Mfg. Co. Natural Resources Defense Council | 8012010196* 8012080291* 8012110248 8012110562 | 71-9073 GA999 PR 30-320 | Р | | 8012040592+ 8012090015 8012090345 8012100472 | 50-220 0 50-220 0 50-410 5 50-220 5 |
| Navy, Dept. of | 8012180337 8012240370+ 8012270052 8012270313 80122703174 | FOIA State Pro 70-2623 70-2623 | 19 | | 80121004754 8012100477 80121004814 8012120637 8012160474 80121604804 | 50-220 S 50-220 S 50-220 S 50-220 G 50-220 R 50-220 R |
| | 8012030038+ 8012030050+ 8012030064+ 8012030094+ | FOIA FOIA FOIA FOIA | | | 8012190399 8012190448 8012190475 8012190514 8012230321 | 50-220 P 50-410 S 50-220 P 50-220 P 50-220 P |
| | 80:2030107# 80:2030107# 80:2030116# 80:2030168# 80:2030173# | FOIA FOIA FOIA FOIA | | | 8012230462 8012230472 8012290446+ 8012290491 8012300503 | 50-410 S 50-220 P 50-220 G 50-220 G 50-220 P |
| | 8012030180# 8012030175# 8012030226# 8012030320+ 6012030393# | FOIA FOIA FOIA FOIA | | Nissho-Iwai American Corp. | 8012310294 8012170317 8012230235 8012120199 | 50-220 G XPORTLIC XPORTLIC PR |
| | 60120305124 8012080817 80120808194 8012110504 80121105064 | FDIA 71-395 71-395 71-400 71-400 | | | 8012240377 * 8012240383* | 71-377 71-377 71-377 50-367 F State Prog |
| Nebraska Public Power District | 8012110508+ 8012010405+ 9012030706 | | O S | Northeast Nuclear Energy Co. (subs. of | | PROJ 50-245 P |
| | 8012030713# 8012090335 8012150079 | | 5 | | 6012020334 6012020527 | 50-336 P 50-336 P 50-336 S |
| | 8012150081+ 8012160128+ 8012160232+ | 50-278 f 50-278 c 50-278 c 50-278 c | ?)) | | 8012020573 8012040151 8012050262 | 50-336 S 50-245 P 50-336 0 50-245 P |
| New England Coalition on Nuclear Pollution | B015300953 | 50-298 F 50-298 F 50-443 C | 1 | | 8012080712 | 50-336 Q NUREQ 50-245 P |
| | 8012170675 | 50-443 G 50-443 G | } | | 8012090172 8012090172 | 50-213 G 50-213 G 71-6144 |
| New England Tonk Classics A. | 8012120076 | PR PR FOIA | | | 8012160117 8012160371 | 50-213 P 50-245 P PR |
| | | | | | | |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT | RY | AFFILIATION | ACCESSION NUMBER | SUBJECT | ì۲ |
|--|---|--|------------------|---|--|--|--|
| | 8012170330 8012180451 8012220123 8012230262 8012230262 | PR 50-245 50-245 50-213 50-213 | P Q P | E E E | 3012300305* 3012300310* 3012300310* 3012300578 | 50-282 50-282 50-282 50-263 50-263 | 6 th th |
| | 8012230262 8012230342 80122303434 8012230346 80122303474 | 50-213 50-245 50-245 50-336 50-336 | P R R R | Northrop Research & Technical Cunter E Northwestarn Univ. | 9012170314 9012170324# 9012040176# | 50-263 50-197 50-197 50-320 PR | P R R H |
| | 8012230384 8012230388* 8012230465 8012230471* 8012230469 | 50-336 50-336 50-336 50-336 50-245 | 5 5 5 5 | Nuclear Assurance Corp. Nuclear Chem Disposal Corp. E | 3012100206 3012240307 3012030448* | PR PR 71-6698 FDIA FOIA | |
| Northeast Utilities | 8012230467 8012310367 8012020769 8012220123 8012270270 | 50-245 50-245 10PREP 50-245 50-245 | S Q Q P | E Nuclear Corp. of America Isotopes Specialities Co. Div. | 9012030528* 9012030619* 9012030034* | FOIA FOIA FOIA FOIA | |
| Northeast Utilities Service Co. Northeastern Univ. Northern Indiana Public Service Co. | 8012300635 8012080712 8012220609 8012020427 8012020703* | 50-245 NUREG NUREG 50-367 50-367 | S A O | | 9012030300+ 9012030307+ | FOIA FOIA FOIA FOIA | |
| | 8012030583 8012070182 8012110014 8012160513 8012170130 | 50-367 50-367 50-367 50-367 50-367 | R R G R | Nuclear Energy Service, Inc. | 8012030397# 8012030535# 8012030551# 8012020318< 8012080495# 8012180304# | FOIA FOIA 50-409 50-409 50-322 | b b |
| | 8012240150 8012240431 8012240181 8012270235 8012300708 | 50-367 50-367 50-367 50-367 50-367 | А В В В | Nuclear Fual Services, Inc. (subs. of Sosty Oil Co.) | B012180307* B012180311* B012010547 | 50-322 50-322 70-143 | G G |
| Northern States Power Co. | 8012310439 8012010070 8012010351 8012010477 80120104934 | 50-367 50-282 50-263 50-282 50-282 | 0 7 7 8 | | 8012070004 8012100676* 8012160269 8012230432 | 50-201 70-143 70-143 70-143 50-201 | O R |
| | 8012020332 6012020476 | 50-282 50-263 | F | Reprocessing Plant | 8012040362 8012040410* | 50-201 | R |
| | 8012080317 8012080319 80120803234 80120803234 60120803274 | 50-282 50-282 50-282 50-282 | P P P | Nueces County TX Oak Ridge National Laboratory | 8012220135 8012030660* 8012100190 8012110003 8012180058 | XPORTLIC FOIA RES RES RES | : |
| | 6012080327+ 60120803604 60120803644 | 50-263 50-263 50-263 | F F | | 8012190185 8012190199 8012190208 | RES RES | |
| | 8012090005 8012090376 8012090381* 8012090396 80120904024 | 50-282 50-282 50-282 50-304 50-304 | 9 3 5 5 5 | Office of the Federal Register | 8012220181 8012300636 8012270250* 8012080142 | NUREO 50-367 ORO PR | Α |
| | 8012100047 8012150048 80121500514 8012150183 | 50-464 50-263 50-263 50-262 | 0 R R S | Westinghouse Electric Corp.) Ogle Patroleum, Inc. | 8012090042 8012150114* 8011170005 | PR 50-327 40-8745 | |
| | 8012150191 8012150197* 8012140453 8012140458* 8012140458* | 50-202 50-202 50-202 50-202 | 8 8 8 | | 8011170007* 8012100483 8012300508 8012300513* 8012120312 | 40-8745 40-8693 40-8745 40-8745 PR | |
| | 8012170440 8012180010 8012220177 8012220177 8012220162 | 50-282 50-263 50-282 50-283 50-263 | 8 0 0 | Ohio, State of Omaha Public Power District | 8012110170 8012110776# 8012050075 8011180569# 8012020607 | PR 50-150 PR 50-285 50-285 | 0 P S |
| | 8012220734 8012220734 8012230278 8012230285 8012230287+ | 50-282 50-282 50-263 50-263 50-263 | 0 0 | | 8012020416* 8012020470 8012020479* 8012040378 8012090092 | 50-285 50-285 50-285 PR PR | 8 |
| | 80122302874 8012240290 80122402944 80122402944 8012300214 | 50-263 50-262 50-262 50-262 50-282 | р 0 0 0 | | 8012100480 8012100484* 8012120210 8012150024 8012170538 | 50-285 50-285 50-285 50-285 | \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ |
| | 8012300214 8012300246 8012300305 8012300302 80123003054 | 50-262 50-263 50-282 50-282 50-282 50-282 | 5 5 5 | Oncavage. Hark | 8012190542* 8012220377 8012220607 8012270400 8012300453 | 50-285 50-285 50-285 50-250 50-243 | R P O O B |
| | | | | | | | ; 1 |

| Discount | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC CATEGO | | AUTHOR AFFILTATION | ACCESSION | SLBUB | ECT . |
|--|--|--|--------------------------------------|---------------|--|--|--|------------------|
| ### Pacific Gas & Electric Co. | Oregon, State of PRC Planning & Economics, Alan M. | 8012080243 80122403794 80123004574 80120800074 | PROJ State P 50-344 50-443 | 70g 0 F | | 80120303854 80120304074 80120304114 80120304214 | FOIA FOIA FOIA | ORY |
| BOIDCASTON BOI | Pacific Oas & Electric Co. | 80120800124 80120804404 80120804404 80122904734 | 50-443 50-443 50-443 50-275 | F F F | | 8012030436+ 8012030437+ 8012030438+ | FOIA FOIA 27-10 FOIA | |
| B0120000430 S0-275 A Paul Hourd Assective B012100030 S0-275 A Paul Hourd Assective B012100030 S0-275 A Paul Hourd Assective B012100030 S0-275 A B01200004 | | 8012040520 8012040520 8012050273 | 50-275 50-275 50-275 | A | | 8012030490# 8012030493# 8012030496 | FOIA FOIA FOIA | |
| BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO120700205 BO-275 BO120700205 BO120700205 BO-275 BO120700205 BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO-275 BO120700205 BO120700205 BO-275 BO120700205 BO-27 | | 8012050430 8012080335 8012080335 | 50-275 50-275 50-275 | A | Paul Howard Associates | 8012160305 8012150008 8012010326 | 40-462: 40-225: FOIA 50-387 50-387 | |
| \$01210025688 | | 8012070235 8012070327 8012070327 | 50-275 50-275 50-275 | AAA | | 8012020452 8012020452 8012020585 | | 88888 |
| BO12105306 50-275 A B01200033 50-297 A B01210530 50-297 B01210514 50-133 R B01210033 50-297 B01210514 50-133 R B01210033 50-297 B01210514 50-133 R B01210033 50-297 B01210514 50-297 B01210514 50-297 B01210514 50-297 B01210514 50-297 B01210524 50-297 B01210524 50-297 B01210524 50-297 B01210524 50-297 B01210524 50-297 B01220032 | | 8012100470 8012100470 8012110386 | 50-275 50-275 50-275 | AAF | | 8012020588 8012030663 8012030663 | 50-387 50-387 50-387 | 8 8 9 0 |
| BO12150149 NURSC BO12160348 S0-275 A BO12160348 S0-275 B BO12160348 S0-275 B BO12160349 S0-275 B BO12160374 PR BO12160374 PR BO12160374 PR BO1220375 PF BO1220375 PF BO1220375 PF BO1220377 S0-207 B BO1220 | | 8012110524 8012110530* 8012110533* | 50-275 50-275 50-275 | A A | | 8012070353 8012110415 8012160037 | 50-387 50-387 50-387 | Q A A A |
| ### SD122401244 50-275 ### SD12240124 50-275 ### S | | 8012150149 8012160158 8012160362 | NUREO 50-275 50-275 | A | | 8012160348 8012190028 6012190573 | 50-387 70-2937 50-387 | A A S |
| B012290134 S0-275 A B01220477 S0-387 B01220477 S0-387 B01220479 S0-275 B012200469 S0-275 B012200469 S0-275 B012200469 S0-275 B012200469 S0-275 B012200469 S0-287 B012200469 S0-287 B01220032 S0-275 B01220032 S0-275 B01220032 S0-275 B012200465 S0-275 B012200465 S0-275 B012200465 S0-275 B012200466 S0-287 B0122000466 B012200466 S0-287 B012200466 B012200466 S0-287 B012200466 B012200466 S0-287 B012200466 B0 | | 8012240127* 8012240134* 8012290008 | 50-275 50-275 50-275 | F Q | | 8012220463 8012230337 8012230474 | 50-387 50-387 50-387 | 8 K K |
| Bolt 23000752 50-275 0 80123000754 50-387 80123000754 50-387 80123000754 50-387 80123000754 50-387 8012300066 50-275 0 801230036 50-387 801230046 50-275 0 801230036 50-387 801230036 50-287 801230036 50-287 801230036 50-287 801230036 50-287 801230036 50-287 801230036 50-287 801230036 50-287 801230036 50-287 801230037 50-287 801230037 50-287 801230037 50-287 801230037 50-287 801230314 50-277 801230314 50-277 801230314 50-277 801230314 50-277 801230314 50-277 801230335 50-277 8 | | 8012270136 8012270136 8012270469+ | 50-275 50-275 50-275 | A A F | | 8012230477# 8012240190 8012290171 | 50-387 50-387 50-387 | K K > 0 0 |
| Pacific Pumps Div. Pains Community Hosp. Palos Park. IL B012300727 SPORTLIC B012300737 XPORTLIC B012300737 XPORTLIC B0123000737 XPORTLIC B012300073 XPORTLIC B012300074 FOLA B012030074 FOLA B012030075 FOLA B0120301174 FOLA B0120301175 FOLA B0120301175 FOLA B0120301175 FOLA B012030177 FOLA B012030177 FOLA B012030177 FOLA B012030177 FOLA B012030077 FOLA B0120 | | 8012300352 8012300352 8012300466 | 50-275 50-275 50-275 | 0 0 | | 8012300075+ 8012300075+ 8012300306 | 50-387 50-387 50-387 | 0 0 A A |
| Parr-Richmond Terminal Cq. Sol2310602* CONTRACT Pennsylvania Voice of Energy Sol2310383 So-397 Sol2300324* Sol2300325* Folia Pennsylvania State of Sol230003 So-299 Sol2300057* Folia Sol2300064* Folia Perkins Cois Stone Client & Sol230003 So-299 Sol2300064* Sol2300064* Folia Perkins Cois Stone Client & Sol2300064* Sol2300064* Folia Sol2300064* Folia Sol230064* Folia Sol230064* | Palos Community Hosp. Palos Park.IL Par Systems Corp. | 8012310274 8012300773 8012180266 | 50-275 XPORTL1C PR | | | 8012310078 8012310078 | 50-387 50-387 50-387 | 8 6 6 6 |
| B0120300624 FOIA People Against Nuclear Energy B012310307 S0-269 B0120300614 FOIA Perkins. Cois. Stone. Glaen & Williams B012310308 B01231030 | | 8012310602* 8012030026* 8012030032* | CONTRACT FOIA FOIA | P | Pennsylvania Voice of Energy Pennsylvania, State of | 8012310383 8012230003 8012080488 | 50-367 50-289 PR | F O H |
| B012030111+ F01A | | 8012030062+ 8012030081+ | FOIA FOIA | | Perkins, Cois, Stone, Olsen & Williams | 8012310307 8012300264 8012240446 | 50-269 50-289 50-522 | 0 0 0 |
| B012030218+ F01A B012020398 50-277 B012030394 F01A B012020371 B012020374 F01A B012020371 50-352 B012030354 F01A B012040373 B012040373 B012040373 B012040374 F01A B012040374 F01A B012040374 F01A B012040311 50-278 B012030360+ F01A B012040411 50-278 B012040411 B0120404 | | 8012030111* 80120301194 | FOIA FOIA FOIA | | | 8012010289 8012010440 8012010455* | 50-277 50-277 50-277 | F 8 8 |
| 8012030340* FDIA 8012040411 50-278 | | 8012030218* 8012030274* 8012030330* | FOIA FOIA FOIA | | | 8012020358 8012020358 8012020471 | 50-277 50-277 50-352 | S P A P |
| 8012030367* FOIA 8012040419 50-277 8012030348* FOIA 8012040439 50-277 | | 8012030340# 8012030367# | FOIA FOIA | | | 9012040411 9012040419 9012040429 | 50-278 50-277 50-277 | 8888 |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | |
|---|---|--|---------------------------------------|---|--|---|-----------------------|
| | 8012050110 8012080190 8012080424 8012090298* | PR REGOD 50-352 50-463 50-463 | A C G | Power Authority of the State of New York | 8012010407 8012010410 8012010415+ 8012010427+ 8012030572 | 50-333 50-284 50-286 50-333 50-286 | T (1) (2) (2) (3) (4) |
| | 8012070441 8012070455 8012070464 80120704704 80121004714 | 50-278 50-277 50-277 50-277 50-463 | 9555 | | 8012030707 8012030733 8012050431 8012050444* 8012080170 | 50-286 50-333 50-333 50-333 REGOD | P 0: 9: 8: |
| | 8012100471* 8012100470 8012100473 8012100459* 8012150141 | 50-463 50-278 50-352 50-278 50-277 | G S A S P | | 8012080455 80120804594 8012080824 8012070003 8012070155# | 50-333 50-333 50-286 50-333 50-333 | 8 0 0 |
| | 8012150141 8012160267 8012160267 8012160272* 8012160272* | 50-277 50-277 50-277 50-277 50-277 | P R R R | | 8012070375 8012100224 8012100457 8012150107 8012150127 | 50-284 50-333 50-333 50-284 50-333 | 88 50 \$10 50 |
| | 8012160276* 8012160276* 8012160472 8012160472 8012160475* | 50-277 50-277 50-277 50-277 50-277 | R R R R | | 8012150130* 8012150132 8012150133* 8012160360 8012160368* | 50-333 50-284 50-286 50-286 50-286 | 8 8 0 |
| | 8012160475* 8012170623 8012170641* 8012180247 8012180250* | 50-277 50-278 50-278 50-277 50-277 | 8 8 8 8 | • | 8012140502 8012140505* 8012140530 8012140536* 8012170352 | 50-333 50-333 50-333 50-333 50-284 | R 8 8 P |
| | 8012230352 8012230359* 801223039 9012230493 8012230051* | 50-277 50-277 50-277 50-277 50-277 | 8889 | | 8012170361 8012180271 8012170033 8012170464 8012220316 | 50-266 PR 71-9080 50-284 50-286 | B P R |
| | 8012300270 8012300527 8012300549 8012300618 8012300618 | 50-171 50-352 50-352 50-277 50-277 | R S A R R | | 6012220321* 6012230381 6012270425 6012270427* 6012270432 | 50-286 50-333 50-286 50-333 | R P 6 8 |
| | 8012300624# 8012300624# 8012310310 8012310320 8012310323# | 50-277 50-277 50-277 50-278 50-278 | R R P B | | 8012270437* 8012270437 8012270441 8012270443 8012270447* | 50-333 50-333 50-333 50-333 50-333 | 8 8 |
| Picker Corp. Pittsburgh, Univ. of Poliackith S. | 8012310327 8012110371* 8012160603 8012110334 8012300176 | 50-277 71-5796 71-350 PR 50-142 | P 0 | | 8012270451+ 8012270453+ 8012270468 8012270474+ 8012300542 | 50-333 50-333 50-333 50-333 50-333 | |
| Porter County Chapter Intervenors Portland Cement Association Portland General Electric Co. | 80123002034 8012100065 80122400514 8012020450* 8012020540 | 50-142 50-367 CONTRACT 50-344 50-344 | T OP | | 8012300546* 8012300552 8012300584 8012300630 8012300638* | 50-333 50-286 50-333 50-333 50-333 | 8000 |
| | 8012080461 8012090078 8012090215 8012090217* 8012090227 | 50-344 PR 50-344 50-344 TOPREP | P P | President of US & Executive Offices Press Intelligence, Inc. Princeton Univ. | 8012300655 8012300662* 8012240020+ 8012120082* 8012020375* | 50-333 50-333 COMMIESI CONTRACT LOCER | |
| | 8012150056 8012150057* 8012150061 8012160437 8012170053 | 50-344 50-344 50-344 90-344 PR | R 8 P | Pro-Tech Support Services, Inc. | 8012080255 8012120151 8012120159 8012120196 8012160017 | PR PR PR PR FOIA | |
| | 8012180325* 8012230305 8012230313 8012230452 8012230455+ | 50-344 50-344 50-344 50-344 80-344 | 0 8 8 8 | Provincetown, MA Public Citizen Litigation Group Public Interest Research Group, New York | 8012030495* 8012290535 8012290538* 8012150138 8012150140* | FOIA 50-367 50-367 50-247 50-247 | 0000 |
| | 8012230465 8012230467 8012300297 8012300405 8012300553 | 50-344 50-344 50-344 50-344 50-344 | \$ 5 F \$ 55 | Public Service Co. of Colorado | 8012150169 8011230201 8011230495 8011250501* 8012010436* | 50-3 50-267 50-267 50-267 50-267 | HRBBO |
| | 80123005584 8012300560 8012300561 80123005654 8012360568 | 50-344 50-344 50-344 50-344 | 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 | | 8012020554 8012020543# 8012020548 8012020575# 8012040404 | 50-267 50-267 50-267 50-267 50-267 | 30000 |
| Potomec Alliance Potomec Electric Power Co. Powder River Basin Resource Council | 8012300573+ 8012300616 8012100006 8012310216 8012160767* | 50-344 50-344 PR 50-448 40-8743 | s s c | | 8012050408 8012050417+ 8012100332 8012100337+ 8012100444 | 50-267 50-267 50-267 50-267 50-267 | 89224 |
| • | | | | | | | V |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC | | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC CATEGO | RY |
|--|---|---|------------------|---|---|--|------------------|
| | 8012100445* 8012100485 8012100491* 8012100503 8012100509* | 50~267 50~267 50~267 50~267 50~267 | 9 9 9 9 | | 8012190216 8012190230* 8012190634 8012190640* 8012230259 | 50-272 50-272 50-272 50-272 50-272 | 46884 |
| | 8012100515 8012100521* 8012100524 8012100537* 8012120130 | 50-267 50-267 50-267 50-267 50-267 | ន ទ ទ | | 8012230379 8012230382* 8012230492 8012240282 8012270132 | 50-272 50-272 50-354 50-354 PR | 5554 |
| | 8012120192 8012160146 8012170417 8012170417 8012170419 | 50-267 50-267 50-267 50-267 50-267 | ь б ь | | 8012300071 8012310284 8012310634 8012310634 8012310636 | 50-272 50-272 50-354 50-354 50-354 | ф ф ф |
| | 8012240237 8012290231 8012290267 8012290435 8012290442* | 50-267 50-267 50-267 50-267 50-267 | 8 8 8 | Pugot Sound Power & Light Co. Purdue Univ. | 8012310635 8012300132 8012310388 8012310201 8012120169 | 50-354 50-289 50-522 PR PR | Q H G |
| Public Service Co. of Indiana, Inc. | 6012300562 8012300567* 8012300591 8012040347* 6012040347* | 50-267 50-267 50-267 50-546 50-546 | 5 8 0 0 | Guadrex Corp. R.E. Williams & Associates, Inc. Radio Free Europe/Radio Liberty Regard Security Service, Inc. | 8012230201 8012110283* 8012290224 8012110471* 8012310570 | NUREO 50-237 NASTE MG FOIA FOIA | τ |
| | 8012040394 8012040400 8012050103 8012220148 8012220168 | 50-546 50-546 PR 50-546 50-546 | s s o o | Rensselaer Polytechnic Inst. Reuter-Stoles, Inc. Rhine-Schelda-Verolme Zware Apparatenbow | 8012120342 8012080639 8012240326 8012300762 8012230239+ | NUREG XPORTLIC XPORTLIC XPORTLIC OA999 | : |
| | 8012220328 8012220323 8012220323 | 50-546 50-546 50-546 | 5 9 | Rhode Island Public Interest Research Group | 8012230246+ 8012110798 | GA777 PR | |
| | 8012220337 8012220337 | 50-546 50-546 | 8 | Rhode Island, State of Richardson-Merrell, Inc. Merrell-National Laboratories Div. | 8012080401 8012010624 | REOGD PR | |
| Public Service Co. of New Hampshire | 8011190378* 8012090232* | 50-443 50-443 | A Q | | 8012100203 | PR | |
| Public Service Co. of Oklahoma | 8012110566 8012230010 8012090037 8012100039 | 50-443 50-443 PR 50-445 | A O M | Rio Aigom, Ltd. Rochester Oas & Electric Corp. | E012080337 E012010282 E012010284 E012010277* E012010387 | 40-8084 50-244 50-244 50-244 | FPP |
| Public Service Electric & Gas Co. of New Jersey | 8012010002 | 71-9089 71-9080 | | | E012070043 8012090278 | 50-244 | ů. |
| , | 8012010004 8012010005 | 71-6574 71-9086 | | | 80120702804 8012160240 8012160427 | 50-244 50-244 50-244 50-244 | G G P P |
| | 8012010009 8012010304 80120103094 8012010398 8012010401 | 71-9079 50-272 50-272 50-272 50-272 | 0 9 9 | | 8012160540 8012160547* 8012170340 8012180391 8012220227 | 50~244 50~244 PR 50~244 | P P |
| | 8012010490 8012020137 8012020137 8012020148# 8012020148# | 71-9010 50-272 50-272 50-272 50-272 | a a a o | | 8012220327 8012220341 8012220440 80122204434 | 50-244 50-244 50-244 50-244 | P P R R |
| | 8012020158* 8012020158* 8012020485 8012020488* 8012020540 | 50-272 50-272 50-272 50-272 50-272 | 9 9 8 8 | Rochester, Univ. of, Medical Center | 8012300393 80123003974 8012300522 80123005254 8012010530 80123005944 | 50-244 50-244 50-244 PR | P S S |
| | 80120205504 8012020570 8012020645 | 50-272 50-272 50-272 | 6 0 8 | Rockwell International Corp., Atomics International Div. | 8012100408 | | s |
| | 8012020452* 8012020455 | 50-272 50-272 | s s | Rockwell International Corp., Energy Systems Div. | 8012020049 | | A |
| | 60120206634 6012030620 6012030624 | 50-272 50-311 50-311 | 8 F | | 6012020377 6012050124 6012050133* | 70-25 71-35 71-35 | |
| | 8012030630 8012040447 8012040621 8012050382 | 50-311 50-272 50-272 50-272 | P 6 0 5 | Ropes & Oray | 8012080786 8011190371 8012190588 8012230010 8012190154* | 50-293 | A O G |
| | 80120503854 8012080122* 8012080131* | 50-272 50-272 50-272 | a a | Rossi, K. Rosweil Park Hemoriai Instituta | 8012190186* 8012230173* 8012300596* | OA999 CONTRACT | G |
| | 8012110403 8012110407* 8012150121 8012150124* | 50-272 | 9 9 6 5 | Sacramento Municipal Utility District | 8012070331 8012070370 | 50-312 1 50-312 1 | S |
| | 8012160340 8012160343* 8012160445 | 50-311 50-311 50-272 | R R | | 6012070411 8012070415 8012120480 | 50-312 f 50-312 f 50-312 f 50-312 f 50-312 f | P R |
| and the second s | 80121404504 8012170413 | 50~272 | R P | | | 50-312 F | |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | RY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATECORY |
|---|---|--|------------------|--|--|---|
| *************************************** | 8012160492+ 8012160507 8012170309 | 50-312 50-312 50-312 | p p | Sigma Chemical Co. (subs. of Sigma-Aldri ch Corp.) | 8012310599 8012080647 | FDIA XPORTLIC |
| | 8012170337 8012170458 | 50-312 50-312 | F P | | 8012110031 8012170294 8012170305 | XPBRTLIC XPBRTLIC XPBRTLIC |
| | 8012180306 8012220309 8012230375 8012290204 8012290228 | 50-312 50-312 50-312 50-312 50-312 | F P F P | Singer, Aerospace & Marine Systems, Kearfatt Div., | 8012230212 8012240361 8012290276 | XPORTLIC XPORTLIC REOGD |
| | 8012270301 8012270303* | 50-312 50-312 | P | Small Business Administration | 8012100022* 8012120432 | CONTRACT |
| Safe Energy Alliance Safe Haven, Ltd. | 8012300447 8012300619 8012290041 8012240002 | 50-312 50-312 70-2709 PR | 8 P | Smith, Kline & French Laboratories Smell & Wilmer Sony Industries | 80122305454 8012110270 8012290430* 8012300487 8012150017 | CONTRACT PR 50-528 0 50-528 0 FOIA |
| Samford Univ., Cumberland School of Lau San Diego Oas & Electric Co. | 8012110328+ 8012040420 8012120413+ 8012240427+ | COMMISSI 50~361 50~206 50~361 | C B B | South Carolina Electric & Gas Co. | 8012010108 8012010117 8012010327 8012020241 | 50-395 A 50-395 A 50-395 A 50-395 R |
| | 8012240427* 8012240428* 8012240428* 8012300374* 8012300374* | 50-361 50-361 50-361 50-361 50-361 | С С К К | | 8012020287 8012020289* 8012020293 8012020369 | 50-395 Q 50-395 Q 50-395 A 50-395 B |
| | 8012300377# 8012300377# | 50~361 50~361 | K K | | 8012020377 8012020434 | 50-395 S 50-395 S |
| Sandia Laboratories | 8012300381* 8012300381* 8012020126 | 50-361 50-361 NUREO | К | | 8012020437 8012020442 8012020445 8012020493 8012020523 | 50-375 8 50-375 8 50-375 8 50-375 8 50-375 8 |
| | 8012020459 8012050482 8012110764* 8012110777* | NUREO RES FOIA FOIA | | | 8012020572 8012020765 8012030613 8012030634 | 50-395 A 50-395 M 50-395 B 50-395 B |
| Sandoz, Inc. | 8012170465 8012170530 8012220717 8012230374 8012120185 | NUREG NUREG NUREG NUREG PR | | | 8012030636 8012070218 8012070230 8012070262 8012070324 | 50-395 A 50-395 A 50-395 A 50-395 A |
| Sargent & Lundy, Inc. Scagit County, NA | 6012170442* 6012240284 6012230001 | 0A999 RECOD 50-522 | o | | 8012070397 8012110682* | 50-395 A |
| Scangewer, Inc. Schott Optical Glass, Inc. Science Applications, Inc. | 8012240052+ 8012240052+ | TOPREP 40-7924 NUREO | | | 8012150035 8012150141 8012160123 | 50-395 A 50-395 S 50-395 O 50-395 A |
| Scientists & Engineers for Socure Energy | 80155500024 80155500034 | CONTRACT CONTRACT PR PR | | | 8012160162 8012160165* 8012160436 8012170431 | 50-395 A 50-395 A 50-395 B 50-395 A |
| Senate | 8012150026 8012150028* 8012020828* 8012030640* 8012030646* | 50-247 50-247 50-170 FOIA FOIA | T T H | | 8012170455 8012170457 8012190132 8012190140 8012190392 | 50-395 A 50-395 A 50-395 K 50-395 A |
| | 80120307194 8012030827* 8012180155 | XPORTLIC 50-320 PR | U | | 8012230280 8012230350 8012230460 | 50-395 A 50-395 B 50-395 A |
| | 8012270262 8012300176 8012300443 | 50-204 50-293 50-483 | H U H | | 8012300252 8012300261 8012300417 | 50-375 A 50-375 A 50-375 A |
| Senate. Environment & Public Works Shaw, Pittman. Potts & Trowbridge | 8010300544* 8012240078* 8012100047 8012110351 | 50-320 COMM1681 50-484 50-312 | V | | 8012300455 8012300458 8012300473 8012300534 | 50-395 A 50-395 B 50-395 D 50-395 B |
| | 8012110354 8012110357 8012110410 8012150175 8012150182 | 50-346 50-266 50-287 50-287 50-524 | 0 0 0 0 | | 8012300628 8012300637 8012300650 8012300650 8012310424 | 50-375 A 50-375 A 50-375 A 50-375 O |
| | 8012220428 8012270171 8012270552 8012270663 8012300067 | 50-387 50-387 50-289 50-320 50-387 | 0 | South Carolina, State of South Carolina, Univ. of South Daxota, State of Southern California Edison Co. | 8012010048 80120202454 8012080664* 8011250285 8011250285 | State Prog 50-395 R 40-1341 50-361 A 50-361 A |
| Sheldon. Harmon & Weiss | 8012300449 8012310214 8012310276 8012020673 8012170675 | 50-287 50-448 50-500 50-443 50-443 | © © © | | 8011250549 8011250549 8011250557* 8012020247 | 50-361 A 50-361 A 50-361 A |
| Shiald-llow Ca-a | 8012270052 8012270217 | 70-2623 50-3 40-7102 | Q | | 8012020247 8012020251* 8012020282 | 50-361 A 50-361 A |
| Shieldalloy Corp. Sierra Club | 8012190463* 8012020727 8012190314* | 50-201 50-275 | р Н | | 8015050851 8015050585 | 50-361 A 50-206 P |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC CATEGO | | | AUTHUR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|--|--|--|-----------------------|-------------------|---|---|--|
| | 8012020405 8012030304 8012030577 8012030577 8012030471 | 50-204 50-361 50-204 50-204 50-395 | P P S | St. | . Margaret's Hosp. Spring Valley.IL. | 8012100169 8012110214 8012120104 8012120310 8012080349 | PR PR PR PR PR |
| | 8012030716 8012030729* 8012090202 | 50-206 50-206 50-361 | P P | St. | . Michael Hosp. Milwaukee.WI ondardised Nuclear Unit Power Plant ystem | 8012220070 8012040403 | PR 50~48⊋ S |
| | 8012100527 8012100534 8012100536 | 50-206 50-361 50-361 | P A A | | | 8012040403 8012040403 8012080336≉ | 50-482 S 50-482 S 50-482 A |
| | 8012100537* 8012100537* 8012120397 8012120413+ | 50-361 50-361 50-206 50-206 | A P P | | | 8012090120 8012100440 8012100440 8012100440 8012300717 | PR 50-482 8 50-482 8 50-482 8 50-482 0 |
| | 8012120426# 8012160335 8012160338# 8012170434 8012170619 | 50~206 50~206 50~206 50~206 50~206 | P R R T S | Sta | inford Research Institute Inford Univ. Ito.Dapt.of | 8012300717 8012300717 8012270511 8012120107 80120105314 | 50-482 Q 50-482 Q NUREG PR COMMISSION |
| | 8012170628* 8012230490 8012230490 8012240425 8012240425 | 50-204 50-361 50-361 | S A C | | ite.Dept.of, Bureau of Octans & iternati Environ. & Scientific Affairs | 8012030552* 8012080132 | FOIA XPORTLIC |
| | 8012240427# 8012240427# | 50-361 50-361 50-361 | c c | | | 80121100216 8012110076 8012110103 | XPORTLIC XPORTLIC XPORTLIC |
| | 8012240428* 8012240428* 8012290254 | 50-361 50-361 50-361 | C C O | | | 8012160647 8012170254 8012170255 8012170257 8012170264 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC |
| | 8012300374* 8012300374* 8012300377* 8012300377* | 50-361 50-361 50-361 50-361 | K K K K | | 8012180420* 8012180427* 8012240218 8012310077 | SECY SECY XPORTLIC XPORTLIC | |
| | 8012300381# 8012300381# 8012300385 8012300385 | 50-361 50-361 50-361 50-361 | K E E | | el. Hector & Davis ne & Hebster Engineering Corp. | 8012310079 8012300516 8012060154 8012080502 8012080731 | XPORTLIC 50-250 G PR RECOD RECOD |
| | 8012300507 8012300507 8012300521 8012300544 8012310072 | 50-341 50-341 50-361 50-206 50-206 | 0 8 P F | | | 8012090102 8012090248 8012100014 8012120618 | PR NUREO PR 50-322 S |
| Southern Illinois Univ., School of | 8012310345 8012310345 8012120071 | 50-361 50-361 PR | S S | | | 8012120633 8012150033 | 50-322 S 50-33B S |
| Medicine Southwest Research Institute | 8012010043 8012010045 8012010046 | RES RES | | នបរា ទីបុទ | Stone & Hebster, Inc. Sun-Bulletin Binghamton,NY Susquehanna Environmental Advocates Switzerland | 8012040645 8012030878 8012290330 8012170388 | 50-334 S F01A 50-387 Q XPORTLIC |
| | 8012010050 8012040383 8012040386 8012040605 | RES RES RES RES | | Syd Ter Trw | Kraft Aktiebolag Sweden ney Morning Herald Ltd. A Corp. , Inc., Energy Systems Planning Div. lahasse.FL | 8012100182 8012310563 8012300733* 8012110382* 80122703754 | XPORTLIC FOIA 50-46& T CONTRACT 50-389 M |
| Southwest Research and Information Center | 8012090308* 8012220164 8012220264* 6012220267* 8012220275* | 50-397 RES FOIA FOIA FOIA | F | Tec | h/Ops (Technical Operations, Inc.) hnassociates, Inc. | B012100667 8012100672* 8012120432 8012230545* | 71-7147 71-9147 CONTRACT CONTRACT |
| Sportmen's Club of Texas,Inc. St. John's Hosp, Lowell,MA St. Joseph Hosp, Kirtwood,MO | 8012240407* 8012030654* 8012030657* 8012170597* 8012290141 | State Pro FOIA FOIA 70-2156 PR | 9 | Tel | hnimet Corp. edgne Enorgy Systems edyne Wah Chang Albany | 8012100073* 8012010034 8012040580* 8012170272 8012170311 | 50-313 P 71-6744 71-6679 XPORTLIC XPORTLIC |
| St. Joseph's Hosp. Highland, N. St. Joseph's Hosp. Tucson. AZ St. Louis Univ. Medical Center St. Louis, MD | 8012290137 8012110219 8012010419 | PR PR PR | | Ten: | nessee Vailey Authority | 8011250423 8012010021 8012010334 | 50-259 P 40-1341 50-327 P |
| 200 Commission of the Commissi | 8012010432 8012010444 | PR PR | | | | 8012020256 8012020256 8012020345* | 50-327 R 50-327 R 50-259 Q |
| | 9012020454 8012020457 8012020467 8012080325 8012110284 | PR PR PR PR PR | | | | 8012020412* 8012020418 8012020421* 8012020444 8012020447* | 50-390 Q 50-260 S 50-260 S 50-296 S 50-296 S |
| bt. Louis Univ. Medical School | 8012180200 8012050519 8012100097 8012100100 8012100103 | PR 'PR PR PR | | | | 8012020497 6012020508* 8012020514 8012020518* 8012020610 | 50-296 |
| | 8012100115 8012100127 8012100130 | PR PR PR | | | | 80120205214 8012020525 | 50-327 6 50-327 9 50-327 9 |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT | | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT |
|-----------------------|---|---|------------------|-----------------------|---|---|
| | 6012020633* 80120206364 8012030599 8012030669 8012030674* | 50-327 50-327 50-260 50-327 50-327 | 8 8 8 8 | | 8012100460 8012100467 8012100467 8012100478 8012100478 | 50-328 \$ 50-438 \$ 50-439 \$ 50-518 \$ 50-518 \$ |
| | 8012030694 8012030823 8012040357 8012040359 8012040352 | 50-328 NUREG 50-564 50-327 50-327 | 8 8 8 | | 8012100478 8012100478 8012100478 8012100478 8012100488 | 50-518 8 50-518 8 50-518 8 50-518 8 50-438 8 |
| | 8012040396+ 8012040416 8012040422 8012040428 8012040428 | 50-327 50-328 50-390 50-390 50-553 | 55555 | | 8012100485 8012100517 8012100517 8012100523 8012100534* | 50-438 |
| | 8012040432 8012040435 8012040435 8012040443 8012040545 | 50-553 50-553 50-553 50-390 70-1966 | 8 8 8 | | 8012100548 8012120466 8012120477* 8012120502 8012120506* | 50-328 S 50-259 S 50-259 S 50-259 S |
| | BD12040457 BD12050349 BD12050349 BD12050349 BD12050349 | 50-518 50-518 50-518 50-518 50-518 | 8 8 8 8 8 | | 8012120509 8012120510 8012120514* 8012120517* 8012150084 | 50-276 6 50-257 5 50-257 5 50-276 5 TOPREP |
| | B012050369 B012050369 B0120503B1 B0120503B1 B0120503B1 | 50-518 50-518 50-518 50-518 50-518 | 9 9 9 9 | | 8012150107 8012150108* 8012150111* 8012150112* 8012150165 | 50-327 P 50-327 P 50-327 P 50-327 P 50-327 B |
| | 8012050381 8012050381 8012050381 8012050397 8012050457 | 50-518 50-518 50-518 50-327 50-390 | 8 8 8 | | 8012150170* 8012150257 8012150261 8012150266 8012150266 | 50-327 8 50-328 8 50-438 8 50-438 8 50-438 8 |
| | 8012080314 8012080314 8012080423 8012080430* 8012080401 | 50-327 50-327 50-327 50-327 50-518 | Բ Բ Տ | | 8012150280 8012160147 8012160152* 8012160301 8012160301 | 50-327 P 50-564 R 50-566 R 50-327 A |
| | 8012080410 8012080414 8012080414 8012080441 8012080468* | 50-327 50-327 50-327 40-1341 50-518 | 0 | | 8012160317 8012160321+ 8012160321+ 8012160321+ 8012160327 | 50-259 R 50-259 R 50-259 R 50-259 R 50-327 P |
| | 8012080725 8012080773 8012080773 8012090142* 6012090186 | 40-1341 50-259 50-259 50-438 50-390 | 9 9 4 | | 8012160327 8012160327 8012160327 8012160327 8012160327 | 50-327 P 50-327 P 50-327 P 50-327 P 50-327 P |
| | 8012070207 8012070207 8012070209 8012070231 8012070231 | 50-259 50-259 50-259 50-259 50-259 | 6 4 4 4 | | 8012160327 8012160327 8012160327 8012160327 8012160327 | 50-327 P 50-327 P 50-327 P 50-327 P 50-327 P |
| | 6012070231 6012070311 6012070311 6012070312* 6012070312* | 50-259 50-327 50-327 50-327 50-327 | ե ե ե | • | 8012160327 8012160327 8012160327 8012160330 8012160333* | 50-327 P 50-327 P 50-327 P 50-327 R 50-327 R |
| | 8012070342 8012070342 8012070344 8012070347 8012070347 | 50-370 50-370 50-257 50-438 50-438 | 8 B P A V | | 8012160447 8012160454* 8012160542 8012160549* 8012160553 | 50-327 8 50-327 8 50-296 8 50-296 8 50-296 8 |
| | 8012090355 8012090359* 8012090359 8012090369 8012090349 | 50-327 50-327 50-390 50-546 50-566 | 9999 | | 80121605597* 8012160675 8012160675 8012160703 8012170306 | 50-276 B 50-438 B 50-438 B 50-438 B 50-4327 P |
| | 8012090370 8012090370 8012090370 8012090370 8012090370 | 50-327 50-327 50-327 50-327 50-327 | 5555 | | 8012170306 8012170316 8012170316 8012170316 8012170316 | 50-327 F 50-327 F 50-327 F 50-327 F 50-327 F |
| | 8012070370 8012070370 8012070410 8012100337 8012100447 | 50-327 50-327 50-259 40-1341 50-438 | 8 5 5 | | 8012170316 8012170316 8012170316 8012170316 8012170316 | 50-327 F 50-327 F 50-327 F 50-327 F 50-327 F |
| | 8012100447 8012100448 8012100448 8012100454 8012100454 | 50-438 50-438 50-438 50-390 50-390 | សព្ធព្ធព្ធ | | 8012170316 8012170316 8012170316 8012170316 8012170316 | 50-327 F 50-327 F 50-327 F 50-327 F 50-327 F |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SURJEC | | | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJE | CT DRY |
|-----------------------|---|--|-----------------------|----|--|---|--|------------------|
| | 8012170405 8012170425 8012170425 8012170460 8012170460 | 50-438 50-390 50-390 50-390 50-390 | នានានានាន | | | 8012310111 8012310111 8012310311 8012310322 8012310327 | 50-259 50-259 50-438 50-566 50-553 | 0 5 5 |
| | 8012170465 8012170515 8012170559 8012170565 8012170585* | 50-566 50-326 50-260 50-276 50-260 | 9 10 10 10 10 | | Tennessee, State of | 8012310335 8012310374 8012310378 6012310382 8012040358+ | 50-516 50-566 50-370 50-438 50-327 | 888 |
| | 8012170596+ 8012170402 8012170603 8012170605+ 8012170612+ | 50-296 50-327 50-296 50-327 50-296 | មានមាន | | Terradex Corp. Texas Border Cooperatives Texas Instruments, Inc. | 80120805564 80121203624 8012030458 8012020259 8012080791 | 50-327 40-6622 50-445 70-33 70-33 | F H |
| | 8012170642 8012170647* 6012180097* 8012180175* 8012190125 | 50-260 50-260 50-260 50-553 50-328 | \$ Q Q | | Texas Nuclear Div. (subs. of Ramsay Eng. | 8012080793+ 8012190043 8012190134* 80121106814 | 70-33 70-33 50-367 CONTRAC | ε |
| | 8012190472* | 50-259 | a | | Texas Utilities Co. | 8012300338 | 50-445 | C |
| | 80121904924 8012190503 80121905794 8012220455 80122204604 | 50-259 50-328 50-327 50-260 | 9 8 8 | | Texas Utilities Generating Co. | 8012300333 8012300344* 8012300344* 8012030758 8012100550* | 50-445 50-445 50-445 50-445 50-445 | 00000 |
| | 8012220595 8012220595 8012220595 8012220110 | 50-259 50-259 50-259 50-518 | 0 0 9 | ·. | | 6012160531 6012160531 6012170672 6012180245 8012170487 | 50-445 50-445 50-445 50-445 50-445 | 0 0 11 9 |
| | 8012230158 8012230163 8012230257 6012230257 G012230355 | 50-327 50-327 50-259 50-259 50-553 | P P P R | | | 8012190487 8012190493* 8012190493* 8012230487 | 50-445 50-445 50-445 Nurec | K K K |
| | 8012230360* 8012230362 8012230365* 8012230384 8012230390 | 50-553 50-327 50-327 50-327 50-328 | R S S S V | | | 8012270151 8012270167 8012270167 8012270338 8012270333 | PR 50-445 50-445 50-445 50-445 | 5 6 6 |
| | 8012230353≠ 8012230451 80122304534 8012240245 8012240237 | 50-327 50-327 50-327 50-259 50-259 | 8 P P P | | | 8012290647 8012300057 8012300057 8012300251 8012300251 | 50-445 50-445 50-445 50-445 50-445 | 0 0 11 |
| 1 | 3012290237 3012290237 3012290238 3012300289 3012300269 | 50-259 50-259 50-327 50-259 50-259 | P P P P | | | 8012300251 8012300534 8012300536 8012300551 | 50-445 50-445 50-445 50-445 | M A A K |
| 6 8 6 | 5012300296 3012300296 3012300296 3012300419 3012300424 | 50-259 50-259 50-327 | P P S S | | Texas, State of | 8012310089 8012310089 8012310290 8012310270 | 50-445 50-445 50-445 50-445 50-445 | K F G G |
| ស ស ស | 012300428 012300432 012300438 0123004444 | 50-259 50-327 | 6 8 6 | | Texas: Univ. of | 8012030661* 8012240008 8012020700 8012230201 | FDIA 50~498 70~157 NUREO | 0 |
| | 012300484 012300496 012300514 | 50-518 50-438 | s s | | Teras, Univ. of, Dallas | 8015010103 8015300989* 80153009684 | 50-466 50-466 PR | T |
| ନ ଶ | 012300518 0123005204 012300531 | 50-240 50-240 50-296 | 8 8 8 8 | 1 | The Nuclear Regulatory Commission Thomas & Hair Three Mile Island Alort Three Mile Island Public Interest | 8012100240 8012220314 8012270227* 6012300264 8012120657* | 50-287 | 0000 |
| 90 90 91 | 0123009374 012300541 012300548* | 50-296 | | 1 | Resource Center Fold Shipyards | 8012040524 8012040533+ 8012020270 | 70-1062 70-1062 | " F |
| 80 80 80 | 012300546 012300570 012300577 | 50-327 9 50-327 A 50-390 9 50-259 9 | s 3 | | | 6012020430 6012020525 6012020533* 6012020559* | 50-346 50-346 50-346 | გ 8 |
| 80 80 80 | 12300615 123006254 12300634 | 50-259 9 50-259 9 50-259 9 | | | | 8012020594* 8012040385 | 50-344 50-346 50-344 | 9 |
| 60 60 | 12300648 5 12300649 5 12300648 5 | 50-259 g 50-259 f 50-259 f 50-259 f | | | | 8012090387* 8012090414 8012120490 | 50-346 50-346 | 5 A 5 6 |
| EO | 123006654 5 | 30-518 R 50-518 R 50-327 0 | | | | 8012120512* | 50-346 | 6 6 8 |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | RY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGOR | |
|--|---|--|-----------------------|---|---|--|------------------|
| | 8012150053 8012150055* 8012150116 8012150118* 8012150168 | 50-346 50-346 50-346 50-346 50-346 | R R S S | | 8012030420# 80120304474 8012030468# 8012030908# 8012030910# | 27-10 27-10 27-10 27-10 27-10 | |
| | 6012150171* 6012170534 6012220446 80122204514 8012310276 | 50-346 50-346 30-346 50-346 50-500 | S S S S S | | 8012030532* 8012030548* 8012030554* 8012030561* 8012030688* | F01A F01A F01A 27-10 F01A | |
| | 6012310319 8012310321 8012310328 + 8012310337 + 8012310422 | 50-346 50-346 50-346 50-346 | \$ \$ \$ 0 | | 8012030692* 8012040575 8012050079 8012120542 8012010550 | FOIA 71-6679 71-6400 27-39 40-8348 | |
| Transamerica Delaval, Inc. Transcommo, Inc. Transnuciear, Inc. | 8012310569 8011210432 80123102624 8011210177 8011210181* | 50-346 50-361 50-445 71-9015 71-9015 | 0 9 M | Union Carbide Corp. | 8012050332 8011180742 8012100146 8012160471* 8012180001 | 40-8584 40-299 RES 70-487 40-299 | |
| | 8012020184 8012020233 8012020243 8012020280 8012020317 | XPBRTLIC 70-2478 70-2479 70-2478 XPBRTLIC | | | 8012170157* 8012170165* 8012220181 8012220624 8012030726 | 50-54 50-54 NURE9 70-687 50-483 | F W |
| | G012020322 6012020327 8012020331* 8012020335* 8012020472 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | e c c | | 80120403034 8012040672* 8012110630* 8012190484 8012190484 | 50-493 50-493 50-493 50-493 | agguo |
| | 8012020477 8012110020 8012110024+ 8012110145 8012110149 | XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC | C C C | Union Minerals Union dil Co. of California | 8012190494 8012190494 8012300610 8012020576 8012120390 | 50-493 50-493 50-493 40-8584 40-8348 | 400 |
| | 8012220473 8012290434 8012300231 80123002354 8012306237# | XPORTLIC XPORTLIC TOPREP TOPREP TOPREP | | Union of Concerned Scientists | 8012120395* 8012150172 8012170474 8012290134 8012290547 | 40-8348 50-289 50-289 50-289 50-289 | 0 H 0 T |
| | ESE00E2108 BSE00E2108 PA001E2108 | XPORTLIC XPORTLIC XPORTLIC | C | Union of Soviet Boctalist Republics United Engineers & Constructors, Inc. (subs. of Raytheon Co.) | 8012110452* 8012020716* | F01A QA999 | - |
| Travenol Laboratories Tri-State Motor Transit Co. (subs. of Georgia Pacific Corp.) | 8012120380 8012020647 | PR 70~1739 | | United Nuclear Corp. | 8012100244* 8012100273* 8012020254 | 70-820 70-820 70-371 | |
| Tupper,S.R. Turner Collie & Braden,Inc. Twomey, Latham & Bchmitt | 8012190070 8012300723+ 8012090126 8012180218 8012290801 | 50-307 50-444 PR PR 50-322 | 0 T | מקונטיים עניי. | 8012020261* 8012020299 8012020394 8012070251* 8012270063 | 70-371 70-820 70-820 70-820 70-820 | |
| U.S. District Court Southern District of Florida URS Co. | 8012270404+ 8012300719+ | 50-369 50-466 | ff T | United Nuclear Corp. Naval Products Div. | 8012010549 | 70-371 | |
| US Ecology, Inc. (Formorty Nuclear Engineering) | 8012030035+ 8012030037+ 8012030042+ | 27-10 27-10 27-10 | • | Universitat Karlsruhe Upjohn Co. | 8012020687 8012020696* 8012240307 8012080343 | 70-371 70-371 NUREO PR | . |
| | 8012030042* 8012030052+ 8012030058+ 8012030058+ 8012030108* | 27-10 27-10 27-10 27-10 27-10 27-10 | | Uraneri USA Inc. Utah, State of | 8012180177 8012170235 8012050508 8012110029 8012160766+ | PR 40-9783 PR PR 40-3453 | |
| | 80120301124 80120301214 8012030134+ 80120301594 8012030165* | 27-10 27-10 27-10 27-10 27-10 27-10 | | Varnum, Riddering, Wierengo & Christenson Volan Valve Co. Vermont Yantez Decommissioning Alliance | 8012190420 8012240127 8012100461 8012150153 8012150157 | FOIA 50-322 50-271 50-271 50-271 | HHH |
| | 80120301854 80120301864 80120302024 80120302024 | 27-10 27-10 27-10 FOIA 27-10 27-10 | | Vermont Yankee Nuclear Power Corp. | 7905070693 8012010089 8012010379 8012010403* 8012020420 | 50-271 50-271 50-271 50-271 50-271 | 9000 |
| | 8012030231* 8012030245+ 8012030268+ 8012030281+ 8012030291+ | 27-10 27-10 FOIA 27-10 27-10 | | | 8012020435 8012020439* 8012050112 8012090190 8012090195* | 50-271 50-271 50-271 50-271 50-271 | 99999 |
| | 80120303104 80120303224 80120303484 80120303724 80120303754 | 27-10 27-10 27-10 27-10 27-10 27-10 | | | 8012070575 8012100505 8012160430 8012160432* 8012230172 | 50-271 50-271 50-271 50-271 50-271 | Q Q R R P |
| | 80120303764 80120304134 | 27-10 FOIA | | Vet. Admin. Hosp. Les Angeles CA | 8012230219 8012080299 8012080345 | 50-271 PR PR | P |
| | | | | | | | í |

CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC | RY | AUTHO AFF1LIAT | 'ION | ACCESSION NUMBER | SUBJECT | |
|---|--|--|---|-------------------|------|--|--|-----------------------|
| Vet. Admin. Hosp. Sepulveda CA Vet. Admin. Hosp. St. Louis, MO | 8012080355 8012080271 8012100184 8012100185 8012120359 | PR PR PR PR PR | | | | 8012160459 8012160467* 8012160514 8012160524* 80121700214 | 50-339 50-339 50-339 50-339 50-280 | 8 8 8 6 |
| Vet. Admin. Medical Center Ann Arbor, MJ Veterans Administration | 8012110154 8012110166 8012120044 8012120147 8012120180 | PR PR PR PR PR | | | | 8012170031+ 8012170291 8012170432 8012170454 8012170611 | 90-338 NUREQ 50-339 50-280 50-281 | G P G S |
| Virginia Electric & Power Co. | 8012170243 8012010277 8012010280* 8012010291 8012010295* | PR 50-339 50-339 50-280 50-280 | 9 9 P | | | 9012170527* 8012170635* 8012170646* 8012170659 8012170937 | 50~281 50~281 50~281 50~281 50~280 | S S 9 0 |
| | 8012010352 8012010353 80120103594 80120103624 8012010363 | 50-339 50-339 50-339 50-339 50-338 | \$ \$ \$ \$ \$ | | | 8012170837 8012170837 8012180142* 8012180172* 8012170354 | 50-280 50-280 50-338 50-338 50-280 | 0 0 0 0 P |
| | 8012010373+ 8012010378 8012010370+ 8012010407+ 8012010407+ | 50-338 50-338 50-338 50-338 50-338 | 8 8 8 F F | | | 8012190354 8012190354 8012190354 8012190378 8012190508 | 50-280 50-280 50-280 50-339 50-338 | P P P R |
| | 8012010614* 8012010614* 8012020276 8012020276 8012020423 | 50-338 50-338 50-280 50-280 50-339 | F F F G | | | 8012190508 8012190513* 8012190532 8012190532 8012190535* | 50-338 50-338 50-260 50-260 50-260 | R R R R |
| | 8012020426# 8012020581 8012020590* 8012020596 80120206024 | 50-339 50-339 50-339 50-339 50-339 | 9 9 6 5 9 | | | 8012190535* 8012220363 8012220363 8012220373 8012220373 | 50-280 50-280 50-280 50-280 50-280 | R F F F |
| | 8012020623 8012020631* 8012020682 8012020712* 8012030709 | 50-338 50-338 50-338 50-338 50-280 | 5 9 6 5 6 5 6 5 6 5 6 6 6 6 6 6 6 6 6 6 | | | 8012230081 8012230081 8012230081 8012230081 8012230214 | 50-280 50-280 50-280 50-280 50-338 | 0 0 0 P |
| | 80120307174 8012030720 8012030723* 8012040306 80120403084 | 50-280 50-281 50-281 50-280 50-280 | 5 5 6 8 R R | | | 8012230285 8012230285 8012230285 | 50-280 50-280 50-280 50-280 50-280 | 11111 |
| | 8012040366 8012040414 8012040669 8012050328 8012050328 | PR 50-339 50-280 50-280 50-280 | P 8 F F | | | 8012230293* 8012230293* 8012230293* 8012230371 8012230376* | 50-280 50-280 50-280 50-339 50-339 | *** |
| | 8012050364 8012050364 80120503704 80120503784 8012050421 | 50-280 50-280 50-280 50-280 50-338 | 5 5 5 5 F | | | 8012230395 8012230403+ 8012230412 8012230416+ | 50-280 50-280 50-281 50-337 50-339 | 6 6 6 5 S |
| | 8012080413 8012080413 8012080541 8012080652 8012080787 | 50-280 09:20 50-338 50-338 PR | P P Q Q | | | 8012230419 8012230423 80122304244 80122304284 8012230439 | 50-339 50-338 50-339 50-338 50-339 | 8 B B B B |
| | 8012090179 8012090179 8012090315 80120903194 8012090350 | 50-280 50-280 50-338 50-338 | P P 8 8 8 | | | 8012240503 8012240503 8012240503 8012240503 8012240503 | 50-280 50-280 50-280 50-280 50-280 | 9 0 0 0 |
| | 80120703514 8012070362 80120703654 8012070401 80120704084 | 50-338 50-338 50-338 50-338 50-338 | 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 | | | 8012270154 8012270154 8012270157* 8012270157* 8012270173 | 50-280 50-280 50-280 50-280 NUREO | P P P |
| | 8012100563 8012100570* 6012110378 6012110373* 6012110378* | 50-337 50-339 50-281 50-281 50-281 | 6 9 8 9 | | | 8012270244 8012270268 8012270268 8012270274 6012270274 | 50-338 50-280 50-280 50-280 50-280 | P P F F |
| | 8012110543 8012110543 8012110543 8012110543 8012120467 | 50~280 50~280 50~280 50~280 50~280 | Q Q Q Q | | | 8012270274 8012270274 8012270280 8012270292 80122702974 | 50-280 50-280 50-338 50-338 | F P P |
| | 8012120467 8012150083 8012150173 8012150176* 8012160142 | 50~280 50-338 50-339 50-339 50-280 | Q P S S P | | | 8012270316 8012270448 8012270455* 8012270460* 8012290585 | 50-339 50-281 50-281 50-281 50-280 | 8 8 8 8 |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT | | AFFILIATION | ACCESSION NUMBER | SUBJECT CATEQURY | , |
|--|--|--|------------------|--|---|--|-----------|
| | 8012300585 8012300585 8012300588 80123100384 8012310285 | 50-280 50-280 50-404 50-338 50-280 | P A 0 P | 8 Hestern Nuclear Inc. Western Zirconium Inc. | 012080765 012310528 012010556 012020248* 012020252* | 40-1162 40-1162 40-1162 40-1162 40-8709 40-8709 | <i>:</i> |
| | 8012310285 8012310285 8012310316 8012310325 80123103304 | 50-280 50-280 50-338 50-338 50-338 | P S S | 8 8 | 012010313+ 012020214 012020462+ 012020481 012020758 | XPORTLIC | Q A |
| Virginia Tech | 8012310333 + 8012030690 8012100226 8012230517 + 8012230518 + | 50-338 50-124 PR 50-124 50-124 | ន គ គ | 8 9 9 | 012080467 | TOPREP TOPREP PR TOPREP 71-3450 | |
| Vollen, R. J. Walker Trucking Co. | 8012100066 8012030483* 8012030502* 8012030542* 8012030569* | 50-367 FOIA FOIA FOIA FOIA | G | 8 8 | 012090111 012090165* 012090169* 012100234* 012150196* | PR 70-1151 70-1151 70-1143 50-364 | Р |
| Halter Kidde & Co., Inc., Fenwal, Inc. Halworth Co. (subs. of IU International Corp.) | 8012030582* 8012150113* 8012170276* | F01A 50-327 0A999 | Р | e 8 | 012150230 012160368* 012170065 | 50-284 PR QA999 | A |
| Warner-Lambert Research Institute Washington County Hosp. Nashville, IL | 8012120115 8012080671 | ₽R ₽R | | 8 | 1012230174 4 1012230467 | TOPREP | |
| Washington Public Power Supply System | 8012070076 8012180230 8012180256 8012030722 8012030728 | PR PR 50-397 50-397 | 0 9 | 8 8 | 012230473 012240372 012290011 012290205 | TOPREP XPORTLIC 70-2909 70-2909 | |
| | 6012030763 600202030 6012070103 6720702103 | 50-397 PR PR 50-397 | œ F | 8 8 | 012300765 012300767 0012310187 0012310193* 0012310198* | XPORTLIC XPORTLIC TOPREP TOPREP | |
| | 8012150162 | 50-397 50-397 | Ą | Westinghouse Electric Corp., Nuclear | 1012310201# 1012120434# | TOPREP 50-206 | P |
| | 8012160128 8012160128 8012160128 | 50-397 50-397 50-397 |]] | Div. | 012100385 | TOPREP | |
| | 8012140128 | 50-397 50-397 | 1 I | | 9012290261 9012290265 | TOPRÉP TOPRÉP | |
| | 8012140134* 8012140134* 8012140134* 8012140134* | 50-397 50-397 50-397 50-397 | I I I | Wharton & Pagalies Wilbur Smith & Associates E | 9012230308 9012300507 9012040088 9012040088 | TOPREP 50~361 50~245 50~245 | 0 F F F |
| | 8012170244 8012170357 8012230371 8012230502 6012300255 | RE00D 50-397 50-397 50-397 50-397 | O F S K | 5 6 6 | 3012040088+ 3012040088+ 3012040088+ 3012040088+ 3012040088+ | 50-245 50-245 50-245 50-245 | FFF |
| Washington State Univ. | 8012300259+ 8012300412 8012300432 8012170231 8012300274 | 50-397 50-397 50-397 PR 50-27 | K A F | 5 6 | 30120400884 30120400884 30120400884 30120400884 30120400884 | 50-245 50-245 50-245 50-245 50-245 | 4444 |
| Washington Univ. Washington, State of | 8012080292 8012030106* 8012030130* 8012030143* 8012030148* | PR 27-39 27-39 FOLA FOLA | | | 8012040088+ 8012040088+ 8012040088+ 8012040114 | 50-245 50-245 50-329 | FFF |
| Washington, Univ. of | 8012080643 8012240370* 8012050552 8012050570 8012050581 | WASTE M State P PR PR PR | | | 8012040114 8012040118 8012040118 8012040141 8012040145 | 50-329 50-334 50-334 50-322 50-352 60-352 | F F F F F |
| | 8012050592 8012080355 8012080361 80120806024 8012100195 | PR PR PR CONTRAC PR | т | | B012040145 B012040147 B012040155* B012040155* B012040155* | 50-245 50-245 50-245 50-245 50-245 | F F F F F |
| | 8012100223 8012110273 8012120036 6012120076 | PR PR PR PR | | | 8012040155* 8012040155* 8012040155* 8012040155* | 50-245 50-245 50-245 50-245 | 1111111 |
| Waukesha Kemorial Hosp. Waukesha.WI | 8012220037 8012220037 | PR PR | | | 8012040155* 8012040155* 8012040155* | 50-245 50-245 | F |
| Wayne A. Coffmann P.E. Hest Texas Utilities Co. Hest Valley Nuclear Wastes Hestchester Paoples Action Coalition, Inc. | 8012020387 8012100037 8012020484 | 50-201 50-445 50-201 50-3 | Р И Е Н | | 8012040155* 8012040155* 8012040155* 8012040155* | 50-245 50-245 50-245 50-245 | F F F F |
| Western Geophysical Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) | 8012010177 8012010177 | 50-329 40-1162 | A | | 8012040155# 8012040171 | 50-245 50-341 | F |
| easts dath. | 6015080523 | 40-1162 | 2 | | 8012040180 | 50-287 | F |
| | | | | | | | |

CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJEC | RY | AUTHOR AFFILIATION | ACCESSION NUMBER | SURJE | |
|---|--|---|-----------------------|------------------------------|---|---|------------------|
| | 8012040180 8012040186 8012040186 8012040186 8012040238 | 50~289 50-245 50~245 50~245 50-267 | 444 | Wyoming, State of Yale Univ. | 8012310527 8012010063 8012050671 8012080698 8012120101 | 40-834 40-834 40-874 | 02 48 43 |
| William Beaumont Hosp. Royal Cak,MI William H. Rorer, Inc. Wisconsin Electric Power Co. | 8012080352 8012080251 8012010364 80120103724 80120506424 | PR PR 50-266 50-266 50-266 | S 5 F | Yankee Atomic Electric Co. | 7810240085 7811280221 7812010146 7904190132 7906130106 | 50-29 50-29 50-29 50-29 50-29 | P Q Q Q |
| | 8012050651* 8012080177 8012090305 8012090314* 8012090378 | 50-266 REGGD 50-301 50-301 50-266 | F S F | | 7907050153 7907090076 7907190684 7908030172 7908070673 | 50-29 50-29 50-29 50-29 50-29 | Q Q Q |
| | 8012150077 8012150077 8012160427 8012160428 8012160428 | 50-266 50-266 50-266 50-266 50-266 | P P R R | | 7908070712 7908160563 7908200004 7908270511 7909100441 | 50-29 50-29 50-29 50-29 50-29 | 0 0 0 0 |
| | 8012170569 8012170598 8012170604* 8012170606* 8012180277 | 50-301 50-301 50-301 50-301 PR | 8 8 8 | | 7909200465 7909210287 7910030679 7910040432 7910180149 | 50-29 50-29 50-29 50-29 50-29 | 0 0 0 |
| | 8012230069 8012240409 8012240473 8012290131 8012300404 | \$0~266 50~266 50~266 50~266 50~266 | Q Q Q P P | | 7910199174 7910310254 7911230340 7912140252 8012020111 | 50-29 50-29 50-29 50-29 50-29 | 5 0 0 F |
| Hisconsin Public Service Carp. | 8012300404 8012300586 8012300586 8012300593 8012020372 | 50-266 50-266 50-266 50-266 50-305 | P P P | | 8012020242 8012020470 8012020475* 8012030681* 6012030684* | 50-27 50-27 50-27 50-261 50-261 | P 66 66 P P |
| | 6012020428 80120204314 80120403024 8012100324 8012100328# | 50-305 50-305 50-305 50-305 50-305 | 8 8 8 | | 6012040334 6012050390 80120503984 6012080497 | PR 50-29 50-29 REGOD REGOD | s s |
| | B012100368 B012120407* B012150264 B012150267* B012160316 | 50-305 50-305 50-305 50-305 50-305 | F Q P P P | | 8012090074* 8012090292 8012090293* 8012090301 8012090304* | 50-29 50-29 50-29 50-29 50-29 | ឲ្យល្បាល |
| | 8012170576 8012170581* 8012170568* 80121705724 8012170600* | 50-305 50-305 50-305 50-305 50-305 | 5 5 5 5 5 | | 8012070429 80120704344 80120704484 8012110772* 8012160507 | 50-29 50-29 50-29 FOIA 50-29 | 5 5 |
| | 6012230385 8012230389+ 8012230397+ 8012300254 8012300413 | 50-305 50-305 50-305 50-305 50-305 | 8 8 F P | | 8012160511→ 8012180259 8012180270 8012180276+ 8012240174 | 50-29 PR 50-29 50-29 50-29 | S R R |
| Wisconsin, Univ. of, Madison | 8012300414 8012300474 8012300559 8012310421 8012120295 | 50-305 50-305 | P P Q | | 8012240259 8012240262+ 8012290249 8012300595 8012300600+ | 50-29 50-29 50-29 50-29 50-29 | P H 8 8 |
| Momen in Energy Wright State Univ. Wyoming Mineral Corp. | 8012170724* 6012110400 8012220029 8012010541 8012010592 | 50-289 | 11 | York, PA | 6012300448 | 50-289 | н |
| | 8012020027 8012040722 8012030075 8012110419 8012170562 | 40-8502 40-8502 40-8565 40-8502 40-8502 | | | | | |

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed Items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

| REPORT NUMBER | ACCESSION NUMBER | SUBJECT CATEGORY | OTHER REPORT NUMBER |
|--|---|--|---|
| 80-12 80-13 80-3 80-8 8012010043 | 8012140272* 8012160274* 8012020245* 8012080464* 8012010043 | 50-277 R 50-277 R 50-395 R 40-1341 REB | |
| 8012010045 8012010046 8012010030 8012040383 8012040386 | 8012010045 8012010046 8012010050 8012040383 8012040384 | REB REB REB REB | |
| 80120405B3 8012040571 8012040605 8012040406 | 8012040583 8012040591 8012040605 8012040606 | RES RES RES | E00-CAAP-5283 E00-LOFT-5244 PNL-2798 |
| 8012050682 | 8012050682 | RES | 4441/ML-16 |
| 8012100146 8012100170 8012100443 8012110003 8012110057 | 8012100146 8012100190 8012100643 8012110003 8012110057 | RES RES RES RES | GRNL/CBD/INF-BO GRNL/MCD/NEES-B EBA L3-5 GRNL/HABRD-73 |
| 8012110548 8012110551 8012120409 8012170781 8012170784 | 8012110548 8012110551 8012120607 8012170781 8012170784* | RES RES RES RES | 46-6776 MTR-80W00121 |
| 8012170788 8012180058 8012190044 8012190049 8012190061 | 8012170788* 8012180058 8012170044 8012170047 8012170061 | RES RES RES RES 50-409 P | MTR-80W00120 E00-TFBP-5259 E00-CAAP-5292 E00-EA-5274 |
| 8012190138 8012190146 9012190151 9012190161 9012190166 | 8012170138 8012170146 8012170151 8012170161 8012170166 | RE8 RE8 RE8 50-537 A | BHC-NUREG-2851 1 |
| 8012190179 8012190185 8012190199 8012190208 80121902047 | 8012190179 8012190185 8012190197 8012190208 8012190347 | RE8 RE8 RE8 RE8 PE8 | ORNL/HASRD-103 ORNL/FTR-782 ORNL/HASRD-102 EQO-EA-5245 |
| 8012220164 8012220174 8012220186 8012240136 | 8012220164 8012220174 8012220186 8012240156 | REB REB REB REB | 17-5023(26) E00-LOFT-5290 |
| 81A0037 | 8012120241* | | 5101-058 |
| 81A0037 81A0040 95-848 8AU-10145 CE-1-A R14 | 8012020318* 8012080495* 8012240096* 8012140413* 8012020217* | 50-409 P 50-409 P COUMISSION TOPREP TOPREP | |
| CEN-139(A)-NP CPO 1-6 CPO 1-6 R1 DDE/E18-0046F V1 DDE/E18-0046F V2 | 8012150101* 8012290504* 8012290510* 8012050474* 8012050485* | 50-368 P 50-320 F 50-320 F PR PR | UC-70 UC-70 |

| REPORT | ACCESSION | SUBJECT | OTHER REPORT |
|--------------------------------------|--|----------------------|----------------------|
| NUMBER | NUMBER | CATEGORY | NUMBER |
| DOE/E18-0046F V3 | 80120504934 | PR | UC-70 |
| FNP-0-RCP-800 | 8012170412* | 50-364 P 50-267 P | |
| GA-C15767 HNF SHR-B | 8012040407* 8012300465* | 50-518 R | |
| 1AEA-CA-39/212 | 8012040347* | PR | |
| 1AEA-CN-39/100 | 8012180430 | HISC | |
| LDL-9557 | 8012100542* | | 8AC-23 |
| NBER 9 ADD 1 NEDC-12620-1 | 8012080487* 8012030854* | 50-184 P 50-10 P | |
| NEDO-20776 R5 | 6012010626* | 70-1308 | |
| NEDO-24030 ADD 1 | 60153009134 | 50-263 P | |
| NEDO-24811 EAR 1 | 8012020245* | TOPREP | |
| NEDO-24823 NED-77 | 8012300486 4 80122400154 | TOPREP COMMISSION | BONEDO42 |
| NURE0-0002 E8 | 8012240025* | COMMISSION | |
| NUREG-0020 V4 NO5 | 6012310304 | NUREO | |
| NUREO-0123 R3 | 8012240312 | NUREO | |
| NUREG-0135 V4 NO1 NUREG-0212 R2 | 8012310297 8012180510 | NUREO NUREO | |
| NURE0-0217 | 8012240031* | COMMISSION | |
| NURE0-0304 V3 | 8012310399 | NUREO | |
| NUREQ-0329-79/9 | 8015310300 | NUREO | |
| NUREG-0470 82 NUREG-0580 V9 NO1 | 8012190214 8012310313 | 50-466 D NUREO | |
| NUREG-0580 V9 NO3 | 8012310308 | NUREO | |
| NUREQ-0588 | 8012310024 | NUREO | |
| NUREO-0606 V2 NO4 | 8012120201 | NUREO | |
| NUREO-0411 NUREO-0419 | 8012310028 | NUREO NUREO | |
| NUREQ-0654 R1 | 8012020653 | NURED | FEMA-REP-1 |
| NUREQ-0690 81 | 8012290383* | 50-289 P | |
| NURE9-0689 | B012110497 | 50-320 I NUREď | |
| NUREQ-0693 NUREQ-0696 | 8012120331 | 50-280 F | |
| NUREO-0720 | 8012310406 | 50-346 P | |
| NURE9-0725 | 8012020732 | NUREO | |
| NUREQ-0737 | 9012160147* 9012270655* | 50-3 P 50-250 P | |
| NUREG-0743 NUREG-0746 | 8012270835* | 50-269 0 | |
| NUREO/CR-0750 | 8012120308 | 50-204 P | UCRL-52706 |
| NUREQ/CR-0773 | 8012310287 | NUREO | PNL-3020 |
| NVREG/CR-0872 | 8012120324 8012120307 | NUREO NUREO | PNL-3045 |
| NUREG/CR-1120 V4 NUREG/CR-1157 V2 | 8012170465 | NUREO | SAND80-1091 |
| NUREQ/CR-1219 | 8012230066 | 50-320 P | |
| NUREO/CR-1232 | 8012230319 | NUREO NUREO | UCRL-52735 V1 |
| NUREQ/CR-1233 V1 NUREQ/CR-1233 V2 | 8012020738 8012020744 | NUREO | UCRL-52735 V2 |
| NUREO/CR-1233 V3 | 8012040070 | NUREG | UCRL-52735 V3 |
| NUREG/CR-1257 | 6012230509 | NUREO | CREARE TN-312 |
| NUREO/CR-1261 | 9012230315 9012230323 | NUREO NUREO | PNL-3257 PNL-3264 |
| NUREQ/CR-1284 NUREQ/CR-1291 | 8012230323 | NUREO | HEDL-8A 1949 |
| NUREO/CR-1277 | 8012120270 | NUREO | PAL-3163 |
| NUREQ/CR-1318 | 8012080014 | NUREO | |
| | | | |

REPORT NUMBER INDEX

| REPORT NUMBER | ACCEBSION NUMBER | EUBJECT CATEGORY | OTHER REPORT |
|----------------------|--------------------------|---------------------|-----------------------------|
| NUREG/CR-1324 | 8012230340 | NUREO | CREARE TN-313 |
| NUREG/CR-1338 | 8012230374 | NUREO | 14E0~080AB |
| NUREQ/CR-1364 | 8012220719 | NUREO | 8AND80~0429 |
| NUREG/CR-1407 | 9012220678 | NUREG | PNL-3345 |
| NUREO/CR-1420 | B012220728 | NUREO | ANL-80-37 |
| NURED/CR-1426 | | | |
| NUREO/CR-1427 | 8012230104 | NUREO | BMI-2051 |
| NUREO/CR-1454 V2 | 8012220716 | NUREG | BLN-NUREG-51185 |
| NUREQ/CR-1454 V3 | 8012120343 | NUREO | 2-08EE-1/49 |
| NUREG/CR-1454 V3 | B012240507 | NUREO | PNL-3380-3 |
| NOREG7 CR-1436 | 8012220470 | NUREO | E00-2035 |
| NUREO/CR-1461 | 8012080794 | NUREO | |
| NUREG/CR-1467 | 8012120350 | NUREO | MHSK-8D 7920 |
| NUREG/CR-1449 | 8012120217 | NUREO | MHBM-8D 7919 |
| NUREG/CR-1469 V14 | 8012020139 | NUREO | 9AND80-0927 |
| NUREQ/CR-1485 V1 ERR | 8012310116 | NUREO | 3014000-0727 |
| NUREO/CR-1493 | 00/0/00000 | 411.00 | |
| NUREO/CR-1474 | 8012170530 8012230095 | NUREO | SAND80-0455 |
| NUREG/CR-1503 | | NUREO | PNL-3381 |
| NUREQ/CR-1511 | 8012230516 | NUREO | NRC-04-77-210 |
| NUREG/CR-1519 | 8012230079 | NUREO | LA-8305-HB |
| HONEGPER "IS19 | 8012230368 | NUREO | NRC-04-78-262 |
| NUREG/CR-1526 V3 | 8012220167 | NUREO | ANL-80-54 V3 |
| NUREQ/CR-1528 | 8012230331 | NUREO | M/6-90-04 43 |
| NUREG/CR-1554 | 8012240309 | NUREO | |
| NUREQ/CR-1558 | 6012120322 | NUREO | EPRI NP-1523 |
| NUREG/CR-1568 | 8012230380 | NUREO | CLAI UL-1989 |
| NUREO/CR-1584 | 8012230335 | 50.500 0 | |
| NUREQ/CR-1585 | 8012230322 | 50~320 P | |
| NUREQ/CR-1595 | 8012230322 | NUREG | NRC-04-76-218 |
| NUREO/CR-1605 | 8012120334 | NUREO | PNL-3454 |
| NUREO/CR-1621 | 8012220634 | NUREO | BNL-NUREG-51241 |
| | G015550934 | NUREQ | |
| NUREO/CR-1626 | 8012110453 | NUREO | PNL-3472 |
| NUREO/CR-1651 | 8012220615 | NUREO | BNL-NURED-51258 |
| NUREG/CR-1440 | 8012230370 | NUREO | UCRL-15227 |
| NUREO/CR-1462 | 8012030823 | NUREO | NRC-04-76-323 |
| NURE0/CR-1663 | 8012230201 | NUREG | NRC-04-76-323 |
| NUREG/CR-1672 | 8012080023 | NUREO | 6AI-219-80-PA |
| NUREO/CR-1674 | 8012220707 | NUREO | |
| NUREO/CR-1694 | 9012080017 | NUREO | E09-2058 |
| NUREQ/CR-1695 | 8012080010 | NUREO | BNL-NUREO-51266 |
| NUREG/CR-1709 | 8012220181 | NUREO | EGG-2060 ORNL/NUREG/CSD/ |
| NUREO/CR-1715 | | | D |
| NUREO/CR-1717 V1 | 8012110558 | NUREO | E00-2041 |
| NUREO/CR-1717 V2 | 8012190424 | NUREO | BNL-NUREG-51263 |
| NUREO/CR-1717 02 | 8012310224 | NUREO | BNL-NUREG-51263 |
| | 8012170524* | NUREO | |
| NUREG/CR-1728 ERR | 8012310031# | NUREQ | |
| NUREO/CR-1730 | 8012220623 | NUREO | EGQ-EA-5188 |
| NUREG/CR-1736 | 8012040061 | NUREO | LMF-78 |
| NUREO/CR-1739 VI | 8012270619 | NUREO | 8AND80-7145 |
| NUREQ/CR-1739 V2 | 8012270615 | NUREO | SAND80-7145/2 |
| NUREO/CR-1746 | 8012020659 | | BANDB0-1324 |

| REPORT NUMBER | | ACCESSION NUMBER | BUBJECT CATEGORY | OTHER REPORT NUMBER |
|---|----|---|--|--|
| NUREG/CR-1749 NUREG/CR-1752 NUREG/CR-1779 NUREG/CR-1793 NUREG/CR-1793 | V1 | 8012020124 8012110471 8012170537 8012160589 8012160598 | NUREO NUREO NUREO NUREO NUREO | SANDBO-1307 UCRL-15277 BHARC-311-80-02 |
| NUREO/CR-1794 NUREO/CR-1804 NUREO/CR-1805 NUREO/CR-1808 NUREO/CR-1817 | V2 | 8012170040 8012310445 8012310394 8012220609 8012120342 | NUREO NUREO NUREO NUREO NUREO | EDIS NOSDC-4 EDS NOSDC-2 |
| NUREG/CR-1922 NUREG/CR-1835 NUREG/CR-1847 DL8-79-124 DR0-4014-10 | | 8012120590 8012290611 8012190432 8012110452* 8012230348* | NUREG NUREO NUREO FOIA 50-83 R | BH1-2069 NRC-04-77-147 |
| PRS-705 PSR-914 QUAD-1-79-234 SECY-79-344 SECY-79-416 | R4 | 8012070214* 8012150113* 8012110283* 7907030173* 8012110445* | 50-361 A 50-327 P 50-237 P 50-367 O FOIA | NEC-COM-0219-R0 |
| BECY-80-925A SECY-80-979 BECY-80-984 SECY-80-416A SECY-80-457 | | 8011200263 8009100422 8012290009* 8011200546 8011280117* | 10CFR BECY 10CFR 50-320 P 10CFR | 45FR71023 |
| SECY-80-474C SECY-80-476 SECY-80-486 SECY-80-489 SECY-80-495 | | 8012270483* 8011280112* 8011140484* 8011200233 8012080754 | 10CFR 10CFR 10CFR SECY 50-579 A | |
| 5ECY-80-500 5ECY-80-504 5ECY-80-507 5ECY-80-512 5ECY-80-513 | | 8011200286 8012020353* 8012050053 8012030773 8012080765 | BECY LOCFR BECY BECY SECY | |
| 8ECY-80-514 BECY-80-519 BECY-80-519 R1 BECY-80-520 SECY-80-523 | | 8012120220 8012110488* 8012110484* 8012180327 8012180416 | BECY 70-143 70-149 BECY BECY | |
| 8ECY-80-534 8ECY-A-80-179C SECY-A-80-179D 8ECY-A-80-179E TC-1799 | | 8012270585 8012170373* 8012270507* 8012270501* 8012050476* | SECY 50-247 T 50-3 T 50-3 T PROJ | |
| TN-RW-101/00-NI TR-675L211 TS-51-56008 VEF-FRD-38 | • | 8012300237# 8012180464# 8012050492# 8012010295# | TOPREP 50-245 P PROJ 50-280 P | |
| HCAP-9763 XN-NF-75-27(A) YAEC-1231 | 92 | 8012040237* 8012230511* 8012240262* | TOPREP TOPREP 50-27 P | |

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | CATEODR | |
|--------------------------|--------------------------|----------------|----------------|----|
| 7907030173 7910150058 | 8012020495 8012030001 | 80/11/20 | 50-367 FOIA | 0 |
| 7911150300 | 8012030001 | 80/10/15 | FOIA | |
| | | | | - |
| 8001030454 | 8001030448 | 79/12/31 | 50-34B | F |
| 8002550083 | 6012020695 | 80/11/20 | 50-367 | 0 |
| 8004100230 | 6004100226 | 80/11/10 | 71-9073 | |
| 8005130347 | 8005130126 | 80/04/10 | 40-6940 | |
| 8800908008 | 8012110643 | 80/11/20 | FOIA | |
| 8008270155 | 8012050033 | 80/11/14 | BECY | |
| 8009180039 | 8012010126 | 80/11/10 | 71-9073 | |
| 8009180046 | 8012010126 | 80/11/10 | 71-9073 | |
| 8009190463 | 8012080720 | 80/10/30 | 40-8106 | |
| 8010230021 | 8012040162 | 80/11/06 | 1 OCFR | |
| 8010260584 | B012010126 | 80/11/10 | 71-9073 | |
| 8010300537 | 8010300535 | 80/10/16 | 50-320 | U |
| 8010300544 | 8010300535 | 80/10/16 | 50-320 | U |
| 8011060013 | 8012010126 | 80/11/10 | 71-7073 | |
| 8011040234 | 8011210740 | 80/10/14 | RECOD | |
| 8011040238 | 8011210740 | 80/10/16 | REGOD | |
| B011130046 | 8012050053 | 80/11/14 | BECY | |
| B011140484 | 8012020176 | 80/11/17 | 10CFR | |
| 8011170009 | 8011170005 | 80/10/13 | 40-8745 | |
| 8011180319 | 6011160303 | 80/10/15 | State Pr | oa |
| 8011180569 | 8011180561 | 80/11/17 | 50-285 | P |
| 8011180703 | 8011180492 | 80/11/11 | 50-325 | 8 |
| 8011190378 | 8011190371 | 80/11/19 | 50-443 | Α |
| E011190383 | 8011170371 | 80/11/18 | 50-443 | A |
| 8011190396 | 8011190371 | 90/11/18 | 50-443 | A |
| 8011170518 | 8011170515 | 80/10/08 | 50-10 | Œ |
| 8011200171 | 8011200186 | 80/10/14 | 40-8714 | |
| 8011210181 | 8011210177 | 80/10/31 | 71-9015 | |
| 8011250108 | 8011250100 | 80/10/31 | 50-279 | 0 |
| 8011250276 | 8011250274 | 80/09/11 | 50-461 | ā |
| 801125027B | 8011250274 | 80/09/11 | 50-461 | ä |
| 8011250501 | B011250495 | 80/11/20 | 50-267 | 8 |
| 8011250557 | 8011250549 | 80/11/14 | 50-361 | Α |
| 8011250704 | 8012080756 | 80/11/05 | 50-579 | Ä |
| 8011280067 | 8011280064 | 80/11/26 | 50-416 | К |
| 8011280112 | 8011280104 | 80/11/21 | LOCFR | 17 |
| 8011280117 | 8011280106 | 80/11/21 | LOCFR | |
| 8012010014 | 8012010010 | 80/10/31 | 50~528 | a |
| 8012010026 | 8012010025 | 80/11/10 | 40-8743 | • |
| 8012010038 | 8012010036 | 80/10/06 | 40-8584 | |
| 8012010078 | 8012010074 | 80/11/19 | 50-277 | Р |
| 8012010081 | 8012010074 | 80/11/19 | 50-277 | þ |
| 8012010085 | 8012010074 | 80/11/19 | 50-277 | p |
| 8012010098 | 8012010077 | 80/11/26 | 20-302 | þ |
| 8012010178 | 8012010177 | 80/11/10 | 71-9073 | • |
| 8012010133 | 8012010126 | 80/11/10 | 71-9073 | |
| 8012010137 | | 80/11/10 | 71-9073 | |
| 0015010149 | -8012010126 | 60/11/10 | 1-70/3 | |

| MCCEGGIOI | T NOTIDER | | |
|--|--|--|--|
| ENCLOSURE | PRINCIPAL | DATE | BUÐJEGT |
| | DOCUMENT | 188UED | CATEGORY |
| 8012010152 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010154 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010160 | 8012010139 | 80/11/24 | 50-255 P |
| 8012010163 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010169 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010173 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010178 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010188 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010176 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010205 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010208 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010223 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010225 | 8012010201 | 80/11/24 | 50-369 A |
| 8012010228 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010234 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010241 8012010242 8012010247 8012010252 8012010257 | 8012010126 8012010126 8012010126 8012010126 | 80/11/21 80/11/10 80/11/10 80/11/10 80/11/10 | 50-293 P 71-9073 71-9073 71-9073 71-9073 |
| 8012010259 8012010260 8012010262 8012010265 8012010265 | 8012010126 8012010126 8012010126 8012010126 | 80/10/08 80/11/10 80/11/10 80/11/10 80/11/10 | PR 71-9073 71-9073 71-9073 71-9073 |
| 8012010269 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010274 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010279 | 8012010126 | 80/11/10 | 71-9073 |
| 8012010280 | 8012010277 | 80/11/19 | 50-339 8 |
| 8012010287 | 8012010286 | 80/11/24 | 50-255 P |
| 8012010295 | 8012010291 | 80/11/19 | 50-280 P |
| 8012010299 | 8012010297 | 80/11/21 | 50-244 P |
| 8012010302 | 8012010298 | 80/10/28 | 71-379 |
| 8012010308 | 8012010304 | 80/11/25 | 50-272 G |
| 8012010313 | 8012010304 | 80/11/25 | 80-272 Q |
| 8012010314 8012010324 8012010335 8012010340 8012010346 | 8012010307 8012010315 8012010322 8012010331 8012010325 | 80/11/20 80/11/20 80/11/24 80/11/20 80/11/20 | 50-368 8 50-368 8 50-368 8 50-368 8 |
| 8012010347 | 8012010341 | 80/11/24 | 50-293 B |
| 8012010357 | 8012010349 | 80/11/24 | 50-346 B |
| 8012010359 | 8012010352 | 80/11/24 | 50-339 B |
| 8012010361 | 8012010354 | 80/11/21 | 80-313 S |
| 8012010362 | 8012010353 | 80/11/19 | 50-339 B |
| 8012010367 | 8012010348 | 80/11/24 | 30-348 B |
| 8012010369 | 8012010354 | 80/11/24 | 30-317 S |
| 8012010372 | 8012010364 | 80/11/21 | 50-266 B |
| 8012010373 | 8012010363 | 80/11/21 | 50-338 B |
| 8012010376 | 8012010366 | 80/11/20 | 50-331 I |

| | ON NUMBER | | | | | ON NUMBER | | | |
|--|--|--|---|-----------------------|---|--|--|---|-----------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE 189UED | SUBJEC | | ENCLOSURE | PRINCIPAL | DATE | BUBJEC | |
| 8012010381 8012010382 8012010383 8012010390 8012010392 | 8012010370 8012010374 8012010371 8012010378 8012010384 | 80/11/19 80/11/18 80/11/20 80/11/24 80/11/25 | 50-368 50-254 50-366 50-338 50-255 | 9 9 9 | 80 (2020379 80 (2020379 80 (2020379 80 (2020389 80 (2020397 | B012020338 8012020338 8012020338 8012020376 8012020376 | 185VED 80/11/18 80/11/18 80/11/18 80/10/28 80/11/20 | 10CFR 10CFR 10CFR 10CFR 40-2259 90-364 | |
| 8012010373 8012010374 8012010403 8012010404 8012010405 | 8012010384 8012010377 8012010379 8012010379 8012010376 | 80/11/20 80/11/24 80/11/24 80/11/21 80/11/06 | 50-366 50-321 50-271 50-313 50-298 | 88889 | 8012020400 8012020402 8012020404 6012020412 8012020412 | 8012020395 8012020395 8012020395 8012020408 8012020418 | 80/11/20 80/11/20 80/11/20 80/11/20 80/11/28 | 50-364 50-364 50-364 50-390 50-260 | 0 0 0 3 |
| 8012010406 8012010415 8012010418 8012010427 8012010431 | 8012010402 8012010410 8012010414 8012010409 8012010421 | 80/11/21 80/11/24 80/10/16 80/11/25 80/11/12 | 50-366 50-286 FR 50-333 50-366 | 8 8 P | 8012020426 6012020431 8012020433 8012020436 8012020437 | 8012020423 8012020428 8012020408 8012020408 8012020435 | 80/11/24 80/11/26 80/11/20 80/11/20 80/11/26 | 50-339 50-305 50-390 50-390 50-271 | 8 8 0 8 |
| 8012010435 8012010436 8012010441 8012010455 8012010476 | 8012010421 8012010417 8012010421 8012010440 8012010470 | 80/11/12 80/11/07 80/11/12 80/11/20 80/11/20 | 50-344 50-267 50-364 50-277 50-438 | P B A | B012020441 B012020443 B012020443 B012020450 B012020456 | 8012020408 8012020440 8012020444 8012020446 8012020453 | 80/11/20 80/11/20 80/12/01 80/11/26 80/11/24 | 50-390 50-364 50-296 50-344 50-409 | G E 80 8 |
| 8012010489 8012010493 8012010529 8012010531 8012010535 | 8012010483 8012010477 8011190098 8012010527 8012010533 | 80/11/12 80/11/26 80/10/31 80/11/04 80/11/18 | 50-265 50-282 50-331 COHMISSI 50-170 | 9 0 0 0 0 | 8012020461 8012020462 8012020468 8012020468 8012020474 | 8012020458 8012020460 8012020463 8012020464 8012020469 | 80/11/25 80/11/24 80/11/26 80/11/26 80/11/12 | 50-368 50-424 50-313 50-289 50-251 | 8 A 8 P 8 |
| 8012010364 8012010571 8012010577 8012010586 8012010587 | 6012010561 8012010561 8012010575 6012010566 8012010584 | 80/11/19 80/11/19 80/11/18 80/11/18 80/11/10 | 50-224 50-224 50-157 50-282 50-324 | О В В | 8012020475 8012020488 8012020499 8012020507 8012020508 | 8012020470 8012020485 8012020492 8012020500 8012020499 | 80/11/26 80/11/26 90/11/24 80/11/26 80/12/01 | 50-29 50-272 50-331 50-366 50-296 | *** |
| 8012010407 8012010414 8012010424 8012020023 8012020042 | 8012020036 8012010602 8012010622 8012010623 | 80/11/13 80/11/13 80/09/17 80/11/19 80/11/07 | 50-338 50-338 70-1308 50-275 50-269 | F | 8012020509 8012020516 8012020518 8012020519 8012020520 | 8012020501 8012020511 8012020514 8012020512 8012020494 | 80/11/24 80/11/26 80/11/28 80/11/26 80/11/21 | 50-335 50-366 50-296 50-364 50-324 | 8 8 8 8 |
| 8012020051 8012020057 8012020073 8012020089 8012020093 | 8015050083 8015050083 8015050094 8015050039 | 80/11/07 80/11/07 80/11/24 80/11/25 80/11/25 | 50-269 50-269 50-438 50-482 50-482 | P A C C | 8012020530 8012020531 8012020533 8012020535 8012020542 | 8012020504 8012020524 8012020525 8012020529 8012020534 | 80/11/28 80/10/31 80/11/26 80/11/24 80/11/19 | 50-317 50-302 50-346 50-336 50-335 | 88885 |
| 8012020110 8012020127 8012020129 8012020133 8012020141 | 8012020099 8012020117 8012020121 8012020117 8012020117 | 80/11/14 80/11/20 80/11/26 80/11/20 90/11/20 | 50-254 50-347 50-250 50-369 50-369 | 0 0 0 | 8012020543 8012020544 8012020546 801202055 8012020555 | 8012020502 8012020538 8012020541 8012020540 8012020548 | 80/11/26 80/11/14 80/11/24 80/11/28 80/11/24 | 50-270 50-250 50-331 50-272 50-335 | 8 8 8 8 |
| 8012020147 8012020148 6012020158 8012020159 8012020154 | 8012020117 8012020137 8012020137 8012020117 8012020170 | 80/11/20 80/11/26 80/11/26 80/11/20 80/10/21 | 50-369 50-272 50-272 50-369 50-265 | 0 0 0 0 | 8012020594 8012020557 801202059 801202059 801202059 | 8012020592 8012020551 8012020545 8012020549 8012020534 | 80/11/25 80/11/06 80/11/26 80/11/18 80/11/25 | 50-219 50-335 50-348 50-346 50-267 | 5 5 6 6 6 |
| 8012020205 8012020216 8012020217 8012020228 8012020245 | 8012020199 8012020210 8012020182 8012020222 8012020241 | 80/10/01 80/10/02 80/11/24 80/10/06 80/11/25 | | Q Q Q R | 8012020566 8012020567 8012020569 8012020574 8012020575 | 8012020545 8012020561 8012020565 8012020545 8012020568 | 80/11/26 80/11/18 80/11/26 80/11/26 80/11/25 | 50-348 50-335 50-325 50-348 50-267 | 8 8 8 8 |
| 8012020248 8012020251 8012020252 8012020261 8012020262 | 8012020239 8012020247 8012020238 8012020254 8012020257 | 80/11/18 80/11/26 80/11/18 80/09/10 80/10/20 | 40-8709 50-341 40-8709 70-371 40-8709 | A | 8012020578 8012020596 8012020591 8012020591 8012020591 | 8012020571 8012020545 8012020581 8012020583 8012020587 | 80/11/20 80/11/26 80/11/24 80/11/20 80/11/19 | 50-324 50-348 50-337 50-249 50-346 | 888 |
| 8012020265 8012020268 8012020289 8012020274 8012020278 | 8012020259 8012020264 8012020287 8012020283 8012020293 | 80/11/13 80/11/20 80/11/18 80/11/13 80/11/20 | State Pro | Q Q A | 8012020393 8012020597 8012020600 8012020601 8012020602 | 8012020545 8012020589 8012020593 8012020545 8012020596 | 80/11/26 80/11/24 80/11/26 80/11/26 80/11/24 | 50-348 50-309 50-318 50-348 50-339 | 8 R 8 8 8 |
| 8012020312 8012020318 8012020328 8012020331 8012020335 | 8012020308 8012020315 8012020323 8012020327 8012020327 | 80/11/10 80/11/26 80/11/28 80/11/04 80/11/04 | 50-409 | Q P A | 8012020606 8012020613 8012020616 8012020617 8012020617 | 8012020599 8012020603 8012020607 8012020604 8012020612 | 80/11/20 80/11/24 80/11/25 80/11/21 80/11/25 | 50-293 50-331 50-295 FOIA 50-317 | 8 8 8 |
| 8012020345 8012020348 8012020349 8012020351 8012020353 | 8012020339 8012020339 8012020340 8012020338 8012020338 | 80/11/20 80/11/20 80/10/23 80/11/18 80/11/18 | | Q Q | 8012020620 8012020621 8012020622 8012020624 8012020630 | 8012020604 8012020610 8012020615 8012020604 8012020604 | 80/11/21 80/11/26 80/11/28 80/11/21 80/11/21 | FOIA 50~327 50-293 FOIA FOIA | 8 |
| 8012020354 8012020356 8012020359 8012020361 8012020364 | 8012020337 8012020339 8012020338 8012020340 8012020339 | 80/11/20 80/11/20 80/11/19 80/10/23 80/11/20 | 50-259 10CFR 40-8084 | Ω Ω | 8012020631 8012020633 8012020634 8012020634 8012020636 | 8012020623 8012020628 8012020628 8012020629 8012020604 | 80/11/24 80/11/21 80/11/26 80/12/01 80/11/21 | 50-338 50-327 50-446 50-327 FDIA | 8 6 8 |

| ACCESSION | | | | | | | ACCESSION | NUMBER | | |
|--|--|--|--|------------------|---|--|--|--|--|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE 188UED | EUDJEC1 CATEQU | łΥ | | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE 165UED | SUBJECT CATEGORY |
| 8012020640 8012020646 8012020652 8012020663 8012020664 | 8012020404 8012020435 801202045 8012020455 8012020458 | 80/11/21 80/11/26 80/11/24 80/11/26 80/11/25 | FQIA 50-302 50-272 50-272 50-387 | 8 8 8 | | | 8012030049 8012030049 8012030050 8012030051 8012030052 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-39 27-10 FOIA FOIA 27-10 |
| 8012020468 8012020474 8012020475 8012020479 8012020483 | 8012020660 8012020660 8012020667 8012020670 8012020667 | 80/11/17 80/11/17 80/11/19 80/11/19 80/11/19 | 50-289 50-289 GA999 50-285 GA999 | G B | | | 8012030053 8012030054 8012030055 8012030056 8012030057 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 FOIA 27-10 FOIA |
| 8012020487 8012020492 8012020494 8012020702 8012020703 | 8012020667 8012020667 8012020689 8012020667 8012020695 | 80/11/17 80/11/19 80/10/16 80/11/19 80/11/20 | 50-289 GA999 70-371 GA999 50-347 | G G | | | 8012030042 8012030040 8012030040 8012030059 8012030058 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA FOIA FOIA FOIA |
| 8012020712 8012020716 8012020718 8012020721 8012020723 | 8012020682 8012020709 8012020695 8012020709 8012020706 | 80/11/25 80/11/14 80/11/20 80/11/14 80/11/28 | 50-338 QA999 50-367 QA999 50-322 | B 0 A | | | 8012030063 8012030064 8012030065 8012030066 8012030067 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 90/10/13 80/10/15 90/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA |
| 8012020726 8012020728 8012020733 8012020740 8012020749 | 8012020709 8012020495 8012020709 8012020731 8012020739 | 80/11/14 80/11/20 80/11/14 80/11/21 80/10/24 | QA999 50-367 QA999 FOIA 50-445 | o a | | | 8012030069 8012030069 8012030070 8012030071 8012030072 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOTA FOTA FOTA FOTA |
| 8012020750 8012020762 8012020770 8012020780 8012020793 | 8012020695 8012020757 8012020761 8012020761 8012020787 | 80/11/20 80/10/23 80/10/28 80/10/28 80/10/30 | 50-367 50-482 50-373 50-373 50-263 | 0 0 0 0 | | | 8012030073 8012030074 8012030075 8012030076 8012030077 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 FOIA FOIA 27-39 |
| 8012020796 8012020797 8012020797 8012020800 8012020802 | 8012020792 8012020784 8012020791 8012020792 8012020792 | 80/11/12 80/02/20 80/10/31 80/11/12 80/11/12 | GA999 50-312 50-289 GA999 GA999 | 0 0 | | | 8012030078 8012030079 8012030080 8012030081 8012030082 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA |
| 8012020804 8012020808 8012020811 8012020821 8012020828 | 8012020784 8012020772 8012020764 8012020815 8012020824 | 80/02/20 80/11/12 80/02/20 80/11/06 80/09/23 | 50-312 QA999 50-312 50-293 50-170 | 0 H H | | | 8012030083 8012030084 8012030085 8012030086 8012030087 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 | 27-39 FOIA FOIA FOIA FOIA |
| 8012020838 8012020838 8012030002 8012030003 8012030005 | 8012020817 8012020834 8012030001 8012030001 8012030001 | 80/11/18 77/02/07 80/10/15 80/10/15 | 50-320 50-367 27-39 27-39 27-39 | H | | | 8012030089 8012030089 8012030090 8012030091 8012030092 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-39 27-10 FOIA |
| 8012030004 8012030007 8012030009 8012030010 8012030011 | B012030001 B012030001 B012030001 B012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-39 27-39 FOIA 27-39 | | 1 | | 8012030073 8012030074 8012030075 8012030076 8012030077 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA 27-10 |
| 8012030012 8012030013 8012030014 8012030015 8012030016 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-39 FOIA 27-39 | | | | 8012030078 8012030077 8012030100 8012030101 8012030102 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-39 FOIA FOIA FOIA FOIA |
| 8012030017 8012030019 8012030020 8012030021 8012030022 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-39 FOIA FOIA FOIA | | | | 8012030103 8012030104 8012030105 8012030106 8012030107 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 FOIA 27-37 FOIA |
| 8012030024 8012030025 8012030026 8012030027 8012030028 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-39 27-10 FOIA FOIA 27-39 | | | | 8012030108 8012030109 8012030110 8012030111 8012030112 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 90/10/15 80/10/15 80/10/15 90/10/15 80/10/15 | 27-10 FOIA FOIA FOIA 27-10 |
| 8012030030 8012030031 8012030032 8012030033 8012030034 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | | | | 8012030113 8012030114 8012030115 8012030116 8012030117 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-39 FOIA FOIA FOIA FOIA |
| 8012030035 8012030038 8012030039 8012030040 8012030041 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA 27-10 27-10 FOIA | | | | 8012030118 8012030120 8012030121 8012030121 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA 27-39 27-10 FOIA |
| 8012030042 8012030043 8012030049 8012030044 8012030047 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 27-10 FOIA FOIA FOIA | | | | 8012030123 8012030124 8012030125 8012030126 8012030127 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA 27~10 |

| ACCESSI | ON NUMBER | | | | | ACCEBBIO | N NUMBER | | |
|---|--|--|---|--|--|--|--|--|--|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | GUBJECT CATEGORY | | | | PRINCIPAL | DATE | SUBJECT |
| 8012030128 8012030129 8012030130 8012030131 8012030132 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 27-39 FOIA FOIA | | | 8012030210 8012030211 8012030212 8012030213 8012030214 | B012030001 8012030001 8012030001 8012030001 8012030001 | 185UED 80/10/15 80/10/15 80/10/15 80/10/15 | CATEGORY 27-10 FOIA FOIA 27-10 FOIA |
| 8012030133 8012030134 8012030135 .8012030136 8012030137 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 27-10 FOIA FOIA 27-10 | | | 8012030215 8012030216 8012030217 8012030218 8012030219 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA FOIA FOIA FOIA |
| 8012030139 8012030149 8012030141 8012030142 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | | | 8012030220 8012030221 8012030222 8012030223 8012030224 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-10 27-39 |
| 8012030143 8012030144 8012030145 8012030146 8012030147 | 8015030001 8015030001 8015030001 8015030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 FOIA FOIA FOIA | | | 8012030225 8012030226 8012030229 8012030229 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA |
| 8012030148 8012030149 8012030150 8012030152 8012030153 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-10 27-10 | | | 8012030230 8012030231 8012030234 8012030235 8012030236 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 27-10 FOIA FOIA |
| 8012030154 8012030155 8012030154 8012030157 8012030158 | 8012030001 8012030001 8012030001 | 80/10/13 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-39 FOIA FOIA | | | 8012030237 8012030238 8012030239 8012030240 8012030241 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-39 FOIA FOIA FOIA FOIA |
| 8012030157 8012030160 8012030161 8012030162 8012030163 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FGIA 27-10 27-39 FOIA | | | 8012030242 8012030243 8012030244 8012030249 8012030246 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-10 FOIA |
| 8012030164 8012030165 8012030166 8012030167 8012030169 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 FOIA 27-39 FOIA | | | 8012030247 8012030249 8012030250 8012030251 8012030252 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA POIA FOIA 27-39 FOIA |
| 8012030149 8012030170 8012030171 8012030172 8012030173 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-10 FOIA | | | 8012030253 8012030255 8012030256 8012030257 8012030258 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-10 27-10 |
| 8012030174 8012030175 8012030176 8012030177 8012030178 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-39 FOIA FOIA | | | 8012030259 8012030260 8012030262 8012030263 8012030264 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA |
| 8012030179 8012030180 8012030181 8012030182 8012030183 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-39 FOIA 27-10 | | | 8012030245 8012030244 8012030247 8012030248 8012030249 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-39 FOIA FOIA FOIA FOIA |
| 8012030184 8012030185 8012030186 8012030187 8012030188 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA 27-10 FOIA FOIA | | | 8012030270 8012030272 8012030273 8012030274 8012030275 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-39 FOIA |
| 7810E02108 0710E02108 1710E02108 2710E02108 E710E02108 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA FOIA 27-10 FOIA | | | 8012030276 8012030277 8012030278 8012030279 8012030280 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA |
| 8012030194 8012030195 8012030194 6012030197 8012030198 | 8012030001 8012030001 8012030001 8012030001 | 80/10/13 80/10/15 80/10/15 80/10/13 80/10/13 | 27-39 FOIA FOIA 27-10 FOIA | | | 8012030281 8012030282 8012030283 8012030284 8012030286 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA FOIA FOIA 27-39 |
| 8012030199 8012030200 8012030201 8012030202 8012030203 | B015030001 B015030001 B015030001 B015030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-10 FOIA | | | 8012030287 8012030288 8012030287 8012030270 8012030271 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 97-10 FOIA 27-10 |
| 8012030204 8012030205 8012030207 8012030208 8012030209 | 8015030001 8015030001 8015030001 8015030001 | 90/10/15 90/10/15 90/10/15 90/10/15 90/10/15 | FOIA FOIA FOIA FOIA | | | 8012030292 8012030293 8012030294 8012030295 8012030296 | B012030001 B012030001 B012030001 B012030001 | 90/10/15 90/10/15 90/10/15 90/10/15 80/10/15 | FOIA FOIA FOIA FOIA |

| ACCESSION | NUMBER | | | ACCESSION NUMBER | | | | | |
|--|--|--|---|--|--|--|--|--|--|
| ENGLOSURE | PRINCIPAL DOCUMENT | DATE IBSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE 188UED | BUBJECT CATEGORY | | |
| 8012030297 8012030298 8012030299 8012030300 8012030301 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA 27-39 | 8012030384 8012030385 8012030306 8012030387 8012030388 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | | |
| 8012030304 8012030304 8012030305 8012030307 8012030308 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FDIA FOIA FOIA FOIA | 8012030389 8012030390 8012030391 8012030392 8012030393 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030309 8012030310 8012030311 8012030312 8012030313 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 27-10 FOIA 27-10 | 8012030374 8012030375 8012030377 8012030378 8012030377 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-37 FOIA FOIA FOIA FOIA | | |
| 8012030314 8012030315 8012030317 8012030318 8012030319 | B012030001 B012030001 B012030001 B012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA 27-10 | 8012030400 8012030402 8012030403 8012030404 8012030405 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030320 8012030321 8012030322 8012030323 8012030324 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | 8012030406 8012030407 8012030408 8012030409 8012030410 | 8012030001 8012030001 8012030001 8012030376 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/28 80/10/15 | FOIA FOIA FOIA 50-546 Q FOIA | | |
| 8012030325 8012030326 8012030327 8012030328 8012030327 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | 8012030411 8012030412 8012030413 8012030414 8012030415 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-39 FOIA | | |
| 8012030330 8012030331 8012030332 8012030333 8012030334 | B012030001 B012030001 B012030001 B012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-10 FOIA FOIA | 6012030416 6012030417 6012030419 6012030419 8012030420 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 60/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA 27-10 | | |
| 8012030335 8012030336 8012030337 8012030338 8012030339 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | 8012030421 8012030422 8012030423 8012030424 8012030426 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030340 8012030341 8012030342 8012030343 8012030345 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | 8012030427 8012030420 8012030429 8012030430 8012030431 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-39 FOIA FOIA FOIA | | |
| 8012030346 8012030347 8012030348 8012030349 8012030350 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-10 FOIA FOIA | 8012030432 8012030434 8012030433 8012030436 8012030437 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA 27-10 | | |
| 8012030351 8012030352 8012030353 8012030354 8012030355 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | 8012030438 8012030439 8012030440 8012030442 8012030443 | 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-39 FOIA FOIA FOIA | | |
| 8012030354 8012030357 8012030358 8012030360 8012030361 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA 27-39 | 8012030444 8012030445 8012030446 8012030447 8012030448 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030362 8012030363 8012030364 8012030366 8012030367 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA 27-10 FOIA 27-10 FOIA | 8012030449 8012030450 8012030451 8012030452 8012030453 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA FOIA FOIA FOIA | | |
| 8012030368 8012030369 8012030370 8012030371 8012030372 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-10 FOIA 27-10 | 8012030454 8012030455 6012030456 8012030457 8012030457 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-39 FOIA FOIA | | |
| 8012030373 8012030374 8012030375 8012030376 8012030377 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-10 27-10 FOIA | 8012030460 8012030461 8012030462 8012030463 8012030464 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030378 8012030380 8012030381 8012030382 8012030383 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 F01A 27-39 F01A 27-10 | 9012030465 9012030466 9012030467 9012030469 8012030469 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| | | | | | | | | | |

| ACCESSION NUMBER | | | ACCESSION NUMBER | | | | | | |
|--|--|--|------------------|--|--|--|--|---|--|
| PRINCIP ENCLOSURE DOCUME | NT ISSUED | SUBJECT CATEGORY | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE 156UED | BUBJEC CATEGO | | |
| 8012030470 8012030 8012030471 8012030 8012030472 8012030 8012030473 8012030 8012030474 8012030 | 001 80/10/15 001 80/10/15 001 80/10/15 001 80/10/15 | FOIA FOIA FOIA FOIA | | 8012030551 8012030552 8012030553 8012030554 8012030555 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030475 8012030 8012030476 8012030 8012030477 8012030 8012030478 8012030 8012030479 8012030 | 001 80/10/15 001 80/10/15 001 80/10/15 | FOIA FOIA FOIA 27-10 FOIA | | 8012030554 8012030557 8012030558 8012030557 8012030560 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030480 80120300 8012030481 80120300 8012030482 80120300 8012030483 80120300 8012030484 80120300 | 001 80/10/15 001 80/10/15 001 80/10/15 | FOIA FOIA FOIA FOIA | | 8012030561 8012030562 8012030563 8012030564 8012030565 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | 27-10 FOIA FOIA POIA FOIA | | |
| 8012030485 80120300 8012030486 80120300 8012030487 80120300 8012030488 80120300 8012030489 80120300 | 001 80/10/15 001 80/10/15 001 80/10/15 | FOIA 27-10 FOIA 27-10 FOIA | | 8012030564 8012030567 8012030569 8012030570 8012030571 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030490 80120300 8012030491 80120300 8012030492 80120300 8012030493 80120300 8012030494 80120300 | 01 80/10/15 01 80/10/15 01 80/10/15 | FOIA FOIA FOIA FOIA | | 8012030572 8012030573 8012030574 8012030575 8012030576 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030495 80120300 8012030497 80120300 8012030498 80120300 8012030499 80120300 8012030500 80120300 | 01 80/10/15 01 80/10/15 01 80/10/15 | 27-10 FOIA FOIA FOIA FOIA | | 8012030578 8012030579 8012030580 8012030581 8012030582 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030501 80120300 8012030502 80120300 8012030503 80120300 8012030504 80120300 8012030505 80120300 | 01 80/10/15 01 80/10/15 01 80/10/15 | FOIA FOIA 27-10 FOIA FOIA | | 8012030584 8012030583 8012030586 8012030587 8012030587 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030504 80120300 8012030507 80120300 8012030508 80120300 8012030509 80120300 8012030510 80120300 | 01 80/10/15 01 80/10/15 01 80/10/15 | FOIA FDIA 27-10 FOIA 27-10 | | 8012030570 8012030591 8012030593 8012030594 8012030595 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030511 80120300 8012030512 80120300 8012030513 80120300 8012030514 80120300 8012030515 80120300 | 01 80/10/15 01 80/10/15 01 80/10/15 | FOIA FOIA FOIA FOIA FOIA | | 8012030374 8012030577 8012030578 8012030400 8012030401 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA 27-10 | | |
| 8012030516 80120300 8012030517 80120300 8012030518 80120300 8012030519 30120300 8012030520 80120300 | 01 80/10/15 01 80/10/15 01 80/10/15 | FOIA FOIA 27-10 FOIA FOIA | | 8012030602 8012030603 8012030605 8012030606 8012030607 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030521 80120300 8012030522 80120300 8012030523 80120300 8012030524 80120300 8012030525 80120300 | 01 80/10/15 01 80/10/15 01 80/10/15 | FOIA FOIA FOIA FOIA | | 8012030608 8012030607 8012030611 8012030612 8012030614 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030526 801203000 8012030527 801203000 8012030528 801203000 8012030529 801203000 8012030530 801203000 | 01 60/10/15 01 60/10/15 01 60/10/15 | FOIA FOIA FOIA FOIA FOIA | | 8012030615 8012030616 8012030618 8012030619 8012030621 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030531 801203000 8012030532 801203000 8012030533 801203000 8012030534 801203000 8012030535 801203000 | 01 80/10/15 01 80/10/15 01 80/10/15 | FOIA FOIA FOIA FOIA | | 8012030622 8012030623 8012030625 8012030627 8012030628 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030534 801203000 8012030537 801203000 8012030538 801203000 8012030540 801203000 | 01 80/10/15 01 80/10/15 01 80/10/15 | FGIA FGIA FGIA FGIA | | 8012030629 8012030631 8012030632 8012030633 8012030635 | 8012930001 8012930001 8012930001 8012930001 8012930001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA | | |
| 8012030541 801203000 8012030542 801203000 8012030543 801203000 8012030544 801203000 8012030545 801203000 | 01 80/10/15 01 80/10/15 01 80/10/15 | FOIA FOIA FOIA FOIA FOIA | | 8012030637 8012030639 8012030640 8012030641 8012030643 | 8012030001 8012030001 8012030001 8012030638 8012030638 | 80/10/15 80/10/15 80/10/15 80/10/15 80/11/24 | FOIA FOIA FOIA 50-368 50-368 | 8 | |
| 8012030544 801203000 8012030547 801203000 8012030548 801203000 8012030549 801203000 8012030550 801203000 | 1 80/10/15 1 80/10/15 1 80/10/15 | FOIA FOIA FOIA FOIA FOIA | | 8012030644 8012030649 8012030646 8012030647 8012030648 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | | |

| ACCEBBION | NUMBER | | | | CESSION NUMBER | | | |
|--|--|--|--|---|--|--|--|--|
| ENGLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLO | PRINCIPAL | DATE ISSUED | BUBJECT CATEGORY | |
| 8012030649 8012030650 8012030651 8012030653 8012030654 | 8012030001 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | 80120 80120 80120 80120 80120 | 40237 8012040228 40247 8012040234 40257 8012040235 40257 8012040255 | 80/11/17 80/11/21 80/10/31 80/10/31 80/11/18 | TOPREP 50-461 Q 50-331 Q 50-331 Q 50-295 Q | |
| 8012030454 8012030457 8012030457 8012030440 8012030661 | 8012030001 8012030001 8012030652 8012030001 8012030001 | 80/10/15 80/10/15 80/11/24 80/10/15 80/10/15 | FOIA FOIA 50-334 8 FOIA FOIA | 80120 80120 80120 80120 80120 | 40302 8012040299 40303 8012040294 40308 8012040304 | 80/11/17 80/11/20 80/11/18 80/12/01 80/10/29 | 50-437 H 50-305 Q 50-483 Q 50-280 R 50-397 Q | |
| 8012030662 8012030664 8012030667 8012030668 8012030670 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA FOIA FOIA FOIA | 80120 80120 80120 80120 80120 | 40319 8012040313 40325 8012040320 40329 8012040323 | 80/10/24 80/10/24 80/11/06 80/10/27 80/11/21 | 50-206 Q 50-206 Q 50-315 P 50-361 Q 100FR | |
| 8012030672 8012030673 8012030674 8012030676 8012030677 | 8012030001 8012030001 8012030669 8012030001 8012030001 | 80/10/15 80/10/15 80/11/26 80/10/15 80/10/15 | FOIA FOIA 50-327 8 FOIA FOIA | 80120 80120 80120 80120 80120 | 40337 6012040324 40339 8012040336 40342 8012040324 | 80/11/14 80/11/21 80/10/23 80/11/21 80/11/20 | 50-10 8 100FR 50-312 0 100FR 50-546 0 | |
| 8012030678 8012030681 8012030682 8012030683 8012030684 | 8012030001 8012030679 8012030001 8012030001 8012030679 | 80/10/15 80/12/01 80/10/15 80/10/15 80/12/01 | F01A 50-261 P F01A F01A 50-261 P | 80120 80120 80120 80120 80120 | 40349 8012040334 40358 8012040353 40364 8012040353 | 80/11/21 80/11/05 60/11/14 80/11/14 | 10CFR PR 50-282 P 50-282 P 50-282 P | |
| 8012030465 8012030468 8012030487 8012030472 8012030493 | 8012030001 8012030001 8012030001 8012030001 | 80/10/15 80/10/15 80/10/15 80/10/15 80/10/15 | FOIA FOIA 27-39 FOIA FOIA | 80120 80120 80120 80120 | 40396 B012040395 40396 B012040392 40397 B012040393 | 00/11/17 10/21/08 10/21/08 10/21/08 | CONTRACT 50-346 8 50-327 8 50-277 P 50-327 F | |
| 8012030496 8012030708 8012030713 8012030714 8012030717 | 8012030001 8012030701 8012030706 8012030701 8012030709 | 80/10/13 80/11/12 80/11/10 60/11/12 60/11/26 | FOIA XPORTLIC 50-298 B XPORTLIC 50-280 B | 80120 80120 80120 80120 80120 | 40410 8012040362 40486 8012040481 40492 8012040483 | 80/12/02 80/10/16 80/11/26 80/10/20 80/10/02 | 50-267 P 50-201 R 50-373 A 70-754 70-1062 | |
| 8012030719 8012030723 8012030729 8012030733 8012030749 | 8012030701 8012030720 8012030716 8012030731 8012030762 | 60/11/12 80/12/01 80/12/01 80/12/01 80/11/17 | XPORTLIC 50-201 8 50-206 P 50-318 B 50-320 U | 80120 80120 80120 80120 80120 | 40590 8012040575 40592 8012040577 40598 8012040589 | 90/11/24 80/11/17 90/10/29 90/11/14 80/11/13 | 50-320 T 71-6679 50-220 G 50-315 F CONTRACT | |
| 8012030781 8012030797 8012030801 8012030803 8012030808 | 8012030774 8012030792 8012030792 8012030792 8012030792 | 80/11/18 80/11/04 80/11/04 80/11/04 80/11/04 | 50-289 H COMMISSION COMMISSION COMMISSION COMMISSION | 80120 80120 80120 80120 80120 | 40679 8012040677 40688 8012040682 40698 8012040691 | 80/11/20 80/09/26 80/10/24 80/10/02 80/12/01 | 50-483 G 50-508 G 50-341 G 50-316 G 50-3 F | |
| 8012030827 8012030833 8012030854 8012030856 8012030859 | 8012030814 8012030001 8012030817 8012030853 8012030850 | 80/11/19 80/10/15 80/11/19 80/10/27 80/11/10 | 50-320 U 27-10 50-10 P 50-320 H MISC | 80120 80120 80120 | 50002 8012050001 50005 8012050001 50009 8012050001 | 80/12/01 80/10/17 80/10/17 80/10/17 80/11/07 | 50-3 F ORO ORO ORO State Prog | |
| 8012030843 8012030877 8012030879 8012030882 8012030883 | 8012030858 8012030875 8012030875 8012030874 8012030875 | 80/10/30 80/11/17 80/11/17 80/11/21 80/11/17 | 71-5769 REVIEW GRP REVIEW GRP FOIA REVIEW GRP | 80120 80120 80120 80120 80120 | 50046 8012050059 50073 8012050053 50133 8012050124 | 80/11/14 80/11/14 80/11/14 80/11/12 80/12/03 | 8ECY BECY BECY 71-35 50-70 P | |
| 8012030884 8012030885 8012030887 8012030890 8012030905 | 8012030872 8012030875 8012030872 8012030879 8012030902 | 80/11/17 80/11/17 80/11/19 80/11/17 80/10/28 | 50-213 F REVIEW ORP 50-213 F REVIEW ORP REVIEW ORP | | 50225 8012050213 | 80/10/17 80/10/17 80/12/02 80/11/26 80/11/26 | 71-5362 71-5362 50-261 P 50-369 A 50-369 A | |
| 8012030910 8012030925 8012030927 8012030926 8012030930 | 8012030902 8012030917 8012030917 8012030924 8012030917 | 80/10/28 80/10/30 80/10/30 80/09/23 80/10/30 | REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP | 80120 80120 80120 | 50378 8012050364 50385 8012050382 50378 8012050390 | 80/12/02 80/12/02 80/11/28 80/12/01 80/11/26 | 50-280 8 50-280 8 50-272 8 50-29 8 50-466 0 | |
| 8012040022 8012040023 8012040039 8012040064 8012040068 | 8012040008 8012040013 8012040032 8012040057 8012040057 | 80/11/14 80/10/20 80/10/24 80/11/20 80/11/20 | 50-369 H GA999 50-498 G 50-295 G | 80120 80120 80120 | 50416 8012050413 50419 8012050408 | 80/11/26 80/11/28 80/11/28 80/11/26 80/12/02 | 50-466 0 50-334 8 50-334 8 50-267 8 50-261 8 | |
| 8012040088 8012040100 8012040115 8012040140 8012040155 | B012040065 B012040093 B012040093 B012040133 B012040065 | 80/12/03 80/09/26 80/09/26 80/11/14 80/12/03 | 50-245 F 50-346 Q 50-346 Q CONTRACT 50-245 F | 80120 80120 | 50444 8012050491 50470 8012050452 50474 8012050462 50485 8012050462 50488 8012050482 | 80/12/02 80/11/26 80/11/28 80/11/28 | 50-333 B 50-335 B PR PR PROJ | |
| 8012040179 8012040176 8012040179 8012040191 8012040205 | 8012040162 8012040169 8012040166 8012040162 8012040162 | 80/11/06 80/11/18 80/10/14 80/11/06 80/11/06 | 50-574 A 50-320 H 70-1308 50-574 A 50-219 Q | 80150 80150 80150 | 50492 8012050482 50493 8012050462 50494 8012050482 50523 8012050517 50530 8012050501 | 80/11/28 80/11/28 80/11/28 80/11/28 80/11/06 | PROJ PR PROJ 50-313 R 50-320 P | |
| | | | | | | | | |

| ACCESSION NUMBER | | | | | ACCESSION NUMBER | | | | | |
|--|--|--|---|-----------------------|------------------|--|--|--|--|--|
| ENGLOSURE | PRINCIPAL DOCUMENT | DATE 188UED | CATEGOR | | | ENCL OSURE | PRINCIPAL DOCUMENT | DATE 188UED | SUBJECT CATEGORY | |
| 8012050535 8012050540 8012050542 8012050584 8012050631 | 8012050501 8012050536 8012050536 8012050564 8012050627 | 80/11/06 80/12/01 80/12/01 80/10/01 80/11/19 | 50-320 50-458 50-458 70-2936 XPORTLIC | P F F | | 8012080439 8012080440 8012080450 8012080459 8012080464 | 8012080434 8012080006 8012080444 8012080455 8012080460 | 80/11/26 80/12/01 80/11/28 80/12/03 80/12/03 | 50-334 8 50-443 F 50-247 8 50-333 8 50-255 P | |
| 8012050642 8012050651 8012080007 8012080012 8012080034 | 8012080028 8012080006 8012080006 8012080008 | 80/12/01 80/12/01 80/12/01 80/12/01 60/11/20 | 50-266 50-266 50-443 50-443 71-399 | FFF | | 8012080482 8012080487 8012080491 8012080495 8012080498 | 8012080479 8012080485 8012080485 8012080489 8012080496 | 80/12/03 80/12/02 80/12/02 80/11/26 80/11/19 | 50-261 P 50-184 P 50-184 P 50-407 P CONTRACT | |
| 8012080035 8012080049 8012080053 8012080059 8012080060 | 8012080027 8012080045 8012080048 8012080048 8012080045 | 80/10/30 80/03/01 80/11/13 80/11/13 80/08/01 | 50-454 50-443 50-298 50-298 50-443 | 0 P P | | 8012080503 8012080505 8012080510 8012080512 8012080516 | 8012080501 8012080504 8012080508 8012080508 8012080612 | 80/11/25 80/11/26 80/12/03 80/12/03 80/12/01 | CONTRACT CONTRACT 50-170 R 50-170 R 70-2909 | |
| 8012080082 8012080095 8012080099 8012080102 8012080104 | 8012080072 8012080087 8012080072 8012080087 8012080097 | 80/10/22 80/11/12 80/10/09 80/11/12 80/11/25 | 50-438 50-237 50-244 50-237 XPORTLIC | 0 P 0 P | | 8012080522 8012080523 8012080527 8012080539 8012080537 | 8012080612 8012080520 8012080525 8012080527 8012080533 | 80/12/01 80/12/05 80/12/04 80/11/13 80/10/29 | 70-2709 50-358 K 50-255 P 50-213 0 50-10 G | |
| 8012080106 8012080115 8012080118 8012080122 8012080123 | 8012080089 8012080108 8012080103 8012080114 8012080120 | 80/11/12 80/10/10 80/12/02 80/10/28 80/10/09 | 50-237 50-387 FOIA 50-272 50-387 | Р Q Q | | 8012080538 8012080544 8012080550 8012080551 8012080555 | 8012080535 8012080535 8012080545 8012080535 8012080535 | 80/11/17 80/11/17 80/12/01 80/11/17 | 50-302 P 50-302 P 50-327 F 50-302 P | |
| 8012080131 8012080165 8012080174 8012080179 8012080183 | 8012080114 8012080141 8012080141 8012080141 8012080161 | 80/10/28 80/11/26 80/11/26 80/11/26 80/11/26 | 50-272 FOIA FOIA FOIA FOIA | a | | 8012080556 8012080563 8012080573 8012080578 8012080582 | 8012080545 8012080545 8012080377 8012080377 8012080377 | 80/12/01 80/12/01 80/11/17 80/11/17 | 50-327 F 50-327 F 50-273 P 50-273 P 50-273 P | |
| 8012080184 8012080187 8012080195 8012080220 8012080223 | 8012080114 8012080114 8012080116 8012080213 8012080213 | 80/10/28 80/10/28 80/10/28 80/12/05 80/12/05 | 50-272 50-272 50-272 50-250 50-250 | 0 0 0 F F | | 8012080593 8012080598 8012080602 8012080606 8012080615 | 8012080587 8012080587 8012080571 8012080572 8012080592 | 80/11/18 80/11/18 80/11/13 80/11/24 80/11/24 | 50-3 P 50-3 P CONTRACT 50-416 F 50-416 F | |
| 8012080234 8012080244 8012080250 8012080254 8012080254 | 8012080227 8012080238 8012080238 8012080232 | 80/11/21 80/11/25 80/11/25 80/11/25 80/10/17 | 50-250 GAPPP GAPPP GAPPP GAPPP | Q | | 8012080620 8012080623 8012080630 8012080631 8012080635 | 8012080592 8012080585 8012080627 8012080626 8012080592 | 80/11/26 80/11/25 80/11/14 80/11/18 80/11/26 | 50-416 F CONTRACT 50-155 F 71-5957 50-416 F | |
| 8012080257 8012080260 8012080265 8012080267 8012080268 | 8012080238 8012080238 8012080238 8012080243 8012080238 | 80/11/23 80/11/25 80/11/25 80/11/17 80/11/25 | 96940 96940 96940 96940 96940 | | | 8012080641 8012080646 8012080649 8012080656 8012080664 | 8012080636 8012080592 8012080645 8012080645 8012080661 | 80/11/28 80/11/26 80/11/14 80/11/14 80/11/07 | CONTRACT 50-416 F 50-369 G 50-369 G 40-1341 | |
| 8012080272 8012080275 8012080282 8012080284 8012080291 | 8012080263 8012080263 8012080263 8012080279 8012080287 | 80/11/17 80/11/17 80/11/17 80/10/30 80/11/19 | GA777 GA777 GA777 50-454 GA777 | a | 1 | 8012080668 8012080678 8012080679 8012080684 8012080693 | 8012080660 8012080660 8012080660 8012080660 | 80/11/25 80/11/25 80/10/17 80/11/25 80/11/25 | 50-518 Q 50-518 Q 40-1341 50-518 Q 50-518 Q | |
| 8012080275 8012080297 8012080300 8012080301 8012080304 | 8012080290 8012080287 8012080287 8012080290 8012080290 | 80/11/12 80/11/17 80/11/17 80/11/12 80/11/12 | 50-260 QA999 GA999 50-260 50-260 | P P | | 8012080721 8012080727 8012080735 8012080742 8012080757 | 8012080713 8012080713 8012080720 8012080720 8012080720 | 80/11/28 80/11/28 80/10/30 80/10/30 80/10/30 | 50-416 F 50-416 F 40-8106 40-8106 40-8106 | |
| 8012080307 8012080322 8012080323 8012080324 8012080329 | 8012080287 8012080313 8012080319 8012080313 8012080319 | 90/11/19 90/11/10 90/12/02 90/11/10 90/12/02 | QA999 50-271 50-282 50-271 50-282 | P P P | | 8012080770 8012080774 8012080778 8012080779 8012080773 | 8012080765 8012080765 8012080765 8012080767 8012080791 | 80/11/19 80/09/29 80/11/19 80/09/29 80/10/15 | BECY 70-754 BECY 70-754 70-33 | |
| 8012080331 8012080336 8012080347 8012080387 8012080360 | 8012080313 8012080320 8012080342 8012080354 8012080353 | 80/11/10 80/11/21 80/11/28 80/12/03 80/12/01 | 50-271 50-482 50-319 50-255 50-263 | PAGPF | | 8012080798 8012080899 8012080812 8012080819 8012080822 | 8012080788 8012080800 8012080807 8012080817 8012080816 | 80/10/01 80/11/17 80/11/13 80/10/17 80/12/03 | 40-8084 XPORTLIC CONTRACT 71-395 50-320 H | |
| 8012080363 8012080364 8012080365 8012080368 8012080370 | 8012080358 8012080358 8012080358 8012080358 | 80/10/30 80/12/01 80/12/03 80/10/30 80/10/30 | 50-367 50-243 50-155 50-387 50-387 | G F G G | | 8012080825 8012080834 8012090011 8012090018 8012090026 | 8012080823 8012080829 8012070005 8012070014 8012070023 | 80/10/03 80/10/23 80/11/20 80/11/22 80/11/25 | 40-8084 50-313 Q 50-275 H NUREG MISC | |
| 8012080378 8012080370 8012080373 8012080375 8012080376 | 8012080358 8012080384 8012080384 8012080389 8012080384 | 80/10/30 80/10/28 80/10/28 80/11/13 80/10/28 | 50-387 50-387 50-387 50-298 50-387 | 9 9 9 9 | | 8012070027 8012070031 8012070032 8012070035 8012070036 | 8012070022 8012070025 8012070028 8012070025 8012070034 | 80/11/05 80/11/21 80/11/26 80/11/21 80/11/13 | 50-206 Q 50-124 P ORG 50-124 P 50-275 Q | |
| B012080403 B012080404 B012080417 B012080430 B012080439 | 8012080389 8012080384 8012080409 8012080423 8012080415 | 80/11/13 80/10/26 80/12/01 80/11/28 80/11/20 | 50-298 50-387 50-293 50-327 50-275 | P Q B B H | | 8012070045 8012070050 8012070051 8012070054 8012070057 | 8012070039 8012070048 8012070048 8012070048 8012070048 | 80/10/03 80/11/12 80/11/12 80/11/12 | 50-254 Q QA999 QA999 QA999 QA999 | |

| ACCESSION NUMBER | | | | | ACCESSION NUMBER | | | | |
|--|--|--|---|-----------------------|---|--|--|--|--|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGOR | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE | SUBJECT CATEGORY | |
| 8012040039 8012040062 8012040063 8012040074 8012040074 | 8012070048 8012070048 8012070048 8012070070 8012070070 | E0/11/12 80/11/12 80/11/12 80/10/23 | 0A999 0A999 0A999 50-29 50-29 | G Q | 901209039B 8012090402 9801209040B 8012090409 8012090413 | 8012070370 8012070376 8012070401 8012070405 8012070406 | 80/12/03 80/12/03 80/12/03 80/12/03 90/11/18 | 50-312 8 50-306 9 50-339 8 50-261 P COMMIGEION | |
| 8012070077 8012070081 8012070083 8012070084 8012070070 | 8012070047 8012070070 8012070047 8012070070 8012070087 | 60/10/29 60/10/23 60/10/29 60/10/23 60/10/31 | 70-135 50-29 70-135 50-29 50-344 | 0 0 0 | 8012070418 8012070422 8012070428 8012070428 8012070429 | 8012090407 8012090406 8012090419 8012090420 8012090419 | 80/11/20 80/11/18 80/12/05 80/12/03 80/12/05 | 50-245 8 CBMMI68ION 50-155 P 50-348 8 50-155 P | |
| 8012070093 8012070095 8012070110 8012070113 8012070115 | 8012070067 8012070087 8012070106 8012070107 8012070106 | 80/10/29 80/10/31 80/11/19 80/12/08 80/11/19 | 70-135 50-344 50-313 50-348 50-313 | Q P F P | B012070434 B012070443 B012070444 B012070445 B012070445 | 8012070423 8012070423 8012070433 8012070431 8012070423 | 80/12/05 80/12/05 80/11/24 80/11/25 90/12/05 | 50-29 P 50-29 P 50-304 8 50-313 8 50-29 P | |
| 8012070118 8012070119 8012070125 8012070130 8012070142 | 8012090107 8012090107 8012090107 8012090107 8012090135 | 80/11/52 80/12/08 80/12/08 80/12/08 | 50-348 50-348 50-348 50-348 50-438 | F F G | 8012070452 8012070458 8012070462 8012070463 8012070463 | 8012090446 8012090451 8012090457 8012090453 8012090464 | 80/11/24 80/11/24 80/12/05 80/12/03 80/11/26 | 50-265 8 50-265 8 50-261 8 50-369 8 50-277 8 | |
| 8012090143 8012090145 8012090144 8012090152 8012090153 | 8012070137 8012070138 8012070135 8012070135 8012070147 | 80/10/15 80/10/24 80/11/25 60/11/25 60/10/28 | 70-1257 50-440 50-438 50-438 50-333 | Q Q Q | 8012070471 8012070473 8012070474 8012070510 8012070517 | 8012070466 8012070461 8012070468 8012070505 8012070513 | 80/12/02 80/11/26 80/11/25 80/10/22 80/10/22 | 50-219 8 50-295 8 50-155 F 50-416 Q 50-321 Q | |
| 8012090154 8012090158 8012090163 8012090165 8012090167 | 8012070135 8012070147 8012070147 8012070162 8012070147 | 80/11/28 80/10/28 80/10/28 80/11/25 80/10/28 | 50-438 50-333 50-333 70-1151 50-333 | 0 | 8012070524 8012070545 8012070573 8012070573 8012100007 | 8012070520 8012070540 8012070554 8012070570 8012100004 | 80/10/23 80/10/09 80/12/01 80/12/01 80/12/03 | 50-424 Q 50-272 Q CONTRACT CONTRACT CONTRACT | |
| 8012090169 8012090176 8012090185 8012090195 8012090197 | 8012070162 8012070162 8012070142 8012070170 8012070171 | 80/11/25 80/11/25 80/11/25 80/12/01 80/10/23 | 70-1151 70-1151 70-1151 50-271 50-395 | P | 9012100022 9012100053 8012100056 9012100056 9012100073 | 8012100017 8012100045 8012100051 8012100054 8012100065 | 80/12/01 80/11/14 80/11/17 80/11/18 80/11/25 | CONTRACT PR 50-312 G PR 50-313 P | |
| 8012090210 8012090212 8012090214 8012090217 8012090219 | 8012070201 8012070211 8012070202 8012070215 8012070216 | 80/10/21 80/12/03 80/12/08 80/12/08 80/10/24 | 50-261 50-302 50-361 50-344 50-395 | G P A P G | 8012100083 8012100087 8012100094 8012100094 8012100096 | 8012100077 8012100077 8012100077 8012100077 8012100077 | 80/10/20 80/10/20 80/10/20 80/10/20 80/10/20 | 50-334 Q 50-334 Q 50-334 Q 50-334 Q ,50-334 Q | |
| 8012070225 8012070228 8012070232 8012070237 8012070240 | 8012070220 8012070222 8012070224 8012070224 8012070224 | 80/12/05 80/10/21 80/10/30 80/10/30 80/10/30 | 50-302 50-261 50-443 50-443 50-443 | P | 8012100125 8012100110 8012100121 8012100125 | 8012100077 8012100106 8012100106 8012100108 8012100108 | 80/10/20 80/11/17 80/11/17 60/11/26 80/11/26 | 50-334 Q 40-8064 40-8064 50-220 Q 50-220 Q | |
| 8012070242 8012070251 8012070253 8012070254 8012070258 | 8012070224 8012070247 8012070247 8012070247 8012070247 | 80/10/30 80/10/28 80/10/28 80/10/28 80/10/28 | 50-443 70-820 70-820 70-820 70-820 | a | 8012100131 8012100134 8012100147 8012100176 | 8012100123 8012100129 8012100140 8012100161 8012100167 | 80/11/30 80/11/05 80/11/07 80/12/01 80/09/25 | NUREO 50-344 Q 50-361 Q 50-142 Q 50-155 Q | |
| 8012070265 8012070266 8012070280 8012070282 8012070287 | 8012070264 8012070264 8012070278 8012070281 8012070286 | 80/12/05 80/11/21 80/12/01 80/12/02 80/12/04 | 50-450 COMMIGSI 50-244 50-247 50-275 | 0N 0P 0 | 8012100189 8012100209 8012100239 8012100234 8012100241 | 8012100183 8012100202 8012100224 8012100227 8012100227 | 80/12/03 90/11/14 80/12/05 80/10/23 80/10/23 | CONTRACT CONTRACT 50-333 Q 70-1143 70-1143 | |
| 0012070271 0012070273 0012070276 0012070276 0012070202 | 8012090277 8012090272 8012090294 8012090297 8012090295 | 80/12/04 80/12/05 80/12/01 80/12/05 80/12/01 | 50-318 50-29 50-331 50-463 50-397 | 400B | 8012100247 8012100264 8012100273 8012100277 8012100280 | 8012100227 8012100256 8012100256 8012100256 8012100256 | 80/10/23 80/10/24 80/10/24 80/10/24 80/10/24 | 70-1143 70-820 70-020 70-820 70-820 | |
| 8012090304 8012090308 8012090312 8012090314 8012090319 | 8012090301 8012090295 8012090311 8012090306 8012090315 | 80/12/05 80/12/01 80/12/05 80/11/25 80/12/04 | 50-29 50-397 50-327 50-301 50-338 | 8 8 8 | 8012100284 8012100328 8012100397 8012100392 8012100407 | 8012100254 8012100324 8012100332 8012100388 8012100404 | 80/10/24 80/12/05 80/12/05 80/10/01 80/09/18 | 70-820 50-303 R 50-267 R 50-397 G 50-335 8 | |
| 8012090321 8012090351 8012090354 8012090358 8012090364 | 8012070318 8012070350 8012070352 8012070355 8012070361 | 80/11/11 80/12/04 80/12/03 80/12/02 80/12/03 | 50-331 50-338 50-324 50-327 50-213 | 8 8 8 | 8012100417 8012100423 8012100432 8012100445 8012100432 | 8012100412 8012100420 8012100430 8012100444 8012100449 | 80/11/25 80/11/20 80/11/05 80/12/04 90/11/19 | CONTRACT CONTRACT 50-155 Q 50-267 P 50-325 8 | |
| 8012090365 8012090368 8012090377 8012090381 8012090384 | 8012070362 8012070366 8012070371 8012070376 8012070377 | 80/12/04 80/12/03 80/12/02 80/12/03 80/12/02 | 50-338 50-407 50-366 50-282 50-321 | 88888 | 8012100455 8012100458 8012100453 8012100463 8012100469 | 8012100453 8012100451 8012100456 8012100462 8012100466 | 60/12/04 60/12/04 60/12/04 60/11/25 60/12/05 | 50-324 8 50-320 P 50-324 8 50-334 8 50-270 8 | |
| 8012070387 8012070392 8012070394 8012070375 8012070377 | 8012070380 8012070389 8012070383 8012070388 8012070393 | 80/12/02 80/12/01 80/11/26 80/12/02 80/11/18 | 50-346 50-334 50-320 50-368 50-409 | 8888 | 8012100471 8012100475 8012100479 8012100481 8012100484 | 8012100464 8012100472 8012100476 8012100477 8012100480 | 80/12/05 80/12/02 80/09/15 80/11/24 80/11/21 | 50-449 Q 50-220 B 50-335 B 50-220 B 50-285 B | |
| | | | | | | | | | |

| ACCESSIO | | | | ACCE6910I | NUMBER | | |
|--|--|--|---|--|--|--|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE Daved | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE 198UED | SUBJECT CATEGORY |
| 8012100491 | 8012100485 | 80/12/05 | 50-247 8 | 8012110379 | 8012110354 | 80/11/19 | 71-5796 |
| 8012100499 | 8012100490 | 80/11/26 | 50-278 8 | 8012110381 | 8012110374 | 80/11/26 | 50-596 A |
| 8012100501 | 8012100497 | 80/12/03 | 50-259 8 | 8012110382 | 8012110373 | 80/11/26 | CONTRACT |
| 8012100506 | 8012100497 | 80/12/03 | 50-259 8 | 8012110391 | 8012110356 | 80/11/19 | 71-5796 |
| 8012100509 | 8012100503 | 80/12/05 | 50-267 8 | 8012110393 | 8012110378 | 80/12/05 | 50-281 S |
| 8012100510 | B012100497 | 80/12/03 | 50-257 9 | 8012110398 | 8012110378 | 80/12/05 | 50-281 B |
| 8012100513 | B012100497 | 80/12/03 | 50-259 8 | 8012110409 | 8012110403 | 80/12/05 | 50-272 B |
| 8012100520 | B012100516 | 80/08/08 | 50-349 8 | 8012110417 | 8012110410 | 80/12/03 | 50-289 0 |
| 8012100521 | B012100515 | 80/12/05 | 50-267 8 | 8012110439 | 8012110435 | 80/11/18 | 50-204 P |
| 8012100526 | B012100517 | 80/12/04 | 50-348 8 | 8012110445 | 8012110438 | 80/12/05 | FOIA |
| 8012100528 | 8012100522 | 80/09/11 | 50-335 8 | 8012110452 | 8012110438 | 80/12/05 | FOIA |
| 8012100534 | 8012100523 | 80/12/03 | 50-260 8 | 8012110460 | 8012110438 | 80/12/05 | FOIA |
| 8012100535 | 8012100529 | 80/11/28 | 50-409 8 | 8012110461 | 8012110454 | 80/11/24 | 50-320 T |
| 8012100537 | 8012100524 | 80/12/05 | 50-267 8 | 8012110465 | 8012110438 | 80/12/05 | FOIA |
| 8012100538 | 8012100532 | 80/09/12 | 50-335 8 | 8012110471 | 8012110438 | 80/12/05 | FOIA |
| 8012100539 8012100540 8012100542 8012100547 8012100550 | 8012100534 8012100530 8012100534 8012100530 8012100544 | 80/12/09 80/11/28 80/12/09 80/11/28 80/11/05 | 50-361 A 50-409 B 50-341 A 50-409 B 50-449 G | 8012110478 8012110481 8012110484 8012110488 8012110502 | 8012110467 8012110467 8012110467 8012110467 8012110500 | 80/12/01 80/12/01 80/12/01 80/12/01 | 70-143 70-143 70-143 70-143 50-320 T |
| 8012100557 | 8012100553 | 80/12/01 | 50-319 8 | 8012110506 | 8012110504 | 80/10/08 | 71-400 |
| 8012100560 | 8012100555 | 80/12/04 | 50-368 8 | 801211050B | 8012110504 | 80/10/08 | 71-400 |
| 8012100562 | 8012100556 | 80/12/04 | 50-364 8 | 8012110527 | 8012110525 | 80/11/26 | CONTRACT |
| 8012100565 | 8012100559 | 80/12/05 | 50-317 8 | 801211052B | 8012110524 | 80/12/04 | 70-143 |
| 8012100566 | 8012100561 | 80/12/03 | 50-317 8 | 8012110530 | 8012110526 | 80/12/02 | 50-275 A |
| 8012100570 | 8012100563 | 80/11/24 | 50-337 8 | 8012110532 | 8012110529 | 80/11/26 | 50-321 G |
| 8012100372 | 8012100567 | 80/12/04 | 50-324 8 | 8012110533 | 8012110524 | 80/12/02 | 50-275 A |
| 8012100576 | 8012100573 | 80/12/01 | 50-293 8 | 8012110534 | 8012110529 | 80/11/26 | 50-321 G |
| 8012100582 | 8012100579 | 80/12/02 | 50-295 Q | 8012110537 | 8012110529 | 80/11/26 | 50-321 G |
| 8012100591 | 8012100589 | 80/11/04 | 50-10 Q | 8012110538 | 8012110535 | 80/12/05 | FOIA |
| 8012100597 | 8012100589 | 80/11/04 | 50-10 Q | 8012110539 | 8012110529 | 80/11/26 | 50-321 0 |
| 8012100635 | 8012100632 | 80/12/02 | 50-331 F | 8012110540 | 8012110556 | 80/12/05 | 50-389 8 |
| 8012100648 | 8012100664 | 80/11/26 | 50-320 U | 8012110591 | 4012110556 | 80/12/05 | 50-389 8 |
| 8012100672 | 8012100669 | 80/10/30 | 71-9147 | 8012110594 | 8012110589 | 80/10/08 | 50-322 0 |
| 8012100676 | 8012100670 | 80/11/28 | 70-143 | 8012110597 | 8012110589 | 80/10/08 | 50-322 0 |
| 8012100480 8012100484 8012110011 8012110015 | 8012100470 8012100470 8012100470 8012110004 8012110008 | 80/11/28 80/11/20 80/11/28 80/10/23 80/11/14 | 70-143 50-286 Q 70-143 50-461 Q 50-226 P | 8012110605 8012110607 8012110608 8012110609 8012110618 | 8012110598 8012110603 8012110602 8012110574 8012110613 | 80/10/06 80/10/07 80/12/01 80/10/28 80/11/12 | 50-410 G 50-387 G 50-10 G CDNTRACT 50-413 Q |
| 8012110016 | 8012110006 | 80/10/23 | 50-451 Q | 8012110620 | 9012110614 | 80/11/03 | 50-348 Q |
| 8012110024 | 8012110020 | 80/11/12 | XPORTLIC | 8012110623 | 9012110613 | 80/11/12 | 50-413 Q |
| 8012110043 | 8012110036 | 80/11/24 | COMMISSION | 8012110629 | 8012110626 | 80/11/03 | 50-250 Q |
| 8012110045 | 8012110041 | 80/10/21 | 50-440 Q | 8012110630 | 9012010621 | 80/11/25 | 50-483 Q |
| 8012110049 | 8012110041 | 80/10/21 | 50-440 Q | 8012110635 | 8012110628 | 80/10/08 | 70-1426 |
| 8012110053 | 8012110040 | 80/11/12 | CONTRACT | 8012110637 | 9012110633 | 80/10/30 | 50-375 Q |
| 8012110079 | 8012110074 | 80/10/10 | 50-412 0 | 8012110645 | 9012110641 | 80/11/05 | 50-282 Q |
| 8012110104 | 8012110082 | 80/10/07 | 50-217 0 | 8012110646 | 9012110636 | 80/10/30 | 50-341 Q |
| 8012110104 | 8012110100 | 80/11/28 | 70-1257 | 8012110656 | 9012110643 | 80/11/20 | FOIA |
| 8012110110 | 8012110104 | 80/10/21 | 50-358 0 | 8012110662 | 9012110643 | 80/11/20 | FOIA |
| 8012110124 8012110133 8012110137 8012110141 8012110144 | 8012110117 8012110127 8012110127 8012110127 8012110127 | 80/10/22 80/11/25 80/11/25 80/11/25 80/11/25 | 50-315 G 50-261 G 50-261 G 50-261 G | 8012110647 8012110648 8012110670 8012110675 8012110676 | 8012110458 8012110443 8012110459 8012110459 8012110464 | 80/11/25 80/11/20 80/12/05 80/12/05 80/11/24 | 50-482 A FDIA 50-375 A 50-375 A 50-413 G |
| 8012110157 | 8012110140 | 80/12/03 | FOIA | 8012110678 | 8012110643 | B0/11/20 | FOIA |
| 8012110158 | 8012110152 | 80/10/07 | 70-1143 | 8012110681 | 8012110674 | B0/11/21 | CONTRACT |
| 8012110161 | 8012110150 | 80/11/19 | COMMIBBION | 8012110682 | 8012110659 | B0/12/05 | 50-395 A |
| 8012110164 | 8012110140 | 80/12/03 | FOIA | 8012110683 | 8012110643 | B0/11/20 | FOIA |
| 8012110167 | 8012110150 | 80/11/19 | COMMIBBION | 8012110684 | 8012110666 | B0/11/24 | 50-413 Q |
| 8012110171 | 8012110163 | 80/10/07 | 70-33 | 8012110484 | 8012110659 | 80/12/05 | 50-395 A |
| 8012110213 | 8012110207 | 80/11/19 | 50-348 Q | 8012110489 | 8012110643 | 80/11/20 | FOIA |
| 8012110218 | 8012110200 | 80/11/26 | FOIA | 8012110492 | 8012110643 | 80/11/20 | FOIA |
| 8012110222 | 8012110207 | 80/11/18 | 50-348 Q | 8012110494 | 8012110688 | 80/10/24 | CONTRACT |
| 8012110223 | 8012110200 | 80/11/26 | FOIA | 8012110702 | 8012110643 | 80/11/20 | FOIA |
| 8012110231 8012110238 8012110239 8012110245 8012110246 | 8012110200 8012110200 8012110200 8012110228 | 80/11/26 80/11/26 80/11/28 80/11/26 80/11/28 | FOIA 50-416 Q FOIA 50-416 Q | 8012110703 8012110707 8012110709 8012110717 8012110723 | 8012110693 8012110643 8012110701 8012110643 8012110643 | 80/11/05 80/11/20 80/10/28 80/11/20 60/11/20 | 50-331 @ FOIA 50-364 @ FOIA FOIA |
| 8012110250 | 8012110228 | 80/11/28 | 50-416 0 | 8012110726 | 8012110718 | 80/11/21 | 50-20 P |
| 8012110252 | 8012110200 | 80/11/26 | FOIA | 8012110734 | 8012110718 | 80/11/21 | 50-20 P |
| 8012110257 | 8012110228 | 80/11/28 | 50-416 0 | 8012110735 | 8012110643 | 80/11/20 | FOIA |
| 8012110247 | 8012110254 | 80/12/03 | 50-295 P | 8012110739 | 8012110643 | 80/11/20 | FOIA |
| 8012110283 | 8012110274 | 80/12/02 | 50-237 P | 8012110747 | 8012110643 | 60/11/20 | FOIA |
| 8012110358 8012110359 8012110359 8012110328 | 8012110318 8012110346 8012110349 8012110358 8012110356 | 80/11/20 80/12/01 80/11/21 80/12/05 80/11/19 | COMMISSION 50-358 0 CONTRACT 50-295 R 71-5796 | 8012110753 8012110785 8012110764 8012110769 8012110779 | 8012110797 8012110643 8012110643 8012110763 8012110643 | 80/10/27 80/11/20 80/11/20 80/11/24 80/11/20 | 50-184 Q FOIA FOIA 50-331 Q FOIA |

| ACCESSION | NUMBER | | | ACCESS IO | NUMBER | | |
|--|--|--|--|--|--|--|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | EUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE 188UED | SUBJECT CATEGORY |
| 8012110777 8012110792 8012110784 8012110787 8012110792 | 8012110643 8012110643 8012110780 8012110643 8012110643 | 80/11/20 80/11/20 80/11/20 80/11/20 | FDIA FDIA 50-267 G FOIA FOIA | 8012120455 8012120457 8012130010 8012130015 6012150023 | 0012120648 8012120653 8012150006 8012150012 8012150022 | 80/11/04 80/11/25 80/12/09 80/12/03 80/11/26 | 50-142 0 50-320 H FOIA FOIA 50-320 H |
| 8012110794 8012110806 8012110810 8012110812 | 8012110768 8012110643 8012110643 8012110643 8012110608 | 80/11/28 80/11/20 80/11/20 80/11/20 60/11/19 | 50-150 Q FOIA FOIA FOIA 50-245 P | 8012150028 8012150030 8012150047 8012150051 8012150054 | 8012150026 8012150026 8012150046 8012150048 8012150052 | 90/11/07 90/11/07 90/12/05 90/12/11 80/12/05 | 50-247 T 50-247 T 50-193 R 50-263 R 50-237 P |
| 8012110816 8012110817 8012110818 8012110819 8012110822 | 8012110643 8012110808 8012110643 8012110808 8012110643 | 80/11/20 80/11/19 80/11/20 80/11/19 80/11/20 | FOIA 50-245 P FOIA 50-245 P FOIA | 8012150055 8012150057 8012150067 8012150074 8012150081 | 8012180053 8012180055 8012180348 8012180073 8012150079 | 80/12/08 80/12/02 80/12/03 80/12/04 80/12/03 | 50-346 R 50-344 R 50-322 H 50-400 R 50-298 R |
| 8012110828 8012110831 8012110832 8012110843 8012110846 | 8012110826 8012110826 8012110826 8012110643 8012110643 | 80/11/17 80/11/17 80/11/17 80/11/20 80/11/20 | 50-285 P 50-285 P 50-285 P FOIA FOIA | 8012130085 8012130089 8012130090 8012130092 8012130094 | 8012150085 8012150087 8012150089 8012150091 8012150093 | 80/12/08 80/12/09 80/12/09 80/12/05 80/12/02 | 50-324 R 50-368 8 50-368 8 50-293 8 50-304 8 |
| 8012110847 8012110848 8012110849 8012110851 8012110853 | 8012110840 8012110643 8012110643 8012110643 8012110643 | 80/10/27 80/11/20 80/11/20 80/11/20 80/11/20 | 50-51B Q FDIA FDIA FDIA FDIA | 8012130096 8012130098 8012130101 8012130108 8012130110 | 8012150095 8012150097 8012150097 8012150107 8012150107 | 80/12/02 80/12/01 80/12/01 80/12/11 80/12/11 | 50-447 B 50-368 P 50-368 P 50-327 P 50-327 P |
| 8012110854 8012120020 8012120025 8012120028 8012120081 | 8012110643 8012120012 8012120012 8012120012 8012120075 | 80/11/20 80/11/15 80/11/15 80/11/15 80/10/23 | FOIA 50-334 P 50-334 P 50-334 P 50-170 H | 8012150111 8012150112 8012150113 8012150114 8012150118 | 8012150107 8012150107 8012150107 8012150107 8012150116 | 80/12/11 80/12/11 80/12/11 80/12/11 80/12/10 | 50-327 P 50-327 P 50-327 P 50-327 P 50-346 8 |
| 8012120082 8012120212 8012120231 8012120237 8012120238 | 8012120074 8012120203 8012120224 8012120224 8012120229 | 80/11/19 80/11/20 80/10/31 80/10/31 80/11/25 | CONTRACT 50-275 H 50-313 0 50-313 0 50-369 A | 8012150120 8012150123 8012150124 8012150130 8012150130 | 8012150117 8012150117 8012150121 8012150127 8012150132 | 80/11/19 80/11/19 80/12/09 80/12/05 80/12/11 | 50-245 Q 50-245 Q 50-272 B 50-333 \$ 50-286 8 |
| 8012120241 8012120243 8012120253 8012120246 8012120272 | 8012120225 8012120235 8012120248 8012120260 8012120260 | 80/12/05 80/11/20 80/10/17 80/11/21 80/11/21 | 50-409 P 8tate Prog 50-312 0 50-312 P 50-312 P | 8012150140 8012150170 8012150171 8012150176 8012150178 | 8012150138 8012150165 8012150168 8012150173 8012150175 | 80/12/10 80/12/09 80/12/11 80/12/04 80/12/10 | 50-247 0 50-327 8 50-346 8 50-339 8 50-289 0 |
| 8012120278 8012120293 8012120300 8012120311 8012120326 | 8012120260 8012120287 8012120287 8012120305 8012120305 | 80/11/21 80/10/20 80/10/20 80/10/20 80/10/20 | 50-312 P 50-483 Q 50-483 Q 50-313 Q | 8012150187 8012150188 8012150195 8012150196 8012150197 | 8012150184 8012150185 8012150189 8012150194 8012150191 | 80/12/05 80/12/08 90/12/05 30/11/18 80/12/11 | 50-366 8 50-320 8 50-346 9 50-364 P 50-282 8 |
| 8012120341 8012120347 8012120366 8012120369 8012120373 | 8012120301 8012120344 8012120354 8012120354 8012120365 | 80/12/10 80/10/21 80/11/14 80/11/14 80/11/26 | 50-237 P 70-27 50-566 G 50-566 Q 50-247 T | 8012150218 8012150220 8012150225 8012150228 6012150229 | 8012150211 8012150216 8012150216 8012150223 8012150222 | 80/12/02 80/12/05 80/12/05 80/11/26 80/12/11 | 50-295 8 50-322 K 50-322 K 50-456 Q 50-261 8 |
| 8012120377 8012120382 8012120398 8012120405 8012120407 | 8012120354 8012120378 8012120370 8012120370 8012120369 | 80/11/14 80/10/08 80/10/07 80/10/07 80/11/24 | 50-564 0 40-6622 40-8348 40-8348 50-305 0 | 8012150249 8012150254 8012150256 8012150258 8012150259 | 8012150241 8012150250 8012150251 8012150255 8012150255 | 80/12/10 80/11/25 80/12/08 80/11/14 80/11/14 | 50-443 0 50-265 8 50-324 8 50-389 0 50-389 0 |
| 8012120413 8012120425 8012120426 8012120434 8012120477 | 8012120379 8012120415 8012120399 8012120399 8012120466 | 80/12/10 80/11/24 80/12/10 80/12/10 80/12/05 | 50-206 P 50-254 Q 50-206 P 50-204 P 50-259 B | 8012150263 8012150267 8012150269 8012150277 8012150281 | 8012150255 8012150264 8012150265 8012150273 8012150278 | 80/11/14 80/12/09 80/11/06 80/12/10 80/12/04 | 50-387 Q 50-305 P 50-331 Q 50-334 R 50-266 Q |
| 8012120484 8012120476 8012120506 8012120512 | 8012120480 8012120470 8012120502 8012120501 8012120510 | 80/12/04 80/12/01 80/12/09 80/12/01 80/12/09 | 50-312 R 50-346 6 50-259 8 50-346 8 50-259 8 | 8012150284 8012150284 8012160009 8012160012 8012160018 | 6012150282 8012150285 8012160004 8012160004 8012160013 | 80/12/08 80/12/05 80/12/07 80/12/09 80/11/19 | 50-286 Q 50-155 P Foia Foia Contract |
| 8012120517 8012120528 8012120539 8012120533 8012120533 | 8012120522 8012120522 8012120522 8012120522 | 80/12/05 80/11/19 90/12/05 80/11/19 80/12/05 | 50-294 8 50-334 P 50-334 8 50-334 P 50-334 8 | 8012140035 8012140041 8012140090 8012140093 8012140097 | 8012160027 8012160038 8012160082 8012160082 8012160082 | 80/11/03 80/10/30 80/11/26 80/11/26 80/11/26 | 50-416 Q 50-302 Q 50-10 Q 50-10 Q 50-10 Q |
| 8012120545 8012120560 8012120562 8012120570 8012120575 | 8012120539 8012120546 8012120559 8012120567 8012120573 | 80/12/05 80/10/16 80/11/25 90/10/23 90/11/14 | 50-334 8 XPORTLIC 50-112 0 50-285 0 50-302 0 | 8012140105 8012140108 8012140110 8012140113 8012140117 | 8012160082 8012160082 8012160107 8012160082 8012160082 | 80/11/26 80/11/26 80/11/26 80/11/26 | 50-277 Q 50-277 Q 50-83 I 50-277 Q 50-277 Q |
| 8012120577 8012120580 8012120584 8012120603 8012120610 | 8012120573 8012120579 8012120579 8012120546 8011210440 | 80/11/14 80/11/14 90/11/14 80/10/16 80/10/31 | 50-302 0 50-335 0 50-335 0 XPORTLIC 50-269 0 | 8012160134 6012160147 9012160152 8012160154 8012160165 | 8012160128 8012160149 8012160144 8012160162 | 80/12/11 80/10/31 80/12/05 80/11/26 80/12/12 | 50-397 I 50-3 P 50-566 R 50-219 G 50-395 A |
| | | | | | 1 | the second control of | |

| ACCEGBIO | | | | | ACCEBSIO | N NUMBER | | | |
|--|--|--|--|-----------------------|--|--|--|---|-----------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE 198UED | SUBJEC CATEOD | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE 18SUED | BUBJECT CATEGOR | |
| 8012160192 8012160221 8012160256 8012160258 8012160260 | 8012160174 8012160216 8012160242 8012160253 8012160255 | 80/12/04 80/12/04 80/12/03 80/12/01 80/11/28 | 50-315 70-143 50-261 50-320 50-206 | Q H P | 8012160616 8012160625 8012160644 8012160717 8012160750 | 8012160605 8012160620 8012160639 8012160639 8012160730 | 80/02/13 80/12/02 80/11/28 80/11/28 | ACR8 8tate Pr 50-389 50-389 50-518 | 0 |
| 8012160272 8012160276 8012160286 8012160309 8012160321 | 9012160267 9012160267 9012160280 9012160304 9012160317 | 80/12/05 80/12/05 80/12/09 80/10/09 80/12/10 | 50-277 50-277 50-409 50-289 50-259 | R R R Q R | 8012160766 8012160767 8012170021 8012170028 8012170031 | 8012160763 8012160764 8012170013 8012170013 8012170023 | 80/11/17 80/11/10 80/12/05 80/12/05 80/12/04 | 40-3453 40-8743 50-280 50-280 50-338 | a a |
| 8012160333 8012160338 8012160343 8012160351 8012160359 | 8012160330 8012160335 8012160340 8012160345 8012160350 | 90/12/10 90/12/09 90/12/11 90/12/09 90/12/04 | 50-327 50-206 50-311 50-348 50-409 | R R B P | 8012170034 8012170036 8012170037 8012170041 8012170048 | 8012170013 8012170023 8012170013 8012170023 8012170023 | 80/12/05 80/12/04 80/12/05 90/12/04 80/12/04 | 50-280 50-338 50-280 50-338 50-338 | 9 |
| 8012160368 8012160387 8012160394 8012160400 8012160406 | 8012160360 8012160381 8012160390 8012160398 8012160403 | 80/12/12 80/12/10 80/12/12 80/12/10 80/12/10 | 50-284 50-318 50-317 50-344 50-348 | 0 8 8 8 | 8012170060 8012170066 8012170070 8012170076 8012170178 | 8012170054 8012170054 8012170054 8012170054 8012170171 | 80/11/26 80/11/26 80/11/26 80/11/26 | 50-413 50-413 50-413 50-413 71-6698 | 0 0 0 |
| 8012160411 8012160413 8012160413 8012160418 8012160420 | 8012160409 8012160410 8012160414 8012160416 8012160417 | 80/12/12 80/12/10 80/12/12 80/12/01 80/12/08 | 50-313 TOPREP 50-368 50-293 50-10 | R R R | 8012170191 8012170279 8012170273 8012170277 8012170287 | 8012170186 8012170201 8012170270 8012170272 8012170280 | 80/12/03 80/11/25 80/12/03 80/12/04 80/12/02 | 71-9070 CONTRACT XPORTLIC XPORTLIC XPORTLIC | |
| 8012160424 8012160426 8012160428 8012160431 8012160432 | 8012160422 8012160425 8012160427 8012160422 8012160430 | 80/12/03 80/12/08 80/12/11 80/12/03 80/12/09 | 70-754 50-255 50-266 50-219 50-271 | R R H R | 8012170299 8012170393 8012170393 8012170382 8012170412 | 8012170275 8012170314 8012170329 8012170372 8012170407 | 80/12/12 80/11/26 80/12/15 80/11/19 80/12/03 | 50-317 50-187 50-498 50-133 50-364 | P R K F P |
| 8012160438 8012160439 8012160440 8012160449 8012160450 | 8012160434 8012160422 8012160433 8012160442 8012160445 | 80/12/09 80/12/03 80/12/10 80/12/10 80/12/11 | 50-261 50-219 50-324 50-409 50-272 | R H S R | 8012170442 8012170439 8012170436 8012170467 8012170473 | B012170440 B012170446 B012170452 B012170464 B012170471 | 80/12/15 80/12/01 90/12/10 80/12/03 80/11/05 | 50-275 50-254 50-155 10CFR 50-43B | Q R R |
| 8012160454 8012160457 8012160458 8012160462 8012160463 | 8012160447 8012160422 8012160453 8012160422 8012160442 | 80/12/10 80/12/03 80/12/11 80/12/03 80/12/10 | 50-327 50-219 50-282 50-219 50-409 | 8 H R H 6 | 8012170477 8012170493 8012170503 8012170524 8012170539 | 8012170476 8012170474 8012170499 8012170519 8012160499 | 80/11/05 80/11/21 80/11/19 80/12/04 80/12/05 | 50-213 50-338 50-289 NUREG 50-528 | P P F |
| 8012160467 8012160468 8012160471 8012160475 8012160477 | 8012160459 8012160466 8012160422 8012160472 8012160469 | 80/12/10 80/12/03 80/12/10 80/12/11 | 50-339 50-250 70-687 50-277 50-324 | B R R | 8012170554 8012170572 8012170585 8012170585 8012170588 | 8012170544 8012170547 8012170576 8012170558 8012170576 | 80/10/24 80/12/12 80/12/11 80/12/12 80/12/11 | 50-237 50-334 50-305 50-260 50-305 | 0 R 8 8 |
| 8012160480 8012160486 8012160489 8012160489 8012160491 | 8012160474 8012160473 8012160481 8012160483 8012160482 | 80/12/08 80/12/10 80/12/10 80/12/12 | 50-220 50-289 50-334 50-302 50-219 | R R R 8 | 8012170592 8012170594 8012170400 8012170404 8012170405 | 8012170574 8012170545 8012170576 8012170549 8012170602 | 80/12/11 80/12/11 80/12/11 80/12/11 80/12/15 | 50-305 50-276 50-305 50-301 50-327 | 88888 |
| 8012160492 8012160496 8012160498 8012160500 8012160504 | 8012160487 8012160493 8012160494 8012160495 8012160494 | 80/12/11 80/12/10 80/12/12 80/12/11 80/12/12 | 50-312 50-315 50-155 50-320 50-155 | 8 8 8 | 8012170606 8012170612 8012170613 8012170618 8012170625 | 8012170598 8012170603 8012170610 8012170607 8012170614 | 80/12/11 80/12/15 80/12/05 80/12/10 80/12/09 | 50-301 50-296 50-289 50-304 50-324 | 88088 |
| 8012160505 8012160508 8012160511 8012160512 | 8012140302 8012160477 8012160474 8012160509 8012160510 | 80/12/09 80/12/05 80/12/12 80/12/11 80/11/24 | 50-333 50-528 50-155 50-29 50-237 | R T 8 8 | 8012170627 8012170628 8012170630 8012170636 8012170637 | 8012170611 8012170619 8012170623 8012170611 8012170629 | 80/12/11 80/12/09 80/12/11 80/12/11 80/12/09 | 50-281 50-204 50-368 50-281 50-366 | 8888 |
| 8012160517 8012160519 8012160522 8012160524 8012160525 | 8012160510 8012160510 8012160510 8012160514 8012160510 | 80/11/24 80/11/24 80/11/24 80/12/10 80/11/24 | 50-237 50-237 50-237 50-339 50-237 | 5 5 5 5 | 8012170641 8012170644 8012170647 8012170651 8012170653 | 8012170633 8012170611 8012170642 8012170648 8012170648 | 80/12/09 80/12/11 80/12/12 80/12/10 80/12/10 | 50-278 50-281 50-260 50-289 50-289 | H 88 |
| 8012160528 8012160529 8012160532 8012160536 8012160537 | 8012160510 8012160520 8012160510 8012160530 8012160510 | 80/11/24 90/11/29 80/11/24 90/12/10 80/11/24 | 50-237 50-454 50-237 50-333 50-237 | 9 9 8 9 | 8012170659 8012170669 8012170673 8012170673 | 8012170648 8012170648 8012170657 8012170648 8012170669 | 80/12/10 80/12/10 80/12/02 80/12/10 80/11/24 | 50-289 50-289 50-387 50-289 90-237 | H 0 H 0 |
| B012160539 B012160541 B012160543 B012160547 B012160549 | 8012160510 8012160535 8012160538 8012160540 8012160542 | 90/11/24 90/10/23 90/12/03 90/12/10 90/12/11 | 50-237 50-456 50-237 50-244 50-296 | 6 8 8 8 | . 8012170681 8012170682 8012170685 8012170687 8012170689 | 8012170648 8012170675 8012170648 8012170679 8012170648 | 80/12/10 80/12/04 80/12/10 80/11/24 80/12/10 | 50-289 50-443 50-289 50-277 50-289 | H O H F H |
| 8012160554 8012160555 8012160557 8012160576 8012160608 | 8012160546 8012160535 8012160553 8012160573 8012160605 | 80/12/04 80/10/23 80/12/15 80/11/04 80/02/13 | 50-219 50-456 50-296 50-182 ACRS | 8 0 8 | 8012170691 8012170693 8012170696 8012170698 8012170704 | 8012170648 8012170669 8012170648 8012170648 8012170648 | 80/12/10 80/11/26 80/12/10 80/12/10 80/12/10 | 50-289 50-237 50-289 50-289 50-289 | HHHHH |
| | | | | | | | | | |

| ACCESSION NUMBER | | | | | ACCEBBION NUMBER | | | | | | |
|--|--|--|--|------------------|--|--|--|--|------------------|--|--|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | BUBJECT | Y | ENCLOSURE | PRINCIPAL DOCUMENT | DATE 16SUED | EUS-JECT CATEGORY | , | | |
| 8012170709 8012170714 8012170717 8012170722 8012170724 | 8012170648 8012170648 8012170648 8012170648 8012170648 | 80/12/10 80/12/10 80/12/10 80/12/10 80/12/10 | 50-287 50-287 50-287 50-287 50-287 | H H H H | 8012180397 8012180365 8012180365 8012180372 8012180375 | 8012180351 8012180360 8012180361 8012180367 8012180361 | 80/12/04 80/12/03 80/12/02 80/11/12 90/12/02 | 70-2609 50-369 50-445 | a a a | | |
| 8012170726 8012170730 8012170733 8012170736 8012170742 | 8012170648 8012170648 8012170648 8012170648 8012170648 | 80/12/10 80/12/10 80/12/10 80/12/10 | 50-287 50-287 50-287 50-287 50-287 | H H H | 80121803B3 80121803B4 80121803P4 80121803P6 80121803P8 | 8012180381 8012180379 8012180391 8012180395 8012180395 | 80/12/10 80/12/11 80/12/11 80/12/09 80/12/09 | 50-364 50-244 50-400 | 0 0 0 | | |
| 8012170784 8012170788 8012180024 8012180039 8012180069 | 8012170781 8012170781 8012180022 8012180032 8012180055 | 79/12/31 79/12/31 80/11/10 80/11/10 80/11/07 | RES RES 50-409 50-261 50-259 | Q Q Q | 8012180399 8012180400 8012180401 8012180407 8012180403 | 8012180397 8012180395 8012180397 8012180395 8012180395 | 80/12/04 80/12/09 80/12/04 80/12/09 80/12/09 | 50-400 50-349 50-400 | 0 0 0 | | |
| 8012180097 8012180099 8012180103 8012180106 8012180109 | 8012180087 8012180087 8012180072 8012180072 8012180087 | 60/11/28 60/11/28 60/12/04 80/12/04 80/11/28 | 50-260 50-260 50-416 50-416 50-260 | 0 0 0 | 8012180407 8012180408 8012180420 8012180427 8012180435 | 8012180404 8012180404 8012180416 8012180414 8012180431 | 80/11/04 80/11/04 80/11/28 80/11/28 80/11/12 | 50-2 50-2 BECY BECY 70-925 | a a | | |
| 8012180110 8012180112 8012180118 8012180128 8012180133 | 8012180092 8012180089 8012180122 8012180122 | 60/12/04 60/11/28 80/12/04 80/10/27 80/10/31 | 50-416 50-260 50-416 50-298 50-358 | 0 0 0 | 8012180464 8012180478 8012180452 8012180526 8012180541 | 8012180451 8012180472 8012180472 8012180520 8012180536 | 80/12/05 80/12/01 80/12/01 80/12/01 80/11/24 | 50-245 70-1113 70-1113 CONTRACT 50-213 | P H | | |
| 8012180135 8012180137 8012180142 8012180144 8012180145 | 8012180130 8012180123 8012180123 8012180140 | 80/10/31 80/11/26 80/11/28 80/11/26 | 50-358 50-413 50-338 50-413 50-338 | 0 0 0 | 8012180590 8012180599 8012180603 8012180603 8012180612 | 8012180586 8012180594 8012180600 8012180602 8012180602 | 80/11/12 80/10/21 80/12/04 80/12/11 80/12/11 | 50-461 GA999 50-155 GA999 GA999 | Q Q | | |
| 8012180146 8012180147 8012180149 8012180150 8012180153 | 8012180140 8012180123 8012180140 8012180123 8012180151 | 80/11/28 80/11/26 80/11/28 80/11/26 80/11/06 | 50-338 50-413 50-338 50-413 50-254 | 0 0 0 0 | 9012180415 9012180421 8012180437 8012180433 8012190440 | 8012180602 8012180602 8012180623 8012180620 8012180620 | 80/12/11 80/12/11 80/09/26 80/11/17 80/11/17 | 0A777 0A777 0A777 50-10 50-10 | P P | | |
| 8012180157 8012180167 8012180175 8012180178 8012180180 | 8012180131 8012180163 8012180169 8012180169 8012180169 | 80/11/06 80/11/05 80/12/01 80/12/01 80/12/01 | 50-254 50-438 50-553 50-553 50-553 | 0 0 0 0 | 8012180444 8012180468 801219041 8012190012 8012190016 | 8012180620 8012180620 8012180620 801219008 801219008 | 80/09/25 80/11/17 80/11/17 80/12/03 80/12/03 | 0A999 50-10 50-10 0A999 0A999 | P P | | |
| 8012180183 8012180184 8012180185 8012180187 8012180172 | 8012180165 8012180169 8012180165 8012180165 8012180188 | 80/11/26 80/12/01 80/11/26 80/11/26 80/12/01 | 50-261 50-553 50-261 50-261 50-338 | 0 0 | 8012190021 8012190057 8012190060 8012190064 8012190068 | 8012170008 8012170053 8012170050 8012170053 8012170050 | 80/12/03 80/12/16 80/12/09 80/12/16 80/12/09 | 0A999 50-317 0A999 50-317 0A999 | F | | |
| 8012180194 8012180199 8012180201 8012180204 8012180205 | 8012180165 8012180188 8012180188 8012180188 8012180188 | 80/11/26 80/12/01 80/12/01 80/12/01 80/12/01 | 50-261 50-338 50-338 50-338 50-338 | 0 0 0 | 8012190074 8012190075 8012190079 8012190080 8012190080 | 8012170050 8012170067 8012170067 8012170050 8012170085 | 80/12/09 80/11/28 80/11/28 80/12/09 80/12/03 | GA999 50-250 50-250 GA999 GA999 | P P | | |
| 8012180207 8012180208 8012180209 8012180212 8012180213 | 9012180199 8012180188 8012180199 8012180199 8012180214 | 80/11/26 80/12/01 80/11/26 80/11/26 80/11/07 | 50-387 50-338 50-387 50-387 50-364 | 0 0 0 | 8012190094 8012190098 8012190104 8012190104 8012190134 | | 80/12/10 80/12/03 80/12/03 80/12/03 80/12/05 | 50-289 GA999 GA999 GA999 50-367 | F | | |
| 8012180217 8012180222 8012180223 8012180232 8012180234 | 8012180199 8012180219 8012180220 8012180226 8012180229 | 80/11/26 80/11/10 80/11/06 80/12/08 80/12/08 | 50-389 50-338 50-259 50-278 70-36 | G G G | 8012170154 8012170159 8012170165 8012170165 8012170167 | 8012190155 8012190095 8012190155 | 80/12/11 80/12/02 80/12/11 80/12/02 80/04/14 | QA999 50-54 QA999 50-54 27-47 | F | | |
| 8012180243 8012180250 8012180263 8012180276 8012180288 | 8012180240 8012180247 8012180258 8012180270 8012180273 | 80/12/15 80/12/09 80/12/06 80/12/10 80/12/10 | 50-368 50-277 50-250 50-29 FOIA | 8 8 | 8012190185 6012190192 8012190194 8012190202 8012190202 | 8012190183 8012190095 8012190095 | 80/12/11 80/11/12 80/12/11 80/12/11 80/11/13 | 9A999 27-47 9A999 9A999 50-364 | œ. | | |
| 8012180287 8012180271 8012180272 8012180275 8012180304 | 8012180284 8012180273 8012180281 8012180273 8012180301 | 80/10/28 80/12/10 80/12/12 80/12/10 80/12/09 | 50-424 FOIA 50-315 FOIA 50-322 | G 8 | 8012190215 8012190225 8012190225 8012190230 | 8012190206 8012190216 8012190221 | 80/12/08 80/12/08 80/12/11 80/11/13 80/12/11 | 50-413 50-413 50-272 50-456 50-272 | 0 P 0 P | | |
| 8012180307 8012180308 8012180308 8012180311 8012180317 | 8012180294 8012180302 8012180301 8012180301 8012180315 | 80/10/27 80/11/10 80/12/09 80/12/09 80/12/10 | 50-390 50-302 50-322 50-322 50-315 | 0 0 0 0 | 801217023 801217026 801217027 801217027 801217030 | 8012170242 8012170271 8012170287 | 80/07/29 80/11/13 80/11/13 80/11/26 80/11/26 | 27-47 50-454 50-331 GA999 GA949 | a a | | |
| 8012180318 8012180321 8012180323 8012180325 8012180353 | 8012180314 8012180315 8012180322 8012180313 8012180351 | 80/11/20 80/12/10 80/12/05 80/12/04 80/12/04 | 50-346 50-315 50-142 50-344 50-247 | PPQQ | 801217031 801217031 801217032 801217033 | 8012170308 8012170314 8012170314 | 80/11/26 80/12/04 80/12/02 80/12/02 80/12/02 | 0A777 50-275 50-213 50-213 50-213 | H P P | | |

| | N NUMBER | | | | ACCE8910 | 4 NUMBER | | | |
|--|--|--|---|------------------|--|--|--|--|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE 188UED | SUBJEC CATEGO | | ###################################### | PRINCIPAL | DATE | SUBJECT | |
| 8012190359 8012190368 8012190374 8012190385 | 8012190351 8012190351 8012190364 8012190351 | 80/12/09 80/12/09 80/12/15 80/12/09 | 50-400 50-400 FOIA 50-400 | <u>a</u> | ENCLOSURE 801217068 8012170680 8012170683 | DOCUMENT 8012170664 8012170673 8012170678 | 80/11/13 80/10/17 80/11/20 | 50-498 50-336 40-7102 | Y 0 0 |
| 8012190400 8012190403 | 8012170376 | 80/12/08 | 50-311 | Q P P | 8012190686 8012190689 | 8012190678 8012190685 | 80/11/20 80/10/30 | 40-7102 50-201 | a |
| 8012170408 8012170409 8012170411 8012170412 | B012170402 B012170376 B012170402 B012170402 | 80/12/10 80/12/08 80/12/10 80/12/10 | 50-261 50-261 50-261 50-261 | 6 6 6 | 8012190690 8012190692 8012190697 8012190698 8012190705 | 8012190678 8012190667 8012190695 8012190694 8012190701 | 80/10/16 80/10/22 80/10/28 80/10/28 | 40-7102 50-305 50-373 70-371 10CFR | Q Q |
| 8012190416 8012190422 8012190426 8012190430 8012190431 | 8012190407 8012190419 8012190414 8012190414 8012190425 | 80/11/04 80/12/05 80/12/10 80/12/10 80/12/11 | 50-478 50-267 50-324 50-324 50-389 | Q P Q K | 8012190707 8012190711 8012190712 8012190717 8012190719 | 8012190703 8012190708 8012190710 8012190713 8012190716 | 80/10/30 80/11/14 80/10/31 80/10/31 80/12/09 | 50-272 50-348 50-333 50-387 50-438 | 0000 |
| 8012190434 8012190439 8012190440 8012190442 8012190445 | 8012170414 8012170433 8012170414 8012170438 8012170438 | 80/12/10 80/09/04 80/12/10 80/12/09 80/12/09 | 50-324 GA999 50-324 GA999 GA999 | a | 8012170728 8012220003 8012220005 8012220006 8012220012 | 8012170724 8012220002 8012220002 8012220004 8012220009 | 80/10/28 80/11/25 80/11/25 80/10/24 80/10/24 | 50-47 CONTRACT CONTRACT 50-29 70-820 | œ œ |
| 8012190446 8012190449 8012190454 8012190463 8012190470 | 8012170433 8012170438 8012170438 8012170457 8012170453 | 80/09/04 80/12/09 80/12/09 80/12/04 80/11/26 | 9779 97799 97799 98 98 | | 8012220019 8012220025 8012220030 8012220031 8012220037 | 8012220015 8012220023 8012220028 8012220035 | 80/10/24 80/10/24 80/12/03 80/10/23 80/10/31 | 50-317 | Q Q Q |
| B012190472 B012190476 B012190479 B0121904B1 B0121904B9 | 8012170466 8012170453 8012170473 8012170466 8012170453 | 80/12/10 80/11/26 80/12/15 80/12/10 80/11/26 | 50-239 99940 50-282 50-259 99940 | G G | 8012220040 8012220045 8012220054 8012220062 8012220067 | 8012220035 8012220042 8012220042 8012220035 8012220065 | 80/10/31 80/11/14 80/11/14 80/10/31 80/10/28 | 50-266 50-266 50-317 | 0 0 0 0 |
| 8012170492 8012170493 8012170496 8012170499 8012170504 | 8012170466 8012170487 8012170483 8012170466 8012170466 | 80/12/10 80/12/15 80/11/26 80/12/10 80/12/10 | 50-259 50-445 04999 50-259 50-259 | Q Q | 8012220077 8012220080 8012220082 8012220085 8012220086 | 8012220071 8012220079 8012220079 8012220079 8012220081 | 80/10/29 80/11/18 80/11/18 80/11/18 80/12/11 | 50-289 50-289 | 0 0 0 |
| 8012190505 8012190509 8012190511 8012190512 8012190513 | 8012170500 8012170501 8012170506 8012170466 8012170508 | 80/12/11 80/12/12 80/10/24 80/12/10 80/12/15 | 50-316 50-334 50-423 50-259 50-338 | R Q Q R | 8012220070 8012220074 8012220076 8012220078 8012220137 | 8012220081 8012220081 8012220093 8012220081 8012220134 | 80/12/11 80/12/11 80/11/16 80/12/11 80/11/25 | 0A999 0A999 40-3392 0A999 40-4492 | |
| 8012170515 8012170517 8012170522 8012170526 8012170534 | 8012190453 8012190517 8012190453 8012190524 8012190529 | 80/11/26 80/12/15 80/11/26 80/12/12 80/12/03 | GA999 50-269 GA999 50-213 50-458 | R R Q | 8012220144 8012220194 8012220290 8012220207 8012220212 | B012220141 8012220183 8012220183 8012220183 8012220183 | 80/12/01 80/12/05 80/12/05 80/12/05 80/12/05 | 50-440 FOIA FOIA FOIA FOIA | A |
| B012170535 8012170534 8012170542 8012170544 8012170530 | 8012170532 8012170525 8012170538 8012170539 8012170548 | 80/12/13 80/12/12 80/12/09 80/10/28 80/10/15 | 50-280 50-324 50-285 50-498 70-687 | R S R Q | 8012220219 8012220224 8012220233 8012220243 8012220244 | 8012220183 8012220183 8012220183 8012220183 8012220239 | 80/12/05 80/12/05 80/12/05 80/12/05 80/12/09 | FOIA FOIA FOIA FOIA 50-320 | н |
| 8012190552 8012190553 8012190540 8012190575 8012190576 | 8012170551 8012170548 8012170559 8012170574 8012170574 | 80/10/30 80/10/15 80/10/15 80/12/08 80/12/08 | GA999 70-687 50-387 50-327 50-327 | 0 0 | 8012220246 8012220249 8012220252 8012220258 8012220264 | 8012220183 8012220240 8012220183 8012220183 8012220183 | 80/12/05 80/12/10 80/12/05 80/12/05 80/12/05 | FOIA CONTRACT FOIA FOIA FOIA | |
| 8012170578 8012170582 8012170585 8012170570 8012170572 | 8012170574 8012170574 8012170583 8012170587 8012170587 | 80/12/08 80/12/08 80/11/13 80/12/12 80/12/12 | 50-327 50-327 50-281 50-334 50-334 | 0 0 8 8 | 8012220265 8012220267 8012220271 8012220275 8012220284 | 8012220296 8012220183 8012220183 | 80/12/10 80/12/09 80/12/10 80/12/09 80/12/09 | FOIA | P |
| 8012190595 8012190596 8012190597 8012190599 8012190600 | 8012190589 8012190587 8012190594 8012190593 8012190587 | 80/06/23 80/12/12 80/12/12 80/12/12 | 27-47 50-334 70-2156 50-331 50-334 | 8 8 | 8012220290 8012220298 8012220307 8012220317 8012220321 | 8012220183 8012220183 8012220301 8012220304 8012220316 | 80/12/05 80/12/05 80/12/18 80/12/16 80/12/12 | 50-302 | 01 83 R |
| 8012170601 8012170604 8012170606 8012170609 | 8012170374 8012170387 8012170374 8012170378 8012170605 | 80/11/06 80/12/12 80/11/06 80/03/20 80/12/03 | 70-2154 50-334 70-2156 27-47 XPGRTLIC | 8 | 8012220330 8012220335 8012220342 8012220348 8012220346 | 8012220324 8012220322 8012220338 8012220338 8012220340 | 80/12/14 90/12/09 90/11/26 90/11/26 90/12/09 | 50-409 50-289 | 8 0 0 |
| 8012190611 8012190619 8012190620 8012190630 8012190633 | 8012170608 8012170615 8012170618 8012170626 8012170627 | 60/11/21 80/12/15 80/11/07 80/12/15 80/12/02 | 71-354 50-269 50-498 50-317 50-458 | R O R | 8012220408 8012220408 8012220407 8012220414 8012220432 | 8012220383 8012220404 8012220405 8012220401 8012220428 | 80/12/15 80/12/10 80/12/03 80/12/16 80/12/15 | 50-219 WASTE MOT 50-318 | 8 8 |
| 8012190638 8012190640 8012190647 8012190650 9012190655 | 8012190629 8012190634 8012190642 8012190643 8012190652 | 80/12/02 80/12/11 80/12/03 80/12/12 80/10/14 | 50-458 50-272 50-498 50-331 50-334 | 0 8 0 8 | 8012220434 8012220443 8012220451 8012220457 8012220460 | 8012220425 8012220440 8012220446 8012220442 8012220453 | 80/12/15 80/12/10 80/12/15 80/12/16 80/12/12 | 50-244 50-346 50-293 | 8 8 8 8 |

| ACCESSION | NUMBER | | | | | ACCESSION | NUMBER | | | |
|--|--|--|--|-----------------------|------|--|--|--|---|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | , | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE | SUBJECT CATEGORY | |
| 8012220466 8012220479 8012220506 8012220534 8012230015 | 8012220452 8012220477 8012220485 8012220485 8012230012 | 80/12/15 80/11/07 80/12/04 80/12/04 80/12/02 | 50-348 WASTE MOT 50-10 50-10 50-445 | 8 P P H | | 8012230445 8012230445 8012230453 8012230454 8012230455 | 8012230441 8012230440 8012230451 8012230458 8012230452 | 80/12/16 80/12/18 80/12/18 80/12/16 80/12/11 | 50-334 8 50-302 8 50-327 P 50-302 8 50-344 8 | |
| 8012230027 8012230033 8012230037 8012230040 8012230041 | 8012230021 8012230021 8012230021 8012230021 8012230034 | 80/12/01 80/12/01 80/12/01 80/12/01 80/10/15 | 50-389 50-389 50-389 50-389 50-352 | 0 0 0 0 | | 8012230505 | 8012230465 8012230474 8012230475 8012230395 8012230501 | 80/12/17 80/11/26 80/12/17 80/12/18 80/12/18 | 50-334 8 50-387 K 50-320 8 50-280 8 50-324 8 | |
| 8012230046 8012230047 8012230061 8012230080 8012230090 | 8012230021 8012230044 8012230054 8012230073 8012230021 | 80/12/01 80/10/17 80/10/14 80/10/16 80/12/01 | 50-389 50-336 70-135 50-410 50-389 | 0 0 0 | | 8012230506 8012230511 8012230515 8012230517 8012230518 | 8012230500 8012230507 8012230510 8012230512 8012230512 | 80/12/12 80/12/12 80/12/12 80/12/12 | TOPREP 50-259 P 50-124 F 50-124 F | |
| 8012230127 8012230134 8012230138 8012230139 8012230149 | 8012230121 8012230121 8012230133 8012230121 8012230144 | 80/11/19 80/11/19 80/12/10 80/11/19 80/11/19 | 50-338 50-338 CONTRACT 50-338 CONTRACT | P P | | 8012230519 8012230523 8012230523 8012230524 8012230525 | 8012230510 8012230514 8012230510 8012230513 8012230521 | 80/12/02 80/12/17 80/12/02 80/12/16 80/12/11 | 50-287 8 50-259 P 50-302 8 50-166 F | 3 |
| 8012230154 8012230173 8012230174 8012230178 8012230183 | 8012230151 8012230168 8012230169 8012230167 8012230169 | 60/11/19 80/11/19 80/12/03 80/12/03 80/12/03 | CONTRACT CONTRACT GA999 GA999 GA999 | | | 8012230533 8012230534 8012230535 8012230537 8012230538 | 8012230528 8012230529 8012230530 8012230530 8012230528 | 80/12/15 80/12/18 80/12/12 80/12/12 80/12/15 | 50-334 B 50-155 S 50-369 A 50-369 A 50-334 E | 4 |
| 8012230193 8012230294 8012230206 8012230207 8012230216 | 8012230187 8012230197 8012230202 8012230205 8012230211 | 80/11/14 80/12/03 80/11/10 80/12/18 80/11/13 | 50-373 XPORTLIC XPORTLIC 50-255 COMMISSI | Р | | 8012230541 8012230543 8012230545 8012230546 8012230548 | 8012230530 8012230530 8012230540 8012230530 8012230530 | 80/12/12 80/12/12 80/12/05 80/12/12 80/12/12 | 50-369 / 50-369 / 50-369 / 50-369 / | A A |
| 8012230221 8012230224 8012230229 8012230239 8012230242 | 8012230217 8012230220 8012230226 8012230234 8012230234 | 80/11/24 80/12/02 80/12/18 80/11/14 80/11/14 | 71-6458 WABTE MG 50-373 GA999 GA999 | T K | | 8012230549 8012240012 8012240015 8012240020 8012240023 | 8012230542 8012240004 8012240004 8012240004 8012240004 | 80/12/11 80/12/10 80/12/10 80/12/10 | 50-346 E COMMISSION COMMISSION COMMISSION | N N N |
| 8012230246 8012230248 8012230247 8012230255 8012230258 | 8012230234 8012230234 8012230234 8012230234 8012230256 | 80/11/14 80/11/14 80/11/14 80/11/14 80/03/24 | QA999 QA999 QA999 QA999 50-10 | P | | 8012240025 8012240028 8012240039 8012240031 6012240034 | 8012240004 8012240004 8012240026 8012240004 8012240004 | 80/12/10 80/12/10 80/11/19 80/12/10 80/12/10 | COMMISSION 50-483 COMMISSION COMMISSION | N O N |
| 8012230240 8012230273 8012230274 8012230287 8012230288 | 8012230254 8012230272 8012230274 8012230285 8012230287 | 80/03/24 80/11/28 80/12/01 80/12/12 80/12/03 | 50-10 71-6744 71-6375 50-263 50-395 | P P D | | 8012240036 8012240037 8012240038 8012240039 8012240044 | E012240032 E012240004 B012240033 B012240004 R012240040 | 80/12/15 80/12/10 80/12/02 80/12/10 80/12/15 | CONTRACT COMMISSIO 50-313 COMMISSIO CONTRACT | Q |
| 8012230289 8012230293 8012230274 8012230295 8012230301 | 8012230285 8012230286 8012230291 8012230292 8012230292 | 80/12/12 80/12/18 80/12/19 80/12/10 80/12/10 | 50-263 50-280 50-358 50-321 50-366 | P F K R | | 8012240045 8012240049 8012240051 8012240054 8012240056 | | 80/11/12 80/10/30 80/12/08 80/11/17 80/12/10 | 50-334 CONTRACT | а С С М |
| 8012230304 8012230307 8012230312 8012230314 8012230318 | 8012230303 8012230302 8012230309 8012230311 8012230316 | 80/12/15 80/12/18 80/12/04 80/12/15 80/12/15 | 50-247 50-52B 50-364 50-331 50-304 | R K P R S | | 8012240061 8012249068 8012240072 8012240074 8012240075 | 8012240066 8012240004 | 80/12/12 80/12/10 80/11/20 80/12/10 80/12/10 | COMMISSIC 50-545 COMMISSIC COMMISSIC | G SN DN |
| 8012230327 8012230343 8012230347 8012230348 8012230349 | 8012230322 8012230342 8012230344 8012230344 8012230341 | 80/12/15 80/12/15 80/12/12 80/12/18 80/12/18 | 50-275 50-245 50-336 50-83 50-155 | 8 R R | | 8012240076 8012240081 8012240082 8012240083 8012240087 | 8012240004 8012240077 8012240004 | 60/12/10 80/12/10 80/11/19 80/12/10 80/11/18 | COMMISSIO COMMISSIO 40-7924 COMMISSIO 40-7924 | DN |
| 8012230354 8012230358 8012230340 8012230345 8012230345 | 8012230351 8012230352 8012230355 8012230362 8012230361 | 80/12/17 80/12/12 80/12/17 80/12/16 80/12/19 | 50-293 50-277 50-553 50-327 50-317 | 8 8 8 | | 8012240090 8012240092 8012240093 8012240094 8012240098 | 8012240004 8012240004 8012240093 | 80/11/18 80/12/10 80/12/10 80/11/18 80/12/10 | 40-7924 COMMISSI COMMISSI 50-346 COMMISSI | P P |
| 8012230373 8012230374 8012230388 8012230388 8012230389 | 8012230369 8012230371 8012230379 8012230364 | 80/12/18 80/12/17 80/12/18 80/12/15 80/12/17 | 50-324 50-339 50-272 50-336 50-305 | 8 8 8 | | 8012240100 801224012 8012240130 8012240130 8012240130 | 8012240118 8012240126 8012240118 | | 50-346 50-275 70-143 50-275 70-143 | P F |
| 8012230397 8012230397 8012230403 8012230406 8012230406 | 8012230386 8012230385 8012230375 8012230401 | 80/12/16 80/12/19 80/12/18 80/12/16 90/12/16 | 50-327 50-305 50-291 50-325 50-317 | 8 8 8 | | 801224013 801224014 801224014 801224014 801224014 | 8012240124 8012240135 8012240135 | 80/12/15 80/11/28 80/11/28 | 70-143 70-143 50-334 50-334 50-334 | P P |
| 8012230416 8012230424 8012230428 8012230437 8012230443 | 8012230412 8012230419 8012230423 8012230433 | 80/12/17 80/12/17 80/12/17 80/12/18 | 50-339 50-339 50-338 50-302 50-324 | 8 8 8 | F 40 | 801224016 801224016 801224016 801224017 801224017 | 4 8012240155 5 8012240161 0 8012240166 | 80/12/12 80/12/09 80/12/09 | 50-443 71-401 71-354 | A |
| | | | | | | | | | | |

| ACCESSI | ON NUMBER | | | | | | ON NUMBER | | | |
|---|--|--|--|-----------------------|----|--|--|--|---|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJE | | | ENGLOSURE | PRINCIPAL | DATE | SUBJEC | |
| 8012240175 8012240177 8012240176 8012240181 8012240184 | 8012240173 8012240147 8012240174 8012240167 | 80/12/09 80/10/31 80/11/18 80/10/31 | 71-24 50-382 | a | | 8012270250 8012270253 8012270253 8012270257 8012270265 8012270266 | DOCUMENT 8012290245 8012290248 8012290255 8012290255 8012290258 | 18SUED 80/12/12 80/12/19 80/12/12 80/12/17 | CATEGO DRG 50-366 REGOD REGOD 50-366 | 3RY S |
| 8012240187 8012240191 8012240202 8012240207 8012240207 | 8012240192 8012240194 8012240194 8012240194 | 80/12/10 80/12/10 80/12/10 | 50-272 50-272 50-277 50-277 50-277 | 5 5 5 | | 8012290249 8012290272 8012290276 8012290282 8012290297 | 8012270295 8012270267 8012270255 8012270255 8012270272 | 80/12/12 80/11/21 80/12/12 80/12/12 | REGOD 50-247 REGOD REGOD 50-338 | P |
| 801 2240221 801 2240226 801 2240228 801 2240233 801 2240251 | 8012240217 8012240217 8012240217 | 80/11/04 80/11/04 80/11/04 | 50-322 50-322 50-322 50-322 70-378 | . G | | 8012290303 8012290319 8012290326 8012290335 8012290345 | 8012270301 8012270313 8012270321 8012270325 8012270331 | 80/12/17 80/12/17 80/12/17 80/12/19 80/12/23 | 50-312 70-2623 50-250 50-321 50-293 | P 9 8 |
| 801 2240253 801 2240256 801 2240258 801 2240261 801 2240262 | 8012240242 8012240247 8012240247 | 80/11/07 80/11/13 80/11/13 | 70-398 50-293 70-398 70-398 50-29 | Qi P | | 8012290357 8012290370 8012290380 8012290383 8012290393 | 8012290356 8012290368 8012290377 8012290377 8012290390 | 80/12/11 80/12/11 80/11/28 80/11/28 | 50-320 50-320 50-289 50-289 50-389 | H P P M |
| 8012240263 8012240269 8012240270 8012240271 8012240277 | 8012240254 8012240264 8012240242 8012240266 8012240266 | 80/12/16 80/11/07 80/10/20 | 50-331 50-321 50-293 50-29 50-29 | 0 0 0 0 | | 8012290395 8012290399 8012290404 8012290405 8012290408 | 8012270370 8012270370 8012270370 8012270403 8012270403 | 80/12/03 80/12/03 80/12/03 80/12/04 80/12/04 | 50-389 50-389 50-389 COMMISS COMMISS | |
| 8012240285 8012240294 8012240304 8012240319 8012240331 | 8012240280 8012240290 8012240297 8012240217 8012240323 | 80/12/16 80/12/19 80/12/16 80/12/04 80/11/25 | 50-346 50-262 50-366 XPORTLI 50-313 | 8 6 6 0 | | 8012290409 8012290412 8012290414 8012290420 8012290421 | 8012270401 8012270406 8012270410 8012270401 8012270416 | 80/12/02 80/12/10 80/12/19 80/12/02 80/12/10 | 50-220 50-237 50-331 50-220 50-289 | G T B G |
| 8012240332 8012240356 9012240370 9012240372 B012240374 | 8012240328 8012240352 8012240365 8012240369 8012240365 | 80/12/19 80/11/24 80/11/17 80/12/12 80/11/17 | 50-302 XPORTLL State P 50-369 State P | rog F | | 8012290426 8012290429 8012290429 8012290430 8012290431 | 8012290401 8012290422 8012290425 8012290423 8012290401 | 80/12/02 80/12/19 80/12/17 80/12/12 80/12/02 | 50-220 50-331 50-286 50-528 50-220 | G 8 0 0 |
| 8012240377 8012240379 8012240380 8012240381 8012240383 | 8012240369 8012240365 8012240375 8012240369 8012240365 | 80/12/12 80/11/17 80/11/21 80/12/12 80/11/17 | 50-369 State Pr XPORTLIC 50-369 State Pr | F | | 8012290434 8012290437 8012290438 8012290442 8012290445 | 8012270401 8012270432 8012270433 8012270435 8012270440 | 80/12/02 80/12/17 80/12/16 80/12/17 80/12/17 | 50-220 50-333 50-313 50-267 50-320 | 0 8 8 8 |
| 8012240370 8012240375 8012240377 8012240404 8012240407 | 8012240365 8012240365 8012240365 8012240365 8012240365 | 80/11/17 80/11/17 80/11/17 80/11/17 | State Pr State Pr State Pr State Pr | rog rog | 4 | 8012270446 8012270447 8012270450 8012270451 8012270452 | 8012270401 8012270437 8012270401 8012270441 8012270447 | 80/12/02 80/12/17 80/12/02 80/12/17 80/12/17 | 50-220 50-333 50-220 50-333 50-320 | 9 9 8 F |
| 8012240427 8012240428 8012240432 8012240434 8012240443 | 8012240425 8012240425 8012240429 8012240433 8012240442 | 80/12/22 80/12/12 80/11/21 80/11/21 | 50-361 50-361 50-10 40-9743 DRO | C C | | 8012270453 8012270455 8012270460 8012270461 8012270467 | 8012290443 8012290448 8012290448 8012290456 8012290464 | 80/12/17 80/12/19 80/12/19 80/12/17 80/12/16 | 50-333 50-281 50-281 50-289 50-275 | 8 8 F F |
| 8012290009 8012290013 8012290015 8012290019 | 8012270007 8012270012 8012270012 8012270012 8012270012 | 80/09/25 80/10/29 80/10/29 80/10/29 80/10/29 | 10CFR 50-416 50-416 50-416 50-416 | AAAA | | 8012290473 8012290474 8012290479 8012290482 8012290483 | 8012270464 8012270469 8012270476 8012270477 8012270476 | 80/12/16 80/12/17 80/12/11 80/12/17 80/12/11 | 50-275 50-333 10CFR 50-320 10CFR | F 6 |
| 8012270022 8012270031 8012270038 8012270065 8012270067 | 8012270012 8012270028 8012270035 8012270062 8012270062 | 80/10/29 80/12/10 80/12/03 80/12/12 80/12/12 | 50-416 50-287 50-155 COMMISSI COMMISSI | | | 8012270484 8012270485 8012270492 8012270494 8012270500 | 8012270480 8012270476 8012270486 8012270490 8012270497 | 80/12/04 80/12/11 80/12/09 80/12/17 80/12/17 | 50-269 100FR 9A999 50-320 50-320 | P F |
| 8012270073 8012270076 8012270081 8012270085 8012270088 | 8012270062 8012270062 8012270062 8012270062 8012270062 | 80/12/12 80/12/12 80/12/12 80/12/12 | COMMISSI COMMISSI COMMISSI COMMISSI | ON ON ON | 44 | 8012270501 8012270503 8012270506 8012270507 8012270510 | 8012270493 8012270499 8012270504 8012270493 8012270504 | 80/12/15 80/12/05 80/12/17 80/12/15 80/12/17 | 50-3 50-244 50-320 50-3 50-320 | T P T F |
| 8012290095 8012290109 8012290137 8012290140 8012290147 | 8012270071 8012270107 8012270154 8012270156 8012270156 | 80/12/18 80/12/23 80/12/18 80/12/18 | 50-466 50-329 50-280 50-466 50-466 | 0 0 P T T | | 8012290531 8012290538 8012290562 8012290589 8012290593 | 8012270527 8012270535 8012270558 8012270585 8012270585 | 80/12/01 80/12/04 80/12/07 80/12/10 80/12/10 | 70-1308 50-367 50-289 SECY SECY | G T |
| 8012290176 8012290179 8012290184 8012290189 8012290191 | 8012270172 8012270174 8012270174 8012270174 8012270174 | 80/12/17 80/12/12 80/12/12 80/12/12 80/12/12 | 50-293 50-289 50-289 50-289 50-289 | R H H H | | 8012270640 8012270645 8012270655 8012270657 8012300003 | 8012270434 8012270436 8012270451 8012270451 8012300001 | 80/12/05 80/12/05 80/12/22 80/12/22 80/10/21 | 50-409 50-409 50-250 50-250 50-247 | TPPQ |
| 8012290195 8012290200 8012290202 8012290225 8012290227 | 8012290174 8012290174 8012290174 8012290219 8012290222 | 80/12/12 80/12/12 90/12/12 90/12/15 80/12/19 | 50-287 50-287 50-289 50-387 50-397 | H H O O | | 8012300009 8012300016 8012300018 8012300024 8012300026 | 8012300005 8012300005 8012300005 8012300013 8012300005 | 80/12/02 80/12/02 80/12/02 80/12/03 80/12/02 | GA999 GA999 GA999 50-445 GA999 | м |
| | | | | | | | | | | |

| | ACCESSION | NUMBER | | | | | ACCESSION | | | | |
|---|--|--------------------------|----------------------|---------------------|------------|---|--------------------------|--|----------------------|---------------------------|----------|
| | enci della | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | , | | ENCLOSURE | PRINCIPAL DECUMENT | DATE | SUBJECT CATEGORY | , |
| | B012300030 | 8012300013 | 80/12/03 | | - H | | 8012300320 | 8012300514 | 80/12/23 | 50-260 | 6 |
| | 8012300039 8012300039 8012300040 | B012300034 B012300013 | 80/10/17 80/12/03 | 70-820 | M | | 8012300525 8012300527 | 8012300522 8012300526 | 60/12/23 60/12/22 | 50-244 50-309 | BR |
| | 8012300051 8012300056 | 8012300045 8012300053 | 80/11/05 | 50-277 50-387 | G | 1 | 8012300530 8012300535 | 8012300523 | 80/12/23 80/12/24 | 30-348 30-327 | 8 |
| | 8012300058 | 8012300045 | 80/11/05 | 50-277 | G G | | 8012300537 | 8012300531 | 80/12/24 | 50-296 | 8 |
| | 8012300059 8012300060 | 8012300055 8012300053 | 80/12/05 80/12/05 | 50-155 50-387 | Ö | | 8012300539 8012300546 | 8012300533 8012300542 | 80/12/18 | 50-34B 50-333 | 8 |
| | 8012300063 8012300070 | 8012300045 8012300045 | 80/11/05 80/11/05 | 50-277 50-277 | Q. | | 8012300547 8012300548 | 8012300543 B012300541 | 80/12/23 | 50-364 50-327 | 8 |
| | 8012300075 | 8012300049 | 80/12/05 | 50-387 | o | | 8012300558 | 8012300553 | 80/12/19 | 50-344 | 8 |
| | 8012300080 8012300084 | 8012300045 8012300081 | 80/11/05 | 50-277 50-237 | 0 | | 8012300544 8012300545 | 8012300555 | 80/12/24 80/12/19 | 50-327 50-344 | 8 |
| | 8012300071 8012300073 | 8012300087 8012300090 | 80/12/11 | 50-247 50-237 | 0 | | 8012300547 8012300573 | 8012300562 8012300568 | 80/12/19 80/12/22 | 50-267 50-344 | 8 |
| | 8012300097 | 8012300087 | 80/12/11 | 50-247 | œ | | 8012300579 | 8012300575 | 80/12/23 | 50-324 50-259 | \$ 8 |
| | 8012300109 8012300113 | 8012300104 8012300104 | 80/12/19 80/12/19 | 50-247 50-247 | G | | 8012300582 8012300589 | 8012300577 8012300583 | 80/12/23 90/12/23 | \$0 ~ 324 | 8 |
| | 8012300124 8012300129 | 8012300118 | 80/12/19 | 50-10 50-237 | Q | | 8012300590 8012300596 | 8012300571 8012300587 | 80/12/19 80/12/29 | 50-325 50-466 | Q |
| | 8012300130 | 8012300118 | 80/12/19 | 50-10 | a | | B012300400 | 8012300575 | 80/12/28 80/12/22 | 50-29 50-263 | 8 ' P |
| | B012300142 B012300154 | 8012300139 8012300149 | 80/12/16 | CONTRACT | | | B012300605 B012300611 | 8012300578 8012300578 8012300578 | 80/12/22 | 50-263 50-263 | P |
| | 0012300160 E012300163 | 8012300153 8012300158 | 80/11/05 | 50-320 CONTRACT | G | | 8012300813 8012300822 | 8012300514 | 80/12/22 | 50-298 | Þ |
| • | 8012300169 | 8012300165 | 80/10/14 | 50-289 | a | | 8012300624 8012300625 | 9012300618 8012300615 | 80/12/19 | 50~277 . 50-259 | R B |
| | 8012300177 8012300185 | 8012300173 8012300173 | 80/11/05 80/11/05 | 50-272 50-272 | 9 | | 8012300631 | 8012300614 8012300614 | 80/11/21 | 50-298 50-298 | P |
| | 8012300195 8012300199 | 8012300189 8012300189 | 80/12/17 80/12/17 | 50-320 50-320 | 0 | | 8012300633 8012300633 | 8012300630 | 80/12/23 | 50-333 | 8 |
| | 8012300203 | 8012300194 | 80/11/28 | 30-142 | o | | 8012300643 8012300644 | 8012300634 8012300636 | 80/12/23 80/11/26 | 50~259 50~347 | B |
| | 8012300212 8012300221 | 8012300208 8012300218 | 80/12/14 | CONTRACT | | | 8012300647 8012300649 | 8012300640 8012300640 | 90/12/12 90/12/12 | 50-220 50-220 | P |
| | 8012300229 8012300230 | 8012300225 8012300227 | 80/12/18 | 50-445 CONTRACT | н | | 8012300653 | 8012300640 | 90/12/12 | 50-220 | P |
| | 8012300235 | 8012300231 | 80/12/24 | TOPREP | | | 8012300458 | 8012300654 8012300655 | 80/12/18 | 50-466 50-333 | 8 |
| | 8012300237 8012300259 | 8012300231 8012300255 | 80/12/24 80/12/17 | TOPREP 50-377 | ĸ | | 8012300664 8012300665 | 8012300654 8012300652 | 80/12/18 | 50-446 50-518 | T R |
| | B012300262 B012300268 | 8012300240 8012300246 | 80/12/18 80/12/18 | 71-102 50-444 | Q | | 8012300667 | 8012300659 | 80/12/18 | 50-334 | 6 |
| | 8012300269 | 8012300264 | 80/12/18 | 50-289 | 0 | | 801230066B 8012300670 | 8012300654 8012300659 | 80/12/18 | 50~466 50~334 | T 8 |
| | 8012300271 8012300272 | 8012300266 8012300267 | 80/12/18 80/11/24 | 50-466 50-344 | Q F | | 8012300675 8012300676 | 8012300654 8012300659 | 80/12/18 | 50~466 50~334 | 8 |
| | B012300273 B012300275 | 8012300264 8012300270 | 80/12/18 80/11/28 | 50-289 50-171 | Q R | | 8012300677 | 8012300454 | 80/12/18 | 50-466 | T |
| | 8012300277 | 8012300266 | 80/12/18 | 50-466 | 0 . | | 8012300681 | 8012300659 8012300654 | 80/12/18 | 50-334 50-466 | 8 T |
| | 8012300279 8012300282 | 8012300266 8012300270 | 80/12/18 80/11/28 | 50-466 50-171 | R | | 8012300484 8012300489 | 8012300659 8012300654 | 80/12/18 80/12/18 | 50-334 50-466 | 8 |
| | 8012300283 | 8012300366 8012300302 | 80/12/18 80/12/19 | 50-466 50-282 | P | | 8012300692 | 8012300654 | 80/12/18 | 50-466 | T |
| | 8012300310 | 8012300302 | 80/12/19 | 50-282 | P | | 8012300496 8012300497 | 8012300654 8012300671 | 80/12/18 | 50-466 50-293 | P |
| | 8012300333 8012300334 | 8012300324 8012300320 | 80/12/01 | 50-237 50-250 | 0 P | | 8012300700 8012300702 | 8012300691 8012300654 | 80/12/10 80/12/18 | 50-293 50-466 | P |
| | 8012300341 8012300344 | 8012300324 8012300338 | 80/12/01 80/12/22 | 50-237 50-445 | C | | 8012300705 | 8012300454 | 80/12/18 | 50-466 | T |
| | 8012300345 | 8012300324 | 80/12/01 | 50-237 50-361 | Q K | | 8012300707 8012300710 | 8012300704 8012300704 | 80/11/21 80/11/21 | 50-271 50-271 | P |
| | 8012300374 8012300375 | 8012300369 8012300371 | 80/12/19 | 50-482 | C K | | B012300711 B012300716 | 8012300654 8012300713 | 80/12/18 80/12/10 | 50~466 50~259 | P |
| | 8012300377 8012300381 | 8012300349 8012300369 | 80/12/19 80/12/19 | 50-361 50-361 | ĸ | • | 8012300719 | 8012300654 | 80/12/18 | 50-466 | T - |
| | 8012300384 | 8012300367 | 80/12/19 | 50-361 50-244 | K | | 8012300721 8012300723 | 8012300713 8012300454 | 80/12/10 | 50-259 50-466 | P |
| | B012300397 B012300402 | 8012300393 8012300398 | 80/12/22 | 50-324 50-293 | 8 | | 8012300724 8012300728 | 8012300713 8012300654 | 80/12/10 | 50-259 50-466 | Ţ |
| | 8012300407 8012300410 | 8012300401 8012300406 | 80/12/19 80/12/23 | 50-255 | 8 | | 8012300731 | 8012300454 | 80/12/19 | 50-466 | T |
| | 8012300415 | 8012300411 | 80/12/24 80/12/15 | 50-261 50-265 | 8 | | 8012300733 8012300758 | 8012300654 8012300755 | 80/12/18 | 50-466 ACRS 50-254 | T |
| | 8012300420 8012300427 | 8012300414 8012300422 | 80/12/23 | 50-155 50-325 | 8 | | 8012300790 8012300793 | 8012300786 8012300786 | 80/12/05 | 50-254 | P |
| | B012300433 B012300444 | 8012300425 8012300438 | 80/12/19 80/12/24 | 50-327 | 8 | | B012300795 | 8012300786 | 80/12/05 | 50-254 | F |
| | 8012300457 8012300468 | 8012300451 8012300465 | 80/12/24 80/12/18 | 50-344 50-331 | 8 | | 801231000B | 8012310004 8012310015 | 80/12/08 | 50-331 50-338 NURE0 | P |
| | 8012300475 8012300483 | 8012300471 8012300478 | 80/12/23 80/12/19 | 50-287 50-309 | 8 B | | 8012310031 8012310038 | | 80/12/18 | 50-339 | a |
| | B012300486 | 8012300482 | 80/12/29 | TOPREP | | | 8012310042 | | | 50-338 | a |
| | 8012300488 8012300493 | 8012300485 8012300490 | 80/12/26 80/12/18 | 50-287 50-320 | 8 | | 8012310044 8012310047 | E015310033 | 90/12/18 | 50-338 | 0 |
| | 8012300498 8012300512 | 8012300475 8012300501 | 80/12/23 | 50-269 50-302 | 8 | | 8012310053 8012310053 | B012310051 | 80/12/02 | 50-344 | F |
| | 8012300513 | 8012300508 | 80/12/24 | 40-B745 | | | 8012310063 | 8012310058 | UO: 11/ K1 | 100 | • |

| ACCESSION | | | | |
|--|--|--|--|-------------------------|
| ENGLOBURE | PRINCIPAL DOCUMENT | DATE 198UED | SUBJECT CATEGOR | |
| 8012310071 8012310091 8012310102 8012310106 | 8012310045 8012310095 8012310094 8012310096 | 80/12/04 80/12/07 80/12/11 80/12/11 | 50-266 50-269 50-247 50-247 TOPREP | о О |
| 8012310178 8012310201 8012310218 8012310228 9012310229 | 8012310187 8012310187 8012310187 8012310215 8012310222 8012310227 | 80/12/23 80/12/23 80/12/23 80/12/01 80/12/24 80/11/17 | TOPREP TOPREP 71-35 50-289 50-344 | Ţ |
| 8012310224 8012310234 8012310239 8012310242 8012310244 | 8012310227 8012310221 8012310222 8012310229 8012310222 | 80/12/24 80/12/03 80/12/24 80/11/21 80/12/24 | 50-289 50-528 50-289 50-261 50-269 | 7 Q T Q T |
| 8012310247 8012310262 8012310287 8012310295 8012310278 | 8012310222 8012310258 8012310288 8012310293 8012310296 | 80/12/24 80/11/10 80/12/22 80/12/18 80/12/30 | 50-289 50-445 50-237 50-413 50-424 | T M Q Q |
| 8012310299 8012310305 8012310312 8012310317 8012310323 | 8012310293 8012310303 8012310309 8012310315 8012310320 | 80/12/18 80/12/30 80/12/22 80/12/30 80/12/17 | 50-413 50-537 50-155 50-461 50-278 | 8 K 8 |
| 8012310328 8012310330 8012310333 8012310337 8012310373 | 8012310321 8012310325 8012310314 8012310319 8012310391 | 80/15/59 80/15/59 80/15/55 80/15/59 80/15/59 | 50-346 50-338 50-338 50-346 CDMMI681 | 8 8 8 8 401 |
| 8012310375 8012310378 8012310403 8012310415 8012310433 | 8012310370 8012310391 8012310391 8012310411 8012310426 | 80/12/15 60/12/02 80/12/02 80/11/19 80/11/04 | 50-948 COMMISS COMMISS 50-228 50-235 | |

| ACCEBSION | NUMBER | | |
|--|--|----------------------------------|--------------------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE 15SUED | SUBJECT CATEGORY |
| 8012310437 | 8012310430 | 80/11/24 | 71-6722 |
| 8012310447 | 8012310442 | 80/11/21 | 50-331 0 |
| 8012310459 | 8012310453 | 80/11/19 | 50-346 0 |
| 8012310470 | 8012310464 | 80/11/03 | 50-373 Q |
| 8012310482 | 8012310478 | 80/11/18 | 50-344 Q |
| 8012310500 | 8012310498 | 80/11/20 | 50-246 Q |
| 8012310508 | 8012310503 | 80/11/25 | 50-460 Q |
| 8012310510 | 8012310504 | 80/10/30 | 50-320 H |
| 8015310218 | 8012310506 | 80/11/20 | 50-341 G |
| 8015310211 | 8012310514 | 80/10/21 | 50-341 G |
| 8012310537 | 8012310534 | 80/11/07 | 40-7402 |
| 8012310538 | 8012310535 | 80/11/20 | 50-344 Q |
| 8012310543 | 8012310534 | 80/11/07 | 40-7402 |
| 8012310545 8012310550 8012310550 | 8012310534 8012310534 | 80/11/13 80/11/07 | 50-360 G 40-7402 |
| 8012310554 8012310573 | 8012310549 8012310534 | 80/11/15 80/11/07 | 50-133 Q 40-7402 40-7402 |
| 8012310577 8012310579 8012310581 | 8012310534 8012310575 8012310534 | 80/11/07 80/11/24 80/11/07 | CONTRACT 40-7402 |
| B012310587 | 8012310534 | 80/11/07 | 40-7402 |
| B012310590 | 8012310583 | 80/12/07 | 50-295 0 |
| 8012310592 | 8012310534 | 80/11/07 | 40-7402 |
| 8012310598 | 8012310534 | 80/11/07 | 40-7402 |
| 8012310602 | 8012310595 | 80/11/26 | Contract |
| 8012310605 | 8012310534 | 80/11/07 | 40-7402 |
| 8012310619 | 8012310616 | 80/09/16 | 70-143 |
| 8012310624 | 8012310620 | 80/09/30 | CONTRACT |
| 8012310630 | 8012310629 | 80/12/09 | 50-10 G |
| 8012310638 | 8012310635 | 80/11/24 | 50-213 P |
| | | | |

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- -3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application,
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC starr for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session Items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.


- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.


XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.





| 100 | | | | | |
|---|---|--|--|--|--|
| NRC FORM 335 (7.77) U.S. NUCLEAR REGULATORY COMMISSION | 1. REPORT NUMBER (Assigned by DDC) | | | | |
| BIBLIOGRAPHIC DATA SHEET | <u></u> | NUREG-0540 | Vol 2, No 12 | | |
| 4. TITLE AND SUBTITLE (Add Volume No., if appropriate) | | 2. (Leave blank) | | | |
| Title List of Documents Made Publicly Availab December 1-31, 1980 | 3. RECIPIENT'S ACCESSION NO. | | | | |
| 7. AUTHOR(S) | | 5. DATE REPORT C | OMPLETED | | |
| | | MONTH | YEAR 1981 | | |
| 9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include 2 | 7'- C-dal | January DATE REPORT 15 | | | |
| | MONTH | YEAR | | | |
| Division of Technical Information and Document C U.S. Nuclear Regulatory Commission | Ontrol | March | 1981 | | |
| Washington, D.C. 20555 | | 6. (Leave blank) | | | |
| | | 8. (Leave blank) | | | |
| 12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include | Zip Code) | TO BROKE OTITARY | OPPORT A BUT NO | | |
| Division of Technical Information and Document C | Control | 10. PROJECT/TASK/WORK UNIT NO. | | | |
| U.S. Nuclear Regulatory Commission Washington, D.C. 20555 | | 11. CONTRACT NO. | | | |
| 13. TYPE OF REPORT | PERIOD COVER | ED (Inclusive dates) | | | |
| Monthly | | | | | |
| 15. SUPPLEMENTARY NOTES | | 14. (Leave plank) | | | |
| | | | | | |
| This document is a monthly publication co information received and generated by the includes (1) docketed material associated plants and other uses of radioactive mate material received and generated by NRC pe regulatory agency. The docketed informat merly issued through the U.S. Department Center under the title Power Reactor Docked document replaces PRDI, which will no long contains the following indexes: Personal Index, and Report Number Index. | US NRC. The with civil with civil with civil writerians and (interior includes of Energy's set Informatinger be prepared. | his informatior ian nuclear pow 2) nondocketed its role as a s information f Technical Info (PRDI). Thared. This doc | ver For- ormation iis cument | | |
| 17. KEY WORDS AND DOCUMENT ANALYSIS | 7a DESCRIPTORS | > | | | |
| 17h IDENTIFIERS OPEN-ENDED TERMS | 19. SECURIT | Y CJ.ASS (This report) | 21 NO OF PAGES | | |
| 18. AVAILABILITY STATEMENT | | Y CLASS (This report) | 32 DD105 | | |
| Unlimited | 20 SECURITY | (CLASS <i>IThus page)</i> | 22 PRICE | | |